

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1901	3	31,180
Addition	1929	3	35,990
Campus Total			67,170

Category : Exterior			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1 Main W	1	EA	7	10+ years	
	Exterior Doors - Exterior AMP Door	#1 Main W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 Main W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 Main W	40	LF	7	10+ years	
	Power Door Operator and Controls	#1 Main W	1	EA	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 Main W	14	LF	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#6- Boiler Room- E	1	EA	5	6-10 years	
	Exterior Stairs - Concrete	#6- Boiler Room- E	3	LF	4	0-1 year	Broken/cracked.
	Entrance Control - Audio	#7 SE	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#7 SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 SE	18	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#7 SE	14	LF	6	6-10 years	
	Exterior Doors - Exterior AMP Door	#8- S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8- S	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#8- S	55	LF	5	0-1 year	Cracking.
oundati	on						
	Foundation - Masonry	Entire Building	325	LF	6	10+ years	
	Foundation - Masonry	Entire Building	40	LF	5	2-5 years	
	Superstructure - Heavy Timber	Entire Building	30,998	SF	7	10+ years	
Lighting							



Latego	ategory : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	6-10 years	
oof Sys							
	Coping - Stone	Entrance 8 roof - S	25	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Entrance 8 roof - S	12	LF	6	10+ years	
	Parapet - Parapet > 30"	Entrance 8 roof - S	25	LF	7	10+ years	
	Roof - Modified Bitumen	Entrance 8 roof - S	75	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Entrance 8 roof - S	75	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Low E roof	57	LF	6	10+ years	
	Liner						
	Chimney - Metal Flue	Low E roof	15	LF	6	10+ years	
	Coping - Clay Tile	Low E roof	45	LF	7	10+ years	
	Coping - Stone	Low E roof	57	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Low E roof	10	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Low E roof	104	LF	7	10+ years	
	Roof - Modified Bitumen	Low E roof	3,135	SF	7	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Low E roof	3,135	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Access Ladder - Wood	Main Roof	1	EA	5	2-5 years	
	Coping - Clay Tile	Main Roof	120	LF	7	10+ years	
	Coping - Stone	Main Roof	249	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	30	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Main Roof	80	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	10	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	80	LF	5	10+ years	
	Parapet - Parapet > 30"	Main Roof	18	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	161	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	6,947	SF	5	6-10 years	
	Roof Hatch - Metal	Main Roof	0,947	EA	7	10+ years	
	Roof Structure - Heavy Timber	Main Roof	6,947	SF	7	10+ years	
	Roof Structure - Heavy Himber		0,947	36	1	10+ years	
Valls							
	Cheek-Wall - Concrete	Entire Building	3	SF	6	6-10 years	
	Cheek-Wall - Concrete	Entire Building	15	SF	6	6-10 years	
	Cornice - Cast Stone	Entire Building	228	LF	6	6-10 years	
	Cornice - Metal Projecting	Entire Building	227	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	10,650	SF	7	6-10 years	
	Exterior Walls - Stone-Cast	Entire Building	2,946	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	130	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	5	SF	7	10+ years	
A./							
Nindows	Curtain wall - Louver	Entire Building	80	SF	6	10+ years	



Catego	ry : Exterior	В	uilding	: Main					
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Guard - Guards perforated	Entire Building	800	SF	7	10+ years			
	Lintels - Brick	Entire Building	62	LF	6	6-10 years			
	Lintels - Steel	Entire Building	300	LF	6	6-10 years			
	Windows - Sash Aluminum Double-pane	Entire Building	2,621	SF	7	10+ years			
	· · · · ·	C C				•			

Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	ncy System	Location	Quantity	0011	Nank	Replacement	ooninients
nerger	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	Serve AC generator
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,094	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	650	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	4	0-1 year	Building has an AC generator. Lighting dimmed and hard to read.
	Exit Signs - Lunchroom	Entire Building	3	EA	4	0-1 year	Building has an AC generator. Hard to read.
	Security System - Intrusion Detection	Entire Building	31,180	SF	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	3	EA	6	6-10 years	Previously not assessed
	Emergency Generator- Outdoor- Diesel - 60 - 100 KW	North Courtyard	1	EA	6	6-10 years	Serves main and addition building
Main Sei	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves main and addition building
	PA System	Entire Building	31,180	SF	6	6-10 years	Serves main and addition buildings
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	0-1 year	Live, deteriorated
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	Found 3
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	4	0-1 year	Deteriorated, rusting, old.
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	10+ years	



	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Catago					Main		
Catego	ry : Fire Protection		В	uilding	main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Electrical Room	1	EA	6	6-10 years	Serves main and addition buildings
	Fire Alarm Strobe Lights	Electrical Room	31,180	SF	6	6-10 years	Ű
	Fire Alarm_System	Electrical Room	31,180	SF	6	6-10 years	
	Fire Pump Controller	Electrical Room	1	EA	6	6-10 years	In pump room
Dump D	oom Assembly						
Ритр К	Fire Pump - Less than 25hp	Fire Pump Room	1	EA	6	6-10 years	In pump room, serves main building
	Jockey Pump	Fire Pump Room	1	EA	6	6-10 years	For a combination wet and dry
	·····				-		system. Building also has an air
							compressor in pump room
Sprinkle	r System						
	Combination Wet and Dry Sprinkler System	Entire Building	31,180	SF	6	6-10 years	Jockey pump and air compressor
	Sprinkler Heads	Entire Building	31,180	SF	7	10+ years	Passed fire marshal inspection
	Sprinkler Piping	Entire Building	31,180	SF	6	6-10 years	Original to building
Catego	ry : Mechanical		В	uilding	: Main		
J	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	Iling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Boiler Room	1	EA	4	1-2 years	Frequent maintenance required,
							deteriorated, serves main building
	Air Intake	Boiler Room	1	EA	5	6-10 years	deteriorated, serves main building Not painted
		Boiler Room Boiler Room	1 1	EA EA	5 4	6-10 years 1-2 years	
	Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft		-			,	Not painted
	Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts	Boiler Room	1	EA LF	4	1-2 years 6-10 years	Not painted Frequent maintenance required Painted
	Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft	Boiler Room Boiler Room	1 100	EA	4 5	1-2 years	Not painted Frequent maintenance required
_Boiler Sv	Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers	Boiler Room Boiler Room	1 100	EA LF	4 5	1-2 years 6-10 years	Not painted Frequent maintenance required Painted Mostly manually controlled, BAS
_Boiler Sy	Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers //stems Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room Boiler Room	1 100	EA LF	4 5	1-2 years 6-10 years	Not painted Frequent maintenance required Painted Mostly manually controlled, BAS
_Boiler Sy	Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers //stems Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP Chemical Feed System	Boiler Room Boiler Room Boiler Room	1 100 14	EA LF EA	4 5 5	1-2 years 6-10 years 6-10 years 6-10 years 6-10 years	Not painted Frequent maintenance required Painted Mostly manually controlled, BAS issue
_Boiler Sy	Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers <u>vstems</u> Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP Chemical Feed System Combustion Dampers	Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	1 100 14 2	EA LF EA EA	4 5 5 5	1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	Not painted Frequent maintenance required Painted Mostly manually controlled, BAS issue
<u>Boiler S</u>	Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers //stems Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP Chemical Feed System	Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	1 100 14 2 1	EA LF EA EA EA	4 5 5 5 5 5	1-2 years 6-10 years 6-10 years 6-10 years 6-10 years	Not painted Frequent maintenance required Painted Mostly manually controlled, BAS issue



Catego	ry : Mechanical		В	uilding	: Main		0041 S Union AVENUE, Chicago, IL 60628
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years	B1, B2, Serves main and addition buildings
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	6-10 years	There are a few pipe clamps, connected to addition
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	6-10 years	Also connect to addition building, there are a few pipe clamps
	Steam Traps	Boiler Room	24	EA	5	6-10 years	
Heating							
	Unit Heater - Gas	Boiler Room	1	EA	6	10+ years	Previously not installed
	Unit Heater - Steam	Boiler Room	2	EA	4	1-2 years	Old, deteriorated, found 2
	Wall Heater - Electric	Entire Building	7	EA	5	6-10 years	
	Fin Tube - Steam	Entire Building	12	LF	5	6-10 years	Paint required.
Tempera	ature Control						
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	Serve unit heaters
	Pneumatic System	Entire Building	31,180	SF	4	1-2 years	Leaks, manually operated
	Thermostats - Pneumatic	Entire Building	14	EA	4	1-2 years	Leak, many need repair, not calibrated
Ventilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Basement, Lower Roof and Warming Kitchen	2	EA	5	6-10 years	Recently serviced, found 2
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Basement, Lower Roof and Warming Kitchen	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
Crown	ltem Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Hot Wate	Item - Type	Location	Quantity		Kalik	Replacement	Comments
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	2012 installation, serves main and addition buildings
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room	1	EA	5	6-10 years	Ceiling mounted
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	31,180	SF	4	1-2 years	There are a few pipe clamps
	Domestic Piping-Hot Water Return Risers	Entire Building	31,180	SF	4	1-2 years	Leaks are occasionally repaired
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	31,180	SF	4	1-2 years	Hot water pressure is sometimes low on top floor
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	31,180	SF	4	1-2 years	1901 installation
	Domestic Piping-Hot/Cold Water Supply	Entire Building	31,180	SF	4	1-2 years	There are a few pipe clamps



Category : Plumbing Building : Main Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments (Risers) Domestic Piping-Hot/Cold Water Supply SF More than 120 years old Entire Building 31.180 4 1-2 vears (from Risers to Fixtures) Sanitary Piping SF 5 Entire Building 31.180 6-10 years 5 Storm Piping Entire Building 31,180 SF 6-10 years SF 5 6-10 years Vent Piping Entire Building 31,180 Pumps Pumps - Domestic Booster Pump-Simplex ΕA Boiler Room 1 5 6-10 vears Serves main and addition building Category : Room **Building : Main** Recommend Location UOM Rank Comments Group Item - Type Quantity Replacement Administrative Suites/Offices ΕA 7 AC Unit Floor 1.5 Principal's Office over west 1 6-10 years Floor 1.5 Principal's Office over west 229 SF 7 Ceiling - Plaster/Drywall 10+ years Doors - Wood Doors inclu hw Floor 1.5 Principal's Office over west ΕA 7 10+ years 1 Floor - Carpet Floor 1.5 Principal's Office over west 229 SF 6 6-10 years Lighting - Pendent/Surface Floor 1.5 Principal's Office over west 10 FΑ 7 6-10 years Power Distribution Floor 1.5 Principal's Office over west 6 FΑ 7 10+ years SF Storage/ Closet Floor 1.5 Principal's Office over west 30 7 10+ vears Walls - Plaster/Drywall SF Floor 1.5 Principal's Office over west 238 7 10+ years Walls - Plaster/Drywall Floor 1.5 Principal's Office over west 60 SF 4 0-1 year Damaged wall Ceiling - Plaster/Drywall SF Janitor's Room - Basement 97 6 10+ years Floor - Concrete Janitor's Room - Basement 97 SF 7 10+ vears Lighting - Pendent/Surface Janitor's Room - Basement 2 FΑ 7 6-10 years Power Distribution Janitor's Room - Basement 4 ΕA 7 10+ vears SF Walls - Masonrv Janitor's Room - Basement 211 6 10+ years Ceiling - Plaster/Drywall SF 7 Kitchen Manager's Office 124 10+ vears Doors - Wood Doors inclu hw Kitchen Manager's Office EA 7 10+ years 1 Floor - Tile SF Kitchen Manager's Office 114 6 10+ years Floor - Tile Kitchen Manager's Office 10 SF 4 0-1 year Damaged tiles Lighting - Pendent/Surface Kitchen Manager's Office 2 ΕA 7 6-10 years Power Distribution Kitchen Manager's Office 4 ΕA 7 10+ years SF Walls - Masonry Kitchen Manager's Office 121 7 10+ vears Walls - Plaster/Drvwall Kitchen Manager's Office 40 SF 7 10+ vears Ceiling - Plaster/Drywall Room 303. Office 95 SF 7 10+ years Doors - Transom Window Room 303, Office 9 SF 7 10+ years 7 Doors - Wood Doors inclu hw Room 303, Office 1 EA 10+ years Room 303, Office SF 6-10 years Floor - Carpet 95 6 Lighting - Pendent/Surface Room 303. Office 1 FΑ 7 6-10 years Power Distribution Room 303. Office 2 FΑ 7 6-10 years Walls - Plaster/Drywall Room 303. Office 123 SF 7 10+ years SF Ceiling - Plaster/Drywall Room 305. Office 3rd floor 95 7 10+ vears Room 305 was not accessible during



Catego	ry : Room		В	uilding	: Main		
J	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-							the site visit as the Building Engineer
							did not have a key to open the room.
	Doors - Wood Doors inclu hw	Room 305, Office 3rd floor	1	EA	6	10+ years	Room 305 was not accessible during
							the site visit as the Building Engineer
							did not have a key to open the room.
	Floor - Carpet	Room 305, Office 3rd floor	95	SF	7	6-10 years	
	Lighting - Pendent/Surface	Room 305, Office 3rd floor	1	EA	7	6-10 years	
	Power Distribution	Room 305, Office 3rd floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 305, Office 3rd floor	123	SF	7	10+ years	
Kitchen	Osilian Francis		000	05	7	0.40	
	Ceiling - Exposed	Basement	382	SF	7	6-10 years	
	Doors - Wood Doors inclu hw Floor - Terrazzo	Basement	1 382	EA SF	6	10+ years	
	Lighting - Pendent/Surface	Basement Basement	302 5	EA	7 7	10+ years	
	Serving Line	Basement	5		7	6-10 years 10+ years	
	Storage/ Closet	Basement	125	SF	7	10+ years	
	Walls - Masonry	Basement	249	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	249	SF	7	10+ years	
	Traile Tractor, Dry Tail	Datement	210	0.	•	lot youro	
Library							
	AC Unit	3rd flr south end of corridor	1	EA	7	6-10 years	
	Casework	3rd flr south end of corridor	67	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd flr south end of corridor	872	SF	7	10+ years	
	Doors - Transom Window	3rd flr south end of corridor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd flr south end of corridor	2	EA	7	10+ years	
	Floor - Wood	3rd flr south end of corridor	872	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd flr south end of corridor	14	EA	7	6-10 years	
	Storage/ Closet	3rd flr south end of corridor	212	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd flr south end of corridor	1,452	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement south end	650	SF	7	10+ years	
	Floor - Terrazzo	Basement south end	650	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement south end	10	EA	7	6-10 years	
	Serving Line	Basement south end	8	LF	7	10+ years	
	Walls - Masonry	Basement south end	1,063	SF	7	10+ years	
MDF_ID	F						
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	75	SF	7	10+ years	
	Other Cooling Unit	1st Floor		EA			



Catego	ry : Room		В	uilding	: Main		0041 S Union AVENUE, Chicago, IL 60628
				3	,	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	43	SF	5	10+ years	Portion of wall missing where piping
							is.
	Janitor's Closet	2nd Floor	43	SF	5	10+ years	Cracking and portion of wall missing.
	Air Intake Plenums	Basement	1,000	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	275	SF	7	10+ years	
	Storage Room	Basement	150	SF	7	10+ years	
	Vaults	Basement	250	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	120	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	120	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	320	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor All Gender	86	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor All Gender	76	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor All Gender	10	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor All Gender	2	EA	7	10+ years	C C
	Floor - Wood	1st Floor All Gender	86	SF	7	10+ years	
	Lavatory	1st Floor All Gender	1	EA	4	0-1 year	Sink not working
	Lighting - Pendent/Surface	1st Floor All Gender	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor All Gender	83	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor All Gender	25	SF	5	0-1 year	Water damage
	Water Closet	1st Floor All Gender	1	EA	7	10+ years	
	Accessories	In Kitchen Manager Office	150	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Kitchen Manager Office	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Kitchen Manager Office	1	EA	7	10+ years	
	Floor - Tile	In Kitchen Manager Office	145	SF	7	10+ years	
	Floor - Tile	In Kitchen Manager Office	5	SF	4	0-1 year	Damaged tiles
	Lavatory	In Kitchen Manager Office	2	EA	7	10+ years	
	Lighting - Pendent/Surface	In Kitchen Manager Office	1	EA	7	6-10 years	
	Partitions	In Kitchen Manager Office	1	EA	7	10+ years	
	Student Lockers - One Tier	In Kitchen Manager Office	1	EA	7	10+ years	
	Walls - Masonry	In Kitchen Manager Office	150	SF	7	10+ years	
	Walls - Plaster/Drywall	In Kitchen Manager Office	140	SF	7	6-10 years	
	Water Closet	In Kitchen Manager Office	1	EA	7	6-10 years	
	Accessories	In Pre-School Room 101	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Pre-School Room 101	65	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Pre-School Room 101	1	EA	6	10+ years	



Catego	ry : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Terrazzo	In Pre-School Room 101	65	SF	7	10+ years		
	Lavatory	In Pre-School Room 101	1	EA	7	10+ years		
	Lighting - Pendent/Surface	In Pre-School Room 101	1	EA	7	6-10 years		
	Partitions	In Pre-School Room 101	1	EA	7	10+ years		
	Walls - Plaster/Drywall	In Pre-School Room 101	320	SF	7	10+ years		
	Water Closet	In Pre-School Room 101	1	EA	7	10+ years		
Catego	ry : Classroom		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #100 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	894	SF	5	0-1 year	Damaged, cracked
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	894	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	142	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,248	SF	7	10+ years	
Classroo	om #101 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	60	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	894	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Carpet	1st Floor	894	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	178	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,120	SF	7	10+ years	
Classroo	om #102 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	AC Units	1st Floor	1	EA	5	2-5 years	
	Ceiling - Plaster/Drywall	1st Floor	894	SF	7	10+ years	
	Chalk Board	1st Floor	48	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	894	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Storage/ Closet	1st Floor	230	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,368	SF	7	10+ years	



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Classroom #200 (Art Room) AC Units 2nd Floor 1 ΕA 7 6-10 years Ceiling - Splined 2nd Floor 894 SF 7 10+ years Doors - Transom Window 2nd Floor SF 7 8 10+ years Doors - Wood Doors inclu hw ΕA 7 10+ years 2nd Floor 1 SF 7 Floor - Tile 2nd Floor 894 6-10 years Lighting - Pendent/Surface 2nd Floor 18 FΑ 7 6-10 years LF Marker Board 2nd Floor 8 7 6-10 years SF Storage/ Closet 2nd Floor 142 7 10+ years Walls - Plaster/Drywall SF 2nd Floor 1,358 7 10+ years Work Sink ΕA 7 2nd Floor 2 10+ years Classroom #201 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 vears Ceiling - Plaster/Drywall SF 2nd Floor 894 7 10+ years Chalk Board 2nd Floor 18 LF 4 2-5 years Doors - Transom Window 2nd Floor 8 SF 7 10+ years Doors - Wood Doors inclu hw 2 ΕA 7 10+ years 2nd Floor SF 7 Floor - Wood 2nd Floor 894 10+ years Lighting - Pendent/Surface 2nd Floor 14 FΑ 7 6-10 years LF Marker Board 2nd Floor 42 7 6-10 years SF Storage/ Closet 2nd Floor 178 7 10+ years Walls - Plaster/Drywall SF 2nd Floor 1,120 7 10+ years Classroom #202 (Regular Classroom) AC Units 2nd Floor ΕA 7 6-10 years 1 Ceiling - Plaster/Drvwall 2nd Floor 894 SF 7 10+ vears Doors - Transom Window SF 2nd Floor 8 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 7 10+ years 2nd Floor SF 7 Floor - Wood 894 10+ years Lighting - Pendent/Surface ΕA 7 6-10 years 2nd Floor 14 LF 7 Marker Board 2nd Floor 36 6-10 years Storage/ Closet 2nd Floor SF 7 191 10+ years SF Walls - Plaster/Drywall 2nd Floor 1,478 7 10+ years Classroom #204 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 years LF Casework 2nd Floor 48 7 10+ years SF Ceiling - Plaster/Drywall 2nd Floor 130 10+ years 6 Doors - Transom Window SF 7 2nd Floor 8 10+ vears Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 7 10+ years Floor - Wood 2nd Floor 130 SF 7 10+ years Lighting - Pendent/Surface 2nd Floor 1 EΑ 7 10+ years



Catego	ory : Classroom		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	169	SF	6	10+ years	
lassroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	894	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	894	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	42	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	178	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,120	SF	7	10+ years	
lassror	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	894	SF	7	10+ years	
	Chalk Board	3rd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	-0	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood Doors inclu nw	3rd Floor	894	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	26	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	191	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,367	SF	7	10+ years	
lassror	om #304 (Regular Classroom)						
1233100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	680	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood Doors inclu nw	3rd Floor	680	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Marker Board	3rd Floor	21		7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,171	SF	7	•	
	waiis - Plastel/Drywaii	310 F1001	1,171	55	/	10+ years	
assroo	om #G1 (Computer Lab)						
	AC Units	Basement	2	EA	7	6-10 years	
	Casework	Basement	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,290	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	



AUDA .	SCHOOIS					1	0041 S Union AVENUE, Chicago, IL 60628
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Basement	1,290	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	15	EA	7	6-10 years	
	Walls - Masonry	Basement	1,348	SF	7	10+ years	
	Wireless System	Basement	1	EA	7	6-10 years	
	Work Sink	Basement	1	EA	7	10+ years	
Catego	ry : Interior		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	1,029	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	. 4	EA	7	10+ years	
	Floor - Asphalt Floor	1st Floor	1,029	SF	7	10+ years	
	· · · · · · · · · · · · · · · · · · ·	4			7		
	Lighting - Pendent/Surface	1st Floor	10	EA	(6-10 years	

	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Floor - Asphalt Floor	1st Floor	1,029	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor	8	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	30	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,086	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,029	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	7	10+ years	
	Floor - Asphalt Floor	2nd Floor	1,029	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	2,086	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,029	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	4	EA	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	1,029	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	2,086	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,754	SF	7	10+ years	
	Doors - Wood Doors include hw	Basement	6	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	1,754	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	16	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement	6	LF	7	10+ years	
	Walls - Masonry	Basement	2,528	SF	7	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	North East	621	SF	6	10+ years	
	Floor - Asphalt	North East	502	SF	7	10+ years	
	Floor - Terrazzo	North East	151	SF	7	10+ years	
	Handrails	North East	192	LF	7	10+ years	
	Lighting - Lay-in	North East	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	North East	4	EA	7	6-10 years	
	Lighting - Wall Mounted	North East	2	EA	7	6-10 years	
	Stairs - Asphalt	North East	90	LF	6	10+ years	
	Walls - Plaster/Drywall	North East	3,300	SF	7	10+ years	



Catego	ry : Interior		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	South	413	SF	6	10+ years	
	Floor - Asphalt	South	240	SF	7	10+ years	
	Floor - Terrazzo	South	600	SF	7	10+ years	
	Handrails	South	192	LF	7	10+ years	
	Lighting - Lay-in	South	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	South	8	EA	7	6-10 years	
	Lighting - Wall Mounted	South	2	EA	6	6-10 years	
	Stairs - Terrazzo	South	90	LF	7	10+ years	
	Walls - Plaster/Drywall	South	3,325	SF	7	10+ years	



Category : Exterior

Recommend Location Replacement Item - Type Quantity UOM **Comments** Group Rank Entrance FΑ 7 Entrance Control - Audio and Video #2. NW 1 10+ years #2. NW 3 FΑ Exterior Doors - Exterior AMP Door 6 6-10 years 3 Exterior Doors - Transom Lite #2. NW EΑ 7 10+ years **Exterior Stairs - Concrete** #2, NW 50 LF 6 6-10 years I F Ramp Handrail - Steel Ramp Handrail #2, NW 36 7 10+ years Ramps - Concrete #2. NW LF 7 112 10+ years LF Stair Handrail - Steel_Stair Handrail #2. NW 18 7 10+ years Exterior Doors - Exterior Stainless Steel #3 N 1 ΕA 5 2-5 years Steel plate/panel on Chain Link fence Door - not a door. FΑ 6 Exterior Doors - Exterior Steel Door #4. NE 1 2-5 vears 1 F Exterior Stairs - Concrete #4. NE 3 6 10+ years #5. E ΕA 0-1 year Rusted and corroded. Exterior Doors - Exterior Steel Door 1 4 Exterior Doors - Side lite #5, E 1 ΕA 4 0-1 year Significant damage. 1 F **Exterior Stairs - Concrete** #5, E 15 4 0-1 year Significant damage. Fire Escape Fire Escape North Facade 52 LF 6 6-10 years Foundation Foundation - Masonry Entire Building 271 LF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 37.739 SF 7 10+ years Liahtina Exterior Lighting - Wall Mounted 7 ΕA Entire Building 6 6-10 years Roof System Coping - Stone Entrance #2 roof - NW LF 10+ years 25 6 **Downspouts - Exterior Downspouts** 12 LF Entrance #2 roof - NW 6 6-10 years Parapet - Parapet > 30" Entrance #2 roof - NW 25 LF 5 10+ years SF Roof - Modified Bitumen Entrance #2 roof - NW 75 5 0-1 year Cracking/open seams Roof Structure - Steel with Clay Tile Arch 75 SF 7 Entrance #2 roof - NW 10+ years LF 7 Chimney - Metal Flue Low E roof 46 10+ years Coping - Clay Tile 50 LF 6 10+ years Low E roof Coping - Metal Low E roof 60 1 F 6 10+ years LF Coping - Stone Low E roof 42 6 6-10 years **Downspouts - Exterior Downspouts** 12 LF 6 6-10 years Low E roof LF Parapet - 16" - 30" Height 10 5 6-10 years Low E roof Parapet - Parapet < 16" Height Low E roof 55 LF 5 6-10 vears Roof - Metal SF Low E roof 120 7 10+ years SF Roof - Modified Bitumen Low E roof 1.914 5 6-10 vears SF 7 Roof Structure - Steel with Clay Tile Arch Low E roof 2,034 10+ years

Building : Addition



10041 S Union AVENUE, Chicago, IL 60628 **Category : Exterior Building : Addition** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Access Ladder - Wood Main Roof EΑ 4 0-1 vear Detached/shaky/aged 1 Coping - Clay Tile 45 LF 5 2-5 vears Main Roof Coping - Stone Main Roof 252 LF 6 6-10 years Downspouts - Interior Downspouts LF 6 6-10 years Main Roof 165 1 F Parapet - 16" - 30" Height Main Roof 40 6 6-10 years LF Parapet - Parapet < 16" Height Main Roof 40 6 10+ years Parapet - Parapet > 30" 25 LF 7 10+ years Main Roof Parapet - Parapet > 30" LF Main Roof 192 7 10+ years Roof - Modified Bitumen Main Roof 6,611 SF 5 0-1 year Open seams/Cracking with some detachment from substrate Roof Hatch - Metal Main Roof ΕA 7 1 10+ vears Roof Structure - Steel with Clay Tile Arch Main Roof 6.611 SF 7 10+ years Chimney - Metal Flue Mid NE roof LF 7 10+ years 62 LF Coping - Stone Mid NE roof 164 6 6-10 years **Downspouts - Interior Downspouts** LF 6 6-10 years Mid NE roof 50 Parapet - 16" - 30" Height 109 LF 7 Mid NE roof 10+ years Parapet - Parapet < 16" Height LF 7 Mid NE roof 15 10+ years LF Parapet - Parapet > 30" Mid NE roof 40 7 10+ years Roof - Modified Bitumen SF Mid NE roof 3.695 5 0-1 vear Soft Spots/Cracking/Detachment from substrate Roof Structure - Steel with Clay Tile Arch 3.695 SF 7 Mid NE roof 10+ years Walls Cheek-Wall - Concrete 3 SF Entire Building 6 6-10 vears Cornice - Masonry Projecting Limestone Entire Building 114 LF 5 10+ years Cornice - Metal Projecting Entire Building LF 5 6-10 years 114 Open joints/rust SF 7 Exterior Walls - Brick Entire Building 15.846 10+ years SF Exterior Walls - Stone-Cast Entire Building 1,599 0-1 year Minor chipping/broken pieces 4 Windows Guard - Guards perforated SF 7 10+ years Entire Building 1,320 LF Lintels - Steel Entire Building 463 6 6-10 years Entire Building 72 LF 7 10+ years Lintels - Stone Skylite - Glass Single-Pane Entire Building 50 SF 4 0-1 year Cracked. Windows - Sash Aluminum Double-pane Entire Building 4.160 SF 7 10+ years **Category : Electrical Building : Addition** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Emergency System SF Emergency A/C Power - Auditoium and Entire Building 3.407 6 6-10 years Aisle Lighting Emergency A/C Power - Corridors and Entire Building 7,234 SF 6 6-10 years



Catego	ory : Electrical	В	Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Stairs							
	Emergency A/C Power - Gym	Entire Building	2,878	SF	6	6-10 years		
	Emergency A/C Power - Students Toilets	Entire Building	2,063	SF	6	6-10 years		
	Exit Signs - Auditoium	Entire Building	8	EA	6	6-10 years		
	Exit Signs - Corridors and Stairs	Entire Building	10	EA	6	6-10 years		
	Exit Signs - Gym	Entire Building	3	EA	4	0-1 year	Broken, hard to read.	
	Security System - Intrusion Detection	Entire Building	35,990	SF	6	6-10 years		
	Emergency Battery Packs - Students Toilets	Entire Building	3	EA	6	6-10 years	Previously not assessed	
Main Se	rvice							
	PA System	Entire Building	35,990	SF	5	6-10 years	Connected to main building	
Power D	Distribution							
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Served from main building. Old	
						,	corroded/rusted.	
Catego	ory : Fire Protection		В	uilding	: Additi	on		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Ala	rm							
	Fire Alarm Strobe Lights	Entire Building	35,990	SF	6	6-10 years		
	Fire Alarm_System	Entire Building	35,990	SF	6	6-10 years		
Catego	ory : Mechanical		В	uilding	: Additi	on		
Ŭ	•			Ŭ		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Air Hand	dling Systems							
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Basement	1	EA	4	1-2 years	Corroded, noisy, serves addition building	
	Air Intake	Basement	1	EA	5	6-10 years	Not painted	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	4	1-2 years	Corroded, noisy motor, old	
	Return Duct Work - Masonry and Ducts-	Basement	100	LF	5	6-10 years	Confided, hoisy motor, old	
	Missing or Existing Shaft	Basement	100	L1	0	o io years		
	Zone Dampers	Basement	14	EA	5	6-10 years		
		Dusement	14	LA	0	o to years		
Boiler S				. –	_			
	Piping - Condensate Pipe- Steel	Entire Building	200	LF	5	6-10 years	Connects to main building, previous not assessed, there are a few pipe clamps	
	Piping - Steam Pipe- Steel	Entire Building	200	LF	5	6-10 years	Previously not assessed, there are	
	i iping - otean i ipe- oteei		200	<u> </u>	0			
	Tiping - Otean Tipe- Oteen	Linio Banang	200	_ 1	0	0-10 years	few pipe clamps, connected to m	



	ichools					1	0041 S Union AVENUE, Chicago, IL 60628
Catego	ry : Mechanical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
					_		building
	Steam Traps	Entire Building	15	EA	5	6-10 years	Previously not assessed
Heating	Devices						
	Radiators - Steam	2nd Floor	8	EA	5	6-10 years	In gym
	Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	
	Fin Tube - Steam	Entire Building	44	LF	5	6-10 years	In restrooms
Tempera	ture Control						
•	Pneumatic System	Entire Building	35,990	SF	4	1-2 years	Mostly manually controlled, connected to the main building, leaks
	Thermostats - Pneumatic	Entire Building	14	EA	4	1-2 years	Leak, not calibrated.
Ventilatio							
venilialio	Exhaust Fans- Roof Mounted - 500 - 1500	Roof and Lower Roof	1	EA	6	6-10 years	
	CFM					,	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof and Lower Roof	2	EA	6	6-10 years	Recently serviced
Cotomo	n. Dlumbing		В	uildina			
Catego	ry : Plumbing		D	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping		20041011	quantity				
<u>i iping</u>	Domestic Piping-Hot Water Return Lines	Entire Building	35,990	SF	6	6-10 years	Minor leaks are occasionally repaired
	Domestic Piping-Hot Water Return Risers	Entire Building	35,990	SF	6	6-10 years	wind leaks are decasionally repared
	Domestic Piping-Hot Water from Risers to	Entire Building	35,990	SF	6	6-10 years	
	Fixtures		,		-	,	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	35,990	SF	6	6-10 years	1929 installation
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	35,990	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	35,990	SF	6	6-10 years	There are a few pipe clamps
	Sanitary Piping	Entire Building	35,990	SF	5	6-10 years	
	Storm Piping	Entire Building	35,990	SF	5	6-10 years	
	Vent Piping	Entire Building	35,990	SF	5	6-10 years	
Catan		-		: . !		-	
Catego	ry : Room		В	unaing	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	rative Suites/Offices		quantity	0.0111			
	Ceiling - Plaster/Drywall	Engineer's office in basement	208	SF	6	10+ years	



Catogo	ry : Room		D	uilding	: Additi	1 00	
Calego	ry . Room		D	unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Doors - Wood Doors inclu hw	Engineer's office in basement	1	EA	7	10+ years	Comments
	Floor - Tile Ceramic/ Porcelain	Engineer's office in basement	208	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineer's office in basement	200	EA	7	6-10 years	
	Power Distribution	Engineer's office in basement	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineer's office in basement	135	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Engineer's office in basement	135	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Gym Office 2nd floor	67	SF	6	10+ years	
	Doors - Transom Window	Gym Office 2nd floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Office 2nd floor	1	ĒA	7	10+ years	
	Floor - Wood	Gym Office 2nd floor	67	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym Office 2nd floor	1	ĒA	7	6-10 years	
	Power Distribution	Gym Office 2nd floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym Office 2nd floor	145	SF	6	10+ years	
	AC Unit	Room 205, Office 2nd floor	1	ĒA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 205, Office 2nd floor	95	SF	7	10+ years	
	Doors - Transom Window	Room 205, Office 2nd floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 205, Office 2nd floor	1	ĒA	7	10+ years	
	Floor - Carpet	Room 205, Office 2nd floor	95	SF	6	6-10 years	
	Lighting - Pendent/Surface	Room 205, Office 2nd floor	1	EA	7	6-10 years	
	Power Distribution	Room 205, Office 2nd floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 205, Office 2nd floor	123	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Teacher lounge 1st floor next to 107	140	SF	7	10+ years	
	Doors - Transom Window	Teacher lounge 1st floor next to 107	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Teacher lounge 1st floor next to 107	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Teacher lounge 1st floor next to 107	140	SF	7	10+ years	
	Lighting - Pendent/Surface	Teacher lounge 1st floor next to 107	2	EA	7	6-10 years	
	Power Distribution	Teacher lounge 1st floor next to 107	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Teacher lounge 1st floor next to 107	480	SF	7	10+ years	
_Auditoriu	m & Theater						
	Balcony Seating	1st Floor	137	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,407	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	<i>6</i>	EA	7	10+ years	
	Floor - Tile	1st Floor	3,377	SF	7	10+ years	
	Floor - Tile	1st Floor	30	SF	4	0-1 year	Damaged tiles
	Lighting - Metal Halide/Sodium Vapor	1st Floor	11	EA	7	6-10 years	0
	Main Floor Seating	1st Floor	336	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	457	SF	6	10+ years	
	Stage Curtain	1st Floor	6	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	8	LF	6	10+ years	
	Storage/ Closet	1st Floor	63	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,599	SF	7	10+ years	



Catego	ry : Room		Building : Addition				
_			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Symnas							
	Ceiling - Plaster/Drywall	2nd Floor	2,878	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	2,878	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	9	EA	7	6-10 years	
	Scoreboards	2nd Floor	1	EA	7	10+ years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,870	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,870	SF	7	10+ years	
/lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	43	SF	7	10+ years	
	Janitor's Closet	2nd Floor	43	SF	7	10+ years	
	Janitor's Closet	3rd Floor	43	SF	7	10+ years	
	Storage Room	3rd Floor	125	SF	5	0-1 year	Unfinished interior
	Air Intake Plenums	Basement	460	SF	7	10+ years	
	Boiler Room	Basement	973	SF	7	10+ years	
	Coal Room	Basement	100	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	369	SF	7	10+ years	
	Storage Room	Basement	425	SF	7	10+ years	
	Storage Room	Basement	427	SF	7	10+ years	
	Storage Room	Formerly Women's Staff Restroom,	96	SF	5	10+ years	The formerly women staff restroon
		2nd Floor		01	0	i er jouro	was not accessible during the site visit as the Building Engineer could not find keys for this room.
Restroo	n						
0.51100	Accessories	1st Floor	276	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	276	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	276	SF	7	10+ years	
	Floor Drain	1st Floor	270	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	480	SF	7	10+ years	
	Water Closet	1st Floor	400	EA	7	10+ years	
	Accessories	1st Floor	231	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	231	SF	7	10+ years	
			201	0	'	ior years	



Building : Addition Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Doors - Transom Window 1st Floor 18 SF 10+ vears 7 Doors - Wood Doors inclu hw 1st Floor ΕA 7 1 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 231 SF 7 10+ years Floor Drain ΕA 7 1st Floor 1 10+ years 7 Hand Dryer 1st Floor 1 EΑ 6-10 years 2 7 Lavatory 1st Floor EΑ 10+ years Lighting - Pendent/Surface 1st Floor 4 ΕA 7 6-10 years 2 Partitions 1st Floor EΑ 7 10+ years Urinals 1st Floor 4 EΑ 7 10+ vears Walls - Structural Glazed Tile SF 1st Floor 300 7 10+ years Water Closet 1st Floor 2 ΕA 7 10+ vears Accessories 2nd Floor 337 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor 337 SF 6 10+ years SF 7 Doors - Transom Window 2nd Floor 18 10+ years Doors - Wood Doors inclu hw 2 ΕA 7 2nd Floor 10+ years 337 SF 7 Floor - Tile Ceramic/ Porcelain 2nd Floor 10+ years ΕA 7 Floor Drain 2nd Floor 1 10+ years Hand Dryer 2nd Floor 1 EΑ 7 6-10 years 2 Lavatorv 2nd Floor EΑ 7 10+ vears Lighting - Pendent/Surface 2nd Floor 4 EΑ 7 6-10 years Partitions 2nd Floor 6 ΕA 7 10+ years Walls - Structural Glazed Tile SF 7 2nd Floor 438 10+ years ΕA 7 Water Closet 2nd Floor 6 10+ years SF 7 Accessories 2nd Floor 231 6-10 years Ceiling - Plaster/Drywall 231 SF 7 2nd Floor 10+ years SF Doors - Transom Window 2nd Floor 18 7 10+ vears Doors - Wood Doors inclu hw 2nd Floor 2 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor 231 SF 6 6-10 years 7 Floor Drain 2nd Floor 1 EΑ 10+ years Hand Drver 2nd Floor 1 ΕA 7 6-10 years 2nd Floor 2 FΑ 7 10+ vears Lavatorv Lighting - Pendent/Surface 2nd Floor 4 ΕA 7 6-10 years Partitions 2 7 2nd Floor FΑ 10+ years Urinals 2nd Floor 4 FΑ 7 10+ years Walls - Structural Glazed Tile 300 SF 7 2nd Floor 10+ years ΕA 7 Water Closet 2nd Floor 2 10+ years SF Accessories 3rd Floor 337 7 6-10 years Ceiling - Plaster/Drywall SF 3rd Floor 337 6 10+ years SF Doors - Transom Window 3rd Floor 18 7 10+ years ΕA Doors - Wood Doors inclu hw 3rd Floor 2 7 10+ vears SF Floor - Tile Ceramic/ Porcelain 3rd Floor 337 7 10+ years FΑ 7 Floor Drain 3rd Floor 10+ vears 1 Hand Dryer 3rd Floor EΑ 7 6-10 years 1 2 Lavatory 3rd Floor EA 7 10+ years



Building : Addition Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface 3rd Floor ΕA 6-10 years 4 7 3rd Floor 6 ΕA 7 Partitions 10+ years Walls - Structural Glazed Tile 3rd Floor 438 SF 7 10+ years Water Closet 6 ΕA 7 3rd Floor 6-10 years SF 7 Accessories 3rd Floor 231 6-10 years SF 7 Ceiling - Plaster/Drywall 3rd Floor 231 10+ years Doors - Transom Window 3rd Floor SF 7 18 10+ years Doors - Wood Doors inclu hw 3rd Floor 2 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Floor 231 SF 6 10+ years Floor Drain 3rd Floor FΑ 7 10+ vears 1 Hand Drver 3rd Floor 1 FΑ 7 6-10 years Lavatory 3rd Floor 2 EΑ 7 10+ years Lighting - Pendent/Surface 4 ΕA 7 6-10 years 3rd Floor 2 ΕA 7 Partitions 3rd Floor 10+ years 7 Urinals 3rd Floor 4 EΑ 10+ years Walls - Structural Glazed Tile 300 SF 7 3rd Floor 10+ years ΕA 7 Water Closet 3rd Floor 2 10+ years Accessories **Basement** 179 SF 7 6-10 years Ceiling - Plaster/Drvwall SF **Basement** 179 7 10+ vears Floor - Tile Ceramic/ Porcelain SF Basement 179 7 10+ years Floor Drain Basement ΕA 7 10+ years 1 7 Hand Dryer Basement 1 EΑ 6-10 years 2 ΕA 7 Lavatory **Basement** 10+ years 7 Lighting - Pendent/Surface Basement 4 FΑ 6-10 years Partitions 2 ΕA 7 Basement 10+ years Urinals Basement 4 ΕA 7 10+ vears Walls - Structural Glazed Tile 232 SF Basement 7 10+ years Water Closet 2 ΕA 7 Basement 10+ years SF 7 Accessories Basement 175 6-10 years Ceiling - Plaster/Drywall Basement 175 SF 7 10+ years Floor - Tile Ceramic/ Porcelain Basement SF 170 7 10+ vears SF Floor - Tile Ceramic/ Porcelain Basement 5 4 0-1 vear Missina. 7 Floor Drain Basement 1 FΑ 10+ years Hand Drver FΑ 7 6-10 years Basement 1 2 7 Lavatory Basement EΑ 10+ years Lighting - Pendent/Surface 2 ΕA 7 Basement 6-10 years 6 Partitions **Basement** EΑ 7 6-10 years Walls - Structural Glazed Tile 232 SF Basement 7 10+ years Water Closet Basement 6 EΑ 7 10+ years SF Accessories Basement 81 7 6-10 vears SF Ceiling - Plaster/Drywall Basement 81 5 2-5 years Doors - Wood Doors inclu hw FΑ 7 Basement 10+ years 1 Floor - Tile Ceramic/ Porcelain **Basement** 81 SF 6 10+ years Lavatory **Basement** 2 EA 6 10+ years



Building : Addition Category : Room Recommend Location Quantity Group Item - Type UOM Rank Replacement Comments Lighting - Pendent/Surface **Basement** ΕA 6-10 years 7 1 Basement ΕA 7 6-10 years Showers 1 Walls - Tile Ceramic/ Porcelain Basement 360 SF 7 10+ years Water Closet ΕA 7 Basement 1 10+ years SF 7 Accessories Engineer's office in basement 45 6-10 years SF Ceiling - Plaster/Drywall 5 Engineer's office in basement 45 0-1 year Water damage. Doors - Wood Doors inclu hw Engineer's office in basement 1 ΕA 7 10+ years SF Floor - Concrete Engineer's office in basement 45 7 10+ years Lavatorv Engineer's office in basement 1 ΕA 7 10+ years Lighting - Pendent/Surface Engineer's office in basement 1 ΕA 7 6-10 years Walls - Plaster/Drvwall Engineer's office in basement 140 SF 5 0-1 vear Water damage. Walls - Vinyl Coated Gypsum Panel Engineer's office in basement 140 SF 5 0-1 year Water damage and rust stains. Water Closet Engineer's office in basement ΕA 7 10+ years 1 Accessories Women's Room 2nd Floor SF 7 98 6-10 years Ceiling - Plaster/Drywall Women's Room 2nd Floor SF 7 98 10+ years Doors - Wood Doors inclu hw EΑ 7 Women's Room 2nd Floor 1 10+ years Floor - Terrazzo SF Women's Room 2nd Floor 98 7 10+ years Lavatorv Women's Room 2nd Floor 1 ΕA 7 10+ years Lighting - Pendent/Surface Women's Room 2nd Floor 1 ΕA 7 6-10 vears Partitions Women's Room 2nd Floor 2 EΑ 7 10+ years Walls - Plaster/Drywall Women's Room 2nd Floor 127 SF 7 10+ years Water Closet Women's Room 2nd Floor 2 ΕA 7 10+ years

~ .

Catego	ory : Classroom	В	Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classro	om #106 (Kindergarten)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	7	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	845	SF	7	10+ years		
	Doors - Transom Window	1st Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Wood	1st Floor	845	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years		
	Marker Board	1st Floor	40	LF	7	6-10 years		
	Storage/ Closet	1st Floor	51	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,383	SF	7	10+ years		
Classroo	om #107 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	6	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	894	SF	7	10+ years		
	Doors - Transom Window	1st Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		

_ -- --



Catan				••••••••			0041 S Union AVENUE, Chicago, IL 60628	
Catego	ry : Classroom		В	Building : Addition				
0	Mana Tana	Leastlen	Owentites		Daula	Recommend	0	
Group	Item - Type Floor - Wood	Location 1st Floor	Quantity	UOM SF	Rank	Replacement	Comments	
			894		7	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	36	LF	7	6-10 years		
	Storage/ Closet	1st Floor	6	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,120	SF	7	10+ years		
Classroo	m #108 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	7	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	. 845	SF	7	10+ years		
	Doors - Transom Window	1st Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Wood	1st Floor	845	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years		
	Marker Board	1st Floor	40	LF	7	6-10 years		
	Storage/ Closet		40 51	SF		•		
		1st Floor		SF	7 7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,383	SF	7	10+ years		
Classroo	m #206 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	7	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	845	SF	7	10+ years		
	Chalk Board	2nd Floor	40	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	7	10+ years		
	Floor - Wood	2nd Floor	845	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	Storage/ Closet	2nd Floor	51	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,383	SF	7	10+ years		
						-		
Classroo	m #207 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	24	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	894	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Wood	2nd Floor	894	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	18	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years		
Classroo	m #208 (Regular Classroom)							
0///00	AC Units	2nd Floor	1	EA	7	6-10 years		
	AC UTILS		1	EA	1	o-ro years		



Category : Classroom Building : Addition					0041 S Union AVENUE, Chicago, IL 60628		
2						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	845	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	845	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	51	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,383	SF	7	10+ years	
Classroo	m #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	845	SF	7	10+ years	
	Chalk Board	3rd Floor	21	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	845	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	21	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	51	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,383	SF	7	10+ years	
Classroo	m #307 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,128	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,128	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,416	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	m #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	845	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	_ 845	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	



Category : Classroom			B	Building : Addition				
Ū.			5		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Marker Board	3rd Floor	42	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	51	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,383	SF	7	10+ years		
0								
Classroo	om #G2 (Store Room)							
	AC Units	Basement	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement	908	SF	7	10+ years		
	Chalk Board	Basement	50	LF	4	2-5 years		
	Doors - Transom Window	Basement	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years		
	Floor - Tile	Basement	908	SF	7	10+ years		
	Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years		
	Walls - Concrete Block	Basement	125	SF	7	10+ years		
	Walls - Masonry	Basement	1,257	SF	7	10+ years		
Classroo	om #G3 (Store Room)							
	AC Units	Basement	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement	924	SF	7	10+ years		
	Chalk Board	Basement	24	LF	4	2-5 years		
	Doors - Transom Window	Basement	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years		
	Floor - Tile	Basement	924	SF	7	10+ years		
	Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years		
	Walls - Concrete Block	Basement	125	SF	7			
		Basement	1,170	SF	7	10+ years 10+ years		
	Walls - Masonry	Dasement	1,170	ЪГ	1	10+ years		
Catego	ry : Interior		В	Building	: Additi			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Corridor		Location	Quantity		Kank	Replacement	Comments	
	Ceiling - Plaster/Drywall	1st Floor	1,725	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years		
	Drinking Fountains - Double Fountain	1st Floor	2	EA	7	6-10 years		
	Floor - Terrazzo	1st Floor	264	SF	7	10+ years		
	Floor - Tile/Sheet	1st Floor	1,340	SF	7	10+ years		
	Floor - Tile/Sheet	1st Floor	121	SF	4	0-1 year	Damaged tiles	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	č	
	Walls - Concrete Block	1st Floor	30	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	3,072	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	1,845	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	4	EA	7	10+ years		
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	6-10 years		
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	6-10 years		
	Difficing Founding - Single Foundin		I	EA	1	0-10 years		



Catego	ry : Interior	B	Building : Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	2nd Floor	264	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,581	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	3,072	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,845	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	3rd Floor	264	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,581	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	3,072	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,605	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Basement	2	EA	7	6-10 years	
	Floor - Terrazzo	Basement	1,605	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	7	10+ years	
	Stairs - Terrazzo	Basement	4	LF	7	10+ years	
	Student Lockers - One Tier	Basement	5	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement	2,322	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	52	SF	7	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	North West	986	SF	6	10+ years	
	Floor - Terrazzo	North West	886	SF	7	10+ years	
	Handrails	North West	192	LF	7	10+ years	
	Lighting - Pendent/Surface	North West	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	North West	2	EA	7	6-10 years	
	Lighting - Wall Mounted	North West	4	EA	7	6-10 years	
	Stairs - Terrazzo	North West	90	LF	7	10+ years	
	Walls - Plaster/Drywall	North West	4,254	SF	6	10+ years	



Category : Site Building : Site Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Athletic SF 7 Surface - Concrete North 4.100 10+ years Civil/Drainage Civil/ Drainage - Catch Basin Entire Site 4 EΑ 7 10+ years Civil/ Drainage - Catch Basin Entire Site 1 FΑ 7 10+ years Civil/ Drainage - Site Manhole Entire Site FΑ 7 10+ years 1 Civil/ Drainage - Site Manhole Entire Site 4 FΑ 7 10+ years Fencing Fencing - Chain Link LF Entire Site 94 6 10+ years Fencing - New Standard Ornamental LF Entire Site 216 6 10+ years Fencing - New Standard Ornamental Entire Site 692 LF 6 10+ years LF Fencing - Wood Fencing w/ Steel Frame Entire Site 86 6 10+ vears Fencing - Wood Fencing w/ Steel Frame LF Entire Site 40 4 0-1 year Missing boards and gaps. Landscape SF Landscape - Grass Entire Site 5.773 6 10+ years Entire Site SF 5 Landscape - Hardscape- Asphalt 150 2-5 vears Landscape - Hardscape- Concrete SF Entire Site 2.348 6 10+ years Landscape - Hardscape- Concrete Entire Site SF 6 1,971 10+ years Landscape - Hardscape- Pavers Entire Site 700 SF 7 10+ years Lighting - Pole Mounted 7 Entire Site 5 EΑ 10+ years Parkway trees Entire Site 24 ΕA 10+ years 6 SF Planting Beds/ Area Entire Site 890 6 6-10 years Plav Area - Synthetic Turf Entire Site 4,000 SF 7 10+ years Retaining Wall - Concrete SF Entire Site 562 6 10+ years Trash Receptacles Entire Site 3 ΕA 6 10+ vears Walking Path - Hardscape- Asphalt SF 7 Entire Site 3.500 10+ years Parking Lot Concrete Curbs LF 7 Parking Lot- North 505 10+ years LF Interior Plantings Parking Lot- North 150 7 10+ years SF Surface - Asphalt Parking Lot- North 6 6-10 years 10.619 Trash Enclosure - Chain Links Parking Lot- North 1,000 SF 5 2-5 years Minor damage/Rust - paint I F 7 Vehicular Screening Parking Lot- North 118 10+ years Playground Equipment - Combo 3-12 North 1 ΕA 7 10+ years Equipment - Swingset North 1 EΑ 7 10+ years Surface - Poured Surface SF North 4,400 7 10+ years



Category : Site			Building : Site				
		La sada s				Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sidewall	(5						
	Sidewalks - Internal Walks	Entire Site	123	LF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	9,005	SF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	4	0-1 year	Cracking.
Signage							
0 0	Flag Pole - Flag Pole	Southwest site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Southwest site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Southwest site	1	EA	6	10+ years	Dirty/Clean

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

Current lleage	Intended Lipper	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window	Smart- Board			
Current Usage Intended Usage Room Location Number Number (SF) Area Area Stop Boar Building : Main												
Art Room	Regular Classroom	2nd Floor	200	200	894	123	72	N	V			
Computer Lab	Kindergarten	Basement	G1	G1	1,290	140	50	N	N			
Office	Regular Classroom	1st Floor	102	102	894	111	39	N	N			
Pre School	Kindergarten	1st Floor	102	102	894	134	72	N	Y			
Regular Classroom	Kindergarten	1st Floor	100	100	894	78	48	N	N			
Regular Classroom	Regular Classroom	2nd Floor	201	201	894	80	48	N	Y			
Regular Classroom	Regular Classroom	2nd Floor	202	202	894	78	48	N	Ŷ			
Regular Classroom	Regular Classroom	2nd Floor	204	204	130	60	60	N	Ň			
Regular Classroom	Regular Classroom	3rd Floor	301	301	894	80	48	N	Y			
Regular Classroom	Regular Classroom	3rd Floor	302	302	894	111	39	N	Ň			
Regular Classroom	Regular Classroom	3rd Floor	304	NA	680	116	35	N	N			
Building : Addition	Kindergerten	1st Floor	106	106	845	132	66	N	V			
Kindergarten Regular Classroom	Kindergarten	1st Floor	108	108	894	132	66	N	T Y			
Regular Classroom	Regular Classroom Regular Classroom	1st Floor	107	107	845	132	66	N	T V			
Regular Classroom	Regular Classroom	2nd Floor	206	206	845	132	66	N				
Regular Classroom	Regular Classroom	2nd Floor	200	200	894	132	66	N				
Regular Classroom	Regular Classroom	2nd Floor	207	207	845	132	66	N				
Regular Classroom	Regular Classroom	3rd Floor	306	306	845	132	66	N	I V			
Regular Classroom	Regular Classroom	3rd Floor	308	308	845	132	66	N	I V			
Science Classroom	Regular Classroom	3rd Floor	308	308	1.128	152	77	N	N			
Store Room	Regular Classroom	Basement	G2	G2	908	104	54	N	N			
Store Room	Regular Classroom	Basement	G3	G3	908	198	60	N	N			