

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1898	3	37,830
Addition 1	1915	3	49,713
Addition 2	1941	3	16,875
Campus Total			104,418

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance						·	
	Exterior Doors - Exterior Steel Door	#2 N	2	EA	6	10+ years	
	Exterior Doors - Side lite	#5 W	2	EA	6	10+ years	
	Exterior Doors - Store Front	#5 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 W	3	EA	6	6-10 years	
	Exterior Stairs - Stone	#5 W	8	LF	5	2-5 years	Minor cracking and chipping.
	Exterior Doors - Exterior Steel Door	#7.5 S	2	EA	7	10+ years	
_Foundatio	on						
	Foundation - Masonry	Entire Building	390	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	16,364	SF	7	10+ years	
Lighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	10+ years	
Roof Syst	rem						
,	Coping - Metal	Main Roof	30	LF	4	0-1 year	Coping damaged & blew off.
	Downspouts - Exterior Downspouts	Main Roof	123	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	10	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	30	LF	6	10+ years	
	Roof - Asphalt Shingle	Main Roof	6,182	SF	6	10+ years	
	Roof - Metal	Main Roof	2,000	SF	7	10+ years	

Campus Name: Field Page : 1 of 38 Assessment Date: 07/19/2021



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Hatch - Metal	Main Roof	4	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	8,182	SF	7	10+ years	
Walls							
	Canopy - Metal	Entire Building	30	SF	7	10+ years	
	Cornice - Metal Projecting	Entire Building	222	LF	6	2-5 years	
	Exterior Walls - Brick	Entire Building	6,872	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	30	SF	3	0-1 year	Missing.
	Exterior Walls - Stone-Cast	Entire Building	444	SF	6	10+ years	-
	Exterior Walls - Stone-Cut	Entire Building	1,554	SF	6	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	1,242	SF	7	10+ years	
	Lintels - Brick	Entire Building	138	LF	6	10+ years	
	Lintels - Steel	Entire Building	40	LF	6	10+ years	
	Lintels - Stone	Entire Building	32	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,250	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Emerger</u>	cy System						
	Automatic Transfer Switch	Basement	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	8	EA	7	6-10 years	
	Security System - CCTV	Entire Building	37,830	SF	7	6-10 years	Per building Engineer no issues wit security system.
	Security System - Intrusion Detection	Entire Building	37,830	SF	6	6-10 years	Security System.
	Emergency A/C Power - Corridors and	Entire Building	12,718	SF	6	6-10 years	
	Stairs	Littile Building	12,710	OI .	U	0-10 years	
Main Ser	vice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	Serves the entire school
	PA System	Entire Building	37,830	SF	6	6-10 years	Serves the entire school
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Panel PP2. Broken door hinges.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	2	0-1 year	Older panel, minor rust.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	c.ac. parior, rimior raca
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp	Little building	'		'	TOT years	

Campus Name: Field Page : 2 of 38 Assessment Date: 07/19/2021



Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years	
	amp	3				,	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	
		3				, , , , ,	
atego	ry : Fire Protection		В	uilding	: Main		
alogo				aag		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•		Location	Quantity	OOM	rtariit	Ropidoomon	Commonto
ire Aları				Ε.Δ.		0.40	0 " " 1 1
	Fire Alarm Panel	Basement	1	EA	6	6-10 years	Serves the entire school
	Fire Alarm Strobe Lights	Basement	37,830	SF	6	6-10 years	
	Fire Alarm_System	Basement	37,830	SF	6	6-10 years	
	Fire Pump Controller	Basement	1	EA	6	6-10 years	
ump Ro	oom Assembly						
,	Fire Pump - Less than 25hp	Mechanical Room	1	EA	6	6-10 years	Signs of previous leakage but no
	·					•	current leaks; apparently upgrade
							since last assessment.
prinkler	System						
P	Dry Sprinkler System	Entire Building	37,830	SF	7	6-10 years	
	Sprinkler Heads	Entire Building	37,830	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	37,830	SF	7	6-10 years	
	Optimized 1 iping	Entire Ballating	07,000	0.	•	o ro youro	
			_	uildina	. Main		
Catego	rv : Mechanical		B	ullallia i	. Iviairi		
atego	ry : Mechanical		B	uilding	. wam	Recommend	
		Location					Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
roup	Item - Type lling Systems		Quantity	UOM	Rank	Replacement	Comments
roup	Item - Type ling Systems Air Handling Unit- Package Multi Zone-	Location Fan Room					Comments
roup	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm	Fan Room	Quantity	UOM	Rank 6	Replacement 10+ years	Comments
roup	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake	Fan Room Fan Room	Quantity 1	UOM EA EA	Rank 6 6	Replacement 10+ years 6-10 years	Comments
roup	Item - Type lling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers	Fan Room Fan Room Fan Room	Quantity	EA EA EA	Rank 6 6 6	10+ years 6-10 years 6-10 years	Comments
Group	Item - Type lling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone-	Fan Room Fan Room	Quantity 1	UOM EA EA	Rank 6 6	Replacement 10+ years 6-10 years	Comments
Group	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm	Fan Room Fan Room Fan Room Fan Room	Quantity 1	EA EA EA EA	6 6 6 6	10+ years 6-10 years 6-10 years 10+ years	Comments
Froup	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake	Fan Room Fan Room Fan Room Fan Room Fan Room	Quantity 1 1 18 1 1	EA EA EA EA	6 6 6 6	Replacement 10+ years 6-10 years 6-10 years 10+ years 6-10 years	Comments
Froup	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers	Fan Room	Quantity 1 1 18 1 1 2	EA EA EA EA EA	6 6 6 6 6	Replacement 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years	Comments
Froup	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake	Fan Room Fan Room Fan Room Fan Room Fan Room	Quantity 1 1 18 1 1	EA EA EA EA EA EA	6 6 6 6	Replacement 10+ years 6-10 years 6-10 years 10+ years 6-10 years	Comments
roup	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Zone Dampers	Fan Room	Quantity 1 1 18 1 1 2	EA EA EA EA EA	6 6 6 6 6	10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	
Froup	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers	Fan Room	Quantity 1 1 18 1 1 2 4	EA EA EA EA EA EA	6 6 6 6 6 6	Replacement 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years	
Froup iir Hand	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Zone Dampers Zone Dampers	Fan Room	Quantity 1 1 18 1 1 2 4	EA EA EA EA EA EA	6 6 6 6 6 6	10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Not safely accessible in the attic a
Group Air Hand	Item - Type lling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Zone Dampers Zone Dampers	Fan Room	Quantity 1 1 18 1 1 2 4 14	EA EA EA EA EA EA EA	6 6 6 6 6 6 6	Replacement 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Not safely accessible in the attic a
Group	Item - Type ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 6000-10000 cfm Air Intake Zone Dampers Zone Dampers Zone Dampers	Fan Room	Quantity 1 1 18 1 1 2 4	EA EA EA EA EA EA	6 6 6 6 6 6	10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Not safely accessible in the attic a

Campus Name: Field Page : 3 of 38 Assessment Date: 07/19/2021



Catego	ry : Mechanical		В	uilding	: Main		770 TY TOTAL AT TYPE TO THE CASE, TE COOLE
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Piping - Steam Pipe- Steel	Boilers in Addition 1	500	LF	6	10+ years	
	Steam Traps	Boilers in Addition 1	12	EA	5	6-10 years	
Heating	Devices						
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	4	EA	2	1-2 years	Older units.
	Cabinet Heaters - With Electric Coil	Entire Building	4	EA	6	6-10 years	
_Mechani	cal Plumbing						
	Condensate-Steel or Galvanized	Entire Building	400	LF	5	6-10 years	
_Tempera	ature Control						
•	Electric Thermostat	Entire Building	1	EA	7	6-10 years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Pneumatic System	Entire Building	37,830	SF	5	6-10 years	Served by Addition 2.
	Thermostats - Pneumatic	Entire Building	11	EA	6	6-10 years	
Unit Ven	tilation						
	Unit Ventilators- Ceiling Mounted- Electric Heating & DX Cooling Coil W/ Remote Mounted Compressor	MDF Room (2nd Floor)	1	EA	6	6-10 years	FC-1
_Ventilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Attic, Electrical Room, Basement	1	EA	6	6-10 years	There is one indoor exhaust fan in the basement of this building.

Category: Plumbing Building: Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping	Kem Type	Location	Quantity		rturik	Ropidoomont	
	Domestic Piping-Hot Water Return Lines	Entire Building	37,830	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	37,830	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	37,830	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	37,830	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	37,830	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	37,830	SF	6	6-10 years	
	Sanitary Piping	Entire Building	37,830	SF	6	6-10 years	
	Storm Piping	Entire Building	37,830	SF	6	6-10 years	



Category: Plumbing **Building: Main** Recommend Group Location Quantity UOM Item - Type Rank Replacement Comments Vent Piping **Entire Building** 37,830 6-10 years SF 6 <u>Pumps</u> Pumps - Sump-Simplex EΑ 6 6-10 years Elevator sump pump. Mechanical Room 1

Category : Room **Building** · Main

Catego	ry : Room		Building : Main					
_						Recommend		
Proup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Administ	rative Suites/Offices							
	AC Unit	1st- 116 Counselor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st- 116 Counselor	639	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st- 116 Counselor	1	EA	6	6-10 years		
	Floor - Tile	1st- 116 Counselor	639	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st- 116 Counselor	12	EA	7	6-10 years		
	Power Distribution	1st- 116 Counselor	8	EA	6	6-10 years		
	Walls - Plaster/Drywall	1st- 116 Counselor	1,332	SF	6	10+ years		
	AC Unit	1st- Main Office	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st- Main Office	678	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st- Main Office	2	EA	6	6-10 years		
	Floor - Carpet	1st- Main Office	438	SF	6	6-10 years		
	Floor - Tile	1st- Main Office	240	SF	6	10+ years		
	Lighting - Pendent/Surface	1st- Main Office	11	EA	7	2-5 years		
	Power Distribution	1st- Main Office	12	EA	6	2-5 years		
	Storage/ Closet	1st- Main Office	125	SF	7	6-10 years		
	Walls - Plaster/Drywall	1st- Main Office	1,752	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st- Parent's Room used as Case Manager Office	180	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st- Parent's Room used as Case Manager Office	1	EA	6	6-10 years		
	Floor - Tile	1st- Parent's Room used as Case Manager Office	180	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st- Parent's Room used as Case Manager Office	2	EA	7	6-10 years		
	Power Distribution	1st- Parent's Room used as Case Manager Office	6	EA	6	6-10 years		
	Walls - Plaster/Drywall	1st- Parent's Room used as Case Manager Office	778	SF	6	10+ years		
	AC Unit	1st- Principal	1	EA	7	6-10 years		
	Ceiling - Lay-in	1st- Principal	525	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st- Principal	1	EA	6	6-10 years		
	Doors - Transom Window	1st- Principal	18	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st- Principal	2	EA	6	6-10 years		
	Floor - Carpet	1st- Principal	515	SF	6	6-10 years		
	Floor - Concrete	1st- Principal	10	SF	7	10+ years		



Category : Room		В	uilding	: Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st- Principal	6	EΑ	6	6-10 years	
	Power Distribution	1st- Principal	27	EA	6	6-10 years	
	Walls - Masonry	1st- Principal	11	SF	6	10+ years	
	Walls - Plaster/Drywall	1st- Principal	1,526	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st- Security Office	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st- Security Office	1	EA	6	6-10 years	
	Floor - Concrete	1st- Security Office	35	SF	7	10+ years	
	Lighting - Pendent/Surface	1st- Security Office	1	EA	6	6-10 years	
	Power Distribution	1st- Security Office	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st- Security Office	242	SF	6	10+ years	
	Work SInk	1st- Security Office	1	EA	7	6-10 years	
	AC Unit	2.5 - Assistant Principal	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2.5 - Assistant Principal	288	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2.5 - Assistant Principal	1	EA	6	6-10 years	
	Floor - Tile/Sheet	2.5 - Assistant Principal	288	SF	7	6-10 years	
	Lighting - Pendent/Surface	2.5 - Assistant Principal	4	EA	6	6-10 years	
	Power Distribution	2.5 - Assistant Principal	4	EA	6	6-10 years	
	Storage/ Closet	2.5 - Assistant Principal	2	SF	7	6-10 years	
	Walls - Plaster/Drywall	2.5 - Assistant Principal	714	SF	6	10+ years	
	Work SInk	2.5 - Assistant Principal	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	448	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	448	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Power Distribution	2nd Floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,232	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd- Speech	93	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd- Speech	1	EA	7	6-10 years	
	Floor - Tile	2nd- Speech	93	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd- Speech	1	EA	7	6-10 years	
	Power Distribution	2nd- Speech	4	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd- Speech	366	SF	7	10+ years	
	AC Unit	Basement - Engineer Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Engineer Office	342	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Engineer Office	2	EA	6	6-10 years	
	Floor - Tile	Basement - Engineer Office	342	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement - Engineer Office	6	EA	7	6-10 years	
	Power Distribution	Basement - Engineer Office	6	EA	6	10+ years	
	Storage/ Closet	Basement - Engineer Office	104	SF	7	6-10 years	
	Walls - Plaster/Drywall	Basement - Engineer Office	807	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement- Staff Lounge	372	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement- Staff Lounge	1	EA	7	6-10 years	
	Floor - Concrete	Basement- Staff Lounge	352	SF	7	10+ years	
	Floor - Concrete	Basement- Staff Lounge	20	SF	5	0-1 year	Repaint
					-	,	•



Catego	ry : Room		В	uilding	: Main		713 14 Ashidha Avender, Onicago, ne 00020
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Basement- Staff Lounge	4	EA	7	6-10 years	
	Lighting - Wall Mounted	Basement- Staff Lounge	1	EA	7	6-10 years	
	Power Distribution	Basement- Staff Lounge	8	EA	6	10+ years	
	Walls - Masonry	Basement- Staff Lounge	912	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement- Staff Lounge	50	SF	7	10+ years	
	Work SInk	Basement- Staff Lounge	1	EA	7	6-10 years	
Library							
,	AC Unit	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	60	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,092	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Carpet	2nd Floor	1,092	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,652	SF	7	10+ years	
	walls - Flastel/Diywall	ZIIU FIOOI	1,032	Si	,	10+ years	
_MDF_ID							
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	6-10 years	
	Finishes	2nd Floor	163	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	
_Mechani	cal/ Service Rooms						
	Storage Room	2nd Floor	5	SF	5	10+ years	
	Air Intake Plenums	Basement	140	SF	7	10+ years	
	Air Tunnel	Basement	2,732	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	152	SF	7	10+ years	
	Storage Room	Basement	643	SF	7	10+ years	
	Vaults	Basement	253	SF	7	10+ years	
	Janitor's Closet	Janitor Closet	4	SF	7	10+ years	
_Restroor	n						
	Accessories	1st - inside classroom 104 - used as	49	SF	7	6-10 years	
	0 ''' 51 / /5 ''	storage		6 -	_	4.0	
	Ceiling - Plaster/Drywall	1st - inside classroom 104 - used as storage	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - inside classroom 104 - used as storage	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st - inside classroom 104 - used as	49	SF	6	10+ years	
	Lavatory	storage 1st - inside classroom 104 - used as	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	storage 1st - inside classroom 104 - used as	1	EA	6	6-10 years	
		storage					



Catego	ry : Room		Building : Main				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st - inside classroom 104 - used as	264	SF	6	10+ years	
		storage					
	Walls - Tile Ceramic/ Porcelain	1st - inside classroom 104 - used as	112	SF	6	10+ years	
		storage			_		
	Water Closet	1st - inside classroom 104 - used as	1	EA	6	6-10 years	
		storage	=0	0=	_	0.40	
	Accessories	1st- Inside Main Office	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Inside Main Office	52	SF	6	10+ years	
	Doors - Transom Window	1st- Inside Main Office	7	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st- Inside Main Office	1	EA	6	6-10 years	
	Floor - Tile	1st- Inside Main Office	52	SF	6	6-10 years	
	Lavatory	1st- Inside Main Office	1	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st- Inside Main Office	1	EA	7	6-10 years	
	Partitions	1st- Inside Main Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st- Inside Main Office	333	SF	6	10+ years	
	Water Closet	1st- Inside Main Office	1	EA	6	6-10 years	
	Accessories	1st- Inside Parent's Room	64	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Inside Parent's Room	64	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside Parent's Room	1	EA	6	6-10 years	
	Floor - Tile	1st- Inside Parent's Room	64	SF	6	6-10 years	
	Lavatory	1st- Inside Parent's Room	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st- Inside Parent's Room	1	EA	7	6-10 years	
	Partitions	1st- Inside Parent's Room	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st- Inside Parent's Room	308	SF	6	10+ years	
	Water Closet	1st- Inside Parent's Room	1	EA	3	1-2 years	Does not work.
	Accessories	1st- Inside rm 119	58	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Inside rm 119	58	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside rm 119	1	EA	6	6-10 years	
	Floor - Tile	1st- Inside rm 119	58	SF	4	0-1 year	Separating throughout.
	Lavatory	1st- Inside rm 119	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st- Inside rm 119	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st- Inside rm 119	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st- Inside rm 119	308	SF	6	10+ years	
	Water Closet	1st- Inside rm 119	1	EA	4	0-1 year	Does not work.
	Accessories	Basement - inside Engineers Office	77	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - inside Engineers Office	77	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - inside Engineers Office	1	EA	6	6-10 years	
	Floor - Concrete	Basement - inside Engineers Office	77	SF	7	10+ years	
	Lavatory	Basement - inside Engineers Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement - inside Engineers Office	1	EΑ	7	6-10 years	
	Partitions	Basement - inside Engineers Office	1	EA	7	6-10 years	
	Showers	Basement - inside Engineers Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement - inside Engineers Office	366	SF	7	10+ years	
	Water Closet	Basement - inside Engineers Office	1	EA	7	10+ years	
		9				,	



Catego	ry : Room		В	uilding	: Main		
Croun	Hom. Type	Location	Quantity	HOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	855	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	855	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	17	LF	7	6-10 years	
	Storage/ Closet	1st Floor	124	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,435	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
_Classroo	om #106 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	857	SF	6	10+ years	
	Chalk Board	1st Floor	63	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	1st Floor	857	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	144	LF	7	6-10 years	
	Storage/ Closet	1st Floor	186	SF	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,425	SF	6	10+ years	
	Wireless System	1st Floor	1	ĒΑ	7	6-10 years	
Classroo	om #115 (Other Instructional Use)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	866	SF	6	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	866	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Storage/ Closet	1st Floor	205	SF	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,510	SF	6	10+ years	
Classroo	om #119 (Office)						
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	866	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	866	SF	6	6-10 years	
			300	٥.	ŭ	2 12 7 0 0 10	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	122	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,510	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	882	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Wood	2nd Floor	882	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	204	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,446	SF	7	10+ years	
Classroo	om #206 (Special Education)						
Ciassioc	Ceiling - Lay-in	2nd Floor	858	SF	7	6-10 years	
	Ceiling - Lay-in Ceiling - Lay-in	2nd Floor	8	SF	4	0-10 years 0-1 year	Water demage
	Chalk Board	2nd Floor		SF LF			Water damage.
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	25 1	EA	4 7	2-5 years	
			· · · · · · · · · · · · · · · · · · ·			6-10 years	
	Floor - Wood	2nd Floor	866	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	211	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,284	SF	6	10+ years	
Classroo	om #216 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	700	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	700	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,519	SF	7	10+ years	
Classroo	om #217 (Other Instructional Use)						
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	663	SF	7	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Wood	2nd Floor	663	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,484	SF	7	10+ years	
	Trans Trastor/Drywan	2110 1 1001	1,704	Oi.	,	ioi yeais	

Campus Name: Field Page : 10 of 38 Assessment Date: 07/19/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassro	om #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	866	SF	7	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Floor - Wood	2nd Floor	866	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	26	EΑ	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	267	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,680	SF	7	10+ years	
	vvalis - Flastei/Drywali	2110 11001	1,000	SF	,	10+ years	
assro	om #219 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	866	SF	7	10+ years	
	Chalk Board	2nd Floor	61	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Wood	2nd Floor	866	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	197	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,680	SF	7	10+ years	
	·	2110 1 1001	·			10+ years	
atego	ry : Interior		В	uilding	: Main	D	
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor			•			•	
	Ceiling - Plaster/Drywall	1st Floor	3,492	SF	6	6-10 years	
			,		6	6-10 years	
	Doors - Steel Doors incl hw	1St Floor	4	ĿΑ	U		
	Doors - Steel Doors incl hw Drinking Fountains - Single Fountain	1st Floor 1st Floor		EA EA			
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	6-10 years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor	1st Floor 1st Floor	3 3,318	EA SF	7 7	6-10 years 10+ years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor	3 3,318 286	EA SF SF	7 7 7	6-10 years 10+ years 6-10 years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor	3 3,318 286 1	EA SF SF EA	7 7 7 7	6-10 years 10+ years 6-10 years 6-10 years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3 3,318 286 1 32	EA SF SF EA EA	7 7 7 7 7	6-10 years 10+ years 6-10 years 6-10 years 6-10 years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Stairs - Concrete Stairs	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3 3,318 286 1 32 11	EA SF SF EA EA LF	7 7 7 7 7 6	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall	1st Floor	3 3,318 286 1 32 11 7,174	EA SF SF EA EA LF SF	7 7 7 7 7 6 6	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Walls - Structural Glazed Tile	1st Floor	3 3,318 286 1 32 11 7,174 138	EA SF SF EA EA LF SF SF	7 7 7 7 7 6 6 6	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 10+ years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall	1st Floor 2nd Floor	3 3,318 286 1 32 11 7,174 138 2,991	EA SF SF EA LF SF SF	7 7 7 7 6 6 6 7	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	1st Floor 2nd Floor 2nd Floor	3 3,318 286 1 32 11 7,174 138 2,991	EA SF EA EA LF SF SF EA	7 7 7 7 6 6 6 7	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Wood Doors include hw	1st Floor 2nd Floor 2nd Floor 2nd Floor	3 3,318 286 1 32 11 7,174 138 2,991 5	EA SF EA LF SF SF EA EA	7 7 7 7 6 6 6 7 7	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Asphalt Floor Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	1st Floor 2nd Floor 2nd Floor	3 3,318 286 1 32 11 7,174 138 2,991	EA SF EA EA LF SF SF EA	7 7 7 7 6 6 6 7	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	



Catego	Category : Interior		Building : Main				713 IV ASIIIAIIA AVEIVOE, Officago, IE 00020
Outogo				ananig	. wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	2nd Floor	215	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	29	EΑ	7	6-10 years	
	Stairs - Concrete Stairs	2nd Floor	6	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6,578	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	168	SF	7	10+ years	
	Ceiling - Lay-in	Basement	652	SF	7	6-10 years	
	Ceiling - Lay-in Ceiling - Plaster/Drywall	Basement	5,175	SF	7	6-10 years	
	Doors - Side-lite	Basement	19	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	4	EA	7	-	
			4		7	10+ years	
	Doors - Store Front Doors - Transom Window	Basement	37	EA SF	7	10+ years	
		Basement	7	Sr EA	7 7	10+ years	
	Doors - Wood Doors include hw	Basement				10+ years	
	Drinking Fountains - Double Fountain	Basement	1	EΑ	7	6-10 years	
	Drinking Fountains - Single Fountain	Basement	2	EA	7	6-10 years	
	Floor - Asphalt Floor	Basement	5,477	SF	7	10+ years	
	Floor - Terrazzo	Basement	180	SF	7	10+ years	
	Lighting - Lay-in	Basement	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement	35	EA	7	6-10 years	
	Lighting - Wall Mounted	Basement	1	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement	17	LF	7	10+ years	
	Stairs - Wood	Basement	13	LF	7	10+ years	
	Walls - Concrete Block	Basement	2,131	SF	7	10+ years	
	Walls - Masonry	Basement	2,826	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	3,217	SF	7	10+ years	
Safety							
•	Camera Viewing Station	entire Building	1	EA	7	6-10 years	
	Security Cameras	entire Building	1	ĒΑ	7	6-10 years	
	coodinity camerate	oning Danamig	•		•	0 .0 ,00.0	
Stairs							
	Handrails	North East	34	LF	7	6-10 years	
	Stairs - Asphalt	North East	44	LF	7	10+ years	
	Walls - Plaster/Drywall	North East	1,170	SF	7	6-10 years	
	Walls - Plaster/Drywall	North East	30	SF	4	0-1 year	Water damage.
	Ceiling - Plaster/Drywall	South East	278	SF	7	10+ years	
	Floor - Asphalt	South East	210	SF	7	10+ years	
	Handrails	South East	115	LF	7	6-10 years	
	Lighting - Pendent/Surface	South East	2	EA	7	6-10 years	
	Stairs - Asphalt	South East	44	LF	7	10+ years	
	Walls - Plaster/Drywall	South East	896	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West	80	SF	7	10+ years	
	Floor - Asphalt	West	23	SF	7	10+ years	
	Handrails	West	34	LF	7	6-10 years	
	Tanatallo	***************************************	34	LI	,	o To years	

Campus Name: Field Page: 12 of 38 Assessment Date: 07/19/2021



Catego	ry : Interior	В	Building : Main						
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	West	1	EA	7	6-10 years			
	Stairs - Asphalt	West	23	LF	7	10+ years			
	Walls - Plaster/Drywall	West	224	SF	7	10+ years			

Campus Name: Field Page: 13 of 38 Assessment Date: 07/19/2021



Category : Exterior Building : Addition 1

Exterior Doors - Exterior Steel Door	Categor	y : Exterior		Building : Addition 1 Recommend					
Intrance			1	0 "					
Exterior Doors - Exterior Steel Door #1 N	Group		Location	Quantity	UOM	Rank	Replacement	Comments	
Exterior Stairs - Concrete #10 NE	Entrance								
Exterior Doors - Exterior Steel Door									
Exterior Doors - Transom Lite #10 NE		Exterior Stairs - Concrete		15			0-1 year		
Exterior Stairs - Concrete #10 NE 15		Exterior Doors - Exterior Steel Door	#10 NE	4	EA	5	0-1 year	Damaged and rusting.	
Exterior Doors - Store Front #3 N 10 LF 6 10+ years Exterior Stairs - Concrete #3 N 10 LF 6 10+ years Exterior Doors - Store Front #4 NW 3 EA 7 10+ years Exterior Doors - Transom Lite #4 NW 11 EA 6 10+ years Exterior Doors - Transom Lite #4 NW 10 LF 6 10+ years Exterior Doors - Transom Lite #4 NW 10 LF 6 10+ years Exterior Doors - Transom Lite #6 W 3 EA 6 6-10 years Exterior Doors - Store Front #6 W 3 EA 6 6-10 years Exterior Doors - Store Front #6 W 3 EA 6 6-10 years Exterior Stairs - Concrete #6 W 10 LF 6 6-10 years Exterior Stairs - Concrete #6 W 10 LF 6 6-10 years Exterior Stairs - Concrete #6 W 10 LF 6 6-10 years Exterior Doors - Store Front #8 S Main Accessible Entrance 1 LEA 7 10+ years Exterior Doors - Store Front #8 S Main Accessible Entrance 4 EA 7 10+ years Exterior Doors - Store Front #8 S Main Accessible Entrance 4 EA 7 10+ years Exterior Doors - Exterior Steel Door #9 SE 1 EA 7 10+ years Exterior Doors - Exterior Steel Door #9 SE 1 EA 7 10+ years Exterior Doors - Exterior Steel Door #9 SE 2 EA 7 10+ years Exterior Doors - Exterior Steel Door #9.5 E 2 EA 7 10+ years Exterior Doors - Exterior Steel Door Fire escape door 1 EA 6 6-10 years The Escape East 37 LF 6 6-10 years The Escape Exterior Doors - Exterior Steel Door Exterior Entrance Entire Building 257 SF 7 10+ years Superstructure - Steel Entire Building 257 SF 7 10+ years Superstructure - Steel Entire Building 257 SF 7 10+ years Exterior Doors - Exterior Entrance Entire Building 257 SF 7 10+ years Exterior Lighting - Wall Mounted Entire Building 19 EA 7 10+ years Chirmey - Brick Chirmey- Concrete/ Mortar Addition 1 E Roof 1 EA 5 10+ years Chirmey - Brick Chirmey- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 ERoof 152 LF 6 10+ years		Exterior Doors - Transom Lite	#10 NE		EA	6	6-10 years		
Exterior Stairs - Concrete #3 N		Exterior Stairs - Concrete		15	LF	5	0-1 year	Cracking and chipping.	
Exterior Doors - Store Front				3	EA	7			
Exterior Doors - Transom Lile				10		6	10+ years		
Exterior Stairs - Concrete		Exterior Doors - Store Front	#4 NW	3	EA	7	10+ years		
Exterior Doors - Store Front		Exterior Doors - Transom Lite	#4 NW	1		6	10+ years		
Exterior Doors - Transom Lite		Exterior Stairs - Concrete	#4 NW	10	LF	6	10+ years		
Exterior Stairs - Concrete		Exterior Doors - Store Front	#6 W	3	EA	6	6-10 years		
Entrance Control - Audio and Video		Exterior Doors - Transom Lite		3	EA	6	6-10 years		
Entrance Control - Audio and Video		Exterior Stairs - Concrete	#6 W	10	LF	6	6-10 years		
Exterior Doors - Store Front		Entrance Control - Audio and Video	#8 S Main Accessible Entrance	1	EA	7			
Power Door Operator and Controls				4	EA	7			
Exterior Doors - Exterior Steel Door				2	EA	7			
Exterior Doors - Exterior Steel Door			#9 SE		EA	7			
Exterior Doors - Exterior Steel Door Fire escape door 1 EA 6 6-10 years		Exterior Doors - Exterior Steel Door	#9.5 SE	2	EA	7			
Fire Escape Fire Escape East 37 LF 6 6-10 years Doundation Foundation - Masonry Superstructure - Steel Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch Entire Building Superstructure - Steel with Clay Tile Arch		Exterior Doors - Exterior Steel Door	Fire escape door		EA	6			
Fire Escape East 37 LF 6 6-10 years Dundation Foundation - Masonry Entire Building 257 SF 7 10+ years Superstructure - Steel Entire Building 257 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 19 EA 7 10+ years Oof System Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years			·				•		
Fire Escape East 37 LF 6 6-10 years Dundation Foundation - Masonry Entire Building 1,232 LF 7 10+ years Superstructure - Steel Entire Building 257 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Exterior Lighting - Wall Mounted Entire Building 19 EA 7 10+ years Oof System Access Ladder - Metal Addition 1 E Roof 90 LF 6 10+ years Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years	Fire Esca	pe							
Foundation - Masonry Entire Building 1,232 LF 7 10+ years Superstructure - Steel Entire Building 257 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years ghting Exterior Lighting - Wall Mounted Entire Building 19 EA 7 10+ years oof System Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years			Fast	37	l F	6	6-10 years		
Foundation - Masonry Entire Building 1,232 LF 7 10+ years Superstructure - Steel Entire Building 257 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 19 EA 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 19 EA 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 19 EA 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 19 EA 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 19 EA 7 10+ years Superstructure - Steel with Clay Tile Addition 1 E Roof 90 LF 6 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 25,700 SF 7 10+ years Superstructur		200apo		01		J	J 10 yourd		
Foundation - Masonry Entire Building 1,232 LF 7 10+ years Superstructure - Steel Entire Building 257 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years Exterior Lighting - Wall Mounted Entire Building 19 EA 7 10+ years Oof System Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years	Foundation	an an							
Superstructure - Steel Entire Building 257 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years ghting Exterior Lighting - Wall Mounted Entire Building 19 EA 7 10+ years oof System Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years	roundalle		Entire Duilding	4 000	1.5	7	10		
Superstructure - Steel with Clay Tile Arch Entire Building 23,692 SF 7 10+ years ghting Exterior Lighting - Wall Mounted Entire Building 19 EA 7 10+ years oof System Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years									
ghting Exterior Lighting - Wall Mounted Entire Building 19 EA 7 10+ years oof System Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years									
Exterior Lighting - Wall Mounted Entire Building 19 EA 7 10+ years Oof System Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Metal Flue Downspouts - Exterior Downspouts Roof - Asphalt Shingle Entire Building 19 EA 7 10+ years 10+ years		Superstructure - Steel with Clay Tile Arch	Entire Building	23,692	SF	1	10+ years		
Exterior Lighting - Wall Mounted Entire Building 19 EA 7 10+ years Oof System Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Metal Flue Downspouts - Exterior Downspouts Roof - Asphalt Shingle Entire Building 19 EA 7 10+ years 10+ years									
Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years	Lighting								
Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years		Exterior Lighting - Wall Mounted	Entire Building	19	EA	7	10+ years		
Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years									
Access Ladder - Metal Addition 1 E Roof 1 EA 5 10+ years Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years	Roof Sys	tem							
Chimney - Brick Chimney- Concrete/ Mortar Addition 1 E Roof 90 LF 6 10+ years Liner Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years			Addition 1 E Roof	1	EA	5	10+ years		
Liner Chimney - Metal Flue Addition 1 E Roof Downspouts - Exterior Downspouts Addition 1 E Roof Roof - Asphalt Shingle Addition 1 E Roof Addition 1 E Roof 11,408 F 6 10+ years 11,408 F 6 10+ years					LF				
Chimney - Metal Flue Addition 1 E Roof 35 LF 7 10+ years Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years			 			•	,		
Downspouts - Exterior Downspouts Addition 1 E Roof 123 LF 6 10+ years Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years			Addition 1 E Roof	35	LF	7	10+ vears		
Roof - Asphalt Shingle Addition 1 E Roof 11,408 SF 6 10+ years									
Roof Hatch - Metal Addition 1 E Roof 2 EA 7 10+ years					_				
Roof Structure - Steel with Clay Tile Arch Addition 1 E Roof 15,751 SF 7 10+ years									
10,701 Of 7 101 yours		1.00. Oli dolaro Oloor Willi Olay Tilo Alori	, tasition i E itool	10,701	J1	,	101 yours		
				,		-	- ,		

Campus Name: Field Page : 14 of 38 Assessment Date: 07/19/2021



Catego	ry : Exterior		Building : Addition 1				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	Addition 1 Elevator Roof	1	EA	4	0-1 year	Bolts missing
	Coping - Stone	Addition 1 Elevator Roof	43	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Addition 1 Elevator Roof	38	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Addition 1 Elevator Roof	37	LF	7	10+ years	
	Parapet - Parapet > 30"	Addition 1 Elevator Roof	6	LF	6	10+ years	
	Roof - Modified Bitumen	Addition 1 Elevator Roof	254	SF	6	10+ years	
	Roof Hatch - Metal	Addition 1 Elevator Roof	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Addition 1 Elevator Roof	254	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Addition 1 N Roof	1	EA	7	10+ years	
	Coping - Metal	Addition 1 N Roof	60	LF	5	0-1 year	Corroded.
	Downspouts - Exterior Downspouts	Addition 1 N Roof	164	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Addition 1 N Roof	60	LF	6	10+ years	
	Roof - Asphalt Shingle	Addition 1 N Roof	4,500	SF	6	10+ years	
	Roof - Metal	Addition 1 N Roof	1,080	SF	6	10+ years	
	Roof - Modified Bitumen	Addition 1 N Roof	100	SF	7	10+ years	
	Roof Hatch - Metal	Addition 1 N Roof	2	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Addition 1 N Roof	5.580	SF	7	10+ years	
	Concrete Topping		2,000	-		, , , , , , , , , , , , , , , , , , , ,	
	Access Ladder - Metal	Addition 1 S Roof	1	EA	4	0-1 year	Unscrewed bolt
	Coping - Metal	Addition 1 S Roof	60	LF	4	0-1 year	Flew off
	Downspouts - Exterior Downspouts	Addition 1 S Roof	123	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Addition 1 S Roof	60	LF	6	10+ years	
	Roof - Asphalt Shingle	Addition 1 S Roof	3,450	SF	6	10+ years	
	Roof - Metal	Addition 1 S Roof	1,600	SF	7	10+ years	
	Roof Hatch - Metal	Addition 1 S Roof	2	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Addition 1 S Roof	5,050	SF	7	10+ years	
	ricer chackare clost man chay the ricer	,	3,333	О.	•	. o · you.o	
Walls							
	Canopy - Metal	Entire Building	30	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	16	SF	5	10+ years	
	Cornice - Metal Projecting	Entire Building	947	LF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	33,756	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2,314	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	6,629	SF	6	10+ years	
_Windows		E 0 B 30	255			40	
	Curtain wall - Glazed Double Pane	Entire Building	228	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	96	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	3,529	SF	6	10+ years	
	Lintels - Brick	Entire Building	54	LF · –	6	10+ years	
	Lintels - Steel	Entire Building	349	LF	6	10+ years	
	Lintels - Stone	Entire Building	126	LF	6	10+ years	
	Windows - Casement Steel	Entire Building	234	SF	6	10+ years	

Campus Name: Field Page: 15 of 38 Assessment Date: 07/19/2021



Catego	ry : Exterior		Building : Addition 1						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Windows - Sash Aluminum Double-pane	Entire Building	4,867	SF	6	10+ years			
atego	ry : Electrical		В	uilding	: Additi	on 1			
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
merger	ncy System								
	Emergency Generator- Indoor- Natural Gas - 101 - 150 KW	Basement	1	EA	7	6-10 years	Automatic Transfer Switches are located in Main.		
	UPS - Less than 30 KW	Boiler Room	1	EA	7	6-10 years			
	Exit Signs - Auditoium	Entire Building	5	EA	6	6-10 years			
	Exit Signs - Auditoium	Entire Building	4	EA	6	6-10 years			
	Exit Signs - Corridors and Stairs	Entire Building	6	ĒΑ	6	6-10 years			
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Recommend removing the "Do not		
	LAR Olgrid Cym	Little Ballallig	_		Ü	o to youro	open this door" sign from the Fire Escape door.		
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	·		
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	4	EA	7	6-10 years			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	7	6-10 years			
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	6,332	SF	6	6-10 years			
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,552	SF	6	6-10 years			
	Emergency A/C Power - Gym	Entire Building	3,433	SF	6	6-10 years			
	Emergency A/C Power - Lunchrooms	Entire Building	1,275	SF	6	6-10 years			
	Emergency A/C Power - Students Toilets	Entire Building	1,150	SF	6	6-10 years			
Main Se	rvice								
	PA System	Entire Building	49,713	SF	6	6-10 years	Served by Main		
Power D	istribution								
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	6-10 years			
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	6-10 years			
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years			
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	2	0-1 year	Older panel, minor rust.		
		-	_			_			
Jatego	ry : Fire Protection		В	uilding	: Additi				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
•	, i	Location	Qualitity	OCIVI	Naiik	Replacement	Comments		
Fire Alar		Fadas Duildi	40.710			0.40			
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	49,713 49,713	SF SF	6 6	6-10 years 6-10 years			
ampus I	Name: Field		Page: 16 of 38				Assessment Date: 07/19/		

Campus Name: Field Page : 16 of 38 Assessment Date: 07/19/2021



Catego	Category : Fire Protection		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Mechanical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Conc							
	Condensing Unit- Roof Mounted - Less than 5 tons	Elevator Roof	1	EA	6	6-10 years	Estimated installation 2015
Boiler S	ystems						
·	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	5	2-5 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	Upgraded since last assessment.
	Feed Water Pumps and Tank	Boiler Room	1	EA	7	10+ years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	6	2-5 years	Boilers are dated but well-maintained. No leaks, fully operational, passed boiler inspection.
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	6-10 years	•
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	6-10 years	
	Steam Traps	Boiler Room	48	EA	5	6-10 years	
Gas Boo	oster						
	Gas Booster	Mechanical Room	1	EA	6	6-10 years	
Heating	Devices						
	Unit Heater - Gas	Entire Building	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	9	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	1	EA	2	0-1 year	Older unit.
	Radiators - Steam	Gym	1	EA	6	10+ years	
	Wall Heater - Electric	Principal Office	2	EA	6	6-10 years	
	Radiators - Steam	Principal Office	1	EA	6	10+ years	
_Tempera	ature Control						
	Pneumatic System	Entire Building	49,713	SF	5	6-10 years	Served by Addition 2
	Thermostats - Pneumatic	Entire Building	18	EA	6	6-10 years	
_Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Attic	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Attic	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Attic	2	EA	6	6-10 years	



Catego	Category : Plumbing				Building : Addition 1				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Hot Wate	er								
	Gas Heater - 150000 - 300000 BTU/HR	Basement	1	EA	7	6-10 years	Installed 2017.		
_Piping									
. •	Domestic Piping-Hot Water Return Lines	Entire Building	49,713	SF	6	10+ years			
	Domestic Piping-Hot Water Return Risers	Entire Building	49,713	SF	6	10+ years			
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	49,713	SF	6	10+ years			
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	49,713	SF	6	10+ years			
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	49,713	SF	6	10+ years			
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	49,713	SF	6	10+ years			
	Sanitary Piping	Entire Building	49,713	SF	6	10+ years			
	Storm Piping	Entire Building	49,713	SF	6	10+ years			
	Vent Piping	Entire Building	49,713	SF	6	10+ years			
Pumps									
	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	6	6-10 years			
	Pumps - Sump-Simplex	Boiler Room	1	EA	5	6-10 years	Elevator pit pump.		

Category : Room **Building: Addition 1**

	·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Plaster/Drywall	Basement - 501 P.T.A. Room	772	SF	6	10+ years	Paint cracking and peeling really bad throughout.
	Doors - Wood Doors inclu hw	Basement - 501 P.T.A. Room	2	EA	6	6-10 years	
	Floor - Tile	Basement - 501 P.T.A. Room	772	SF	7	6-10 years	
	Lighting - Pendent/Surface	Basement - 501 P.T.A. Room	21	EA	7	6-10 years	
	Storage/ Closet	Basement - 501 P.T.A. Room	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - 501 P.T.A. Room	897	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - 507 Music Office	725	SF	7	10+ years	
	Doors - Transom Window	Basement - 507 Music Office	7	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Basement - 507 Music Office	2	EA	7	6-10 years	
	Floor - Wood	Basement - 507 Music Office	725	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - 507 Music Office	15	EA	7	6-10 years	
	Storage/ Closet	Basement - 507 Music Office	142	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - 507 Music Office	1,037	SF	6	10+ years	
_Auditori	um & Theater						
	Balcony Seating	Basement	6	EA	7	6-10 years	

Campus Name: Field Page : 18 of 38 Assessment Date: 07/19/2021



Catego	ategory : Room		В	uilding	: Additi	on 1	· ·
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Balcony Seating	Basement	90	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	6,332	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	9	EA	6	6-10 years	
	Floor - Concrete	Basement	687	SF	7	10+ years	
	Floor - Tile	Basement	4,736	SF	7	6-10 years	
	Floor - Tile	Basement	8	SF	4	0-1 year	Chipping.
	Floor - Wood	Basement	900	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	22	EA	7	6-10 years	
	Lighting - Wall Mounted	Basement	14	EA	7	6-10 years	
	Main Floor Seating	Basement	1,000	EA	7	10+ years	
	Sound System	Basement	1	EA	7	6-10 years	
	Stage	Basement	723	SF	7	6-10 years	
	Stage Curtain	Basement	10	EA	7	6-10 years	
	Stage Lift	Basement	1	EA	7	6-10 years	
	Stage Lighting System	Basement	1	EA	7	6-10 years	
	Stage-Stairs - Tile	Basement	11	LF	6	6-10 years	
	Stairs - Asphalt	Basement	21	LF	6	10+ years	
	Storage/ Closet	Basement	114	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	15,137	SF	7	10+ years	
_Gymnas							
	Ceiling - Plaster/Drywall	1st Floor	3,233	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	200	SF	4	0-1 year	Water damage.
	Doors - Transom Window	1st Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Wood	1st Floor	3,433	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	30	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,853	SF	6	10+ years	
Kitchen							
THEH	Ceiling - Lay-in	Basement	567	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	6-10 years	
	Floor - Tile	Basement	567	SF	7	6-10 years	
	Lighting - Lay-in	Basement	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement	793	SF	7	10+ years	
		2000	700	٥.	•	. c . y care	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	Basement	1,275	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	6-10 years	
	Floor - Tile	Basement	1,275	SF	7	6-10 years	

Campus Name: Field Page: 19 of 38 Assessment Date: 07/19/2021



Catego	Category : Room		Building : Addition 1				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Basement	10	EA	7	6-10 years	
	Serving Line	Basement	25	LF	7	6-10 years	
	Walls - Metal Panel	Basement	261	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,192	SF	7	10+ years	
_Mechan	cal/ Service Rooms						
	Janitor's Closet	1st Floor	13	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	36	SF	5	10+ years	
	Auditorium Plenums	Basement	723	SF	7	10+ years	
	Boiler Room	Basement	1,485	SF	7	10+ years	
	Coal Room	Basement	438	SF	5	10+ years	
	Janitor's Closet	Basement	17	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	460	SF	7	10+ years	
	Storage Room	Basement	163	SF	7	10+ years	
Restroo	n						
	Accessories	1st - Boys Bath	226	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Boys Bath	226	SF	6	10+ years	
	Doors - Transom Window	1st - Boys Bath	21	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st - Boys Bath	1	ĒΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st - Boys Bath	226	SF	6	10+ years	
	Floor Drain	1st - Boys Bath	1	EA	7	2-5 years	
	Hand Dryer	1st - Boys Bath	2	ĒΑ	7	6-10 years	
	Lavatory	1st - Boys Bath	3	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st - Boys Bath	2	EΑ	7	6-10 years	
	Partitions	1st - Boys Bath	2	EΑ	7	6-10 years	
	Urinals	1st - Boys Bath	3	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st - Boys Bath	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st - Boys Bath	402	SF	6	10+ years	
	Water Closet	1st - Boys Bath	2	EA	6	6-10 years	
	Accessories	1st - Girls Bath	210	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st - Girls Bath	210	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - Girls Bath	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st - Girls Bath	210	SF	6	10+ years	
	Floor Drain	1st - Girls Bath	1	EA	7	10+ years	
	Hand Dryer	1st - Girls Bath	2	EA	5		
			3	EA	5 6	6-10 years	
	Lavatory	1st - Girls Bath				6-10 years	
	Lighting - Pendent/Surface	1st - Girls Bath	2	EΑ	7	6-10 years	
	Partitions	1st - Girls Bath	5	EA	5	6-10 years	
	Walls - Plaster/Drywall	1st - Girls Bath	406	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st - Girls Bath	406	SF	6	10+ years	
	Water Closet	1st - Girls Bath	5	EA	6	6-10 years	
	Accessories	1st- Women's Staff	133	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st- Women's Staff	133	SF	6	6-10 years	

Campus Name: Field Page : 20 of 38 Assessment Date: 07/19/2021



Catego	ry : Room		Building : Addition 1					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	1st- Women's Staff	12	SF	5	6-10 years		
	Doors - Wood Doors inclu hw	1st- Women's Staff	2	EA	6	6-10 years		
	Floor - Tile/Sheet	1st- Women's Staff	133	SF	5	6-10 years		
	Hand Dryer	1st- Women's Staff	1	EA	5	6-10 years		
	Lavatory	1st- Women's Staff	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	1st- Women's Staff	1	EA	7	6-10 years		
	Lighting - Wall Mounted	1st- Women's Staff	1	EA	7	6-10 years		
	Partitions	1st- Women's Staff	2	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st- Women's Staff	556	SF	6	10+ years		
	Water Closet	1st- Women's Staff	2	EA	6	6-10 years		
	Accessories	2nd - Boy's Bath	226	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd - Boy's Bath	226	SF	7	10+ years		
	Doors - Transom Window	2nd - Boy's Bath	21	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd - Boy's Bath	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd - Boy's Bath	226	SF	7	6-10 years		
	Floor Drain	2nd - Boy's Bath	1	EA	7	10+ years		
	Hand Dryer	2nd - Boy's Bath	2	EA	7	6-10 years		
	Lavatory	2nd - Boy's Bath	3	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd - Boy's Bath	2	EA	7	6-10 years		
	Partitions	2nd - Boy's Bath	2	EA	7	6-10 years		
	Urinals	2nd - Boy's Bath	3	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd - Boy's Bath	418	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd - Boy's Bath	402	SF	6	10+ years		
	Water Closet	2nd - Boy's Bath	2	EA	7	6-10 years		
	Accessories	2nd - Girls Bath	212	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd - Girls Bath	212	SF	7	10+ years		
	Doors - Transom Window	2nd - Girls Bath	16	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd - Girls Bath	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd - Girls Bath	212	SF	7	10+ years		
	Floor Drain	2nd - Girls Bath	1	EA	7	10+ years		
	Hand Dryer	2nd - Girls Bath	2	EA	7	6-10 years		
	Lavatory	2nd - Girls Bath	3	EΑ	7	10+ years	D 1 " " 1	
	Lighting - Pendent/Surface	2nd - Girls Bath	2	EA	6	6-10 years	Re lamp one fixture	
	Partitions	2nd - Girls Bath	5	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd - Girls Bath	402	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd - Girls Bath	404	SF	6	10+ years		
	Water Closet	2nd - Girls Bath	5	EA	7	6-10 years		
	Accessories	2nd- Teacher's Toilet	133	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd- Teacher's Toilet	133	SF	7	10+ years		
	Doors - Transom Window	2nd- Teacher's Toilet	12	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd- Teacher's Toilet	1	EΑ	7	10+ years		
	Doors - Wood Doors inclu hw	2nd- Teacher's Toilet	1	EA	7	6-10 years		
	Floor - Tile	2nd- Teacher's Toilet	133	SF	7	6-10 years		
	Hand Dryer	2nd- Teacher's Toilet	1	EA	7	6-10 years		

Campus Name: Field Page : 21 of 38 Assessment Date: 07/19/2021



Category : Room			Building : Addition 1					
					Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lavatory	2nd- Teacher's Toilet	1	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd- Teacher's Toilet	2	EA	7	6-10 years		
	Lighting - Wall Mounted	2nd- Teacher's Toilet	1	EA	7	6-10 years		
	Partitions	2nd- Teacher's Toilet	2	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd- Teacher's Toilet	556	SF	7	10+ years		
	Water Closet	2nd- Teacher's Toilet	2	EA	7	6-10 years		
	Accessories	Basement - Girls Bath	211	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement - Girls Bath	211	SF	7	10+ years		
	Doors - Transom Window	Basement - Girls Bath	11	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	Basement - Girls Bath	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Basement - Girls Bath	211	SF	7	10+ years		
	Floor Drain	Basement - Girls Bath	1	EA	7	10+ years		
	Hand Dryer	Basement - Girls Bath	2	EA	7	6-10 years		
	Lavatory	Basement - Girls Bath	3	EA	7	6-10 years		
	Lighting - Pendent/Surface	Basement - Girls Bath	2	EA	7	6-10 years		
	Partitions	Basement - Girls Bath	5	EA	7	6-10 years		
	Walls - Plaster/Drywall	Basement - Girls Bath	228	SF	7	10+ years		
	Walls - Structural Glazed Tile	Basement - Girls Bath	408	SF	6	10+ years		
	Water Closet	Basement - Girls Bath	5	EΑ	7	6-10 years		
	Accessories	Basement boys	225	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement boys	225	SF	7	10+ years		
	Doors - Transom Window	Basement boys	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement boys	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Basement boys	225	SF	7	10+ years		
	Floor Drain	Basement boys	1	EA	7	10+ years		
	Hand Dryer	Basement boys	2	EA	7	6-10 years		
	Lavatory	Basement boys	3	EA	7	10+ years		
	Lighting - Pendent/Surface	Basement boys	2	EA	7	6-10 years		
	Partitions	Basement boys	2	EA	7	6-10 years		
	Urinals		3	EA	7	<u>-</u>		
	Walls - Plaster/Drywall	Basement boys Basement boys	200	SF	7	10+ years 10+ years		
	Walls - Structural Glazed Tile	Basement boys	300	SF	7	,		
				Sr EA	7	10+ years		
	Water Closet	Basement boys	2			10+ years		
	Accessories	Basement- Men's Staff	133 133	SF SF	7 7	6-10 years		
	Ceiling - Plaster/Drywall	Basement- Men's Staff				10+ years		
	Doors - Transom Window	Basement- Men's Staff	7	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	Basement- Men's Staff	2	EA	7	6-10 years		
	Floor - Tile	Basement- Men's Staff	133	SF	4	0-1 year	Separating and buckling throughout	
	Hand Dryer	Basement- Men's Staff	1	EΑ	7	6-10 years		
	Lavatory	Basement- Men's Staff	1	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	Basement- Men's Staff	2	EA	7	6-10 years		
	Lighting - Wall Mounted	Basement- Men's Staff	1	EA	7	6-10 years		
	Urinals	Basement- Men's Staff	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	Basement- Men's Staff	553	SF	6	10+ years	Paint peeling.	

Campus Name: Field Page : 22 of 38 Assessment Date: 07/19/2021



	Schools						19 N Ashland AVENUE, Chicago, IL 60626
Catego	ry : Room	В	uilding	: Additi			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	Basement- Men's Staff	1	EA	7	6-10 years	
			_				
Catego	ry : Classroom		В	uilding	: Additi		
Group	Itom Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity	UOIVI	Kalik	Replacement	Comments
_Classroo	om #101 (Regular Classroom)	=				0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	802	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	802	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	52	SF	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,383	SF	6	10+ years	
Classroo	om #102 (Regular Classroom)						
<u> </u>	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	799	SF	6	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	13	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	799	SF	6	•	
		1st Floor		EA	7	6-10 years 6-10 years	
	Lighting - Pendent/Surface		12 30	LF	7	•	
	Marker Board	1st Floor		SF		6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,421	5F	6	10+ years	
_Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	799	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	1st Floor	799	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	1	EA	5	6-10 years	
	Marker Board	1st Floor	39	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,421	SF	6	10+ years	
Classro	om #107 (Regular Classroom)						
_Cia55100	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	1st Floor	798	SF	6	10+ years	
	Cenning - Flaster/Drywall	151 F1001	190	ЗF	O	TOT years	



Category : Classroom			В	Building : Addition 1					
						Recommend			
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Chalk Board	1st Floor	6	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years			
	Floor - Wood	1st Floor	798	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Marker Board	1st Floor	15	LF	7	6-10 years			
,	Walls - Plaster/Drywall	1st Floor	1,391	SF	6	10+ years			
Classroom	n #113 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	1st Floor	799	SF	6	6-10 years			
	Chalk Board	1st Floor	8	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years			
	Floor - Wood	1st Floor	799	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years			
	Marker Board	1st Floor	12	LF	7				
		1st Floor		SF	6	6-10 years			
	Walls - Plaster/Drywall	151 11001	1,121	SF	0	10+ years			
	n #114 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	1st Floor	799	SF	6	6-10 years			
	Chalk Board	1st Floor	6	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years			
	Floor - Tile	1st Floor	799	SF	6	6-10 years			
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years			
	Marker Board	1st Floor	24	LF	6	6-10 years			
,	Walls - Plaster/Drywall	1st Floor	1,405	SF	6	10+ years			
,	Walls - Plaster/Drywall	1st Floor	16	SF	4	1-2 years	Water damage.		
Classroom	n #201 (Office)								
	Casework	2nd Floor	9	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	802	SF	7	10+ years			
	Chalk Board	2nd Floor	67	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	6-10 years			
	Floor - Wood	2nd Floor	802	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Storage/ Closet	2nd Floor	52	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,385	SF	7	10+ years			
	·		,			•			
Classroom	n #202 (Regular Classroom)								

Campus Name: Field Page : 24 of 38 Assessment Date: 07/19/2021



Catego	ry : Classroom		В	Building : Addition 1					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	9	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	799	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years			
	Floor - Wood	2nd Floor	799	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years			
	Marker Board	2nd Floor	42	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	57	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,610	SF	7	10+ years			
Classrae	om #203 (Regular Classroom)								
<u> Ulassi UC</u>	, ,	2nd Floor	-	Г^		6.10			
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	9	LF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	799	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years			
	Floor - Wood	2nd Floor	799	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	42	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	57	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,610	SF	7	10+ years			
Classroo	om #207 (Regular Classroom)								
	Casework	2nd Floor	10	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	804	SF	7	10+ years			
	Chalk Board	2nd Floor	20	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years			
				SF	7				
	Floor - Wood	2nd Floor	804		=	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	14	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,380	SF	7	10+ years			
Classroc	om #213 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	9	LF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	799	SF	7	10+ years			
	Chalk Board	2nd Floor	15	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years			
	Floor - Wood	2nd Floor	799	SF	7	10+ years			
	1 1001 - VV00U	2110 1 1001	799	Ji	,	TOT years			

Campus Name: Field Page : 25 of 38 Assessment Date: 07/19/2021



Catego	Category : Classroom			Building : Addition 1					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years			
	Marker Board	2nd Floor	20	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	60	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,421	SF	7	10+ years			
Classroo	om #214 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	9	LF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	763	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	35	SF	5	0-1 year	Water damage.		
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years	3		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	6-10 years			
	Floor - Wood	2nd Floor	799	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years			
	Marker Board	2nd Floor	40	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	60	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,605	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	0-1 year	Water damage.		
	om #504 (Art Room) Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw	Basement Basement Basement Basement Basement	15 852 10 12 2	LF SF LF SF EA	6 7 4 7 7	6-10 years 10+ years 2-5 years 6-10 years 6-10 years			
	Floor - Wood	Basement	852	SF	7	10+ years			
	Instructional Surface	Basement	16	LF	7	10+ years			
	Lighting - Pendent/Surface	Basement	18	ĒΑ	7	6-10 years			
	Storage/ Closet	Basement	119	SF	7	10+ years			
	Walls - Plaster/Drywall	Basement	1,116	SF	7	10+ years			
	Work Sink	Basement	1	ĒΑ	7	6-10 years			
Classroo	om #513 (Music Room)								
	AC Units	Basement	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement	1,310	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement	2	ĒΑ	7	6-10 years			
	Floor - Wood	Basement	1,310	SF	7	10+ years			
	Lighting - Pendent/Surface	Basement	8	ĒΑ	7	6-10 years			
	Marker Board	Basement	26	LF	7	6-10 years			
	Storage/ Closet	Basement	284	SF	7	10+ years			
	Walls - Masonry	Basement	1,623	SF	7	10+ years			
	Work Sink	Basement	1	EΑ	7	6-10 years			
	Work Onk	Buomont	1	_/ \	,	o io youis			



Category : Interior			В	Building : Addition 1					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Plaster/Drywall	1st Floor	1,119	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	8	EA	6	6-10 years			
	Floor - Asphalt Floor	1st Floor	1,119	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	2,355	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	2,051	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	4	EA	7	10+ years			
	Floor - Asphalt Floor	2nd Floor	2,051	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	2,162	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Basement	1,893	SF	7	10+ years			
	Doors - Side-lite	Basement	36	SF	7	10+ years			
	Doors - Steel Doors incl hw	Basement	8	EA	7	10+ years			
	Doors - Transom Window	Basement	70	SF	7	10+ years			
	Doors - Wood Doors include hw	Basement	9	EA	7	10+ years			
	Floor - Asphalt Floor	Basement	1,893	SF	7	10+ years			
	Lighting - Pendent/Surface	Basement	22	EA	7	6-10 years			
	Lighting - Wall Mounted	Basement	2	EA	7	6-10 years			
	Stairs - Concrete Stairs	Basement	26	LF	7	10+ years			
	Walls - Concrete Block	Basement	97	SF	7	10+ years			
	Walls - Masonry	Basement	2,862	SF	7	10+ years			
	Walls - Plaster/Drywall	Basement	946	SF	6	10+ years			
Stairs									
Otalis	Floor - Asphalt	North	27	SF	7	10+ years			
	Handrails	North	78	LF	7	10+ years			
	Stairs - Asphalt	North	39	LF	7	10+ years			
	Walls - Plaster/Drywall	North	434	SF	7	10+ years			
	Ceiling - Plaster/Drywall	North West	298	SF	7	10+ years			
	Floor - Asphalt	North West	88	SF	7	10+ years			
	Handrails	North West	100	LF	7	10+ years			
	Lighting - Pendent/Surface	North West	2	EA	7	6-10 years			
	Stairs - Asphalt	North West	44	LF	7	10+ years			
	Walls - Plaster/Drywall	North West	1,512	SF	7	10+ years			
	Ceiling - Plaster/Drywall	South West	298	SF	7	10+ years			
	Floor - Asphalt	South West	88	SF	7	10+ years			
	Handrails	South West	100	LF	7	10+ years			
	Lighting - Pendent/Surface	South West	2	EA	7	6-10 years			
	Stairs - Asphalt	South West	44	LF	7	10+ years			
	Walls - Plaster/Drywall	South West	1,512	SF	7	10+ years			
_Vertical (Conveyance								

Campus Name: Field Page : 27 of 38 Assessment Date: 07/19/2021



Building: Addition 1 Category : Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	
	Wheelchair Lift - Platform Lift	1st Floor	1	EA	7	6-10 years	

Campus Name: Field Page : 28 of 38 Assessment Date: 07/19/2021



Category : Exterior			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Exterior Doors - Store Front	#7 S	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#7 S	3	EA	6	6-10 years	
	Exterior Stairs - Stone	#7 S	30	LF	6	6-10 years	
_Foundati	on						
Odridat	Foundation - Concrete	Entire Building	315	LF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	13,260	SF	7	10+ years	
	Caparon actars Coor man cray the first	Zimio Bananig	10,200	O.	•	.o. youro	
_Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	7	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Addition 2 Main Roof	1	EA	7	10+ years	
	Coping - Metal	Addition 2 Main Roof	200	LF	5	10+ years	
	Downspouts - Interior Downspouts	Addition 2 Main Roof	164	LF	6	10+ years	
	Roof - Asphalt Shingle	Addition 2 Main Roof	5,123	SF	7	10+ years	
	Roof - Modified Bitumen	Addition 2 Main Roof	1,507	SF	6	6-10 years	
	Roof Hatch - Metal	Addition 2 Main Roof	1	EΑ	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Addition 2 Main Roof	6,630	SF	7	10+ years	
Walls							
	Cheek-Wall - Stone	Entire Building	12	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	215	LF	5	10+ years	
	Exterior Walls - Brick	Entire Building	6,455	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	2,016	SF	5	10+ years	
_Windows							
	Guard - Guards perforated	Entire Building	1,248	SF	6	6-10 years	
	Lintels - Brick	Entire Building	12	LF	6	10+ years	
	Lintels - Stone	Entire Building	40	LF	6	10+ years	
	Windows - Casement Steel	Entire Building	312	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,048	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Additi	on 2	
				_		Recommend	
Group	7 1	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	Lighting dimmed.
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	7	6-10 years	

Campus Name: Field Page : 29 of 38 Assessment Date: 07/19/2021



Category : Electrical			В	uilding	: Additi	on 2	
						Recommend	•
Group	Item - Type Emergency A/C Power - Corridors and	Location Entire Building	Quantity 2,709	UOM SF	Rank 6	Replacement 6-10 years	Comments
	Stairs	Entire Building	2,709	SF	6	6-10 years	
	Stano						
Main Se	rvice						
	PA System	Entire Building	16,875	SF	6	6-10 years	Served by Main
	·	· ·				•	•
_Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
•	E. B. ()		_		A 1 1141	•	
Catego	ry : Fire Protection		В	uilding	: Additi	on 2 Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar		Location	Quantity	OOM	IXAIIK	Replacement	Comments
_ I II C Alai	Fire Alarm Strobe Lights	Entire Building	16,875	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	16,875	SF	6	6-10 years	
	_ ,	3	•			,	
Catego	ry : Mechanical		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Hand	Iling Systems					0.40	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Basement	1	EA	5	6-10 years	
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Basement	1	EA	5	1-2 years	Filter media old and appears loaded.
						,	Motor is aged. Bypass dampers
							corroded. Fan and coil corroded and
	Datum Durt Warls Manager and Durts	Danamant	40	. –	_	0.40	old.
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	40	LF	5	6-10 years	
	Zone Dampers	Basement	16	EA	5	2-5 years	
						,	
_Heating	Devices						
·	Wall Heater - Electric	1st Floor	2	EA	6	6-10 years	
	Cabinet Heaters - With Electric Coil	Entire Building	1	EA	7	6-10 years	Installed 2008
_Tempera	ature Control	F (1 D 11)	10.0==			0.10	0 " " ' '
	Pneumatic System Thermostats - Pneumatic	Entire Building	16,875	SF EA	6 6	6-10 years	Serves the entire school
	memiosiais - Pheumatic	Entire Building	11	EA	О	6-10 years	



Eugene Field Elementary School

XP.	Schools		7019 N Ashland AVENUE, Chicago, IL 60626						
Catego	ry : Plumbing		В	uilding	: Addition	on 2			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Piping									
	Storm Piping	Entire Building	16,875	SF	6	10+ years			
•	_		_		A 1 1141	•			
Catego	ry : Room		В	uilding	: Addition				
Craun	Hom Type	Logotion	Ouantitu	ПОМ	Donk	Recommend	Comments		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Administ	rative Suites/Offices								
	Ceiling - Plaster/Drywall	1st - 108 Office	259	SF	6	10+ years			
	Doors - Transom Window	1st - 108 Office	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st - 108 Office	1	EA	6	6-10 years			
	Floor - Tile	1st - 108 Office	259	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st - 108 Office	4	EA	7	6-10 years			
	Power Distribution	1st - 108 Office	6	EA	6	6-10 years			
	Storage/ Closet	1st - 108 Office	9	SF	5	6-10 years			
	Walls - Plaster/Drywall	1st - 108 Office	888	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd - 208 Faculty Office	260	SF	7	10+ years			
	Doors - Transom Window	2nd - 208 Faculty Office	9	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd - 208 Faculty Office	1	EA	7	6-10 years			
	Floor - Wood	2nd - 208 Faculty Office	260	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd - 208 Faculty Office	3	EΑ	7	6-10 years			
	Power Distribution	2nd - 208 Faculty Office	8	EΑ	7	6-10 years			
	Storage/ Closet	2nd - 208 Faculty Office	9	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd - 208 Faculty Office	918	SF	6	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Plaster/Drywall	Basement	1,720	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement	4	ĒΑ	7	6-10 years			
	Floor - Tile	Basement	1,720	SF	7	6-10 years			
	Lighting - Pendent/Surface	Basement	24	ĒΑ	7	6-10 years			
	Serving Line	Basement	18	LF	7	6-10 years			
	Walls - Concrete Block	Basement	116	SF	7	10+ years			
	Walls - Masonry	Basement	2,534	SF	7	10+ years			
Mechani	cal/ Service Rooms								
	Mechanical/ Service Rooms	Basement	417	SF	7	10+ years			
Catego	ry : Classroom		В	uildina	: Additio	on 2			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
_	om #109 (Regular Classroom)								
	Casework	1st Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	754	SF	6	10+ years			
	Coming Tidotof/Drywan	1301 1001	754	O.	J	ioi youis			



Catego	Category : Classroom			uilding	: Additi	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	6-10 years	
	Floor - Wood	1st Floor	754	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	43	LF	7	6-10 years	
	Storage/ Closet	1st Floor	48	SF	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,369	SF	6	10+ years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	756	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	756	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	21	LF	7	6-10 years	
	Storage/ Closet	1st Floor	48	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,371	SF	6	10+ years	
	Walls - Flastel/Drywall	ist Floor	1,371	SF	O	10+ years	
Classroo	om #111 (Office)						
	Casework	1st Floor	7	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	755	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	1st Floor	755	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	27	LF	7	6-10 years	
	Storage/ Closet	1st Floor	56	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,421	SF	6	10+ years	
Classroo	om #112 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	755	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood Bools ilicid flw	1st Floor	755	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor 1st Floor	44 1,421	SF	6	•	
	vvalis - Flastei/DryWall	151 F1001	1,421	SF	О	10+ years	
Classroo	om #209 (Regular Classroom)						
	-						

Campus Name: Field Page : 32 of 38 Assessment Date: 07/19/2021



Catego	ry : Classroom	Building : Addition 2					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	7	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	754	SF	7	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	1	SF	7	6-10 years	
	Floor - Wood	2nd Floor	754	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	42	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,402	SF	7	10+ years	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	753	SF	7	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Wood Books inclu hw	2nd Floor	753	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7		
	Storage/ Closet	2nd Floor 2nd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,392	SF	7	10+ years	
	vvalis - Flaster/Drywali	2110 F1001	1,392	SF	,	10+ years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	755	SF	7	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	6-10 years	
	Floor - Wood	2nd Floor	755	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,422	SF	7	10+ years	
Classroo	om #212 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	755	SF	7	10+ years	
	Chalk Board	2nd Floor	44	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	POOLS - MADOR POOLS HIGH HM	ZHU FIUUI	1	ĽA	1	o- io yeais	

Campus Name: Field Page : 33 of 38 Assessment Date: 07/19/2021



Category : Classroom			В	uilding			
_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	755	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,421	SF	7	10+ years	
Classroc	om #510 (Science Classroom)						
	Casework	Basement	38	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement	1,095	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	6-10 years	
	Floor - Tile	Basement	1,085	SF	7	6-10 years	
	Floor - Tile	Basement	10	SF	4	0-1 year	Cracking and chipping.
	Lighting - Pendent/Surface	Basement	27	EA	7	6-10 years	Half of the lights are not working
	Marker Board	Basement	16	LF	7	6-10 years	
	Storage/ Closet	Basement	130	SF	7	6-10 years	
	Walls - Masonry	Basement	1,309	SF	7	10+ years	
	Work Sink	Basement	2	EA	7	6-10 years	

Category: Interior Building: Addition 2

						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	784	SF	6	10+ years	
	Doors - Side-lite	1st Floor	26	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	37	SF	6	6-10 years	
	Doors - Wood Doors include hw	1st Floor	2	EA	6	6-10 years	
	Floor - Asphalt Floor	1st Floor	784	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,715	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	843	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	26	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	37	SF	7	6-10 years	
	Doors - Wood Doors include hw	2nd Floor	2	EΑ	7	6-10 years	
	Floor - Asphalt Floor	2nd Floor	843	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,607	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	937	SF	7	10+ years	
	Doors - Transom Window	Basement	27	SF	7	6-10 years	
	Doors - Wood Doors include hw	Basement	5	EA	7	6-10 years	
	Floor - Asphalt Floor	Basement	937	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	7	EΑ	7	6-10 years	
	Lighting - Wall Mounted	Basement	1	EA	7	6-10 years	
	Stairs - Terrazzo	Basement	6	LF	7	10+ years	
	Student Lockers - One Tier	Basement	40	EA	7	10+ years	
	Walls - Masonry	Basement	1,469	SF	7	10+ years	

Campus Name: Field Page : 34 of 38 Assessment Date: 07/19/2021



Catego	ry : Interior		Building : Addition 2							
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Plaster/Drywall	Basement	420	SF	7	10+ years				
Stairs										
	Ceiling - Plaster/Drywall	South	288	SF	7	10+ years				
	Floor - Terrazzo	South	145	SF	7	10+ years				
	Handrails	South	145	LF	7	6-10 years				
	Lighting - Pendent/Surface	South	2	EΑ	7	6-10 years				
	Stairs - Terrazzo	South	40	LF	7	10+ years				
	Walls - Plaster/Drywall	South	1,544	SF	7	10+ years				

Campus Name: Field Page : 35 of 38 Assessment Date: 07/19/2021



Category : Site Building : Site

Catego	ry : Site		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
\thletic_							
	Surface - Asphalt	South	5,000	SF	7	10+ years	
	Surface - Synthetic	South	17,000	SF	7	10+ years	
ivil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	17	EA	6	10+ years	
encina							
	Fencing - Chain Link	Entire Site	25	LF	6	10+ years	
	Fencing - Iron and Concrete Post	Entire Site	889	LF	6	10+ years	
	Fencing - Iron and Concrete Post	Entire Site	25	LF	4	0-1 year	Falling over.
	Fencing - New Standard Ornamental	Entire Site	91	LF	7	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	370	LF	6	10+ years	
andsca	pe						
	Benches	Entire Site	2	EA	7	10+ years	
	Landscape - Grass	Entire Site	14,100	SF	5	2-5 years	
	Landscape - Mulch	Entire Site	2,400	SF	5	2-5 years	
	Parkway trees	Entire Site	28	EA	6	2-5 years	
	Planting Beds/ Area	Entire Site	3,000	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	10	SF	7	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	3,000	SF	7	6-10 years	
	Trash Receptacles	Entire Site	4	ĒA	6	6-10 years	
	Walking Path - Crushed Stone	Entire Site	2,500	SF	7	10+ years	
Parking I	Lot						
	Concrete Curbs	Parking Lot- East	356	LF	6	6-10 years	
	Interior Plantings	Parking Lot- East	135	LF	6	6-10 years	
	Surface - Asphalt	Parking Lot- East	28,462	SF	6	10+ years	
	Trash Enclosure - Wood	Parking Lot- East	395	SF	5	6-10 years	
	Vehicular Screening	Parking Lot- East	85	LF	6	6-10 years	
Playgrou	and						
, g. 00	Equipment - Combo 3-12	North	2	EA	7	10+ years	
	Equipment - Swingset	North	1	EA	7	10+ years	
	Surface - Poured Surface	North	3,000	SF	7	10+ years	
Sidewalk	(S						
nac wair	Sidewalks - Internal Walks	Entire Site	25	LF	6	6-10 years	
			20		Ŭ	o .o youro	

Campus Name: Field Page : 36 of 38 Assessment Date: 07/19/2021



Category : Site			В	_			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	2,220	LF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	13,850	SF	6	6-10 years	
Signage							
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter	Entire Site	1	EA	6	10+ years	
	Sign						
	Monument - Building Mounted Cut Letter	Entire Site	1	EA	6	10+ years	
	Sign						
	Monument - Building Mounted Cut Letter	Entire Site	2	EA	6	10+ years	
	Sign						

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Field Page: 37 of 38 Assessment Date: 07/19/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	intended Osage	100m Eddation	Humber	Hamber	(01)	Alca	Aica	Оюр	Board
Computer Lab	Regular Classroom	1st Floor	106	106	857	150	50	N	N
Computer Lab	Regular Classroom	2nd Floor	216	216	700	48	16	N	N
Office	Kindergarten	1st Floor	119	119	866	54	30	N	N
Other Instructional Use	Regular Classroom	1st Floor	115	115	866	72	35	N	N
Other Instructional Use	Science Classroom	2nd Floor	217	217	663	90	45	N	N
Regular Classroom	Library	2nd Floor	218	218	866	36	20	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	855	150	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	882	150	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	866	120	60	N	N
Special Education	Regular Classroom	2nd Floor	206	206	866	171	56	N	N
			•	•	•	•		•	•
Building : Addition 1									
Art Room	Art Room	Basement	504	4	852	90	29	N	N
Music Room	Store Room	Basement	513	5	1,310	126	60	N	N
Office	Regular Classroom	2nd Floor	201	201	802	250	82	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	802	215	70	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	799	150	50	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	799	140	70	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	798	215	70	N	N
Regular Classroom	Regular Classroom	1st Floor	113	113	799	140	70	N	N
Regular Classroom	Regular Classroom	1st Floor	114	114	799	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	799	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	799	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	804	250	82	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	799	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	799	112	48	N	N
Building : Addition 2									
Office	Regular Classroom	1st Floor	111	111	755	72	36	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	754	172	56	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	756	172	56	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	755	128	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	754	184	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	753	184	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	755	72	36	N	N
Science Classroom	Office	Basement	510	10	1,095	160	52	N	N
Store Room	Regular Classroom	2nd Floor	212	212	755	72	36	N	N