

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1921	3	94,900
Campus Total			94,900

Catego	Category : Exterior				: Main		
			-			Recommend	• · · ·
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	Entrance 2-NW	2	EA	6	2-5 years	
	Exterior Doors - Transom Lite	Entrance 2-NW	4	EA	6	2-5 years	
	Exterior Stairs - Concrete	Entrance 2-NW	18	LF	5	2-5 years	Crack in concrete
	Exterior Doors - Exterior Steel Door	Entrance 3-North	4	EA	6	10+ years	
	Power Door Operator and Controls	Entrance 3-North	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 3A-NW / Boiler Room	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 4-North / Outside Yard Storage -	2	EA	4	1-2 years	Corroded doors and frames
	Exterior Stairs - Concrete	Entrance 4-North / Outside Yard Storage -	6	LF	5	2-5 years	
	Exterior Doors - Exterior FRP Door	Entrance 5-West / Auditorium vestibule	1	EA	5	1-2 years	Corroded frame, damaged
	Exterior Doors - Exterior Steel Door	Entrance 5-West / Auditorium vestibule	6	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 5-West / Auditorium vestibule	3	EA	7	10+ years	
	Exterior Stairs - Concrete	Entrance 5-West / Auditorium vestibule	112	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 5-West / Auditorium vestibule	120	LF	6	10+ years	
	Ramps - Concrete	Entrance 5-West / Auditorium vestibule	60	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 5-West / Auditorium vestibule	30	LF	6	10+ years	



ry : Exterior			uilding	. Walli		
			Ŭ		Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Exterior Doors - Exterior FRP Door	Entrance 6-SW / Inside 110	2	EA	6	10+ years	
Exterior Doors - Transom Lite	Entrance 6-SW / Inside 110	1	EA	6	10+ years	
Exterior Stairs - Concrete	Entrance 6-SW / Inside 110 classroom	8	LF	4	0-1 year	Settlement of slab. 3 inch gap between door and slab, tripping hazard
Exterior Stairs - Stone	Entrance 6-SW / Inside 110 classroom	6	LF	7	10+ years	
Exterior Doors - Exterior Steel Door		4	EA	6	2-5 years	
		•				Hairline cracks
		-				Hairline cracks
		0				
		-				
		-				
Stair Handrail - Steel_Stair Handrail	Main Entrance 1-East	80	LF	6	10+ years	
on						
Foundation - Concrete	Entire Building	1,010	LF	7	10+ years	
	5		LF	5		
Superstructure - Steel with Clay Tile Arch	Entire Building	94,900	SF	7	10+ years	
Exterior Lighting - Wall Mounted	Entire Building	11	EA	6	6-10 years	
tem						
Access Ladder - Metal	Roof 1	2	EA	4	1-2 years	One ladder has a loose rung, thi spins when it is stepped . Secon metal ladder is not attached
Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1	10	LF	6	10+ years	
	Roof 1	125	LF	6	6-10 vears	
				-		
					•	
Parapet - Parapet > 30"	Roof 1	40	LF	5	1-2 years	Open joints, deteriorating mortal cracked brick
Roof - Modified Bitumen	Roof 1	12 135	SF	5	6-10 years	
						Tar roofing cement has failed at
		500	0	4	1-2 years	rai rooning cement has lailed at
	Exterior Doors - Transom Lite Exterior Stairs - Concrete Exterior Stairs - Stone Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Stairs - Concrete Exterior Stairs - Stone Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Stairs - Concrete Stair Handrail - Steel_Stair Handrail D Foundation - Concrete Superstructure - Steel with Clay Tile Arch Exterior Lighting - Wall Mounted tem Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Clay Tile Coping - Terra Cotta Downspouts - Interior Downspouts Parapet - 16" - 30" Height Parapet - Parapet < 16" Height	Exterior Doors - Exterior FRP DoorEntrance 6-SW / Inside 110 classroomExterior Doors - Transom LiteEntrance 6-SW / Inside 110 classroomExterior Stairs - ConcreteEntrance 6-SW / Inside 110 classroomExterior Stairs - StoneEntrance 6-SW / Inside 110 classroomExterior Doors - Exterior Steel DoorEntrance 6-SW / Inside 110 classroomExterior Doors - Exterior Steel DoorEntrance 7-South Entrance 8-SWExterior Doors - Transom LiteEntrance 8-SW Entrance 8-SWExterior Stairs - StoneEntrance 8-SW Entrance 8-SWExterior Stairs - ConcreteEntrance 8-SW Entrance 8-SWExterior Doors - Exterior Steel DoorMain Entrance 1-East Main Entrance 1-EastExterior Doors - Exterior Steel DoorMain Entrance 1-East Main Entrance 1-EastExterior Stairs - ConcreteMain Entrance 1-East Main Entrance 1-EastExterior Stairs - ConcreteMain Entrance 1-East Main Entrance 1-EastFoundation - ConcreteEntire Building Entrie BuildingFoundation - ConcreteEntire BuildingFoundation - ConcreteEntire BuildingExterior Lighting - Wall MountedEntire BuildingEterCoping - Clay TileRoof 1Coping - Clay TileRoof 1Coping - Clay TileRoof 1Parapet - 16' - 30'' HeightRoof 1Parapet - 16'' - 30'' HeightRoof 1Parapet - Parapet < 16'' Height	Exterior Doors - Exterior FRP DoorEntrance 6-SW / Inside 110 classroom2 classroomExterior Doors - Transom LiteEntrance 6-SW / Inside 110 classroom1Exterior Stairs - ConcreteEntrance 6-SW / Inside 110 classroom8Exterior Stairs - StoneEntrance 6-SW / Inside 110 classroom6Exterior Doors - Exterior Steel DoorEntrance 7-South4Exterior Doors - Exterior Steel DoorEntrance 8-SW Entrance 8-SW2Exterior Doors - Exterior Steel DoorEntrance 8-SW Entrance 8-SW4Exterior Doors - Transom LiteEntrance 8-SW Entrance 8-SW10Exterior Stairs - ConcreteEntrance 8-SW Entrance 8-SW6Entrance Control - Audio and VideoMain Entrance 1-East Main Entrance 1-East3Exterior Doors - Transom LiteMain Entrance 1-East Main Entrance 1-East30Poundation - ConcreteEntire Building Entire Building1,010Foundation - ConcreteEntire Building Entire Building11temAccess Ladder - MetalRoof 12Chimney - Brick Chimney- Concrete/Mortar LinerRoof 126Coping - Clay TileRoof 1580580Downspouts - Interior DownspoutsRoof 1580Parapet - Parapet < 16" Height	Exterior Doors - Exterior FRP DoorEntrance 6-SW / Inside 110 classroom2EA classroomExterior Doors - Transom LiteEntrance 6-SW / Inside 110 classroom1EA classroomExterior Stairs - ConcreteEntrance 6-SW / Inside 110 classroom8LFExterior Stairs - StoneEntrance 6-SW / Inside 110 classroom6LFExterior Doors - Exterior Steel DoorEntrance 8-SW 	Exterior Doors - Exterior FRP DoorEntrance 6-SW / Inside 1102EA6Exterior Doors - Transom LiteEntrance 6-SW / Inside 1101EA6Exterior Stairs - ConcreteEntrance 6-SW / Inside 1108LF4Exterior Stairs - StoneEntrance 6-SW / Inside 1106LF7Exterior Doors - Exterior Steel DoorEntrance 7-South4EA6Exterior Doors - Exterior Steel DoorEntrance 7-South4EA6Exterior Doors - Exterior Steel DoorEntrance 8-SW2EA7Exterior Doors - Transom LiteEntrance 8-SW4EA6Exterior Stairs - ConcreteEntrance 8-SW10LF5Exterior Stairs - StoneEntrance 8-SW6LF5Entrance Ortrol - Audio and VideoMain Entrance 1-East1EA7Exterior Doors - Transom LiteMain Entrance 1-East20LF7Exterior Doors - Transom LiteMain Entrance 1-East20LF7Exterior Doors - Transom LiteMain Entrance 1-East20LF7Exterior ConcreteMain Entrance 1-East20LF7Foundation - ConcreteEntire Building10.10LF7Foundation - ConcreteEntire Building60LF5Superstructure - Steel with Clay Tile ArchEntire Building11EA6termCoping - Clay TileRoof 110LF6Coping - Clay Tile	Item - TypeLocationQuantityUOMRankReplacementExterior Doors - Exterior FRP DoorEntrance 6-SW / Inside 1102EA610+ yearsExterior Doors - Transom LiteEntrance 6-SW / Inside 1101EA610+ yearsExterior Stairs - ConcreteEntrance 6-SW / Inside 1108LF40-1 yearExterior Stairs - StoneEntrance 6-SW / Inside 1106LF710+ yearsExterior Obors - Exterior Steel DoorEntrance 6-SW / Inside 1106LF710+ yearsExterior Doors - Exterior Steel DoorEntrance 7-South4EA62-5 yearsExterior Stairs - ConcreteEntrance 8-SW2EA710+ yearsExterior Doors - Transom LiteEntrance 8-SW4EA610+ yearsExterior Stairs - ConcreteEntrance 8-SW10LF56-10 yearsExterior Doors - Transom LiteEntrance 1-East1EA710+ yearsExterior Doors - Transom LiteMain Entrance 1-East3EA710+ yearsExterior Doors - Transom LiteMain Entrance 1-East3EA710+ yearsExterior Stairs - ConcreteMain Entrance 1-East2EA710+ yearsExterior Stairs - ConcreteMain Entrance 1-East2EA710+ yearsExterior Stairs - ConcreteMain Entrance 1-East2EA710+ yearsSuperstructure - Steel with Clay Tile Arch



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							gutters. Large cracks and openings
	Roof Structure - Steel with Clay Tile Arch	Roof 1	12,635	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	1	EA	4	0-1 year	Ladder is not attached to the building
	Coping - Terra Cotta	Roof 2	260	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2	240	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 2	220	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 2	40	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	7,500	SF	5	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 2	7,500	SF	7	10+ years	
	Coping - Terra Cotta	Roof 3	183	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	45	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 3	183	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	3,347	SF	5	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof 3	270	SF	7	10+ years	
	Concrete Topping						
	Roof Structure - Steel with Clay Tile Arch	Roof 3	3,077	SF	7	10+ years	
	Coping - Terra Cotta	Roof 4	127	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 4	45	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 4	127	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4	1,858	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 4	1,858	SF	7	10+ years	
	Access Ladder - Metal	Roof 5	1	EA	4	1-2 years	Ladder is old, unsafe, only attached to the wall st top.
	Coping - Terra Cotta	Roof 5	260	LF	6	10+ years	·
	Downspouts - Interior Downspouts	Roof 5	240	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 5	220	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 5	30	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 5	10	LF	5	1-2 years	Cracked or sprawled brick, open joints
	Roof - Modified Bitumen	Roof 5	7,000	SF	5	6-10 years	-
	Roof - Modified Bitumen	Roof 5	500	SF	4	0-1 year	Roofing tar around gutters has failed. Large cracks and openings in the metal
	Roof Structure - Steel with Clay Tile Arch	Roof 5	7,500	SF	7	10+ years	inotai
Walls							
	Cheek-Wall - Concrete	Entire Building	115	SF	7	10+ years	
	Cheek-Wall - Stone	Entire Building	30	SF	5	10+ years	Deteriorated mortar at brick cheek wall
	Cornice - Metal Projecting	Entire Building	945	LF	7	10+ years	
	Cornice - Terra Cotta	Entire Building	855	LF	5	10+ years	
	Cornice - Terra Cotta	Entire Building	100	LF	5	1-2 years	Open joints at various areas of the cornice, especially at roofs
	Exterior Walls - Brick	Entire Building	43,450	SF	6	10+ years	······································



Catego	ory : Exterior		В	uilding	: Main		TIS N Laramie AVENCE, Chicago, IL 60651
- alogo	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	20	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	80	SF	4	0-1 year	Open joints and deteriorated mortar
				•	•	0 i j0a.	near door 4
	Exterior Walls - Brick	Entire Building	48	SF	4	0-1 year	Open joints and deteriorated mortar
		Entiro Bananig	10	0.	•	o i you	at door number eight wall
	Exterior Walls - Brick	Entire Building	60	SF	4	1-2 years	Open joints at wall near door number
		Entiro Bananig	00	0.	•	1 2 youro	seven
	Exterior Walls - Brick	Entire Building	30	SF	4	0-1 year	Cheek walls and walls at door
				•	-	0 i jea.	number two have open joints and
							deteriorated mortar
	Exterior Walls - Stone-Cast	Entire Building	600	SF	5	10+ years	Deteriorated mortar, open joints
	Exterior Walls - Stone-Cut	Entire Building	845	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	4,830	SF	5	10+ years	
		Entire Banang	4,000	01	0	Tor years	
Nindow	S						
	Guard - Guards perforated	Entire Building	4,925	SF	6	6-10 years	
	Guard - Guards wire guard	Entire Building	465	SF	6	10+ years	
	Lintels - Steel	Entire Building	455	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	605	LF	7	10+ years	
	Skylite - Glass Single-Pane	Entire Building	374	SF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	6	SF	5	1-2 years	Broken glass pane
	Windows - Louver	Entire Building	30	SF	6	6-10 years	Droken glace parte
	Windows - Sash Aluminum Double-pane	Entire Building	8,675	SF	6	6-10 years	
			0,010	•	Ū.	0 10 900.0	
Catego	ory : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	ncy System	Looation	quantity	0011	Nam	Replacement	
merge	Emergency A/C Power - Auditoium and	1st floor, Entire building	6,635	SF	6	10+ years	
	Aisle Lighting	Tat hoor, Entire building	0,000	01	0	TO+ years	
	Emergency A/C Power - Corridors and	1st floor, Entire building	16,909	SF	6	10+ years	
	Stairs	Tat hoor, Entire building	10,000	01	0	Tor years	
	Emergency A/C Power - Gym	1st floor, Entire building	4,450	SF	6	10+ years	
	Emergency Battery Packs - Auditoium and	1st, 3rd floor, Entire Building	14	EA	7	6-10 years	
	Aisle Lighting	Tat, ord noor, Entire Building	17		'	o io years	
	Emergency Battery Packs - Corridors and	1st, 3rd floor, Entire Building	37	EA	7	6-10 years	
	Stairs	rst, sra noor, Entire Banang	51		'	0-10 years	
	Otalis	Act. Ord floor Fating Duilding	2	EA	7	6-10 years	Quantity change per current
	Emergency Battery Packs - Gym	1st statioor Entire Building		L/\		0 TO yours	Quantity change per current
	Emergency Battery Packs - Gym	1st, 3rd floor, Entire Building	-				observation
		-		F۵	7	6-10 years	observation
	Emergency Battery Packs - Lunchrooms	1st, 3rd floor, Entire Building	2	ΕA	7	6-10 years	observation Installed new in 2021
	Emergency Battery Packs - Lunchrooms Automatic Transfer Switch	1st, 3rd floor, Entire Building Electrical Room	2 1	EA	6	10+ years	
	Emergency Battery Packs - Lunchrooms Automatic Transfer Switch Security System - CCTV	1st, 3rd floor, Entire Building Electrical Room Entire Building	2 1 94,900	EA SF	6 6	10+ years 6-10 years	
	Emergency Battery Packs - Lunchrooms Automatic Transfer Switch	1st, 3rd floor, Entire Building Electrical Room	2 1	EA	6	10+ years	



	Chools					10	18 N Laramie AVENUE, Chicago, IL 60651
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Exit Signs - Corridors and Stairs	Entire Building	23	EA	6	6-10 years	With batteries
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	With batteries
	Exit Signs - Lunchroom	Entire Building	3	EA	7	6-10 years	New item added per current observation Installed new in 2021 With batteries
Main Se	Nice						
<u>mam oo</u>	Independent Electrical Service for	Electrical Room	1	EA	6	10+ years	
	emergency power						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	94,908	SF	5	6-10 years	Old system
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	9	EA	7	10+ years	Move to new item added
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	2	2-5 years	Move from original Missing breakers and exposed Auditorium stage
	Lighting and Power Panels - Above 100 A	Entire Building	8	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	Quantity change per current observation
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Mechanical Room	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Mechanical Room	13,055	SF	6	10+ years	Location change Entire building
	Fire Alarm_System	Mechanical Room	94,900	SF	5	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ling Systems Air Handling Unit- Built Up- Single Zone-	Mechanical Room	1	EA	5	6-10 years	
	Steam Coils - 8001 - 15000 cfm		4	Ξ.			
	Air Intake	Mechanical Room	1	EA	6	10+ years	



Catego	ry : Mechanical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	Control needs to be adjusted
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	7	10+ years	
	Missing or Existing Shaft				_	0.40	
	Air Handling Unit- Built Up- Single Zone w/	Mechanical Room	1	EA	5	6-10 years	AHU-3 Manually controlled bypass
	Air Tunnel- Steam Coils - Greater than						dampers
	35000 cfm Air Handling Unit- Built Up- Single Zone w/	Mechanical Room	1	EA	5	6-10 years	AHU-2 Manually controlled bypass
	Air Tunnel- Steam Coils - Greater than		I	EA	5	0-10 years	dampers
	35000 cfm						dampers
	Air Intake	Mechanical Room	2	EA	5	10+ years	Manually controlled dampers
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	5	6-10 years	Served north Manually controlled
			1		0	o io years	dampers
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	5	6-10 years	Served south Manually controlled
					Ū	e le jeale	dampers
	Reheat Boxes - Reheat Boxes with Steam	Mechanical Room	6	EA	6	10+ years	Served north
	Coil						
	Reheat Boxes - Reheat Boxes with Steam	Mechanical Room	6	EA	6	10+ years	Served south
	Coil						
	Return Duct Work - Sheet Metal- Exterior	Mechanical Room	200	LF	7	10+ years	Combined north and south
	Vertical Shaft and Ducts				_		
	Zone Dampers	Mechanical Room	18	EA	5	6-10 years	Manually controlled actuators
	Zone Dampers	Mechanical Room	18	EA	5	6-10 years	Manually controlled actuators
Boiler Sv	vstems						
,	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	6	10+ years	
	Pressure Boiler - 101 - 150 HP					,	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	5	6-10 years	Pump needs repair
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	New item added per current
							observation Served boilers and make
	Orandra anta Duran	Deiler Deers	-	F ^	0	0.4	up tank
	Condensate Pump	Boiler Room Boiler Room	2	EA	2	0-1 year	Both pumps not working
	Feed Water Pumps and Tank		4	EA	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EA	6	10+ years	
	Steam- Low Pressure Boiler - 101 - 150 HP Piping - Condensate Pipe- Steel	Boiler Room	200	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	200	LF	6	10+ years	
	Steam Traps	Boiler Room	35	EA	5	6-10 years	Minor repair needed
				LA	5	o io years	
Gas Boo	ster						
	Gas Booster	Mechanical Room	1	EA	6	10+ years	
					-		



Catego	ry : Mechanical		В	uilding	: Main		
C	How Two	Leasting	Quantitu	UOM	Dault	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating				– •		0.40	
	Unit Heater - Gas	Entire Building	1	EA	5	6-10 years	Control needs to be replaced
	Radiators - Steam	Entire Building	28	EA	6	10+ years	
	Fin Tube - Steam	Entire Building	75	LF	6	10+ years	
	Wall Heater - Electric	Entire Building	10	EA	5	6-10 years	
Tempera	ture Control						
	Electric Thermostat	Entire Building	11	EA	5	6-10 years	
	Pneumatic System	Entire Building	94,900	SF	4	2-5 years	Manually open and close actuators
	Thermostats - Pneumatic	Entire Building	57	ĒA	5	6-10 years	Manually open and close
	Thermostats - Pneumatic	Entire Building	1	EA	4	0-1 year	Move from original Cover missing -
		Linuto Dalianty	·	_ / (o i your	lunch room
Ventilatio	n						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	5	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	4	EA	6	10+ years	Quantity change per current
	CFM				Ū	let yeare	observation Installed all new in 2021
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	6-10 years	Quantity change per current
	CFM				-	,	observation Installed new in 2021 Not connected
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	No fire suppression system
Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - Less than	Mechanical Room	1	EA	6	6-10 years	
	200 Gallons						
	Electric Heater - 20 - 50 KW	Mechanical Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	94,900	SF	6	10+ years	Two clamps on pipe
	Domestic Piping-Hot Water Return Risers	Entire Building	94,900	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	94,900	SF	6	10+ years	
	Fixtures		0.,000	. .	÷	,	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	94,900	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	94,900	SF	6	10+ years	
	(RISEIS)			SF			



				uilding	- M.c.'	10	To N Laramie AVENUE, Chicago, il 60651
Catego	ry : Plumbing						
0	Hanna Tama	Leasting	Overstit		David	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sanitary Piping	Entire Building	94,900	SF	6	10+ years	
	Storm Piping	Entire Building	94,900	SF	6	10+ years	
	Vent Piping	Entire Building	94,900	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	5	6-10 years	Pump needs to be replaced Running hot
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	5	6-10 years	Pump needs to be replaced Running hot
	Pumps - Sump-Duplex	Mechanical Room	1	EA	6	10+ years	not
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	AC Unit	1st floor asst. principal and business manager	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor asst. principal and business manager	452	SF	7	10+ years	
	Doors - Side-lite	1st floor asst. principal and business manager	90	SF	6	10+ years	
	Doors - Transom Window	1st floor asst. principal and business	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	manager 1st floor asst. principal and business	1	EA	6	10+ years	
	Floor - Carpet	manager 1st floor asst. principal and business	452	SF	6	2-5 years	
	Lighting - Pendent/Surface	manager 1st floor asst. principal and business	6	EA	6	10+ years	
	Power Distribution	manager 1st floor asst. principal and business	11	EA	7	10	
		manager				10+ years	
	Walls - Plaster/Drywall	1st floor asst. principal and business manager	970	SF	6	10+ years	
	Work Slnk	1st floor asst. principal and business manager	1	EA	7	10+ years	
	Ceiling - Exposed	Eng. office in basement	485	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Eng. office in basement	1	EA	5	2-5 years	
	Floor - Concrete	Eng. office in basement	485	SF	7	10+ years	
	Lighting - Pendent/Surface	Eng. office in basement	3	EA	7	10+ years	
	Power Distribution	Eng. office in basement	8	EA	7	10+ years	
	Walls - Masonry	Eng. office in basement	728	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Gym office	250	SF	6	10+ years	Updated quantity
	Doors - Wood Doors inclu hw	Gym office	250	EA	6	10+ years	
	Floor - Tile	Gym office	250	SF	6	10+ years	Updated quantity
						, -	



Catego	ry : Room		В	uilding	: Main		
Ŭ				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Pendent/Surface	Gym office	5	EA	6	10+ years	Updated quantity
	Power Distribution	Gym office	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Gym office	832	SF	6	10+ years	Updated quantity
	AC Unit	Main office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main office	452	SF	6	10+ years	
	Doors - Side-lite	Main office	90	SF	7	10+ years	
	Doors - Transom Window	Main office	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main office	1	EA	6	10+ years	
	Floor - Tile	Main office	452	SF	7	10+ years	
	Lighting - Pendent/Surface	Main office	7	EA	6	10+ years	
	Power Distribution	Main office	15	EA	6	10+ years	
	Storage/ Closet	Main office	5	SF	7	10+ years	
	Walls - Plaster/Drywall	Main office	870	SF	6	10+ years	
	AC Unit	Principals office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principals office	460	SF	6	10+ years	
	Doors - Side-lite	Principals office	36	SF	7	10+ years	
	Doors - Transom Window	Principals office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principals office	1	EA	7	10+ years	
	Floor - Tile/Sheet	Principals office	460	SF	7	10+ years	
	Lighting - Pendent/Surface	Principals office	7	EA	7	10+ years	
	Power Distribution	Principals office	15	EA	7	10+ years	
	Walls - Plaster/Drywall	Principals office	1,010	SF	6	10+ years	
Auditoriu	um & Theater						
	Balcony Seating	1st Floor	186	EA	5	2-5 years	
	Balcony Seating	1st Floor	12	EA	4	0-1 year	Broken seats
	Ceiling - Plaster/Drywall	1st Floor	6,707	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	10	EA	7	10+ years	
	Floor - Carpet	1st Floor	1,345	SF	5	6-10 years	
	Floor - Concrete	1st Floor	3,640	SF	5	10+ years	
	Floor - Wood	1st Floor	1,650	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	2-5 years	
	Lighting - Wall Mounted	1st Floor	9	EA	5	10+ years	
	Main Floor Seating	1st Floor	551	EA	5	2-5 years	
	Main Floor Seating	1st Floor	5	EA	4	0-1 year	Missing/damaged seats
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	1,110	SF	6	10+ years	
	Stage Curtain	1st Floor	2	EA	7	10+ years	
	Stage Lighting System	1st Floor	- 1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	4	LF	6	10+ years	
	Stairs - Wood	1st Floor	55	LF	6	10+ years	
	Storage/ Closet	1st Floor	69	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	8,949	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	30	SF	5	1-2 years	Cracked wall
	,					2	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
.							
Symnasi	a Ceiling - Plaster/Drywall	3rd Floor	F	SF	6	6.10 10000	Decling point
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	3rd Floor 3rd Floor	5 5,415	SF	6	6-10 years	Peeling paint
	Doors - Wood Doors inclu hw	3rd Floor	5,415	EA	6 6	10+ years	Missing bordwore
	Floor - Wood	3rd Floor	5,420	SF	6	10+ years 10+ years	Missing hardware
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	24	EA	7	10+ years	
	Storage/ Closet	3rd Floor	24	SF	5	10+ years	Door knob and lock broken so as to
	Storage/ Closet	310 1001	250	36	5	10+ years	be inaccessible
	Walls - Plaster/Drywall	3rd Floor	5,240	SF	6	10+ years	
litchen							
	Ceiling - Lay-in	Lunchroom/kitchen in 103	780	SF	6	10+ years	
	Doors - Transom Window	Lunchroom/kitchen in 103	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Lunchroom/kitchen in 103	1	EA	6	10+ years	
	Floor - Terrazzo	Lunchroom/kitchen in 103	780	SF	6	10+ years	
	Lighting - Lay-in	Lunchroom/kitchen in 103	14	EA	7	10+ years	
	Serving Line	Lunchroom/kitchen in 103	20	LF	6	10+ years	
	Storage/ Closet	Lunchroom/kitchen in 103	15	SF	5	10+ years	
	Walls - Plaster/Drywall	Lunchroom/kitchen in 103	1,250	SF	6	6-10 years	
ibrary							
	AC Unit	2nd Floor	2	EA	7	6-10 years	Updated to match current observations
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,720	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	28	EA	6	10+ years	
	Storage/ Closet	2nd Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,345	SF	6	10+ years	
unch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	101 and 102	1,536	SF	6	2-5 years	
	Ceiling - Plaster/Drywall	101 and 102	10	SF	5	1-2 years	Cracked ceiling
	Chalk Board	101 and 102	16	LF	4	2-5 years	č
	Doors - Transom Window	101 and 102	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	101 and 102	2	EA	7	10+ years	
	Floor - Terrazzo	101 and 102	30	SF	7	6-10 years	Repaired
	Floor - Terrazzo	101 and 102	1,506	SF	6	10+ years	
	Lighting - Pendent/Surface	101 and 102	28	ĒA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
_					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	101 and 102	90	SF	7	10+ years	
	Walls - Plaster/Drywall	101 and 102	2,020	SF	6	10+ years	
						-	
MDF_ID							
	Doors - Store Front	3rd Floor	1	EA	7	10+ years	
	Finishes	3rd Floor	54	SF	7	6-10 years	
	Finishes	3rd Floor	6	SF	5	1-2 years	Water damage, failed plaster
	Window AC Unit	3rd Floor	1	EA	7	6-10 years	
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	87	SF	5	10+ years	
	Janitor's Closet	1st Floor	114	SF	5	10+ years	
	Storage Room	1st Floor	96	SF	7	10+ years	Under repair
	Janitor's Closet	2nd Floor	350	SF	5	10+ years	·
	Janitor's Closet	2nd Floor	85	SF	5	10+ years	
	Storage Room	2nd Floor	240	SF	7	10+ years	Engineer didn't have keys to acces
	Storage Room	2nd Floor	250	SF	7	10+ years	
	Janitor's Closet	3rd Floor	350	SF	7	10+ years	
	Janitor's Closet	3rd Floor	350	SF	7	10+ years	
	Air Intake Plenums	Basement	273	SF	5	10+ years	
	Air Tunnel	Basement	3,250	SF	5	10+ years	
	Auditorium Plenums	Basement	4,087	SF	5	•	
			4,087	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement				10+ years	
	Mechanical/ Service Rooms	Basement	1,320	SF	5	10+ years	
	Storage Room	Basement	117	SF	5	10+ years	
Restroo	m						
	Accessories	104	37	SF	7	6-10 years	
	Ceiling - Lay-in	104	37	SF	6	10+ years	
	Doors - Wood Doors inclu hw	104	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	104	37	SF	6	10+ years	
	Floor Drain	104	1	EA	7	10+ years	
	Lavatory	104	1	EA	7	10+ years	
	Lighting - Pendent/Surface	104	1	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	104	180	SF	6	10+ years	
	Water Closet	104	1	EA	7	10+ years	
	Accessories	107	37	SF	7	6-10 years	
	Ceiling - Lay-in	107	37	SF	7	10+ years	
	Doors - Wood Doors inclu hw	107	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	107	37	SF	6	10+ years	
	Floor Drain	107	37 1	EA	6 7		
			1	EA		10+ years	
	Lavatory	107	1		7	10+ years	
	Lighting - Pendent/Surface	107	1	EA	7	10+ years	



Catego	ory : Room		В	uilding	: Main		To N Laramie AVENUE, Chicago, il 60651
<u>-</u>	· · · · · · · · · · · · · · · · · · ·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Walls - Vinyl Coated Gypsum Panel	107	190	SF	6	10+ years	
	Water Closet	107	1	EA	6	10+ years	
	Accessories	1st fl Mens auditorium - storage	155	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	1st fl Mens auditorium - storage	140	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st fl Mens auditorium - storage	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st fl Mens auditorium - storage	1	EA	6	10+ years	
	Floor - Terrazzo	1st fl Mens auditorium - storage	155	SF	5	10+ years	
	Lighting - Pendent/Surface	1st fl Mens auditorium - storage	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st fl Mens auditorium - storage	155	SF	6	10+ years	
	Accessories	1st fl Women's auditorium - storage	240	SF	4	1-2 years	Missing
	Ceiling - Plaster/Drywall	1st fl Women's auditorium - storage	240	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st fl Women's auditorium - storage	1	EA	6	2-5 years	
	Floor - Terrazzo	1st fl Women's auditorium - storage	240	SF	7	10+ years	
	Lighting - Pendent/Surface	1st fl Women's auditorium - storage	3	EA	6	6-10 years	
	Partitions	1st fl Women's auditorium - storage	2	EA	5	10+ years	
	Walls - Plaster/Drywall	1st fl Women's auditorium - storage	597	SF	6	10+ years	
	Water Closet	1st fl Women's auditorium - storage	2	EA	4	0-1 year	Missing
	Accessories	1st floor Boys - Across from	225	SF	7	10+ years	
		principals office		0-	•	4.0	
	Ceiling - Plaster/Drywall	1st floor Boys - Across from	225	SF	6	10+ years	
		principals office		0-	_	4.0	
	Floor - Terrazzo	1st floor Boys - Across from	225	SF	7	10+ years	
	Flana Davia	principals office	4	F A	7	10	
	Floor Drain	1st floor Boys - Across from	1	EA	7	10+ years	
	Leveter	principals office	0		<u>^</u>	10	
	Lavatory	1st floor Boys - Across from	2	EA	6	10+ years	
	Lighting Dondont/Surface	principals office	c	EA	7	10	
	Lighting - Pendent/Surface	1st floor Boys - Across from principals office	6	EA	7	10+ years	
	Partitions	1st floor Boys - Across from	2	EA	5	10+ years	
	Faillions	principals office	2	EA	5	10+ years	
	Urinals	1st floor Boys - Across from	4	EA	7	10+ years	
	Officials	principals office	4	EA	1	TOT years	
	Walls - Plaster/Drywall	1st floor Boys - Across from	30	SF	6	10+ years	
	Walls - Flastel/Drywall	principals office	30	36	0	TOT years	
	Walls - Structural Glazed Tile	1st floor Boys - Across from	690	SF	7	10+ years	
		principals office	030	01	'	TOF years	
	Water Closet	1st floor Boys - Across from	2	EA	6	10+ years	
	Water Closet	principals office	2	LA	0	TOF years	
	Accessories	1st floor girls. Across from 103	250	SF	7	10+ years	
		kitchen	200	0	,	ioi youio	
	Ceiling - Plaster/Drywall	1st floor girls. Across from 103	250	SF	6	2-5 years	
		kitchen	200	0	U	2 0 yours	
	Floor - Terrazzo	1st floor girls. Across from 103	250	SF	7	10+ years	
			200	0.		is. youro	



Catego	ry : Room		В	uilding	: Main		
Ŭ	-			J		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		kitchen			_		
	Floor Drain	1st floor girls. Across from 103	1	EA	7	10+ years	
		kitchen	0		0	10	
	Lavatory	1st floor girls. Across from 103	2	EA	6	10+ years	
	Lighting - Pendent/Surface	kitchen 1st floor girls. Across from 103	6	EA	7	10+ years	
		kitchen	0	LA	'	TOT years	
	Partitions	1st floor girls. Across from 103	6	EA	5	2-5 years	
		kitchen	-		•	,	
	Walls - Plaster/Drywall	1st floor girls. Across from 103	30	SF	6	10+ years	
	-	kitchen				-	
	Walls - Structural Glazed Tile	1st floor girls. Across from 103	760	SF	7	10+ years	
		kitchen					
	Water Closet	1st floor girls. Across from 103	6	EA	7	10+ years	
	A	kitchen	005	05	7	10	
	Accessories	2nd floor boys	225	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd floor boys	225	SF	6	10+ years	
	Floor - Terrazzo	2nd floor boys	213	SF	7	10+ years	
	Floor - Terrazzo	2nd floor boys	12	SF	5	1-2 years	Cracking
	Floor Drain	2nd floor boys	1	EA	7	10+ years	
	Lavatory	2nd floor boys	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor boys	4	EA	6	10+ years	
	Partitions	2nd floor boys	2	EA	7	10+ years	Updated to match current observations
	Urinals	2nd floor boys	5	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor boys	30	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor boys	690	SF	6	10+ years	
	Water Closet	2nd floor boys	2	EA	7	10+ years	
	Accessories	2nd floor girls	250	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd floor girls	235	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd floor girls	15	SF	4	1-2 years	Water damage
	Floor - Terrazzo	2nd floor girls	250	SF	7	10+ years	Mater damage
	Floor Drain	2nd floor girls	200	EA	7	10+ years	
		2nd floor girls	1	EA	7	10+ years	
	Lavatory						
	Lighting - Pendent/Surface	2nd floor girls	4	EA	6	10+ years	Lindata dita matakan sumant
	Partitions	2nd floor girls	6	EA	7	10+ years	Updated to match current observations, repainted
	Partitions	2nd floor girls	1	EA	5	1-2 years	Hinge damaged
	Walls - Structural Glazed Tile	2nd floor girls	760	SF	7	10+ years	
	Water Closet	2nd floor girls	7	EA	7	10+ years	
	Accessories	3rd floor boys	225	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys	225	SF	6	10+ years	
	Floor - Terrazzo	3rd floor boys	225	SF	6	10+ years	
	Floor Drain	3rd floor boys	1	EA	7	10+ years	



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	3rd floor boys	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor boys	4	EA	6	10+ years	
	Partitions	3rd floor boys	2	EA	7	10+ years	
	Urinals	3rd floor boys	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	3rd floor boys	690	SF	7	10+ years	
	Water Closet	3rd floor boys	2	EA	7	10+ years	
	Accessories	3rd floor girls	250	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor girls	250	SF	6	10+ years	
	Floor - Terrazzo	3rd floor girls	250	SF	6	10+ years	
	Floor Drain	3rd floor girls	1	EA	7	10+ years	
	Lavatory	3rd floor girls	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor girls	6	EA	6	10+ years	
	Partitions	3rd floor girls	7	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd floor girls	760	SF	6	10+ years	
	Water Closet	3rd floor girls	7	EA	6	10+ years	
	Accessories	Boiler Room	29	SF	5	2-5 years	
	Ceiling - Exposed	Boiler Room	29	SF	4	0-1 year	Heavily peeling paint
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	5	2-5 years	
	Floor - Concrete	Boiler Room	29	SF	7	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	4	1-2 years	Does not work
	Lighting - Wall Mounted	Boiler Room	1	EA	6	2-5 years	
	Walls - Masonry	Boiler Room	270	SF	5	1-2 years	
	Walls - Masonry	Boiler Room	2	SF	4	0-1 year	
	Water Closet	Boiler Room	1	EA	7	10+ years	
	Accessories	Kindergarten restroom, 110	72	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Kindergarten restroom, 110	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kindergarten restroom, 110	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Kindergarten restroom, 110	72	SF	6	10+ years	
	Lavatory	Kindergarten restroom, 110	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Kindergarten restroom, 110	1	EA	7	10+ years	
	Partitions	Kindergarten restroom, 110	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Kindergarten restroom, 110	418	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Kindergarten restroom, 110	160	SF	6	10+ years	
	Water Closet	Kindergarten restroom, 110	2	EA	7	10+ years	
	Accessories	Kindergarten restroom, 110	62	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Kindergarten restroom, 110	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kindergarten restroom, 110	1	ĒA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Kindergarten restroom, 110	62	SF	6	10+ years	
	Lavatory	Kindergarten restroom, 110	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Kindergarten restroom, 110	1	EA	7	10+ years	
	Partitions	Kindergarten restroom, 110	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Kindergarten restroom, 110	416	SF	6	10+ years	
	Water Closet	Kindergarten restroom, 110	2	EA	7	10+ years	
	Accessories	Principals restroom between 1st and	78	SF	7	10+ years	
	///////////////////////////////////////	i inoipaio rootroom botwoon rot anu	70	0	'	ioi youio	



Catego	Category : Room		В	uilding	: Main	-	To N Landmic AVENOE, Onicago, ie 00001
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd floors Principals restroom between 1st and 2nd floors	78	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	Principals restroom between 1st and 2nd floors	1	EA	7	10+ years	
	Floor - Terrazzo	Principals restroom between 1st and 2nd floors	78	SF	6	10+ years	
	Lavatory	Principals restroom between 1st and 2nd floors	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Principals restroom between 1st and 2nd floors	1	EA	6	10+ years	
	Partitions	Principals restroom between 1st and 2nd floors	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Principals restroom between 1st and 2nd floors	350	SF	6	2-5 years	
	Water Closet	Principals restroom between 1st and 2nd floors	2	EA	6	10+ years	
	Accessories	Unisex restroom between 2nd & 3rd floor north	175	SF	7	6-10 years	Room not accounted for in previous assessment
	Ceiling - Plaster/Drywall	Unisex restroom between 2nd & 3rd floor north	175	SF	6	10+ years	Room not accounted for in previous assessment
	Doors - Wood Doors inclu hw	Unisex restroom between 2nd & 3rd floor north	1	EA	6	10+ years	Room not accounted for in previous assessment
	Floor - Terrazzo	Unisex restroom between 2nd & 3rd floor north	175	SF	7	10+ years	Room not accounted for in previous assessment
	Lavatory	Unisex restroom between 2nd & 3rd floor north	1	EA	6	10+ years	Room not accounted for in previous assessment
	Lighting - Lay-in	Unisex restroom between 2nd & 3rd floor north	1	EA	7	10+ years	Room not accounted for in previous assessment
	Lighting - Pendent/Surface	Unisex restroom between 2nd & 3rd floor north	1	EA	7	10+ years	Room not accounted for in previous assessment
	Partitions	Unisex restroom between 2nd & 3rd floor north	1	EA	7	10+ years	Room not accounted for in previous assessment
	Partitions	Unisex restroom between 2nd & 3rd floor north	1	EA	5	1-2 years	Door hits toilet when opening
	Walls - Plaster/Drywall	Unisex restroom between 2nd & 3rd floor north	655	SF	6	10+ years	Room not accounted for in previous assessment
	Water Closet	Unisex restroom between 2nd & 3rd floor north	2	EA	7	10+ years	Room not accounted for in previous assessment
	Accessories	Unisex south between 2nd & 3rd floors	175	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex south between 2nd & 3rd floors	175	SF	6	10+ years	
	Doors - Hardware	Unisex south between 2nd & 3rd	1	EA	6	1-2 years	Knob loose



	ry : Room		D	uilding	· Main	10	018 N Laramie AVENUE, Chicago, IL 60651
Calego	iy. NOOM		D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group		floors	quantity	00111	Marin	Replacement	
	Doors - Wood Doors inclu hw	Unisex south between 2nd & 3rd	1	EA	6	10+ years	
		floors				,	
	Floor - Terrazzo	Unisex south between 2nd & 3rd	175	SF	7	10+ years	
		floors			_		
	Lavatory	Unisex south between 2nd & 3rd	1	EA	6	10+ years	
	Lighting - Pendent/Surface	floors Unisex south between 2nd & 3rd	2	EA	6	10+ years	
	Lighting - Fenden/Sunace	floors	2	LA	0	IUT years	
	Partitions	Unisex south between 2nd & 3rd	2	EA	7	10+ years	
		floors	-		•	let yeare	
	Walls - Plaster/Drywall	Unisex south between 2nd & 3rd	655	SF	6	10+ years	
		floors					
	Water Closet	Unisex south between 2nd & 3rd	2	EA	7	10+ years	
	Accession	floors	50	05	7	0.40	
	Accessories	Unisex toilet room at 4th floor landing south center stair	50	SF	7	6-10 years	
	Ceiling - Lay-in	Unisex toilet room at 4th floor	50	SF	6	10+ years	
		landing south center stair	00	01	Ũ	for yourd	
	Doors - Wood Doors inclu hw	Unisex toilet room at 4th floor	1	EA	6	10+ years	
		landing south center stair				-	
	Floor - Tile	Unisex toilet room at 4th floor	50	SF	6	10+ years	
		landing south center stair			_	10	
	Floor Drain	Unisex toilet room at 4th floor	1	EA	7	10+ years	
	Hand Dryer	landing south center stair Unisex toilet room at 4th floor	1	EA	7	10+ years	
		landing south center stair	1	LA	'	TOT years	
	Lavatory	Unisex toilet room at 4th floor	1	EA	7	10+ years	
	,	landing south center stair				,	
	Lighting - Pendent/Surface	Unisex toilet room at 4th floor	1	EA	7	10+ years	
		landing south center stair			_		
	Walls - Plaster/Drywall	Unisex toilet room at 4th floor	252	SF	6	10+ years	
	Water Closet	landing south center stair Unisex toilet room at 4th floor	1	EA	7	10+ years	
	Water Closet	landing south center stair	1	LA	'	IUT years	
	Accessories	Womens restroom between 1st and	78	SF	7	6-10 years	
		2nd floors					
	Ceiling - Plaster/Drywall	Womens restroom between 1st and	78	SF	6	10+ years	
		2nd floors					
	Doors - Wood Doors inclu hw	Womens restroom between 1st and	1	EA	6	10+ years	
		2nd floors	70	<u>с</u> г	6	10, 10,000	
	Floor - Terrazzo	Womens restroom between 1st and 2nd floors	78	SF	6	10+ years	
	Lavatory	Womens restroom between 1st and	1	EA	7	10+ years	
				-/ \	•	io. youro	



Catego	Category : Room				Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
		2nd floors								
	Lighting - Pendent/Surface	Womens restroom between 1st and	1	EA	7	10+ years				
		2nd floors								
	Partitions	Womens restroom between 1st and	2	EA	7	10+ years				
		2nd floors								
	Walls - Plaster/Drywall	Womens restroom between 1st and	350	SF	6	10+ years				
		2nd floors								
	Water Closet	Womens restroom between 1st and	2	EA	7	10+ years				
		2nd floors								

Category : Classroom

Category : Classroom			B	uilding	: Main		
	Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #104 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	965	SF	6	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	965	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Storage/ Closet	1st Floor	5	SF	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	2	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,520	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	Combined quantities
Classroo	om #105 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	6	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	775	SF	6	10+ years	
	Floor - Wood	1st Floor	5	SF	5	0-1 year	Damaged, missing, warped
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,475	SF	6	10+ years	
Classroo	om #106 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	780	SF	6	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,475	SF	6	10+ years	
Classroc	m #107 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	740	SF	6	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,654	SF	6	10+ years	
	Work Sink	1st Floor	1,001	EA	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	m #108 (Vacant)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,475	SF	6	10+ years	
Classroc	m #109 (Faculty Lounge)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	onum bouru						
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	



Category : Classroom				uilding	: Main				
	· · · · · ·					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Wood	1st Floor	780	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years			
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Storage/ Closet	1st Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,475	SF	6	10+ years			
lassroo	m #110 (Kindergarten)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	25	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,805	SF	6	10+ years			
	Doors - Transom Window	1st Floor	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	1,805	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	26	EA	7	10+ years			
	Storage/ Closet	1st Floor	82	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,873	SF	6	10+ years			
	Work Sink	1st Floor	2	EA	7	10+ years			
assroo	m #201 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	20	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years			
	Chalk Board	2nd Floor	16	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years			
	Floor - Wood	2nd Floor	780	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years			
	Storage/ Closet	2nd Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years			
lassroo	m #202 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	9	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood	2nd Floor	780	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	6	10+ years			
	Marker Board	2nd Floor	11	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	Updated to match current		
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	observations		



Catego	Category : Classroom		В	uilding	: Main	10	To N Laranie AVENOE, Chicago, ie 00051
calege			_	anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #203 (Office)					-	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	- 1	EA	6	10+ years	
	Floor - Wood	2nd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	
0							
Classroo	0m #206 (Art Room)					0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
		2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	7	10+ years	Deleme
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	Relamp
	Lighting - Pendent/Surface	2nd Floor	13	EA	6	10+ years	
	Marker Board	2nd Floor	12	LF SF	6	6-10 years	Indeted to motely summers
	Storage/ Closet	2nd Floor	54		7	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	5	6-10 years	Not in use
Classroo	m #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
			8	01	0	ioi youio	



Category : Classroom			В	uilding	: Main		
	-			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	6	10+ years	Reseal
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	
lassroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	4	1-2 years	Broken and loose chipping tiles throughout
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	inoughout
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	
lassroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
	Chalk Board	2nd Floor	26	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	13	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Missing cover
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	Updated to match current observations
			4 475	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,475	01	Ũ	- ,	
lassroo	Walls - Plaster/Drywall	2nd Floor	1,475	01	0		
Classroo		2nd Floor 2nd Floor	1,475	EA			
Classroo	om #211 (Regular Classroom)		1		7	6-10 years	
Classroo	om #211 (Regular Classroom) AC Units Casework	2nd Floor		EA LF	7 6	6-10 years 10+ years	
Classroo	om #211 (Regular Classroom) AC Units	2nd Floor 2nd Floor	1 20 780	EA LF SF	7 6 6	6-10 years 10+ years 10+ years	
Classroo	om #211 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Chalk Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1 20 780 26	EA LF SF LF	7 6 6 4	6-10 years 10+ years 10+ years 2-5 years	
Classroo	om #211 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor	1 20 780	EA LF SF	7 6 6	6-10 years 10+ years 10+ years	



Category : Classroom			В	uilding	: Main		
J	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Storage/ Closet	2nd Floor	54	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	
Classroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	
		21011001	1,+75	01	0	TOF years	
lassroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,760	SF	6	10+ years	
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	6	SF	5	1-2 years	Water damage
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	3rd Floor	1,760	SF	6	10+ years	UDSELVALIULIS



Category : Classroom		В	uilding	: Main	-	To N Latarile AVENUE, Chicago, 12 0003	
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	ĒA	6	10+ years	
	Floor - Wood	3rd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	5	10+ years	Crumbling plaster
	Walls - Plaster/Drywall	3rd Floor	1,760	SF	6	10+ years	31
0							
Jassroo	om #304 (Regular Classroom)	Ord Elect		EA	7	6 10	
	AC Units	3rd Floor	1		7	6-10 years	
	Casework	3rd Floor	15	LF SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	812		6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	18	SF	5	1-2 years	Cracking in corner
	Chalk Board	3rd Floor	26	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	39	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	827	SF	6	10+ years	
	Floor - Wood	3rd Floor	3	SF	5	1-2 years	Broken boards
	Lighting - Pendent/Surface	3rd Floor	15	EA	6	10+ years	
	Storage/ Closet	3rd Floor	54	SF	5	10+ years	Filing cabinet blocking access
	Walls - Plaster/Drywall	3rd Floor	1,827	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	8	SF	5	1-2 years	Cracking
lassroc	om #305 (Computer Lab)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	830	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	39	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,835	SF	6	10+ years	
laceror	om #306 (Music Room)						
1033100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor 3rd Floor	22	LF	6		
		3rd Floor 3rd Floor	750	SF	6 6	10+ years	
	Ceiling - Plaster/Drywall		750 30	SF	ю 4	10+ years	Water damage
	Ceiling - Plaster/Drywall	3rd Floor	30	35	4	0-1 year	Water damage



Jatedo	ny i Classroom		D	uildina	Main		
, and ge	ry : Classroom		В	uilding	: main	Decommond	
	Hom Turne	Location	Quentity	UOM	Donk	Recommend	Commente
Group	Item - Type Chalk Board	3rd Floor	Quantity	LF	Rank	2-5 years	Comments
			14	SF	4		
	Doors - Transom Window	3rd Floor	8		7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	780	SF	6	10+ years	Updated to match current observations
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years	
	Storage/ Closet	3rd Floor	54	SF	5	10+ years	Crumbling plaster
	Walls - Plaster/Drywall	3rd Floor	1,760	SF	6	10+ years	
assroo	om #307 (Music Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	774	SF	6	10+ years	
	Floor - Wood	3rd Floor	6	SF	5	1-2 years	Broken boards
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,759	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1	SF	5	1-2 years	Crumbling from previous fixture
							attachment
1	(1000 (O) D)						attachment
assroo	m #308 (Store Room)					0.40	attachment
assroo	AC Units	3rd Floor	1	EA	7	6-10 years	attachment
assroc	AC Units Casework	3rd Floor	9	LF	6	10+ years	attachment
assroo	AC Units Casework Ceiling - Plaster/Drywall	3rd Floor 3rd Floor	9 780	LF SF	6 6	10+ years 10+ years	attachment
assroc	AC Units Casework Ceiling - Plaster/Drywall Chalk Board	3rd Floor 3rd Floor 3rd Floor	9 780 24	LF SF LF	6 6 4	10+ years 10+ years 2-5 years	attachment
assroo	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window	3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8	LF SF LF SF	6 6 4 7	10+ years 10+ years 2-5 years 10+ years	attachment
assroo	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8 1	LF SF LF SF EA	6 6 4 7 6	10+ years 10+ years 2-5 years 10+ years 10+ years	attachment
assroo	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8 1 780	LF SF LF EA SF	6 6 4 7 6 6	10+ years 10+ years 2-5 years 10+ years	attachment
assroo	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8 1	LF SF LF SF EA SF EA	6 6 4 7 6 6 6	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years	
assroo	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8 1 780	LF SF LF EA SF	6 6 4 7 6 6	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years	Updated to match current observations
assroo	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8 1 780 14	LF SF LF SF EA SF EA	6 6 4 7 6 6 6	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years	Updated to match current
assroo	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Storage/ Closet	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8 1 780 14 54	LF SF LF SF EA SF SF	6 4 7 6 6 7	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years	Updated to match current
	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall Walls - Plaster/Drywall m #309 (Regular Classroom)	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8 1 780 14 54 1,748	LF SF EA SF EA SF SF	6 4 7 6 6 7	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years	Updated to match current observations
	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall Walls - Plaster/Drywall	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8 1 780 14 54 1,748	LF SF EA SF EA SF SF SF	6 4 7 6 6 7	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years	Updated to match current observations
	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall Walls - Plaster/Drywall m #309 (Regular Classroom)	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	9 780 24 8 1 780 14 54 1,748 12	LF SF EA SF EA SF SF	6 4 7 6 6 7 6 5	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Updated to match current observations
	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall Walls - Plaster/Drywall m #309 (Regular Classroom) AC Units Casework	3rd Floor 3rd Floor	9 780 24 8 1 780 14 54 1,748 12	LF SF EA SF EA SF SF SF	6 4 7 6 6 7 6 5 7 6	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 1-2 years 6-10 years 10+ years	Updated to match current observations
	AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall Walls - Plaster/Drywall m #309 (Regular Classroom) AC Units	3rd Floor 3rd Floor	9 780 24 8 1 780 14 54 1,748 12	LF SF EA SF EA SF SF SF LF	6 4 7 6 6 7 6 5 7	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 1-2 years 6-10 years	Updated to match current observations



Category : Classroom		В	uilding	: Main				
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	772	SF	6	10+ years		
	Floor - Tile	3rd Floor	8	SF	5	1-2 years	Cracking	
	Lighting - Pendent/Surface	3rd Floor	13	EA	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	6-10 years	Relamp	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	Updated to match current observations	
	Walls - Plaster/Drywall	3rd Floor	1,748	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	12	SF	5	1-2 years	Cracking in corner	
assroo	om #310 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	5	1-2 years	Cracking in corner	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	C C	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Wood	3rd Floor	778	SF	6	10+ years		
	Floor - Wood	3rd Floor	2	SF	5	1-2 years	Broken boards	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years		
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	Updated to match current observations	
	Walls - Plaster/Drywall	3rd Floor	1,758	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	1-2 years	Cracking around fixture	
ssroo	m #311 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years		
	Chalk Board	3rd Floor	24	LF	4	2-5 years		
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Wood	3rd Floor	780	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years		
	Storage/ Closet	3rd Floor	54	SF	5	10+ years	Water damage	
	Walls - Plaster/Drywall	3rd Floor	1,760	SF	6	10+ years		
assroo	om #312 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years		



Catego	Category : Classroom			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	9	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	Updated to match current
	-					2	observations
	Walls - Plaster/Drywall	3rd Floor	1,760	SF	6	10+ years	
	-						

Building : Main

Category : Interior

_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	5,838	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	22	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	5,475	SF	7	10+ years	
	Floor - Terrazzo	1st Floor	200	SF	4	1-2 years	Cracked floor
	Lighting - Pendent/Surface	1st Floor	61	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	6	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	10,043	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	700	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,885	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,855	SF	7	10+ years	Updated to match current observations
	Floor - Tile/Sheet	2nd Floor	30	SF	5	6-10 years	Gapping between tiles
	Lighting - Pendent/Surface	2nd Floor	34	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6,322	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	1-2 years	Cracking around door framing
	Ceiling - Plaster/Drywall	3rd Floor	3,885	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years	Updated to match current observations, quantity changed
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	5	1-2 years	Out of order
	Floor - Tile/Sheet	3rd Floor	3,885	SF	7	10+ years	Updated to match current observations
	Floor - Tile/Sheet	3rd Floor	30	SF	5	1-2 years	Cracking tiles
	Floor - Tile/Sheet	3rd Floor	20	SF	5	1-2 years	Dents in sheet
	Lighting - Pendent/Surface	3rd Floor	34	EA	6	10+ years	
	Student Lockers - One Tier	3rd Floor	250	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	6,324	SF	6	10+ years	



Category : Interior		B	uilding	• Main			
oulego				unung	· main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.000	Walls - Plaster/Drywall	3rd Floor	16	SF	5	1-2 years	Cracking around door framing
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Cracking, sagging
	,					,	6, 66 6
Stairs							
	Ceiling - Plaster/Drywall	Auditorium vestibule north stairwell	90	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Auditorium vestibule north stairwell	20	SF	7	10+ years	
	Handrails	Auditorium vestibule north stairwell	41	LF	7	10+ years	
	Stairs - Asphalt	Auditorium vestibule north stairwell	15	LF	6	10+ years	
	Walls - Plaster/Drywall	Auditorium vestibule north stairwell	638	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Auditorium vestibule south stairwell	90	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Auditorium vestibule south stairwell	20	SF	7	10+ years	
	Handrails	Auditorium vestibule south stairwell	41	LF	7	10+ years	
	Stairs - Asphalt	Auditorium vestibule south stairwell	15	LF	6	10+ years	
	Walls - Plaster/Drywall	Auditorium vestibule south stairwell	598	SF	6	1-2 years	Heavily peeling walls
	Walls - Plaster/Drywall	Auditorium vestibule south stairwell	40	SF	5	1-2 years	Damaged wall
	Ceiling - Plaster/Drywall	Stairwell # 1	278	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairwell # 1	30	SF SF	5	1-2 years	Damaged wall
	Floor - Tile Handrails	Stairwell # 1 Stairwell # 1	320 120	SF LF	6 5	10+ years	
	Lighting - Pendent/Surface	Stairwell # 1	120	EA	5 6	2-5 years 10+ years	
	Stairs - Asphalt	Stairwell # 1	60		6	10+ years	
	Walls - Plaster/Drywall	Stairwell # 1	2,300	SF	6	6-10 years	
	Walls - Plaster/Drywall	Stairwell # 1	40	SF	5	1-2 years	Cracked wall
	Ceiling - Plaster/Drywall	Stairwell # 2	302	SF	6	10+ years	
	Floor - Asphalt	Stairwell # 2	490	SF	6	10+ years	
	Floor - Tile	Stairwell # 2	320	SF	7	10+ years	
	Handrails	Stairwell # 2	140	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell # 2	8	EA	6	10+ years	
	Stairs - Asphalt	Stairwell # 2	70	LF	7	10+ years	
	Walls - Plaster/Drywall	Stairwell # 2	3,120	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairwell # 3	302	SF	6	10+ years	
	Floor - Tile	Stairwell # 3	320	SF	6	10+ years	
	Handrails	Stairwell # 3	140	LF	5	10+ years	
	Lighting - Pendent/Surface	Stairwell # 3	8	EA	7	10+ years	
	Stairs - Asphalt	Stairwell # 3	70	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell # 3	3,120	SF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell # 3	20	SF	5	1-2 years	Cracked wall
	Ceiling - Plaster/Drywall	Stairwell # 4	308	SF	6	10+ years	
	Floor - Tile	Stairwell # 4	320	SF	6	10+ years	
	Handrails	Stairwell # 4	120	LF	7	10+ years	
	Lighting - Pendent/Surface Stairs - Asphalt	Stairwell # 4 Stairwell # 4	6	EA LF	6 7	10+ years	
	Walls - Plaster/Drywall	Stairwell # 4 Stairwell # 4	60 2,340	SF	6	10+ years	
	vvalis - Flasiel/DiyWall	Stall well # 4	2,340	ЪГ	0	10+ years	



Category : Site			В	uilding			
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Synthetic including exc & retention	SE	16,500	SF	7	10+ years	
Civil/Drai	nage						
	Civil/ Drainage - Bioswale	Entire Site	2,230	SF	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	6	10+ years	
Fencing							
	Fencing - New Standard Ornamental	Entire Site	330	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	240	LF	5	1-2 years	Corroded fence
	Fencing - Old Standard Ornamental	Entire Site	1,450	LF	6	10+ years	
	Fencing - Old Standard Ornamental	Entire Site	6	LF	4	1-2 years	Missing half of Gates, and section of
	C C						fence has corroded attachments ar Is loose at wall
andscap							
	Benches	Entire Site	2	EA	4	1-2 years	Broken benches, missing parts
	Landscape - Grass	Entire Site	37,800	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	14,927	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	100	SF	5	1-2 years	Alligatored and broken asphalt nea playground
	Landscape - Hardscape- Concrete	Entire Site	5,460	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	75	SF	4	1-2 years	Broken concrete by door one
	Landscape - Hardscape- Concrete	Entire Site	200	SF	4	0-1 year	Collapsed, settled concrete at door number five
	Landscape - Hardscape- Pavers	Entire Site	2,000	SF	7	10+ years	
	Parkway trees	Entire Site	35	EA	6	10+ years	
	Parkway trees	Entire Site	5	EA	4	1-2 years	Missing parkway trees
	Planting Beds/ Area	Entire Site	18,600	SF	6	10+ years	mooning parkway hood
Parking L	ot						
	Concrete Curbs	Northwest	432	LF	7	10+ years	
	Surface - Asphalt	Northwest	432	SF	6	6-10 years	Large cracks, some alligatored
		Northwest			0		surface areas
	Surface - Asphalt	Northwest	1,500	SF	5	0-1 year	Alligatoring surface, large cracks
	Surface - Concrete	Northwest	435	SF	7	10+ years	
	Surface - Concrete	Northwest	300	SF	6	1-2 years	Cracked, spalling concrete
	Trash Enclosure - Wood	Northwest	810	SF	4	1-2 years	Broken wood pieces, most of the world is showing signs of weatherin and has mold growing on it



John Hay Elementary Community Academy

1018 N Laramie AVENUE, Chicago, IL 60651

Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Playgrou</u>	Ind						
,,,	Equipment - Pre K 3-5	SW	1	EA	6	6-10 years	Assessed based on current observations
	Surface - Poured Surface	SW	2,000	SF	6	6-10 years	
	Equipment - School Age 5-12	West	1	EA	4	0-1 year	Rusted parts, missing parts
	Surface - Square Rubber Mats	West	2,500	SF	4	0-1 year	Large gaps and broken pieces of flooring
Sidewall	ks						
	Sidewalks - Internal Walks	Entire Site	755	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	12,945	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	20	SF	6	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	5	1-2 years	Spalled, cracked concrete
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	5	2-5 years	Marquee was replaced but old one is still standing
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	7	10+ years	New

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Room Number	(SF)	Area	Area	Stop	Board
3	Building : Main					Alca	Alca	0.00	Board
Art Room	Regular Classroom	2nd Floor	206	206	780	128	64	N	N
Computer Lab	Office	3rd Floor	305	305	830	85	34	N	N
Faculty Lounge	Regular Classroom	1st Floor	109	109	780	160	45	N	N
Kindergarten	Kindergarten	1st Floor	110	110	1,805	240	100	N	N
Kindergarten	Regular Classroom	1st Floor	105	105	780	160	64	N	Y
Kindergarten	Regular Classroom	1st Floor	106	106	780	160	64	N	N
Music Room	Regular Classroom	3rd Floor	306	306	780	128	64	N	N
Music Room	Regular Classroom	3rd Floor	307	307	780	126	64	N	N
Office	Regular Classroom	2nd Floor	203	203	780	128	64	N	N
Pre School	Regular Classroom	1st Floor	104	104	965	200	48	N	N
Pre School	Regular Classroom	1st Floor	107	107	740	160	32	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	780	128	64	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	780	128	64	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	780	128	64	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	780	128	64	N	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	780	128	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	780	128	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	780	128	64	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	780	128	64	N	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	780	128	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	780	128	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	780	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	830	136	68	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	780	128	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	780	128	64	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	311	311	780	128	64	N	Y
Regular Classroom	Regular Classroom	3rd Floor	312	312	780	128	64	N	Ν
Store Room	Regular Classroom	3rd Floor	308	308	780	128	64	N	Ν
Vacant	Regular Classroom	1st Floor	108	108	780	160	45	Ν	Ν