

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1970	3	159,500
Campus Total			159,500

Catego	ry : Exterior	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Door 1 - West north	1	EA	7	10+ years	
	Exterior Doors - Exterior AMP Door	Door 1 - West north	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 1 - West north	4	EA	7	10+ years	
	Exterior Doors - Exterior Stainless Steel	Door 10 - Pool northeast	1	EA	6	10+ years	
	Door						
	Exterior Doors - Exterior Stainless Steel	Door 11 - Pool southeast	1	EA	6	10+ years	
	Door						
	Exterior Doors - Exterior FRP Door	Door 12 - Gym south 2nd floor	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 12 - Gym south 2nd floor	100	LF	6	10+ years	Cracking
	Exterior Doors - Exterior Steel Door	Door 2 - North	2	EA	5	0-1 year	Denting throughout
	Exterior Doors - Side lite	Door 2 - North	2	EA	6	6-10 years	
	Exterior Doors - Side lite	Door 2 - North	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door 2 - North	3	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 3 - East north	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 3 - East north	1	EA	7	10+ years	
	Entrance Control - Audio and Video	Door 4 - East center	1	EA	7	10+ years	
	Exterior Doors - Exterior AMP Door	Door 4 - East center	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 4 - East center	4	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 5 - Southwest	2	EA	5	2-5 years	Severe paint pealing
	Exterior Doors - Side lite	Door 5 - Southwest	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door 5 - Southwest	3	EA	6	6-10 years	
	Power Door Operator and Controls	Door 5 - Southwest	1	EA	7	10+ years	
	Exterior Doors - Overhead Rolling/ Garage Door	Door 6 - South center	1	EA	6	6-10 years	



ALL A							5515 S Lowe AVENUE, Chicago, IL 60621
Catego	ry : Exterior		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Side lite	Door 6 - South center	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 6 - South center	25	LF	5	0-1 year	Cracking
	Exterior Doors - Exterior Steel Door	Door 6.5 - Southeast	1	EA	4	0-1 year	Corroded
	Exterior Doors - Side lite	Door 6.5 - Southeast	2	EA	5	2-5 years	
	Exterior Doors - Transom Lite	Door 6.5 - Southeast	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Door 7 - West south	1	EA	7	10+ years	
	Exterior Doors - Exterior AMP Door	Door 7 - West south	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 7 - West south	4	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 8	2	EA	6	10+ years	Graffiti
	Exterior Doors - Side lite	Door 8	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 8	3	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 9 - Gym north 2nd floor	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 9 - Gym north 2nd floor	100	LF	6	6-10 years	
		,)	
Foundat	on						
	Foundation - Concrete	Entire Building	1,116	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	159,500	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	6	6-10 years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	20	EA	6	6-10 years	
DeefOr							
Roof Sys		Deef 4	4 4 5 4		<u>^</u>	10	
	Coping - Metal	Roof 1	1,151	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	270	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 1	767	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 1	384	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	47,040	SF	4	0-1 year	Bubbling, blisters and ponding throughout
	Roof Hatch - Metal	Roof 1	2	EA	7	10+ years	0
	Roof Structure - Concrete	Roof 1	47,040	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years	
	Coping - Metal	Roof 2	338	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 2	24	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 2	338	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	5,045	SF	5	0-1 year	Ponding
	Roof Structure - Concrete	Roof 2	5,045	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	2	EA	5	10+ years	
	Chimney - Metal Flue	Roof 3	10	LF	6	10+ years	
	Coping - Metal	Roof 3	130	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	30	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 3	30	LF	7	10+ years	
	-1 araper -1 araper > 00		50		'	IUT years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Roof 3	2,650	SF	5	2-5 years	patches
	Roof Hatch - Metal	Roof 3	1	EA	5	10+ years	
	Roof Structure - Concrete	Roof 3	2,650	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	51,230	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	400	SF	5	6-10 years	
Windows							
	Guard - Guards perforated	Entire Building	2,908	SF	5	6-10 years	
	Lintels - Steel	Entire Building	1,580	LF	6	10+ years	
	Skylite - Lexan	Entire Building	1,960	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	9,828	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
ealoge			_	anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	159,500	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	159,500	SF	6	2-5 years	
	Exit Signs - Corridors and Stairs	Entire Building	36	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	3	EA	4	0-1 year	Damaged sign face with lettering that is difficult to read. Reason and Priority Rep changed to match current observations.
	Exit Signs - Gym	Entire Building	4	EA	6	6-10 years	Quantity, Rank, Reason and Priority Rep changed to match current observations.
	Exit Signs - Multipurpose Room	Entire Building	3	EA	6	6-10 years	Quantity, Rank, Reason and Priority Rep changed to match current observations.
	Exit Signs - Pool	Entire Building	3	EA	6	6-10 years	Rank, Reason and Priority Rep changed to match current observations.
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	2-5 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	30,184	SF	6	2-5 years	
	Emergency A/C Power - Gym	Entire Building	4,450	SF	6	2-5 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	8,595	SF	6	2-5 years	
	Emergency A/C Power - Pool	Entire Building	3,854	SF	6	2-5 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,843	SF	6	2-5 years	



Catego	ry : Electrical		B	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Emergency Generator- Outdoor- Natural Gas - 101 - 150 KW	Site South	1	EA	6	6-10 years	
Main Se	rvice						
	PA System Main Electrical Service - 1600 A 277/480/3PH	Entire Building Roof	159,500 1	SF EA	54	2-5 years 1-2 years	50-plus-year-old equipment installed in a rooftop shed and subject to outdoor ambient temperature and humidity. Fully serviceable with long- term surface corrosion observed throughout. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer
	Main Electrical Service - 800 A and 277/480/3PH	Roof	5	EA	4	1-2 years	50-plus-year-old equipment installed in rooftop sheds and subject to outdoor ambient temperature and humidity. Fully serviceable with long- term surface corrosion observed throughout. Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. Quantity changed to match current observations.
	Main Electrical Service - 800 A and Less than 277/480/3PH	Roof	1	EA	4	1-2 years	400 A supply rating. 50-plus-year-old equipment installed in a rooftop shed and subject to outdoor ambient temperature and humidity. Fully serviceable with long-term surface corrosion observed throughout. Rank, Reason and Priority Rep established based on current observations and per review with Building Engineer.
Power D	Distribution						
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Entire Building Entire Building	1 5	EA EA	6 6	6-10 years 6-10 years	EM fuse panel Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	EM fuse panel. Fully operational 50- plus-year-old equipment with appreciable surface corrosion noted. Rank, Reason, Priority Rep and Location changed to match current



Catego	ry : Electrical		В	uilding	: Main		
Calege	.,		_	anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observations.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Missing devices expose live
	5 5	5				,	conductors presenting a live-front
							condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Panel is partially separated from
							frame.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	Quantity changed as total has been
							divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	Quantity and location changed to
							match current observations.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	Doors not attached to panels.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Door not attached to panel.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Door not attached to panel.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	EM fuse panel
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	26	EA	6	6-10 years	Quantity changed as total has been
	Lishting and Deven Develop Above 400.4	Fatire Duilding	0		4	0.5	divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	2-5 years	Fully operational 50-plus-year-old
							equipment with appreciable surface
							corrosion noted. Rank, Reason, Priority Rep and Location changed to
							match current observations.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	6-10 years	Quantity changed as total has been
	Main Distribution raneis - 400 - 000 amp	Entite Building	2	LA	0	0-10 years	divided/aggregated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	divided/aggregated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Door removed from panel due to
		Entro Dananig		L/\		o i your	damaged hinge.
	Main Distribution Panels - Less than 400	Entire Building	2	EA	6	6-10 years	damaged miger
	amp	g	_		-		
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	6-10 years	
	amp	5				,	
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	10+ years	
	amp						
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	6-10 years	
	amp						
	Main Distribution Panels - Less than 400	Entire Building	1	EA	4	0-1 year	Fully operational 50-plus-year-old
	amp						equipment with surface corrosion
				_			noted.
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	2	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	



Catego	ry : Fire Protection		В	uilding	: Main		
_			•			Recommend	. .
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	1st Floor	1	EA	6	6-10 years	Priority Rep revised based on current observations.
	Fire Alarm Strobe Lights	1st Floor	159,500	SF	7	6-10 years	Priority Rep revised based on current observations.
	Fire Alarm_System	1st Floor	159,500	SF	6	6-10 years	Priority Rep revised based on current observations.
	Fire Pump Controller	1st Floor	1	EA	6	6-10 years	Priority Rep revised based on current observations.
Pump Rr	com Assembly						
	Fire Pump - 25-50 hp	Pump Room	1	EA	5	2-5 years	No leaks at the time of assessment but considerable evidence of past leakage.
	Jockey Pump	Pump Room	1	EA	5	2-5 years	
Sprinkler	r System						
	Sprinkler Heads	Entire Building	159,500	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	159,500	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	159,500	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litioning						
	Condensing Unit- Roof Mounted - 5-10 tons	Roofs	1	EA	6	6-10 years	Serves the pool dehumidification system. CU-2
<u>Air Hand</u>	lling Systems						
	Dehumidification Unit- Outdoor- Gas Heating- DX Cooling with Remote Mounted Compressor - 4001 - 8000 cfm	Lower Roof	1	EA	6	6-10 years	RTU-2PE, 4 zones.
	Dehumidification Unit- Outdoor- Gas Heating- DX Cooling with Remote Mounted Compressor - 4001 - 8000 cfm	Lower Roof	1	EA	6	6-10 years	RTU-1PE, 4 zones. Rank and Priority Rep adjusted based on current observations and per review
	Zone Dampers	Roof	155	EA	6	6-10 years	with Building Engineer. Internal to the multi-zone RTUs. Not directly accessible in a safe manner at the time of assessment.
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof - RTU-1C	1	EA	6	6-10 years	Operability confirmed by the Building Engineer. RTU-1C, 6 zones. Repairs made



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-1E	1	EA	6	6-10 years	Priority Rep adjusted based on current observations and per review with Building Engineer. RTU-1E, 6 zones. Rank and Priority Rep adjusted based on current observations and per review with
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-1N	1	EA	6	6-10 years	Building Engineer. RTU-1N, 10 zones. Rank and Priority Rep adjusted based on current observations and per review with
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating Coils - 10 - 20 tons	Roof - RTU-1S	1	EA	6	6-10 years	Building Engineer. RTU-1S, 1 zone. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-1W	1	EA	6	6-10 years	RTU-1W, 6 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-2C	1	EA	6	6-10 years	RTU-2C, 7 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-2E	1	EA	6	6-10 years	RTU-2E, 6 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-2N	1	EA	6	6-10 years	RTU-2N, 9 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-2S	1	EA	6	6-10 years	RTU-2S, 8 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-2W	1	EA	6	6-10 years	RTU-2W, 6 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-3C	1	EA	6	6-10 years	RTU-3C, 8 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof - RTU-3E	1	EA	6	6-10 years	RTU-3E, 5 zones. Rank and Priority



Catego	Category : Mechanical			uilding			
_			• •••			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heating and DX Cooling - 10 - 20 tons Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-3N	1	EA	6	6-10 years	Rep adjusted based on current observations and per review with Building Engineer. RTU-3N, 10 zones. Rank and Priority Rep adjusted based on current observations and per review with
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-3S	1	EA	6	6-10 years	Building Engineer. RTU-3S, 10 zones. Rank and Priority Rep adjusted based on current observations and per review with
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 10 - 20 tons	Roof - RTU-3W	1	EA	6	6-10 years	Building Engineer. RTU-3E, 6 zones. Rank and Priority Rep adjusted based on current observations and per review with
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-4C	1	EA	6	6-10 years	Building Engineer. RTU-4C, 6 zones. Repaired made since last assessment. Priority Rep adjusted based on current observations and per review with
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 10 - 20 tons	Roof - RTU-4E	1	EA	6	6-10 years	Building Engineer. RTU-4E, 5 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons	Roof - RTU-4W	1	EA	6	6-10 years	RTU-4W, 6 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-5E	1	EA	6	6-10 years	RTU-5E, 6 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-5W	1	EA	6	6-10 years	RTU-5W, 6 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-6E	1	EA	6	6-10 years	RTU-6E, 7 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-6W	1	EA	6	6-10 years	RTU-6W, 7 zones. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer.



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy	etems						
Donier Gy	Combustion Dampers	Mechanical Room	2	EA	6	6-10 years	Serve the pool water heater and the domestic water heaters.
Heating I	Devices						
0	Cabinet Heaters - With Electric Coil	Entire Building	16	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	7	EA	6	6-10 years	
	Fin Tube - Electric	Entire Building	114	LF	6	6-10 years	Quantity changed as total has been divided/aggregated, hence N/A here Fin tube throughout the building has Rank of 6 at the time of assessment
	Fin Tube - Electric	Entire Building	4	LF	6	6-10 years	
	Unit Heater - Electric	Mechanical Room	1	EA	6	6-10 years	
Tempera	ture Control						
	DDC System	Entire Building	159,500	SF	6	6-10 years	Rank changed based on current observations and per review with Building Engineer; a software upgrade is needed.
	Electric Thermostat	Entire Building	5	EA	6	6-10 years	upgrade is needed.
	Thermostats - DDC	Entire Building	155	EA	6	6-10 years	
/entilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	13	EA	6	6-10 years	Quantity changed to match current observations, and as the total has been divided/aggregated.
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	5	0-1 year	Older unit, serves kitchen; visible surface corrosion on exterior. No undue noise or vibration. No dataplate found.
	Roof Mounted Duct Work	Entire Building	30	LF	7	6-10 years	
	Roof Mounted Duct Work	Entire Building	210	LF	7	6-10 years	Quantity changed based on current observations and as total has been divided/aggregated.
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	Quantity changed based on current observations.
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



	SCHOOIS						5515 S Lowe AVENUE, Chicago, IL 606
						Replacement	
ot Wate	er						
	Gas Heater - Greater than 600000 BTU/HR	Mechanical Room	1	EA	7	10+ years	WH-1 installed in 2022. Rank, Reason and Priority Rep adjusted based on current observations.
	Gas Heater - Greater than 600000 BTU/HR	Mechanical Room	1	EA	4	1-2 years	WH-2. 1985-vintage equipment. I in service at the time of assessme although it is mechanically operabl and could be used as a temporary backup, if needed; Priority Rep adjusted accordingly.
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Mechanical Room	1	EA	6	6-10 years	Original to the building. Minor corrosion, no leaks.
ping							
	Domestic Piping-Hot Water Return Lines	Entire Building	159,500	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	159,500	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	159,500	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	159,500	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	159,500	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	159,500	SF	6	6-10 years	
	Sanitary Piping	Entire Building	159,500	SF	6	6-10 years	
	Storm Piping	Entire Building	159,500	SF	6	6-10 years	
	Vent Piping	Entire Building	159,500	SF	6	6-10 years	
ol Sys	tems						
,	Pool Drain Piping	Basement	50	LF	4	1-2 years	Pool has been out of service for e vears.
	Pool Filtration System including Pump	Basement	1	EA	4	1-2 years	Pool has been out of service for years.
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	4	1-2 years	Pool has been out of service for years. Flue is corroding.
	Pool Supply and Return Piping	Basement	100	LF	4	1-2 years	Pool has been out of service for e years.
mps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	7	6-10 years	
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	2-5 years	
	Pumps - Sump-Duplex	Entire Building	1	EA	6	2-5 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Located at the bottom of the elev pit, inaccessible at the time of assessment. Fully operational p



Replacement

review with Building Engineer.

atego	ry : Room	В					
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	Ceiling - Lay-in	108C Auditorium Support	124	SF	5	2-5 years	Cracked tile
	Doors - Transom Window	108C Auditorium Support	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	108C Auditorium Support	1	EA	6	10+ years	
	Floor - Tile	108C Auditorium Support	124	SF	6	10+ years	
	Lighting - Lay-in	108C Auditorium Support	3	EA	6	6-10 years	
	Power Distribution	108C Auditorium Support	6	EA	7	10+ years	
	Storage/ Closet	108C Auditorium Support	98	SF	5	10+ years	
	Walls - Concrete Block	108C Auditorium Support	275	SF	6	10+ years	
	Ceiling - Lay-in	180B - Dressing Rm Off Stage	124	SF	5	2-5 years	
	Doors - Transom Window	180B - Dressing Rm Off Stage	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	180B - Dressing Rm Off Stage	1	EA	6	10+ years	
	Floor - Tile	180B - Dressing Rm Off Stage	124	SF	6	10+ years	
	Lighting - Lay-in	180B - Dressing Rm Off Stage	3	EA	6	6-10 years	
	Power Distribution	180B - Dressing Rm Off Stage	6	EA	7	10+ years	
	Storage/ Closet	180B - Dressing Rm Off Stage	98	SF	5	10+ years	
	Walls - Concrete Block	180B - Dressing Rm Off Stage	275	SF	6	10+ years	
	Ceiling - Lay-in	1st Flr- Asst Principal in Main Office	129	SF	6	10+ years	
	Ceiling - Lay-in	1st Flr- Asst Principal in Main Office	6	SF	4	0-1 year	Buckled and water damage.
	Doors - Transom Window	1st Flr- Asst Principal in Main Office	7	SF	6	10+ years	5
	Doors - Wood Doors inclu hw	1st FIr- Asst Principal in Main Office	1	EA	6	10+ years	
	Floor - Tile	1st FIr- Asst Principal in Main Office	135	SF	6	10+ years	
	Lighting - Lay-in	1st FIr- Asst Principal in Main Office	3	EA	6	6-10 years	
	Power Distribution	1st FIr- Asst Principal in Main Office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1st FIr- Asst Principal in Main Office	226	SF	6	10+ years	
	Ceiling - Lay-in	1st FIr- Conference Room in Main	135	SF	5	2-5 years	
	5 5	Office		-	-	- ,	
	Doors - Transom Window	1st FIr- Conference Room in Main	7	SF	6	10+ years	
		Office			-	, see geene	
	Doors - Wood Doors inclu hw	1st FIr- Conference Room in Main	1	EA	6	10+ years	
		Office			-	, see geene	
	Floor - Tile	1st FIr- Conference Room in Main	135	SF	6	10+ years	
		Office		•	Ū.	i o i goulo	
	Lighting - Lay-in	1st FIr- Conference Room in Main	3	EA	6	6-10 years	
	gg,	Office	Ū	_/ \	Ū.	0 10 900.0	
	Power Distribution	1st FIr- Conference Room in Main	9	EA	7	10+ years	
		Office	Ũ	<u> </u>	•	101 90010	
	Walls - Plaster/Drywall	1st FIr- Conference Room in Main	226	SF	6	10+ years	
		Office	220	0.	Ŭ	101 90010	
	Ceiling - Lay-in	1st Flr- Main Office	568	SF	5	2-5 years	
	Ceiling - Lay-in	1st Flr- Main Office	18	SF	4	0-1 year	Buckled Tiles



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Doors - Side-lite 1st Flr- Main Office 100 SF 6 10+ vears SF 6 Doors - Transom Window 1st Flr- Main Office 16 10+ years Doors - Wood Doors inclu hw 1st Flr- Main Office 2 EΑ 6 10+ years Floor - Tile SF 6 1st FIr- Main Office 586 10+ years Lighting - Lay-in 1st Flr- Main Office 12 EΑ 6 6-10 years **Power Distribution** 7 1st Flr- Main Office 18 EΑ 10+ years Storage/ Closet 1st FIr- Main Office SF 5 10+ years 101 SF Storage/ Closet 1st Flr- Main Office 27 5 10+ years Storage/ Closet 1st Flr- Main Office 4 SF 5 10+ years SF Walls - Masonry 242 6 10+ years 1st FIr- Main Office SF Walls - Plaster/Drvwall 1st Flr- Main Office 728 6 10+ vears Ceiling - Lay-in 1st FIr- Principal Office in Main 212 SF 5 2-5 years Office Ceiling - Lay-in 1st FIr- Principal Office in Main 12 SF 4 0-1 year Water damage. Office Doors - Transom Window 1st FIr- Principal Office in Main SF 21 6 10+ years Office Doors - Wood Doors inclu hw 1st FIr- Principal Office in Main 4 EΑ 6 10+ years Office Floor - Tile 1st FIr- Principal Office in Main 224 SF 6 10+ years Office Lighting - Lay-in 1st FIr- Principal Office in Main 5 EA 6 6-10 years Office Power Distribution 1st FIr- Principal Office in Main 8 FΑ 7 10+ years Office Storage/ Closet 1st FIr- Principal Office in Main 94 SF 7 10+ years Office Walls - Plaster/Drywall 1st FIr- Principal Office in Main SF 448 6 10+ years Office Ceiling - Lay-in 1st floor Assistant Eng. office 103 SF 5 2-5 years Doors - Wood Doors inclu hw 1st floor Assistant Eng. office ΕA 6 10+ vears 1 Floor - Tile 1st floor Assistant Eng. office 103 SF 6 10+ vears Lighting - Lay-in FΑ 1st floor Assistant Eng. office 2 6 6-10 years Power Distribution 1st floor Assistant Eng. office 4 ΕA 7 10+ years SF Walls - Concrete Block 1st floor Assistant Eng. office 340 6 10+ years SF 6 Ceiling - Lay-in 1st floor Chief engineer office 136 10+ years SF Ceiling - Lay-in 1st floor Chief engineer office 4 4 0-1 year Cracking/missing and buckled Doors - Transom Window 1st floor Chief engineer office 18 SF 6 10+ years Doors - Wood Doors inclu hw 1st floor Chief engineer office 2 EΑ 6 10+ years SF Floor - Carpet 1st floor Chief engineer office 140 6 6-10 vears Lighting - Lay-in 1st floor Chief engineer office 3 ΕA 6 6-10 years Power Distribution 1st floor Chief engineer office FΑ 7 4 10+ years Walls - Concrete Block 1st floor Chief engineer office 280 SF 6 10+ years 1st floor custodian's office SF Ceiling - Lay-in 220 4 0-1 year Water damage and damaged



Catego	ry : Room		В	uilding	: Main		
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							throughout.
	Doors - Transom Window	1st floor custodian's office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor custodian's office	1	EA	6	10+ years	
	Floor - Tile	1st floor custodian's office	220	SF	6	10+ years	
	Lighting - Lay-in	1st floor custodian's office	3	EA	6	6-10 years	
	Power Distribution	1st floor custodian's office	4	EA	7	10+ years	
	Walls - Concrete Block	1st floor custodian's office	440	SF	6	10+ years	
	Ceiling - Lay-in	345D Office	243	SF	6	10+ years	
	Doors - Steel Doors incl hw	345D Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	345D Office	243	SF	7	10+ years	
	Lighting - Pendent/Surface	345D Office	2	EA	7	6-10 years	
	Power Distribution	345D Office	4	EA	7	10+ years	
	Walls - Concrete Block	345D Office	523	SF	7	10+ years	
	Walls - Plaster/Drywall	345D Office	100	SF	6	10+ years	
	Ceiling - Lay-in	Gym office A	85	SF	6	10+ years	
	Ceiling - Lay-in	Gym office A	5	SF	4	0-1 year	Missing
	Doors - Wood Doors inclu hw	Gym office A	1	EA	6	10+ years	5
	Floor - Tile	Gym office A	90	SF	6	10+ years	
	Lighting - Lay-in	Gym office A	3	EA	6	6-10 years	
	Power Distribution	Gym office A	6	EA	6	10+ years	
	Walls - Concrete Block	Gym office A	180	SF	6	10+ years	
	Ceiling - Lay-in	Gym office B	75	SF	6	10+ years	
	Ceiling - Lay-in	Gym office B	15	SF	4	0-1 year	Missing
	Doors - Wood Doors inclu hw	Gym office B	1	EA	6	10+ years	3
	Floor - Tile	Gym office B	90	SF	6	10+ years	
	Lighting - Lay-in	Gym office B	3	ĒA	6	6-10 years	
	Power Distribution	Gym office B	6	EA	6	10+ years	
	Walls - Concrete Block	Gym office B	165	SF	6	10+ years	
	Walls - Concrete Block	Gym office B	15	SF	4	0-1 year	Hole in wall
	Ceiling - Lay-in	Library Computer Lab	195	SF	6	10+ years	
	Ceiling - Lay-in	Library Computer Lab	5	SF	4	1-2 years	Missing
	Doors - Side-lite	Library Computer Lab	100	SF	6	10+ years	
	Doors - Steel Doors incl hw	Library Computer Lab	1	EA	6	10+ years	
	Doors - Transom Window	Library Computer Lab	12	SF	6	10+ years	
	Floor - Carpet	Library Computer Lab	200	SF	6	6-10 years	
	Lighting - Lay-in	Library Computer Lab	5	EA	6	6-10 years	
	Power Distribution	Library Computer Lab	12	EA	7	10+ years	
	Walls - Concrete Block	Library Computer Lab	120	SF	6	10+ years	
	Walls - Plaster/Drywall	Library Computer Lab	200	SF	6	10+ years	
	Ceiling - Lay-in	Library Copy Office	129	SF	6	10+ years	
	Ceiling - Lay-in	Library Copy Office	3	SF	4	0-1 year	Missing.
	Doors - Steel Doors incl hw	Library Copy Office	1	EA	6	10+ years	wildonig.
	Floor - Carpet	Library Copy Office	132	SF	6	6-10 years	
	Lighting - Lay-in	Library Copy Office	2	EA	7	6-10 years	
	Lighting - Lay-in	Library Copy Onice	Z	LA	1	0-10 years	



Catego	ry : Room		В	uilding	: Main		
	·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Library Copy Office	6	EA	7	10+ years	
	Walls - Concrete Block	Library Copy Office	80	SF	6	10+ years	
	Walls - Masonry	Library Copy Office	120	SF	6	10+ years	
	Walls - Plaster/Drywall	Library Copy Office	80	SF	6	10+ years	
	Ceiling - Lay-in	Library Staff Lounge	352	SF	6	10+ years	
	Doors - Steel Doors incl hw	Library Staff Lounge	1	ĒA	6	10+ years	
	Doors - Transom Window	Library Staff Lounge	9	SF	6	10+ years	
	Floor - Tile	Library Staff Lounge	352	SF	6	10+ years	
	Lighting - Lay-in	Library Staff Lounge	8	ĒA	6	6-10 years	
	Power Distribution	Library Staff Lounge	10	EA	7	10+ years	
	Walls - Concrete Block	Library Staff Lounge	480	SF	6	10+ years	
	Work Sink	Library Staff Lounge	1	ĒA	7	10+ years	
	Ceiling - Lay-in	RM 308A - Community Office	238	SF	6	10+ years	
	Doors - Side-lite	RM 308A - Community Office	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	RM 308A - Community Office	1	EA	6	10+ years	
	Doors - Transom Window	RM 308A - Community Office	9	SF	6	10+ years	
	Floor - Tile	RM 308A - Community Office	238	SF	6	10+ years	
	Lighting - Lay-in	RM 308A - Community Office	200	EA	7	6-10 years	
	Power Distribution	RM 308A - Community Office	8	EA	7	10+ years	
	Walls - Concrete Block	RM 308A - Community Office	340	SF	6	10+ years	
	Walls - Metal Panel	RM 308A - Community Office	110	SF	6	10+ years	
	Ceiling - Lay-in	RM 331 Assistant Principals Office	180	SF	6	10+ years	
	Doors - Steel Doors incl hw	RM 331 Assistant Principals Office	100	EA	6	10+ years	
	Floor - Tile	RM 331 Assistant Principals Office	180	SF	6	10+ years	
	Lighting - Lay-in	RM 331 Assistant Principals Office	4	EA	6	6-10 years	
	Power Distribution	RM 331 Assistant Principals Office	8	EA	7	10+ years	
	Walls - Concrete Block	RM 331 Assistant Principals Office	200	SF	6	10+ years	
	Walls - Plaster/Drywall	RM 331 Assistant Principals Office	200	SF	6	10+ years	
	Ceiling - Lay-in	Rm 100A- Attendance Office	200 94	SF	5	2-5 years	
	Doors - Transom Window	Rm 100A- Attendance Office	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 100A- Attendance Office	1	EA	6	10+ years	
	Floor - Tile	Rm 100A- Attendance Office	94	SF	6		
	Lighting - Lay-in	Rm 100A- Attendance Office	94 2	EA	6	10+ years 6-10 years	
	Power Distribution	Rm 100A- Attendance Office	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 100A- Attendance Office	113	SF	6		
				SF		10+ years	
	Walls - Metal Panel	Rm 100A- Attendance Office	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 107A- CPD Office	75		5	2-5 years	Dualdad Tilaa
	Ceiling - Lay-in	Rm 107A- CPD Office	18	SF SF	4	0-1 year	Buckled Tiles
	Doors - Side-lite	Rm 107A- CPD Office	9		6	10+ years	
	Doors - Transom Window	Rm 107A- CPD Office	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 107A- CPD Office	1	EA	6	10+ years	
	Floor - Tile	Rm 107A- CPD Office	93	SF	6	10+ years	
	Lighting - Lay-in	Rm 107A- CPD Office	2	EA	6	6-10 years	
	Power Distribution	Rm 107A- CPD Office	6	EA	7	10+ years	



Catego	ery : Room		В	uilding	: Main		
_				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Rm 107A- CPD Office	113	SF	6	10+ years	
	Walls - Metal Panel	Rm 107A- CPD Office	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 108A- Business Manager Office	210	SF	5	2-5 years	
	Ceiling - Lay-in	Rm 108A- Business Manager Office	6	SF	4	0-1 year	Buckle Tile
	Doors - Side-lite	Rm 108A- Business Manager Office	9	SF	6	10+ years	
	Doors - Transom Window	Rm 108A- Business Manager Office	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 108A- Business Manager Office	1	EA	6	10+ years	
	Floor - Tile	Rm 108A- Business Manager Office	216	SF	6	10+ years	
	Lighting - Lay-in	Rm 108A- Business Manager Office	5	EA	6	6-10 years	
	Power Distribution	Rm 108A- Business Manager Office	12	EA	7	10+ years	
	Walls - Concrete Block	Rm 108A- Business Manager Office	215	SF	6	10+ years	
	Walls - Metal Panel	Rm 108A- Business Manager Office	215	SF	6	10+ years	
	Ceiling - Lay-in	Rm 137- Student Services Office	349	SF	6	10+ years	
	Doors - Transom Window	Rm 137- Student Services Office	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 137- Student Services Office	2	EA	6	10+ years	
	Floor - Carpet	Rm 137- Student Services Office	112	SF	6	6-10 years	
	Floor - Tile	Rm 137- Student Services Office	237	SF	6	10+ years	
	Lighting - Lay-in	Rm 137- Student Services Office	8	EA	6	6-10 years	
	Power Distribution	Rm 137- Student Services Office	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 137- Student Services Office	765	SF	6	10+ years	
	Ceiling - Lay-in	Rm 137A- Program Manager's office	120	SF	5	2-5 years	
	Doors - Steel Doors incl hw	Rm 137A- Program Manager's office	1	EA	6	10+ years	
	Floor - Carpet	Rm 137A- Program Manager's office	120	SF	5	2-5 years	
	Lighting - Lay-in	Rm 137A- Program Manager's office	3	EA	5	0-1 year	Lights not working
	Power Distribution	Rm 137A- Program Manager's office	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 137A- Program Manager's office	130	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 137A- Program Manager's office	130	SF	6	10+ years	
	Ceiling - Lay-in	Rm 137B- Post Secondary office	120	SF	5	2-5 years	
	Doors - Steel Doors incl hw	Rm 137B- Post Secondary office	1	EA	6	10+ years	
	Floor - Carpet	Rm 137B- Post Secondary office	120	SF	6	6-10 years	Linkte o et considér e
	Lighting - Lay-in	Rm 137B- Post Secondary office	3	EA	6	6-10 years	Lights not working
	Power Distribution	Rm 137B- Post Secondary office	4	EA	7	10+ years	
	Walls - Concrete Block	Rm 137B- Post Secondary office	130	SF SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 137B- Post Secondary office	130	SF	6	10+ years	
	Ceiling - Lay-in	Rm 137C- Counselors office	120		5	2-5 years	
	Doors - Steel Doors incl hw	Rm 137C- Counselors office	1	EA	6	10+ years	
	Floor - Carpet	Rm 137C- Counselors office Rm 137C- Counselors office	120	SF EA	6	6-10 years	Lighte met werking
	Lighting - Lay-in		3 4		5	0-1 year	Lights not working
	Power Distribution	Rm 137C- Counselors office	-	EA SF	6	10+ years	
	Walls - Concrete Block	Rm 137C- Counselors office	130		6	10+ years	
	Walls - Plaster/Drywall	Rm 137C- Counselors office	130	SF SF	6	10+ years	
	Ceiling - Lay-in	Rm 207A- Office	88	SF SF	6	10+ years	Brokon tilo
	Ceiling - Lay-in	Rm 207A- Office	5 9		4	0-1 year	Broken tile
	Doors - Side-lite	Rm 207A- Office	9	SF	6	10+ years	



Catego	ory : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	Rm 207A- Office	13	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Rm 207A- Office	1	EA	6	10+ years		
	Floor - Tile	Rm 207A- Office	93	SF	6	10+ years		
	Lighting - Lay-in	Rm 207A- Office	2	EA	6	6-10 years		
	Power Distribution	Rm 207A- Office	6	EA	7	10+ years		
	Walls - Concrete Block	Rm 207A- Office	113	SF	6	10+ years		
	Walls - Metal Panel	Rm 207A- Office	113	SF	6	10+ years		
	Ceiling - Lay-in	Rm 208A- Group Teacher/Student	216	SF	6	10+ years		
		Room		•	U U	ier jeare		
	Doors - Side-lite	Rm 208A- Group Teacher/Student	9	SF	6	10+ years		
		Room	0	01	Ū	ior youro		
	Doors - Transom Window	Rm 208A- Group Teacher/Student	7	SF	6	10+ years		
		Room	'	01	0	TO+ years		
	Doors - Wood Doors inclu hw	Rm 208A- Group Teacher/Student	1	EA	6	10+ years		
		•	1	LA	0	IUT years		
	Floor - Tile	Room	216	SF	6			
	Floor - The	Rm 208A- Group Teacher/Student	210	ЪГ	0	2-5 years		
	Linda Garan I. and in	Room	-	Γ.	~	0.40		
	Lighting - Lay-in	Rm 208A- Group Teacher/Student	5	EA	6	6-10 years		
		Room	10		_	4.0		
	Power Distribution	Rm 208A- Group Teacher/Student	12	EA	7	10+ years		
		Room						
	Walls - Concrete Block	Rm 208A- Group Teacher/Student	215	SF	6	10+ years		
		Room						
	Walls - Metal Panel	Rm 208A- Group Teacher/Student	215	SF	6	10+ years		
		Room						
	Ceiling - Lay-in	Rm 221- KIPP Main Office	229	SF	6	10+ years		
	Doors - Side-lite	Rm 221- KIPP Main Office	9	SF	6	10+ years		
	Doors - Transom Window	Rm 221- KIPP Main Office	7	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Rm 221- KIPP Main Office	1	EA	6	10+ years		
	Floor - Tile	Rm 221- KIPP Main Office	229	SF	6	10+ years		
	Lighting - Lay-in	Rm 221- KIPP Main Office	6	EA	6	6-10 years		
	Power Distribution	Rm 221- KIPP Main Office	6	EA	7	10+ years		
	Storage/ Closet	Rm 221- KIPP Main Office	95	SF	7	10+ years		
	Walls - Concrete Block	Rm 221- KIPP Main Office	220	SF	6	10+ years		
	Walls - Plaster/Drywall	Rm 221- KIPP Main Office	220	SF	6	10+ years		
	Ceiling - Lay-in	Rm 221.1 - Conference Room	118	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Rm 221.1 - Conference Room	1	EA	6	10+ years		
	Floor - Tile	Rm 221.1 - Conference Room	118	SF	6	10+ years		
	Lighting - Lay-in	Rm 221.1 - Conference Room	4	EA	6	6-10 years		
	Power Distribution	Rm 221.1 - Conference Room	18	EA	7	10+ years		
	Walls - Concrete Block	Rm 221.1 - Conference Room	113	SF	6	10+ years		
	Walls - Plaster/Drywall	Rm 221.1 - Conference Room	113	SF	6	10+ years		
	Ceiling - Lay-in	Rm 221.1 - Conference Room Rm 221.2 - Work Room	113	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Rm 221.2 - Work Room Rm 221.2 - Work Room		EA	6 6	•		
	Doors - wood Doors Inclu nw	RIII ZZI.Z - WORK ROOM	1	EA	ю	10+ years		



Catego	ry : Room		В	uilding	: Main		
				Ū		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Rm 221.2 - Work Room	118	SF	6	10+ years	
	Lighting - Lay-in	Rm 221.2 - Work Room	4	EA	6	6-10 years	
	Power Distribution	Rm 221.2 - Work Room	12	EA	7	10+ years	
	Walls - Concrete Block	Rm 221.2 - Work Room	113	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 221.2 - Work Room	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 226- Principal	635	SF	6	10+ years	
	Doors - Transom Window	Rm 226- Principal	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 226- Principal	1	EA	6	10+ years	
	Floor - Tile	Rm 226- Principal	635	SF	6	10+ years	
	Lighting - Lay-in	Rm 226- Principal	13	EA	6	6-10 years	
	Power Distribution	Rm 226- Principal	20	EA	7	10+ years	
	Walls - Concrete Block	Rm 226- Principal	430	SF	6	10+ years	
	Walls - Metal Panel	Rm 226- Principal	430	SF	6	10+ years	
	Ceiling - Lay-in	Rm 228- Vacant Office	93	SF	6	10+ years	
	Doors - Side-lite	Rm 228- Vacant Office	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	Rm 228- Vacant Office	1	EA	6	10+ years	
	Doors - Transom Window	Rm 228- Vacant Office	13	SF	6	10+ years	
	Floor - Carpet	Rm 228- Vacant Office	93	SF	6	2-5 years	
	Lighting - Lay-in	Rm 228- Vacant Office	2	EA	6	6-10 years	
	Power Distribution	Rm 228- Vacant Office	8	EA	7	10+ years	
	Walls - Concrete Block	Rm 228- Vacant Office	113	SF	6	10+ years	
	Walls - Metal Panel	Rm 228- Vacant Office	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 231-Asst Principal Office	216	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 231-Asst Principal Office	1	EA	6	10+ years	
	Floor - Tile	Rm 231-Asst Principal Office	216	SF	6	10+ years	
	Lighting - Lay-in	Rm 231-Asst Principal Office	4	ĒA	6	6-10 years	
	Power Distribution	Rm 231-Asst Principal Office	14	EA	7	10+ years	
	Walls - Concrete Block	Rm 231-Asst Principal Office	215	SF	6	10+ years	
	Walls - Metal Panel	Rm 231-Asst Principal Office	215	SF	6	10+ years	
	Ceiling - Lay-in	Rm 236-	216	SF	6	10+ years	
	Doors - Side-lite	Rm 236-	9	SF	6	10+ years	
	Doors - Transom Window	Rm 236-	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 236-	1	ĒA	6	10+ years	
	Floor - Tile	Rm 236-	216	SF	6	10+ years	
	Lighting - Lay-in	Rm 236-	5	ĒA	6	6-10 years	
	Power Distribution	Rm 236-	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 236-	215	SF	6	10+ years	
	Walls - Metal Panel	Rm 236-	215	SF	6	10+ years	
	Ceiling - Lay-in	Rm 236A- Dean's Office	133	SF	6	10+ years	
	Doors - Side-lite	Rm 236A- Dean's Office	11	SF	6	10+ years	
	Doors - Steel Doors incl hw	Rm 236A- Dean's Office	1	EA	6	10+ years	
	Doors - Transom Window	Rm 236A- Dean's Office	13	SF	6	10+ years	
	Floor - Carpet	Rm 236A- Dean's Office	133	SF	6	6-10 years	
	Lighting - Lay-in	Rm 236A- Dean's Office	3	EA	6	6-10 years	
			0		Ũ	5 10 90010	



Catego	ry : Room		В	uilding	: Main		ž
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Rm 236A- Dean's Office	12	EA	6	10+ years	
	Walls - Concrete Block	Rm 236A- Dean's Office	113	SF	6	10+ years	
	Walls - Metal Panel	Rm 236A- Dean's Office	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 239- Conference Rm	216	SF	6	10+ years	
	Doors - Side-lite	Rm 239- Conference Rm	9	SF	6	10+ years	
	Doors - Transom Window	Rm 239- Conference Rm	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 239- Conference Rm	1	EA	6	10+ years	
	Floor - Tile	Rm 239- Conference Rm	216	SF	6	10+ years	
	Lighting - Lay-in	Rm 239- Conference Rm	4	EA	6	6-10 years	
	Power Distribution	Rm 239- Conference Rm	14	EA	7	10+ vears	
	Walls - Concrete Block	Rm 239- Conference Rm	430	SF	6	10+ years	
	Ceiling - Lay-in	Rm 239A- Diverse Learner's	133	SF	6	10+ years	
		Corrdinator Office			-	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Doors - Steel Doors incl hw	Rm 239A- Diverse Learner's	1	EA	6	10+ years	
		Corrdinator Office			Ũ	rot youro	
	Doors - Transom Window	Rm 239A- Diverse Learner's	13	SF	6	10+ years	
		Corrdinator Office	10	01	0	ior youro	
	Floor - Tile	Rm 239A- Diverse Learner's	133	SF	6	10+ years	
		Corrdinator Office	100	01	0	TO+ years	
	Lighting - Lay-in	Rm 239A- Diverse Learner's	3	EA	6	6-10 years	
	Lighting - Lay-in	Corrdinator Office	5	LA	0	0-10 years	
	Power Distribution	Rm 239A- Diverse Learner's	6	EA	7	10+ years	
	Fower Distribution	Corrdinator Office	0	LA	1	TUT years	
	Walls - Concrete Block	Rm 239A- Diverse Learner's	113	SF	6	10+ years	
	Walls - Concrete Block	Corrdinator Office	113	36	0	TUT years	
	Walla Matel Danal	Rm 239A- Diverse Learner's	110	SF	6	10, 10000	
	Walls - Metal Panel	Corrdinator Office	113	55	ю	10+ years	
		Condinator Office					
Auditoriu	um & Theater						
	Ceiling - Plaster/Drywall	1st Floor	2,990	SF	6	10+ years	
	Floor - Carpet	1st Floor	1,475	SF	6	2-5 years	Minor ripping
	Floor - Tile	1st Floor	1,515	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	136	EA	6	6-10 years	
	Main Floor Seating	1st Floor	160	EA	5	10+ years	
	Sound System	1st Floor	1	EA	5	6-10 years	
	Stage	1st Floor	1	SF	6	10+ years	
	Stage Lift	1st Floor	1	EA	5	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Tile	1st Floor	5	LF	7	10+ years	
	Stairs - Wood	1st Floor	12	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	874	SF	6	10+ years	
	Walls - Concrete Block Walls - Masonry	1st Floor	234	SF	6	10+ years	
	Walls - Masonry Walls - Plaster/Drywall	1st Floor	234	SF	6		
	vvalis - Plastel/DryWall	IST FIODI	440	35	ю	10+ years	



Catego	ry : Room		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Clinic							
	Ceiling - Lay-in	Rm 100- Nurse	470	SF	5	2-5 years	
	Doors - Transom Window	Rm 100- Nurse	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 100- Nurse	1	EA	6	10+ years	
	Floor - Tile/Sheet	Rm 100- Nurse	470	SF	5	10+ years	
	Lighting - Lay-in	Rm 100- Nurse	11	EA	6	6-10 years	
	Walls - Concrete Block	Rm 100- Nurse	645	SF	6	10+ years	
	Walls - Metal Panel	Rm 100- Nurse	215	SF	6	10+ years	
Gvmnasi	ia.						
-yuuuasi	Ceiling - Plaster/Drywall	2nd Floor	4,400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	4	0-1 year	Holes present
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	4,450	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	24	ĒA	6	6-10 years	
	Scoreboards	2nd Floor	2	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	506	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	6,580	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	1,251	SF	6	10+ years	
Kitchen							
	Ceiling - Splined	1st Floor	1,760	SF	4	0-1 year	Worn and old.
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	1,760	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	20	EA	6	6-10 years	
	Serving Line	1st Floor	20	LF	6	10+ years	
	Storage/ Closet	1st Floor	270	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,700	SF	6	10+ years	
ibrony							
ibrary	Casework	2nd Floor	200	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	450	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	430	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	4,490	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	4 60	SF	6	10+ years	
	Floor - Carpet	2nd Floor	4,915	SF	6	6-10 years	
	Floor - Carpet	2nd Floor	4,915	SF	4	0-1 year	Torn
	Floor - Tile	2nd Floor	25 45	SF	4 6	10+ years	1011
	Lighting - Lay-in	2nd Floor	45 6	EA	6	6-10 years	
		2nd Floor		EA	6		
	Lighting - Pendent/Surface Storage/ Closet	2nd Floor 2nd Floor	128	SF	-	6-10 years	
			283		5	10+ years	
	Walls - Concrete Block	2nd Floor	1,150	SF	6	10+ years	



Catego	ory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Masonry	2nd Floor	2,250	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	1,800	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	800	SF	6	10+ years	
Locker/S	Shower Room						
	Accessories	1st Floor- Pool Unisex Locker Rm	99	SF	5	6-10 years	
	Benches, ped mounted	1st Floor- Pool Unisex Locker Rm	4	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor- Pool Unisex Locker Rm	99	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor- Pool Unisex Locker Rm	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor- Pool Unisex Locker Rm	99	SF	5	10+ years	
	Floor Drain	1st Floor- Pool Unisex Locker Rm	1	EA	7	10+ years	
	Lavatory	1st Floor- Pool Unisex Locker Rm	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor- Pool Unisex Locker Rm	2	EA	6	6-10 years	
	Showers	1st Floor- Pool Unisex Locker Rm	1	EA	5	6-10 years	
	Student Lockers - One Tier	1st Floor- Pool Unisex Locker Rm	4	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor- Pool Unisex Locker Rm	300	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor- Pool Unisex Locker Rm	65	SF	6	10+ years	
	Water Closet	1st Floor- Pool Unisex Locker Rm	1	EA	6	6-10 years	
	Accessories	1st Fir- Pool Boys locker room	1,197	SF	7	6-10 years	
	Benches, ped mounted	1st Fir- Pool Boys locker room	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Fir- Pool Boys locker room	1,180	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Fir- Pool Boys locker room	17	SF	4	0-1 year	Water leak
	Doors - Steel Doors incl hw	1st Fir- Pool Boys locker room	3	EA	6	10+ years	Trater Toals
	Floor - Tile Ceramic/ Porcelain	1st Fir- Pool Boys locker room	1,197	SF	6	10+ years	
	Floor Drain	1st Fir- Pool Boys locker room	6	EA	7	10+ years	
	Lavatory	1st Fir- Pool Boys locker room	1	EA	6	10+ years	
	Lighting - Lay-in	1st Fir- Pool Boys locker room	13	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st FIr- Pool Boys locker room	1	EA	6	6-10 years	
	Partitions	1st Fir- Pool Boys locker room	2	EA	5	10+ years	
	Showers	1st Fir- Pool Boys locker room	16	EA	7	10+ years	
	Student Lockers - One Tier	1st Fir- Pool Boys locker room	48	EA	6	10+ years	
	Student Lockers - Two Tier	1st Fir- Pool Boys locker room	30	EA	6	10+ years	
	Urinals	1st Fir- Pool Boys locker room	2	EA	6	10+ years	
	Walls - Concrete Block	1st Fir- Pool Boys locker room	1,525	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fir- Pool Boys locker room	72	SF	6	10+ years	
	Water Closet	1st Fir- Pool Boys locker room	2	EA	3	1-2 years	Toilet missing
	Accessories	1st flr Pool Girls locker room	1,197	SF	5	6-10 years	Tollet Missing
	Benches, ped mounted	1st flr Pool Girls locker room	1,137	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st flr Pool Girls locker room	1,187	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st flr Pool Girls locker room	1,187	SF	4	0-1 year	Hole.
	Doors - Steel Doors incl hw	1st flr Pool Girls locker room	10	EA	4 6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr Pool Girls locker room	1,197	SF	6	10+ years	
	Floor Drain	1st flr Pool Girls locker room	1,197	EA	6 7	,	
			-		7	10+ years	
	Hand Dryer	1st flr Pool Girls locker room	8	EA	1	6-10 years	



atego	ry : Room		В	uilding	: Main		
_				_		Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st flr Pool Girls locker room	1	EA	6	10+ years	
	Lighting - Lay-in	1st flr Pool Girls locker room	21	EA	6	6-10 years	
	Partitions	1st flr Pool Girls locker room	2	EA	5	10+ years	
	Showers	1st flr Pool Girls locker room	16	EA	7	10+ years	
	Storage/ Closet	1st flr Pool Girls locker room	36	SF	4	0-1 year	Water Damaged
	Student Lockers - One Tier	1st flr Pool Girls locker room	48	EA	6	10+ years	·
	Student Lockers - Two Tier	1st flr Pool Girls locker room	30	EA	6	10+ years	
	Walls - Concrete Block	1st flr Pool Girls locker room	1,495	SF	6	10+ years	
	Walls - Concrete Block	1st flr Pool Girls locker room	30	SF	4	0-1 year	Missing.
	Walls - Tile Ceramic/ Porcelain	1st flr Pool Girls locker room	72	SF	6	10+ years	5
	Water Closet	1st flr Pool Girls locker room	2	ĒA	6	10+ years	
	Accessories	2nd floor gym boys locker room	620	SF	7	6-10 years	
	Benches, ped mounted	2nd floor gym boys locker room	25	LF	6	10+ years	
	Ceiling - Lay-in	2nd floor gym boys locker room	580	SF	6	10+ years	
	Ceiling - Lay-in	2nd floor gym boys locker room	10	SF	4	0-1 year	Missing
	Ceiling - Plaster/Drywall	2nd floor gym boys locker room	30	SF	6	10+ years	Wissing
	Doors - Wood Doors inclu hw	2nd floor gym boys locker room	3	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor gym boys locker room	30	SF	6	10+ years	
	Floor - Tile/Sheet	2nd floor gym boys locker room	590	SF	7	10+ years	
	Floor Drain	2nd floor gym boys locker room	1	EA	7	10+ years	
	Hand Dryer	2nd floor gym boys locker room	1	EA	7		
	•	2nd floor gym boys locker room	1		6	6-10 years	
	Lavatory			EA EA	6	10+ years	
	Lighting - Lay-in	2nd floor gym boys locker room	13		-	6-10 years	
	Lighting - Pendent/Surface	2nd floor gym boys locker room	1	EA SF	6	6-10 years	
	Walls - Concrete Block	2nd floor gym boys locker room	1,120		6	10+ years	
	Water Closet	2nd floor gym boys locker room	1	EA	6	10+ years	
	Accessories	2nd floor gym girls locker room	620	SF	7	6-10 years	
	Benches, ped mounted	2nd floor gym girls locker room	40	LF	6	10+ years	
	Ceiling - Lay-in	2nd floor gym girls locker room	590	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd floor gym girls locker room	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor gym girls locker room	3	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor gym girls locker room	30	SF	6	10+ years	
	Floor - Tile/Sheet	2nd floor gym girls locker room	620	SF	7	10+ years	
	Floor Drain	2nd floor gym girls locker room	1	EA	7	10+ years	
	Hand Dryer	2nd floor gym girls locker room	1	EA	7	6-10 years	
	Lavatory	2nd floor gym girls locker room	1	EA	6	10+ years	
	Lighting - Lay-in	2nd floor gym girls locker room	13	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd floor gym girls locker room	1	EA	6	6-10 years	
	Student Lockers - One Tier	2nd floor gym girls locker room	50	EA	6	10+ years	
	Walls - Concrete Block	2nd floor gym girls locker room	1,120	SF	6	10+ years	
	Water Closet	2nd floor gym girls locker room	1	EA	6	10+ years	
ich &	Multipurpose Room						
	Ceiling - Lay-in	122 Cafeteria	735	SF	6	10+ years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Doors - Steel Doors incl hw 122 Cafeteria 2 ΕA 6 10+ vears Floor - Tile 735 SF 6 122 Cafeteria 10+ years Lighting - Lay-in 122 Cafeteria 20 FΑ 6 6-10 years Serving Line 32 LF 6 122 Cafeteria 10+ years SF Walls - Concrete Block 122 Cafeteria 380 6 10+ years SF Walls - Masonry 122 Cafeteria 490 6 10+ years Ceiling - Lay-in 1st floor- House 1 1,689 SF 6 10+ years SF Ceiling - Lay-in 1st floor- House 1 30 4 0-1 year Water damage. Doors - Side-lite 1st floor- House 1 800 SF 6 10+ vears SF Floor - Tile 1st floor- House 1 1.719 6 10+ vears Lighting - Lav-in 1st floor- House 1 32 ΕA 6 6-10 years Serving Line 1st floor- House 1 18 LF 6 10+ years Walls - Concrete Block 790 SF 6 1st floor- House 1 10+ years SF 6 Walls - Metal Panel 1st floor- House 1 640 10+ years SF Ceiling - Lay-in 2nd floor- House 2 1,719 6 10+ years Doors - Side-lite SF 6 2nd floor- House 2 800 10+ years Floor - Tile SF 2nd floor- House 2 1.719 6 10+ years Lighting - Lay-in 2nd floor- House 2 32 ΕA 6 6-10 years LF Serving Line 2nd floor- House 2 18 6 10+ vears Walls - Concrete Block SF 2nd floor- House 2 790 6 10+ years Walls - Metal Panel 2nd floor- House 2 640 SF 6 10+ years Ceiling - Lay-in SF 2nd floor- House 3 1,719 6 10+ years Doors - Side-lite SF 6 2nd floor- House 3 800 10+ years Floor - Tile SF 2nd floor- House 3 1.719 6 10+ years Lighting - Lay-in ΕA 6 2nd floor- House 3 32 6-10 years LF Serving Line 2nd floor- House 3 18 6 10+ vears Walls - Concrete Block SF 2nd floor- House 3 790 6 10+ years Walls - Metal Panel 640 SF 6 2nd floor- House 3 10+ years SF Ceiling - Lay-in 3rd floor- House 4 1,719 6 10+ years Doors - Side-lite 3rd floor- House 4 800 SF 6 10+ years SF Floor - Tile 3rd floor- House 4 1.719 6 10+ vears Lighting - Lav-in 3rd floor- House 4 32 EΑ 6 6-10 years Serving Line LF 3rd floor- House 4 18 6 10+ years Walls - Concrete Block 3rd floor- House 4 790 SF 6 10+ years SF Walls - Metal Panel 3rd floor- House 4 640 6 10+ years SF 6 Ceiling - Lay-in 3rd floor- House 5 1,719 10+ years SF Doors - Side-lite 3rd floor- House 5 800 6 10+ years Floor - Tile SF 3rd floor- House 5 1.719 6 10+ years Lighting - Lay-in 3rd floor- House 5 32 ΕA 6 6-10 years LF Serving Line 3rd floor- House 5 18 6 10+ vears SF Walls - Concrete Block 3rd floor- House 5 790 6 10+ years Walls - Metal Panel SF 3rd floor- House 5 640 6 10+ years

MDF IDF



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	MDF RM in Library Storage	1	EA	7	6-10 years	
	Ceiling - Lay-in	MDF RM in Library Storage	126	SF	4	0-1 year	Missing/stained throughout
	Doors - Steel Doors incl hw	MDF RM in Library Storage	1	EA	6	10+ years	
	Floor - Tile	MDF RM in Library Storage	126	SF	6	10+ years	
	Lighting - Lay-in	MDF RM in Library Storage	3	EA	6	6-10 years	
	Other Cooling Unit	MDF RM in Library Storage	1	EA	7	6-10 years	Ductless split system
	Power Distribution	MDF RM in Library Storage	12	EA	7	10+ years	
	Walls - Concrete Block	MDF RM in Library Storage	125	SF	6	10+ years	
	Walls - Plaster/Drywall	MDF RM in Library Storage	125	SF	6	10+ years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	43	SF	5	10+ years	
	Janitor's Closet	1st Floor	23	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	41	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	929	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	36	SF	5	10+ years	
	Storage Room	1st Floor	1,006	SF	7	10+ years	
	Storage Room	1st Floor	280	SF	5	10+ years	
	Storage Room	1st Floor	72	SF	5	10+ years	
	Storage Room	1st Floor	105	SF	5	10+ years	
	Vaults	1st Floor	65	SF	5 7	,	
	Janitor's Closet	2nd Floor	21	SF	7	10+ years	
						10+ years	
	Janitor's Closet	2nd Floor	43	SF	5	10+ years	Water damage ceiling.
	Mechanical/ Service Rooms	2nd Floor	50	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	20	SF	7	10+ years	
	Storage Room	2nd Floor	798	SF	7	10+ years	
	Janitor's Closet	3rd Floor	36	SF	5	10+ years	Water damage/missing ceiling.
	Janitor's Closet	3rd Floor	36	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	30	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	56	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	196	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	30	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	47	SF	5	10+ years	
	Storage Room	3rd Floor	220	SF	5	10+ years	
	Storage Room	3rd Floor	365	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement- Under Pool area only	748	SF	5	10+ years	
Pool & N	latatorium						
	Ceiling - Plaster/Drywall	1st Floor	3,854	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	3,854	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	44	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EA	4	0-1 year	Do not work
	Pool Basin	1st Floor	1,840	SF	5	2-5 years	Pool out of order for 8 years
			1,010	0.	U	L o youro	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pool Deck Drains	1st Floor	10	EA	5	2-5 years	Does not work.
	Storage/ Closet	1st Floor	51	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	3,000	SF	6	10+ years	
Prep Rod	om						
1	Casework	306A	20	LF	6	10+ years	
	Ceiling - Lay-in	306A	211	SF	6	10+ years	
	Doors - Steel Doors incl hw	306A	1	EA	6	10+ years	
	Floor - Tile	306A	211	SF	6	10+ years	
	Lighting - Lay-in	306A	4	EA	7	6-10 years	
	Walls - Concrete Block	306A	130	SF	7	10+ years	
	Walls - Plaster/Drywall			SF	6	•	
		306A	430	LF		10+ years	
	Casework	330A	9		6	10+ years	
	Ceiling - Lay-in	330A	182	SF	6	10+ years	
	Doors - Steel Doors incl hw	330A	1	EA	6	10+ years	
	Floor - Tile	330A	182	SF	6	10+ years	
	Lighting - Lay-in	330A	4	EA	6	6-10 years	
	Walls - Concrete Block	330A	90	SF	7	10+ years	
	Walls - Plaster/Drywall	330A	300	SF	6	10+ years	
Destroom	-						
Restroor	Accessories	105A - 1st floor boys north	180	SF		6-10 years	
	Ceiling - Plaster/Drywall	105A - 1st floor boys north	180	SF	5		
	Celling - Plaster/Drywall			SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	105A - 1st floor boys north	180		6	10+ years	
	Floor Drain	105A - 1st floor boys north	1	EA	7	10+ years	
	Hand Dryer	105A - 1st floor boys north	2	EA	7	6-10 years	
	Lavatory	105A - 1st floor boys north	3	EA	6	10+ years	
	Lighting - Lay-in	105A - 1st floor boys north	5	EA	6	6-10 years	
	Partitions	105A - 1st floor boys north	2	EA	5	10+ years	
	Urinals	105A - 1st floor boys north	4	EA	6	10+ years	
	Walls - Concrete Block	105A - 1st floor boys north	360	SF	6	10+ years	
	Water Closet	105A - 1st floor boys north	2	EA	6	10+ years	
	Accessories	105C - 1st floor girls north	180	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	105C - 1st floor girls north	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	105C - 1st floor girls north	180	SF	6	10+ years	
	Floor Drain	105C - 1st floor girls north	1	EA	7	10+ years	
	Hand Dryer	105C - 1st floor girls north	2	EA	7	6-10 years	
	Lavatory	105C - 1st floor girls north	3	EA	6	10+ years	
	Lighting - Lay-in	105C - 1st floor girls north	5	EA	6	6-10 years	
	Partitions	105C - 1st floor girls north	4	EA	5	10+ years	
	Walls - Concrete Block	105C - 1st floor girls north	-	SF			
			320		6	10+ years	
	Water Closet	105C - 1st floor girls north	4	EA	6	10+ years	
	Accessories	132D - 1st floor kitchen women	150	SF	7	6-10 years	
	Ceiling - Lay-in	132D - 1st floor kitchen women	150	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main			
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	132D - 1st floor kitchen women	2	EA	6	10+ years		
	Floor - Tile	132D - 1st floor kitchen women	85	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	132D - 1st floor kitchen women	65	SF	6	10+ years		
	Floor Drain	132D - 1st floor kitchen women	1	EA	7	10+ years		
	Lavatory	132D - 1st floor kitchen women	1	EA	6	10+ years		
	Lighting - Lay-in	132D - 1st floor kitchen women	3	EA	6	6-10 years		
	Partitions	132D - 1st floor kitchen women	1	EA	7	10+ years		
	Student Lockers - One Tier	132D - 1st floor kitchen women	16	EA	6	10+ years		
	Walls - Concrete Block	132D - 1st floor kitchen women	170	SF	6	10+ years		
	Walls - Masonry	132D - 1st floor kitchen women	130	SF	6	10+ years		
	Water Closet	132D - 1st floor kitchen women	1	EA	6	10+ years		
	Accessories	132F - 1st floor kitchen men	65	SF	7	6-10 years		
	Ceiling - Lay-in	132F - 1st floor kitchen men	65	SF	6	10+ years		
	Doors - Wood Doors inclu hw	132F - 1st floor kitchen men	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	132F - 1st floor kitchen men	65	SF	6	10+ years		
	Floor Drain	132F - 1st floor kitchen men	1	EA	7	10+ years		
	Lavatory	132F - 1st floor kitchen men	1	EA	6	10+ years		
	Lighting - Lay-in	132F - 1st floor kitchen men	1	EA	7	6-10 years		
	Partitions	132F - 1st floor kitchen men	1	EA	5	10+ years		
	Student Lockers - One Tier	132F - 1st floor kitchen men	11	EA	6	10+ years		
	Walls - Concrete Block	132F - 1st floor kitchen men	130	SF	6	10+ years		
	Water Closet	132F - 1st floor kitchen men	1	EA	6	10+ years		
	Accessories	136A - 1st flr Women's	245	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	136A - 1st flr Women's	245	SF	6	10+ years		
	Doors - Transom Window	136A - 1st flr Women's	7	SF	6	10+ years		
	Doors - Wood Doors inclu hw	136A - 1st flr Women's	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	136A - 1st flr Women's	245	SF	6	10+ years		
	Floor Drain	136A - 1st flr Women's		EA	7	10+ years		
	Hand Dryer	136A - 1st flr Women's	1	EA	7	6-10 years		
	Lavatory	136A - 1st flr Women's	4	EA	6	10+ years		
	Lighting - Lay-in	136A - 1st flr Women's	7	EA	6	6-10 years		
	Partitions	136A - 1st flr Women's	5	EA	5	10+ years		
	Walls - Concrete Block	136A - 1st flr Women's	440	SF	6	10+ years		
	Water Closet	136A - 1st flr Women's	5	EA	6	10+ years		
	Accessories	181 Boys (By Main Office)	245	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	181 Boys (By Main Office)	245	SF	6	10+ years		
	Doors - Transom Window	181 Boys (By Main Office)	7	SF	6	10+ years		
	Doors - Wood Doors inclu hw	181 Boys (By Main Office)	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	181 Boys (By Main Office)	245	SF	6	10+ years		
	Floor Drain	181 Boys (By Main Office)	243	EA	7	10+ years		
	Hand Dryer	181 Boys (By Main Office)	1	EA	7	6-10 years		
	Lavatory	181 Boys (By Main Office)	4	EA	6	10+ years		
	Lavatory Lighting - Lay-in	181 Boys (By Main Office)	4 7	EA	6	6-10 years		
	Partitions	181 Boys (By Main Office)	3	EA	5	10+ years		
			3	EA	5	ior years		



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments 181 Boys (By Main Office) Urinals 3 EΑ 10+ vears 6 181 Boys (By Main Office) 440 SF 6 Walls - Concrete Block 10+ years Water Closet 181 Boys (By Main Office) 3 FΑ 6 10+ years 181A - Unisex ADA RR 76 SF 7 Accessories 6-10 years SF Ceiling - Lay-in 181A - Unisex ADA RR 76 6 10+ years Doors - Wood Doors inclu hw 181A - Unisex ADA RR 1 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 76 SF 6 181A - Unisex ADA RR 10+ years Floor Drain 181A - Unisex ADA RR 1 ΕA 7 10+ years Lavatory 181A - Unisex ADA RR 1 ΕA 6 10+ years Lighting - Pendent/Surface 2 FΑ 6 6-10 years 181A - Unisex ADA RR Walls - Concrete Block 181A - Unisex ADA RR 93 SF 6 10+ vears Walls - Tile Ceramic/ Porcelain 181A - Unisex ADA RR 57 SF 6 10+ years Water Closet ΕA 6 181A - Unisex ADA RR 1 10+ years SF 5 Accessories 1st Flr- In Nurse's Office 18 6-10 years SF 7 Ceiling - Lay-in 1st Flr- In Nurse's Office 18 6-10 years Doors - Wood Doors inclu hw FΑ 1st Flr- In Nurse's Office 1 6 10+ years SF Floor - Tile 1st Flr- In Nurse's Office 18 6 10+ vears Lavatorv 1st FIr- In Nurse's Office 1 ΕA 6 10+ years Lighting - Pendent/Surface 1 EΑ 6 6-10 vears 1st Flr- In Nurse's Office Walls - Concrete Block 1st FIr- In Nurse's Office 36 SF 6 10+ years Water Closet 1st Flr- In Nurse's Office 1 ΕA 6 10+ years SF 5 Accessories 1st Flr- In Principal's Office 18 6-10 years SF 6 Ceiling - Plaster/Drywall 1st Flr- In Principal's Office 18 10+ years SF Doors - Transom Window 1st FIr- In Principal's Office 6 10+ years 1 Doors - Wood Doors inclu hw EΑ 6 1st FIr- In Principal's Office 1 10+ years Floor - Tile Ceramic/ Porcelain 1st Flr- In Principal's Office 18 SF 5 10+ vears 1st Flr- In Principal's Office EA 6 10+ years Lavatory 1 Lighting - Pendent/Surface 1st FIr- In Principal's Office ΕA 6 6-10 years 1 Walls - Plaster/Drywall SF 1st Flr- In Principal's Office 36 6 10+ years Water Closet 1st FIr- In Principal's Office 1 ΕA 6 10+ years Accessories 1st floor chief engineer restroom 15 SF 7 6-10 years SF Ceiling - Lav-in 1st floor chief engineer restroom 15 4 0-1 vear Cracked throughout Doors - Wood Doors inclu hw FΑ 6 1st floor chief engineer restroom 1 10+ years Floor - Tile 1st floor chief engineer restroom 15 SF 6 10+ years 7 Floor Drain 1st floor chief engineer restroom 1 EΑ 10+ years ΕA Lavatory 1st floor chief engineer restroom 1 6 10+ years Lighting - Pendent/Surface 1st floor chief engineer restroom 1 EΑ 6 6-10 years Walls - Concrete Block 30 SF 1st floor chief engineer restroom 6 10+ years Water Closet 1st floor chief engineer restroom 1 EA 6 10+ years SF 7 Accessories 1st floor custodian office 65 6-10 vears SF Ceiling - Lay-in 1st floor custodian office 65 6 10+ years Doors - Wood Doors inclu hw FΑ 6 1st floor custodian office 1 10+ vears Floor - Tile Ceramic/ Porcelain 1st floor custodian office 60 SF 5 2-5 years SF Floor - Tile Ceramic/ Porcelain 1st floor custodian office 5 4 0-1 year Missing tiles



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st floor custodian office	1	EA	7	10+ years	
	Lavatory	1st floor custodian office	1	EA	6	10+ years	
	Lighting - Lay-in	1st floor custodian office	1	EA	6	6-10 years	
	Partitions	1st floor custodian office	1	EA	5	10+ years	Corrosion
	Student Lockers - One Tier	1st floor custodian office	11	EA	6	10+ years	
	Walls - Concrete Block	1st floor custodian office	130	SF	6	10+ years	
	Water Closet	1st floor custodian office	1	EA	6	10+ years	
	Accessories	2nd Floor	200	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	200	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	200	SF	6	10+ years	
	Lavatory	2nd Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	6-10 years	
	Partitions	2nd Floor	3	EA	7	10+ years	
	Urinals	2nd Floor	2	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	450	SF	6	10+ years	
	Water Closet	2nd Floor	3	EA	6	10+ years	
	Accessories	2nd Flr-By-Gym Unisex 2 (Storage)	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Flr-By-Gym Unisex 2 (Storage)	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr-By-Gym Unisex 2 (Storage)	44	SF	6	10+ years	
	Floor Drain	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	7	10+ years	
	Lavatory	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	6	10+ years	
	Lighting - Lay-in	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	6	6-10 years	
	Partitions	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	5	6-10 years	
	Walls - Concrete Block	2nd Flr-By-Gym Unisex 2 (Storage)	88	SF	6	10+ years	
	Water Closet	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	6	10+ years	
	Accessories	2nd floor boys north	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boys north	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys north	180	SF	6	10+ years	
	Floor Drain	2nd floor boys north	1	EA	7	10+ years	
	Hand Dryer	2nd floor boys north	2	EA	7	10+ years	
	Lavatory	2nd floor boys north	3	EA	6	10+ years	
	Lighting - Lay-in	2nd floor boys north	5	EA	6	6-10 years	
	Partitions	2nd floor boys north	2	EA	7	10+ years	
	Urinals	2nd floor boys north	4	EA	6	10+ years	
	Walls - Concrete Block	2nd floor boys north	360	SF	6	10+ years	
	Water Closet	2nd floor boys north	2	EA	6	10+ years	
	Accessories	2nd floor boys south	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boys south	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys south	180	SF	6	10+ years	
	Floor Drain	2nd floor boys south	1	EA	7	10+ years	
	Hand Dryer	2nd floor boys south	2	EA	7	6-10 years	
	Lavatory	2nd floor boys south	4	EA	6	10+ years	
	Lighting - Lay-in	2nd floor boys south	5	EA	6	6-10 years	



Catego	ory : Room		В	uilding	: Main		
Ū	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd floor boys south	3	EA	7	10+ years	
	Urinals	2nd floor boys south	3	EA	6	10+ years	
	Walls - Concrete Block	2nd floor boys south	360	SF	6	10+ years	
	Water Closet	2nd floor boys south	3	EA	6	10+ years	
	Accessories	2nd floor girls South	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls South	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls South	180	SF	6	10+ years	
	Floor Drain	2nd floor girls South	1	EA	7	10+ years	
	Hand Dryer	2nd floor girls South	2	EA	7	6-10 years	
	Lavatory	2nd floor girls South	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor girls South	7	EA	6	6-10 years	
	Partitions	2nd floor girls South	4	EA	7	10+ years	
	Walls - Concrete Block	2nd floor girls South	320	SF	6	10+ years	
	Water Closet	2nd floor girls South	4	EA	6	10+ years	
	Accessories	2nd floor girls north	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls north	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls north	180	SF	6	10+ years	
	Floor Drain	2nd floor girls north	1	EA	7	10+ years	
	Hand Dryer	2nd floor girls north	2	EA	7	6-10 years	
	Lavatory	2nd floor girls north	3	EA	6	10+ years	
	Lighting - Lay-in	2nd floor girls north	5	EA	6	6-10 years	
	Partitions	2nd floor girls north	6	EA	5	10+ years	
	Walls - Concrete Block	2nd floor girls north	320	SF	6	10+ years	
	Water Closet	2nd floor girls north	6	EA	6	10+ years	All toilets present
	Accessories	2nd flr Womens (By 239)	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd flr Womens (By 239)	245	SF	6	10+ years	
	Doors - Transom Window	2nd flr Womens (By 239)	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd flr Womens (By 239)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd flr Womens (By 239)	245	SF	6	10+ years	
	Floor Drain	2nd flr Womens (By 239)	1	EA	7	10+ years	
	Hand Dryer	2nd flr Womens (By 239)	1	EA	7	6-10 years	
	Lavatory	2nd flr Womens (By 239)	4	EA	6	10+ years	
	Lighting - Lay-in	2nd flr Womens (By 239)	7	EA	6	6-10 years	
	Partitions	2nd flr Womens (By 239)	5	EA	7	10+ years	
	Walls - Concrete Block	2nd flr Womens (By 239)	440	SF	6	10+ years	
	Water Closet	2nd flr Womens (By 239)	5	EA	6	10+ years	
	Accessories	2nd flr-By Gym -Unisex restroom 1	44	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd flr-By Gym -Unisex restroom 1	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd flr-By Gym -Unisex restroom 1	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd flr-By Gym -Unisex restroom 1	44	SF	6	10+ years	
	Floor Drain	2nd flr-By Gym -Unisex restroom 1	1	EA	7	10+ years	
	Lavatory	2nd flr-By Gym -Unisex restroom 1	1	EA	6	10+ years	
	Lighting - Lay-in	2nd flr-By Gym -Unisex restroom 1	1	EA	6	6-10 years	
	Walls - Concrete Block	2nd flr-By Gym -Unisex restroom 1	88	SF	6	10+ years	



Catego	ry : Room		Building : Main					
_			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Water Closet	2nd flr-By Gym -Unisex restroom 1	1	EA	6	10+ years		
	Accessories	3rd floor boys north	180	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	3rd floor boys north	180	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd floor boys north	180	SF	6	10+ years		
	Floor Drain	3rd floor boys north	1	EA	7	10+ years		
	Hand Dryer	3rd floor boys north	2	EA	7	6-10 years		
	Lavatory	3rd floor boys north	3	EA	6	10+ years		
	Lighting - Lay-in	3rd floor boys north	5	EA	6	6-10 years		
	Partitions	3rd floor boys north	2	EA	5	10+ years		
	Urinals	3rd floor boys north	4	EA	6	10+ years		
	Walls - Concrete Block	3rd floor boys north	360	SF	6	10+ years		
	Water Closet	3rd floor boys north	2	EA	6	10+ years		
	Accessories	3rd floor boys south	180	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	3rd floor boys south	180	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd floor boys south	180	SF	6	10+ years		
	Floor Drain	3rd floor boys south	1	ĒA	7	10+ years		
	Hand Dryer	3rd floor boys south	2	EA	7	6-10 years		
	Lavatory	3rd floor boys south	3	EA	6	10+ years		
	Lighting - Pendent/Surface	3rd floor boys south	5	EA	6	6-10 years		
	Partitions	3rd floor boys south	2	EA	5	10+ years		
	Urinals	3rd floor boys south	2	EA	6	10+ years		
	Walls - Concrete Block	3rd floor boys south	360	SF	6	10+ years		
	Water Closet	3rd floor boys south	2	EA	6	10+ years		
	Accessories	3rd floor girls South	180	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	3rd floor girls South	180	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd floor girls South	180	SF	6	10+ years		
	Floor Drain	3rd floor girls South	1	EA	7	10+ years		
	Hand Dryer	3rd floor girls South	2	EA	7	6-10 years		
	Lavatory	3rd floor girls South	3	EA	6	10+ years		
	Lighting - Pendent/Surface	3rd floor girls South	5	EA	7	6-10 years		
	Partitions	3rd floor girls South	4	EA	5	10+ years		
	Walls - Concrete Block	3rd floor girls South	320	SF	6	10+ years		
	Water Closet	3rd floor girls South	4	EA	6	10+ years		
	Accessories	3rd floor girls north	180	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	3rd floor girls north	180	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd floor girls north	180	SF	6	10+ years		
	Floor Drain	3rd floor girls north	1	EA	7	10+ years		
	Hand Dryer	3rd floor girls north	2	EA	7	6-10 years		
	Lavatory	3rd floor girls north	3	EA	6	10+ years		
	Lighting - Lay-in	3rd floor girls north	5	EA	6	6-10 years		
	Partitions	3rd floor girls north	5	EA	5	10+ years		
	Walls - Concrete Block	3rd floor girls north	320	SF	6	10+ years		
	Water Closet	3rd floor girls north	5	EA	6	10+ years		
	Accessories	3rd floor mens west	245	SF	5	6-10 years		
			210	0.	Ũ	5 10 ,0010		



Catego	ory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd floor mens west	245	SF	6	10+ years	
	Doors - Transom Window	3rd floor mens west	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor mens west	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor mens west	245	SF	6	10+ years	
	Floor Drain	3rd floor mens west	1	EA	7	10+ years	
	Hand Dryer	3rd floor mens west	1	EA	7	6-10 years	
	Lavatory	3rd floor mens west	4	EA	6	10+ years	
	Lighting - Lay-in	3rd floor mens west	7	EA	6	6-10 years	
	Partitions	3rd floor mens west	3	EA	5	10+ years	
	Urinals	3rd floor mens west	3	EA	6	10+ years	
	Walls - Concrete Block	3rd floor mens west	454	SF	6	10+ years	
	Water Closet	3rd floor mens west	3	EA	6	10+ years	
	Accessories	3rd floor womens east	245	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor womens east	245	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd floor womens east	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor womens east	245	SF	6	10+ years	
	Floor Drain	3rd floor womens east	1	EA	7	10+ years	
	Hand Dryer	3rd floor womens east	1	EA	7	6-10 years	
	Lavatory	3rd floor womens east	4	EA	6	10+ years	
	Lighting - Lay-in	3rd floor womens east	6	EA	6	6-10 years	
	Lighting - Lay-in	3rd floor womens east	1	EA	4	0-1 year	Missing cover
	Partitions	3rd floor womens east	5	EA	5	10+ years	
	Walls - Concrete Block	3rd floor womens east	440	SF	6	10+ years	
	Water Closet	3rd floor womens east	5	EA	6	10+ years	
	Accessories	Gym office A restroom	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym office A restroom	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym office A restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym office A restroom	30	SF	6	10+ years	
	Floor Drain	Gym office A restroom	1	EA	7	10+ years	
	Lavatory	Gym office A restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Gym office A restroom	1	EA	6	6-10 years	
	Student Lockers - One Tier	Gym office A restroom	1	EA	6	10+ years	
	Walls - Concrete Block	Gym office A restroom	60	SF	6	10+ years	
	Water Closet	Gym office A restroom	1	EA	6	10+ years	
	Accessories	Gym office B restroom	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym office B restroom	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym office B restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym office B restroom	30	SF	6	10+ years	
	Floor Drain	Gym office B restroom	1	ĒΑ	7	10+ years	
	Lavatory	Gym office B restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Gym office B restroom	1	EA	6	6-10 years	
	Walls - Concrete Block	Gym office B restroom	60	SF	6	10+ years	
	Water Closet	Gym office B restroom	1	EA	6	10+ years	
	Accessories	Inside 108C	18	SF	5	6-10 years	
			10	0.	v	0.0,00.0	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Inside 108C	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Inside 108C	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 108C	18	SF	6	10+ years	
	Lavatory	Inside 108C	1	EA	6	10+ years	
	Lighting - Wall Mounted	Inside 108C	1	EA	6	6-10 years	
	Walls - Concrete Block	Inside 108C	36	SF	6	10+ years	
	Water Closet	Inside 108C	1	EA	6	10+ years	
	Accessories	Inside 180B - Dressing Rm off stage	18	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Inside 180B - Dressing Rm off stage	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Inside 180B - Dressing Rm off stage	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 180B - Dressing Rm off stage	18	SF	6	10+ years	
	Lavatory	Inside 180B - Dressing Rm off stage	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Inside 180B - Dressing Rm off stage	1	EA	6	6-10 years	
	Walls - Concrete Block	Inside 180B - Dressing Rm off stage	36	SF	6	10+ years	
	Water Closet	Inside 180B - Dressing Rm off stage	1	EA	6	10+ years	

Catego	ry : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #101 (Vacant)						
	Casework	1st Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	829	SF	5	2-5 years	
	Ceiling - Lay-in	1st Floor	6	SF	4	0-1 year	Cracked / falling tile
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	455	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	610	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	2-5 years	
Classroo	m #102 (Store Room)						
	Ceiling - Lay-in	1st Floor	835	SF	5	2-5 years	
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	115	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	950	SF	6	10+ years	



Catego	ry : Classroom	Building : Main					
Crown	Hom Tuno	Lesstien	Quantity	UOM	Denk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
Classroo	om #103 (Vacant)			~-	_		
	Ceiling - Lay-in	1st Floor	835	SF	5	2-5 years	
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	135	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	340	SF	6	10+ years	
Classroo	om #104/105 (Vacant)						
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,455	SF	5	2-5 years	
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,455	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	32	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	885	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	610	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	340	SF	6	10+ years	
	Work Sink	1st Floor		EA	5	10+ years	
	WOR SIIK	151 F1001	I	EA	5	10+ years	
Classroo	m #106 (Science Lab Level 3)						
	Casework	1st Floor	55	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	995	SF	5	2-5 years	
	Ceiling - Lay-in	1st Floor	40	SF	4	1-2 years	Water damage.
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Eye Wash Station	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,035	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Science Lab Elements	1st Floor	24	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	645	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	645	SF	6	10+ years	
	Work Sink	1st Floor	4	EA	5	2-5 years	
Classroo	m #108 (Vacant)						
	Ceiling - Lay-in	1st Floor	835	SF	5	2-5 years	



Catego	Category : Classroom		В				
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	455	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	340	SF	6	10+ years	
Classroo	om #109 (Vacant)						
	Ceiling - Lay-in	1st Floor	817	SF	5	2-5 years	
	Ceiling - Lay-in	1st Floor	18	SF	4	0-1 year	Buckled
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Door knob missing
	Floor - Carpet	1st Floor	835	SF	4	0-1 year	Torn and past useful life
	Lighting - Lay-in	1st Floor	18	EA	5	0-1 year	Lights not working
	Marker Board	1st Floor	12	LF	7	6-10 years	3
	Walls - Concrete Block	1st Floor	135	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	340	SF	6	10+ years	
Classroo	om #110 (Store Room)						
	Ceiling - Lay-in	1st Floor	823	SF	5	2-5 years	
	Ceiling - Lay-in	1st Floor	12	SF	4	0-1 year	Buckled
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	5	2-5 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	115	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	950	SF	6	10+ years	
Classroo	m #111 (Store Room)						
	Casework	1st Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	823	SF	5	2-5 years	
	Ceiling - Lay-in	1st Floor	12	SF	4	0-1 year	Buckled
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
		-			-	,	



	Building : Main				
	-			Recommend	•
Group Item - Type Location	Quantity	UOM	Rank	Replacement	Comments
Lighting - Lay-in 1st Floor	18	EA	7	6-10 years	
Marker Board 1st Floor	12	LF	7	6-10 years	
Walls - Concrete Block 1st Floor	455	SF	6	10+ years	
Walls - Metal Panel 1st Floor	610	SF	6	10+ years	
Classroom #121 (Store Room)					
Ceiling - Lay-in 1st Floor	2,013	SF	5	2-5 years	
Doors - Steel Doors incl hw 1st Floor	3	EA	6	10+ years	
Floor - Carpet 1st Floor	2,013	SF	6	6-10 years	
Lighting - Lay-in 1st Floor	40	ĒA	6	6-10 years	
Marker Board 1st Floor	10	LF	7	6-10 years	
Storage/ Closet 1st Floor	152	SF	7	10+ years	
Walls - Plaster/Drywall 1st Floor	3,800	SF	6	10+ years	
	0,000	01	Ū	for years	
Classroom #132 (Computer Lab)					
Ceiling - Lay-in 1st Floor	1,195	SF	5	2-5 years	
Doors - Steel Doors incl hw 1st Floor	1	EA	6	10+ years	
Doors - Transom Window 1st Floor	9	SF	6	10+ years	
Floor - Tile 1st Floor	1,195	SF	6	10+ years	
Lighting - Lay-in 1st Floor	24	EA	6	6-10 years	
Marker Board 1st Floor	10	LF	7	6-10 years	
Walls - Concrete Block 1st Floor	1,300	SF	6	10+ years	
Walls - Plaster/Drywall 1st Floor	1,140	SF	6	10+ years	
Wireless System 1st Floor	1	EA	7	6-10 years	
Classroom #134 (Store Room)					
Ceiling - Lay-in 1st Floor	2,058	SF	5	2-5 years	
Doors - Steel Doors incl hw 1st Floor	2	ĒA	6	10+ years	
Doors - Transom Window 1st Floor	18	SF	6	10+ years	
Floor - Tile 1st Floor	2,058	SF	6	10+ years	
Lighting - Lay-in 1st Floor	36	EA	6	6-10 years	
Marker Board 1st Floor	10	LF	6	6-10 years	
Wall Mirrors 1st Floor	40	SF	7	10+ years	
Walls - Concrete Block 1st Floor	6	SF	6	10+ years	
Walls - Concrete Block 1st Floor	3,619	SF	6	10+ years	
Work Sink 1st Floor	1	EA	7	10+ years	
Classroom #135 (Regular Classroom)					
Casework 1st Floor	14	LF	6	10+ years	
	750	SF			
			5	2-5 years	
Doors - Steel Doors incl hw 1st Floor	1	EA	6	10+ years	
Doors - Transom Window 1st Floor	9	SF	6	10+ years	
Floor - Tile 1st Floor	750	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
0				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Lay-in	1st Floor	15	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,270	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #200 (Multi Purpose Room)						
	Ceiling - Lay-in	2nd Floor	670	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	670	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	380	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	500	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
	Wileicos Oystern	211011001			,		
Classroo	om #201 (Regular Classroom)		2				
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	17	EA	6	6-10 years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	610	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	115	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	950	SF	6	10+ years	
Classro	om #203 (Special Program)						
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor		SF			
	Doors - Side-lite	2na Fioor	9	SF	6	10+ years	



Catego	ry : Classroom	Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	885	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	610	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
	Walls - Flastel/Drywall	2110 1 1001	540	51	0	10+ years	
Classroo	om #205 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	620	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Floor - Tile	2nd Floor	620	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	845	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	820	SF	7	10+ years	
Classroo	om #206 (Store Room)						
	Casework	2nd Floor	54	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,035	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1,000	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Eye Wash Station	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,035	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	24		6	6-10 years	
			24	SF			
	Science Lab Elements	2nd Floor	24	EA	7 7	10+ years	
	Science Lab Shower	2nd Floor	1	EA	1	10+ years	



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	645	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	645	SF	6	10+ years	
	Work Sink	2nd Floor	4	EA	7	10+ years	
					-	let jeale	
Classroo	m #208 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	2-5 years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	435	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
	Wallo Thatton Drywall	21011001	010	01	Ū	ior youro	
lassroo	m #209 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
Classroo	m #210 (Begular Classroom)						
Jassioo	<u>m #210 (Regular Classroom)</u> Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	5	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	20		6 7		
	Walls - Concrete Block	2nd Floor 2nd Floor		SF		6-10 years	
			115	SF SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	950	SF	6	10+ years	
Classroo	m #211 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	



m - Type bors - Transom Window bors - Wood Doors inclu hw bor - Tile ghting - Lay-in arker Board alls - Concrete Block alls - Metal Panel 212 (Eitness Room) asework biling - Lay-in bors - Transom Window bors - Wood Doors inclu hw bor - Tile ghting - Lay-in arker Board	Location 2nd Floor 2nd Floor	Quantity 7 1 835 18 12 455 610 15 1,180 14	UOM SF EA SF EA LF SF SF	Rank 6 6 6 7 6 6	Recommend Replacement 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years	Comments
ors - Transom Window ors - Wood Doors inclu hw oor - Tile ghting - Lay-in arker Board alls - Concrete Block alls - Metal Panel 212 (Fitness Room) asework villing - Lay-in oors - Transom Window oors - Wood Doors inclu hw oor - Tile ghting - Lay-in arker Board	2nd Floor 2nd Floor	7 1 835 18 12 455 610 15 1,180 14	SF EA EA LF SF SF	6 6 6 7 6 6	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	Comments
oors - Wood Doors inclu hw oor - Tile hting - Lay-in arker Board alls - Concrete Block alls - Metal Panel 212 (Fitness Room) asework wiling - Lay-in oors - Transom Window oors - Wood Doors inclu hw oor - Tile hting - Lay-in arker Board	2nd Floor 2nd Floor	1 835 18 12 455 610 15 1,180 14	EA SF EA LF SF SF	6 6 7 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	
oor - Tile phting - Lay-in arker Board alls - Concrete Block alls - Metal Panel 212 (Fitness Room) sework illing - Lay-in pors - Transom Window pors - Wood Doors inclu hw por - Tile phting - Lay-in arker Board	2nd Floor 2nd Floor	835 18 12 455 610 15 1,180 14	SF EA LF SF SF LF	6 6 7 6 6	10+ years 6-10 years 6-10 years 10+ years 10+ years	
hting - Lay-in arker Board alls - Concrete Block alls - Metal Panel 212 (Fitness Room) asework filing - Lay-in pors - Transom Window pors - Wood Doors inclu hw por - Tile ghting - Lay-in arker Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	18 12 455 610 15 1,180 14	EA LF SF SF LF	6 7 6 6	6-10 years 6-10 years 10+ years 10+ years	
arker Board alls - Concrete Block alls - Metal Panel 212 (Fitness Room) sework viling - Lay-in vors - Transom Window vors - Wood Doors inclu hw voor - Tile yhting - Lay-in arker Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	12 455 610 15 1,180 14	LF SF SF LF	7 6 6	6-10 years 10+ years 10+ years	
alls - Concrete Block alls - Metal Panel 212 (Fitness Room) sework viling - Lay-in vors - Transom Window vors - Wood Doors inclu hw vor - Tile yhting - Lay-in arker Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	455 610 15 1,180 14	SF SF LF	6 6	10+ years 10+ years	
alls - Metal Panel 212 (Fitness Room) Isework illing - Lay-in Iors - Transom Window Iors - Wood Doors inclu hw Iorr - Tile Inting - Lay-in Arker Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	610 15 1,180 14	SF	6	10+ years	
212 (Fitness Room) Isework Vors - Lay-in Vors - Transom Window Vors - Wood Doors inclu hw Voor - Tile Inting - Lay-in Arker Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	15 1,180 14	LF	-	10+ years	
sework biling - Lay-in bors - Transom Window bors - Wood Doors inclu hw bor - Tile ghting - Lay-in arker Board	2nd Floor 2nd Floor 2nd Floor	1,180 14		6	10+ years	
sework biling - Lay-in bors - Transom Window bors - Wood Doors inclu hw bor - Tile ghting - Lay-in arker Board	2nd Floor 2nd Floor 2nd Floor	1,180 14		6	10+ years	
oors - Transom Window oors - Wood Doors inclu hw oor - Tile yhting - Lay-in arker Board	2nd Floor 2nd Floor 2nd Floor	1,180 14		-		
oors - Transom Window oors - Wood Doors inclu hw oor - Tile yhting - Lay-in arker Board	2nd Floor 2nd Floor	14		6	10+ years	
oors - Wood Doors inclu hw oor - Tile yhting - Lay-in arker Board	2nd Floor		SF	6	10+ years	
oor - Tile hting - Lay-in arker Board		2	EA	6	10+ years	
hting - Lay-in arker Board		1,180	SF	6	10+ years	
arker Board	2nd Floor	25	EA	6	6-10 years	
	2nd Floor	16	LF	6	6-10 years	
	2nd Floor	840	SF	6	10+ years	
alls - Concrete Block alls - Plaster/Drywall	2nd Floor	249	SF	6	10+ years	
reless System	2nd Floor	249	EA	7		
reless System		I	EA	1	10+ years	
222 (Regular Classroom)						
iling - Lay-in	2nd Floor	835	SF	6	10+ years	
ors - Side-lite	2nd Floor	9	SF	6	10+ years	
ors - Transom Window	2nd Floor	7	SF	6	10+ years	
ors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
oor - Tile	2nd Floor	835	SF	6	10+ years	
ihting - Lay-in	2nd Floor	18	EA	6	6-10 years	
arker Board	2nd Floor	16		6	6-10 years	
alls - Concrete Block	2nd Floor	455	SF	6	10+ years	
alls - Metal Panel	2nd Floor	610	SF	6	10+ years	
223 (Regular Classroom)						
iling - Lay-in	2nd Floor	835	SF	6	10+ years	
ors - Side-lite	2nd Floor	9	SF		10+ years	
ors - Transom Window	2nd Floor	7	SF	6		
ors - Wood Doors inclu hw	2nd Floor	1	EA	6		
por - Tile		835				
					-	
arker Board						
alls - Concrete Block						
oogharlall all 22ilioooogh	rs - Wood Doors inclu hw r - Tile ting - Lay-in ker Board s - Concrete Block ls - Metal Panel 23 (Regular Classroom) ing - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw rr - Tile ting - Lay-in	rs - Wood Doors inclu hw 2nd Floor ting - Lay-in 2nd Floor ker Board 2nd Floor s - Concrete Block 2nd Floor s - Metal Panel 2nd Floor 23 (Regular Classroom) 23 (Regular Classroom) 21 (Floor 22 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 21 (Floor 21 (Floor 22 (Regular Classroom) 21 (Floor 21 (Flo	rs - Wood Doors inclu hw 2nd Floor 1 rr - Tile 2nd Floor 835 ting - Lay-in 2nd Floor 18 ker Board 2nd Floor 16 s - Concrete Block 2nd Floor 455 s - Metal Panel 2nd Floor 610 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 27 (Regular Classroom) 29 (Regular Classroom) 29 (Regular Classroom) 20 (Regular Classroom) 20 (Regular Classroom) 21 (Regular Classroom) 22 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 21 (Regular Classroom) 23 (Regular Classroom) 24 (Regular Classroom) 25 (Regular Classroom) 26 (Regular Classroom) 27 (Regular Classroom) 28 (Regular Classroom) 29 (Regular Classroom) 20 (Regular Classroom) 20 (Regular Classroom) 20 (Regular Classroom) 23 (Regular Classroom) 24 (Regular Classroom) 25 (Regular Classroom) 26 (Regular Classroom) 27 (Regular Classroom) 28 (Regular Classr	rs - Wood Doors inclu hw 2nd Floor 1 EA r - Tile 2nd Floor 835 SF ting - Lay-in 2nd Floor 18 EA ker Board 2nd Floor 16 LF s - Concrete Block 2nd Floor 455 SF s - Metal Panel 2nd Floor 610 SF 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 7 SF rs - Side-lite 2nd Floor 9 SF rs - Transom Window 2nd Floor 7 SF rs - Wood Doors inclu hw 2nd Floor 7 SF rs - Wood Doors inclu hw 2nd Floor 1 EA rr - Tile 2nd Floor 1 EA ting - Lay-in 2nd Floor 1 EA s - Concrete Block 2nd Floor 1835 SF ting - Lay-in 2nd Floor 1 EA s - Concrete Block 2nd Floor 12 LF s - Concrete Block 2nd Floor 12 LF	rs - Wood Doors inclu hw 2nd Floor 1 EA 6 rr - Tile 2nd Floor 835 SF 6 ting - Lay-in 2nd Floor 18 EA 6 ker Board 2nd Floor 16 LF 6 is - Concrete Block 2nd Floor 455 SF 6 is - Metal Panel 2nd Floor 610 SF 6 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 7 SF 6 rs - Side-lite 2nd Floor 9 SF 6 rs - Transom Window 2nd Floor 7 SF 6 rs - Transom Window 2nd Floor 7 SF 6 rs - Wood Doors inclu hw 2nd Floor 1 EA 6 ing - Lay-in 2nd Floor 1 EA 6 ting - Lay-in 2nd Floor 1835 SF 6 ting - Lay-in 2nd Floor 1835 SF 6 ting - Lay-in 2nd Floor 18 EA 6 ting - Lay-in 2nd Floor 12 LF 7 is - Concrete Block 2nd Floor 12 LF 7	rs - Wood Doors inclu hw 2nd Floor 1 EA 6 10+ years rr - Tile 2nd Floor 835 SF 6 10+ years ting - Lay-in 2nd Floor 18 EA 6 6-10 years ker Board 2nd Floor 16 LF 6 6-10 years s - Concrete Block 2nd Floor 455 SF 6 10+ years s - Metal Panel 2nd Floor 610 SF 6 10+ years 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 23 (Regular Classroom) 27 SF 6 10+ years 7 SF 6 10+ years 835 SF 6 10+ years 7 SF 6 10+ years 835 SF 6 10+ years 835 SF 6 10+ years 835 SF 6 10+ years 1 EA 6 10+ years 1 EA 6 10+ years 1 S SF 6 10+ years



Catego	ry : Classroom	Building : Main					
2						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
Classroo	om #225 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
Classroo	om #230 (Science Lab Level 3)						
	Casework	2nd Floor	54	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,035	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	. 7	SF	6	10+ years	
	Eye Wash Station	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,035	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Science Lab Elements	2nd Floor	24	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	645	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	645	SF	6	10+ years	
	Work Sink	2nd Floor	4	EA	7	10+ years	
Classroo	om #232 (Special Education)						
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	, 1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	12		6	6-10 years	
	Martor Dourd	21011001	12	LI	U	0 10 years	



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	532	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	266	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	266	SF	6	10+ years	
lassroo	m #233 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	532	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	266	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	266	SF	6	10+ years	
	Walls Thaster/Drywall	21011001	200	01	0	Tor years	
lassroo	m #234 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	266	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	799	SF	6	10+ years	
lassroo	m #235 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	610	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	455	SF	6	10+ years	
	Work Sink	2nd Floor	400	EA	7	10+ years	
	WOR SIIK	2110 ΓΙΟΟΙ	I	ĽA	1	ior years	
assroo	m #300 (Office)						
	Ceiling - Lay-in	3rd Floor	960	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	80	SF	6	10+ years	



Category : Classroom			Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years		
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	960	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years		
	Marker Board	3rd Floor	12	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	81	SF	5	10+ years		
	Walls - Concrete Block	3rd Floor	1,100	SF	6	10+ years		
	Walls - Metal Panel	3rd Floor	1,100	SF	6	10+ years		
	Wireless System	3rd Floor	1	EA	7	6-10 years		
Classroo	om #301 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years		
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years		
	Floor - Tile	3rd Floor	835	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	1,099	SF	6	10+ years		
	Walls - Metal Panel	3rd Floor	1,100	SF	6	10+ years		
			1,100	01	0	TO+ years		
Classroo	om #302 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	-	ĒA	6	10+ years		
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years		
	Floor - Tile	3rd Floor	835	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	8	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	1,100	SF	6	10+ years		
	Walls - Metal Panel	3rd Floor	1,100	SF	6	10+ years		
Classroo	om #303 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	9	EA	6	10+ years		
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years		
	Floor - Tile	3rd Floor	835	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	8		7	6-10 years		
	Walls - Concrete Block	3rd Floor	o 1,100	SF	6	10+ years		
	Walls - Metal Panel	3rd Floor	1,100	SF	6	-		
	vvalis - ivielai Faliei	310 1001	1,100	эг	U	10+ years		



Catego	ry : Classroom		В	uilding	: Main		•
_			• •			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classica							
Classico	m #304 (Regular Classroom)		044	05	0	10	
	Ceiling - Lay-in	3rd Floor	811	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	24	SF	4	0-1 year	Cracked tiles
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,100	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	1,100	SF	6	10+ years	
Classroo	m #305 (Regular Classroom)						
2100100	Ceiling - Lay-in	3rd Floor	620	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	ĒA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	620	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	845	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	820	SF	6	10+ years	
			020	01	Ũ	lot youro	
Classroo	m #306 (Science Lab Level 3)						
	Casework	3rd Floor	65	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,073	SF	7	10+ years	No damage observed
	Doors - Steel Doors incl hw	3rd Floor	3	EA	6	10+ years	
	Eye Wash Station	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,073	SF	6	10+ years	
	Gas Line	3rd Floor	8	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	20	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	6	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	910	SF	6	10+ years	
	Work Sink	3rd Floor	9	EA	5	2-5 years	
0						A	
Classroo	m #308 (Regular Classroom)	and Floor	005	<u> </u>	6	10, 10, 10, 10, 10, 10, 10, 10, 10, 10,	
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	



Juicgo	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	435	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	
lacero	om #309 (Regular Classroom)						
1000	,	3rd Floor	005	0	<u>^</u>	10	
	Ceiling - Lay-in		835	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	330	SF	6	10+ years	
	-			•	C C	jeule	
lassroc	om #310 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
				SF			
	Walls - Concrete Block Walls - Metal Panel	3rd Floor 3rd Floor	115 950	SF	6 6	10+ years	
	Walls - Metal Parlel	310 F1001	950	55	0	10+ years	
lassroo	om #311 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6		
						10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	610	SF	6	10+ years	
lassror	om #312 (Music Room)						
	Ceiling - Lay-in	3rd Floor	1,066	SF	6	10+ years	



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	3rd Floor	5	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	45	SF	6	10+ years	
	Floor - Tile	3rd Floor	1,066	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	22	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	183	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	1,800	SF	6	10+ years	
Classro	om #322 (Regular Classroom)						
_01222100	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4		
	Doors - Side-lite	3rd Floor		SF	-	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	12	EA	6	10+ years	
			1	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9		6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	610	SF	6	10+ years	
Classroo	om #323 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	ĒA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	115	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	950	SF	6	10+ years	
Clease	m #224 (Dogular Classroom)						
Classio	om #324 (Regular Classroom)	and Floor	005	0-	<u>^</u>	10, , , , , , , , , , , , , , , , , , ,	
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	



Catego	ry : Classroom		B	uilding	: Main		
	-					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #325 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	823	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	Cracked tiles
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	
Classroo	m #326 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	620	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	620	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	ĒA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	430	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	340	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	5	2-5 years	
Classroo	m #330 (Science Lab Level 3)						
_01033100	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,035	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	3	EA	6	10+ years	
	Eye Wash Station	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,035	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	ĒA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	6	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	645	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	645	SF	6	10+ years	
	Work Sink	3rd Floor	4	EA	5	2-5 years	
Classroo	m #332 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
			•	_, ,	~	, , , , , , , , , , , , , , , , , , , ,	



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,000	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,000	SF	6	10+ years	
Classroo	om #333 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	
Classroo	om #334 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	829	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Cracked tiles
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	115	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	950	SF	6	10+ years	
Classroo	om #335 (Regular Classroom)						
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	827	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Cracked tiles
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	610	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	4	0-1 year	Not in use
						-	



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #336 (Office)						
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	828	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	828	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,128	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	400	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	9,300	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	66	SF	4	0-1 year	Water damage and buckling.
	Ceiling - Plaster/Drywall	1st Floor	1,280	SF	6	10+ years	
	Doors - Side-lite	1st Floor	54	SF	6	10+ years	
	Doors - Store Front	1st Floor	8	EA	6	10+ years	
	Doors - Transom Window	1st Floor	56	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	12	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	10+ years	
	Floor - Concrete	1st Floor	216	SF	7	10+ years	
	Floor - Tile Quarry	1st Floor	740	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	9,690	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	154	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	8	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	153	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	5,000	SF	6	10+ years	
	Walls - Masonry	1st Floor	7,350	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	3,120	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	9,100	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	120	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	148	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	20	EA	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	9,100	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	116	EA	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	280	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	2,712	SF	6	10+ years	
	Walls - Masonry	2nd Floor	1,850	SF	6	10+ years	
			,				



Category : Interior			Building : Main					
_	-			_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Metal Panel	2nd Floor	5,215	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	280	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	8,514	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	120	SF	6	10+ years		
	Doors - Transom Window	3rd Floor	148	SF	6	10+ years		
	Doors - Wood Doors include hw	3rd Floor	16	EA	6	10+ years		
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	8,514	SF	5	10+ years		
	Lighting - Lay-in	3rd Floor	107	EA	6	6-10 years		
	Student Lockers - One Tier	3rd Floor	280	EA	6	10+ years		
	Walls - Concrete Block	3rd Floor	220	SF	6	10+ years		
	Walls - Masonry	3rd Floor	1,850	SF	6	10+ years		
	Walls - Metal Panel	3rd Floor	5,215	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,650	SF	6	10+ years		
Safety								
-	Camera Viewing Station	1st Floor	3	EA	7	6-10 years		
	Security Cameras	1st Floor	19	EA	7	6-10 years		
	Security Cameras	1st Floor	10	EA	7	6-10 years		
Stairs								
	Ceiling - Plaster/Drywall	East	780	SF	6	10+ years		
	Floor - Concrete Epoxy/ Painted	East	460	SF	5	10+ years		
	Handrails	East	120	LF	7	10+ years		
	Lighting - Pendent/Surface	East	6	EA	6	6-10 years		
	Lighting - Wall Mounted	East	1	EA	6	6-10 years		
	Stairs - Concrete	East	60	LF	6	10+ years		
	Walls - Concrete Block	East	2,100	SF	6	10+ years		
	Walls - Masonry	East	890	SF	6	10+ years		
	Ceiling - Lay-in	In Pool/Gym Wing	103	SF	6	10+ years		
	Floor - Concrete	In Pool/Gym Wing	52	SF	5	10+ years		
	Handrails	In Pool/Gym Wing	48	LF	5	10+ years		
	Lighting - Wall Mounted	In Pool/Gym Wing	3	EA	7	6-10 years		
	Stairs - Asphalt	In Pool/Gym Wing	24	LF	5	10+ years		
	Walls - Concrete Block	In Pool/Gym Wing	936	SF	6	10+ years		
	Ceiling - Lay-in	NW Stairs Adj to Library	200	SF	6	10+ years		
	Floor - Tile	NW Stairs Adj to Library	16	SF	6	10+ years		
	Handrails	NW Stairs Adj to Library	48	LF	7	10+ years		
	Lighting - Lay-in	NW Stairs Adj to Library	7	EA	6	6-10 years		
	Stairs - Rubber	NW Stairs Adj to Library	24	LF	6	10+ years		
	Walls - Masonry	NW Stairs Adj to Library	800	SF	6	10+ years		
	Ceiling - Plaster/Drywall	North	790	SF	6	10+ years		
	Floor - Concrete Epoxy/ Painted	North	460	SF	5	10+ years		
	Handrails	North	120	LF	7	10+ years		



ego	ry : Interior		Building : Main						
						Recommend			
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	North	10	EA	7	6-10 years			
	Stairs - Concrete	North	60	LF	5	10+ years			
	Walls - Concrete Block	North	2,100	SF	6	10+ years			
	Walls - Masonry	North	890	SF	6	10+ years			
	Ceiling - Lay-in	SE stairs adj. to Library	200	SF	6	10+ years			
	Floor - Tile	SE stairs adj. to Library	16	SF	6	10+ years			
	Handrails	SE stairs adj. to Library	48	LF	7	10+ years			
	Lighting - Lay-in	SE stairs adj. to Library	7	EA	6	6-10 years			
	Stairs - Rubber	SE stairs adj. to Library	24	LF	6	10+ years			
	Walls - Masonry	SE stairs adj. to Library	800	SF	6	10+ years			
	Ceiling - Plaster/Drywall	South	790	SF	6	10+ years			
	Floor - Concrete Epoxy/ Painted	South	460	SF	5	10+ years			
	Handrails	South	120	LF	7	10+ years			
	Lighting - Pendent/Surface	South	12	EA	7	6-10 years			
	Stairs - Concrete	South	60	LF	6	10+ years			
	Walls - Concrete Block	South	2,100	SF	6	10+ years			
	Walls - Masonry	South	890	SF	6	10+ years			
	Ceiling - Plaster/Drywall	West	780	SF	6	10+ years			
	Floor - Concrete Epoxy/ Painted	West	460	SF	4	0-1 year	Worn throughout.		
	Handrails	West	120	LF	5	10+ years			
	Lighting - Pendent/Surface	West	6	EA	6	6-10 years			
	Lighting - Wall Mounted	West	1	EA	6	6-10 years			
	Stairs - Concrete	West	60	LF	4	0-1 year	Worn throughout		
	Walls - Concrete Block	West	2,100	SF	6	10+ years	C C		
	Walls - Masonry	West	890	SF	6	10+ years			
						-			
ertical (Conveyance								
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years			



Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	Site South	9,400	SF	4	0-1 year	Worn and cracking throughout.
	Surface - Natural	South site	147,500	SF	5	2-5 years	Significant amount of mud.
Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	5	0-1 year	Sinking and standing water observe
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	17	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	16	EA	6	10+ years	
Fencing							
	Fencing - Chain Link	Entire Site	1,910	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	532	LF	4	0-1 year	Rusted and bent throughout
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	63	LF	6	10+ years	C C
andsca	pe						
	Benches	Entire Site	5	EA	6	6-10 years	
	Landscape - Grass	Entire Site	16,330	SF	6	10+ years	Muddy
	Landscape - Hardscape- Concrete	Entire Site	23,220	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	3,500	SF	4	0-1 year	Cracking, holes, vegetation growth.
	Parkway trees	Entire Site	42	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	2,910	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	645	SF	6	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	10+ years	
Parking I	ot						
	Surface - Asphalt	Parking Lot- South	34,900	SF	4	0-1 year	Severe cracking and potholes. Entir surface is crumbling
	Trash Enclosure - Chain Links	Parking Lot- South	912	SF	7	10+ years	
	Concrete Curbs	Parking Lot- West	363	LF	6	10+ years	
	Interior Plantings	Parking Lot- West	20	LF	6	10+ years	
	Surface - Asphalt	Parking Lot- West	6,310	SF	6	10+ years	
	Surface - Asphalt	Parking Lot- West	5,515	SF	6	10+ years	
	Vehicular Screening	Parking Lot- West	291	LF	6	10+ years	
Playgrou	nd						
-, 3	Equipment - Combo 3-12	West	1	EA	6	6-10 years	
	Surface - Poured Surface	West	1,838	SF	6	6-10 years	
Sidewalk	s						



							core e como ra cinez, orneago, ie cooer
Catego	Category : Site			uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	13,000	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	3,700	SF	4	0-1 year	Cracking, broken, uneven.
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main						-			
Computer Lab	Regular Classroom	1st Floor	132	132	1,195	100	10	N	N
Fitness Room	Computer Lab	2nd Floor	212		1,180	368	72	N	N
Multi Purpose Room	Regular Classroom	2nd Floor	200	200	670	184	35	Y	Y
Music Room	Music Room	3rd Floor	312	321	1,066	368	72	N	Ν
Office	Computer Lab	3rd Floor	300	300	960	184	36	N	Ν
Office	Regular Classroom	3rd Floor	336	336	828	230	45	N	Ν
Regular Classroom	Art Room	2nd Floor	204		835	460	90	Y	N
Regular Classroom	Regular Classroom	1st Floor	135	135	750	64	24	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	201		835	184	36	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	202		835	184	36	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	205		620	276	54	Y	
Regular Classroom	Regular Classroom	2nd Floor	208		835	184	36	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	209		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	210		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	211		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	222		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	223		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	224		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	225		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	233		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	234		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	235		835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	835	184	36	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	303	303	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	620	276	54	Y	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	322	322	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	323	323	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	324	324	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	325	325	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	326	326	620	276	54	Ý	N
Regular Classroom	Regular Classroom	3rd Floor	332	332	835	184	36	Ý	N
Regular Classroom	Regular Classroom	3rd Floor	333	333	835	184	36	Ý	N



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	3rd Floor	334	334	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	335	335	835	184	36	Y	N
Science Lab Level 3	Science Lab Level 3	1st Floor	106		1,035	0	0	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	230		1,035	0	0	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	306	306	1,073	0	0	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	330	330	1,035	0	0	N	N
Special Education	Regular Classroom	2nd Floor	232		835	184	36	Y	N
Special Program	Regular Classroom	2nd Floor	203		835	184	36	Y	N
Store Room	Regular Classroom	1st Floor	102		835	184	36	Y	N
Store Room	Regular Classroom	1st Floor	110		835	184	36	Y	N
Store Room	Regular Classroom	1st Floor	111		835	184	36	Y	N
Store Room	Regular Classroom	1st Floor	121	121/123	2,013	124	24	Y	N
Store Room	Regular Classroom	1st Floor	134	134	2,058	60	12	N	N
Store Room	Science Lab Level 3	2nd Floor	206		1,035	0	0	N	N
Vacant	Regular Classroom	1st Floor	101		835	184	36	Y	N
Vacant	Regular Classroom	1st Floor	103		835	184	36	Y	Ν
Vacant	Regular Classroom	1st Floor	104/105		1,455	460	90	Y	Ν
Vacant	Regular Classroom	1st Floor	108		835	184	36	Y	Ν
Vacant	Regular Classroom	1st Floor	109		835	184	36	Y	N