

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1928	3	55,088
Addition	1998	3	73,040
Campus Total			128,128

Catego	ry : Exterior	В	uilding				
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	pment						
	Cell Equipment - Antenna	Roof	6	EA	7	6-10 years	
	Cell Equipment - Cabinets	Roof	2	EA	7	6-10 years	
Entrance							
	Exterior Doors - Exterior FRP Door	#1 W	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 W	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1 W	75	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 W	40	LF	6	6-10 years	Minor chips
	Exterior Doors - Exterior FRP Door	#1.5 W	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1.5 W	1	EA	6	10+ years	
	Exterior Stairs - Stone	#1.5 W	3	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage Door	#11 E OVH	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#12	1	EA	6	6-10 years	
	Exterior Doors - Side lite	#12	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#12	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#12	36	LF	5	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#12	30	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#13 W	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#13 W	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#13 W	30	LF	5	1-2 years	Large crack
	Exterior Stairs - Stone	#13 W	50	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#13 W	25	LF	6	6-10 years	Minor chips



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior FRP Door	#2 W	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2 W	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2 W	75	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2 W	40	LF	5	6-10 years	Concrete has broken because the railing post
	Exterior Doors - Exterior FRP Door	#2.5 W	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2.5 W	2	EA	6	6-10 years	
	Exterior Stairs - Stone	#2.5 W	50	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2.5 W	25	LF	7	6-10 years	Repainted
	Exterior Doors - Exterior FRP Door	#3 S	2	EA	6	6-10 years	•
	Exterior Doors - Transom Lite	#3 S	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#3 S	60	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 S	30	LF	7	6-10 years	Railings
	Exterior Doors - Exterior Steel Door	11.5 N	1	EΑ	6	6-10 years	90
	Exterior Doors - Transom Lite	11.5 N	1	EΑ	7	10+ years	
	Exterior Boors Transom Lite	11.014	•	L/\	,	101 years	
Foundat							
	Foundation - Concrete	Entire Building	950	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	55,088	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	7	10+ years	New light fixtures
Roof Sys	stem						
	Access Ladder - Metal	East Low Roof	1	EA	7	10+ years	New
	Coping - Terra Cotta	East Low Roof	133	LF	7	10+ years	Repaired
	Downspouts - Interior Downspouts	East Low Roof	45	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	East Low Roof	133	LF	7	10+ years	Repaired
	Roof - Modified Bitumen	East Low Roof	1,897	SF	7	10+ years	New
	Roof Structure - Concrete	East Low Roof	1,897	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1,007	EA	7	10+ years	New ladders
	Access Ladder - Metal	Main Roof	1	EA	4	0-1 year	Dangerous transition from one ladder
		IVIAIIT IXOOI	'		4	0-1 year	to another.
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	42	LF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	30	LF	7	10+ years	
	Coping - Terra Cotta	Main Roof	464	LF	7	10+ years	Repaired
	Downspouts - Interior Downspouts	Main Roof	180	LF	6	10+ years	Ropallou
	Parapet - Parapet > 30"	Main Roof	465	LF LF	7	10+ years	Repaired
	Roof - Modified Bitumen	Main Roof	11,373	SF	7 7	10+ years 10+ years	New
			•				
	Roof Hatch - Metal Roof Structure - Concrete	Main Roof	2 11,373	EA SF	7 7	10+ years	New
	ROOLSTUCTURA - LONCTATA	Main Roof	11 3/3	>-	/	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
J 5 - 6						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Coping - Terra Cotta	North Low Roof	202	LF	7	10+ years	Repaired
	Downspouts - Interior Downspouts	North Low Roof	60	LF	6	6-10 years	•
	Parapet - Parapet < 16" Height	North Low Roof	202	LF	7	10+ years	Repaired
	Roof - Modified Bitumen	North Low Roof	3,770	SF	7	10+ years	New roof
	Roof Structure - Concrete	North Low Roof	3,770	SF	7	10+ years	
	Access Ladder - Metal	South Low Roof	. 1	EA	7	10+ years	
	Coping - Terra Cotta	South Low Roof	380	LF	7	10+ years	Repaired
	Downspouts - Interior Downspouts	South Low Roof	90	LF	6	6-10 years	- F
	Parapet - 16" - 30" Height	South Low Roof	380	LF	7	10+ years	Repaired
	Roof - Modified Bitumen	South Low Roof	8,347	SF	7	10+ years	•
	Roof - Modified Bitumen	South Low Roof	8	SF	5	0-1 year	Missing counter flashing
	Roof Hatch - Metal	South Low Roof	1	ĒΑ	7	10+ years	3
	Roof Structure - Concrete	South Low Roof	8,353	SF	7	10+ years	
Walls							
TTUILO	Cheek-Wall - Concrete	Entire Building	80	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	28,000	SF	7	10+ years	Recently fully tuck pointed
	Exterior Walls - Brick	Entire Building	500	SF	5	10+ years	Deteriorated mortar, some have oper
	Exterior Walls - Terra Cotta	Entire Building	2,800	SF	5	10+ years	joints
Windows	S						
	Clerestory - Glass Single-Pane	Entire Building	600	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	960	SF	6	6-10 years	
	Guard - Guards wire guard	Entire Building	1,040	SF	6	6-10 years	
	Lintels - Steel	Entire Building	472	LF	6	10+ years	
	Lintels - Stone	Entire Building	16	LF	6	6-10 years	
	Windows - Sash Aluminum	Entire Building	5,100	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
_		Location				Recommend	Commonto
Group	Item - Type ncy System	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	Automatic Transfer Switch	Boiler Room	2	EA	6	10+ years	ATS-1 & ATS-2. Quantity changed
		Dallan Danas		<b>-</b> ^	0		as total has been divided/aggregated
	Automatic Transfer Switch	Boiler Room Courtyard	1	EΑ	6	10+ years	ATS-3
	Emergency Generator- Outdoor- Natural Gas - 60 - 100 KW	Courtyard	1	EA	6	6-10 years	Serves emergency systems for the entire school. Unable to gain direct access at the time of assessment. Tested regularly per Building Engineer.
	Consumity Cychom CCTV	Entire Building	55,088	SF	5	6-10 years	<del>-</del>
	Security System - CCTV			0.			

Campus Name: Mckay Page : 3 of 45 Assessment Date: 10/12/2021



All M	Schools					69	901 S Fairfield AVENUE, Chicago, IL 60629
Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Auditoium and	Entire Building	3,140	SF	6	10+ years	
	Aisle Lighting				_		
	Emergency A/C Power - Corridors and	Entire Building	9,863	SF	6	10+ years	
	Stairs	F (	0.004	05	•	40	
	Emergency A/C Power - Gym	Entire Building Entire Building	3,021	SF SF	6	10+ years	
	Emergency A/C Power - Students Toilets Exit Signs - Auditoium	Entire Building	1,824 6	SF EA	6 6	10+ years 2-5 years	Ungraded since last accomment. No
	Exit Signs - Auditolum	Entire Building	b	EA	O	2-5 years	Upgraded since last assessment. No deficient exit signs are present.
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	6	2-5 years	denoient exit signs are present.
	Exit Signs - Gym	Entire Building	2	EΑ	6	2-5 years	Upgraded since last assessment
	Emergency Battery Packs - Auditoium and	Entire Building	7	EΑ	6	6-10 years	opg. acca coc lact accoccc
	Aisle Lighting	g				- · · · <b>,</b> · · · ·	
Main Sei	rvice Main Electrical Service - 1600 A	Electrical Room	1	EA	6	6-10 years	
	120/208/3PH	Liectrical Room	'	LA	O	0-10 years	
	PA System	Entire Building	55,088	SF	6	6-10 years	Served by Addition
		g			-	5 . c , c c	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	17	EA	6	10+ years	Quantity changed as total has been
	Main Distribution Danala 400 000 ann	Catina Duildina	0	Ε.	•	10	divided/aggregated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	Quantity changed to match current observations.
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	Quantity changed to match current
	amp	Little Building	,	_/\	O	101 years	observations.
	· 		_				
Catego	ry : Fire Protection		В	uilding	: Main	Decemmend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar		Location	Quantity	OCIVI	Italik	Replacement	Comments
FIIE AIAI	Fire Alarm_System	Entire Building	55,088	SF	4	0-1 year	FACP is in Addition. No strobes and
	The Alami_System	Littile Building	33,000	Si	4	0-1 year	dated devices in Main.
							aatoa ao tiooo iii maiiii
Catego	ry : Mechanical		В	uilding	: Main		
Group	Itam - Typa	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity	UUIVI	Nank	Nepiacement	Comments
AIT Hand	lling Systems	Machanical Dage	4	Г^		6.40	ALILL 1 auditorium
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-1, auditorium
	Air Intake	Mechanical Room	1	EA	6	6-10 years	Common with AHU-2
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	Common with Arro-2
				_, 、	J	o io youio	



Category : Mechanical			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	20	LF	6	10+ years	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-4, gym
	Air Intake	Mechanical Room	1	EA	6	6-10 years	Common with AHU-3
	Auxiliaries - 4000 - 8000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	20	LF	6	10+ years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-2, serves north.
	Air Intake	Mechanical Room	1	EA	6	10+ years	Common with AHU-1
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	4	EA	6	10+ years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	60	LF	6	10+ years	
	Zone Dampers	Mechanical Room	13	EA	6	10+ years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-3, south
	Air Intake	Mechanical Room	1	EA	5	6-10 years	Common with AHU-4
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	6	EA	6	10+ years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	6	10+ years	
	Zone Dampers	Mechanical Room	20	EA	6	10+ years	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	7	10+ years	Serves AHU-1, auditorium. Installed in 2020.
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	7	10+ years	Serves AHU-2, north. Installed in 2020. Quantity changed to match current observations.
	Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM	Roof	1	EA	7	10+ years	Serves AHU-3, south. Installed in 2020.
	Outdoor Return Fans- Air Handling Unit Type - Less than 5000 CFM	Roof	1	EA	7	10+ years	Serves AHU-4, gym. Installed in 2020.
Boiler Sy	ystems						
•	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	2	EA	6	10+ years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	

Campus Name: Mckay Page : 5 of 45 Assessment Date: 10/12/2021



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	4	2-5 years	Leaks repaired throughout the system with no active leaks. RUL adjusted to match current observations.
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	6-10 years	
	Steam Traps	Boiler Room	78	EA	5	6-10 years	Quantity changed to match current conditions/observations.
Heating	Devices						
Ū	Unit Heater - Steam	Boiler Room	1	EA	5	2-5 years	
	Radiators - Steam	Entire Building	16	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	14	EA	5	2-5 years	Quantity changed to match current observations.
	Fin Tube - Steam	Entire Building	8	LF	6	6-10 years	
Tempera	ture Control						
•	DDC System	Entire Building	55,088	SF	6	6-10 years	Upgraded since last assessment per Building Engineer. Serves the entire school.
	Electric Thermostat	Entire Building	1	EA	5	6-10 years	Serves the unit heater.
	Thermostats - DDC	Entire Building	35	EA	6	10+ years	33 zone dampers and 2 single zone AHUs.
Ventilatio	200						
Zemilani	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	10+ years	Installed in 2020.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	Installed in 2020. Quantity changed to match current observations.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	1	EA	7	10+ years	Installed in 2020.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	10+ years	Installed in 2020.
	Roof Mounted Duct Work	Roof	70	LF	7	10+ years	Installed in 2020
	Roof Mounted Duct Work	Roof	24	LF	7	10+ years	Installed in 2020
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
				_, ·	_	J . J J J J J J J J J J J J J J J J J J	



Catego	ry : Plumbing		В	uilding	: Main		
Group Piping	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
iping	Domestic Piping-Hot Water Return Lines	Entire Building	55,088	SF	4	2-5 years	No current active leaks but some pip clamps throughout the system; galvanized piping over 40 years old. RUL adjusted to match current observations.
	Domestic Piping-Hot Water Return Risers	Entire Building	55,088	SF	4	2-5 years	No current active leaks but some piclamps throughout the system; galvanized piping over 40 years old RUL adjusted to match current observations.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	55,088	SF	4	2-5 years	No current active leaks but some pip clamps throughout the system; galvanized piping over 40 years old. RUL adjusted to match current observations.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	55,088	SF	4	2-5 years	No current active leaks but some pil clamps throughout the system; galvanized piping over 40 years old
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	55,088	SF	4	2-5 years	No current active leaks but some pip clamps throughout the system; galvanized piping over 40 years old. RUL adjusted to match current observations.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	55,088	SF	4	2-5 years	No current active leaks but some pi clamps throughout the system; galvanized piping over 40 years old RUL adjusted to match current observations.
	Sanitary Piping	Entire Building	55,088	SF	5	6-10 years	
	Storm Piping	Entire Building	55,088	SF SF	6 5	10+ years	
	Vent Piping	Entire Building	55,088	SF	3	6-10 years	
umps							
	Pumps - Domestic Booster Pump-Duplex Pumps - Sump-Duplex	Mechanical Room Mechanical Room	1	EA EA	5 5	6-10 years 6-10 years	Serves the entire school
atego	ry : Room		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	rative Suites/Offices						
	Ceiling - Plaster/Drywall Doors - Transom Window	202 Office 202 Office	340 8	SF SF	6 6	10+ years 10+ years	



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	202 Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	202 Office	340	SF	7	10+ years	
	Lighting - Pendent/Surface	202 Office	4	EA	6	6-10 years	
	Power Distribution	202 Office	2	EA	6	10+ years	
	Walls - Masonry	202 Office	448	SF	6	10+ years	
	Walls - Plaster/Drywall	202 Office	448	SF	6	10+ years	
	AC Unit	302 Office	1	EA	5	6-10 years	
	Ceiling - Lay-in	302 Office	340	SF	6	10+ years	
	Doors - Transom Window	302 Office	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	302 Office	1	EA	6	10+ years	
	Floor - Wood	302 Office	340	SF	6	6-10 years	
	Lighting - Lay-in	302 Office	4	EA	7	6-10 years	
	Power Distribution	302 Office	2	EA	6	10+ years	
	Walls - Masonry	302 Office	448	SF	6	10+ years	
	Walls - Plaster/Drywall	302 Office	448	SF	6	10+ years	
	AC Unit	Counselors Office	1	EA	4	2-5 years	
	Ceiling - Lay-in	Counselors Office	145	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselors Office	1	EA	6	10+ years	
	Floor - Tile	Counselors Office	145	SF	6	6-10 years	
	Lighting - Lay-in	Counselors Office	4	ĒΑ	6	6-10 years	
	Power Distribution	Counselors Office	2	EA	6	10+ years	
	Walls - Plaster/Drywall	Counselors Office	445	SF	6	10+ years	
	Ceiling - Lay-in	Engineer office in boiler room	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer office in boiler room	1	ĒΑ	6	10+ years	
	Floor - Tile	Engineer office in boiler room	80	SF	6	10+ years	
	Floor - Tile	Engineer office in boiler room	20	SF	4	0-1 year	9x9 tile possible asbestos
	Lighting - Lay-in	Engineer office in boiler room	2	ĒΑ	7	6-10 years	ene ine pessione descende
	Walls - Plaster/Drywall	Engineer office in boiler room	396	SF	6	10+ years	
	AC Unit	Office next to 103	1	EA	5	2-5 years	
	Ceiling - Lay-in	Office next to 103	724	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office next to 103	1	EA	6	10+ years	
	Floor - Tile	Office next to 103	724	SF	6	10+ years	
	Lighting - Lay-in	Office next to 103	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	Office next to 103	946	SF	6	10+ years	
	Ceiling - Lay-in	Room 110	153	SF	6	10+ years	
	Doors - Transom Window	Room 110	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 110	1	EA	6	10+ years	
	Floor - Wood	Room 110	153	SF	6	10+ years	
	Lighting - Lay-in	Room 110	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 110	478	SF	6	10+ years	
	vvans - i lasten/biywan	NOOM 110	410	OI.	0	10+ years	
ditoriu	ım & Theater						
	Balcony Seating	1st Floor	101	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,140	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		· ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Carpet	1st Floor	3,140	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	22	EA	7	6-10 years	
	Main Floor Seating	1st Floor	282	EA	7	10+ years	
	Stage	1st Floor	400	SF	6	10+ years	
	Stage Curtain	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	4	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,642	SF	6	10+ years	
Gymnasi	ia .						
•	Ceiling - Plaster/Drywall	1st Floor	3,021	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	3,021	SF	6	10+ years	Edited to match room size
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	200	SF	7	6-10 years	Repaired
	Walls - Plaster/Drywall	1st Floor	7,124	SF	6	10+ years	
	•		.,			, , , , , , , , , , , , , , , , , , ,	
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	1,497	SF	7	10+ years	
	Janitor's Closet	1st Floor	60	SF	7	10+ years	
	Storage Room	1st Floor	608	SF	7	10+ years	
	Janitor's Closet	2nd Floor	86	SF	5	10+ years	
	Janitor's Closet	3rd Floor	30	SF	5	6-10 years	
	Storage Room	3rd Floor	336	SF	5	6-10 years	Floor has been refinished
Restroon	n						
	Accessories	1st Floor Men's Staff	126	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Men's Staff	126	SF	6	10+ years	
	Doors - Transom Window	1st Floor Men's Staff	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Men's Staff	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Men's Staff	126	SF	6	6-10 years	
	Lavatory	1st Floor Men's Staff	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Men's Staff	1	EA	6	6-10 years	
	Partitions	1st Floor Men's Staff	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Men's Staff	285	SF	7	6-10 years	Repaired
	Water Closet	1st Floor Men's Staff	2	EA	6	10+ years	- p. 200
	Accessories	1st Fir Boys next to 104	282	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fir Boys next to 104	280	SF	6	10+ years	
	Doors - Transom Window	1st Fir Boys next to 104	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fir Boys next to 104	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Fir Boys next to 104	282	SF	5	6-10 years	
	Floor Drain	1st Fir Boys next to 104	1	EA	7	10+ years	
	i iooi Dialli	ISCI II DOYS HEAL TO TO	Į.	$\vdash \cap$	ı	IUT years	

Campus Name: Mckay Page : 9 of 45 Assessment Date: 10/12/2021



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st FIr Boys next to 104	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Flr Boys next to 104	4	EA	6	6-10 years	
	Partitions	1st FIr Boys next to 104	2	EA	7	10+ years	
	Urinals	1st FIr Boys next to 104	6	EA	6	10+ years	
	Walls - Plaster/Drywall	1st FIr Boys next to 104	304	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Flr Boys next to 104	304	SF	6	10+ years	
	Water Closet	1st FIr Boys next to 104	2	EA	6	10+ years	
	Accessories	1st flr Girls across from 111	348	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr Girls across from 111	340	SF	6	6-10 years	
	Doors - Transom Window	1st flr Girls across from 111	20	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st flr Girls across from 111	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr Girls across from 111	346	SF	5	6-10 years	
	Floor Drain	1st flr Girls across from 111	1	ĒΑ	7	10+ years	
	Lavatory	1st flr Girls across from 111	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st flr Girls across from 111	3	EA	6	6-10 years	
	Partitions	1st flr Girls across from 111	8	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st flr Girls across from 111	316	SF	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st flr Girls across from 111	316	SF	6	6-10 years	
	Water Closet	1st flr Girls across from 111	8	EA	6	10+ years	
	Accessories	2nd Floor Women's	126	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Women's	126	SF	6	10+ years	
	Doors - Transom Window	2nd Floor Women's	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Women's	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Women's	126	SF	6	10+ years	
	Lavatory	2nd Floor Women's	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Women's	1	EΑ	6	6-10 years	
	Partitions	2nd Floor Women's	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Women's	285	SF	6	10+ years	
	Water Closet	2nd Floor Women's	2	EA	6	10+ years	
	Accessories	2nd Floor Women's 2nd Flr Boys next to 204	282	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Fir Boys next to 204	282	SF	6	10+ years	
	Doors - Transom Window	2nd Fir Boys next to 204	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Fir Boys next to 204	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Fir Boys next to 204	282	SF	6	10+ years	
	Floor Drain	2nd Fir Boys next to 204  2nd Fir Boys next to 204	1	EA	7	10+ years	
	Lavatory	2nd Fir Boys next to 204	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Fir Boys next to 204  2nd Fir Boys next to 204	4	EA	6	6-10 years	
	Partitions		7	EA	7		
	Urinals	2nd FIr Boys next to 204 2nd FIr Boys next to 204	6	EA	6	10+ years 10+ years	
	Walls - Plaster/Drywall		304	SF	6	-	
	Walls - Plaster/Drywaii Walls - Structural Glazed Tile	2nd Fir Boys next to 204	304 304	SF SF	7	10+ years	
		2nd Fir Boys next to 204	304 7	SF EA	, 6	10+ years	
	Water Closet Accessories	2nd Flr Boys next to 204 2nd flr Girls across from 209	7 348	SF	6 7	10+ years	
		2nd fir Girls across from 209	348	SF SF	6	6-10 years	
	Ceiling - Plaster/Drywall	ZIIU III GIIIS ACIUSS IIUIII ZUS	3 <del>4</del> 0	SF	O	10+ years	

Campus Name: Mckay Page : 10 of 45 Assessment Date: 10/12/2021



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd flr Girls across from 209	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd flr Girls across from 209	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd flr Girls across from 209	348	SF	6	10+ years	
	Floor Drain	2nd flr Girls across from 209	1	EA	7	10+ years	
	Lavatory	2nd flr Girls across from 209	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd flr Girls across from 209	3	EA	6	6-10 years	
	Partitions	2nd flr Girls across from 209	8	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd flr Girls across from 209	316	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd flr Girls across from 209	316	SF	6	10+ years	
	Water Closet	2nd flr Girls across from 209	8	EA	6	10+ years	
	Accessories	3rd FIr Boys next to 304	282	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd FIr Boys next to 304	282	SF	6	10+ years	No water damage present
	Doors - Transom Window	3rd FIr Boys next to 304	20	SF	6	10+ years	<b>.</b>
	Doors - Wood Doors inclu hw	3rd Flr Boys next to 304	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Flr Boys next to 304	282	SF	6	10+ years	
	Floor Drain	3rd Flr Boys next to 304	1	EA	7	10+ years	
	Lavatory	3rd Flr Boys next to 304	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Flr Boys next to 304	4	EA	6	6-10 years	
	Partitions	3rd Flr Boys next to 304	2	EA	7	10+ years	
	Urinals	3rd Flr Boys next to 304	5	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Flr Boys next to 304	304	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Flr Boys next to 304	304	SF	6	10+ years	
	Water Closet	3rd Flr Boys next to 304	2	EA	6	10+ years	
	Accessories	3rd flr Girls next to 308	282	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd flr Girls next to 308	282	SF	6	10+ years	
	Doors - Transom Window	3rd flr Girls next to 308	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd flr Girls next to 308	4	ĒA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd flr Girls next to 308	282	SF	6	10+ years	
	Floor Drain	3rd flr Girls next to 308	1	EA	7	10+ years	
	Lavatory	3rd flr Girls next to 308	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd flr Girls next to 308	3	EA	6	6-10 years	
	Partitions	3rd flr Girls next to 308	7	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd flr Girls next to 308	304	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd flr Girls next to 308	304	SF	6	10+ years	
	Water Closet	3rd flr Girls next to 308	7	EA	6	10+ years	
	Accessories	Auditorium men	4	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Auditorium men	89	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Auditorium men	1	EA	6	6-10 years	
	Floor - Tile Quarry	Auditorium men	89	SF	6	2-5 years	
	Floor Drain	Auditorium men	1	EA	7	6-10 years	
	Lavatory	Auditorium men	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Auditorium men	1	EA	6	6-10 years	
	Partitions	Auditorium men	1	EA	5	6-10 years	
	Urinals	Auditorium men	1	EA	6	6-10 years	
			•		•	,	

Campus Name: Mckay Page : 11 of 45 Assessment Date: 10/12/2021



Catego	ry : Room	-	Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Plaster/Drywall	Auditorium men	271	SF	6	6-10 years				
	Water Closet	Auditorium men	1	EA	6	6-10 years				
	Accessories	Auditorium women	4	SF	5	2-5 years				
	Ceiling - Plaster/Drywall	Auditorium women	89	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	Auditorium women	1	EA	6	6-10 years				
	Floor - Tile Quarry	Auditorium women	89	SF	6	6-10 years				
	Floor Drain	Auditorium women	1	ĒΑ	7	6-10 years				
	Lavatory	Auditorium women	1	EA	6	6-10 years				
	Lighting - Pendent/Surface	Auditorium women	1	EA	6	6-10 years				
	Partitions	Auditorium women	1	EA	5	6-10 years				
	Walls - Plaster/Drywall	Auditorium women	266	SF	6	6-10 years				
	Walls - Plaster/Drywall	Auditorium women	5	SF	5	1-2 years				
	Water Closet	Auditorium women	1	EA	7	10+ years				
	Accessories	Restroom in Counselors Office	23	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Restroom in Counselors Office	23	SF	6	2-5 years				
	Doors - Wood Doors inclu hw	Restroom in Counselors Office	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Restroom in Counselors Office	23	SF	6	6-10 years				
	Lavatory	Restroom in Counselors Office	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Restroom in Counselors Office	1	EA	6	6-10 years				
	Walls - Plaster/Drywall	Restroom in Counselors Office	175	SF	6	10+ years				
	Water Closet	Restroom in Counselors Office	1/3	EA	6	10+ years				
	Accessories	Restroom in Engineers Office	40	SF	7	•				
	Ceiling - Plaster/Drywall	Restroom in Engineers Office	40	SF	6	10+ years	Damagad			
	Doors - Wood Doors inclu hw	Restroom in Engineers Office	-	EA	-	1-2 years	Damaged			
		Restroom in Engineers Office	1 25		6	2-5 years				
	Floor - Tile			SF	6	2-5 years	OvO tile demonstrad missions			
	Floor - Tile	Restroom in Engineers Office	15	SF	4	0-1 year	9x9 tile damaged missing			
	Lavatory	Restroom in Engineers Office	1	EΑ	6	1-2 years				
	Lighting - Pendent/Surface	Restroom in Engineers Office	1	EA	6	2-5 years	<b>.</b>			
	Walls - Plaster/Drywall	Restroom in Engineers Office	208	SF	5	1-2 years	Damaged			
	Water Closet	Restroom in Engineers Office	1	EA	6	2-5 years				
Catogo	ry : Classroom		D	uilding	· Main					
Calego	iy. Glassi Odili		D	unung	. IVIAIII	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
•	om #103 (Regular Classroom)	200000			- Carin	. topicomont				
Ciassiuc	Casework	1st Floor	9	LF	6	10+ years				
	Casework Ceiling - Lay-in	1st Floor	574	SF	6	10+ years				
	Doors - Transom Window		_	SF SF	-	-				
	Doors - Transom Window  Doors - Wood Doors inclu hw	1st Floor	8 1	SF EA	6	10+ years				
		1st Floor		SF	6	10+ years				
	Floor - Tile	1st Floor	574		7	10+ years				
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st Floor	638	SF	6	10+ years				
Classroo	m #104 (Regular Classroom)									

Campus Name: Mckay Page : 12 of 45 Assessment Date: 10/12/2021



Category : Class	room		E	Building	: Main		
				_		Recommend	
Group Item - Ty		Location	Quantity	UOM	Rank	Replacement	Comments
AC Units		1st Floor	1	EA	5	2-5 years	
Casewor		1st Floor	9	LF	6	10+ years	
Ceiling -		1st Floor	746	SF	6	10+ years	
Doors - T	ransom Window	1st Floor	16	SF	6	10+ years	
Doors - V	Vood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - W		1st Floor	746	SF	6	6-10 years	Repaired
Lighting		1st Floor	12	EA	7	6-10 years	
	laster/Drywall	1st Floor	27	SF	7	6-10 years	Repaired
Walls - P	laster/Drywall	1st Floor	919	SF	6	10+ years	
Classroom #105 (R	egular Classroom)						
AC Units		1st Floor	1	EA	5	2-5 years	
Casewor	k	1st Floor	9	LF	6	10+ years	
Ceiling -		1st Floor	574	SF	6	10+ years	
	ransom Window	1st Floor	8	SF	6	10+ years	
	Vood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Ti	le	1st Floor	574	SF	7	10+ years	
Lighting	- Lay-in	1st Floor	12	EA	7	6-10 years	
	laster/Drywall	1st Floor	638	SF	6	10+ years	
Classroom #107 (R	egular Classroom)						
AC Units		1st Floor	1	EA	7	6-10 years	New ac unit
Casewor		1st Floor	40	LF	6	10+ years	
Ceiling -		1st Floor	666	SF	6	10+ years	
	ransom Window	1st Floor	16	SF	6	10+ years	
	Vood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
Floor - W		1st Floor	666	SF	6	10+ years	
Lighting		1st Floor	12	ĒΑ	7	6-10 years	
Marker B		1st Floor	16	LF	6	10+ years	
	laster/Drywall	1st Floor	925	SF	6	10+ years	
Classroom #108 (R	egular Classroom)						
AC Units		1st Floor	1	EA	7	6-10 years	New ac unit
Casewor		1st Floor	9	LF	6	10+ years	
Ceiling -		1st Floor	746	SF	6	10+ years	
	ransom Window	1st Floor	16	SF	6	10+ years	
	Vood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Ti		1st Floor	746	SF	7	10+ years	
Lighting		1st Floor	12	EΑ	7	6-10 years	
Marker B	,	1st Floor	18	LF	7	6-10 years	
	laster/Drywall	1st Floor	946	SF	6	10+ years	
_Classroom #111 (R	egular Classroom)						

Campus Name: Mckay Page : 13 of 45 Assessment Date: 10/12/2021



Catego	ory : Classroom		В	uilding	: Main		501 01 amilia Avenoe, omcago, le 00025
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	Repaired
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	724	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	724	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	925	SF	6	10+ years	
Classroo	om #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	2-5 years	
	Casework	1st Floor	13	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	326	SF	6	10+ years	
	Chalk Board	1st Floor	52	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood Doors inclu riw	1st Floor	326	SF	6	10+ years	
		1st Floor	6	EA	7		
	Lighting - Lay-in		_		7	6-10 years	
	Marker Board	1st Floor	18	LF SF		6-10 years	
	Walls - Plaster/Drywall	1st Floor	438	SF	6	10+ years	
Classroo	om #113 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	724	SF	6	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	724	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	925	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	724	SF	6	10+ years	
	Chalk Board	2nd Floor	52	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	724	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	925	SF	6	10+ years	
	Trans Taster, Dry Wall	2110 1 1001	923	Ji	U	TOT years	

Campus Name: Mckay Page : 14 of 45 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Main		501 01 amilia AVENOE, Officago, ie 00025
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	724	SF	6	10+ years	
	Chalk Board	2nd Floor	52	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	724	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	925	SF	6	10+ years	
_Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	52	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	940	SF	6	10+ years	
	•					,	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	724	SF	6	10+ years	
	Chalk Board	2nd Floor	52	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	724	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	925	SF	6	10+ years	
_Classroo	om #206 (Store Room)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	52	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood Bools Inclu IIW	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	944	SF	7	•	
	vvalis - Flastel/DiyWall	ZHU FIUUI	944	ЗF	,	10+ years	

Campus Name: Mckay Page : 15 of 45 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Main			
	W		•	11614		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #207 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	9	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	724	SF	6	10+ years		
	Chalk Board	2nd Floor	52	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	16	SF	6	•		
	Doors - Wood Doors inclu hw		2	EA	6	10+ years		
		2nd Floor			-	10+ years		
	Floor - Wood	2nd Floor	724	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	925	SF	6	10+ years		
Classroo	m #208 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	9	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	746	SF	6	10+ years		
	Chalk Board	2nd Floor	54	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years		
	Floor - Wood	2nd Floor	746	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years		
				SF		•		
	Walls - Plaster/Drywall	2nd Floor	946		6	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
Classroo	m #209 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	22	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	700	SF	6	10+ years		
	Chalk Board	2nd Floor	14	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	700	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	925	SF	6			
					-	10+ years		
	Work Sink	2nd Floor	1	EΑ	5	10+ years		
	Work Sink	2nd Floor	1	EA	5	10+ years		
Classroo	m #210 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	21	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	312	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	10+ years		
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years		
	200.0 Halloom William	2110 1 1001	O	<b>J</b> i	J	ioi youis		

Campus Name: Mckay Page : 16 of 45 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	312	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	420	SF	6	10+ years	
Classroo	m #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	22	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	700	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6		
					_	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	700	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	925	SF	6	10+ years	
Classroc	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	600	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	600	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EΑ	6	6-10 years	
	Walls - Concrete Block	2nd Floor	298	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	925	SF	6	10+ years	
Classroo	m #301 (Regular Classroom)						
Oldssioc	AC Units	3rd Floor	1	EA	5	6-10 years	
	Casework		9	LF			
		3rd Floor		SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	724		6	10+ years	
	Chalk Board	3rd Floor	52	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	724	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	925	SF	6	10+ years	
Classroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	5	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	54	LF	4	2-5 years	
		5.455.	01		·	20,00.0	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	2	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	951	SF	6	10+ years	
Classroo	om #304 (Regular Classroom)						
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	738	SF	6	10+ years	
	Chalk Board	3rd Floor	52	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
					_	,	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	738	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	952	SF	6	10+ years	
Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	5	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	54	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	951	SF	6	10+ years	
Classroo	om #306 (Regular Classroom)						
0.000.00	AC Units	3rd Floor	1	EA	5	6-10 years	
	Casework	3rd Floor	9	LF	6	•	
		3rd Floor		SF	6	10+ years	Edited to match room size
	Ceiling - Lay-in		720		_	10+ years	Edited to match room size
	Chalk Board	3rd Floor	52	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	940	SF	6	10+ years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	6-10 years	
	Chalk Board	3rd Floor	54	LF	4	2-5 years	
	Shain Board	0.4 1.001	J+		7	2 o yours	

Campus Name: Mckay Page : 18 of 45 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	2	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EΑ	6	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	951	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	54	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	951	SF	6	10+ years	

**Building: Main** Category: Interior

						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Corridor</u>							
	Ceiling - Lay-in	1st Floor	3,382	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,382	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	15	SF	4	1-2 years	Damaged
	Lighting - Lay-in	1st Floor	39	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	133	EA	6	10+ years	
	Student Lockers - One Tier	1st Floor	17	EA	5	1-2 years	Damaged
	Walls - Plaster/Drywall	1st Floor	2,708	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,708	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,120	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	262	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	2nd Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,382	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	33	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EΑ	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	153	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,708	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,708	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,840	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	3rd Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	7	10+ years	

Campus Name: Mckay Page : 19 of 45 Assessment Date: 10/12/2021



Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	3rd Floor	1,840	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	27	EΑ	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	91	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,476	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,476	SF	6	10+ years	
Safety							
·	Security Cameras	Entire Building	2	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Stair 113	389	SF	6	10+ years	
	Floor - Tile	Stair 113	389	SF	7	10+ years	
	Handrails	Stair 113	116	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair 113	8	EA	7	6-10 years	
	Stairs - Terrazzo	Stair 113	58	LF	7	10+ years	
	Walls - Plaster/Drywall	Stair 113	1,980	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stair 113	1,980	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair by Assembly Hall	435	SF	6	10+ years	
	Floor - Terrazzo	Stair by Assembly Hall	435	SF	7	10+ years	
	Handrails	Stair by Assembly Hall	116	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair by Assembly Hall	8	EA	7	6-10 years	
	Stairs - Terrazzo	Stair by Assembly Hall	58	LF	7	10+ years	
	Walls - Plaster/Drywall	Stair by Assembly Hall	1,980	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stair by Assembly Hall	1,980	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair by Gymnasium	435	SF	6	10+ years	
	Floor - Tile	Stair by Gymnasium	435	SF	7	10+ years	
	Handrails	Stair by Gymnasium	116	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair by Gymnasium	8	EA	7	6-10 years	
	Stairs - Terrazzo	Stair by Gymnasium	58	LF	7	10+ years	
	Walls - Masonry	Stair by Gymnasium	1,980	SF	6	10+ years	
	Walls - Plaster/Drywall	Stair by Gymnasium	1,980	SF	6	10+ years	



Category : Exterior **Building: Addition** 

Recommend							
	Name Tame	Lagadan	0	LIONS	David		0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Exterior Doors - Exterior Steel Door	#10 Exit W	2	EA	6	6-10 years	
	Exterior Doors - Store Front	#4 W	2	EA	5	1-2 years	Missing hardware
	Entrance Control - Audio and Video	#5 S	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#5 S	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#5 S	1	EΑ	6	6-10 years	
	Entrance Control - Audio and Video	#6 E	1	EA	6	6-10 years	
	Exterior Doors - Side lite	#6 E	4	EA	6	6-10 years	
	Exterior Doors - Store Front	#6 E	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#6 E	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6 E	48	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#6 E	120	LF	6	2-5 years	
	Ramps - Concrete	#6 E	60	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#6 E	30	LF	6	6-10 years	
	Exterior Doors - Store Front	#7 E	2	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	#7 E	48	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	#7 E	30	LF	7	6-10 years	Railing was repainted
	Exterior Doors - Store Front	#8 E	2	ĒΑ	6	6-10 years	rading rate repairment
	Exterior Doors - Exterior Steel Door	#8.5 E	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#8.5 E	24	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#8.5 E	20	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9 Exit E	1	EA	6	2-5 years	
	Exterior Stairs - Concrete	#9 Exit E	24	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#9 Exit E	62	LF	7	10+ years	
	Ramps - Concrete	#9 Exit E	30	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#9 Exit E	20	LF	7	6-10 years	Repainted
	Otali Flaridian Oteol_Otali Flaridian	#3 EXIL	20		'	o to years	Repairited
oundatio	an .						
Junuani	Foundation - Concrete	Entire Building	1,070	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	73,040	SF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	73,040	SI	,	10+ years	
ahtina							
ignung	Exterior Lighting - Wall Mounted	Entire Building	14	EA	7	10+ years	New light fixtures
	Extendi Lighting Wall Woulded	Entire Ballating			,	Tot youro	Now light lixtures
oof Sys	tem						
-	Access Ladder - Metal	Main Roof	1	EA	4	0-1 year	bolts are loose, ladder is loose
	Coping - Stone	Main Roof	917	LF	7	10+ years	Coping repaired
	Downspouts - Interior Downspouts	Main Roof	240	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	917	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	25,172	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	7	6-10 years	
		Main Roof		SF	,	o io youio	

Campus Name: Mckay Page : 21 of 45 Assessment Date: 10/12/2021



Category : Exterior		Building : Addition								
5 ,		Recommend								
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
Concrete Topping										
Coping - Stone	North Low Roof	212	LF	7	10+ years	Roof repairs, new roof 2020				
Downspouts - Interior Downspouts	North Low Roof	120	LF	6	6-10 years	•				
Parapet - 16" - 30" Height	North Low Roof	212	LF	7	10+ years	Roof repairs, new roof 2020				
Roof - Modified Bitumen	North Low Roof	4,539	SF	7	10+ years	New roof 2020				
Roof Structure - Steel / Metal Deck/ Concrete Topping	North Low Roof	4,539	SF	7	10+ years					
Walls										
Exterior Walls - Brick	Entire Building	28,890	SF	6	10+ years					
Exterior Walls - Stone-Cast	Entire Building	3,210	SF	6	10+ years					
Windows										
Windows Guard - Guards perforated	Entire Building	3,424	SF	7	10+ years					

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
_	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	73,040	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	73,040	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	36	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	26	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	3	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	19,668	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	Entire Building	3,990	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,386	SF	6	10+ years	
Main Sei	rvice						
	Main Electrical Service - 2001 to 3000 A 277/480/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room, Fire Pump Room	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Electrical Room, Fire Pump Room	1	EA	6	10+ years	Serves the fire sprinkler system in Addition.
	PA System	Entire Building	73,040	SF	6	6-10 years	Serves the entire school

Campus Name: Mckay Page : 22 of 45 Assessment Date: 10/12/2021



atego	ry : Electrical		В	uilding	: Addition	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ower D	intribution						
owerD	istribution	Entire Delilation	04	ΓΛ	7	40	O
	Lighting and Power Panels - Above 100 A	Entire Building	21	EA	7	10+ years	Quantity changed to match curren observations.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	6	EA	7	10+ years	
	amp	F (	4	_ ^	•	40	
	Transformers - 277/480 - 120/208	Entire Building	4	EA	6	10+ years	
atego	ry : Fire Protection		В	uilding	: Additio	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Serves the entire school
	Fire Alarm Strobe Lights	Entire Building	73,040	SF	6	10+ years	
	Fire Alarm_System	Entire Building	73,040	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
ump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Plumbing Room	1	EA	5	2-5 years	Corrosion due to active leak.
	Jockey Pump	Plumbing Room	1	EA	7	10+ years	Installed in 2019
prinklei	System						
<del></del>	Sprinkler Heads	Entire Building	73,040	SF	7	10+ years	
	Sprinkler Piping	Entire Building	73,040	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	73,040	SF	5	10+ years	Pump has corrosion and a leak
	The opinion of others	g				•	. ap nao oonoonon ana a loak
atego	ry : Mechanical		В	uilding	: Addition		
	Ham. Time	Location	Overetite :	HOM	Dank	Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Cond	itioning					0.40	
	Chemical Pot Feeder	Entire Building	1	EA	6	6-10 years	
	Chiller-Air Cooled- Recipricating-Roof	Entire Building	1	EA	7	10+ years	
	Mounted - 201 - 300 tons	Fusing Delibing	4	_^	0	0.40	
	Glycol Feed	Entire Building	1	EA	6	6-10 years	
ir Hand	ling Systems						
	Air Handling Unit-Package Single Zone-	2nd Floor Mechanical Room	1	EA	5	6-10 years	AHU-1, serves 1st Floor
	Indoor- Hot Water and Chilled Water Coils -					•	•
	12001-20000 cfm						
	Air Intake	2nd Floor Mechanical Room	1	EA	6	10+ years	
	Induction Fan	2nd Floor Mechanical Room	1	EA	6	6-10 years	

Campus Name: Mckay Page : 23 of 45 Assessment Date: 10/12/2021



Category : Mechanical		Building : Addition					
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	VAV Box	2nd Floor Mechanical Room	13	EA	6	10+ years	
	Air Handling Unit-Package Single Zone-	2nd Floor Mechanical Room	1	EA	5	6-10 years	AHU-3, serves Multipurpose Room.
	Indoor- Hot Water and Chilled Water Coils -						
	12001-20000 cfm						
	Air Intake	2nd Floor Mechanical Room	1	EA	6	10+ years	
	Induction Fan	2nd Floor Mechanical Room	1	EA	6	6-10 years	
	VAV Box	2nd Floor Mechanical Room	5	EA	6	10+ years	
	Air Handling Unit-Package Single Zone-	Boiler Room	1	EA	5	6-10 years	AHU-2, serves 2nd and 3rd Floors
	Indoor- Hot Water and Chilled Water Coils -						
	Greater than 30,000 cfm	B 11 B				4.0	
	Air Intake	Boiler Room	1	EΑ	6	10+ years	
	Induction Fan	Boiler Room	1	EΑ	6	6-10 years	
	VAV Box	Boiler Room	11	EΑ	6	10+ years	0 11 41111 0
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	4	EA	5	6-10 years	Served by AHU-3
	Fan Power Box - Fan Power Box with Hot	Entire Building	38	EA	5	6-10 years	Served by AHU-2
	Water Coil						
	Fan Power Box - Fan Power Box with Hot	Entire Building	14	EA	5	6-10 years	Served by AHU-1
	Water Coil						
	Indoor Return Fans- Centrifugal Inline -	Mechanical Room	2	EA	5	6-10 years	RF-1 & RF-3
	10001 - 20000 CFM						
	Indoor Return Fans- Centrifugal Inline -	Mechanical Room	1	EA	5	6-10 years	RF-2
	Greater than 20000 CFM						
	Make Up Air Unit- Roof Mounted- Electric	Roof	1	EA	7	10+ years	Installed in 2020
	Coils - 6000 - 10,000 cfm						
Boiler Sy	vstems vstems						
	Boiler Auxiliary- Non Condensing Hot Water	Mechanical Room	1	EA	6	10+ years	
	- 1001 - 2000 MBH					•	
	Boiler Auxiliary- Non Condensing Hot Water	Mechanical Room	1	EA	6	10+ years	
	- 1001 - 2000 MBH					-	
	Boiler Auxiliary- Non Condensing Hot Water	Mechanical Room	1	EA	4	1-2 years	Corrosion and leaks.
	- 2001 - 3000 MBH						
	Chemical Pot Feeder	Mechanical Room	1	EA	6	6-10 years	
	Combustion Dampers	Mechanical Room	1	EA	6	10+ years	Duct-mounted
	Non Condensing- Water Tube- Flexible	Mechanical Room	1	EA	6	10+ years	
	Tube- Force Draft- Hot Water Boiler - 1001						
	- 2000 MBH						
	Non Condensing- Water Tube- Flexible	Mechanical Room	1	EA	6	10+ years	
	Tube- Force Draft- Hot Water Boiler - 1001						
	- 2000 MBH						
	Non Condensing- Water Tube- Flexible	Mechanical Room	1	EA	4	1-2 years	Corrosion, damage and leaks. Boiler
	Tube- Force Draft- Hot Water Boiler - 2001						2, well-maintained but nonfunctional
	- 3000 MBH						at the time of assessment, original to

Campus Name: Mckay Page : 24 of 45 Assessment Date: 10/12/2021



Catego	ry : Mechanical		В	uilding	: Addition	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							the building.
	Water Fill System	Mechanical Room	1	EA	6	6-10 years	
leating	Devices						
	Cabinet Heaters - With Hot Water Coil	1st Floor	5	EA	6	10+ years	Quantity adjusted to match current observations
	Unit Heater - Hot Water	Plumbing Room	1	EA	6	10+ years	observations
/lechani	cal Plumbing						
100HaH	Hydronic Supply and Return - Copper	Entire Building	2,000	LF	6	10+ years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	2,000	EA	6	6-10 years	Completing annual maintenance
	The trade is ample to 2011	Westianical Result	_		J	o To youro	protocol for heating season at the time of assessment.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	time of decedement.
	Hot Water Pump - Less than 10	Mechanical Room	2	EΑ	6	6-10 years	Quantity changed as total has been
	•					•	divided/aggregated.
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	2	EA	5	6-10 years	
empera	ture Control						
	DDC System	Entire Building	73,040	SF	6	10+ years	Controls are in Main
	Electric Thermostat	Entire Building	1	EA	6	10+ years	Controls the exhaust fan
	Electric Thermostat	Entire Building	1	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Controls unit heater.
	Electric Thermostat	Entire Building	1	EA	6	10+ years	
	Thermostats - DDC	Entire Building	86	EA	6	10+ years	1 MAU, 29 VAVs, and 56 FPBs.
entilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	10+ years	Needs to be cleaned but otherwise operates as intended.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	7	10+ years	Installed in 2020
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	2	EA	7	10+ years	Installed in 2020
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	In the former dishwashing room.
		Ü	<b>.</b>	!! -!!	. A .I .I!4!	-	Ç
atego	ry : Plumbing		В	uliaing	: Addition		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate		Location	Quantity	COM	Italik	Replacement	Comments
ivevvalt	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Quantity changed as total has been

Campus Name: Mckay Page : 25 of 45 Assessment Date: 10/12/2021



Catego	ry : Plumbing		В	uilding	: Additi	on		
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	O Ht 000004 000000 PTH/HD	Dellas Deess	4	<b>-</b> ^	-	0.40	divided/aggregated.	
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Quantity changed as total has been divided/aggregated. In the midst of repair at the time of assessment.	
_Piping								
	Domestic Piping-Hot Water Return Lines	Entire Building	73,040	SF	6	10+ years		
	Domestic Piping-Hot Water Return Risers	Entire Building	73,040	SF	6	10+ years		
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	73,040	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	73,040	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	73,040	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	73,040	SF	6	10+ years		
	Sanitary Piping	Entire Building	73,040	SF	6	10+ years		
	Storm Piping	Entire Building	73,040	SF	6	10+ years		
	Vent Piping	Entire Building	73,040	SF	6	10+ years		
Pumps								
·	Pumps - Domestic Booster Pump-Duplex	Plumbing Room	1	EA	5	6-10 years	The building is operating satisfactorily with this pump out of service however a new pump motor has now been received and is awaiting replacement.	
	Pumps - Sump-Simplex	Plumbing Room	1	EA	6	6-10 years	Installed in the bottom of the elevator pit.	

Category: Room **Building: Addition** 

oup Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ministrative Suites/Offices						
Ceiling - Lay-in	223 Office	468	SF	6	10+ years	
Doors - Side-lite	223 Office	8	SF	6	10+ years	
Doors - Wood Doors inclu hw	223 Office	1	EΑ	6	10+ years	
Floor - Tile	223 Office	468	SF	7	10+ years	
Lighting - Lay-in	223 Office	6	EΑ	6	6-10 years	
Power Distribution	223 Office	6	EΑ	7	10+ years	
Walls - Concrete Block	223 Office	698	SF	6	10+ years	
Walls - Plaster/Drywall	223 Office	259	SF	6	10+ years	
Ceiling - Lay-in	323 Office	468	SF	6	10+ years	
Doors - Side-lite	323 Office	8	SF	6	10+ years	
Doors - Wood Doors inclu hw	323 Office	1	EA	6	10+ years	

Campus Name: Mckay Page : 26 of 45 Assessment Date: 10/12/2021



Catego	Category : Room			uilding	: Additi	on	. 5
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	323 Office	468	SF	7	10+ years	
	Lighting - Lay-in	323 Office	6	EA	6	6-10 years	
	Power Distribution	323 Office	6	EA	7	10+ years	
	Walls - Concrete Block	323 Office	698	SF	6	10+ years	
	Walls - Plaster/Drywall	323 Office	259	SF	6	10+ years	
	Ceiling - Lay-in	Assistant Principal office	290	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal office	1	EA	7	10+ years	
	Floor - Carpet	Assistant Principal office	290	SF	6	6-10 years	
	Lighting - Lay-in	Assistant Principal office	2	EA	7	10+ years	
	Power Distribution	Assistant Principal office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Assistant Principal office	445	SF	7	6-10 years	
	Ceiling - Lay-in	Kitchen Office	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	ĒA	7	10+ years	
	Floor - Epoxy/ Painted	Kitchen Office	80	SF	5	6-10 years	
	Lighting - Lay-in	Kitchen Office	2	EA	6	6-10 years	
	Power Distribution	Kitchen Office	1	EΑ	7	10+ years	
	Walls - Concrete Block	Kitchen Office	380	SF	6	10+ years	
	Ceiling - Lay-in	Main Office Suite	1,868	SF	6	10+ years	
	Doors - Side-lite	Main Office Suite	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office Suite	1	EA	6	10+ years	
	Floor - Tile	Main Office Suite	1,868	SF	6	10+ years	
	Lighting - Lay-in	Main Office Suite	24	EA	6	6-10 years	
	Walls - Concrete Block	Main Office Suite	1.764	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office Suite	1,764	SF	6	10+ years	
	Ceiling - Lay-in	Principal Office	290	SF	7	6-10 years	
	Doors - Wood Doors inclu hw		290	EA	7		
	Floor - Carpet	Principal Office	290	SF		10+ years	
	•	Principal Office		SF EA	6	6-10 years	
	Lighting - Lay-in	Principal Office	2	EA EA	7	6-10 years	
	Power Distribution	Principal Office	2		7	10+ years	
	Walls - Concrete Block	Principal Office	140	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal Office	305	SF	7	10+ years	
	Ceiling - Lay-in	Room 125	440	SF	6	6-10 years	0
	Ceiling - Lay-in	Room 125	8	SF	4	1-2 years	Stained
	Doors - Side-lite	Room 125	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 125	1	EA	6	10+ years	
	Floor - Tile	Room 125	440	SF	6	6-10 years	
	Lighting - Lay-in	Room 125	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	Room 125	550	SF	6	6-10 years	
	Ceiling - Lay-in	Teachers Lounge	620	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Teachers Lounge	1	EA	7	10+ years	
	Floor - Tile	Teachers Lounge	620	SF	6	6-10 years	
	Lighting - Lay-in	Teachers Lounge	6	EA	7	6-10 years	
	Power Distribution	Teachers Lounge	3	EA	7	6-10 years	
	Walls - Concrete Block	Teachers Lounge	1,383	SF	7	10+ years	
		-					



Catego	Category : Room			Building : Addition				
	.,		_		. ,	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	Teachers Lounge	624	SF	7	6-10 years		
	Work SInk	Teachers Lounge	1	ĒΑ	7	6-10 years		
		3				,		
Gymnas	ia							
	Ceiling - Exposed	1st Floor	3,990	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years		
	Floor - Sport Flooring	1st Floor	3,990	SF	5	2-5 years		
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years		
	Scoreboards	1st Floor	1	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	12,118	SF	6	10+ years		
I/italaan								
Kitchen	Ceiling - Lay-in	1st Floor	3,420	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years		
	Floor - Concrete	1st Floor	3,420	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	4,800	SF	6	10+ years		
	Walls - Coliciete block	ISt Floor	4,000	SI	O	10+ years		
Library								
	Casework	222 Library	60	LF	6	10+ years		
	Ceiling - Lay-in	222 Library	2,816	SF	6	10+ years		
	Doors - Side-lite	222 Library	16	SF	6	10+ years		
	Doors - Wood Doors inclu hw	222 Library	2	EA	6	10+ years		
	Floor - Tile	222 Library	2,816	SF	7	10+ years		
	Lighting - Lay-in	222 Library	27	EA	7	6-10 years		
	Storage/ Closet	222 Library	119	SF	7	10+ years		
	Walls - Concrete Block	222 Library	1,440	SF	6	10+ years		
MDF ID	Œ							
	Doors - Wood Doors inclu hw	MDF in library	1	EA	6	10+ years		
	Finishes	MDF in library	492	SF	7	10+ years		
	Other Cooling Unit	MDF in library	1	EA	7	6-10 years		
Machan	ical/ Service Rooms							
wechan		4 of Close			7	40		
	Janitor's Closet	1st Floor	50	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	834	SF	7	10+ years		
	Janitor's Closet	2nd Floor	50	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	4,343	SF	7	10+ years		
	Janitor's Closet	3rd Floor	50	SF	7	10+ years		
	Mechanical/ Service Rooms	3rd Floor	4,267	SF	7	10+ years		
	Storage Room	3rd Floor	450	SF	7	10+ years		

Campus Name: Mckay Page : 28 of 45 Assessment Date: 10/12/2021



Catego	ry : Room		В	uilding	: Additi	on	_
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
estrooi	n						
	Accessories	1st Floor	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	54	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Terrazzo	1st Floor	54	SF	6	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	294	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor	231	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	231	SF	6	10+ years	
	Floor - Terrazzo	1st Floor	231	SF	6	6-10 years	
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	3	ĒΑ	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	425	SF	6	10+ years	
	Water Closet	1st Floor	2	EA	6	10+ years	
	Accessories	1st Floor	231	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	231	SF	6	10+ years	
	Floor - Terrazzo	1st Floor	231	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	5	EΑ	6	6-10 years	
	Partitions	1st Floor	5	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	425	SF	6	10+ years	
	Water Closet	1st Floor	5	EA	6	10+ years	
	Accessories	2nd Floor	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	54	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor	54	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	294	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	6	10+ years	
	Accessories	2nd Floor	231	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	231	SF SF	6	•	
	Floor - Terrazzo	2nd Floor	231	SF SF	6	10+ years	
	Floor Drain	2nd Floor		SF EA	7	10+ years	
			1	EA EA		10+ years	
	Lavatory	2nd Floor	3		6	10+ years	
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years	



Catego	Category : Room			uilding	: Addition	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd Floor	2	EA	7	6-10 years	
	Urinals	2nd Floor	3	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	425	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	2nd Floor	231	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	231	SF	6	10+ years	
	Floor - Terrazzo	2nd Floor	231	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	3	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	5	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	425	SF	6	10+ years	
	Water Closet	2nd Floor	5	EA	6	10+ years	
	Accessories	3rd Floor	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	54	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Terrazzo	3rd Floor	54	SF	6	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Lavatory	3rd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	294	SF	6	10+ years	
	Water Closet	3rd Floor	1	EA	6	10+ years	
	Accessories	3rd Floor	231	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	231	SF	6	10+ years	
	Floor - Terrazzo	3rd Floor	231	SF	6	10+ years	
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years	
	Lavatory	3rd Floor	3	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	6-10 years	
	Urinals	3rd Floor	3	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	425	SF	6	10+ years	
	Water Closet	3rd Floor	2	ĒΑ	6	10+ years	
	Accessories	3rd Floor	231	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	231	SF	6	10+ years	
	Floor - Terrazzo	3rd Floor	231	SF	6	10+ years	
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years	
	Lavatory	3rd Floor	3	EΑ	6	10+ years	
	Lighting - Lay-in	3rd Floor	5	EΑ	6	6-10 years	
	Partitions	3rd Floor	5	EΑ	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	425	SF	6	10+ years	
	Water Closet	3rd Floor	5	EA	6	10+ years	
	Accessories	In room 128	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In room 128	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In room 128	1	EA	6	10+ years	
	20010 Wood 20010 Hold HW	111100111 120	'	L, (	J	ioi youis	



Catego	Category : Room			uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	In room 128	40	SF	6	6-10 years	
	Floor Drain	In room 128	1	EA	7	10+ years	
	Lavatory	In room 128	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	In room 128	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	In room 128	234	SF	6	10+ years	
	Water Closet	In room 128	1	EA	6	10+ years	
	Accessories	In room 129	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In room 129	40	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	In room 129	1	EA	6	10+ years	
	Floor - Terrazzo	In room 129	40	SF	6	6-10 years	
	Floor Drain	In room 129	1	EA	7	10+ years	
	Lavatory	In room 129	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	In room 129	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	In room 129	234	SF	6	10+ years	
	Water Closet	In room 129	1	EA	6	10+ years	
	Accessories	In room 130	40	SF	7	6-10 years	
	Ceiling - Lay-in	In room 130	4	SF	4	1-2 years	Hole in tile
	Ceiling - Plaster/Drywall	In room 130	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In room 130	1	EA	6	10+ years	
	Floor - Terrazzo	In room 130	40	SF	6	10+ years	
	Floor Drain	In room 130	1	EΑ	7	10+ years	
	Lavatory	In room 130	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	In room 130	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	In room 130	234	SF	7	10+ years	
	Water Closet	In room 130	1	EΑ	6	10+ years	
	Accessories	In room 131	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In room 131	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In room 131	1	EΑ	6	10+ years	
	Floor - Terrazzo	In room 131	40	SF	6	10+ years	
	Floor Drain	In room 131	1	EA	7	10+ years	
	Lavatory	In room 131	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In room 131	1	EΑ	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	In room 131	234	SF	6	10+ years	
	Water Closet	In room 131	1	EΑ	6	10+ years	
	Accessories	In room 132	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In room 132	40	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	In room 132	1	EA	6	10+ years	
	Floor - Terrazzo	In room 132	40	SF	6	10+ years	
	Floor Drain	In room 132	1	EA	7	10+ years	
	Lavatory	In room 132	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In room 132	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	In room 132	234	SF	6	10+ years	
	Water Closet	In room 132	1	ĒΑ	6	10+ years	
	Accessories	In room 133	40	SF	7	6-10 years	
						,	



Category : Room

#### Francis M McKay Elementary School 6901 S Fairfield AVENUE, Chicago, IL 60629

**Building: Addition** 

atego	ry : Room			ullaing	: Additi		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Plaster/Drywall	In room 133	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In room 133	1	ĒΑ	6	10+ years	
	Floor - Terrazzo	In room 133	40	SF	6	10+ years	
						•	
	Floor Drain	In room 133	1	EA	7	10+ years	
	Lavatory	In room 133	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In room 133	1	EΑ	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	In room 133	234	SF	6	10+ years	
	Water Closet	In room 133	1	EA	6	10+ years	
atego	ry : Classroom		В	uilding	: Additi	on	
			0			Recommend	•
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assro	nm #127 (Regular Classroom)						
	Casework	1st Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	880	SF	7	6-10 years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	880	SF	6	6-10 years	
		1st Floor		_	-		
	Lighting - Lay-in		12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	946	SF	6	6-10 years	
lassroo	om #128 (Kindergarten)						
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,232	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	1,232	SF	7	10+ years	
			,	EA	7		
	Lighting - Lay-in	1st Floor	17			6-10 years	
	Marker Board	1st Floor	10	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,340	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
assroo	om #129 (Regular Classroom)						
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,232	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,232	SF	7	•	
						10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,340	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
	Nama: Makay		Dogo : 22 of 45				Accessment Date: 10/12/
mniin	Nomo: Mokov		11000 122 of 1E				0.00000mont Data: 10/10/

Page : 32 of 45 Assessment Date: 10/12/2021 Campus Name: Mckay



Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #130 (Kindergarten)						
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,232	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	16	SF	4	1-2 years	Stained
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Transom Window	1st Floor	1	SF	6	10+ years	
	Floor - Tile	1st Floor	1,229	SF	6	6-10 years	
	Floor - Tile	1st Floor	3	SF	4	1-2 years	Damaged
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,340	SF	6	2-5 years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #131 (Kindergarten)	4 at Ela an				40	
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,232	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,232	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,340	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #132 (Kindergarten)						
Oldobioc	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,232	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,232	SF	7	10+ years	
		1st Floor		SF EA	7		
	Lighting - Lay-in		17			6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,340	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #133 (Kindergarten)						
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,232	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,232	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17,232	EA	7	6-10 years	
	Lighting - Lay-in	1301 1001	17		,	u- iu yeais	

Campus Name: Mckay Page : 33 of 45 Assessment Date: 10/12/2021



Catego	ategory : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	10	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,340	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #225 (Regular Classroom)						
	Casework	2nd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	472	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	474	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	om #226 (Regular Classroom)						
Oldooroo	Casework	2nd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	473	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	om #227 (Regular Classroom)						
	Casework	2nd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	894	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	1	SF	6	10+ years	
	Floor - Tile	2nd Floor	894	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	473	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	

Campus Name: Mckay Page : 34 of 45 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #228 (Regular Classroom)						
	Casework	2nd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	1	SF	6	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	6	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	473	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #229 (Regular Classroom)						
	Casework	2nd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	920	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	920	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	473	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	om #230 (Regular Classroom)						
Diagonoc	Casework	2nd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	900	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	1	SF	6	10+ years	
	Floor - Tile	2nd Floor	900	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	460	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	520	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Closses	om #231 (Regular Classroom)						
Ciassioc	om #231 (Regular Classroom)  Casework	2nd Floor	38	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	880	SF	6		
	Chalk Board	2nd Floor 2nd Floor	24	SF LF	4	10+ years 2-5 years	
	Chair Dualu	ZIIU FIUUI	24	ᄕ	4	z-o years	

Campus Name: Mckay Page : 35 of 45 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	473	SF	6	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	10+ years	
Classroo	om #232 (Regular Classroom)						
	Casework	2nd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	878	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor 2nd Floor	24	LF	4	2-5 years	vvater damage
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
			-		-	•	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	456	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	456	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	om #233 (Regular Classroom)						
	Casework	2nd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	473	SF	6	-	
		2nd Floor 2nd Floor	473	SF		10+ years	
	Walls - Plaster/Drywall Work Sink	2nd Floor	473	EA	6 7	10+ years 10+ years	
						•	
Classroc	om #320 (Regular Classroom)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	

Campus Name: Mckay Page : 36 of 45 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Addition	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	12	EΑ	6	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	473	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #322 (Regular Classroom)						
	Casework	2nd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
			8	SF		-	
	Doors - Side-lite	2nd Floor			6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	473	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	om #324 (Computer Lab)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EΑ	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	473	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #325 (Computer Lab)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
			0	SF SF			
	Doors - Transom Window	3rd Floor		SF SF	6	10+ years	
	Floor - Tile	3rd Floor	880		7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	472	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	474	SF	6	10+ years	
	Work Sink	3rd Floor	1	EΑ	7	10+ years	

Campus Name: Mckay Page : 37 of 45 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
01	(1000 /D   1   0    )						
Classroo	om #326 (Regular Classroom)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	473	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classics	om #327 (Regular Classroom)						
JIASSIOO	Casework	3rd Floor	38	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	880	SF	6		
	Chalk Board	3rd Floor	24	LF	4	10+ years	
	Doors - Side-lite	3rd Floor	8	SF		2-5 years	
			8		6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	·	EA	6	6-10 years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	473	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #328 (Regular Classroom)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	•	
	Walls - Concrete Block	3rd Floor 3rd Floor	473	SF SF	, 6	10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	3rd Floor 3rd Floor		SF SF	_	10+ years	
	Work Sink	3rd Floor	473 1	Sr EA	6 7	10+ years 10+ years	
			·		-	- <b>,</b>	
Classroo	om #329 (Regular Classroom)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Addition	on	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	473	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
lassroc	om #330 (Regular Classroom)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	473	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroc	om #331 (Regular Classroom)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	473	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
lassroc	om #332 (Science Classroom)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	

Campus Name: Mckay Page : 39 of 45 Assessment Date: 10/12/2021



\_Safety\_

Catego	ry : Classroom		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	473	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	m #333 (Regular Classroom)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	473	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	473	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Catego	ry : Interior		В	uildina	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Corridor	Item - Type	Location	Quantity	UOM	Rank		Comments
•	Item - Type  Ceiling - Lay-in	Location  1st Floor	Quantity 6,200	<b>UOM</b> SF	Rank 6		Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor 1st Floor	6,200	SF EA	6 6	Replacement  10+ years 10+ years	Comments
•	Ceiling - Lay-in	1st Floor 1st Floor 1st Floor	6,200 2 1	SF EA EA	6 6 7	Replacement  10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo	1st Floor 1st Floor 1st Floor 1st Floor	6,200	SF EA EA SF	6 6 7 6	10+ years 10+ years 10+ years 10+ years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	6,200 2 1 6,200 145	SF EA EA SF EA	6 6 7 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	6,200 2 1 6,200 145 14,500	SF EA EA SF EA SF	6 6 7 6 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	6,200 2 1 6,200 145 14,500 6,200	SF EA EA SF EA SF SF	6 6 7 6 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor	6,200 2 1 6,200 145 14,500 6,200 2	SF EA SF EA SF SF EA	6 6 7 6 7 7 6 6	10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor	6,200 2 1 6,200 145 14,500 6,200 2	SF EA SF EA SF SF EA EA	6 6 7 6 7 7 6 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	6,200 2 1 6,200 145 14,500 6,200 2 1 6,200	SF EA SF EA SF EA EA SF	6 6 7 6 7 6 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	6,200 2 1 6,200 145 14,500 6,200 2 1 6,200 145	SF EA SF EA SF EA EA SF	6 6 7 6 7 6 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor	6,200 2 1 6,200 145 14,500 6,200 2 1 6,200 145 14,500	SF EA SF EA SF EA EA SF EA SF	6 6 7 6 7 6 6 7 6 7	Replacement  10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor	6,200 2 1 6,200 145 14,500 6,200 2 1 6,200 145 14,500 6,200	SF EA SF EA SF EA SF EA SF EA SF	6 6 7 6 7 6 6 7 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor	6,200 2 1 6,200 145 14,500 6,200 2 1 6,200 145 14,500 6,200 2	SF EA SF EA SF EA SF EA SF EA	6 6 7 6 7 6 6 7 6 7 6	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	6,200 2 1 6,200 145 14,500 6,200 2 1 6,200 145 14,500 6,200 2 2	SF EA SF EA SF EA SF EA SF EA	6 6 7 6 7 6 6 7 6 7 6	Replacement  10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	6,200 2 1 6,200 145 14,500 6,200 2 1 6,200 145 14,500 6,200 2 2 6,200	SF EA SF EA SF EA SF EA SF EA SF EA SF	6 6 7 6 7 6 6 7 6 7 6	Replacement  10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
•	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block Ceiling - Lay-in Walls - Concrete Block Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	6,200 2 1 6,200 145 14,500 6,200 2 1 6,200 145 14,500 6,200 2 2	SF EA SF EA SF EA SF EA SF EA	6 6 7 6 7 6 6 7 6 7 6	Replacement  10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments



Catego	ry : Interior		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Metal Dedector	Entire Building	1	EA	7	10+ years			
	Security Cameras	Entire Building	2	EA	7	10+ years			
Stairs									
	Ceiling - Exposed	Stair 1	356	SF	6	10+ years			
	Floor - Terrazzo	Stair 1	356	SF	6	10+ years			
	Handrails	Stair 1	114	LF	7	10+ years			
	Lighting - Pendent/Surface	Stair 1	7	EA	7	6-10 years			
	Stairs - Terrazzo	Stair 1	57	LF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	Stair 1	3,290	SF	7	10+ years			
	Ceiling - Lay-in	Stair 2	356	SF	6	10+ years			
	Floor - Terrazzo	Stair 2	356	SF	6	10+ years			
	Handrails	Stair 2	114	LF	7	10+ years			
	Lighting - Lay-in	Stair 2	7	EA	6	6-10 years			
	Stairs - Terrazzo	Stair 2	57	LF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	Stair 2	3,290	SF	6	10+ years			
	Ceiling - Lay-in	Stair 3	356	SF	7	10+ years			
	Floor - Terrazzo	Stair 3	356	SF	6	10+ years			
	Handrails	Stair 3	114	LF	7	10+ years			
	Lighting - Lay-in	Stair 3	7	EA	7	6-10 years			
	Stairs - Terrazzo	Stair 3	57	LF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	Stair 3	3,240	SF	6	10+ years			
Vertical (	Conveyance								
	Elevator - Hydraulic Elevator	North	1	EA	6	10+ years			





Category : Site **Building: Site** 

	ry : Site			ullaing	. Site		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
vil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	6	6-10 years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	0-1 year	Collapsed catch basin
	Civil/ Drainage - Catch Basin	Entire Site	1	EΑ	4	0-1 year	Collapsed catch basin
	Civil/ Drainage - Site Manhole	Entire Site	12	EA	6	6-10 years	
encing							
	Fencing - Chain Link	Entire Site	264	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	1,618	LF	6	6-10 years	
ndsca	pe Benches	Entire Site	4	EA	6	6-10 years	
	Landscape - Grass	Entire Site	15,000	SF	6	10+ years	
	Landscape - Grass	Entire Site Entire Site	14,000	SF	4	1-2 years	Barren soil, and full of weeds. Currer
	Lanuscape - Grass		14,000		4	1-2 years	google earth images show ground trampled by contractor's equipment
	Landscape - Hardscape- Concrete	Entire Site	700	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	400	SF	5	1-2 years	Displaced, large cracks
	Parkway trees	Entire Site	62	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	96	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	5,796	SF	6	6-10 years	
rking	Lot						
9	Concrete Curbs	North Courtyard	202	LF	6	10+ years	
	Surface - Asphalt	North Courtyard	8,558	SF	6	6-10 years	
	Surface - Asphalt	North Courtyard	2,000	SF	5	1-2 years	Large uneven surfaces that pool, and a lot of alligatored surface
	Trash Compactor	North Courtyard	1	EA	6	6-10 years	a lot of alligatored surface
	Trash Enclosure - Chain Links	North Courtyard	140	SF	6	6-10 years	
	Vehicular Screening	North Courtyard	202	LF	6	10+ years	Bushes
	Concrete Curbs	South Courtyard	704	LF	6		Dusties
						10+ years	
	Interior Plantings	South Courtyard	70	LF	6	10+ years	
	Lighting - Pole Mounted	South Courtyard	8	EA	6	6-10 years	
	Surface - Asphalt	South Courtyard	14,673	SF	6	6-10 years	
	Surface - Asphalt	South Courtyard	100	SF	4	0-1 year	Sinkhole
	Vehicular Screening	South Courtyard	578	LF	6	10+ years	
aygrou	ınd						
-	Equipment - School Age 5-12	South Courtyard	5	EA	5	2-5 years	Rusting and damaged components
	Equipment - Swingset	South Courtyard	1	EA	4	0-1 year	swings missing
	Surface - Square Rubber Mats	South Courtyard	4,104	SF	4	2-5 years	Old rubber tiles with several pieces

Campus Name: Mckay Page : 42 of 45 Assessment Date: 10/12/2021



Catego	ry : Site		В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	994	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	10,642	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	20	SF	5	1-2 years	Upheaved, cracked concrete
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	6	6-10 years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Monument - Sign	Entire Site	1	EA	7	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Mckay Page: 43 of 45 Assessment Date: 10/12/2021

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary				FI DI		01	0		
			Room	Floor Plan Room	A ====	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Hoose	Room Location	Number	Number	Area (SF)	Area	Area		Board
Building : Main	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Doard
Regular Classroom	Kindergarten	1st Floor	103	101	574	100	110	NI NI	T NI
Regular Classroom		1st Floor	105	101	574	128 128	110	N N	N N
	Kindergarten	1st Floor	105	101	746	140	127	N N	N
Regular Classroom	Regular Classroom								
Regular Classroom	Regular Classroom	1st Floor	107	103	666	140	127 127	N	N
Regular Classroom	Regular Classroom	1st Floor	108	106	746	140			<u> </u>
Regular Classroom	Regular Classroom	1st Floor	111	107	724	112	110		<b>_</b>
Regular Classroom	Regular Classroom	1st Floor	112	112	326	140	127		<u> </u>
Regular Classroom	Regular Classroom	1st Floor	113	113	724	112	110	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	724	140	127		<u> </u>
Regular Classroom	Regular Classroom	2nd Floor	203	203	724	140	127		
Regular Classroom	Regular Classroom	2nd Floor	204	204	730	140	127		<u> </u>
Regular Classroom	Regular Classroom	2nd Floor	205	205	724	140	127		
Regular Classroom	Regular Classroom	2nd Floor	207	207	724	140	127		
Regular Classroom	Regular Classroom	2nd Floor	208	208	746	140	127		
Regular Classroom	Regular Classroom	2nd Floor	209	209/211	700	140	127		
Regular Classroom	Regular Classroom	2nd Floor	210	210	312	25	14		
Regular Classroom	Regular Classroom	2nd Floor	211	209/211	700	140	127		
Regular Classroom	Regular Classroom	2nd Floor	212	210	600	140	127		
Regular Classroom	Regular Classroom	3rd Floor	301	301	724	140	127		
Regular Classroom	Regular Classroom	3rd Floor	303	303	730	140	127		
Regular Classroom	Regular Classroom	3rd Floor	304	304	738	140	127		
Regular Classroom	Regular Classroom	3rd Floor	305	305	730	140	127		
Regular Classroom	Regular Classroom	3rd Floor	306	306	720	140	127		
Regular Classroom	Regular Classroom	3rd Floor	307	307	730	140	127		
Regular Classroom	Regular Classroom	3rd Floor	308	308	730	140	127		
Store Room	Regular Classroom	2nd Floor	206	206	720	140	127		
Building : Addition									
Computer Lab	Regular Classroom	3rd Floor	324	3-13	880	158	79		
Computer Lab	Regular Classroom	3rd Floor	325	3-03	880	66	48		
Kindergarten	Kindergarten	1st Floor	128	1-20	1,232	190	240		
Kindergarten	Kindergarten	1st Floor	130	1-17	1,232	190	240		
Kindergarten	Kindergarten	1st Floor	131	1-07	1,232	190	240		
Kindergarten	Kindergarten	1st Floor	132	1-14	1,232	190	240		
Kindergarten	Kindergarten	1st Floor	133	1-10	1,232	190	240		
Regular Classroom	Pre School	1st Floor	129	1-04	1,232	190	240		
Regular Classroom	Regular Classroom	1st Floor	127	1-03	880	66	48		
Regular Classroom	Regular Classroom	2nd Floor	225	2-03	880	66	48		



**Classroom Summary** 

j			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	226	2-12	880	158	79		
Regular Classroom	Regular Classroom	2nd Floor	227	2-04	894	66	96		
Regular Classroom	Regular Classroom	2nd Floor	228	2-11	880	66	48		
Regular Classroom	Regular Classroom	2nd Floor	229	2-04	920	66	96		
Regular Classroom	Regular Classroom	2nd Floor	230	2-10	900	70	96		
Regular Classroom	Regular Classroom	2nd Floor	231	2-06	880	66	96		
Regular Classroom	Regular Classroom	2nd Floor	232	2-09	880	70	96		
Regular Classroom	Regular Classroom	2nd Floor	233	2-07	880	70	96		
Regular Classroom	Regular Classroom	2nd Floor	322	3-14	880	158	79		
Regular Classroom	Regular Classroom	3rd Floor	320	3-15	880	66	48		
Regular Classroom	Regular Classroom	3rd Floor	326	3-12	880	158	79		
Regular Classroom	Regular Classroom	3rd Floor	327	3-04	880	66	48		
Regular Classroom	Regular Classroom	3rd Floor	328	3-11	880	66	48		
Regular Classroom	Regular Classroom	3rd Floor	329	3-05	880	66	48		
Regular Classroom	Regular Classroom	3rd Floor	330	3-10	880	66	48		
Regular Classroom	Regular Classroom	3rd Floor	331	3-06	880	66	48		
Regular Classroom	Regular Classroom	3rd Floor	333	3-07	880	66	48		
Science Classroom	Regular Classroom	3rd Floor	332	3-09	880	66	48		