

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1892	3	50,700
Addition	1970	1	5,685
Campus Total			56,385

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	,						
	Entrance Control - Audio and Video	#1 N	1	EA	6	10+ years	
	Exterior Doors - Store Front	#1 N	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 N	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 N	13	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#2 Exit E	1	EA	6	10+ years	
	Exterior Doors - Store Front	#3 E	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 E	3	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#4 E	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 S	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6 S	1	EA	6	10+ years	
	Exterior Doors - Store Front	#9 N	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#9 N	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 N	12	LF	5	1-2 years	Spalled, cracked concrete
	Exterior Doors - Exterior Steel Door	Fire Escape Entrances	2	EA	6	10+ years	•
Fire Esc	ape						
	Fire Escape	South Façade	112	LF	6	10+ years	
_Foundat	ion						
	Foundation - Masonry	Entire Building	624	LF	7	10+ years	
	Foundation - Masonry	Entire Building	28	LF	6	10+ years	No seepage reported by current engineer. Deteriorated mortar and



Catego	ry : Exterior		B	uilding	• Main		2233 W Onio STREET, Chicago, IE 60612
Jaicgo	y . Exterior			unung	. Mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.000							stone
	Superstructure - Heavy Timber	Entire Building	50,700	SF	7	10+ years	
		C C				,	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	7	10+ years	
		Entrie Danality		-/ (•	io: youro	
Roof Svs	stem						
	Coping - Stone	#1	80	LF	7	10+ years	
	Downspouts - Exterior Downspouts	#1	26	LF	7	10+ years	
	Parapet - Parapet < 16" Height	#1	80	LF	7	10+ years	
	Roof - Modified Bitumen	#1	738	SF	7	10+ years	
	Roof Structure - Heavy Timber	#1	738	SF	7	10+ years	
	Coping - Metal	#2	30	LF	7	10+ years	
	Downspouts - Interior Downspouts	#2	13	LF	6	10+ years	
	Parapet - Parapet < 16" Height	#2	30	LF	7	10+ years	
	Roof - Modified Bitumen	#2	144	SF	7	10+ years	
	Roof Structure - Heavy Timber	#2	144	SF	7	10+ years	
	Access Ladder - Wood	#2 #3	144	EA	4	2-5 years	Old wooden ladder, loose access
	Access Lauder - Wood	#3	1	EA	4	2-5 years	
							panel, unsafe transition to another
	Assess Ladder Mand	#2	4		4	0.1	unsafe ladder
	Access Ladder - Wood	#3	1	EA	4	0-1 year	Handmade wood ladder, loose nails
	Coping - Metal	#3	164	LF	7	10+ years	
	Downspouts - Interior Downspouts	#3	72	LF	6	10+ years	
	Parapet - 16" - 30" Height	#3	164	LF	7	10+ years	
	Roof - Modified Bitumen	#3	3,075	SF	7	10+ years	
	Roof Hatch - Metal	#3	1	EA	7	10+ years	Only one hatch on this roof
	Roof Structure - Heavy Timber	#3	3,075	SF	7	10+ years	
	Access Ladder - Metal	#4	2	EA	7	10+ years	
	Coping - Stone	#4	30	LF	7	10+ years	
	Coping - Stone	#4	30	LF	7	10+ years	
	Downspouts - Exterior Downspouts	#4	28	LF	7	10+ years	
	Parapet - 16" - 30" Height	#4	60	LF	7	10+ years	
	Roof - Modified Bitumen	#4	4,721	SF	7	10+ years	
	Roof Structure - Heavy Timber	#4	4,721	SF	7	10+ years	
	Access Ladder - Metal	#5	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	#5	49	LF	6	10+ years	
	Liner						
	Coping - Metal	#5	137	LF	7	10+ years	
	Coping - Stone	#5	20	LF	7	10+ years	
	Downspouts - Interior Downspouts	#5	42	LF	6	10+ years	
	Parapet - 16" - 30" Height	#5	157	LF	7	10+ years	
	Roof - PVC Membrane	#5	3,078	SF	7	10+ years	
	Roof Hatch - Metal	#5	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	#5	3,078	SF	7	10+ years	



							2233 W Ohio STREET, Chicago, IL 60612
Catego	ry : Exterior		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Metal	#6	38	LF	7	10+ years	
	Downspouts - Exterior Downspouts	#6	13	LF	7	10+ years	
	Parapet - Parapet < 16" Height	#6	38	LF	7	10+ years	
	Roof - Modified Bitumen	#6	345	SF	7	10+ years	
	Roof Structure - Heavy Timber	#6	345	SF	7	10+ years	
	Coping - Stone	#7	144	LF	7	10+ years	
	Downspouts - Interior Downspouts	#7	30	LF	6	10+ years	
	Parapet - 16" - 30" Height	#7	144	LF	7	10+ years	
	Roof - Modified Bitumen	#7	1,429	SF	7	10+ years	
	Roof Structure - Heavy Timber	#7	1,429	SF	7	10+ years	
	Coping - Stone	#8	62	LF	7	10+ years	
	Downspouts - Exterior Downspouts	#8	26	LF	7	10+ years	
	Parapet - Parapet < 16" Height	#8	62	LF	7	10+ years	
	Roof - Modified Bitumen	#8	1,686	SF	7	10+ years	
	Roof Structure - Heavy Timber	#8	1,686	SF	7	10+ years	
			-,			,	
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	70	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	450	LF	7	10+ years	Painted
	Exterior Walls - Brick	Entire Building	23,720	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	212	SF	5	10+ years	Brick is in good shape, there are
		C					some areas of deteriorated mortar
	Exterior Walls - Brick	Entire Building	80	SF	4	1-2 years	Deteriorated mortar and open joints
		C					Roof number 5 wall
	Exterior Walls - Stone-Cast	Entire Building	72	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	2,200	SF	6	10+ years	
Windows	Guard - Guards perforated	Entire Building	1,816	SF	7	10+ years	
	Lintels - Brick	Entire Building	372	LF	6	10+ years	
	Lintels - Steel	Entire Building	33	LF	6	10+ years	
	Lintels - Stone	Entire Building	302	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,960	SF	7	10+ years	
	Windows - Sash Aldmindin Double-parle Windows - Sash Lexan	Entire Building	512	SF	7		
	Windows - Sasii Lexan	Entire Building	512	35	1	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
0	Hom. Tuno	Leastion	Overtite		Daul	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
∟merger	ncy System Automatic Transfer Switch	Electrical Room	4	EA	6	6 10 years	
			1	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	2	EA	6	6-10 years	
	Stairs Emergency Battery Packs - Students Toilets	Entiro Ruilding	3	EA	6	6 10 vooro	Quantity change per current
	Emergency dattery Facks - Students Tollets	Entire Building	3	ËA	O	6-10 years	Quantity change per current



Catego	ry : Electrical		B	uilding	: Main		2233 W Ohio STREET, Chicago, IL 6061
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observation
	Exit Signs - Corridors and Stairs	Entire Building	17	EA	2	0-1 year	no back up generator.
	Exit Signs - Lunchroom	Entire Building	5	EA	2	0-1 year	no back up generator.
	Security System - CCTV	Entire Building	50,700	SF	4	0-1 year	Cameras are working but very poo video and can't replace
	Security System - Intrusion Detection	Entire Building	50,700	SF	5	6-10 years	Old system needs to be replaced
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,802	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	2,877	SF	6	6-10 years	
/lain Se	vice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Site	50,700	SF	3	0-1 year	PA system is old and parts not available
ower D	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	New item added per current observation
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Missing cover
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	6-10 years	
atego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ire Alar							
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Replaced new fire alarm system in 2021



Categor							2233 W Onio STREET, Chicago, IL 60612
_	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	0	SF	7	10+ years	New item added per current observation Installed new fire alarm system in 2021
	Fire Alarm_System	Entire Building	50,700	SF	7	10+ years	Per current observation installed entire building strobe lights Replaced new fire alarm system in 2021
	Fire Pump Controller	Entire Building	1	EA	4	0-1 year	Can't replace parts not available
Pump Ro	oom Assembly						
	Fire Pump - Less than 25hp	Mechanical Room	1	EA	5	6-10 years	Seals leaking and need some cleaning
Sprinkler	System						
-	Dry Sprinkler System	Entire Building	50,700	SF	5	6-10 years	Need some cleaning
	Sprinkler Heads	Entire Building	50,700	SF	7	6-10 years	g
	Sprinkler Piping	Entire Building	50,700	SF	6	6-10 years	
		C C				-	
Categor	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Handl	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Entire Building	1	EA	5	6-10 years	
	Air Intake	Entire Building	1	EA	5	6-10 years	
	Auxiliaries - Greater than 35000 cfm	Entire Building	1	EA	4	1-2 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Entire Building	100	LF	5	6-10 years	
	Zone Dampers	Entire Building	29	EA	4	0-1 year	Manually open and close
Boiler Sys	stems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Entire Building	1	EA	5	6-10 years	Flue needs repair
	Chemical Feed System	Entire Building	1	EA	5	6-10 years	
	Chemical Feeder	Entire Building	1	EA	5	6-10 years	
	Combustion Dampers	Entire Building	1	EA	2	0-1 year	Actuator is corroded
	Condensate Pump	Entire Building	1	EA	5	2-5 years	Pipes and pumps are aged
	Condensate Pump	Entire Building	1	EA	5	2-5 years	Pipes and pumps are aged
	Feed Water Pumps and Tank	Entire Building	1	EA	5	6-10 years	Motors need to be replaced
			-	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Entire Building	1	EA	5	0-10 years	Only one boiler
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	-	1 300	LF	5		
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building Entire Building Entire Building				2-5 years 2-5 years	Pipes are aged Pipes are aged



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Gas Boo	ster						
	Gas Booster	Boiler Room	1	EA	6	6-10 years	
	Gas booster	Boller Room	I	LA	0	0-10 years	
Heating	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	6	6-10 years	
	Radiators - Steam	Entire Building	34	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	8	EA	5	2-5 years	Control needs to be repaired
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Cover missing and needs to repair
	Fin Tube - Steam	Entire Building	30	LF	6	6-10 years	
	Fin Tube - Steam		63	LF	5	6-10 years	
	Fill Tube - Steam	Entire Building	03	LF	5	0-10 years	
Tempera	ture Control						
	DDC System	Entire Building	50,700	SF	7	10+ years	New item added per current observation Control only all radiato
	Pneumatic System	Entire Building	50,700	SF	6	10+ years	Installed new system- per current observation and working
	Thermostats - Pneumatic	Entire Building	29	EA	4	0-1 year	Manually open and close
Ventilatio	n						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	7	10+ years	Installed new roof and exhaust in 2019
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	10+ years	Installed new roof and exhaust in 2019
	Type II Exhaust Hood- Warming Kitchen	Roof	1	EA	5	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	
				273	•	ior years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	50,700	SF	4	2-5 years	Pipes are aged
	Domestic Piping-Hot Water Return Risers	Entire Building	50,700	SF	4	2-5 years	Pipes are aged and galvanized
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	50,700	SF	4	2-5 years	Pipes are aged
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	50,700	SF	4	2-5 years	Pipes are aged
		Entire Building	50,700	SF	4	2-5 years	Pipes are aged and galvanized
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entro Banang	,			•	



Catego	Category : Plumbing				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	50,700	SF	6	6-10 years	
	Storm Piping	Entire Building	50,700	SF	6	6-10 years	
	Vent Piping	Entire Building	50,700	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	5	2-5 years	Per current observation seals replaced and no water around pump

Building : Main

Category : Room

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	rative Suites/Offices						
	AC Unit	1st Floor-101A Faculty Lounge	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-101A Faculty Lounge	416	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-101A Faculty Lounge	1	EA	6	10+ years	
	Floor - Tile	1st Floor-101A Faculty Lounge	416	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-101A Faculty Lounge	4	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-101A Faculty Lounge	1,115	SF	6	10+ years	
	Work SInk	1st Floor-101A Faculty Lounge	1	EA	7	6-10 years	
	AC Unit	1st Floor-104 Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-104 Office	390	SF	6	10+ years	
	Doors - Transom Window	1st Floor-104 Office	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-104 Office	1	EA	6	10+ years	
	Floor - Wood	1st Floor-104 Office	390	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-104 Office	5	EA	6	10+ years	
	Power Distribution	1st Floor-104 Office	8	EA	6	10+ years	
	Storage/ Closet	1st Floor-104 Office	10	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-104 Office	1,372	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-104A Principals Office	700	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-104A Principals Office	2	EA	6	10+ years	
	Floor - Tile	1st Floor-104A Principals Office	700	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-104A Principals Office	8	EA	6	10+ years	
	Power Distribution	1st Floor-104A Principals Office	44	EA	7	10+ years	
	Storage/ Closet	1st Floor-104A Principals Office	72	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-104A Principals Office	1,400	SF	6	10+ years	
	AC Unit	1st Floor-Main Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Main Office	455	SF	6	10+ years	
	Doors - Side-lite	1st Floor-Main Office	48	SF	6	10+ years	
	Doors - Transom Window	1st Floor-Main Office	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Main Office	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Main Office	455	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Main Office	5	EA	6	10+ years	
	Power Distribution	1st Floor-Main Office	24	EA	6	10+ years	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Walls - Plaster/Drvwall 1st Floor-Main Office 1.700 SF 6 10+ vears ΕA 7 6-10 vears AC Unit 206 Teacher storage/work room 1 Ceiling - Plaster/Drywall 206 Teacher storage/work room 705 SF 6 10+ years Doors - Transom Window 206 Teacher storage/work room SF 7 15 10+ years Doors - Wood Doors inclu hw 206 Teacher storage/work room 1 EΑ 6 10+ years 206 Teacher storage/work room SF Floor - Tile 705 6 10+ years Lighting - Pendent/Surface 206 Teacher storage/work room ΕA 7 10+ years 9 Walls - Plaster/Drywall SF 206 Teacher storage/work room 1.155 6 10+ years Ceiling - Plaster/Drywall Basement-Engingeer's Office 380 SF 6 6-10 vears Doors - Wood Doors inclu hw Basement-Engingeer's Office EΑ 6 10+ vears 1 Floor - Carpet Basement-Engingeer's Office 380 SF 6 6-10 vears Lighting - Pendent/Surface Basement-Engingeer's Office 4 ΕA 6 6-10 years **Power Distribution Basement-Engingeer's Office** 6 ΕA 6 10+ years SF 785 6 Walls - Plaster/Drywall **Basement-Engingeer's Office** 10+ years Basement-Lunchroom Manager's SF Ceiling - Plaster/Drywall 200 6 10+ years Office Doors - Steel Doors incl hw **Basement-Lunchroom Manager's** 1 ΕA 6 10+ years Office SF Floor - Concrete Epoxy/ Painted Basement-Lunchroom Manager's 200 7 10+ years Office Lighting - Pendent/Surface Basement-Lunchroom Manager's 2 ΕA 6 6-10 years Office Power Distribution **Basement-Lunchroom Manager's** 4 EA 6 10+ years Office Storage/ Closet **Basement-Lunchroom Manager's** 5 SF 5 10+ years Office Walls - Masonry **Basement-Lunchroom Manager's** 440 SF 6 10+ years Office Walls - Masonry **Basement-Lunchroom Manager's** 10 SF 6 10+ years Office SF Ceiling - Plaster/Drywall Basement-Parent's Resource Room 480 6 10+ vears Doors - Wood Doors inclu hw Basement-Parent's Resource Room 1 ΕA 6 10+ vears SF Floor - Wood Basement-Parent's Resource Room 6 480 10+ years Lighting - Pendent/Surface Basement-Parent's Resource Room 6 ΕA 6 10+ years Power Distribution Basement-Parent's Resource Room 16 ΕA 6 10+ years Walls - Plaster/Drywall SF **Basement-Parent's Resource Room** 875 6 10+ years Kitchen SF Ceiling - Plaster/Drywall Basement-Kitchen and Lunchroom 988 6 10+ vears Doors - Wood Doors inclu hw Basement-Kitchen and Lunchroom EΑ 6 10+ years 1 Floor - Tile 988 SF 6 **Basement-Kitchen and Lunchroom** 10+ years Lighting - Pendent/Surface ΕA Basement-Kitchen and Lunchroom 6 6 6-10 years Serving Line Basement-Kitchen and Lunchroom 20 LF 6 10+ years SF 5 Storage/ Closet Basement-Kitchen and Lunchroom 65 10+ years



Catego	ry : Room		В	uilding	: Main		
calogo				anding	····	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Walls - Concrete Block	Basement-Kitchen and Lunchroom	1,220	SF	6	10+ years	Commente
			1,220	01	0	ior youro	
Library							
,	AC Unit	1st Floor-106 Library	1	EA	7	6-10 years	
	Casework	1st Floor-106 Library	45	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor-106 Library	968	SF	6	10+ years	
	Doors - Transom Window	1st Floor-106 Library	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-106 Library	1	EA	6	10+ years	
	Floor - Carpet	1st Floor-106 Library	968	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-106 Library	14	ĒA	6	10+ years	
	Storage/ Closet	1st Floor-106 Library	135	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-106 Library	1,695	SF	6	10+ years	
	······		.,		-	, ,	
unch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement-Lunchroom - 2, at Girl's Playroom	925	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement-Lunchroom - 2, at Girl's Playroom	925	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement-Lunchroom - 2, at Girl's Playroom	6	EA	6	6-10 years	
	Lighting - Wall Mounted	Basement-Lunchroom - 2, at Girl's Playroom	1	EA	6	6-10 years	
	Serving Line	Basement-Lunchroom - 2, at Girl's Playroom	5	LF	6	10+ years	
	Walls - Masonry	Basement-Lunchroom - 2, at Girl's Playroom	5	SF	6	10+ years	
	Walls - Masonry	Basement-Lunchroom - 2, at Girl's Playroom	350	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Lunchroom - 2, at Girl's Playroom	305	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Basement-Lunchroom - 2, at Girl's Playroom	335	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Multipurpose Room at Boy's Playroom	945	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement-Multipurpose Room at Boy's Playroom	945	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-Multipurpose Room at Boy's Playroom	7	EA	6	10+ years	
	Walls - Masonry	Basement-Multipurpose Room at Boy's Playroom	600	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Multipurpose Room at Boy's Playroom	600	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		-
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
MDF_ID	F						
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Finishes	1st Floor	195	SF	7	10+ years	
	Window AC Unit	1st Floor	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Storage Room	1st Floor	125	SF	7	10+ years	
	Janitor's Closet	2F 203C Janitor's Closet	6	SF	7	10+ years	
	Boiler Room	Basement	1,075	SF	7	10+ years	
	Coal Room	Basement	440	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	295	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	606	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	150	SF	7	10+ years	
	Storage Room	Basement	180	SF	7	10+ years	
	Storage Room	Basement	185	SF	7	10+ years	
	Storage Room	Basement	450	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor-101A Unisex Restroom 1	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-101A Unisex Restroom 1	35	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor-101A Unisex Restroom 1	1	ĒA	6	10+ years	
	Floor - Tile	1st Floor-101A Unisex Restroom 1	35	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-101A Unisex Restroom 1	1	EA	6	10+ years	
	Walls - Metal Panel	1st Floor-101A Unisex Restroom 1	45	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-101A Unisex Restroom 1	170	SF	6	10+ years	
	Water Closet	1st Floor-101A Unisex Restroom 1	1	EA	6	6-10 years	
	Accessories	1st Floor-101A Unisex Restroom 2	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-101A Unisex Restroom 2	35	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor-101A Unisex Restroom 2	1	EA	6	10+ years	
	Floor - Tile	1st Floor-101A Unisex Restroom 2	35	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-101A Unisex Restroom 2	1	EA	6	1-2 years	Broken cover
	Walls - Metal Panel	1st Floor-101A Unisex Restroom 2	45	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-101A Unisex Restroom 2	170	SF	6	10+ years	
	Water Closet	1st Floor-101A Unisex Restroom 2	1	EA	6	6-10 years	
	Accessories	1st Floor-Main Office Unisex	75	SF	7	6-10 years	
		Restroom			,	0-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Main Office Unisex Restroom	75	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Main Office Unisex Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Main Office Unisex Restroom	75	SF	6	10+ years	
	Lavatory	1st Floor-Main Office Unisex	1	EA	6	6-10 years	



	ry : Room		B	uilding	· Main		2233 W Ohio STREET, Chicago, IL 60612
Calego	iy. Room		D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup		Restroom	Quantity	00111	Nank	Replacement	ooninients
	Lighting - Pendent/Surface	1st Floor-Main Office Unisex	1	EA	6	10+ years	
	gg · · · · · · · · · · · · · · · ·	Restroom			-	, e , j e e	
	Walls - Plaster/Drywall	1st Floor-Main Office Unisex	315	SF	6	10+ years	
		Restroom					
	Water Closet	1st Floor-Main Office Unisex	1	EA	6	6-10 years	
		Restroom					
	Accessories	2nd Floor Boys (203A)	100	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boys (203A)	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Boys (203A)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys (203A)	100	SF	7	10+ years	
	Hand Dryer	2nd Floor Boys (203A)	1	EA	7	6-10 years	
	Lavatory	2nd Floor Boys (203A)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Boys (203A)	2	EA	7	6-10 years	
	Partitions	2nd Floor Boys (203A)	1	EA	7	6-10 years	
	Urinals	2nd Floor Boys (203A)	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Boys (203A)	360	SF	7	10+ years	
	Water Closet	2nd Floor Boys (203A)	1	EA	7	10+ years	
	Accessories	2nd Floor Girls (203B)	155	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls (203B)	155	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girls (203B)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls (203B)	155	SF	7	10+ years	
	Hand Dryer	2nd Floor Girls (203B)	1	EA	7	6-10 years	
	Lavatory	2nd Floor Girls (203B)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls (203B)	2	EA	7	6-10 years	
	Partitions	2nd Floor Girls (203B)	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Girls (203B)	460	SF	7	10+ years	
	Water Closet	2nd Floor Girls (203B)	1	EA	7	10+ years	
	Accessories	Basement-Boy's Restroom	455	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Boy's Restroom	455	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Boy's Restroom	455	SF	6	10+ years	
	Floor Drain	Basement-Boy's Restroom	1	EA	7	10+ years	
	Lavatory	Basement-Boy's Restroom	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Boy's Restroom	6	EA	6	10+ years	
	Lighting - Wall Mounted	Basement-Boy's Restroom	1	EA	6	10+ years	
	Partitions	Basement-Boy's Restroom	5	EA	7	6-10 years	
	Urinals	Basement-Boy's Restroom	9	EA	6	6-10 years	
	Walls - Concrete Block	Basement-Boy's Restroom	650	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Boy's Restroom	536	SF	6	10+ years	
	Water Closet	Basement-Boy's Restroom	5	EA	6	6-10 years	
	Accessories	Basement-Girl's Restroom	500	SF	5	6-10 years	
	Ceiling - Splined	Basement-Girl's Restroom	500	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Girl's Restroom	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Girl's Restroom	500	SF	6	10+ years	



Cataga			Р	uilding	Main		2233 W Onio STREET, Chicago, IL 60612
Catego	ry : Room		В	uilding	: main	Deserves	
Group	Itom Tuno	Location	Quantity	UOM	Rank	Recommend Replacement	Commonto
Group	Item - Type Floor Drain	Basement-Girl's Restroom	Quantity 2	EA	7	10+ years	Comments
	Lavatory	Basement-Girl's Restroom	4	EA	6	6-10 years	
		Basement-Girl's Restroom	4	EA	6	6-10 years	
	Lighting - Pendent/Surface Partitions	Basement-Girl's Restroom	4 12	EA		6-10 years	
	Walls - Concrete Block	Basement-Girl's Restroom	500	SF	5 6		
	Walls - Plaster/Drywall	Basement-Girl's Restroom	390	SF	6	10+ years 10+ years	
	Walls - Flaster/Drywall Water Closet	Basement-Girl's Restroom	390 12	EA	6	10+ years	
	Ceiling - Exposed	Basement-Janitor's Suite/Bathroom	500	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Janitor's Suite/Bathroom	1	EA		•	
	Floor - Concrete Epoxy/ Painted		500	SF	6 5	10+ years 10+ years	
		Basement-Janitor's Suite/Bathroom	500	EA	5 7	10+ years	
	Floor Drain Lighting - Pendent/Surface	Basement-Janitor's Suite/Bathroom	4	EA	6		
		Basement-Janitor's Suite/Bathroom		SF		6-10 years	
	Walls - Masonry	Basement-Janitor's Suite/Bathroom	830	SF	6	10+ years	
	Accessories	Basement-Lunchroon Unisex Restroom	100		5	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Lunchroon Unisex Restroom	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Lunchroon Unisex Restroom	2	EA	6	10+ years	
	Floor - Epoxy/ Painted	Basement-Lunchroon Unisex Restroom	100	SF	7	10+ years	
	Lavatory	Basement-Lunchroon Unisex Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Lunchroon Unisex Restroom	1	EA	6	6-10 years	
	Partitions	Basement-Lunchroon Unisex Restroom	1	EA	5	6-10 years	
	Student Lockers - One Tier	Basement-Lunchroon Unisex Restroom	5	EA	6	10+ years	
	Walls - Masonry	Basement-Lunchroon Unisex Restroom	450	SF	6	10+ years	
	Water Closet	Basement-Lunchroon Unisex Restroom	1	EA	6	10+ years	
	Accessories	Basement-Staff Restroom, near Boy's Playroom	136	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Staff Restroom, near Boy's Playroom	136	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Staff Restroom, near Boy's Playroom	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement-Staff Restroom, near Boy's Playroom	136	SF	7	10+ years	
	Lavatory	Basement-Staff Restroom, near Boy's Playroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Staff Restroom, near	2	EA	6	10+ years	



Oatar					Main		
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Boy's Playroom					
	Partitions	Basement-Staff Restroom, near	1	EA	7	6-10 years	
		Boy's Playroom					
	Walls - Metal Panel	Basement-Staff Restroom, near	225	SF	6	10+ years	
		Boy's Playroom					
	Walls - Plaster/Drywall	Basement-Staff Restroom, near	275	SF	6	10+ years	
		Boy's Playroom					
	Water Closet	Basement-Staff Restroom, near	1	EA	6	6-10 years	
		Boy's Playroom					
	Accessories	Engineer Office Restroom	100	SF	5	2-5 years	
	Ceiling - Exposed	Engineer Office Restroom	100	SF	5	2-5 years	
	Doors - Wood Doors inclu hw	Engineer Office Restroom	1	EA	6	2-5 years	
	Floor - Carpet	Engineer Office Restroom	100	SF	6	2-5 years	
	Lavatory	Engineer Office Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Engineer Office Restroom	2	EA	6	2-5 years	
	Partitions	Engineer Office Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Engineer Office Restroom	360	SF	6	10+ years	
	Water Closet	Engineer Office Restroom	1	EA	6	10+ years	
	Accessories	Restroom inside class 101	25	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Restroom inside class 101	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Restroom inside class 101	1	EA	6	6-10 years	
	Floor - Tile	Restroom inside class 101	25	SF	6	6-10 years	
	Lavatory	Restroom inside class 101	1	EA	5	6-10 years	Leaking pipe
	Lighting - Pendent/Surface	Restroom inside class 101	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Restroom inside class 101	70	SF	6	10+ years	
	Water Closet	Restroom inside class 101	1	EA	7	10+ years	
						•	

Category : Classroom			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	952	SF	6	10+ years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Storage/ Closet	1st Floor	135	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,400	SF	6	10+ years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Casework	1st Floor	6	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	952	SF	6	10+ years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Storage/ Closet	1st Floor	165	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,400	SF	6	10+ years	
Classroc	om #103 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	952	SF	6	10+ years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	47	LF	7	6-10 years	
	Storage/ Closet	1st Floor	165	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,400	SF	6	10+ years	
Classroo	om #105 (Special Education)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	952	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	5	0-1 year	Falling tile
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	-
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	135	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,400	SF	6	10+ years	
Classroc	om #107 (Music Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	723	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	723	SF	6	10+ years	



Category : Classroom			B	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,133	SF	6	10+ years		
lassroc	om #201 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	6	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	952	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	15	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Wood	2nd Floor	952	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years		
	Marker Board	2nd Floor	37	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	165	SF	5	10+ years	Half of light fixture not functioning	
	Walls - Plaster/Drywall	2nd Floor	1,400	SF	6	10+ years	Than of light lixture hot functioning	
laceroc	om #202 (Regular Classroom)							
1455100	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	6	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	952	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	15	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Wood	2nd Floor	952	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	952	EA	6	6-10 years		
	Marker Board	2nd Floor	37	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	165	SF	5	10+ years		
				SF	-	•		
	Walls - Plaster/Drywall Walls - Plaster/Drywall	2nd Floor	1,370	SF	6 5	10+ years	December of peoling	
	Walls - Plastel/Drywall	2nd Floor	30	55	5	1-2 years	Baseboard peeling	
lassroc	om #204 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	6	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	950	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	50	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Wood	2nd Floor	950	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Water damage	
	Marker Board	2nd Floor	24	LF	6	6-10 years	-	
	Walls - Plaster/Drywall	2nd Floor	1,500	SF	6	10+ years		
lassroc	om #205 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	6	LF	7	6-10 years		



	Schools						2233 W Ohio STREET, Chicago, IL 60612
Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	952	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	37	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	165	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,400	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	952	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,400	SF	6	10+ years	
Classroo	om #208 (Art Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	952	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Marker Board	2nd Floor	37	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	165	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,400	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	5	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	952	SF	6	6-10 years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	28	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	165	SF	5	2-5 years	Door hardware damaged
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	6	10+ years	č
	2						



Catego	ry : Classroom		B	uilding	• Main		2233 W Onio STREET, Chicago, ie 60612
Guicgo				unung	· mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	om #302 (Regular Classroom)		,				
	AC Units	3rd Floor	1	EA	5	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	952	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	13	EA	5	2-5 years	
	Floor - Wood	3rd Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	51	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	165	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	6	10+ years	
	Walls - T lastel/Drywall	514 1 1001	1,400	01	0	TOF years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Updated to match current
			700	05	0	0.40	observations
	Ceiling - Lay-in	3rd Floor	790	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	790	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,334	SF	6	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	5	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	952	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	13	EA	6	10+ years	
	Floor - Tile	3rd Floor	952	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	
	Marker Board	3rd Floor	14	LF	6		
	Walker Board Walls - Plaster/Drywall	3rd Floor	1,400	SF	6	6-10 years 10+ years	
		310 F1001	1,400	эг	0	10+ years	
Classroo	om #305 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	790	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	790	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,334	SF	6	10+ years	
			1,004	0.	0	101 youro	



Catego	ry : Classroom		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
lassror	m #306 (Science)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	20	LF	6	6-10 years		
	Ceiling - Lay-in	3rd Floor	952	SF	6	10+ years		
	Doors - Transom Window	3rd Floor	15	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	1-2 years	Frame splintering	
	Floor - Tile	3rd Floor	952	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years		
	Marker Board	3rd Floor	17	LF	6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	6	10+ years		
						-		
assroc	m #307 (Regular Classroom)			– ^		0.40		
	AC Units	3rd Floor	1	EA	5	6-10 years		
	Casework	3rd Floor	6	LF	6	6-10 years		
	Ceiling - Lay-in	3rd Floor	952	SF	6	10+ years		
	Doors - Transom Window	3rd Floor	15	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	952	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	13	EA	6	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years		
	Marker Board	3rd Floor	30	LF	6	6-10 years		
	Storage/ Closet	3rd Floor	135	SF	7	10+ years	Updated to match current observations	
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	7	10+ years	Updated to match current observations	
assroc	m #308 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	Updated to match current	
	Casework	3rd Floor	10	LF	6	6-10 years	observations	
	Ceiling - Lay-in	3rd Floor	952	SF	6	10+ years		
	Chalk Board	3rd Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	952	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years		
	Marker Board	3rd Floor	32	LA	6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	6	10+ years		
atego	ry : Interior			uilding	: Main	-		
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
orridor								



Category : Interior **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drvwall 1st Floor 1.150 SF 10+ vears 6 Ceiling - Plaster/Drywall 1st Floor 230 SF 6 10+ years **Drinking Fountains - Triple Fountain** 1st Floor 3 EΑ 7 10+ years Floor - Concrete Epoxy/ Painted SF 7 1st Floor 312 10+ years SF Floor - Tile Ceramic/ Porcelain 1st Floor 15 6 10+ years SF Floor - Wood 1st Floor 1,150 6 10+ years Lighting - Pendent/Surface 1st Floor ΕA 6 10+ years 13 Walls - Plaster/Drvwall SF 1st Floor 3.428 6 10+ years SF Ceiling - Plaster/Drywall 2nd Floor 868 6 10+ years Drinking Fountains - Double Fountain 2nd Floor 2 EΑ 7 2-5 years Floor - Wood 2nd Floor 868 SF 6 10+ vears Lighting - Pendent/Surface 2nd Floor 12 EΑ 6 10+ years Walls - Plaster/Drywall 2nd Floor 2,110 SF 6 10+ years SF 6 Ceiling - Lay-in 3rd Floor 908 10+ years Drinking Fountains - Double Fountain 2 ΕA 7 3rd Floor 10+ years Floor - Wood 868 SF 3rd Floor 6 10+ years Lighting - Pendent/Surface ΕA 3rd Floor 12 6 6-10 years Walls - Plaster/Drywall 3rd Floor 2.110 SF 6 10+ years Ceiling - Plaster/Drvwall SF Ground Floor 2.330 6 10+ vears Ceiling - Plaster/Drywall SF Ground Floor 30 5 10+ years Crack ceiling Doors - Transom Window Ground Floor 35 SF 6 10+ years 8 6 10+ years Doors - Wood Doors include hw Ground Floor EΑ 7 4 ΕA Drinking Fountains - Single Fountain Ground Floor 6-10 years SF Floor - Concrete Epoxy/ Painted Ground Floor 150 5 1-2 years Missing pieces of epoxy Floor - Concrete Epoxy/ Painted Ground Floor 2.755 SF 5 10+ years Lighting - Pendent/Surface Ground Floor 21 ΕA 6 6-10 vears Lighting - Wall Mounted Ground Floor 4 EA 6 6-10 years Stairs - Concrete Stairs Ground Floor 5 LF 6 10+ years LF Stairs - Concrete Stairs Ground Floor 3 6 10+ years Walls - Masonry Ground Floor 652 SF 6 10+ years SF Walls - Masonry Ground Floor 20 6 10+ vears SF Walls - Metal Panel Ground Floor 340 6 10+ vears SF Walls - Plaster/Drvwall Ground Floor 5.505 6 10+ years Walls - Plaster/Drywall Ground Floor 5 SF 6 10+ years Safety Camera Viewing Station FΑ 7 Entire Building 1 6-10 years Security Cameras Entire Building 5 FΑ 7 6-10 years 2 Security Cameras Entire Building ΕA 7 6-10 years Stairs Ceiling - Lay-in E Stairs #3 250 SF 6 10+ years Floor - Concrete Epoxy/ Painted SF E Stairs #3 258 5 10+ years Handrails E Stairs #3 156 LF 5 10+ years



Category : Interior		Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	E Stairs #3	6	EA	6	6-10 years	
	Stairs - Concrete	E Stairs #3	75	LF	6	10+ years	
	Walls - Plaster/Drywall	E Stairs #3	4,132	SF	6	10+ years	
	Ceiling - Plaster/Drywall	N Stair #1	115	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	N Stair #1	55	SF	7	10+ years	Updated to match current observations
	Handrails	N Stair #1	48	LF	7	10+ years	Updated to match current observations
	Lighting - Wall Mounted	N Stair #1	1	EA	6	6-10 years	
	Stairs - Concrete	N Stair #1	20	LF	6	10+ years	
	Walls - Plaster/Drywall	N Stair #1	1,000	SF	6	10+ years	
	Ceiling - Lay-in	W Stair #2	232	SF	6	10+ years	
	Ceiling - Plaster/Drywall	W Stair #2	231	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	W Stair #2	510	SF	7	10+ years	
	Handrails	W Stair #2	204	LF	7	10+ years	
	Lighting - Pendent/Surface	W Stair #2	5	EA	6	10+ years	
	Lighting - Wall Mounted	W Stair #2	1	EA	6	10+ years	
	Stairs - Concrete	W Stair #2	82	LF	6	10+ years	
	Walls - Plaster/Drywall	W Stair #2	2,000	SF	6	10+ years	



2233 W Ohio STREET, Chicago, IL 60612

Category : Exterior			Building : Addition					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ntrance								
	Exterior Doors - Exterior Steel Door	#7 S	2	EA	6	10+ years		
	Exterior Stairs - Concrete	#7 S	10	LF	6	10+ years		
	Exterior Stairs - Stone	#7 S	6	LF	5	1-2 years	Broken stone	
	Stair Handrail - Steel_Stair Handrail	#7 S	12	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	#8 N	2	EA	6	10+ years		
	Exterior Stairs - Concrete	#8 N	12	LF	6	10+ years		
	Exterior Stairs - Stone	#8 N	6	LF	6	10+ years	Stone is showing deterioration at base and general wear and tear	
	Stair Handrail - Steel_Stair Handrail	#8 N	12	LF	6	10+ years		
oundati	on							
	Foundation - Concrete	Entire Building	298	LF	7	10+ years		
	Foundation - Concrete	Entire Building	2	LF	6	6-10 years		
	Superstructure - Slab on Grade	Entire Building	5,685	SF	7	10+ years		
ighting								
0 0	Exterior Lighting - Wall Mounted	Entire Building	9	EA	7	10+ years		
oof Sys	tom							
001 398	Access Ladder - Metal	#10	1	EA	7	10+ years		
	Chimney - Metal Flue	#10	12	LF	7	10+ years		
	Coping - Metal	#10	300	LF	7	10+ years		
	Downspouts - Interior Downspouts	#10	36	LF	6	10+ years		
	Parapet - Parapet < 16" Height	#10	300	LF	7			
	Roof - Modified Bitumen	#10	5,148	SF	7	10+ years		
		-		SF	7	10+ years		
	Roof Structure - Steel / Metal Deck/	#10	5,148	55	1	10+ years		
	Concrete Topping Access Ladder - Metal	#9	1	EA	7	10+ years		
		#9 #9	30		7			
	Coping - Metal			LF		10+ years		
	Downspouts - Interior Downspouts	#9	13		6	10+ years		
	Parapet - Parapet < 16" Height	#9	30	LF	7	10+ years		
	Roof - Modified Bitumen	#9	627	SF	7	10+ years		
	Roof Hatch - Metal	#9	1	EA	7	10+ years		
	Roof Structure - Heavy Timber	#9	627	SF	7	10+ years		
Valls								
	Exterior Walls - Brick	Entire Building	6,200	SF	6	10+ years		
	Exterior Walls - Brick	Entire Building	400	SF	5	10+ years	Deteriorated mortar	
lindows								



Catego	ry : Exterior		В	uilding	: Additio	on	
-				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lintels - Steel	Entire Building	64	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	312	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Additie	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
0	Emergency A/C Power - Corridors and Stairs	Entire Building	1,525	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	3,900	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	No back up system or EG Quantity change per current observation
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	No back up system or EG
	Emergency Battery Packs - Gym	Gym	4	EA	6	6-10 years	Very old and needs new battery packs
Main Se							
	PA System	Entire Building	5,685	SF	3	0-1 year	PA system doesn't work properly. Served from main
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	1-2 years	
Catego	ry : Fire Protection		В	uilding	: Additie	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	5,685	SF	7	10+ years	Per current observation installed
	· · · · · · · · · · · · · · · · · · ·		0,000	0.			
	Fire Alarm_System	Entire Building	5,685	SF	7	10+ years	entire building strobe lights Replace new fire alarm system in 2021 Per current observation installed entire building strobe lights Replace new fire alarm system in 2021
Catego	-	Entire Building	5,685	SF	7 : Additie	on	new fire alarm system in 2021 Per current observation installed entire building strobe lights Replace
	Fire Alarm_System	Entire Building	5,685	SF		on Recommend	new fire alarm system in 2021 Per current observation installed entire building strobe lights Replace new fire alarm system in 2021
Group	Fire Alarm_System ry : Mechanical Item - Type		5,685 B	SF uilding	: Additio	on Recommend	new fire alarm system in 2021 Per current observation installed entire building strobe lights Replace new fire alarm system in 2021
	Fire Alarm_System ry : Mechanical Item - Type Devices	Location	5,685 B Quantity	SF uilding UOM	: Additio Rank	on Recommend Replacement	new fire alarm system in 2021 Per current observation installed entire building strobe lights Replac new fire alarm system in 2021
Group	Fire Alarm_System ry : Mechanical Item - Type		5,685 B	SF uilding	: Additio	on Recommend	new fire alarm system in 2021 Per current observation installed entire building strobe lights Replac new fire alarm system in 2021



Catego	ry : Mechanical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Heater - Gas	Gym	2	EA	6	6-10 years	
Tempera	ature Control						
	Electric Controls	Entire Building	1	SF	6	6-10 years	New item added per current observation- Gym office served electric heater
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
- 0	Domestic Piping-Hot Water Return Lines	Entire Building	5,685	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	5,685	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	5,685	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	5,685	SF	6	6-10 years	
	Sanitary Piping	Entire Building	5,685	SF	6	6-10 years	
	Storm Piping	Entire Building	5,685	SF	6	6-10 years	
	Vent Piping	Entire Building	5,685	SF	6	6-10 years	
Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	Gym Office	120	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	6	10+ years	
	Floor - Tile	Gym Office	120	SF	7	10+ years	
	Floor - Tile	Gym Office	6	SF	5	2-5 years	Tiles chipping
	Lighting - Lay-in	Gym Office	2	EA	7	10+ years	
	Power Distribution	Gym Office	2	EA	7	10+ years	
	Walls - Concrete Block	Gym Office	320	SF	6	10+ years	
Gymnas	ia						
,	Ceiling - Exposed	Ground floor	3,900	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Ground floor	600	SF	6	10+ years	
	Doors - Hardware	Ground floor	2	EA	6	10+ years	
	Floor - Sport Flooring	Ground floor	600	SF	7	10+ years	
	Floor - Wood	Ground floor	3,900	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	Ground floor	10	EA	7	10+ years	
	Lighting - Pendent/Surface	Ground floor	6	EA	7	10+ years	
	5 · · 5 · · · · · · · · · · · · · · · · · · ·		C C	·	•		



Category : Room			В	uilding	: Additi		
				Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sound System	Ground floor	1	EA	7	6-10 years	
	Stage	Ground floor	750	SF	6	10+ years	
	Stage	Ground floor	8	SF	5	0-1 year	Wood splintering
	Stage	Ground floor	6	SF	5	0-1 year	Loose tile
	Stage Curtain	Ground floor	9	EA	7	6-10 years	
	Stage-Stairs - Wood	Ground floor	10	LF	6	10+ years	
	Storage/ Closet	Ground floor	120	SF	7	10+ years	
	Walls - Concrete Block	Ground floor	4,800	SF	6	10+ years	
	Walls - Structural Glazed Tile	Ground floor	1,425	SF	6	10+ years	
<i>Jechani</i>	cal/ Service Rooms						
	Storage Room	1st Floor	90	SF	5	10+ years	
Restroon	1						
	Accessories	Gym, Boys Restroom	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym, Boys Restroom	70	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym, Boys Restroom	2	ĒA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym, Boys Restroom	70	SF	6	10+ years	
	Lavatory	Gym, Boys Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Gym, Boys Restroom	1	EA	6	0-1 year	Light dim
	Partitions	Gym, Boys Restroom	1	EA	7	6-10 years	Light and
	Showers	Gym, Boys Restroom	1	EA	7	6-10 years	
	Student Lockers - Two Tiers	Gym, Boys Restroom	18	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Gym, Boys Restroom	340	SF	6	10+ years	
	Water Closet	Gym, Boys Restroom	1	EA	6	6-10 years	
	Accessories	Gym, Girls Restroom	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym, Girls Restroom	70	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym, Girls Restroom	1	EA	7	10+ years	Updated to match current observations
	Doors - Wood Doors inclu hw	Gym, Girls Restroom	1	EA	6	0-1 year	Missing grate
	Floor - Tile Ceramic/ Porcelain	Gym, Girls Restroom	70	SF	6	10+ years	Missing grate
	Lavatory	Gym, Girls Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Gym, Girls Restroom	1	EA	7	10+ years	
	Partitions	Gym, Girls Restroom	1	EA	7	6-10 years	
	Showers	Gym, Girls Restroom	1	EA	7	6-10 years	Not in use
	Student Lockers - Two Tiers	Gym, Girls Restroom	18	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Gym, Girls Restroom	340	SF	6	10+ years	
	Water Closet	Gym, Girls Restroom	340 1	EA	6	6-10 years	
Catego	ategory : Interior		В	uilding			
	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Group	nem - Type	Location	Quantity	UOW	Rank	Replacement	Comments



i
ig and chipping



Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Civil/Dra			j				
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	6	10+ years	
Fencina							
- crioing	Fencing - Chain Link	Entire Site	75	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,532	LF	6	10+ years	
Landsca	De						
Landood	Benches	Entire Site	2	EA	7	10+ years	
	Benches	Entire Site	13	EA	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	9,556	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	4,290	SF	4	0-1 year	Large cracks and vegetation growth
	Landscape - Hardscape- Concrete	Entire Site	3,837	SF	6	6-10 years	
	Landscape - Hardscape- Pavers	Entire Site	720	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	4	EA	6	10+ years	
	Parkway trees	Entire Site	24	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	2.281	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	13,438	SF	6	10+ years	
	Play Area - Synthetic Turf	Entire Site	7,708	SF	6	10+ years	
	Trash Receptacles	Entire Site	5	EA	6	10+ years	
Parking I	ot						
	Lighting - Pole Mounted	S Parking Lot	3	EA	6	10+ years	
	Surface - Asphalt	S Parking Lot	25,085	SF	6	6-10 years	
	Surface - Asphalt	S Parking Lot	200	SF	5	0-1 year	Potholes and disintegrated asphalt
	Surface - Concrete	S Parking Lot	600	SF	6	10+ years	5 1
	Trash Enclosure - Chain Links	S Parking Lot	740	SF	6	10+ years	
Playgrou	nd						
	Equipment - Combo 3-12	E Playground	1	EA	7	10+ years	
	Equipment - School Age 5-12	E Playground	1	EA	7	10+ years	
	Surface - Poured Surface	E Playground	4,213	SF	7	10+ years	
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	172	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	30	LF	4	0-1 year	Damaged concrete, broken, spalled
	Sidewalks - Perimeter Sidewalks	Entire Site	10,910	SF	6	10+ years	- · · · · ·
	Sidewalks - Perimeter Sidewalks	Entire Site	50	SF	4	0-1 year	Damaged apron



Category : Site Building : Site Recommend Replacement Group Item - Type Location Quantity UOM Rank Comments Signage Flag Pole - Flag Pole 1 ΕA 5 Entire Site 6-10 years The concrete base is spalled, not broken Entire Site ΕA 6 Marquee - Free Standing Back Lighted 1 10+ years Monument - Building Mounted Cut Letter **Entire Site** ΕA 6 10+ years 1 Sign

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

• Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated

• Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	v	•		,					
Art Room	Regular Classroom	2nd Floor	208	208	952	100	60	N	N
Kindergarten	Regular Classroom	1st Floor	103	103	952	110	60	N	N
Music Room	Regular Classroom	1st Floor	107	107	723	108	60	N	N
Pre School	Regular Classroom	1st Floor	101	101	952	100	60	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	952	100	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	952	100	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	952	100	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	950	106	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	952	110	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	952	100	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	952	100	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	952	100	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	790	60	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	952	56	32	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	790	44	26	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	952	100	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	952	100	60	N	Ν
Science	Regular Classroom	3rd Floor	306	306	952	56	32	N	Ν
Special Education	Gymnasium	1st Floor	105	105	952	110	60	N	Ν