

the end of this report.

**Facility Assessment Report** 

# This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1949	2	18,117
Addition	1953	2	15,101
Campus Total			33,218

Category: Exterior **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Entrance Entrance Control - Audio #1 - Main - NW 1 EΑ 7 6-10 years Exterior Doors - Exterior Steel Door #1 - Main - NW 2 EΑ 6 10+ years 2 Exterior Doors - Transom Lite #1 - Main - NW EΑ 6 10+ years LF Exterior Stairs - Concrete #1 - Main - NW 24 6 10+ years Exterior Stairs - Concrete 6 LF 5 6-10 years #1 - Main - NW Power Door Operator and Controls #1 - Main - NW EΑ 7 6-10 years Ramp Handrail - Steel Ramp Handrail #1 - Main - NW 120 LF 5 10+ years LF Ramps - Concrete #1 - Main - NW 50 6 10+ years ΙF 5 Ramps - Concrete #1 - Main - NW 10 Cracks in the concrete retaining wall 1-2 years and Ramp LF 5 Stair Handrail - Steel Stair Handrail #1 - Main - NW 14 10+ years Exterior Doors - Exterior Steel Door #2 - SW 2 EΑ 6 10+ years Exterior Doors - Transom Lite #2 - SW 2 6 10+ years EΑ Exterior Stairs - Concrete #2 - SW 72 LF 5 2-5 years Crack in the concrete LF 7 Exterior Stairs - Stone #2 - SW 6 10+ years LF Stair Handrail - Steel\_Stair Handrail #2 - SW 16 7 10+ years Exterior Doors - Exterior Steel Door #7 - E EΑ 7 10+ years 1 LF Exterior Stairs - Concrete #7 - E 40 6 10+ years Exterior Stairs - Concrete #7 - E 20 LF 5 1-2 years Cracked, chipped concrete steps ΙF Stair Handrail - Steel Stair Handrail 50 7 #7 - E 10+ years Foundation Foundation - Concrete **Entire Building** 5 LF 7 10+ years



Category : Exterior			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Foundation - Concrete	Entire Building	345	LF	7	10+ years	
	Foundation - Concrete	Entire Building	10	LF	5	1-2 years	Cracked concrete foundation at Ligh well, Cracked foundation wall
	Superstructure - Concrete	Entire Building	17,367	SF	7	10+ years	·
	Superstructure - Steel	Entire Building	750	SF	7	10+ years	
المطامة							
Lighting	Exterior Limbting Descript or Deaf Marintal	Fatina Duildina		ΓΛ		0.40	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	5	EΑ	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	6-10 years	
Roof Sys							
	Coping - Metal	Low roof	55	LF	7	10+ years	
	Downspouts - Interior Downspouts	Low roof	62	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Low roof	55	LF	6	10+ years	
	Roof - Modified Bitumen	Low roof	375	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Low roof	375	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EΑ	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	54	LF	7	10+ years	
	Coping - Stone	Main Roof	379	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	72	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	1	LF	5	1-2 years	Missing drain strainer
	Parapet - 16" - 30" Height	Main Roof	379	LF	6	10+ years	imboning drain ordinarior
	Roof - Modified Bitumen	Main Roof	7,257	SF	6	10+ years	
	Roof Hatch - Metal	Main Roof	1,201	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	7,257	SF	7	10+ years	
Malla							
<i>N</i> alls	Cheek-Wall - Concrete	Entire Building	103	SF	7	10+ years	
	Cheek-Wall - Concrete	Entire Building	5	SF	5	1-2 years	Cracked concrete at cheek wall
	Cheek-Wall - Stone	Entire Building	140	SF	6	10+ years	
	Cornice - Cast Stone	Entire Building	305	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	10,810	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	5	10+ years	Deteriorated mortar, flush pointed
		ŭ				-	masonry
	Exterior Walls - Stone-Cast	Entire Building	680	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	40	SF	5	10+ years	
Vindows	3						
	Curtain wall - Insulated Panel	Entire Building	12	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	1,044	SF	7	10+ years	
		Entire Building	137	LF	7	,	

Campus Name: Owen Page : 2 of 23 Assessment Date: 02/10/2022



Catego	ry : Exterior		В	uilding	: Main	_	
0	Ham Time	Location	0	11014	Devil	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lintels - Stone	Entire Building Entire Building	104 2,146	LF SF	7 7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire building	2,140	SF	,	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	cy System	Location	Quantity	COM	Rank	Replacement	Comments
-merger	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	33,218	SF	6	6-10 years	
				SF			
	Security System - Intrusion Detection	Entire Building	33,281		6	6-10 years	N. 1. (6 1 1.
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	2	0-1 year	No battery backup
	Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	6	2-5 years	Quantity change per current observation
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,766	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	992	SF	6	10+ years	
Main Ser							
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	18,117	SF	4	0-1 year	Partially working per current observation
Power D	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	2-5 years	Fuse panel from original
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	r dee parier nem enginar
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Item type change per current
	Lighting and Fower Fallers - Above 100 A	Entire Building	'	LA	,	10+ years	observation 100Amp to Above 100Amp
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	New item added per current observation Cover missing
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	2-5 years	Missing breakers and cover
	Main Distribution Panels - Less than 400	Entire Building  Entire Building	1	EA	7	10+ years	Missing broakers and cover
	amp Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Boiler Room and Entire Building	1	EA	6	0-1 year	Intermittent issues and not connected

Campus Name: Owen Page: 3 of 23 Assessment Date: 02/10/2022



Categor	y : Fire Protection		В	uilding	: Main		
	Name Time	Lasadan	0	11014	Danie	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Boiler Room and Entire Building	18,117	SF	6	6-10 years	to emergency phone services
	Fire Alarm_System	Boiler Room and Entire Building	18,117	SF	6	6-10 years	
	The Alann_System	Boller Room and Entire Building	10,117	OI.	U	0-10 years	
ategor	y : Mechanical		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Handl	ing Systems						
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Attic	1	EA	5	2-5 years	
	Air Handling Unit- Built Up- Multi Zone- Hot Water Coils - 25001 - 35000 cfm	Boiler Room, Roof & Entire Building	1	EA	5	6-10 years	Pump replaced in 2021
	Air Intake	Boiler Room, Roof & Entire Building	1	EA	5	6-10 years	Rusty
	Auxiliaries - 25001 - 35000 cfm	Boiler Room, Roof & Entire Building	1	EA	5	6-10 years	Control needs to be adjusted
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Boiler Room, Roof & Entire Building	100	LF	5	6-10 years	Need to be rebalanced
	Zone Dampers	Boiler Room, Roof & Entire Building	21	EA	5	6-10 years	Need to adjusted
oiler Sys	stems						
·	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Boiler Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	6-10 years	
leating C	Devices						
J	Fin Tube - Hot Water	1st Floor	16	LF	6	10+ years	New item added per current observation
	Unit Heater - Electric	Entire Building	1	EA	6	10+ years	New item added per current observation Elevator room
	Wall Heater - Electric	Entire Building	1	EA	4	1-2 years	Corroded, missing bottom cover
	Wall Heater - Electric	Entire Building	1	EA	2	0-1 year	Missing cover and not working Engineer office
lechanic	eal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	2	EA	5	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	300	LF	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	100	LF	6	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ature Control	2004.1011	quantity		rtaint	replacement	
	Electric Thermostat	Entire Building	1	EA	6	10+ years	New item added per current observation Elevator room heater
	Hybrid Pneumatic/DDC System	Entire Building	33,218	SF	5	6-10 years	
√entilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM Exhaust Fans- Indoor - Less than 500 CFM	Entire Building Entire Building	1 2	EA EA	6 6	6-10 years 6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	18,117	SF	4	2-5 years	Pipes are galvanized
	Domestic Piping-Hot Water Return Risers	Entire Building	18,117	SF	4	2-5 years	Pipes are galvanized
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	18,117	SF	4	2-5 years	Pipes are galvanized
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	18,117	SF	4	2-5 years	Pipes are galvanized
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	18,117	SF	4	2-5 years	Pipes are galvanized
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	18,117	SF	4	2-5 years	Pipes are galvanized
	Sanitary Piping	Entire Building	18,117	SF	6	6-10 years	
	Storm Piping	Entire Building	18,117	SF	6	6-10 years	
	Vent Piping	Entire Building	18,117	SF	6	6-10 years	
umps							
	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	2	0-1 year	Not working per current observation
	Pumps - Ejector-Duplex Pumps - Sump-Simplex	Boiler Room Boiler Room	1 1	EA EA	6 6	6-10 years 6-10 years	Not accessible
Catego	ry : Room		В	uilding	: Main		
J -			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Exposed	Engineer's Office	110	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	7	10+ years	
	Floor - Tile	Engineer's Office	110	SF	6	10+ years	

Campus Name: Owen Page : 5 of 23 Assessment Date: 02/10/2022



Catego	Category : Room			uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	6-10 years	
	Power Distribution	Engineer's Office	4	EA	7	10+ years	
	Storage/ Closet	Engineer's Office	6	SF	7	10+ years	
	Walls - Masonry	Engineer's Office	246	SF	7	10+ years	
	AC Unit	Main Office, 1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office, 1st Floor	343	SF	7	10+ years	
	Doors - Transom Window	Main Office, 1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office, 1st Floor	1	EA	7	10+ years	
	Floor - Carpet	Main Office, 1st Floor	118	SF	7	10+ years	
	Floor - Carpet	Main Office, 1st Floor	2	SF	4	0-1 year	Torn
	Floor - Tile	Main Office, 1st Floor	198	SF	7	10+ years	
	Floor - Tile	Main Office, 1st Floor	25	SF	4	0-1 year	Cracking
	Lighting - Pendent/Surface	Main Office, 1st Floor	7	EΑ	7	6-10 years	
	Power Distribution	Main Office, 1st Floor	10	EA	7	10+ years	
	Storage/ Closet	Main Office, 1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office, 1st Floor	480	SF	7	10+ years	
	Work SInk	Main Office, 1st Floor	1	EA	7	10+ years	
	AC Unit	Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Office	181	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	7	10+ years	
	Floor - Carpet	Principal's Office	181	SF	7	6-10 years	
	Floor - Carpet	Principal's Office	3	SF	5	1-2 years	Cracked tile
	Lighting - Pendent/Surface	Principal's Office	4	EA	7	6-10 years	
	Power Distribution	Principal's Office	6	EA	7	10+ years	
	Storage/ Closet	Principal's Office	20	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office	330	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office	3	SF	6	1-2 years	Holes through wall
	Work SInk	Principal's Office	1	EA	7	10+ years	ŭ
		·				·	
Kitchen							
	Ceiling - Plaster/Drywall	2nd Floor - North of South stair	353	SF	7	10+ years	
	Doors - Transom Window	2nd Floor - North of South stair	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - North of South stair	1	EA	7	10+ years	
	Floor - Tile	2nd Floor - North of South stair	343	SF	7	10+ years	
	Floor - Tile	2nd Floor - North of South stair	10	SF	4	0-1 year	Cracking
	Lighting - Pendent/Surface	2nd Floor - North of South stair	3	EA	7	6-10 years	-
	Walls - Plaster/Drywall	2nd Floor - North of South stair	912	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - North of South stair	8	SF	5	0-1 year	Plaster cracking
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	36	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	42	SF	7	10+ years	
	Vaults	1st Floor	64	SF	7	10+ years	
	Janitor's Closet	2nd Floor	60	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	2nd Floor	70	SF	7	10+ years	
	Air Intake Plenums	Basement	358	SF	7	10+ years	
	Air Tunnel	Basement	522	SF	7	10+ years	
	Boiler Room	Basement	1,503	SF	7	10+ years	
	Coal Room	Basement	374	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	9,048	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	380	SF	7	10+ years	
	Storage Room	Basement	351	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor	221	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	221	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	221	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	1	EΑ	7	10+ years	
	Urinals	1st Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	100	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	398	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	6	SF	5	0-1 year	Cracking
	Water Closet	1st Floor	1	ĒΑ	7	10+ years	
	Accessories	1st Floor	275	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	275	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	275	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EΑ	7	6-10 years	
	Lavatory	1st Floor	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	102	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	430	SF	7	10+ years	
	Walls - Structural Glazed Tile Walls - Structural Glazed Tile	1st Floor	430	SF	5	1-2 years	Cracking mortar, damage
	Water Closet	1st Floor	6	EA	7	10+ years	Cracking mortar, damage
	Accessories	1st Floor - inside classroom 102	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - inside classroom 102	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - inside classroom 102	1	EA	7	10+ years	
	Floor - Tile	1st Floor - inside classroom 102	35	SF	7	10+ years	
	Lavatory	1st Floor - inside classroom 102	1	EA	7	10+ years	
	Lavatory Lighting - Pendent/Surface	1st Floor - inside classroom 102	1	EA	7		
	Walls - Concrete Block		96	SF	7	6-10 years	
	vvalis - Concrete Block	1st Floor - inside classroom 102	96	SF.	1	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor - inside classroom 102	96	SF	7	10+ years	
	Water Closet	1st Floor - inside classroom 102	1	EA	7	10+ years	
	Accessories	2nd Floor	221	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	221	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	221	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years	
	Partitions	2nd Floor	1	EA	7	10+ years	
	Urinals	2nd Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	398	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	8	SF	5	1-2 years	Cracking
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor	275	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	275	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	275	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years	
	Partitions	2nd Floor	6	ΕA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	102	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	326	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	8	SF	6	1-2 years	Missing mortar
	Water Closet	2nd Floor	6	ĒΑ	7	10+ years	gg
	Accessories	2nd Floor - Kitchen	49	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Kitchen	49	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Kitchen	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Kitchen	49	SF	7	10+ years	
	Lavatory	2nd Floor - Kitchen	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Kitchen	1	EΑ	7	6-10 years	
	Partitions	2nd Floor - Kitchen	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Kitchen	252	SF	7	10+ years	
	Water Closet	2nd Floor - Kitchen	1	EA	7	10+ years	
	Accessories	In Engineer's Office	24	SF	7	6-10 years	
	Ceiling - Exposed	In Engineer's Office	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Engineer's Office	1	EA	7	10+ years	
	Floor - Tile	In Engineer's Office	24	SF	6	•	
	1 1001 - 1 116	III Engineer 5 Onice	24	ЭF	O	10+ years	

Campus Name: Owen Page : 8 of 23 Assessment Date: 02/10/2022



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	In Engineer's Office	1	EA	7	6-10 years	
	Walls - Masonry	In Engineer's Office	25	SF	7	10+ years	
	Walls - Plaster/Drywall	In Engineer's Office	70	SF	7	10+ years	
	Water Closet	In Engineer's Office	1	EA	7	6-10 years	
	Accessories	In the Main Office	64	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In the Main Office	64	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In the Main Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In the Main Office	64	SF	7	10+ years	
	Lighting - Pendent/Surface	In the Main Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	In the Main Office	157	SF	7	10+ years	
	Water Closet	In the Main Office	1	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #100 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	692	SF	7	10+ years	
	Chalk Board	1st Floor	28	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	692	SF SF	7	10+ years	Objection tile
	Floor - Tile	1st Floor	2		5	1-2 years	Chipping tile
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,120	SF	7	10+ years	
Classroc	om #101 (Other Instructional Use)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	340	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	340	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Marker Board	1st Floor	4	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	936	SF	7	10+ years	
Classroc	om #102 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	835	SF	7	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
						•	



Catego	ry : Classroom		В	uilding	: Main		7 6 Offinstiana AVENOE, Officago, 12 00032
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	835	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,952	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Damaged
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5		Lagge gover
				SF		1-2 years	Loose cover
	Storage/ Closet	1st Floor	14	SF SF	5 7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,296	SF	/	10+ years	
Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	692	SF	7	10+ years	
	Chalk Board	2nd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	692	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years	
Classroo	om #201 (Library)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	46	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	995	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Carpet	2nd Floor	995	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,677	SF	7	10+ years	
	Walls - Plaster/Drywall Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,077	SF SF	<i>7</i> 6		Loose fixture
						1-2 years	LOOSE HYIME
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	



Guicgo	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	686	SF	6	10+ years	
	Chalk Board	2nd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	686	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	676	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	676	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	•	
	Storage/ Closet	2nd Floor 2nd Floor	14	SF	7	6-10 years 10+ years	
			1,296	SF	7	-	
	Walls - Plaster/Drywall	2nd Floor	1,296	SF	/	10+ years	
atego	ry : Interior		В	uilding	: Main		
						Recommend	
			A	11084	D I-	D I (	0 1 -
•	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•						•	Comments
•	Ceiling - Plaster/Drywall	1st Floor	1,498	SF	7	10+ years	Comments
•	Ceiling - Plaster/Drywall Doors - Wood Doors include hw	1st Floor 1st Floor	1,498	SF EA	7 6	•	Comments
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain	1st Floor	1,498	SF EA EA	7 6 7	10+ years	Comments
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw	1st Floor 1st Floor	1,498	SF EA	7 6	10+ years 10+ years	Updated to match current
•	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor	1,498 4 1 1,492	SF EA EA SF	7 6 7 7	10+ years 10+ years 10+ years 10+ years	Updated to match current observations
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor	1,498 4 1 1,492	SF EA EA SF	7 6 7 7	10+ years 10+ years 10+ years 10+ years 1-2 years	Updated to match current
•	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,498 4 1 1,492 16 14	SF EA EA SF SF	7 6 7 7 5	10+ years 10+ years 10+ years 10+ years 1-2 years 6-10 years	Updated to match current observations
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier	1st Floor	1,498 4 1 1,492 16 14 73	SF EA EA SF SF EA EA	7 6 7 7 5 7 6	10+ years 10+ years 10+ years 10+ years 1-2 years 6-10 years 10+ years	Updated to match current observations
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall	1st Floor	1,498 4 1 1,492 16 14 73 1,599	SF EA SF SF EA EA SF	7 6 7 7 5 7 6	10+ years 10+ years 10+ years 10+ years 1-2 years 6-10 years 10+ years 10+ years	Updated to match current observations
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet  Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile	1st Floor	1,498 4 1 1,492 16 14 73 1,599 1,599	SF EA SF SF EA EA SF SF	7 6 7 7 5 7 6 6 6	10+ years 10+ years 10+ years 10+ years 1-2 years 6-10 years 10+ years 10+ years	Updated to match current observations
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet  Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall	1st Floor 2nd Floor	1,498 4 1 1,492 16 14 73 1,599 1,599 1,486	SF EA SF SF EA EA SF SF SF	7 6 7 7 5 7 6 6 6	10+ years 10+ years 10+ years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Updated to match current observations Cracking
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet  Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	1st Floor 2nd Floor 2nd Floor	1,498 4 1 1,492 16 14 73 1,599 1,599 1,486 12	SF EA SF SF EA SF SF SF SF	7 6 7 7 5 7 6 6 6 7	10+ years 10+ years 10+ years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	Updated to match current observations
•	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet  Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Wood Doors include hw	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,498 4 1 1,492 16 14 73 1,599 1,599 1,486 12 4	SF EA SF SF EA SF SF SF SF EA	7 6 7 7 5 7 6 6 6 7 5	10+ years 10+ years 10+ years 10+ years 1-2 years 6-10 years 10+ years	Updated to match current observations Cracking
•	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet  Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Double Fountain	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,498 4 1 1,492 16 14 73 1,599 1,599 1,486 12 4	SF EA SF SF EA SF SF SF EA EA	7 6 7 7 5 7 6 6 6 7 5 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Updated to match current observations Cracking
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet  Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Tile/Sheet	1st Floor 2nd Floor	1,498 4 1 1,492 16 14 73 1,599 1,599 1,486 12 4 1	SF EA SF SF EA SF SF SF EA SF	7 6 7 7 5 7 6 6 6 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Updated to match current observations Cracking
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet  Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 2nd Floor	1,498 4 1 1,492 16 14 73 1,599 1,599 1,486 12 4 1 1,498	SF EA SF SF EA SF SF SF EA SF EA	7 6 7 7 5 7 6 6 6 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Updated to match current observations Cracking
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet  Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier	1st Floor 2nd Floor	1,498 4 1 1,492 16 14 73 1,599 1,599 1,486 12 4 1 1,498 14	SF EA SF SF EA SF SF EA SF EA EA	7 6 7 7 5 7 6 6 6 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Updated to match current observations Cracking
Group Corridor	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Triple Fountain Floor - Tile/Sheet  Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 2nd Floor	1,498 4 1 1,492 16 14 73 1,599 1,599 1,486 12 4 1 1,498	SF EA SF SF EA SF SF SF EA SF EA	7 6 7 7 5 7 6 6 6 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Updated to match current observations Cracking



Catego	ry : Interior		В	uilding	: Main		<del>-</del>
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Safety							
•	Camera Viewing Station	Entire Building & Site	1	EA	7	6-10 years	
	Security Cameras	Entire Building & Site	1	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	539	SF	7	10+ years	
	Floor - Terrazzo	North	360	SF	6	10+ years	
	Handrails	North	64	LF	7	10+ years	
	Lighting - Pendent/Surface	North	4	EΑ	6	6-10 years	
	Stairs - Terrazzo	North	30	LF	6	10+ years	
	Walls - Plaster/Drywall	North	907	SF	7	10+ years	
	Walls - Plaster/Drywall	North	7	SF	5	1-2 years	Cracking
	Walls - Structural Glazed Tile	North	914	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	539	SF	7	10+ years	
	Floor - Terrazzo	South	360	SF	7	10+ years	
	Handrails	South	64	LF	7	10+ years	
	Lighting - Pendent/Surface	South	4	EΑ	7	6-10 years	
	Stairs - Terrazzo	South	30	LF	7	10+ years	
	Walls - Plaster/Drywall	South	914	SF	7	10+ years	
	Walls - Structural Glazed Tile	South	904	SF	7	10+ years	
	Walls - Structural Glazed Tile	South	10	SF	5	1-2 years	
Vertical (	Conveyance						
	Elevator - Elevator- Roped Holeless Hydraulic	1st Floor	1	EA	6	10+ years	





Category: Exterior **Building: Addition** 

	y : Exterior	Building : Addition								
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Entrance										
	Exterior Doors - Exterior Steel Door	#3 - S	3	EA	7	10+ years				
	Exterior Doors - Transom Lite	#3 - S	3	EA	7	10+ years				
	Exterior Stairs - Concrete	#3 - S	60	LF	7	10+ years				
	Exterior Stairs - Concrete	#3 - S	30	LF	5	1-2 years				
	Stair Handrail - Steel_Stair Handrail	#3 - S	28	LF	6	10+ years				
	Exterior Doors - Exterior Steel Door	#4 - SE	1	EA	7	10+ years				
	Exterior Stairs - Steel or Aluminum	#4 - SE	20	LF	7	10+ years				
	Stair Handrail - Steel_Stair Handrail	#4 - SE	15	LF	7	10+ years				
	Entrance Control - Audio	#5 - E	1	ĒΑ	7	6-10 years				
	Exterior Doors - Exterior Steel Door	#5 - E	1	EA	7	10+ years				
	Exterior Stairs - Concrete	#5 - E	100	LF	7	10+ years				
	Exterior Stairs - Concrete	#5 - E	5	LF	5	1-2 years	Cracks in the concrete at most post			
	Extend Stand Controls		9		Ū	. <i>-</i> youro	bases			
	Ramp Handrail - Steel_Ramp Handrail	#5 - E	100	LF	5	10+ years				
	Ramps - Concrete	#5 - E	50	LF	5	1-2 years	Cracks in the concrete at most post			
	Tramps Concrete				Ū	. <i>-</i> youro	bases			
	Stair Handrail - Steel_Stair Handrail	#5 - E	10	LF	5	10+ years				
	Exterior Doors - Exterior Steel Door	#6 - NE	2	EA	7	10+ years				
	Extend Door Extend Gloci Door	,,, o .,,_	_	_, .	•	ioi youro				
Foundation	nn									
Touridanc	Foundation - Concrete	Entire Building	399	LF	7	10+ years				
	Superstructure - Concrete	Entire Building	15,101	SF	7	10+ years				
	Superstructure - Concrete	Littile Building	13,101	01	'	10+ years				
Lighting										
Lighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	7	6-10 years				
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	7	6-10 years				
	Exterior Lighting Wall Modified	Entire Ballating	J	L/\	,	o io years				
Roof Syst	em									
,	Coping - Stone	Low E roof	157	LF	7	10+ years				
	Downspouts - Interior Downspouts	Low E roof	60	LF	7	10+ years				
	Parapet - 16" - 30" Height	Low E roof	157	LF	7	10+ years				
	Roof - Modified Bitumen	Low E roof	3,184	SF	6	10+ years				
	Roof Structure - Steel with Clay Tile Arch	Low E roof	3,184	SF	7	10+ years				
	Coping - Stone	Low NE roof	104	LF	6	10+ years				
	Downspouts - Interior Downspouts	Low NE roof	17	LF	6	10+ years				
	Parapet - 16" - 30" Height	Low NE roof	104	LF	7	10+ years				
	Roof - Modified Bitumen	Low NE roof	1,109	SF	6	10+ years				
	Roof Structure - Steel with Clay Tile Arch	Low NE roof	1,109	SF	7	10+ years				
	Access Ladder - Metal	Main Roof	1	EΑ	7	10+ years				
	Coping - Stone	Main Roof	303	LF	6	10+ years				
	Downspouts - Interior Downspouts	Main Roof	72	LF	7	10+ years				
	1				-	- <b>,</b>				

Campus Name: Owen Page : 13 of 23 Assessment Date: 02/10/2022



Catego	ry : Exterior		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	Main Roof	303	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	5,404	SF	6	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	5,404	SF	7	10+ years	
Nalls							
	Cheek-Wall - Concrete	Entire Building	140	SF	7	10+ years	
	Cornice - Cast Stone	Entire Building	182	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	12,210	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	500	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	10	SF	4	1-2 years	Cracks and open joints, deteriorate
		G				-	mortar
	Exterior Walls - Stone-Cast	Entire Building	698	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	100	SF	5	10+ years	
Vindows							
	Guard - Guards perforated	Entire Building	899	SF	7	10+ years	
	Lintels - Steel	Entire Building	10	LF	7	10+ years	
	Lintels - Steel	Entire Building	111	LF	7	10+ years	
	Lintels - Stone	Entire Building	82	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,711	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
_	Emergency A/C Power - Corridors and Stairs	Entire Building	3,200	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	3,053	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	6	6-10 years	No battery backup or generator
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	2	0-10 years 0-1 year	No battery backup
	Exit Signs - Comdors and Stairs  Exit Signs - Gym	•	8	EA	2	-	Quantity change per current
	Exit Signs - Gyin	Entire Building	0	EA	2	0-1 year	observation No generator or batter backup
	Security System - CCTV	Entire Building	15,101	SF	6	6-10 years	addiap
	Security System - Intrusion Detection	Entire Building	15,101	SF	6	6-10 years	
	rvice						
/Jain Se		Entire Building	15,101	SF	6	10+ years	New item added per current

Campus Name: Owen Page : 14 of 23 Assessment Date: 02/10/2022



Catego	ry : Electrical	В	uilding	: Additi	on		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	UOIVI	Naiik	Replacement	Comments
Fire Alar	Fire Alarm Panel	Entire Duilding	1	EA	6	0.1	Intermittent issues and not connected
	File Alaim Panei	Entire Building	ı	EA	0	0-1 year	to emergency phone services
	Fire Alarm Strobe Lights	Entire Building	15,101	SF	6	6-10 years	to emergency priorite services
	Fire Alarm_System	Entire Building	15,101	SF	6	6-10 years	
	i iio / iiaiiii_Oyoloiii	Zittiro Dallallig	10,101	O.	Ü	o io youro	
Catego	ry : Mechanical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
	Wall Heater - Electric	Entire Building	2	EA	5	2-5 years	Quantity change per current observation Control needs to be adjusted
Tempera	ature Control						
	Hybrid Pneumatic/DDC System	Entire Building	15,101	SF	5	6-10 years	Served from main Need to be
	TI DDG	F // B // P				0.40	adjusted
	Thermostats - DDC	Entire Building	11	EA	6	6-10 years	
Ventilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM Exhaust Fans- Roof Mounted - Less than	Entire Building	2	EA EA	6 6	6-10 years	
	500 CFM	Entire Building	ı	EA	0	6-10 years	
Catago	ry : Plumbing		ь	uilding	. Additi	an.	
Calego	ry . Fidilibilig			unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping	nom Type	2004	Quantity	<b>33</b>	rtariit	rtopiacomoni	Commonte
ршу	Domestic Piping-Hot Water Return Lines	Entire Building	15,101	SF	4	2-5 years	Pipes are galvanized
	Domestic Piping-Hot Water Return Risers	Entire Building	15,101	SF	4	2-5 years	Pipes are galvanized
	Domestic Fibility Flot Water Netulli Nisels			SF	4	2-5 years 2-5 years	Pipes are galvanized
		Entire Building					
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	15,101	O.	•	2 o youro	i ipes are gaivanized
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building  Entire Building	15,101	SF	4	-	•
	Domestic Piping-Hot Water from Risers to	·			-	2-5 years	Pipes are galvanized

Campus Name: Owen Page : 15 of 23 Assessment Date: 02/10/2022



Catego	ry : Plumbing		В	uilding	: Additi		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	15,101	SF	4	2-5 years	Pipes are galvanized
	(from Risers to Fixtures)	E B	4= 404	0=	•	0.40	
	Sanitary Piping	Entire Building	15,101	SF	6	6-10 years	
	Storm Piping	Entire Building	15,101	SF	6	6-10 years	
	Vent Piping	Entire Building	15,101	SF	6	6-10 years	
Catego	ry : Classroom		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #104 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	7	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	14	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,296	SF	7	10+ years	
Classroo	m #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	6	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	686	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	14	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,296	SF	7	10+ years	
Classroo	m #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	6	2-5 years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	686	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	10+ years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,120	SF	7	10+ years	

Campus Name: Owen Page : 16 of 23 Assessment Date: 02/10/2022



Categor	ry : Classroom		В	uilding	: Additio		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	725	SF	6	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	725	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,120	SF	7	10+ years	
Classroo	m #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	692	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	692	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,152	SF	6	10+ years	
Classroo	m #205 (Science)						
	AC Units	2nd Floor	1	EA	5	1-2 years	Doesn't blow cold air
	Casework	2nd Floor	54	LF	6	10+ years	Docont blow cold all
	Ceiling - Plaster/Drywall	2nd Floor	845	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	845	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,478	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	676	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	676	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
				SF	7	•	
	Storage/ Closet	2nd Floor	14	OF.	,	10+ years	

Campus Name: Owen Page : 17 of 23 Assessment Date: 02/10/2022



Mechanical/ Service Rooms

Janitor's Closet Janitor's Closet

Storage Room

#### William Bishop Owen Scholastic Academy ES

XIII S	Schools	8247 S Christiana AVENUE, Chicago, IL 60652							
Catego	ry : Classroom		Building : Addition						
						Recommend			
∂roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	2nd Floor	1,296	SF	6	10+ years			
lassroo	om #208 (Band Room)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years			
	Chalk Board	2nd Floor	40	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Carpet	2nd Floor	725	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,152	SF	6	10+ years			
	Wireless System	2nd Floor	1	EA	7	6-10 years			
atego	ategory : Room		В	uilding					
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ymnasi	ia								
•	Ceiling - Splined	1st Floor	3,053	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	5	EA	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years			
	Floor - Wood	1st Floor	3,053	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years			
	Scoreboards	1st Floor	1	EA	7	10+ years			
	Sound System	1st Floor	1	EA	7	10+ years			
	Stage	1st Floor	405	SF	7	10+ years			
	Stage Curtain	1st Floor	2	EA	7	10+ years			
	Stage Lighting System	1st Floor	1	EA	7	10+ years			
	Stage-Stairs - Asphalt	1st Floor	32	LF	7	10+ years			
	Storage/ Closet	1st Floor	260	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	4,800	SF	7	10+ years			
IDF_ID	F								
1DF_IDI		1st Floor - Room 104A	1	EA	7	10+ years			
1DF_ID	F Doors - Steel Doors incl hw Finishes	1st Floor - Room 104A 1st Floor - Room 104A	1 208	EA SF	7 7	10+ years 10+ years			

20

36

85

SF

SF

SF

7

7

7

10+ years

10+ years

10+ years

1st Floor

2nd Floor

2nd Floor



Catego	ry : Room		Building : Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Restroor	n									
	Accessories	1st Floor - Men	113	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor - Men	113	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor - Men	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men	113	SF	7	10+ years				
	Floor Drain	1st Floor - Men	1	EΑ	7	10+ years				
	Lavatory	1st Floor - Men	1	EΑ	7	10+ years				
	Lighting - Pendent/Surface	1st Floor - Men	1	EΑ	7	6-10 years				
	Lighting - Wall Mounted	1st Floor - Men	1	EΑ	7	6-10 years				
	Partitions	1st Floor - Men	1	EΑ	7	10+ years				
	Urinals	1st Floor - Men	2	EΑ	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Men	97	SF	7	10+ years				
	Walls - Structural Glazed Tile	1st Floor - Men	97	SF	7	10+ years				
	Water Closet	1st Floor - Men	1	EA	7	10+ years				
	Accessories	1st Floor - Women	117	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor - Women	117	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor - Women	1	EΑ	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women	117	SF	7	10+ years				
	Floor Drain	1st Floor - Women	1	EA	7	10+ years				
	Lavatory	1st Floor - Women	1	EΑ	7	10+ years				
	Lighting - Pendent/Surface	1st Floor - Women	1	EΑ	7	6-10 years				
	Lighting - Wall Mounted	1st Floor - Women	1	EΑ	7	6-10 years				
	Partitions	1st Floor - Women	2	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Women	98	SF	7	10+ years				
	Walls - Structural Glazed Tile	1st Floor - Women	98	SF	7	10+ years				
	Water Closet	1st Floor - Women	2	EA	7	10+ years				

Category : Interior **Building: Addition** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Corridor</u>							
	Ceiling - Plaster/Drywall	1st Floor	1,867	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	5	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,867	SF	5	6-10 years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	101	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,989	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,989	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,163	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	2	EA	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	1,163	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	

Campus Name: Owen Page : 19 of 23 Assessment Date: 02/10/2022



Catego	ory : Interior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	2nd Floor	85	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,030	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,030	SF	7	10+ years	
Safetv							
,	Camera Viewing Station	Entire Building & Site	1	EΑ	7	6-10 years	
	Security Cameras	Entire Building & Site	5	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	South	227	SF	7	10+ years	
	Floor - Terrazzo	South	170	SF	7	10+ years	
	Handrails	South	64	LF	7	10+ years	
	Lighting - Pendent/Surface	South	3	EA	7	6-10 years	
	Stairs - Terrazzo	South	30	LF	7	10+ years	
	Walls - Plaster/Drywall	South	670	SF	6	10+ years	
	Walls - Structural Glazed Tile	South	670	SF	6	10+ years	



Category : Site **Building: Site** 

Outogo	iy. Oile			ununig	. Oile	December			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Athletic_									
	Surface - Natural	North	46,952	SF	6	10+ years			
_Civil/Dra	inage								
	Civil/ Drainage - Catch Basin	Entire Site	11	EA	7	10+ years	No sunken manhole was observed		
	Civil/ Drainage - Site Drain	Entire Site	1	EΑ	5	10+ years	THE CALINOT MAINTENE WAS EDUCATED		
	Civil/ Drainage - Site Manhole	Entire Site	3	EΑ	7	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	1	EΑ	4	0-1 year	Sunken manhole		
	Olvii, Brainage Olio Marinolo	Zitaro otto	'		•	o i youi	Carmon mannolo		
Fencing									
Ü	Fencing - Chain Link	Entire Site	128	LF	7	10+ years			
	Fencing - Chain Link	Entire Site	115	LF	7	10+ years			
	Fencing - Chain Link	Entire Site	30	LF	5	1-2 years	Missing top rail, bedposts		
	Fencing - New Standard Ornamental	Entire Site	397	LF	7	10+ years	3,,		
	Fencing - New Standard Ornamental	Entire Site	40	LF	6	10+ years			
	i i g					, , , , ,			
_Landsca	pe								
	Benches	Entire Site	3	EA	7	10+ years			
	Landscape - Grass	Entire Site	50	SF	7	10+ years			
	Landscape - Grass	Entire Site	50	SF	7	10+ years	Grass blanketed in snow, assuming		
	·						that the grass is in similar condition		
							as the last assessment		
	Landscape - Grass	Entire Site	34,998	SF	7	10+ years	Grass blanketed in snow, assuming		
	•		,			,	that the grass is in similar condition		
							as the last assessment		
	Landscape - Hardscape- Concrete	Entire Site	100	SF	5	1-2 years	Broken concrete at door number		
						,	seven		
	Parkway trees	Entire Site	68	EA	7	10+ years			
	Planting Beds/ Area	Entire Site	5,135	SF	7	10+ years			
	Play Area - Hardscape- Asphalt	Entire Site	26,052	SF	7	10+ years			
	Play Area - Hardscape- Asphalt	Entire Site	2,293	SF	6	6-10 years			
	Play Area - Hardscape- Asphalt	Entire Site	500	SF	4	1-2 years			
	Retaining Wall - Concrete	Entire Site	296	SF	7	10+ years			
	Retaining Wall - Concrete	Entire Site	24	SF	5	1-2 years	Cracked retaining wall seeping water		
	Trash Receptacles	Entire Site	2	EA	7	10+ years	Cracked rotalining wall occoping water		
	Trasii Neceptacies	Entire one	_	L/ \	,	101 years			
_Parking_	Lot								
·	Concrete Curbs	Parking Lot- East	387	LF	7	10+ years			
	Interior Plantings	Parking Lot- East	186	LF	7	10+ years			
	Surface - Asphalt	Parking Lot- East	23,820	SF	6	6-10 years			
	Trash Enclosure - Chain Links	Parking Lot- East	461	SF	7	10+ years			
	Vehicular Screening	Parking Lot- East	100	LF	7	10+ years			
	Č	•				,			

Campus Name: Owen Page : 21 of 23 Assessment Date: 02/10/2022



Catego	ry : Site		В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	nem - Type	Location	Quantity	OOM	Kank	Replacement	Comments
_Playgrou	nd						
	Equipment - School Age 5-12	North	1	EA	4	2-5 years	Damaged and old equipment
	Surface - Square Rubber Mats	North	2,390	SF	4	2-5 years	Large gaps, some tiles are out of place or damaged
Sidewalk	s						
	Sidewalks - Internal Walks	Entire Site	76	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	12,264	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	175	SF	4	0-1 year	Upheaved sidewalks, more than an inch and a half in some places
Signage							
0 0	Flag Pole - Building Mounted Flag Pole	West	1	EA	7	10+ years	
	Monument - Sign-Lighted	West	1	EA	7	6-10 years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Owen Page: 22 of 23 Assessment Date: 02/10/2022

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Science

Science

**Classroom Summary** 

Olassicom Guilliary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		•	•	•		•		•	
Kindergarten	Kindergarten	1st Floor	102	102	835	270	45	N	Υ
Library	Regular Classroom	2nd Floor	201	201	995	126	18	N	N
Other Instructional Use	Other Instructional Use	1st Floor	101	101	340	54	8	N	N
Regular Classroom	Regular Classroom	1st Floor	100	100	692	180	30	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	690	108	15	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	692	180	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	686	180	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	690	108	15	N	N
Building : Addition									
Band Room	Regular Classroom	2nd Floor	208	208	725	180	30	N	N
Office	Regular Classroom	1st Floor	104	104	686	108	15	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	686	180	30	N	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	686	180	30	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	725	180	30	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	692	180	30	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	690	108	15	N	Υ

205

205

845

126

18

Ν

N

2nd Floor

Campus Name: Owen Page : 23 of 23 Assessment Date: 02/10/2022