

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1958	1	18,593
Addition	1961	2	14,900
Campus Total			33,493

Category : Exterior Building : Main

	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	1						
	Exterior Doors - Exterior Steel Door	Entrance 1 - Northeast	1	EA	4	1-2 years	Corroded door and frame
	Exterior Doors - Transom Lite	Entrance 1 - Northeast	1	EA	6	10+ years	
	Exterior Stairs - Stone	Entrance 1 - Northeast	3	LF	5	6-10 years	
	Entrance Control - Audio and Video	Entrance 4 - Southwest	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 4 - Southwest	3	EA	6	10+ years	
	Exterior Doors - Side lite	Entrance 4 - Southwest	6	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 4 - Southwest	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 4 - Southwest	26	LF	6	10+ years	
	Power Door Operator and Controls	Entrance 4 - Southwest	2	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 4 - Southwest	60	LF	5	1-2 years	Corroded post bases
	Ramps - Concrete	Entrance 4 - Southwest	35	LF	5	1-2 years	Hairline cracks at Posts, Chunks of concrete falling off at posts
	Stair Handrail - Steel_Stair Handrail	Entrance 4 - Southwest	16	LF	6	10+ years	
	Entrance Control - Audio and Video	Entrance 5 - Northwest	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 5 - Northwest	2	EA	6	10+ years	
	Exterior Doors - Side lite	Entrance 5 - Northwest	6	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 5 - Northwest	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 5 - Northwest	10	LF	6	10+ years	
	Exterior Stairs - Stone	Entrance 5 - Northwest	9	LF	5	10+ years	Capped, repaired
	Exterior Doors - Exterior FRP Door	Entrance 6 - southwest	1	EA	6	6-10 years	Door is in fair shape
	Exterior Doors - Side lite	Entrance 6 - southwest	1	EA	7	10+ years	·
	Exterior Doors - Transom Lite	Entrance 6 - southwest	1	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Foundat	ion						
	Foundation - Concrete	Entire Building	665	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	18,593	SF	7	10+ years	
	•	G	,			,	
Lighting							
<u></u>	Exterior Lighting - Wall Mounted	Entire Building	15	EA	5	6-10 years	
	Extends Lighting Trail Mountou	Zimio Bananig	10	_, \	Ü	o lo youlo	
Roof Sys	stem						
-	Access Ladder - Metal	Roof 1	1	EA	5	2-5 years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	8	LF	6	10+ years	
	Liner						
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	20	LF	5	10+ years	Cracks
	Liner						
	Chimney - Metal Flue	Roof 1	18	LF	6	10+ years	
	Chimney - Metal Flue	Roof 1	17	LF	4	1-2 years	Corroded
	Coping - Metal	Roof 1	600	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	12	LF	5	1-2 years	Not fully connected at top
	Downspouts - Interior Downspouts	Roof 1	52	LF	6	10+ years	•
	Roof - PVC Membrane	Roof 1	16,769	SF	3	1-2 years	Soft spots and Active leaks, open
						•	seams, ponding throughout
	Roof Hatch - Metal	Roof 1	1	EA	5	1-2 years	Corroded hatch with broken hinges
	Roof Structure - Concrete	Roof 1	16,769	SF	7	10+ years	•
	Coping - Metal	Roof 2	165	LF	6	10+ years	
	Coping - Metal	Roof 2	10	LF	5	1-2 years	Corroding coping
	Downspouts - Exterior Downspouts	Roof 2	54	LF	6	10+ years	o and a supplied
	Roof - PVC Membrane	Roof 2	1,824	SF	4	1-2 years	Open seams, ponding, tears, soft
	. too.	. 100. =	.,0=.	•	-	,	spots throughout
	Roof Structure - Steel / Metal Deck/	Roof 2	1,824	SF	7	10+ years	opoto unougnout
	Concrete Topping	1,001.2	1,021	O.	•	io. youro	
	3						
Walls							
	Canopy - Concrete/ Stucco	Entire Building	60	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	325	SF	5	1-2 years	Ceiling has been repaired, connection
							of downspout to roof is poor. Ceiling
							paint is flaking in some places. PVC
							Roof surface is poor
	Exterior Walls - Brick	Entire Building	5,150	SF	6	10+ years	·
	Exterior Walls - Brick	Entire Building	500	SF	5	10+ years	Deteriorated mortar
	Exterior Walls - Stone-Cast	Entire Building	430	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	22	SF	5	10+ years	Minor cracks at some windowsills. No
		3		-	-	· , · · · ·	efflorescence noted
	Exterior Walls - Stone-Cut	Entire Building	300	SF	5	10+ years	
		•				·	



Catego	y : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Windows							
	Guard - Guards perforated	Entire Building	2,510	SF	6	10+ years	
	Lintels - Steel	Entire Building	465	LF	6	10+ years	
	Windows - Louver	Entire Building	22	SF	6	10+ years	
	Windows - Louver	Entire Building	20	SF	5	1-2 years	Corroded
	Windows - Sash Aluminum Double-pane	Entire Building	2,660	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergen	cy System						
-	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	7	6-10 years	With battery power
	Exit Signs - Multipurpose Room	Entire Building	2	EA	7	6-10 years	With battery power
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,100	SF	6	6-10 years	, ,
	Security System - CCTV	Entire Building	18,593	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	18,593	SF	7	6-10 years	
Main Ser	vice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	1	SF	7	6-10 years	
Power Di	stribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	4	0-1 year	Live Front exposed - fuse panel Quantity change per current observation
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	ΕA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	6-10 years	
Catego	y : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments



Catego	ry : Fire Protection			Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Panel	Electrical Room	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Electrical Room	18,593		7	6-10 years	
	Fire Alarm_System	Electrical Room	18,593	SF	6	6-10 years	
Catego	ry : Mechanical		ı	Building	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	Iling Systems	Location	Quantity	OOM	Italik	Replacement	Comments
All Hall	Fan Coil Unit- Celing Mounted - Steam	Entire Building	2	EA	5	6-10 years	Control needs adjustment
	Roof Top Unit-Single Zone-Roof Mounted-	Lower Roof	1	EA	6	6-10 years	Served multipurpose
	DX Cooling Only with Self Contained Compressor - 11 - 20 tons	Lower Roof	·	L/	J	o ro years	Cerved Maniparpose
	Roof Top Unit-Single Zone-Roof Mounted-	Lower Roof	1	EA	7	6-10 years	Served clinical
	DX Cooling Only with Self Contained					,	
	Compressor - 5 - 10 tons						
Boiler Sy	ystems						
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	6-10 years	B-1 valve leaking
	Pressure Boiler - 50 - 75 HP				_		
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	2-5 years	
	Condensate Pump	Boiler Room	2		6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	2-5 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EA	5	6-10 years	Control needs replacement
	Steam- Low Pressure Boiler - 50 - 75 HP				_		
	Piping - Condensate Pipe- Steel	Boiler Room	300		6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	300		6	6-10 years	
	Steam Traps	Boiler Room	45		5	6-10 years	Minor repair needed
	Vacuum Pump	Boiler Room	1	EA	6	6-10 years	
Gas Boo	oster						
	Gas Booster	Boiler Room	1	EA	5	2-5 years	Corroded
Heating	Devices						
	Radiators - Steam	Entire Building	2	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	4		6	6-10 years	
	Fin Tube - Steam	Entire Building	48		5	2-5 years	Control needs replacement
	Cabinet Heaters - With Steam Coil	Entire Building	13	EA	6	10+ years	·
Tempera	ature Control						
•	Electric Thermostat	Entire Building	6	EA	6	2-5 years	
	Electric Thermostat	Entire Building	5		6	2-5 years	
	Pneumatic System	Entire Building	18,593		3	0-1 year	Served addition also New item added
0	Name: Simpson HS		Page : 4 of 25				Assessment Date: 05/26/202
amplie							



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Thermostats - Pneumatic	Entire Building	6	EA	5	2-5 years	per current observation System needs replacement not working per building engineer Pneumatic system is not working per building engineer
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Steam Heating w/ DX Cooling Coil & w/ Self Contained Compressors	1st Floor	8	EA	7	10+ years	
Ventilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Roof	1	EA	6	6-10 years	Switch gear room inside New item added per current observation
	Exhaust Fans- Indoor - Less than 500 CFM	Roof	1	EA	6	6-10 years	,
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	Quantity change per current observation
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	4	1-2 years	Noisy and vibrating
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	10+ years	Replace new in 2021
	Roof Mounted Duct Work	Roof	18	LF	6	6-10 years	New item added per current observation

Category : Plumbing **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wat	,	Location	Quantity	OOM	Marik	Replacement	Comments
_HOL Wall	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	1st Floor	18,593	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	1st Floor	18,593	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	1st Floor	18,593	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	1st Floor	18,593	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	1st Floor	18,593	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	1st Floor	18,593	SF	6	6-10 years	
	Sanitary Piping	1st Floor	18,593	SF	6	6-10 years	
	Storm Piping	1st Floor	18,593	SF	6	6-10 years	



Category: Plumbing Building: Main

Recommend Location Quantity UOM Rank Item - Type Replacement Comments Group Vent Piping 1st Floor 18,593 2-5 years SF 6

<u>Pumps</u>

Pumps - Sump-Simplex Boiler Room EΑ 5 2-5 years 1

Building: Main Category: Room

Catego	ry : Room		Building: Main							
_			0	11014		Recommend	•			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Administ	trative Suites/Offices									
	AC Unit	111 - Main Office	1	EA	5	1-2 years	Doesn't work properly			
	Ceiling - Lay-in	111 - Main Office	348	SF	7	10+ years				
	Ceiling - Lay-in	111 - Main Office	2	SF	7	10+ years				
	Doors - Side-lite	111 - Main Office	24	SF	7	10+ years				
	Doors - Store Front	111 - Main Office	1	EA	7	10+ years				
	Doors - Wood Doors inclu hw	111 - Main Office	1	EA	7	10+ years				
	Floor - Carpet	111 - Main Office	222	SF	7	6-10 years				
	Floor - Carpet	111 - Main Office	2	SF	4	0-1 year	Trip hazard/live outlet			
	Floor - Tile	111 - Main Office	127	SF	7	10+ years				
	Lighting - Lay-in	111 - Main Office	6	EA	7	10+ years				
	Power Distribution	111 - Main Office	6	EA	7	10+ years				
	Walls - Concrete Block	111 - Main Office	808	SF	7	10+ years				
	Ceiling - Lay-in	Health Clinic - Breakroom	83	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Health Clinic - Breakroom	1	EA	7	10+ years				
	Floor - Tile	Health Clinic - Breakroom	83	SF	7	10+ years				
	Lighting - Lay-in	Health Clinic - Breakroom	1	EA	7	10+ years				
	Power Distribution	Health Clinic - Breakroom	6	EA	7	10+ years				
	Walls - Plaster/Drywall	Health Clinic - Breakroom	260	SF	7	10+ years				
	Work SInk	Health Clinic - Breakroom	1	EA	7	10+ years				
	Ceiling - Lay-in	Health Clinic - Mental Health	98	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Health Clinic - Mental Health	1	EA	7	10+ years				
	Floor - Tile	Health Clinic - Mental Health	98	SF	7	10+ years				
	Lighting - Lay-in	Health Clinic - Mental Health	2	EA	7	10+ years				
	Power Distribution	Health Clinic - Mental Health	8	EA	7	10+ years				
	Walls - Plaster/Drywall	Health Clinic - Mental Health	365	SF	7	10+ years				
	Ceiling - Lay-in	Health Clinic Exam rm 2	104	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Health Clinic Exam rm 2	1	EA	7	10+ years				
	Floor - Tile	Health Clinic Exam rm 2	104	SF	7	10+ years				
	Lighting - Lay-in	Health Clinic Exam rm 2	2	EA	7	6-10 years				
	Power Distribution	Health Clinic Exam rm 2	3	EA	7	6-10 years				
	Walls - Plaster/Drywall	Health Clinic Exam rm 2	290	SF	7	10+ years				
	Work SInk	Health Clinic Exam rm 2	1	EA	7	10+ years				
	Ceiling - Lay-in	Health Clinic Exam rm 3	104	SF	7	6-10 years				
	Doors - Wood Doors inclu hw	Health Clinic Exam rm 3	1	EA	7	10+ years				
	Floor - Tile	Health Clinic Exam rm 3	104	SF	7	10+ years				



Catego	ry : Room		В	uilding	: Main	·	321 01 adima officer, officago, ie oodoo
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Health Clinic Exam rm 3	2	EA	7	6-10 years	
	Power Distribution	Health Clinic Exam rm 3	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	Health Clinic Exam rm 3	290	SF	7	10+ years	
	Work SInk	Health Clinic Exam rm 3	1	EA	7	10+ years	
	Ceiling - Lay-in	Health Clinic exam rm 1	104	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Health Clinic exam rm 1	1	EA	7	10+ years	
	Floor - Tile	Health Clinic exam rm 1	100	SF	7	10+ years	
	Floor - Tile	Health Clinic exam rm 1	4	SF	4	0-1 year	Chipped
	Lighting - Lay-in	Health Clinic exam rm 1	2	EA	7	10+ years	
	Power Distribution	Health Clinic exam rm 1	8	EΑ	7	10+ years	
	Walls - Concrete Block	Health Clinic exam rm 1	122	SF	7	10+ years	
	Walls - Plaster/Drywall	Health Clinic exam rm 1	122	SF	7	10+ years	
	Work SInk	Health Clinic exam rm 1	1	EΑ	7	10+ years	
	AC Unit	Main Office - Principal	1	EA	7	6-10 years	
	Ceiling - Lay-in	Main Office - Principal	195	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office - Principal	1	EA	7	10+ years	
	Floor - Carpet	Main Office - Principal	195	SF	7	6-10 years	
	Lighting - Lay-in	Main Office - Principal	2	EA	7	10+ years	
	Power Distribution	Main Office - Principal	6	EA	7	10+ years	
	Walls - Concrete Block	Main Office - Principal	550	SF	7	10+ years	
	Walls - Structural Glazed Tile	Main Office - Principal	100	SF	7	10+ years	
Oliveire							
Clinic	0.11	11.01. 105	77.			40	
	Ceiling - Lay-in	next to Classroom 105	775	SF	7	10+ years	
	Ceiling - Plaster/Drywall	next to Classroom 105	110	SF	7	10+ years	
	Doors - Steel Doors incl hw	next to Classroom 105	1	EΑ	7	10+ years	
	Doors - Wood Doors inclu hw	next to Classroom 105	5	EA	7	10+ years	
	Floor - Tile/Sheet	next to Classroom 105	865	SF	7	10+ years	One all the males of the
	Floor - Tile/Sheet	next to Classroom 105	20	SF	4	1-2 years	Crack/broken tile
	Lighting - Lay-in	next to Classroom 105	19	EΑ	7	10+ years	
	Lighting - Pendent/Surface	next to Classroom 105	2	EA	7	10+ years	
	Walls - Plaster/Drywall	next to Classroom 105	2,881	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Exposed	113	1,683	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113	4	EA	7	10+ years	
	Floor - Tile	113	1,683	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	113	8	EA	7	10+ years	
	Lighting - Pendent/Surface	113	3	EA	7	10+ years	
	Serving Line	113	26	LF	7	10+ years	
	Storage/ Closet	113	63	SF	7	10+ years	
	Walls - Concrete Block	113	2,508	SF	7	10+ years	
	Walls - Structural Glazed Tile	113	200	SF	7	10+ years	
	2		200		•	,	



Catego	ry : Room		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
/IDF_ID							
	Doors - Steel Doors incl hw	Room 114	2	EA	7	10+ years	
	Finishes	Room 114	135	SF	7	10+ years	
	Finishes	Room 114	10	SF	4	0-1 year	Missing ceiling tile
	Window AC Unit	Room 114	1	EA	7	6-10 years	
/lechani	cal/ Service Rooms						
VICCHAIII	Mechanical/ Service Rooms	1st Floor	216	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	55	SF	4	0-1 years	Water damaged
	Mechanical Service Rooms	151 F1001	55	SF	4	0-1 year	water damaged
rep Ro							
	Ceiling - Plaster/Drywall	Lunchroom	206	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Lunchroom	2	EA	7	10+ years	
	Floor - Tile	Lunchroom	206	SF	7	10+ years	
	Lighting - Pendent/Surface	Lunchroom	2	EA	7	10+ years	
	Walls - Concrete Block	Lunchroom	468	SF	7	10+ years	
	Walls - Structural Glazed Tile	Lunchroom	45	SF	7	10+ years	
	Work Sink	Lunchroom	3	EA	7	10+ years	
Restroor	n						
	Accessories	115	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	115	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	115	1	EA	7	10+ years	
	Floor - Tile	115	30	SF	7	10+ years	
	Lavatory	115	1	EA	7	10+ years	
	Lighting - Pendent/Surface	115	1	EA	7	10+ years	
	Walls - Concrete Block	115	80	SF	7	10+ years	
	Walls - Concrete Block Walls - Structural Glazed Tile	115	15	SF	7	,	
			15			10+ years	
	Water Closet	115	=	EA	7 7	10+ years	
	Accessories	1st Floor - next to Classroom 106	225	SF SF		6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - next to Classroom 106	225		7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - next to Classroom 106	225	SF	7	10+ years	
	Floor Drain	1st Floor - next to Classroom 106	1	EΑ	7	10+ years	N
	Hand Dryer	1st Floor - next to Classroom 106	2	EΑ	5	1-2 years	Not working
	Lavatory	1st Floor - next to Classroom 106	3	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - next to Classroom 106	3	EA	7	10+ years	
	Partitions	1st Floor - next to Classroom 106	5	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - next to Classroom 106	175	SF	7	10+ years	
	Walls - Tile	1st Floor - next to Classroom 106	432	SF	7	10+ years	
	Water Closet	1st Floor - next to Classroom 106	5	EA	7	10+ years	
	Accessories	Boiler Room	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boiler Room	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Boiler Room	16	SF	6	10+ years	
	Floor - Tile	Boiler Room	10	SF	4	0-1 year	Damaged 9x9 tile
	Lavatory	Boiler Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	7	10+ years	
	Lighting - Wall Mounted	Boiler Room	1	EΑ	7	10+ years	
	Walls - Concrete Block	Boiler Room	184	SF	7	10+ years	
	Water Closet	Boiler Room	1	EΑ	6	10+ years	
	Accessories	Health Clinic	52	SF	7	6-10 years	
	Ceiling - Lay-in	Health Clinic	44	SF	7	10+ years	
	Ceiling - Lay-in	Health Clinic	8	SF	4	0-1 year	Damaged tile
	Doors - Wood Doors inclu hw	Health Clinic	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Health Clinic	52	SF	7	10+ years	
	Floor Drain	Health Clinic	1	EA	7	10+ years	
	Lavatory	Health Clinic	1	EA	7	10+ years	
	Lighting - Lay-in	Health Clinic	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Health Clinic	142	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Health Clinic	142	SF	7	10+ years	
	Water Closet	Health Clinic	1	EA	7	10+ years	
	Accessories	Main Office Suite	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office Suite	60	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Main Office Suite	10	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	Main Office Suite	1	EA	7	10+ years	
	Floor - Tile	Main Office Suite	70	SF	7	10+ years	
	Lavatory	Main Office Suite	1	EA	7	10+ years	
	Lighting - Lay-in	Main Office Suite	2	EA	7	10+ years	
	Lighting - Wall Mounted	Main Office Suite	1	EA	7	10+ years	
	Partitions	Main Office Suite	1	EA	7	10+ years	
	Walls - Concrete Block	Main Office Suite	280	SF	7	10+ years	
	Walls - Structural Glazed Tile	Main Office Suite	20	SF	7	10+ years	
	Water Closet	Main Office Suite	1	EΑ	7	10+ years	
	Accessories	next to Girl's Restroom	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	next to Girl's Restroom	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	next to Girl's Restroom	1	EΑ	7	10+ years	
	Floor - Tile	next to Girl's Restroom	42	SF	7	10+ years	
	Floor Drain	next to Girl's Restroom	1	EΑ	7	10+ years	
	Hand Dryer	next to Girl's Restroom	1	EA	7	6-10 years	Repaired
	Lavatory	next to Girl's Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	next to Girl's Restroom	1	EA	7	10+ years	
	Walls - Concrete Block	next to Girl's Restroom	115	SF	7	10+ years	
	Walls - Plaster/Drywall	next to Girl's Restroom	47	SF	7	10+ years	
	Walls - Tile	next to Girl's Restroom	29	SF	7	10+ years	
	Water Closet	next to Girl's Restroom	1	ĒΑ	7	10+ years	
						,	



Catego	ry : Classroom		В	uilding	: Main		321 01 adima OTNEET, Officago, 12 00000
_				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	742	SF	7	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	740	SF	7	10+ years	
	Floor - Tile	1st Floor	2	SF	7	6-10 years	Repaired
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	934	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	226	SF	7	10+ years	
Classroo	om #102 (Other Instructional Use)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	825	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	825	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Student Lockers - Three Tiers	1st Floor	3	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	929	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	226	SF	7	10+ years	
_Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	840	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	840	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	934	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	226	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	610	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	160	SF	3	0-1 year	Water damage



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	770	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	929	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	226	SF	7	10+ years	
Classroo	om #105 (Science)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	850	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Eye Wash Station	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	850	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	•	
	Marker Board	1st Floor	20	LF		10+ years	
	Science Lab Shower	1st Floor	20	EA	7	6-10 years	
			· · · · · · · · · · · · · · · · · · ·		7	10+ years	
	Walls - Concrete Block	1st Floor	934	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	226	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #106 (Faculty Lounge)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	769	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	56	SF	4	0-1 year	Water damage
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	825	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	929	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	226	SF	7	10+ years	
Classroo	om #114 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	970	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	968	SF	, 5		Warped floor
	Floor - Tile Floor - Tile	1st Floor	900	SF SF	5 4	10+ years	Chipped floor
						0-1 year	Спірреа поог
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	



Catego	ry : Classroom		В	uilding			
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Storage/ Closet	1st Floor	44	SF	7	10+ years	
	Storage/ Closet	1st Floor	4	SF	4	0-1 year	Damaged tile
	Walls - Concrete Block	1st Floor	881	SF	7	10+ years	ŭ
	Walls - Plaster/Drywall	1st Floor	294	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	100	SF	7	10+ years	
						,	
Classro	om #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Splined	1st Floor	689	SF	7	10+ years	
	Ceiling - Splined	1st Floor	4	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	657	SF	7	10+ years	
	Floor - Tile	1st Floor	40	SF	4	1-2 years	Damaged tile/flexing within floor
		1st Floor	5	EA	7		Damaged the/hexing within 11001
	Lighting - Pendent/Surface				7	10+ years	
	Marker Board	1st Floor	16	LF		6-10 years	
	Storage/ Closet	1st Floor	51	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	800	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	239	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	80	SF	7	10+ years	
Catego			80	SF uilding	-	10+ years	
_	Walls - Structural Glazed Tile ry : Interior	1st Floor	80 B	uilding	: Main	Recommend	
Group	Walls - Structural Glazed Tile ry : Interior Item - Type		80		-	•	Comments
Group	Walls - Structural Glazed Tile ry : Interior Item - Type	1st Floor Location	80 B Quantity	uilding UOM	: Main Rank	Recommend Replacement	Comments
Group	Walls - Structural Glazed Tile ry : Interior Item - Type Ceiling - Lay-in	1st Floor Location 1st Floor	80 B Quantity 1,258	UOM SF	: Main Rank	Recommend Replacement 10+ years	
Group	Walls - Structural Glazed Tile ry : Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in	1st Floor Location 1st Floor 1st Floor	80 B Quantity	UOM SF SF	Rank	Recommend Replacement 10+ years 0-1 year	Comments Stain tile
Catego Group Corridor	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor Location 1st Floor 1st Floor 1st Floor 1st Floor	80 Quantity 1,258 10 745	UOM SF SF SF SF	7 3 7	Recommend Replacement 10+ years	
Group	Walls - Structural Glazed Tile ry : Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in	1st Floor Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	90 Quantity 1,258 10	UOM SF SF	Rank	Recommend Replacement 10+ years 0-1 year	
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor Location 1st Floor 1st Floor 1st Floor 1st Floor	80 Quantity 1,258 10 745	UOM SF SF SF SF	7 3 7	Recommend Replacement 10+ years 0-1 year 10+ years	
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite	1st Floor Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	80 Quantity 1,258 10 745 48	UOM SF SF SF SF SF	7 3 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years	
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window	1st Floor Location 1st Floor	80 Quantity 1,258 10 745 48 8 60	UOM SF SF SF SF EA SF	7 3 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years	
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw	1st Floor Location 1st Floor	80 Quantity 1,258 10 745 48 8 60 2	UOM SF SF SF SF EA SF EA	7 3 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler	1st Floor Location 1st Floor	80 R Quantity 1,258 10 745 48 8 60 2 2	UOM SF SF SF SF EA SF EA EA	7 3 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years	
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain	1st Floor Location 1st Floor	80 R Quantity 1,258 10 745 48 8 60 2 2 2 204	UOM SF SF SF SF EA SF EA SF EA SF	7 3 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years	
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet	1st Floor Location 1st Floor	80 R Quantity 1,258 10 745 48 8 60 2 2 2 204 2,498	UOM SF SF SF SF EA	7 3 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years	Stain tile
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet	1st Floor Location 1st Floor	80 R Quantity 1,258 10 745 48 8 60 2 2 2 204 2,498 15	UOM SF SF SF EA SF EA SF EA SF SF SF SF SF SF SF	7 3 7 7 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years	
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in	1st Floor Location 1st Floor	80 R Quantity 1,258 10 745 48 8 60 2 2 204 2,498 15 28	UOM SF SF SF EA SF EA SF EA SF EA	7 3 7 7 7 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years	Stain tile
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface	1st Floor Location 1st Floor	80 R Quantity 1,258 10 745 48 8 60 2 2 2 204 2,498 15 28 3	UOM SF SF SF EA SF EA SF EA EA EA SF EA	7 3 7 7 7 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years	Stain tile
Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Concrete Block	1st Floor Location 1st Floor	80 R Quantity 1,258 10 745 48 8 60 2 2 2 204 2,498 15 28 3 6,122	UOM SF SF SF EA SF EA SF EA SF	7 3 7 7 7 7 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years	Stain tile
- Group	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface	1st Floor Location 1st Floor	80 R Quantity 1,258 10 745 48 8 60 2 2 2 204 2,498 15 28 3	UOM SF SF SF EA SF EA SF EA EA EA SF EA	7 3 7 7 7 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years	Stain tile
- Froup	Walls - Structural Glazed Tile ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Concrete Block	1st Floor Location 1st Floor	80 R Quantity 1,258 10 745 48 8 60 2 2 2 204 2,498 15 28 3 6,122	UOM SF SF SF EA SF EA SF EA SF	7 3 7 7 7 7 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years	Stain tile



Building: Main Category: Interior

Recommend Location UOM Group Item - Type Quantity Rank Replacement Comments Security Cameras 1st Floor 3 EΑ 6-10 years

Campus Name: Simpson HS Page : 13 of 25 Assessment Date: 05/26/2022





Building: Addition Category: Exterior

	egory : Exterior		Building : Addition					
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ntrance								
	Entrance Control - Audio and Video	Entrance 2 - Northwest	1	EA	6	10+ years		
	Exterior Doors - Exterior FRP Door	Entrance 2 - Northwest	2	EΑ	6	10+ years		
	Exterior Doors - Exterior FRP Door	Entrance 3 - Southeast	2	EΑ	6	10+ years		
	Exterior Stairs - Concrete	Entrance 3 - Southeast	15	LF	6	10+ years		
	Exterior Stairs - Stone	Entrance 3 - Southeast	6	LF	5	10+ years		
	Exterior stairs - storie	Emilance 3 - Southeast	O	LI	3	10+ years		
oundation	on							
	Foundation - Concrete	Entire Building	360	LF	7	10+ years		
	Superstructure - Concrete	Entire Building	14,122	SF	7	10+ years		
iabtina								
ighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	6	10+ years		
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EΑ	4	1-2 years	Damaged late, not in use	
	Exterior Lighting - Wall Mounted	Entire Building	3	EΑ	7	10+ years	Damaged late, flet in dee	
	Exterior Lighting - Wall Mounted	Entire Building	1	EΑ	5	2-5 years		
	Extendi Lighting Wall Modified	Entire Ballating	•	_, 、	Ü	2 o youro		
Roof Sys	tem							
	Access Ladder - Metal	Roof 3	1	EA	5	2-5 years		
	Access Ladder - Metal	Roof 3	1	EA	5	1-2 years	Corroding, obsolete exterior metal	
	Coping - Metal	Roof 3	360	LF	6	10+ years	144401	
	Downspouts - Interior Downspouts	Roof 3	48	LF	6	10+ years		
	Roof - PVC Membrane	Roof 3	7,450	SF	2	0-1 year	Extreme ponding with active leaks	
	1001 - 1 VO Wellibralle	10013	7,400	OI.	2	0-1 year	open seams, soft spots throughou	
	Roof Hatch - Metal	Roof 3	1	EA	3	1-2 years	Corroded, unused hatch	
	Roof Structure - Concrete	Roof 3	7,450	SF	7	10+ years		
Valls								
valis	Canopy - Concrete/ Stucco	Entire Building	60	SF	6	10+ years		
	Canopy - Concrete/ Stucco	Entire Building	60	SF	6	10+ years		
	Exterior Walls - Brick	Entire Building	3,008	SF	6	10+ years		
	Exterior Walls - Brick	Entire Building	1	SF	4	1-2 years	Missing bricks at pilaster, door 4	
	Exterior Walls - Brick	Entire Building	204	SF	4	1-2 years	Open joints	
	Exterior Walls - Stone-Cast	Entire Building	212	SF	5	10+ years	Open joints	
	Exterior Walls - Stone-Cut	Entire Building	385	SF	6	10+ years		
	Exterior Walls - Storie-Gut	Entire Building	303	OI.	U	10+ years		
Vindows								
	Guard - Guards perforated	Entire Building	1,008	SF	6	10+ years		
	Lintels - Steel	Entire Building	15	LF	6	10+ years		
				SF				



Catego	ry : Exterior		В	uilding	on		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Windows - Louver	Entire Building	50	SF	6	10+ years	
	Windows - Louver	Entire Building	4	SF	4	1-2 years	Corroded Louvers
	Windows - Sash Aluminum Double-pane	Entire Building	2,136	SF	6	10+ years	
Catego	ry : Electrical		В	uildina	: Additi	on	
	, - =					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
- 0	Security System - CCTV	Entire Building	7,450	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	7,450	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	2	ĒΑ	6	6-10 years	
	3	.				, , , , , ,	
/lain Se							
	PA System	Entire Building	7,450	SF	7	6-10 years	Served from main
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	2-5 years	Fuse panel
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	. 200 раше
		J					
Catego	ry : Fire Protection		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ire Alar			•			•	
	Fire Alarm Strobe Lights	Entire Building	14,900	SF	7	6-10 years	New item added per current
	F: Al 0 /	F B	44.000	0.5	_	0.40	observation
	Fire Alarm_System	Entire Building	14,900	SF	7	6-10 years	
Catego	ry : Mechanical		В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Devices	Loudion	Quantity		Main	Ropidocilicit	Commone
realing	Cabinet Heaters - With Steam Coil	1st Floor	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	
	vvali i leater - Liectiic	Little building	2	LA	U	0-10 years	
empera	ature Control						
	Electric Thermostat	Entire Building	5	EA	6	2-5 years	
Init Ven	tilation						
Jnit Ven	tilation Unit Ventilators- Floor Mounted- Steam	Entire Building	7	EA	5	2-5 years	Control needs replacement



Category : Mechanical		В	uilding			
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Ventilation						
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	7	10+ years	Quantity change per current observation Replace new in 2021
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	10+ years	Quantity change per current observation Replace new in 2021

Category: Plumbing Building: Addition

			_	۳۳9	. ,	•	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
iping	item - Type	Location	Qualitity	OOW	Italik	Replacement	Comments
iping	Domestic Piping-Hot Water Return Lines	Entire Building	7,450	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	7,450	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	7,450	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	7,450	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	7,450	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	7,450	SF	6	6-10 years	
	Sanitary Piping	Entire Building	7,450	SF	6	6-10 years	
	Storm Piping	Entire Building	7,450	SF	6	6-10 years	
	Vent Piping	Entire Building	7,450	SF	6	6-10 years	
umps							
·	Pumps - Ejector-Simplex	Basement	1	EA	5	2-5 years	

Category: Room **Building: Addition**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	rative Suites/Offices	2004	Quantity		Marik	. topiasomont	
	AC Unit	119	1	EA	7	6-10 years	
	Ceiling - Exposed	119	732	SF	7	10+ years	
	Ceiling - Lay-in	119	8	SF	4	1-2 years	Stain tile
	Doors - Wood Doors inclu hw	119	1	EA	7	10+ years	
	Floor - Tile	119	740	SF	6	6-10 years	
	Lighting - Lay-in	119	16	EA	7	6-10 years	
	Power Distribution	119	9	EA	7	10+ years	
	Walls - Concrete Block	119	741	SF	7	10+ years	
	Walls - Structural Glazed Tile	119	75	SF	7	10+ years	
	Work SInk	119	1	EA	7	10+ years	
	Ceiling - Exposed	210 Staff lounge	150	SF	7	10+ years	



Catego	egory : Room			uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	210 Staff lounge	20	SF	5	1-2 years	Water stain
	Doors - Wood Doors inclu hw	210 Staff lounge	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	210 Staff lounge	170	SF	7	6-10 years	
	Lighting - Pendent/Surface	210 Staff lounge	2	EA	7	6-10 years	
	Walls - Concrete Block	210 Staff lounge	540	SF	7	10+ years	
	Walls - Structural Glazed Tile	210 Staff lounge	40	SF	7	10+ years	
	AC Unit	RM 116	1	EΑ	7	6-10 years	
	Ceiling - Exposed	RM 116	390	SF	7	10+ years	
	Doors - Wood Doors inclu hw	RM 116	1	EA	7	10+ years	
	Floor - Tile	RM 116	380	SF	7	6-10 years	
	Floor - Tile	RM 116	10	SF	7	6-10 years	Repaired
	Lighting - Pendent/Surface	RM 116	6	EA	7	6-10 years	
	Power Distribution	RM 116	13	EΑ	6	10+ years	
	Walls - Concrete Block	RM 116	450	SF	7	10+ years	
	Walls - Plaster/Drywall	RM 116	218	SF	7	10+ years	
	Walls - Structural Glazed Tile	RM 116	50	SF	7	10+ years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st and 2nd floor	37	SF	7	10+ years	
	Janitor's Closet	1st and 2nd floor	37	SF	7	10+ years	
	Storage Room	1st and 2nd floor	170	SF	7	10+ years	
Restroon	•						
Resilooi	Accessories	Across from rm 119	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Across from rm 119	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Across from rm 119	45 1	EA	7	•	
		Across from rm 119		SF		10+ years 6-10 years	
	Floor - Tile Ceramic/ Porcelain		45		6 7		
	Lavatory	Across from rm 119	1	EΑ	-	10+ years	Light decembers of managers
	Lighting - Chandelier, Incandescent	Across from rm 119	•	EΑ	6	1-2 years	Light doesn't work properly
	Lighting - Pendent/Surface Partitions	Across from rm 119	1	EA EA	7 7	6-10 years	
		Across from rm 119	165	SF	-	10+ years	
	Walls - Concrete Block	Across from rm 119			7	10+ years	
	Walls - Structural Glazed Tile	Across from rm 119	20	SF	7	10+ years	
	Water Closet	Across from rm 119	1	EA	7	10+ years	
	Accessories	Girls restroom across from 119	170	SF SF	7	6-10 years	
	Ceiling - Exposed	Girls restroom across from 119	170		7	10+ years	
	Doors - Wood Doors inclu hw	Girls restroom across from 119	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls restroom across from 119	170	SF	7	6-10 years	
	Hand Dryer	Girls restroom across from 119	1	EΑ	7	10+ years	
	Lavatory	Girls restroom across from 119	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Girls restroom across from 119	3	EA	7	6-10 years	
	Partitions	Girls restroom across from 119	4	EA	7	10+ years	
	Walls - Concrete Block	Girls restroom across from 119	580	SF EA	7 7	10+ years	
	Water Closet	Girls restroom across from 119	4			10+ years	



Catego	ry : Room	Building : Addition						
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Accessories	Next to 212	170	SF	7	6-10 years		
	Ceiling - Exposed	Next to 212	170	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Next to 212	2	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Next to 212	170	SF	7	6-10 years		
	Lavatory	Next to 212	2	EA	7	10+ years		
	Lighting - Pendent/Surface	Next to 212	2	EA	7	6-10 years		
	Partitions	Next to 212	4	EA	7	10+ years		
	Walls - Concrete Block	Next to 212	540	SF	7	10+ years		
	Walls - Structural Glazed Tile	Next to 212	40	SF	7	10+ years		
	Water Closet	Next to 212	4	EA	7	10+ years		
	Accessories	Restroom staff next to 210	50	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Restroom staff next to 210	50	SF	5	10+ years	Water stain	
	Doors - Wood Doors inclu hw	Restroom staff next to 210	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Restroom staff next to 210	50	SF	7	6-10 years		
	Lavatory	Restroom staff next to 210	1	EA	7	10+ years		
	Lighting - Lay-in	Restroom staff next to 210	1	EA	7	6-10 years		
	Partitions	Restroom staff next to 210	1	EA	7	10+ years		
	Walls - Concrete Block	Restroom staff next to 210	120	SF	7	10+ years		
	Water Closet	Restroom staff next to 210	1	EA	7	10+ years		

Building: Addition Category : Classroom

Group Item - Type Location Quantity UOM Rank Replacement Commercial Classroom #113 (Store Room) AC Units 1st Floor 1 EA 4 1-2 years Missing Casework 1st Floor 22 LF 7 10+ years Ceiling - Plaster/Drywall 1st Floor 769 SF 7 10+ years Chalk Board 1st Floor 40 LF 4 2-5 years Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years	
AC Units 1st Floor 1 EA 4 1-2 years Missing of the strength of the	nts
Casework1st Floor22LF710+ yearsCeiling - Plaster/Drywall1st Floor769SF710+ yearsChalk Board1st Floor40LF42-5 years	
Ceiling - Plaster/Drywall1st Floor769SF710+ yearsChalk Board1st Floor40LF42-5 years	cover
Chalk Board 1st Floor 40 LF 4 2-5 years	
,	
Doors Wood Doors include was 1st Floor 1 FA 7 10 Lycars	
Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years	
Floor - Tile 1st Floor 769 SF 6 6-10 years	
Lighting - Pendent/Surface 1st Floor 6 EA 7 6-10 years	
Marker Board 1st Floor 4 LF 7 6-10 years	
Walls - Concrete Block 1st Floor 788 SF 7 10+ years	
Walls - Structural Glazed Tile 1st Floor 80 SF 7 10+ years	
Work Sink 1st Floor 1 EA 7 10+ years	
Classroom #118 (Art Room)	
AC Units 1st Floor 1 EA 7 6-10 years	
Casework 1st Floor 28 LF 7 10+ years	
Ceiling - Plaster/Drywall 1st Floor 1,103 SF 7 10+ years	
Ceiling - Plaster/Drywall 1st Floor 20 SF 4 0-1 year Water da	ımage
Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years	
Floor - Tile 1st Floor 1,123 SF 7 6-10 years	
Instructional Surface 1st Floor 28 LF 7 10+ years	

Campus Name: Simpson HS Page : 18 of 25 Assessment Date: 05/26/2022



Catego	ry : Classroom		Building : Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	431	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	536	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	30	SF	7	10+ years	
	Work Sink	1st Floor	2	ĒΑ	7	10+ years	
Classroc	om #120 (Adult Education)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	390	SF	7	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	13	EA	7	10+ years	
	Floor - Tile	1st Floor	390	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor		SF	7	•	
			433	SF SF		10+ years	
	Walls - Plaster/Drywall	1st Floor	238	51	7	10+ years	
Classroc	om #121 (Office)						
	AC Units	1st Floor	1	EA	7	1-2 years	Doesn't blow cool air
	Casework	1st Floor	22	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	769	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	769	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	788	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	80	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
Classroc	om #212 (Store Room)						
	Ceiling - Plaster/Drywall	2nd Floor	375	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	375	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years	
				SF		•	
	Walls - Concrete Block	2nd Floor	570		7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	7	10+ years	
Classroc	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	790	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	790	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	830	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	738	SF	7	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	738	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	729	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
_Classroo	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	751	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	751	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	741	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #216 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	774	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	774	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	19	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	727	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	7	10+ years	
		2nd Floor		EA	•	, , , , , , , , ,	



Simpson Academy HS for Young Women

XII.	Schools					1	321 S Paulina STREET, Chicago, IL 606		
Catego	ry : Classroom		В	Building : Addition					
						Recommend			
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	om #217 (Computer Lab)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	22	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	762	SF	7	10+ years			
	Chalk Board	2nd Floor	20	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	762	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years			
	Marker Board	2nd Floor	8	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	730	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	80	SF	7	10+ years			
	Wireless System	2nd Floor	1	EA	7	10+ years			
	Work Sink	2nd Floor	1	EA	7	10+ years			
atego	ry : Interior		В	uilding	: Additi	on			
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
orridor									
	Ceiling - Lay-in	1st Floor	1,294	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	127	SF	7	10+ years			
	Doors - Wood Doors include hw	1st Floor	4	EA	7	10+ years			
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years			
	Floor - Terrazzo	1st Floor	327	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	127	SF	6	6-10 years			
	Floor - Tile/Sheet	1st Floor	967	SF	7	6-10 years			
	Lighting Lovin	1ot Floor	10	⊏∧	7	6 10 years			

Corridor							
	Ceiling - Lay-in	1st Floor	1,294	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	127	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	327	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	127	SF	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	967	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	19	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	2	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	71	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	2,299	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,157	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,127	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	30	SF	4	0-1 year	Buckling floor
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,877	SF	7	10+ years	
Safety							
,	Camera Viewing Station	Entire Building	1	EA	7	10+ years	
	Metal Dedector	Entire Building	1	EA	7	10+ years	
	Security Cameras	Entire Building	3	EA	7	10+ years	
Staire							

<u>Stairs</u>



Category : Interior			Building : Addition							
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Plaster/Drywall	NW at Entrance 2	175	SF	7	10+ years				
	Floor - Terrazzo	NW at Entrance 2	125	SF	7	10+ years				
	Handrails	NW at Entrance 2	52	LF	7	10+ years				
	Lighting - Pendent/Surface	NW at Entrance 2	1	EΑ	7	6-10 years				
	Stairs - Terrazzo	NW at Entrance 2	22	LF	7	10+ years				
	Walls - Concrete Block	NW at Entrance 2	1,020	SF	7	10+ years				
	Ceiling - Plaster/Drywall	SE at Entrance 3	205	SF	7	10+ years				
	Floor - Terrazzo	SE at Entrance 3	103	SF	7	10+ years				
	Handrails	SE at Entrance 3	52	LF	7	10+ years				
	Lighting - Pendent/Surface	SE at Entrance 3	1	EA	7	6-10 years				
	Stairs - Terrazzo	SE at Entrance 3	22	LF	7	10+ years				
	Walls - Concrete Block	SE at Entrance 3	1,044	SF	7	10+ years				

Campus Name: Simpson HS Page : 22 of 25 Assessment Date: 05/26/2022





Category: Site Building: Site

Category : Site		Building : Site							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Civil/Dra	inage		_						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	8	EΑ	6	10+ years			
	Civil Brainage Cite Marinele	Little Oilo	0		Ū	101 youro			
Fencing									
rending	Fencing - Chain Link	Entire Site	885	LF	6	10+ years			
	Fencing - Chain Link Fencing - Chain Link	Entire Site	80	LF	5	1-2 years	Corroded, bent fencing		
	Fencing - Chain Link Fencing - New Standard Ornamental	Entire Site	145	LF	7	6-10 years	Corroded, bent fending		
	rending - New Standard Ornamental	Entire Site	145	LF	,	6-10 years			
Landsca	pe								
	Benches	Entire Site	1	EA	7	10+ years			
	Benches	Entire Site	5	EA	4	1-2 years	Broken concrete and mosaic benches		
	Landscape - Grass	Entire Site	14,345	SF	6	10+ years			
	Landscape - Grass	Entire Site	500	SF	5	1-2 years	Bare soil		
	Landscape - Grass	Entire Site	25	SF	4	0-1 year	Sinkhole next to foundation.		
	Landscape - Hardscape- Pavers	Entire Site	10,993	SF	6	10+ years			
	Parkway trees	Entire Site	12	ĒΑ	6	10+ years			
	Parkway trees	Entire Site	2	ΕA	4	1-2 years	Missing trees, chopped up pieces left		
						,	behind		
	Planting Beds/ Area	Entire Site	2,580	SF	6	10+ years			
Parking	Lot								
J	Concrete Curbs	North	450	LF	6	10+ years			
	Pavers	North	9,509	SF	6	10+ years			
0:1 "									
Sidewall	s Sidewalks - Internal Walks	Entire Site	600	LF	6	10+ years			
	Sidewalks - Internal Walks	Entire Site	30	LF	4	0-1 year	Broken, upheaved, severely		
	Sidewalks - Internal Walks	Little Oile	30	LI	7	0-1 year	damaged concrete		
	Sidewalks - Perimeter Sidewalks	Entire Site	5,992	SF	6	10+ years	damaged concrete		
	Sidewalks - Perimeter Sidewalks	Entire Site	1,250	SF	4	1-2 years	Upheaved, cracked, spalled, broken		
	Cidemanie i crimiciei Cidemanie	Zinii o ono	1,200	O.	•	. 2 you.o	concrete		
Signage									
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years			
	Monument - Building Mounted Cut Letter	Entire Site	1	EΑ	5	1-2 years	Damage letters, missing school name		
	Sign		•	=	-	,	g,g		
	Monument - Building Mounted Cut Letter	Entire Site	1	EA	5	1-2 years	Missing school name		
	Sign		•		-	. = ,	 		
	Monument - Sign	Entire Site	3	EA	6	10+ years			
	5		_		-	<i>,</i>			



Simpson Academy HS for Young Women

1321 S Paulina STREET, Chicago, IL 60608

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	intended Osage	Room Eccation	Humber	Number	(01)	Alea	Alea	σιορ	Doard
Faculty Lounge	Regular Classroom	1st Floor	106	106	825	105	49	Y	N
Other Instructional Use	Regular Classroom	1st Floor	102	102	825	201	52	Y	N
Regular Classroom	Regular Classroom	1st Floor	101	101	742	160	80	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	840	201	52	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	770	201	52	N	Υ
Regular Classroom	Regular Classroom	1st Floor	114	110	970	208	79	N	N
Regular Classroom	Regular Classroom	1st Floor	115	111	697	166	63	N	Υ
Science	Regular Classroom	1st Floor	105	105	850	201	52	Υ	Υ
	· -		•	•					
Building : Addition			-	+			t .	*	
Adult Education	Adult Education	1st Floor	120	112	390	83	31		
Art Room	Art Room	1st Floor	118	114	1,123	249	94	N	N
Computer Lab	Regular Classroom	2nd Floor	217	217	762	166	63	N	N
Office	Regular Classroom	1st Floor	121	117	769	166	63	N	N
04 1 6 6 111	B 1 01	0 1 51	0.4.0	0.1.0		400			

Building : Addition									
Adult Education	Adult Education	1st Floor	120	112	390	83	31		
Art Room	Art Room	1st Floor	118	114	1,123	249	94	N	N
Computer Lab	Regular Classroom	2nd Floor	217	217	762	166	63	N	N
Office	Regular Classroom	1st Floor	121	117	769	166	63	N	N
Other Instructional Use	Regular Classroom	2nd Floor	216	216	774	166	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	790	166	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	738	166	63	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	215	215	751	166	63	N	Υ
Store Room	Regular Classroom	1st Floor	113	113	769	166	63	N	N
Store Room	Regular Classroom	2nd Floor	212	212	375	83	31	N	N