

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1973	2	76,920
Campus Total			76,920

Category : Exterior Building : Main

	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance			•			•	
	Exterior Doors - Exterior Steel Door	Door #17 - Second Floor West Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door #17 - Second Floor West Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	East Over sized Steel Doors	2	EA	7	10+ years	
	Entrance Control - Audio and Video	Entrance 1	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 1	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 1	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 10 - North	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 10 - North	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 11 - North	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 11 - North	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 12	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 12	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 13 - East	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 13 - East	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 13 - East	6	LF	6	6-10 years	Stair/Stoop cracked and broken in spots
	Exterior Doors - Exterior Steel Door	Entrance 16 - South 2nd FL	1	EA	6	6-10 years	·
	Exterior Doors - Exterior Steel Door	Entrance 2 - South Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 2 - South Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 3 - West Courtyard	6	EA	6	6-10 years	
	Exterior Doors - Side lite	Entrance 3 - West Courtyard	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 3 - West Courtyard	7	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	Entrance 4 - North Courtyard	1	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 4 - North Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 5 - North Courtyard	1	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 5 - North Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 6 - East	2	EA	6	6-10 years	Pull Plate needs Repair-Affixing to Door Slab.
	Exterior Doors - Transom Lite	Entrance 6 - East	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 7 - South	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 7 - South	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 7 - South	8	LF	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 7 - South	4	LF	5	0-1 year	Cracking, spalling
	Exterior Doors - Exterior Steel Door	Entrance 8 - West	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 8 - West	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Exit 14 - North 2nd Flr	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Exit 14 - North 2nd Flr	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Exit 15 - South 2nd Flr	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Exit 15 - South 2nd Flr	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Exit 9 - West	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Exit 9 - West	1	EA	6	6-10 years	
						•	
_Foundati	on						
	Foundation - Concrete	Entire Building	963	LF	7	10+ years	
	Superstructure - Slab on Grade	Entire Building	83,370	SF	7	10+ years	Item Typed Changed to "Slab on Grade".
_Lighting_							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	14	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	6-10 years	
Roof Sys							
	Access Ladder - Metal	A	1	EA	7	10+ years	
	Chimney - Metal Flue	A	6	LF	7	10+ years	
	Coping - Metal	Α	1,470	LF	7	10+ years	
	Downspouts - Interior Downspouts	A	936	LF	7	10+ years	
	Roof - EPDM/ Synthetic Rubber	A	49,740	SF	6	6-10 years	
	Roof Hatch - Metal	A	1	EA	7	10+ years	
	Roof Structure - Concrete	A	49,740	SF	7	10+ years	
_Walls							
_vvalls	Canopy - Metal	Entire Building	3,600	SF	6	6-10 years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	27,880	SF	6	6-10 years	
	Wall	Entire Dullating	21,000	Oi.	Ū	o io youis	



	pry: Exterior		D	uilding	· Main		744 E 103rd STREET, Chicago, IL 6062
Catego	ry : Exterior		D	unaing	: wam		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	· · · · · · · · · · · · · · · · · · ·	Location	Quantity	OCIVI	Naiik	Replacement	Comments
Vindow:							
	Curtain wall - Glazed Double Pane	Entire Building	13,134	SF	6	6-10 years	
	Curtain wall - Insulated Panel	Entire Building	19,864	SF	6	6-10 years	
	Curtain wall - Louver	Entire Building	300	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	4,124	SF	6	6-10 years	
	Windows - Casement Steel Double-pane	Entire Building	96	SF	7	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
:mergei	ncy System						
-	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	2 ATSs found
	Exit Signs - Corridors and Stairs	Entire Building	21	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	5	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	5	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	33	EA	6	6-10 years	
	Stairs						
	Emergency Battery Packs - Gym	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	5	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	18,919	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	4,674	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,211	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,214	SF	6	10+ years	
	Security System - CCTV	Entire Building	76,920	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	76,920	SF	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 2001 to 3000 A 277/480/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	76,920	SF	6	6-10 years	
	Independent Electrical Service for	Entire Building	1	ĒΑ	6	10+ years	Second meter
	emergency power	<b>.</b>				, , , , , ,	
ower D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	Cleaned and tested, 2 found, functional panels rated 7
	Lighting and Power Panels - Above 100 A	Entire Building	12	EA	7	10+ years	Functional panels rated 7
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	7	10+ years	Functional panels rated 7
	Main Distribution Panels - Greater than 600	Entire Building	2	EΑ	7	10+ years	Functional panels rated 7
	amp		_	<b></b> .	•	,	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	10+ years	
		<b>J</b>			-	,	

Campus Name: Smith Page: 3 of 30 Assessment Date: 09/23/2021



	001000						744 E 10310 STREET, Chicago, IL 60626
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Transformers - 120/240 - 120/208	Entire Building	6	EA	6	10+ years	1973 installation
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar			•			•	
	Fire Alarm Panel	Entire Building	1	EA	3	1-2 years	Relay logic technology, old, replacement parts difficult to find
	Fire Alarm_System	Entire Building	83,370	SF	4	1-2 years	More than 40 years old, functional, n strobes
Sprinkle	r System						
·	Combination Wet and Dry Sprinkler System	Entire Building	76,920	SF	6	10+ years	Balcony and vestibule, exterior, dry system. School interior is wet system, using city pressure
	Sprinkler Heads	Entire Building	76,920	SF	7	10+ years	Using city pressure
	Sprinkler Piping	Entire Building	76,920	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	3						
	Condensing Unit- Roof Mounted - Greater than 50 tons	Roof	1	EA	4	2-5 years	Serves roof top unit, more than 30 years old, frequently repaired
Air Hand	lling Systems						
	Make Up Air Unit- Indoor Mounted- Gas Heating Coils - 6000 - 10,000 cfm	Mechanical Room	1	EA	3	0-1 year	Heating only, does not work well, serves kitchen area, corroded, 1973 installation
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Greater than 45 tons	Roof	1	EA	4	1-2 years	Difficult to control, corroded, connected to condenser unit
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 46 - 60 tons	Roof	3	EA	4	2-5 years	1973 installation, difficult to control, corroded
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - Greater than 60 tons	Roof	2	EA	4	2-5 years	1973 installation, difficult to control, corroded
			00	EA	4	2-5 years	No signal from thermostats, Inside of
	Zone Dampers	Roof	62	LA	4	2 o youro	roof top units, manually operated
Heating .		Roof	62	LA	4	2 o youro	

Campus Name: Smith Page : 4 of 30 Assessment Date: 09/23/2021



Catego	ry : Mechanical		B	uilding	· Main		744 E 1001d 011(EE1, Officago, 1E 00020
Catego	i y . Micchailleai			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
o.oup	nom Typo	2004.101.	Quantity	00	rtannt	rtopiacomont	Commonic
Tempera	ature Control						
_топрои	DDC System	Entire Building	83,370	SF	2	0-1 year	Does not work, manually operated
	Thermostats - DDC	Entire Building	63	EA	4	2-5 years	Difficult to control, BAS does not work
		g				,	well, manually controlled
							temperatures
<u>Ventilation</u>	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	3	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	5	6-10 years	Exhaust fan for kitchen, centrifugal
	CFM	F (1 B 11 II	•		_	40	style
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	5	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	Serves dishwasher, functional, tested
	.,po	g	·		· ·	0 .0 ,00.0	<b>3</b>
Catego	ry : Plumbing		В	uilding	: Main		
				Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	4	2-5 years	1994 installation, more than 25 years
							old, functional, burners cleaned
_Piping_							
	Domestic Piping-Hot Water Return Lines	Entire Building	76,920	SF	6	6-10 years	Leaks repaired, 1973 installation
	Domestic Piping-Hot Water Return Risers	Entire Building	76,920	SF	6	6-10 years	Leaks repaired, 1973 installation
	Domestic Piping-Hot Water from Risers to	Entire Building	76,920	SF	6	6-10 years	Leaks repaired
	Fixtures Domestic Piping-Hot/Cold Water Supply	Entire Building	76,920	SF	6	6-10 years	Leaks repaired
	(Horizontal Lines)	Little Ballaling	70,920	OI.	O	0-10 years	Leaks repaired
	Domestic Piping-Hot/Cold Water Supply	Entire Building	76,920	SF	6	6-10 years	Leaks repaired
	(Risers)	3	-,-			<b>,</b>	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	76,920	SF	6	6-10 years	Leaks repaired, 1973 installation
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	76,920	SF	6	10+ years	1973 installation
	Storm Piping	Entire Building	76,920	SF	6	10+ years	
	Vent Piping	Entire Building	76,920	SF	6	10+ years	
Dumne							
Pumps	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	4	2-5 years	Currently being repaired
	Pumps - Sump-Simplex	Mechanical Room	1	EA	5	6-10 years	Under elevator, previously not
	i ampo Gump Gimpiex	Woonamou Room	'	LA	J	o to years	assessed
							accocca

Campus Name: Smith Page : 5 of 30 Assessment Date: 09/23/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Splined	146 Admin Office	139	SF	6	10+ years	
	Doors - Transom Window	146 Admin Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	146 Admin Office	1	ĒΑ	6	10+ years	
	Floor - Tile	146 Admin Office	139	SF	6	10+ years	
	Lighting - Pendent/Surface	146 Admin Office	3	ĒΑ	7	6-10 years	3 fixtures
	Walls - Plaster/Drywall	146 Admin Office	479	SF	7	10+ years	
	Ceiling - Lay-in	147 Vault	100	SF	6	10+ years	
	Doors - Steel Doors incl hw	147 Vault	1	EA	6	10+ years	
	Floor - Tile	147 Vault	100	SF	6	10+ years	
	Lighting - Lay-in	147 Vault	2	EA	6	6-10 years	
	Power Distribution	147 Vault	4	EA	6	6-10 years	
	Walls - Concrete Block	147 Vault	380	SF	6	10+ years	
	Ceiling - Splined	149 Copy Room	92	SF	7	10+ years	No damage observed
	Doors - Transom Window	149 Copy Room	18	SF	6	10+ years	<b>G</b>
	Doors - Wood Doors inclu hw	149 Copy Room	2	EA	6	10+ years	
	Floor - Tile	149 Copy Room	92	SF	6	10+ years	
	Lighting - Pendent/Surface	149 Copy Room	2	EA	7	6-10 years	
	Power Distribution	149 Copy Room	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	149 Copy Room	273	SF	7	10+ years	
	Ceiling - Splined	153 Copy Room	200	SF	7	10+ years	No damage observed
	Doors - Transom Window	153 Copy Room	9	SF	6	10+ years	S .
	Doors - Wood Doors inclu hw	153 Copy Room	1	EA	6	10+ years	
	Floor - Tile	153 Copy Room	200	SF	6	10+ years	
	Lighting - Pendent/Surface	153 Copy Room	6	EA	7	6-10 years	
	Power Distribution	153 Copy Room	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	153 Copy Room	486	SF	6	10+ years	
	Ceiling - Lay-in	155 Admin Kitchenette	90	SF	6	10+ years	
	Doors - Transom Window	155 Admin Kitchenette	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	155 Admin Kitchenette	1	EA	6	10+ years	
	Floor - Tile	155 Admin Kitchenette	90	SF	6	10+ years	
	Lighting - Pendent/Surface	155 Admin Kitchenette	2	EA	7	6-10 years	
	Power Distribution	155 Admin Kitchenette	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	155 Admin Kitchenette	328	SF	6	10+ years	
	Work Sink	155 Admin Kitchenette	1	EA	7	6-10 years	
	Ceiling - Lay-in	156 Work Rm/Main Office	134	SF	6	10+ years	
	Doors - Transom Window	156 Work Rm/Main Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	156 Work Rm/Main Office	1	EA	6	10+ years	
	Floor - Tile	156 Work Rm/Main Office	134	SF	6	10+ years	
	Lighting - Pendent/Surface	156 Work Rm/Main Office	3	EA	6	6-10 years	
	Power Distribution	156 Work Rm/Main Office	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	156 Work Rm/Main Office	460	SF	7	10+ years	
	Ceiling - Lay-in	157 (on door) Office (in Main Office	86	SF	7	10+ years	
	-	Admin.)				-	



Catego	Category : Room		В	uilding	: Main		· · · · · · · · · · · · · · · · · · ·		
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	157 (on door) Office (in Main Office Admin.)	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	157 (on door) Office (in Main Office Admin.)	1	EA	6	10+ years			
	Floor - Tile	157 (on door) Office (in Main Office Admin.)	86	SF	6	10+ years			
	Lighting - Pendent/Surface	157 (on door) Office (in Main Office Admin.)	2	EA	6	6-10 years			
	Power Distribution	157 (on door) Office (in Main Office Admin.)	4	EA	6	6-10 years			
	Walls - Plaster/Drywall	157 (on door) Office (in Main Office Admin.)	330	SF	6	10+ years			
	Ceiling - Lay-in	Conference Rm-Main Office	349	SF	6	10+ years			
	Doors - Steel Doors incl hw	Conference Rm-Main Office	1	ĒΑ	6	10+ years			
	Doors - Transom Window	Conference Rm-Main Office	9	SF	6	10+ years			
	Floor - Tile	Conference Rm-Main Office	349	SF	6	10+ years			
	Lighting - Pendent/Surface	Conference Rm-Main Office	10	EA	7	6-10 years			
	Power Distribution	Conference Rm-Main Office	2	EA	6	6-10 years			
	Walls - Plaster/Drywall	Conference Rm-Main Office	717	SF	7	10+ years			
	Ceiling - Splined	Engineer's Key Office	140	SF	7	10+ years	No damage observed		
	Doors - Wood Doors inclu hw	Engineer's Key Office	1	EA	6	10+ years	ŭ		
	Floor - Tile	Engineer's Key Office	140	SF	6	6-10 years			
	Lighting - Pendent/Surface	Engineer's Key Office	2	ĒA	6	6-10 years			
	Storage/ Closet	Engineer's Key Office	22	SF	7	10+ years			
	Walls - Concrete Block	Engineer's Key Office	330	SF	6	10+ years			
	Ceiling - Splined	Engineer's Office 1st Fl	315	SF	6	10+ years			
	Ceiling - Splined	Engineer's Office 1st Fl	1	SF	4	0-1 year	Missing tile & damaged tiles		
	Doors - Wood Doors inclu hw	Engineer's Office 1st Fl	1	ĒA	6	10+ years	3		
	Floor - Tile	Engineer's Office 1st Fl	316	SF	6	6-10 years			
	Lighting - Pendent/Surface	Engineer's Office 1st Fl	2	ĒA	7	6-10 years			
	Power Distribution	Engineer's Office 1st Fl	4	EA	6	6-10 years			
	Storage/ Closet	Engineer's Office 1st Fl	176	SF	7	10+ years			
	Walls - Concrete Block	Engineer's Office 1st Fl	479	SF	6	10+ years			
	Ceiling - Splined	Gym Office	126	SF	7	6-10 years	No damage observed		
	Doors - Side-lite	Gym Office	36	SF	6	10+ years	uaage ezee.rea		
	Doors - Transom Window	Gym Office	6	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Gym Office	1	EA	6	10+ years			
	Floor - Wood	Gym Office	126	SF	7	10+ years			
	Lighting - Pendent/Surface	Gym Office	2	EA	7	6-10 years			
	Walls - Concrete Block	Gym Office	375	SF	6	10+ years			
	Ceiling - Splined	L-6 used as Storage	136	SF	7	6-10 years	No damage observed		
	Doors - Hardware	L-6 used as Storage	1	EA	4	0-1 year	Missing hardware		
	Doors - Transom Window	L-6 used as Storage	9	SF	6	10+ years	mooning hardware		
	Doors - Wood Doors inclu hw	L-6 used as Storage	1	EA	6	10+ years			
	200.0 Wood 20010 IIIold IIW	2 0 dood do otorago		_/ \	J	101 yours			



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	L-6 used as Storage	136	SF	7	10+ years	
	Lighting - Pendent/Surface	L-6 used as Storage	2	EA	6	6-10 years	
	Power Distribution	L-6 used as Storage	4	EA	6	6-10 years	
	Walls - Metal Panel	L-6 used as Storage	344	SF	6	10+ years	
	Ceiling - Splined	L-9 (Library)	140	SF	7	10+ years	
	Doors - Transom Window	L-9 (Library)	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	L-9 (Library)	1	EA	6	10+ years	
	Floor - Tile	L-9 (Library)	140	SF	7	10+ years	
	Lighting - Pendent/Surface	L-9 (Library)	3	EA	5	6-10 years	
	Power Distribution	L-9 (Library)	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	L-9 (Library)	334	SF	6	10+ years	
	Ceiling - Splined	L4 Library Office	145	SF	7	10+ years	
	Doors - Transom Window	L4 Library Office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	L4 Library Office	1	EΑ	6	10+ years	
	Floor - Tile	L4 Library Office	145	SF	6	10+ years	
	Lighting - Pendent/Surface	L4 Library Office	6	ĒA	6	6-10 years	
	Power Distribution	L4 Library Office	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	L4 Library Office	440	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Main Office Lobby/Reception	546	SF	6	10+ years	
	Doors - Side-lite	Main Office Lobby/Reception	50	SF	7	10+ years	
	Doors - Steel Doors incl hw	Main Office Lobby/Reception	1	ĒΑ	6	10+ years	
	Doors - Transom Window	Main Office Lobby/Reception	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office Lobby/Reception	1	ĒΑ	6	10+ years	
	Floor - Tile	Main Office Lobby/Reception	546	SF	6	10+ years	
	Lighting - Pendent/Surface	Main Office Lobby/Reception	12	ĒΑ	7	6-10 years	
	Power Distribution	Main Office Lobby/Reception	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Main Office Lobby/Reception	430	SF	6	10+ years	
	Ceiling - Splined	Office 108	581	SF	7	10+ years	No damage observed
	Doors - Transom Window	Office 108	9	SF	6	10+ years	. to damage observed
	Doors - Wood Doors inclu hw	Office 108	1	EA	6	10+ years	
	Floor - Tile	Office 108	581	SF	6	10+ years	
	Lighting - Pendent/Surface	Office 108	12	EA	7	6-10 years	
	Power Distribution	Office 108	16	EΑ	6	6-10 years	
	Walls - Metal Panel	Office 108	763	SF	6	10+ years	
	Ceiling - Lay-in	Principal's Office	200	SF	6	10+ years	
	Doors - Side-lite	Principal's Office	1	SF	7	10+ years	
	Doors - Transom Window	Principal's Office	9	SF	6	2-5 years	
	Floor - Tile	Principal's Office	200	SF	6	10+ years	
	Lighting - Pendent/Surface	Principal's Office	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	Principal's Office	535	SF	6	10+ years	
	Work Sink	Principal's Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Work Room off Library	284	SF	7	10+ years	
	Doors - Side-lite	Work Room off Library	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Work Room off Library	1	EA	6	10+ years	
	20013 WOOG 20013 IIIOIG IIW	WORK ROOM ON LIDIARY	'	LA	U	TOT years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Work Room off Library	284	SF	6	10+ years	
	Lighting - Pendent/Surface	Work Room off Library	6	EA	7	6-10 years	
	Power Distribution	Work Room off Library	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	Work Room off Library	480	SF	6	10+ years	
	Work Slnk	Work Room off Library	1	ĒΑ	4	6-10 years	
Gvmnas	ia						
Суппаз	Ceiling - Exposed	1st Floor	4	SF	7	10+ years	No damage observed
	Ceiling - Exposed	1st Floor	4,670	SF	6	10+ years	140 damage observed
	Doors - Steel Doors incl hw	1st Floor	-	EA			
			2		6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	7	EA	6	10+ years	
	Floor - Wood	1st Floor	4,674	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	536	SF	6	6-10 years	
	Stage Curtain	1st Floor	9	ĒΑ	7	6-10 years	
	Stage Lift	1st Floor	1	EΑ	7	6-10 years	
	Stage Lighting System	1st Floor	1	EΑ	7	6-10 years	
	Stage Lighting System Storage/ Closet	1st Floor	152	SF	7	•	
						10+ years	
	Walls - Concrete Block	1st Floor	6,761	SF	6	10+ years	
	Walls - Masonry	1st Floor	780	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	1,441	SF	6	10+ years	Edited to match room size
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	1,441	SF	6	10+ years	Edited to match room size
	Lighting - Pendent/Surface	1st Floor	13	EA	6	6-10 years	
	Storage/ Closet	1st Floor	289	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,402	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Serving Room	138	SF	6	10+ years	
	Doors - Wood Doors inclu hw			EA	6	-	
		Serving Room	1			10+ years	
	Floor - Tile	Serving Room	138	SF	6	10+ years	
	Lighting - Pendent/Surface	Serving Room	2	EA	6	6-10 years	
	Serving Line	Serving Room	7	LF	6	6-10 years	
	Walls - Plaster/Drywall	Serving Room	449	SF	6	10+ years	
Library							
•	Casework	1st Floor	327	LF	6	10+ years	
	Ceiling - Splined	1st Floor	3,049	SF	6	10+ years	Edited to match room size
	Doors - Transom Window	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	DOGIS - VVOCA DOGIS IIICIA IIW	131 1001	Į.	$\vdash \cap$	U	io+ years	
	Floor - Carpet	1st Floor	3,049	SF	6	6-10 years	Edited to match room size



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	60	EA	7	6-10 years	
	Storage/ Closet	1st Floor	202	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,370	SF	6	10+ years	
ocker/S	shower Room						
	Accessories	2nd Fl Men's Locker Rm	150	SF	7	6-10 years	
	Ceiling - Splined (Moister Resistance)	2nd Fl Men's Locker Rm	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Fl Men's Locker Rm	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Fl Men's Locker Rm	150	SF	6	10+ years	
	Floor Drain	2nd Fl Men's Locker Rm	1	ĒΑ	7	10+ years	
	Lavatory	2nd Fl Men's Locker Rm	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Fl Men's Locker Rm	2	EA	6	6-10 years	
	Partitions	2nd Fl Men's Locker Rm	_ 1	EA	7	6-10 years	
	Showers	2nd Fl Men's Locker Rm	1	ĒΑ	7	6-10 years	
	Walls - Concrete Block	2nd Fl Men's Locker Rm	250	SF	7	10+ years	
	Walls - Tile	2nd Fl Men's Locker Rm	170	SF	6	10+ years	
	Water Closet	2nd Fl Men's Locker Rm	1	EA	6	6-10 years	
nch &	Multipurpose Room						
поп о	Ceiling - Plaster/Drywall	1st Floor	2,104	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	10+ years	
	Floor - Tile	1st Floor	2,104	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	50	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	260	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	2,634	SF	6	•	
	Doors - Steel Doors incl hw	2nd Floor 2nd Floor	2,034	EA	6	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	2,634	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	,	EA	7	10+ years	
	Walls - Plaster/Drywall		50	SF	, 6	10+ years	
	Ceiling - Splined	2nd Floor	260 1,170	SF SF	_	10+ years	
	Doors - Store Front	L11	1,170	Sr EA	6 7	6-10 years	
		L11		SF		10+ years	
	Doors - Transom Window	L11	18		7	10+ years	
	Floor - Tile	L11	1,170	SF	6	6-10 years	
	Lighting - Pendent/Surface	L11	24	EA	7	6-10 years	Down of the countries well assets as
	Walls - Metal Panel	L11	120	SF	7	10+ years	Part of the curtain wall system
	Walls - Plaster/Drywall	L11	985	SF	7	10+ years	
	Ceiling - Splined	South of Library	1,465	SF	6	6-10 years	
	Doors - Steel Doors incl hw	South of Library	1	EA	7	10+ years	
	Floor - Tile	South of Library	1,465	SF	7	10+ years	
	Lighting - Pendent/Surface	South of Library	30	EA	7	10+ years	<b>5</b>
	Walls - Metal Panel	South of Library	238	SF	7	10+ years	Part of the exterior curtain wall system
	Walls - Plaster/Drywall	South of Library	793	SF	7	10+ years	
	Ceiling - Splined	Staff Lounge	577	SF	7	10+ years	No damage observed

Campus Name: Smith Page: 10 of 30 Assessment Date: 09/23/2021



Catego	ry : Room		R	uilding	: Main	744 E 10314 011(EE1, Officago, 12 00020	
Gulogo	, , , , , , , , , , , , , , , , , , ,			anamg	· Wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. о пр	Doors - Steel Doors incl hw	Staff Lounge	1	EA	7	10+ years	
	Doors - Transom Window	Staff Lounge	9	SF	7	10+ years	
	Floor - Tile	Staff Lounge	577	SF	6	6-10 years	
	Lighting - Pendent/Surface	Staff Lounge	12	EA	7	6-10 years	
	Walls - Metal Panel	Staff Lounge	200	SF	7	10+ years	
				_		•	
	Walls - Plaster/Drywall	Staff Lounge	379	SF	7	10+ years	
MDF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Finishes	2nd Floor	92	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	4	0-1 year	Portable AC
Maahani	ical/ Service Rooms						
iviechali		Dools Characte Dome has Clarester	005	SF	7	40	
	Storage Room	Book Storage Rom by Classroom 119	225		7	10+ years	
	Storage Room	East Storage Closet in Gym	20	SF	7	10+ years	
	Storage Room	Gym Storage Room	196	SF	7	10+ years	
	Storage Room	In Library- storefront wall Door Locked	175	SF	7	10+ years	
	Janitor's Closet	Janitor Closets First Floor - by	176	SF	7	10+ years	
	lanitaria Olasat	Engineer's Office	45	0.5	7	40	
	Janitor's Closet	Janitor Closets Second Floor by Elevator	45	SF	7	10+ years	
	Storage Room	Library Stotage	587	SF	7	10+ years	
	Boiler Room	Mechanical First Floor	437	SF	7	10+ years	
	Storage Room	NE Storage Room in Gym	202	SF	7	10+ years	
	Storage Room	Stage Closet in Gym	125	SF	7	10+ years	
	Storage Room	Storage First Floor- across Engineer Office	433	SF	7	10+ years	
	Storage Room	Storage Room in Library	100	SF	7	10+ years	
	Storage Room	Storage Room next to a Engineer's	126	SF	7	10+ years	
	Storage Room	Office	120	OI.	,	10+ years	
	Janitor's Closet	Throughout Building	31	SF	7	10+ years	
	Mechanical/ Service Rooms	Throughout Building	433	SF	7	10+ years	
	Mechanical/ Service Rooms	Throughout Building	41	SF	7	10+ years	
	Mechanical/ Service Rooms	Throughout Building	46	SF	7	10+ years	
	Mechanical/ Service Rooms	Throughout Building	437	SF	7	10+ years	
	Mechanical/ Service Rooms			SF	7	•	
		Throughout Building	235 100	SF SF	7 7	10+ years	
	Mechanical/ Service Rooms	Throughout Building				10+ years	
	Storage Room	Throughout Building	225	SF	7	10+ years	
	Storage Room	Throughout Building	196	SF	7	10+ years	
	Storage Room	Throughout Building	587	SF	7	10+ years	
	Storage Room	Throughout Building	48	SF	7	10+ years	
	Storage Room	Throughout Building	175	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	Throughout Building	176	SF	7	10+ years	
	Storage Room	Throughout Building	202	SF	7	10+ years	
Restroo							
	Ceiling - Plaster/Drywall	119A Kindergarden	19	SF	6	10+ years	
	Doors - Wood Doors inclu hw	119A Kindergarden	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	119A Kindergarden	19	SF	6	10+ years	
	Lavatory	119A Kindergarden	1	EA	6	10+ years	
	Lighting - Lay-in	119A Kindergarden	1	EA	6	10+ years	
	Walls - Concrete Block	119A Kindergarden	91	SF	6	10+ years	
	Walls - Plaster/Drywall	119A Kindergarden	32	SF	6	10+ years	
	Water Closet	119A Kindergarden	1	EA	6	10+ years	
	Accessories	120A Kindergarden	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	120A Kindergarden	20	SF	6	10+ years	
	Doors - Transom Window	120A Kindergarden	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	120A Kindergarden	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	120A Kindergarden	20	SF	6	10+ years	
	Lavatory	120A Kindergarden	1	EA	6	10+ years	
	Lighting - Lay-in	120A Kindergarden	1	EΑ	7	10+ years	
	Walls - Concrete Block	120A Kindergarden	91	SF	6	10+ years	
	Walls - Plaster/Drywall	120A Kindergarden	32	SF	6	10+ years	
	Water Closet	120A Kindergarden	1	ĒΑ	6	10+ years	
	Accessories	1st Floor West	207	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor West	207	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor West	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor West	207	SF	6	10+ years	
	Hand Dryer	1st Floor West	2	EA	7	6-10 years	
	Lavatory	1st Floor West	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor West	6	EA	7	10+ years	
	Partitions	1st Floor West	5	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor West	436	SF	6	10+ years	
	Water Closet	1st Floor West	5	EA	6	10+ years	
	Accessories	1st Floor West	207	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor West	207	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor West	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor West	207	SF	6	•	
	Floor - Tile Ceramic/ Porcelain Floor Drain	1st Floor West	207	SF EA	7	10+ years	
		1st Floor West		EA EA	7	10+ years	
	Hand Dryer		1			6-10 years	
	Lavatory	1st Floor West	3	EΑ	6	10+ years	
	Lighting - Lay-in	1st Floor West	6	EΑ	7	10+ years	
	Partitions	1st Floor West	3	EΑ	7	6-10 years	
	Urinals	1st Floor West	2	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor West	436	SF	6	10+ years	
	Water Closet	1st Floor West	3	EA	7	10+ years	

Campus Name: Smith Page: 12 of 30 Assessment Date: 09/23/2021



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	2nd Floor North End	87	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor North End	87	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor North End	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor North End	87	SF	6	10+ years	
	Floor Drain	2nd Floor North End	1	EA	7	10+ years	
	Hand Dryer	2nd Floor North End	2	EA	7	6-10 years	
	Lavatory	2nd Floor North End	4	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor North End	2	EA	7	10+ years	
	Partitions	2nd Floor North End	4	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor North End	359	SF	6	10+ years	
	Water Closet	2nd Floor North End	4	EA	6	10+ years	
	Accessories	2nd Floor North End	87	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor North End	87	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor North End	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor North End	87	SF	6	10+ years	
	Floor Drain	2nd Floor North End	1	EA	7	10+ years	
	Hand Dryer	2nd Floor North End	2	EA	7	10+ years	
	Lavatory	2nd Floor North End	4	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor North End	2	EA	7	10+ years	
	Partitions	2nd Floor North End	2	EA	7	10+ years	
	Partitions	2nd Floor North End	1	EA	5	2-5 years	
	Urinals	2nd Floor North End	2	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor North End	359	SF	6	10+ years	
	Water Closet	2nd Floor North End	2	EA	7	10+ years	
	Accessories	2nd Floor West	258	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor West	258	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor West	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor West	258	SF	6	10+ years	
	Floor Drain	2nd Floor West	1	EA	7	10+ years	
	Hand Dryer	2nd Floor West	1	EA	7	6-10 years	
	Lavatory	2nd Floor West	5	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor West	4	EA	6	10+ years	
	Partitions	2nd Floor West	9	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor West	587	SF	6	10+ years	
	Water Closet	2nd Floor West	9	EA	7	10+ years	
	Accessories	2nd Floor West	258	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor West	258	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor West	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor West	258	SF	6	10+ years	
	Floor Drain	2nd Floor West	1	EA	7	10+ years	
	Hand Dryer	2nd Floor West	2	EA	7	6-10 years	
	Lavatory	2nd Floor West	4	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor West	4	EA	7	10+ years	
	Partitions	2nd Floor West	4	EA	7	10+ years	
						•	

Campus Name: Smith Page: 13 of 30 Assessment Date: 09/23/2021



Catego	ry : Room		Building : Main				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Urinals	2nd Floor West	6	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor West	587	SF	6	10+ years	
	Water Closet	2nd Floor West	4	EA	6	10+ years	
	Accessories	Across Library	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Across Library	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Across Library	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Across Library	120	SF	7	10+ years	
	Floor Drain	Across Library	1	EA	7	10+ years	
	Lavatory	Across Library	2	EA	7	10+ years	
	Lighting - Lay-in	Across Library	4	EA	7	6-10 years	
	Partitions	Across Library	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Across Library	64	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Across Library	300	SF	7	10+ years	
	Water Closet	Across Library	2	EA	7	10+ years	
	Accessories	Across Library	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Across Library	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Across Library	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Across Library	120	SF	7	10+ years	
	Floor Drain	Across Library	1	EA	7	10+ years	
	Lavatory	Across Library	2	EA	7	10+ years	
	Lighting - Lay-in	Across Library	4	EA	7	10+ years	
	Partitions	Across Library	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Across Library	64	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Across Library	300	SF	7	10+ years	
	Water Closet	Across Library	2	EA	7	10+ years	
	Accessories	East Unisex Across from 118- Under Construction	19	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	East Unisex Across from 118- Under Construction	19	SF	6	10+ years	
	Doors - Wood Doors inclu hw	East Unisex Across from 118- Under Construction	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	East Unisex Across from 118- Under Construction	19	SF	6	10+ years	
	Lavatory	East Unisex Across from 118- Under Construction	1	EA	6	10+ years	
	Lighting - Lay-in	East Unisex Across from 118- Under Construction	1	EA	6	10+ years	
	Walls - Concrete Block	East Unisex Across from 118- Under Construction	135	SF	6	10+ years	
	Water Closet	East Unisex Across from 118- Under Construction	1	EA	6	10+ years	
	Accessories	East Unisex Across from 220	19	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	East Unisex Across from 220	19	SF	6	10+ years	
	Doors - Wood Doors inclu hw	East Unisex Across from 220	1	EA	6	10+ years	
	200.0 From Booto mola inv	Edot Grison / Island Horn E20		_, .	J	.o. youro	



Category : Room			Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Tile Ceramic/ Porcelain	East Unisex Across from 220	19	SF	6	10+ years				
	Lavatory	East Unisex Across from 220	1	EA	6	10+ years				
	Lighting - Lay-in	East Unisex Across from 220	1	EA	7	10+ years				
	Walls - Concrete Block	East Unisex Across from 220	157	SF	6	10+ years				
	Water Closet	East Unisex Across from 220	1	EA	6	10+ years				
	Accessories	Engineer's Toilet 1st Floor	19	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Engineer's Toilet 1st Floor	19	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Engineer's Toilet 1st Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Engineer's Toilet 1st Floor	19	SF	6	10+ years				
	Lavatory	Engineer's Toilet 1st Floor	1	EA	6	10+ years				
	Lighting - Lay-in	Engineer's Toilet 1st Floor	1	EA	7	10+ years				
	Walls - Concrete Block	Engineer's Toilet 1st Floor	100	SF	6	10+ years				
	Walls - Plaster/Drywall	Engineer's Toilet 1st Floor	42	SF	6	10+ years				
	Water Closet	Engineer's Toilet 1st Floor	1	EA	7	10+ years				
	Accessories	Gym Office RR	20	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Gym Office RR	20	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Gym Office RR	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Gym Office RR	20	SF	6	10+ years				
	Lavatory	Gym Office RR	1	EA	6	10+ years				
	Lighting - Lay-in	Gym Office RR	1	EA	7	10+ years				
	Walls - Concrete Block	Gym Office RR	141	SF	6	10+ years				
	Water Closet	Gym Office RR	1	EA	7	10+ years				
	Accessories	Gym Toilet	20	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Gym Toilet	20	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Gym Toilet	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Gym Toilet	20	SF	6	10+ years				
	Lavatory	Gym Toilet	1	ĒΑ	6	10+ years				
	Lighting - Lay-in	Gym Toilet	1	EA	6	10+ years				
	Walls - Concrete Block	Gym Toilet	165	SF	6	10+ years				
	Walls - Plaster/Drywall	Gym Toilet	45	SF	6	10+ years				
	Water Closet	Gym Toilet	1	ĒΑ	6	10+ years				
	Ceiling - Plaster/Drywall	Kitchen Mens	53	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Kitchen Mens	1	ĒΑ	6	10+ years				
	Floor - Tile Quarry	Kitchen Mens	53	SF	6	10+ years				
	Lavatory	Kitchen Mens	1	ĒΑ	6	10+ years				
	Lighting - Lay-in	Kitchen Mens	1	EA	7	10+ years				
	Partitions	Kitchen Mens	1	EA	7	10+ years				
	Student Lockers - One Tier	Kitchen Mens	1	EA	6	10+ years				
	Walls - Plaster/Drywall	Kitchen Mens	222	SF	6	10+ years				
	Water Closet	Kitchen Mens	1	ĒΑ	7	10+ years				
	Ceiling - Plaster/Drywall	Kitchen Womens	53	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Kitchen Womens	1	EA	6	10+ years				
	Floor - Tile Quarry	Kitchen Womens	53	SF	6	10+ years				
	Lavatory	Kitchen Womens	1	EA	6	10+ years				
	·· <i>-</i>		•		•	,				



Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Lay-in	Kitchen Womens	1	EA	7	10+ years				
	Partitions	Kitchen Womens	1	EA	7	10+ years				
	Student Lockers - One Tier	Kitchen Womens	1	EA	6	10+ years				
	Walls - Plaster/Drywall	Kitchen Womens	222	SF	6	10+ years				
	Water Closet	Kitchen Womens	1	EA	7	10+ years				
	Ceiling - Plaster/Drywall	Principal's Office	18	SF	6	10+ years				
	Doors - Transom Window	Principal's Office	9	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Principal's Office	1	ĒΑ	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Principal's Office	18	SF	6	10+ years				
	Lavatory	Principal's Office	1	ĒΑ	6	10+ years				
	Lighting - Lay-in	Principal's Office	1	EA	7	10+ years				
	Walls - Concrete Block	Principal's Office	80	SF	7	10+ years				
	Walls - Plaster/Drywall	Principal's Office	70	SF	7	10+ years				
	Water Closet	Principal's Office	1	EA	6	10+ years				
	Accessories	Unisex Across from 217	19	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Unisex Across from 217	19	SF	6	10+ years				
	Doors - Steel Doors incl hw	Unisex Across from 217	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Unisex Across from 217	19	SF	6	10+ years				
	Lavatory	Unisex Across from 217	13	EA	6	10+ years				
	Lighting - Lay-in	Unisex Across from 217	1	EA	6	10+ years				
	Walls - Plaster/Drywall	Unisex Across from 217	159	SF	6	10+ years				
	Water Closet	Unisex Across from 217	139	EA	7	10+ years				
	Ceiling - Plaster/Drywall	Unisex Staff RR North Near Main	20	SF	6	10+ years				
	Celling - Flaster/Drywaii	Office	20	SI	O	10+ years				
	Doors - Wood Doors inclu hw	Unisex Staff RR North Near Main Office	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Unisex Staff RR North Near Main Office	20	SF	6	10+ years				
	Lavatory	Unisex Staff RR North Near Main Office	1	EA	6	10+ years				
	Lighting - Lay-in	Unisex Staff RR North Near Main Office	1	EA	7	10+ years				
	Walls - Concrete Block	Unisex Staff RR North Near Main Office	157	SF	6	10+ years				
	Water Closet	Unisex Staff RR North Near Main Office	1	EA	6	10+ years				
	Accessories	Unisex Staff RR South Near Main Office	20	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Unisex Staff RR South Near Main Office	20	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Unisex Staff RR South Near Main Office	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Unisex Staff RR South Near Main Office	20	SF	6	10+ years				

Campus Name: Smith Page : 16 of 30 Assessment Date: 09/23/2021



Category : Room		В	uilding	: Main			
0	T	l a antian	0	LIOM	DI-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Unisex Staff RR South Near Main Office	1	EA	6	10+ years	
	Lighting - Lay-in	Unisex Staff RR South Near Main Office	1	EA	7	10+ years	
	Walls - Concrete Block	Unisex Staff RR South Near Main Office	150	SF	6	10+ years	
	Walls - Plaster/Drywall	Unisex Staff RR South Near Main Office	50	SF	6	10+ years	
	Water Closet	Unisex Staff RR South Near Main Office	1	EA	7	10+ years	
	Accessories	West Unisex Across from 118 - Demolished	19	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	West Unisex Across from 118 - Demolished	19	SF	6	10+ years	
	Doors - Wood Doors inclu hw	West Unisex Across from 118 - Demolished	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	West Unisex Across from 118 - Demolished	19	SF	6	10+ years	
	Lavatory	West Unisex Across from 118 - Demolished	1	EA	6	10+ years	
	Lighting - Lay-in	West Unisex Across from 118 - Demolished	1	EA	6	10+ years	
	Walls - Concrete Block	West Unisex Across from 118 - Demolished	105	SF	6	10+ years	
	Walls - Plaster/Drywall	West Unisex Across from 118 - Demolished	36	SF	6	10+ years	
	Water Closet	West Unisex Across from 118 - Demolished	1	EA	6	10+ years	
	Accessories	West Unisex Across from 220	19	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West Unisex Across from 220	19	SF	6	10+ years	
	Doors - Wood Doors inclu hw	West Unisex Across from 220	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	West Unisex Across from 220	19	SF	6	10+ years	
	Lavatory	West Unisex Across from 220	1	EA	6	10+ years	
	Lighting - Lay-in	West Unisex Across from 220	1	EA	7	10+ years	
	Walls - Concrete Block	West Unisex Across from 220	156	SF	6	10+ years	
	Water Closet	West Unisex Across from 220	1	EA	7	10+ years	
	Accessories	in 153	19	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	in 153	19	SF	6	10+ years	
	Doors - Wood Doors inclu hw	in 153	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	in 153	19	SF	6	10+ years	
	Lavatory	in 153	1	EA	6	10+ years	
	Lighting - Lay-in	in 153	1	EA	6	10+ years	
	Walls - Concrete Block	in 153	90	SF	6	10+ years	
	Walls - Plaster/Drywall	in 153	69	SF	6	10+ years	



	: Room		В	uilding	: Main		
						Recommend	
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	in 153	1	EA	6	10+ years	
ategory	: Classroom		R	uilding	· Main		
alegory	. Classicolli			unung	. Walli	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroom	n #109 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	884	SF	7	10+ years	
	Doors - Side-lite	1st Floor	15	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Marker Board		15	LF			
		1st Floor			7	6-10 years	
,	Walls - Metal Panel	1st Floor	920	SF	6	10+ years	
lassroom	n #111 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	884	SF	7	10+ years	
	Doors - Side-lite	1st Floor	15	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	929	SF	6	10+ years	
	vvalis - Metai i ariei	13111001	323	OI.	Ü	10+ years	
	n #113 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	884	SF	7	10+ years	
I	Doors - Side-lite	1st Floor	15	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	884	SF	7	10+ years	
1	Lighting - Pendent/Surface	1st Floor	17	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	929	SF	6	10+ years	
loooroo~	2 #114 (Pagular Classroom)						
	n #114 (Regular Classroom)	4 - 4 - Tla	004	C.E.	7	10	
	Ceiling - Lay-in	1st Floor	884	SF	7	10+ years	
	Doors - Side-lite	1st Floor	15	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
١	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	Rank updated to match current observation
	Floor - Tile	1st Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	ĒΑ	6	6-10 years	

Campus Name: Smith Page: 18 of 30 Assessment Date: 09/23/2021



Catego	ory : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	927	SF	6	10+ years	
Classro	om #115 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	884	SF	7	10+ years	
	Doors - Side-lite	1st Floor	15	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	927	SF	6	10+ years	
Classro	om #116 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	884	SF	7	10+ years	
	Doors - Side-lite	1st Floor	15	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	6	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	927	SF	6	10+ years	
Classro	om #118 (Regular Classroom)						
Classio		4 - 4 El "	4.477	0.5	7	40	
	Ceiling - Lay-in	1st Floor	1,177	SF	7	10+ years	
	Doors - Side-lite	1st Floor	30	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,177	SF	7	10+ years	Tile rank updated to match current observation
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	1,023	SF	6	10+ years	
Classro	om #119 (Kindergarten)						
	Ceiling - Lay-in	1st Floor	1,177	SF	6	6-10 years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	45	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	6	10+ years	
	Floor - Tile	1st Floor	1,177	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	6	•	
	Lighting - Fertuent/Surface	191 LIOOI	24	EA	Ö	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	1,070	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	m #120 (Kindergarten)						
	Ceiling - Lay-in	1st Floor	1,177	SF	6	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	15	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,177	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	6	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	977	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
	Work Girik	13111001	2	LA	,	0-10 years	
Classroo	m #201 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	872	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	872	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	919	SF	6	10+ years	
Classroo	m #202 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	6	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
Classroo	m #203 (Regular Classroom)						
CiassiUC	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite			SF SF		•	
		2nd Floor	15	SF SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	

Campus Name: Smith Page : 20 of 30 Assessment Date: 09/23/2021



Catego	ry : Classroom		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Pendent/Surface	2nd Floor	17	EΑ	6	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
Classroo	nm #204 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	557	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	557	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	840	SF	6	10+ years	
						j	
Classroo	om #205 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	6	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
Classroo	om #206 (Vacant)						
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	6	6-10 years	
	Marker Board	2nd Floor	15	LF	6	6-10 years	
	Walls - Metal Panel	2nd Floor 2nd Floor	927	SF	6	10+ years	
	Trails Wicker and	2110 1 1001	321	01	O	ioi youio	
Classroo	m #208 (Music Room)						

Campus Name: Smith Page : 21 of 30 Assessment Date: 09/23/2021



Ceilir Door Door Floor Light Mark Walls  Classroom #20 Ceilir Door Door Floor Light Mark	ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface ker Board s - Metal Panel  19 (Regular Classroom) ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	Location  2nd Floor  2nd Floor	Quantity  884 11 9 1 884 17 15 927	SF SF SF EA SF EA LF SF	Rank 6 6 6 6 7 7 6	Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
Ceilir Door Door Floor Light Mark Walls  Classroom #20 Ceilir Door Door Floor Light Mark	ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface ker Board s - Metal Panel  99 (Regular Classroom) ng - Lay-in rs - Side-lite rs - Transom Window r - Tile	2nd Floor	884 11 9 1 884 17 15 927	SF SF EA SF EA LF	6 6 6 6 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	Comments
Door Door Floor Light Mark Walls Classroom #20 Ceilir Door Door Floor Light Mark	rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface ker Board s - Metal Panel  09 (Regular Classroom) ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	2nd Floor	11 9 1 884 17 15 927	SF SF EA SF EA LF	6 6 6 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	
Door Door Floor Light Mark Walls Classroom #20 Ceilir Door Door Door Floor Light Mark	rs - Transom Window rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface ker Board s - Metal Panel  09 (Regular Classroom) ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	2nd Floor	9 1 884 17 15 927	SF EA SF EA LF	6 6 6 7 7	10+ years 10+ years 10+ years 10+ years 6-10 years	
Door Floor Light Mark Walls Classroom #20 Ceilir Door Door Door Floor Light Mark	rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface ker Board s - Metal Panel  09 (Regular Classroom) ng - Lay-in rs - Side-lite rs - Transom Window r - Tile	2nd Floor	1 884 17 15 927	EA SF EA LF	6 6 7 7	10+ years 10+ years 10+ years 6-10 years	
Floor Light Mark Walls Classroom #20 Ceilir Door Door Door Floor Light Mark	r - Tile ting - Pendent/Surface ker Board s - Metal Panel  09 (Regular Classroom) ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	884 17 15 927	SF EA LF	6 7 7	10+ years 10+ years 6-10 years	
Light Mark Walls  Classroom #20 Ceilir Door Door Door Floor Light Mark	ting - Pendent/Surface Ker Board s - Metal Panel  D9 (Regular Classroom) ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	17 15 927 884	EA LF	7	10+ years 6-10 years	
Mark Walls Classroom #20 Ceilir Door Door Door Floor Light Mark	xer Board s - Metal Panel  09 (Regular Classroom)  ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor	15 927 884	LF	7	6-10 years	
Walls  Classroom #20 Ceilir Door Door Door Floor Light Mark	s - Metal Panel  9 (Regular Classroom)  ng - Lay-in  rs - Side-lite  rs - Transom Window  rs - Wood Doors inclu hw  r - Tile	2nd Floor 2nd Floor 2nd Floor	927				
Classroom #20 Ceilir Door Door Door Floor Light Mark	09 (Regular Classroom) ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	2nd Floor 2nd Floor	884	SF	6	10+ years	
Ceilir Door Door Door Floor Light Mark	ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	2nd Floor					
Ceilir Door Door Door Floor Light Mark	ng - Lay-in rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	2nd Floor					
Door Door Door Floor Light Mark	rs - Side-lite rs - Transom Window rs - Wood Doors inclu hw r - Tile	2nd Floor		SF	6	10+ years	
Door Door Floor Light Mark	rs - Transom Window rs - Wood Doors inclu hw r - Tile		15	SF	6	10+ years	
Door Floor Light Mark	rs - Wood Doors inclu hw r - Tile	ZHO FIOOF	9	SF	6	10+ years	
Floor Light Mark	r - Tile	2nd Floor	1	EA	6	10+ years	
Light Mark		2nd Floor	884	SF	6	10+ years	
Mark	ting - Pendent/Surface	2nd Floor	18	EA	7	10+ years	
	ker Board	2nd Floor	15	LF	7	6-10 years	
vvalis	s - Metal Panel	2nd Floor	927	SF	6	10+ years	
	S - Metal Panel	2110 F1001	921	SF	б	10+ years	
	1 (Regular Classroom)						
Ceilir	ng - Lay-in	2nd Floor	884	SF	6	10+ years	
	rs - Side-lite	2nd Floor	15	SF	6	10+ years	
Door	rs - Transom Window	2nd Floor	9	SF	6	10+ years	
Door	rs - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	Priority replacement (a.k.a. RUL)
						•	changed to update/correct to match current observations
Floor	r - Tile	2nd Floor	884	SF	6	10+ years	our one oboor valions
	ting - Pendent/Surface	2nd Floor	17	EA	7	10+ years	
	ker Board	2nd Floor	12	LF	7	6-10 years	
	s - Metal Panel	2nd Floor	927	SF	6	-	
vvaiis	S - IVIELAI FAITEI	2110 11001	921	SF	b	10+ years	
	13 (Regular Classroom)						
	ng - Lay-in	2nd Floor	884	SF	6	10+ years	
Chall	lk Board	2nd Floor	16	LF	4	2-5 years	
Door	rs - Side-lite	2nd Floor	15	SF	6	10+ years	
Door	rs - Transom Window	2nd Floor	9	SF	6	10+ years	
Door	rs - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	r - Tile	2nd Floor	884	SF	6	10+ years	
	ting - Pendent/Surface	2nd Floor	18	ĒΑ	7	10+ years	
	ker Board	2nd Floor	15	LF	7	6-10 years	
	s - Metal Panel	2nd Floor	927	SF	6	10+ years	
01	4 (Regular Classroom)					•	

Campus Name: Smith Page : 22 of 30 Assessment Date: 09/23/2021



Catego	ry : Classroom		В	uilding	: Main		· ·
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	10+ years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
Classroo	om #215 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	10+ years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
Classroo	om #216 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	10+ years	
	Marker Board	2nd Floor	15	LF	7		
	Walls - Metal Panel	2nd Floor 2nd Floor	927	SF	6	6-10 years 10+ years	
Classus	one #047 (Demiller Classers on)					•	
Ciassion	om #217 (Regular Classroom)	0	204			40	
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
Classroo	om #218 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	7	10+ years	
						·	

Campus Name: Smith Page : 23 of 30 Assessment Date: 09/23/2021



Catego	Category : Classroom			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	10+ years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
_Classroo	om #219 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	Priority replacement (a.k.a. RUL)
	Doors Wood Doors mold fiw	210 1 1001		L/(	Ü	o to years	changed to update/correct to match current observations
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
	Wireless System	2nd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #220 (Store Room)						
	Casework	2nd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,081	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	54	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	1,081	SF	6	10+ years	
	Gas Line	2nd Floor	6	EΑ	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EΑ	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	1,095	SF	6	10+ years	
	Work Sink	2nd Floor	4	EA	5	2-5 years	
_Classroo	om #221 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	850	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	850	SF	6	10+ years 10+ years	
					-		
	Lighting - Lay-in	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	15 858	LF SF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	050	~.∟	6	10+ years	

Campus Name: Smith Page : 24 of 30 Assessment Date: 09/23/2021



Category : Classroom			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #222 (Counseling Room)						
	Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	927	SF	6	10+ years	
Classras	m #224 (Bagular Classroom)						
Classion	m #224 (Regular Classroom)  Ceiling - Lay-in	2nd Floor	884	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	•	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years 10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	928	SF	6	10+ years	
					0	ioi youlo	
						·	
Catego	ry : Interior		В	uilding	: Main	•	
	ry : Interior	Lacation		uilding		Recommend	Comments
Group		Location	B Quantity		: Main Rank	·	Comments
	ry : Interior Item - Type		Quantity	uilding UOM	Rank	Recommend Replacement	
Group	ry : Interior  Item - Type  Ceiling - Splined	1st Engineer Corridor	Quantity 931	UOM SF	Rank 5	Recommend Replacement  0-1 year	Comments  Damaged tiles
Group	ry: Interior  Item - Type  Ceiling - Splined Doors - Steel Doors incl hw	1st Engineer Corridor 1st Engineer Corridor	Quantity 931 2	UOM SF EA	<b>Rank</b> 5 6	Recommend Replacement  0-1 year 10+ years	
Group	ry: Interior  Item - Type  Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window	1st Engineer Corridor 1st Engineer Corridor 1st Engineer Corridor	<b>Quantity</b> 931 2 6	UOM SF EA SF	<b>Rank</b> 5 6 6	Recommend Replacement  0-1 year 10+ years 10+ years	
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete	1st Engineer Corridor 1st Engineer Corridor 1st Engineer Corridor 1st Engineer Corridor	931 2 6 931	UOM  SF EA SF SF SF	5 6 6 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years	
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface	1st Engineer Corridor	931 2 6 931 8	UOM  SF EA SF SF EA	5 6 6 7 6	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years	
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block	1st Engineer Corridor	931 2 6 931 8 1,225	UOM  SF EA SF SF EA SF EA SF	5 6 6 7 6 6 6	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years	
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined	1st Engineer Corridor	931 2 6 931 8 1,225 6,174	UOM  SF EA SF EA SF EA SF EA SF	5 6 6 7 6 6 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite	1st Engineer Corridor 1st NW 1st NW	931 2 6 931 8 1,225 6,174 50	UOM  SF EA SF EA SF EA SF EA SF SF SF	5 6 6 7 6 6 7 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window	1st Engineer Corridor 1st NW 1st NW 1st NW	931 2 6 931 8 1,225 6,174 50 24	UOM  SF EA SF EA SF SF SF SF SF SF	5 6 6 7 6 6 7 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Wood Doors include hw	1st Engineer Corridor 1st NW 1st NW 1st NW 1st NW	931 2 6 931 8 1,225 6,174 50 24	UOM  SF EA SF EA SF SF SF SF SF SF SF	5 6 6 7 6 6 7 7 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Damaged tiles
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Fountain	1st Engineer Corridor 1st NW 1st NW 1st NW 1st NW 1st NW	931 2 6 931 8 1,225 6,174 50 24 4	UOM  SF EA SF EA SF EA SF EA SF EA SF EA EA	5 6 6 7 6 6 7 7 7 6	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years	
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Engineer Corridor 1st NW	931 2 6 931 8 1,225 6,174 50 24 4 1 6,174	UOM  SF EA SF EA SF SF EA SF	5 6 6 7 6 6 7 7 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years	Damaged tiles
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface	1st Engineer Corridor 1st NW	931 2 6 931 8 1,225 6,174 50 24 4 1 6,174 76	UOM  SF EA SF EA SF SF SF SF EA EA SF EA	5 6 6 7 6 6 7 7 7 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 6-10 years	Damaged tiles
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Stairs - Concrete Stairs	1st Engineer Corridor 1st NW	931 2 6 931 8 1,225 6,174 50 24 4 1 6,174 76 26	UOM  SF EA SF EA SF SF EA SF EA LF	5 6 6 7 6 6 7 7 7 6 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	Damaged tiles
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Stairs - Concrete Stairs Student Lockers - One Tier	1st Engineer Corridor 1st NW	931 2 6 931 8 1,225 6,174 50 24 4 1 6,174 76 26 105	UOM  SF EA SF EA SF SF EA LF EA	5 6 6 7 6 6 7 7 7 7 6 7 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Damaged tiles
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Stairs - Concrete Stairs Student Lockers - One Tier Walls - Metal Panel	1st Engineer Corridor 1st NW	931 2 6 931 8 1,225 6,174 50 24 4 1 6,174 76 26 105 2,875	UOM  SF EA S	5 6 6 7 6 6 7 7 7 6 7 7 6 6 6	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	Damaged tiles
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Stairs - Concrete Stairs Student Lockers - One Tier Walls - Metal Panel Ceiling - Splined	1st Engineer Corridor 1st NW	931 2 6 931 8 1,225 6,174 50 24 4 1 6,174 76 26 105 2,875 597	UOM  SF EA SF SF SF EA SF SF SF EA SF	5 6 6 7 6 6 7 7 7 6 7 7 6 6 6 7	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years	Damaged tiles
Group	Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Stairs - Concrete Stairs Student Lockers - One Tier Walls - Metal Panel	1st Engineer Corridor 1st NW	931 2 6 931 8 1,225 6,174 50 24 4 1 6,174 76 26 105 2,875	UOM  SF EA S	5 6 6 7 6 6 7 7 7 6 7 7 6 6 6	Recommend Replacement  0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	Damaged tiles

Campus Name: Smith Page : 25 of 30 Assessment Date: 09/23/2021



Catego	ry : Interior	Building : Main							
_									
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	1st South Corridor	18	SF	6	10+ years			
	Floor - Tile/Sheet	1st South Corridor	597	SF	7	10+ years			
	Lighting - Pendent/Surface	1st South Corridor	12	EA	7	10+ years			
	Walls - Metal Panel	1st South Corridor	696	SF	6	10+ years			
	Ceiling - Splined	2nd Floor Corridor - Main	7,060	SF	5	10+ years			
	Drinking Fountains - Single Fountain	2nd Floor Corridor - Main	1	EA	5	6-10 years			
	Floor - Tile/Sheet	2nd Floor Corridor - Main	7,060	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor Corridor - Main	94	EA	6	6-10 years			
	Student Lockers - One Tier	2nd Floor Corridor - Main	147	EA	6	10+ years			
	Walls - Metal Panel	2nd Floor Corridor - Main	3,240	SF	6	10+ years			
	Ceiling - Splined	2nd Floor South	2,541	SF	5	6-10 years			
	Drinking Fountains - Single Fountain	2nd Floor South	1	EA	7	6-10 years			
	Drinking Fountains - Single Fountain	2nd Floor South	1	EA	5	6-10 years			
	Floor - Tile/Sheet	2nd Floor South	2,541	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor South	54	EA	6	6-10 years			
	Stairs - Concrete Stairs	2nd Floor South	84	LF	6	10+ years			
	Student Lockers - One Tier	2nd Floor South	60	EA	6	10+ years			
	Walls - Metal Panel	2nd Floor South	2,330	SF	6	10+ years			
	Ceiling - Splined	Administrative Corridor 1st FI	384	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Administrative Corridor 1st Fl	1	EA	7	6-10 years			
	Floor - Tile/Sheet	Administrative Corridor 1st FI	384	SF	7	10+ years			
	Lighting - Pendent/Surface	Administrative Corridor 1st FI	6	EΑ	7	6-10 years			
	Walls - Plaster/Drywall	Administrative Corridor 1st FI	450	SF	7	10+ years			
	Ceiling - Splined	Engineer's West	140	SF	5	10+ years			
	Doors - Steel Doors incl hw	Engineer's West	1	EΑ	6	10+ years			
	Floor - Concrete	Engineer's West	140	SF	7	10+ years			
	Lighting - Pendent/Surface	Engineer's West	2	EA	6	6-10 years			
	Walls - Concrete Block	Engineer's West	396	SF	6	10+ years			
	Walls - Concrete Block	Engineer's West	8	SF	5	0-1 year	Cracked masonry		
	Ceiling - Splined	Library Vestibule	180	SF	6	6-10 years	Damaged tiles		
	Ceiling - Splined	Library Vestibule	12	SF	4	0-1 year	Damaged		
	Doors - Steel Doors incl hw	Library Vestibule	4	EA	6	10+ years			
	Doors - Transom Window	Library Vestibule	12	SF	6	10+ years			
	Floor - Tile/Sheet	Library Vestibule	192	SF	7	10+ years			
	Lighting - Pendent/Surface	Library Vestibule	4	EA	6	6-10 years			
	Walls - Plaster/Drywall	Library Vestibule	265	SF	6	10+ years			
Safety									
	Camera Viewing Station	Throughout Building	2	EA	7	6-10 years	Room 211 dean of students		
	Security Cameras	Throughout Building	15	EA	7	6-10 years			
Stairs									
Julia	Ceiling - Splined	Engineer's Office	208	SF	6	10+ years			
	Floor - Concrete	Engineer's Office	70	SF	7	10+ years			
		<b>3</b> <del></del>	. •		-	- <b>,</b>			

Campus Name: Smith Page : 26 of 30 Assessment Date: 09/23/2021



Category : Interior			В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Handrails	Engineer's Office	80	LF	7	10+ years	
	Lighting - Lay-in	Engineer's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	10+ years	
	Stairs - Concrete	Engineer's Office	80	LF	6	10+ years	
	Walls - Concrete Block	Engineer's Office	1,619	SF	6	10+ years	
	Ceiling - Splined	North Stair	260	SF	6	10+ years	
	Floor - Rubber Floor	North Stair	60	SF	6	10+ years	
	Handrails	North Stair	80	LF	7	10+ years	
	Lighting - Pendent/Surface	North Stair	5	EA	6	10+ years	
	Stairs - Rubber	North Stair	150	LF	6	10+ years	
	Ceiling - Exposed	Northeast Stairway	175	SF	6	10+ years	
	Ceiling - Splined	Northeast Stairway	50	SF	6	10+ years	
	Floor - Rubber Floor	Northeast Stairway	225	SF	6	10+ years	
	Handrails	Northeast Stairway	68	LF	7	10+ years	
	Lighting - Pendent/Surface	Northeast Stairway	4	EA	7	10+ years	
	Stairs - Rubber	Northeast Stairway	120	LF	6	10+ years	
	Ceiling - Splined	South Stair	260	SF	6	10+ years	
	Floor - Concrete	South Stair	60	SF	7	10+ years	
	Handrails	South Stair	80	LF	7	10+ years	
	Lighting - Pendent/Surface	South Stair	5	EA	6	10+ years	
	Stairs - Concrete	South Stair	150	LF	7	10+ years	
	Walls - Concrete Block	South Stair	2,350	SF	7	10+ years	
Vertical (	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	2-5 years	Damaged finishes

Campus Name: Smith Page : 27 of 30 Assessment Date: 09/23/2021





Category : Site **Building: Site** 

atego	ry : Site	Building : Site							
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
vil/Drai	nage								
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	7	6-10 years			
	Civil/ Drainage - Site Drain	Entire Site	1	EA	7	6-10 years			
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	7	6-10 years			
	3					,			
encing									
	Fencing - Chain Link	Entire Site	856	LF	6	6-10 years			
	Fencing - New Standard Ornamental	Entire Site	416	LF	6	6-10 years			
	Fencing - New Standard Ornamental	Entire Site	121	LF	4	0-1 year	At Entrances #8/#9: Fence needs		
	-					•	Scrape/Paint/Repair		
andscaı	ne.								
лизиа	Benches	Entire Site	6	EA	7	6-10 years			
	Benches	Entire Site	1	EA	5	1-2 years	Wood Bench - Rotted		
	Landscape - Grass	Entire Site	38,970	SF	6	10+ years			
	Landscape - Hardscape- Asphalt	Entire Site	2,043	SF	7	10+ years			
	Landscape - Hardscape- Asphalt	Entire Site	500	SF	5	1-2 years	Crack Creep -Through Out		
	Landscape - Hardscape- Concrete	Entire Site	10,000	SF	7	10+ years	orden Groop Timough Gut		
	Landscape - Hardscape- Concrete	Entire Site	540	SF	4	1-2 years	Concrete Cracked		
	Landscape - Hardscape- Pavers	Entire Site	200	SF	7	6-10 years	000.0.0		
	Lighting - Pole Mounted	Entire Site	2	EA	7	6-10 years			
	Parkway trees	Entire Site	24	EA	7	10+ years			
	Planting Beds/ Area	Entire Site	120	SF	7	6-10 years			
	Trash Receptacles	Entire Site	3	EA	6	6-10 years			
	Trasii Neceptacies	Entire Oile	0		O	o to years			
arking L									
	Concrete Curbs	Entire Site	1,028	LF	6	6-10 years			
	Interior Plantings	Entire Site	17	LF	7	10+ years			
	Surface - Asphalt	Entire Site	3,456	SF	6	2-5 years			
	Surface - Asphalt	Entire Site	144	SF	4	1-2 years	Asphalt - Damaged/Failing		
	Trash Enclosure - Chain Links	Entire Site	475	SF	6	6-10 years			
aygrou	nd								
<del> , g. ou</del>	Equipment - Pre K 3-5	West	1	EA	7	6-10 years			
	Equipment - School Age 5-12	West	1	EA	7	6-10 years			
	Surface - Poured Surface	West	4,450	SF	7	6-10 years			
			1,100		-	, <b>,</b>			
dewalk									
	Sidewalks - Internal Walks	Internal Sidewalks	750	LF	5	6-10 years			
			0.405	0.	^	0.40			
	Sidewalks - Perimeter Sidewalks Sidewalks - Perimeter Sidewalks	South South	2,465 25	SF SF	6 5	6-10 years 1-2 years	Sidewalk Damaged		

Campus Name: Smith Page : 28 of 30 Assessment Date: 09/23/2021



Catego	Category : Site			uilding				
Group	Item - Type Location		Quantity	UOM	Rank	Recommend Replacement	Comments	
Signage								
	Flag Pole - Flag Pole	Entire Site	1	EA	5	1-2 years	Repaired per Site Engineer	
	Marquee - Free Standing Back Lighted	Entire Site	2	EA	6	6-10 years		
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	6-10 years		
	Monument - Sign	Entire Site	1	EA	7	6-10 years		

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Smith Page: 29 of 30 Assessment Date: 09/23/2021

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

Classicom Guilliary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	michaea coage	Noom Location	Humbon	Hamboi	(0.)	Alou	Alou	Clop	Doura
Computer Lab	Computer Lab	2nd Floor	219	219	884	216	20	N	N
Counseling Room	Regular Classroom	2nd Floor	222	222	884	216	20	N	N
Kindergarten	Kindergarten	1st Floor	119	119	1,177	216	20	N	N
Kindergarten	Kindergarten	1st Floor	120	120	1,177	288	72	N	N
Music Room	Regular Classroom	2nd Floor	208	208	884	216	20	N	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	884	216	20	N	N
Regular Classroom	Regular Classroom	1st Floor	111	111	884	216	20	N	N
Regular Classroom	Regular Classroom	1st Floor	113	113	884	216	24	N	N
Regular Classroom	Regular Classroom	1st Floor	114	114	884	216	20	N	N
Regular Classroom	Regular Classroom	1st Floor	115	115	884	216	20	N	N
Regular Classroom	Regular Classroom	1st Floor	116	116	884	215	20	N	N
Regular Classroom	Regular Classroom	1st Floor	118	117/118	1,177	288	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	872	216	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	884	216	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	884	216	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	557	90	14	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	884	216	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	884	216	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	884	216	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	884	216	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	884	216	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	884	216	20	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	215	215	884	216	20	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	216	216	884	216	20	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	217	884	216	20	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	218	218	884	216	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	221	221	850	145	19	N	N
Regular Classroom	Regular Classroom	2nd Floor	224	224	884	216	20	N	N
Store Room	Science Lab Level 2	2nd Floor	220	220	1,081	216	20	N	N
Vacant	Regular Classroom	2nd Floor	206	206	884	216	20	N	N