

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1930	4	248,453
Campus Total			248,453

Category : Exterior			В	uilding			
0	No	Leader	Owentites		Daula	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ							
	Cell Equipment - Antenna	North Roof	1	EA	7	10+ years	
	Cell Equipment - Cabinets	North Roof	1	EA	7	10+ years	
Entrance	2						
	Exterior Doors - Exterior Wood Door	#A W	4	EA	6	10+ years	
	Exterior Stairs - Concrete	#A W	133	LF	7	10+ years	Separated out damaged areas
	Exterior Stairs - Concrete	#A W	2	LF	5	1-2 years	Spalled
	Stair Handrail - Steel_Stair Handrail	#A W	50	LF	7	10+ years	
	Entrance Control - Audio and Video	#B W	1	EA	7	10+ years	
	Exterior Doors - Exterior AMP Door	#B W	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#B W	90	LF	7	10+ years	
	Power Door Operator and Controls	#B W	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#B W	84	LF	6	10+ years	
	Ramps - Concrete	#B W	42	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#B W	40	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#C W	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#C W	306	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#C W	102	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#D W	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#D W	225	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#D W	80	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#E E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#E E	72	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#E E	30	LF	6	10+ years	



atego	ry : Exterior		В	Building : Main			
-				U		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Exterior Doors - Exterior Steel Door	#E.5 Exit E Basement level	2	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#E.5 Exit E Basement level	30	LF	6	10+ years	Not previously assessed
	Ramps - Concrete	#E.5 Exit E Basement level	30	LF	7	10+ years	Not previously assessed
	Entrance Control - Audio and Video	#F E	1	EA	7	10+ years	. ,
	Exterior Doors - Exterior AMP Door	#F E	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#F E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#F E	90	LF	7	10+ years	
	Power Door Operator and Controls	#F E	1	ĒA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#F E	100	LF	6	10+ years	
	Ramps - Concrete	#F E	50	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#F E	30	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#G E	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#G E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#G E	60	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#G E	30	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#H Exit E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#H Exit E	72	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#H Exit E	30	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	#H.5 E	1	EA	6	10+ years	
	Door		-		-	2	
	Exterior Doors - Exterior FRP Door	#I N	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#J N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#J N	72	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#J N	30	LF	6	6-10 years	No issues observed
	Exterior Doors - Exterior Steel Door	Main Roof North	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Main Roof South	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Main Roof center	1	EA	6	10+ years	
oundati	ion						
	Foundation - Concrete	Entire Building	1,930	LF	7	10+ years	
	Foundation - Concrete	Entire Building	50	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	248,453	SF	7	10+ years	
ghting							
- 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	37	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	20	EA	7	6-10 years	
			20		·	5.0,00.0	
oof Sys		Main Dalat	400			10	
	Coping - Metal	Main Roof	102	LF	7	10+ years	
	Coping - Terra Cotta	Main Roof	783	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	40	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	370	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	368	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet < 16" Height	Main Roof	148	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	368	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	21,403	SF	7	10+ years	
	Roof Structure - Concrete	Main Roof	21,403	SF	7	10+ years	
	Access Ladder - Metal	North Roof	2	EA	7	10+ years	
	Access Ladder - Wood	North Roof	- 1	EA	4	1-2 years	Too short, not secured
	Chimney - Brick Chimney- Concrete/ Mortar	North Roof	30	LF	7	10+ years	
	Liner		00			ior youro	
	Chimney - Brick Chimney- Concrete/ Mortar	North Roof	42	LF	7	10+ years	
	Liner		72	-	'	Tor years	
	Coping - Terra Cotta	North Roof	598	LF	7	10+ years	
	Downspouts - Interior Downspouts	North Roof	225	LF	7	10+ years	
	Parapet - 16" - 30" Height	North Roof	149	LF	7	10+ years	
	Parapet - Parapet > 30"	North Roof	449	LF	7		
						10+ years	
	Roof - Modified Bitumen	North Roof	21,131	SF	7	10+ years	
	Roof Hatch - Metal	North Roof	1	EA SF	7	10+ years	
	Roof Structure - Concrete	North Roof	21,131		7	10+ years	
	Access Ladder - Metal	South Roof	1	EA	7	10+ years	— • •
	Access Ladder - Metal	South Roof	1	EA	4	1-2 years	Too short
	Access Ladder - Wood	South Roof	1	EA	4	1-2 years	Missing rung, too short
	Coping - Terra Cotta	South Roof	630	LF	7	10+ years	
	Downspouts - Exterior Downspouts	South Roof	40	LF	7	10+ years	
	Downspouts - Interior Downspouts	South Roof	225	LF	7	10+ years	
	Parapet - 16" - 30" Height	South Roof	157	LF	7	10+ years	
	Parapet - Parapet > 30"	South Roof	473	LF	7	10+ years	
	Roof - Metal	South Roof	140	SF	7	10+ years	
	Roof - Modified Bitumen	South Roof	22,746	SF	7	10+ years	
	Roof Hatch - Metal	South Roof	1	EA	7	10+ years	
	Roof Structure - Concrete	South Roof	22,886	SF	7	10+ years	
Valls							
	Canopy - Fabric	Entire Building	164	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	440	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	92,992	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,190	SF	7	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	3,489	SF	7	10+ years	
			-,			, e e e e e e e e e e e e e e e e e e e	
Vindows							
	Guard - Guards perforated	Entire Building	5,037	SF	7	10+ years	
	Guard - Guards wire guard	Entire Building	3,269	SF	7	10+ years	
	Guard - Guards wire guard	Entire Building	396	SF	7	10+ years	
	Lintels - Steel	Entire Building	141	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	2,219	LF	7	10+ years	
	Skylite - Glass Double-Pane	Entire Building	2,831	SF	7	10+ years	
	-	5				2	



Catego	Category : Exterior				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Windows - Decorative	Entire Building	396	SF	7	10+ years	
	Windows - Louver	Entire Building	400	SF	7	10+ years	Not previously assessed
	Windows - Sash Aluminum	Entire Building	64	SF	7	10+ years	Com
	Windows - Sash Aluminum	Entire Building	275	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	23,577	SF	7	10+ years	

Catego	ry : Electrical	B	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch Security System - CCTV	Electrical Room Entire Building	1 248,453	EA SF	6 6	10+ years 6-10 years	
	Security System - Intrusion Detection	Entire Building	248,453	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	15	EA	6	6-10 years	Building is equipped with an ATS and independent electrical service for emergency power, hence Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Exit Signs - Corridors and Stairs	Entire Building	35	EA	6	6-10 years	Building is equipped with an ATS and independent electrical service for emergency power, hence Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Exit Signs - Gym	Entire Building	1	EA	7	6-10 years	Quantity changed as total has been divided/aggregated. Building is equipped with an ATS and independent electrical service for emergency power, hence Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	Signs are appropriately visible and substantially equivalent to standard exit signs, although the sign face lettering is hand-painted. Building is equipped with an ATS and independent electrical service for emergency power, hence Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Exit Signs - Lunchroom	Entire Building	2	EA	7	6-10 years	Building is equipped with an ATS and



atego	ry : Electrical		В	uilding	: Main		
	No		0			Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments independent electrical service for
	Exit Signs - Pool	Entire Building	1	EA	7	6-10 years	emergency power, hence Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. Building is equipped with an ATS ar
	J	J				,	independent electrical service for emergency power, hence Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	3	EA	2	0-1 year	Vintage equipment that is inoperative and not maintained. Obsolete and abandoned in place. Priority Rep adjusted based on current observations and per review with Building Engineer.
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	1	EA	2	0-1 year	Vintage equipment that is inoperativand not maintained. Obsolete and abandoned in place.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	2	0-1 year	Vintage equipment that is inoperative and not maintained. Obsolete and abandoned in place. Priority Rep adjusted based on current observations and per review with Building Engineer.
	Emergency Battery Packs - Gym	Entire Building	2	EA	2	0-1 year	Vintage equipment that is inoperati and not maintained. Obsolete and abandoned in place. Priority Rep adjusted based on current observations and per review with Building Engineer.
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	6,421	SF	7	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	34,935	SF	7	10+ years	
	Emergency A/C Power - Gym	Entire Building	13,506	SF	7	10+ years	Includes East and West Gymnasia
	Emergency A/C Power - Lunchrooms	Entire Building	4,175	SF	7	10+ years	
	Emergency A/C Power - Pool	Entire Building	3,346	SF	7	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	4,695	SF	7	10+ years	
ain Se							
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Consists of one section. Minor rusting at bottom of housing.
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Consists of four sections. Lower area of exterior housing shows signs of considerable corrosion/oxidation, however based on current observations and per review with Building Engineer, the equipment is fully operational and reliable, has been subject to numerous upgrades over its time in service, and the rusted housing does not affect the overall integrity of the equipment. Rank, Reason and Priority Rep adjusted accordingly.
	PA System	Entire Building	248,453	SF	6	6-10 years	, 0,
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	10+ years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - 100 A	Entire Building	9	EA	6	2-5 years	00 0
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Empty breaker slot exposing open terminals and presenting a live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Empty breaker slot exposing open terminals and presenting a live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Empty live fuse sockets expose live conductors and present a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	26	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	Older panels but based on current observations and per review with Building Engineer, they are fully operational and experience no lack of integrity. Rank, Reason and Priority Rep adjusted accordingly.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Empty breaker slot (covered with tape) exposing open terminals and presenting a live front condition.



Catego	ry : Electrical		В	uilding	: Main		
	-			-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Empty breaker slot exposing open terminals and presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Quantity changed based on current observations.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	Quantity changed to match current observations. Older panel but per review with Building Engineer, it is fully operational and experiences no lack of integrity. Rank, Reason and Priority Rep adjusted accordingly.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	6	6-10 years	Quantity changed based on current observations.
	Main Distribution Panels - Less than 400 amp	Entire Building	4	EA	6	6-10 years	Quantity changed to match current observations. Older panels but per review with Building Engineer, they are fully operational and experience no lack of integrity. Rank, Reason and Priority Rep adjusted accordingly.

Catego	Category : Fire Protection			Building : Main			
Group Fire Alar	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Fire Alarm Panel	Basement	1	EA	3	2-5 years	Older panel that passes inspection and is functional, however it employs antiquated technology, is not able to be upgraded, and is approaching the end of its anticipated service life. Rank and Reason changed to match current observations.
	Fire Alarm Strobe Lights	Basement	248,453	SF	4	0-1 year	Building is severely underserved, especially with regard to the classrooms with approximately half of them not equipped with strobes.
	Fire Alarm_System	Basement	248,453	SF	4	2-5 years	Older system that passes inspection and is functional, however it employs



Category : Fire Protection	Building : Main				
Group Item - Type	Location	Quantity I	UOM Rank	Recommend Replacement	Comments
	2004.000	quantity		nophooment	antiquated technology, is not able to be upgraded, and is approaching the end of its anticipated service life. Reason and Priority Rep changed to match current observations.

Catego	y : Mechanical		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ling Systems		,				
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Mechanical Room	1	EA	5	6-10 years	Serves auditorium.
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room 1	1	EA	5	6-10 years	AHU-1, serves southwest parts of the building.
	Air Intake	Mechanical Room 1	1	EA	6	6-10 years	Shares with AHU-4. OA dampers respond to the pneumatic control system.
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room 1	1	EA	5	6-10 years	Based on current observations and per review with Building Engineer, repairs have been made since last assessment. Rank, Reason and Priority Rep adjusted accordingly. Quantity changed to match current observations.
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room 1	5	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room 1	100	LF	7	10+ years	
	Zone Dampers	Mechanical Room 1	14	EA	5	6-10 years	Quantity changed to match current observations. Damper actuators do not respond to the pneumatic temperature control system and are manually adjusted throughout the building. Based on current observations and per review with Building Engineer, all dampers are functional; Priority Rep adjusted accordingly.
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room 2	1	EA	5	6-10 years	AHU-2, serves auditorium. Item Type changed to match current observations.OA dampers respond to the pneumatic control system. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Air Intake	Mechanical Room 2	1	EA	6	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room 2	1	EA	6	6-10 years	Filter bank installed since last assessment.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room 2	25	LF	6	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room 3	1	EA	5	6-10 years	AHU-3, serves lunchroom and associated spaces.
	Air Intake	Mechanical Room 3	1	EA	6	6-10 years	Shares with AHU-4. OA dampers respond to the pneumatic control system. Rank, Reason and Priority Rep adjusted based based on current observations and per review with Building Engineer.
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room 3	1	EA	6	6-10 years	Based on current observations and per review with Building Engineer, repairs have been made since last assessment. Rank, Reason and Priority Rep adjusted accordingly. Filter bank installed since last assessment.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room 3	100	LF	7	10+ years	
	Zone Dampers	Mechanical Room 3	8	EA	5	6-10 years	Damper actuators do not respond to the pneumatic temperature control system and are manually adjusted throughout the building. Based on current observations and per review with Building Engineer, all dampers are functional; Priority Rep adjusted accordingly.
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room 4	1	EA	5	6-10 years	AHU-4, serves southeast parts of the building.
	Air Intake	Mechanical Room 4	1	EA	6	6-10 years	Shares with AHU-3. OA dampers respond to the pneumatic control system.
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room 4	1	EA	6	6-10 years	Based on current observations and per review with Building Engineer, repairs have been made since last assessment. Rank, Reason and Priority Rep adjusted accordingly.
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room 4	5	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room 4	166	LF	7	10+ years	
	Zone Dampers	Mechanical Room 4	25	EA	5	6-10 years	Quantity changed to match current



Catego	ategory : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments observations. Damper actuators do not respond to the pneumatic temperature control system and are manually adjusted throughout the building. Based on current observations and per review with Building Engineer, all dampers are functional; Priority Rep adjusted accordingly.
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room 5	1	EA	5	6-10 years	AHU-5, serves northeast parts of the building. Item Type (Group Attribute 4) changed to match current observations.
	Air Intake	Mechanical Room 5	1	EA	5	6-10 years	Shares with AHU-8. OA dampers respond to the pneumatic control system.
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room 5	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room 5	6	EA	6	6-10 years	Quantity changed to match current observations.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room 5	100	LF	7	10+ years	
	Zone Dampers	Mechanical Room 5	22	EA	5	6-10 years	Quantity changed to match current observations. Damper actuators do not respond to the pneumatic temperature control system and are manually adjusted throughout the building. Based on current observations and per review with Building Engineer, all dampers are functional; Priority Rep adjusted accordingly.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room 6	1	EA	5	6-10 years	AHU-6, serves west gym, pool area, and associated spaces.
	Air Intake	Mechanical Room 6	1	EA	6	6-10 years	Shares with AHU-7. OA dampers respond to the pneumatic control system. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room 6	1	EA	6	6-10 years	Filter bank installed since last assessment.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room 6	100	LF	7	10+ years	
	Zone Dampers	Mechanical Room 6	10	EA	5	6-10 years	Damper actuators do not respond to



Catego	ry : Mechanical		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments the pneumatic temperature control system and are manually adjusted throughout the building. Based on current observations and per review with Building Engineer, all dampers are functional; Priority Rep adjusted accordingly.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Mechanical Room 7	1	EA	5	6-10 years	AHU-7, serves east gym and associated spaces.
	Air Intake	Mechanical Room 7	1	EA	6	6-10 years	Shares with AHU-6. OA dampers respond to the pneumatic control system. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room 7	1	EA	5	6-10 years	Filter bank installed since last assessment.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room 7	100	LF	7	10+ years	
	Zone Dampers	Mechanical Room 7	13	EA	5	6-10 years	Damper actuators do not respond to the pneumatic temperature control system and are manually adjusted throughout the building. Based on current observations and per review with Building Engineer, all dampers are functional; Priority Rep adjusted accordingly.
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room 8	1	EA	5	6-10 years	AHU-8 serves northwest parts of the building.
	Air Intake	Mechanical Room 8	1	EA	6	6-10 years	Shares with AHU-5. OA dampers respond to the pneumatic control system and have been upgraded since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room 8	1	EA	5	6-10 years	Based on current observations and per review with Building Engineer, repairs have been made since last assessment. Rank, Reason and Priority Rep adjusted accordingly.
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room 8	3	EA	6	6-10 years	, , . ,
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room 8	100	LF	7	10+ years	



Building : Main Category : Mechanical Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments and Ducts Mechanical Room 8 ΕA 5 Zone Dampers 12 6-10 years Damper actuators do not respond to the pneumatic temperature control system and are manually adjusted throughout the building. Based on current observations and per review with Building Engineer, all dampers are functional; Priority Rep adjusted accordingly. Boiler Systems Boiler Auxiliary- Steam Boiler - Greater than Boiler Room 3 ΕA 6 6-10 years 200 HP **Chemical Feed System** Boiler Room 1 ΕA 6 6-10 years 3 ΕA 6 Combustion Dampers Boiler Room 6-10 vears Condensate Pump Boiler Room 7 FΑ 6 6-10 years Feed Water Pumps and Tank Boiler Room 1 FΑ 4 0-1 year No signs of pumps leaking at the time of assessment. Tank insulation is damaged, has multiple duct tape repairs, and contains material generally considered to require abatement ΕA Boiler Room 3 6 Vintage equipment with some signs Non Condensing- Water Tube- Flexible 6-10 years Tube- Force Draft- Steam Boiler - Greater of aging and deterioration, but verv than 200 HP well maintained over their service life with no loss of integrity. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. LF Piping - Condensate Pipe- Steel Boiler Room 1.000 5 6-10 years Vintage piping with signs of aging and deterioration, but very well maintained over its service life with no loss of integrity and no leaks. There are no signs of impending failure or breakdown. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. Piping - Steam Pipe- Steel Boiler Room 1.000 LF 5 6-10 years Vintage piping with signs of aging and deterioration, but very well maintained over its service life with no loss of integrity and no leaks. There are no signs of impending failure or breakdown. Rank, Reason



Catego	ry : Mechanical		В	uilding	: Main		039 N Rimball AVENDE, Chicago, ie 60625
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Steam Traps	Boiler Room	170	EA	5	6-10 years	and Priority Rep adjusted based on current observations and per review with Building Engineer. Steam traps are well maintained and show no signs of impending breakdown. Priority Rep adjusted based on current observations and per review with Building Engineer.
Heating	Devices						
-	Radiators - Steam	Entire Building	76	EA	5	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	8	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	8	EA	5	2-5 years	Quantity changed to match current
							observations. Units are aged and some may be operational but have not generally been in service.
	Unit Heater - Electric	Entire Building	1	EA	6	2-5 years	C
	Unit Heater - Steam	Entire Building	3	EA	6	2-5 years	
	Fin Tube - Steam	Entire Building	85	LF	6	6-10 years	
Tempera	ature Control						
•	Electric Thermostat	Entire Building	3	EA	6	6-10 years	Control the unit heaters.
	Electric Thermostat	Entire Building	4	EA	6	6-10 years	Choir Room thermostat dates to
					-	,	2018.
	Pneumatic System	Entire Building	248,453	SF	4	1-2 years	Based on current observations and per detailed review with the Building Engineer, the pneumatic system is operational for AHU OA dampers but is in a failure mode for all thermostats. Reason and Priority Rep adjusted accordingly.
	Thermostats - Pneumatic	Entire Building	103	EA	4	0-1 year	All pneumatic thermostats throughout the building are vintage equipment, are nonfunctional, do not respond to the pneumatic control system, are contaminated with oil, and are irreparable.
	Thermostats - Pneumatic	Entire Building	1	EA	4	0-1 year	Cover missing. Vintage equipment and nonfunctional; does not respond to the pneumatic control system, is contaminated with oil, and is irreparable.



Group							
-	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
/entilatio	, , , , , , , , , , , , , , , , , , ,	Location	Quantity		Nalik	Replacement	Comments
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	4	0-1 year	Vintage unit not directly accessible a safe manner at the time of assessment due to unreliable mean of climbing and crawling in the attic space. No audible evidence of normal operation.
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Mounted on north facade.
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Located in kitchen.
	Exhaust Fans- Indoor - Greater than 8000 CFM	Entire Building	1	EA	4	1-2 years	Vintage unit not directly accessible a safe manner at the time of assessment due to unreliable mean of climbing and crawling in the attic space. Audible evidence of abnorm operation.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	8	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	5	6-10 years	Units have been upgraded since la assessment; Priority Rep adjusted based on current observations and per review with Building Engineer.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Quantity changed as total has beer divided/aggregated.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression.
Categor	y : Plumbing		В	uilding	: Main		
			.			Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate				Ξ.	•	10	
	Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room Boiler Room	2 4	EA EA	6 7	10+ years 10+ years	
Piping							
_iping	Domestic Piping-Hot Water Return Lines	Entire Building	248,453	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	248,453	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to			SF			
	Fixtures	Entire Building	248,453	35	6	10+ years	



Friedrich W von Steuben Metropolitan Science HS

5039 N Kimball AVENUE, Chicago, IL 60625 **Category : Plumbing Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Domestic Piping-Hot/Cold Water Supply Entire Building 248.453 SF 6 10+ vears (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply Entire Building 238.453 SF 6 10+ years (Risers) Domestic Piping-Hot/Cold Water Supply Entire Building 248,453 SF 6 10+ years (from Risers to Fixtures) Sanitary Piping SF 6 Entire Building 248,453 10+ years SF Storm Piping Entire Building 248,453 6 10+ years Vent Piping Entire Building 248,453 SF 6 10+ years Pool Systems Pool Drain Piping Mechanical Room 25 LF 6 6-10 years Misidentified in previous assessment. Pool drain piping shows no signs of loss of integrity. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. Pool Filtration System including Pump Mechanical Room 1 ΕA 6 6-10 years Upgraded with new system components since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. Pool Hot Water Heater - Gas Fired Mechanical Room ΕA 6 Installed in 2018. 1 10+ vears Pool Supply and Return Piping Mechanical Room 100 LF 6 10+ years Quantity changed as total has been divided/aggregated. Pumps Pumps - Domestic Booster Pump-Duplex Basement 1 FΑ 7 6-10 vears Pumps - Ejector-Duplex Basement 1 FΑ 6 6-10 years Pumps - Sump-Duplex ΕA Basement 1 6 6-10 years Located in the space beneath the boiler room. Pumps - Sump-Duplex 4 ΕA 6 Basement 6-10 years Pumps - Sump-Simplex Basement 2 EΑ 6 6-10 years Located at the bottom of the elevator pit for both the freight and passenger elevators. Inaccessible at the time of assessment. Condition and functionality verified by the Building Engineer.



Friedrich W von Steuben Metropolitan Science HS

5039 N Kimball AVENUE, Chicago, IL 60625

Building : Main Category : Room Recommend **Replacement** Comments Group Item - Type Location Quantity UOM Rank Administrative Suites/Offices Ceiling - Lay-in 90 SF 6 110 B 10+ years Doors - Wood Doors inclu hw 110 B 1 ΕA 7 10+ years Floor - Wood 90 SF 6 110 B 10+ years Lighting - Lay-in 2 ΕA 6 6-10 years 110 B 7 Power Distribution 110 B 6 FΑ 10+ years Walls - Plaster/Drvwall 110 B 224 SF 6 10+ years SF Ceiling - Lay-in 111C Office 120 6 10+ years Doors - Wood Doors inclu hw ΕA 7 111C Office 10+ vears 1 Floor - Carpet 111C Office 120 SF 6 6-10 years Lighting - Lay-in 111C Office ΕA 6 2 6-10 years **Power Distribution** 111C Office 4 EΑ 7 10+ years Walls - Plaster/Drvwall 111C Office SF 352 6 10+ vears Ceiling - Lav-in SF 119 422 7 10+ years Doors - Wood Doors inclu hw 2 ΕA 7 119 10+ vears Floor - Carpet 119 422 SF 6 6-10 years 7 Lighting - Lay-in 119 9 FΑ 6-10 years 8 **Power Distribution** 119 ΕA 7 10+ years SF 7 Walls - Plaster/Drywall 119 945 10+ years Ceiling - Plaster/Drywall 200 Nurse's Office SF 159 6 10+ years Doors - Wood Doors inclu hw 200 Nurse's Office 1 ΕA 7 10+ years Floor - Concrete Epoxy/ Painted 200 Nurse's Office 159 SF 7 10+ vears Lighting - Pendent/Surface 200 Nurse's Office 2 FΑ 6 6-10 years Power Distribution 6 ΕA 7 200 Nurse's Office 10+ vears Walls - Plaster/Drywall 200 Nurse's Office 690 SF 6 10+ years AC Unit ΕA 7 6-10 years 203A Conf. room 1 Construction, previous assessment data used Ceiling - Plaster/Drywall SF 6 203A Conf. room 167 10+ years Doors - Transom Window SF 7 10+ years 203A Conf. room 9 ΕA 7 Doors - Wood Doors inclu hw 203A Conf. room 1 10+ vears Floor - Concrete Epoxy/ Painted 203A Conf. room 167 SF 5 10+ years Lighting - Pendent/Surface 203A Conf. room 2 ΕA 6 6-10 years Power Distribution 203A Conf. room 4 EΑ 7 10+ years Storage/ Closet 203A Conf. room 12 SF 7 10+ years Walls - Plaster/Drywall 203A Conf. room 792 SF 6 10+ years 7 AC Unit 203B office 1 EΑ 6-10 years Construction, previous assessment data used Ceiling - Plaster/Drywall 203B office SF 6 113 10+ years SF Doors - Transom Window 203B office 9 7 10+ vears 10+ years Doors - Wood Doors inclu hw 203B office 1 ΕA 7 Floor - Tile 203B office 113 SF 10+ years 6 Lighting - Pendent/Surface 203B office 1 ΕA 6 6-10 years Power Distribution 203B office 4 ΕA 7 10+ years SF 7 Storage/ Closet 203B office 9 10+ years



Catego	ry : Room		В	uilding	: Main		-
	-			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	203B office	549	SF	6	10+ years	
	AC Unit	203C Counselor Office	1	EA	7	6-10 years	Construction, previous assessment data used
	Ceiling - Plaster/Drywall	203C Counselor Office	173	SF	6	10+ years	
	Doors - Wood Doors inclu hw	203C Counselor Office	1	EA	7	10+ years	
	Floor - Tile	203C Counselor Office	173	SF	6	10+ years	
	Lighting - Pendent/Surface	203C Counselor Office	2	EA	6	6-10 years	
	Power Distribution	203C Counselor Office	12	EA	7	10+ years	
	Storage/ Closet	203C Counselor Office	9	SF	7	10+ years	
	Walls - Plaster/Drywall	203C Counselor Office	650	SF	6	10+ years	
	AC Unit	208 Case Manager Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	208 Case Manager Office	402	SF	6	10+ years	
	Doors - Transom Window	208 Case Manager Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	208 Case Manager Office	1	EA	7	10+ years	
	Floor - Tile	208 Case Manager Office	402	SF	6	6-10 years	
	Lighting - Lay-in	208 Case Manager Office	6	EA	6	6-10 years	
	Power Distribution	208 Case Manager Office	7	EA	7	10+ years	
	Walls - Plaster/Drywall	208 Case Manager Office	624	SF	6	10+ years	
	Ceiling - Lay-in	208B office next to Faculty Toilet	111	SF	6	10+ years	Construction, previous assessment data used
	Doors - Transom Window	208B office next to Faculty Toilet	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	208B office next to Faculty Toilet	1	EA	7	10+ years	
	Floor - Wood	208B office next to Faculty Toilet	111	SF	6	10+ years	
	Lighting - Lay-in	208B office next to Faculty Toilet	2	ĒA	6	6-10 years	
	Power Distribution	208B office next to Faculty Toilet	4	EA	7	10+ years	
	Walls - Plaster/Drywall	208B office next to Faculty Toilet	470	SF	6	10+ years	
	Ceiling - Lay-in	213A Computer Equipment Rm	332	SF	7	10+ years	
	Doors - Transom Window	213A Computer Equipment Rm	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	213A Computer Equipment Rm	1	EA	7	10+ years	
	Floor - Tile	213A Computer Equipment Rm	332	SF	6	6-10 years	
	Lighting - Lay-in	213A Computer Equipment Rm	5	EA	6	6-10 years	
	Power Distribution	213A Computer Equipment Rm	6	EA	7	10+ years	
	Storage/ Closet	213A Computer Equipment Rm	39	SF	7	10+ years	
	Walls - Plaster/Drywall	213A Computer Equipment Rm	822	SF	6	10+ years	
	Ceiling - Lay-in	223B Office	147	SF	6	10+ years	
	Doors - Side-lite	223B Office	8	SF	7	10+ years	
	Doors - Side-lite	223B Office	8	SF	7	10+ years	
	Doors - Transom Window	223B Office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	223B Office	1	EA	7	10+ years	
	Floor - Tile	223B Office	147	SF	6	6-10 years	
	Lighting - Pendent/Surface	223B Office	2	EA	6	6-10 years	
	Power Distribution	223B Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	223B Office	658	SF	6	10+ years	
	Work Sink	223B Office	1	EA	7	10+ years	



Catego	ntegory : Room		Building : Main				
	-			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	223D East Gym office	149	SF	6	10+ years	
	Doors - Side-lite	223D East Gym office	40	SF	7	10+ years	
	Doors - Transom Window	223D East Gym office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	223D East Gym office	1	EA	7	10+ years	
	Floor - Wood	223D East Gym office	149	SF	6	10+ years	
	Lighting - Pendent/Surface	223D East Gym office	2	EA	6	6-10 years	
	Power Distribution	223D East Gym office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	223D East Gym office	600	SF	6	10+ years	
	Work SInk	223D East Gym office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	223F Office	120	SF	6	10+ years	
	Doors - Transom Window	223F Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	223F Office	1	EA	7	10+ years	
	Floor - Wood	223F Office	120	SF	6	10+ years	
	Lighting - Pendent/Surface	223F Office	2	EA	6	6-10 years	
	Power Distribution	223F Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	223F Office	549	SF	6	10+ years	
	AC Unit	226 Assistant Principal	1	EA	7	6-10 years	
	Ceiling - Lay-in	226 Assistant Principal	364	SF	6	10+ years	
	Doors - Transom Window	226 Assistant Principal	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	226 Assistant Principal	1	EA	7	10+ years	
	Floor - Wood	226 Assistant Principal	364	SF	6	10+ years	
	Lighting - Lay-in	226 Assistant Principal	6	EA	6	6-10 years	
	Power Distribution	226 Assistant Principal	10	EA	7	10+ years	
	Walls - Plaster/Drywall	226 Assistant Principal	800	SF	6	10+ years	
	Ceiling - Plaster/Drywall	275 Light and Sound	118	SF	6	10+ years	
	Ceiling - Plaster/Drywall	275 Light and Sound	7	SF	4	1-2 years	
	Doors - Steel Doors incl hw	275 Light and Sound	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	275 Light and Sound	125	SF	7	10+ years	
	Lighting - Pendent/Surface	275 Light and Sound	2	EA	6	6-10 years	
	Power Distribution	275 Light and Sound	6	EA	7	10+ years	
	Walls - Plaster/Drywall	275 Light and Sound	428	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd FIr West Gym office in Gym	104	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Flr West Gym office in Gym	1	EA	7	10+ years	
	Floor - Wood	2nd Flr West Gym office in Gym	104	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Flr West Gym office in Gym	2	EA	6	6-10 years	
	Power Distribution	2nd Flr West Gym office in Gym	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Flr West Gym office in Gym	410	SF	6	10+ years	
	Work SInk	2nd Flr West Gym office in Gym	1	EA	7	10+ years	
	Ceiling - Lay-in	307 Office in Lunchroom	120	SF	6	10+ years	Construction, previous assessment data used
	Doors - Side-lite	307 Office in Lunchroom	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	307 Office in Lunchroom	1	EA	7	10+ years	
	Floor - Tile	307 Office in Lunchroom	120	SF	6	10+ years	
	Lighting - Lay-in	307 Office in Lunchroom	1	EA	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		
	-					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Power Distribution	307 Office in Lunchroom	4	EA	7	10+ years	
	Walls - Plaster/Drywall	307 Office in Lunchroom	160	SF	6	10+ years	
	Walls - Structural Glazed Tile	307 Office in Lunchroom	160	SF	7	10+ years	
	AC Unit	308 Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	308 Office	365	SF	6	10+ years	
	Doors - Transom Window	308 Office	9	SF	7	10+ years	
	Doors - Transom Window	308 Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	308 Office	1	EA	7	10+ years	
	Floor - Terrazzo	308 Office	7	SF	6	10+ years	
	Floor - Tile	308 Office	358	SF	6	6-10 years	
	Lighting - Lay-in	308 Office	6	EA	6	6-10 years	
	Power Distribution	308 Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	308 Office	800	SF	6	10+ years	
	Walls - Structural Glazed Tile	308 Office	276	SF	7	10+ years	
	Ceiling - Lay-in	308B Assistant Principal	140	SF	7	10+ years	
	Doors - Transom Window	308B Assistant Principal	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	308B Assistant Principal	1	EA	7	10+ years	
	Floor - Tile	308B Assistant Principal	140	SF	6	6-10 years	
	Lighting - Lay-in	308B Assistant Principal	2	EA	6	6-10 years	
	Power Distribution	308B Assistant Principal	4	EA	7	10+ years	
	Walls - Plaster/Drywall	308B Assistant Principal	480	SF	6	10+ years	
	Ceiling - Lay-in	313B office in 313	166	SF	6	10+ years	Construction, previous assessment data used
	Ceiling - Lay-in	313B office in 313	4	SF	4	1-2 years	Water damage
	Doors - Side-lite	313B office in 313	30	SF	7	10+ years	ů.
	Doors - Wood Doors inclu hw	313B office in 313	1	EA	7	10+ years	
	Floor - Tile	313B office in 313	170	SF	6	10+ years	
	Lighting - Lay-in	313B office in 313	3	EA	6	6-10 years	
	Power Distribution	313B office in 313	4	EA	7	10+ years	
	Walls - Plaster/Drywall	313B office in 313	470	SF	6	10+ years	
	Walls - Plaster/Drywall	313B office in 313	10	SF	4	0-1 year	Water damage
	Work SInk	313B office in 313	1	EA	7	6-10 years	0
	Ceiling - Lay-in	315A Stor./Office in 315	170	SF	6	10+ years	Construction, previous assessmen data used
	Doors - Side-lite	315A Stor./Office in 315	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	315A Stor./Office in 315	1	EA	7	10+ years	
	Floor - Tile	315A Stor./Office in 315	170	SF	6	10+ years	
	Lighting - Lay-in	315A Stor./Office in 315	3	EA	6	6-10 years	
	Power Distribution	315A Stor./Office in 315	4	EA	7	10+ years	
	Walls - Plaster/Drywall	315A Stor./Office in 315	480	SF	6	10+ years	
	Work SInk	315A Stor./Office in 315	2	EA	7	6-10 years	
	AC Unit	Rm 103A- Engineer Office	- 1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Rm 103A- Engineer Office	138	SF	6	10+ years	
	Doors - Side-lite	Rm 103A- Engineer Office	24	SF	7	10+ years	



Category : Room

Building : Main

Catego	ry : Room		D	unaing	: wain		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	Rm 103A- Engineer Office	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 103A- Engineer Office	1	EA	7	10+ years	
	Floor - Tile	Rm 103A- Engineer Office	138	SF	6	10+ years	
	Lighting - Pendent/Surface	Rm 103A- Engineer Office	2	EA	6	6-10 years	
	Power Distribution	Rm 103A- Engineer Office	4	EA	7	10+ years	
	Storage/ Closet	Rm 103A- Engineer Office	12	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 103A- Engineer Office	534	SF	6	10+ years	
	AC Unit	Rm 103B- Asst Engineer Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Rm 103B- Asst Engineer Office	112	SF	6	10+ years	
	Doors - Side-lite	Rm 103B- Asst Engineer Office	24	SF	7	10+ years	
	Doors - Transom Window	Rm 103B- Asst Engineer Office	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 103B- Asst Engineer Office	1	EA	7	10+ years	
	Floor - Tile	Rm 103B- Asst Engineer Office	112	SF	6	10+ years	
	Lighting - Pendent/Surface	Rm 103B- Asst Engineer Office	2	EA	7	6-10 years	
	Power Distribution	Rm 103B- Asst Engineer Office	4	EA	7	10+ years	
	Storage/ Closet	Rm 103B- Asst Engineer Office	12	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 103B- Asst Engineer Office	534	SF	6	10+ years	
	Ceiling - Lay-in	Rm 108- Security Office- 1st flr	134	SF	6	10+ years	
	Doors - Transom Window	Rm 108- Security Office- 1st flr	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 108- Security Office- 1st flr	1	EA	7	10+ years	
	Floor - Tile	Rm 108- Security Office- 1st flr	134	SF	6	10+ years	
	Lighting - Lay-in	Rm 108- Security Office- 1st flr	2	EA	6	6-10 years	
	Power Distribution	Rm 108- Security Office- 1st flr	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 108- Security Office- 1st flr	423	SF	6	10+ years	
	AC Unit	Rm 109- Counselors Office- 1st flr	1	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 109- Counselors Office- 1st flr	223	SF	6	10+ years	
	Doors - Transom Window	Rm 109- Counselors Office- 1st flr	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 109- Counselors Office- 1st flr	1	EA	7	10+ years	
	Floor - Carpet	Rm 109- Counselors Office- 1st flr	216	SF	6	6-10 years	
	Floor - Terrazzo	Rm 109- Counselors Office- 1st flr	7	SF	6	10+ years	
	Lighting - Lay-in	Rm 109- Counselors Office- 1st flr	4	EA	6	6-10 years	
	Power Distribution	Rm 109- Counselors Office- 1st flr	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 109- Counselors Office- 1st flr	334	SF	6	10+ years	
	Ceiling - Lay-in	Rm 109A- Counselor- 1st flr	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 109A- Counselor- 1st flr	1	EA	7	10+ years	
	Floor - Carpet	Rm 109A- Counselor- 1st flr	100	SF	6	6-10 years	
	Lighting - Lay-in	Rm 109A- Counselor- 1st flr	3	ĒA	6	6-10 years	
	Power Distribution	Rm 109A- Counselor- 1st flr	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 109A- Counselor- 1st flr	404	SF	6	10+ years	
	Ceiling - Lay-in	Rm 109B- Counselor- 1st flr	167	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 109B- Counselor- 1st flr	1	EA	7	10+ years	
			407			,	

Floor - Carpet

Lighting - Lay-in

Power Distribution

2

2

SF

ΕA

ΕA

167

6

6

7

6-10 years

6-10 years

10+ years

Rm 109B- Counselor- 1st flr

Rm 109B- Counselor- 1st flr

Rm 109B- Counselor- 1st flr



Category : Room

Group

Building : Main

SF

SF

ΕA

EΑ

SF

SF

ΕA

SF

ΕA

ΕA

SF

SF

ΕA

6

6

6

7

6

6

7

6

6

7

6

6

7

6-10 years

10+ years

6-10 years

10+ years

10+ years

10+ years

10+ years

6-10 years

6-10 years

10+ years

10+ years

10+ years

10+ years

466

7

7

4

626

120

120

352

120

1

1

2

4

Item - TypeLocationQuantityUOMRankReplacementConstantWalls - Plaster/DrywallRm 109B- Counselor- 1st flr258SF610+ yearsCeiling - Lay-inRm 109C- Counselor- 1st flr107SF610+ years	Comments
Ceiling - Lay-in Rm 109C- Counselor- 1st flr 107 SF 6 10+ years	
Doors - Wood Doors inclu hw Rm 109C- Counselor- 1st flr 1 EA 7 10+ years	
Floor - CarpetRm 109C- Counselor- 1st flr107SF66-10 years	
Lighting - Lay-in Rm 109C- Counselor- 1st flr 3 EA 6 6-10 years	
Power Distribution Rm 109C- Counselor- 1st flr 2 EA 7 10+ years	
Walls - Plaster/DrywallRm 109C- Counselor- 1st flr404SF610+ years	
AC Unit Rm 109D- Counselor- 1st flr 1 EA 7 6-10 years	
Ceiling - Lay-in Rm 109D- Counselor- 1st flr 120 SF 6 10+ years	
Doors - Wood Doors inclu hw Rm 109D- Counselor- 1st flr 1 EA 7 10+ years	
Floor - Carpet Rm 109D- Counselor- 1st flr 120 SF 6 6-10 years	
Lighting - Lay-in Rm 109D- Counselor- 1st flr 2 EA 6 6-10 years	
Power Distribution Rm 109D- Counselor- 1st flr 2 EA 7 10+ years	
Walls - Plaster/Drywall Rm 109D- Counselor- 1st flr 404 SF 6 10+ years	
Ceiling - Lay-in Rm 110- Student Services 724 SF 6 10+ years	
Doors - Transom Window Rm 110- Student Services 9 SF 7 10+ years	
Doors - Wood Doors inclu hw Rm 110- Student Services 2 EA 7 10+ years	
Floor - Terrazzo Rm 110- Student Services 7 SF 6 10+ years	
Floor - Wood Rm 110- Student Services 724 SF 6 10+ years	
Lighting - Lay-in Rm 110- Student Services 11 EA 6 6-10 years	
Power Distribution Rm 110- Student Services 10 EA 7 10+ years	
Walls - Plaster/Drywall Rm 110- Student Services 1,132 SF 6 10+ years	
Ceiling - Lay-in Rm 110A 90 SF 6 10+ years	
Doors - Wood Doors inclu hw Rm 110A 1 EA 7 10+ years	
Floor - Wood Rm 110A 90 SF 6 10+ years	
Lighting - Lay-in Rm 110A 2 EA 6 6-10 years	
Power Distribution Rm 110A 6 EA 7 10+ years	
Walls - Plaster/DrywallRm 110A224SF610+ years	
Ceiling - Lay-in Rm 111- Discipline office- 1st flr 473 SF 6 10+ years	
Doors - Transom Window Rm 111- Discipline office- 1st flr 18 SF 7 10+ years	
Doors - Wood Doors inclu hw Rm 111- Discipline office- 1st flr 2 EA 7 10+ years	

Rm 111- Discipline office- 1st flr

Rm 111A- Counselor Office- 1st Flr

Rm 111B- Asst Principal- 1st flr

Rm 111B- Asst Principal- 1st flr

Campus Name: Von Steuben HS

Floor - Carpet

Floor - Terrazzo

Lighting - Lay-in

Ceiling - Lay-in

Floor - Carpet

Lighting - Lay-in

Ceiling - Lay-in

Power Distribution

Walls - Plaster/Drywall

Power Distribution

Walls - Plaster/Drywall

Doors - Wood Doors inclu hw

Doors - Wood Doors inclu hw



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	Rm 111B- Asst Principal- 1st flr	120	SF	6	6-10 years	
	Lighting - Lay-in	Rm 111B- Asst Principal- 1st flr	2	EA	6	6-10 years	
	Power Distribution	Rm 111B- Asst Principal- 1st flr	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 111B- Asst Principal- 1st flr	352	SF	6	10+ years	
	AC Unit	Rm 112- Community Room- 1st flr	2	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 112- Community Room- 1st flr	815	SF	6	10+ years	
	Doors - Transom Window	Rm 112- Community Room- 1st flr	18	SF	7	10+ years	
	Doors - Transom Window	Rm 112- Community Room- 1st flr	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 112- Community Room- 1st flr	2	EA	7	10+ years	
	Floor - Terrazzo	Rm 112- Community Room- 1st flr	7	SF	6	10+ years	
	Floor - Wood	Rm 112- Community Room- 1st flr	808	SF	6	10+ years	
	Lighting - Lay-in	Rm 112- Community Room- 1st flr	14	EA	6	6-10 years	
	Power Distribution	Rm 112- Community Room- 1st flr	8	EA	7	10+ years	
	Storage/ Closet	Rm 112- Community Room- 1st flr	23	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 112- Community Room- 1st flr	1,406	SF	6	10+ years	
	AC Unit	Rm 113- Main Office- 1st Flr	1	ĒA	7	6-10 years	
	Ceiling - Lay-in	Rm 113- Main Office- 1st Flr	572	SF	6	10+ years	
	Doors - Side-lite	Rm 113- Main Office- 1st Flr	28	SF	7	10+ years	
	Doors - Transom Window	Rm 113- Main Office- 1st Flr	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 113- Main Office- 1st Flr	2	EA	7	10+ years	
	Floor - Carpet	Rm 113- Main Office- 1st Flr	310	SF	6	6-10 years	
	Floor - Tile	Rm 113- Main Office- 1st Flr	262	SF	6	10+ years	
	Lighting - Lay-in	Rm 113- Main Office- 1st Flr	12	EA	6	6-10 years	
	Lighting - Pendent/Surface	Rm 113- Main Office- 1st Fir	3	EA	6	6-10 years	
	Power Distribution	Rm 113- Main Office- 1st Flr	8	EA	7	10+ years	
	Storage/ Closet	Rm 113- Main Office- 1st Fir	5	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 113- Main Office- 1st Fir	1,214	SF	6		
	Ceiling - Lay-in	Rm 113A- Office- 1st Flr	1,214	SF	6	10+ years 10+ years	
	Doors - Wood Doors inclu hw	Rm 113A- Office- 1st Fir	107	EA	6 7	•	
				SF		10+ years	
	Floor - Carpet	Rm 113A- Office- 1st Flr	107		6	6-10 years	
	Lighting - Lay-in	Rm 113A- Office- 1st Flr	2	EA	6	6-10 years	
	Power Distribution	Rm 113A- Office- 1st Flr	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 113A- Office- 1st Flr	420	SF	6	10+ years	
	AC Unit	Rm 113D- Principal- 1st Flr	1	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 113D- Principal- 1st Flr	309	SF	6	10+ years	
	Doors - Side-lite	Rm 113D- Principal- 1st Flr	14	SF	7	10+ years	
	Doors - Transom Window	Rm 113D- Principal- 1st Flr	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 113D- Principal- 1st Flr	2	EA	7	10+ years	
	Floor - Carpet	Rm 113D- Principal- 1st Flr	309	SF	6	6-10 years	
	Lighting - Lay-in	Rm 113D- Principal- 1st Flr	6	EA	6	6-10 years	
	Power Distribution	Rm 113D- Principal- 1st Flr	6	EA	7	10+ years	
	Storage/ Closet	Rm 113D- Principal- 1st Flr	23	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 113D- Principal- 1st Flr	780	SF	6	10+ years	
	Ceiling - Lay-in	Rm 114B- Test Coordinators Office-	144	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main	_	
Group	Itom Tuno	Location	Quantity	UOM	Bonk	Recommend	Commonte
Group	Item - Type	1st flr	Quantity		Rank	Replacement	Comments
	Doors - Side-lite	Rm 114B- Test Coordinators Office- 1st flr	20	SF	7	10+ years	
	Doors - Transom Window	Rm 114B- Test Coordinators Office- 1st flr	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 114B- Test Coordinators Office- 1st flr	2	EA	7	10+ years	
	Floor - Tile	Rm 114B- Test Coordinators Office- 1st flr	144	SF	6	10+ years	
	Lighting - Lay-in	Rm 114B- Test Coordinators Office- 1st flr	1	EA	6	6-10 years	
	Power Distribution	Rm 114B- Test Coordinators Office- 1st flr	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 114B- Test Coordinators Office- 1st flr	475	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Rm 121C - PE Office	188	SF	6	10+ years	
	Doors - Side-lite	Rm 121C - PE Office	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 121C - PE Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Rm 121C - PE Office	188	SF	6	10+ years	
	Lighting - Pendent/Surface	Rm 121C - PE Office	2	EA	6	6-10 years	
	Power Distribution	Rm 121C - PE Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 121C - PE Office	361	SF	6	10+ years	
	Walls - Structural Glazed Tile	Rm 121C - PE Office	361	SF	7	10+ years	
	Ceiling - Splined	Rm 123A- Pool Office	58	SF	6	10+ years	
	Doors - Side-lite	Rm 123A- Pool Office	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 123A- Pool Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Rm 123A- Pool Office	58	SF	6	10+ years	
	Power Distribution	Rm 123A- Pool Office	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	Rm 123A- Pool Office	200	SF	6	10+ years	
	Ceiling - Lay-in	Rm 125A- PE Office	249	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 125A- PE Office	1	EA	7	10+ years	
	Floor - Tile	Rm 125A- PE Office	249	SF	6	10+ years	
	Lighting - Lay-in	Rm 125A- PE Office	4	EA	6	6-10 years	
	Power Distribution	Rm 125A- PE Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 125A- PE Office	667	SF	6	10+ years	
	AC Unit	Rm 126- Computer Dept classroom	1	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 126- Computer Dept classroom	494	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 126- Computer Dept classroom	1	EA	7	10+ years	
	Floor - Tile	Rm 126- Computer Dept classroom	494	SF	6	10+ years	
	Lighting - Pendent/Surface	Rm 126- Computer Dept classroom	12	EA	6	6-10 years	
	Power Distribution	Rm 126- Computer Dept classroom	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 126- Computer Dept classroom	885	SF	6	10+ years	
	AC Unit	Rm 126D- Copy/Workroom- Classroom	1	EA	7	6-10 years	



Group tem - Type Location Quantity UOM Rank Replacement Ceiing - Lay-in Rm 126D-Copy/Workroom- Classroom 497 SF 6 10+ years Doors - Wood Doors inclu hw Rm 126D-Copy/Workroom- Classroom 1 EA 7 10+ years Floor - Tile Rm 126D-Copy/Workroom- Classroom 497 SF 6 10+ years Lighting - Lay-in Rm 126D-Copy/Workroom- Classroom 497 SF 6 10+ years Power Distribution Rm 126D-Copy/Workroom- Classroom 8 EA 7 10+ years Ceiling - Plaster/Dywall Rm 127-Yearbook office 96 SF 6 10+ years Doors - Wood Doors inclu hw Rm 127-Yearbook office 9 SF 7 10+ years Doors - Transom Window Rm 127-Yearbook office 9 SF 6 10+ years Doors - Vood Doors inclu hw Rm 127-Yearbook office 8 EA 7 10+ years Doors - Vood Doors inclu hw Rm 127-Yearbook office 8 EA 7	Category : Room			В	uilding	: Main			
Ceiling - Lay-inRm 126D - Copy/Workroom- (Gastroom497SF610+ yearsDoors - Wood Doors inclu hwRm 126D - Copy/Workroom- Classroom1EA710+ yearsFloor - TileRm 126D - Copy/Workroom- Classroom497SF610+ yearsLighting - Lay-inRm 126D - Copy/Workroom- Classroom12EA66-10 yearsPower DistributionRm 126D - Copy/Workroom- Classroom8EA710+ yearsWalls - Plaster/DrywallRm 127- Yearbook office666SF610+ yearsCeiling - Plaster/DrywallRm 127- Yearbook office9SF710+ yearsDoors - Transom WindowRm 127- Yearbook office1EA710+ yearsDoors - Transom WindowRm 127- Yearbook office666SF610+ yearsDoors - Tilde Ceramic/ PorcelainRm 127- Yearbook office8EA710+ yearsPower DistributionRm 127- Yearbook office8EA610+ yearsWalls - Plaster/DrywallRm 127- Yearbook office8EA610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office8EA710+ yearsWalls - Blaster/DrywallRm 127- Yearbook office1462SF610+ yearsCeiling - ExposedRm 87 Basement Custodial WkRm1,201SF610+ yearsWalls - Blaster/DrywallRm 127- Yearbook office594SF710+ years </th <th></th> <th></th> <th></th> <th></th> <th>Ū</th> <th></th> <th>Recommend</th> <th></th> <th></th>					Ū		Recommend		
Classroom1EA710+ yearsDors - Wood Doors inclu hwRn 126D- Copy/Workroom- Classroom497SF610+ yearsFloor - TileRn 126D- Copy/Workroom- Classroom12EA66-10 yearsLighting - Lay-inRn 126D- Copy/Workroom- Classroom12EA66-10 yearsPower DistributionRm 126D- Copy/Workroom- Classroom8EA710+ yearsWalls - Plaster/DrywallRm 126D- Copy/Workroom- Classroom982SF610+ yearsCeiling - Plaster/DrywallRm 127- Yearbook office986SF610+ yearsDoors - Transom WindowRm 127- Yearbook office9SF710+ yearsDoors - Wood Doors inclu hwRm 127- Yearbook office9SF610+ yearsDoors - Wood Doors inclu hwRm 127- Yearbook office8EA66-10 yearsPower DistributionRm 127- Yearbook office8EA66-10 yearsWalls - Plaster/DrywallRm 127- Yearbook office8EA66-10 yearsWalls - Structural Glazad TileRm 127- Yearbook office1.462SF610+ yearsWalls - Plaster/DrywallRm 127- Yearbook office5F610+ yearsWalls - Structural Glazad TileRm 127- Yearbook office5F610+ yearsUighting - Pendent/SurfaceRm B7 Basement Custodial WkRm1.201SF610+ yearsPower Distribution	Group Item - Typ	ре	Location	Quantity	UOM	Rank	Replacement	Comments	
Doors - Wood Doors inclu hwRn 126D- Copy/Workroom- Classroom1EA710+ yearsFloor - TileRn 126D- Copy/Workroom- Classroom497SF610+ yearsLighting - Lay-inRm 126D- Copy/Workroom- Classroom12EA66-10 yearsPower DistributionRm 126D- Copy/Workroom- Classroom8EA710+ yearsWalls - Plaster/DrywallRm 126D- Copy/Workroom- Classroom982SF610+ yearsCeiling - Plaster/DrywallRm 127- Yearbook office696SF610+ yearsDoors - Transom WindowRm 127- Yearbook office9SF710+ yearsDoors - Transom WindowRm 127- Yearbook office9SF610+ yearsDoors - Wood Doors inclu hwRm 127- Yearbook office8EA710+ yearsPower DistributionRm 127- Yearbook office8EA66-10 yearsPower DistributionRm 127- Yearbook office14.25SF610+ yearsWalls - Btacter/DywallRm 127- Yearbook office14.62SF610+ yearsWalls - Btacter/DywallRm 127- Yearbook office14.62SF610+ yearsWalls - Btacter/DywallRm 127- Yearbook office14.62SF610+ yearsWalls - Btacter/DywallRm 127- Yearbook office14.64SF710+ yearsWalls - Structural Glazed TileRm 127- Yearbook office14.64SF710+ years <tr<< td=""><td>Ceiling - L</td><td>Lay-in</td><td>Rm 126D- Copy/Workroom-</td><td>497</td><td>SF</td><td>6</td><td>10+ years</td><td></td><td></td></tr<<>	Ceiling - L	Lay-in	Rm 126D- Copy/Workroom-	497	SF	6	10+ years		
Classroom497SF610+ yearsLighting - Lay-inRm 126D- Copy/Workroom- Classroom12EA66-10 yearsPower DistributionRm 126D- Copy/Workroom- Classroom8EA710+ yearsWalls - Plaster/DrywallRm 126D- Copy/Workroom- Classroom8EA710+ yearsCeiling - Plaster/DrywallRm 127- Yearbook office666SF610+ yearsDoors - Transom WindowRm 127- Yearbook office9SF710+ yearsDoors - Transom WindowRm 127- Yearbook office1EA710+ yearsDoors - Wood Doors inclu hwRm 127- Yearbook office1EA710+ yearsPower DistributionRm 127- Yearbook office1EA710+ yearsPower DistributionRm 127- Yearbook office1.462SF610+ yearsWalls - Plaster/DrywallRm 127- Yearbook office1.462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office1.462SF610+ yearsWalls - Plaster/DrywallRm 127- Yearbook office1.462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office1.462SF610+ yearsWalls - Plaster/DrywallRm 127- Yearbook office1.462SF610+ yearsWalls - Raster/DrywallRm 127- Yearbook office1.462SF610+ yearsWalls - Raster/DrywallRm 127- Yearbook offi									
Floor - TileRm 126D - Copy/Workroom- Classroom497SF610+ yearsLighting - Lay-inRm 126D - Copy/Workroom- Classroom12EA66-10 yearsPower DistributionRm 126D - Copy/Workroom- Classroom8EA710+ yearsWalls - Plaster/DrywallRm 126D - Copy/Workroom- Classroom982SF610+ yearsConstructClassroom982SF610+ yearsConstructClassroom982SF610+ yearsDoors - Transon WindowRm 127. Yearbook office9SF710+ yearsDoors - Transon WindowRm 127. Yearbook office8EA710+ yearsPower DistributionRm 127. Yearbook office8EA66-10 yearsPower DistributionRm 127. Yearbook office8EA66-10 yearsWalls - Plaster/DrywallRm 127. Yearbook office14EA710+ yearsWalls - Plaster/DrywallRm 127. Yearbook office14EA710+ yearsWalls - Plaster/DrywallRm 127. Yearbook office14EA66-10 yearsWalls - Structural Glazed TileRm 127. Yearbook office14EA710+ yearsCelling - ExposedRm B7 Basement Custodial WkRm1,201SF710+ yearsCelling - ExposedRm B7 Basement Custodial WkRm1,201SF610+ yearsCelling - ExposedRm B7 Basement Custodial WkRm1,21 <td< td=""><td>Doors - W</td><td>lood Doors inclu hw</td><td></td><td>1</td><td>EA</td><td>7</td><td>10+ years</td><td></td><td></td></td<>	Doors - W	lood Doors inclu hw		1	EA	7	10+ years		
Classroom12EA66-10 yearsLighting - Lay-inRm 126D- Copy/Workroom- Classroom8EA710+ yearsWalls - Plaster/DrywallRm 126D- Copy/Workroom- Classroom982SF610+ yearsWalls - Plaster/DrywallRm 127- Yearbook office696SF610+ yearsDoors - Transom WindowRm 127- Yearbook office9SF710+ yearsDoors - Transom WindowRm 127- Yearbook office1EA710+ yearsDoors - Wood Doors inclu hwRm 127- Yearbook office666SF610+ yearsPower DistributionRm 127- Yearbook office8EA66-10 yearsPower DistributionRm 127- Yearbook office1.462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office1.462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office1.462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office1.462SF610+ yearsFloor - Concrete Epoxyl PaintedRm B7 Basement Custodial WkRm1.201SF710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm1.201SF610+ yearsDoors - Wood Doors inclu hwRm B7B Basement Break room48SF610+ yearsDoors - Wood Doors inclu hwRm B7B Basement Break room48SF610+ yearsDoors - Wood Doors inclu hw<	Floor - Tile	e		497	SE	6	10+ vears		
ClassroomClassroom8EA710+ years ClassroomWalls - Plaster/DrywallRm 126D- Copy/Workroom- Classroom982SF610+ yearsCeiling - Plaster/DrywallRm 127- Yearbook office696SF610+ yearsDoors - Transom WindowRm 127- Yearbook office9SF710+ yearsDoors - Transom WindowRm 127- Yearbook office9SF710+ yearsDoors - Wood Doors inclu hwRm 127- Yearbook office696SF610+ yearsElighting - Pendent/SurfaceRm 127- Yearbook office8EA710+ yearsPower DistributionRm 127- Yearbook office8EA66-10 yearsPower DistributionRm 127- Yearbook office8EA710+ yearsWalls - Plaster/DrywallRm 127- Yearbook office8EA710+ yearsWalls - Structural Clazed TileRm 127- Yearbook office1462SF610+ yearsCeiling - ExposedRm B7 Basement Custodial WkRm1,201SF710+ yearsFloor - Concrete Epoxy/ PaintedRm B7 Basement Custodial WkRm1,201SF710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm1,154SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Dreak room2EA710+ yearsDoors - Vood Doors inclu hwRm B7B- Basement Dreak room2EA710+ yearsDoors - Wood Doors incl		0	Classroom	107	01	Ũ	lot youro		
ClassroomSF610+ yearsCeiling - Plaster/DrywallRm 127- Yearbook office696SF610+ yearsDoors - Transon WindowRm 127- Yearbook office9SF710+ yearsDoors - Wood Doors inclu hwRm 127- Yearbook office9SF710+ yearsDoors - Wood Doors inclu hwRm 127- Yearbook office9SF710+ yearsFloor - Tile Caranic/ PorcelainRm 127- Yearbook office696SF610+ yearsPower DistributionRm 127- Yearbook office8EA66-10 yearsWalls - Plaster/DrywallRm 127- Yearbook office14.462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office594SF710+ yearsWalls - Structural Glazed TileRm 127- Yearbook office594SF710+ yearsFloor - Concrete Epoxy/ PaintedRm B7 Basement Custodial WkRm1,201SF710+ yearsLighting - Pendent/SurfaceRm B7 Basement Custodial WkRm1,201SF710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm1,154SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsPower DistributionRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B	Lighting -	- Lay-in		12	EA	6	6-10 years		
Walls - Plaster/DrywallRm 126D- Copy/Workroom- Classroom982SF610+ yearsCeiling - Plaster/DrywallRm 127- Yearbook office9SF710+ yearsDoors - Transom WindowRm 127- Yearbook office9SF710+ yearsDoors - Wood Doors inclu hwRm 127- Yearbook office9SF610+ yearsFloor - Tile Ceramic/ PorcelainRm 127- Yearbook office8EA66-10 yearsPower DistributionRm 127- Yearbook office8EA66-10 yearsPower DistributionRm 127- Yearbook office1,462SF610+ yearsWalls - Plaster/DrywallRm 127- Yearbook office1,462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office1,462SF710+ yearsCeiling - ExposedRm B7 Basement Custodial WkRm1,201SF710+ yearsCeiling - ExposedRm B7 Basement Custodial WkRm1,201SF710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm1,154SF610+ yearsWalls - MasonryRm B7 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm B7B- Basement Custodial WkRm1,154SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Custodial WkRm1,154SF610+ yearsEditing - Pendent/SurfaceRm B7B- Basement Break room48SF610+ years<	Power Dis	stribution		8	EA	7	10+ years		
ClassroomClassroomCeiling - Plater/DrywallRm 127 - Yearbook office696SF610+ yearsDoors - Transom WindowRm 127 - Yearbook office9SF710+ yearsDoors - Tile Ceramic/ PorcelainRm 127 - Yearbook office696SF610+ yearsLighting - Pendent/SurfaceRm 127 - Yearbook office8EA66-10 yearsPower DistributionRm 127 - Yearbook office8EA710+ yearsWalls - Plaster/DrywallRm 127 - Yearbook office1,462SF610+ yearsWalls - Structural Glazed TileRm 127 - Yearbook office1,462SF610+ yearsCeiling - ExposedRm 87 Basement Custodial WRRm1,201SF710+ yearsFloor - Concrete Epoxy/ PaintedRm 87 Basement Custodial WRRm1,201SF710+ yearsLighting - Pendent/SurfaceRm 87 Basement Custodial WRRm1,201SF610+ yearsPower DistributionRm B7 Basement Custodial WRRm1,214SF610+ yearsStorage/ ClosetRm 87 Basement Custodial WRRm1,154SF610+ yearsDoors - TileRm 87B- Basement Custodial WRRm1,154SF610+ yearsDoors - Wood Doors inclu hwRm 87B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm 87B- Basement Break room488SF610+ yearsAC UnitRm 115A- Business Manager Office26	Walls - Pla	aster/Drywall		982	SF	6	10+ vears		
DoorsTransom WindowRm 127 - Yearbook office9SF710-yearsDoors- Wood Doors inclu hwRm 127 - Yearbook office1EA710+yearsFloor - Tile Ceramic/ PorcelainRm 127 - Yearbook office696SF610+ yearsLighting - Pendent/SurfaceRm 127 - Yearbook office8EA66-10 yearsPower DistributionRm 127 - Yearbook office1.462SF610+ yearsWalls - Plaster/DrywallRm 127 - Yearbook office594SF710+ yearsWalls - Structural Glazed TileRm 127 - Yearbook office594SF710+ yearsFloor - Concrete Epoxyl PaintedRm B7 Basement Custodial WkRm1,201SF610+ yearsLighting - Pendent/SurfaceRm B7 Basement Custodial WkRm8EA66-10 yearsPower DistributionRm B7 Basement Custodial WkRm117SF710+ yearsWalls - NasonyRm B7 Basement Custodial WkRm117SF610+ yearsWalls - NasonyRm B7B-Basement Break room2EA710+ yearsDoors - Wood Doors inclu hwRm B7B-Basement Break room488SF610+ yearsPower DistributionRm B7B-Basement Break room8EA66-10 yearsDoors - TileRm B7B-Basement Break room8EA66-10 yearsPower DistributionRm B7B-Basement Break room6EA710+ yearsHalls - P		-	Classroom				let yeare		
Doors - Wood Doors inclu hwRm 127 - Yearbook office1EA710+ yearsFloor - Tile Ceramic/ PorcelainRm 127 - Yearbook office696SF610+ yearsLighting - Pendent/SurfaceRm 127 - Yearbook office8EA66-10 yearsPower DistributionRm 127 - Yearbook office1,462SF610+ yearsWalls - Structural Glazed TileRm 127 - Yearbook office594SF710+ yearsCeiling - ExposedRm 87 Basement Custodial WkRm1,201SF610+ yearsFloor - Concrete Epoxyl PaintedRm 87 Basement Custodial WkRm1,201SF710+ yearsPower DistributionRm 87 Basement Custodial WkRm1,201SF710+ yearsPower DistributionRm 87 Basement Custodial WkRm1,201SF710+ yearsStorage/ ClosetRm 87 Basement Custodial WkRm1,154SF610+ yearsValls - MasonryRm 87 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm 87B Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm 87B Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm 87B Basement Break room8EA66-10 yearsPower DistributionRm 87B Basement Break room488SF610+ yearsCeiling - Lay-inRm 87B Basement Break room6EA710+ years	•	-							
Floor - Tile Ceramic/ PorcelainRm 127 - Yearbook office696SF610+ yearsLighting - Pendent/SurfaceRm 127 - Yearbook office8EA66-10 yearsPower DistributionRm 127 - Yearbook office1.462SF610+ yearsWalls - Plaster/DrywallRm 127 - Yearbook office1.462SF610+ yearsWalls - Structural Glazed TileRm 127 - Yearbook office594SF710+ yearsCeiling - ExposedRm B7 Basement Custodial WkRm1.201SF610+ yearsFloor - Concrete Epoxy/ PaintedRm B7 Basement Custodial WkRm1.201SF710+ yearsPower DistributionRm B7 Basement Custodial WkRm1.201SF710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm1.17SF710+ yearsWalls - MasonryRm B7B Basement Drustodial WkRm1.17SF610+ yearsCeiling - ExposedRm B7B-Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B-Basement Break room2EA710+ yearsFloor - TileRm B7B-Basement Break room8EA66-10 yearsAGL S-Plaster/DrywallRm B7B-Basement Break room6EA710+ yearsPower DistributionRm B7B-Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B-Basement Break room6EA710+ yearsCorr Tile<	Doors - Tr	ransom Window	Rm 127- Yearbook office	9			10+ years		
Lighting - Pendent/SurfaceRm 127 - Yearbook office8EA66-10 'yearsPower DistributionRm 127 - Yearbook office8EA710+ yearsWalls - Plaster/DrywallRm 127 - Yearbook office1.462SF610+ yearsWalls - Structural Glazed TileRm 127 - Yearbook office594SF710+ yearsCeiling - ExposedRm B7 Basement Custodial WkRm1.201SF610+ yearsCorrecte Epoxy/ PaintedRm B7 Basement Custodial WkRm1.201SF66-10 yearsFloor - Concrete Epoxy/ PaintedRm B7 Basement Custodial WkRm8EA66-10 yearsPower DistributionRm B7 Basement Custodial WkRm8EA66-10 yearsStorage/ ClosetRm B7 Basement Custodial WkRm1,154SF610+ yearsWalls - MasonryRm B7B Basement Break room2EA710+ yearsCeiling - ExposedRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsHowr DistributionRm B7B- Basement Break room710SF610+ yearsValls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsCeiling - Lay-inRm 115A- Business Manager Office1EA76-10 yearsDoors - Wood Doors inclu hwRm 115A- Business Manager Office1EA76-10 yearsD	Doors - W	/ood Doors inclu hw	Rm 127- Yearbook office	1	EA		10+ years		
Power DistributionRm 127- Yearbook office8EA710+ yearsWalls - Plaster/DrywallRm 127- Yearbook office1,462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office594SF710+ yearsCeiling - ExposedRm B7 Basement Custodial WkRm1,201SF610+ yearsFloor - Concrete Epoxyl PaintedRm B7 Basement Custodial WkRm1,201SF710+ yearsLighting - Pendent/SurfaceRm B7 Basement Custodial WkRm1,8EA66-10 yearsPower DistributionRm B7 Basement Custodial WkRm117SF710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room488SF610+ yearsPower DistributionRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room8EA610+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsCeiling - Lay-inRm B7B- Basement Break room710SF610+ yearsDoors - Wood Doors inclu hwRm 97B- Basement Break room710SF610+ years <t< td=""><td>Floor - Tile</td><td>e Ceramic/ Porcelain</td><td>Rm 127- Yearbook office</td><td>696</td><td>SF</td><td>6</td><td>10+ years</td><td></td><td></td></t<>	Floor - Tile	e Ceramic/ Porcelain	Rm 127- Yearbook office	696	SF	6	10+ years		
Walls - Plaster/DrywallRm 127- Yearbook office1,462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office594SF710+ yearsCeiling - ExposedRm 87 Basement Custodial WkRm1,201SF610+ yearsFloor - Concrete Epoxy/ PaintedRm 87 Basement Custodial WkRm1,201SF710+ yearsLighting - Pendent/SurfaceRm 87 Basement Custodial WkRm8EA66-10 yearsPower DistributionRm 87 Basement Custodial WkRm8EA710+ yearsStorage/ ClosetRm 87 Basement Custodial WkRm117SF710+ yearsWalls - MasonryRm 87 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm 87B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm 87B- Basement Break room488SF610+ yearsFloor - TileRm 87B- Basement Break room8EA710+ yearsLighting - Pendent/SurfaceRm 87B- Basement Break room8EA66-10 yearsPower DistributionRm 87B- Basement Break room8EA710+ yearsKalls - Plaster/DrywallRm 87B- Basement Break room710SF610+ yearsLighting - Lay-inRm 115A- Business Manager Office1EA710+ yearsDoors - Wood Doors inclu hwRm 115A- Business Manager Office263SF610+ years	Lighting -	- Pendent/Surface	Rm 127- Yearbook office	8	EA	6	6-10 years		
Walls - Plaster/DrywallRm 127- Yearbook office1,462SF610+ yearsWalls - Structural Glazed TileRm 127- Yearbook office594SF710+ yearsCeiling - ExposedRm 87 Basement Custodial WkRm1,201SF610+ yearsFloor - Concrete Epoxy/ PaintedRm 87 Basement Custodial WkRm1,201SF710+ yearsLighting - Pendent/SurfaceRm 87 Basement Custodial WkRm8EA66-10 yearsPower DistributionRm 87 Basement Custodial WkRm8EA710+ yearsStorage/ ClosetRm 87 Basement Custodial WkRm117SF710+ yearsWalls - MasonryRm 87 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm 87B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm 87B- Basement Break room488SF610+ yearsFloor - TileRm 87B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm 87B- Basement Break room8EA710+ yearsWalls - Plaster/DrywallRm 87B- Basement Break room8EA710+ yearsWalls - Plaster/DrywallRm 115A- Business Manager Office1EA710+ yearsCeiling - Lay-inRm 115A- Business Manager Office1EA710+ yearsFloor - TileRm 115A- Business Manager Office263SF610+ yearsDoo	Power Dis	stribution	Rm 127- Yearbook office	8	EA	7	10+ years		
Walls - Structural Glazed TileRm 127- Yearbook office594SF710+ yearsCeiling - ExposedRm B7 Basement Custodial WkRm1,201SF610+ yearsFloor - Concrete Epoxyl PaintedRm B7 Basement Custodial WkRm1,201SF710+ yearsLighting - Pendent/SurfaceRm B7 Basement Custodial WkRm8EA66-10 yearsPower DistributionRm B7 Basement Custodial WkRm6EA710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm117SF610+ yearsWalls - MasonryRm B7 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm B7B- Basement Custodial WkRm1,154SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsFloor - TileRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room488SF610+ yearsPower DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsAC UnitRm 115A- Business Manager Office1EA7610 yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ years			Rm 127- Yearbook office	1.462			•		
Ceiling - ExposedRm B7 Basement Custodial WkRm1,201SF610+ yearsFloor - Concrete Epoxy/ PaintedRm B7 Basement Custodial WkRm1,201SF710+ yearsLighting - Pendent/SurfaceRm B7 Basement Custodial WkRm8EA66-10 yearsPower DistributionRm B7 Basement Custodial WkRm117SF710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm117SF610+ yearsWalls - MasonryRm B7 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsFloor - TileRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room488SF610+ yearsPower DistributionRm B7B- Basement Break room8EA66-10 yearsWalls - Plaster/DrywallRm B7B- Basement Break room6EA710+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsDoors - Vood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office4EA66-10 years <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>									
Floor - Concrete Epoxy/ PaintedRm B7 Basement Custodial WkRm1,201SF710+ yearsLighting - Pendent/SurfaceRm B7 Basement Custodial WkRm8EA66-10 yearsPower DistributionRm B7 Basement Custodial WkRm6EA710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm117SF710+ yearsWalls - MasonryRm B7 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsFloor - TileRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room6EA710+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsFloor - TileRm-115A- Business Manager Office1EA710+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsFloor - TileRm-115A- Business Manager Office4EA66-10 yearsPower Distributi									
Lighting - Pendent/SurfaceRm B7 Basement Custodial WkRm8EA66-10 yearsPower DistributionRm B7 Basement Custodial WkRm6EA710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm117SF710+ yearsWalls - MasonryRm B7 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsFloor - TileRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office263SF610+ yearsAC UnitRm-115A- Business Manager Office263SF610+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office4EA710+ yearsPower Distribution <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>									
Power DistributionRm B7 Basement Custodial WkRm6EA710+ yearsStorage/ ClosetRm B7 Basement Custodial WkRm117SF710+ yearsWalls - MasonryRm B7 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsFloor - TileRm B7B- Basement Break room2EA710+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room8EA66-10 yearsWalls - Plaster/DrywallRm B7B- Basement Break room6EA710+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsCeiling - Lay-inRm-115A- Business Manager Office1EA76-10 yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office263SF610+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office4EA66-10 yearsPower DistributionRm-115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm-115A- Business Ma									
Storage/ ClosetRm B7 Basement Custodial WkRm117SF710+ yearsWalls - MasonryRm B7 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsFloor - TileRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office263SF610+ yearsFloor - TileRm-115A- Business Manager Office1EA710+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office263SF610+ yearsFloor - TileRm-115A- Business Manager Office4EA710+ yearsLighting - Lay-inRm-115A- Business Manager Office4EA710+ yearsValls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWork SlnkR									
Walls - MasonryRm B7 Basement Custodial WkRm1,154SF610+ yearsCeiling - ExposedRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsFloor - TileRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsCeiling - Lay-inRm-115A- Business Manager Office1EA710+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office263SF610+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office4EA66-10 yearsPower DistributionRm-115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWork SlnkRm-115A- Busine									
Ceiling - ExposedRm B7B- Basement Break room488SF610+ yearsDoors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsFloor - TileRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsCeiling - Lay-inRm-115A- Business Manager Office1EA710+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsLighting - Lay-inRm-115A- Business Manager Office1EA710+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office4EA66-10 yearsPower DistributionRm-115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWork SlnkRm-115A- Business Manager Office1EA710+ yearsWork SlnkRm-115A- Bu									
Doors - Wood Doors inclu hwRm B7B- Basement Break room2EA710+ yearsFloor - TileRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room6EA710+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsCeiling - Lay-inRm-115A- Business Manager Office263SF610+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office263SF610+ yearsPower DistributionRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office4EA66-10 yearsPower DistributionRm-115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWork SlnkRm-115A- Business Manager Office4EA710+ yearsWork SlnkRm-115A- Business Manager Office1EA710+ yearsWork SlnkRm-115A- Business						-	•		
Floor - TileRm B7B- Basement Break room488SF610+ yearsLighting - Pendent/SurfaceRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsCeiling - Lay-inRm-115A- Business Manager Office263SF610+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office263SF610+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office263SF610+ yearsPower DistributionRm-115A- Business Manager Office4EA66-10 yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWork SlnkRm-115A- Business Manager Office1EA710+ yearsWork SlnkRm-115A- Business Manager Office1EA710+ yearsWork SlnkRoom 408, North book storage180SF610+ years									
Lighting - Pendent/SurfaceRm B7B- Basement Break room8EA66-10 yearsPower DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsCeiling - Lay-inRm-115A- Business Manager Office263SF610+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office263SF610+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA66-10 yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWork SlnkRm-115A- Business Manager Office1EA710+ yearsWork SlnkRm-115A- Business Manager Office1EA710+ yearsWork SlnkRoom 408, North book storage180SF610+ years							-		
Power DistributionRm B7B- Basement Break room6EA710+ yearsWalls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsAC UnitRm-115A- Business Manager Office1EA76-10 yearsCeiling - Lay-inRm-115A- Business Manager Office263SF610+ yearsDoors - Wood Doors inclu hwRm-115A- Business Manager Office1EA710+ yearsFloor - TileRm-115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm-115A- Business Manager Office263SF610+ yearsPower DistributionRm-115A- Business Manager Office4EA66-10 yearsWalls - Plaster/DrywallRm-115A- Business Manager Office4EA710+ yearsWork SInkRm-115A- Business Manager Office654SF610+ yearsWork SInkRoom 408, North book storage180SF610+ years									
Walls - Plaster/DrywallRm B7B- Basement Break room710SF610+ yearsAC UnitRm- 115A- Business Manager Office1EA76-10 yearsCeiling - Lay-inRm- 115A- Business Manager Office263SF610+ yearsDoors - Wood Doors inclu hwRm- 115A- Business Manager Office1EA710+ yearsFloor - TileRm- 115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm- 115A- Business Manager Office4EA66-10 yearsPower DistributionRm- 115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm- 115A- Business Manager Office4EA710+ yearsWork SInkRm- 115A- Business Manager Office1EA710+ yearsWork SInkRoom 408, North book storage180SF610+ years							•		
AC UnitRm- 115A- Business Manager Office1EA76-10 yearsCeiling - Lay-inRm- 115A- Business Manager Office263SF610+ yearsDoors - Wood Doors inclu hwRm- 115A- Business Manager Office1EA710+ yearsFloor - TileRm- 115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm- 115A- Business Manager Office4EA66-10 yearsPower DistributionRm- 115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm- 115A- Business Manager Office654SF610+ yearsWork SInkRm- 115A- Business Manager Office1EA710+ yearsCeiling - Plaster/DrywallRoom 408, North book storage180SF610+ years									
Ceiling - Lay-inRm- 115A- Business Manager Office263SF610+ yearsDoors - Wood Doors inclu hwRm- 115A- Business Manager Office1EA710+ yearsFloor - TileRm- 115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm- 115A- Business Manager Office4EA66-10 yearsPower DistributionRm- 115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm- 115A- Business Manager Office654SF610+ yearsWork SInkRm- 115A- Business Manager Office1EA710+ yearsCeiling - Plaster/DrywallRoom 408, North book storage180SF610+ years		aster/Drywall							
Doors - Wood Doors inclu hwRm- 115A- Business Manager Office1EA710+ yearsFloor - TileRm- 115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm- 115A- Business Manager Office4EA66-10 yearsPower DistributionRm- 115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm- 115A- Business Manager Office654SF610+ yearsWork SInkRm- 115A- Business Manager Office1EA710+ yearsCeiling - Plaster/DrywallRoom 408, North book storage180SF610+ years									
Floor - TileRm- 115A- Business Manager Office263SF610+ yearsLighting - Lay-inRm- 115A- Business Manager Office4EA66-10 yearsPower DistributionRm- 115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm- 115A- Business Manager Office654SF610+ yearsWork SInkRm- 115A- Business Manager Office1EA710+ yearsCeiling - Plaster/DrywallRoom 408, North book storage180SF610+ years				263			10+ years		
Lighting - Lay-inRm- 115A- Business Manager Office4EA66-10 yearsPower DistributionRm- 115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm- 115A- Business Manager Office654SF610+ yearsWork SInkRm- 115A- Business Manager Office1EA710+ yearsCeiling - Plaster/DrywallRoom 408, North book storage180SF610+ years							10+ years		
Power DistributionRm- 115A- Business Manager Office4EA710+ yearsWalls - Plaster/DrywallRm- 115A- Business Manager Office654SF610+ yearsWork SInkRm- 115A- Business Manager Office1EA710+ yearsCeiling - Plaster/DrywallRoom 408, North book storage180SF610+ years	Floor - Tile	e		263	SF	6	10+ years		
Walls - Plaster/DrywallRm- 115A- Business Manager Office654SF610+ yearsWork SInkRm- 115A- Business Manager Office1EA710+ yearsCeiling - Plaster/DrywallRoom 408, North book storage180SF610+ years	Lighting -	- Lay-in	Rm- 115A- Business Manager Office	4		6	6-10 years		
Work SInk Rm- 115A- Business Manager Office 1 EA 7 10+ years Ceiling - Plaster/Drywall Room 408, North book storage 180 SF 6 10+ years	Power Dis	stribution	Rm- 115A- Business Manager Office	4		7	10+ years		
Work SInkRm- 115A- Business Manager Office1EA710+ yearsCeiling - Plaster/DrywallRoom 408, North book storage180SF610+ years	Walls - Pla	aster/Drywall	Rm- 115A- Business Manager Office	654		6	10+ years		
Ceiling - Plaster/Drywall Room 408, North book storage 180 SF 6 10+ years					EA	7	-		
				180					
	•	-							
Doors - Wood Doors inclu hw Room 408, North book storage 1 EA 7 10+ years							•		
Floor - Wood Devis mild nu Floor - Room 408, North book storage 180 SF 6 10+ years			-				•		



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface Room 408, North book storage 4 ΕA 6 6-10 vears Walls - Plaster/Drvwall Room 408. North book storage 560 SF 6 10+ years Ceiling - Plaster/Drywall Room 419A 70 SF 6 10+ years Doors - Steel Doors incl hw Room 419A ΕA 7 1 10+ years 70 SF Floor - Tile Room 419A 6 10+ years Lighting - Pendent/Surface ΕA Room 419A 1 6 6-10 years **Power Distribution** Room 419A 2 ΕA 7 10+ years Walls - Plaster/Drvwall SF Room 419A 170 6 10+ years Work SInk Room 419A 1 EΑ 7 10+ years SF Ceiling - Lay-in Room 419B 138 6 10+ vears SF Ceiling - Lav-in Room 419B 5 5 1-2 vears Missing tiles Doors - Side-lite Room 419B 30 SF 7 10+ years Doors - Wood Doors inclu hw Room 419B ΕA 7 10+ years 1 SF Floor - Tile Room 419B 143 6 10+ years Lighting - Lay-in 2 ΕA 6 Room 419B 6-10 years Walls - Plaster/Drywall 360 SF 6 Room 419B 10+ years ΕA 7 Work SInk Room 419B 1 6-10 years SF Ceiling - Lay-in Room 421B 212 6 10+ years Doors - Side-lite SF Room 421B 6 7 10+ vears Doors - Wood Doors inclu hw Room 421B 1 EΑ 7 10+ years Floor - Tile Room 421B 212 SF 6 10+ years Lighting - Lay-in ΕA 6 Room 421B 4 6-10 years SF Walls - Plaster/Drywall 440 6 Room 421B 10+ years Work SInk 7 Room 421B 2 FΑ 6-10 years Auditorium & Theater 7 Balcony Seating 1st Floor 232 ΕA 10+ years Ceiling - Plaster/Drywall 1st Floor 2,386 SF 6 10+ years Ceiling - Splined SF 6 1st Floor 4.035 10+ years Doors - Steel Doors incl hw ΕA 7 1st Floor 2 10+ years Doors - Wood Doors inclu hw 1st Floor 16 ΕA 7 10+ years SF Floor - Carpet 1st Floor 1.286 6 6-10 years SF Floor - Carpet 1st Floor 4,035 6 6-10 years Floor - Concrete Epoxy/ Painted 1st Floor 97 SF 7 10+ years Floor - Terrazzo 1st Floor 206 SF 7 10+ years SF Floor - Tile 1st Floor 797 6 10+ years 7 Lighting - Chandelier, Incandescent 1st Floor 10 FΑ 6-10 years Lighting - Pendent/Surface 49 FΑ 7 1st Floor 6-10 years Lighting - Wall Mounted 1st Floor 18 ΕA 7 6-10 vears Main Floor Seating 1st Floor 420 ΕA 7 10+ years Sound System ΕA 7 6-10 years 1st Floor 1 SF Stage 1st Floor 940 6 10+ years Stage Curtain 1st Floor 8 ΕA 7 10+ years 7 Stage Lighting System 1st Floor 1 EΑ 6-10 years



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stage-Stairs - Wood	1st Floor	8	LF	6	10+ years	
	Stairs - Terrazzo	1st Floor	48	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	8,747	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	386	SF	7	10+ years	
Symnas	ia						
	Ceiling - Plaster/Drywall	121 A men's weight room in locker	1,350	SF	6	10+ years	
		room	1,000	•	Ũ	ier jeale	
	Doors - Steel Doors incl hw	121 A men's weight room in locker	1	EA	7	10+ years	
		room	·	_/ (•	lor youro	
	Floor - Weight/ Fitness Room Floor Matting	121 A men's weight room in locker	1,350	SF	7	10+ years	
		room	1,000	0.	•	lor youro	
	Lighting - Pendent/Surface	121 A men's weight room in locker	6	EA	6	6-10 years	
	Lighting - r enden/Sunace	room	0	LA	0	0-10 years	
	Walls - Structural Glazed Tile	121 A men's weight room in locker	400	SF	7	10+ years	
	Walls - Structural Glazed The	room	400	51	'	TUT years	
	Bleacher Seating	221/223 West Gym Boys	111		7	10	
	Ceiling - Lay-in	221/223 West Gym Boys	5,982	EA SF	6	10+ years	
				EA		10+ years	
	Doors - Wood Doors inclu hw	221/223 West Gym Boys	4		7	10+ years	
	Floor - Wood	221/223 West Gym Boys	5,982	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure	221/223 West Gym Boys	18	EA	6	6-10 years	
	Sodium				_		
	Scoreboards	221/223 West Gym Boys	1	EA	7	10+ years	
	Sound System	221/223 West Gym Boys	1	EA	7	10+ years	
	Storage/ Closet	221/223 West Gym Boys	47	SF	7	10+ years	
	Walls - Structural Glazed Tile	221/223 West Gym Boys	7,916	SF	7	10+ years	
	Ceiling - Lay-in	225 East Gym Girls	5,995	SF	6	6-10 years	
	Doors - Transom Window	225 East Gym Girls	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	225 East Gym Girls	4	EA	7	10+ years	
	Floor - Wood	225 East Gym Girls	5,995	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure	225 East Gym Girls	18	EA	6	6-10 years	
	Sodium						
	Scoreboards	225 East Gym Girls	1	EA	7	10+ years	
	Sound System	225 East Gym Girls	1	EA	7	10+ years	
	Storage/ Closet	225 East Gym Girls	47	SF	7	10+ years	
	Walls - Structural Glazed Tile	225 East Gym Girls	7,904	SF	6	10+ years	
	Walls - Structural Glazed Tile	225 East Gym Girls	40	SF	4	1-2 years	
	Ceiling - Lay-in	323 Small Gym	1,529	SF	6	10+ years	
	Doors - Transom Window	323 Small Gym	1,529	SF	7	10+ years	
		323 Small Gym		EA	7		
	Doors - Wood Doors inclu hw		2 1 5 2 0			10+ years	
	Floor - Sport Flooring	323 Small Gym	1,529	SF	7	10+ years	
	Lighting - Pendent/Surface	323 Small Gym	12	EA	6	6-10 years	
	Storage/ Closet	323 Small Gym	172	SF	7	10+ years	
	Walls - Plaster/Drywall	323 Small Gym	1,690	SF	6	10+ years	



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
tchen							
	Ceiling - Plaster/Drywall	307 Lunchroom/Serving Line 307B	1,083	SF	6	10+ years	
	Doors - Wood Doors inclu hw	307 Lunchroom/Serving Line 307B	2	EA	7	10+ years	
	Floor - Tile	307 Lunchroom/Serving Line 307B	1,083	SF	6	6-10 years	
	Lighting - Pendent/Surface	307 Lunchroom/Serving Line 307B	45	EA	6	6-10 years	
	Serving Line	307 Lunchroom/Serving Line 307B	120	LF	7	6-10 years	
	Walls - Plaster/Drywall	307 Lunchroom/Serving Line 307B	930	SF	6	6-10 years	
	Walls - Structural Glazed Tile	307 Lunchroom/Serving Line 307B	930	SF	7	10+ years	
	Ceiling - Plaster/Drywall	307A Kitchen	740	SF	6	10+ years	
	Doors - Transom Window	307A Kitchen	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	307A Kitchen	1	EA	7	10+ years	
	Floor - Tile	307A Kitchen	740	SF	6	6-10 years	
	Lighting - Pendent/Surface	307A Kitchen	12	EA	6	6-10 years	
	Storage/ Closet	307A Kitchen	32	SF	7	10+ years	
	Walls - Plaster/Drywall	307A Kitchen	760	SF	6	10+ years	
	Walls - Structural Glazed Tile	307A Kitchen	760	SF	7	10+ years	
	Ceiling - Plaster/Drywall	307C Kitchen	470	SF	6	10+ years	Construction, previous assessme
	Coming Thatacon Dry Man			0.	Ũ	io: youro	data used
	Doors - Transom Window	307C Kitchen	9	SF	7	10+ years	
	Floor - Tile	307C Kitchen	470	SF	6	10+ years	
	Lighting - Pendent/Surface	307C Kitchen	4/0	EA	6	6-10 years	
	Walls - Structural Glazed Tile	307C Kitchen	1,020	SF	7	10+ years	
	Ceiling - Plaster/Drywall	307F Bakery	276	SF	7	10+ years	
	Doors - Transom Window	307F Bakery	270	SF	7	10+ years	
	Doors - Wood Doors inclu hw	307F Bakery	5	EA	7	•	
		307F Bakery		SF	6	10+ years	
	Floor - Terrazzo		276	-	-	10+ years	
	Lighting - Pendent/Surface	307F Bakery	4	EA	6 7	6-10 years	
	Walls - Structural Glazed Tile	307F Bakery	880	SF	/	10+ years	
rary							
,	AC Unit	1st floor Room 115	4	EA	7	6-10 years	
	Casework	1st floor Room 115	104	LF	7	10+ years	
	Ceiling - Lay-in	1st floor Room 115	1,976	SF	6	10+ years	
	Ceiling - Lay-in	1st floor Room 115	25	SF	5	1-2 years	Missing tiles
	Doors - Wood Doors inclu hw	1st floor Room 115	2	EA	7	10+ years	-
	Floor - Tile	1st floor Room 115	2,001	SF	6	10+ years	
	Lighting - Lay-in	1st floor Room 115	57	EA	6	6-10 years	
	Storage/ Closet	1st floor Room 115	469	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor Room 115	958	SF	6	10+ years	
akor/O	hower Room						
skel/S	hower Room		050	05	7	0.40	
	Accessories	1st FI, Staff Locker room (next to	250	SF	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		engineer office)					
	Ceiling - Plaster/Drywall	1st FI, Staff Locker room (next to	250	SF	6	10+ years	
		engineer office)	_		_		
	Doors - Transom Window	1st FI, Staff Locker room (next to	8	SF	7	10+ years	
		engineer office)	0	- ^	-	40	
	Doors - Wood Doors inclu hw	1st FI, Staff Locker room (next to	2	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	engineer office) 1st FI, Staff Locker room (next to	125	SF	5	6-10 years	
	FIOU - CONCIELE EPOXY/ Fainted	engineer office)	125	ЗГ	5	0-10 years	
	Floor - Tile Ceramic/ Porcelain	1st FI, Staff Locker room (next to	125	SF	6	10+ years	
		engineer office)	120	01	0	Tor years	
	Floor Drain	1st FI, Staff Locker room (next to	1	EA	7	10+ years	
		engineer office)	-		-	,	
	Lavatory	1st FI, Staff Locker room (next to	1	EA	7	10+ years	
	2	engineer office)					
	Lighting - Pendent/Surface	1st FI, Staff Locker room (next to	3	EA	6	6-10 years	
		engineer office)					
	Showers	1st FI, Staff Locker room (next to	1	EA	7	10+ years	
		engineer office)	_				
	Student Lockers - One Tier	1st FI, Staff Locker room (next to	9	EA	6	10+ years	
		engineer office)	004	05	0	10	
	Walls - Plaster/Drywall	1st FI, Staff Locker room (next to engineer office)	894	SF	6	10+ years	
	Walls - Plaster/Drywall	1st FI, Staff Locker room (next to	50	SF	5	1-2 years	Peeling
	Walls - Flastel/Drywall	engineer office)	50	0	5	1-2 years	reening
	Walls - Tile Ceramic/ Porcelain	1st FI, Staff Locker room (next to	85	SF	6	10+ years	
		engineer office)	00	0.	U	io i youro	
	Water Closet	1st FI, Staff Locker room (next to	1	EA	7	10+ years	
		engineer office)				,	
	Accessories	223A Locker Room	262	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	223A Locker Room	262	SF	6	10+ years	
	Doors - Side-lite	223A Locker Room	8	SF	7	10+ years	
	Doors - Transom Window	223A Locker Room	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	223A Locker Room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	223A Locker Room	262	SF	6	10+ years	
	Floor Drain	223A Locker Room	2	EA	7	10+ years	
	Lavatory	223A Locker Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface Showers	223A Locker Room 223A Locker Room	3	EA EA	6 7	6-10 years	
	Student Lockers - One Tier	223A Locker Room	7	EA	7	10+ years 10+ years	
	Walls - Plaster/Drywall	223A Locker Room	672	SF	6	10+ years	
	Water Closet	223A Locker Room	1	EA	7	10+ years	
	Accessories	Rm 121- Boys Locker	680	SF	7	6-10 years	
	Benches, ped mounted	Rm 121- Boys Locker	32	LF	7	10+ years	
			02		•	,	



Catego	ry : Room		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Rm 121- Boys Locker	3,954	SF	6	10+ years	
	Doors - Transom Window	Rm 121- Boys Locker	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 121- Boys Locker	2	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Rm 121- Boys Locker	1,926	SF	7	10+ years	
	Floor - Terrazzo	Rm 121- Boys Locker	105	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Rm 121- Boys Locker	1,923	SF	6	10+ years	
	Floor Drain	Rm 121- Boys Locker	7	EA	7	10+ years	
	Lavatory	Rm 121- Boys Locker	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Rm 121- Boys Locker	32	EA	6	6-10 years	
	Lighting - Wall Mounted	Rm 121- Boys Locker	1	EA	6	6-10 years	
	Partitions	Rm 121- Boys Locker	2	EA	7	10+ years	
	Showers	Rm 121- Boys Locker	15	EA	7	10+ years	
	Student Lockers - One Tier	Rm 121- Boys Locker	11	EA	7	10+ years	
	Student Lockers - Two Tier	Rm 121- Boys Locker	125	EA	7	10+ years	
	Student Lockers - Two Tier	Rm 121- Boys Locker	3	EA	5	6-10 years	
	Urinals	Rm 121- Boys Locker	4	EA	7	10+ years	
	Walls - Metal Panel	Rm 121- Boys Locker	200	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 121- Boys Locker	311	SF	6	10+ years	
	Walls - Structural Glazed Tile	Rm 121- Boys Locker	6,794	SF	7	10+ years	
	Walls - Structural Glazed Tile	Rm 121- Boys Locker	1,078	SF	7	10+ years	
	Walls - Structural Glazed Tile	Rm 121- Boys Locker	12	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Rm 121- Boys Locker	53	SF	7	10+ years	
	Water Closet	Rm 121- Boys Locker	2	EA	7	10+ years	
	Accessories	Rm 125- Womens Locker	238	SF	5	6-10 years	
	Benches, ped mounted	Rm 125- Womens Locker	136	LF	7	10+ years	
	Ceiling - Lay-in	Rm 125- Womens Locker	238	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Rm 125- Womens Locker	4,436	SF	6	10+ years	
	Doors - Transom Window	Rm 125- Womens Locker	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 125- Womens Locker	4	EA	7	10+ years	
	Floor - Terrazzo	Rm 125- Womens Locker	238	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Rm 125- Womens Locker	4,436	SF	6	10+ years	
	Floor Drain	Rm 125- Womens Locker	33	EA	7	10+ years	
	Lavatory	Rm 125- Womens Locker	2	EA	7	10+ years	
	Lighting - Lay-in	Rm 125- Womens Locker	5	EA	6	6-10 years	
	Lighting - Pendent/Surface	Rm 125- Womens Locker	50	EA	6	6-10 years	
	Lighting - Wall Mounted	Rm 125- Womens Locker	1	EA	6	6-10 years	
	Partitions	Rm 125- Womens Locker	4	EA	7	10+ years	
	Showers	Rm 125- Womens Locker	23	EA	7	10+ years	
	Showers	Rm 125- Womens Locker	29	EA	5	2-5 years	
	Student Lockers - Three Tiers	Rm 125- Womens Locker	96	EA	7	10+ years	
	Student Lockers - Two Tier	Rm 125- Womens Locker	145	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 125- Womens Locker	1,571	SF	6	10+ years	
	Walls - Structural Glazed Tile	Rm 125- Womens Locker	5,350	SF	7	10+ years	
	Walls - Structural Glazed Tile	Rm 125- Womens Locker	382	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	Rm 125- Womens Locker	4	EA	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	307 Lunchroom	4,175	SF	6	10+ years	Construction, previous assessmer data used
	Doors - Wood Doors inclu hw	307 Lunchroom	4	EA	7	10+ years	
	Floor - Tile	307 Lunchroom	4,175	SF	6	10+ years	
	Lighting - Pendent/Surface	307 Lunchroom	48	EA	6	6-10 years	
	Storage/ Closet	307 Lunchroom	164	SF	7	10+ years	
	Walls - Plaster/Drywall	307 Lunchroom	1,744	SF	6	10+ years	
	Walls - Structural Glazed Tile	307 Lunchroom	1,744	SF	7	10+ years	
MDF ID	F						
	Doors - Steel Doors incl hw	Located in Room 213A	1	EA	7	10+ years	
	Finishes	Located in Room 213A	160	SF	7	10+ years	
	Window AC Unit	Located in Room 213A	2	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	64	SF	7	10+ years	
	Storage Room	1st Floor	496	SF	7	10+ years	
	Storage Room	1st Floor	22	SF	7	10+ years	
	Vaults	1st Floor	25	SF	7	10+ years	
	Janitor's Closet	2nd Floor	61	SF	7	10+ years	
	Janitor's Closet	3rd Floor	75	SF	7	10+ years	
	Janitor's Closet	3rd Floor	66	SF	7	10+ years	
	Janitor's Closet	4th Floor	65	SF	7	10+ years	
	Storage Room	4th Floor	600	SF	7	10+ years	
	Air Tunnel	Basement	8,000	SF	7	10+ years	
	Boiler Room	Basement	2,590	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	1,168	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	13,724	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,935	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	3,651	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	336	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	40	SF	7	10+ years	
	Storage Room	Basement	10,588	SF	7	10+ years	
	Vaults	Basement	300	SF	7	10+ years	
			200		·		
Pool & N	latatorium Bleachers Seating/Plank Seating	1st Floor	65	EA	7	10	
			65			10+ years	
	Ceiling - Plaster/Drywall	1st Floor	232	SF	6	10+ years	
	Ceiling - Splined (Moister Resistance)	1st Floor	3,114	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	60	SF	7	10+ years	
	Floor - Terrazzo	1st Floor	132	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	59	EA	6	6-10 years	
	Pool Basin	1st Floor	1,479	SF	7	10+ years	
	Pool Deck	1st Floor	1,755	SF	7	10+ years	
	Pool Deck Drains	1st Floor	7	EA	7	10+ years	
	Storage/ Closet	1st Floor	67	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,020	SF	7	10+ years	
Prep Ro	om						
	Casework	409A	6	LF	7	10+ years	
	Ceiling - Lay-in	409A	185	SF	7	10+ years	
	Doors - Wood Doors inclu hw	409A	1	EA	7	10+ years	
	Floor - Tile	409A	185	SF	7	10+ years	
	Lighting - Lay-in	409A	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	409A	411	SF	7	10+ years	
	Work Sink	409A	1	EA	7	10+ years	
	Casework	413A	4	LF	7	10+ years	
	Ceiling - Lay-in	413A	72	SF	6	10+ years	
	Doors - Steel Doors incl hw	413A	1	EA	7	10+ years	
	Floor - Tile	413A	72	SF	6	10+ years	
	Lighting - Lay-in	413A	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	413A	312	SF	6	10+ years	
	Work Sink	413A	1	EA	7	6-10 years	
	Casework	413B inside 413	30	LF	7	10+ years	
	Ceiling - Lay-in	413B inside 413	174	SF	6	10+ years	
	Doors - Steel Doors incl hw	413B inside 413	1	EA	7	10+ years	
	Floor - Tile	413B inside 413	174	SF	6	10+ years	
	Lighting - Lay-in	413B inside 413	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	413B inside 413	300	SF	6	10+ years	
	Work Sink	413B inside 413	2	EA	7	6-10 years	
	Casework	421A	10	LF	7	10+ years	
	Ceiling - Lay-in	421A	70	SF	6	10+ years	
	Doors - Steel Doors incl hw	421A	1	EA	7	10+ years	
	Floor - Tile	421A	70	SF	6	10+ years	
	Lighting - Lay-in	421A	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	421A	350	SF	6	10+ years	
	Work Sink	421A	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Prep Room 215A in 215	168	SF	7	10+ years	
	Doors - Side-lite	Prep Room 215A in 215	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Prep Room 215A in 215	1	EA	7	10+ years	
	Floor - Tile	Prep Room 215A in 215	168	SF	6	10+ years	
	Lighting - Pendent/Surface	Prep Room 215A in 215	2	EA	6	6-10 years	
		•				•	
	Walls - Plaster/Drywall	Prep Room 215A in 215	615	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		Noss N Nimball AVENUE, Chicago, IE 00025
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Prep Room 215A in 215	50	SF	6	10+ years	
	Casework	Prep Room in 309 Room 309A	10	LF	7	10+ years	Room under construction
	Ceiling - Lay-in	Prep Room in 309 Room 309A	188	SF	7	10+ years	
	Doors - Steel Doors incl hw	Prep Room in 309 Room 309A	1	EA	7	10+ years	
	Floor - Tile	Prep Room in 309 Room 309A	188	SF	7	10+ years	
	Lighting - Lay-in	Prep Room in 309 Room 309A	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Prep Room in 309 Room 309A	480	SF	7	10+ years	
	Work Sink	Prep Room in 309 Room 309A	1	EA	7	6-10 years	
	Casework	Prep room in 313	10	LF	7	10+ years	
	Ceiling - Lay-in	Prep room in 313	62	SF	6	10+ years	
	Ceiling - Lay-in	Prep room in 313	10	SF	5	2-5 years	Water damage
	Doors - Steel Doors incl hw	Prep room in 313	1	EA	7	10+ years	C C
	Floor - Tile	Prep room in 313	72	SF	6	10+ years	
	Lighting - Lay-in	Prep room in 313	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	Prep room in 313	312	SF	6	10+ years	
	Work Sink	Prep room in 313	1	EA	7	6-10 years	
	Casework	Rm 114A- Prep room for food for	20	LF	7	10+ years	
		Community Rm 112					
	Ceiling - Lay-in	Rm 114A- Prep room for food for	164	SF	6	10+ years	
	3	Community Rm 112				· , · · · ·	
	Doors - Transom Window	Rm 114A- Prep room for food for	9	SF	7	10+ years	
		Community Rm 112				,	
	Doors - Wood Doors inclu hw	Rm 114A- Prep room for food for	1	EA	7	10+ years	
		Community Rm 112				· , · · · ·	
	Floor - Tile	Rm 114A- Prep room for food for	154	SF	6	10+ years	
		Community Rm 112				· , · · · ·	
	Floor - Tile	Rm 114A- Prep room for food for	10	SF	4	1-2 years	Chipped/cracked
		Community Rm 112				,	
	Lighting - Lay-in	Rm 114A- Prep room for food for	4	EA	6	6-10 years	
		Community Rm 112			-	- · · · · · · ·	
	Walls - Plaster/Drywall	Rm 114A- Prep room for food for	490	SF	6	10+ years	
		Community Rm 112		•	U U	ier jeale	
	Work Sink	Rm 114A- Prep room for food for	1	EA	7	10+ years	
		Community Rm 112		_/ `		ier jeale	
	Ceiling - Lay-in	Room 413C	149	SF	6	10+ years	
	Ceiling - Lay-in	Room 413C	4	SF	4	1-2 years	Stained
	Doors - Steel Doors incl hw	Room 413C	1	ĒA	7	10+ years	
	Floor - Tile	Room 413C	153	SF	6	10+ years	
	Lighting - Lay-in	Room 413C	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	Room 413C	253	SF	6	10+ years	
			200	•	Ũ	i e i jeule	
Restroor	m						
	Accessories	1st FI Boys- by 120	259	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI Boys- by 120	221	SF	6	10+ years	
		· · · ·				-	



Catego	ory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st FI Boys- by 120	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI Boys- by 120	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI Boys- by 120	254	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI Boys- by 120	5	SF	6	10+ years	
	Floor Drain	1st FI Boys- by 120	1	EA	7	10+ years	
	Lavatory	1st FI Boys- by 120	2	EA	7	10+ years	
	Lighting - Lay-in	1st FI Boys- by 120	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st FI Boys- by 120	1	EA	6	6-10 years	
	Partitions	1st FI Boys- by 120	2	EA	7	10+ years	
	Urinals	1st Fl Boys- by 120	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st FI Boys- by 120	760	SF	6	10+ years	
	Water Closet	1st Fl Boys- by 120	2	EA	7	10+ years	
	Accessories	1st FI Girls- By 108	338	SF	7	6-10 years	
	Ceiling - Lay-in	1st Fl Girls- By 108	303	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Fl Girls- By 108	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl Girls- By 108	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Fl Girls- By 108	338	SF	6	10+ years	
	Floor Drain	1st Fl Girls- By 108	1	EA	7	10+ years	
	Lavatory	1st Fl Girls- By 108	2	EA	7	10+ years	
	Lighting - Lay-in	1st Fl Girls- By 108	6	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Fl Girls- By 108	1	EA	6	6-10 years	
	Partitions	1st Fl Girls- By 108	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Fl Girls- By 108	778	SF	6	10+ years	
	Water Closet	1st FI Girls- By 108	4	EA	7	10+ years	
	Accessories	1st Fl Girls- By 122	276	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI Girls- By 122	243	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st FI Girls- By 122	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI Girls- By 122	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Fl Girls- By 122	276	SF	6	10+ years	
	Floor Drain	1st Fl Girls- By 122	1	ĒA	7	10+ years	
	Lavatory	1st Fl Girls- By 122	2	EA	7	10+ years	
	Lighting - Lay-in	1st Fl Girls- By 122	8	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Fl Girls- By 122	1	EA	6	6-10 years	
	Partitions	1st Fl Girls- By 122	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Fl Girls- By 122	798	SF	6	10+ years	
	Water Closet	1st Fl Girls- By 122	4	EA	7	10+ years	
	Accessories	1st Fl Men's- Across from 108	121	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI Men's- Across from 108	121	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl Men's- Across from 108	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI Men's- Across from 108	121	SF	6	10+ years	
	Lavatory	1st FI Men's- Across from 108	1	EA	7	10+ years	
	Lighting - Lay-in	1st FI Men's- Across from 108	2	EA	6	6-10 years	
	Partitions	1st FI Men's- Across from 108	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st FI Men's- Across from 108	445	SF	6	10+ years	
			-+5	5	0	ior years	



Catego	ory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st FI Men's- Across from 108	5	SF	5	1-2 years	Peeling
	Water Closet	1st FI Men's- Across from 108	2	EA	7	10+ years	
	Accessories	1st FI, in principal office	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI, in principal office	28	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI, in principal office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI, in principal office	28	SF	6	10+ years	
	Lavatory	1st FI, in principal office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st FI, in principal office	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Fl, in principal office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st FI, in principal office	211	SF	6	10+ years	
	Water Closet	1st Fl, in principal office	1	EA	7	10+ vears	
	Accessories	1st FI- Across from Freight Elevator	23	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI- Across from Freight Elevator	23	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI- Across from Freight Elevator		ĒA	7	10+ years	
	Floor - Tile	1st FI- Across from Freight Elevator	7	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI- Across from Freight Elevator	16	SF	6	10+ years	
	Lavatory	1st FI- Across from Freight Elevator	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st FI- Across from Freight Elevator	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st FI- Across from Freight Elevator	170	SF	6	10+ years	
	Water Closet	1st FI- Across from Freight Elevator	1/0	EA	7	10+ years	
	Accessories	1st FI- Auditorium Women's	150	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI- Auditorium Women's	150	SF	6	•	
	Doors - Wood Doors inclu hw		150	EA		10+ years	
		1st FI- Auditorium Women's		SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI- Auditorium Women's	150		6	10+ years	
	Lavatory	1st FI- Auditorium Women's	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st FI- Auditorium Women's	2	EA	6	6-10 years	
	Lighting - Wall Mounted	1st FI- Auditorium Women's	1	EA	6	6-10 years	
	Partitions	1st FI- Auditorium Women's	2	EA	7	10+ years	
	Walls - Masonry	1st FI- Auditorium Women's	166	SF	7	10+ years	
	Walls - Plaster/Drywall	1st FI- Auditorium Women's	333	SF	6	10+ years	
	Water Closet	1st FI- Auditorium Women's	2	EA	6	10+ years	
	Accessories	1st FI- Auditorium- Men's	150	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI- Auditorium- Men's	150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI- Auditorium- Men's	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI- Auditorium- Men's	150	SF	6	10+ years	
	Lavatory	1st FI- Auditorium- Men's	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st FI- Auditorium- Men's	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st FI- Auditorium- Men's	2	EA	6	6-10 years	
	Partitions	1st FI- Auditorium- Men's	2	EA	7	10+ years	
	Urinals	1st FI- Auditorium- Men's	2	EA	7	10+ years	
	Walls - Masonry	1st FI- Auditorium- Men's	166	SF	7	10+ years	
	Walls - Plaster/Drywall	1st FI- Auditorium- Men's	333	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI- Auditorium- Men's	50	SF	7	10+ years	
	Water Closet	1st FI- Auditorium- Men's	2	EA	7	10+ years	



: Main	

Catego	ry : Room		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Accessories	1st FI- By 104 (Storage)	246	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI- By 104 (Storage)	215	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st FI- By 104 (Storage)	31	SF	6	10+ years	
	Doors - Transom Window	1st FI- By 104 (Storage)	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FI- By 104 (Storage)	3	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI- By 104 (Storage)	246	SF	6	10+ years	
	Floor Drain	1st FI- By 104 (Storage)	1	EA	7	10+ years	
	Lavatory	1st FI- By 104 (Storage)	2	EA	7	10+ years	
	Lighting - Lay-in	1st FI- By 104 (Storage)	6	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st FI- By 104 (Storage)	1	EA	6	6-10 years	
	Partitions	1st FI- By 104 (Storage)	2	EA	7	10+ years	
	Urinals	1st FI- By 104 (Storage)	6	EA	7	10+ years	
	Urinals	1st FI- By 104 (Storage)	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st FI- By 104 (Storage)	700	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI- By 104 (Storage)	54	SF	7	10+ years	
	Water Closet	1st FI- By 104 (Storage)	2	EA	7	10+ years	
	Accessories	1st flr Men- next to 110	291	SF	7	6-10 years	
	Ceiling - Lay-in	1st flr Men- next to 110	255	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st flr Men- next to 110	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr Men- next to 110	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr Men- next to 110	291	SF	6	10+ years	
	Floor Drain	1st flr Men- next to 110	1	EA	7	10+ years	
	Lavatory	1st flr Men- next to 110	2	EA	7	10+ years	
	Lighting - Lay-in	1st flr Men- next to 110	6	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st flr Men- next to 110	1	EA	6	6-10 years	
	Partitions	1st flr Men- next to 110	2	EA	7	10+ years	
	Urinals	1st flr Men- next to 110	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st flr Men- next to 110	798	SF	6	10+ years	
	Water Closet	1st flr Men- next to 110	2	EA	7	10+ years	
	Accessories	3rd FIr Men faculty next to 306	291	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Flr Men faculty next to 306	291	SF	6	10+ years	
	Doors - Transom Window	3rd FIr Men faculty next to 306	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd FIr Men faculty next to 306	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd FIr Men faculty next to 306	291	SF	6	10+ years	
	Floor Drain	3rd FIr Men faculty next to 306	1	EA	7	10+ years	
	Lavatory	3rd FIr Men faculty next to 306	2	EA	7	10+ years	
	Lighting - Lay-in	3rd FIr Men faculty next to 306	4	EA	6	6-10 years	
	Partitions	3rd FIr Men faculty next to 306	4	EA	7	10+ years	
	Urinals	3rd FIr Men faculty next to 306	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Flr Men faculty next to 306	798	SF	7	10+ years	
	Water Closet	3rd Flr Men faculty next to 306	2	EA	7	10+ years	
	Accessories	4th FI North, Boys	265	SF	7	6-10 years	
	Ceiling - Lay-in	4th FI North, Boys	265	SF	6	10+ years	
	Doors - Side-lite	4th Fl North, Boys	21	SF	7	10+ years	



Group

Category : Room

Item - Type

Floor Drain

Lavatory

Partitions

Water Closet

Accessories

Floor Drain

Lavatory

Partitions

Water Closet

Accessories

Lavatory

Water Closet

Accessories

Ceiling - Plaster/Drywall

Urinals

Friedrich W von Steuben Metropolitan Science HS

5039 N Kimball AVENUE, Chicago, IL 60625 **Building : Main** Recommend Location Quantity UOM Rank Replacement Comments Doors - Transom Window 4th Fl North, Boys 16 SF 10+ vears 7 ΕA 7 Doors - Wood Doors inclu hw 4th FI North. Boys 1 10+ years Floor - Tile Ceramic/ Porcelain 4th Fl North, Boys 265 SF 6 10+ years ΕA 7 4th Fl North, Boys 1 10+ years 2 4th Fl North, Boys EΑ 7 10+ years 6 Lighting - Lay-in 4th Fl North, Boys ΕA 6 6-10 years 4th FI North, Boys 2 ΕA 7 10+ years 4th Fl North, Boys 8 ΕA 7 10+ years Walls - Structural Glazed Tile 4th FI North, Boys 760 SF 7 10+ years 4th FI North. Boys 2 ΕA 7 10+ vears 4th Fl South. Girls 350 SF 7 6-10 years Ceiling - Lay-in 4th Fl South, Girls 350 SF 6 10+ years Doors - Side-lite SF 7 4th Fl South, Girls 21 10+ years SF 7 Doors - Transom Window 4th Fl South, Girls 16 10+ years ΕA 7 Doors - Wood Doors inclu hw 4th Fl South, Girls 1 10+ years 350 SF Floor - Tile Ceramic/ Porcelain 4th FI South, Girls 6 10+ years ΕA 7 4th Fl South, Girls 1 10+ vears 4th Fl South, Girls 2 EΑ 7 10+ years Lighting - Lay-in 4th Fl South, Girls 8 EΑ 6 6-10 years 4th Fl South, Girls 9 EΑ 7 10+ years Walls - Structural Glazed Tile 4th FI South, Girls 700 SF 7 10+ years 7 4th Fl South, Girls 9 EΑ 10+ years SF 7 In Rm 103A, Engineer Restroom 23 6-10 years SF Ceiling - Plaster/Drywall In Rm 103A, Engineer Restroom 23 6 10+ years Doors - Wood Doors inclu hw In Rm 103A, Engineer Restroom ΕA 7 1 10+ years Floor - Tile Ceramic/ Porcelain In Rm 103A. Engineer Restroom 23 SF 6 10+ vears In Rm 103A, Engineer Restroom 7 1 EΑ 10+ years Lighting - Pendent/Surface In Rm 103A, Engineer Restroom 1 ΕA 6 6-10 years Walls - Plaster/Drywall SF In Rm 103A, Engineer Restroom 246 6 10+ years Walls - Plaster/Drywall In Rm 103A, Engineer Restroom 10 SF 4 1-2 years Damaged plaster/drywall 7 In Rm 103A, Engineer Restroom 1 EΑ 10+ vears In Rm 103B. Asst Engineer 42 SF 7 6-10 vears Restroom

42

2

42

1

2

240

SF

EΑ

SF

EΑ

FΑ

SF

6

7

6

7

6

6

10+ years

10+ years

10+ years

10+ years

6-10 years

10+ years

Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Lavatorv Lighting - Pendent/Surface Walls - Plaster/Drywall

In Rm 103B. Asst Engineer

In Rm 103B, Asst Engineer

In Rm 103B, Asst Engineer

In Rm 103B. Asst Engineer

In Rm 103B. Asst Engineer

In Rm 103B, Asst Engineer

Restroom

Restroom

Restroom

Restroom

Restroom



Category : Room

Friedrich W von Steuben Metropolitan Science HS 5039 N Kimball AVENUE, Chicago, IL 60625 **Building : Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ereup		Restroom	quantity				
	Walls - Plaster/Drywall	In Rm 103B, Asst Engineer Restroom	20	SF	4	0-1 year	Peeling
	Water Closet	In Rm 103B, Asst Engineer Restroom	1	EA	7	10+ years	
	Accessories	Men next to 204	259	SF	7	6-10 years	Locked and engineer has no key, previous assessment data used
	Ceiling - Lay-in	Men next to 204	229	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Men next to 204	30	SF	6	10+ years	
	Doors - Transom Window	Men next to 204	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men next to 204	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men next to 204	259	SF	6	10+ years	
	Floor Drain	Men next to 204	1	EA	7	10+ years	
	Lavatory	Men next to 204	2	EA	7	10+ years	
	Lighting - Lay-in	Men next to 204	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Men next to 204	1	EA	6	6-10 years	
	Partitions	Men next to 204	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	Men next to 204	760	SF	7	10+ years	
	Water Closet	Men next to 204	4	EA	7	10+ years	
	Accessories	Men next to 210	291	SF	7	6-10 years	Blocked off due to construction
	Ceiling - Lay-in	Men next to 210	255	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Men next to 210	36	SF	6	10+ years	
	Doors - Side-lite	Men next to 210	21	SF	7	10+ years	
	Doors - Transom Window	Men next to 210	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men next to 210	1	ĒA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men next to 210	291	SF	6	10+ years	
	Floor Drain	Men next to 210	1	EA	7	10+ years	
	Lavatory	Men next to 210	2	EA	7	10+ years	
	Lighting - Lay-in	Men next to 210	6	EA	6	6-10 years	
	Lighting - Pendent/Surface	Men next to 210	1	EA	6	6-10 years	
	Partitions	Men next to 210	2	EA	7	10+ years	
	Urinals	Men next to 210	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	Men next to 210	798	SF	7	10+ years	
	Water Closet	Men next to 210	2	EA	7	10+ years	
	Accessories	Men next to 218	246	SF	7	6-10 years	
	Ceiling - Lay-in	Men next to 218	210	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Men next to 218	36	SF	6	10+ years	
	Doors - Side-lite	Men next to 218	21	SF	7	10+ years	
	Doors - Transom Window	Men next to 218	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men next to 218	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men next to 218	246	SF	6	6-10 years	
	Floor Drain	Men next to 218	1	EA	7	10+ years	
	Lavatory	Men next to 218	2	EA	7	10+ years	
	Lighting - Lay-in	Men next to 218	4	EA	6	6-10 years	



Category : Room			Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Men next to 218	1	EA	6	6-10 years	
	Partitions	Men next to 218	2	EA	7	10+ years	
	Urinals	Men next to 218	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	Men next to 218	754	SF	7	10+ years	
	Water Closet	Men next to 218	2	EA	7	10+ years	
	Accessories	Men next to 310	291	SF	7	6-10 years	
	Ceiling - Lay-in	Men next to 310	255	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Men next to 310	36	SF	6	10+ years	
	Doors - Side-lite	Men next to 310	21	SF	7	10+ years	
	Doors - Transom Window	Men next to 310	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men next to 310	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men next to 310	291	SF	6	10+ years	
	Floor Drain	Men next to 310	1	EA	7	10+ years	
	Lavatory	Men next to 310	2	EA	7	10+ years	
	Lighting - Lay-in	Men next to 310	6	EA	6	6-10 years	
	Lighting - Pendent/Surface	Men next to 310	1	EA	6	6-10 years	
	Partitions	Men next to 310	2	EA	7	10+ years	
	Urinals	Men next to 310	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	Men next to 310	798	SF	7	10+ years	
	Water Closet	Men next to 310	2	ĒΑ	7	6-10 years	
	Accessories	Men next to 318	259	SF	7	6-10 years	
	Ceiling - Lay-in	Men next to 318	220	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Men next to 318	36	SF	6	10+ years	
	Doors - Side-lite	Men next to 318	21	SF	7	10+ years	
	Doors - Transom Window	Men next to 318	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men next to 318	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men next to 318	259	SF	6	10+ years	
	Floor Drain	Men next to 318	1	EA	7	10+ years	
	Lavatory	Men next to 318	2	EA	7	10+ years	
	Lighting - Lay-in	Men next to 318	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Men next to 318	1	EA	6	6-10 years	
	Partitions	Men next to 318	2	EA	7	10+ years	
	Urinals	Men next to 318	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	Men next to 318	760	SF	7	10+ years	
	Water Closet	Men next to 318	2	EA	7	10+ years	
	Accessories	North restroom inside 203B office	23	SF	7	6-10 years	Blocked off due to construction
	Ceiling - Plaster/Drywall	North restroom inside 200B office	23	SF	6	10+ years	
	Doors - Transom Window	North restroom inside 203B office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	North restroom inside 203B office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	North restroom inside 203B office	23	SF	6	10+ years	
	Lavatory	North restroom inside 203B office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	North restroom inside 203B office	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	North restroom inside 203B office	256	SF	6	10+ years	
	Walls - Flaster/Drywall Water Closet	North restroom inside 203B office	250	EA	7	10+ years	
			1	LA	'	IUT years	



Category : Room		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	North restroom inside 203C office	39	SF	7	6-10 years	Blocked off due to construction
	Ceiling - Plaster/Drywall	North restroom inside 203C office	39	SF	6	10+ years	
	Doors - Wood Doors inclu hw	North restroom inside 203C office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	North restroom inside 203C office	39	SF	6	10+ years	
	Lavatory	North restroom inside 203C office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	North restroom inside 203C office	1	EA	6	6-10 years	
	Partitions	North restroom inside 203C office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	North restroom inside 203C office	249	SF	6	10+ years	
	Water Closet	North restroom inside 203C office	1	EA	7	10+ years	
	Accessories	Staff Restroom next to room 208	121	SF	7	6-10 years	
	Ceiling - Lay-in	Staff Restroom next to room 208	121	SF	6	10+ years	
	Doors - Transom Window	Staff Restroom next to room 208	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff Restroom next to room 208	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Staff Restroom next to room 208	121	SF	6	10+ years	
	Lavatory	Staff Restroom next to room 208	1	EA	7	10+ years	
	Lighting - Lay-in	Staff Restroom next to room 208	2	EA	6	6-10 years	
	Partitions	Staff Restroom next to room 208	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Staff Restroom next to room 208	450	SF	6	10+ years	
	Water Closet	Staff Restroom next to room 208	2	EA	7	10+ years	
	Accessories	Staff Restroom next to room 308	121	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff Restroom next to room 308	121	SF	6	10+ years	
	Doors - Transom Window	Staff Restroom next to room 308	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff Restroom next to room 308	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Staff Restroom next to room 308	121	SF	6	10+ years	
	Lavatory	Staff Restroom next to room 308	1	EA	7	6-10 years	
	Lighting - Lay-in	Staff Restroom next to room 308	2	EA	6	6-10 years	
	Partitions	Staff Restroom next to room 308	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Staff Restroom next to room 308	450	SF	6	10+ years	
	Water Closet	Staff Restroom next to room 308	2	EA	7	6-10 years	
	Accessories	Women across from 307	355	SF	7	6-10 years	
	Ceiling - Lay-in	Women across from 307	319	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Women across from 307	36	SF	6	10+ years	
	Doors - Side-lite	Women across from 307	21	SF	7	10+ years	
	Doors - Transom Window	Women across from 307	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Women across from 307	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women across from 307	355	SF	6	10+ years	
	Floor Drain	Women across from 307	1	EA	7	10+ years	
		Women across from 307	2	EA	7	10+ years	
	Lavatory Lighting - Lay-in	Women across from 307	2	EA	6	6-10 years	
		Women across from 307	3	EA	6	6-10 years	
	Lighting - Pendent/Surface						
	Partitions	Women across from 307	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	Women across from 307	805	SF	7	10+ years	
	Water Closet	Women across from 307	4	EA	7	10+ years	
	Accessories	Women next to 208B	276	SF	7	6-10 years	



Category : Room **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Ceiling - Lay-in Women next to 208B 240 SF 6 10+ vears Ceiling - Plaster/Drywall SF 6 Women next to 208B 36 10+ years Doors - Side-lite Women next to 208B 21 SF 7 10+ years Doors - Transom Window SF 7 Women next to 208B 16 10+ years Doors - Wood Doors inclu hw Women next to 208B 1 EΑ 7 10+ years SF 276 Floor - Tile Ceramic/ Porcelain Women next to 208B 6 10+ years Floor Drain ΕA 7 Women next to 208B 1 10+ years 10+ years Lavatory Women next to 208B 2 EΑ 7 Lighting - Lay-in Women next to 208B 6 ΕA 6 6-10 years Lighting - Pendent/Surface 1 FΑ 6 6-10 years Women next to 208B Partitions Women next to 208B 4 ΕA 7 10+ vears Walls - Structural Glazed Tile Women next to 208B 778 SF 7 10+ years Water Closet ΕA 7 Women next to 208B 4 10+ years SF 7 Accessories Women next to 220 338 6-10 years SF Ceiling - Lay-in Women next to 220 302 6 10+ years Ceiling - Plaster/Drywall SF 6 Women next to 220 36 10+ years SF 7 Doors - Side-lite Women next to 220 21 10+ years SF Doors - Transom Window Women next to 220 16 7 10+ years ΕA Doors - Wood Doors inclu hw Women next to 220 1 7 10+ vears Floor - Tile Ceramic/ Porcelain Women next to 220 338 SF 6 10+ years Floor Drain Women next to 220 1 ΕA 7 10+ years 2 7 10+ years Lavatory Women next to 220 EΑ 8 ΕA Lighting - Lay-in Women next to 220 6 6-10 years Lighting - Pendent/Surface Women next to 220 1 FΑ 6 6-10 years 4 ΕA 7 Partitions Women next to 220 10+ years SF Walls - Structural Glazed Tile Women next to 220 778 7 10+ vears Water Closet Women next to 220 EΑ 7 10+ years 4 355 SF 7 6-10 years Accessories Women next to 320 SF Ceiling - Lay-in Women next to 320 319 6 10+ years Ceiling - Plaster/Drywall Women next to 320 36 SF 6 10+ years Doors - Side-lite SF Women next to 320 21 7 10+ vears Doors - Transom Window SF Women next to 320 16 7 10+ vears FΑ 7 Doors - Wood Doors inclu hw Women next to 320 1 10+ years Floor - Tile Ceramic/ Porcelain Women next to 320 355 SF 7 6-10 years Floor Drain 7 Women next to 320 1 EΑ 10+ years 2 ΕA 7 Lavatory Women next to 320 10+ years Lighting - Lay-in Women next to 320 8 EΑ 6 6-10 years Lighting - Pendent/Surface ΕA Women next to 320 1 6 6-10 years Partitions Women next to 320 4 EΑ 7 10+ years SF Walls - Structural Glazed Tile Women next to 320 805 7 10+ vears Water Closet Women next to 320 4 EΑ 7 10+ years Category : Classroom Building : Main Group Item - Type Location UOM Rank Quantity Recommend Comments

Schools						5039 N Kimball AVENUE, Chicago, IL 60			
			Replacement						
assroom #101 (Regular Classroom)									
AC Units	1st Floor	1	EA	7	6-10 years				
Casework	1st Floor	8	LF	7	10+ years				
Ceiling - Lay-in	1st Floor	724	SF	6	10+ years				
Chalk Board	1st Floor	20	LF	4	2-5 years				
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years				
Floor - Terrazzo	1st Floor	6	SF	6	10+ years				
Floor - Wood	1st Floor	723	SF	6	10+ years				
Lighting - Lay-in	1st Floor	14	EA	6	6-10 years				
Marker Board	1st Floor	16	LF	7	6-10 years				
Walls - Plaster/Drywall	1st Floor	899	SF	6	10+ years				
Walls - Plaster/Drywall	1st Floor	10	SF	4	1-2 years	Peeling			
ssroom #102 (Regular Classroom)									
AC Units	1st Floor	1	EA	7	6-10 years				
Casework	1st Floor	8	LF	6	10+ years				
Ceiling - Lay-in	1st Floor	730	SF	6	10+ years				
Chalk Board	1st Floor	22	LF	4	2-5 years				
Doors - Transom Window	1st Floor		SF	7	10+ years				
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years				
Floor - Terrazzo	1st Floor	7	SF	6	10+ years				
Floor - Wood	1st Floor	723	SF	6	10+ years				
Lighting - Lay-in	1st Floor	14	EA	6	6-10 years				
Marker Board	1st Floor	14	LF	7	6-10 years				
Walls - Plaster/Drywall	1st Floor	1,030	SF	6	10+ years				
ssroom #104 (Regular Classroom)									
AC Units	1st Floor	2	EA	7	6-10 years				
Casework	1st Floor	8	LF	6	10+ years				
Casework Ceiling - Lay-in	1st Floor		SF		-				
		725	LF	6 4	10+ years				
Chalk Board Doors - Transom Window	1st Floor 1st Floor	22 9	SF	4 7	2-5 years				
Doors - Wood Doors inclu hw			EA		10+ years				
	1st Floor	2		7	10+ years				
Floor - Terrazzo	1st Floor	7	SF	6	10+ years				
Floor - Wood	1st Floor	725	SF	6	10+ years				
Lighting - Lay-in	1st Floor	14	EA	6	6-10 years				
Marker Board	1st Floor	22	LF	7	6-10 years				
Walls - Plaster/Drywall	1st Floor	909	SF	6	10+ years				
Work Sink	1st Floor	1	EA	7	10+ years				
ssroom #106 (Regular Classroom)									
AC Units	1st Floor	2	EA	7	6-10 years				
Casework	1st Floor	8	LF	6	10+ years				
Ceiling - Lay-in	1st Floor	780	SF	6	10+ years				
Chalk Board	1st Floor	32	LF	4	2-5 years				



	Chicago Public
XT	Public Schools

					Replacement	
Doors - Transom Window	1st Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
Floor - Terrazzo	1st Floor	7	SF	6	10+ years	
Floor - Tile	1st Floor	773	SF	6	10+ years	
Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
Marker Board	1st Floor	24	LF	7	6-10 years	
Walls - Plaster/Drywall	1st Floor	1,077	SF	6	10+ years	
Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #116 (Computer Lab)						
AC Units	1st Floor	2	EA	7	6-10 years	
Casework	1st Floor	- 8	LF	6	10+ years	
Ceiling - Lay-in	1st Floor	896	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
Floor - Terrazzo	1st Floor	7	SF	6	10+ years	
Floor - Wood	1st Floor	889	SF	6	10+ years	
Lighting - Lay-in	1st Floor	27	EA	6	6-10 years	
Marker Board	1st Floor	6	LF	7	6-10 years	
	1st Floor	-	SF	6		
Walls - Plaster/Drywall		1,040	эг	0	10+ years	
Classroom #118 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	7	LF	6	10+ years	
Ceiling - Lay-in	1st Floor	496	SF	6	10+ years	
Chalk Board	1st Floor	11	LF	4	2-5 years	
Doors - Transom Window	1st Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	496	SF	6	10+ years	
Lighting - Lay-in	1st Floor	8	EA	6	6-10 years	
Marker Board	1st Floor	22	LF	7	6-10 years	
Walls - Plaster/Drywall	1st Floor	688	SF	6	10+ years	
<u>Classroom #120 (Regular Classroom)</u>						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	7	LF	6	10+ years	
Ceiling - Lay-in	1st Floor	496	SF	6	10+ years	
Doors - Transom Window	1st Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Terrazzo	1st Floor	7	SF	6	10+ years	
Floor - Tile	1st Floor	489	SF	6	10+ years	
Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
Marker Board	1st Floor	18	LF	7	6-10 years	
Walls - Plaster/Drywall	1st Floor	668	SF	6	10+ years	
Walls - Plaster/Drywall	1st Floor	20	SF	4	0-1 year	Hole/damaged
Walls Thater, Drywall	13(1100)	20	01	т	0 i youi	nois, damayou

Public Schools			Fried			en Metropolitan Science
					Replacement	
ssroom #122 (Regular Classroom)						
AC Units	1st Floor	2	EA	7	6-10 years	
Casework	1st Floor	11	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	962	SF	6	10+ years	
Chalk Board	1st Floor	22	LF	4	2-5 years	
Doors - Transom Window	1st Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
Floor - Terrazzo	1st Floor	7	SF	6	10+ years	
Floor - Tile	1st Floor	955	SF	6	10+ years	
Lighting - Lay-in	1st Floor	27	EA	6	6-10 years	
Marker Board	1st Floor	15	LF	7	6-10 years	
Walls - Plaster/Drywall	1st Floor	1,027	SF	6	10+ years	
sroom #124 (Regular Classroom)						
AC Units	1st Floor	2	EA	7	6-10 years	
Casework	1st Floor	11	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	1,017	SF	6	10+ years	
Doors - Transom Window	1st Floor	9	SF	7	10+ years	
Doors - Transom Window	1st Floor	18	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	-	
Floor - Terrazzo		7	SF		10+ years	
Floor - Wood	1st Floor		SF	6	10+ years	
	1st Floor	1,010		6	10+ years	
Lighting - Lay-in	1st Floor	18	EA	1	6-10 years	
Marker Board	1st Floor	21	LF	7	6-10 years	
Walls - Plaster/Drywall	1st Floor	1,033	SF	6	10+ years	
Walls - Plaster/Drywall	1st Floor	26	SF	5	1-2 years	Peeling
Work Sink	1st Floor	2	EA	7	10+ years	
sroom #201 (Regular Classroom)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Casework	2nd Floor	8	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
Chalk Board	2nd Floor	30	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Wood	2nd Floor	713	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
Marker Board	2nd Floor	15	LF	7	6-10 years	
Walls - Plaster/Drywall	2nd Floor	909	SF	6	10+ years	
sroom #202 (Regular Classroom)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Casework	2nd Floor	8	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	



5CI 10013					5039	N KIMDAII AVENUE, Chicago, IL 60625
					Replacement	
Chalk Board	2nd Floor	5	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Wood	2nd Floor	723	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
Marker Board	2nd Floor	16	LF	7	6-10 years	
Walls - Plaster/Drywall	2nd Floor	1,030	SF	6	10+ years	
Classroom #204 (Regular Classroom)						
	2nd Floor	3		7	6.10 years	
AC Units		2	EA	7	6-10 years	
Casework	2nd Floor	8	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Wood	2nd Floor	713	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
Marker Board	2nd Floor	15	LF	7	6-10 years	
Walls - Plaster/Drywall	2nd Floor	909	SF	6	10+ years	
Classroom #206 (Regular Classroom)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Casework	2nd Floor	8	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	o 716	SF	6	-	
Chalk Board			LF	4	10+ years	
	2nd Floor	10			2-5 years	
Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Tile	2nd Floor	709	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
Marker Board	2nd Floor	6	LF	7	6-10 years	
Walls - Plaster/Drywall	2nd Floor	909	SF	6	10+ years	
Classroom #209 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	8	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	703	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Tile	2nd Floor	696	SF	6	6-10 years	
Lighting - Lay-in	2nd Floor	21	EA	6	6-10 years	
Marker Board	2nd Floor 2nd Floor		LF	6 7		
		8	SF	-	6-10 years	
Walls - Plaster/Drywall	2nd Floor	893	35	6	10+ years	



					Replacement	
Classroom #210 (Regular Classroom)					•	
AC Units	2nd Floor	1	EA	7	6-10 years	Under construction, previous assessment assessment data was used
Casework	2nd Floor	26	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	726	SF	6	10+ years	
Chalk Board	2nd Floor	38	LF	4	2-5 years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Wood	2nd Floor	719	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
Walls - Plaster/Drywall	2nd Floor	907	SF	6	10+ years	
Walls - Plaster/Drywall	2nd Floor	2	SF	5	1-2 years	Damaged
Classroom #211 (Regular Classroom)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Casework	2nd Floor	8	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Tile	2nd Floor	713	SF	6	6-10 years	
Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
Marker Board	2nd Floor	12	LF	7	6-10 years	
Walls - Plaster/Drywall	2nd Floor	909	SF	6	10+ years	
Classroom #212 (Computer Lab)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Casework	2nd Floor	26	LF	7	10+ years	
Ceiling - Lay-in	2nd Floor	1,097	SF	6	10+ years	
Ceiling - Lay-in	2nd Floor	20	SF	5	1-2 years	Missing tile
Chalk Board	2nd Floor	12	LF	4	2-5 years	•
Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Tile	2nd Floor	1,110	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	20	EA	6	6-10 years	
Walls - Plaster/Drywall	2nd Floor	1,145	SF	6	10+ years	
Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroom #213 (Computer Lab)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Casework	2nd Floor	11	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	716	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Tile	2nd Floor	709	SF	6	10+ years	



XC Schools						5	6039 N Kimball AVENUE, Chicago, IL 60625
						Replacement	
Lighting	g - Lay-in	2nd Floor	18	EA	6	6-10 years	
Marker	r Board	2nd Floor	10	LF	7	6-10 years	
Walls -	- Plaster/Drywall	2nd Floor	909	SF	6	10+ years	
	2					2	
Classroom #214	(Office)						
AC Uni		2nd Floor	1	EA	7	6-10 years	
Casew	vork	2nd Floor	10	LF	6	10+ years	
	g - Lay-in	2nd Floor	430	SF	6	10+ years	
Doors	- Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor -		2nd Floor	423	SF	6	6-10 years	
	ig - Lay-in	2nd Floor	6	EA	6	6-10 years	
Walls -	- Plaster/Drywall	2nd Floor	644	SF	6	10+ years	
valis		21011001	044	01	0	Tor years	
Classroom #215	(Science Lab Level 2)						
AC Uni		2nd Floor	2	EA	7	6-10 years	Under construction, previous
						,	assessment assessment data was
							used
Casew	vork	2nd Floor	20	LF	6	10+ years	
Ceiling	g - Lay-in	2nd Floor	1,095	SF	6	10+ years	
Chalk I		2nd Floor	48	LF	4	2-5 years	
	- Transom Window	2nd Floor	18	SF	7	10+ years	
Doors -	- Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	ash Station	2nd Floor	1	EA	7	10+ years	
Floor -		2nd Floor	1,095	SF	6	10+ years	
Gas Li		2nd Floor	5	ĒA	6	10+ years	
Lightin	g - Lay-in	2nd Floor	22	EA	6	6-10 years	
	the Lab Elements	2nd Floor	1.095	SF	7	6-10 years	
	- Plaster/Drywall	2nd Floor	1,119	SF	6	10+ years	
	- Plaster/Drywall	2nd Floor	26	SF	5	1-2 years	Damaged
Work S	•	2nd Floor	3	EA	7	10+ years	2 4
				_/ \	•	.e. jeule	
Classroom #216	(Regular Classroom)						
AC Uni		2nd Floor	2	EA	7	6-10 years	
Casew		2nd Floor	14	LF	6	10+ years	
	g - Lay-in	2nd Floor	1,185	SF	6	10+ years	
Chalk I		2nd Floor	48	LF	4	2-5 years	
	- Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor -		2nd Floor	1,178	SF	6	6-10 years	
	ig - Lay-in	2nd Floor	33	EA	6	6-10 years	
	- Plaster/Drywall	2nd Floor	1,175	SF	6	10+ years	
	-					-	
Classroom #217	(Regular Classroom)						
AC Uni	its	2nd Floor	1	EA	7	6-10 years	



XUR Schools							N Kimball AVENUE, Chicago, IL 60625
						Replacement	
Casew	vork	2nd Floor	24	LF	7	10+ years	
Ceiling	g - Lay-in	2nd Floor	745	SF	6	10+ years	
Chalk	Board	2nd Floor	16	LF	4	2-5 years	
Doors	- Transom Window	2nd Floor	9	SF	7	10+ years	
Doors	- Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor -	Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor -		2nd Floor	738	SF	6	10+ years	
	ng - Lay-in	2nd Floor	21	EA	6	6-10 years	
	r Board	2nd Floor	8	LF	7	6-10 years	
	- Plaster/Drywall	2nd Floor	1,060	SF	6	10+ years	
Work S		2nd Floor	1,000	EA	7	10+ years	
Classroom #218	(Regular Classroom)						
AC Un	, S	2nd Floor	1	EA	7	6-10 years	
Casew		2nd Floor	8	LF	6	10+ years	
	g - Lay-in	2nd Floor	787	SF	6	10+ years	
Cening Chalk		2nd Floor		LF	4	2-5 years	
			8			•	
	- Transom Window	2nd Floor	18	SF	7	10+ years	
	- Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Wood	2nd Floor	787	SF	6	10+ years	
	ng Lay-in	2nd Floor	14	EA	6	6-10 years	
	r Board	2nd Floor	34	LF	7	6-10 years	
Walls -	- Plaster/Drywall	2nd Floor	1,103	SF	6	10+ years	
Classroom #219	(Regular Classroom)						
AC Un	nits	2nd Floor	2	EA	7	6-10 years	
Casew	vork	2nd Floor	3	LF	6	10+ years	
	g - Lay-in	2nd Floor	720	SF	6	10+ years	
Chalk		2nd Floor	26	LF	4	2-5 years	
	- Transom Window	2nd Floor	9	SF	7	10+ years	
	- Wood Doors inclu hw	2nd Floor	3 1	EA	7	10+ years	
	· Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor -		2nd Floor	713	SF	6	10+ years	
	ig - Lay-in	2nd Floor	21	EA	7	6-10 years	
				LF	7	•	
	r Board - Plaster/Drywall	2nd Floor 2nd Floor	10 909	SF	7	6-10 years	
waiis -	- Plastel/Drywall	2110 11001	909	эг	1	10+ years	
	(Regular Classroom)						
AC Un		2nd Floor	2	EA	7	6-10 years	
Casew		2nd Floor	11	LF	7	10+ years	
	g - Lay-in	2nd Floor	962	SF	6	10+ years	
Chalk		2nd Floor	26	LF	4	2-5 years	
Doors	- Transom Window	2nd Floor	9	SF	7	10+ years	
Doors	- Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor -	Wood	2nd Floor	962	SF	6	10+ years	
Lightin	ig - Lay-in	2nd Floor	18	EA	6	6-10 years	
0							



Schools						N Kimball AVENUE, Chicago, IL 6062
					Replacement	
Marker Board	2nd Floor	15	LF	7	6-10 years	
Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years	
Work Sink	2nd Floor	1	EA	7	10+ years	
Classroom #222 (Regular Classroom)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Casework	2nd Floor	11	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	972	SF	6	10+ years	
Chalk Board	2nd Floor	8	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor - Wood	2nd Floor	972	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
Marker Board	2nd Floor	20	LF	7	6-10 years	
Walls - Plaster/Drywall	2nd Floor	1,014	SF	6	10+ years	
Walls - Thaster/Drywall	21011001	1,014	01	0	TO+ years	
Classroom #224 (Regular Classroom)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Casework	2nd Floor	29	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	1,092	SF	6	10+ years	
Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	7	SF	6	10+ years	
Floor - Wood	2nd Floor	, 1,085	SF	6	10+ years	
				-		
Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	22	EA LF	6 7	6-10 years	
		16	SF	6	6-10 years	
Walls - Plaster/Drywall	2nd Floor	1,149	SF	6	10+ years	
Classroom #301 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	8	LF	7	10+ years	
Ceiling - Lay-in	3rd Floor	720	SF	6	10+ years	
Chalk Board	3rd Floor	30	LF	4	2-5 years	
Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
Floor - Terrazzo	3rd Floor	7	SF	6	10+ years	
Floor - Wood	3rd Floor	713	SF	6	10+ years	
Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
Marker Board	3rd Floor	20		7	6-10 years	
Walls - Plaster/Drywall	3rd Floor	20 950	SF	6	10+ years	
Walls - Structural Glazed Tile			SF	7		
Waiis - Structural Giazeu Tile	3rd Floor	26	эг	1	10+ years	
Classroom #302 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
		•	_, ,	•	, • • • •	


Schools					503	89 N Kimball AVENUE, Chicago, IL 60625
					Replacement	
Casework	3rd Floor	8	LF	7	10+ years	
Ceiling - Lay-in	3rd Floor	720	SF	6	10+ years	
Chalk Board	3rd Floor	25	LF	4	2-5 years	
Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
Floor - Terrazzo	3rd Floor	7	SF	6	10+ years	
Floor - Wood	3rd Floor	713	SF	6	10+ years	
Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
Marker Board	3rd Floor	20	LF	7	6-10 years	
Walls - Plaster/Drywall	3rd Floor	706	SF	6	10+ years	
Walls - Plaster/Drywall	3rd Floor	244	SF	5	1-2 years	
Walls - Structural Glazed Tile	3rd Floor	26	SF	6	10+ years	
Classroom #303 (Choral Room)						
AC Units	3rd Floor	2	EA	7	6-10 years	
Casework	3rd Floor	10	LF	7	10+ years	
	3rd Floor		SF		•	
Ceiling - Plaster/Drywall		1,148		6	10+ years	
Ceiling - Splined	3rd Floor	383	SF	6	10+ years	
Chalk Board	3rd Floor	24	LF	4	2-5 years	
Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
Floor - Wood	3rd Floor	1,531	SF	6	10+ years	
Lighting - Lay-in	3rd Floor	24	EA	6	6-10 years	
Risers	3rd Floor	224	LF	7	10+ years	
Sound System	3rd Floor	1	EA	7	6-10 years	
Walls - Plaster/Drywall	3rd Floor	1,764	SF	6	10+ years	
Classroom #304 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	8	LF	7	10+ years	
Ceiling - Lay-in	3rd Floor	720	SF	6	10+ years	
Chalk Board	3rd Floor	6	LF	4	2-5 years	
Doors - Transom Window	3rd Floor	28	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	7	10+ years	
Floor - Terrazzo	3rd Floor	7	SF	6	10+ years	
Floor - Wood	3rd Floor	713	SF	6	10+ years	
Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
Marker Board	3rd Floor	20	LF	7	6-10 years	
Walls - Plaster/Drywall	3rd Floor	950	SF	6	10+ years	
Classroom #305 (Band Room)						
AC Units	3rd Floor	3	EA	7	6-10 years	
Casework	3rd Floor	10	LF	7	10+ years	
Ceiling - Lay-in	3rd Floor	1,754	SF	6	10+ years	
			LF		•	
Chalk Board Doors - Transom Window	3rd Floor 3rd Floor	4 9	SF	4 7	2-5 years	
	310 1001	9	эг	(10+ years	



Friedrich W von Steuben Metropolitan Science HS 5039 N Kimball AVENUE, Chicago, IL 60625

Donlog


Dears Transam Window					Replacement	
Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
Floor - Wood	3rd Floor	1,754	SF	6	10+ years	
Instrument Storage Casework	3rd Floor	100	LF	7	10+ years	
Lighting - Lay-in	3rd Floor	24	EA	6	6-10 years	
Marker Board	3rd Floor	4	LF	7	6-10 years	
Sound System	3rd Floor	1	EA	7	6-10 years	
Storage/ Closet	3rd Floor	30	SF	7	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,680	SF	6	10+ years	
Classroom #306 (Faculty Lounge)						
AC Units	3rd Floor	2	EA	7	6-10 years	
Casework	3rd Floor	8	LF	7	10+ years	
Ceiling - Lay-in	3rd Floor	720	SF	6		
Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
Floor - Tile	3rd Floor	720	SF	6	10+ years	
				-	6-10 years	
Lighting - Lay-in	3rd Floor	14	EA SF	6	6-10 years	
Walls - Plaster/Drywall Work Sink	3rd Floor	950	SF EA	6	10+ years	
WORK SINK	3rd Floor	1	EA	7	6-10 years	
Classroom #309 (Science Lab Level 3)						
AC Units	3rd Floor	2	EA	7	6-10 years	Room under construction
AC Units Ceiling - Lay-in	3rd Floor 3rd Floor	2 1,075	EA SF	7 7	6-10 years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board						Room under construction
Ceiling - Lay-in	3rd Floor	1,075	SF	7	10+ years	Room under construction
Ceiling - Lay-in Chalk Board	3rd Floor 3rd Floor	1,075 16	SF LF	7 4	10+ years 2-5 years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window	3rd Floor 3rd Floor 3rd Floor	1,075 16 9	SF LF SF	7 4 7	10+ years 2-5 years 10+ years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window	3rd Floor 3rd Floor 3rd Floor 3rd Floor	1,075 16 9 18	SF LF SF SF	7 4 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	1,075 16 9 18	SF LF SF SF EA	7 4 7 7 7	10+ years 2-5 years 10+ years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	1,075 16 9 18 2 1 7	SF LF SF EA EA	7 4 7 7 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station Floor - Terrazzo	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	1,075 16 9 18 2 1	SF LF SF EA EA SF	7 4 7 7 7 6	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station Floor - Terrazzo Floor - Tile Gas Line	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	1,075 16 9 18 2 1 7 1,068	SF SF SF EA SF SF	7 4 7 7 7 6 6 7	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station Floor - Terrazzo Floor - Tile Gas Line Lighting - Lay-in	3rd Floor 3rd Floor	1,075 16 9 18 2 1 7 1,068 18 17	SF SF EA EA SF SF EA	7 4 7 7 7 6 6 7 6	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station Floor - Terrazzo Floor - Tile Gas Line Lighting - Lay-in Marker Board	3rd Floor 3rd Floor	1,075 16 9 18 2 1 7 1,068 18 17 32	SF LF SF EA SF EA EA LF	7 4 7 7 7 6 6 7 6 7	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station Floor - Terrazzo Floor - Tile Gas Line Lighting - Lay-in	3rd Floor 3rd Floor	1,075 16 9 18 2 1 7 1,068 18 17	SF LF SF EA SF EA LF SF	7 4 7 7 7 6 6 7 6 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station Floor - Terrazzo Floor - Tile Gas Line Lighting - Lay-in Marker Board Science Lab Elements	3rd Floor 3rd Floor	1,075 16 9 18 2 1 7 1,068 18 17 32 1,075	SF LF SF EA SF EA LF SF EA	7 4 7 7 7 6 6 7 6 7 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station Floor - Terrazzo Floor - Tile Gas Line Lighting - Lay-in Marker Board Science Lab Elements Science Lab Fume Hood Science Lab Shower	3rd Floor 3rd Floor	1,075 16 9 18 2 1 7 1,068 18 17 32 1,075 1 1	SF LF SF EA SF EA SF EA LF EA EA	7 4 7 7 7 6 6 7 6 7 7 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station Floor - Terrazzo Floor - Tile Gas Line Lighting - Lay-in Marker Board Science Lab Elements Science Lab Fume Hood Science Lab Shower Storage/ Closet	3rd Floor 3rd Floor	1,075 16 9 18 2 1 7 1,068 18 17 32 1,075 1 1 72	SF SF SF EA SF EA SF EA SF EA SF	7 4 7 7 7 6 6 7 6 7 7 7 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	Room under construction
Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Eye Wash Station Floor - Terrazzo Floor - Tile Gas Line Lighting - Lay-in Marker Board Science Lab Elements Science Lab Fume Hood Science Lab Shower	3rd Floor 3rd Floor	1,075 16 9 18 2 1 7 1,068 18 17 32 1,075 1 1	SF LF SF EA SF EA SF EA LF EA EA	7 4 7 7 7 6 6 7 6 7 7 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Room under construction



Chicaao



ALLA SCHOOIS					5039 1	N Kimball AVENUE, Chicago, IL 60625
					Replacement	
Casework	3rd Floor	8	LF	7	10+ years	
Ceiling - Lay-in	3rd Floor	426	SF	6	10+ years	
Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
Floor - Tile	3rd Floor	426	SF	6	6-10 years	
Lighting - Lay-in	3rd Floor	6	EA	6	6-10 years	
Marker Board	3rd Floor	16	LF	7	6-10 years	
Walls - Plaster/Drywall	3rd Floor	770	SF	6	10+ years	
Classroom #315 (Science Lab Level 3)						
AC Units	3rd Floor	2	EA	7	6-10 years	
Ceiling - Lay-in	3rd Floor	1,075	SF	6	10+ years	
Doors - Transom Window	3rd Floor		SF			
		9		7	10+ years	
Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
Eye Wash Station	3rd Floor	1	EA	7	10+ years	
Floor - Terrazzo	3rd Floor	7	SF	6	10+ years	
Floor - Tile	3rd Floor	1,068	SF	6	6-10 years	
Gas Line	3rd Floor	5	EA	7	10+ years	
Lighting - Lay-in	3rd Floor	31	EA	7	6-10 years	
Marker Board	3rd Floor	20	LF	7	6-10 years	
Science Lab Elements	3rd Floor	1,075	SF	7	10+ years	
Storage/ Closet	3rd Floor	35	SF	7	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,240	SF	7	10+ years	
Walls - Structural Glazed Tile	3rd Floor	26	SF	7	10+ years	
Work Sink	3rd Floor	3	EA	7	6-10 years	
Classroom #316 (Regular Classroom)						
AC Units	3rd Floor	2	EA	7	6-10 years	
Casework	3rd Floor	12	LF	7	10+ years	
Ceiling - Lay-in	3rd Floor	1,107	SF	6	10+ years	
Chalk Board	3rd Floor	50	LF	4	2-5 years	
Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
Floor - Terrazzo	3rd Floor	- 7	SF	6	10+ years	
Floor - Wood	3rd Floor	1,100	SF	6	10+ years	
Lighting - Lay-in	3rd Floor	22	EA	6	6-10 years	
Marker Board	3rd Floor	30	LF	7	6-10 years	
Walls - Plaster/Drywall	3rd Floor	1,230	SF	6	10+ years	
	3rd Floor		SF	7		
Walls - Structural Glazed Tile		26		7	10+ years	
Work Sink	3rd Floor	2	EA	1	6-10 years	
Classroom #317 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	8	LF	7	10+ years	



Chicago

Public Schools



SCHOOIS						503	9 N Kimball AVENUE, Chicago, IL 606
						Replacement	
Ceiling - Lay-in		3rd Floor	800	SF	6	10+ years	
Chalk Board		3rd Floor	12	LF	4	2-5 years	
Doors - Transon	n Window	3rd Floor	16	SF	7	10+ years	
Doors - Transon	n Window	3rd Floor	9	SF	7	10+ years	
Doors - Wood D		3rd Floor	2	ĒA	7	10+ years	
Floor - Terrazzo		3rd Floor	- 7	SF	6	10+ years	
Floor - Wood		3rd Floor	793	SF	6	10+ years	
Lighting - Lay-ir	,	3rd Floor	14	EA	6	6-10 years	
Marker Board	1	3rd Floor	12	LA	7	6-10 years	
Walls - Plaster/E		3rd Floor		SF	6	,	
			1,020			10+ years	
Walls - Structura	al Giazed The	3rd Floor	26	SF	7	10+ years	
Classroom #322 (Art Roon	n)						
AC Units		3rd Floor	2	EA	7	6-10 years	
Casework		3rd Floor	50	LF	7	10+ years	
Ceiling - Lay-in		3rd Floor	1,075	SF	6	10+ years	
Doors - Transon	n Window	3rd Floor	9	SF	7	10+ years	
Doors - Transon		3rd Floor	27	SF	7	10+ years	
Doors - Wood D		3rd Floor	3	EA	7	10+ years	
Floor - Terrazzo		3rd Floor	3	SF	6		
			1,068	-	-	10+ years	
Floor - Wood		3rd Floor		SF	6	10+ years	
Lighting - Lay-ir		3rd Floor	20	EA	6	6-10 years	
Walls - Plaster/D		3rd Floor	120	SF	6	10+ years	
Walls - Structura	al Glazed Tile	3rd Floor	26	SF	7	10+ years	
Work Sink		3rd Floor	2	EA	7	6-10 years	
Classroom #324 (Art Roon	ר)						
AC Units	/	3rd Floor	2	EA	7	6-10 years	
Casework		3rd Floor	40	LF	7	10+ years	
Ceiling - Lay-in		3rd Floor	1,075	SF	6	10+ years	
Chalk Board		3rd Floor	20	LF	4	2-5 years	
Doors - Transon	Window	3rd Floor	9	SF	7	10+ years	
Doors - Transon		3rd Floor	18	SF	7	10+ years	
Doors - Wood D		3rd Floor	2	EA	7	,	
						10+ years	
Floor - Terrazzo		3rd Floor	7	SF	6	10+ years	
Floor - Wood		3rd Floor	1,068	SF	6	10+ years	
Lighting - Lay-ir	1	3rd Floor	20	EA	7	6-10 years	
Marker Board		3rd Floor	20	LF	7	6-10 years	
Storage/ Closet		3rd Floor	362	SF	7	10+ years	
Walls - Plaster/D		3rd Floor	1,200	SF	6	10+ years	
Walls - Structura	al Glazed Tile	3rd Floor	26	SF	6	10+ years	
Work Sink		3rd Floor	4	EA	7	6-10 years	
Classroom #409 (Science	l ab l evel 1)						
AC Units		4th Floor	2	EA	7	6-10 years	
Casework		4th Floor	25	LF	7	10+ years	



Deplese

		-				
AC Units	4th Floor	2	EA	7	6-10 years	
Classroom #413 (Science Lab Level 1)						
Walls - Structural Glazed Tile	4th Floor	6	SF	7	10+ years	
Walls - Plaster/Drywall	4th Floor	950	SF	6	10+ years	
Marker Board	4th Floor	20	LF	7	6-10 years	
Lighting - Lay-in	4th Floor	14	EA	6	6-10 years	
Floor - Wood	4th Floor	713	SF	6	10+ years	
Floor - Terrazzo	4th Floor	7	SF	6	10+ years	
Doors - Wood Doors inclu hw	4th Floor	2	EA	7	10+ years	
Doors - Transom Window	4th Floor	18	SF	7	10+ years	
Doors - Transom Window	4th Floor	9	SF	7	10+ years	
Chalk Board	4th Floor	20	LF	4	2-5 years	
Ceiling - Lay-in	4th Floor	720	SF	6	10+ years	
Casework	4th Floor	20		7	10+ years	
		1	EA LF	7	6-10 years	
ssroom #412 (Regular Classroom) AC Units	4th Floor		EA	7	6 10 years	
Walls - Structural Glazed Tile	4th Floor	26	SF	7	10+ years	
Walls - Plaster/Drywall	4th Floor	950	SF	6	10+ years	
Marker Board	4th Floor	20	LF	7	6-10 years	
Lighting - Lay-in	4th Floor	14	EA	7	6-10 years	
Floor - Wood	4th Floor	713	SF	6	10+ years	
Floor - Terrazzo	4th Floor	7	SF	6	10+ years	
Doors - Wood Doors inclu hw	4th Floor	2	EA	7	10+ years	
Doors - Transom Window	4th Floor	9	SF	7	10+ years	
Doors - Transom Window	4th Floor	18	SF	7	10+ years	
Chalk Board	4th Floor	20	LF	4	2-5 years	
Ceiling - Lay-in	4th Floor	720	SF	6	10+ years	
Casework	4th Floor	20	LF	7	10+ years	
AC Units	4th Floor	1	EA	7	6-10 years	
ssroom #410 (Regular Classroom)			<u></u>	7	0.40	
Work Sink	4th Floor	1	EA	7	6-10 years	
Walls - Structural Glazed Tile	4th Floor	26	SF	7	10+ years	
Walls - Plaster/Drywall	4th Floor	1,086	SF	6	10+ years	
Science Lab Fume Hood	4th Floor	1	EA	7	10+ years	
Science Lab Elements	4th Floor	972	SF	7	10+ years	
Marker Board	4th Floor	56	LF	7	6-10 years	
Lighting - Lay-in	4th Floor	18	EA	6	6-10 years	
Floor - Tile	4th Floor	965	SF	6	10+ years	
Floor - Terrazzo	4th Floor	7	SF	6	10+ years	
Doors - Wood Doors inclu hw	4th Floor	2	EA	7	10+ years	
Doors - Transom Window	4th Floor	9	SF	7	10+ years	
Doors - Transom Window	4th Floor	18	SF	7	10+ years	
		-				
Ceiling - Lay-in	4th Floor	972	SF	6	Replacement 10+ years	



						Replacement	
	Ceiling - Lay-in	4th Floor	972	SF	6	10+ years	
	Doors - Transom Window	4th Floor	9	SF	7	10+ years	
	Doors - Transom Window	4th Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw		2	EA	7		
		4th Floor	2			10+ years	
	Eye Wash Station	4th Floor	1	EA	7	10+ years	
	Floor - Terrazzo	4th Floor	7	SF	6	10+ years	
	Floor - Tile	4th Floor	965	SF	6	10+ years	
	Gas Line	4th Floor	14	EA	7	10+ years	
	Lighting - Lay-in	4th Floor	18	EA	6	6-10 years	
	Marker Board	4th Floor	10	LF	7	6-10 years	
	Science Lab Elements	4th Floor	972	SF	7	10+ years	
	Science Lab Fume Hood	4th Floor	2	EA	7	10+ years	
	Science Lab Shower	4th Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	1,086	SF	6	10+ years	
	Walls - Structural Glazed Tile	4th Floor	26	SF	7	10+ years	
	Work Sink	4th Floor	5	EA	7	10+ years	
Classroo	om #414 (Regular Classroom)						
	AC Units	4th Floor	1	EA	7	10+ years	
	Casework	4th Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	598	SF	6	10+ years	
	Doors - Transom Window	4th Floor	18	SF	7	10+ years	
	Doors - Transom Window	4th Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	7	10+ years	
	Floor - Terrazzo	4th Floor	7	SF	6	10+ years	
	Floor - Tile	4th Floor	586	SF	6	10+ years	
	Floor - Tile	4th Floor	5	SF	4	1-2 years	Cracked
	Lighting - Lay-in	4th Floor	11	EA	4 6	6-10 years	Clacked
	Marker Board	4th Floor	20	LF	7	6-10 years	
		4th Floor	20 910	SF	6		
	Walls - Plaster/Drywall			SF	6 7	10+ years	
	Walls - Structural Glazed Tile	4th Floor	26	55	7	10+ years	
Classroo	om #416 (Regular Classroom)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	598	SF	6	10+ years	
	Doors - Transom Window	4th Floor	18	SF	7	10+ years	
	Doors - Transom Window	4th Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	7	10+ years	
	Floor - Terrazzo	4th Floor	7	SF	6	10+ years	
	Floor - Tile	4th Floor	591	SF	6	10+ years	
	Lighting - Lay-in	4th Floor	11	EA	6	6-10 years	
	Marker Board	4th Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	910	SF	6	10+ years	
	Walls - Structural Glazed Tile	4th Floor	6	SF	7	10+ years	
						-	

Chicago Public Schools			Fried	rich V	V von Steuben Metropo 5039 N Kimball AV	litan Science HS /ENUE, Chicago, IL 60625
					Replacement	
Classroom #418 (Regular Classroom)						
AC Units	4th Floor	1	EA	7	6-10 years	
Casework	4th Floor	20	LF	7	10+ years	
Ceiling - Lay-in	4th Floor	720	SF	6	10+ years	
Chalk Board	4th Floor	20	LF	4	2-5 years	
Doors - Transom Window	4th Floor		SF	7	10+ years	
Doors - Transom Window	4th Floor	18	SF	7	10+ years	
Doors - Wood Doors inclu hw	4th Floor	2	EA	7	10+ years	
Floor - Terrazzo	4th Floor	7	SF	6	10+ years	
Floor - Wood	4th Floor	713	SF	6	10+ years	
Lighting - Lay-in	4th Floor	14	EA	6	6-10 years	
Marker Board	4th Floor	20	LF	7	6-10 years	
Walls - Plaster/Drywall	4th Floor	950	SF	6	10+ years	
Walls - Structural Glazed Tile	4th Floor	26	SF	7	10+ years	
	40111001	20	01	'		
Classroom #419 (Science Lab Level 1)						
AC Units	4th Floor	2	EA	7	6-10 years	
Ceiling - Lay-in	4th Floor	1,075	SF	6	10+ years	
Doors - Transom Window	4th Floor	18	SF	7	10+ years	
Doors - Transom Window	4th Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	4th Floor	2	EA	7	10+ years	
Eye Wash Station	4th Floor	1	EA	7	10+ years	
Floor - Terrazzo	4th Floor	7	SF	6	10+ years	
Floor - Tile	4th Floor	1,068	SF	6	10+ years	
Gas Line	4th Floor	6	EA	7	10+ years	
Lighting - Lay-in	4th Floor	33	EA	6	6-10 years	
Marker Board	4th Floor	20	LF	7	6-10 years	
Walls - Plaster/Drywall	4th Floor	1,330	SF	6	10+ years	
Walls - Structural Glazed Tile	4th Floor	26	SF	7	10+ years	
Work Sink	4th Floor	3	EA	7	6-10 years	
<u>Classroom #420 (Regular Classroom)</u>						
AC Units	4th Floor	1	EA	7	6-10 years	
Casework	4th Floor	8		7		
			SF		10+ years	
Ceiling - Lay-in Doors - Transom Window	4th Floor 4th Floor	720	SF	6 7	10+ years	
Doors - Transom Window Doors - Transom Window	4th Floor	18 9	SF	7	10+ years 10+ years	
				7		
Doors - Wood Doors inclu hw Floor - Terrazzo	4th Floor 4th Floor	2 7	EA SF	6	10+ years	
Floor - Wood	4th Floor		SF	-	10+ years	
		713		6	10+ years	
Lighting - Lay-in Marker Baard	4th Floor 4th Floor	14	EA LF	6	6-10 years	
Marker Board	4th Floor 4th Floor	40		7	6-10 years	
Walls - Plaster/Drywall	4th Floor 4th Floor	950	SF	6	10+ years	
Walls - Structural Glazed Tile	4th Floor	26	SF	7	10+ years	

AC Units 4th Floor Ceiling - Lay-in 4th Floor Doors - Transom Window 4th Floor Doors - Transom Window 4th Floor Doors - Transom Window 4th Floor Doors - Wood Doors inclu hw 4th Floor Eye Wash Station 4th Floor Floor - Terrazzo 4th Floor Floor - Tile 4th Floor Gas Line 4th Floor	2 1,075 18 9 2	EA SF SF	7 6	Replacement 6-10 years)39 N Kimball AVENUE, Chicago, IL 6
AC Units4th FloorCeiling - Lay-in4th FloorDoors - Transom Window4th FloorDoors - Transom Window4th FloorDoors - Wood Doors inclu hw4th FloorEye Wash Station4th FloorFloor - Terrazzo4th FloorFloor - Tile4th FloorGas Line4th Floor	1,075 18 9 2	SF SF			
Ceiling - Lay-in4th FloorDoors - Transom Window4th FloorDoors - Transom Window4th FloorDoors - Wood Doors inclu hw4th FloorEye Wash Station4th FloorFloor - Terrazzo4th FloorFloor - Tile4th FloorGas Line4th Floor	1,075 18 9 2	SF SF			
Doors - Transom Window4th FloorDoors - Transom Window4th FloorDoors - Wood Doors inclu hw4th FloorEye Wash Station4th FloorFloor - Terrazzo4th FloorFloor - Tile4th FloorGas Line4th Floor	18 9 2	SF	6		
Doors - Transom Window4th FloorDoors - Wood Doors inclu hw4th FloorEye Wash Station4th FloorFloor - Terrazzo4th FloorFloor - Tile4th FloorGas Line4th Floor	9 2			10+ years	
Doors - Wood Doors inclu hw4th FloorEye Wash Station4th FloorFloor - Terrazzo4th FloorFloor - Tile4th FloorGas Line4th Floor	2		7	10+ years	
Eye Wash Station4th FloorFloor - Terrazzo4th FloorFloor - Tile4th FloorGas Line4th Floor		SF	7	10+ years	
Floor - Terrazzo4th FloorFloor - Tile4th FloorGas Line4th Floor	1	EA	7	10+ years	
Floor - Tile4th FloorGas Line4th Floor		EA	7	10+ years	
Gas Line 4th Floor	7	SF	6	10+ years	
	1,068	SF	7	10+ years	
	32	EA	7	10+ years	
Lighting - Lay-in 4th Floor	33	EA	6	6-10 years	
Marker Board 4th Floor	16	LF	7	6-10 years	
Science Lab Elements 4th Floor	1,075	SF	7	10+ years	
Science Lab Fume Hood 4th Floor	1	EA	7	10+ years	
Science Lab Shower 4th Floor	1	EA	7	10+ years	
Walls - Plaster/Drywall 4th Floor	1,240	SF	6	10+ years	
Walls - Structural Glazed Tile 4th Floor	26	SF	7	10+ years	
Work Sink 4th Floor	6	EA	7	10+ years	
	0	L/ (•	lot youro	
ntegory : Interior	В	uilding	: Main		
				Recommend	
oup Item - Type Location	Quantity	UOM	Rank	Replacement	Comments
rridor					
Ceiling - Lay-in 1st Floor	8,708	SF	6	10+ years	
Ceiling - Plaster/Drywall 1st Floor	1,789	SF	6	10+ years	
Doors - Steel Doors incl hw 1st Floor	1	EA	7	10+ years	
Doors - Transom Window 1st Floor	159	SF	7	10+ years	
Doors - Wood Doors include hw 1st Floor	35	EA	7	10+ years	
Drinking Fountains - Single Fountain 1st Floor	12	EA	7	6-10 years	
Floor - Terrazzo 1st Floor	3,306	SF	7	10+ years	
Floor - Terrazzo 1st Floor	34	SF	6	10+ years	
Floor - Tile/Sheet 1st Floor	7,157	SF	7	10+ years	
Lighting - Lay-in 1st Floor	92	EA	6	6-10 years	
Lighting - Pendent/Surface 1st Floor	22	EA	6	6-10 years	
Stairs - Terrazzo 1st Floor	7	LF	7	10+ years	
Stairs - Terrazzo 1st Floor	50	LF	7	10+ years	
Student Lockers - One Tier 1st Floor	465	EA	7	10+ years	
Walls - Plaster/Drywall 1st Floor	14,777	SF	7	10+ years	
Walls - Structural Glazed Tile 1st Floor	10,556	SF	7	10+ years	
Walls - Tile Ceramic/ Porcelain 1st Floor	760	SF	7	10+ years	
Ceiling - Lay-in 2nd Floor	8,708	SF	7	10+ years	
Doors - Transom Window 2nd Floor	140	SF	7	10+ years	
Doors - Wood Doors include hw 2nd Floor	140	EA	7	10+ years	
Drinking Fountains - Single Fountain 2nd Floor	10	EA	7	•	
Floor - Terrazzo 2nd Floor		SF	7	6-10 years	
Floor - Tile/Sheet 2nd Floor	1,779 6,930	SF	7	6-10 years 6-10 years	



Building : Main Category : Interior Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Lighting - Lay-in 2nd Floor 79 ΕA 6 6-10 vears Lighting - Pendent/Surface 2nd Floor 6 ΕA 6 6-10 vears Stairs - Terrazzo 2nd Floor 32 LF 7 10+ years Stairs - Terrazzo 6 LF 7 2nd Floor 10+ years Student Lockers - One Tier 2nd Floor 521 EΑ 7 10+ years SF Walls - Plaster/Drywall 2nd Floor 10,333 6 10+ years Walls - Structural Glazed Tile 2nd Floor 14,528 SF 6 10+ years SF Ceiling - Lay-in 3rd Floor 8.528 6 10+ years Ceiling - Plaster/Drvwall 3rd Floor 180 SF 6 10+ years Doors - Transom Window SF 3rd Floor 140 7 10+ years Doors - Wood Doors include hw 3rd Floor 15 ΕA 7 10+ vears Drinking Fountains - Single Fountain 3rd Floor 11 EΑ 7 6-10 years Floor - Terrazzo 1,779 SF 7 3rd Floor 10+ years SF 7 Floor - Tile/Sheet 3rd Floor 6,930 6-10 years ΕA 7 6-10 years Lighting - Lay-in 3rd Floor 74 Lighting - Pendent/Surface 2 ΕA 7 3rd Floor 6-10 years Student Lockers - One Tier 521 7 3rd Floor ΕA 10+ years Walls - Plaster/Drvwall 3rd Floor 10.333 SF 6 10+ years SF Walls - Structural Glazed Tile 3rd Floor 14.528 7 10+ vears SF Ceiling - Lay-in 4th Floor 4,014 6 10+ years Doors - Transom Window 4th Floor 126 SF 7 10+ years Doors - Wood Doors include hw 7 4th Floor 15 EΑ 10+ years 7 Drinking Fountains - Single Fountain 4th Floor 4 EΑ 6-10 years SF 7 Floor - Terrazzo 4th Floor 1.294 10+ years Floor - Tile/Sheet 2.720 SF 7 4th Floor 10+ years Lighting - Lav-in 4th Floor 34 ΕA 6 6-10 years Student Lockers - One Tier 7 4th Floor 174 ΕA 10+ years Walls - Plaster/Drywall 4th Floor 3.080 SF 6 10+ years Walls - Structural Glazed Tile SF 7 4th Floor 4,328 10+ years Ceiling - Exposed **Basement** 3,000 SF 7 10+ years Doors - Wood Doors include hw Basement 2 ΕA 7 10+ vears Floor - Concrete Basement 3.000 SF 7 10+ vears FΑ Lighting - Pendent/Surface Basement 6 6-10 years 1 Stairs - Concrete Stairs 8 LF 7 Basement 10+ years 2,720 SF Walls - Masonry **Basement** 6 10+ years Safety Camera Viewing Station 1st Floor 2 FΑ 7 6-10 years Metal Dedector 1st Floor 2 ΕA 7 6-10 vears Security Cameras 1st Floor 10 ΕA 7 6-10 years Stairs Ceiling - Lay-in SF Stairwell B (SW) 45 6 10+ years Ceiling - Plaster/Drywall Stairwell B (SW) 445 SF 6 10+ years



Catego	ry : Interior		В	uilding	: Main		
5				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	Stairwell B (SW)	835	SF	6	10+ years	
	Floor - Terrazzo	Stairwell B (SW)	5	SF	4	0-1 year	Chipped/missing trim
	Handrails	Stairwell B (SW)	150	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell B (SW)	6	EA	6	6-10 years	
	Stairs - Terrazzo	Stairwell B (SW)	75	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell B (SW)	1,430	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stairwell B (SW)	2,340	SF	7	10+ years	
	Ceiling - Lay-in	Stairwell C (S)	45	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairwell C (S)	445	SF	6	10+ years	
	Floor - Terrazzo	Stairwell C (S)	840	SF	6	10+ years	
	Handrails	Stairwell C (S)	150	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell C (S)	6	EA	6	6-10 years	
	Stairs - Terrazzo	Stairwell C (S)	75	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell C (S)	1,430	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stairwell C (S)	2,340	SF	7		
		Stairwell D (SE)	2,340	SF	6	10+ years	
	Ceiling - Lay-in		8	SF	4	10+ years	
	Ceiling - Lay-in	Stairwell D (SE)		SF		1-2 years	
	Ceiling - Plaster/Drywall	Stairwell D (SE)	445		6	10+ years	
	Floor - Terrazzo	Stairwell D (SE)	840	SF	7	10+ years	
	Handrails	Stairwell D (SE)	150	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell D (SE)	6	EA	6	6-10 years	
	Stairs - Terrazzo	Stairwell D (SE)	4	LF	6	10+ years	
	Stairs - Terrazzo	Stairwell D (SE)	71	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell D (SE)	1,415	SF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell D (SE)	15	SF	4	1-2 years	
	Walls - Structural Glazed Tile	Stairwell D (SE)	2,340	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stairwell E (NE)	286	SF	6	10+ years	
	Floor - Terrazzo	Stairwell E (NE)	154	SF	6	10+ years	
	Handrails	Stairwell E (NE)	116	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell E (NE)	4	EA	6	6-10 years	
	Stairs - Terrazzo	Stairwell E (NE)	56	LF	6	10+ years	
	Stairs - Terrazzo	Stairwell E (NE)	2	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell E (NE)	700	SF	7	10+ years	
	Walls - Structural Glazed Tile	Stairwell E (NE)	1,280	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stairwell H (NW)	286	SF	6	10+ years	
	Floor - Terrazzo	Stairwell H (NW)	154	SF	6	10+ years	
	Handrails	Stairwell H (NW)	116	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell H (NW)	4	EA	6	6-10 years	
	Stairs - Terrazzo	Stairwell H (NW)	58	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell H (NW)	550	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stairwell H (NW)	1,430	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stairwell J (photo name 205S) (W)	89	SF	6	10+ years	
	Floor - Terrazzo	Stairwell J (photo name 2005) (W)	40	SF	6	10+ years	
	Handrails	Stairwell J (photo name 2000) (W)	82	LF	7	10+ years	
	i landi allo		02	L1	i	ior years	



Catego	ry : Interior		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	Stairwell J (photo name 205S) (W)	1	EA	6	6-10 years			
	Lighting - Wall Mounted	Stairwell J (photo name 205S) (W)	1	EA	6	6-10 years			
	Stairs - Terrazzo	Stairwell J (photo name 205S) (W)	41	LF	6	10+ years			
	Walls - Plaster/Drywall	Stairwell J (photo name 205S) (W)	3,978	SF	6	10+ years			
Vertical (Conveyance								
	Elevator - Freight Elevator	Entire building	1	EA	7	10+ years			
	Elevator - Hydraulic Elevator	Entire building	1	EA	7	10+ years			



Catego	ry : Site		В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Athletic	nem - Type	Location	Quantity		Marik	Replacement	Comments
Amenc	Surface - Synthetic	East	15,000	SF	7	10+ years	
<u></u>							
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	23	EA	6	10+ years	
Fencing							
0	Fencing - Chain Link	Entire Site	27	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,521	LF	6	10+ years	
Landscar	De						
	Benches	Entire Site	14	EA	7	10+ years	
	Landscape - Grass	Entire Site	17,540	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	980	SF	5	1-2 years	Heaved, cracked, not previously assessed
	Landscape - Hardscape- Concrete	Entire Site	6,570	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	450	SF	4	0-1 year	Cracked
	Landscape - Hardscape- Pavers	Entire Site	204	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	7	EA	6	6-10 years	Not previously assessed
	Parkway trees	Entire Site	18	EA	6	10+ years	Corrected quantity
	Parkway trees	Entire Site	1	EA	4	1-2 years	Missing
	Planting Beds/ Area	Entire Site	3,320	SF	6	10+ years	-
	Retaining Wall - Concrete	Entire Site	850	SF	6	10+ years	
	Trash Receptacles	Entire Site	6	EA	7	10+ years	
Parking L	ot						
	Surface - Asphalt	Parking Lot- South	9,048	SF	6	10+ years	
Sidewalk	S						
	Sidewalks - Internal Walks	Entire site, Site West	975	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire site, Site West	6,210	SF	7	10+ years	
Signage							
ыупауе	Flag Pole - Flag Pole	Northwest at property, West and East Facade	1	EA	7	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Northwest at property, West and East Facade	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Northwest at property, West and East Facade	4	EA	7	10+ years	



¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main						•	•		
Art Room	Art Room	3rd Floor	322	324	1,075	258	12	Y	Y
Art Room	Art Room	3rd Floor	324	324	1,075	258	12	Y	Ν
Band Room	Music Room	3rd Floor	305	305	1,754	348	17	Y	Ν
Choral Room	Music Room	3rd Floor	303	303	1,531	0	0	N	Y
Computer Lab	Computer Lab	2nd Floor	212	212	1,117	126	20	Y	Ν
Computer Lab	Regular Classroom	1st Floor	116	116	896	109	20	Y	Ν
Computer Lab	Regular Classroom	2nd Floor	213	213	716	84	15	Y	Ν
Faculty Lounge	Regular Classroom	3rd Floor	306	306	720	172	8	Y	Ν
Office	Office	2nd Floor	214	214	430	40	4	Y	Ν
Regular Classroom	Art Room	1st Floor	122	122	962	91	15	Y	Ν
Regular Classroom	Art Room	3rd Floor	318	318	720	172	8	Y	Ν
Regular Classroom	Computer Lab	2nd Floor	211	211	720	104	15	Y	Ν
Regular Classroom	Computer Lab	2nd Floor	216	216	1,185	126	20	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	101	101	724	84	15	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	102	102	730	84	15	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	104	104	725	84	15	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	106	106	780	84	15	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	118	118	496	40	4	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	120	120	496	40	4	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	124	124	1,017	109	20	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	201	201	720	84	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	202	202	730	84	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	204	204	720	84	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	206	206	716	84	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	209	209	703	84	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	210	210	726	84	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	217	217	745	84	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	218	218	787	84	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	219	219	720	84	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	220	220	962	91	15	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	222	222	972	109	6	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	224	224	1,092	113	7	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	301	301	720	172	8	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	302	302	720	172	8	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	304	304	720	172	8	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	310	310	720	172	8	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	317	317	720	172	8	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	319	319	720	172	8	Y	Ν



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	3rd Floor	320	320	800	166	8	Y	N
Regular Classroom	Regular Classroom	4th Floor	410	410	720	176	8	Y	N
Regular Classroom	Regular Classroom	4th Floor	412	412	720	176	8	Y	N
Regular Classroom	Regular Classroom	4th Floor	414	414	598	90	6	Y	N
Regular Classroom	Regular Classroom	4th Floor	416	416	598	90	6	Y	N
Regular Classroom	Regular Classroom	4th Floor	418	418	720	176	8	Y	N
Regular Classroom	Regular Classroom	4th Floor	420	420	720	176	8	Y	Y
Regular Classroom	Science Classroom	3rd Floor	316	316	1,107	258	12	Y	N
Science Lab Level 1	Regular Classroom	4th Floor	413	413	972	236	11	Y	N
Science Lab Level 1	Science Lab Level 1	4th Floor	409	409/411	972	236	11	Y	N
Science Lab Level 1	Science Lab Level 1	4th Floor	419	419	1,075	166	8	Y	N
Science Lab Level 1	Science Lab Level 1	4th Floor	421	423	1,075	258	12	Y	N
Science Lab Level 2	Science Lab Level 2	2nd Floor	215	215	1,095	84	15	Y	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	312	312	1,107	258	12	Y	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	309	311	1,075	172	12	Y	Ν
Science Lab Level 3	Science Lab Level 3	3rd Floor	313	313	1,075	172	12	Y	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	315	315	1,075	172	12	Y	Ν
Special Education	Office	3rd Floor	314	314	426	86	4	Y	N