

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1911	3	58,148
Annex	2020	3	31,100
Linked Addition	2009	1	4,699
Campus Total			93,947

Catego	ry : Exterior		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Overhead Rolling/ Garage	#5.1 W	1	EA	7	10+ years	
	Door						
	Entrance Control - Audio and Video	1-E Main	1	EA	6	10+ years	
	Exterior Doors - Store Front	1-E Main	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	1-E Main	2	EA	6	10+ years	
	Exterior Stairs - Concrete	1-E Main	12	LF	5	0-1 year	Cracking.
	Exterior Doors - Side lite	2-E	2	EA	6	10+ years	
	Exterior Doors - Store Front	2-E	5	EA	6	10+ years	
	Exterior Doors - Transom Lite	2-E	3	EA	6	10+ years	
	Exterior Doors - Store Front	3-E	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	3-E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	3-E	12	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	5-W now 9	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	5-W now 9	1	EA	6	10+ years	
	Exterior Stairs - Concrete	5-W now 9	5	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	6-W now 10	1	EA	5	0-1 year	Rusting at bottom portion of door.
	Exterior Doors - Transom Lite	6-W now 10	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	7-W	1	EA	6	10+ years	
	Exterior Doors - Side lite	7-W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	7-W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	7-W	3	LF	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
C	Hom Tune	Leastion	O urantitu		Denk	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Foundati			0.50	. –			
	Foundation - Concrete	Entire Building	853	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	59,684	SF	7	10+ years	
iahtina							
-igning	Exterior Lighting - Wall Mounted	Entire Building	31	EA	6	10+ years	
Deef Su	tom						
Roof Sys	Access Ladder - Metal	A	2	EA	5	1.2 vooro	Large distance between rungs, old
	Access Ladder - Metal	A	2	EA	5	1-2 years	ladder.
	Access Ladder - Metal	A	2	EA	4	0-1 year	Improperly secured, missing bolt.
			2	L/\	7	0 i year	Ladder bounces upon use
	Chimney - Brick Chimney- Concrete/ Mortar	А	80	LF	7	10+ years	This chimney has been recently tuc
	Liner					, <u>,</u>	pointed
	Coping - Stone	A	686	LF	7	10+ years	•
	Downspouts - Interior Downspouts	A	110	LF	6	10+ years	
	Downspouts - Interior Downspouts	А	90	LF	6	10+ years	
	Downspouts - Interior Downspouts	А	20	LF	5	0-1 year	Water leaks down this downspout.
	Parapet - 16" - 30" Height	A	536	LF	7	10+ years	· · · · · · · · · · · · · · · · · · ·
	Parapet - Parapet < 16" Height	A	150	LF	7	10+ years	
	Roof - Modified Bitumen	A	17.700	SF	7	10+ years	
	Roof Hatch - Metal	A	2	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	A	17,700	SF	7	10+ years	
	Coping - Stone	В	126	LF	6	10+ years	
	Downspouts - Interior Downspouts	B	34	LF	6	10+ years	
	Parapet - Parapet < 16" Height	B	126		6	10+ years	
	Roof - Modified Bitumen	B		SF	7		
			2,744 2,744	SF		10+ years	
	Roof Structure - Steel with Clay Tile Arch	B		LF	7	10+ years	Coolont repaired
	Coping - Stone	С	166		7	10+ years	Sealant repaired
	Downspouts - Exterior Downspouts	С	84	LF	6	10+ years	
	Parapet - 16" - 30" Height	C	166	LF	7	10+ years	
	Roof - Modified Bitumen	С	3,300	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	С	3,300	SF	7	10+ years	
	Coping - Stone	D	96	LF	6	10+ years	
	Downspouts - Interior Downspouts	D	32	LF	6	10+ years	
	Parapet - Parapet < 16" Height	D	96	LF	6	10+ years	
	Roof - Modified Bitumen	D	540	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	D	540	SF	7	10+ years	
	Coping - Stone	E	48	LF	6	10+ years	
	Downspouts - Exterior Downspouts	E	30	LF	7	10+ years	
	Parapet - Parapet < 16" Height	E	48	LF	6	10+ years	
	Roof - Modified Bitumen	E	560	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	E	560	SF	7	10+ years	



	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Concrete Topping					-	
Valls							
	Cornice - Masonry Projecting Limestone	Entire Building	358	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	1,136	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	24,653	SF	6	10+ years	• • • • • • • • •
	Exterior Walls - Brick	Entire Building	500	SF	4	0-1 year	Open joints, cracking/chipping.
	Exterior Walls - Stone-Cut	Entire Building	4,134	SF	6	10+ years	
/indows	5						
	Curtain wall - Insulated Panel	Entire Building	293	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	78	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	2,306	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	408	SF	6	10+ years	
	Lintels - Brick	Entire Building	16	LF LF	6	10+ years	
	Lintels - Steel	Entire Building	468	LF	6	10+ years	
	Lintels - Stone	Entire Building	329 126	SF	6 6	10+ years	
	Windows - Decorative Windows - Decorative	Entire Building Entire Building	408	SF	6	10+ years 10+ years	
	Windows - Decorative Windows - Sash Aluminum Double-pane	Entire Building	7,585	SF	6	10+ years	
	Windows - Sash Aldminum Double-pane Windows - Wood- Single-pane	Entire Building	128	SF	4	1-2 years	Old wooden windows at light well
	Windows - Wood- Single-pane		120	36	4	1-2 years	Old wooden windows at light weir
Catego	ry : Electrical		В	uilding	: Main	D	
	Kenne Trune	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
iroup	item - i vde		Quantity				
-	Item - Type	Location	Quantity				
iroup merger	ncy System Security System - CCTV	1st Floor	58,148	SF	7	6-10 years	
-	Security System - CCTV Security System - Intrusion Detection			SF SF	7 6	6-10 years 6-10 years	
-	ncy System Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch	1st Floor	58,148	SF	7	6-10 years 0-1 year	Disconnected.
-	Security System - CCTV Security System - Intrusion Detection	1st Floor 1st Floor	58,148 58,148	SF SF	7 6	6-10 years	
-	ncy System Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch	1st Floor 1st Floor Boiler Room	58,148 58,148 1	SF SF EA	7 6 2	6-10 years 0-1 year	No EM generator Bulb needs to b replaced Hard to read
	Acy System Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch Exit Signs - Corridors and Stairs	1st Floor 1st Floor Boiler Room Entire Building	58,148 58,148 1 11	SF SF EA EA	7 6 2 2	6-10 years 0-1 year 0-1 year	No EM generator Bulb needs to b replaced Hard to read No EM generator Bulb needs to b
-	Acy System Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Corridors and Stairs	1st Floor 1st Floor Boiler Room Entire Building Entire Building Entire Building	58,148 58,148 1 11	SF SF EA EA EA	7 6 2 2 2	6-10 years 0-1 year 0-1 year 0-1 year 0-1 year	No EM generator Bulb needs to b replaced Hard to read No EM generator Bulb needs to b replaced Hard to read No backup generator.
-	Acy System Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Corridors and	1st Floor 1st Floor Boiler Room Entire Building Entire Building	58,148 58,148 1 11 6 22	SF SF EA EA EA	7 6 2 2 2 2 4	6-10 years 0-1 year 0-1 year 0-1 year	No EM generator Bulb needs to b replaced Hard to read No EM generator Bulb needs to b replaced Hard to read No backup generator. No backup generator.
-	Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	1st Floor 1st Floor Boiler Room Entire Building Entire Building Entire Building Entire Building	58,148 58,148 1 11 6 22 5	SF SF EA EA EA EA	7 6 2 2 2 2 4 4	6-10 years 0-1 year 0-1 year 0-1 year 0-1 year 0-1 year	No EM generator Bulb needs to b replaced Hard to read No EM generator Bulb needs to b replaced Hard to read No backup generator.
	Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and	1st Floor 1st Floor Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building	58,148 58,148 1 11 6 22 5 6	SF EA EA EA EA EA EA	7 6 2 2 2 4 4 4	6-10 years 0-1 year 0-1 year 0-1 year 0-1 year 0-1 year 0-1 year	No EM generator Bulb needs to b replaced Hard to read No EM generator Bulb needs to b replaced Hard to read No backup generator. No backup generator.
	Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym	1st Floor 1st Floor Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	58,148 58,148 1 11 6 22 5 6 8,368	SF EA EA EA EA EA EA SF	7 6 2 2 2 4 4 4 4 6	6-10 years 0-1 year 0-1 year 0-1 year 0-1 year 0-1 year 0-1 year 6-10 years	No EM generator Bulb needs to b replaced Hard to read No EM generator Bulb needs to b replaced Hard to read No backup generator. No backup generator.



						-	0 N Campbell AVENUE, Chicago, IL 6062
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	120/208/3PH PA System	Entire Building	58,148	SF	5		Working par ourrant observation
	Independent Electrical Service for	Entire Building	1	EA	3	2-5 years 0-1 year	Working per current observation. Non functional, ATS disconnected.
	emergency power		ľ	LA	5	0-1 year	Non functional, ATS disconnected.
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	12	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	New item added per current
		-				-	observation.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	4	0-1 year	Older panel
	amp	J				,	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Entire Building	58,148	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	58,148	SF	7	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
		Location				Recommend Replacement	Comments
Group	Item - Type	Location	B Quantity	uilding UOM	: Main Rank	Recommend Replacement	Comments
Group	Item - Type ling Systems		Quantity	UOM	Rank	Replacement	Comments
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone-	Location Mechanical Room					Comments
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	Quantity 2	UOM EA	Rank 7	Replacement 10+ years	Comments
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake	Mechanical Room Mechanical Room	Quantity 2 2	UOM EA EA	Rank 7 6	Replacement 10+ years 10+ years	Comments
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm	Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 2	UOM EA EA EA	Rank 7 6 6	Replacement 10+ years 10+ years 10+ years	Comments
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts-	Mechanical Room Mechanical Room	Quantity 2 2	UOM EA EA	Rank 7 6	Replacement 10+ years 10+ years	Comments
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 2 200	UOM EA EA EA LF	Rank 7 6 6 6 6	Replacement 10+ years 10+ years 10+ years 10+ years	Comments
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers	Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 2	UOM EA EA EA	Rank 7 6 6	Replacement 10+ years 10+ years 10+ years 10+ years 10+ years	
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone-	Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 200 35	UOM EA EA EA LF EA	Rank 7 6 6 6 7 7	Replacement 10+ years 10+ years 10+ years 10+ years	
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers	Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 200 35	UOM EA EA EA LF EA	Rank 7 6 6 6 7 7 7	Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 200 35	UOM EA EA EA LF EA EA	Rank 7 6 6 6 7 7	Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm	Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 200 35	UOM EA EA EA LF EA EA EA	Rank 7 6 6 7 7 7 6	Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake	Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 200 35 1 1 1	UOM EA EA EA LF EA EA EA EA	Rank 7 6 6 7 7 7 6 6 6	Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Group Air Hand	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 200 35 1 1 1	UOM EA EA EA LF EA EA EA EA	Rank 7 6 6 7 7 7 6 6 6	Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments Suspended on railing. Serves Gyr
Group	Item - Type ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 2 2 200 35 1 1 1	UOM EA EA EA LF EA EA EA EA	Rank 7 6 6 7 7 7 6 6 6	Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	



Catego	ry : Mechanical		B	uilding	: Main	454		
	· · · · · · · · · · · · · · · · · · ·					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Chemical Feeder	Boiler Room	1	EA	7	10+ years		
	Combustion Dampers	Boiler Room	2	EA	6	10+ years		
	Condensate Pump	Boiler Room	1	EA	6	2-5 years		
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years		
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years		
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	6	6-10 years		
	Piping - Steam Pipe- Steel	Boiler Room	300	LF	5	2-5 years	Minor repair	
	Steam Traps	Boiler Room	1	EA	5	2-5 years	Minor repair	
Gas Boo	ster							
	Gas Booster	Boiler Room	2	EA	6	6-10 years		
leating	Devices							
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	New item added per current observation Storage and electrical room.	
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years		
	Unit Heater - Gas	Entire Building	1	EA	6	6-10 years		
	Wall Heater - Electric	Entire Building	6	EA	6	6-10 years		
	Wall Heater - Electric	Entire Building	2	EA	5	1-2 years	Controls needs to be replaced.	
	Wall Heater - Electric	Entire Building	2	EA	4	0-1 year	Not working, cover missing.	
	Radiators - Steam	Entire Building	8	EA	6	6-10 years	Paint required.	
Tempera	ature Control							
	Pneumatic System	Entire Building	58.148	SF	6	6-10 years		
	Thermostats - Pneumatic	Entire Building	35	EA	6	6-10 years		
/entilatio	on							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	New item added per current observation Storage	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	observation Storage	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years		
Catego	ry : Plumbing		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Hot Wate	er							
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years		
Pinina								

Piping



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Lines	Entire Building	59,684	SF	7	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	59,684	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	59,684	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	59,684	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	59,684	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	59,684	SF	6	6-10 years	
	Sanitary Piping	Entire Building	59,684	SF	5	1-2 years	Old galvanized pipes
	Storm Piping	Entire Building	59,684	SF	5	1-2 years	Old galvanized pipes
	Vent Piping	Entire Building	59,684	SF	5	1-2 years	Old galvanized pipes
Catego	ry : Boom		В	uildina	· Main		

Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
dminis	trative Suites/Offices									
	AC Unit	110 Main Office	2	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	110 Main Office	754	SF	7	10+ years				
	Doors - Steel Doors incl hw	110 Main Office	1	EA	7	10+ years				
	Doors - Transom Window	110 Main Office	24	SF	7	10+ years				
	Doors - Wood Doors inclu hw	110 Main Office	5	EA	7	10+ years				
	Floor - Carpet	110 Main Office	408	SF	6	6-10 years				
	Floor - Tile	110 Main Office	346	SF	7	10+ years				
	Lighting - Pendent/Surface	110 Main Office	8	EA	7	6-10 years				
	Power Distribution	110 Main Office	20	EA	7	10+ years				
	Storage/ Closet	110 Main Office	92	SF	7	10+ years				
	Walls - Plaster/Drywall	110 Main Office	2,140	SF	7	10+ years				
	Work SInk	110 Main Office	1	EA	7	10+ years				
	AC Unit	1st Floor Teacher's Lounge	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor Teacher's Lounge	700	SF	6	10+ years				
	Doors - Transom Window	1st Floor Teacher's Lounge	12	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor Teacher's Lounge	3	EA	6	10+ years				
	Floor - Tile	1st Floor Teacher's Lounge	80	SF	7	10+ years				
	Floor - Tile	1st Floor Teacher's Lounge	620	SF	7	6-10 years				
	Lighting - Pendent/Surface	1st Floor Teacher's Lounge	13	EA	7	6-10 years				
	Power Distribution	1st Floor Teacher's Lounge	14	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor Teacher's Lounge	1,330	SF	6	10+ years				
	Work SInk	1st Floor Teacher's Lounge	1	EA	7	10+ years				
	AC Unit	212 Counselor's Office	1	EA	5	0-1 year	Cover missing.			
	Ceiling - Plaster/Drywall	212 Counselor's Office	390	SF	7	10+ years				
	Doors - Side-lite	212 Counselor's Office	100	SF	7	10+ years				
	Doors - Transom Window	212 Counselor's Office	20	SF	7	10+ years				



Catego	ry : Room		В	uilding	: Main	101	
j•				3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	212 Counselor's Office	1	EA	7	10+ years	
	Floor - Tile	212 Counselor's Office	390	SF	7	10+ years	
	Lighting - Pendent/Surface	212 Counselor's Office	6	EA	7	6-10 years	
	Power Distribution	212 Counselor's Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	212 Counselor's Office	850	SF	6	10+ years	
	AC Unit	314 School Counselor (above stair)	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	314 School Counselor (above stair)		SF	7	10+ years	
	Doors - Wood Doors inclu hw	314 School Counselor (above stair)	1	EA	7	10+ years	
	Floor - Wood	314 School Counselor (above stair)	216	SF	7	10+ years	
	Lighting - Pendent/Surface	314 School Counselor (above stair)	4	EA	7	6-10 years	
	Power Distribution	314 School Counselor (above stair)	4	EA	7	10+ years	
	Walls - Plaster/Drywall	314 School Counselor (above stair)	420	SF	7	10+ years	
	Walls - Plaster/Drywall	314 School Counselor (above stair)	22	SF	5	0-1 year	Crack in wall
	AC Unit	315 Social Worker(above stair)	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	315 Social Worker(above stair)	216	SF	7	10+ years	
	Doors - Wood Doors inclu hw	315 Social Worker(above stair)	1	ĒA	7	10+ years	
	Floor - Wood	315 Social Worker(above stair)	216	SF	7	10+ years	
	Lighting - Pendent/Surface	315 Social Worker(above stair)	4	EA	7	6-10 years	
	Power Distribution	315 Social Worker(above stair)	2	EA	7	10+ years	
	Walls - Plaster/Drywall	315 Social Worker(above stair)	442	SF	7	10+ years	
	Ceiling - Lay-in	Engineer's Office	140	SF	6	10+ years	
	Ceiling - Lay-in	Engineer's Office	8	SF	4	0-1 year	Broken tile
	Doors - Transom Window	Engineer's Office	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	2	EA	6	10+ years	
	Floor - Carpet	Engineer's Office	148	SF	6	2-5 years	Torn carpet
	Lighting - Pendent/Surface	Engineer's Office	2	EA	7	6-10 years	
	Power Distribution	Engineer's Office	2	EA	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	344	SF	7	10+ years	
	AC Unit	Principals office in main office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principals office in main office	130	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principals office in main office	130	EA	7	10+ years	
	Floor - Carpet	Principals office in main office	130	SF	7	6-10 years	
	Lighting - Pendent/Surface	Principals office in main office	2	EA	7	6-10 years	
	Power Distribution	Principals office in main office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Principals office in main office	450	SF	7	10+ years	
	Walls - Plaster/Drywall	Principals office in main office	430	SF	5	0-1 year	Damage near window.
	Walls - Flaster/Drywall	Fincipais once in main once	10	36	5	0-1 year	Damage hear window.
_Gymnas							
	Ceiling - Plaster/Drywall	1st Floor	3,350	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Wood	1st Floor	3,350	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		540 N Campbell AVENUE, Chicago, IL 600	
Salogo	,			-nanig	· man	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Stage	1st Floor	566	SF	7	10+ years		
	Stage Curtain	1st Floor	3	ĒA	7	10+ years		
	Stage Lift	1st Floor	1	EA	7	6-10 years		
	Stage Lighting System	1st Floor	1	EA	7	10+ years		
	Stage-Stairs - Wood	1st Floor	72	LF	7	10+ years		
	Storage/ Closet	1st Floor	242	SF	7	10+ years		
	Walls - Masonry	1st Floor	1,350	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	2,100	SF	7	10+ years		
	=							
_	Doors - Steel Doors incl hw	in Computer Lab 101	1	EA	6	10+ years		
	Finishes	in Computer Lab 101	138	SF	5	10+ years	Paint around windows needed.	
	Window AC Unit	in Computer Lab 101	1	EA	7	6-10 years		
lechanio	cal/ Service Rooms							
	Air Tunnel	1st Floor	750	SF	7	10+ years		
	Boiler Room	1st Floor	1,160	SF	5	10+ years	Peeling paint from ceiling	
	Janitor's Closet	1st Floor	20	SF	5	2-5 years	314 4 3	
	Mechanical/ Service Rooms	1st Floor	1,200	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	190	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	600	SF	7	10+ years		
	Storage Room	1st Floor	50	SF	7	10+ years		
	Storage Room	1st Floor	400	SF	7	10+ years		
	Vaults	1st Floor	200	SF	7	10+ years		
	Janitor's Closet	2nd Floor	30	SF	5	10+ years	Water damage to walls.	
	Storage Room	2nd Floor	45	SF	5	10+ years	Water damage to walls.	
	Janitor's Closet	3rd Floor	10	SF	5	10+ years	Water damage to waits.	
	Storage Room	3rd Floor	45	SF	5	10+ years		
Restroon	n							
	Accessories	1st Floor	320	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	320	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years		
	Floor - Concrete Epoxy/ Painted	1st Floor	320	SF	4	0-1 year	Missing pieces throughout.	
	Floor Drain	1st Floor	1	EA	7	10+ years	51 5 6	
	Hand Dryer	1st Floor	2	EA	7	6-10 years		
	Lavatory	1st Floor	1	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years		
	Partitions	1st Floor	2	EA	7	10+ years		
	Urinals	1st Floor	1	EA	7	10+ years	Repaired	
	Urinals	1st Floor	4	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	126	SF	7	10+ years		



Catego	ry : Room		B	uilding	• Main	404	O N Campbell AVENUE, Chicago, IL 60625
Catego				unung	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oreup	Walls - Masonry	1st Floor	300	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	650	SF	7	10+ years	
	Water Closet	1st Floor	2	ĒA	7	10+ years	
	Accessories	1st Floor	314	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	314	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	300	SF	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	14	SF	4	0-1 year	Damaged.
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	6	2-5 years	
	Partitions	1st Floor	5	EA	5	6-10 years	
	Walls - Concrete Block	1st Floor	120	SF	6	10+ years	
	Walls - Masonry	1st Floor	300	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	650	SF	6	10+ years	
	Water Closet	1st Floor	5	EA	6	10+ years	
	Accessories	1st Floor	46	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	40	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	6	SF	7	6-10 years	Repaired
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	42	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	4	SF	5	0-1 year	Cracked floor
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Wall Mounted	1st Floor	1	EA	6	6-10 years	
	Partitions	1st Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	256	SF	6	6-10 years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	2nd Floor	368	SF SF	7 7	6-10 years	
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	368 1	EA	7	10+ years 10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	•	
	Floor - Concrete Epoxy/ Painted	2nd Floor	368	SF	4	10+ years 0-1 year	Missing pieces throughout.
	Floor Drain	2nd Floor 2nd Floor	300 1	EA	4	0-1 year	Broken drain cover
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	Dioken diam cover
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7	6-10 years	
	Urinals	2nd Floor	5	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	120	SF	7	10+ years	
	Walls - Masonry	2nd Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	650	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
			-		•	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	



Catego	ry : Room		B	uilding	• Main	404	0 N Campbell AVENUE, Chicago, IL 60625
Catego				unung	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.000	Accessories	2nd Floor	46	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	46	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	2nd Floor	46	SF	7	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor	1	EA	7	6-10 years	
	Partitions	2nd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	256	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor	368	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	368	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	2nd Floor	368	SF	4	0-1 year	Damaged throughout.
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	4	0-1 year	Does not work.
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	120	SF	7	10+ years	
	Walls - Masonry	2nd Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	650	SF	7	10+ years	
	Water Closet	2nd Floor	5	EA	7	10+ years	
		3rd Floor	46	SF	7	6-10 years	
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	3rd Floor	46 1	SF EA	7	10+ years	
		3rd Floor 3rd Floor	46	SF	7 7	10+ years	
	Floor - Concrete Epoxy/ Painted		40	EA	7	10+ years	Densired
	Lavatory Lighting - Wall Mounted	3rd Floor 3rd Floor	1	EA	7	10+ years 6-10 years	Repaired
	Partitions	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	256	SF	7	10+ years	
	Water Closet	3rd Floor	230	EA	7	10+ years	
	Accessories	3rd Floor	368	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	368	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	- 1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd Floor	368	SF	5	10+ years	
	Floor Drain	3rd Floor	1	ĒA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	4	0-1 year	Doesn't work
	Lavatory	3rd Floor	_ 1	EA	7	10+ years	
	Lavatory	3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	6-10 years	
	Partitions	3rd Floor	5	EA	7	10+ years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Walls - Concrete Block 3rd Floor 120 SF 10+ years 7 Walls - Masonry 3rd Floor 300 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 650 SF 7 10+ years Water Closet 5 ΕA 7 3rd Floor 10+ years SF 7 Accessories 3rd Floor 368 6-10 years SF Ceiling - Plaster/Drywall 7 3rd Floor 368 10+ years Doors - Wood Doors inclu hw 3rd Floor 2 ΕA 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 ΕA 7 10+ years SF Floor - Concrete Epoxy/ Painted 3rd Floor 353 5 10+ years SF Floor - Concrete Epoxy/ Painted 3rd Floor 15 4 0-1 year Cracked flooring 3rd Floor Floor Drain 1 ΕA 7 10+ vears Hand Dryer 3rd Floor 2 ΕA 7 6-10 years Lavatory 3rd Floor 1 ΕA 7 10+ years Lighting - Pendent/Surface 5 ΕA 7 3rd Floor 6-10 years 2 Partitions ΕA 5 2-5 years 3rd Floor 5 ΕA 7 Urinals 3rd Floor 10+ years Walls - Concrete Block 120 SF 7 3rd Floor 10+ years SF Walls - Masonrv 3rd Floor 300 7 10+ years Walls - Plaster/Drywall SF 3rd Floor 650 7 10+ vears Water Closet 3rd Floor 2 EΑ 7 10+ years Accessories Engineer's Toilet 25 SF 5 0-1 year Missing cover Ceiling - Plaster/Drywall 25 SF 7 Engineer's Toilet 10+ years Doors - Wood Doors inclu hw ΕA Engineer's Toilet 1 6 10+ years SF Floor - Concrete Epoxy/ Painted **Engineer's Toilet** 20 5 6-10 years Floor - Concrete Epoxy/ Painted **Engineer's Toilet** 5 SF 4 0-1 year Cracked floor Lighting - Wall Mounted Engineer's Toilet 1 ΕA 7 6-10 vears Walls - Masonry SF **Engineer's Toilet** 100 7 10+ years SF Walls - Plaster/Drywall **Engineer's Toilet** 150 7 10+ years Water Closet ΕA **Engineer's Toilet** 1 7 10+ years

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroo	m #101 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Casework	1st Floor	21	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	720	SF	4	0-1 year	Torn throughout.
	Lighting - Pendent/Surface	1st Floor	13	EA	6	6-10 years	-
	Marker Board	1st Floor	15	LF	7	6-10 years	



Catego	ry : Classroom		B	uilding	: Main		
- 3 -	-			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,100	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	10+ years	
Classro	om #105 (Kindergarten)						
CIASSIU	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
		1st Floor	907	SF			
	Ceiling - Plaster/Drywall				7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	907	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,116	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	144	SF	6	10+ years	
Classroo	om #107 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	907	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	12	EA	6		
			-			10+ years	
	Floor - Wood	1st Floor	907	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,260	SF	7	10+ years	
Classroo	om #108 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	877	SF	6	10+ years	Paint cracking and peeling throughout.
	Doors - Side-lite	1st Floor	18	SF	6	10+ years	anoughout
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	877	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	•	
		1st Floor		SF		10+ years	
	Walls - Plaster/Drywall		1,100		7	10+ years	Densired
	Walls - Plaster/Drywall	1st Floor	100	SF	7	10+ years	Repaired.



Catego	ry : Classroom		В	uilding	: Main		·
U	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #111 (Office)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	907	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	10+ years	
	Floor - Wood	1st Floor	907	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,200	SF	6	10+ years	
			.,••	•	Ū.	let yeare	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	7	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	800	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	7	10+ years	
0							
Jassroo	om #202 (Regular Classroom)	and Elean	4		7	0.10	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	7	10+ years	
	Chalk Board	2nd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	7	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	7	10+ years	
		2.13 1.661	020	0.		101 youro	



Catego	ry : Classroom		B	uilding	: Main		
-				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	820	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,280	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	805	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	15	SF	7	10+ years	Repaired.
	Chalk Board	2nd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	820	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	7	10+ years	Repaired.
	Walls - Plaster/Drywall	2nd Floor	1,150	SF	6	10+ years	
Classroo	om #205 (Science Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	7	10+ years	
	Chalk Board	2nd Floor	48	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	820	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
Classroo	om #207 (Regular Classroom) AC Units	2nd Floor	1	EA	7	6-10 years	
Classroo	AC Units	2nd Floor 2nd Floor		EA LF	7 7	6-10 years 10+ vears	
Classroo	AC Units Casework	2nd Floor	8	LF	7	10+ years	
Classroo	AC Units Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	8 800	LF SF	7 6	10+ years 10+ years	
Classroo	AC Units Casework	2nd Floor	8	LF	7	10+ years	



Catego	ry : Classroom		B	Building : Main			
eulege				anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	780	SF	7	10+ years	
	Floor - Wood	2nd Floor	20	SF	4	0-1 year	Bubbling and sinking
	Lighting - Pendent/Surface	2nd Floor	16	ĒA	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	7	10+ years	Repaired.
	Walls - Plaster/Drywall	2nd Floor	1,190	SF	6	10+ years	
Classroc	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	7	10+ years	Repaired.
	Chalk Board	2nd Floor	45	LF	4	2-5 years	-
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	740	SF	7	10+ years	
	Floor - Wood	2nd Floor	80	SF	4	0-1 year	Bubbling.
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	C C
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	40	SF	7	10+ years	Repaired.
	Walls - Structural Glazed Tile	2nd Floor	1,180	SF	7	10+ years	
Classroc	m #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	60	SF	5	0-1 year	Bubbling and cracking
lassroc	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	2-5 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	15	SF	7	10+ years	Repaired.
	Ceiling - Plaster/Drywall	2nd Floor	805	SF	7	10+ years	
	Chalk Board	2nd Floor	54	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
-				3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,190	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	30	SF	5	0-1 year	Water damage.
lassroc	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	7	10+ years	
	Chalk Board	2nd Floor	48	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	7	10+ years	
laceroo	om #301 (Regular Classroom)						
1033100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	•	
	Casework Ceiling - Plaster/Drywall	3rd Floor	800	SF	7	10+ years	
	Chalk Board	3rd Floor		LF		10+ years	
	Doors - Transom Window	3rd Floor	36 12	SF	4 7	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	12	EA	7	10+ years 10+ years	
	Floor - Wood Doors Inclu nw	3rd Floor	800	SF	6		
		3rd Floor		EA		10+ years	
	Lighting - Pendent/Surface Marker Board	3rd Floor	14 30		7 7	6-10 years	
	Storage/ Closet	3rd Floor	30 60	SF		6-10 years	
		3rd Floor	1,200	SF	5 6	10+ years	
	Walls - Plaster/Drywall	310 F1001	1,200	55	0	10+ years	
lassroc	om #302 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	42	LF	6	10+ years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	7	10+ years	Repaired.
	Chalk Board	3rd Floor	23	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	7	10+ years	




Cataga			P	uildina	Main	454	
Catego	ry : Classroom		В	uilding	: wain	Decementary	
Crour	Hom Tuno	Leastion	Questitu		Donk	Recommend	Commente
Group	Item - Type Lighting - Pendent/Surface	Location 3rd Floor	Quantity	UOM EA	Rank	Replacement 6-10 years	Comments
			16		7		
	Storage/ Closet	3rd Floor	60	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,170	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	30	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
Classroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	6	10+ years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	10		7	•	
		3rd Floor	10 60	SF	7	6-10 years	
	Storage/ Closet					10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,260	SF	6	10+ years	
Classroo	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years	
Classree	m #305 (Science Classroom)						
01855100	AC Units	3rd Floor	4	۲۸	7	6 10	
			1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	48	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	5 5		30	LF	7		



Catego	ry : Classroom		P	uilding	• Main	101	0 N Campbell AVENUE, Chicago, IL 6062
Jaleyo	19.0103510011			unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
noup	Storage/ Closet	3rd Floor	40	SF	7	10+ years	Comments
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years	
	Work Sink	3rd Floor	1,200	EA	7	6-10 years	
	Work Onik			L/	,		
lassroc	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	6	10+ years	
	Chalk Board	3rd Floor	42	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	800	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
lassroc	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	45	SF	7	•	
	Doors - Wood Doors inclu hw	3rd Floor	12	EA	7	10+ years	
			-			10+ years	
	Floor - Wood	3rd Floor	785	SF	6	10+ years	F lass a back blin a
	Floor - Wood	3rd Floor	35	SF	4	0-1 year	Floor bubbling
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years	
lassroc	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	7	10+ years	
	Chalk Board	3rd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	7	10+ years	
		514 1 1001	1,200	0	ı	io+ years	



Catego	ry : Classroom		В	uilding	: Main		ON Campbell AVENUE, Chicago, IL 60625	
_	-			_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #310 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	40	SF	7	10+ years	Repaired.	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years		
	Chalk Board	3rd Floor	45	LF	4	2-5 years		
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Wood	3rd Floor	820	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years		
	Storage/ Closet	3rd Floor	60	SF	5	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,140	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	60	SF	4	0-1 year	Cracking.	
	-					,	5	
Classroo	m #311 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Wood	3rd Floor	820	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	30	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	Updated to match current observations	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years		
Classroo	m #312 (Special Education)							
000000	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	390	SF	7	10+ years		
	Chalk Board	3rd Floor	8	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	100	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	20	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	390	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years		
	Marker Board	3rd Floor	8	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	8	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	850	SF	7	10+ years		
•	-		-			-		
-	ry : Interior			uilding		_		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments	



Stairs

Chicago



					40401	n Camp
					Replacement	
Ceiling - Plaster/Drywall	North East	900	SF	7	10+ years	
Floor - Concrete Epoxy/ Painted	North East	28	SF	7	10+ years	
Floor - Tile	North East	760	SF	7	10+ years	
Handrails	North East	190	LF	7	10+ years	
Lighting - Pendent/Surface	North East	8	EA	7	6-10 years	
Lighting - Wall Mounted	North East	3	EA	7	6-10 years	
Stairs - Concrete	North East	512	LF	7	10+ years	
Walls - Plaster/Drywall	North East	2,800	SF	7	10+ years	
Ceiling - Plaster/Drywall	South East	900	SF	7	10+ years	
Floor - Concrete Epoxy/ Painted	South East	28	SF	7	10+ years	
Floor - Tile	South East	760	SF	7	10+ years	
Handrails	South East	190	LF	7	10+ years	
Lighting - Pendent/Surface	South East	8	EA	7	6-10 years	
Lighting - Wall Mounted	South East	3	EA	7	6-10 years	
Stairs - Concrete	South East	512	LF	7	10+ years	
Walls - Plaster/Drywall	South East	2,800	SF	7	10+ years	



Category : Exterior

Building : Annex Recommend

					Recommend	
roup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance			•••••			
Entrance Control - Audio and Video	4	1	EA	7	10+ years	
Exterior Doors - Side lite	4	1	EA	7	10+ years	
Exterior Doors - Store Front	4	3	EA	7	10+ years	
Exterior Doors - Transom Lite	4	2	EA	7	10+ years	
Exterior Doors - Side lite	5	2	EA	7	10+ years	
Exterior Doors - Store Front	5	2	EA	7	10+ years	
Exterior Doors - Transom Lite	5	2	EA	7	10+ years	
	6			7	•	
Exterior Doors - Store Front	6	2	EA		10+ years	
Exterior Doors - Transom Lite	÷	1	EA	7	10+ years	
Exterior Stairs - Concrete	6	20	LF	7	10+ years	
Ramp Handrail - Steel_Ramp Handrail	6	80	LF	7	10+ years	
Ramps - Concrete	6	40	LF	7	10+ years	
Stair Handrail - Steel_Stair Handrail	6	25	LF	7	10+ years	
Entrance Control - Audio and Video	7	1	EA	7	10+ years	
Exterior Doors - Store Front	7	1	EA	7	10+ years	
Exterior Doors - Transom Lite	7	1	EA	7	10+ years	Louver
Entrance Control - Audio and Video	8	1	EA	7	10+ years	
Exterior Doors - Side lite	8	2	EA	7	10+ years	
Exterior Doors - Store Front	8	3	EA	7	10+ years	
Exterior Doors - Transom Lite	8	2	EA	7	10+ years	
Exterior Stairs - Concrete	8	54	LF	7	10+ years	
Power Door Operator and Controls	8	1	EA	7	10+ years	
Ramps - Concrete	8	36	LF	7	10+ years	
Stair Handrail - Steel_Stair Handrail	8	15	LF	7	10+ years	
oundation						
Foundation - Concrete	Entire Building	502	LF	7	10+ years	
Superstructure - Metal Deck/ Concrete	Entire Building	31,100	SF	7	10+ years	
Topping						
1.4						
ghting Exterior Lighting - Wall Mounted	Entiro Duilding	7	EA	7	10, 10, 10, 10, 10, 10, 10, 10, 10, 10,	
	Entire Building	7	EA	1	10+ years	
pof System						
Coping - Metal	Canopy Roof	300	LF	7	10+ years	
Downspouts - Interior Downspouts	Canopy Roof	12	LF	7	10+ years	
Roof - Modified Bitumen	Canopy Roof	300	SF	7	10+ years	
Roof Structure - Steel / Metal Deck/	Canopy Roof	300	SF	7	10+ years	
Concrete Topping		500	0.		io. youro	
Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
Coping - Metal	Main Roof	520	LF	7	10+ years	



	Schools	4540 N Campbell AVENUE, Chicago, IL 606								
Catego	ry : Exterior		Building : Annex							
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
	Downspouts - Interior Downspouts	Main Roof	210	LF	7	10+ years				
	Roof - Modified Bitumen	Main Roof	15,050	SF	7	10+ years				
	Roof Hatch - Metal	Main Roof	1	EA	4	1-2 years	The hatch is too small for the stair, username is always beware do not bump their head			
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	15,050	SF	7	10+ years				
Walls										
	Canopy - Metal	Entire Building	1,000	SF	7	10+ years				
	Cheek-Wall - Concrete	Entire Building	20	SF	7	10+ years				
	Exterior Walls - Brick	Entire Building	13,744	SF	7	10+ years				
	Exterior Walls - Stone-Cast	Entire Building	880	SF	7	10+ years				
Windows	3									
	Curtain wall - Glazed Double Pane	Entire Building	2,448	SF	7	10+ years				
	Lintels - Steel	Entire Building	400	LF	7	10+ years				
	Storefront Windows	Entire Building	360	SF	7	10+ years				
	Windows - Sash Aluminum Double-pane	Entire Building	1,648	SF	7	10+ years				

Building : Annex

Category : Electrical

Ŭ				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
-	Emergency Battery Packs - Corridors and Stairs	Entire Building	15	EA	7	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	6	EA	7	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	7	6-10 years	
	Security System - CCTV	Entire Building	31,100	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	31,100	SF	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	25	EA	2	0-1 year	No EM generator or battery backup
	Exit Signs - Lunchroom	Entire Building	3	EA	2	0-1 year	No EM generator or battery backup
	Emergency A/C Power - Corridors and Stairs	Entire Building	31,100	SF	7	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	31,100	SF	7	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	31,100	SF	7	6-10 years	
Main Se	vice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	31,100	SF	7	10+ years	Served from main



							O N Campbell AVENUE, Chicago, IL 60623
Catego	ry : Electrical		B	uilding	: Annex		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
					-		
Power D	istribution						
	Lighting and Power Panels - Above 100 A	1st Floor	5	EA	7	10+ years	Electrical room
	Lighting and Power Panels - Above 100 A	1st Floor		EA	7		
			2			10+ years	
	Lighting and Power Panels - Above 100 A	1st Floor	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	10+ years	IDF room
	Main Distribution Panels - 400 - 600 amp	1st Floor	1	EA	7	10+ years	Electrical room
Catego	ry : Fire Protection		B	uilding	: Annex		
Jalego				unung	. Annea	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Ebballon	Quantity	0011	Kank	Replacement	Comments
Fire Alar	Fire Alarm Panel	Entire Duilding	4	EA	<u> </u>	10	Served from main
		Entire Building	1	SF	6	10+ years	Served from main
	Fire Alarm Strobe Lights	Entire Building	31,100		7	10+ years	
	Fire Alarm_System	Entire Building	31,100	SF	7	10+ years	
	Fire Pump Controller	Entire Building	1	EA	7	10+ years	
Pumn R	oom Assembly						
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	10+ years	Pump base shows corrosion
	Jockey Pump	Mechanical Room	1	EA	7		Fump base shows conosion
	Jockey Fullip	Mechanical Room	1	LA	'	10+ years	
Sprinkle	r System						
opinitio	Sprinkler Heads	Mechanical Room	31,100	SF	7	10+ years	
	Sprinkler Piping	Mechanical Room	31,100	SF	7	10+ years	
	Wet Sprinkler System	Mechanical Room	31,100	SF	7	10+ years	
		Mechanical Room	51,100	36	'	10+ years	
Catego	ry : Mechanical		В	uilding	: Annex		
						Recommend	
Group	ltem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	litioning						
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	7	10+ years	
	than 5 tons						
Air Hand	lling Systems						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	7	10+ years	
	DX Cooling Only with Self Contained						
	Compressor - 31 - 45 tons						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	10+ years	Unit is working. Unit control needs
	DX Cooling Only with Self Contained		·		~	, care	be adjusted and does not integrate
	Compressor - 11 - 20 tons						with BAs system.
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	7	10+ years	with brid system.
	DX Cooling Only with Self Contained		I	ĽA	1	ior years	



Catego	ry : Mechanical		В	4540 N Campbell AVENUE, Chicago, IL Building : Annex				
calogo	, j i moonamou		_	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	Compressor - Greater than 45 tons							
	VAV Box	Roof	10	EA	7	10+ years	RTU-1	
	VAV Box	Roof	18	EA	7	10+ years	RTU-2	
Boiler Sy	vstems							
	Boiler Auxiliary- Scotch Marine- Hot Water Boiler - Less than 1000 MBH	1st Floor	2	EA	7	10+ years		
	Chemical Pot Feeder	1st Floor	1	EA	7	10+ years		
	Combustion Dampers	1st Floor	2	EA	7	10+ years		
	Glycol Feed System	1st Floor	1	EA	7	10+ years		
	Non Condensing- Scotch Marine- Hot Water	1st Floor	2	EA	7	10+ years		
	Boiler - Less than 1000 MBH							
	Water Fill System	1st Floor	1	EA	7	10+ years		
Heating	Devices							
-	Radiator Panels - Hot Water	Entire Building	12	EA	7	10+ years		
	Unit Heater - Electric	Entire Building	3	EA	7	10+ years		
	Unit Heater - Hot Water	Entire Building	2	EA	7	10+ years		
	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	7	10+ years		
Mechani	cal Plumbing							
	Hot Water Pump - Less than 10	1st Floor	2	EA	7	10+ years		
	Hydronic Supply and Return - Copper	Entire Building	500	LF	7	10+ years		
	Hydronic Supply and Return - Steel	Entire Building	1,500	LF	7	10+ years		
Tempera	ature Control							
	DDC System	Entire Building	31,100	SF	7	10+ years		
	Electric Thermostat	Entire Building	1	EA	7	10+ years		
Ventilatio	on							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	7	10+ years		
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	7	10+ years		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	7	10+ years		
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	7	10+ years		
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression system.	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	7	10+ years	No me suppression system.	
	rype in Exhaust 1000- Wanning Kitchen		1	LA	'	IUT years		



)	SCHOOIS						0 N Campbell AVENUE, Chicago,
Catego	ory : Plumbing		В	uilding	: Annex		
-	H (1) T (1)		0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	2	EA	7	10+ years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	31,100	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	31,100	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	31,100	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	31,100	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	31,100	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	31,100	SF	7	10+ years	
	Sanitary Piping	Entire Building	31,100	SF	7	10+ years	
	Storm Piping	Entire Building	31,100	SF	7	10+ years	
	Vent Piping	Entire Building	31,100	SF	7	10+ years	
Pumps							
•	Pumps - Sump-Simplex	1st Floor	1	EA	7	10+ years	Not accessible Elevator pit
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	2	EA	7	10+ years	· · · · · · · · · · · · · · · · · · ·
Catego	ory : Room		В	uilding	: Annex		
J				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	Quilling Director/Drawell		05	05	7	10	

7					
dministrative Suites/Offices					
Ceiling - Plaster/Drywall	1st Floor	85	SF	7	10+ years
Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years
Floor - Tile Quarry	1st Floor	85	SF	7	10+ years
Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years
Walls - Plaster/Drywall	1st Floor	304	SF	7	10+ years
Ceiling - Lay-in	218 Vestibule	140	SF	7	10+ years
Doors - Wood Doors inclu hw	218 Vestibule	1	EA	7	10+ years
Floor - Tile/Sheet	218 Vestibule	140	SF	7	10+ years
Lighting - Pendent/Surface	218 Vestibule	5	EA	7	10+ years
Walls - Plaster/Drywall	218 Vestibule	432	SF	7	10+ years
Ceiling - Lay-in	218A Asst Principal	108	SF	7	10+ years
Doors - Wood Doors inclu hw	218A Asst Principal	1	EA	7	10+ years
Floor - Tile/Sheet	218A Asst Principal	108	SF	7	10+ years
Lighting - Lay-in	218A Asst Principal	3	EA	7	10+ years
Walls - Plaster/Drywall	218A Asst Principal	304	SF	7	10+ years
Ceiling - Lay-in	218B Principal	112	SF	7	10+ years
Doors - Wood Doors inclu hw	218B Principal	1	EA	7	10+ years



Catego	ry : Room		Building : Annex					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile/Sheet	218B Principal	112	SF	7	10+ years		
	Lighting - Lay-in	218B Principal	3	EA	7	10+ years		
	Walls - Plaster/Drywall	218B Principal	352	SF	7	10+ years		
	Ceiling - Lay-in	218C Conference	168	SF	7	10+ years		
	Doors - Wood Doors inclu hw	218C Conference	1	EA	7	10+ years		
	Floor - Tile/Sheet	218C Conference	168	SF	7	10+ years		
	Lighting - Pendent/Surface	218C Conference	5	EA	7	10+ years		
	Walls - Plaster/Drywall	218C Conference	464	SF	7	10+ years		
Kitchen								
	Ceiling - Lay-in	1st Floor	4,415	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years		
	Floor - Tile Quarry	1st Floor	4,415	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years		
	Serving Line	1st Floor	47	LF	7	10+ years		
	Storage/ Closet	1st Floor	220	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	399	SF	7	10+ years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	798	SF	7	10+ years		
Lunch &	Multipurpose Room							
	Ceiling - Lay-in	1st Floor	2,394	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	ĒA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	2,394	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	18	EA	7	10+ years		
	Storage/ Closet	1st Floor	294	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,584	SF	7	10+ years		
	F							
_	Doors - Wood Doors inclu hw	218D	1	EA	7	10+ years		
	Finishes	218D	99	SF	7	10+ years		
	Other Cooling Unit	218D	1	EA	7	10+ years	Ductless split system.	
Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	10	SF	7	10+ years		
	Janitor's Closet	1st Floor	36	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	92	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	243	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	336	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	135	SF	7	10+ years		
	Janitor's Closet	2nd Floor	36	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	21	SF	7	10+ years		
	Storage Room	2nd Floor	196	SF	7	10+ years		



Catego	ry : Room		В	uilding	: Annex	[
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	3rd Floor	42	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	60	SF	7	10+ years	
	Storage Room	3rd Floor	196	SF	7	10+ years	
	Storage Room	3rd Floor	108	SF	7	10+ years	
Restroor	m						
	Accessories	1st Floor	73	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	73	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	73	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7		
		1st Floor	1			10+ years	
	Lavatory	1st Floor	•	EA	7	10+ years	
	Lighting - Lay-in		2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	100	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	172	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	231	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	231	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	231	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	3	EA	7	10+ years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	2	EA	7	10+ years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	600	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor	231	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	231	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	231	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	3	EA	7	10+ years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	2	EA	7	10+ years	
	Partitions	1st Floor	4	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	600	SF	7	10+ years	
	Water Closet	1st Floor	4	EA	7	10+ years	
	Accessories	2nd Floor	185	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	185	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	185	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	10+ years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lavalory	21011001	5		1	io+ years	



Catego	ry : Room		В	uildina	: Annex		ON Campbell AVENUE, Chicago, il 60625
e alege	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	402	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	73	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	73	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	73	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	172	SF	7	10+ years	
	Water Closet	2nd Floor	<u>-</u> 1	ĒA	7	10+ years	
	Accessories	2nd Floor	231	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	231	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	231	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	3	EA	7	10+ years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Wall Mounted	2nd Floor	2	EA	7	10+ years	
	Partitions	2nd Floor	4	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	600	SF	7	10+ years	
	Water Closet	2nd Floor	4	EA	7	10+ years	
	Accessories	3rd Floor	185	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	185	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	185	SF	7	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	10+ years	
	Lavatory	3rd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	10+ years	
	Partitions	3rd Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	114	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	402	SF	7	10+ years	
	Water Closet	3rd Floor	402	EA	7	10+ years	
	Accessories	3rd Floor	54	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	54	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	34 1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	54	SF	7	10+ years	
	Floor Drain	3rd Floor	34 1	EA	7	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	10+ years	
	Lavatory	3rd Floor	1	EA	7	10+ years	
	Lavalory	310 1 1001	I	LA	1	IUT years	



Catego	ry : Room		Building : Annex						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	3rd Floor	2	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	136	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	3rd Floor	360	SF	7	10+ years			
	Water Closet	3rd Floor	1	EA	7	10+ years			
	Accessories	3rd Floor	185	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	185	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	185	SF	7	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	2	EA	7	10+ years			
	Lavatory	3rd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	10+ years			
	Partitions	3rd Floor	2	EA	7	10+ years			
	Urinals	3rd Floor	2	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	114	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	3rd Floor	402	SF	7	10+ years			
	Water Closet	3rd Floor	2	EA	7	10+ years			

Category : Classroom

Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	om #214 (Music Room)	Location	Quantity		Nank	Replacement	Comments
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,076	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,076	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	ĒA	7	10+ years	
	Marker Board	2nd Floor	60	LF	7	6-10 years	
	Sound Panels	2nd Floor	36	EA	7	10+ years	
	Sound System	2nd Floor	1	EA	7	10+ years	
	Storage/ Closet	2nd Floor	208	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,024	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #215 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	766	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	766	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	10+ years	
	Marker Board	2nd Floor	60	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,664	SF	7	10+ years	
Classroo	om #216 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	726	SF	7	10+ years	



Catara							0 N Campbell AVENUE, Chicago, IL 6062		
Catego	ry : Classroom		Building : Annex						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Group	Doors - Wood Doors inclu hw	2nd Floor	Quantity 1	EA	7	10+ years	Comments		
	Floor - Tile/Sheet	2nd Floor	726	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	9	EA	7	10+ years			
	Marker Board	2nd Floor		LA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	848	SF	7	10+ years			
	-			•	·				
Classroo	m #217 (Regular Classroom)								
	Casework	2nd Floor	4	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	736	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	736	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	9	EA	7	10+ years			
	Marker Board	2nd Floor	60	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	800	SF	7	10+ years			
	Work Sink	2nd Floor	1	EA	7	10+ years			
Classroo	m #219 (Art Room)								
	Casework	2nd Floor	10	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	911	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	911	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years			
	Marker Board	2nd Floor	60	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	928	SF	7	10+ years			
	Work Sink	2nd Floor	1	EA	7	10+ years			
Classroo	m #316 (Other Instructional Use)								
	Ceiling - Lay-in	3rd Floor	2,308	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years			
	Floor - Carpet	3rd Floor	2,308	SF	7	6-10 years			
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years			
	Marker Board	3rd Floor	20	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	1,664	SF	7	10+ years			
Classroo	m #317 (Regular Classroom)								
	Ceiling - Lay-in	3rd Floor	733	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years			
	Floor - Tile/Sheet	3rd Floor	733	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	9	EA	7	10+ years			
	Marker Board	3rd Floor	20	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	864	SF	7	10+ years			



Catego	ry : Classroom		B	uilding	· Anney		ON Campbell AVENUE, Chicago, IL 6062	
Calego			Building : Annex Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	om #318 (Regular Classroom)		-,,,,-,-,-,-,-,-,-,-,-,-,-,-,-,					
01233100	Ceiling - Lay-in	3rd Floor	712	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	712	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	9	EA	7	10+ years		
	Marker Board	3rd Floor	20	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	832	SF	7	10+ years		
			002	0.	•	lot youro		
Classroc	om #319 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	745	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	745	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	9	EA	7	10+ years		
	Marker Board	3rd Floor	20	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	816	SF	7	10+ years		
Classroo	om #322 (Regular Classroom)							
01455100	Ceiling - Lay-in	3rd Floor	730	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	730	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	8	EA	7	10+ years		
	Lighting - Lay-in	3rd Floor	1	EA	5	0-1 year	Not functioning	
	Marker Board	3rd Floor	60	LF	7	10+ years	Not functioning	
	Walls - Plaster/Drywall	3rd Floor	1,024	SF	7	10+ years		
Cotogo	ry : Interior		P	uilding	: Annex			
Calego	ry . Interior		D	unung	. Annex	Recommend		
Group	ltem - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Lay-in	1st Floor	2,144	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years		
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	2,144	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	2,244	SF	7	10+ years		
					_	10		
	Ceiling - Lay-in	2nd Floor	2,144	SF	7	10+ years		
	Ceiling - Lay-in Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years		
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain	2nd Floor 2nd Floor	23	EA EA	7 7	10+ years 10+ years		
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet	2nd Floor 2nd Floor 2nd Floor	2 3 2,144	EA EA SF	7 7 7	10+ years 10+ years 10+ years		
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	2nd Floor 2nd Floor 2nd Floor 2nd Floor	2 3 2,144 22	EA EA SF EA	7 7 7 7	10+ years 10+ years 10+ years 10+ years		
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	2 3 2,144 22 163	EA EA SF EA EA	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years		
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	2nd Floor 2nd Floor 2nd Floor 2nd Floor	2 3 2,144 22	EA EA SF EA	7 7 7 7	10+ years 10+ years 10+ years 10+ years		



Catego	ry : Interior		В				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,144	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	22	EA	7	10+ years	
	Student Lockers - Two Tiers	3rd Floor	207	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,928	SF	7	10+ years	
Safetv							
y	Security Cameras	1st Floor	10	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Stair #3 NW	216	SF	7	10+ years	
	Floor - Tile/Sheet	Stair #3 NW	176	SF	7	10+ years	
	Handrails	Stair #3 NW	316	LF	7	10+ years	
	Lighting - Lay-in	Stair #3 NW	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Stair #3 NW	2	EA	7	10+ years	
	Stairs - Rubber	Stair #3 NW	260	LF	7	10+ years	
	Walls - Plaster/Drywall	Stair #3 NW	2,240	SF	7	10+ years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	



Category : Exterior			B	uilding	: Linked	Addition	
						Recommend	
Group Item - Type		Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
Entrance Control - Au	dio and Video	E-11 now15	1	EA	7	10+ years	
Exterior Doors - Store	Front	E-11 now15	2	EA	7	10+ years	
Exterior Doors - Exteri		Garage Entrance	1	EA	6	10+ years	
Exterior Doors - Overh		Garage OH Door	1	EA	7	10+ years	
Door	J					,	
Exterior Doors - Side I	ite	S-10 now14	2	EA	7	10+ years	
Exterior Doors - Store	Front	S-10 now14	1	EA	7	10+ years	
Exterior Doors - Trans	om Lite	S-10 now14	1	EA	7	10+ years	
Exterior Doors - Side I	ite	S-8 now 12	2	EA	7	10+ years	
Exterior Doors - Store	Front	S-8 now 12	1	EA	7	10+ years	
Exterior Doors - Trans	om Lite	S-8 now 12	1	EA	7	10+ years	
Exterior Doors - Side I	ite	S-9 now 13	2	EA	7	10+ years	
Exterior Doors - Store	Front	S-9 now 13	1	EA	7	10+ years	
Exterior Doors - Trans	om Lite	S-9 now 13	1	EA	7	10+ years	
Entrance Control - Au	dio and Video	W-7 now 11	1	EA	7	10+ years	
Exterior Doors - Store	Front	W-7 now 11	2	EA	7	10+ years	
						-	
Foundation							
Foundation - Concrete		Entire Building	384	LF	7	10+ years	
Superstructure - Slab		Entire Building	5,030	SF	7	10+ years	
·		5					
Lighting							
Exterior Lighting - Wal	I Mounted	Entire Building	6	EA	6	10+ years	
Roof System							
Access Ladder - Meta		A	1	EA	7	10+ years	
Coping - Metal		A	30	LF	7	10+ years	
Downspouts - Exterio		A	30	LF	6	10+ years	
Roof - Asphalt Gravel		A	4,260	SF	6	6-10 years	Green Roof.
Roof Structure - Steel	/ Metal Deck/	A	4,260	SF	7	10+ years	
Concrete Topping							
Coping - Metal		В	30	LF	6	10+ years	Verified dimension
Downspouts - Exterio		В	4	LF	6	6-10 years	
Roof - Modified Bitume	en	В	210	SF	6	6-10 years	
Roof Structure - Steel	/ Metal Deck/	В	210	SF	7	10+ years	
Concrete Topping							
Malla							
Walls Canopy - Fabric		Entire Building	280	SF	6	10+ years	
Canopy - Fabric							
Extorior Mollo Driek		Entiro Building		C.L.	12	1() 1 1/0000	
Exterior Walls - Brick Exterior Walls - Prefa	hricated Metal Panel	Entire Building Entire Building	3,895 670	SF SF	6 6	10+ years 10+ years	



Catego	ry : Exterior		B	Building : Linked Addition					
Ŭ				U		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Wall					-			
Windows									
	Guard - Guards perforated	Entire Building	63	SF	7	10+ years			
	Lintels - Steel	Entire Building	63	LF	7	10+ years			
	Storefront Windows	Entire Building	560	SF	7	10+ years			
	Windows - Decorative	Entire Building	343	SF	7	10+ years			
		Entrio Dananig	010	0.	•	ior youro			
Catego	ry : Electrical		В	uilding	: Linkec	Addition			
_			.			Recommend	-		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Emerger	icy System								
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	No EM generator or battery backup		
	Exit Signs - Lunchroom	Entire Building	4	EA	2	0-1 year	No EM generator or battery backup		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	4	0-1 year	No EM generator or battery backup		
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	4	0-1 year	No EM generator or battery backup		
	Security System - CCTV	Entire Building	4,699	SF	7	6-10 years	New item added per current		
		Entrie Bananig	1,000	0.		e re yeare	observation		
	Security System - Intrusion Detection	Entire Building	4,699	SF	6	6-10 years	observation		
	Emergency A/C Power - Multipurpose	Entire Building	1,980	SF	6	2			
	Room	Entire Building	1,900	ЪГ	0	6-10 years			
	Emergency A/C Power - Students Toilets	Entire Building	100	SF	6	6-10 years			
Main Sei	vice								
	PA System	Entire Building	4,699	SF	7	6-10 years	Installed new in renovation of 2020.		
Dowor D	stribution								
-ower D	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years			
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years			
	Main Distribution Failers - 400 - 000 amp	Entire Building	I	LA	1	10+ years			
Catego	ry : Fire Protection		В	uilding	: Linked	Addition			
_				-		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar	m								
	Fire Alarm Strobe Lights	Entire Building	4,699	SF	7	10+ years			
	Fire Alarm_System	Entire Building	4,699	SF	7	10+ years			
Catego	ry : Mechanical		В	uildina	: Linkec	Addition			
	-			3		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		



							0 N Campbell AVENUE, Chicago, IL 6062
Catego	ry : Mechanical		В	uilding	: Linked	Addition	
		•	0			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	VAV Box	Entire Building	3	EA	7	10+ years	Located above ceiling.
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating Coil - 11 - 20 tons	Roof	1	EA	7	10+ years	
Boiler Sy							
	Boiler Auxiliary- Condensing Hot Water - Less than 500 HP	Mechanical Room	1	EA	7	10+ years	
	Chemical Pot Feeder	Mechanical Room	1	EA	7	10+ years	
	Condensing- Hot Water Boiler - Less than 500 MBH	Mechanical Room	1	EA	7	10+ years	
	Hot Water Pump	Mechanical Room	2	EA	4	0-1 year	Per current observation only one pump working.
Heating I	Devices						
	Cabinet Heaters - With Hot Water Coil	Entire Building	1	EA	5	0-1 year	Hot water not working properly
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Mechanical Room	300	LF	7	10+ years	
F							
Tempera	ture Control		4 000			0.40	
	Electric Controls	Entire Building	4,699	SF	7	6-10 years	
	Electric Thermostat	Entire Building	3	EA	7	10+ years	
/entilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	3	0-1 year	Quantity change per current observation Only one exhaust fan Not working
	Roof Mounted Duct Work	Roof	15	LF	7	10+ years	Not Wollding
Catego	ry : Plumbing		В	uildina	: Linked	Addition	
Ŭ	, ,			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Mechanical Room	1	EA	7	10+ years	
_							
Piping						4.0	
	Domestic Piping-Hot Water Return Lines	Entire Building	5,030	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	5,030	SF	7	10+ years	
		Entire Building Entire Building	5,030	SF SF	7 7	10+ years 10+ years	



Catego	ry : Plumbing		В	Building : Linked Addition						
-				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Vent Piping	Entire Building	5,030	SF	7	10+ years				
ateac	ry : Room		в	uilding	·linker	I Addition				
alege	iy. Room			unung	. Linket	Recommend				
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
dminis	trative Suites/Offices					-				
	Ceiling - Lay-in	Teachers lounge	912	SF	7	6-10 years				
	Ceiling - Lay-in	Teachers lounge	8	SF	4	0-1 year	Water damage.			
	Doors - Wood Doors inclu hw	Teachers lounge	1	EA	7	10+ years	Mater admage.			
	Floor - Tile	Teachers lounge	920	SF	7	10+ years				
	Lighting - Lay-in	Teachers lounge	520 8	EA	7	6-10 years				
	Market Board	Teachers lounge	12		7	6-10 years				
	Walls - Plaster/Drywall	Teachers lounge	1,890	SF	7					
				EA	7	10+ years				
	Work SInk	Teachers lounge	1	EA	/	10+ years				
inch &	Multipurpose Room									
	Ceiling - Exposed	1st Floor	1,825	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor	155	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	1st Floor	1,980	SF	5	0-1 year	Cracking throughout.			
	Lighting - Lay-in	1st Floor	4	EA	7	6-10 years	erdering throughout			
	Lighting - Pendent/Surface	1st Floor	34	EA	7	6-10 years				
	Serving Line	1st Floor	12	LF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	2,000	SF	7					
			2,000	эг	/	10+ years				
echan	ical/ Service Rooms									
	Janitor's Closet	1st Floor	28	SF	5	10+ years				
	Mechanical/ Service Rooms	1st Floor	174	SF	5	10+ years				
estroo	m									
	Accessories	1st Floor	50	SF	7	6-10 years				
	Ceiling - Lay-in	1st Floor	50	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor	50	SF	7	10+ years				
	Floor Drain	1st Floor	1	EA	7	10+ years				
	Hand Dryer	1st Floor	1	EA	7	6-10 years				
	Lavatory	1st Floor	1	EA	7	10+ years				
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st Floor	150	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	1st Floor	82	SF	7	10+ years				
	Water Closet	1st Floor	02	EA	7	10+ years				
			50	SF	7		Room was not accossible			
	Accessories	1st Floor	50	эг	1	6-10 years	Room was not accessible. Components ranked based on sin			

Components ranked based on similar



							0 N Campbell AVENUE, Chicago, IL 60625
Catego	ry : Room		В	uilding	: Linke	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	-				_		rooms.
	Ceiling - Lay-in	1st Floor	50	SF	7	10+ years	Room was not accessible.
							Components ranked based on similar
	Deere Weed Deere include	1 at Elaar	4		7	10	rooms.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	Room was not accessible.
							Components ranked based on simila rooms.
	Floor - Tile Ceramic/ Porcelain	1st Floor	50	SF	7	10+ years	Tooms.
	Floor Drain	1st Floor	1	EA	7	10+ years	Room was not accessible.
		13(1100)	1	L/\	'	Tor years	Components ranked based on simila
							rooms.
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	150	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	82	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
atego	ry : Classroom		В	uildina	: Linke	d Addition	
Ŭ				Ŭ		Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	m #112B (Regular Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	890	SF	5	0-1 year	Large cracking throughout.
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	250	SF	(10+ years	
	Walls - Plaster/Drywall Work Sink	1st Floor	1,400 2	SF EA	7 7	10+ years	
	WUR SIIK	1st Floor	2	EA	1	10+ years	

Category : Interior

Building : Linked Addition

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	Link	196	SF	7	10+ years	
	Doors - Steel Doors incl hw	Link	6	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Link	196	SF	7	10+ years	
	Lighting - Lay-in	Link	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	Link	315	SF	7	10+ years	



Catego	Category : Site			uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ivil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	6	10+ years	
encing							
	Fencing - Iron and Concrete Post	Entire Site	1,232	LF	4	0-1 year	Corroded iron fence with damaged concrete piers.
	Fencing - New Standard Ornamental	Entire Site	703	LF	6	10+ years	
andsca	De						
	Benches	Entire Site	23	EA	6	10+ years	
	Landscape - Grass	Entire Site	2,500	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	3,640	SF	4	0-1 year	Missing pieces throughout.
	Lighting - Pole Mounted	Entire Site	7	EA	6	10+ years	31
	Lighting - Pole Mounted	Entire Site	7	EA	6	10+ years	
	Parkway trees	Entire Site	48	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	63,917	SF	6	10+ years	
	Play Area - Synthetic Turf	Entire Site	11,169	SF	6	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
	Walking Path - Crushed Stone	Entire Site	8,839	SF	6		
	Walking Pain - Crushed Stone	Entire Site	0,039	SF	0	10+ years	
Parking I	ot						
C C	Concrete Curbs	Entire Site	503	LF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	4	EA	6	10+ years	
	Pavers	Entire Site	6,700	SF	6	10+ years	Verified dimension
	Surface - Asphalt	Entire Site	6,500	SF	6	10+ years	Verified dimension
	Surface - Concrete	Entire Site	1,000	SF	7	10+ years	Verified dimension
	Trash Enclosure - Chain Links	Entire Site	100	SF	4	0-1 year	Hardware is broken at these steel
	Thash Enclosure Onlain Einits	Entire Oile	100	01	-	0 i your	gates
	Trash Enclosure - Masonry	Entire Site	600	SF	5	10+ years	Deteriorated mortar
	Vehicular Screening	Entire Site	349	LF	7	10+ years	Detenorated montal
	venicular objectning		0-10	L1	,	for years	
Playgrou							
	Equipment - Combo 3-12	Site - North West	1	EA	6	10+ years	
	Surface - Poured Surface	Site - North West	2,139	SF	6	10+ years	
Service (Garage						
	Service Garage - Free-Standing	South	348	SF	6	10+ years	
Sidewalk	s						
	Sidewalks - Internal Walks	Entire Site	362	LF	6	10+ years	



Catego	ry : Site	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	8,369	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	10	SF	4	0-1 year	Cracked and uneven.
	Sidewalks - Perimeter Sidewalks	Entire Site	10	SF	4	0-1 year	Cracked concrete
Signage							
	Flag Pole - Flag Pole	North East	1	EA	7	6-10 years	
	Marquee - Free Standing Back Lighted	North East	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	North East	1	EA	6	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Dear	Floor Plan		Glazed	Operable	M/instance	0
0	haten de dilles no	Dears Leasting	Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Degular Classroom	Act Floor	105	405	007	470	20	NI	
Kindergarten	Regular Classroom	1st Floor	105 107	105	907	170	36	N	N
Kindergarten	Regular Classroom	1st Floor		107	907	170	36	N	N
Office	Library	1st Floor	111	111	907	170	36	N	N
Pre School	Regular Classroom	1st Floor	108	108	877	130	23	N	N
Regular Classroom	Computer Lab	1st Floor	101	101	720	230	36	N	N
Regular Classroom	Office	2nd Floor	210	210	820	196	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	800	214	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	820	214	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	820	142	36	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	820	214	54	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	800	214	54	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	208	208	820	196	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	820	156	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	820	214	54	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	800	170	54	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	820	114	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	820	150	75	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	800	170	54	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	820	170	54	N	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	820	170	54	N	Y
Regular Classroom	Regular Classroom	3rd Floor	310	310	820	170	54	N	Y
Regular Classroom	Regular Classroom	3rd Floor	311	311	820	170	54	N	Y
Science Classroom	Regular Classroom	2nd Floor	205	205	820	214	54	N	N
Science Classroom	Regular Classroom	3rd Floor	302	302	820	170	54	N	Y
Science Classroom	Regular Classroom	3rd Floor	305	305	820	170	54	N	N
Special Education	Store Room	3rd Floor	312	312	390	104	32	N	N
						•			
Building : Annex									
Art Room	Art Room	2nd Floor	219	219	911	84	0		
Music Room	Music Room	2nd Floor	214		1,076	54	18		
Other Instructional Use	Other Instructional Use	3rd Floor	316	316	2,308	212	0		
Regular Classroom	Regular Classroom	2nd Floor	215	215	766	24	24		
Regular Classroom	Regular Classroom	2nd Floor	216	216	726	48	48		
Regular Classroom	Regular Classroom	2nd Floor	217	217	736	48	48		
Regular Classroom	Regular Classroom	3rd Floor	317	317	733	48	48		
Regular Classroom	Regular Classroom	3rd Floor	318	318	712	48	48		
Regular Classroom	Regular Classroom	3rd Floor	319	319	745	48	48		
Regular Classroom	Regular Classroom	3rd Floor	322	322	730	48	48		



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Linked Addition									
Regular Classroom	Regular Classroom	1st Floor	112B	NA	890	270	0	N	Ν