

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like new condition and no work is required while rank 1 means the item has failed and has led to an immediate life sofoty condition. The remaining ranks apporally means that the

or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1881	3	77,900
Annex	1991	3	61,000
Campus Total			138,900

Category: Exterior Building: Main

	, 1 =					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio	#1 W	1	EA	6	6-10 years	
	Exterior Doors - Exterior AMP Door	#1 W	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#1 W	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1 W	20	LF	5	0-1 year	Cracking.
	Exterior Doors - Exterior AMP Door	#2 W	2	EA	6	10+ years	-
	Exterior Doors - Transom Lite	#2 W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 W	24	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#3 S	2	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 E	1	EΑ	6	10+ years	
	Exterior Doors - Side lite	#4 E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#4 E	6	LF	5	10+ years	Minor cracking.
	Exterior Doors - Exterior Steel Door	#5 E	1	EA	6	10+ years	Area under construction, doorframes, temporarily dislodged
	Exterior Stairs - Concrete	#5 E	4	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6 N	1	EA	6	6-10 years	Verify that this door is in fair working condition and solid, including frames.
	Exterior Doors - Exterior AMP Door	#7 N	2	EA	6	10+ years	
	Ramps - Concrete	#7 N	24	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Fire escape	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Fire escape	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Lightwell entrance	1	EA	6	10+ years	
	Exterior Stairs - Stone	Lightwell entrance	3	LF	5	6-10 years	



Categor	y : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Esca	••	Location	Quantity	CON	IVALIK	Replacement	Comments
FIIE ESC	Exterior Doors - Exterior Steel Door	West	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	West	2	EA	6	10+ years	
	Fire Escape	West	126	LF	5	1-2 years	Broken connectors, spalled
	·					•	connectors
	Paints	West	126	LF	3	0-1 year	Corroding fire escape
oundation	on						
	Foundation - Concrete	Entire Building	1,242	LF	7	10+ years	
	Foundation - Concrete	Entire Building	10	LF	5	0-1 year	Open joints at Stone foundation, broken stone. Of particular note is the missing foundation at the corner of the building between doors, six and seven. Missing foundation is cracking the stone about it as it is being displaced. Water from the roof above has been diverted towards this area of the building, and has undermined the foundation wall and the stone above it.
	Superstructure - Heavy Timber	Entire Building	77,900	SF	7	10+ years	
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	12	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	6-10 years	
oof Sys	tem						
coor cys	Coping - Metal	1 - North Roofs	116	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	1 - North Roofs	61	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	1 - North Roofs	35	LF	4	0-1 year	Of particular note is the missing foundation at the corner of the building between doors, six and seven. Missing foundation is cracking the stone above it as it is being displaced. Water from the roof above has been diverted towards this area of the building, and has undermined the foundation wall and the stone above it.
	Parapet - Parapet < 16" Height	1 - North Roofs	116	LF	6	10+ years	abovo it.
	Roof - Modified Bitumen	1 - North Roofs	1,620	SF	6	2-5 years	Not able to access the southern roofs. Clouded over Lexan fixed windows, poor visibility



atego	ry : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Heavy Timber	1 - North Roofs	1,620	SF	7	10+ years	
	Access Ladder - Wood	2 - South Roofs	1	EA	4	0-1 year	Unable to access.
	Coping - Clay Tile	2 - South Roofs	203	LF	6	10+ years	
	Downspouts - Exterior Downspouts	2 - South Roofs	157	LF	6	6-10 years	
	Parapet - 16" - 30" Height	2 - South Roofs	203	LF	6	10+ years	
	Roof - Modified Bitumen	2 - South Roofs	2,033	SF	6	6-10 years	Per Engineer Unsafe access.
	Roof Structure - Heavy Timber	2 - South Roofs	2,033	SF	7	10+ years	
	Coping - Clay Tile	3 - Sloped Roofs	280	LF	6	10+ years	
	Parapet - Parapet < 16" Height	3 - Sloped Roofs	270	LF	6	10+ years	
	Parapet - Parapet < 16" Height	3 - Sloped Roofs	10	LF	5	1-2 years	Open joints, cracked brick
	Roof - Asphalt Shingle	3 - Sloped Roofs	11,311	SF	6	6-10 years	•
	Roof - Asphalt Shingle	3 - Sloped Roofs	220	SF	4	0-1 year	Missing shingles throughout larger
	1 3	•				,	roofs, deteriorated and curling
							shingles
	Roof Structure - Heavy Timber	3 - Sloped Roofs	11,531	SF	7	10+ years	5g.55
	Access Ladder - Metal	4 - Center North	1	ĒΑ	7	6-10 years	
	Chimney - Brick Chimney- Concrete/ Mortar	4 - Center North	20	LF	7	10+ years	Repaired
	Liner	. Comer Herm	20		•	ioi youro	rtopanoa
	Chimney - Brick Chimney- Concrete/ Mortar	4 - Center North	48	LF	6	10+ years	
	Liner	4 - Genter North	40	LI	O	10+ years	
	Coping - Clay Tile	4 - Center North	65	LF	6	10+ years	
	Downspouts - Exterior Downspouts	4 - Center North	48	LF	7	10+ years	
	Downspouts - Exterior Downspouts	4 - Center North	48	LF	6	6-10 years	
	Parapet - 16" - 30" Height	4 - Center North	65	LF	6	10+ years	
	Roof - Modified Bitumen	4 - Center North	1,143	SF	5	0-1 year	Some soft spots, no current leaks
	Roof Structure - Heavy Timber	4 - Center North	1,143	SF	7	10+ years	Some son spots, no current leaks
	Access Ladder - Wood	5 - Upper Center	1,143	EA	4	0-1 year	Homemade wood Ladder is secure
	Access Lauder - Wood	5 - Opper Center	ı	EA	4	0-1 year	
							with only one construction screw a
	Coning Clay Tile	5 Umman Cantan	077	LF	•	40	each side
	Coping - Clay Tile	5 - Upper Center	277	LF LF	6	10+ years	
	Downspouts - Exterior Downspouts	5 - Upper Center	144		6	6-10 years	
	Parapet - 16" - 30" Height	5 - Upper Center	269	LF	6	10+ years	ъ .
	Parapet - 16" - 30" Height	5 - Upper Center	8	LF	4	0-1 year	Bowing parapet
	Roof - Modified Bitumen	5 - Upper Center	3,823	SF	6	6-10 years	
	Roof Hatch - Metal	5 - Upper Center	1	EA	5	1-2 years	Corroded old hatch
	Roof Structure - Heavy Timber	5 - Upper Center	3,823	SF	7	10+ years	
	Coping - Clay Tile	6 - Center South	80	LF	6	10+ years	
	Coping - Metal_	6 - Center South	3	LF	6	10+ years	
	Downspouts - Exterior Downspouts	6 - Center South	144	LF	6	6-10 years	
	Parapet - 16" - 30" Height	6 - Center South	80	LF	6	10+ years	
	Roof - Modified Bitumen	6 - Center South	1,819	SF	6	6-10 years	Slight blistering
	Roof Structure - Heavy Timber	6 - Center South	1,819	SF	7	10+ years	
	Coping - Clay Tile	7 - Lower East	269	LF	6	10+ years	Several pieces Replaced with new
	Downspouts - Exterior Downspouts	7 - Lower East	85	LF	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet < 16" Height	7 - Lower East	269	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	7 - Lower East	3,950	SF	4	0-1 year	Severe blistering, vegetation growth open seams at termination bar, no counter flashing holes in membrane
	Roof - Metal	7 - Lower East	48	SF	4	0-1 year	Corroding metal roof
	Roof Structure - Heavy Timber	7 - Lower East	3,998	SF	7	10+ years	
Valls							
	Cornice - Cast Stone	Entire Building	318	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	45,245	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	400	SF	5	2-5 years	
	Exterior Walls - Brick	Entire Building	200	SF	4	0-1 year	Deteriorated sealant at control joints
	Exterior Walls - Prefabricated Metal Panel	Entire Building	128	SF	5	0-1 year	spalled, cracked brick, open joints Corroding metal
	Wall						
	Exterior Walls - Stone-Cast	Entire Building	4,158	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	1,469	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	35	SF	4	1-2 years	Cracked stone. Stone is cracking near door four, between doors, six and seven, because there is a missing piece of foundation. The wais unsupported.
Vindow		Fatina Divildia a	00	SF		C 40 vacara	
	Clerestory - Glass Double-Pane	Entire Building	96		6	6-10 years	
	Guard - Guards wire guard	Entire Building	3,062	SF LF	6	6-10 years	
	Lintels - Brick	Entire Building	160	LF LF	6	6-10 years	One also allegials failing a lintal
	Lintels - Brick	Entire Building	5		5	1-2 years	Cracked brick, failing lintel
	Lintels - Steel	Entire Building	520	LF	6	10+ years	
	Lintels - Stone	Entire Building	135	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	48	SF	5	1-2 years	Only one skylight, broken glass
	Windows - Louver	Entire Building	15	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,280	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	580	SF	5	2-5 years	
	Windows - Sash Aluminum Double-pane	Entire Building	48	SF	4	0-1 year	Two missing windows
	ry : Electrical		В	uilding	: Main	Danamand	
Catego						Recommend	
J	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Froup	Item - Type ncy System	Location	Quantity	UOM	Rank	Replacement	Comments



Catego	ry : Electrical		В	uilding	: Main	<u> </u>	TIZ W Occingo OTNEET, Omocago, ie occito
2 3 0	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	33	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	7	10+ years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	2,583	SF	6	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	16,048	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,113	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	776	SF	6	10+ years	
	Security System - CCTV	Entire Building	77,900	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	77,900	SF	6	6-10 years	
_Main Se	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	To be installed
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	For fire pump.
	Main Electrical Service - 1200 A 277/480/3PH	Electrical Room	1	EA	7	10+ years	For Chiller only
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	77,900	SF	6	2-5 years	
Power D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	6	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	10+ years	



Catego	ry : Fire Protection		В	uilding	: Main		<u> </u>
0	Mana Tana	Laadlan	0	HOM	Danila	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Fire Alar		Fating Duitsting				40	A
	Fire Alarm Panel Fire Alarm Panel	Entire Building Entire Building	1	EA EA	7 7	10+ years	Annunciator.
	Fire Alarm Strobe Lights	Entire Building	77,900	SF	6	10+ years 10+ years	
	Fire Alarm_System	Entire Building	77,900	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
Pump R	oom Assembly						
•	Fire Pump - 25-50 hp	Mechanical Room	1	EA	4	1-2 years	Corroding
Sprinkle	r System						
	Dry Sprinkler System	Entire Building	77,900	SF	5	6-10 years	
	Sprinkler Heads	Entire Building	77,900	SF	4	2-5 years	Dated
	Sprinkler Piping	Entire Building	77,900	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Conc							
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	10+ years	To be installed
	Chiller-Air Cooled-Scroll Type-Ground Mounted - Greater than 200 tons	Site - East	1	EA	7	10+ years	
Δir Hand	lling Systems						
All Hall	Air Handling Unit- Built Up- Multi Zone-	Basement	1	EA	7	10+ years	To be installed
	Double Delivery- Hot Water and Chilled Water Coils - 45001 - 60000 cfm	basement	1	LA	,	10+ years	To be installed
	Air Intake	Basement	1	EA	7	10+ years	
	Auxiliaries - 45001 - 60000 cfm	Basement	1	EA	7	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	200	LF	7	10+ years	
	Zone Dampers	Basement	25	EA	7	10+ years	
Boiler Sy	vstems						
·	Boiler Auxiliary- Condensing Hot Water - 2001 - 3000 HP	Boiler Room	2	EA	7	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	7	10+ years	
	Condensing- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	7	10+ years	
	Dual Temperature Pump	Boiler Room	1	EA	7	10+ years	
	Dual Temperature Pump	Boiler Room	1	EA	7	10+ years	



O-t-					N '	32	212 W George STREET, Chicago, IL 6067
Catego	ry : Mechanical		В	uilding	: Main		
C	Itana Tuma	Location	0	HOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Glycol Feed System	Boiler Room	1	EA	7	10+ years	
Heating	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	14	EA	7	10+ years	New
	Cabinet Heaters - With Electric Coil	Entire Building	2	EA	5	6-10 years	
	Fin Tube - Hot Water	Entire Building	150	LF	7	10+ years	New
Mechani	cal Plumbing						
	Dual Temperature Pump - Less than 10	Air Handling Unit	1	EA	7	10+ years	
	Dual Temperature Pump - Less than 10	Air Handling Unit	1	ĒΑ	7	10+ years	
	Hydronic Supply and Return - Copper	Entire Building	300	LF	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	300	LF	7	10+ years	
Temnera	ture Control						
Отпроте	DDC System	Entire Building	77,900	SF	7	10+ years	
	Electric Thermostat	Entire Building	2	EA	5	2-5 years	
	Thermostats - DDC	Entire Building	37	EA	7	10+ years	
	memostats - DDO	Entire Ballating	51	LA	,	10+ years	
√entilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	7	10+ years	New
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	7	10+ years	New
	CFM						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	4	0-1 year	No longer in use
2010.00			D	يم منالم الدي	. Main		
Jalego	ry : Plumbing		В	uilding	. IVIAIII	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate		Location	Quantity	00111	IXAIIK	Replacement	Comments
ioi vvai	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	7	10+ years	Newly installed
						·	•
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	77,900	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	77,900	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	77,900	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	77,900	SF	6	10+ years	
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	Entire Building	77,900	SF	6	10+ years	
	1 3 11 0 11 0 11 0 1 1 1 1 1 1 1 1 1 1 1		,		-	- ,	



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	77,900	SF	6	10+ years	
	(from Risers to Fixtures)	•				•	
	Sanitary Piping	Entire Building	77,900	SF	6	10+ years	
	Storm Piping	Entire Building	77,900	SF	6	10+ years	
	Vent Piping	Entire Building	77,900	SF	6	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	7	10+ years	Newly installed

Category : Room **Building: Main**

						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	AC Unit	1st Floor - Assistant Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Assistant Principal's Office	260	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Assistant Principal's Office	2	EA	7	10+ years	
	Floor - Tile	1st Floor - Assistant Principal's Office	260	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Assistant Principal's Office	3	EA	7	6-10 years	
	Power Distribution	1st Floor - Assistant Principal's Office	6	EA	7	10+ years	
	Storage/ Closet	1st Floor - Assistant Principal's Office	100	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Assistant Principal's Office	516	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Copy Room 100 (currently under construction)	176	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Copy Room 100 (currently under construction)	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Copy Room 100 (currently under construction)	176	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Copy Room 100 (currently under construction)	3	EA	7	10+ years	
	Power Distribution	1st Floor - Copy Room 100 (currently under construction)	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Copy Room 100 (currently under construction)	176	SF	6	10+ years	
	AC Unit	1st Floor - Main Office	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Main Office	423	SF	6	10+ years	



Category : Room		В	uilding	: Main				
						Recommend		
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	1st Floor - Main Office	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - Main Office	1	EA	7	10+ years		
	Floor - Tile	1st Floor - Main Office	419	SF	7	10+ years		
	Floor - Tile	1st Floor - Main Office	4	SF	4	0-1 year	Broken tile, subfloor exposed	
	Lighting - Pendent/Surface	1st Floor - Main Office	3	EA	7	6-10 years		
	Power Distribution	1st Floor - Main Office	6	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - Main Office	816	SF	6	10+ years		
	AC Unit	1st Floor - Staff Lounge	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor - Staff Lounge	230	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - Staff Lounge	1	EA	6	10+ years		
	Floor - Tile	1st Floor - Staff Lounge	230	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor - Staff Lounge	3	EA	6	6-10 years		
	Power Distribution	1st Floor - Staff Lounge	10	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - Staff Lounge	414	SF	6	10+ years		
	AC Unit	2nd Floor - Office 206	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor - Office 206	370	SF	6	10+ years		
	Doors - Side-lite	2nd Floor - Office 206	40	SF	6	10+ years		
	Doors - Transom Window	2nd Floor - Office 206	12	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor - Office 206	1	EΑ	7	10+ years		
	Floor - Wood	2nd Floor - Office 206	370	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor - Office 206	5	ĒΑ	7	10+ years		
	Power Distribution	2nd Floor - Office 206	8	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor - Office 206	800	SF	6	10+ years		
	AC Unit	2nd Floor - Office 208 (under	1	EA	7	6-10 years		
		construction)						
	Ceiling - Plaster/Drywall	2nd Floor - Office 208 (under	377	SF	6	10+ years		
		construction)						
	Doors - Transom Window	2nd Floor - Office 208 (under	6	SF	7	10+ years		
		construction)						
	Doors - Wood Doors inclu hw	2nd Floor - Office 208 (under	1	EA	7	10+ years		
		construction)				•		
	Floor - Tile	2nd Floor - Office 208 (under	377	SF	6	10+ years		
		construction)				•		
	Lighting - Pendent/Surface	2nd Floor - Office 208 (under	6	EA	7	6-10 years		
		construction)				•		
	Power Distribution	2nd Floor - Office 208 (under	6	EA	7	10+ years		
		construction)				,		
	Walls - Plaster/Drywall	2nd Floor - Office 208 (under	1,097	SF	6	10+ years		
		construction)	.,501	-	·	,		
	Ceiling - Plaster/Drywall	3rd Floor - Office 302 (Under	370	SF	6	10+ years		
	January Wall	construction)	0.0	٥.	J	io. youro		
	Doors - Wood Doors inclu hw	3rd Floor - Office 302 (Under	1	EA	6	10+ years		
	Doors - Wood Doors India HW	construction)	'	LA	U	TOT years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor - Office 302 (Under	370	SF	6	10+ years		
	1 1001 - THE CETAITHO FUICEIAIH	314 FIDDI - OHICE 302 (UNGE)	370	SI-	U	10+ years		





Catego	ry : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
		construction)						
	Lighting - Pendent/Surface	3rd Floor - Office 302 (Under	5	EA	7	6-10 years		
	D. Divile	construction)	40	_^	•	40		
	Power Distribution	3rd Floor - Office 302 (Under	10	EA	6	10+ years		
	Malla Diagtor/Draviali	construction)	000	C.E.	•	40		
	Walls - Plaster/Drywall	3rd Floor - Office 302 (Under	800	SF	6	10+ years		
	Ceiling - Plaster/Drywall	construction) 3rd Floor - PTA Room 300	394	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor - PTA Room 300	1	EA	7	10+ years		
	Floor - Wood	3rd Floor - PTA Room 300	394	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor - PTA Room 300	5	EA	7	6-10 years		
	Power Distribution	3rd Floor - PTA Room 300	6	EA	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor - PTA Room 300	882	SF	6	10+ years		
	AC Unit	Basement - Engineer's Office	1	EA	5	6-10 years		
	AC OTH	(Currently Storage)		LA	3	0-10 years		
	Ceiling - Lay-in	Basement - Engineer's Office	115	SF	6	10+ years		
	20g 2a,	(Currently Storage)		О.	ŭ	. o · you.o		
	Doors - Wood Doors inclu hw	Basement - Engineer's Office	1	EA	6	10+ years		
		(Currently Storage)				,		
	Floor - Wood	Basement - Engineer's Office	115	SF	7	10+ years		
		(Currently Storage)				-		
	Lighting - Pendent/Surface	Basement - Engineer's Office	1	EA	7	6-10 years		
		(Currently Storage)						
	Power Distribution	Basement - Engineer's Office	6	EA	6	10+ years		
		(Currently Storage)						
	Walls - Plaster/Drywall	Basement - Engineer's Office	258	SF	6	10+ years		
		(Currently Storage)			_			
	Ceiling - Exposed	Kitchen Manager office	300	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Kitchen Manager office	1	EA	6	10+ years		
	Floor - Concrete Epoxy/ Painted	Kitchen Manager office	300	SF	5	10+ years		
	Lighting - Pendent/Surface	Kitchen Manager office	3	EA	7	6-10 years		
	Power Distribution	Kitchen Manager office	2	EA	7	10+ years		
	Walls - Masonry	Kitchen Manager office	550	SF	7	10+ years		
	Walls - Plaster/Drywall	Kitchen Manager office	140	SF	6	10+ years		
_Auditoriu	ım & Theater							
	Ceiling - Plaster/Drywall	3rd Floor	2,583	SF	6	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years		
	Floor - Wood	3rd Floor	2,583	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	16	EΑ	7	6-10 years		
	Main Floor Seating	3rd Floor	250	EΑ	7	10+ years		
	Sound System	3rd Floor	1	EA	7	6-10 years		
	Stage	3rd Floor	500	SF	7	10+ years		
	Stage Curtain	3rd Floor	1	EA	7	10+ years		



Catego	ry : Room		В	uilding	: Main		212 W George STREET, Chicago, IL 60616
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stage Lighting System	3rd Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	3rd Floor	12	LF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,133	SF	6	10+ years	
Gvmnas	ia						
,	Ceiling - Plaster/Drywall	3rd Floor	3,113	SF	6	10+ years	No max occupancy sign
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years	. , ,
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Sport Flooring	3rd Floor	3,113	SF	7	6-10 years	Updated to match current
	Lighting - Metal Halide/ High Pressure	3rd Floor	8	EA	7	6-10 years	observations
	Sodium Walls - Plaster/Drywall	3rd Floor	4,611	SF	6	10+ years	
	Wallo Tlasten Bly Wall	314 1 1001	4,011	O.	O	101 years	
Kitchen							
	AC Unit	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	709	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	709	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	10	EA	7	6-10 years	
	Serving Line	Basement	16	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,070	SF	6	10+ years	
Lunch &	Multipurpose Room						
	AC Unit	Basement	1	EA	5	0-1 year	Does not work.
	Ceiling - Plaster/Drywall	Basement	1,068	SF	6	10+ years	No max occupancy sign
	Floor - Tile/Sheet	Basement	1,068	SF	7	10+ years	. , ,
	Lighting - Pendent/Surface	Basement	12	EA	7	6-10 years	
	Storage/ Closet	Basement	300	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,380	SF	6	10+ years	
MDF ID	F						
	Doors - Wood Doors inclu hw	2nd Floor inside Classroom 210	1	EA	7	10+ years	
	Finishes	2nd Floor inside Classroom 210	105	SF	7	10+ years	
	Window AC Unit	2nd Floor inside Classroom 210	1	EA	7	6-10 years	
Mechani	ical/ Service Rooms						
WECHAII	Janitor's Closet	1st Floor	6	SF	5	10+ years	Water damage to walls
	Janitor's Closet	2nd Floor	20	SF	5	10+ years	Nonfunctional light
	Janitor's Closet	3rd Floor	6	SF	5	10+ years	Nonfunctional light, strong must odor
	Air Tunnel	Basement	930	SF	5	10+ years	
	Boiler Room	Basement	1,217	SF	7	10+ years	Under construction
	Coal Room	Basement	250	SF	7	10+ years	Under construction
		2300110111	200	٥.	•	.o. youro	223. 30.131.431.011



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	Basement	100	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	350	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	95	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	290	SF	7	10+ years	
	Storage Room	Basement	121	SF	7	10+ years	Under construction
	Storage Room	Basement	100	SF	7	10+ years	
	Storage Room	Basement	95	SF	7	10+ years	
	Storage Room	Basement	150	SF	7	10+ years	
	Storage Room	Basement	95	SF	5	10+ years	Under construction
Restroon	n						
	Accessories	1st Floor - 106 Restroom	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - 106 Restroom	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - 106 Restroom	1	EA	7	10+ years	
	Floor - Tile	1st Floor - 106 Restroom	40	SF	6	6-10 years	
	Lavatory	1st Floor - 106 Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - 106 Restroom	1	EA	7	6-10 years	
	Partitions	1st Floor - 106 Restroom	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - 106 Restroom	82	SF	7	10+ years	
	Water Closet	1st Floor - 106 Restroom	1	EA	7	10+ years	
	Accessories	1st Floor - Staff Lounge Restroom	115	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Staff Lounge Restroom	115	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Staff Lounge Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor - Staff Lounge Restroom	110	SF	6	10+ years	
	Floor - Tile	1st Floor - Staff Lounge Restroom	5	SF	4	1-2 years	Loose and broken tiles
	Floor Drain	1st Floor - Staff Lounge Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor - Staff Lounge Restroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Staff Lounge Restroom	2	EA	7	6-10 years	
	Partitions	1st Floor - Staff Lounge Restroom	3	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Staff Lounge Restroom	269	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Staff Lounge Restroom	5	SF	5	1-2 years	Water damage
	Water Closet	1st Floor - Staff Lounge Restroom	3	EA	7	10+ years	
	Accessories	1st Floor Principal Toilet	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Principal Toilet	56	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Principal Toilet	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Principal Toilet	56	SF	6	10+ years	
	Lavatory	1st Floor Principal Toilet	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Principal Toilet	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor Principal Toilet	115	SF	6	10+ years	
	Water Closet	1st Floor Principal Toilet	1	ĒΑ	7	10+ years	
	Accessories	2nd Floor - Boys Room	206	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Boys Room	206	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Boys Room	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Boys Room	206	SF	7	10+ years	





Catego	ry : Room	Building : Main							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor Drain	2nd Floor - Boys Room	1	EA	7	10+ years			
	Hand Dryer	2nd Floor - Boys Room	2	EA	7	6-10 years			
	Lavatory	2nd Floor - Boys Room	2	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor - Boys Room	4	EA	7	6-10 years			
	Partitions	2nd Floor - Boys Room	2	EA	7	10+ years			
	Urinals	2nd Floor - Boys Room	6	EΑ	7	10+ years			
	Walls - Concrete Block	2nd Floor - Boys Room	403	SF	7	10+ years			
	Water Closet	2nd Floor - Boys Room	2	EA	7	10+ years			
	Accessories	2nd Floor - Girls Restroom	206	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor - Girls Restroom	206	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor - Girls Restroom	2	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Girls Restroom	206	SF	7	10+ years			
	Floor Drain	2nd Floor - Girls Restroom	1	EA	7	10+ years			
	Hand Dryer	2nd Floor - Girls Restroom	2	EA	7	6-10 years			
	Lavatory	2nd Floor - Girls Restroom	2	EA	7	10+ vears	Updated quantity		
	Lighting - Pendent/Surface	2nd Floor - Girls Restroom	4	EA	7	6-10 years	-1 49		
	Partitions	2nd Floor - Girls Restroom	7	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor - Girls Restroom	403	SF	7	10+ years			
	Water Closet	2nd Floor - Girls Restroom	7	ĒΑ	7	10+ years			
	Accessories	2nd Floor - Men's Staff Restroom	210	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor - Men's Staff Restroom	210	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor - Men's Staff Restroom	1	ĒΑ	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Men's Staff Restroom	210	SF	7	10+ years			
	Floor Drain	2nd Floor - Men's Staff Restroom	1	ĒΑ	7	10+ years			
	Lavatory	2nd Floor - Men's Staff Restroom	1	EΑ	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor - Men's Staff Restroom	1	EΑ	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor - Men's Staff Restroom	488	SF	7	10+ years			
	Water Closet	2nd Floor - Men's Staff Restroom	1	EA	7	10+ years			
	Accessories	2nd Floor - Women's Staff Room	210	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor - Women's Staff Room	210	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor - Women's Staff Room	2	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Women's Staff Room	90	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Women's Staff Room	120	SF	7	10+ years			
	Floor Drain	2nd Floor - Women's Staff Room	1	EA	7	10+ years			
	Lavatory	2nd Floor - Women's Staff Room	1	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor - Women's Staff Room	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor - Women's Staff Room	488	SF	7	10+ years			
	Water Closet	2nd Floor - Women's Staff Room	1	EA	7	10+ years			
	Accessories	Basement - North Boy's Restroom	170	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement - North Boy's Restroom	170	SF	7	<u>-</u>			
	Floor - Tile Ceramic/ Porcelain	Basement - North Boy's Restroom	170	SF SF	7	10+ years 10+ years			
				SF EA		•			
	Floor Drain	Basement - North Boy's Restroom	1	EA EA	7	10+ years			
	Lavatory	Basement - North Boy's Restroom	2	EA EA	7 7	10+ years			
	Lighting - Pendent/Surface	Basement - North Boy's Restroom	3	ĽΑ	1	6-10 years			



Category : Room			Building : Main						
						Recommend	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	Basement - North Boy's Restroom	2	EA	7	10+ years			
	Urinals	Basement - North Boy's Restroom	2	EA	7	10+ years			
	Walls - Plaster/Drywall	Basement - North Boy's Restroom	162	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement - North Boy's Restroom	278	SF	7	10+ years			
	Water Closet	Basement - North Boy's Restroom	2	EA	7	10+ years			
	Accessories	Basement - North Girls' Restroom	215	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement - North Girls' Restroom	215	SF	6	10+ years	paint peeling		
	Floor - Tile Ceramic/ Porcelain	Basement - North Girls' Restroom	215	SF	7	6-10 years			
	Floor Drain	Basement - North Girls' Restroom	1	EA	7	10+ years			
	Lavatory	Basement - North Girls' Restroom	3	EA	7	10+ years			
	Lighting - Pendent/Surface	Basement - North Girls' Restroom	4	EA	7	6-10 years			
	Partitions	Basement - North Girls' Restroom	4	EΑ	7	10+ years			
	Walls - Plaster/Drywall	Basement - North Girls' Restroom	186	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement - North Girls' Restroom	434	SF	7	10+ years			
	Water Closet	Basement - North Girls' Restroom	4	EA	7	10+ years			
	Accessories	Basement - Restroom across from	65	SF	7	6-10 years			
	710003301103	Lunchroom	00	O.	,	o to years			
	Ceiling - Lay-in	Basement - Restroom across from	65	SF	7	10+ years			
	Ceiling - Lay-in	Lunchroom	03	Si	,	10+ years			
	Doors - Wood Doors inclu hw	Basement - Restroom across from	2	EA	7	10+ years			
	Doors - Wood Doors Inclu IIW		2	EA	,	10+ years			
	Flace Tile	Lunchroom	C.F.	C.E.	7	40			
	Floor - Tile	Basement - Restroom across from	65	SF	7	10+ years			
	Floor Drain	Lunchroom	4	EA	7	40			
	Floor Drain	Basement - Restroom across from	1	EA	7	10+ years			
		Lunchroom		- ^	-	0.40			
	Hand Dryer	Basement - Restroom across from	1	EA	7	6-10 years			
		Lunchroom			_				
	Lavatory	Basement - Restroom across from	1	EA	7	10+ years			
		Lunchroom	_		_				
	Lighting - Pendent/Surface	Basement - Restroom across from	1	EA	7	6-10 years			
		Lunchroom							
	Walls - Plaster/Drywall	Basement - Restroom across from	130	SF	7	10+ years			
		Lunchroom							
	Water Closet	Basement - Restroom across from	1	EA	7	10+ years			
		Lunchroom							
	Accessories	Basement - South Boys' Restroom	650	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement - South Boys' Restroom	650	SF	7	10+ years			
	Floor - Concrete Epoxy/ Painted	Basement - South Boys' Restroom	650	SF	7	10+ years			
	Floor Drain	Basement - South Boys' Restroom	1	EA	7	10+ years			
	Hand Dryer	Basement - South Boys' Restroom	2	EA	7	10+ years	Shared with S Girls' Restroom		
	Lavatory	Basement - South Boys' Restroom	4	EA	7	10+ years	Shared with S Girl's Restroom		
	Lighting - Pendent/Surface	Basement - South Boys' Restroom	4	EA	7	10+ years			
	Partitions	Basement - South Boys' Restroom	7	EΑ	4	0-1 year	Doors removed from stalls with		
		232	·		-	- , ,	urinals to create dividers		
							aa.o to oroato arriadio		



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Urinals	Basement - South Boys' Restroom	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - South Boys' Restroom	224	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement - South Boys' Restroom	500	SF	7	10+ years	
	Water Closet	Basement - South Boys' Restroom	4	EA	7	10+ years	
	Accessories	Basement - South Girl's Restroom	650	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - South Girl's Restroom	650	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement - South Girl's Restroom	650	SF	7	10+ years	
	Floor Drain	Basement - South Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement - South Girl's Restroom	2	EA	7	6-10 years	
	Lavatory	Basement - South Girl's Restroom	4	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement - South Girl's Restroom	4	EA	7	10+ years	
	Partitions	Basement - South Girl's Restroom	7	EΑ	7	10+ years	Updated quantity
	Walls - Plaster/Drywall	Basement - South Girl's Restroom	219	SF	7	10+ years	opacion quartity
	Walls - Plaster/Drywall	Basement - South Girl's Restroom	5	SF	4	0-1 year	Hole through plaster due to
	•	Basement Godin Gins Residoin	_			o i yeai	construction
	Walls - Structural Glazed Tile	Basement - South Girl's Restroom	500	SF	7	10+ years	
	Water Closet	Basement - South Girl's Restroom	7	EΑ	7	10+ years	Updated quantity
	Accessories	Basement - Women's Staff Restroom	140	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Women's Staff Restroom	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Women's Staff Restroom	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement - Women's Staff Restroom	140	SF	7	10+ years	
	Lavatory	Basement - Women's Staff Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement - Women's Staff Restroom	2	EA	7	10+ years	
	Partitions	Basement - Women's Staff Restroom	2	EA	7	10+ years	
	Student Lockers - One Tier	Basement - Women's Staff Restroom	1	EA	7	10+ years	
	Walls - Masonry	Basement - Women's Staff Restroom	80	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Women's Staff Restroom	310	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Women's Staff Restroom	10	SF	5	1-2 years	Damage from the previous construction
	Water Closet	Basement - Women's Staff Restroom	2	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



					Replacement	, , ,
Classroom #101 (Office)						
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	757	SF	6	10+ years	
Chalk Board	1st Floor	25	LF	4	2-5 years	
Doors - Transom Window	1st Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
Floor - Wood	1st Floor	757	SF	7	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
Marker Board	1st Floor	12	LF	6	6-10 years	
Storage/ Closet	1st Floor	125	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	1,313	SF	6	10+ years	
_Classroom #102 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	756	SF	6	10+ years	
Doors - Transom Window	1st Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	740	SF	7	10+ years	
Floor - Tile	1st Floor	16	SF	4	0-1 year	Broken tiles
Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Dioken tiles
Marker Board	1st Floor	17	LF	7	6-10 years	
Storage/ Closet	1st Floor	100	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	1,313	SF	7	10+ years	
Walls - Flaster/Drywall	131 1001	1,515	OI.	,	10+ years	
Classroom #103 (Regular Classroom)						
AC Units	1st Floor	1	EΑ	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	823	SF	6	10+ years	
Doors - Transom Window	1st Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
Floor - Wood	1st Floor	823	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
Marker Board	1st Floor	12	LF	7	6-10 years	
Storage/ Closet	1st Floor	125	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	1,397	SF	7	10+ years	
Classroom #104 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	850	SF	6	10+ years	
Chalk Board	1st Floor	25	LF	4	2-5 years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Wood	1st Floor	850	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
Marker Board	1st Floor	12	LF	7	6-10 years	
Walls - Plaster/Drywall	1st Floor	1,397	SF	6	10+ years	
		1,001	٥.	Ŭ	. o . youro	



					Replacement	
assroom #105 (Regular Classroom)					replacement	
AC Units	1st Floor	2	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	808	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Wood	1st Floor	808	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EA	7		
Marker Board	1st Floor		LF	7	10+ years	
	1st Floor	12	SF		6-10 years	
Storage/ Closet		125		7	10+ years	
Walls - Plaster/Drywall	1st Floor	1,382	SF	6	10+ years	
assroom #106 (Pre School)						
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	823	SF	6	10+ years	
Doors - Transom Window	1st Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
Floor - Tile	1st Floor	823	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
Marker Board	1st Floor	6	LF	7	6-10 years	
Storage/ Closet	1st Floor	40	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	1,387	SF	7	10+ years	
Walls Flaster/BryWall	13(1100)	1,007	Oi.	,	101 years	
ssroom #107 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	817	SF	6	10+ years	
Doors - Transom Window	1st Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Wood	1st Floor	817	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
Marker Board	1st Floor	12	LF	7	6-10 years	
Storage/ Closet	1st Floor	125	SF	5	10+ years	Water damage, crumbling plaste
Walls - Plaster/Drywall	1st Floor	1,380	SF	6	10+ years	
ssroom #108 (Kindergarten)						
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	800	SF	6	10+ years	
Doors - Transom Window	1st Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	800	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor			7		
		14	EA SF		6-10 years	
Storage/ Closet	1st Floor	125		7	10+ years	
Walls - Plaster/Drywall	1st Floor	1,380	SF	7	10+ years	
Work Sink	1st Floor	1	EA	7	10+ years	
ssroom #109 (Regular Classroom)						



					Replacement	
Ceiling - Plaster/Drywall	1st Floor	754	SF	6	10+ years	
Doors - Transom Window	1st Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Wood	1st Floor	754	SF	7	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
Marker Board	1st Floor	12	LF	7	6-10 years	
Storage/ Closet	1st Floor	125	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	1,313	SF	7	10+ years	
assroom #110 (Regular Classroom)						
AC Units	1st Floor	2	EΑ	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	762	SF	6	10+ years	
Doors - Transom Window	1st Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Wood	1st Floor	762	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
Marker Board	1st Floor	6	LF	7	6-10 years	
Storage/ Closet	1st Floor	125	SF			
				7	10+ years	
Walls - Plaster/Drywall	1st Floor	1,313	SF	7	10+ years	
assroom #201 (Regular Classroom)						
AC Units	2nd Floor	1	EΑ	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	753	SF	6	10+ years	
Chalk Board	2nd Floor	24	LF	4	2-5 years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Wood	2nd Floor	753	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	10+ years	
Marker Board	2nd Floor	12	LF	7	6-10 years	
Storage/ Closet	2nd Floor	125	SF	7	10+ years	Updated to match current
•					•	observations
Walls - Plaster/Drywall	2nd Floor	1,313	SF	7	10+ years	
ssroom #202 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	756	SF	6	10+ years	
Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Wood	2nd Floor	756	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	6	10+ years	
Marker Board	2nd Floor	12	LF	7		
					6-10 years	Motor domesto colling and a
Storage/ Closet	2nd Floor	125	SF	5	10+ years	Water, damage to ceiling and wa near windows
				7	10+ years	



						212 W George GTREET, Officago, IE 00010
4011.5	2 15		- ^	_	Replacement	
AC Units	2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	823	SF	6	10+ years	
Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
Floor - Wood	2nd Floor	823	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	10+ years	
Marker Board	2nd Floor	12	LF	7	6-10 years	
Storage/ Closet	2nd Floor	125	SF	5	10+ years	Water damage on walls
Walls - Plaster/Drywall	2nd Floor	1,397	SF	7	10+ years	
_Classroom #204 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	835	SF	6	10+ years	
Chalk Board	2nd Floor	44	LF	4	2-5 years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Wood	2nd Floor		SF			
		835		6	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
Marker Board	2nd Floor	16	LF	7	6-10 years	
Storage/ Closet	2nd Floor	125	SF	5	10+ years	Cracking plaster and peeling paint
Walls - Plaster/Drywall	2nd Floor	1,397	SF	7	10+ years	
Classroom #205 (Regular Classroom)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years	
Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
Floor - Wood	2nd Floor	810	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	10+ years	
Marker Board	2nd Floor	24	LF	7	6-10 years	
Storage/ Closet	2nd Floor	125	SF	5	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,382	SF	7	10+ years	
Walls - Flastel/Diywall	211d F1001	1,302	SF	,	10+ years	
_Classroom #207 (Regular Classroom)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	812	SF	6	10+ years	
Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
Floor - Wood	2nd Floor	812	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
Marker Board	2nd Floor	12	LF	7	6-10 years	
Storage/ Closet	2nd Floor	125	SF	5	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,382	SF	7	10+ years	
Classroom #209 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
AC UIIIS	ZHU FIOOI	1	LA	,	0-10 years	



7227 00110013						212 W George STREET, Chicago, IL 60616
					Replacement	
Ceiling - Plaster/Drywall	2nd Floor	814	SF	6	10+ years	
Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Wood	2nd Floor	814	SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
Marker Board	2nd Floor	18	LF	7	6-10 years	
Storage/ Closet	2nd Floor	125	SF	5	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,382	SF	6	10+ years	
Classroom #210 (Computer Lab)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	830	SF	6	10+ years	
Chalk Board	2nd Floor	6	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	10+ years	
Floor - Wood	2nd Floor	830	SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	10+ years	
Marker Board	2nd Floor	26	LF	7	6-10 years	
	2nd Floor	125	SF		10+ years	
Storage/ Closet				5	•	
Walls - Plaster/Drywall	2nd Floor	1,397	SF	7	10+ years	
Work Sink	2nd Floor	1	EA	5	0-1 year	Nonfunctional
Classroom #211 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	760	SF	6	10+ years	
Doors - Wood Doors inclu hw		700				
	2nd Floor	I	EA	7	10+ years	
Floor - Wood	2nd Floor	760	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
Marker Board	2nd Floor	24	LF	7	6-10 years	
Storage/ Closet	2nd Floor	125	SF	5	10+ years	Water damage, crumbling plaster
Walls - Plaster/Drywall	2nd Floor	1,313	SF	6	10+ years	3,
Classroom #212 (Regular Classroom)						
	On d Ele - :				0.40	
AC Units	2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	761	SF	6	10+ years	
Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Wood	2nd Floor	761	SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
Marker Board	2nd Floor		LF			
		24		7	6-10 years	
Storage/ Closet	2nd Floor	121	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,313	SF	6	10+ years	
Classroom #301 (Music Room)						
AC Units	3rd Floor	2	EA	7	6-10 years	
AO Offico	010 1 1001	۷	L A	'	o lo years	



					Replacement	
Ceiling - Plaster/Drywall	3rd Floor	828	SF	6	10+ years	
				6		
Doors - Transom Window	3rd Floor	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
Floor - Wood	3rd Floor	828	SF	7	6-10 years	
Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
Marker Board	3rd Floor	8	LF	7	6-10 years	
Storage/ Closet	3rd Floor	125	SF	5	6-10 years	Peeling paint
Walls - Plaster/Drywall	3rd Floor	1,397	SF	6	10+ years	· .
_Classroom #303 (Store Room)						
AC Units	3rd Floor	3	EA	7	6-10 years	
Ceiling - Plaster/Drywall	3rd Floor	821	SF	6	10+ years	
Chalk Board	3rd Floor	29	LF	4	2-5 years	
Doors - Transom Window	3rd Floor		SF		•	
		6		7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
Floor - Tile	3rd Floor	781	SF	6	6-10 years	
Floor - Tile	3rd Floor	40	SF	4	0-1 year	Cracking through tiles
Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
Marker Board	3rd Floor	12	LF	7	6-10 years	
Storage/ Closet	3rd Floor	125	SF	5	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,397	SF	6	10+ years	
_Classroom #B-1 (Faculty Lounge)						
AC Units	Basement	2	EA	7	6-10 years	
Ceiling - Plaster/Drywall	Basement	668	SF	6	10+ years	
Chalk Board	Basement	12	LF	4	2-5 years	
Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
Floor - Wood	Basement	668	SF	7	10+ years	
		14	EA	7		
Lighting - Pendent/Surface	Basement				6-10 years	
Marker Board	Basement	15	LF	7	6-10 years	
Walls - Plaster/Drywall	Basement	980	SF	7	10+ years	
Classroom #B-2 (Store Room)						
AC Units	Basement	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	Basement	724	SF	6	10+ years	
Ceiling - Plaster/Drywall	Basement	100	SF	4	0-1 year	Water damage to ceiling
Chalk Board	Basement	10	ĹF	4	2-5 years	5 5
Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
Floor - Tile	Basement	804	SF	6	10+ years	
Floor - Tile	Basement	20	SF	4	0-1 year	Missing and broken tiles
Lighting - Pendent/Surface	Basement	14	EA	7		wissing and broken tiles
				-	6-10 years	
Walls - Masonry	Basement	760	SF	7	10+ years	NA/ 4 1
Walls - Masonry Walls - Plaster/Drywall	Basement Basement	30 396	SF SF	5 6	0-1 year 10+ years	Water damage



					Replacement	
assroom #B-3 (Regular Classroom)					•	
AC Units	Basement	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	Basement	704	SF	6	10+ years	
Ceiling - Plaster/Drywall	Basement	120	SF	5	1-2 years	Cracking plaster
Chalk Board	Basement	8	LF	4	2-5 years	Graeimig placter
Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
Floor - Wood	Basement	824	SF	7	10+ years	
Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years	
Marker Board	Basement	6	LF	6	6-10 years	
Walls - Masonry	Basement	790	SF	7	10+ years	
Walls - Plaster/Drywall	Basement	396	SF	6	10+ years	
assroom #B-4 (Store Room) AC Units	Dagament	2	EA	7	6.10.40000	
	Basement Basement	2 872	EA SF	7	6-10 years	
Ceiling - Plaster/Drywall		- · -	SF LF	6	10+ years	
Chalk Board	Basement	18		4	2-5 years	
Doors - Wood Doors inclu hw	Basement	1	EA SF	7	10+ years	
Floor - Wood	Basement	872	SF EA	7	10+ years	
Lighting - Pendent/Surface	Basement	14		6	6-10 years	
Marker Board	Basement	12	LF	7	6-10 years	
Walls - Masonry Walls - Plaster/Drywall	Basement	790 396	SF SF	6 6	10+ years	
walls - Flastel/Drywall	Basement	390	SI	O	10+ years	
assroom #B-5 (Multi Purpose Room)						
AC Units	Basement	2	EA	7	6-10 years	
Ceiling - Plaster/Drywall	Basement	724	SF	6	10+ years	
Chalk Board	Basement	12	LF	4	2-5 years	
Doors - Steel Doors incl hw	Basement	1	EA	7	10+ years	
Doors - Transom Window	Basement	8	SF	7	10+ years	
Floor - Wood	Basement	724	SF	7	10+ years	
Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years	
Walls - Plaster/Drywall	Basement	1,028	SF	6	10+ years	
lassroom #B-6 (Store Room)						
AC Units	Basement	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	Basement	882	SF	6	10+ years	
Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
Floor - Wood	Basement	882	SF	7	10+ years	
Lighting - Pendent/Surface	Basement	12	EA	7	10+ years	
Marker Board	Basement	14	LF	7	6-10 years	
Walls - Masonry	Basement	730	SF	7	10+ years	
	Basement	60	SF	5	0-1 year	Water damage, spalling
Walls - Masonry			SF	7	10+ years	



					Replacement	
AC Units	Basement	2	EA	7	6-10 years	
Ceiling - Plaster/Drywall	Basement	718	SF	6	10+ years	
Doors - Transom Window	Basement	8	SF	7	10+ years	
Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
Floor - Tile	Basement	658	SF	7	10+ years	
Floor - Tile	Basement	60	SF	4	0-1 year	Cracking tiles
Lighting - Pendent/Surface	Basement	14	EA	7	10+ years	
Marker Board	Basement	16	LF	7	6-10 years	
Walls - Plaster/Drywall	Basement	1,018	SF	6	10+ years	
_Classroom #Library 3rd Fl (Music Room)						
AC Units	3rd Floor	2	EA	7	6-10 years	
Ceiling - Plaster/Drywall	3rd Floor	824	SF	6	10+ years	
Doors - Steel Doors incl hw	3rd Floor	3	EA	6	10+ years	
Floor - Tile	3rd Floor	814	SF	7	6-10 years	
Floor - Tile	3rd Floor	10	SF	4	1-2 years	Missing/chipping.
Lighting - Pendent/Surface	3rd Floor	16	EA	6	10+ years	3 3
Storage/ Closet	3rd Floor	125	SF	7	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,260	SF	6	10+ years	

Category : Interior Building: Main

						Recommend	
Group Item -	Туре	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
Ceiling	g - Plaster/Drywall	1st Floor	2,560	SF	7	10+ years	
Doors	- Wood Doors include hw	1st Floor	2	EA	7	10+ years	
Drinkir	ng Fountains - Double Fountain	1st Floor	2	EA	7	10+ years	
Floor -	- Asphalt Floor	1st Floor	1,280	SF	7	10+ years	
Floor -	- Wood	1st Floor	1,280	SF	7	10+ years	
Lightin	ng - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
Stude	nt Lockers - One Tier	1st Floor	12	EA	7	10+ years	
Walls	- Plaster/Drywall	1st Floor	6,088	SF	6	10+ years	
	g - Plaster/Drywall	2nd Floor	2,568	SF	6	10+ years	
Drinkir	ng Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
Drinkir	ng Fountains - Triple Fountain	2nd Floor	1	EA	7	10+ years	
Floor -	- Asphalt Floor	2nd Floor	1,700	SF	7	10+ years	
Floor -	- Wood	2nd Floor	868	SF	7	10+ years	
Lightin	ng - Pendent/Surface	2nd Floor	18	EA	7	10+ years	
Walls	- Plaster/Drywall	2nd Floor	6,088	SF	7	10+ years	
Ceiling	g - Plaster/Drywall	3rd Floor	1,158	SF	7	10+ years	
Doors	- Wood Doors include hw	3rd Floor	2	EA	7	10+ years	
Drinkir	ng Fountains - Double Fountain	3rd Floor	1	EA	5	1-2 years	Out of order
	- Asphalt Floor	3rd Floor	570	SF	7	10+ years	
	- Wood	3rd Floor	588	SF	7	10+ years	
Lightin	ng - Pendent/Surface	3rd Floor	8	EA	7	6-10 years	
•	- Plaster/Drywall	3rd Floor	2,084	SF	6	10+ years	

Page : 23 of 51



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement	1,926	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	4	EA	7	10+ years	
	Drinking Fountains - Triple Fountain	Basement	1	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	1,926	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	18	EA	6	6-10 years	
	Walls - Masonry	Basement	2,503	SF	7	10+ years	
Safetv							
,	Camera Viewing Station	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	8	EA	7	6-10 years	
	Security Cameras	Entire Building	10	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	#1	138	SF	6	10+ years	
	Floor - Tile	#1	276	SF	6	10+ years	
	Handrails	#1	170	LF	7	6-10 years	
	Lighting - Pendent/Surface	#1	2	EA	7	6-10 years	
	Stairs - Asphalt	#1	600	LF	7	10+ years	
	Walls - Plaster/Drywall	#1	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	#2	138	SF	6	10+ years	
	Floor - Asphalt	#2	276	SF	6	10+ years	
	Handrails	#2	170	LF	7	6-10 years	
	Lighting - Pendent/Surface	#2	2	EA	7	10+ years	
	Stairs - Asphalt	#2	420	LF	7	10+ years	
	Walls - Plaster/Drywall	#2	1,180	SF	6	10+ years	
	Ceiling - Plaster/Drywall	#3	138	SF	7	10+ years	
	Floor - Asphalt	#3	276	SF	7	10+ years	
	Handrails	#3	170	LF	7	10+ years	
	Lighting - Pendent/Surface	#3	6	EA	7	10+ years	
	Stairs - Asphalt	#3	420	LF	7	10+ years	
	Walls - Plaster/Drywall	#3	1,180	SF	7	10+ years	
	Ceiling - Plaster/Drywall	#7	138	SF	6	10+ years	
	Floor - Asphalt	#7	276	SF	7	10+ years	
	Handrails	#7	170	LF	7	10+ years	
	Lighting - Pendent/Surface	#7	2	EA	7	6-10 years	
	Stairs - Asphalt	#7	420	LF	7	10+ years	
	Walls - Plaster/Drywall	#7	1,180	SF	6	10+ years	





Category : Exterior **Building: Annex**

JOIY . Exterior			unung		Recommend	
o Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nce		•			•	
Entrance Control - Audio and Video	#01 S	1	EA	6	6-10 years	
Exterior Doors - Side lite	#01 S	3	EA	6	10+ years	
Exterior Doors - Store Front	#01 S	4	EΑ	6	6-10 years	
Exterior Doors - Transom Lite	#01 S	2	EA	6	6-10 years	
Exterior Stairs - Concrete	#01 S	18	LF	6	10+ years	
Power Door Operator and Controls	#01 S	1	EA	7	6-10 years	
Exterior Doors - Exterior Steel Door	#02 S	1	ΕA	6	10+ years	
Exterior Doors - Transom Lite	#02 S	1	EA	6	10+ years	
Exterior Stairs - Concrete	#02 S	3	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#03 E	1	ĒΑ	6	10+ years	
Exterior Doors - Transom Lite	#03 E	1	EΑ	6	10+ years	
Exterior Stairs - Concrete	#03 E	3	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#04 E	2	EA	6	10+ years	
Exterior Doors - Transom Lite	#04 E	_ 1	EΑ	5	1-2 years	Corroded door frames
Exterior Stairs - Concrete	#04 E	6	LF	6	10+ years	Concaca acor names
Exterior Doors - Exterior Steel Door	#05 E	1	EA	6	10+ years	
Exterior Doors - Transom Lite	#05 E	1	EΑ	6	10+ years	
Exterior Stairs - Concrete	#05 E	3	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#06 E	1	ĒΑ	5	1-2 years	Corroded door frame
Exterior Doors - Transom Lite	#06 E	1	EΑ	6	10+ years	Concaca acor name
Exterior Stairs - Concrete	#06 E	3	LF	5	0-1 year	Crumbling.
Exterior Doors - Exterior Steel Door	#07 E	2	ĒΑ	6	10+ years	Grambling.
Exterior Doors - Transom Lite	#07 E	1	EΑ	6	10+ years	
Exterior Stairs - Concrete	#07 E	6	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#08 E	1	EΑ	6	6-10 years	
Exterior Doors - Transom Lite	#08 E	· 1	ĒΑ	4	0-1 year	Corroding
Exterior Stairs - Concrete	#08 E	3	LF	6	10+ years	Corroaning
Exterior Doors - Exterior Steel Door	#09 N	1	EΑ	6	10+ years	
Exterior Doors - Transom Lite	#09 N	1	EA	6	10+ years	
Exterior Stairs - Concrete	#09 N	3	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#10 N	1	EA	6	10+ years	
Exterior Doors - Transom Lite	#10 N	1	EA	6	10+ years	
Exterior Stairs - Concrete	#10 N	3	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#11 N	1	ĒΑ	5	1-2 years	Corroded door frame
Exterior Doors - Transom Lite	#11 N	1	EA	6	10+ years	Sofficial door frame
Exterior Stairs - Concrete	#11 N	3	LF	5	6-10 years	
Exterior Doors - Exterior Steel Door	Roof	1	EA	5	1-2 years	Roof threshold is retaining water a corroding the door
Exterior Stairs - Concrete	Roof	3	LF	6	10+ years	corroding the door
dation						
Foundation - Concrete	Entire Building	662	LF	7	10+ years	



Category : Exterior			В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Foundation - Concrete	Entire Building	20	LF	6	1-2 years	Cracked concrete foundation, some missing pieces, broken concrete. There has been some settlement a the gym.
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	61,000	SF	7	10+ years	3,
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	12	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	17	EA	6	6-10 years	
Roof Sys	stem						
	Access Ladder - Metal	1 - Main	1	EA	7	6-10 years	
	Chimney - Metal Flue	1 - Main	5	LF	6	6-10 years	
	Coping - Metal	1 - Main	625	LF	6	6-10 years	
	Downspouts - Interior Downspouts	1 - Main	240	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	1 - Main	625	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	1 - Main	15,190	SF	5	0-1 year	Roof is ponding, water is not being delivered to the drains. Poorly pitched. Open seams, constantly being repaired.
	Roof Hatch - Metal	1 - Main	1	EA	5	0-1 year	Corroding hatch
	Roof Structure - Steel / Metal Deck/ Concrete Topping	1 - Main	15,190	SF	7	10+ years	Consum g manum
	Coping - Metal	2 - Lower east	205	LF	6	6-10 years	
	Downspouts - Interior Downspouts	2 - Lower east	52	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	2 - Lower east	205	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	2 - Lower east	4,045	SF	4	0-1 year	Ponding, improperly pitched, continuously being repaired. Termination bar only, no counter flashing. Soft spots throughout.
	Roof Structure - Steel / Metal Deck/ Concrete Topping	2 - Lower east	4,045	SF	7	10+ years	g. con op oo among.com
	Coping - Metal	3 - Lower South	171	LF	6	6-10 years	
	Downspouts - Interior Downspouts	3 - Lower South	26	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	3 - Lower South	171	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	3 - Lower South	6,160	SF	4	0-1 year	Ponding, improperly pitched, continuously being repaired. Termination bar only, no counter flashing. Soft spots throughout.
	Roof Structure - Steel / Metal Deck/ Concrete Topping	3 - Lower South	6,160	SF	7	10+ years	nacining. Con opole unoughout.





Category : Exterior			Building : Annex					
Catego	Ty . Exterior			unung	. Alliex	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	nem - Type	Location	Quantity	OOW	Italik	Replacement	Comments	
Walls	E (' W II D' I	E 0 B 1 P	04.505			10		
	Exterior Walls - Brick	Entire Building	31,535	SF	6	10+ years	5	
	Exterior Walls - Brick	Entire Building	200	SF	5	1-2 years	Deteriorated sealant at control joints,	
							cracked or spalled brick	
Windows								
	Lintels - Steel	Entire Building	852	LF	5	10+ years		
	Storefront Windows	Entire Building	480	SF	6	6-10 years		
	Windows - Casement Aluminum Double-	Entire Building	2,504	SF	6	6-10 years		
	pane							
	Windows - Casement Aluminum Double-	Entire Building	1,136	SF	6	6-10 years		
	pane							
	Windows - Louver	Entire Building	48	SF	6	10+ years		
<u>.</u> .			_		_			
Catego	ry : Electrical		В	uilding	: Annex			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Emerger	ncy System							
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years		
	Security System - CCTV	Entire Building	77,900	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	77,900	SF	6	2-5 years		
	Emergency Battery Packs - Corridors and	Entire Building	17	EA	6	10+ years		
	Stairs							
	Emergency Battery Packs - Gym	Entire Building	4	EΑ	6	10+ years		
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	7	10+ years		
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	10+ years		
	Emergency A/C Power - Corridors and	Entire Building	10,735	SF	6	10+ years		
	Stairs							
	Emergency A/C Power - Lunchrooms	Entire Building	3,338	SF	6	10+ years		
	Emergency A/C Power - Multipurpose	Entire Building	6,355	SF	6	10+ years		
	Room							
	Emergency A/C Power - Students Toilets	Entire Building	950	SF	6	10+ years		
	Exit Signs - Corridors and Stairs	Entire Building	18	EA	6	6-10 years		
	Exit Signs - Gym	Entire Building	4	EA	6	6-10 years		
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years		
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years		
Main Se								
	Main Electrical Service - 1200 A	Electrical Room	1	EA	6	10+ years		
	277/480/3PH							
	Independent Electrical Service for	Entire Building	1	EA	6	10+ years		
	emergency power							
	Independent Electrical Service for	Entire Building	1	EA	6	10+ years	For fire pump.	





Catego	ry : Electrical		В	uilding	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	emergency power						
	PA System	Entire Building	61,000	SF	6	2-5 years	
wer D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	6	10+ years	
	amp	3				,	
	Transformers - 277/480 - 120/208	Entire Building	2	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
	F. B. (1)	ŭ	_			•	
atego	ry : Fire Protection		В	uilding	: Annex	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
re Alaı	m						
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Annunciator.
	Fire Alarm Panel	Entire Building	1	EA	3	1-2 years	Dated, cannot be upgraded
	Fire Alarm_System	Entire Building	61,000	SF	4	0-1 year	Dated system, no strobes in
							classrooms
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	
ımp R	oom Assembly						
•	Fire Pump - 25-50 hp	1st Floor	1	EA	6	10+ years	
	Jockey Pump	1st Floor	1	EA	6	10+ years	
orinkle	r System						
	Sprinkler Heads	Entire Building	61,000	SF	7	10+ years	
	Sprinkler Piping	Entire Building	61,000	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	61,000	SF	7	10+ years	
atego	ry : Mechanical		В	uilding	: Annex		
						Recommend	
		Location	Quantity	UOM	Rank	Replacement	Comments
oup	Item - Type						
•	Item - Type ditioning Chiller-Air Cooled- Recipricating-Ground			EA			



ategory : Mechanical		В	uilding	: Annex				
		0	11014		Recommend			
oup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Mounted - 201 - 300 tons						per engineer, difficult to get replacement parts		
Pipes - Chilled Water Pipe- Steel	Boiler Room	100	LF	6	6-10 years			
Condensing Unit- Ground Mounted -	Site North	1	EA	4	0-1 year	Consistent issues per engineer		
Greater than 50 tons					-	heavily rusted		
Condensing Unit- Ground Mounted -	Site North	1	EA	4	0-1 year	Consistent issues per engineer,		
Greater than 50 tons						heavily rusted		
Handling Systems								
Air Handling Unit- Package Single Zone-	2nd Floor - AHU3	1	EA	6	10+ years	AHU-3		
Indoor- Dual Temperature Coils - 6000-					•			
10000 cfm								
Air Intake	2nd Floor - AHU3	1	EA	6	10+ years			
Air Handling Unit- Package Single Zone-	3rd Floor - AHU4	1	EA	6	10+ years	AHU-4		
Indoor- Dual Temperature Coils - 15001-					•			
20000 cfm	Ond Floring Al III.4	4	_^	0	40			
Air Intake	3rd Floor - AHU4	1	EA EA	6	10+ years	ALILLO lacated above spiling		
Air Handling Unit- Package Single Zone-	AHU-2	1	EA	6	10+ years	AHU-2, located above ceiling.		
Indoor- Dual Temperature Coils - Less than								
6000 cfm Air Intake	AHU-2	4	ГΛ	6	6 10 veers			
Air Handling Unit- Package Single Zone-	Kitchen/Mechanical Room - AHU1	1	EA EA	6 5	6-10 years 6-10 years	ALILI 1 leasted shave sailing		
Indoor- Dual Temperature Coils - Less than	Kitchen/Mechanical Room - And i	1	EA	5	6-10 years	AHU-1, located above ceiling.		
6000 cfm								
Air Intake	Kitchen/Mechanical Room - AHU1	1	EA	6	6-10 years			
All littake	Kitcheri/iviechanical Koom - Arto i	ı	LA	O	0-10 years			
ler Systems								
Boiler Auxiliary- Non Condensing Hot Water - 3001 - 4000 MBH	Boiler Room	2	EA	6	6-10 years			
Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years			
Combustion Dampers	Boiler Room	1	EA	2	0-1 year	There is no outside air source.		
Non Condensing- Flexible Tube-	Boiler Room	2	EA	6	10+ years			
Atmospheric- Hot Water Boiler - 3001 - 4000					•			
MBH .								
Water Fill System	Boiler Room	1	EA	6	10+ years			
ating Devices								
Fin Tube - Electric	Entire Building	20	LF	4	1-2 years	Covers are damaged.		
Fin Tube - Hot Water	Entire Building	60	LF	6	6-10 years			
Cabinet Heaters - With Hot Water Coil	Entire Building	8	EA	5	6-10 years			
Unit Heater - Hot Water	Entire Building	4	ĒΑ	6	10+ years			
	-				•			
chanical Plumbing								



Categor	ry : Mechanical	3212 W George STREET, Chicago, Building : Annex					
Caregory - moonamous				unung	. Allica	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	Comments
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years 2-5 years	
	Dual Temperature Pump - 21 - 50 HP	Boiler Room	1	EA	5	2-5 years 2-5 years	
			1				
	Dual Temperature Pump - 21 - 50 HP	Boiler Room		EA	5	2-5 years	Maria
	Hydronic Supply and Return - Steel	Entire Building	1,000	LF	7	10+ years	New
	Chilled Water Pump - 21 - 50 HP	Mechanical Room	1	EA	5	2-5 years	
	Chilled Water Pump - 21 - 50 HP	Mechanical Room	1	EA	5	2-5 years	
Tempera	ture Control						
'	Electric Thermostat	Entire Building	2	EA	5	6-10 years	
	Electric Thermostat	Entire Building	_ 1	EA	5	6-10 years	
	Pneumatic System	Entire Building	61,000	SF	3	0-1 year	Not operational
	Thermostats - Pneumatic	Entire Building	38	EA	4	0-1 year	Not operational
	memosiais - medinaic	Entire Ballaing	30	LA	7	0-1 year	Not operational
Unit Vent							
	Unit Ventilators- Floor Mounted- Dual	Entire Building	23	EA	5	2-5 years	
	Temperature Coils (Hot/Chilled) Water						
Ventilatio	in.						
Veridiado	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	2	EA	7	10+ years	
	CFM	Entire Building	2	LA	,	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	2	EA	7	10+ years	
	CFM						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	10	EA	6	10+ years	EF 6,10,22,20,7,19,18,9,1,5
	CFM				_	4.0	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	7	10+ years	
	CFM		_	- 4	_	4.0	
	Exhaust Fans- Roof Mounted - Less than	Entire Building	5	EA	7	10+ years	Installed 2021
	500 CFM Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	
	Type I Exhaust Hood- Michell	Entire Ballating	'	LA	U	0-10 years	
Categor	y : Plumbing		В	uilding	: Annex		
Group	Itom - Typo	Location	Quantity	HOM	Donk	Recommend	Comments
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
THUL WATE	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	6	6-10 years	
	Cas rieater - Less than 190000 BTO/TIK	Bollet Room	2	LA	U	0-10 years	
Piping							
5	Domestic Piping-Hot Water Return Lines	Entire Building	61,000	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	61,000	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	61,000	SF	6	10+ years	
	Fixtures	Ç	•			•	

Page : 30 of 51





Catego	ry : Plumbing	Building : Annex							
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	61,000	SF	6	10+ years			
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	61,000	SF	6	10+ years			
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	61,000	SF	6	10+ years			
	Sanitary Piping	Entire Building	61,000	SF	6	10+ years			
	Storm Piping	Entire Building	61,000	SF	6	10+ years			
	Vent Piping	Entire Building	61,000	SF	6	10+ years			
Pumps									
·	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	6	6-10 vears			

Catego	ry : Room		Building : Annex							
						Recommend				
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
dminist	rative Suites/Offices									
	Ceiling - Lay-in	1st Floor - 103 Office	90	SF	7	10+ years				
	Doors - Steel Doors incl hw	1st Floor - 103 Office	1	EA	7	10+ years				
	Floor - Tile/Sheet	1st Floor - 103 Office	90	SF	7	10+ years				
	Lighting - Lay-in	1st Floor - 103 Office	1	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - 103 Office	162	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor-114 Teacher's Lounge	828	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-114 Teacher's Lounge	3	EA	6	10+ years				
	Floor - Tile	1st Floor-114 Teacher's Lounge	828	SF	7	6-10 years				
	Lighting - Lay-in	1st Floor-114 Teacher's Lounge	8	EA	7	10+ years				
	Power Distribution	1st Floor-114 Teacher's Lounge	6	EA	6	10+ years				
	Storage/ Closet	1st Floor-114 Teacher's Lounge	25	SF	7	10+ years				
	Walls - Concrete Block	1st Floor-114 Teacher's Lounge	265	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor-114 Teacher's Lounge	1,635	SF	6	10+ years				
	Work SInk	1st Floor-114 Teacher's Lounge	1	EA	7	6-10 years				
	Ceiling - Lay-in	1st Floor-Boiler Room Office	118	SF	7	10+ years				
	Doors - Steel Doors incl hw	1st Floor-Boiler Room Office	1	EA	7	10+ years				
	Floor - Tile	1st Floor-Boiler Room Office	118	SF	7	10+ years				
	Lighting - Lay-in	1st Floor-Boiler Room Office	2	EA	7	10+ years				
	Power Distribution	1st Floor-Boiler Room Office	6	EA	7	10+ years				
	Walls - Concrete Block	1st Floor-Boiler Room Office	260	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor-Gym Office	115	SF	7	10+ years				
	Doors - Side-lite	1st Floor-Gym Office	6	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-Gym Office	1	EA	7	10+ years				
	Floor - Tile	1st Floor-Gym Office	115	SF	7	10+ years				
	Lighting - Lay-in	1st Floor-Gym Office	2	EA	7	10+ years				
	Power Distribution	1st Floor-Gym Office	6	EA	7	10+ years				
	Walls - Concrete Block	1st Floor-Gym Office	254	SF	7	10+ years				







Category: Room **Building: Annex** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments 1st Floor-Lunchroom Manager's SF Ceiling - Lay-in 108 7 10+ years Office Doors - Steel Doors incl hw 1st Floor-Lunchroom Manager's 1 FΑ 7 10+ years Floor - Tile 1st Floor-Lunchroom Manager's 108 SF 7 10+ years Office Lighting - Lay-in 1st Floor-Lunchroom Manager's 2 EΑ 7 10+ years Office Power Distribution 1st Floor-Lunchroom Manager's 4 EΑ 6 10+ years Office Walls - Concrete Block 1st Floor-Lunchroom Manager's 282 SF 7 10+ vears Office 1st Floor-Main Office 670 SF 7 Ceiling - Lay-in 10+ years SF Ceiling - Lay-in 1st Floor-Main Office 60 4 0-1 year Water damage Doors - Side-lite SF 7 1st Floor-Main Office 124 10+ years Doors - Transom Window SF 7 1st Floor-Main Office 12 10+ years 2 EΑ Doors - Wood Doors inclu hw 1st Floor-Main Office 6 10+ years SF Floor - Carpet 1st Floor-Main Office 565 7 6-10 years SF Floor - Tile 1st Floor-Main Office 165 7 6-10 years Lighting - Lay-in 1st Floor-Main Office 6 EΑ 7 6-10 years Power Distribution 1st Floor-Main Office 12 EΑ 6 10+ years SF 7 Storage/ Closet 1st Floor-Main Office 215 10+ years Walls - Plaster/Drywall SF 1st Floor-Main Office 856 6 10+ years SF 7 Ceiling - Lay-in 1st Floor-Multipurpose Room Office 80 10+ years Doors - Wood Doors inclu hw 1st Floor-Multipurpose Room Office EΑ 6 1 10+ years Floor - Tile 1st Floor-Multipurpose Room Office 80 SF 7 10+ years 1st Floor-Multipurpose Room Office Lighting - Lay-in EΑ 7 6-10 years 1 Power Distribution 1st Floor-Multipurpose Room Office 4 EΑ 6 10+ years 1st Floor-Multipurpose Room Office SF 7 Walls - Concrete Block 160 10+ years Ceiling - Lay-in 1st Floor-Nurse's Office 105 115 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor-Nurse's Office 105 FΑ 7 10+ years 1 Floor - Tile 1st Floor-Nurse's Office 105 115 SF 7 10+ years Lighting - Lay-in FΑ 7 1st Floor-Nurse's Office 105 2 10+ years Power Distribution 1st Floor-Nurse's Office 105 4 FΑ 7 10+ years 125 SF 7 Walls - Concrete Block 1st Floor-Nurse's Office 105 10+ years SF Walls - Plaster/Drywall 1st Floor-Nurse's Office 105 100 6 10+ years SF Ceiling - Lay-in 1st Floor-Office 115 168 7 6-10 years Ceiling - Lay-in 1st Floor-Office 115 SF 8 4 1-2 years Water damage Doors - Wood Doors inclu hw 1st Floor-Office 115 1 EΑ 7 10+ years SF Floor - Tile 1st Floor-Office 115 176 7 6-10 years Lighting - Lay-in 1st Floor-Office 115 2 EΑ 7 6-10 years FΑ 7 Power Distribution 1st Floor-Office 115 8 10+ vears Walls - Concrete Block 1st Floor-Office 115 155 SF 7 10+ years Walls - Plaster/Drywall SF 1st Floor-Office 115 196 7 10+ years





Catego	ry : Room		В	uilding	: Annex		<u> </u>
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor-Principal's Office	215	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office	1	EA	7	10+ years	
	Floor - Carpet	1st Floor-Principal's Office	215	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor-Principal's Office	2	EA	6	6-10 years	
	Power Distribution	1st Floor-Principal's Office	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Principal's Office	355	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Principal's Office	155	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-Library Office	200	SF	7	6-10 years	
	Doors - Side-lite	2nd Floor-Library Office	8	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor-Library Office	1	EA	7	10+ years	
	Floor - Tile	2nd Floor-Library Office	200	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor-Library Office	2	EA	7	6-10 years	
	Power Distribution	2nd Floor-Library Office	22	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor-Library Office	212	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor-Library Office	230	SF	7	10+ years	
	Work SInk	2nd Floor-Library Office	1	EΑ	7	10+ years	
	Ceiling - Lay-in	Office #1 (inside the main office)	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office #1 (inside the main office)	1	EA	6	10+ years	
	Floor - Carpet	Office #1 (inside the main office)	140	SF	6	6-10 years	
	Lighting - Lay-in	Office #1 (inside the main office)	2	EA	6	6-10 years	
	Power Distribution	Office #1 (inside the main office)	6	EA	6	10+ years	
	Walls - Concrete Block	Office #1 (inside the main office)	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Office #1 (inside the main office)	196	SF	6	10+ years	
	Ceiling - Lay-in	Office #2 (inside the main office)	145	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office #2 (inside the main office)	1-13	EA	7	10+ years	
	Floor - Carpet	Office #2 (inside the main office)	145	SF	7	6-10 years	
	Lighting - Lay-in	Office #2 (inside the main office)	2	EA	7	10+ years	
	Power Distribution	Office #2 (inside the main office)	12	EA	7	10+ years	
	Walls - Concrete Block	Office #2 (inside the main office)	96	SF	7	-	
				SF	6	10+ years	
	Walls - Plaster/Drywall	Office #2 (inside the main office)	185	SF	О	10+ years	
_Gvmnas	ia						
_Оуппаз	Ceiling - Exposed	1st Floor	3,855	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EΑ	7	10+ years	
	Floor - Tile	1st Floor	3,855	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure	1st Floor	13	EA	7	10+ years	
	Sodium		_			-	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	176	SF	7	10+ years	
	Storage/ Closet	1st Floor	107	SF	7	10+ years	
	Storage/ Closet	1st Floor	24	SF	4	0-1 year	Water damage in closet. Quantity is updated to match current observations





Category : Room			Building : Annex				
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	7,330	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	388	SF	7	10+ years	
itchen							
	Ceiling - Lay-in	1st Floor	1,320	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,320	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	
	Serving Line	1st Floor	25	LF	7	10+ years	
	Storage/ Closet	1st Floor	166	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,168	SF	7	10+ years	
brary							
	Casework	2nd Floor-205 Library	110	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-205 Library	1,574	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-205 Library	16	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor-205 Library	20	SF	7	10+ years	•
	Doors - Wood Doors inclu hw	2nd Floor-205 Library	3	EA	7	10+ years	
	Floor - Carpet	2nd Floor-205 Library	1,490	SF	6	2-5 years	
	Floor - Carpet	2nd Floor-205 Library	100	SF	4	0-1 year	Missing and torn carpet
	Lighting - Lay-in	2nd Floor-205 Library	20	ĒΑ	7	10+ years	3
	Storage/ Closet	2nd Floor-205 Library	100	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor-205 Library	3	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor-205 Library	1,875	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor-205 Library	1,165	SF	7	10+ years	
ocker/S	Shower Room						
JONOIT C	Accessories	1st Floor-Boiler Room Locker Room	75	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1 1st Floor-Boiler Room Locker Room 1	75	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-Boiler Room Locker Room	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor-Boiler Room Locker Room 1	75	SF	7	10+ years	
	Floor Drain	1st Floor-Boiler Room Locker Room 1	1	EA	7	10+ years	
	Lavatory	1st Floor-Boiler Room Locker Room 1	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Boiler Room Locker Room 1	1	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor-Boiler Room Locker Room 1	1	EA	7	10+ years	





Catego	ry : Room	В	uilding	: Annex			
	Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	1st Floor-Boiler Room Locker Room 1	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Boiler Room Locker Room 1	105	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Boiler Room Locker Room	100	SF	7	10+ years	
	Water Closet	1st Floor-Boiler Room Locker Room	1	EA	7	10+ years	
	Accessories	1st Floor-Boiler Room Locker Room	75	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Boiler Room Locker Room 2	75	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-Boiler Room Locker Room 2	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor-Boiler Room Locker Room 2	75	SF	7	10+ years	
	Floor Drain	1st Floor-Boiler Room Locker Room 2	1	EA	7	10+ years	
	Lavatory	1st Floor-Boiler Room Locker Room 2	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Boiler Room Locker Room 2	1	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor-Boiler Room Locker Room	1	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor-Boiler Room Locker Room 2	6	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Boiler Room Locker Room 2	105	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Boiler Room Locker Room 2	100	SF	7	10+ years	
	Water Closet	1st Floor-Boiler Room Locker Room 2	1	EA	7	10+ years	
		· ·					
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	2,950	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,932	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	18	SF	4	0-1 year	Cracking near windows
	Lighting - Lay-in	1st Floor	40	EA	7	10+ years	
	Storage/ Closet	1st Floor	100	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,100	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,100	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	2,255	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	100	SF	4	0-1 year	Water damaged tiles



Category : Room			В	uilding	: Annex		
			Recommend				
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	2,355	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	34	EA	7	10+ years	
	Storage/ Closet	1st Floor	55	SF	7	10+ years	
	Storage/ Closet	1st Floor	65	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,752	SF	6	10+ years	
IDF ID	F						
	Doors - Wood Doors inclu hw	112 MDF Room	1	EA	7	10+ years	
	Finishes	112 MDF Room	105	SF	7	10+ years	
	Window AC Unit	112 MDF Room	1	EA	7	6-10 years	CRAC unit.
lechani	ical/ Service Rooms						
	Boiler Room	1st Floor	1,365	SF	7	10+ years	
	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	438	SF	7	10+ years	
	Storage Room	1st Floor	180	SF	7	10+ years	
	Storage Room	1st Floor	85	SF	7	10+ years	
	Storage Room	1st Floor	108	SF	5	10+ years	Water damaged ceiling tiles
	Janitor's Closet	2nd Floor	25	SF	5	10+ years	rrater damaged coming mee
	Mechanical/ Service Rooms	2nd Floor	408	SF	7	10+ years	
	Janitor's Closet	3rd Floor	9	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	408	SF	7	10+ years	
	Storage Room	3rd Floor	96	SF	7	10+ years	
	Storage Room	3rd Floor	85	SF	7	10+ years	
rep Ro	om						
	Casework	In Classroom 216	30	LF	7	10+ years	
	Ceiling - Lay-in	In Classroom 216	100	SF	7	6-10 years	
	Doors - Steel Doors incl hw	In Classroom 216	1	EΑ	7	10+ years	
	Floor - Tile/Sheet	In Classroom 216	100	SF	7	6-10 years	
	Lighting - Lay-in	In Classroom 216	3	EA	6	6-10 years	
	Walls - Concrete Block	In Classroom 216	175	SF	7	10+ years	
	Work Sink	In Classroom 216	1	EA	7	10+ years	
estrooi	m						
	Accessories	1st Floor - Staff Across from Main Office	100	SF	7	6-10 years	Quantity updated to match curren observations
	Ceiling - Lay-in	1st Floor - Staff Across from Main Office	100	SF	7	10+ years	Quantity updated to match curren observations
	Doors - Wood Doors inclu hw	1st Floor - Staff Across from Main Office	1	EA	7	10+ years	SSSST VALIOTIS
	Floor - Tile	1st Floor - Staff Across from Main	100	SF	7	10+ years	Quantity updated to match curren



Catego	ry : Room		Building : Annex						
	_					Recommend	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Elean Dunio	Office		_ ^	_	40.	observations		
	Floor Drain	1st Floor - Staff Across from Main	1	EA	7	10+ years			
	Hand Dryer	Office 1st Floor - Staff Across from Main	1	EA	7	10 Lyong			
	Hallu Diyel	Office	ı	EA	7	10+ years			
	Lavatory	1st Floor - Staff Across from Main	1	EA	7	10+ years			
	Lavatory	Office	'	LA		10+ years			
	Lighting - Pendent/Surface	1st Floor - Staff Across from Main	2	EA	7	6-10 years	Quantity updated to match current		
	gg	Office				5 · 6 , 5 · 6 · 6	observations		
	Walls - Plaster/Drywall	1st Floor - Staff Across from Main	208	SF	7	10+ years	Quantity updated to match current		
	·	Office				·	observations		
	Water Closet	1st Floor - Staff Across from Main	1	EA	7	10+ years			
		Office							
	Accessories	1st Floor-Boy's Restroom	225	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor-Boy's Restroom	225	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor-Boy's Restroom	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	225	SF	6	10+ years			
	Floor Drain	1st Floor-Boy's Restroom	1	EA	7	10+ years			
	Hand Dryer	1st Floor-Boy's Restroom	2	EA	7	10+ years			
	Lavatory	1st Floor-Boy's Restroom	2	EA	6	10+ years			
	Lighting - Lay-in	1st Floor-Boy's Restroom	4	EA	7	10+ years			
	Partitions	1st Floor-Boy's Restroom	2	EA	7	6-10 years			
	Urinals	1st Floor-Boy's Restroom	2	EA	6	10+ years			
	Walls - Concrete Block	1st Floor-Boy's Restroom	566	SF	7	10+ years			
	Water Closet	1st Floor-Boy's Restroom	2	EΑ	6	10+ years			
	Accessories	1st Floor-Girl's Restroom	225	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor-Girl's Restroom	225	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor-Girl's Restroom	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom	225	SF	7	6-10 years			
	Floor Drain	1st Floor-Girl's Restroom	1	EA	7	10+ years			
	Hand Dryer	1st Floor-Girl's Restroom	2	EA	7				
		1st Floor-Girl's Restroom		EA		10+ years			
	Lavatory		2		6	10+ years			
	Lighting - Lay-in	1st Floor-Girl's Restroom	4	EΑ	6	6-10 years			
	Partitions	1st Floor-Girl's Restroom	4	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor-Girl's Restroom	566	SF	7	10+ years			
	Water Closet	1st Floor-Girl's Restroom	4	EA	6	10+ years			
	Accessories	2nd Floor-Boy's Restroom	255	SF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor-Boy's Restroom	255	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor-Boy's Restroom	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Boy's Restroom	255	SF	6	10+ years			
	Floor Drain	2nd Floor-Boy's Restroom	1	EA	7	10+ years			
	Hand Dryer	2nd Floor-Boy's Restroom	2	EA	7	6-10 years			
	Lavatory	2nd Floor-Boy's Restroom	2	EA	6	10+ years			
	Lighting - Lay-in	2nd Floor-Boy's Restroom	3	EA	6	10+ years			
	- • •	•				•			







Category: Room **Building: Annex** Recommend Location Group Item - Type Quantity **UOM** Rank Replacement Comments **Partitions** 2nd Floor-Boy's Restroom 2 EΑ 6-10 years 7 2nd Floor-Bov's Restroom 3 EΑ Urinals 6 10+ years Walls - Concrete Block 2nd Floor-Boy's Restroom 590 SF 6 10+ years Water Closet 2 EΑ 6 2nd Floor-Boy's Restroom 10+ years 255 SF 7 Accessories 2nd Floor-Girl's Restroom 6-10 years SF Ceiling - Lay-in 2nd Floor-Girl's Restroom 255 6 10+ years Doors - Wood Doors inclu hw EΑ 6 2nd Floor-Girl's Restroom 2 10+ years SF Floor - Tile Ceramic/ Porcelain 2nd Floor-Girl's Restroom 255 6 10+ years Floor Drain 2nd Floor-Girl's Restroom 1 EΑ 7 10+ years Hand Drver 2nd Floor-Girl's Restroom 2 FΑ 7 10+ years Lavatory 2nd Floor-Girl's Restroom 2 FΑ 6 10+ years Lighting - Lay-in 2nd Floor-Girl's Restroom 4 EΑ 6 6-10 years **Partitions** 4 EΑ 7 6-10 years 2nd Floor-Girl's Restroom SF Walls - Concrete Block 2nd Floor-Girl's Restroom 590 6 10+ years Water Closet EΑ 2nd Floor-Girl's Restroom 4 6 10+ years 30 SF 7 Accessories 2nd Floor-Men's Restroom 6-10 years SF Ceiling - Lav-in 2nd Floor-Men's Restroom 30 0-1 year Water damage. Doors - Wood Doors inclu hw 2nd Floor-Men's Restroom 1 EΑ 6 10+ years SF Floor - Tile 2nd Floor-Men's Restroom 30 7 6-10 years Floor Drain 2nd Floor-Men's Restroom 1 EΑ 7 10+ years Lavatory 2nd Floor-Men's Restroom 1 EΑ 6 10+ years 2nd Floor-Men's Restroom 7 Lighting - Wall Mounted 1 EΑ 6-10 years SF Walls - Concrete Block 2nd Floor-Men's Restroom 32 6 10+ years SF Walls - Plaster/Drywall 2nd Floor-Men's Restroom 30 6 10+ years Water Closet FΑ 6 2nd Floor-Men's Restroom 1 10+ years SF Accessories 2nd Floor-Women's Restroom 30 7 6-10 years SF Ceiling - Lay-in 2nd Floor-Women's Restroom 30 4 1-2 years Water damage Doors - Wood Doors inclu hw 2nd Floor-Women's Restroom 1 EΑ 6 10+ years Floor - Tile SF 2nd Floor-Women's Restroom 30 6 6-10 years Floor Drain 2nd Floor-Women's Restroom 1 EΑ 7 10+ years 2nd Floor-Women's Restroom 1 FΑ 6 10+ vears Lavatory Lighting - Wall Mounted 2nd Floor-Women's Restroom 1 EΑ 6 6-10 years Walls - Concrete Block SF 2nd Floor-Women's Restroom 32 6 10+ years Walls - Plaster/Drywall 2nd Floor-Women's Restroom 36 SF 6 10+ years Water Closet 2nd Floor-Women's Restroom 1 EΑ 6 10+ years SF 7 Accessories 3rd Floor-Boy's Restroom 255 6-10 years SF Ceiling - Lay-in 3rd Floor-Boy's Restroom 255 7 10+ years Doors - Wood Doors inclu hw 3rd Floor-Boy's Restroom EΑ 7 1 10+ years SF Floor - Tile Ceramic/ Porcelain 3rd Floor-Boy's Restroom 255 7 10+ years EΑ Floor Drain 3rd Floor-Boy's Restroom 1 7 10+ vears Hand Dryer 3rd Floor-Boy's Restroom 2 FΑ 7 6-10 years 3rd Floor-Boy's Restroom 2 FΑ 7 Lavatory 10+ vears Lighting - Lay-in 3rd Floor-Boy's Restroom 3 EΑ 7 10+ years **Partitions** 2 3rd Floor-Boy's Restroom EΑ 7 10+ years







Category: Room **Building: Annex** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments 3rd Floor-Boy's Restroom Urinals 3 EΑ 10+ vears 7 Walls - Concrete Block 3rd Floor-Boy's Restroom 590 SF 7 10+ years Water Closet 3rd Floor-Boy's Restroom 2 FΑ 7 10+ years 3rd Floor-Girl's Restroom 255 SF 7 Accessories 6-10 years SF 7 Ceiling - Lay-in 3rd Floor-Girl's Restroom 255 10+ years EΑ 7 Doors - Wood Doors inclu hw 3rd Floor-Girl's Restroom 1 10+ years Floor - Tile Ceramic/ Porcelain 3rd Floor-Girl's Restroom 255 SF 7 10+ years Floor Drain 3rd Floor-Girl's Restroom 1 EΑ 7 10+ years Hand Dryer 3rd Floor-Girl's Restroom 2 EΑ 7 6-10 years 2 3rd Floor-Girl's Restroom FΑ 7 10+ years Lavatory Lighting - Lav-in 3rd Floor-Girl's Restroom 3 EΑ 7 10+ years Partitions 3rd Floor-Girl's Restroom 4 EΑ 7 10+ years Walls - Concrete Block 3rd Floor-Girl's Restroom 590 SF 7 10+ years Water Closet EΑ 7 3rd Floor-Girl's Restroom 10+ years 30 SF 7 Accessories 3rd Floor-Men's Restroom 6-10 years 30 SF 7 Ceiling - Lay-in 3rd Floor-Men's Restroom 10+ years Doors - Steel Doors incl hw EΑ 7 3rd Floor-Men's Restroom 1 10+ years SF Floor - Tile 3rd Floor-Men's Restroom 30 7 10+ years Floor Drain 3rd Floor-Men's Restroom 1 EΑ 7 10+ years Lavatory 3rd Floor-Men's Restroom 1 EΑ 7 10+ years Lighting - Wall Mounted 3rd Floor-Men's Restroom 1 EΑ 7 10+ years Walls - Concrete Block 3rd Floor-Men's Restroom SF 7 32 10+ years SF Walls - Plaster/Drywall 7 3rd Floor-Men's Restroom 32 10+ years Water Closet 3rd Floor-Men's Restroom 1 FΑ 6 10+ years Accessories 30 SF 7 6-10 years 3rd Floor-Women's Restroom SF Ceiling - Lav-in 3rd Floor-Women's Restroom 30 4 1-2 years Water damage Doors - Steel Doors incl hw 7 3rd Floor-Women's Restroom 1 EΑ 10+ years Floor - Tile 3rd Floor-Women's Restroom 30 SF 7 10+ years EΑ Lavatory 3rd Floor-Women's Restroom 1 7 10+ years Lighting - Wall Mounted 3rd Floor-Women's Restroom 1 EΑ 7 6-10 years Walls - Concrete Block SF 3rd Floor-Women's Restroom 32 7 10+ vears SF Walls - Plaster/Drywall 3rd Floor-Women's Restroom 32 7 10+ years FΑ 7 10+ years Water Closet 3rd Floor-Women's Restroom 1 Accessories In Main Office #2 30 SF 7 6-10 years SF 30 7 Ceiling - Lay-in In Main Office #2 6-10 years Deficiency fixed Doors - Wood Doors inclu hw EΑ In Main Office #2 1 6 10+ years SF Floor - Tile In Main Office #2 30 7 6-10 years Floor Drain EΑ 7 In Main Office #2 1 10+ years Lavatory In Main Office #2 1 EΑ 6 10+ years Lighting - Wall Mounted 7 In Main Office #2 1 EΑ 6-10 years Walls - Plaster/Drywall SF In Main Office #2 67 6 10+ years FΑ 6 Water Closet In Main Office #2 10+ years 1 Accessories Inside Main Office #1 30 SF 7 6-10 years SF 7 10+ years Ceiling - Lay-in Inside Main Office #1 30 Deficiency fixed



Catego	ry : Room		В	uildina	: Annex	(
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Inside Main Office #1	1	EA	6	10+ years	
	Floor - Tile	Inside Main Office #1	30	SF	7	6-10 years	
	Floor Drain	Inside Main Office #1	1	EA	7	10+ years	
	Lavatory	Inside Main Office #1	1	EA	7	10+ years	
	Lighting - Wall Mounted	Inside Main Office #1	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Inside Main Office #1	67	SF	7	10+ years	
	Water Closet	Inside Main Office #1	1	EΑ	7	10+ years	
Catego	ry : Classroom		В	uildina	: Annex	.	
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #102 (Faculty Lounge)						
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	895	SF	7	10+ years	
	Chalk Board	1st Floor	20	ĹF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	895	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EΑ	7	10+ years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	885	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	295	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #104 (Faculty Lounge)						
Classici	Casework	1st Floor	10	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	850	SF	7	•	
	Doors - Wood Doors inclu hw	1st Floor		EA		10+ years	
		1st Floor	1	SF	7	10+ years	
	Floor - Tile		850		7	10+ years	
	Lighting - Lay-in	1st Floor 1st Floor	12	EA	7 7	10+ years	
	Marker Board		8	LF		6-10 years	
	Student Lockers - One Tier	1st Floor	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	252	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,145	SF	7	10+ years	
Classroo	om #106 (Science Classroom)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	850	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	850	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	2	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Annex	{	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	252	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,145	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroc	om #202 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	807	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	43	SF	4	0-1 year	Warped ceiling tiles due to humidity issues. Quantity updated to match current observations
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	870	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	300	SF	7	10+ years	
Classroc	m #204 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	850	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	850	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	14	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	870	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	850	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	850	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	870	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	15	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	850	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	2	EA	7	10+ years	
	Olddell Lockers - Olle 1161	2110 1 1001	2	ĽA	,	TOT YEARS	



Catego	ory : Classroom		В	uilding	: Annex		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	870	SF	7	10+ years	
Classro	om #210 (Computer Lab)						
	Casework	2nd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,003	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	32	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	S .
	Floor - Tile	2nd Floor	1,035	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	998	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	268	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classro	om #212 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	850	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	850	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	20	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	525	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	788	SF	7	10+ years	
Classro	om #214 (Store Room)						
Olassio	Ceiling - Lay-in	2nd Floor	842	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-10 years 0-1 year	Water damage
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	Water damage
	Floor - Tile	2nd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	•	
	Marker Board	2nd Floor	6	LF	7	10+ years 6-10 years	
		2nd Floor	75	SF	7		
	Storage/ Closet	2nd Floor 2nd Floor	75		7 7	10+ years	
	Student Lockers - One Tier			EA SF	-	10+ years	
	Walls - Concrete Block	2nd Floor 2nd Floor	525		7 7	10+ years	
	Walls - Plaster/Drywall		525	SF		10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classro	om #215 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	850	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	850	SF	7	10+ years	



Catego	ry : Classroom		В	uildina	: Annex		212 W George STREET, Chicago, IL 60616
Galogo				anamg	. / (11110)	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	12	ΕA	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	870	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	300	SF	7	10+ years	
_Classroo	om #216 (Regular Classroom)						
	Casework	2nd Floor	18	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	850	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	100	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	2	ĒΑ	7	10+ years	
	Walls - Concrete Block	2nd Floor	525	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	525	SF	7	10+ years	
	Work Sink	2nd Floor	2	ĒΑ	7	10+ years	
_Classroo	om #302 (Regular Classroom)						
	Casework	3rd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	2	EΑ	7	10+ years	
	Walls - Concrete Block	3rd Floor	870	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	314	SF	7	10+ years	
_Classroo	om #304 (Regular Classroom)						
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	2	ĒΑ	7	10+ years	
	Walls - Concrete Block	3rd Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	870	SF	7	10+ years	
_Classroo	om #305 (Science Classroom)						
	Casework	3rd Floor	68	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	975	SF	7	10+ years	
	3,	2.2	0.0		-	,	





Catego	ry : Classroom		В	uildina	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	975	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	15	SF	7	10+ years	
	Storage/ Closet	3rd Floor	96	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	940	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	330	SF	7	10+ years	
	Work Sink	3rd Floor	3	EA	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	870	SF	7	10+ years	
Classroo	om #308 (Regular Classroom)						
Oldoorox	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	302	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	868	SF	7	10+ years	
	walls - Flaster/Drywall	310 1 1001	000	OI.	,	10+ years	
Classroo	om #310 (Regular Classroom)						
	Casework	3rd Floor	35	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,070	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,070	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,010	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	10	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	300	SF	7	10+ years	





Catego	ry : Classroom		В	uildina	: Annex		212 W George STREET, Chicago, IL 6061
Jalogo	i y i Gidooroom			anamg	. , (11110)	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
•	,		•			•	
_Classroo	m #312 (Regular Classroom)						
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	805	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	805	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	585	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	585	SF	7	10+ years	
Classroo	m #314 (Regular Classroom)						
_Classioo	m #314 (Regular Classroom) Casework	3rd Floor	32	LF	7	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	850	SF	7	,	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years 10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7		
				SF	7	10+ years	
	Walls - Concrete Block	3rd Floor 3rd Floor	606 606	SF SF		10+ years	
	Walls - Plaster/Drywall Work Sink	3rd Floor	1	SF EA	7 7	10+ years	
	WORK SINK	31a F1001	ı	EA	,	10+ years	
_Classroo	m #315 (Regular Classroom)						
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	870	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	300	SF	6	10+ years	
Classroo	m #316 (Regular Classroom)						
	Casework	3rd Floor	26	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	805	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	805	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	100	SF	7	10+ years	
	2.3.4gg/ 0.000t	014 1 1001	100	<u> </u>	,	10. yours	







Building: Annex Category: Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	3rd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	585	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	585	SF	7	10+ years	

Category: Interior Building: Annex

Catego	ry : interior		D	unaing	. Annex		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Lay-in	1st Floor	2,507	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	7	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	1st Floor	262	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Doors - Store Front	1st Floor	2	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	3	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	262	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,514	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	32	EA	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	82	EA	7	10+ years	
	Walls - Masonry	1st Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,855	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	3,576	SF	7	10+ years	
	Ceiling - Exposed	1st Floor-Boiler Room Corridor	168	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-Boiler Room Corridor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor-Boiler Room Corridor	168	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Boiler Room Corridor	3	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Boiler Room Corridor	1,316	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,575	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	2,575	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	314	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,580	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	2,910	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	2,510	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	65	SF	4	1-2 years	Water damage
	Doors - Steel Doors incl hw	3rd Floor	4	EA	7	10+ years	· ·
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,547	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	28	SF	4	0-1 year	Cracking/chipped
	Lighting - Lay-in	3rd Floor	20	EA	7	10+ years	3
	Student Lockers - Two Tiers	3rd Floor	314	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,580	SF	7	10+ years	
				SF		•	



Catego	ry : Interior	В	uilding	: Annex	ζ		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Safety							
	Camera Viewing Station	Entire Building	2	EA	7	6-10 years	In main office and principal's office
	Security Cameras	Entire Building	10	EA	7	6-10 years	
	Security Cameras	Entire Building	9	EA	7	6-10 years	
0							
Stairs	Cailing Lawin	Nicordia	220		7	40	
	Ceiling - Lay-in	North	338	SF	7	10+ years	
	Floor - Tile	North	183	SF	7	10+ years	One diam consenting and chinains
	Floor - Tile	North	155	SF	4	0-1 year	Cracking, separating, and chipping tiles. Quantity updated to match current observations
	Handrails	North	122	LF	7	6-10 years	
	Lighting - Wall Mounted	North	5	EA	7	10+ years	
	Stairs - Rubber	North	248	LF	7	10+ years	
	Walls - Concrete Block	North	1,058	SF	7	10+ years	
	Ceiling - Lay-in	North East	596	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North East	138	SF	6	10+ years	
	Floor - Tile	North East	605	SF	6	10+ years	
	Handrails	North East	170	LF	7	6-10 years	
	Lighting - Lay-in	North East	3	EA	7	6-10 years	
	Lighting - Wall Mounted	North East	2	EA	7	6-10 years	
	Stairs - Rubber	North East	263	LF	7	10+ years	
	Walls - Concrete Block	North East	1,493	SF	7	10+ years	
	Ceiling - Lay-in	South West	596	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South West	138	SF	6	10+ years	
	Floor - Tile	South West	231	SF	6	10+ years	
	Floor - Tile	South West	45	SF	4	1-2 years	Chipped tiles
	Handrails	South West	170	LF	7	10+ years	
	Lighting - Lay-in	South West	3	EA	7	6-10 years	
	Lighting - Wall Mounted	South West	2	EA	7	6-10 years	
	Stairs - Rubber	South West	263	LF	7	10+ years	
	Walls - Concrete Block	South West	1,204	SF	7	10+ years	
Vertical	Conveyance						
VOLUCAL	Elevator - Hydraulic Elevator	Annex building	1	EA	7	10+ years	
	Liovator Trydraumo Lievator	Allies ballaling	1	L /\	,	TOT years	



Category : Site			В	Building : Site				
	· _			Recommend				
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
thletic								
	Lighting	East	1	EA	7	10+ years		
	Surface - Synthetic including exc & retention	East	12,984	SF	7	10+ years		
ivil/Dra	inage							
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	6-10 years		
	Civil/ Drainage - Site Manhole	Entire Site	17	EA	6	6-10 years		
encina								
	Fencing - Chain Link	Entire Site	157	LF	6	6-10 years		
	Fencing - New Standard Ornamental	Entire Site	300	LF	7	10+ years		
	Fencing - New Standard Ornamental	Entire Site	2,172	LF	6	10+ years		
	Fencing - New Standard Ornamental	Entire Site	60	LF	4	0-1 year	Bent posts, damaged bars	
andsca	pe							
	Benches	Entire Site	6	EA	6	6-10 years		
	Landscape - Grass	Entire Site	10,482	SF	6	10+ years		
	Landscape - Grass	Entire Site	2,000	SF	5	0-1 year	Bare soil	
	Landscape - Hardscape- Asphalt	Entire Site	14,538	SF	6	6-10 years		
	Landscape - Hardscape- Concrete	Entire Site	8,166	SF	6	10+ years		
	Parkway trees	Entire Site	48	EA	6	10+ years		
	Planting Beds/ Area	Entire Site	1,964	SF	6	10+ years		
	Play Area - Synthetic Turf	Entire Site	7,095	SF	7	10+ years		
	Trash Receptacles	Entire Site	3	EA	6	6-10 years		
Parking I	ot							
9	Concrete Curbs	East	772	LF	6	10+ years		
	Lighting - Pole Mounted	East	8	EA	6	6-10 years		
	Surface - Asphalt	East	39,858	SF	4	0-1 year	Alligatoring, large cracks, disintegrating surface, potholes	
	Surface - Concrete	East	2,200	SF	6	10+ years	distriction surface, portfoles	
	Trash Enclosure - Chain Links	East	750	SF	6	6-10 years		
	Trash Enclosure - Chain Links	East	1,356	SF	6	6-10 years		
Playgrou	nd	,						
, g. 20	Equipment - Combo 3-12	East	1	EA	7	10+ years		
	Surface - Poured Surface	East	1,600	SF	7	10+ years		
	Equipment - Combo 3-12	West	1	EA	6	10+ years	New	
	Surface - Poured Surface	West	2,150	SF	6	10+ years	New	



Catego	Category : Site			uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sidewalks - Internal Walks Sidewalks - Perimeter Sidewalks	Entire Site Entire Site	700 1,000	LF SF	6 7	10+ years 10+ years	New
	Sidewalks - Perimeter Sidewalks Sidewalks - Perimeter Sidewalks	Entire Site Entire Site	18,800 50	SF SF	6 4	10+ years 0-1 year	Cracking.
_Signage							
	Flag Pole - Flag Pole	Entire Site	2	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	4	1-2 years	Electricity on the sign does not work. Sign is leaning to one side.
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	6	10+ years	
	Monument - Sign	Entire Site	2	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				FI. DI					
			D	Floor Plan Room	A	Glazed Window	Operable Window	VA/i	Commont
Command Haama	luten ded Heere	Doom Location	Room		Area			Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Communitariliah	Ond Floor	240	240	000	10	0.4	l N	N.
Computer Lab	Computer Lab	2nd Floor	210 B-1	210 B-1	830 668	49 161	24 70	N N	N N
Faculty Lounge	Regular Classroom	Basement 1st Floor	108	108	800	99	98		N
Kindergarten	Regular Classroom							N	
Multi Purpose Room	Regular Classroom	Basement	B-5	B-5 B-7	724	152	60	N	N
Multi Purpose Room	Regular Classroom	Basement	B-7		718	152 36	60 36	N Y	N
Music Room	Library	3rd Floor	Library 3rd Fl	Library	824	36	36	Y	N
Music Room	Regular Classroom	3rd Floor	301	301	828	121	114	N	N
Office	Regular Classroom	1st Floor	101	101	757	169	128	N	N
Pre School	Regular Classroom	1st Floor	106	106	823	99	98	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	756	99	74	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	823	102	64	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	850	93	18	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	808	121	114	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	817	126	103	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	754	169	128	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	762	99	74	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	753	169	128	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	756	126	112	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	823	102	64	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	835	74	49	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	810	101	76	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	812	101	76	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	814	102	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	760	99	74	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	761	99	74	N	N
Regular Classroom	Regular Classroom	Basement	B-3	B-3	824	135	40	N	N
Store Room	Regular Classroom	3rd Floor	303	303	821	121	114	N	N
Store Room	Regular Classroom	Basement	B-2	B-2	824	135	40	N	N
Store Room	Regular Classroom	Basement	B-4	B-4	872	135	40	N	N
Store Room	Regular Classroom	Basement	B-6	B-6	882	135	40	N	N
Building : Annex									
Computer Lab	Regular Classroom	2nd Floor	210	210	1,035	93	18	N	N
Faculty Lounge	Regular Classroom	1st Floor	102	102	895	93	18	N	N
Faculty Lounge	Regular Classroom	1st Floor	104	104	850	93	18	N	N
Regular Classroom	Regular Classroom	1st Floor	212	212	850	93	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	850	93	18	N	N





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	204	204	850	93	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	850	93	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	850	93	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	850	93	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	850	93	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	850	93	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	850	93	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	850	93	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	1,070	93	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	312	312	805	93	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	850	93	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	315	315	850	93	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	316	316	805	93	18	N	N
Regular Classroom	Science Classroom	2nd Floor	216	216	850	93	18	N	N
Science Classroom	Regular Classroom	1st Floor	106	106	850	93	18	N	N
Science Classroom	Science Classroom	3rd Floor	305	305	975	93	18	N	N
Store Room	Regular Classroom	2nd Floor	214	214	850	93	18	N	N