

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1929	3	47,741
Campus Total			47,741

Catego	Category : Exterior			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	9						
	Entrance Control - Audio and Video	#1 Main - SE	1	EA	7	10+ years	
	Exterior Doors - Store Front	#1 Main - SE	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 Main - SE	60	LF	5	2-5 years	
	Exterior Stairs - Stone	#1 Main - SE	8	LF	6	10+ years	
	Entrance Control - Audio and Video	#2 S	1	EA	6	10+ years	
	Exterior Doors - Side lite	#2 S	1	EA	6	10+ years	
	Exterior Doors - Store Front	#2 S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 S	3	EA	6	10+ years	
	Exterior Stairs - Stone	#2 S	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#3 - SW	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 - W	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - W	1	EA	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	#5 - W	1	EA	6	10+ years	
	Door					5	
	Exterior Doors - Overhead Rolling/ Garage	#5A - W OVH	1	EA	7	10+ years	New
	Door					,	
	Entrance Control - Audio and Video	#6 - NW	1	EA	7	10+ years	
	Exterior Doors - Store Front	#6 - NW	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 - NW	4	EA	6	10+ years	
	Power Door Operator and Controls	#6 - NW	2	EA	7	10+ years	
	Exterior Doors - Store Front	#7 - NE	6	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 - NE	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 - NE	200	LF	5	2-5 years	
	Exterior Stairs - Concrete	#7 - NE	50	LF	4	0-1 year	Exposed rebar, cracked
						. j	·····



Catego	ry : Exterior		В	uilding	: Main		
	·			J		Recommend	
Group	ltem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Store Front	#8 - E	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 - E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 - E	108	LF	6	10+ years	
	Exterior Stairs - Stone	#8 - E	12	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#8 - E	36	LF	6	10+ years	
		#0 - L	50	LI	0	IUT years	
oundati	ion						
	Foundation - Concrete	Entire Building	738	LF	7	10+ years	
	Superstructure - Steel	Entire Building	643	SF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	47,098	SF	7	10+ years	
ighting							
-grining	Exterior Lighting - Wall Mounted	Entire Building	14	EA	6	10+ years	
Roof Sys	stem						
-	Coping - Stone	Low NW roof	121	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low NW roof	24	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low NW roof	121	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Low NW roof	998	SF	4	0-1 year	Bubbling, cracking, patches throughout
	Roof - Modified Bitumen	Low NW roof	205	SF	6	6-10 years	throughout
	Roof Structure - Steel with Clay Tile Arch	Low NW roof	1,203	SF	7	10+ years	
	Access Ladder - Wood	Main Roof	1,200	EA	4	0-1 year	Wood, loose
	Coping - Stone	Main Roof	425	LF	7	10+ years	11000,10000
	Downspouts - Interior Downspouts	Main Roof	141	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	425	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast			SF			
		Main Roof	9,566		5	2-5 years	
	Roof Hatch - Metal	Main Roof	1	EA	4	0-1 year	Misaligned
	Roof Structure - Steel with Clay Tile Arch	Main Roof	9,566	SF	7	10+ years	
	Coping - Stone	Mid W roof	43	LF	6	10+ years	
	Downspouts - Interior Downspouts	Mid W roof	41	LF	6	10+ years	
	Parapet - 16" - 30" Height	Mid W roof	43	LF	6	10+ years	
	Roof - Modified Bitumen	Mid W roof	205	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Mid W roof	205	SF	7	10+ years	
	Access Ladder - Metal	N upper roof	1	EA	7	10+ years	
			1	EA			Not extension missigned
	Access Ladder - Metal	N upper roof			5	1-2 years	Not extension, misaligned
	Coping - Stone	N upper roof	309	LF	6	10+ years	
	Downspouts - Interior Downspouts	N upper roof	120	LF	6	10+ years	
	Parapet - 16" - 30" Height	N upper roof	80	LF	7	10+ years	
	Parapet - Parapet > 30"	N upper roof	229	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	N upper roof	5,798	SF	5	2-5 years	
	Roof Hatch - Metal	N upper roof	1	EA	5	1-2 years	Corroded, difficult to open



Catego	ry : Exterior		B	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Steel with Clay Tile Arch	N upper roof	5,798	SF	7	10+ years	
	Chimney - Metal Flue	West Boiler Roof	16	LF	7	10+ years	Chimney shortened
	Coping - Stone	West Boiler Roof	240	LF	6	10+ years	
	Downspouts - Interior Downspouts	West Boiler Roof	12	LF	6	10+ years	
	Downspouts - Interior Downspouts	West Boiler Roof	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	West Boiler Roof	52	LF	7	10+ years	
	Parapet - Parapet > 30"	West Boiler Roof	188	LF	4	1-2 years	Cracking, deteriorated mortar
	Roof - Asphalt Gravel Ballast	West Boiler Roof	2,052	SF	4	1-2 years	Cracking, bubbling
	Roof - Modified Bitumen	West Boiler Roof	750	SF	7	10+ years	Addition
	Roof Structure - Steel with Clay Tile Arch	West Boiler Roof	2,802	SF	7	10+ years	
Walls							
	Cheek-Wall - Stone	Entire Building	120	SF	6	10+ years	
	Cornice - Cast Stone	Entire Building	1,531	LF	6	10+ years	
	Cornice - Cast Stone	Entire Building	43	LF	5	10+ years	
	Exterior Walls - Brick	Entire Building	28,303	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	650	SF	4	0-1 year	Stepped cracking, deteriorated mort
	Exterior Walls - Stone-Cast	Entire Building	1,245	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	4	SF	5	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	595	SF	6	10+ years	
Nindow	5						
	Guard - Guards wire guard	Entire Building	66	SF	6	10+ years	
	Lintels - Brick	Entire Building	18	LF	6	10+ years	
	Lintels - Steel	Entire Building	359	LF	6	10+ years	
	Lintels - Stone	Entire Building	254	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,764	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	220	SF	4	1-2 years	Windows don't stay open
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	ltem - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Entire Building	1	EA	6	10+ years	
	Automatic Transfer Switch	Entire Building	1	EA	6	10+ years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,654	SF	6	6-10 years	Location changed for clarification; the auditorium occupies space on 2nd floor, 1st floor and basement.
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,941	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	3,458	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	12	EA	7	6-10 years	Location changed for clarification as the auditorium occupies space on



Catego	ry : Electrical		В	uilding	: Main	_	
_	·····		•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments 2nd floor, 1st floor and basement. Quantity, Rank, Reason and Priority Rep adjusted based on current
	Emergency Battery Packs - Corridors and Stairs	Entire Building	30	EA	7	6-10 years	observations. Quantity and Rank adjusted based of current observations.
	Emergency Battery Packs - Gym	Entire Building	5	EA	7	6-10 years	Quantity and Rank adjusted based of current observations.
	Exit Signs - Auditoium	Entire Building	7	EA	6	6-10 years	Location changed for clarification as the auditorium occupies space on 2nd floor, 1st floor and basement. Quantity changed to match current observations.
	Exit Signs - Corridors and Stairs	Entire Building	22	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	47,741	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	47,741	SF	5	6-10 years	
lain Sei	vice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	47,741	SF	5	6-10 years	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	6-10 years	Quantity changed to match current observations.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Located in the auditorium vestibule. Rank, Reason and Priority Rep changed due to an open fuse receptacle exposes live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	12	EA	6	6-10 years	Quantity and location changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification; panel is located inside the engineering office entryway. Reasc and Priority Rep adjusted as misaligned cover and door assembl exposes live conductors presenting live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Actively in the midst of being install on the day of assessment.



Category : Electrical			Building : Main				
Group	ltem - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Quantity changed as total has been divided/aggregated. Rank, Reason and Priority Rep adjusted based on current observations.
	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.

Catego	Category : Fire Protection			uilding	: Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
Fire Alar	Fire Alarm									
	Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	Annunciator panel. Unable to assign a Rank in the absence of an Item and Item Type. Installed in 2023, Rank is 7.			
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Rank and Priority Rep adjusted as the fire alarm system including the FACP was replaced since previous assessment.			
	Fire Alarm Strobe Lights	Entire Building	47,741	SF	7	10+ years	Rank and Priority Rep adjusted as the fire alarm system including the FACP was replaced since previous assessment.			
	Fire Alarm_System	Entire Building	47,741	SF	7	10+ years	Rank and Priority Rep adjusted as the fire alarm system including the FACP was replaced since previous assessment.			

Catego	Category : Mechanical				: Main		
Group	Item - Type dling Systems	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Air Handling Unit- Built Up- Multi Zone- Hot Water Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	7	10+ years	AHU-1, serves all spaces throughout the building that are located south of the auditorium. Installed in 2023. No CPS Asset Tag present.
	Air Intake	Mechanical Room	1	EA	7	10+ years	Rank, Reason and Priority Rep adjusted as the dampers and their control equipment have been replaced since previous assessment.
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	7	10+ years	Rank, Reason and Priority Rep adjusted as the auxiliaries have been replaced since previous assessment.



omments
omments
uantity changed to match current oservations. Rank changed to atch current observations as the amper actuators have been made Ily operational by the DDC since evious assessment.
HU-2, serves gym, auditorium, and sociated spaces. Installed in 2023. to CPS Asset Tag present.
Justed as the dampers and their ontrol equipment have been placed since previous assessment.
Justed as the auxiliaries have been placed since previous assessment.
1 B-2
em Type, Quantity, Rank, and riority Rep changed to match irrent observations; steam cabinet eaters replaced with hot water units 2023.
uantity changed as total has been vided/aggregated.
issing cover exposes live onductors presenting a live front ondition.
Ilyevision artijon partijon — 1 — mriorra 2 uzioson



Catego	ry : Mechanical		В	uilding	: Main		
Creatin	How Twee	Location	Ouentitu		Denk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal Plumbing	Facting Decilations			7	10	
	Hot Water Pump - 10 - 20 HP Hot Water Pump - 10 - 20 HP	Entire Building	1	EA EA	7 7	10+ years	No CPS Asset Tag present. No CPS Asset Tag present.
	Hot Water Pump - 10 - 20 HP Hot Water Pump - Less than 10	Entire Building Entire Building	1	EA	7	10+ years 10+ years	No CPS Asset Tag present.
	Hot Water Pump - Less than 10	Entire Building	1	EA	7	10+ years	No CPS Asset Tag present.
	Hydronic Supply and Return - Copper	Entire Building	1,200	LA	7	10+ years	Hydronic piping is a mixture of black
			1,200	-	•	lot youro	steel and copper.
Tempera	ature Control						
<u> </u>	DDC System	Entire Building	47,741	SF	7	10+ years	
	Electric Thermostat	Entire Building	6	ĒA	7	6-10 years	
	Thermostats - DDC	Entire Building	22	EA	7	10+ years	
Ventilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	7	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	Location changed for clarification.
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	-
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	7	10+ years	Quantity, Rank, Reason and Priority Rep changed as the unit was replaced with two new water heaters since previous assessment.
	Electric Heater - Less than 20 KW	Kitchen	1	EA	5	2-5 years	Location changed for clarification. Unit is leak-free with no signs of deterioration, however Reason and Priority Rep adjusted as the unit is approaching its EUL.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	47,741	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	47,741	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	47,741	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	47,741	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	47,741	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	47,741	SF	6	6-10 years	



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
0.0up	(from Risers to Fixtures)	20041011	Quantity			Replacement	
	Sanitary Piping	Entire Building	47,741	SF	6	10+ years	
	Storm Piping	Entire Building	47,741	SF	6	10+ years	
	Vent Piping	Entire Building	47,741	SF	6	10+ years	
Pumps							
·	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	7	10+ years	No CPS Asset Tag present. Rank, Reason and Priority Rep adjusted based on current observations as the pump unit was installed in 2023.
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	10+ years	
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	10+ years	No CPS Asset Tag present.
	Pumps - Sump-Duplex	Entire Building	1	EA	6	10+ years	No CPS Asset Tag present.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Located at the bottom of the elevator pit and not accessible at the time of assessment. Location changed for clarification. No CPS Asset Tag available. Condition verified by the Building Engineer; Rank adjusted per review with Building Engineer.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present. Location changed for clarification.

Category	: Room
----------	--------

Catego	ry : Room	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	Basement engineer's office	213	SF	7	10+ years	
	Doors - Transom Window	Basement engineer's office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement engineer's office	1	EA	6	10+ years	
	Floor - Tile	Basement engineer's office	213	SF	6	10+ years	
	Floor - Tile	Basement engineer's office	5	SF	5	1-2 years	Damaged
	Lighting - Pendent/Surface	Basement engineer's office	3	EA	6	6-10 years	
	Power Distribution	Basement engineer's office	6	EA	6	10+ years	
	Storage/ Closet	Basement engineer's office	50	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement engineer's office	809	SF	7	10+ years	
	AC Unit	Main Office 1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office 1st Floor	410	SF	7	10+ years	
	Doors - Transom Window	Main Office 1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office 1st Floor	1	EA	6	10+ years	
	Floor - Wood	Main Office 1st Floor	410	SF	6	10+ years	
	Lighting - Pendent/Surface	Main Office 1st Floor	2	EA	7	6-10 years	
	Power Distribution	Main Office 1st Floor	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office 1st Floor	800	SF	7	10+ years	



Catego	ry : Room		R	uilding	• Main	10	
Calego	y. Room		D	unung	. พลาก	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Ceiling - Plaster/Drywall	Nurse in auditorium	239	SF	7	10+ years	Comments
	Doors - Wood Doors inclu hw	Nurse in auditorium	200	EA	7	10+ years	
	Floor - Wood	Nurse in auditorium	239	SF	7	10+ years	
	Lighting - Pendent/Surface	Nurse in auditorium	200	EA	7	6-10 years	
	Power Distribution	Nurse in auditorium	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Nurse in auditorium	600	SF	7	10+ years	
	AC Unit	Principal's Office 103	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Office 103	220	SF	7	10+ years	
	Doors - Transom Window	Principal's Office 103	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office 103	2	EA	6	10+ years	
	Floor - Wood	Principal's Office 103	220	SF	6	10+ years	
	Lighting - Pendent/Surface	Principal's Office 103	2	ĒA	7	6-10 years	
	Power Distribution	Principal's Office 103	6	EA	7	10+ years	
	Storage/ Closet	Principal's Office 103	90	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office 103	780	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 211, Lunch Room Office	151	SF	7	10+ years	
	Doors - Steel Doors incl hw	Room 211, Lunch Room Office	1	ĒA	7	10+ years	
	Floor - Tile	Room 211, Lunch Room Office	151	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 211, Lunch Room Office	1	EA	7	6-10 years	
	Power Distribution	Room 211, Lunch Room Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 211, Lunch Room Office	256	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 301, Gym Instructor's Office	315	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 301, Gym Instructor's Office	2	EA	7	10+ years	
	Floor - Wood	Room 301, Gym Instructor's Office	315	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 301, Gym Instructor's Office	2	ĒA	7	6-10 years	
	Power Distribution	Room 301, Gym Instructor's Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 301, Gym Instructor's Office	501	SF	7	10+ years	
Auditoriu	m & Theater						
Auditoriu	Balcony Seating	Basement	186	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	3,654	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	4	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	913	SF	7	10+ years	Balcony
	Floor - Tile	Basement	3,624	SF	6	10+ years	Dalcony
	Floor - Tile	Basement	30	SF	5	1-2 years	Damaged
	Lighting - Chandelier, Incandescent	Basement	8	EA	7	6-10 years	Damagea
	Main Floor Seating	Basement	266	EA	7	6-10 years	
	Stage	Basement	489	SF	6	10+ years	
	Stage Curtain	Basement	10	EA	7	6-10 years	
	Stage Lift	Basement	10	EA	7	6-10 years	
	Stage Lighting System	Basement	1	EA	7	6-10 years	
	Stage-Stairs - Wood	Basement	10	LF	6	10+ years	
	Stairs - Terrazzo	Basement	8	LF	6	10+ years	
		Duschieft	0	SF	0	i or years	



Catego	ategory : Room			Building : Main					
						Recommend	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	Basement	5,584	SF	7	10+ years			
Gymnasi	a								
-	Ceiling - Plaster/Drywall	2nd Floor	3,458	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years			
	Floor - Wood	2nd Floor	3,458	SF	7	10+ years			
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	9	EA	7	6-10 years			
	Scoreboards	2nd Floor	1	EA	7	6-10 years			
	Sound System	2nd Floor	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	2,093	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	2,093	SF	7	10+ years			
Kitchen									
	Ceiling - Plaster/Drywall	2nd Floor	279	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	279	SF	7	10+ vears			
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	423	SF	7	10+ years			
Locker/S	hower Room								
	Accessories	Basement next to engineer's office	185	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement next to engineer's office	185	SF	7	10+ years			
	Doors - Transom Window	Basement next to engineer's office	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement next to engineer's office	1	ĒA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	Basement next to engineer's office	185	SF	7	10+ years			
	Floor Drain	Basement next to engineer's office	2	ĒA	7	10+ years			
	Lavatory	Basement next to engineer's office	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	Basement next to engineer's office	2	EA	7	6-10 years			
	Partitions	Basement next to engineer's office	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	Basement next to engineer's office	640	SF	7	10+ years			
	Water Closet	Basement next to engineer's office	1	EA	6	6-10 years			
MDF_ID	F								
	Finishes	1st flr inside main office suite	76	SF	7	10+ years			
	Window AC Unit	1st flr inside main office suite	1	EA	7	6-10 years			
Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	37	SF	7	10+ years			
	Storage Room	1st Floor	100	SF	7	10+ years			
	Janitor's Closet	2nd Floor	28	SF	7	10+ years			
	Boiler Room	Basement	1,481	SF	7	10+ years			
	Coal Room	Basement	392	SF	7	10+ years			



Catego	ry : Room		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Janitor's Closet	Basement	75	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	2,469	SF	7	10+ years		
	Storage Room	Basement	102	SF	7	10+ years		
	Storage Room	Formerly the Men's Room in the Auditorium lobby	87	SF	7	10+ years		
Restroor	n							
	Accessories	1st Floor Boy's Restroom (110)	344	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor Boy's Restroom (110)	344	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor Boy's Restroom (110)	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor Boy's Restroom (110)	344	SF	7	10+ years		
	Floor Drain	1st Floor Boy's Restroom (110)	1	EA	7	10+ years		
	Hand Dryer	1st Floor Boy's Restroom (110)	1	EA	7	6-10 years		
	Lavatory	1st Floor Boy's Restroom (110)	2	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor Boy's Restroom (110)	3	EA	7	6-10 years		
	Partitions	1st Floor Boy's Restroom (110)	1	EA	7	10+ years		
	Partitions	1st Floor Boy's Restroom (110)	1	EA	4	1-2 years	Damaged	
	Urinals	1st Floor Boy's Restroom (110)	6	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor Boy's Restroom (110)	99	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor Boy's Restroom (110)	396	SF	6	10+ years		
	Water Closet	1st Floor Boy's Restroom (110)	2	EA	7	10+ years		
	Accessories	1st Floor Girls Restroom (106)	303	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor Girls Restroom (106)	303	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor Girls Restroom (106)	1	ĒA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls Restroom (106)	303	SF	6	10+ years		
	Floor Drain	1st Floor Girls Restroom (106)	1	EA	7	10+ years		
	Hand Dryer	1st Floor Girls Restroom (106)	1	EA	7	6-10 years		
	Lavatory	1st Floor Girls Restroom (106)	2	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor Girls Restroom (106)	3	EA	6	6-10 years		
	Partitions	1st Floor Girls Restroom (106)	4	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor Girls Restroom (106)	96	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor Girls Restroom (106)	383	SF	6	10+ years		
	Water Closet	1st Floor Girls Restroom (106)	4	EA	7	10+ years		
	Accessories	1st Floor Teacher's Restroom used	71	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor Teacher's Restroom used as office	170	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor Teacher's Restroom used as office	1	EA	6	10+ years		
	Floor - Tile	1st Floor Teacher's Restroom used as office	165	SF	6	10+ years		
	Floor - Tile	1st Floor Teacher's Restroom used as office	5	SF	5	1-2 years	Damaged	
	Lavatory	1st Floor Teacher's Restroom used	1	EA	6	6-10 years		



Catego	ry : Room		В	uilding	: Main		
	-			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-		as office					
	Lighting - Pendent/Surface	1st Floor Teacher's Restroom used	1	EA	6	6-10 years	
		as office					
	Partitions	1st Floor Teacher's Restroom used	1	EA	7	6-10 years	
		as office					
	Walls - Plaster/Drywall	1st Floor Teacher's Restroom used	520	SF	7	10+ years	
		as office			_		
	Water Closet	1st Floor Teacher's Restroom used	1	EA	6	6-10 years	
	. .	as office		0-	_	0.40	
	Accessories	2nd Floor Teacher's Restroom	71	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Teacher's Restroom	71	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Teacher's Restroom	1	EA	7	10+ years	
	Floor - Tile	2nd Floor Teacher's Restroom	71	SF	7	10+ years	
	Lavatory	2nd Floor Teacher's Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Teacher's Restroom	1	EA	7	6-10 years	
	Partitions	2nd Floor Teacher's Restroom	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Teacher's Restroom	220	SF	7	10+ years	
	Water Closet	2nd Floor Teacher's Restroom	1	EA	7	10+ years	
	Accessories	Basement Boy's	253	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement Boy's	253	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement Boy's	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Boy's	253	SF	6	10+ years	
	Floor Drain	Basement Boy's	1	EA	7	10+ years	
	Hand Dryer	Basement Boy's	1	EA	7	6-10 years	
	•	Basement Boy's	2	EA	7	-	
	Lavatory					6-10 years	
	Lighting - Pendent/Surface	Basement Boy's	3	EA	6	6-10 years	
	Partitions	Basement Boy's	2	EA	7	10+ years	
	Urinals	Basement Boy's	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement Boy's	200	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement Boy's	599	SF	6	10+ years	
	Water Closet	Basement Boy's	2	EA	7	10+ years	
	Accessories	Basement Girl's Restroom	262	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement Girl's Restroom	262	SF	5	10+ years	
	Doors - Wood Doors inclu hw	Basement Girl's Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Girl's Restroom	262	SF	6	10+ years	
	Floor Drain	Basement Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	Basement Girl's Restroom	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement Girl's Restroom	4	EA	6	6-10 years	
	Partitions	Basement Girl's Restroom	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement Girl's Restroom	204	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement Girl's Restroom	613	SF	6	10+ years	
	Water Closet	Basement Girl's Restroom	3	EA	7	10+ years	
	Accessories		35	SF	7		
	AUCESSUIIES	Basement inside engineer's office	35	эг	1	6-10 years	



Group

Building : Main Category : Room Recommend Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drvwall Basement inside engineer's office 35 SF 10+ vears 7 Doors - Wood Doors inclu hw Basement inside engineer's office 1 ΕA 6 10+ years Floor - Concrete Epoxy/ Painted Basement inside engineer's office 35 SF 7 10+ years Basement inside engineer's office ΕA Lavatory 1 6 6-10 years 7 Lighting - Pendent/Surface Basement inside engineer's office 1 EΑ 6-10 years SF Walls - Plaster/Drywall 7 Basement inside engineer's office 216 10+ years Water Closet Basement inside engineer's office ΕA 7 6-10 years 1 SF Accessories In Room 003 40 7 6-10 years SF Ceiling - Plaster/Drvwall In Room 003 40 7 10+ years Doors - Wood Doors inclu hw In Room 003 1 EΑ 6 10+ vears Floor - Concrete Epoxy/ Painted In Room 003 40 SF 7 10+ vears Lavatory In Room 003 1 ΕA 7 10+ years Lighting - Pendent/Surface In Room 003 1 ΕA 6 6-10 years SF 7 Walls - Plaster/Drywall In Room 003 93 10+ years Water Closet ΕA 7 In Room 003 1 10+ years In lobby of Auditorium used as SF 7 Accessories 156 6-10 years storage Ceiling - Plaster/Drywall In lobby of Auditorium used as 156 SF 6 10+ years storage Doors - Wood Doors inclu hw In lobby of Auditorium used as 1 ΕA 6 10+ years storage In lobby of Auditorium used as SF Floor - Tile Ceramic/ Porcelain 156 6 10+ years storage In lobby of Auditorium used as FΑ 5 2-5 years Not working no access Lavatory 1 storage Lighting - Pendent/Surface In lobby of Auditorium used as 1 FΑ 7 10+ years storage Partitions In lobby of Auditorium used as 2 ΕA 7 6-10 years storage Walls - Plaster/Drywall In lobby of Auditorium used as 264 SF 6 10+ years storage

2

55

55

55

1

2

1

1

40

144

1

ΕA

SF

SF

ΕA

SF

ΕA

ΕA

ΕA

SF

FΑ

SF

6

7

7

6

7

7

6

7

7

7

7

6-10 years

6-10 years

10+ years

10+ years

10+ years

10+ years

6-10 years

6-10 years

10+ years

10+ vears

6-10 years

Water Closet

Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Pendent/Surface Partitions Walls - Plaster/Drywall Water Closet Accessories

Page : 13 of 25

In lobby of Auditorium used as

Restroom in Principals Office

Restroom in Principals Office

Restroom in Principals Office

Restroom in Principals Office

Room 108B Kindergarten in Room

storage

108



Catego	ry : Room		В				
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Room 108B Kindergarten in Room 108	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 108B Kindergarten in Room 108	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 108B Kindergarten in Room 108	40	SF	7	10+ years	
	Lavatory	Room 108B Kindergarten in Room 108	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 108B Kindergarten in Room 108	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Room 108B Kindergarten in Room 108	93	SF	6	10+ years	
	Water Closet	Room 108B Kindergarten in Room 108	1	EA	7	10+ years	
	Accessories	Room 206, Girl's Room	303	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 206, Girl's Room	303	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 206, Girl's Room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 206, Girl's Room	303	SF	7	10+ years	
	Floor Drain	Room 206, Girl's Room	1	EA	7	10+ years	
	Hand Dryer	Room 206, Girl's Room	1	EA	7	6-10 years	
	Lavatory	Room 206, Girl's Room	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 206, Girl's Room	3	EA	7	6-10 years	
	Partitions	Room 206, Girl's Room	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 206, Girl's Room	96	SF	7	10+ years	
	Walls - Structural Glazed Tile	Room 206, Girl's Room	383	SF	7	10+ years	
	Water Closet	Room 206, Girl's Room	4	EA	7	10+ years	
	Accessories	Room 210, Boy's Room	344	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 210, Boy's Room	344	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 210, Boy's Room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 210, Boy's Room	344	SF	7	10+ years	
	Floor Drain	Room 210, Boy's Room	1	EA	7	10+ years	
	Hand Dryer	Room 210, Boy's Room	1	EA	7	6-10 years	
	Lavatory	Room 210, Boy's Room	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 210, Boy's Room	3	EA	7	6-10 years	
	Partitions	Room 210, Boy's Room	2	EA	7	10+ years	
	Partitions	Room 210, Boy's Room	1	EA	4	1-2 years	Damaged
	Urinals	Room 210, Boy's Room	5	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 210, Boy's Room	99	SF	7	10+ years	
	Walls - Structural Glazed Tile	Room 210, Boy's Room	396	SF	7	10+ years	
	Water Closet	Room 210, Boy's Room	3	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #001 (Faculty Lounge)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	428	SF	7	10+ years	
	Doors - Transom Window	Basement	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	425	SF	6	10+ years	
	Floor - Tile	Basement	3	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	Basement	6	EA	6	6-10 years	
	Marker Board	Basement	36	LF	7	6-10 years	
	Walls - Masonry	Basement	934	SF	6	10+ years	
Classroo	om #002 (Regular Classroom)						
	AC Units	Basement	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	768	SF	7	10+ years	
	Doors - Transom Window	Basement	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	758	SF	6	10+ years	
	Floor - Tile	Basement	10	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	Basement	10	EA	7	6-10 years	0
	Marker Board	Basement	24	LF	7	6-10 years	
	Walls - Masonry	Basement	1,204	SF	6	10+ years	
Classroo	om #003 (Counseling Room)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	375	SF	7	10+ years	
	Doors - Transom Window	Basement	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	372	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	4	EA	7	6-10 years	
	Marker Board	Basement	8	LF	7	6-10 years	
	Storage/ Closet	Basement	6	SF	7	10+ years	
	Student Lockers - One Tier	Basement	10	EA	7	2-5 years	
	Walls - Plaster/Drywall	Basement	888	SF	7	10+ years	
Classroo	om #004 (Faculty Lounge)						
	Ceiling - Plaster/Drywall	Basement	372	SF	7	10+ years	
	Doors - Transom Window	Basement	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	ĒA	6	10+ years	
	Floor - Tile	Basement	372	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	2	EA	7	6-10 years	
	Marker Board	Basement	- 8	LF	7	6-10 years	
	Storage/ Closet	Basement	6	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	888	SF	7	10+ years	
	•					•	



Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Work Sink	Basement	1	EA	7	6-10 years			
Classroo	om #005 (Pre School)								
	AC Units	Basement	3	EA	7	6-10 years			
	Casework	Basement	6	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	Basement	1,210	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years			
	Floor - Tile	Basement	1,210	SF	6	10+ years			
	Lighting - Pendent/Surface	Basement	12	EA	7	6-10 years			
	Walls - Masonry	Basement	1,628	SF	7	10+ years			
	Work Sink	Basement	2	EA	7	6-10 years			
						,			
Classroo	om #101 (Regular Classroom)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	750	SF	7	10+ years			
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	750	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years			
	Marker Board	1st Floor	20	LF	6	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,329	SF	7	10+ years			
	·······		.,	•		, every end			
Classroo	om #102 (Regular Classroom)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	708	SF	7	10+ years			
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	708	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years			
	Marker Board	1st Floor	24	LF	6	6-10 years			
	Storage/ Closet	1st Floor	6	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,346	SF	7	10+ years			
	walls - Flaster/Drywall	13111001	1,0+0	01	,	TOF years			
Classroo	om #104 (Regular Classroom)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	708	SF	7	10+ years			
	Chalk Board	1st Floor	6	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
			I	LA	U	ior years			



Catego	ry : Classroom		В	uilding	: Main		
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Wood	1st Floor	708	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒA	7	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,346	SF	7	10+ years	
	······		.,			, ,	
lassroc	m #107 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	750	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,329	SF	7	10+ years	
			.,0_0	•	•	let jeale	
lassroc	om #108 (Kindergarten)						
	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	865	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	865	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	197	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,530	SF	7	10+ years	
	,		,			,	
lassroc	m #109 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	750	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,329	SF	7	10+ years	
Nee							
Jassroc	m #201 (Regular Classroom)			Ξ.		0.40	
	AC Units	2nd Floor	2	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		correctionality officer, childings, in our lo
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,196	SF	7	10+ years	
Classroo	om #202 (Computer Lab)						
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	708	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	708	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,346	SF	7	10+ years	
	Wireless System	2nd Floor	1,010	EA	7	6-10 years	
Classro	om #203 (Regular Classroom)						
_01233100	AC Units	2nd Floor	4	EA	7	6.10	
		2nd Floor 2nd Floor	1 8		7 7	6-10 years	
	Casework	2nd Floor 2nd Floor		SF		10+ years	
	Ceiling - Plaster/Drywall		750		7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,196	SF	7	10+ years	
_Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	48	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	708	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	708	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	4	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,346	SF	7	10+ years	
Classroo	om #205 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
			12	-	,	ioi youio	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	381	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	381	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	965	SF	7	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Chalk Board	2nd Floor		LF		•	
			12		4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,196	SF	6	10+ years	
Classroo	om #208 (Science Classroom)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,110	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,098	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	12	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor	25	ĒA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,780	SF	7	10+ years	
	Work Sink	2nd Floor	1,700	EA	7	10+ years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu nw	2nd Floor 2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,196	SF	7	10+ years	
Classroo	om #400 (Faculty Lounge)						
	AC Units	3rd Floor	2	EA	7	6-10 years	



Category : Classroom			B	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	422	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	422	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,050	SF	7	10+ years	

Category : Interior

Catego	Category : Interior			uilding			
			• • • •			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	204	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,190	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	204	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	2,190	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	6	6-10 years	
	Stairs - Terrazzo	1st Floor	22	LF	6	10+ years	
	Student Lockers - One Tier	1st Floor	87	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,799	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,866	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,394	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	2,394	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	
	Stairs - Terrazzo	2nd Floor	70	LF	7	10+ years	
	Student Lockers - Two Tiers	2nd Floor	214	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,707	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,707	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	153	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	153	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	459	SF	7	10+ years	
	Ceiling - Lay-in	Basement	204	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	2,190	SF	7	10+ years	
	Doors - Store Front	Basement	4	EA	6	10+ years	
	Doors - Wood Doors include hw	Basement	9	EA	6	10+ years	
	Drinking Fountains - Single Water Cooler	Basement	2	EA	7	6-10 years	
	Floor - Terrazzo	Basement	913	SF	6	10+ years	
	Floor - Tile/Sheet	Basement	1,461	SF	7	10+ years	



Category : Interior		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	Basement	20	SF	4	1-2 years	Damaged
	Lighting - Lay-in	Basement	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement	19	EA	6	6-10 years	
	Stairs - Terrazzo	Basement	6	LF	6	10+ years	
	Student Lockers - One Tier	Basement	47	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement	1,123	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	2,245	SF	6	10+ years	
Safety							
<u> </u>	Camera Viewing Station	interior & exterior	2	EA	7	6-10 years	
	Security Cameras	interior & exterior	2	EA	7	6-10 years	
	Security Cameras	interior & exterior	6	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North East	748	SF	7	10+ years	
	Floor - Terrazzo	North East	520	SF	7	10+ years	
	Handrails	North East	192	LF	7	10+ years	
	Lighting - Pendent/Surface	North East	7	EA	7	6-10 years	
	Stairs - Terrazzo	North East	630	LF	7	10+ years	
	Walls - Plaster/Drywall	North East	4,565	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North West	283	SF	7	10+ years	
	Floor - Terrazzo	North West	200	SF	7	10+ years	
	Handrails	North West	64	LF	7	10+ years	
	Lighting - Pendent/Surface	North West	1	EA	7	6-10 years	
	Stairs - Terrazzo	North West	210	LF	7	10+ years	
	Walls - Plaster/Drywall	North West	1,006	SF	7	10+ years	
	Walls - Structural Glazed Tile	North West	503	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	490	SF	7	10+ years	
	Floor - Terrazzo	South	280	SF	7	10+ years	
	Handrails	South	128	LF	7	10+ years	
	Lighting - Pendent/Surface	South	7	EA	7	6-10 years	
	Stairs - Terrazzo	South	420	LF	7	10+ years	
	Walls - Plaster/Drywall	South	1,120	SF	7	10+ years	
	Walls - Structural Glazed Tile	South	1,120	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South East	283	SF	7	10+ years	
	Floor - Terrazzo	South East	200	SF	7	10+ years	
	Handrails	South East	64	LF	7	10+ years	
	Lighting - Pendent/Surface	South East	2	EA	7	6-10 years	
	Stairs - Terrazzo	South East	210	LF	7	10+ years	
	Walls - Plaster/Drywall	South East	1,006	SF	7	10+ years	
	Walls - Structural Glazed Tile	South East	503	SF	7	10+ years	
	Walls - Structural Glazed Lile	South East	503	SF	7	10+ years	

Vertical Conveyance



Catego	ry : Interior		В	uilding			
Group	21 · · · · · · · · · · · · · · · · · · ·		Quantity	UOM	Rank	Recommend Replacement	Comments
	Elevator - Elevator- Roped Holeless Hydraulic	1st Floor	1	EA	7	10+ years	
	Wheelchair Lift - Chair Lift Wheelchair Lift - Platform Lift	1st Floor 1st Floor	1 1	EA EA	7 7	10+ years 10+ years	



Category : Site Building : Site Recommend Location Item - Type Quantity UOM Rank Replacement **Comments** Group Athletic SF Surface - Natural North 14,206 4 0-1 year Grass grown over asphalt Civil/Drainage Civil/ Drainage - Catch Basin Entire Site 3 ΕA 6 10+ years 3 Civil/ Drainage - Site Manhole Entire Site ΕA 6 10+ years Fencing Fencing - Chain Link Entire Site 601 LF 6 10+ years LF Fencing - Chain Link Entire Site 504 5 2-5 years LF Fencing - Chain Link Entire Site 18 4 0-1 year Corroded, leaning LF Fencing - New Standard Ornamental Entire Site 201 6 10+ years Landscape Benches Entire Site 4 ΕA 6 10+ years 91,988 SF Landscape - Grass Entire Site 6 10+ years Landscape - Hardscape- Pavers Entire Site 100 SF 6 10+ vears Parkway trees Entire Site 33 ΕA 6 10+ years Planting Beds/ Area Entire Site 1.533 SF 6 10+ years SF Play Area - Hardscape- Asphalt Entire Site 2.729 6 10+ years Retaining Wall - Concrete Entire Site 30 SF 6 10+ years **Trash Receptacles** Entire Site 1 EΑ 6 10+ years Parking Lot Surface - Asphalt Northwest 4,782 SF 5 2-5 years Trash Enclosure - Chain Links Northwest 625 SF 7 10+ years SF Surface - Asphalt Southwest 12,063 6 6-10 years SF 5 Surface - Asphalt Southwest 100 2-5 years 1 F Vehicular Screening Southwest 70 6 10+ years Playground Equipment - Pre K 3-5 West 7 1 EΑ 10+ years Surface - Square Rubber Mats West 3.646 SF 7 10+ years Sidewalks Sidewalks - Internal Walks Entire Site 554 LF 7 10+ years Replaced LF Sidewalks - Internal Walks Entire Site 453 6 10+ years SF Sidewalks - Perimeter Sidewalks Entire Site 10,078 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site 25 SF 4 0-1 year Spalling



Alice L Barnard Computer Math & Science Ctr ES

10354 S Charles STREET, Chicago, IL 60643

Catego	ry : Site	В	uilding				
Group	Item - Type Location		Quantity	Quantity UOM Rank			Comments
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter	Entire Site	3	EA	6	10+ years	
	Sign						
	Monument - Sign	Entire Site	1	EA	7	10+ years	
	Monument - Sign-Lighted	Entire Site	1	EA	6	6-10 years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

• Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated

• Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		•		•					
Computer Lab	Regular Classroom	2nd Floor	202	202	708	100	40	Y	N
Counseling Room	Special Program	Basement	003	003	372	38	19	N	N
Faculty Lounge	Regular Classroom	3rd Floor	400	400	422	66	30	Y	N
Faculty Lounge	Special Program	Basement	001	001	428	38	19	N	Y
Faculty Lounge	Special Program	Basement	004	004	372	38	19	N	N
Kindergarten	Kindergarten	1st Floor	108	108	865	130	60	N	Y
Office	Special Program	2nd Floor	205	205	381	30	10	Y	N
Pre School	Pre School	Basement	005	005	1,210	69	34	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	750	198	90	N	Y
Regular Classroom	Regular Classroom	1st Floor	102	102	708	110	50	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	708	110	50	Ν	Y
Regular Classroom	Regular Classroom	1st Floor	107	107	750	198	90	N	Y
Regular Classroom	Regular Classroom	1st Floor	109	109	750	198	90	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	750	198	90	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	750	198	90	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	708	110	50	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	750	198	90	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	750	198	90	Y	N
Regular Classroom	Regular Classroom	Basement	002	002	768	69	34	N	Y
Science Classroom	Science Classroom	2nd Floor	208	208	1,110	170	80	Y	N