

the end of this report.

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1919	3	92,937
Addition	1998	3	58,757
Campus Total			151,694

Catego	ry : Exterior	Building : Main							
			0	11014	.	Recommend	•		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Cell Equ	•								
	Cell Equipment - Antenna	Northwest low roof	2	EA	7	6-10 years	Corrected quantity		
	Cell Equipment - Cabinets	Northwest low roof	2	EA	7	6-10 years	Corrected quantity		
Entrance									
	Entrance Control - Audio and Video	#1, 2 & 3 - main entrance - E	1	EA	7	6-10 years			
	Exterior Doors - Exterior Steel Door	#1, 2 & 3 - main entrance - E	6	EA	6	6-10 years			
	Exterior Doors - Transom Lite	#1, 2 & 3 - main entrance - E	3	EA	6	6-10 years			
	Exterior Stairs - Concrete	#1, 2 & 3 - main entrance - E	232	LF	6	2-5 years			
	Stair Handrail - Steel_Stair Handrail	#1, 2 & 3 - main entrance - E	52	LF	6	6-10 years			
	Exterior Doors - Exterior Steel Door	#12 - S	2	EA	6	10+ years			
	Exterior Doors - Transom Lite	#12 - S	2	EA	6	10+ years			
	Exterior Stairs - Concrete	#12 - S	68	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	#13 - S	4	EA	6	6-10 years			
	Exterior Doors - Transom Lite	#13 - S	4	EA	6	6-10 years			
	Exterior Stairs - Concrete	#13 - S	92	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	#14 - S	2	EA	6	6-10 years			
	Exterior Doors - Transom Lite	#14 - S	1	EA	6	6-10 years			
	Exterior Stairs - Concrete	#14 - S	10	LF	6	10+ years			
	Exterior Stairs - Stone	#14 - S	3	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	#15 - SW	1	EA	6	6-10 years			
	Ramp Handrail - Steel_Ramp Handrail	#15 - SW	40	LF	6	2-5 years			
	Ramps - Concrete	#15 - SW	20	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	#16, 17 & 18 - W	6	EA	6	6-10 years			



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	#16, 17 & 18 - W	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#16, 17 & 18 - W	158	LF	6	10+ years	
	Exterior Stairs - Concrete	#16, 17 & 18 - W	10	LF	5	1-2 years	Cracks
	Stair Handrail - Steel_Stair Handrail	#16, 17 & 18 - W	20	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#19 - NW	1	EA	6	10+ years	
	Exterior Doors - Side lite	#19 - NW	1	EA	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage Door	#20 - N Overhead	1	EA	6	2-5 years	
	Exterior Doors - Exterior Steel Door	#21 - N	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#21 - N	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#21 - N	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#22 - N	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#22 - N	2	EA	6	6-10 years	
_Foundat	ion						
	Foundation - Concrete	Entire Building	866	LF	7	10+ years	
	Foundation - Concrete	Entire Building	50	LF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	92,847	SF	6	10+ years	
_Lighting							
- 0 - 0	Exterior Lighting - Wall Mounted	Entire Building	27	EA	6	6-10 years	
Roof Sys	stem						
	Coping - Terra Cotta	Court yard - center	120	LF	7	10+ years	
	Downspouts - Interior Downspouts	Court yard - center	26	LF	6	10+ years	
	Parapet - 16" - 30" Height	Court yard - center	100	LF	6	10+ years	
	Roof - Metal	Court yard - center	810	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Court yard - center	810	SF	7	10+ years	
	Access Ladder - Metal	Low NW roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Low NW roof	60	LF	7	10+ years	Not previously assessed
	Coping - Stone	Low NW roof	155	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low NW roof	36	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low NW roof	155	LF	5	2-5 years	Spalling throughout
	Roof - Modified Bitumen	Low NW roof	2,669	SF	5	1-2 years	Active roof leaks
	Roof Structure - Steel with Clay Tile Arch	Low NW roof	2,669	SF	7	10+ years	
	Coping - Stone	Low SW roof	136	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low SW roof	18	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Low SW roof	86	LF	5	10+ years	
	Parapet - Parapet < 16" Height	Low SW roof	50	LF	5	10+ years	
	Roof - Modified Bitumen	Low SW roof	2,148	SF	4	0-1 year	Alligator cracks, bubbles
	Roof Structure - Steel with Clay Tile Arch	Low SW roof	2,148	SF	6	10+ years	
	Access Ladder - Metal	Main Roof	4	EA	4	0-1 year	Lower ladder not high enough, upper ladder as bouncy and not aligned with
							, 3



Catego	Category : Exterior		В	uilding	: Main			
	-	1	A 41.	11614	ъ.	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	107	LF	6	6-10 years	hatch	
	Liner	Mail Rooi	107	LI	O	0-10 years		
	Coping - Stone	Main Roof	569	LF	6	2-5 years		
	Coping - Terra Cotta	Main Roof	120	LF	7	10+ years		
	Downspouts - Interior Downspouts	Main Roof	422	LF	6	6-10 years	Recombined quantities	
	Parapet - 16" - 30" Height	Main Roof	647	LF	5	1-2 years	Crumbling brick	
	Parapet - Parapet > 30"	Main Roof	45	LF	5	1-2 years	Crumbling brick	
	Roof - Modified Bitumen	Main Roof	13,280	SF	5	2-5 years	-	
	Roof Hatch - Metal	Main Roof	2	EA	5	0-1 year	Not sealed well, no hinges, not	
							aligned with ladder	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	13,280	SF	7	10+ years		
	Access Ladder - Metal	Upper NE roof	3	EA	5	2-5 years	Not tall enough	
	Coping - Stone	Upper NE roof	255	LF	6	10+ years		
	Downspouts - Interior Downspouts	Upper NE roof	228	LF	6	10+ years		
	Parapet - 16" - 30" Height	Upper NE roof	205	LF LF	5	0-1 year	Crumbling brick	
	Parapet - Parapet > 30" Roof - Modified Bitumen	Upper NE roof Upper NE roof	50 7,212	SF	5 4	0-1 year	Crumbling brick Bubbling, alligator cracking	
	Roof Hatch - Metal	Upper NE roof	1,212	EA	5	1-2 years 1-2 years	Small opening, poorly sealed	
	Roof Structure - Steel with Clay Tile Arch	Upper NE roof	7,212	SF	7	10+ years	Small opening, poonly sealed	
	Access Ladder - Metal	Upper SE roof	3	EA	5	2-5 years	Not high enough	
	Coping - Stone	Upper SE roof	259	LF	6	2-5 years	rtot riigir onougri	
	Downspouts - Interior Downspouts	Upper SE roof	228	LF	6	6-10 years		
	Parapet - 16" - 30" Height	Upper SE roof	259	LF	5	1-2 years	Spalling, crumbling	
	Roof - Modified Bitumen	Upper SE roof	7,317	SF	5	1-2 years	Alligator cracks, bubbles	
	Roof Hatch - Metal	Upper SE roof	1	EA	5	2-5 years	Small, not hinged	
	Roof Structure - Steel with Clay Tile Arch	Upper SE roof	7,317	SF	7	10+ years	-	
Walls								
	Cheek-Wall - Stone	Entire Building	175	SF	6	6-10 years		
	Cheek-Wall - Stone	Entire Building	25	SF	5	1-2 years	Cracked, displaced stone	
	Cornice - Masonry Projecting Limestone	Entire Building	2,788	LF	6	10+ years	Recombined quantities	
	Exterior Walls - Brick	Entire Building	60,970	SF	7	10+ years		
	Exterior Walls - Brick	Entire Building	430	SF	4	2-5 years	Water infiltration, combined quantities	
	Exterior Walls - Stone-Cut	Entire Building	2,032	SF	5	10+ years		
Windows								
V V II IUUVVS	Guard - Guards perforated	Entire Building	2,142	SF	6	10+ years		
	Lintels - Steel	Entire Building	270	LF	6	10+ years		
	Lintels - Stone	Entire Building	60	LF	6	10+ years		
	Skylite - Glass Single-Pane	Entire Building	900	SF	4	0-1 year	Cracked glass corrected quantity	
	Windows - Sash Aluminum Double-pane	Entire Building	10,302	SF	6	10+ years	3	
		3	,			,		



Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years	
	Security System - CCTV	Entire Building	92,937	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	92,937	SF	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	6,024	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	16,865	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	5,468	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	22,154	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	12	ĒA	6	6-10 years	Exit signs have been upgraded throughout the building since last assessment. Rank, Reason and Priority Rep adjusted based on current observations.
	Exit Signs - Corridors and Stairs	Entire Building	28	EA	6	6-10 years	Exit signs have been upgraded throughout the building since last assessment. Rank, Reason and Priority Rep adjusted based on current observations.
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Exit signs have been upgraded throughout the building since last assessment. Rank, Reason and Priority Rep adjusted based on current observations.
Main Se	rvice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	92,937	SF	7	6-10 years	Also serves Addition. Overall system upgrade completed in October, 2022. Rank, Reason and Priority Rep adjusted accordingly.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots expose conductors presenting a live front condition, and are ineffectively covered with electrical tape.



vaityu	ory : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	EM fuse panel. Open fuse receptacles present a live-front situation.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	Quantity changed to match current observations.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Located adjacent to the door for Room 401.
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Quantity changed as total has been divided/aggregated. Location changed based on current observations.
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	rm						
	Fire Alarm Panel	Entire Building	1	EA	3	2-5 years	Older panel beyond its EUL. Serves Main and Addition.
	Fire Alarm Strobe Lights	Entire Building	92,937	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	92,937	SF	6	6-10 years	
_	wy . Machanical		_	uildina	: Main		
Catego	ory : wechanicai		В	unung			
Catego	ory : Mechanical		В	unung		Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location					Comments
Group	Item - Type dling Systems Indoor Return Fans- Centrifugal Inline -	Location Attic					Comments Dataplate not accessible at the time of assessment.
Group	Item - Type dling Systems		Quantity	UOM	Rank	Replacement	Dataplate not accessible at the time
Group	Item - Type dling Systems Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Indoor Return Fans- Centrifugal Inline -	Attic	Quantity	UOM	Rank 7	Replacement 10+ years	Dataplate not accessible at the time of assessment. Dataplate not accessible at the time of assessment. AHU-3, serves auditorium and
Group	Item - Type dling Systems Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Hot	Attic Attic	Quantity 1	UOM EA EA	7 7 7	10+ years 10+ years 10+ years	Dataplate not accessible at the time of assessment. Dataplate not accessible at the time of assessment.
Group	Item - Type dling Systems Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Hot Water Coils - 8001 - 15000 cfm Air Intake	Attic Attic Mechanical Room	Quantity 1 1 1	UOM EA EA EA	7 7 7 7	10+ years 10+ years 10+ years 10+ years	Dataplate not accessible at the time of assessment. Dataplate not accessible at the time of assessment. AHU-3, serves auditorium and
Group	Item - Type dling Systems Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Hot Water Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Sheet Metal- Exterior	Attic Attic Mechanical Room Mechanical Room	Quantity 1 1 1 1	UOM EA EA EA EA	7 7 7	10+ years 10+ years 10+ years	Dataplate not accessible at the time of assessment. Dataplate not accessible at the time of assessment. AHU-3, serves auditorium and
Group	Item - Type dling Systems Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Hot Water Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Hot Water Coils - 15001 - 25000	Attic Attic Mechanical Room Mechanical Room Mechanical Room	Quantity 1 1 1 1 1 1 1	EA EA EA EA EA EA	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Dataplate not accessible at the time of assessment. Dataplate not accessible at the time of assessment. AHU-3, serves auditorium and
Group	Item - Type dling Systems Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Hot Water Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Hot Water Coils - 15001 - 25000 cfm	Attic Attic Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 1 1 1 1 50	EA	7 7 7 7 7 7 6	10+ years	Dataplate not accessible at the time of assessment. Dataplate not accessible at the time of assessment. AHU-3, serves auditorium and gymnasium in Main.
Group	Item - Type dling Systems Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Hot Water Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Hot Water Coils - 15001 - 25000	Attic Attic Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Quantity 1 1 1 1 1 50	EA EA EA EA LF	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	10+ years	Dataplate not accessible at the time of assessment. Dataplate not accessible at the time of assessment. AHU-3, serves auditorium and gymnasium in Main.



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical Room	5	EA	7	10+ years	Numbered 2 through 6. Quantity changed based on current observations.
	Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts	Mechanical Room	75	LF	7	10+ years	
	Zone Dampers	Mechanical Room	16	EA	7	6-10 years	Quantity changed based on current observations.
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Hot Water Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	7	10+ years	AHU-2, serves north part of Main
	Air Intake	Mechanical Room	1	EA	7	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	7	10+ years	
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical Room	6	EA	7	10+ years	Numbered 8 through 13
	Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts	Mechanical Room	75	LF	7	10+ years	
	Zone Dampers	Mechanical Room	19	EA	7	6-10 years	Quantity changed to match current observations.
Boiler Sy	vstems						
·	Boiler Auxiliary- Condensing Hot Water - Less than 500 HP	Boiler Room	2	EA	7	10+ years	
	Chemical Pot Feeder	Boiler Room	2	EA	7	10+ years	
	Condensing- Hot Water Boiler - Greater 4000 MBH	Boiler Room	2	EA	7	10+ years	B-1 and B-2
	Glycol Feed System	Boiler Room	1	EA	7	10+ years	
Gas Boo	ster						
	Gas Booster	Boiler Room	2	EA	7	10+ years	
_Heating	Devices						
Ū	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Location and Priority Rep changed based on current observations.
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	Controlled by an integral internal thermostat.
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Controlled by an external electric thermostat.
	Wall Heater - Electric	Entire Building	1	EA	7	6-10 years	

Campus Name: Bateman Page : 6 of 51 Assessment Date: 07/24/2023



	y : Mechanical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wall Heater - Electric	Entire Building	4	EA	7	6-10 years	
	Wall Heater - Electric	Entire Building	10	EA	7	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	7	6-10 years	
	Wall Heater - Electric	Entire Building	1	EA	7	6-10 years	Located in the hallway area across
	Fin Tube - Electric	Entire Building	6	LF	7	6-10 years	from Room 401. Located in student restrooms.
	Fin Tube - Electric	Entire Building	6	LF	7	6-10 years	
	Fin Tube - Electric	Entire Building	18	LF	6	6-10 years	
lechanic	cal Plumbing						
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	7	6-10 years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	7	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	400	LF	7	10+ years	
empera	ture Control						
	DDC System	Entire Building	92,937	SF	7	6-10 years	
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	Controls the unit heater.
	Electric Thermostat	Entire Building	2	EΑ	7	6-10 years	Controls for the two electric unit
		g	_		•	0 .0 you.o	heaters
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	Controls the unit heater.
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	Controls the unit heater.
	Thermostats - DDC	Entire Building	34	EA	7	6-10 years	
entilatio	n						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	7	10+ years	Located in student restrooms.
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	_ 1	EA	7	10+ years	Quantity changed as total has been
	CFM	g	·		•	.0. ,00.0	divided/aggregated. Location
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	7	10+ years	modified to reflect specific roof area
	CFM						
atego	y : Plumbing		В	uilding	: Main		
	_					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate	r						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	2-5 years	Water heater is leak-free with no appreciable corrosion observed, however it has exceeded its EUL.
iping							

Campus Name: Bateman Page : 7 of 51 Assessment Date: 07/24/2023



Catego	Category : Plumbing			uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Risers	Entire Building	92,937	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	92,937	SF	6	6-10 years	Per review with Building Engineer there are approx. 5 to 10 pipe clamps throughout Main.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	92,937	SF	6	6-10 years	Per review with Building Engineer there are approx. 5 to 10 pipe clamps throughout Main.
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	92,937	SF	6	6-10 years	Per review with Building Engineer there are approx. 5 to 10 pipe clamps throughout Main.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	92,937	SF	6	6-10 years	Per review with Building Engineer there are approx. 5 to 10 pipe clamps throughout Main.
	Sanitary Piping	Entire Building	92,937	SF	6	6-10 years	
	Storm Piping	Entire Building	92,937	SF	6	6-10 years	
	Vent Piping	Entire Building	92,937	SF	7	6-10 years	
Pumps							
•	Pumps - Ejector-Duplex	Entire Building	1	EA	7	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	7	6-10 years	No CPS Asset Tag present at the time of assessment.

Category: Room **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	1st - Assistant Principal Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Assistant Principal Office	450	SF	7	6-10 years	
	Doors - Side-lite	1st - Assistant Principal Office	44	SF	6	6-10 years	
	Doors - Transom Window	1st - Assistant Principal Office	68	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st - Assistant Principal Office	2	EΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st - Assistant Principal Office	450	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st - Assistant Principal Office	9	EA	6	6-10 years	
	Power Distribution	1st - Assistant Principal Office	8	EA	6	6-10 years	
	Storage/ Closet	1st - Assistant Principal Office	41	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st - Assistant Principal Office	1,213	SF	6	6-10 years	
	AC Unit	1st - General Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - General Office	458	SF	6	6-10 years	
	Doors - Side-lite	1st - General Office	88	SF	6	6-10 years	
	Doors - Transom Window	1st - General Office	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st - General Office	1	EΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st - General Office	458	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st - General Office	9	EΑ	7	6-10 years	
	Power Distribution	1st - General Office	10	EA	6	6-10 years	

Campus Name: Bateman Page : 8 of 51 Assessment Date: 07/24/2023



Catego	ry : Room		В	uilding	: Main		
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st - General Office	80	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st - General Office	1,226	SF	6	6-10 years	
	Work SInk	1st - General Office	1	EΑ	7	6-10 years	
	AC Unit	1st - Office 105 across from general	1	EA	7	6-10 years	
		office				•	
	Ceiling - Plaster/Drywall	1st - Office 105 across from general	445	SF	7	6-10 years	
	3	office				,	
	Doors - Side-lite	1st - Office 105 across from general	88	SF	6	6-10 years	
		office		-	-	,	
	Doors - Transom Window	1st - Office 105 across from general	11	SF	6	6-10 years	
	Doors Transom Window	office		O.	O	o to years	
	Doors - Wood Doors inclu hw	1st - Office 105 across from general	1	EA	6	6-10 years	
	Doors - Wood Doors Inclu IIW	office	'	LA	U	0-10 years	
	Floor Tile Coronie/ Boroslein		4.45	C.E.	^	0.40	
	Floor - Tile Ceramic/ Porcelain	1st - Office 105 across from general	445	SF	6	6-10 years	
	1:16: 5 1 1/0 (office		_ ^	•	0.40	
	Lighting - Pendent/Surface	1st - Office 105 across from general	9	EA	6	6-10 years	
		office					
	Power Distribution	1st - Office 105 across from general	6	EA	6	6-10 years	
		office					
	Walls - Plaster/Drywall	1st - Office 105 across from general	1,213	SF	6	6-10 years	
		office					
	Work SInk	1st - Office 105 across from general	1	EΑ	7	6-10 years	
		office				•	
	Ceiling - Lay-in	1st- 100-A Vacant Office	141	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st- 100-A Vacant Office	1	EA	6	6-10 years	
	Floor - Carpet	1st- 100-A Vacant Office	141	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st- 100-A Vacant Office	3	EA	7	6-10 years	
	Power Distribution	1st- 100-A Vacant Office	6	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st- 100-A Vacant Office	522	SF	7	6-10 years	
	Ceiling - Lay-in	1st- 100-A Vacant Office	140	SF	7	6-10 years	
	Celling - Lay-III	Therapy Room	140	SI	1	0-10 years	
	Doors - Wood Doors inclu hw		4	EA	7	6.10 vooro	
	Doors - Wood Doors Inclu nw	1st- 100-B Special Ed Physical	1	EA	7	6-10 years	
	FI 0 .	Therapy Room	4.40	0=	•	0.40	
	Floor - Carpet	1st- 100-B Special Ed Physical	140	SF	6	6-10 years	
		Therapy Room					
	Lighting - Pendent/Surface	1st- 100-B Special Ed Physical	3	EA	7	6-10 years	
		Therapy Room					
	Power Distribution	1st- 100-B Special Ed Physical	4	EΑ	6	6-10 years	
		Therapy Room					
	Walls - Plaster/Drywall	1st- 100-B Special Ed Physical	522	SF	6	6-10 years	
	•	Therapy Room				•	
	AC Unit	402 Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	402 Office	286	SF	6	10+ years	
	Ceiling - Plaster/Drywall	402 Office	20	SF	4	1-2 years	Water damage
	coming i lactor bij man	.02 011100	20	٥.	•	. = 300.0	



Catego	ry : Room		В	uilding	: Main		. 5
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	402 Office	1	EA	6	10+ years	
	Floor - Wood	402 Office	306	SF	6	10+ years	
	Lighting - Pendent/Surface	402 Office	8	EA	6	6-10 years	
	Power Distribution	402 Office	8	EA	6	10+ years	
	Walls - Plaster/Drywall	402 Office	987	SF	6	10+ years	
	Work SInk	402 Office	1	EA	7	10+ years	
_Auditoriu	um & Theater						
	Balcony Seating	1st Floor	100	EA	7	6-10 years	
	Balcony Seating	1st Floor	12	EA	4	0-1 year	Broken seats
	Ceiling - Plaster/Drywall	1st Floor	6,269	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	18	EA	6	6-10 years	
	Floor - Carpet	1st Floor	279	SF	6	6-10 years	
	Floor - Terrazzo	1st Floor	382	SF	6	6-10 years	
	Floor - Tile	1st Floor	8	SF	6	6-10 years	
	Floor - Tile	1st Floor	2,637	SF	6	6-10 years	
	Floor - Wood	1st Floor	2,963	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	75	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	1,505	SF	6	6-10 years	
	Stage Curtain	1st Floor	8	EA	7	6-10 years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Asphalt	1st Floor	12	LF	6	6-10 years	
	Stairs - Asphalt	1st Floor	32	LF	7	6-10 years	
	Storage/ Closet	1st Floor	38	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	12,310	SF	7	6-10 years	
_Gymnas	ia						
_Суппаз	Ceiling - Plaster/Drywall	3rd Floor	5,468	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	44	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	6-10 years	
	Floor - Wood	3rd Floor	5,468	SF	6	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	24	EA	6	6-10 years	
	Scoreboards	3rd Floor	1	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	62	SF	7	6-10 years	
	Storage/ Closet	3rd Floor	51	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	5,928	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	12	SF	6	6-10 years	
_Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st- Staff Lounge	462	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st- Staff Lounge	1	EA	6	6-10 years	
	Doors - Wood Doors inclu hw	1st- Staff Lounge	1	EA	6	6-10 years	
	255.5 Trood Boots mold five	70t Otali Lourigo		_, 、	J	o lo youlo	

Campus Name: Bateman Page : 10 of 51 Assessment Date: 07/24/2023



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	1st- Staff Lounge	462	SF	6	6-10 years	
	Lighting - Lay-in	1st- Staff Lounge	6	EΑ	7	6-10 years	
	Student Lockers - One Tier	1st- Staff Lounge	16	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st- Staff Lounge	935	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st- Staff Lounge	128	SF	6	6-10 years	
MDF IDE	F						
<u> </u>	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Finishes	2nd Floor	1,148	SF	7	6-10 years	
	Filliplies	211d F1001	1,140	Si	,	0-10 years	
Mechanic	cal/ Service Rooms						
	Janitor's Closet	1st Floor	11	SF	5	6-10 years	
	Storage Room	1st Floor	68	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st- Inside room 100	95	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st- Inside room 100	1	EA	6	6-10 years	
	Floor - Concrete	1st- Inside room 100	95	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st- Inside room 100	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st- Inside room 100	500	SF	7	10+ years	
	Janitor's Closet	2nd Floor	11	SF	5	6-10 years	
	Storage Room	2nd Floor	159	SF	7	6-10 years	
	Janitor's Closet	3rd Floor	11	SF	5	6-10 years	
	Storage Room	3rd Floor	157	SF	7	6-10 years	
	Air Tunnel	Basement	5,410	SF	5	6-10 years	
	Auditorium Plenums	Basement	1,505	SF	5	6-10 years	
	Boiler Room	Basement	1,574	SF	5	6-10 years	
	Coal Room	Basement	522	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	1,867	SF	5	6-10 years	
	Storage Room	Basement	314	SF	5	6-10 years	
Restroon	m.						
1769110011	Accessories	1st - inside classroom 102	41	SF	7	6-10 years	
	Ceiling - Lay-in	1st - inside classroom 102	41	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st - inside classroom 102	1	ĒΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st - inside classroom 102	41	SF	6	6-10 years	
	Lavatory	1st - inside classroom 102	1	ĒΑ	7	6-10 years	
	Lighting - Lay-in	1st - inside classroom 102	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st - inside classroom 102	239	SF	7	6-10 years	
	Water Closet	1st - inside classroom 102	1	EA	7	6-10 years	
	Accessories	1st Floor	359	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	359	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	22	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	359	SF	6	6-10 years	
	. i.c iio Goraniio, i Grociani	10111001	300	0.	J	3 To yours	



	Room	Building : Main	_
Floor Drain		-	
Layatory			
Lighting - Pendent/Surface			
Partitions		,	
Urinals			
Walls - Plaster/Dywall 1st Floor 567 SF 6 6-10 years Walls - Structural Glazed Tile 1st Floor 2 EA 6 6-10 years Water Closet 1st Floor 2 EA 6 6-10 years Accessories 1st Floor 359 SF 7 6-10 years Ceiling - Plaster/Drywall 1st Floor 22 SF 6 6-10 years Doors - Transom Window 1st Floor 2 EA 6 6-10 years Floor - Tile Ceramic/ Porcelain 1st Floor 359 SF 6 6-10 years Floor - Tile Ceramic/ Porcelain 1st Floor 329 SF 6 6-10 years Floor - Tile Ceramic/ Porcelain 1st Floor 359 SF 6 6-10 years Floor - Tile Ceramic/ Porcelain 1st Floor 359 SF 6 6-10 years Floor - Torin 1st Floor 359 SF 6 6-10 years Laytatory 1st Floor 6 CA 7	rtitions 1st Floor		
Walls - Structural Glazed Tile 1st Floor 567 SF 6 6-10 years Accessories 1st Floor 359 SF 7 6-10 years Ceiling - Plaster/Drywall 1st Floor 359 SF 6 6-10 years Doors - Transom Window 1st Floor 22 SF 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 359 SF 6 6-10 years Floor Tile Ceramic/ Porcelain 1st Floor 359 SF 6 6-10 years Floor Drain 1st Floor 359 SF 6 6-10 years Floor Drain 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 6 EA 6 6-10 years Partitions 1st Floor 6 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 657 SF 6 10			
Water Closet			
Accessories	alls - Structural Glazed Tile 1st Floor		
Ceiling - Plaster/Drywall		· · · · · · · · · · · · · · · · · · ·	
Doors - Transom Window			
Doors - Wood Doors inclu hw	iling - Plaster/Drywall 1st Floor		
Floor - Tile Ceramic/ Porcelain			
Floor Drain			
Layatory	oor - Tile Ceramic/ Porcelain 1st Floor	59 SF 6 6-10 years	
Lightling - Pendent/Surface	por Drain 1st Floor	3 EA 7 6-10 years	
Partitions	vatory 1st Floor	2 EA 6 6-10 years	
Walls - Plaster/Drywall 1st Floor 657 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 657 SF 6 6-10 years Water Closet 1st Floor 6 EA 6 6-10 years Ceiling - Plaster/Drywall 1st - Men's Assembly Hall Lobby 145 SF 6 6-10 years Doors - Wood Doors inclu hw 1st - Men's Assembly Hall Lobby 1 EA 6 6-10 years Floor - Concrete 1st - Men's Assembly Hall Lobby 142 SF 7 6-10 years Partitions 1st - Men's Assembly Hall Lobby 2 EA 7 6-10 years Walls - Plaster/Drywall 1st - Men's Assembly Hall Lobby 388 SF 6 6-10 years Walls - Plaster/Drywall 1st - Unisex Inside Room 100 53 SF 7 6-10 years Accessories 1st - Unisex Inside Room 100 53 SF 6 6-10 years Ceiling - Lay-in 1st - Unisex Inside Room 100 1 EA 6 6-10 years Floor Terrazon <t< td=""><td>hting - Pendent/Surface 1st Floor</td><td></td><td></td></t<>	hting - Pendent/Surface 1st Floor		
Walls - Structural Glazed Tile 1st Floor 657 SF 6 6-10 years Water Closet 1st Floor 6 EA 6 6-10 years Ceiling - Plaster/Drywall 1st- Men's Assembly Hall Lobby 145 SF 6 6-10 years Doors - Wood Doors inclu hw 1st- Men's Assembly Hall Lobby 1 EA 6 6-10 years Floor - Concrete 1st- Men's Assembly Hall Lobby 142 SF 7 6-10 years Partitions 1st- Men's Assembly Hall Lobby 2 EA 7 6-10 years Partitions 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years Walls - Plaster/Drywall 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years Accessories 1st- Unisex Inside Room 100 53 SF 7 6-10 years Ceiling - Lay-in 1st- Unisex Inside Room 100 1 EA 6 6-10 years Floor - Terrazzo 1st- Unisex Inside Room 100 1 EA 7 6-10 years <tr< td=""><td>rtitions 1st Floor</td><td>6 EA 7 6-10 years</td><td></td></tr<>	rtitions 1st Floor	6 EA 7 6-10 years	
Water Closet 1st Floor 6 EA 6 6-10 years Ceiling - Plaster/Drywall 1st- Men's Assembly Hall Lobby 145 SF 6 6-10 years Doors - Wood Doors inclu hw 1st- Men's Assembly Hall Lobby 1 EA 6 6-10 years Floor - Concrete 1st- Men's Assembly Hall Lobby 142 SF 7 6-10 years Partitions 1st- Men's Assembly Hall Lobby 2 EA 7 6-10 years Partitions 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years Walls - Plaster/Drywall 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years Accessories 1st- Unisex Inside Room 100 53 SF 7 6-10 years Ceiling - Lay-in 1st- Unisex Inside Room 100 1 EA 6 6-10 years Floor Drain 1st- Unisex Inside Room 100 1 EA 7 6-10 years Lay-tory 1st- Unisex Inside Room 100 1 EA 6 6-10 years <	alls - Plaster/Drywall 1st Floor	557 SF 6 10+ years	
Ceiling - Plaster/Drywall 1st- Men's Assembly Hall Lobby 145 SF 6 6-10 years Doors - Wood Doors inclu hw 1st- Men's Assembly Hall Lobby 1 EA 6 6-10 years Floor - Concrete 1st- Men's Assembly Hall Lobby 142 SF 7 6-10 years Partitions 1st- Men's Assembly Hall Lobby 2 EA 7 6-10 years Walls - Plaster/Drywall 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years Walls - Plaster/Drywall 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years Accessories 1st- Unisex Inside Room 100 53 SF 7 6-10 years Ceiling - Lay-in 1st- Unisex Inside Room 100 1 EA 6 6-10 years Floor Train 1st- Unisex Inside Room 100 1 EA 6 6-10 years Lighting - Lay-in 1st- Unisex Inside Room 100 1 EA 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st- Unisex Inside Room 100 258 SF	alls - Structural Glazed Tile 1st Floor		
Doors - Wood Doors inclu hw Floor - Concrete 1st- Men's Assembly Hall Lobby 142 SF 7 6-10 years 1st- Men's Assembly Hall Lobby 2 EA 7 6-10 years 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years 4 6-10 years 4 6-10 years 4 6-10 years 5 6-10 years 5 7 6-10 years 6 8-10 years 7 6-10 years 8 8-10 years 8 9-10 years 9	ater Closet 1st Floor	6 EA 6 6-10 years	
Floor - Concrete	illing - Plaster/Drywall 1st- Men's Assembly Hall Lobby	45 SF 6 6-10 years	
Partitions 1st- Men's Assembly Hall Lobby 2 EA 7 6-10 years Walls - Plaster/Drywall 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years Accessories 1st- Unisex Inside Room 100 53 SF 7 6-10 years Ceiling - Lay-in 1st- Unisex Inside Room 100 53 SF 6 6-10 years Doors - Wood Doors inclu hw 1st- Unisex Inside Room 100 1 EA 6 6-10 years Floor - Terrazzo 1st- Unisex Inside Room 100 53 SF 6 6-10 years Floor Drain 1st- Unisex Inside Room 100 1 EA 7 6-10 years Layatory 1st- Unisex Inside Room 100 1 EA 6 6-10 years Lighting - Lay-in 1st- Unisex Inside Room 100 1 EA 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st- Unisex Inside Room 100 258 SF 6 6-10 years Water Closet 1st- Unisex Inside Room 100 2 EA 7 6-10 years Ceiling - Plaster/Drywall 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby	ors - Wood Doors inclu hw 1st- Men's Assembly Hall Lobby	1 EA 6 6-10 years	
Partitions 1st- Men's Assembly Hall Lobby 2 EA 7 6-10 years Walls - Plaster/Drywall 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years Accessories 1st- Unisex Inside Room 100 53 SF 7 6-10 years Ceiling - Lay-in 1st- Unisex Inside Room 100 53 SF 6 6-10 years Doors - Wood Doors inclu hw 1st- Unisex Inside Room 100 1 EA 6 6-10 years Floor - Terrazzo 1st- Unisex Inside Room 100 53 SF 6 6-10 years Floor Drain 1st- Unisex Inside Room 100 1 EA 7 6-10 years Layatory 1st- Unisex Inside Room 100 1 EA 6 6-10 years Lighting - Lay-in 1st- Unisex Inside Room 100 1 EA 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st- Unisex Inside Room 100 258 SF 6 6-10 years Water Closet 1st- Unisex Inside Room 100 2 EA 7 6-10 years Ceiling - Plaster/Drywall 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby	por - Concrete 1st- Men's Assembly Hall Lobby		
Walls - Plaster/Drywall 1st- Men's Assembly Hall Lobby 388 SF 6 6-10 years Accessories 1st- Unisex Inside Room 100 53 SF 7 6-10 years Ceiling - Lay-in 1st- Unisex Inside Room 100 53 SF 6 6-10 years Doors - Wood Doors inclu hw 1st- Unisex Inside Room 100 1 EA 6 6-10 years Floor - Terrazzo 1st- Unisex Inside Room 100 1 EA 7 6-10 years Floor Drain 1st- Unisex Inside Room 100 1 EA 7 6-10 years Layatory 1st- Unisex Inside Room 100 1 EA 6 6-10 years Lighting - Lay-in 1st- Unisex Inside Room 100 1 EA 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st- Unisex Inside Room 100 258 SF 6 6-10 years Water Closet 1st- Unisex Inside Room 100 2 EA 7 6-10 years Ceiling - Plaster/Drywall 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in			
Accessories			
Ceiling - Lay-in 1st- Unisex Inside Room 100 53 SF 6 6-10 years Doors - Wood Doors inclu hw 1st- Unisex Inside Room 100 1 EA 6 6-10 years Floor - Terrazzo 1st- Unisex Inside Room 100 53 SF 6 6-10 years Floor Drain 1st- Unisex Inside Room 100 1 EA 7 6-10 years Layatory 1st- Unisex Inside Room 100 1 EA 6 6-10 years Lighting - Lay-in 1st- Unisex Inside Room 100 1 EA 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st- Unisex Inside Room 100 258 SF 6 6-10 years Water Closet 1st- Unisex Inside Room 100 258 SF 6 6-10 years Ceiling - Plaster/Drywall 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Doors - Wood Doors inclu hw 1st- Women's in Assembly Hall 2 EA 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby			
Doors - Wood Doors inclu hw Floor - Terrazzo Step - Unisex Inside Room 100 Step - Unisex Inside	illing - Lay-in 1st- Unisex Inside Room 100		
Floor - Terrazzo 1st- Unisex Inside Room 100 53 SF 6 6-10 years Floor Drain 1st- Unisex Inside Room 100 1 EA 7 6-10 years Lavatory 1st- Unisex Inside Room 100 1 EA 6 6-10 years Lighting - Lay-in 1st- Unisex Inside Room 100 1 EA 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st- Unisex Inside Room 100 258 SF 6 6-10 years Water Closet 1st- Unisex Inside Room 100 2 EA 7 6-10 years Ceiling - Plaster/Drywall 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Doors - Wood Doors inclu hw 1st- Women's in Assembly Hall 2 EA 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby			
Floor Drain Lavatory Lavatory Lighting - Lay-in Walls - Vinyl Coated Gypsum Panel St- Unisex Inside Room 100 1 EA 7 6-10 years Lighting - Lay-in St- Unisex Inside Room 100 1 EA 7 6-10 years Lighting - Lay-in St- Unisex Inside Room 100 1 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 2 EA 7 6-10 years St- Unisex Inside Room 100 3 EA 7 6-10 years St- Unisex Inside Room 100 3 EA 7 6-10 years St- Unisex Inside Room 100 4 EA 7 6-10 years St- Unisex Inside Room 100 5 EA 7 6-10 years St- Unisex Inside Room 100 5 EA 7 6-10 years St- Unisex Inside Room 100 5 EA 7 6-10 years St- Unisex Inside Room 100 5 EA 7 6-10 years St- Unisex Inside Room 100 5 EA 7 6-10 years St- Unisex Inside Room 100 5 EA 7 6-10	por - Terrazzo 1st- Unisex Inside Room 100		
Lavatory Lighting - Lay-in Sighting - Lay-in Sig	por Drain 1st- Unisex Inside Room 100		
Lighting - Lay-in 1st- Unisex Inside Room 100 1 EA 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st- Unisex Inside Room 100 258 SF 6 6-10 years Water Closet 1st- Unisex Inside Room 100 2 EA 7 6-10 years Ceiling - Plaster/Drywall 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Doors - Wood Doors inclu hw 1st- Women's in Assembly Hall 2 EA 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby			
Walls - Vinyl Coated Gypsum Panel 1st- Unisex Inside Room 100 258 SF 6 6-10 years Water Closet 1st- Unisex Inside Room 100 2 EA 7 6-10 years Ceiling - Plaster/Drywall 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Doors - Wood Doors inclu hw 1st- Women's in Assembly Hall 2 EA 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby			
Water Closet 1st- Unisex Inside Room 100 2 EA 7 6-10 years Ceiling - Plaster/Drywall 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby Doors - Wood Doors inclu hw 1st- Women's in Assembly Hall 2 EA 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby			
Ceiling - Plaster/Drywall 1st- Women's in Assembly Hall Lobby Doors - Wood Doors inclu hw 1st- Women's in Assembly Hall 2 EA 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby		· · · · · · · · · · · · · · · · · · ·	
Doors - Wood Doors inclu hw 1st- Women's in Assembly Hall 2 EA 6 6-10 years Lobby Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby	eiling - Plaster/Drywall 1st- Women's in Assembly Hall		
Floor - Terrazzo 1st- Women's in Assembly Hall 145 SF 6 6-10 years Lobby	ors - Wood Doors inclu hw 1st- Women's in Assembly Hall	2 EA 6 6-10 years	
	oor - Terrazzo 1st- Women's in Assembly Hall	45 SF 6 6-10 years	
Lobby	alls - Plaster/Drywall 1st- Women's in Assembly Hall	888 SF 6 6-10 years	
Water Closet 1st- Women's in Assembly Hall 1 EA 6 6-10 years Lobby	ater Closet 1st- Women's in Assembly Hall	1 EA 6 6-10 years	



Category : Room			Building : Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Accessories	2nd Floor	279	SF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	175	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	104	SF	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	279	SF	7	6-10 years		
	Floor Drain	2nd Floor	1	EA	7	6-10 years		
	Hand Dryer	2nd Floor	3	EA	7	6-10 years		
	Lavatory	2nd Floor	4	EA	7	6-10 years		
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years		
	Lighting - Lay-in	2nd Floor	4	EA	7	6-10 years		
	Partitions	2nd Floor	6	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	104	SF	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	705	SF	7	6-10 years		
	Water Closet	2nd Floor	6	EA	7	6-10 years		
	Accessories	2nd Floor	289	SF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	185	SF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	104	SF	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	289	SF	6	10+ years		
	Floor Drain	2nd Floor	1	EA	7	6-10 years		
	Hand Dryer	2nd Floor	1	EA	7	6-10 years		
	Lavatory	2nd Floor	4	EA	7	6-10 years		
	Lighting - Lay-in	2nd Floor	4	EA	7	6-10 years		
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years		
	Partitions	2nd Floor	2	EA	7	6-10 years		
	Urinals	2nd Floor	4	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	104	SF	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	727	SF	6	6-10 years		
	Water Closet	2nd Floor	2	EA	7	6-10 years		
	Accessories	2nd- Men's Staff RR	69	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd- Men's Staff RR	69	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd- Men's Staff RR	1	EA	6	6-10 years		
	Floor - Terrazzo	2nd- Men's Staff RR	69	SF	6	10+ years		
	Lavatory	2nd- Men's Staff RR	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	2nd- Men's Staff RR	1	EA	6	6-10 years		
	Lighting - Wall Mounted	2nd- Men's Staff RR	1	EA	6	6-10 years		
	Partitions	2nd- Men's Staff RR	2	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd- Men's Staff RR	298	SF	6	6-10 years		
	Water Closet	2nd- Men's Staff RR	2	EA	6	6-10 years		
	Accessories	2nd- Women's Staff RR	69	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd- Women's Staff RR	69	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd- Women's Staff RR	1	EA	6	6-10 years		
	Floor - Terrazzo	2nd- Women's Staff RR	69	SF	6	6-10 years		
	Lavatory	2nd- Women's Staff RR	1	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd- Women's Staff RR	1	EA	7	6-10 years		
	Lighting - Wall Mounted	2nd- Women's Staff RR	1	EA	7	6-10 years		
						•		

Campus Name: Bateman Page : 13 of 51 Assessment Date: 07/24/2023



Catego	ry : Room		В	_			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd- Women's Staff RR	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd- Women's Staff RR	298	SF	6	6-10 years	
	Water Closet	2nd- Women's Staff RR	2	EA	7	6-10 years	
	Accessories	3rd Floor	359	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	359	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	22	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	359	SF	6	6-10 years	
	Floor Drain	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	6-10 years	
	Urinals	3rd Floor	5	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	567	SF	6	2-5 years	
	Walls - Structural Glazed Tile	3rd Floor	557	SF	6	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor	10	SF	4	0-1 year	Missing tile
	Water Closet	3rd Floor	2	EA	6	6-10 years	
	Accessories	3rd Floor	359	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	359	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	22	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	359	SF	6	6-10 years	
	Floor Drain	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Partitions	3rd Floor	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	567	SF	6	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor	564	SF	6	6-10 years	
	Water Closet	3rd Floor	6	EA	7	6-10 years	
Catego	rv : Classroom		B	uildina	· Main		

Building : Main Category : Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #100 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,054	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	1,054	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,164	SF	6	6-10 years	
_Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	6-10 years	

Campus Name: Bateman Page : 14 of 51 Assessment Date: 07/24/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	747	SF	7	6-10 years	
	Doors - Transom Window	1st Floor	11	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	6-10 years	
	Floor - Wood	1st Floor	747	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,376	SF	7	6-10 years	
Classroc	om #102 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,065	SF	6	6-10 years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA		•	
				SF	6	6-10 years	
	Floor - Tile	1st Floor	1,065		6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	142	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,563	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	60	SF	4	0-1 year	Cracked
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroc	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EΑ	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	752	SF	6	6-10 years	
	Chalk Board	1st Floor	28	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	1st Floor	752	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,386	SF	6	6-10 years	
Classroc	om #107 (Regular Classroom)						
VIGSSIUU	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF CF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	759	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	759	SF	6	6-10 years	



Catego	ory : Classroom		В	uilding	: Main		•
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,383	SF	6	6-10 years	
Classro	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	746	SF	5	1-2 years	Pealing paint throughout
	Doors - Transom Window	1st Floor	11	SF	6	6-10 years	0.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	746	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,374	SF	6	6-10 years	
Classro	om #109 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	755	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	1st Floor	755	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,378	SF	6	6-10 years	
Classro	om #110 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	755	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	755	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Storage/ Closet	1st Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,370	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,370	SF	5	0-10 years 0-1 year	Damaged
	Work Sink	1st Floor	1	EA	7	6-10 years	Damaged
	WOIN SIIIN	131 1 1001	1	LA	,	0-10 years	



Catego	ry : Classroom		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group		Location	Quantity	UOIVI	Kalik	Replacement	Comments
Classroo	m #111 (Regular Classroom)	4-4-51			7	0.40	
	AC Units	1st Floor	1	EA LF	7	6-10 years	
	Casework	1st Floor	9	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	755	SF SF	6	6-10 years	
	Doors - Transom Window Doors - Wood Doors inclu hw	1st Floor 1st Floor	11	SF EA	6 6	6-10 years	
			1	SF	6	6-10 years	
	Floor - Wood	1st Floor 1st Floor	755	Sr EA	7	6-10 years	
	Lighting - Pendent/Surface Lighting - Pendent/Surface		13	EA	6	6-10 years	
	Marker Board	1st Floor 1st Floor	24	LF	7	6-10 years 6-10 years	
	Storage/ Closet	1st Floor	66	SF	7		
	Walls - Plaster/Drywall	1st Floor		SF	7	6-10 years	
	walls - Plaster/Drywall	1St Floor	1,378	5F	/	6-10 years	
Classroo	m #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	755	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	755	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,000	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	381	SF	4	0-1 year	Water damage
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	6	6-10 years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	740	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,353	SF	6	6-10 years	
Classroo	m #202 (Regular Classroom)						
Ciassioo		2nd Floor	4	ГΛ	7	6.10 years	
	AC Units	2nd Floor 2nd Floor	1	EA LF	7	6-10 years	
	Casework		9	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	753	SF	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	753	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,382	SF	6	6-10 years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	752	SF	6	6-10 years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
		2nd Floor		EA	6	-	
	Doors - Wood Doors inclu hw		1			6-10 years	
	Floor - Wood	2nd Floor	752	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,369	SF	6	6-10 years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,185	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	16	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	22	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	1,185	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EΑ	7	6-10 years	
	Marker Board	2nd Floor	23	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,607	SF	6	6-10 years	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,073	SF	6	6-10 years	
	Chalk Board	2nd Floor	23	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	6	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	22	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA SF	6	6-10 years	
	Floor - Wood	2nd Floor	1,073	SE	6	6-10 years	



Category : Classroom Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	23	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,647	SF	6	6-10 years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	753	SF	6	6-10 years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	753	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor		SF	6		
	Walls - Plaster/Drywall	2110 F1001	1,375	SF	б	6-10 years	
Classroo	m #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	752	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	752	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	23	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,375	SF	6	6-10 years	
Classroo	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	740	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	23	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,359	SF	6	6-10 years 6-10 years	
	vvalis - Flastel/Diywall	Ζιία Γίου!	1,359	SF	O	0-10 years	
Classroo	m #209 (Regular Classroom)						

Campus Name: Bateman Page : 19 of 51 Assessment Date: 07/24/2023



Catego	ry : Classroom		В	uilding	: Main	.==	o Wittenmond Office 1, Onleago, 12 00010
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	755	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	755	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,378	SF	7	6-10 years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	755	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	755	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	38	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,378	SF	6	6-10 years	
	•		1,0.0	٠.	· ·	0 .0 ,00.0	
_Classroc	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	755	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	755	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,378	SF	6	6-10 years	
Classroo	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	755	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	755	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	



Category : Classroom		В					
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,378	SF	6	6-10 years	
Classroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	742	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	742	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,385	SF	6	6-10 years	
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	753	SF	6	6-10 years	Ceiling has been fixed
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	3rd Floor	736	SF	6	6-10 years	
	Floor - Tile	3rd Floor	17	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	6	6-10 years	- 11
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,382	SF	6	6-10 years	
Classroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	652	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	100	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	3.
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	752	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,381	SF	6	6-10 years	
Classroc	m #304 (Regular Classroom)						

Campus Name: Bateman Page : 21 of 51 Assessment Date: 07/24/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	2	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,002	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	100	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	16	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	22	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	3rd Floor	1,102	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,925	SF	7	6-10 years	
	Work Sink	3rd Floor	, 1	EA	7	6-10 years	
ssroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,158	SF	6	6-10 years	
	Doors - Side-lite	3rd Floor	16	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	22	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	1,158	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	38	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,850	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	64	SF	4	•	Water demage
	walls - Plastel/Drywall	310 11001	04	SF	4	0-1 year	Water damage
sroo	m #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	654	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	100	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	754	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,334	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	50	SF	5	0-1 year	Water damage



Category : Classroom		В	Building : Main				
						Recommend	
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	454	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	300	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	754	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,392	SF	6	6-10 years	
lassroc	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	742	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	742	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall		1,378	SF	6		
	walls - Plaster/Drywall	3rd Floor	1,376	SF	б	6-10 years	
lassroc	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	755	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	755	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,378	SF	6	10+ years	Water damage has been fixed
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	755	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood Doors Inclu hw	3rd Floor		SF	6	•	
	F1001 - VV00U	314 11001	755	ЭF	Ö	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		o w Month of MeE 1, officago, in coord
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,378	SF	6	6-10 years	
Classroo	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	755	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	746	SF	6	6-10 years	
	Floor - Tile	3rd Floor	9	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,378	SF	6	6-10 years	
Classroo	om #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	747	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	8	SF	5	0-1 year	Pealing plaster
	Doors - Transom Window	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	6-10 years	
	Floor - Wood	3rd Floor	755	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	66	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,378	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	5	0-1 year	Water damage
Classroo	om #401 (Office)						
	AC Units	Mezzanine	1	EA	7	6-10 years	
	Casework	Mezzanine	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Mezzanine	306	SF	6	6-10 years	Water damage has been fixed
	Chalk Board	Mezzanine	8	LF	4	2-5 years	-
	Doors - Wood Doors inclu hw	Mezzanine	1	EA	6	6-10 years	
	Floor - Wood	Mezzanine	306	SF	6	6-10 years	
	Lighting - Pendent/Surface	Mezzanine	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	Mezzanine	987	SF	6	6-10 years	



Catego	Category : Interior			uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,356	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,061	SF	6	10+ years	
	Doors - Transom Window	1st Floor	179	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	11	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	8	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	5,932	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	6	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	362	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	27	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	2	EA	7	6-10 years	
	Stairs - Wood	1st Floor	10	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	9,020	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	7	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,283	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	5	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,820	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	98	SF	6	6-10 years	
	Doors - Wood Doors include hw	2nd Floor	4	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	3,974	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	7,388	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	5	0-1 year	Water damage
	Ceiling - Plaster/Drywall	3rd Floor	3,808	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	12	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	98	SF	6	6-10 years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	3,966	SF	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	3	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	19	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	279	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	7,434	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	6	6-10 years	
Safety							
	Camera Viewing Station	Entire building	2	EA	7	6-10 years	
	Security Cameras	Entire building	5	EA	7	6-10 years	
	Security Cameras	Entire building	5	EA	7	6-10 years	
	y		•	** *	-	,	



_	50010015					422	UN RICHMOND STREET, Chicago, IL 606
Catego	ry : Interior		В	uilding	: Main		
_			<u></u>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Stairs							
	Ceiling - Plaster/Drywall	North	498	SF	5	1-2 years	Peeling plaster throughout
	Floor - Tile	North	244	SF	6	6-10 years	
	Handrails	North	122	LF	7	6-10 years	
	Lighting - Pendent/Surface	North	6	EA	7	6-10 years	
	Stairs - Rubber	North	58	LF	6	6-10 years	
	Walls - Plaster/Drywall	North	3,023	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North Center Stairs	762	SF	6	6-10 years	
	Floor - Tile	North Center Stairs	1,067	SF	6	6-10 years	
	Handrails	North Center Stairs	141	LF	7	6-10 years	
	Lighting - Pendent/Surface	North Center Stairs	11	EA	7	6-10 years	
	Stairs - Rubber	North Center Stairs	86	LF	6	6-10 years	
	Walls - Plaster/Drywall	North Center Stairs	3,184	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	South	498	SF	6	6-10 years	
	Floor - Tile	South	244	SF	6	6-10 years	
	Handrails	South	122	LF	7	6-10 years	
	Lighting - Pendent/Surface	South	6	EA	7	6-10 years	
	Stairs - Rubber	South	58	LF	6	6-10 years	
	Walls - Plaster/Drywall	South	3,023	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	South Center Stairs	782	SF	6	6-10 years	
	Floor - Tile	South Center Stairs	1,067	SF	6	6-10 years	
	Handrails	South Center Stairs	141	LF	7	6-10 years	
	Lighting - Pendent/Surface	South Center Stairs	11	EA	7	6-10 years	
	Stairs - Rubber	South Center Stairs	66	LF	6	6-10 years	
	Walls - Plaster/Drywall	South Center Stairs	3,184	SF	6	6-10 years	
	•					•	



Category : Exterior **Building: Addition**

						Recommend	
р	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nce							
	Exterior Doors - Store Front	#10 - N	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#10 - N	2	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#11 - N	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#11.1 - Roof	1	EΑ	6	10+ years	
	Entrance Control - Audio and Video	#4 - E	1	EΑ	7	6-10 years	
	Exterior Doors - Store Front	#4 - E	2	EΑ	7	10+ years	
	Exterior Doors - Transom Lite	#4 - E	1	EA	7	6-10 years	
	Entrance Control - Audio and Video	#5 - SE	1	EΑ	6	6-10 years	
	Exterior Doors - Side lite	#5 - SE	2	EA	7	6-10 years	
	Exterior Doors - Store Front	#5 - SE	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#5 - SE	<u></u>	EΑ	7	6-10 years	
	Exterior Doors - Store Front	#6 - S	2	EΑ	7	10+ years	
	Exterior Doors - Transom Lite	#6 - S	2	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#7 - SW	_ 1	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8 - NW	2	ΕA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#9 - NW	2	EA	7	10+ years	
			_	_, ,	•	. o · you.o	
ndati	on						
	Foundation - Concrete	Entire Building	711	LF	7	10+ years	
	Superstructure - Steel	Entire Building	58,737	SF	7	10+ years	
		g		-		, , , , , , , , , , , , , , , , , , , ,	
nting							
J	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	6-10 years	
		Ŭ				•	
f Sys							
	Coping - Stone	Low NW roof	181	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low NW roof	144	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low NW roof	181	LF	6	10+ years	
	Roof - Modified Bitumen	Low NW roof	4,483	SF	4	1-2 years	Bubbles alligator cracks
	Roof Structure - Steel / Metal Deck/	Low NW roof	4,483	SF	7	10+ years	-
	Concrete Topping						
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Main Roof	25	LF	7	6-10 years	
	Coping - Stone	Main Roof	679	LF	6	2-5 years	
	Downspouts - Interior Downspouts	Main Roof	306	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	644	LF	6	10+ years	
	Parapet - Parapet > 30"	Main Roof	35	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	17,958	SF	4	1-2 years	Bubbling alligator cracks
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	and an experience
	Roof Structure - Steel / Metal Deck/	Main Roof	17,958	SF	7	10+ years	
	Concrete Topping		,500	<u> </u>	•	. c . youro	



Catego	ry : Exterior	В	uilding	: Additi	on		
		1	0	11014	D	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Walls							
vvans	Cornice - Cast Stone	Entire Building	711	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20.082	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	14,547	SF	7	10+ years	
	Exterior Wallo Storio Sast	Little Ballating	1 1,0 17	O.	•	To Tyouro	
Window	8						
	Curtain wall - Louver	Entire Building	200	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	972	SF	6	6-10 years	
	Lintels - Steel	Entire Building	418	LF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,072	SF	6	6-10 years	Recombined quantities
	·	· ·				•	·
Catego	ry : Electrical		В	uilding	: Additi	on	
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerge	ncy System						
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,813	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	4,107	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,245	SF	6	6-10 years	
	Automatic Transfer Switch	Entire Building	· 1	EA	7	10+ years	Serves Addition.
	Exit Signs - Corridors and Stairs	Entire Building	22	EA	6	6-10 years	Upgraded since last assessment; Rank, Reason and Priority Rep adjusted accordingly.
	Exit Signs - Multipurpose Room	Entire Building	3	EA	6	6-10 years	aujuotou aooo. ag.y.
	Security System - CCTV	Entire Building	58,757	SF	6	6-10 years	System upgraded since last assessment. Priority Rep adjusted accordingly.
	Security System - Intrusion Detection	Entire Building	58,757	SF	6	6-10 years	System upgraded since last assessment. Priority Rep adjusted accordingly.
Main Se	rvice						
_wan oc	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	58,757	SF	7	6-10 years	Served by Main. Overall system upgrade completed in October, 2022.
	Independent Electrical Service for emergency power	Entire Building	1	EA	7	10+ years	Serves Addition.
	Independent Electrical Service for emergency power	Entire Building	1	EA	7	10+ years	Serves the fire sprinkler system in Addition.

Campus Name: Bateman Page : 28 of 51 Assessment Date: 07/24/2023



Catego	ry : Electrical		В	uilding	: Addition		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ower D'	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	3rd Floor Mech. Room
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	2nd Floor Mech. Room
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	3rd floor electrical closet. Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	2nd floor electrical closet. Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	1st floor electrical closet.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	EM fuse panel. Open fuse receptacles expose live parts and present a live-front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	1st floor electrical closet.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	3rd Floor Mech. Room
Catego	ry : Fire Protection		В	uilding			
						Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar							
	Fire Alarm Strobe Lights	Entire Building	58,757	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	58,757	SF	6	2-5 years	
	Fire Pump Controller	Entire Building	1	EA	7	6-10 years	
ump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Plumbing Room	1	EA	6	6-10 years	
	Jockey Pump	Plumbing Room	1	EA	6	6-10 years	
prinkle	System						
	Sprinkler Heads	Entire Building	58,757	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	58,757	SF	7	6-10 years	
	Wet Sprinkler System	Entire Building	58,757	SF	7	6-10 years	
atego	ry : Mechanical		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	litioning						
ir Cond	morning	Roof					

Campus Name: Bateman Page : 29 of 51 Assessment Date: 07/24/2023



Category : Mechanical			В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chiller-Air Cooled- Recipricating-Roof Mounted - 101 - 200 tons	Roof	1	EA	7	10+ years	
	Glycol Feed	Roof	1	EA	6	6-10 years	3rd Floor Mech. Room.
	Pipes - Chilled Water Pipe- Steel	Roof	200	LF	7	10+ years	
	Pressure Fill System	Roof	1	EA	6	6-10 years	3rd Floor Mech. Room.
Air Hand	ling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	2nd Floor Mechanical Room - AHU- 1	1	EA	6	6-10 years	2nd Floor Mech. Room. AHU-1 serves the first floor of Addition.
	Air Intake	2nd Floor Mechanical Room - AHU-	1	EA	6	6-10 years	
	Induction Fan	2nd Floor Mechanical Room - AHU-	1	EA	6	6-10 years	IF-1. 2nd Floor Mech. Room.
	VAV Box	2nd Floor Mechanical Room - AHU-	7	EA	6	6-10 years	Located above the suspended ceiling grid.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	2nd Floor Mechanical Room - AHU- 3	1	EA	6	10+ years	2nd Floor Mech. Room. AHU-3 serves kitchen and multipurpose room.
	Air Intake	2nd Floor Mechanical Room - AHU-	1	EA	6	6-10 years	Toom.
	Induction Fan	2nd Floor Mechanical Room - AHU-3	1	EA	6	6-10 years	IF-3. 2nd Floor Mech. Room.
	VAV Box	2nd Floor Mechanical Room - AHU-3	2	EA	6	6-10 years	Not directly accessible in a safe manner at the time of assessment due to the height of this equipment.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	3rd Floor Mechanical Room - AHU-2	1	EA	6	10+ years	3rd Floor Mech. Room
	Air Intake	3rd Floor Mechanical Room - AHU-2	1	EA	7	6-10 years	
	Induction Fan	3rd Floor Mechanical Room - AHU-2	1	EA	6	6-10 years	IF-2. 3rd Floor Mech. Room.
	VAV Box	3rd Floor Mechanical Room - AHU-2	11	EA	6	6-10 years	Located above the suspended ceiling grid.
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	4	EA	6	6-10 years	Served by AHU-3
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	6	EA	6	6-10 years	Served by AHU-1
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	18	EA	6	6-10 years	Served by AHU-2
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	2	EA	6	6-10 years	RF-1 and RF-3. 2nd Floor Mech. Room.
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-2. 3rd Floor Mech. Room. Quantity changed as total has been divided/aggregated.

Campus Name: Bateman Page : 30 of 51 Assessment Date: 07/24/2023



Catego	ry : Mechanical	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Make Up Air Unit- Roof Mounted- Electric Coils - Less than 6000 cfm	Roof	1	EA	5	2-5 years	No CPS Asset Tag present on the unit at the time of assessment.
Boiler Sy	vstems						
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	3rd Floor	3	EA	6	6-10 years	3rd Floor Mech. Room.
	Chemical Pot Feeder	3rd Floor	1	EA	5	2-5 years	3rd Floor Mech. Room.
	Combustion Dampers	3rd Floor	3	EA	6	10+ years	3rd Floor Mech. Room.
	Glycol Feed System	3rd Floor	1	EΑ	6	6-10 years	3rd Floor Mech. Room.
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	3rd Floor	1	EA	6	6-10 years	B-1. 3rd Floor Mech. Room. Boilers undergoing seasonal maintenance protocol at the time of assessment and do not require major repairs;
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	3rd Floor	1	EA	6	6-10 years	Rank adjusted accordingly. B-3. 3rd Floor Mech. Room. Boilers undergoing seasonal maintenance protocol at the time of assessment and do not require major repairs; Rank adjusted accordingly.
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	3rd Floor	1	EA	6	6-10 years	B-2. 3rd Floor Mech. Room. Boilers undergoing seasonal maintenance protocol at the time of assessment and do not require major repairs; Rank adjusted accordingly.
	Water Fill System	3rd Floor	1	EA	6	6-10 years	3rd Floor Mech. Room.
Heating I	Devices						
	Unit Heater - Electric	Entire Building	1	EA	7	6-10 years	
	Unit Heater - Hot Water	Entire Building	3	EA	6	6-10 years	3rd Floor Mech. Room. Location and quantity changed based on current observations. Quantity changed as the total has been divided/aggregated.
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	2nd Floor Mech. Room
	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	6	6-10 years	Quantity changed based on current observations.
	Radiator Panels - Hot Water	Entire Building	19	EA	6	6-10 years	observations.
Mechani	cal Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	600	LF	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	300	LF	7	10+ years	Item Type changed to match current observations.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	2nd Floor Mech. Room. Recirculating

Campus Name: Bateman Page : 31 of 51 Assessment Date: 07/24/2023



Catego	ry : Mechanical		B	uilding	: Additi	on	
						Recommend	
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							pump for AHU-3. CPS Asset Tag
							inaccessible at the time of
							assessment due to location on the AHU.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	3rd Floor Mech. Room. Dataplate
	That water i unip Less than 10	Weenanical Room		L/\	O	o io years	missing.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	3rd Floor Mech. Room. Recirculating
	, , , , , , , , , , , , , , , , , , , ,					, , , , , , ,	pump for AHU-2. CPS Asset Tag
							inaccessible at the time of
							assessment due to location on the
							AHU.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	3rd Floor Mech. Room.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	2nd Floor Mech. Room. Recirculating
							pump for AHU-1. CPS Asset Tag
							inaccessible at the time of
							assessment due to location on the AHU.
	Chilled Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	3rd Floor Mech. Room.
	Chilled Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	3rd Floor Mech. Room.
	Crimed Water Fump - Less man 10	Mechanical Room	1	LA	U	0-10 years	Sid i looi Mech. Room.
Tempera	ture Control						
•	DDC System	Entire Building	58,757	SF	7	6-10 years	
	Thermostats - DDC	Entire Building	48	EA	7	6-10 years	Quantity changed as total has been
							divided/aggregated, and adjusted to
							match the number of fan power boxes
							plus VAV boxes.
Ventilatio	nn						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	6-10 years	Missing pieces replaced since last
	CFM	Ğ				•	assessment. Cover is dented but
							otherwise the unit fully intact. Rank,
							Reason and Priority Rep adjusted
					_		based on current observations.
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	3	EA	6	6-10 years	
	CFM	Fatina Deitsia a	4	_^	0	0.40	0
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Cover replaced since last assessment.
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	7	6-10 years	assessment.
	•	Zitaro Dananig				-	
Catego	ry : Plumbing		В	uilding	: Additi		
					.	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						



Catego	ry : Plumbing		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	2	EA	6	10+ years	3rd Floor Mech. Room. The return pump for 120-degree hot water is noisy. Water heater has been in service for five years; Rank has been adjusted to reflect the reduced EUL since the last assessment.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	58,757	SF	6	6-10 years	Some of the return piping shows signs of corrosion and missing insulation.
	Domestic Piping-Hot Water Return Risers	Entire Building	58,757	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	58,757	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	58,757	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	58,757	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	58,757	SF	6	6-10 years	
	Sanitary Piping	Entire Building	58,757	SF	6	6-10 years	
	Storm Piping	Entire Building	58,757	SF	6	6-10 years	
	Vent Piping	Entire Building	58,757	SF	6	6-10 years	
Pumps							
·	Pumps - Domestic Booster Pump-Duplex	Plumbing Room	1	EA	6	6-10 years	Booster pump is in good condition but has not been used for a few years and was not being used at the time of assessment; the Addition uses incoming city water pressure which is adequate for the building.

Category: Room **Building: Addition**

						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Administrative Suites/Offices								
	Ceiling - Lay-in	1st - Office next to west stairs (storage)	154	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st - Office next to west stairs (storage)	1	EA	6	6-10 years		
	Floor - Tile	1st - Office next to west stairs (storage)	154	SF	6	6-10 years		
	Lighting - Lay-in	1st - Office next to west stairs	1	EA	7	6-10 years		

Campus Name: Bateman Page : 33 of 51 Assessment Date: 07/24/2023



Category : Room			Building : Addition				
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		(storage)					
	Power Distribution	1st - Office next to west stairs	2	EA	6	6-10 years	
		(storage)			_		
	Walls - Concrete Block	1st - Office next to west stairs	323	SF	6	6-10 years	
	W II DI (/D II	(storage)	040	05	•	0.40	
	Walls - Plaster/Drywall	1st - Office next to west stairs	318	SF	6	6-10 years	
	Cailing Lavin	(storage)	604	SF	6	6.10	
	Ceiling - Lay-in Doors - Side-lite	1st- 120 Main Office 1st- 120 Main Office	694	SF SF	6	6-10 years	
	Doors - Side-life Doors - Wood Doors inclu hw		130	SF EA	6	6-10 years	
		1st- 120 Main Office 1st- 120 Main Office	2 694	SF	7	6-10 years	
	Floor - Carpet	1st- 120 Main Office	13	SF EA	6	6-10 years	
	Lighting - Lay-in Power Distribution			EA	7 6	6-10 years	
		1st- 120 Main Office	8	SF		6-10 years	
	Storage/ Closet	1st- 120 Main Office	17		7	6-10 years	
	Walls - Concrete Block	1st- 120 Main Office	992	SF SF	6	6-10 years	
	Walls - Plaster/Drywall	1st- 120 Main Office	1,075	SF SF	6	6-10 years	
	Ceiling - Lay-in	1st- 122 Nurse	133		6	6-10 years	
	Doors - Wood Doors inclu hw	1st- 122 Nurse	1	EA	6	6-10 years	
	Floor - Carpet	1st- 122 Nurse	133	SF	6	6-10 years	
	Lighting - Lay-in	1st- 122 Nurse	2	EΑ	7	6-10 years	
	Power Distribution	1st- 122 Nurse	8	EA	6	6-10 years	
	Walls - Concrete Block	1st- 122 Nurse	294	SF	6	2-5 years	
	Walls - Plaster/Drywall	1st- 122 Nurse	294	SF	5	6-10 years	
	Work SInk	1st- 122 Nurse	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st- 124 Faculty Lounge	412	SF	6	10+ years	
	Ceiling - Lay-in	1st- 124 Faculty Lounge	3	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st- 124 Faculty Lounge	1	EA	6	6-10 years	
	Floor - Carpet	1st- 124 Faculty Lounge	295	SF	6	6-10 years	
	Floor - Tile	1st- 124 Faculty Lounge	120	SF	6	6-10 years	
	Lighting - Lay-in	1st- 124 Faculty Lounge	6	EA	7	6-10 years	
	Power Distribution	1st- 124 Faculty Lounge	14	EA	6	6-10 years	
	Walls - Concrete Block	1st- 124 Faculty Lounge	1,070	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st- 124 Faculty Lounge	30	SF	6	6-10 years	
	Work SInk	1st- 124 Faculty Lounge	_1	EA	7	6-10 years	
	Ceiling - Lay-in	1st- Kitchen Office	54	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st- Kitchen Office	_1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st- Kitchen Office	54	SF	7	6-10 years	
	Lighting - Lay-in	1st- Kitchen Office	1	EA	7	6-10 years	
	Power Distribution	1st- Kitchen Office	2	EA	6	6-10 years	
	Walls - Concrete Block	1st- Kitchen Office	290	SF	6	6-10 years	
	Ceiling - Lay-in	1st- Principal	327	SF	6	6-10 years	
	Ceiling - Lay-in	1st- Principal	4	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st- Principal	1	EA	6	6-10 years	
	Floor - Carpet	1st- Principal	331	SF	6	6-10 years	

Campus Name: Bateman Page : 34 of 51 Assessment Date: 07/24/2023



Category : Room			Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	1st- Principal	4	EA	7	6-10 years		
	Power Distribution	1st- Principal	14	EA	6	6-10 years		
	Walls - Concrete Block	1st- Principal	369	SF	6	6-10 years		
	Walls - Plaster/Drywall	1st- Principal	650	SF	6	6-10 years		
	Ceiling - Lay-in	1st- Work Room inside Main Office	158	SF	6	6-10 years		
	Doors - Steel Doors incl hw	1st- Work Room inside Main Office	1	EA	6	6-10 years		
	Floor - Tile	1st- Work Room inside Main Office	158	SF	6	6-10 years		
	Lighting - Lay-in	1st- Work Room inside Main Office	4	EA	7	6-10 years		
	Power Distribution	1st- Work Room inside Main Office	4	EA	6	6-10 years		
	Walls - Concrete Block	1st- Work Room inside Main Office	631	SF	6	6-10 years		
	Work Sink	1st- Work Room inside Main Office	1	EA	7	6-10 years		
	Ceiling - Lay-in	2nd - Engineer Office at west end of corridor	417	SF	6	6-10 years		
	Ceiling - Lay-in	2nd - Engineer Office at west end of corridor	16	SF	5	1-2 years	Tiles missing	
	Doors - Wood Doors inclu hw	2nd - Engineer Office at west end of corridor	1	EA	6	6-10 years		
	Floor - Tile	2nd - Engineer Office at west end of corridor	433	SF	6	6-10 years		
	Lighting - Lay-in	2nd - Engineer Office at west end of corridor	2	EA	7	6-10 years		
	Power Distribution	2nd - Engineer Office at west end of corridor	14	EA	6	6-10 years		
	Walls - Concrete Block	2nd - Engineer Office at west end of corridor	869	SF	6	6-10 years		
	Ceiling - Lay-in	2nd- Office inside rm220	145	SF	6	6-10 years		
	Ceiling - Lay-in	2nd- Office inside rm220	3	SF	4	1-2 years	Water damage	
	Doors - Wood Doors inclu hw	2nd- Office inside rm220	1	EA	6	6-10 years	water damage	
	Floor - Tile	2nd- Office inside rm220	148	SF	6	6-10 years		
	Lighting - Lay-in	2nd- Office inside rm220	1	EA	7	6-10 years		
	Power Distribution	2nd- Office inside rm220	6	EΑ	6	6-10 years		
	Walls - Concrete Block	2nd- Office inside rm220	525	SF	6	6-10 years		
	Ceiling - Lay-in	2nd- Work room inside Library	135	SF	6	6-10 years		
	Ceiling - Lay-in	2nd- Work room inside Library	8	SF	4	1-2 years	Water damage	
	Doors - Wood Doors inclu hw	2nd- Work room inside Library	1	ĒΑ	6	6-10 years		
	Floor - Tile	2nd- Work room inside Library	143	SF	6	6-10 years		
	Lighting - Lay-in	2nd- Work room inside Library	2	EA	7	6-10 years		
	Power Distribution	2nd- Work room inside Library	6	EA	6	6-10 years		
	Walls - Concrete Block	2nd- Work room inside Library	155	SF	6	6-10 years		
	Walls - Plaster/Drywall	2nd- Work room inside Library	360	SF	6	6-10 years		
	Work SInk	2nd- Work room inside Library	1	EA	7	6-10 years		
	Ceiling - Lay-in	3rd - Ms. Kniffin Office / Storage	233	SF	6	6-10 years		
	Ceiling - Lay-in	3rd - Ms. Kniffin Office / Storage	10	SF	5	1-2 years	Water damage	
	Doors - Wood Doors inclu hw	3rd - Ms. Kniffin Office / Storage	1	EA	6	6-10 years	-	

Campus Name: Bateman Page : 35 of 51 Assessment Date: 07/24/2023



Category : Room			Building : Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	3rd - Ms. Kniffin Office / Storage	233	SF	6	6-10 years	
	Lighting - Lay-in	3rd - Ms. Kniffin Office / Storage	1	EA	7	6-10 years	
	Lighting - Lay-in	3rd - Ms. Kniffin Office / Storage	1	EA	6	1-2 years	Not working
	Power Distribution	3rd - Ms. Kniffin Office / Storage	2	EA	6	6-10 years	
	Walls - Concrete Block	3rd - Ms. Kniffin Office / Storage	606	SF	6	6-10 years	
_Kitchen							
TAILCHEIL	Ceiling - Lay-in	1st Floor	1,122	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,122	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	1,122	EA	7	6-10 years	
				SF	7		
	Storage/ Closet	1st Floor	134		=	6-10 years	
	Walls - Concrete Block	1st Floor	2,748	SF	6	6-10 years	
	Ceiling - Lay-in	1st- Dishwashing	155	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st- Dishwashing	1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st- Dishwashing	155	SF	7	6-10 years	
	Lighting - Lay-in	1st- Dishwashing	3	EA	7	6-10 years	
	Serving Line	1st- Dishwashing	8	LF	7	10+ years	
	Walls - Concrete Block	1st- Dishwashing	638	SF	6	6-10 years	
Library							
	Casework	2nd Floor	112	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	2,263	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	22	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	2,263	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	3	EA	6	1-2 years	Not working
	Storage/ Closet	2nd Floor	61	SF	7	6-10 years	Not working
	Walls - Concrete Block	2nd Floor	1,714	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	607	SF	6	6-10 years	
	Walls - Flastel/Drywall	ZIIG FIOOI	007	SI	0	0-10 years	
Lunch &	Multipurpose Room						
	Ceiling - Exposed	1st Floor	4,107	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	4,107	SF	7	6-10 years	
	Lighting - Metal Halide/ High Pressure	1st Floor	9	EA	7	6-10 years	
	Sodium					-	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Storage/ Closet	1st Floor	172	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	9,077	SF	6	6-10 years	
	Ceiling - Lay-in	1st- Serverie	888	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st- Serverie	5	EA	7	6-10 years	
			· ·	_, ,	•	3 .0 ,00.0	

Campus Name: Bateman Page : 36 of 51 Assessment Date: 07/24/2023



Category : Room			Building : Addition				
_			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Concrete Epoxy/ Painted	1st- Serverie	888	SF	7	6-10 years	
	Lighting - Lay-in	1st- Serverie	12	EA	7	6-10 years	
	Serving Line	1st- Serverie	57	LF	6	6-10 years	
	Walls - Concrete Block	1st- Serverie	1,489	SF	6	6-10 years	
MDF_ID	E						
<u> </u>	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	6-10 years	
	Finishes	2nd Floor	210	SF	7	6-10 years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	27	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	60	SF	7	6-10 years	
	Mechanical/ Service Rooms	1st Floor	88	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	43	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	359	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	217	SF	5	6-10 years	
	Storage Room	1st Floor		SF	7	•	
	•		80	SF SF		10+ years	
	Janitor's Closet	2nd Floor	27		5	6-10 years	
	Mechanical/ Service Rooms	2nd Floor	3,249	SF	5	6-10 years	
	Mechanical/ Service Rooms	2nd Floor	60	SF	5	6-10 years	
	Mechanical/ Service Rooms	2nd Floor	43	SF	5	6-10 years	
	Storage Room	2nd Floor	391	SF	7	6-10 years	
	Storage Room	2nd Floor	196	SF	7	6-10 years	
	Storage Room	2nd Floor	139	SF	7	6-10 years	
	Storage Room	2nd Floor	153	SF	7	6-10 years	
	Storage Room	2nd Floor	197	SF	5	6-10 years	
	Janitor's Closet	3rd Floor	27	SF	5	6-10 years	
	Mechanical/ Service Rooms	3rd Floor	43	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	60	SF	7	6-10 years	
	Mechanical/ Service Rooms	3rd Floor	3,249	SF	7	6-10 years	
	Storage Room	3rd Floor	153	SF	7	6-10 years	
	Storage Room	3rd Floor	198	SF	7	6-10 years	
	Storage Room	3rd Floor	148	SF	7	6-10 years	
	Storage Room	3rd Floor	195	SF	7	10+ years	
	Storage Room	3rd Floor	496	SF	7	•	
	Storage Room	314 [100]	490	Si	,	6-10 years	
Restroor							
	Accessories	1st - Boys Bath	207	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Boys Bath	207	SF	6	6-10 years	
	Floor - Terrazzo	1st - Boys Bath	207	SF	6	6-10 years	
	Floor Drain	1st - Boys Bath	2	EA	7	6-10 years	
	Hand Dryer	1st - Boys Bath	2	EA	7	6-10 years	
	Lavatory	1st - Boys Bath	3	EA	6	6-10 years	



Category : Room			Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	1st - Boys Bath	5	EA	7	6-10 years		
	Partitions	1st - Boys Bath	2	EA	7	6-10 years		
	Urinals	1st - Boys Bath	2	EA	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	1st - Boys Bath	594	SF	6	6-10 years		
	Water Closet	1st - Boys Bath	2	EA	6	6-10 years		
	Accessories	1st - Girls Bath	208	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st - Girls Bath	208	SF	6	6-10 years		
	Floor - Terrazzo	1st - Girls Bath	208	SF	6	6-10 years		
	Floor Drain	1st - Girls Bath	2	EA	7	6-10 years		
	Hand Dryer	1st - Girls Bath	2	EA	7	6-10 years		
	Lavatory	1st - Girls Bath	3	EA	6	6-10 years		
	Lighting - Lay-in	1st - Girls Bath	5	EA	7	6-10 years		
	Partitions	1st - Girls Bath	4	EA	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	1st - Girls Bath	593	SF	6	6-10 years		
	Water Closet	1st - Girls Bath	4	EA	6	6-10 years		
	Accessories	1st - Unisex Bath	42	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st - Unisex Bath	38	SF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st - Unisex Bath	4	SF	4	0-1 year	Hole	
	Doors - Wood Doors inclu hw	1st - Unisex Bath	1	EA	6	6-10 years		
	Floor - Terrazzo	1st - Unisex Bath	42	SF	6	6-10 years		
	Floor Drain	1st - Unisex Bath	1	EA	7	6-10 years		
	Lavatory	1st - Unisex Bath	1	EA	6	6-10 years		
	Lighting - Lay-in	1st - Unisex Bath	1	EA	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	1st - Unisex Bath	259	SF	6	6-10 years		
	Water Closet	1st - Unisex Bath	1	EA	6	6-10 years		
	Accessories	1st- Inside Rm 119	39	SF	7	6-10 years		
	Ceiling - Lay-in	1st- Inside Rm 119	39	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st- Inside Rm 119	1	EA	6	6-10 years		
	Floor - Terrazzo	1st- Inside Rm 119	39	SF	6	6-10 years		
	Floor Drain	1st- Inside Rm 119	1	EA	7	6-10 years		
	Lavatory	1st- Inside Rm 119	1	EA	6	6-10 years		
	Lighting - Lay-in	1st- Inside Rm 119	1	EA	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	1st- Inside Rm 119	250	SF	6	6-10 years		
	Water Closet	1st- Inside Rm 119	1	EA	6	6-10 years		
	Accessories	1st- Kitchen staff	36	SF	7	6-10 years		
	Ceiling - Lay-in	1st- Kitchen staff	36	SF	6	6-10 years		
	Doors - Steel Doors incl hw	1st- Kitchen staff	1	EA	6	6-10 years		
	Floor - Concrete Epoxy/ Painted	1st- Kitchen staff	36	SF	7	6-10 years		
	Floor Drain	1st- Kitchen staff	1	EA	7	6-10 years		
	Lavatory	1st- Kitchen staff	1	EA	6	6-10 years		
	Lighting - Lay-in	1st- Kitchen staff	1	EA	7	6-10 years		
	Walls - Concrete Block	1st- Kitchen staff	222	SF	6	6-10 years		
	Water Closet	1st- Kitchen staff	1	EA	6	6-10 years		
	Accessories	2nd - Boys Bath	207	SF	7	6-10 years		
		-				•		

Campus Name: Bateman Page : 38 of 51 Assessment Date: 07/24/2023



Category : Room			Building : Addition					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	2nd - Boys Bath	207	SF	6	6-10 years		
	Floor - Terrazzo	2nd - Boys Bath	207	SF	6	6-10 years		
	Floor Drain	2nd - Boys Bath	2	EA	7	6-10 years		
	Hand Dryer	2nd - Boys Bath	2	EA	7	6-10 years		
	Lavatory	2nd - Boys Bath	3	EA	6	6-10 years		
	Lighting - Lay-in	2nd - Boys Bath	5	EA	7	6-10 years		
	Partitions	2nd - Boys Bath	2	EA	7	6-10 years		
	Urinals	2nd - Boys Bath	2	EA	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd - Boys Bath	594	SF	6	6-10 years		
	Water Closet	2nd - Boys Bath	2	EA	6	6-10 years		
	Accessories	2nd - Girls Bath	208	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd - Girls Bath	208	SF	6	6-10 years		
	Floor - Terrazzo	2nd - Girls Bath	208	SF	6	6-10 years		
	Floor Drain	2nd - Girls Bath	2	EA	7	6-10 years		
	Hand Dryer	2nd - Girls Bath	2	EA	7	6-10 years		
	Lavatory	2nd - Girls Bath	3	EA	6	6-10 years		
	Lighting - Lay-in	2nd - Girls Bath	5	EA	7	6-10 years		
	Partitions	2nd - Girls Bath	4	EA	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd - Girls Bath	593	SF	6	6-10 years		
	Water Closet	2nd - Girls Bath	4	EA	6	6-10 years		
	Accessories	2nd - Unisex Bath	42	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd - Unisex Bath	36	SF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd - Unisex Bath	6	SF	5	1-2 years	Damaged, hole in ceiling	
	Doors - Wood Doors inclu hw	2nd - Unisex Bath	1	EA	6	6-10 years		
	Floor - Terrazzo	2nd - Unisex Bath	42	SF	6	6-10 years		
	Floor Drain	2nd - Unisex Bath	1	EA	7	6-10 years		
	Lavatory	2nd - Unisex Bath	1	EΑ	6	6-10 years		
	Lighting - Lay-in	2nd - Unisex Bath	1	EA	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd - Unisex Bath	259	SF	6	6-10 years		
	Water Closet	2nd - Unisex Bath	1	EA	7	6-10 years		
	Accessories	3rd - Boys Bath	207	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd - Boys Bath	207	SF	6	6-10 years		
	Floor - Terrazzo	3rd - Boys Bath	207	SF	6	6-10 years		
	Floor Drain	3rd - Boys Bath	2	EΑ	7	6-10 years		
	Hand Dryer	3rd - Boys Bath	2	EΑ	7	6-10 years		
	Lavatory	3rd - Boys Bath	3	EΑ	6	6-10 years		
	Lighting - Lay-in	3rd - Boys Bath	5	EΑ	7	6-10 years		
	Partitions	3rd - Boys Bath	2	EΑ	7	6-10 years		
	Urinals	3rd - Boys Bath	2	EA	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	3rd - Boys Bath	594	SF	6	6-10 years		
	Water Closet	3rd - Boys Bath	2	EA	6	6-10 years		
	Accessories	3rd - Girls Bath	208	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd - Girls Bath	208	SF	7	6-10 years		
	Floor - Terrazzo	3rd - Girls Bath	208	SF	7	6-10 years		

Campus Name: Bateman Page : 39 of 51 Assessment Date: 07/24/2023



Categor	ry : Room		В	uilding	: Addition	on	•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	3rd - Girls Bath	2	EA	7	6-10 years	
	Hand Dryer	3rd - Girls Bath	2	EA	7	6-10 years	
	Lavatory	3rd - Girls Bath	3	EA	6	6-10 years	
	Lighting - Lay-in	3rd - Girls Bath	5	EA	7	6-10 years	
	Partitions	3rd - Girls Bath	4	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	3rd - Girls Bath	593	SF	6	6-10 years	
	Water Closet	3rd - Girls Bath	4	EA	6	6-10 years	
	Accessories	3rd - Unisex Bath	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd - Unisex Bath	42	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd - Unisex Bath	1	EA	6	6-10 years	
	Floor - Terrazzo	3rd - Unisex Bath	42	SF	7	6-10 years	
	Floor Drain	3rd - Unisex Bath	1	EA	7	6-10 years	
	Lavatory	3rd - Unisex Bath	1	EA	7	6-10 years	
	Lighting - Lay-in	3rd - Unisex Bath	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	3rd - Unisex Bath	259	SF	6	6-10 years	
	Water Closet	3rd - Unisex Bath	1	ĒΑ	6	6-10 years	
					_	,	
Categor	ry : Classroom		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classrooi	m #114 (Store Room)						
	Ceiling - Lay-in	1st Floor	393	SF	6	6-10 years	
	Chalk Board	1st Floor	22	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	393	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	681	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	338	SF	6	6-10 years	
Classrooi	m #118 (Special Program)						
	Ceiling - Lay-in	1st Floor	1,000	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	20	SF	4	1-2 years	Water stains
	Chalk Board	1st Floor	11	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	22	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	6-10 years	
	Floor - Tile	1st Floor	1,020	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	580	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	675	SF	7	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #119 (Pre School)						



Catego	ry : Classroom		В	uilding	: Additi		o w Merimona o Meet, omeago, ie ooo to
3						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	1,051	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	16	SF	4	1-2 years	Water damage
	Doors - Side-lite	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	6-10 years	
	Floor - Tile	1st Floor	1,067	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,656	SF	6	6-10 years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	om #126 (Pre School)						
	Casework	1st Floor	39	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	910	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	5	SF	4	0-1 year	Water stains
	Doors - Side-lite	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	915	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,406	SF	7	6-10 years	
	Work Sink	1st Floor	1,400	EA	7	6-10 years	
Classroo	om #128 (Music Room)						
	Ceiling - Lay-in	1st Floor	1,016	SF	6	6-10 years	
	Doors - Side-lite	1st Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,010	SF	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	6	SF	4	2-5 years	Broken and chipped tile
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	Brokeri and chipped tile
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	155	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,036	SF	6	6-10 years	
				SF SF	6	•	
	Walls - Plaster/Drywall	1st Floor	420	SF	О	6-10 years	
Classroo	om #220 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	1,043	SF	6	2-5 years	144
	Ceiling - Lay-in	2nd Floor	10	SF	5	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	1,053	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	6	1-2 years	No working
	Marker Board	2nd Floor	24	LF	7	6-10 years	



Catego	ry : Classroom	Building : Addition					
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	725	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	599	SF	6	6-10 years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroo	om #224 (Kindergarten)						
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	857	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Missing tiles and water stains
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	865	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	10+ years	
	Walls - Concrete Block	2nd Floor	620	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	583	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #226 (Special Program)						
JIASSIUC	Casework	2nd Floor	14	LF	6	6-10 years	
	Casework Ceiling - Lay-in	2nd Floor	448	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	1-2 years	Water stains
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	Water Stairis
	Doors - Side-lite Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	464	SF	6	6-10 years	
		2nd Floor 2nd Floor		EA	7		
	Lighting - Lay-in Marker Board	2nd Floor	6 22	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor 2nd Floor	644	SF	<i>7</i> 6	6-10 years	
						6-10 years	Orogles in annuable of
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor 2nd Floor	4 262	SF SF	6 6	1-2 years 6-10 years	Cracks in cmu block
	walls - Flaster/Drywall	2110 1 1001	202	OI .	U	0-10 years	
Classroc	om #227 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	432	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	-
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	432	SF	6	6-10 years	
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Broken and cracked tiles
	Lighting - Lay-in	2nd Floor	6	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	572	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	319	SF	6	6-10 years	



Catego	Category : Classroom		Building : Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #228 (Science Classroom)						
	Casework	2nd Floor	101	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,021	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	1,021	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	139	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,205	SF	7	6-10 years	
	Work Sink	2nd Floor	3	EA	7	6-10 years	
Classroo	om #314 (Regular Classroom)						
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	865	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	6	SF	5	1-2 years	Tiles out of place
	Doors - Side-lite	3rd Floor	11	SF	6	6-10 years	Those out or place
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	865	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	10+ years	
	Walls - Concrete Block	3rd Floor	620	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	583	SF	6	6-10 years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #316 (Regular Classroom)						
Oldboroo	Casework	3rd Floor	39	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	857	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	6	SF	5	1-2 years	Tile out of place
	Ceiling - Lay-in	3rd Floor	2	SF	5	1-2 years	Water damaged
	Doors - Side-lite	3rd Floor	11	SF	6	6-10 years	vvater damaged
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	865	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	620	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	583	SF	6	6-10 years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #318 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	835	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	16	SF	5	1-2 years	Tiles out of place
	coming Lay iii	2110 1 1001	10	01	0	1 2 yours	out of place



	ry : Classroom	Building : Addition					
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	14	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	865	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	620	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	583	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7		
	WORK SILIK	211d F1001	ı	EA	,	6-10 years	
Classro	om #320 (Special Program)						
	Ceiling - Lay-in	3rd Floor	401	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	14	SF	4	1-2 years	Water damage
	Doors - Side-lite	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	415	SF	6	6-10 years	
		3rd Floor	6	EA	7	•	
	Lighting - Lay-in			LF		6-10 years	
	Marker Board	3rd Floor	24		7	6-10 years	
	Walls - Concrete Block	3rd Floor	452	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	452	SF	6	6-10 years	
Classro	om #322 (Regular Classroom)						
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	865	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	4	SF	4	1-2 years	Water damage
	Doors - Side-lite	3rd Floor	11	SF	6		water damage
				Sr EA	-	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1		6	6-10 years	
	Floor - Tile	3rd Floor	865	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	4	1-2 years	No working
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	620	SF	6	6-10 years	
			620				
	Walls - Concrete Block Walls - Plaster/Drywall Work Sink	3rd Floor 3rd Floor 3rd Floor		SF SF EA	6 6 7	6-10 years 6-10 years 6-10 years	
Classro	Walls - Plaster/Drywall Work Sink	3rd Floor	620 583	SF	6	6-10 years	
Classroo	Walls - Plaster/Drywall Work Sink om #324 (Regular Classroom)	3rd Floor 3rd Floor	620 583 1	SF EA	6 7	6-10 years 6-10 years	
Classroo	Walls - Plaster/Drywall Work Sink om #324 (Regular Classroom) Casework	3rd Floor 3rd Floor 3rd Floor	620 583 1	SF EA LF	6 7 7	6-10 years 6-10 years 6-10 years	
Classroo	Walls - Plaster/Drywall Work Sink om #324 (Regular Classroom) Casework Ceiling - Lay-in	3rd Floor 3rd Floor 3rd Floor 3rd Floor	620 583 1 10 865	SF EA LF SF	6 7 7 7	6-10 years 6-10 years 6-10 years 10+ years	
Classroo	Walls - Plaster/Drywall Work Sink om #324 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	620 583 1 10 865 11	SF EA LF SF SF	7 7 7 7	6-10 years 6-10 years 6-10 years 10+ years 10+ years	
Classroo	Walls - Plaster/Drywall Work Sink om #324 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	620 583 1 10 865 11 1	SF EA LF SF SF EA	6 7 7 7 7 7 6	6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years	
Classroo	Walls - Plaster/Drywall Work Sink om #324 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite	3rd Floor	620 583 1 10 865 11	SF EA LF SF SF EA SF	7 7 7 7	6-10 years 6-10 years 6-10 years 10+ years 10+ years	
Classroo	Walls - Plaster/Drywall Work Sink om #324 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	620 583 1 10 865 11 1	SF EA LF SF SF EA	6 7 7 7 7 7 6	6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years	



Catego	Category : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	3rd Floor	620	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	583	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #326 (Regular Classroom)						
	Casework	3rd Floor	15	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	465	SF	6	6-10 years	
	Doors - Side-lite	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	455	SF	6	6-10 years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Broken and damaged tile
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	2. onon and damaged me
	Marker Board	3rd Floor	20	LF	7	10+ years	
	Walls - Concrete Block	3rd Floor	580	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	265	SF	6	6-10 years	
	•	014 1 1001	200	O.	Ū	o royouro	
Classroo	om #327 (Office)	0.15	4.5			0.40	
	Casework	3rd Floor	15	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	455	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	1-2 years	Water damage
	Doors - Side-lite	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	463	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	6	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	585	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	312	SF	6	6-10 years	
Classroo	om #328 (Science Classroom)						
	Casework	3rd Floor	26	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,023	SF	6	6-10 years	
	Doors - Side-lite	3rd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	1,000	SF	6	6-10 years	
	Floor - Tile/Sheet	3rd Floor	23	SF	4	0-1 year	Gaps in structural floooring
	Lighting - Lay-in	3rd Floor	12	ĒA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	154	SF	5	6-10 years	
	Walls - Concrete Block	3rd Floor	1,203	SF	6	6-10 years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Catego	ry : Interior		В	uilding	: Additi	on	
	Item - Type	Location	Quantity	UOM	Rank		Comments
J. Jup		2000.011	Quantity		Haint	. toooond	C C



						Replacement	
Corridor							
	Ceiling - Lay-in	1st Floor	2,114	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	373	SF	6	6-10 years	
	Doors - Side-lite	1st Floor	38	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	6-10 years	
	Doors - Store Front	1st Floor	1	EΑ	6	6-10 years	
	Doors - Wood Doors include hw	1st Floor	1	EΑ	6	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	2	EΑ	7	6-10 years	
	Floor - Terrazzo	1st Floor	2,487	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	49	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	1	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	7,996	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,287	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	1-2 years	Water damage loose tiles
	Ceiling - Lay-in Ceiling - Plaster/Drywall	2nd Floor	137	SF	6	6-10 years	Water damage 1003e tiles
	Doors - Wood Doors include hw	2nd Floor	5	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor 2nd Floor	3,440	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	30	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	60	EA	6	1-2 years	Not working
	Student Lockers - One Tier	2nd Floor	22	EA	6	6-10 years	Not working
	Walls - Concrete Block	2nd Floor	4,071	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	3,260	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	3,260	SF	5	1-2 years	Ceiling tile out of place
	Ceiling - Lay-in		10	SF	5 5		
	Ceiling - Lay-in Ceiling - Plaster/Drywall	3rd Floor 3rd Floor	137	SF	5 6	1-2 years 6-10 years	Water damage
	Doors - Steel Doors incl hw			SF EA	-		
		3rd Floor	5		6 7	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor	2 440	EA	-	6-10 years	
	Floor - Terrazzo	3rd Floor	3,440	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	30	EΑ	7	6-10 years	Linkto above la deservação ao est
	Lighting - Lay-in	3rd Floor	60	EA	6	1-2 years	Lights above lockers are no on, not
	0: 1 :1 1 0 T	0 15	450	_ ^	•	0.40	sure if they are in operational
	Student Lockers - One Tier	3rd Floor	153	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	4,071	SF	6	6-10 years	
_Safetv							
Carety	Camera Viewing Station	Entire building	2	EA	7	6-10 years	
	Security Cameras	Entire building	_ 5	EΑ	7	6-10 years	
	Security Cameras	Entire building	6	EA	7	6-10 years	
	Coounty Camerao	g	•		-	0 .0 you.o	
Stairs							
	Ceiling - Lay-in	East	519	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	East	94	SF	6	6-10 years	
	Floor - Terrazzo	East	723	SF	6	6-10 years	
	Handrails	East	168	LF	7	6-10 years	



					Replacement	
Lighting - Lay-in	East	10	EΑ	7	6-10 years	
Lighting - Wall Mounted	East	2	EA	7	6-10 years	
Stairs - Terrazzo	East	67	LF	6	6-10 years	
Walls - Concrete Block	East	2,782	SF	6	6-10 years	
Ceiling - Lay-in	West	519	SF	6	6-10 years	
Ceiling - Plaster/Drywall	West	94	SF	6	6-10 years	
Floor - Terrazzo	West	723	SF	6	6-10 years	
Handrails	West	168	LF	7	6-10 years	
Lighting - Lay-in	West	7	EA	7	6-10 years	
Lighting - Lay-in	West	3	EA	6	1-2 years	No working
Lighting - Wall Mounted	West	2	EA	7	6-10 years	
Stairs - Terrazzo	West	67	LF	6	6-10 years	
Walls - Concrete Block	West	2,782	SF	6	6-10 years	
Vertical Conveyance						
Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	





Category: Site **Building: Site**

Categor	y : Site			ullaing	. Site		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Metal Bleachers	South	40	LF	6	2-5 years	
	Surface - Synthetic	South	5,629	SF	7	6-10 years	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	13	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	18	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	6	10+ years	
	on a contract of					, , , , , , , , , , , , , , , , , , , ,	
encing							
	Fencing - Chain Link	Entire Site	260	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,134	LF	7	10+ years	
on do oor	20						
_andscap	Benches	Entire Site	2	EA	6	10+ years	
	Landscape - Grass	Entire Site	7,165	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	6,525	SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	3,636	SF	6	10+ years	
	Landscape - Mulch	Entire Site	5,302	SF	7	10+ years	
	Landscape - Poured Rubber Surface	Entire Site	7,670	SF	6	10+ years	Corrected quantity
	Parkway trees	Entire Site	21	ĒΑ	6	10+ years	consolica quantity
	Parkway trees	Entire Site	2	EA	4	1-2 years	Missing
	Planting Beds/ Area	Entire Site	6,015	SF	7	10+ years	9
	Retaining Wall - Concrete	Entire Site	430	SF	6	2-5 years	
	Retaining Wall - Masonry	Entire Site	588	SF	6	2-5 years	
	Trash Receptacles	Entire Site	2	ĒΑ	7	10+ years	
						•	
Parking L	Lighting - Lighting	NW site	11		7	6-10 years	
	Surface - Asphalt	NW site	16,149	EA SF	6	10+ years	
	Surface - Asphalt	NW site	2,000	SF SF	4	0-1 years	Potholes
	Surface - Aspiralit Surface - Concrete	NW site	800	SF	7	6-10 years	rotifoles
	Vehicular Screening	NW site	60	LF	6	10+ years	
	Verlicular Screening	NVV Site	00	LI	O	10+ years	
Playgrou	nd						
	Equipment - School Age 5-12	South	1	EA	7	6-10 years	
	Surface - Poured Surface	South	2,100	SF	7	6-10 years	Corrected quantity
	Surface - Poured Surface	South	50	SF	5	0-1 year	Corrected quantity, damage, missir sections
Sidewalk	S						



Category : Site			В	uilding	: Site	, , , , , , , , , , , , , , , , , , , ,	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	564	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	13,945	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	5	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	5	1-2 years	Displacement
Signage							
0 0	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	10+ years	
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Building Mounted Back Lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-	
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board	
Building : Main										
Art Room	Kindergarten	1st Floor	100	100	1,054	160	84	N	N	
Kindergarten	Kindergarten	1st Floor	109	109	755	136	64	N	N	
Kindergarten	Kindergarten	1st Floor	110	110	755	136	64	N	Υ	
Kindergarten	Laboratory/Shop	1st Floor	102	102	1,065	215	70	N	N	
Office	Regular Classroom	Mezzanine	401	401	306	62	24	N	N	
Regular Classroom	Regular Classroom	1st Floor	101	101	747	172	56	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	106	106	752	172	56	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	107	107	759	172	56	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	108	105	746	172	56	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	111	111	755	136	64	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	112	112	755	136	64	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	201	201	740	172	56	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	202	202	753	172	56	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	203	203	752	172	56	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	204	204	1,185	172	56	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	205	205	1,073	172	56	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	206	206	753	172	56	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	207	207	752	172	56	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	208	208	740	172	56	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	209	209	755	136	64	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	210	210	755	136	64	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	211	211	755	136	64	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	212	212	755	136	64	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	301	301	742	172	56	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	302	302	753	172	56	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	303	303	752	172	56	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	304	304	1,102	172	56	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	305	305	1,158	136	64	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	306	306	754	172	56	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	307	307	754	172	56	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	308	308	742	172	56	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	309	309	755	136	64	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	310	310	755	136	64	N	Y	
Regular Classroom	Regular Classroom	3rd Floor	311	311	755	136	64	N	Y	
Regular Classroom	Regular Classroom	3rd Floor	312	312	755	174	56	N	Υ	
Building : Addition										
Computer Lab	Computer Lab	2nd Floor	220		1,053	125	56	N	N	





Classroom Summary

,			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Kindergarten	Regular Classroom	2nd Floor	224		865	99	45	N	Υ
Music Room	Music Room	1st Floor	128	-	1,016	150	50	Ν	N
Office	Special Program	3rd Floor	327	-	463	50	16	Ν	N
Pre School	Pre School	1st Floor	119		1,067	192	88	Ν	N
Pre School	Regular Classroom	1st Floor	126	-	915	106	34	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	227	-	436	50	16	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	318		865	118	52	Ν	Υ
Regular Classroom	Regular Classroom	3rd Floor	314		865	99	45	Ν	Υ
Regular Classroom	Regular Classroom	3rd Floor	316		865	99	45	Ν	Υ
Regular Classroom	Regular Classroom	3rd Floor	322		865	99	45	N	N
Regular Classroom	Regular Classroom	3rd Floor	324	324	865	99	45		
Regular Classroom	Regular Classroom	3rd Floor	326	324	465	50	16	N	Υ
Science Classroom	Science Classroom	2nd Floor	228	-	1,021	150	50	N	Υ
Science Classroom	Science Classroom	3rd Floor	328	-	1,023	150	50	N	Υ
Special Program	Special Program	1st Floor	118		1,020	200	100	N	N
Special Program	Special Program	2nd Floor	226	-	464	50	16	N	N
Special Program	Special Program	3rd Floor	320		415	59	26	N	N
Store Room	Regular Classroom	1st Floor	114		393	63	30	N	N

Campus Name: Bateman Page : 51 of 51 Assessment Date: 07/24/2023