

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1961	1	14,788
Addition	1995	1	23,160
Campus Total			37,948

Category: Exterior **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Entrance Exterior Doors - Exterior Steel Door 10 1 EΑ 6 10+ years Exterior Doors - Exterior Steel Door 7 1 EΑ 6 10+ years Ramp Handrail - Steel Ramp Handrail 7 10 LF 5 2-5 years Corroded, bent and unsecured really LF 5 Ramps - Concrete 7 12 0-1 year Large gap, large cracks Exterior Doors - Exterior Steel Door 8 EΑ 2-5 years Engineer reports that this door is 1 warped. It has been shaved off several times and it still does not close properly. FΑ Entrance Control - Audio and Video 9 10+ years 1 6 Exterior Doors - Exterior Steel Door 9 2 FΑ 6 10+ years Exterior Doors - Transom Lite 1 EΑ 6 10+ years Exterior Doors - Exterior Steel Door Mechanical Room 1 EΑ 6 10+ years Exterior Doors - Transom Lite 10+ years Mechanical Room 1 EΑ 6 Exterior Doors - Exterior Steel Door Storage Room EΑ 6 10+ years LF Ramps - Concrete Storage Room 6 6 10+ years Foundation Foundation - Concrete **Entire Building** 634 LF 7 10+ years Foundation - Concrete **Entire Building** 1 LF 5 1-2 years Broken concrete with exposed reinforcement SF 7 Superstructure - Metal Deck/ Concrete **Entire Building** 14.788 10+ years **Topping**

Campus Name: Blair Page : 1 of 26 Assessment Date: 09/19/2023



Lighting Ext Ext Ext Acc	terior Lighting - Wall Mounted cess Ladder - Metal imney - Brick Chimney- Concrete/ Mortar	Entire Building Entire Building Entire Building Roof A	Quantity 1 1 3	UOM EA EA EA	Rank 7 5 5	Recommend Replacement 10+ years 0-1 year	Comments Burnt out cover, obsolete light
Lighting Ext Ext Ext Acc Chi	terior Lighting - Wall Mounted terior Lighting - Wall Mounted terior Lighting - Wall Mounted cess Ladder - Metal imney - Brick Chimney- Concrete/ Mortar	Entire Building Entire Building Entire Building	1 1	EA EA	7 5	10+ years 0-1 year	
Ext Ext Ext Roof System Acc Chi	terior Lighting - Wall Mounted terior Lighting - Wall Mounted cess Ladder - Metal imney - Brick Chimney- Concrete/ Mortar	Entire Building Entire Building Roof A	1	EA	5	0-1 year	Burnt out cover, obsolete light
Ext Ext Ext Roof System Acc Chi	terior Lighting - Wall Mounted terior Lighting - Wall Mounted cess Ladder - Metal imney - Brick Chimney- Concrete/ Mortar	Entire Building Entire Building Roof A	1	EA	5	0-1 year	Burnt out cover, obsolete light
Ext Ext _Roof System_ Acc Chi	terior Lighting - Wall Mounted terior Lighting - Wall Mounted cess Ladder - Metal imney - Brick Chimney- Concrete/ Mortar	Entire Building Entire Building Roof A	•			0-1 year	Burnt out cover, obsolete light
Roof System Acc Chi	terior Lighting - Wall Mounted cess Ladder - Metal imney - Brick Chimney- Concrete/ Mortar	Entire Building Roof A	3				
Acc Chi	imney - Brick Chimney- Concrete/ Mortar				-	2-5 years	, ,
Acc Chi	imney - Brick Chimney- Concrete/ Mortar						
Chi	imney - Brick Chimney- Concrete/ Mortar		2	EA	7	10+ years	
	•	Roof A	12	LF	, 5	6-10 years	
	ei	KOOI A	12	LF	5	6-10 years	
Chi Line	imney - Brick Chimney- Concrete/ Mortar	Roof A	2	LF	3	1-2 years	Cracked, broken concrete cap
	imney - Brick Chimney- Stainless Steel	Roof A	13	LF	6	10+ years	
Line	•	NOOLA	13	Li	O	10+ years	
Cop	ping - Metal	Roof A	478	LF	6	10+ years	
Do	wnspouts - Interior Downspouts	Roof A	60	LF	6	10+ years	
Roo	of - Modified Bitumen	Roof A	12,812	SF	4	1-2 years	Blistering, soft spots throughout, ponding
Roo	of Hatch - Metal	Roof A	1	EA	3	2-5 years	Corroding hatch
	of Structure - Steel / Metal Deck/	Roof A	12,812	SF	7	10+ years	Corroding rictors
	ncrete Topping		,-	-	•	, , , , , , , , , , , , , , , , , , , ,	
	ping - Stone	Roof B	180	LF	6	10+ years	
	wnspouts - Interior Downspouts	Roof B	20	LF	6	10+ years	
	rapet - Parapet < 16" Height	Roof B	180	LF	6	10+ years	
	of - Modified Bitumen	Roof B	1,976	SF	4	1-2 years	Blistering, soft spots throughout
Roo	of Structure - Steel / Metal Deck/	Roof B	1,976	SF	7	10+ years	3, 1
Cor	ncrete Topping		,			,	
_Walls							
	nopy - Concrete/ Stucco	Entire Building	635	SF	6	10+ years	
	terior Walls - Brick	Entire Building	4,869	SF	6	10+ years	
\\ <i>\\</i> ;							
_Windows		E 0 D 3 P				40	
	ard - Guards perforated	Entire Building	681	SF	7	10+ years	
	tels - Steel	Entire Building	452	LF	6	10+ years	
	ndows - Insulated Panel	Entire Building	375	SF	6	10+ years	
	ndows - Louver	Entire Building	120	SF	6	10+ years	English and an english to the control of
VVir	ndows - Sash Aluminum Double-pane	Entire Building	2,908	SF	4	2-5 years	Engineer report that the windows are cracking at the sashes, there have been many repairs with wood putty



Catego	ry : Electrical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Exit Signs - Corridors and Stairs	Corridors and Stairs	2	EA	4	2-5 years	Over 20 years old with incandesce bulbs
	Emergency A/C Power - Corridors and Stairs	Corridors and Stairs	1,763	SF	6	6-10 years	
	Security System - CCTV	Entire Building	14,788	SF	5	2-5 years	
	Security System - Intrusion Detection	Entire Building	14,788	SF	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Student Toilets	2	EA	7	10+ years	
Main Se	rvice						
	PA System	Entire Building	14,788	SF	6	2-5 years	
ower D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	14,788	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	14,788	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy							
	Boiler Auxiliary- Condensing Hot Water - 500 - 1000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	2-5 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	
	Condensing- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	2	EA	6	10+ years	
	Water Fill System	Boiler Room	1	EA	6	6-10 years	
-leating	Devices						
3	Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	6	6-10 years	



Catego	ry : Mechanical		В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	10+ years	
Tempera	ature Control						
•	DDC System	Entire Building	14,788	SF	5	2-5 years	
	Thermostats - DDC	Entire Building	13	EA	6	2-5 years	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	Entire Building	13	EA	6	2-5 years	
Ventilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	1	EA	5	2-5 years	

Category: Plumbing

Building: Main

Category : Flumbing		<u> </u>	unung	. Iviaiii			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	14,788	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	14,788	SF	6	6-10 years	
	Sanitary Piping	Entire Building	14,788	SF	6	6-10 years	
	Storm Piping	Entire Building	14,788	SF	6	6-10 years	
	Vent Piping	Entire Building	14,788	SF	6	6-10 years	
	Vent Piping	Entire Building	14,788	SF	6	6-10 years	





Catego	ry : Room		В	uilding	: Main		6751 W 65IU FLACE, CHICAGO, IL 60656
Jaiogo						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Splined	102 C - Teacher's Lounge	327	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	102 C - Teacher's Lounge	1	EA	6	6-10 years	
	Floor - Carpet	102 C - Teacher's Lounge	285	SF	6	6-10 years	
	Floor - Tile	102 C - Teacher's Lounge	42	SF	7	6-10 years	
	Lighting - Pendent/Surface	102 C - Teacher's Lounge	5	ĒΑ	6	6-10 years	
	Power Distribution	102 C - Teacher's Lounge	6	ΕA	6	6-10 years	
	Walls - Concrete Block	102 C - Teacher's Lounge	756	SF	6	6-10 years	
	Ceiling - Splined	102A	494	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	102A	2	ĒΑ	6	6-10 years	
	Floor - Tile	102A	494	SF	6	6-10 years	
	Lighting - Pendent/Surface	102A	9	EA	6	6-10 years	
	Power Distribution	102A	8	EA	6	6-10 years	
	Storage/ Closet	102A	72	SF	7	6-10 years	
	Walls - Concrete Block	102A	1,000	SF	6	6-10 years	
	Ceiling - Splined	Engineer's Office	195	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EΑ	6	6-10 years	
	Floor - Tile	Engineer's Office	195	SF	7	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office	2	EA	7	6-10 years	
	Walls - Concrete Block	Engineer's Office	560	SF	7	6-10 years	
	Work SInk	Engineer's Office	1	EA	7	10+ years	
	Ceiling - Splined	Nurse's Office 102B	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Nurse's Office 102B	1	EA	6	6-10 years	
	Floor - Tile	Nurse's Office 102B	56	SF	7	6-10 years	
	Lighting - Pendent/Surface	Nurse's Office 102B	1	EA	6	6-10 years	
	Storage/ Closet	Nurse's Office 102B	20	SF	7	10+ years	
	Walls - Concrete Block	Nurse's Office 102B	288	SF	6	6-10 years	
Lunch 8	Multipurpose Room						
_LUIICII X	Ceiling - Splined	Therapy Room 99	1 700	SF	6	6 10 vooro	
	Doors - Steel Doors incl hw	Therapy Room 99 Therapy Room 99	1,780 4	SF EA	6 6	6-10 years 6-10 years	
	Doors - Wood Doors inclu hw	Therapy Room 99	6	EA	6	6-10 years	
	Floor - Tile	Therapy Room 99	1,780	SF	6	6-10 years	
	Lighting - Pendent/Surface	Therapy Room 99 Therapy Room 99	1,760	EA	6	6-10 years	
	Storage/ Closet	Therapy Room 99	88 88	SF	7	6-10 years	
	Walls - Concrete Block	Therapy Room 99	1,245	SF	7	10+ years	
	Walls - Structural Glazed Tile	Therapy Room 99	1,245	SF	7	10+ years	
	Walls - Structural Glazed Tile	merapy Room 99	1,243	31	,	10+ years	
_Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	600	SF	5	6-10 years	
	Janitor's Closet	1st Floor	25	SF	5	6-10 years	
	Storage Room	1st Floor	90	SF	7	10+ years	
	Vaults	1st Floor	60	SF	7	10+ years	
						-	





atego	ry : Room		R	uilding	· Main		6751 W 63rd PLACE, Chicago, IL 60
alogo	. y . 1.00iii			ananig	· wan	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
up		2004	quantity	00	rtaint	rtopiacomont	
estroor	m						
	Accessories	100	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	100	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	100	1	EA	6	6-10 years	
	Floor - Tile	100	30	SF	6	6-10 years	
	Lavatory	100	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	100	1	EA	6	6-10 years	
	Walls - Concrete Block	100	176	SF	6	10+ years	
	Water Closet	100	1	ĒΑ	6	6-10 years	
	Accessories	102 B	56	SF	7	10+ years	
	Ceiling - Plaster/Drywall	102 B	56	SF	6	10+ years	
	Doors - Wood Doors inclu hw	102 B	1	EA	6	10+ years	
	Floor - Tile	102 B	56	SF	6	10+ years	
	Lavatory	102 B	1	EA	6	10+ years	
	Lighting - Pendent/Surface	102 B	1	EΑ	6	10+ years	
	Partitions	102 B	1	EA	7	10+ years	
	Walls - Concrete Block	102 B	240	SF	6	10+ years	
	Water Closet	102 B	1	EA	6	10+ years	
	Accessories	102 C	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	102 C	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	102 C	1	EA	6	6-10 years	
	Floor - Tile	102 C	56	SF	7	6-10 years	
	Lavatory	102 C	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	102 C 102 C	1	EA	6	6-10 years	
	Walls - Concrete Block	102 C	270	SF	6	•	
	Water Closet	102 C		EA	6	6-10 years 6-10 years	
	Accessories	Boys 122	1 410	SF	7		
		DOYS 122		SF SF		6-10 years	
	Ceiling - Plaster/Drywall	Boys 122	410		6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Boys 122	410	SF	6	6-10 years	
	Floor Drain	Boys 122	1	EΑ	7	6-10 years	
	Lavatory	Boys 122	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Boys 122	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Boys 122	1	EΑ	6	6-10 years	
	Partitions	Boys 122	2	EA	7	6-10 years	
	Urinals	Boys 122	1	EA	6	6-10 years	
	Walls - Concrete Block	Boys 122	240	SF	6	10+ years	
	Walls - Structural Glazed Tile	Boys 122	630	SF	6	10+ years	
	Water Closet	Boys 122	2	EA	6	6-10 years	
	Accessories	Girls 125	410	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls 125	410	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Girls 125	410	SF	7	6-10 years	
	Floor Drain	Girls 125	1	EA	7	6-10 years	
	Lavatory	Girls 125	3	EA	6	6-10 years	





Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Girls 125	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Girls 125	1	EA	6	6-10 years	
	Partitions	Girls 125	3	EA	7	6-10 years	
	Walls - Concrete Block	Girls 125	240	SF	6	6-10 years	
	Walls - Structural Glazed Tile	Girls 125	630	SF	6	6-10 years	
	Water Closet	Girls 125	3	EA	6	10+ years	
	Accessories	Mechanical Room (Engineer's Restroom)	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Mechanical Room (Engineer's Restroom)	35	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Mechanical Room (Engineer's Restroom)	1	EA	6	6-10 years	
	Floor - Tile	Mechanical Room (Engineer's Restroom)	35	SF	7	6-10 years	
	Lavatory	Mechanical Room (Engineer's Restroom)	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Mechanical Room (Engineer's Restroom)	1	EA	6	6-10 years	
	Walls - Concrete Block	Mechanical Room (Engineer's Restroom)	240	SF	6	6-10 years	
	Water Closet	Mechanical Room (Engineer's Restroom)	1	EA	6	6-10 years	
	Accessories	Unisex 123	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex 123	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Unisex 123	1	EA	6	6-10 years	
	Floor - Tile	Unisex 123	30	SF	6	6-10 years	
	Hand Dryer	Unisex 123	1	EA	7	6-10 years	
	Lavatory	Unisex 123	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Unisex 123	1	EA	6	6-10 years	
	Walls - Concrete Block	Unisex 123	176	SF	7	6-10 years	
	Water Closet	Unisex 123	1	EA	6	6-10 years	

Category : Classroom

Building: Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	om #100 (Kindergarten)	Location	Quantity	COM	Rank	Replacement	Comments
_ CIASSION	Casework	1st Floor	35	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	1,100	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,100	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	19	EA	6	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,385	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	





Catego	ory : Classroom		В	uilding			
			_	9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	•		•			•	
Classroo	om #102D (Other Instructional Use)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	404	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Carpet	1st Floor	404	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	640	SF	7	6-10 years	
Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	848	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	10	SF	5	1-2 years	Water staimed
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	858	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	910	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #104 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	858	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	1st Floor	858	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	974	SF	6	6-10 years	
	Work Sink	1st Floor	1	ĒΑ	7	6-10 years	
Classroo	om #105 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	858	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
		1st Floor	858	SF	7	6-10 years	
	Floor - Tile	13(1100)		-			
		1st Floor	12	EA	6	6-10 vears	
	Lighting - Pendent/Surface	1st Floor			6 7	6-10 years 6-10 years	
			12	EA SF SF	_	6-10 years 6-10 years 10+ years	



Catago	ry : Classroom		D	uilding	· Main		•
Calego	ry . Classicolli		В	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	m #106 (Regular Classroom)			• • • • • • • • • • • • • • • • • • • •			
21000	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	858	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	000	EA	6	6-10 years	
	Floor - Tile	1st Floor	758	SF	6	6-10 years	
	Floor - Tile	1st Floor	100	SF	5	1-2 years	Disjointed, stained, and chipping
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	Disjointed, stained, and chipping
	Storage/ Closet	1st Floor	40	SF	7	•	
	Walls - Concrete Block	1st Floor	974	SF	6	6-10 years 6-10 years	
	Work Sink	1st Floor	9/4	EA	7	6-10 years	
	WOIR SIIIR	1st Floor	1	LA	,	0-10 years	
lassroo	m #107 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	858	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	6-10 years	
	Floor - Tile	1st Floor	858	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	974	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroo	m #108 (Regular Classroom)						
1000100	Casework	1st Floor	25	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	858	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	858	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	0-1 year	Re-lamp fixture
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	Tto lamp lixture
	Walls - Concrete Block	1st Floor	974	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
atogo	ry : Interior		B	uilding	· Main		
alogo	, , , , , , , , , , , , , , , , , , ,			anding	. wan	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Splined	1st Floor	1,698	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	30	SF	4	1-2 years	Missing tiles
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	6-10 years	Quantity updated to match current observations
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,728	SF	7	6-10 years	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	3,264	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Vestibule #109	35	SF	5	1-2 years	Water damage and missing tiles
	Doors - Steel Doors incl hw	Vestibule #109	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Vestibule #109	35	SF	7	10+ years	
	Lighting - Pendent/Surface	Vestibule #109	1	EA	6	6-10 years	
	Walls - Masonry	Vestibule #109	9	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule 101	120	SF	7	10+ years	
	Doors - Steel Doors incl hw	Vestibule 101	2	EA	7	10+ years	
	Floor - Tile/Sheet	Vestibule 101	120	SF	7	6-10 years	
	Lighting - Lay-in	Vestibule 101	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Vestibule 101	210	SF	7	10+ years	
_Safetv							
	Camera Viewing Station	engineers office	1	EA	7	6-10 years	

Campus Name: Blair Page : 10 of 26 Assessment Date: 09/19/2023



Category : Exterior Building : Addition

atego	ry : Exterior		В	unung	: Additio	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•		Location	Quantity	UOIVI	Naiik	Replacement	Comments
trance						40	
	Entrance Control - Audio and Video	1	1	EA	6	10+ years	
	Exterior Doors - Store Front	1	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	1	1	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	2	1	EΑ	6	10+ years	
	Entrance Control - Audio and Video	3	1	EΑ	6	10+ years	
	Exterior Doors - Side lite	3	2	EA	6	10+ years	
	Exterior Doors - Store Front	3	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	3	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	4	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	5 - Mechanical	1	EA	6	6-10 years	
	Exterior Doors - Store Front	6	1	EA	4	1-2 years	Engineer reports that this store is warped. It has been shaved off several times and it still does not close properly.only one door seen this location
	Exterior Doors - Transom Lite	6	1	EA	6	10+ years	Only one door and one transom a this location
	Exterior Doors - Exterior Steel Door	Yard Storage	2	EA	6	6-10 years	
undati	on						
	Foundation - Concrete	Entire Building	650	LF	7	10+ years	
	Foundation - Concrete	Entire Building	70	LF	5	1-2 years	Settlement toward the street side
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	23,160	SF	7	10+ years	the addition, interior wall cracks
nting_							
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	5	2-5 years	
of Sys	tem						
-	Coping - Metal	Roof C	101	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof C	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof C	43	LF	6	10+ years	
	Roof - Modified Bitumen	Roof C	1,247	SF	4	1-2 years	Blistering, soft spots throughout
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof C	1,247	SF	7	10+ years	
	Access Ladder - Metal	Roof D	1	EA	7	10+ years	
		Roof D	5	LF	6	10+ years	
	Chimney - Metal Flue						
	Chimney - Metal Flue Coping - Metal		666	LF	6	10+ vears	
	Chimney - Metal Flue Coping - Metal Downspouts - Interior Downspouts	Roof D Roof D	666 72	LF LF	6 6	10+ years 10+ years	

Campus Name: Blair Page : 11 of 26 Assessment Date: 09/19/2023



Catego	ry : Exterior		В	uilding	: Additi	on	
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Hatch - Metal	Roof D	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof D	21,853	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	Roof E	60	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof E	2	LF	6	10+ years	
	Roof - Modified Bitumen	Roof E	60	SF	4	0-1 year	Ponding, blistering
	Roof Structure - Steel / Metal Deck/	Roof E	60	SF	7	10+ years	
	Concrete Topping						
Walls							
	Canopy - Concrete/ Stucco	Entire Building	109	SF	7	10+ years	
	Canopy - Fabric	Entire Building	200	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	7,367	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	5	1-2 years	Deteriorated sealant at control joints
	Exterior Walls - Concrete Block	Entire Building	720	SF	6	10+ years	,
_Windows	3						
	Guard - Guards perforated	Entire Building	930	SF	7	10+ years	
	Lintels - Steel	Entire Building	410	LF	6	10+ years	
	Storefront Windows	Entire Building	280	SF	6	10+ years	
	Windows - Louver	Entire Building	30	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,247	SF	4	2-5 years	Engineer report that the windows are cracking at the sashes, there have been many repairs with wood putty

Category : Electrical **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	2-5 years	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	1	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,001	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,123	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,050	SF	6	6-10 years	
	Security System - CCTV	Entire Building	23,160	SF	5	2-5 years	
	Security System - Intrusion Detection	Entire Building	23,160	SF	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	10+ years	

Campus Name: Blair Page : 12 of 26 Assessment Date: 09/19/2023



Catego	ry : Electrical		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	120/208/3PH						
	Independent Electrical Service for	Electrical Room	1	EA	7	6-10 years	
	emergency power						
	PA System	Entire Building	23,160	SF	6	6-10 years	
_Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	6-10 years	

Category: Fire Protection

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar	,						
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	23,160 23,160	SF SF	7 6	6-10 years 6-10 years	
Sprinkle	r System						
•	Sprinkler Heads Sprinkler Piping Wet Sprinkler System	Entire Building Entire Building Entire Building	23,160 23,160 23,160	SF SF SF	7 6 6	6-10 years 6-10 years 6-10 years	

Building: Addition

Building: Addition

Category : Mechanical

	. ,		_	۳ه9		•	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litioning						
	Chiller-Air Cooled- Recipricating-Roof Mounted - 50 - 100 tons	Roof	1	EA	4	1-2 years	Over 20 years old with compressors and piping corroding, running often and loudly
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	
Air Hand	lling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Less than 4000 cfm	Office Above Ceiling	1	EA	5	6-10 years	
	Air Intake	Office Above Ceiling	1	EA	5	2-5 years	
Boiler S	vstems						
	Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH	Boiler Room	2	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	

Campus Name: Blair Page : 13 of 26 Assessment Date: 09/19/2023



Catego	ry : Mechanical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	6	6-10 years	
leating	Devices						
	Unit Heater - Hot Water	Boiler Room	1	EA	6	6-10 years	
	Fin Tube - Hot Water	Entire Building	156	LF	6	6-10 years	
Mechani	cal Plumbing						
	Chilled Water Pump - Less than 10	Boiler Room	1	EA	6	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	2-5 years	
	Hydronic Supply and Return - Steel	Entire Building	400	LF	5	2-5 years	
Tempera	ture Control						
	Electric Controls	Entire Building	23,160	SF	5	2-5 years	
	Electric Thermostat - DDC	Entire Building	6	EA	5	2-5 years	For Air Handler
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water & Chilled Water Coils	Entire Building	11	EA	6	2-5 years	
	Unit Ventilators- Ceiling Mounted- Hot Water & Chilled Water Coils	Kitchen	1	EA	4	1-2 years	Current observations based off last assessment
√entilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	4	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	5	2-5 years	
	Roof Mounted Duct Work	Roof	30	LF	5	2-5 years	
Catego	ry : Plumbing	Building : Addition					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ot Wate			•			•	
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	7	10+ years	

Campus Name: Blair Page : 14 of 26 Assessment Date: 09/19/2023





Catego	ry : Plumbing	Вι					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	23,160	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	23,160	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	23,160	SF	6	6-10 years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	23,160	SF	6	6-10 years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	23,160	SF	6	6-10 years	
	(Risers)				_		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	23,160	SF	6	6-10 years	
	(from Risers to Fixtures)				_		
	Sanitary Piping	Entire Building	23,160	SF	6	6-10 years	
	Storm Piping	Entire Building	23,160	SF	6	6-10 years	
	Vent Piping	Entire Building	23,160	SF	6	6-10 years	

Category: Room **Building: Addition**

ategory . Room			Building . Addition					
					Recommend			
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
rative Suites/Offices								
Ceiling - Lay-in	104 - Main Office	507	SF	6	6-10 years			
Doors - Wood Doors inclu hw	104 - Main Office	1	EA	6	6-10 years			
Floor - Tile	104 - Main Office	507	SF	6	6-10 years			
Lighting - Lay-in	104 - Main Office	8	EA	6	6-10 years			
Power Distribution	104 - Main Office	10	EA	6	6-10 years			
Walls - Concrete Block	104 - Main Office	468	SF	6	10+ years			
Walls - Concrete Block	104 - Main Office	60	SF	6	10+ years			
Ceiling - Lay-in	Assistant Principal - 110	172	SF	6	10+ years			
Ceiling - Lay-in	Assistant Principal - 110	8	SF	4	1-2 years	Water damage		
Doors - Wood Doors inclu hw	Assistant Principal - 110	1	EA	6	10+ years			
Floor - Carpet	Assistant Principal - 110	180	SF	6	6-10 years			
Lighting - Lay-in	Assistant Principal - 110	2	EA	6	10+ years			
Power Distribution	Assistant Principal - 110	4		6	10+ years			
Walls - Concrete Block	Assistant Principal - 110	432		6	10+ years			
Ceiling - Lay-in	Counsel 113	84	SF	7	10+ years			
Doors - Wood Doors inclu hw	Counsel 113	1	EA	6	6-10 years			
Floor - Tile	Counsel 113	84	SF	7	6-10 years			
Lighting - Lay-in	Counsel 113	1		6	10+ years			
Power Distribution	Counsel 113	2	EA	7	6-10 years			
Walls - Concrete Block	Counsel 113	342	SF	7	6-10 years			
Ceiling - Lay-in	Faculty Lounge - Room 107	450	SF	6	6-10 years			
Doors - Wood Doors inclu hw	Faculty Lounge - Room 107	1		6	6-10 years			
Floor - Tile	Faculty Lounge - Room 107	450	SF	7	6-10 years			
Lighting - Lay-in	Faculty Lounge - Room 107	6	EA	6	6-10 years			
Power Distribution	Faculty Lounge - Room 107	6	EA	6	6-10 years			
	Item - Type Trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Concrete Block Walls - Concrete Block Ceiling - Lay-in Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in Power Distribution Walls - Concrete Block Ceiling - Lay-in Power Distribution Walls - Concrete Block Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Concrete Block Ceiling - Lay-in Power Distribution Walls - Concrete Block Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	Item - Type Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Poors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Poors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Poors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in Lighting - Lay-in Power Distribution Assistant Principal - 110 Ceiling - Lay-in Assistant Principal - 110 Assistant Principal - 110 Assistant Principal - 110 Coursel 113 Counsel 113 Counsel 113 Lighting - Lay-in Counsel 113 Counsel 13 Counsel 10 Counsel 113 Counsel	Item - Type Location Quantity Trative Suites/Offices Ceiling - Lay-in 104 - Main Office 507 Doors - Wood Doors inclu hw 104 - Main Office 507 Lighting - Lay-in 104 - Main Office 507 Lighting - Lay-in 104 - Main Office 8 Power Distribution 104 - Main Office 100 Walls - Concrete Block 104 - Main Office 468 Walls - Concrete Block 104 - Main Office 600 Ceiling - Lay-in Assistant Principal - 110 172 Ceiling - Lay-in Assistant Principal - 110 172 Ceiling - Lay-in Assistant Principal - 110 172 Ceiling - Lay-in Assistant Principal - 110 180 Lighting - Lay-in Assistant Principal - 110 180 Lighting - Lay-in Assistant Principal - 110 180 Lighting - Lay-in Assistant Principal - 110 4 Walls - Concrete Block Assistant Principal - 110 4 Walls - Concrete Block Assistant Principal - 110 4 Walls - Concrete Block Counsel 113 184 Lighting - Lay-in Counsel 113 184 Lighting - Lay-in Counsel 113 19 Power Distribution Counsel 113 19 Walls - Concrete Block Counsel 113 19 Walls - Concrete Block Counsel 113 19 Walls - Concrete Block Counsel 113 19 Power Distribution Faculty Lounge - Room 107 19 Poors - Wood Doors inclu hw Faculty Lounge - Room 107 19 Foor - Tile Faculty Lounge - Room 107 450 Lighting - Lay-in Faculty Lounge - Room 107 450 Lighting - Lay-in Faculty Lounge - Room 107 450	Location	Location Quantity UOM Rank Italies Surative Suites Offices	Item - Type		

Campus Name: Blair Page : 15 of 26 Assessment Date: 09/19/2023





Catego	Category : Room		В	uilding	: Additi	on		
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	Faculty Lounge - Room 107	630	SF	6	6-10 years		
	Work SInk	Faculty Lounge - Room 107	1	EA	7	6-10 years		
	Ceiling - Lay-in	Principal's Office Room 106	210	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Principal's Office Room 106	1	EA	6	10+ years		
	Floor - Carpet	Principal's Office Room 106	210	SF	6	6-10 years		
	Lighting - Lay-in	Principal's Office Room 106	4	EΑ	6	10+ years		
	Power Distribution	Principal's Office Room 106	6	EΑ	7	10+ years		
	Walls - Concrete Block	Principal's Office Room 106	450	SF	7	10+ years		
	Ceiling - Lay-in	Vault/Storage - 109	170	SF	6	10+ years		
	Ceiling - Lay-in	Vault/Storage - 109	10	SF	4	1-2 years	Water damage	
	Doors - Steel Doors incl hw	Vault/Storage - 109	1	EA	6	10+ years		
	Floor - Tile	Vault/Storage - 109	180	SF	7	10+ years		
	Lighting - Lay-in	Vault/Storage - 109	4	EA	6	10+ years		
	Power Distribution	Vault/Storage - 109	2	EΑ	6	10+ years		
	Walls - Concrete Block	Vault/Storage - 109	432	SF	6	10+ years		
Kitchen								
	Ceiling - Lay-in	1st Floor	795	SF	7	6-10 years		
	Floor - Tile	1st Floor	795	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	10	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	900	SF	7	10+ years		
	Ceiling - Lay-in	Kitchen office (147) (storage)	98	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Kitchen office (147) (storage)	1	EA	7	6-10 years		
	Floor - Tile	Kitchen office (147) (storage)	98	SF	7	10+ years		
	Lighting - Lay-in	Kitchen office (147) (storage)	1	EΑ	7	10+ years		
	Walls - Concrete Block	Kitchen office (147) (storage)	336	SF	7	10+ years		
Locker/S	Shower Room							
	Ceiling - Plaster/Drywall	144	50	SF	7	10+ years		
	Doors - Wood Doors inclu hw	144	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	144	50	SF	7	6-10 years		
	Floor Drain	144	1	EA	7	10+ years		
	Lavatory	144	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	144	1	EΑ	7	10+ years		
	Showers	144	1	EA	7	10+ years		
	Walls - Concrete Block	144	174	SF	7	10+ years		
	Walls - Tile	144	66	SF	7	10+ years		
	Accessories	Shower / 132	35	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Shower / 132	35	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Shower / 132	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Shower / 132	35	SF	6	10+ years		
	Floor Drain	Shower / 132	2	EA	7	6-10 years		
	Lighting - Pendent/Surface	Shower / 132	1	EA	7	10+ years		
	Showers	Shower / 132	1	EA	7	10+ years		

Campus Name: Blair Page : 16 of 26 Assessment Date: 09/19/2023



outogo.	ry : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Concrete Block	Shower / 132	153	SF	6	10+ years			
	Walls - Tile	Shower / 132	63	SF	7	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Lay-in	110 A / 150	1,050	SF	7	10+ years			
	Doors - Wood Doors inclu hw	110 A / 150	2	EA	7	6-10 years			
	Floor - Tile	110 A / 150	1,050	SF	6	10+ years			
	Lighting - Lay-in	110 A / 150	15	ĒΑ	7	10+ years			
	Walls - Concrete Block	110 A / 150	890	SF	7	10+ years			
	Walls - Metal Panel	110 A / 150	24	SF	7	10+ years	Sliding panel.		
	Ceiling - Lay-in	110 B / 149	1,123	SF	7	10+ years	No max occupancy sign		
	Doors - Transom Window	110 B / 149	30	SF	7	6-10 years	140 max occupancy sign		
	Doors - Wood Doors inclu hw	110 B / 149	4	EA	7	6-10 years			
	Floor - Tile	110 B / 149	1,123	SF	7	10+ years			
	Lighting - Lay-in	110 B / 149 110 B / 149	1,123	EA	7	10+ years			
	Serving Line		_	LF					
		110 B / 149	10	SF	7	6-10 years			
	Storage/ Closet	110 B / 149	63		7	6-10 years			
	Walls - Concrete Block	110 B / 149	810	SF	7	10+ years			
	Walls - Metal Panel	110 B / 149	24	SF	7	10+ years	Sliding panel.		
MDF_IDE									
	Doors - Steel Doors incl hw	Mechanical Room	1	EA	7	10+ years			
	Doors - Wood Doors inclu hw	Mechanical Room	1	EA	7	10+ years			
	Finishes	Mechanical Room	120	SF	7	10+ years			
	Other Cooling Unit	Mechanical Room	1	EA	7	10+ years			
Mechanic	cal/ Service Rooms								
	Mechanical/ Service Rooms	1st Floor	768	SF	7	10+ years			
	Mechanical/ Service Rooms	Elect. Room	180	SF	7	10+ years			
	Janitor's Closet	Janitor's Closet	35	SF	7	10+ years			
	Storage Room	Outside Store Room	120	SF	7	10+ years			
	Storage Room	Storage 119	126	SF	7	10+ years			
	Storage Room	Storage 124	126	SF	7	10+ years			
	Clorage Noom	Otorage 124	120	Oi.	,	101 years			
Restroom									
	Accessories	114 / 128	40	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	114 / 128	40	SF	7	10+ years			
	Doors - Wood Doors inclu hw	114 / 128	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	114 / 128	40	SF	7	10+ years			
	Floor Drain	114 / 128	1	EA	7	10+ years			
	Lavatory	114 / 128	1	EA	7	10+ years			
	Lighting - Pendent/Surface	114 / 128	1	EA	7	10+ years			
	Walls - Concrete Block	114 / 128	208	SF	7	10+ years			

Campus Name: Blair Page : 17 of 26 Assessment Date: 09/19/2023



						Building : Addition						
					Recommend							
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments						
Water Closet	114 / 128	1	EA	4	1-2 years	Out of order per staff						
Accessories	117 / 121	40	SF	7	6-10 years							
Ceiling - Lay-in	117 / 121	40	SF	7	10+ years							
Doors - Wood Doors inclu hw		1	EA	7	10+ years							
Floor - Tile Ceramic/ Porcelai		40	SF	7	10+ years							
Floor Drain	117 / 121	1	EA	7	10+ years							
Lavatory	117 / 121	1	EA	7	10+ years							
Lighting - Lay-in	117 / 121	1	EA	7	10+ years							
Walls - Concrete Block	117 / 121	208	SF	7	10+ years							
Water Closet	117 / 121	1	EA	7	10+ years							
Accessories	119 / 120	40	SF	7	6-10 years							
Ceiling - Lay-in	119 / 120	40	SF	7	10+ years							
Doors - Wood Doors inclu hw	119 / 120	1	EA	7	6-10 years							
Floor - Tile Ceramic/ Porcelai		40	SF	7	10+ years							
Floor Drain	119 / 120	1	ĒΑ	7	6-10 years							
Lavatory	119 / 120	1	EA	7	6-10 years							
Lighting - Lay-in	119 / 120	1	EΑ	7	10+ years							
Walls - Concrete Block	119 / 120	208	SF	7	10+ years							
Water Closet	119 / 120	1	ĒΑ	7	6-10 years							
Accessories	Boys (134)	192	SF	7	6-10 years							
Ceiling - Lay-in	Boys (134)	192	SF	6	10+ years							
Doors - Wood Doors inclu hw		1	ĒΑ	6	6-10 years							
Floor - Tile Ceramic/ Porcelai	, , ,	192	SF	7	10+ years							
Floor Drain	Boys (134)	1	ĒΑ	7	6-10 years							
Lavatory	Boys (134)	2	EA	7	6-10 years							
Lighting - Lay-in	Boys (134)	3	EΑ	7	10+ years							
Partitions	Boys (134)	3	EΑ	7	6-10 years							
Urinals	Boys (134)	1	EΑ	7	6-10 years							
Walls - Concrete Block	Boys (134)	576	SF	7	10+ years							
Water Closet	Boys (134)	3	EA	7	6-10 years							
Accessories	Girls (135)	192	SF	7	6-10 years							
Ceiling - Lay-in	Girls (135)	192	SF	6	10+ years							
Doors - Wood Doors inclu hw		1	EA	7	6-10 years							
Floor - Tile Ceramic/ Porcelai		192	SF	7	10+ years							
Floor Drain	Girls (135)	1	EA	7	6-10 years							
Lavatory	Girls (135)	2	EΑ	7	6-10 years							
Lighting - Lay-in	Girls (135)	3	EΑ	7	10+ years							
Partitions	Girls (135)	3	EA	7	6-10 years							
Walls - Concrete Block	Girls (135)	576	SF	7	10+ years							
Water Closet	Girls (135)	3	EA	6	6-10 years							
Ceiling - Lay-in	Laundry Room	130	SF	7	10+ years							
Doors - Wood Doors inclu hw		130	EA	7	6-10 years							
Floor - Tile	Laundry Room	128	SF	7	10+ years							
Floor - Tile	Laundry Room	2	SF	5	1-2 years	Cracking and broken tiles around						
i iooi - i iic	Laundry Room	2	OI.	J	1-2 years	Cracking and broken thes around						

Campus Name: Blair Page : 18 of 26 Assessment Date: 09/19/2023



Catego	ry : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
					_		floor drain		
	Floor Drain	Laundry Room	1	EA	7	6-10 years			
	Lavatory	Laundry Room	1	EA	7	10+ years	Updated quantity		
	Lighting - Lay-in	Laundry Room	2	EA	7	10+ years			
	Walls - Concrete Block	Laundry Room	416	SF	7	10+ years			
	Accessories	Mechanical Room (Eng)	35	SF	7	6-10 years			
	Ceiling - Lay-in	Mechanical Room (Eng)	35	SF	7	10+ years			
	Doors - Hardware	Mechanical Room (Eng)	1	EA	4	0-1 year	Missing door handle		
	Doors - Wood Doors inclu hw	Mechanical Room (Eng)	1	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	Mechanical Room (Eng)	35	SF	7	10+ years			
	Floor Drain	Mechanical Room (Eng)	1	EA	7	6-10 years			
	Lavatory	Mechanical Room (Eng)	1	EA	7	6-10 years			
	Lighting - Lay-in	Mechanical Room (Eng)	1	EA	7	10+ years			
	Walls - Concrete Block	Mechanical Room (Eng)	192	SF	7	10+ years			
	Water Closet	Mechanical Room (Eng)	1	ĒΑ	7	10+ years			
	Accessories	Staff Unisex RR (111)	48	SF	7	6-10 years			
	Ceiling - Lay-in	Staff Unisex RR (111)	40	SF	6	6-10 years			
	Ceiling - Lay-in	Staff Unisex RR (111)	8	SF	4	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	Staff Unisex RR (111)	1	EA	6	10+ years	vvator damage		
	Floor - Tile	Staff Unisex RR (111)	48	SF	7	10+ years			
	Floor Drain	Staff Unisex RR (111)	1	EA	7	10+ years			
	Lavatory	Staff Unisex RR (111)	1	EA	7	6-10 years			
	Lighting - Lay-in	Staff Unisex RR (111)	1	EA	7	10+ years			
	Walls - Concrete Block	Staff Unisex RR (111)	224	SF	7	10+ years			
	Water Closet	Staff Unisex RR (111)	1	EA	7	-			
		` ,	48	SF	7	6-10 years			
	Accessories	Staff Unisex RR (112)	48	SF SF	7 7	6-10 years			
	Ceiling - Lay-in	Staff Unisex RR (112)		SF SF		6-10 years	Water dame as		
	Ceiling - Lay-in	Staff Unisex RR (112)	1		4	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	Staff Unisex RR (112)	1	EA	6	6-10 years			
	Floor - Tile	Staff Unisex RR (112)	48	SF	6	10+ years			
	Floor Drain	Staff Unisex RR (112)	1	EA	7	6-10 years			
	Lavatory	Staff Unisex RR (112)	1	EA	7	6-10 years			
	Lighting - Lay-in	Staff Unisex RR (112)	1	EA	7	10+ years			
	Walls - Concrete Block	Staff Unisex RR (112)	224	SF	7	10+ years			
	Water Closet	Staff Unisex RR (112)	1	EA	7	6-10 years			
	Accessories	Women's by 110C	107	SF	7	6-10 years			
	Ceiling - Lay-in	Women's by 110C	99	SF	7	10+ years			
	Ceiling - Lay-in	Women's by 110C	8	SF	4	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	Women's by 110C	2	EA	7	10+ years			
	Floor - Tile	Women's by 110C	72	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Women's by 110C	35	SF	6	10+ years			
	Floor Drain	Women's by 110C	1	EA	7	10+ years			
	Lavatory	Women's by 110C	1	EA	7	6-10 years			
	Lighting - Lay-in	Women's by 110C	2	EA	7	10+ years			

Campus Name: Blair Page : 19 of 26 Assessment Date: 09/19/2023



Category : Room	В	uilding	: Additi	on	
				Recommend	
Group Item - Type Location	Quantity	UOM	Rank	Replacement	Comments
Student Lockers - One Tier Women's by 110C	4	EA	7	10+ years	Updated quantity to reflect current observations
Walls - Concrete Block Women's by 110C	480	SF	7	10+ years	
Water Closet Women's by 110C	1	ĒΑ	7	6-10 years	
Category : Classroom	В	uilding	: Additi		
Group Item - Type Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #109 (Regular Classroom)	Quantity	OOM	Italik	Replacement	Comments
Casework 1st Floor	41	LF	7	6-10 years	
	1,050	SF	7		
				10+ years	
Doors - Wood Doors inclu hw 1st Floor	2	EA	7	6-10 years	
Floor - Tile 1st Floor	1,050	SF	7	10+ years	
Lighting - Lay-in 1st Floor	12	EA	7	10+ years	
Walls - Concrete Block 1st Floor	1,016	SF	7	10+ years	
Walls - Concrete Block 1st Floor	15	SF	5	1-2 years	Cracking mortar
Work Sink 1st Floor	1	EA	7	6-10 years	
Classroom #110C (Regular Classroom)					
Casework 1st Floor	41	LF	7	6-10 years	
Ceiling - Lay-in 1st Floor	1,050	SF	7	10+ years	
Doors - Wood Doors inclu hw 1st Floor	2	EA	7	10+ years	
Floor - Tile 1st Floor	1,050	SF	7	10+ years	
Lighting - Lay-in 1st Floor	12	ĒΑ	7	10+ years	
Walls - Concrete Block 1st Floor	1,016	SF	7	10+ years	
Work Sink 1st Floor	1	ĒΑ	7	10+ years	
Classroom #111 (Regular Classroom)					
Casework 1st Floor	41	LF	7	6-10 years	
Ceiling - Lay-in 1st Floor	1,050	SF	7	10+ years	
Doors - Wood Doors inclu hw 1st Floor	2	EA	7	10+ years	
Floor - Tile 1st Floor	850	SF	7	10+ years	
Floor - Tile 1st Floor	200	SF	5	1-2 years	Cracking
Lighting - Lay-in 1st Floor	12	EA	7	10+ years	Cracking
Walls - Concrete Block 1st Floor					
	1,016	SF	7 7	10+ years	
Work Sink 1st Floor	1	EA	,	6-10 years	
classroom #112 (Kindergarten)					
Casework 1st Floor	41	LF	7	6-10 years	
Ceiling - Lay-in 1st Floor	1,050	SF	7	10+ years	
Doors - Wood Doors inclu hw 1st Floor	2	EA	7	10+ years	
Floor - Tile 1st Floor	1,050	SF	7	10+ years	
Lighting - Lay-in 1st Floor	12	EA	7	10+ years	
Lighting - Lay-in 1st Floor	12	_, .	•	ioi youlo	

Campus Name: Blair Page : 20 of 26 Assessment Date: 09/19/2023



Category : Classroom			В	uildina	: Additi	on	
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Walls - Concrete Block	1st Floor	1,016	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classro	om #113 (Regular Classroom)						
	Casework	1st Floor	41	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	. 2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	1,016	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	108	SF	7	6-10 years	Updated to match current
	·					•	observations
	Work Sink	1st Floor	1	EA	7	6-10 years	
_Classro	om #114 (Special Education)						
	Casework	1st Floor	30	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,020	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,020	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,010	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classro	om #115 (Regular Classroom)						
	Casework	1st Floor	41	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,016	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #117 (Pre School)						
	Casework	1st Floor	33	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	810	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	810	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,061	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	10	SF	6	10+ years	
	Work Sink	1st Floor	10	EA	7	10+ years	
			•	_, .	•	.o. youro	



6751 W 63rd PLACE, Chicago, IL 60638



Building: Addition Category: Classroom Recommend Item - Type Location Group Quantity UOM Rank Replacement Comments Classroom #119 (Pre School) Casework 1st Floor 33 LF 7 6-10 years 10+ years Ceiling - Lay-in 1st Floor 810 SF 7 Doors - Wood Doors inclu hw 10+ years 1st Floor EΑ 7 1 10+ years Floor - Tile 810 SF 1st Floor Lighting - Lay-in 1st Floor 8 EΑ 7 10+ years Walls - Concrete Block 1st Floor 1,001 SF 7 10+ years SF Walls - Concrete Block 1st Floor 60 7 6-10 years Mortar cracks filled Work Sink EΑ 1st Floor 1 7 6-10 years

Category : Interior Building : Addition

Category : interior		Building : Addition							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Lay-in	1st Floor	3,810	SF	7	10+ years			
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	10+ years			
	Floor - Tile/Sheet	1st Floor	3,810	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	23	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	5,130	SF	7	10+ years			
	Ceiling - Lay-in	Lobby (103)	720	SF	6	10+ years			
	Floor - Tile Quarry	Lobby (103)	720	SF	7	10+ years			
	Lighting - Lay-in	Lobby (103)	9	EA	7	10+ years			
	Walls - Concrete Block	Lobby (103)	270	SF	7	10+ years			
	Ceiling - Lay-in	Main office 108 Corridor passage	200	SF	7	6-10 years			
	Doors - Wood Doors include hw	Main office 108 Corridor passage	2	EA	7	6-10 years			
	Floor - Tile/Sheet	Main office 108 Corridor passage	200	SF	7	6-10 years			
	Lighting - Lay-in	Main office 108 Corridor passage	2	EA	7	6-10 years			
	Walls - Concrete Block	Main office 108 Corridor passage	810	SF	7	6-10 years			
	Ceiling - Lay-in	Vestibule #1 (102)	255	SF	7	6-10 years			
	Ceiling - Lay-in	Vestibule #1 (102)	15	SF	4	0-1 year	Water damage		
	Doors - Side-lite	Vestibule #1 (102)	6	SF	7	6-10 years			
	Doors - Store Front	Vestibule #1 (102)	2	EA	7	6-10 years			
	Doors - Transom Window	Vestibule #1 (102)	1	SF	7	6-10 years			
	Floor - Tile Quarry	Vestibule #1 (102)	270	SF	7	10+ years			
	Lighting - Lay-in	Vestibule #1 (102)	3	EA	7	10+ years			
	Walls - Concrete Block	Vestibule #1 (102)	162	SF	7	10+ years			
	Ceiling - Lay-in	Vestibule #2 (122)	81	SF	7	10+ years			
	Doors - Wood Doors include hw	Vestibule #2 (122)	2	EA	7	10+ years			
	Floor - Tile/Sheet	Vestibule #2 (122)	64	SF	7	10+ years			
	Lighting - Lay-in	Vestibule #2 (122)	1	EA	7	10+ years			
	Walls - Concrete Block	Vestibule #2 (122)	288	SF	7	10+ years			
	Ceiling - Lay-in	Vestibule #3 (125)	120	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Vestibule #3 (125)	120	SF	7	10+ years			
	Lighting - Lay-in	Vestibule #3 (125)	1	EA	7	10+ years			

Campus Name: Blair Page: 22 of 26 Assessment Date: 09/19/2023



Category : Interior Building : Ad						on		, , , , , , , , , , , , , , , , , , ,
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Walls - Concrete Block	Vestibule #3 (125)	180	SF	7	10+ years		
Safety								
•	Camera Viewing Station Security Cameras	1st Floor 1st Floor	1 4	EA EA	7 7	6-10 years 6-10 years		

Campus Name: Blair Page : 23 of 26 Assessment Date: 09/19/2023



Category : Site Building : Site

Salego	ry . Site			unung	. Oile	Decemberd	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Civil/Dra		Location	Quantity	CON	IXAIIK	Replacement	Comments
avii/Dia	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	10+ years	
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Manhole	Entire Site	7	EA	6	10+ years	
	Olvii, Brainage Olic Marinole	Entire Oile	,	L/\	O	101 years	
encina							
9	Fencing - Chain Link	Entire Site	25	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	460	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	29	LF	6	10+ years	
andsca	pe						
	Benches	Entire Site	5	EA	6	10+ years	
	Landscape - Grass	Entire Site	11,519	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	2,759	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	50	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	500	SF	5	1-2 years	Broken, cracked concrete at drivewa
	Parkway trees	Entire Site	23	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	1,550	SF	6	10+ years	
arking	Lot						
ŭ	Concrete Curbs	Entire Site	154	LF	6	10+ years	
	Surface - Asphalt	Entire Site	500	SF	6	6-10 years	
	Surface - Asphalt	Entire Site	7,468	SF	4	0-1 year	Large, potholes, alligatored surface, uneven throughout
	Surface - Concrete	Entire Site	5,400	SF	6	10+ years	<u> </u>
laygrou	ınd						
70	Equipment - Pre K 3-5	East	1	EA	6	10+ years	
	Surface - Poured Surface	East	4,480	SF	6	10+ years	
	Surface - Poured Surface	East	120	SF	5	1-2 years	Depressed surface, torn surface
	Equipment - Pre K 3-5	West	1	EA	6	10+ years	
	Equipment - Swingset	West	1	EA	6	10+ years	
	Surface - Poured Surface	West	4,080	SF	6	10+ years	
idewalk	KS.						
	Sidewalks - Internal Walks	Entire Site	255	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	10	LF	5	1-2 years	Broken interior sidewalk at entrance number one
	Sidewalks - Perimeter Sidewalks	Entire Site	4,950	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	50	SF	5	1-2 years	Sunken sidewalk, cracks
Signage							

Campus Name: Blair Page : 24 of 26 Assessment Date: 09/19/2023



Catego	ry : Site	В	Building : Site						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years			
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	7	10+ years			
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	6	10+ years			

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Blair Page: 25 of 26 Assessment Date: 09/19/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

0	lutan da dilia ana	Down Location	Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Kindergarten	Kindergarten	1st Floor	100	100	1,100	251	68	Υ	Υ
Other Instructional Use	Regular Classroom	1st Floor	102D	102	404	74	18	Υ	N
Regular Classroom	Regular Classroom	1st Floor	103	103	858	150	38	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	858	150	38	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	105	105	858	150	38	Y	Y
Regular Classroom	Regular Classroom	1st Floor	106	106	858	150	38	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	858	150	38	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	858	150	38	Y	Υ
							•	•	
Building : Addition									
Kindergarten	Kindergarten	1st Floor	112	129	1,050	160	53	Y	Υ
Dua Calanal	Dua Calanal	4 a 4 🗀 a a u	447	440	040	4.40	40	V	V

Building : Addition									_
Kindergarten	Kindergarten	1st Floor	112	129	1,050	160	53	Y	Υ
Pre School	Pre School	1st Floor	117	118	810	140	46	Y	Υ
Pre School	Pre School	1st Floor	119	123	810	140	46	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	109	114	1,050	160	53	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	110C	130	1,050	160	53	Y	N
Regular Classroom	Regular Classroom	1st Floor	111	115	1,050	160	53	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	113	116	1,050	160	53	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	115	117	1,050	160	53	Y	Υ
Special Education	Kindergarten	1st Floor	114	128/126	1,020	140	46	Y	N

Campus Name: Blair Page : 26 of 26 Assessment Date: 09/19/2023