

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1929	3	90,517
Addition	2001	3	74,847
Campus Total			165,364

atego	y : Exterior		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ell Equi	pment						
	Cell Equipment - Antenna	Entire Building	3	EA	7	10+ years	
ntrance							
	Exterior Doors - Exterior Steel Door	#10- NE	2	EA	5	1-2 years	Corroding frames at base
	Exterior Stairs - Concrete	#10- NE	80	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#10- NE	30	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#11- NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#11- NE	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#12- NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#12- NE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#12- NE	60	LF	6	10+ years	
	Exterior Stairs - Concrete	#12- NE	12	LF	5	1-2 years	Cracked landing
	Stair Handrail - Steel_Stair Handrail	#12- NE	20	LF	6	10+ years	-
	Exterior Doors - Exterior FRP Door	#13- NE	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#13- NE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#13- NE	48	LF	6	10+ years	
	Exterior Stairs - Concrete	#13- NE	6	LF	5	1-2 years	Cracked landing
	Stair Handrail - Steel_Stair Handrail	#13- NE	32	LF	6	10+ years	· ·
	Exterior Doors - Exterior Steel Door	#14- SE- Boiler Room	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#14.1- SE- Coal Room	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#14.2- SE- Coal Room	2	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#15- SE	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#16- SE	1	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		1000 N Mobile AVENUE, Officago, IE 00000
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	#16- SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#16- SE	54	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#16- SE	20	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#17- SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#17- SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#17- SE	6	LF	5	0-1 year	Cracked concrete
	Ramp Handrail - Steel_Ramp Handrail	#17- SE	120	LF	5	1-2 years	Corroded bases and anchors. Concrete ramp is broken at every one
							of these locations.
	Ramps - Concrete	#17- SE	55	LF	5	1-2 years	Cracks in the ramp, broken ramp at handrail bases
	Exterior Doors - Exterior Steel Door	#17.5- S	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#17.5- S	10	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#17.5- S	8	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#18- S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#18- S	_ 1	EΑ	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#18- S	88	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#18- S	2	LF	5	1-2 years	Rock and curb, exposed rail base
	Ramps - Concrete	#18- S	30	LF	6	10+ years	rtook and care, expected rail bacc
	Ramps - Concrete	#18- S	15	LF	5	1-2 years	Broken curb, cracked ramp
	Exterior Doors - Exterior FRP Door	#19- SW	2	EA	6	10+ years	Broken cars, cracked ramp
	Exterior Stairs - Concrete	#19- SW	6	LF	5	1-2 years	Broken, spalled concrete
	Exterior Doors - Exterior Steel Door	#20- SW	2	EA	6	10+ years	Broken, opalica concrete
	Exterior Doors - Transom Lite	#20- SW	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#20- SW	70	LF	5	1-2 years	Cracked concrete
	Stair Handrail - Steel Stair Handrail	#20- SW	24	LF	6	10+ years	Cracked concrete
	Exterior Doors - Exterior FRP Door	#21- SW	1	EA	7	10+ years	
	Exterior Doors - Side lite	#21- SW	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#21-SW	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#21- OW #22- NE	2	EA	5	0-1 years	Corroded doors and frames
	Exterior Doors - Transom Lite	#22- NE	1	EA	6	10+ years	Corroded doors and frames
	Exterior Stairs - Concrete	#22- NE	70	LF	5	1-2 years	Cracked concrete
	Stair Handrail - Steel_Stair Handrail	#22- NE	24	LF	6	10+ years	Oracked concrete
	Exterior Doors - Exterior Steel Door	14.3 - Chiller Enclosure	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Roof Doors	1	EA	6	10+ years	
_Foundat	ion						
	Foundation - Concrete	Entire Building	924	LF	7	10+ years	
	Foundation - Concrete	Entire Building Entire Building	30	LF	5	1-2 years	Cracks in the tunnel and building
		· ·				•	foundation. Some are leaking.
	Superstructure - Concrete	Entire Building	90,517	SF	7	10+ years	
_Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	8	EA	6	10+ years	

Campus Name: Burbank Page : 2 of 58 Assessment Date: 10/10/2023



Group							
Group						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	5	0-1 year	Broken light fixture
	Exterior Lighting - Wall Mounted	Entire Building	11	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	0-1 year	Broken cover and bulb
Roof Syst	tem						
•	Access Ladder - Metal	Boiler room roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Boiler room roof	30	LF	7	10+ years	
	Liner					,	
	Chimney - Metal Flue	Boiler room roof	10	LF	6	10+ years	Corrected quantity
	Coping - Terra Cotta	Boiler room roof	163	LF	6	10+ years	1
	Downspouts - Interior Downspouts	Boiler room roof	88	LF	6	10+ years	
	Parapet - 16" - 30" Height	Boiler room roof	163	LF	7	10+ years	
	Roof - Modified Bitumen	Boiler room roof	2,849	SF	6	6-10 years	
	Roof - Modified Bitumen	Boiler room roof	40	SF	5	2-5 years	Soft spots Assessed based on current conditions
	Roof Structure - Steel with Clay Tile Arch	Boiler room roof	2,889	SF	7	10+ years	current conditions
	Access Ladder - Metal	Dock roof	2,009	EA	7	,	
	Chimney - Metal Flue	Dock roof	4	LF	7	10+ years	
				LF LF		10+ years	
	Coping - Terra Cotta	Dock roof	128		6	10+ years	
	Downspouts - Interior Downspouts	Dock roof	45	LF	6	10+ years	
	Parapet - 16" - 30" Height	Dock roof	71	LF	7	10+ years	
	Parapet - Parapet > 30"	Dock roof	57	LF 0F	7	10+ years	
	Roof - Modified Bitumen	Dock roof	2,370	SF	6	6-10 years	DI: 4 ·
	Roof - Modified Bitumen	Dock roof	25	SF	4	1-2 years	Blistering
	Roof Structure - Concrete	Dock roof	2,395	SF	7	10+ years	
	Coping - Metal	Electrical Rm Roof -E court yard	16	LF	6	10+ years	5
	Downspouts - Exterior Downspouts	Electrical Rm Roof -E court yard	10	LF	5	1-2 years	Damaged, broken downspout
	Roof - Modified Bitumen	Electrical Rm Roof -E court yard	66	SF	6	6-10 years	Rufus and fair condition , much debon it
	Roof Structure - Concrete	Electrical Rm Roof -E court yard	66	SF	7	10+ years	
	Access Ladder - Metal	Low N roof	1	EA	7	10+ years	
	Coping - Terra Cotta	Low N roof	65	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low N roof	30	LF	6	10+ years	
	Parapet - Parapet > 30"	Low N roof	65	LF	7	10+ years	
	Roof - Modified Bitumen	Low N roof	541	SF	6	6-10 years	
	Roof - Modified Bitumen	Low N roof	150	SF	4	1-2 years	Soft spots
	Roof Structure - Concrete	Low N roof	691	SF	7	10+ years	·
	Coping - Terra Cotta	Low NE roof	62	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low NE roof	36	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low NE roof	62	LF	6	10+ years	
	Roof - Modified Bitumen	Low NE roof	439	SF	6	6-10 years	
	Roof Structure - Concrete	Low NE roof	439	SF	7	10+ years	
	Access Ladder - Metal	Low S roof	1	EA	7	10+ years	
	Coping - Stone	Low S roof	75	LF	7	10+ years	



Catego	ory : Exterior		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Interior Downspouts	Low S roof	44	LF	6	10+ years	
	Parapet - Parapet > 30"	Low S roof	75	LF	7	10+ years	
	Roof - Modified Bitumen	Low S roof	681	SF	6	6-10 years	
	Roof - Modified Bitumen	Low S roof	10	SF	5	1-2 years	Blistered membrane, detached from substrate
	Roof Structure - Concrete	Low S roof	691	SF	7	10+ years	
	Coping - Terra Cotta	Low SW roof	38	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low SW roof	15	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low SW roof	38	LF	6	10+ years	
	Roof - Modified Bitumen	Low SW roof	176	SF	6	6-10 years	
	Roof Structure - Concrete	Low SW roof	176	SF	6	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	7	2-5 years	
	Access Ladder - Metal	Main Roof	4	EA	7	10+ years	
	Access Ladder - Wood	Main Roof	3	EΑ	3	2-5 years	Old homemade wood ladder
	Coping - Terra Cotta	Main Roof	5	LF	6	10+ years	
	Coping - Terra Cotta	Main Roof	903	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	40	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	208	LF	6	10+ years	
	Parapet - Parapet > 30"	Main Roof	908	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	17,802	SF	6	6-10 years	
	Roof - Modified Bitumen	Main Roof	200	SF	4	0-1 year	Ponding. Roof is below gutter
	Roof Hatch - Metal	Main Roof	2	EA	7	10+ years	r onding. Roof to bolow guttor
	Roof Hatch - Metal	Main Roof	1	EA	3	2-5 years	Small, old hatch
	Roof Hatch - Metal	Main Roof	2	EA	3	1-2 years	Damaged old hatches, unused
	Roof Structure - Concrete	Main Roof	18,002	SF	7	10+ years	Damagoa ola Hatorioo, arracoa
	Coping - Terra Cotta	Mid E roof	287	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Mid E roof	145	LF	6	10+ years	
	Parapet - 16" - 30" Height	Mid E roof	287	LF	6	10+ years	
	Roof - Modified Bitumen	Mid E roof	100	SF	6	6-10 years	
	Roof - Modified Bitumen	Mid E roof	6,920	SF	6	10+ years	
	Roof - Modified Bitumen	Mid E roof	300	SF	5	1-2 years	Worn out, cracked surface
	Roof Structure - Concrete	Mid E roof	7,320	SF	7	10+ years	Wolli out, clacked sullace
	Access Ladder - Metal	Mid SE roof	7,320	EA	7	10+ years 10+ years	
	Coping - Terra Cotta	Mid SE roof	16	LF	6	-	
	Downspouts - Exterior Downspouts	Mid SE roof	33	LF	6	10+ years	
	Parapet - 16" - 30" Height	Mid SE roof	16	LF	7	10+ years	
	Roof - Modified Bitumen	Mid SE roof	_	SF		10+ years	
			71		6	6-10 years	
	Roof Structure - Concrete	Mid SE roof	71	SF	7	10+ years	
Walls							
	Canopy - Metal	Entire Building	658	SF	6	10+ years	Metal canopy, old paint, dirty
	Cheek-Wall - Concrete	Entire Building	1,250	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	108	SF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	1,908	LF	6	10+ years	
	· · · · · · ·	-				-	



1 21000	ry : Exterior		D	uilding	· Main	_	2035 N Mobile AVENUE, Chicago, IL 6063
Calego	Ty . Exterior		D	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Exterior Walls - Brick	Entire Building	28,612	SF	6	10+ years	Comments
	Exterior Walls - Brick	Entire Building	500	SF	5	10+ years	
				SF			Control igint doog not have coolent
	Exterior Walls - Brick	Entire Building	30		4	1-2 years	Control joint does not have sealant Open joints, cracked mortar.
	Exterior Walls - Stone-Cast	Entire Building	2,862	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	430	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	200	SF	5	10+ years	
Vindows							
	Guard - Guards perforated	Entire Building	3,127	SF	7	10+ years	
	Lintels - Steel	Entire Building	631	LF	6	10+ years	
		Entire Building	2,912	SF	6	•	
	Windows - Casement Aluminum Double- pane	Entire building	2,912	SF	0	10+ years	
	Windows - Louver	Entire Building	80	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,427	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Emergency Generator- Outdoor- Natural Gas - 101 - 150 KW	Courtyard	1	EA	6	10+ years	
	Automatic Transfer Switch	Electrical Room	1	EΑ	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	14	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	31	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	7	6-10 years	
			2			-	Dualcan
	Exit Signs - Gym	Entire Building		EA	2	0-1 year	Broken
	Security System - CCTV	Entire Building	90,517	SF	7	10+ years	New system
	Security System - Intrusion Detection	Entire Building	90,517	SF	6	6-10 years	
	Emergency A/C Power - Auditoium and	Entire Building	3,781	SF	6	6-10 years	
	• •	-	3,701	O.			
	Aisle Lighting Emergency A/C Power - Corridors and	Entire Building	13,400	SF	6	6-10 years	
	Aisle Lighting Emergency A/C Power - Corridors and Stairs	· ·	13,400	SF			
	Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym	Entire Building	13,400 2,879	SF SF	6	6-10 years	
	Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets	Entire Building Entire Building	13,400 2,879 1,551	SF SF SF	6 6	6-10 years 6-10 years	
	Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym	Entire Building	13,400 2,879	SF SF SF EA	6	6-10 years	
	Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Auditoium and	Entire Building Entire Building	13,400 2,879 1,551	SF SF SF	6 6	6-10 years 6-10 years	
Main Se	Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Students Toilets	Entire Building Entire Building Entire Building	13,400 2,879 1,551 2	SF SF SF EA	6 6 6	6-10 years 6-10 years 6-10 years	
<i>l</i> lain Se	Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Students Toilets	Entire Building Entire Building Entire Building	13,400 2,879 1,551 2	SF SF SF EA	6 6 6	6-10 years 6-10 years 6-10 years	



	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	emergency power	Fating Duilding	00.547	0.5	_	0.5	December and in all areas
	PA System	Entire Building	90,517	SF	5	2-5 years	Doesn't work in all areas
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	7	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	2	EA	6	10+ years	
atego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları		E C B TE	00.547	05		0.10	
	Fire Alarm Strobe Lights	Entire Building	90,517	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	90,517	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litioning						
	•	Site - East	4	EA	6	10+ years	
	Chiller-Air Cooled-Screw Type-Ground	Sile - Lasi	1			,	
	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons	Sile - Lasi	1				
	Mounted - 101 - 200 tons		·	LF	6	6-10 years	
		Site - East	100	LF	6	6-10 years	
ir Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper	Site - East	100				
sir Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001		·	LF EA	6	6-10 years 10+ years	
ir Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm	Site - East AHU1 - North	100	EA	6	10+ years	
ir Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm Air Intake	Site - East AHU1 - North AHU1 - North	100	EA EA	6	10+ years 6-10 years	
sir Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm	Site - East AHU1 - North AHU1 - North AHU1 - North	100	EA EA EA	6	10+ years	
vir Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Hot	Site - East AHU1 - North AHU1 - North	100	EA EA	6	10+ years 6-10 years	
air Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Hot Water Coil	Site - East AHU1 - North AHU1 - North AHU1 - North	100	EA EA EA	6 6 7	10+ years 6-10 years 10+ years 10+ years	
ir Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Hot	Site - East AHU1 - North AHU1 - North AHU1 - North AHU1 - North	100 1 1 1 1 1 5	EA EA EA	6 6 7 6	10+ years 6-10 years 10+ years	
Air Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Hot Water Coil Return Duct Work - Indoor- Vertical Shaft	Site - East AHU1 - North AHU1 - North AHU1 - North AHU1 - North	100 1 1 1 1 5 100	EA EA EA EA	6 6 7 6 7	10+ years 6-10 years 10+ years 10+ years 10+ years	
Air Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Hot Water Coil Return Duct Work - Indoor- Vertical Shaft and Ducts	Site - East AHU1 - North AHU1 - North AHU1 - North AHU1 - North AHU1 - North	100 1 1 1 1 1 5	EA EA EA	6 6 7 6	10+ years 6-10 years 10+ years 10+ years 10+ years	Air flow directional damper in tunne
ir Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Hot Water Coil Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001	Site - East AHU1 - North AHU1 - North AHU1 - North AHU1 - North AHU1 - North AHU1 - North	100 1 1 1 1 5 100 21	EA EA EA LF EA	6 6 7 6 7	10+ years 6-10 years 10+ years 10+ years 10+ years	Air flow directional damper in tunne has detached from supports
Air Hand	Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper lling Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Hot Water Coil Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers Air Handling Unit- Built Up- Single Zone w/	Site - East AHU1 - North AHU1 - North AHU1 - North AHU1 - North AHU1 - North AHU1 - North	100 1 1 1 1 5 100 21	EA EA EA LF EA	6 6 7 6 7	10+ years 6-10 years 10+ years 10+ years 10+ years	Air flow directional damper in tunne has detached from supports

Campus Name: Burbank Page : 6 of 58 Assessment Date: 10/10/2023



Catego	ry : Mechanical		В	uilding	: Main		2005 N Mobile AVENUE, Officago, 12 00055
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Reheat Boxes - Reheat Boxes with Hot Water Coil	AHU2 - South	6	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	AHU2 - South	100	LF	7	10+ years	
	Zone Dampers	AHU2 - South	23	EA	6	10+ years	
	Air Handling Unit- Built Up- Multi Zone- Dual	Auditorium	1	EA	6	10+ years	
	Temperature Coils - 15001 - 25000 cfm	Additionant	·		Ü	101 youro	
	Air Intake	Auditorium	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Auditorium	1	EA	6	10+ years	
	Zone Dampers	Auditorium	5	EA	6	10+ years	
	Outdoor Return Fans- inline Centrifugal - Greater than 20000 CFM	Roof	1	EA	5	6-10 years	
	Outdoor Return Fans- inline Centrifugal - Greater than 20000 CFM	Roof	1	EA	5	6-10 years	
Boiler Sy	vstems						
	Boiler Auxiliary- Condensing Hot Water - 2001 - 3000 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Condensing- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	
Heating	Devices						
	Unit Heater - Hot Water	Boiler Room	2	EA	6	6-10 years	
	Fin Tube - Hot Water	Entire Building	230	LF	6	10+ years	
	Wall Heater - Electric	Entire Building	14	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	5	2-5 years	
_Mechani	cal Plumbing						
	Dual Temperature Pump - 10 - 20 HP	Basement	1	EA	6	6-10 years	
	Dual Temperature Pump - 10 - 20 HP	Basement	1	EA	6	6-10 years	
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	1,000	LF	6	10+ years	
Tempera	ature Control						
	DDC System	Entire Building	90,517	SF	7	10+ years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	52	EA	6	6-10 years	
Ventilation	on						

Campus Name: Burbank Page : 7 of 58 Assessment Date: 10/10/2023



Catego	ry : Mechanical		В	uilding			
				J		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Exhaust Fans- Indoor - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	2	EA	6	6-10 years	
	CFM	. 1001	_		Ū	o lo youlo	
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	2	EA	6	6-10 years	
	CFM	. 1001	_		Ū	o lo youlo	
	Roof Mounted Duct Work	Roof	200	LF	7	10+ years	
					•	.o. you.o	
atego	ry : Plumbing		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ot Wate		Location	Quantity	COM	Italik	replacement	Comments
JI VVAIG	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	
	240 1.04.0.	20.00. 1 (00	_		· ·	o .o you.o	
ping							
	Domestic Piping-Hot Water Return Lines	Entire Building	90,517	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	90,517	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	90,517	SF	7	10+ years	
	Fixtures	9				·	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	90,517	SF	7	10+ years	
	(Horizontal Lines)	g	22,2	-	-	, , , , , , , , , , , , , , , , , , , ,	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	90,517	SF	7	10+ years	
	(Risers)	g	33,311	•	•	.o. you.o	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	90,517	SF	7	10+ years	
	(from Risers to Fixtures)	Entire Ballating	00,017	O.	•	101 youro	
	Sanitary Piping	Entire Building	90,517	SF	7	10+ years	
	Storm Piping	Entire Building	90,517	SF	7	10+ years	
	. •	<u> </u>		SF	7	•	
	Vent Piping	Entire Building	90,517	SF	,	10+ years	
ımps							
	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	5	6-10 years	Consistent scratching noise
	Pumps - Sump-Duplex	Basement	1	EA	4	0-1 year	Leaking at shut-off valves
ateno	ry : Room		R	uilding	· Main		
	.,			29		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	AC Unit	1st - 101D Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st - 101D Office	373	SF	6	10+ years	
	Doors - Transom Window	1st - 101D Office	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st - 101D Office	2	EA	6	6-10 years	
	Floor - Carpet	1st - 101D Office	272	SF	6	6-10 years	
	Floor - Tile	1st - 101D Office	101	SF	6	6-10 years	
	I IOOI - TIIG	13t - 101D OIIICE	101	Ji	U	U-10 years	
mn N	Jama: Purhank		Dogo : 9 of 50				Accomment Date: 10/1

Assessment Date: 10/10/2023 Campus Name: Burbank Page : 8 of 58



Catego	ry : Room		Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Lay-in	1st - 101D Office	8	EA	7	10+ years				
	Power Distribution	1st - 101D Office	6	EA	6	10+ years				
	Walls - Plaster/Drywall	1st - 101D Office	904	SF	6	10+ years				
	Ceiling - Lay-in	1st - 103 Parent Room	1,094	SF	6	6-10 years				
	Doors - Side-lite	1st - 103 Parent Room	16	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st - 103 Parent Room	2	EA	6	6-10 years				
	Floor - Concrete Epoxy/ Painted	1st - 103 Parent Room	1,014	SF	7	6-10 years				
	Floor - Concrete Epoxy/ Painted	1st - 103 Parent Room	80	SF	5	1-2 years	Cracking			
	Lighting - Lay-in	1st - 103 Parent Room	15	EA	7	6-10 years				
	Power Distribution	1st - 103 Parent Room	14	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st - 103 Parent Room	1,415	SF	7	6-10 years				
	Walls - Plaster/Drywall	1st - 103 Parent Room	10	SF	5	1-2 years	Cracking			
	Work SInk	1st - 103 Parent Room	1	EA	7	6-10 years				
	Ceiling - Lay-in	1st - 107 Social Work Office	271	SF	7	10+ years				
	Doors - Transom Window	1st - 107 Social Work Office	18	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st - 107 Social Work Office	2	EA	6	10+ years				
	Floor - Tile	1st - 107 Social Work Office	268	SF	6	10+ years				
	Floor - Tile	1st - 107 Social Work Office	3	SF	5	1-2 years	Missing tiles			
	Lighting - Lay-in	1st - 107 Social Work Office	6	EA	6	6-10 years	•			
	Power Distribution	1st - 107 Social Work Office	2	EA	6	10+ years				
	Walls - Plaster/Drywall	1st - 107 Social Work Office	600	SF	6	10+ years				
	Ceiling - Lay-in	1st - 119 Office	292	SF	6	6-10 years				
	Doors - Transom Window	1st - 119 Office	8	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st - 119 Office	1	EA	6	6-10 years				
	Floor - Tile	1st - 119 Office	292	SF	6	10+ years				
	Lighting - Lay-in	1st - 119 Office	6	EA	7	10+ years				
	Power Distribution	1st - 119 Office	4	EA	6	10+ years				
	Storage/ Closet	1st - 119 Office	140	SF	7	6-10 years				
	Walls - Plaster/Drywall	1st - 119 Office	617	SF	6	6-10 years				
	Ceiling - Lay-in	1st - 121 Office	419	SF	6	6-10 years				
	Doors - Transom Window	1st - 121 Office	8	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st - 121 Office	1	EA	6	6-10 years				
	Floor - Tile	1st - 121 Office	419	SF	6	6-10 years				
	Lighting - Lay-in	1st - 121 Office	6	EA	7	6-10 years				
	Power Distribution	1st - 121 Office	3	EA	6	6-10 years				
	Walls - Plaster/Drywall	1st - 121 Office	843	SF	6	6-10 years				
	Ceiling - Plaster/Drywall	1st - Office inside 133 Gym	121	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st - Office inside 133 Gym	1	EA	6	6-10 years				
	Floor - Tile Ceramic/ Porcelain	1st - Office inside 133 Gym	121	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st - Office inside 133 Gym	1	EA	6	6-10 years				
	Power Distribution	1st - Office inside 133 Gym	5	EA	6	6-10 years				
	Walls - Plaster/Drywall	1st - Office inside 133 Gym	134	SF	6	10+ years				
	Walls - Structural Glazed Tile	1st - Office inside 133 Gym	312	SF	6	10+ years				
	AC Unit	1st - Principal Office inside 101D	1	ĒΑ	7	6-10 years				
		,				,				



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st - Principal Office inside 101D	151	SF	6	6-10 years	
	Doors - Transom Window	1st - Principal Office inside 101D	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st - Principal Office inside 101D	1	EA	6	6-10 years	
	Floor - Carpet	1st - Principal Office inside 101D	151	SF	6	6-10 years	
	Lighting - Lay-in	1st - Principal Office inside 101D	2	EΑ	7	10+ years	
	Power Distribution	1st - Principal Office inside 101D	2	EΑ	6	10+ years	
	Walls - Plaster/Drywall	1st - Principal Office inside 101D	545	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st - Principal Office inside 101D	15	SF	5	1-2 years	Sagging and cracking
	Ceiling - Plaster/Drywall	1st - Rm 129B Curriculum	644	SF	6	6-10 years	
	3	Coordinator's Office & Book Storage				,	
	Doors - Side-lite	1st - Rm 129B Curriculum	45	SF	6	6-10 years	
		Coordinator's Office & Book Storage		-	•	- · · · · · · · · · · · · · · · · · · ·	
	Doors - Steel Doors incl hw	1st - Rm 129B Curriculum	4	EA	6	6-10 years	
	200.0 0.00. 200.0	Coordinator's Office & Book Storage	•	_, ,	Ū	0 .0 ,00.0	
	Doors - Transom Window	1st - Rm 129B Curriculum	23	SF	6	6-10 years	
	Boold Halloom William	Coordinator's Office & Book Storage	20	O.	· ·	o to youro	
	Doors - Wood Doors inclu hw	1st - Rm 129B Curriculum	1	EA	6	6-10 years	
	Doors - Wood Doors med nw	Coordinator's Office & Book Storage		LA	U	0-10 years	
	Floor - Tile	1st - Rm 129B Curriculum	644	SF	6	6-10 years	
	Floor - Tile	Coordinator's Office & Book Storage	044	SI	O	0-10 years	
	Lighting - Pendent/Surface	1st - Rm 129B Curriculum	16	EA	7	10+ years	
	Lighting - Pendent/Surface	Coordinator's Office & Book Storage	10	EA	1	10+ years	
	Dower Distribution	· · · · · · · · · · · · · · · · · · ·	4	ГΛ	e	6 10 years	
	Power Distribution	1st - Rm 129B Curriculum	4	EA	6	6-10 years	
	\\/-!!- \\ \\	Coordinator's Office & Book Storage	4 0 4 0	0.5	•	0.40	
	Walls - Masonry	1st - Rm 129B Curriculum	1,040	SF	6	6-10 years	
	Onlike a Lauria	Coordinator's Office & Book Storage	700	0.5	•	0.40	
	Ceiling - Lay-in	2nd - 203 Faculty	720	SF	6	6-10 years	
	Doors - Transom Window	2nd - 203 Faculty	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd - 203 Faculty	1	EA	6	6-10 years	
	Floor - Wood	2nd - 203 Faculty	720	SF	6	6-10 years	
	Lighting - Lay-in	2nd - 203 Faculty	12	EA	6	6-10 years	
	Power Distribution	2nd - 203 Faculty	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd - 203 Faculty	1,110	SF	6	6-10 years	
	Ceiling - Lay-in	2nd - 205 Office	354	SF	6	6-10 years	
	Doors - Transom Window	2nd - 205 Office	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd - 205 Office	1	EA	6	6-10 years	
	Floor - Tile	2nd - 205 Office	354	SF	6	6-10 years	
	Lighting - Lay-in	2nd - 205 Office	6	EA	6	6-10 years	
	Power Distribution	2nd - 205 Office	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd - 205 Office	785	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd - 205 Office	6	SF	5	1-2 years	Cracking plaster
	AC Unit	2nd - 225 Office	1	EA	7	6-10 years	Updated to match current
						-	observations
	Ceiling - Lay-in	2nd - 225 Office	200	SF	6	6-10 years	
	-					•	

Campus Name: Burbank Page : 10 of 58 Assessment Date: 10/10/2023



Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	2nd - 225 Office	8	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd - 225 Office	1	EA	6	6-10 years			
	Floor - Carpet	2nd - 225 Office	200	SF	6	6-10 years			
	Lighting - Lay-in	2nd - 225 Office	3	EΑ	6	6-10 years			
	Power Distribution	2nd - 225 Office	6	EA	6	6-10 years			
	Walls - Plaster/Drywall	2nd - 225 Office	669	SF	6	6-10 years			
	AC Unit	2nd - Rm 227 Spec Ed Case Manager	1	EA	7	6-10 years			
	Ceiling - Lay-in	2nd - Rm 227 Spec Ed Case Manager	327	SF	6	10+ years			
	Doors - Transom Window	2nd - Rm 227 Spec Ed Case Manager	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd - Rm 227 Spec Ed Case Manager	1	EA	6	10+ years			
	Floor - Tile	2nd - Rm 227 Spec Ed Case Manager	327	SF	6	10+ years			
	Lighting - Lay-in	2nd - Rm 227 Spec Ed Case Manager	5	EA	7	6-10 years			
	Power Distribution	2nd - Rm 227 Spec Ed Case Manager	6	EA	6	10+ years			
	Walls - Plaster/Drywall	2nd - Rm 227 Spec Ed Case Manager	774	SF	6	10+ years			
	Work Sink	2nd - Rm 227 Spec Ed Case Manager	1	EA	5	1-2 years	Not in use		
	Ceiling - Lay-in	3rd - 305 Office	344	SF	6	6-10 years			
	Doors - Transom Window	3rd - 305 Office	8	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	3rd - 305 Office	1	ĒΑ	6	6-10 years			
	Floor - Wood	3rd - 305 Office	344	SF	6	6-10 years			
	Lighting - Lay-in	3rd - 305 Office	6	ĒΑ	6	6-10 years			
	Power Distribution	3rd - 305 Office	4	EA	6	6-10 years			
	Walls - Plaster/Drywall	3rd - 305 Office	815	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	Basement - Office 1 at Upper Level in Boiler	88	SF	6	6-10 years			
	Doors - Side-lite	Basement - Office 1 at Upper Level in Boiler	10	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Basement - Office 1 at Upper Level in Boiler	1	EA	6	10+ years			
	Floor - Tile	Basement - Office 1 at Upper Level in Boiler	88	SF	4	1-2 years	Cracking and broken tiles		
	Lighting - Pendent/Surface	Basement - Office 1 at Upper Level in Boiler	2	EA	6	6-10 years			
	Power Distribution	Basement - Office 1 at Upper Level in Boiler	2	EA	6	10+ years			
	Walls - Plaster/Drywall	Basement - Office 1 at Upper Level	342	SF	6	6-10 years			



Catego	Category : Room			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		in Boiler					
	Ceiling - Plaster/Drywall	Basement - Office 2 at Upper Level	64	SF	6	6-10 years	
	5 W 15 11	in Boiler			_	40	
	Doors - Wood Doors inclu hw	Basement - Office 2 at Upper Level	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	in Boiler Basement - Office 2 at Upper Level	64	SF	7	6-10 years	
	Floor - Concrete Epoxy/ Fainted	in Boiler	04	SF	,	0-10 years	
	Lighting - Pendent/Surface	Basement - Office 2 at Upper Level	1	EA	6	6-10 years	
	Lighting Tondon Canado	in Boiler	•	_, 、	Ü	o io youio	
	Walls - Plaster/Drywall	Basement - Office 2 at Upper Level	292	SF	6	6-10 years	
	•	in Boiler				•	
	Ceiling - Plaster/Drywall	Basement - Office 3 at Upper Level	68	SF	6	6-10 years	
		in Boiler					
	Doors - Wood Doors inclu hw	Basement - Office 3 at Upper Level	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	in Boiler Basement - Office 3 at Upper Level	60	SF	7	6-10 years	
	Floor - Concrete Epoxy/ Fainted	in Boiler	68	SF	,	0-10 years	
	Lighting - Pendent/Surface	Basement - Office 3 at Upper Level	1	EA	7	6-10 years	
	Lighting T chacht Canade	in Boiler	•	L/\	,	o to years	
	Walls - Plaster/Drywall	Basement - Office 3 at Upper Level	302	SF	6	10+ years	
	,	in Boiler				,	
_Auditoriu	um & Theater						
	Balcony Seating	1st - 131 Assembly Hall	176	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - 131 Assembly Hall	3,781	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - 131 Assembly Hall	10	EA	6	10+ years	
	Floor - Tile	1st - 131 Assembly Hall	3,781	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	1st - 131 Assembly Hall	5	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st - 131 Assembly Hall	4	EA	7	10+ years	
	Lighting - Wall Mounted	1st - 131 Assembly Hall	21	EA	6	6-10 years	
	Main Floor Seating	1st - 131 Assembly Hall	400	EA	7	6-10 years	
	Sound System	1st - 131 Assembly Hall	1	EA	7	10+ years	
	Stage	1st - 131 Assembly Hall	1,361	SF	6	10+ years	
	Stage Curtain	1st - 131 Assembly Hall	12	EA	7	6-10 years	
	Stage Lighting System	1st - 131 Assembly Hall	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st - 131 Assembly Hall	5	LF	6	10+ years	
	Stairs - Terrazzo	1st - 131 Assembly Hall	10	LF	6	10+ years	
	Storage/ Closet	1st - 131 Assembly Hall	263	SF	7	10+ years	
	Walls - Concrete Block	1st - 131 Assembly Hall	1,267	SF	6	10+ years	
	Walls - Plaster/Drywall	1st - 131 Assembly Hall	4,624	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st - 131 Assembly Hall	532	SF	6	10+ years	
Clinic							
	Ceiling - Plaster/Drywall	1st - 101B Nurse	144	SF	6	10+ years	



Category : Room		В	uilding	: Main				
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	1st - 101B Nurse	1	EA	6	6-10 years		
	Floor - Carpet	1st - 101B Nurse	144	SF	4	1-2 years	Bubbling, damaged	
	Lighting - Pendent/Surface	1st - 101B Nurse	2	EA	7	10+ years		
	Walls - Plaster/Drywall	1st - 101B Nurse	610	SF	6	6-10 years		
ymnas	ia							
-	Ceiling - Plaster/Drywall	1st - 133 Gym	2,879	SF	6	10+ years	No max occupancy sign	
	Doors - Wood Doors inclu hw	1st - 133 Gym	4	EA	6	6-10 years	. , ,	
	Floor - Wood	1st - 133 Gym	2,879	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st - 133 Gym	12	EA	7	10+ years		
	Scoreboards	1st - 133 Gym	1	EA	4	1-2 years	Dented and missing pieces	
	Storage/ Closet	1st - 133 Gym	332	SF	7	10+ years	3,	
	Walls - Plaster/Drywall	1st - 133 Gym	4,138	SF	6	10+ years		
	Walls - Structural Glazed Tile	1st - 133 Gym	1,565	SF	6	10+ years		
unch &	Multipurpose Room							
	Ceiling - Plaster/Drywall	1st - 125 Classroom	1,026	SF	6	6-10 years		
	Doors - Transom Window	1st - 125 Classroom	16	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st - 125 Classroom	2	EA	6	6-10 years		
	Floor - Tile	1st - 125 Classroom	1,020	SF	6	6-10 years		
	Floor - Tile	1st - 125 Classroom	, 6	SF	5	1-2 years	Cracking and chipping at corners	
	Lighting - Pendent/Surface	1st - 125 Classroom	16	ĒΑ	7	10+ years	3	
	Storage/ Closet	1st - 125 Classroom	17	SF	7	6-10 years		
	Walls - Metal Panel	1st - 125 Classroom	214	SF	6	6-10 years		
	Walls - Plaster/Drywall	1st - 125 Classroom	1,689	SF	6	6-10 years		
	Walls - Plaster/Drywall	1st - 125 Classroom	20	SF	5	1-2 years	Cracking and dented plaster	
	Ceiling - Lay-in	1st - Room 105 - Faculty Lounge	256	SF	6	6-10 years	No max occupancy	
	Doors - Transom Window	1st - Room 105 - Faculty Lounge	18	SF	6	6-10 years	Tto max occupancy	
	Doors - Wood Doors inclu hw	1st - Room 105 - Faculty Lounge	2	EA	6	6-10 years		
	Floor - Tile	1st - Room 105 - Faculty Lounge	246	SF	6	6-10 years		
	Floor - Tile	1st - Room 105 - Faculty Lounge	10	SF	5	0-10 years	Broken tiles	
	Lighting - Lay-in	1st - Room 105 - Faculty Lounge	4	EA	7	10+ years	Dioken tiles	
	Lighting - Pendent/Surface	1st - Room 105 - Faculty Lounge	1	EA	7	10+ years		
	Walls - Plaster/Drywall	1st - Room 105 - Faculty Lounge	592	SF	6	6-10 years		
echani	ical/ Service Rooms							
	Janitor's Closet	1st Floor	14	SF	5	6-10 years	Plaster spalling, ceiling fallen in	
	Janitor's Closet	1st Floor	14	SF	5	6-10 years	Water damage to ceiling and wal	
	Loading Docks	1st Floor	539	SF	7	10+ years	129A Loading Dock	
	Mechanical/ Service Rooms	1st Floor	153	SF	7	10+ years	1207 Lodding Dook	
	Storage Room	1st Floor	124	SF	7	10+ years		
	Janitor's Closet	2nd Floor	18	SF	7	6-10 years		
	Janitor's Closet	2nd Floor	18	SF	, 5	•	Cracking and peeling walls	
	Janiilon & Chosel	ZIIU FIUUI	10	SF	ວ	6-10 years	Cracking and peeling wans	

Campus Name: Burbank Page : 13 of 58 Assessment Date: 10/10/2023



ategory : Room		В	uilding	: Main				
						Recommend	d	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Janitor's Closet	3rd Floor	35	SF	7	10+ years		
	Janitor's Closet	3rd Floor	20	SF	5	10+ years	Light nonfunctional	
	Air Intake Plenums	Basement	969	SF	7	6-10 years		
	Air Tunnel	Basement	2,902	SF	7	6-10 years		
	Auditorium Plenums	Basement	4,272	SF	7	6-10 years		
	Boiler Room	Basement	1,353	SF	7	10+ years		
	Coal Room	Basement	409	SF	7	6-10 years		
	Crawl Space - Unfinished	Basement	8,406	SF	7	6-10 years		
	Mechanical/ Service Rooms	Basement	7,743	SF	7	6-10 years		
	Storage Room	Basement	2,791	SF	7	6-10 years		
	Clorage Noom	Bassmont	2,701	O.	,	o ro youro		
stroon	n Accessories	1at In Principal Office	24	QE.	7	6 10 years		
		1st - In Principal Office	24 24	SF SF	7 6	6-10 years		
	Ceiling - Plaster/Drywall	1st - In Principal Office			6	6-10 years		
	Doors - Wood Doors inclu hw	1st - In Principal Office	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	1st - In Principal Office	24	SF	6	10+ years		
	Lavatory	1st - In Principal Office	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	1st - In Principal Office	1	EA	5	1-2 years	Missing cover, relamp	
	Walls - Plaster/Drywall	1st - In Principal Office	186	SF	6	6-10 years		
	Water Closet	1st - In Principal Office	1	EA	6	6-10 years		
	Accessories	1st - Inside 119 Office	58	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st - Inside 119 Office	58	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st - Inside 119 Office	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	1st - Inside 119 Office	58	SF	6	6-10 years		
	Floor Drain	1st - Inside 119 Office	1	ĒΑ	7	10+ years		
	Lighting - Pendent/Surface	1st - Inside 119 Office	1	EA	7	10+ years		
	Partitions	1st - Inside 119 Office	2	EΑ	7	6-10 years		
	Walls - Plaster/Drywall	1st - Inside 119 Office	300	SF	6	6-10 years		
	Water Closet	1st - Inside 119 Office	2	EA	4	0-1 year	Rust stains, not in use	
	Accessories	1st - Inside 113 Gym used as	121	SF	7	6-10 years	rust stairis, not in use	
		Storage	121		1	•		
	Ceiling - Plaster/Drywall	1st - Inside 133 Gym used as Storage	121	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st - Inside 133 Gym used as Storage	1	EA	4	0-1 year	Damaged window pane, veneer peeling	
	Floor - Tile Ceramic/ Porcelain	1st - Inside 133 Gym used as Storage	121	SF	6	10+ years	F9	
	Lavatory	1st - Inside 133 Gym used as Storage	1	EA	6	10+ years		
	Lighting - Pendent/Surface	1st - Inside 133 Gym used as Storage	1	EA	6	6-10 years		
	Partitions	1st - Inside 133 Gym used as Storage	1	EA	4	0-1 year	Missing door	
	Walls - Plaster/Drywall	1st - Inside 133 Gym used as	137	SF	6	6-10 years		

Campus Name: Burbank Page : 14 of 58 Assessment Date: 10/10/2023



Storage	Quantity 319	UOM	Rank	Recommend Replacement	Comments
Walls - Structural Glazed Tile Water Closet Water Closet Accessories Accessorie	•		Rank	Replacement	Comments
Walls - Structural Glazed Tile Water Closet Accessories Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Pendent/Surface Walls - Plaster/Drywall Staff (N of Auditority Accessories 1st - Men's Staff (N of Auditority Staf	319	C.E.			J J
Water Closet Accessories Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Pendent/Surface Walls - Plaster/Drywall Water Closet Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Tst - Men's Staff (N of Auditoring Staff (N of	319		_		
Water Closet Accessories Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Pendent/Surface Walls - Plaster/Drywall Water Closet Accessories Ceiling - Plaster/Drywall Staff (N of Auditoring Staff (SF	6	6-10 years	
Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Pendent/Surface Walls - Plaster/Drywall Water Closet Accessories Ceiling - Plaster/Drywall Staff (N of Auditori 1st - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Staff (N of Auditori 1st - Unisex RR (South of Auditorium)	1	EA	4	0-1 year	Nonfunctional
Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Pendent/Surface Walls - Plaster/Drywall Water Closet Accessories Ceiling - Plaster/Drywall St - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain 1st - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium)	ļ	EA	4	0-1 year	Nonunctional
Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Pendent/Surface Walls - Plaster/Drywall Water Closet Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Tist - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain 1st - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium)	ium) 26	SF	7	6-10 years	
Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Pendent/Surface Walls - Plaster/Drywall Water Closet Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Tist - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain 1st - Unisex RR (South of Auditorium)		SF	6	6-10 years	
Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Pendent/Surface Walls - Plaster/Drywall Water Closet Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain 1st - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium)		ĒΑ	6	6-10 years	
Lighting - Pendent/Surface Walls - Plaster/Drywall Walls - Plaster/Drywall Water Closet Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain 1st - Men's Staff (N of Auditori 1st - Men's Staff (N of Auditori 1st - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium)		SF	6	6-10 years	
Walls - Plaster/Drywall Walls - Plaster/Drywall Water Closet Accessories Staff (N of Auditori 1st - Men's Staff (N of Auditori 1st - Men's Staff (N of Auditori 1st - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium) Star - Unisex RR (South of Auditorium) Doors - Wood Doors inclu hw 1st - Unisex RR (South of Auditorium) Floor - Tile Ceramic/ Porcelain 1st - Unisex RR (South of Auditorium) 1st - Unisex RR (South of Auditorium)		EA	6	6-10 years	
Walls - Plaster/Drywall Water Closet Accessories 1st - Men's Staff (N of Auditori 1st - Men's Staff (N of Auditori 1st - Men's Staff (N of Auditori 1st - Unisex RR (South of Auditorium) 1st - Unisex RR (South of Auditorium) Doors - Wood Doors inclu hw 1st - Unisex RR (South of Auditorium) 1st - Unisex RR (South of Auditorium) Floor - Tile Ceramic/ Porcelain 1st - Unisex RR (South of Auditorium)		EA	7	10+ years	
Water Closet Accessories 1st - Men's Staff (N of Auditorian) Ceiling - Plaster/Drywall 1st - Unisex RR (South of Auditorium) Doors - Wood Doors inclu hw 1st - Unisex RR (South of Auditorium) The Ceramic Porcelain 1st - Unisex RR (South of Auditorium) 1st - Unisex RR (South of Auditorium) Auditorium)	ium) 233	SF	6	6-10 years	
Accessories 1st - Unisex RR (South of Auditorium) Ceiling - Plaster/Drywall 1st - Unisex RR (South of Auditorium) Doors - Wood Doors inclu hw 1st - Unisex RR (South of Auditorium) Floor - Tile Ceramic/ Porcelain 1st - Unisex RR (South of Auditorium) Auditorium)	ium) 10	SF	5	1-2 years	Cracking
Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Auditorium) 1st - Unisex RR (South of Auditorium) 1st - Unisex RR (South of Auditorium) 1st - Unisex RR (South of Auditorium)	ium) 1	EA	6	6-10 years	
Ceiling - Plaster/Drywall 1st - Unisex RR (South of Auditorium) Doors - Wood Doors inclu hw 1st - Unisex RR (South of Auditorium) Floor - Tile Ceramic/ Porcelain 1st - Unisex RR (South of Auditorium)	119	SF	7	10+ years	
Doors - Wood Doors inclu hw 1st - Unisex RR (South of Auditorium) Floor - Tile Ceramic/ Porcelain 1st - Unisex RR (South of Auditorium)	119	SF	7	6-10 years	
Floor - Tile Ceramic/ Porcelain 1st - Unisex RR (South of Auditorium)	1	EA	7	10+ years	
	119	SF	7	6-10 years	
Auditorium)	1	EA	7	10+ years	
Hand Dryer 1st - Unisex RR (South of Auditorium)	1	EA	7	6-10 years	
Lavatory 1st - Unisex RR (South of Auditorium)	1	EA	7	6-10 years	
Lighting - Pendent/Surface 1st - Unisex RR (South of Auditorium)	3	EA	7	6-10 years	
Walls - Tile Ceramic/ Porcelain 1st - Unisex RR (South of Auditorium)	432	SF	7	6-10 years	
Water Closet 1st - Unisex RR (South of Auditorium)	1	EA	7	6-10 years	
Accessories 1st - Women's Staff (S of Auditorium)	92	SF	7	6-10 years	
Ceiling - Plaster/Drywall 1st - Women's Staff (S of Auditorium)	92	SF	6	6-10 years	
Doors - Wood Doors inclu hw 1st - Women's Staff (S of Auditorium)	1	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain 1st - Women's Staff (S of Auditorium)	92	SF	6	6-10 years	
Lavatory 1st - Women's Staff (S of Auditorium)	1	EA	6	6-10 years	

Campus Name: Burbank Page : 15 of 58 Assessment Date: 10/10/2023



Catego	egory : Room		В	uilding	: Main		· 5 ·
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st - Women's Staff (S of	2	EΑ	7	10+ years	
		Auditorium)					
	Partitions	1st - Women's Staff (S of	1	EΑ	7	6-10 years	
		Auditorium)					
	Walls - Plaster/Drywall	1st - Women's Staff (S of	350	SF	6	6-10 years	
		Auditorium)					
	Water Closet	1st - Women's Staff (S of	1	EA	6	6-10 years	
		Auditorium)					
	Accessories	1st Floor	232	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	232	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	232	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	4	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	730	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1	SF	5	1-2 years	Damaged tiles
	Water Closet	1st Floor	2	EA	6	10+ years	•
	Accessories	1st Floor	285	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	285	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	285	SF	6	10+ years	
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	6-10 years	
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	810	SF	6	10+ years	
	Water Closet	1st Floor	6	EΑ	6	10+ years	
	Accessories	2nd - Inside Rm 227 (Used as	14	SF	5	1-2 years	Not in use
		Storage)				,	
	Ceiling - Lay-in	2nd - Inside Rm 227 (Used as	14	SF	6	6-10 years	
	3 3	Storage)				,	
	Doors - Wood Doors inclu hw	2nd - Inside Rm 227 (Used as	1	EA	6	6-10 years	
		Storage)			•	- · · · · · · · · · · · · · · · · · · ·	
	Floor - Tile Ceramic/ Porcelain	2nd - Inside Rm 227 (Used as	14	SF	6	6-10 years	
	The Coramic Torocian	Storage)		O.	Ŭ	o io jouio	
	Walls - Plaster/Drywall	2nd - Inside Rm 227 (Used as	120	SF	6	6-10 years	
	Trans Tractor/21/Trans	Storage)	120	O.	Ŭ	o io jouio	
	Water Closet	2nd - Inside Rm 227 (Used as	1	EA	4	1-2 years	Not in use
		Storage)		_/ \	7	1 2 yours	1101 400
	Accessories	2nd - Unisex Staff (N End of	65	SF	7	6-10 years	
	, 10000001100	Balcony)	00	0.	,	J 10 yours	
		zaioony,					



Catego	Category : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd - Unisex Staff (N End of Balcony)	65	SF	6	6-10 years	
	Doors - Transom Window	2nd - Unisex Staff (N End of Balcony)	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd - Unisex Staff (N End of Balcony)	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd - Unisex Staff (N End of Balcony)	65	SF	6	6-10 years	
	Floor Drain	2nd - Unisex Staff (N End of Balcony)	1	EA	7	6-10 years	
	Hand Dryer	2nd - Unisex Staff (N End of Balcony)	1	EA	7	6-10 years	
	Lavatory	2nd - Unisex Staff (N End of Balcony)	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd - Unisex Staff (N End of Balcony)	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd - Unisex Staff (N End of Balcony)	374	SF	6	6-10 years	
	Water Closet	2nd - Unisex Staff (N End of Balcony)	1	EA	6	6-10 years	
	Accessories	2nd - Unisex Staff (South of Balcony)	65	SF	7	6-10 years	
	Ceiling - Lay-in	2nd - Unisex Staff (South of Balcony)	65	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd - Unisex Staff (South of Balcony)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd - Unisex Staff (South of Balcony)	65	SF	6	10+ years	
	Floor Drain	2nd - Unisex Staff (South of Balcony)	1	EA	7	10+ years	
	Lavatory	2nd - Unisex Staff (South of Balcony)	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd - Unisex Staff (South of Balcony)	1	EA	6	6-10 years	
	Partitions	2nd - Unisex Staff (South of Balcony)	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd - Unisex Staff (South of Balcony)	334	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd - Unisex Staff (South of Balcony)	10	SF	5	1-2 years	Cracking plaster
	Water Closet	2nd - Unisex Staff (South of Balcony)	1	EA	6	10+ years	
	Accessories	2nd Floor	285	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	285	SF	6	10+ years	



ategory : Room		В	uilding	: Main			
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor	285	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	6-10 years	
	Partitions	2nd Floor	7	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	910	SF	6	10+ years	
	Water Closet	2nd Floor	7	EA	6	10+ years	
	Accessories	2nd Floor	232	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	232	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	232	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	6	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	730	SF	6	10+ years	
		2nd Floor	730	EA	6	•	
	Water Closet			SF	7	10+ years	
	Accessories	3rd - Inside 325	40	SF SF		6-10 years	
	Ceiling - Lay-in	3rd - Inside 325	40		7	6-10 years	
	Doors - Wood Doors inclu hw	3rd - Inside 325	1	EA	7	6-10 years	
	Floor - Tile	3rd - Inside 325	40	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd - Inside 325	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd - Inside 325	286	SF	7	6-10 years	
	Water Closet	3rd - Inside 325	1	EA	7	10+ years	
	Accessories	3rd - Unisex Staff RR (North of Balcony)	72	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd - Unisex Staff RR (North of Balcony)	72	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd - Unisex Staff RR (North of Balcony)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd - Unisex Staff RR (North of Balcony)	72	SF	7	10+ years	
	Floor Drain	3rd - Unisex Staff RR (North of Balcony)	1	EA	7	10+ years	
	Hand Dryer	3rd - Unisex Staff RR (North of Balcony)	1	EA	7	6-10 years	
	Lavatory	3rd - Unisex Staff RR (North of Balcony)	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd - Unisex Staff RR (North of Balcony)	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd - Unisex Staff RR (North of	180	SF	7	6-10 years	

Campus Name: Burbank Page : 18 of 58 Assessment Date: 10/10/2023



Catego	ry : Room		Building : Main						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	W. II. O	Balcony)	400	0=	_	0.40			
	Walls - Structural Glazed Tile	3rd - Unisex Staff RR (North of	160	SF	7	6-10 years			
	Water Closet	Balcony)	4	EA	7	10			
	water Closet	3rd - Unisex Staff RR (North of Balcony)	1	EA	1	10+ years			
	Accessories	3rd Floor	285	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	285	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	285	SF	6	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	2	EA	7	10+ years			
	Lavatory	3rd Floor	2	EΑ	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	4	EΑ	6	6-10 years			
	Partitions	3rd Floor	7	EA	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	810	SF	6	10+ years			
	Water Closet	3rd Floor	7	EA	6	10+ years			
	Accessories	3rd Floor	232	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	232	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	232	SF	6	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	2	EA	7	6-10 years			
	Lavatory	3rd Floor	1	EA	6	10+ years			
	Lavatory	3rd Floor	1	EA	5	1-2 years	Not draining, causing overflow		
	Lighting - Pendent/Surface	3rd Floor	4	EA	6	6-10 years			
	Partitions	3rd Floor	2	EA	7	10+ years			
	Urinals	3rd Floor	4	EA	6	10+ years	Updated quantity		
	Walls - Structural Glazed Tile	3rd Floor	730	SF	6	10+ years			
	Water Closet	3rd Floor	2	EA	6	10+ years			
	Accessories	Basement	24	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement	24	SF	4	1-2 years	Plaster damage around vent opening		
	Doors - Wood Doors inclu hw	Basement	1	EA	6	6-10 years			
	Floor - Concrete Epoxy/ Painted	Basement	24	SF	7	6-10 years			
	Lavatory	Basement	1	EA	6	6-10 years			
	Lighting - Wall Mounted	Basement	1	EA	6	6-10 years			
	Walls - Concrete Block	Basement	137	SF	6	6-10 years			
	Walls - Masonry	Basement	41	SF	5	1-2 years	Masonry crumbling		
	Water Closet	Basement	1	EA	6	6-10 years			
	Accessories	Basement - Inside Office 1 at Upper Boiler	23	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement - Inside Office 1 at Upper Boiler	23	SF	6	6-10 years			

Campus Name: Burbank Page : 19 of 58 Assessment Date: 10/10/2023



Catego	ry : Room		Building : Main							
0	Name Tama	l ti	0 111	11014	D- 1	Recommend	0			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Wood Doors inclu hw	Basement - Inside Office 1 at Upper Boiler	1	EA	6	6-10 years				
	Floor - Tile	Basement - Inside Office 1 at Upper Boiler	23	SF	6	6-10 years				
	Lavatory	Basement - Inside Office 1 at Upper Boiler	1	EA	5	1-2 years	Cracking and rust stained			
	Lighting - Pendent/Surface	Basement - Inside Office 1 at Upper Boiler	1	EA	6	6-10 years				
	Walls - Plaster/Drywall	Basement - Inside Office 1 at Upper Boiler	176	SF	4	1-2 years	Spalling plaster			
	Water Closet	Basement - Inside Office 1 at Upper Boiler	1	EA	6	6-10 years				
	Ceiling - Plaster/Drywall	Basement - Inside Office 2 at Upper Boiler	21	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	Basement - Inside Office 2 at Upper Boiler	1	EA	6	6-10 years				
	Floor - Concrete Epoxy/ Painted	Basement - Inside Office 2 at Upper Boiler	21	SF	7	6-10 years				
	Lavatory	Basement - Inside Office 2 at Upper Boiler	1	EA	4	0-1 year	Rusting, nonfunctional			
	Lighting - Pendent/Surface	Basement - Inside Office 2 at Upper Boiler	1	EA	6	6-10 years				
	Walls - Plaster/Drywall	Basement - Inside Office 2 at Upper Boiler	162	SF	6	6-10 years				
	Walls - Plaster/Drywall	Basement - Inside Office 2 at Upper Boiler	10	SF	5	0-1 year	Spalling plaster			
	Water Closet	Basement - Inside Office 2 at Upper Boiler	1	EA	3	0-1 year	Actively leaking			
	Ceiling - Plaster/Drywall	Basement - Inside Office 3 at Upper Boiler	18	SF	5	1-2 years	Spalling plaster			
	Doors - Wood Doors inclu hw	Basement - Inside Office 3 at Upper Boiler	1	EA	6	6-10 years				
	Floor - Concrete Epoxy/ Painted	Basement - Inside Office 3 at Upper Boiler	18	SF	7	6-10 years				
	Lavatory	Basement - Inside Office 3 at Upper Boiler	1	EA	4	0-1 year	Fully rusted, nonfunctional			
	Lighting - Pendent/Surface	Basement - Inside Office 3 at Upper Boiler	1	EA	7	10+ years				
	Walls - Plaster/Drywall	Basement - Inside Office 3 at Upper Boiler	151	SF	6	6-10 years				
	Walls - Plaster/Drywall	Basement - Inside Office 3 at Upper Boiler	10	SF	5	0-1 year	Spalling plaster			
	Water Closet	Basement - Inside Office 3 at Upper Boiler	1	EA	4	0-1 year	Nonfunctional			

Campus Name: Burbank Page : 20 of 58 Assessment Date: 10/10/2023



$\overline{}$	ry : Room		В	uilding	: Main		2035 N MODIIE AVENUE, Chicago, IL 60639
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catago	ry : Classroom		D	uildina	. Main		
Calego	ry . Classiooni		В	uilding	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #109 (Regular Classroom)		•			•	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	720	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Wood	1st Floor	720	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,105	SF	6	10+ years	
	Walls - Flastel/Drywall	13(1100)	1,103	OI.	U	10+ years	
Classroo	om #111 (Regular Classroom)						
	Casework	1st Floor	56	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	700	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	700	SF	6	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,036	SF	6	10+ years	
Classro	m #112 (Kindergerten)						
Classio	om #113 (Kindergarten)	4 . =1				10	
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,365	SF	6	10+ years	
	Doors - Transom Window	1st Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Carpet	1st Floor	932	SF	6	6-10 years	
	Floor - Tile	1st Floor	433	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	85	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	245	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,173	SF	6	10+ years	
Classro	om #123 (Kindergarten)						
	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	86	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	1,095	SF	6	10+ years 10+ years	
	Doors - Transom Window	1st Floor	8	SF	6		
			0	SF EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĽΑ	Ö	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	1st Floor	1,095	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	134	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,768	SF	6	6-10 years	
Classroc	om #201 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	733	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood Books including	2nd Floor	733	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor 2nd Floor	12	EA	7	•	
		2nd Floor		LF		10+ years	
	Marker Board		24	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	938	5F	6	10+ years	
Classroc	m #207 (Music Room)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	32	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,156	SF	6	10+ years	
Classroc	om #211 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	733	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	733	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	935	SF	6	10+ years	
Classroo	om #213 (Regular Classroom)						
CiassiUL	`	2nd Floor	0	LF	e	101.1/2072	
	Casework		8		6	10+ years	
	Ceiling - Lay-in	2nd Floor	732	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	

Campus Name: Burbank Page : 22 of 58 Assessment Date: 10/10/2023



Catego	ategory : Classroom		В	uilding	: Main		2000 N Mobile AVENOE, Officago, 12 00000		
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Wood	2nd Floor	732	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	939	SF	6	10+ years			
_Classroo	om #215 (Regular Classroom)								
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	718	SF	6	10+ years			
	Chalk Board	2nd Floor	24	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Wood	2nd Floor	718	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	936	SF	6	10+ years			
	Walls - Flastel/Drywall	2110 F1001	930	SF	O	10+ years			
Classroo	om #221 (Regular Classroom)	. —							
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	722	SF	6	10+ years			
	Chalk Board	2nd Floor	4	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Wood	2nd Floor	722	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	936	SF	6	10+ years			
_Classroo	om #223 (Computer Lab)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	12	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	850	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	850	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,004	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Cracking, bubbling		
	Wireless System	2nd Floor	10	EA	7	10+ years	Cracking, bubbling		
01	(1000 (D I. Ol)								
Classro	om #229 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	10+ years			
	Casework	2nd Floor	_ 8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years			
	Chalk Board	2nd Floor	8	LF	4	2-5 years			



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,156	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	733	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	733	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	938	SF	6	•	
	Walls - Flastel/Drywall	314 F1001	930	SF	b	10+ years	
Classroo	om #303 (Store Room)						
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	711	SF	6	10+ years	
	Chalk Board	3rd Floor	32	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	711	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,148	SF	6	10+ years	
Classroo	om #307 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,156	SF	6	10+ years	
Classro	om #309 (Regular Classroom)						
VIGSSIU	` • • • • • • • • • • • • • • • • • • •	3rd Floor	0	LF	e	10 L VOOTO	
	Casework		8		6	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	

Campus Name: Burbank Page : 24 of 58 Assessment Date: 10/10/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,156	SF	6	10+ years	
Classroo	m #311 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	731	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	731	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	940	SF	6	10+ years	
	vvalis - Flastei/Diywali	314 F1001	940	SF	b	10+ years	
Classroo	m #313 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	731	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	731	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	940	SF	6	10+ years	
Classroo	m #315 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	731	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	731	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	ĒΑ	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EΑ	6	6-10 years	Relamp
	Marker Board	3rd Floor	24	LF	7	6-10 years	Rolamp
	Walls - Plaster/Drywall	3rd Floor	936	SF	6	10+ years	
Classroo	m #317 (Regular Classroom)						
CIGOSIUC	Casework	3rd Floor	8	LF	6	10+ years	
				SF		•	
	Ceiling - Lay-in	3rd Floor	720	SF LF	6	10+ years	
	Chalk Board	3rd Floor	2		4	2-5 years	
	Doors - Transom Window Doors - Wood Doors inclu hw	3rd Floor	9	SF EA	6	10+ years	
		3rd Floor	1	⊢ Δ	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,156	SF	6	10+ years	
lassroc	m #319 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	6	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EΑ	6	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,156	SF	6	10+ years	
lassroc	m #321 (Office)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	932	SF	6	10+ years	
lassroc	m #323 (Regular Classroom)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Casework	3rd Floor	32	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,100	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	16	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	1,116	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	15	EA	7	10+ years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,153	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
lassroc	m #325 (Computer Lab)						
	AC Units	3rd Floor	3	EA	7	10+ years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	940	SF	6	10+ years	
	Celling - Lav-III						

Campus Name: Burbank Page : 26 of 58 Assessment Date: 10/10/2023



Luther Burbank Elementary School

ALL H	SCHOOIS					2	2035 N Mobile AVENUE, Chicago, IL 60639
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	940	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	15	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EΑ	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	106	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,343	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	48	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Catego	Category : Interior			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	nom Type	200411011	quantity	•	rtann	Ropidoomont	
Comaoi	Ceiling - Lay-in	1st Floor	2,852	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,960	SF	6	6-10 years	
	Doors - Side-lite	1st Floor	28	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	8	SF	6	6-10 years	
	Doors - Wood Doors include hw	1st Floor	13	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	1,037	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	4,212	SF	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	40	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	47	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	6	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	205	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,726	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	5,349	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,697	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,697	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	52	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	162	EA	6	10+ years	
	Student Lockers - One Tier	2nd Floor	1	EA	4	1-2 years	Bent open
	Walls - Plaster/Drywall	2nd Floor	4,261	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,983	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	3,298	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	160	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	3,102	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	38	SF	4	1-2 years	Damaged tiles
	Lighting - Lay-in	3rd Floor	55	EA	7	6-10 years	

Campus Name: Burbank Page : 27 of 58 Assessment Date: 10/10/2023



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	3rd Floor	184	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	3,355	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	2,595	SF	6	10+ years	
Safety							
,	Camera Viewing Station	1st Floor	2	EA	7	10+ years	Shared with Addition building
	Security Cameras	1st Floor	1	EA	7	10+ years	S
Stairs							
lalis	Ceiling - Lay-in	North East	274	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North East	88	SF	6	10+ years	
	Floor - Terrazzo	North East	113	SF	6	10+ years	
	Handrails	North East	116	LF	7	10+ years	
	Lighting - Lay-in	North East	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	North East	1	EΑ	7	6-10 years	
	Stairs - Terrazzo	North East	56	LF	6	10+ years	
	Walls - Plaster/Drywall	North East	963	SF	6	10+ years	
	Walls - Structural Glazed Tile	North East	475	SF	6	10+ years	
	Ceiling - Lay-in	North West	274	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North West	88	SF	6	10+ years	
	Floor - Terrazzo	North West	113	SF	6	10+ years	
	Handrails	North West	116	LF	7	10+ years	
	Lighting - Lay-in	North West	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	North West	1	EA	7	6-10 years	
	Stairs - Terrazzo	North West	56	LF	6	10+ years	
	Walls - Plaster/Drywall	North West	963	SF	6	10+ years	
	Walls - Structural Glazed Tile	North West	475	SF	6	10+ years	
	Ceiling - Exposed	North of Gym	206	SF	6	10+ years	
	Ceiling - Exposed Ceiling - Plaster/Drywall	North of Gym	215	SF	6	10+ years	
	Floor - Concrete	North of Gym	306	SF	7	10+ years	
	Handrails	North of Gym	108	LF	7	10+ years	
	Lighting - Pendent/Surface	North of Gym	2	EA	6	6-10 years	
	Stairs - Concrete	North of Gym	56	LF	7	10+ years	
	Walls - Masonry	North of Gym	268	SF	6	10+ years	
	Walls - Plaster/Drywall	North of Gym	915	SF	6	10+ years	
	Walls - Structural Glazed Tile	North of Gym	916	SF	6	10+ years	
				SF	6		
	Ceiling - Lay-in Ceiling - Plaster/Drywall	South East	274 88	SF SF	6	10+ years	
	Floor - Terrazzo	South East		SF SF	_	10+ years	
		South East	113		6 7	10+ years	
	Handrails	South East	116	LF		10+ years	
	Lighting - Lay-in	South East	2	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	South East	2	EA	7	6-10 years	
	Stairs - Terrazzo	South East	56	LF	6	10+ years	
	Walls - Plaster/Drywall	South East	963	SF	6	10+ years	

Campus Name: Burbank Page : 28 of 58 Assessment Date: 10/10/2023



Catego	ry : Interior		В	uilding	: Main				
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Structural Glazed Tile	South East	475	SF	6	10+ years			
	Ceiling - Lay-in	South West	274	SF	6	10+ years			
	Ceiling - Plaster/Drywall	South West	88	SF	6	10+ years			
	Floor - Terrazzo	South West	113	SF	6	10+ years			
	Handrails	South West	116	LF	7	10+ years			
	Lighting - Lay-in	South West	2	EA	7	6-10 years			
	Lighting - Pendent/Surface	South West	2	EA	7	6-10 years			
	Stairs - Terrazzo	South West	56	LF	6	10+ years			
	Walls - Plaster/Drywall	South West	963	SF	6	10+ years			
	Walls - Structural Glazed Tile	South West	475	SF	6	10+ years			
	Handrails	South of Gym (abandoned no access)	108	LF	5	10+ years	No access		

Campus Name: Burbank Page : 29 of 58 Assessment Date: 10/10/2023



Category : Exterior Building : Addition

	y . Exterior			anamg	. Additio		
	_					Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ll Equi	pment						
	Cell Equipment - Antenna	Entire Building	6	EA	7	10+ years	
	Cell Equipment - Cabinets	Entire Building	3	EA	7	10+ years	
	1. 1.	3				, , , , , ,	
trance	1						
	Entrance Control - Audio and Video	#1- W- Main Accessible	1	EA	6	10+ years	
	Exterior Doors - Store Front	#1- W- Main Accessible	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1- W- Main Accessible	3	EA	6	10+ years	
	Exterior Doors - Store Front	#2- NW	3	EA	4	1-2 years	Settlement of north west corner of
						,	property has affected doors number
							two and these are not closing
							properly. There's also signs of
							settlement on the adjoining CMU
							walls. Buckled frames
	Exterior Doors - Transom Lite	#2- NW	3	EA	4	1-2 years	Settlement of north west corner of
	ZAMONOL ZOOLO THANGON ZHO	<i>"</i> -	· ·	_, ,	-	/ 505	property has affected doors number
							two and these are not closing
							properly. There's also signs of
							settlement on the adjoining CMU
							walls. Buckled frames
	Exterior Doors - Store Front	#3- NE	3	EA	6	10+ years	walls. Duckled frames
	Exterior Doors - Transom Lite	#3- NE	6	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4- SE	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5- SE	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6- SE	1	EA	6	10+ years	
	Exterior Doors - Store Front	#7- SW	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8- SW- Pump Rm	2	EA	6	10+ years	
	Exterior Doors - Store Front	#9- SW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#9- SW	46	LF	6	10+ years	
	Exterior Stairs - Concrete	#9- SW	10	LF	3	•	Cracked and spalled concrete at
	Exterior Stalls - Contrete	#9- 3VV	10	LF	3	0-1 year	entry threshold, stairs, and landing
	Stair Handrail - Steel_Stair Handrail	#9- SW	16	LF	6	10 Lyong	entry uneshold, stalls, and landing
	Exterior Doors - Exterior Steel Door	Roof Doors	16	EA	6	10+ years	
			2	LF	6 7	10+ years	
	Exterior Stairs - Concrete	Roof Doors	б	LF	/	10+ years	
undatio	on						
	Foundation - Concrete	Entire Building	744	LF	7	10+ years	
	Foundation - Concrete	Entire Building	70	LF	4	0-1 year	Settlement of walls at NW corner of
		· ·				•	building. Doors #2 have also been
							compromised and are not closing
							properly.
	Superstructure - Steel	Entire Building	74,847	SF	7	10+ years	1 1 - 7
	Subelstructure - Steer					IUT VEGIO	

Campus Name: Burbank Page : 30 of 58 Assessment Date: 10/10/2023



Category : Exterior			В	uilding	•		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Linktin n							
Lighting	Exterior Lighting - Lighting	Entire Building	6	EA	6	10+ years	
	Exterior Lighting - Lighting	Entire Building	1	EA	5	0-1 year	Missing light cover
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	10+ years	whoshing light dovor
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	3	EΑ	5	0-1 year	Broken lamp, missing, light cover
	3 4 3 4 44	, , , , , , , , , , , , , , , , , , ,				,	3, 3, 11
Roof Sys							
	Coping - Stone	Low E roof	216	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low E roof	120	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low E roof	216	LF	6	10+ years	
	Roof - Modified Bitumen	Low E roof	5,337	SF	6	2-5 years	
	Roof Structure - Steel / Metal Deck/	Low E roof	5,337	SF	6	10+ years	
	Concrete Topping				_		
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Main Roof	69	LF	6	10+ years	
	Coping - Stone	Main Roof	568	LF	7	10+ years	
	Coping - Stone	Main Roof	200	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	513	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	708	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	60	LF	5	1-2 years	Loose membrane
	Roof - Modified Bitumen	Main Roof	23,120	SF	6	2-5 years	
	Roof - Modified Bitumen	Main Roof	50	SF	5	2-5 years	
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Main Roof	23,170	SF	7	10+ years	
	Concrete Topping						
Nalls							
	Cheek-Wall - Concrete	Entire Building	600	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	39,948	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	4,070	SF	6	10+ years	
Nindows							
MINUOWS	Curtain wall - Glazed Double Pane	Entire Building	1,132	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	5,508	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,117	LF	6	10+ years	
	Windows - Louver	Entire Building	200	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	9,844	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	80	SF	5	1-2 years	Large window in room 212 is leakir
	Timacita Gasii Alaimininin Bousie pane	Entire Building	00	Oi.	J	i z youis	water into the room, window in 226 cracked

Campus Name: Burbank Page : 31 of 58 Assessment Date: 10/10/2023



Category : Electrical

Luther Burbank Elementary School 2035 N Mobile AVENUE, Chicago, IL 60639

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergen	cy System						
-	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	31	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	20	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	5	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	3	EA	6	6-10 years	
	Security System - CCTV	Entire Building	74,847	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	74,847	SF	5	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	18,513	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	4,932	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,980	SF	6	6-10 years	
Main Ser	vice						
	Main Electrical Service - 2000 A 277/480/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	74,847	SF	5	6-10 years	
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	6-10 years	For fire
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	6-10 years	
Power Di	stribution						
	Lighting and Power Panels - Above 100 A	Electrical Room	24	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Electrical Room	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Electrical Room	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Electrical Room	3	EA	7	10+ years	
Catego	y : Fire Protection		В	uilding	: Additio		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarr	m		<u> </u>				
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Annunciator Panel
	Fire Alarm Strobe Lights	Entire Building	74,847	SF	6	6-10 years	, and locator raile
	Fire Alarm_System	Entire Building	74,847	SF	5	6-10 years	Sprinkler tamper panel needs

Building: Addition

Campus Name: Burbank Page : 32 of 58 Assessment Date: 10/10/2023



	ry : Fire Protection		B	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							replacing, bad power supply board
							per engineer
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	
Pump R	oom Assembly	F: D D				2.1	0 111 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Fire Pump - 25-50 hp	Fire Pump Room	1	EΑ	2	0-1 year	Corroded, doesn't pass fire inspection
	Jockey Pump	Fire Pump Room	1	EA	6	6-10 years	
Sprinkle	r System						
эринке	Sprinkler Heads	Entire Building	74,847	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	74,847	SF	6	6-10 years	
	Wet Sprinkler System	Entire Building	74,847	SF	6	6-10 years	
	Wet Ophilikier System	Entire Building	74,047	OI .	O	0-10 years	
Catego	ry : Mechanical		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litioning						
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	5	2-5 years	Beginning to rust heavily on one side
	than 5 tons						dated. Serves MDF room.
	Chemical Pot Feeder	Roof and Boiler Room	1	EA	6	6-10 years	
	Chiller-Air Cooled-Screw Type-Roof	Roof and Boiler Room	1	EA	6	10+ years	
	Chiller-Air Cooled-Screw Type-Roof Mounted - 201 - 300 tons	Roof and Boiler Room	1	EA	6	10+ years	
∖ir Hand	Mounted - 201 - 300 tons	Roof and Boiler Room	1		6	10+ years	
Air Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone-	Roof and Boiler Room AHU1 - 2nd Floor	1	EA EA	5	10+ years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons		·				Serves multipurpose room area
sir Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone-		·				Serves multipurpose room area
sir Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils -		·				Serves multipurpose room area
sir Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	AHU1 - 2nd Floor	1	EA	5	6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake	AHU1 - 2nd Floor AHU1 - 2nd Floor	1	EA EA	5	6-10 years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor	1 1 1	EA EA EA	5 6 6	6-10 years 6-10 years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils -	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor	1 1 1 1 2	EA EA EA EA	5 6 6 6	6-10 years 6-10 years 6-10 years 2-5 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor	1 1 1 2 1	EA EA EA EA	5 6 6 6 5	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor	1 1 2 1	EA EA EA EA	5 6 6 5	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor	1 1 1 2 1	EA EA EA EA EA	5 6 6 5 6	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years 6-10 years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor	1 1 1 2 1 1 1 1 6	EA EA EA EA EA EA	5 6 6 6 5	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years 6-10 years 2-5 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons lling Systems Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- VAV Box Air Handling Unit-Package Single Zone-	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor	1 1 1 2 1	EA EA EA EA EA	5 6 6 5 6	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years 6-10 years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils -	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor	1 1 1 2 1 1 1 1 6	EA EA EA EA EA EA	5 6 6 6 5	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years 6-10 years 2-5 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU3 - 3rd Floor	1 1 1 2 1 1 1 6	EA EA EA EA EA EA	5 6 6 6 5 6 6 5	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years 6-10 years 2-5 years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm Air Intake	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU3 - 3rd Floor	1 1 1 2 1 1 1 6	EA EA EA EA EA EA	5 6 6 6 6 5 6	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years 6-10 years 2-5 years 6-10 years 2-5 years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm Air Intake Induction Fan	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU3 - 3rd Floor AHU3 - 3rd Floor AHU3 - 3rd Floor	1 1 1 2 1 1 1 6 1	EA EA EA EA EA EA EA	5 6 6 6 6 5 6 6	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years 6-10 years 2-5 years 6-10 years 6-10 years 6-10 years	Serves multipurpose room area
Air Hand	Mounted - 201 - 300 tons Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm Air Intake Induction Fan VAV Box Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm Air Intake	AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU1 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU2 - 2nd Floor AHU3 - 3rd Floor	1 1 1 2 1 1 1 6	EA EA EA EA EA EA	5 6 6 6 6 5 6	6-10 years 6-10 years 6-10 years 2-5 years 6-10 years 6-10 years 2-5 years 6-10 years 2-5 years 6-10 years	Serves multipurpose room area

Campus Name: Burbank Page : 33 of 58 Assessment Date: 10/10/2023



Category : Mechanical			В	uilding	: Additi	on	
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Coil Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	4	EA	6	6-10 years	Serves multipurpose room, by AHU1
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	28	EA	6	6-10 years	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	6	6-10 years	Relief fan
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	6	6-10 years	Relief fan
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	5	6-10 years	Relief fan, does not provide enough flow to AHU3 at start up causing return ductwork to suction up, needs adjusting
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Roof	1	EA	6	6-10 years	adjusting
Boiler S	vstems						
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	2	EA	5	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	5	2-5 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	5	2-5 years	Burners need replacing often
	Water Fill System	Boiler Room	1	EA	6	2-5 years	
Heating	Devices						
Ū	Unit Heater - Electric	Entire Building	3	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	4	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	9	EA	6	6-10 years	
Mechani	cal Plumbing						
	Chilled Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Chilled Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	1,500	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	800	LF	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	2-5 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	2-5 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	5	2-5 years	

Page : 34 of 58 Campus Name: Burbank Assessment Date: 10/10/2023



Category : Mechanical			В	uilding	: Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	5	2-5 years	
empera	ature Control						
	DDC System	Entire Building	74,847	SF	4	1-2 years	Dated and devices not responding
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	For mechanical room exhaust fans
	Electric Thermostat	Entire Building	1	EA	5	2-5 years	
	Thermostats - DDC	Entire Building	56	EA	4	1-2 years	Damaged or not operational
/entilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	5	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	2	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EΑ	6	6-10 years	
	.,pc =aaccaag	9	·	_, .	· ·	5 .5 years	
Category : Plumbing			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
		Location	Quantity	UOIVI	Naiik	Replacement	Comments
	or						
tot vvat		Boiler Room	2	FΔ	6	10± vears	
tot vvat	er Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	10+ years	
	Gas Heater - 150000 - 300000 BTU/HR		2	EA	6	•	
	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines	Entire Building	74,847	SF	6	10+ years 10+ years	
	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Entire Building Entire Building	74,847 74,847			10+ years 10+ years	
	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines	Entire Building	74,847	SF	6	10+ years	
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building	74,847 74,847	SF SF	6 6	10+ years 10+ years	
	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures	Entire Building Entire Building Entire Building	74,847 74,847 74,847	SF SF SF	6 6 6	10+ years 10+ years 10+ years	
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building Entire Building Entire Building	74,847 74,847 74,847 74,847	SF SF SF	6 6 6	10+ years 10+ years 10+ years 10+ years	
Hot Wat	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	74,847 74,847 74,847 74,847 74,847	SF SF SF SF	6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years	
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping	Entire Building	74,847 74,847 74,847 74,847 74,847 74,847	SF SF SF SF SF	6 6 6 6 6	10+ years	
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	74,847 74,847 74,847 74,847 74,847	SF SF SF SF	6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years	
Piping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping	Entire Building	74,847 74,847 74,847 74,847 74,847 74,847 74,847	SF SF SF SF SF SF	6 6 6 6 6 6	10+ years	
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping	Entire Building	74,847 74,847 74,847 74,847 74,847 74,847 74,847	SF SF SF SF SF SF	6 6 6 6 6 6	10+ years	

Campus Name: Burbank Page : 35 of 58 Assessment Date: 10/10/2023



Category : Room			Building : Addition				2005 N Mobile AVENUE, Officago, 12 00005
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	1st - 100 Reception	10	SF	7	6-10 years	
	Ceiling - Lay-in	1st - 100 Reception	642	SF	6	6-10 years	
	Doors - Side-lite	1st - 100 Reception	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st - 100 Reception	2	ĒΑ	6	6-10 years	
	Floor - Carpet	1st - 100 Reception	224	SF	6	6-10 years	
	Floor - Terrazzo	1st - 100 Reception	428	SF	6	6-10 years	
	Lighting - Lay-in	1st - 100 Reception	10	ĒΑ	6	10+ years	
	Power Distribution	1st - 100 Reception	10	EA	6	10+ years	
	Storage/ Closet	1st - 100 Reception	16	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st - 100 Reception	1,110	SF	6	10+ years	
	Walls - Plaster/Drywall	1st - 100 Reception	1,118	SF	6	10+ years	
	Ceiling - Lay-in	1st - 100A Student Services	2	SF	7	6-10 years	
	Ceiling - Lay-in	1st - 100A Student Services	107	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st - 100A Student Services	1	EA	6	6-10 years	
	Floor - Tile	1st - 100A Student Services	109	SF	6	10+ years	
	Lighting - Lay-in	1st - 100A Student Services	2	EA	7	10+ years	
	Power Distribution	1st - 100A Student Services	12	EA	7	10+ years	
	Walls - Concrete Block	1st - 100A Student Services	548	SF	6	6-10 years	
	Work Sink	1st - 100A Student Services	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st - 100C Asst. Principle	148	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - 100C Asst. Principle	1	EA	6	6-10 years	
	Floor - Carpet	1st - 100C Asst. Principle	148	SF	6	6-10 years	
	Lighting - Lay-in	1st - 100C Asst. Principle	2	EA	7	10+ years	
	Power Distribution	1st - 100C Asst. Principle	6	EA	7	10+ years	
	Walls - Concrete Block	1st - 100C Asst. Principle	431	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st - 100C Asst. Principle	178	SF	6	6-10 years	
	Ceiling - Lay-in	1st - 100D Conference	151	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - 100D Conference	1	EA	6	6-10 years	
	Floor - Carpet	1st - 100D Conference	20	SF	7	6-10 years	All in good condition
	Floor - Carpet	1st - 100D Conference	131	SF	6	6-10 years	
	Lighting - Lay-in	1st - 100D Conference	2	EA	7	10+ years	
	Power Distribution	1st - 100D Conference	8	EA	7	10+ years	
	Walls - Concrete Block	1st - 100D Conference	435	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st - 100D Conference	178	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor - Faculty Lounge Room 102	322	SF	6	10+ years	
	Doors - Side-lite	1st Floor - Faculty Lounge Room 102	10	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor - Faculty Lounge Room 102	1	EA	6	6-10 years	
	Floor - Carpet	1st Floor - Faculty Lounge Room 102	322	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor - Faculty Lounge Room	4	EA	7	10+ years	

Campus Name: Burbank Page : 36 of 58 Assessment Date: 10/10/2023



Category : Room			Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Dance Distribution	102	40	- ^	0	40			
	Power Distribution	1st Floor - Faculty Lounge Room 102	10	EA	6	10+ years			
	Walls - Concrete Block	1st Floor - Faculty Lounge Room	450	SF	6	10+ years			
	Walls - Plaster/Drywall	102 1st Floor - Faculty Lounge Room	450	SF	6	6-10 years			
	·	102	+30	OI	U	0-10 years			
	Work SInk	1st Floor - Faculty Lounge Room 102	1	EA	7	6-10 years			
	Ceiling - Lay-in	1st- 122B Kitchen Manager Office	51	SF	6	10+ years			
	Doors - Side-lite	1st- 122B Kitchen Manager Office	25	SF	7	6-10 years			
	Doors - Steel Doors incl hw	1st- 122B Kitchen Manager Office	1	EA	6	6-10 years			
	Floor - Tile	1st- 122B Kitchen Manager Office	51	SF	6	10+ years			
	Lighting - Lay-in	1st- 122B Kitchen Manager Office	1	EA	7	10+ years			
	Power Distribution	1st- 122B Kitchen Manager Office	2	EA	7	10+ years			
	Walls - Concrete Block	1st- 122B Kitchen Manager Office	264	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor - 204A Workroom	210	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor - 204A Workroom	1	EA	6	6-10 years			
	Floor - Tile	2nd Floor - 204A Workroom	210	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor - 204A Workroom	3	EA	6	10+ years			
	Power Distribution	2nd Floor - 204A Workroom	12	EA	7	10+ years			
	Storage/ Closet	2nd Floor - 204A Workroom	60	SF	7	6-10 years			
	Walls - Concrete Block	2nd Floor - 204A Workroom	175	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor - 204A Workroom	520	SF	6	10+ years			
	Work SInk	2nd Floor - 204A Workroom	1	EA	7	6-10 years			
	Ceiling - Lay-in	2nd- Rm 228 Maintenance Office	307	SF	6	10+ years			
	Ceiling - Lay-in	2nd- Rm 228 Maintenance Office	56	SF	4	1-2 years	Missing ceiling tiles, corrected quantity		
	Doors - Steel Doors incl hw	2nd- Rm 228 Maintenance Office	2	EA	7	6-10 years	quantity		
	Floor - Tile	2nd- Rm 228 Maintenance Office	363	SF	6	10+ years			
	Lighting - Lay-in	2nd- Rm 228 Maintenance Office	6	EA	7	10+ years			
	Power Distribution	2nd- Rm 228 Maintenance Office	8	EA	7	10+ years			
	Walls - Concrete Block	2nd- Rm 228 Maintenance Office	990	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor - Office/Storage Room 330	320	SF	6	6-10 years			
	Doors - Side-lite	3rd Floor - Office/Storage Room 330	10	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	3rd Floor - Office/Storage Room 330	1	EA	6	6-10 years			
	Floor - Tile	3rd Floor - Office/Storage Room 330	320	SF	6	6-10 years			
	Lighting - Lay-in	3rd Floor - Office/Storage Room 330	4	EA	6	6-10 years			
	Power Distribution	3rd Floor - Office/Storage Room 330	8	EA	6	6-10 years			
	Walls - Concrete Block	3rd Floor - Office/Storage Room 330	858	SF	6	6-10 years			
Kitchen									
THICHEIL	Ceiling - Lay-in	122A Kitchen	1,259	SF	6	10+ years			
	Doors - Steel Doors incl hw	122A Kitchen	1,233	EA	6	6-10 years			
			•		-				

Campus Name: Burbank Page : 37 of 58 Assessment Date: 10/10/2023



Catego	ry : Room	Building : Addition					
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Epoxy/ Painted	122A Kitchen	1,259	SF	7	10+ years	
	Lighting - Lay-in	122A Kitchen	12	EA	7	10+ years	
	Storage/ Closet	122A Kitchen	110	SF	7	6-10 years	
	Walls - Concrete Block	122A Kitchen	1,368	SF	7	10+ years	
	Ceiling - Lay-in	1st- Rm 122A Servery	740	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st- Rm 122A Servery	5	EΑ	6	6-10 years	
	Floor - Tile	1st- Rm 122A Servery	740	SF	6	10+ years	
	Lighting - Lay-in	1st- Rm 122A Servery	10	EA	7	10+ years	
	Serving Line	1st- Rm 122A Servery	45	LF	7	6-10 years	
	Walls - Concrete Block	1st- Rm 122A Servery	985	SF	6	10+ years	
Library							
,	Casework	2nd Floor	170	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	2,255	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	20	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	6-10 years	
	Floor - Carpet	2nd Floor	2,255	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	30	ĒΑ	6	10+ years	
	Walls - Concrete Block	2nd Floor	1,710	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	570	SF	6	10+ years	
Locker/S	Shower Room						
	Benches, ped mounted	1st- 122l Kitchen Staff Locker Rm	3	LF	6	6-10 years	
	Ceiling - Lay-in	1st- 122l Kitchen Staff Locker Rm	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st- 122l Kitchen Staff Locker Rm	1	EΑ	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st- 122l Kitchen Staff Locker Rm	32	SF	7	10+ years	
	Lighting - Lay-in	1st- 122l Kitchen Staff Locker Rm	1	EA	7	10+ years	
	Student Lockers - Two Tier	1st- 122l Kitchen Staff Locker Rm	10	EA	6	6-10 years	
	Walls - Structural Glazed Tile	1st- 122I Kitchen Staff Locker Rm	207	SF	7	10+ years	
	Benches, ped mounted	1st- 122J Kitchen Staff Locker Rm	3	LF	6	6-10 years	
	Ceiling - Lay-in	1st- 122J Kitchen Staff Locker Rm	36	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st- 122J Kitchen Staff Locker Rm	1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st- 122J Kitchen Staff Locker Rm	36	SF	7	10+ years	
	Lighting - Lay-in	1st- 122J Kitchen Staff Locker Rm	1	EA	7	10+ years	
	Student Lockers - Two Tier	1st- 122J Kitchen Staff Locker Rm	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st- 122J Kitchen Staff Locker Rm	227	SF	7	10+ years	
Lunch &	Multipurpose Room						
<u> </u>	Ceiling - Exposed	1st Floor	4,932	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4,932	EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	4,932	SF	7	•	
	Lighting - Pendent/Surface	1st Floor	4,932	EA	7	10+ years 10+ years	
	Storage/ Closet	1st Floor	290	SF	7	6-10 years	
	Storage/ Closet	191 LIOOI	290	SF	,	o- to years	

Campus Name: Burbank Page : 38 of 58 Assessment Date: 10/10/2023



Category : Room			B	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	10,947	SF	6	10+ years	
MDF_ID							
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Finishes	2nd Floor	291	SF	7	6-10 years	
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Building AC
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	40	SF	5	10+ years	Mold on broken tiles
	Mechanical/ Service Rooms	1st Floor	622	SF	7	10+ years	
	Vaults	1st Floor	448	SF	7	6-10 years	
	Janitor's Closet	2nd Floor	41	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	2,619	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	160	SF	7	10+ years	
	Janitor's Closet	3rd Floor	42	SF	7	10+ years	In good condition
	Mechanical/ Service Rooms	3rd Floor	160	SF	7	10+ years	9
	Mechanical/ Service Rooms	3rd Floor	2,489	SF	5	10+ years	Needs cleaning, mostly the floor
	Storage Room	3rd Floor	290	SF	7	10+ years	In good condition
D t						•	·
Restroor		1 at incide 100 Decention	20	SF	7	6.10 vooro	
	Accessories	1st - inside 100 Reception	39	SF SF	7	6-10 years	
	Ceiling - Lay-in	1st - inside 100 Reception	39		6	10+ years	
	Doors - Wood Doors inclu hw	1st - inside 100 Reception	1	EA	6	6-10 years	
	Floor - Tile	1st - inside 100 Reception	39	SF	6	10+ years	
	Floor Drain	1st - inside 100 Reception	1	EΑ	7	6-10 years	
	Lavatory	1st - inside 100 Reception	1	EA	6	6-10 years	
	Lighting - Lay-in	1st - inside 100 Reception	1	EA	7	10+ years	
	Walls - Concrete Block	1st - inside 100 Reception	235	SF	6	10+ years	
	Water Closet	1st - inside 100 Reception	1	EA	6	6-10 years	
	Accessories	1st - inside 110	42	SF	7	6-10 years	
	Ceiling - Lay-in	1st - inside 110	2	SF	7	6-10 years	
	Ceiling - Lay-in	1st - inside 110	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - inside 110	1	EA	6	6-10 years	
	Floor - Tile	1st - inside 110	42	SF	6	10+ years	
	Floor Drain	1st - inside 110	1	EA	7	6-10 years	
	Lavatory	1st - inside 110	1	EA	6	6-10 years	
	Lighting - Lay-in	1st - inside 110	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st - inside 110	243	SF	7	10+ years	
	Water Closet	1st - inside 110	1	EA	6	6-10 years	
	Accessories	1st - inside 118	42	SF	7	6-10 years	
	Ceiling - Lay-in	1st - inside 118	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - inside 118	1	EA	6	6-10 years	
	Floor - Tile	1st - inside 118	38	SF	6	10+ years	

Campus Name: Burbank Page : 39 of 58 Assessment Date: 10/10/2023



Category : Room			Building : Addition						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	1st - inside 118	4	SF	4	1-2 years	Still cracked by drain		
	Floor Drain	1st - inside 118	1	EA	7	6-10 years			
	Lavatory	1st - inside 118	1	EA	6	6-10 years			
	Lighting - Lay-in	1st - inside 118	1	EΑ	7	10+ years			
	Walls - Structural Glazed Tile	1st - inside 118	243	SF	7	10+ years			
	Water Closet	1st - inside 118	1	EA	6	6-10 years			
	Accessories	1st Floor	232	SF	7	6-10 years			
	Accessories	1st Floor	5	SF	5	1-2 years	Broken soap dispenser, broken trash		
			_		•	,	receptacle, leaky toilet		
	Ceiling - Plaster/Drywall	1st Floor	237	SF	6	10+ years	•		
	Floor - Terrazzo	1st Floor	237	SF	6	10+ years			
	Floor Drain	1st Floor	2	EA	7	6-10 years			
	Lavatory	1st Floor	3	EΑ	6	6-10 years			
	Lighting - Lay-in	1st Floor	4	EA	7	10+ years			
	Partitions	1st Floor	5	EA	7	6-10 years			
	Walls - Structural Glazed Tile	1st Floor	597	SF	7	10+ years			
	Water Closet	1st Floor	5	EA	6	6-10 years			
	Accessories	1st Floor	53	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	53	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	6-10 years			
	Floor - Terrazzo	1st Floor	53	SF	6	10+ years			
	Floor Drain	1st Floor	1	EA	7	6-10 years			
	Lavatory	1st Floor	1	EΑ	6	6-10 years			
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	232	SF	6	10+ years			
	Water Closet	1st Floor	1	EA	6	6-10 years			
	Accessories	1st Floor	238	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	238	SF	6	6-10 years			
	Floor - Terrazzo	1st Floor	238	SF	6	10+ years			
	Floor Drain	1st Floor	230	EA	7	6-10 years			
	Lavatory	1st Floor	3	EA	6	6-10 years			
	Lighting - Lay-in	1st Floor	4	EA	7	10+ years			
	Partitions	1st Floor	2	EA	7	6-10 years			
	Urinals	1st Floor	3	EA	6	6-10 years			
	Walls - Structural Glazed Tile	1st Floor	597	SF	7	10+ years			
	Water Closet	1st Floor	2	EA	6	6-10 years			
	Accessories	1st-Inside Rm 112	60	SF	7	6-10 years			
				SF		•			
	Ceiling - Lay-in Doors - Wood Doors inclu hw	1st-Inside Rm 112	60 1	SF EA	7 6	10+ years			
	Floor - Tile	1st- Inside Rm 112		SF		6-10 years			
		1st- Inside Rm 112	60		6	10+ years			
	Floor Drain	1st- Inside Rm 112	1	EΑ	7	6-10 years			
	Lavatory	1st- Inside Rm 112	1	EΑ	6	6-10 years			
	Lighting - Lay-in	1st- Inside Rm 112	1	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st- Inside Rm 112	247	SF	7	10+ years			



Catego	Category : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st- Inside Rm 112	1	EA	6	6-10 years	
	Accessories	1st- Inside Rm 114	60	SF	7	6-10 years	
	Ceiling - Lay-in	1st- Inside Rm 114	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 114	1	EA	6	6-10 years	
	Floor - Tile	1st- Inside Rm 114	60	SF	7	6-10 years	
	Floor Drain	1st- Inside Rm 114	1	EA	7	6-10 years	
	Lavatory	1st- Inside Rm 114	1	EA	7	6-10 years	
	Lighting - Lay-in	1st- Inside Rm 114	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st- Inside Rm 114	247	SF	7	10+ years	
	Water Closet	1st- Inside Rm 114	1	EA	7	6-10 years	
	Accessories	1st- Inside Rm 116	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Inside Rm 116	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 116	1	ĒA	6	6-10 years	
	Floor - Tile	1st- Inside Rm 116	60	SF	6	10+ years	
	Floor Drain	1st- Inside Rm 116	1	EA	7	6-10 years	
	Lavatory	1st- Inside Rm 116	1	EΑ	6	6-10 years	
	Lighting - Lay-in	1st- Inside Rm 116	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st- Inside Rm 116	247	SF	7	10+ years	
	Water Closet	1st- Inside Rm 116	1	EA	6	6-10 years	
	Accessories	1st- Inside Rm 120	60	SF	7	6-10 years	
	Ceiling - Lay-in	1st- Inside Rm 120	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 120	1	EA	6	6-10 years	
	Floor - Tile	1st- Inside Rm 120	60	SF	6	10+ years	
	Floor Drain	1st- Inside Rm 120	1	EA	7	6-10 years	
	Lavatory	1st- Inside Rm 120	1	EA	6	6-10 years	
	Lighting - Lay-in	1st- Inside Rm 120	1	EA	7	-	
	Walls - Structural Glazed Tile	1st- Inside Rm 120	247	SF	7	10+ years 10+ years	
	Water Closet	1st- Inside Rm 120	1	EA	6	,	
	Accessories	1st- Kitchen Staff Toilet	44	SF	7	6-10 years	
		1st- Kitchen Staff Toilet	44	SF SF		6-10 years	
	Ceiling - Lay-in Doors - Steel Doors incl hw	1st- Kitchen Staff Toilet	1	Sr EA	7	10+ years	
			="	SF	6 7	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st- Kitchen Staff Toilet	44			10+ years	
	Floor Drain	1st- Kitchen Staff Toilet	1	EΑ	7	6-10 years	
	Lavatory	1st- Kitchen Staff Toilet	1	EΑ	6	6-10 years	
	Lighting - Lay-in	1st- Kitchen Staff Toilet	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st- Kitchen Staff Toilet	115	SF	7	10+ years	
	Water Closet	1st- Kitchen Staff Toilet	1	EA	6	6-10 years	
	Accessories	2nd Floor	53	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	53	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Terrazzo	2nd Floor	53	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	1	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years	



Catego	ry : Room		В	Building : Addition						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Structural Glazed Tile	2nd Floor	232	SF	7	10+ years				
	Water Closet	2nd Floor	1	EA	6	6-10 years				
	Accessories	2nd Floor	237	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	237	SF	6	10+ years				
	Floor - Terrazzo	2nd Floor	237	SF	6	10+ years				
	Floor Drain	2nd Floor	2	EA	7	6-10 years				
	Lavatory	2nd Floor	3	EA	6	6-10 years				
	Lighting - Lay-in	2nd Floor	4	EA	7	10+ years				
	Partitions	2nd Floor	5	EA	7	6-10 years				
	Walls - Structural Glazed Tile	2nd Floor	597	SF	7	10+ years				
	Water Closet	2nd Floor	5	EA	6	6-10 years				
	Accessories	2nd Floor	238	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	238	SF	6	10+ years				
	Floor - Terrazzo	2nd Floor	238	SF	6	10+ years				
	Floor Drain	2nd Floor	2	EA	7	6-10 years				
	Lavatory	2nd Floor	3	EA	6	6-10 years				
	Lighting - Lay-in	2nd Floor	4	EA	7	10+ years				
	Partitions	2nd Floor	2	EA	7	6-10 years				
	Urinals	2nd Floor	3	EA	6	6-10 years				
	Walls - Structural Glazed Tile	2nd Floor	597	SF	7	10+ years				
	Water Closet	2nd Floor	2	EA	6	6-10 years				
	Accessories	3rd Floor	235	SF	7	6-10 years				
	Accessories	3rd Floor	2	SF	5	6-10 years	Feminine napkin dispenser dented			
	Ceiling - Plaster/Drywall	3rd Floor	237	SF	6	6-10 years	• •			
	Floor - Terrazzo	3rd Floor	237	SF	6	6-10 years				
	Floor Drain	3rd Floor	2	EA	7	6-10 years				
	Lavatory	3rd Floor	3	EA	6	6-10 years				
	Lighting - Lay-in	3rd Floor	4	EA	7	6-10 years				
	Partitions	3rd Floor	5	EA	5	6-10 years	Heavy wear and tear			
	Walls - Structural Glazed Tile	3rd Floor	597	SF	6	6-10 years	,			
	Water Closet	3rd Floor	5	EA	6	6-10 years				
	Accessories	3rd Floor	237	SF	7	6-10 years				
	Accessories	3rd Floor	1	SF	5	6-10 years	Missing soap dispenser			
	Ceiling - Plaster/Drywall	3rd Floor	238	SF	6	6-10 years	0 1 1			
	Floor - Terrazzo	3rd Floor	238	SF	6	6-10 years				
	Floor Drain	3rd Floor	2	EA	7	6-10 years				
	Lavatory	3rd Floor	3	EA	6	6-10 years				
	Lighting - Lay-in	3rd Floor	4	EA	6	6-10 years				
	Partitions	3rd Floor	2	ΕA	7	6-10 years	In good condition			
	Urinals	3rd Floor	3	EA	6	6-10 years	9			
	Walls - Structural Glazed Tile	3rd Floor	597	SF	6	6-10 years				
	Water Closet	3rd Floor	2	EΑ	6	6-10 years				
	Accessories	3rd Floor Unisex	53	SF	7	6-10 years	All accessories in good condition			
	Ceiling - Lay-in	3rd Floor Unisex	53	SF	6	6-10 years	gera emana.			
	5 -7				-	,				

Campus Name: Burbank Page : 42 of 58 Assessment Date: 10/10/2023



Category : Room			Building : Addition						
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Doors - Wood Doors inclu hw	3rd Floor Unisex	1	EΑ	6	6-10 years			
	Floor - Terrazzo	3rd Floor Unisex	53	SF	6	6-10 years			
	Floor Drain	3rd Floor Unisex	1	EA	7	6-10 years			
	Lavatory	3rd Floor Unisex	1	EA	6	6-10 years			
	Lighting - Lay-in	3rd Floor Unisex	1	EA	6	6-10 years			
	Walls - Structural Glazed Tile	3rd Floor Unisex	232	SF	6	6-10 years			
	Water Closet	3rd Floor Unisex	1	EA	6	6-10 years			
Catego	ory : Classroom		В	uilding	: Additi	on			
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classro	om #104 (Regular Classroom)								
	Casework	1st Floor	35	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	8	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	877	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	885	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years			
	Marker Board	1st Floor	10	LF	7	10+ years			
	Walls - Concrete Block	1st Floor	10	SF	6	1-2 years	Large crack in outside wall		
	Walls - Concrete Block	1st Floor	907	SF	6	10+ years	g		
	Walls - Plaster/Drywall	1st Floor	372	SF	6	10+ years			
_Classro	om #106 (Regular Classroom)								
	Casework	1st Floor	35	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	908	SF	6	10+ years			
	Doors - Side-lite	1st Floor	8	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	908	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years			
	Marker Board	1st Floor	10	LF	7	6-10 years			
	Walls - Concrete Block	1st Floor	940	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	372	SF	6	10+ years			
Classro	om #110 (Kindergarten)								
	Casework	1st Floor	52	LF	6	10+ years			
	Casework Ceiling - Lay-in	1st Floor	20	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	1,094	SF	6	10+ years			
	Doors - Side-lite	1st Floor	1,094	SF	6	10+ years			
	Doors - Side-life Doors - Wood Doors inclu hw	1st Floor	0	EA	6	10+ years			
			•	SF	-	•			
	Floor - Tile	1st Floor	1,114		6	10+ years			
	Lighting - Lay-in	1st Floor	17	EA	7	10+ years			
	Marker Board	1st Floor	16	LF	7	6-10 years			

Campus Name: Burbank Page : 43 of 58 Assessment Date: 10/10/2023



Catego	ry : Classroom		В	uilding	: Addition	on	
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	48	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,189	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	281	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	Quantity change since there are 2
	Work Sink	1st Floor	1	EA	5	1-2 years	total sinks and 1 water fountain Leaky sink
Classroc	om #112 (Kindergarten)						
	Ceiling - Lay-in	1st Floor	1,057	SF	6	10+ years	
	Doors - Side-lite	1st Floor	10	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	1,057	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17,037	EA	6	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	47	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,236	SF	6	•	
	Walls - Plaster/Drywall	1st Floor	312	SF		10+ years	
	Work Sink	1st Floor	2	EA	6 7	10+ years 6-10 years	
Classroc	om #114 (Kindergarten)						
	Casework	2nd Floor	32	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,040	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,040	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	17	ĒΑ	6	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	775	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	775	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
Classroo	om #116 (Pre School)						
	Ceiling - Lay-in	1st Floor	2	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,055	SF	6	10+ years	
	Doors - Side-lite	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	6	10+ years	
	Floor - Tile	1st Floor	1,057	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	1,057	EA	7	10+ years	
	Marker Board	1st Floor		LF	7		
		1st Floor 1st Floor	16 47	SF	-	6-10 years	
	Storage/ Closet				7	10+ years	
	Walls - Concrete Block	1st Floor	1,236	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	312	SF	6	10+ years	

Campus Name: Burbank Page : 44 of 58 Assessment Date: 10/10/2023



Category : Classroom			В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #118 (Kindergarten)						
	Casework	1st Floor	52	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	2	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,151	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,153	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	ĒΑ	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	48	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,223	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	281	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	Updated the quantity since one is a
	Work Sink	1st Floor	1	EA	5	1-2 years	drinking fountain. Not working sink
Classroo	m #120 (Pre School)						
	Ceiling - Lay-in	1st Floor	1,057	SF	6	10+ years	
	Doors - Side-lite	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,057	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	47	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,236	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	312	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	m #200 (Regular Classroom)						
	Casework	2nd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	830	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	6	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	690	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	690	SF	6	10+ years	
Classroo	m #206 (Regular Classroom)						



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	830	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,035	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	345	SF	6	10+ years	
Classroo	om #210 (Special Education)						
	Casework	2nd Floor	23	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	585	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	585	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	•	
	Marker Board	2nd Floor	24	LF	7	10+ years	
				SF		6-10 years	
	Walls - Concrete Block	2nd Floor	545	SF SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	600	SF	6	10+ years	
Classroc	om #212 (Regular Classroom)						
	Casework	2nd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	830	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	690	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	690	SF	6	10+ years	
Classroc	om #214 (Special Program)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	585	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	585	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor 2nd Floor	24 448	SF	<i>7</i> 6	10+ years	



Catego	Category : Classroom		В	uilding		2000 N Mobile Avenue, Officago, 12 00000	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	643	SF	6	10+ years	
Classro	om #216 (Regular Classroom)						
<u> </u>	Casework	2nd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	830	SF	7	10+ years	
		2nd Floor	12	EA	6	•	
	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	20	LF	7	10+ years 6-10 years	
		2nd Floor 2nd Floor	30	SF	7		
	Storage/ Closet					10+ years	
	Walls - Concrete Block	2nd Floor	690	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	690	SF	6	10+ years	
Classroo	om #218 (Special Program)						
	Casework	2nd Floor	23	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	585	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	585	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	545	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	600	SF	7	10+ years	
Classro	om #220 (Regular Classroom)						
Ciassion	Casework	2nd Floor	34	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	•	
	Floor - Tile	2nd Floor	· · · · · · · · · · · · · · · · · · ·	SF	7	10+ years	
		2nd Floor	820	EA	6	10+ years	
	Lighting - Lay-in Marker Board		12		_	10+ years	
	Storage/ Closet	2nd Floor 2nd Floor	20 30	LF SF	7 7	6-10 years	
						10+ years	
	Walls - Concrete Block	2nd Floor	688	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	688	SF	6	10+ years	
_Classroo	om #222 (Regular Classroom)						
	Casework	2nd Floor	34	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	885	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	885	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	10+ years	
	- •					·	



Catego	ry : Classroom	Building : Addition					
	_		_			Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,378	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	643	SF	6	10+ years	
Classroo	om #224 (Regular Classroom)						
	Casework	2nd Floor	34	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	6	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	688	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	688	SF	6	10+ years	
	walls - Flaster/Drywall	2110 F1001	000	SF	O	10+ years	
Classroo	om #226 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	1-2 years	Broken, sagging doors
	Casework	2nd Floor	28	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	885	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	885	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,378	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	643	SF	6	10+ years	
Classroo	om #300 (Regular Classroom)						
Ciassion	Casework	3rd Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	10	EA	6		
			· · · · · · · · · · · · · · · · · · ·		-	10+ years	
	Floor - Tile	3rd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	172	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	700	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	700	SF	6	10+ years	
Classroo	om #302 (Art Room)						
	Casework	3rd Floor	54	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,035	SF	6	10+ years	
		5.455	.,500	٥.	Ŭ	. o . youro	



Catego	ry : Classroom	В	uilding	2033 N MODILE AVENUE, CHICAGO, IL 60639			
90	,		_				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,035	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	['] 12	EA	6	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	125	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,158	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	386	SF	7	10+ years	
	Work Sink	3rd Floor	2	ĒΑ	7	10+ years	
_Classroo	om #304 (Regular Classroom)						
	Casework	3rd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	900	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,440	SF	6	10+ years	
_Classroo	om #306 (Regular Classroom)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	830	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	830	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	6	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	690	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	690	SF	6	10+ years	
Classroo	om #310 (Regular Classroom)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	830	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	830	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	690	SF	6	10+ years	



Catego	ry : Classroom	В	uilding	<u> </u>			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	690	SF	6	10+ years	
Classro	om #312 (Regular Classroom)						
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	885	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	885	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,378	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	643	SF	6	10+ years	
Classro	om #314 (Regular Classroom)						
_01833100	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	830	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	10	EA	6	10+ years	
	Floor - Tile	3rd Floor	830	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	690	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	690	SF	6	10+ years	
Classro	om #316 (Regular Classroom)						
Classiu	Casework	3rd Floor	38	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	885	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	10+ years	
	Floor - Tile	3rd Floor	885	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	735	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	595	SF	6	10+ years	
Classro	om #318 (Special Program)						
_Cid55iU	Casework	3rd Floor	24	LF	6	10± voors	
	Casework Ceiling - Lay-in	3rd Floor	585	SF	6	10+ years 10+ years	
	Doors - Side-lite			SF SF		•	
	Doors - Side-lite Doors - Wood Doors inclu hw	3rd Floor 3rd Floor	10	SF EA	6	10+ years	
			1 585	SF	6	10+ years	
	Floor - Tile	3rd Floor		SF EA	6 7	10+ years	
	Lighting - Lay-in	3rd Floor	9	ĽΑ	1	10+ years	

Campus Name: Burbank Page : 50 of 58 Assessment Date: 10/10/2023



Category : Classroom			В	on			
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,164	SF	6	10+ years	
lassroc	om #320 (Regular Classroom)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	830	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	830	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	6	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	690	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	690	SF	6	10+ years	
	vvalis - i lastei/Diywali	310 1 1001	090	OI.	U	10+ years	
lassroc	om #322 (Science Classroom)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,610	SF	6	10+ years	Quantity increased: Prep room
							removed and combined with
							classroom
	Doors - Side-lite	3rd Floor	40	SF	6	10+ years	Quantity increased: Prep room
						•	removed and combined with
							classroom
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	10+ years	Quantity increased: Prep room
						, , , , ,	removed and combined with
							classroom
	Floor - Tile	3rd Floor	1,610	SF	6	10+ years	Quantity increased: Prep room
	11001 1110	0.01.001	1,010	O.	·	ioi youlo	removed and combined with
							classroom
	Lighting - Lay-in	3rd Floor	18	EA	7	10+ years	Classicom
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	8	SF	7	10+ years	
	Walls - Concrete Block		_	SF SF	<i>7</i> 6		Quantity ingranged, Dress
	walls - Concrete Block	3rd Floor	1,735	5F	О	10+ years	Quantity increased: Prep room
							removed and combined with
	\\	0.15		0=	_	40	classroom
	Walls - Plaster/Drywall	3rd Floor	685	SF	6	10+ years	Quantity increased: Prep room
							removed and combined with
							classroom
	Work Sink	3rd Floor	2	EA	7	10+ years	
lassroc	om #324 (Regular Classroom)						
-	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	830	SF	6	10+ years	
	Coming Lay III	010 1 1001	330	01	J	ioi yeais	



Catego	ry : Classroom	В	Building : Addition							
				Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Side-lite	3rd Floor	10	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years				
	Floor - Tile	3rd Floor	830	SF	6	10+ years				
	Lighting - Lay-in	3rd Floor	12	EΑ	6	10+ years				
	Marker Board	3rd Floor	20	LF	7	6-10 years				
	Storage/ Closet	3rd Floor	30	SF	7	10+ years				
	Walls - Concrete Block	3rd Floor	520	SF	6	10+ years				
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years				
	•					,				

Category : Interior **Building** · Addition

Category : Interior			В	Building : Addition					
						Recommend	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Lay-in	1st Floor	4,581	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	2,100	SF	6	10+ years			
	Doors - Side-lite	1st Floor	189	SF	6	6-10 years			
	Doors - Steel Doors incl hw	1st Floor	12	EA	6	6-10 years			
	Doors - Store Front	1st Floor	3	EA	6	6-10 years			
	Doors - Transom Window	1st Floor	158	SF	6	6-10 years			
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years			
	Floor - Terrazzo	1st Floor	6,988	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	191	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	5	EA	7	10+ years			
	Lighting - Wall Mounted	1st Floor	17	EA	7	10+ years			
	Stairs - Terrazzo	1st Floor	26	LF	6	6-10 years			
	Walls - Concrete Block	1st Floor	3,150	SF	6	10+ years			
	Walls - Masonry	1st Floor	3,531	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	4,594	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor	6,446	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	4,793	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	12	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	10	EA	6	6-10 years			
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	Fountain in good condition		
	Floor - Terrazzo	2nd Floor	5,424	SF	6	10+ years	3		
	Lighting - Lay-in	2nd Floor	172	EA	7	10+ years			
	Stairs - Terrazzo	2nd Floor	6	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	420	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	425	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	6,230	SF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	5,115	SF	6	6-10 years			
	Ceiling - Lay-in	3rd Floor	16	SF	5	1-2 years	water damage		
	Ceiling - Plaster/Drywall	3rd Floor	97	SF	6	6-10 years			
	Doors - Steel Doors incl hw	3rd Floor	10	EA	6	6-10 years			
	Drinking Fountains - Single Fountain	3rd Floor	2	EΑ	7	6-10 years	In working condition		

Campus Name: Burbank Page : 52 of 58 Assessment Date: 10/10/2023



Catego	ry : Interior	Building : Addition						
			Recommen					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Terrazzo	3rd Floor	5,228	SF	6	6-10 years		
	Lighting - Lay-in	3rd Floor	172	EA	6	6-10 years		
	Walls - Concrete Block	3rd Floor	417	SF	6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	495	SF	6	6-10 years		
	Walls - Structural Glazed Tile	3rd Floor	6,229	SF	6	6-10 years		
Safety								
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	All in working order	
	Security Cameras	1st Floor	3	EA	7	6-10 years	All in working order	
Stairs								
	Ceiling - Lay-in	Center - adjacent to Bathrooms	375	SF	6	6-10 years		
	Ceiling - Lay-in	Center - adjacent to Bathrooms	20	SF	4	1-2 years	Water damage	
	Floor - Terrazzo	Center - adjacent to Bathrooms	291	SF	6	6-10 years		
	Handrails	Center - adjacent to Bathrooms	172	LF	7	6-10 years		
	Lighting - Lay-in	Center - adjacent to Bathrooms	7	EA	7	10+ years	Quantity updated to include all light in stairwell	
	Lighting - Lay-in	Center - adjacent to Bathrooms	3	EA	6	6-10 years	3 sets of bulbs need replacing	
	Lighting - Wall Mounted	Center - adjacent to Bathrooms	1	EA	7	10+ years	a construction of the same	
	Stairs - Terrazzo	Center - adjacent to Bathrooms	76	LF	6	6-10 years		
	Walls - Concrete Block	Center - adjacent to Bathrooms	1,350	SF	6	10+ years		
	Ceiling - Lay-in	North East	375	SF	6	6-10 years		
	Ceiling - Lay-in	North East	10	SF	4	0-1 year	Water damage and missing tiles	
	Floor - Terrazzo	North East	291	SF	6	10+ years	Trator damage and Imporing mod	
	Handrails	North East	172	LF	7	6-10 years		
	Lighting - Lay-in	North East	6	EA	7	6-10 years	Quantity updated to include all stairwell lights	
	Lighting - Lay-in	North East	4	EA	6	6-10 years	4 stairwell lights are out	
	Lighting - Wall Mounted	North East	1	EΑ	7	10+ years	r stall Woll lights are out	
	Stairs - Terrazzo	North East	76	LF	6	6-10 years		
	Walls - Concrete Block	North East	1,350	SF	6	10+ years		
	Ceiling - Lay-in	North West	375	SF	6	6-10 years		
	Ceiling - Lay-in	North West	20	SF	4	1-2 years	Water damage	
	Floor - Terrazzo	North West	291	SF	6	10+ years	Water damage	
	Handrails	North West	172	LF	7	6-10 years		
	Lighting - Lay-in	North West	9	EA	7	10+ years	Quantity updated to include all light	
					_	-	in stairwell	
	Lighting - Lay-in	North West	1	EA	6	6-10 years	Lights are out	
	Lighting - Wall Mounted	North West	1	EA	7	10+ years		
	Stairs - Terrazzo	North West	76	LF	6	6-10 years		
	Walls - Concrete Block	North West	1,350	SF	6	10+ years		

Campus Name: Burbank Page : 53 of 58 Assessment Date: 10/10/2023



Building: Addition Category: Interior

Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Elevator - Hydraulic Elevator South West EΑ 6-10 years 6

Campus Name: Burbank Page : 54 of 58 Assessment Date: 10/10/2023



Category : Site Building : Site

Catego	ry : Site		В	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	18	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	0-1 year	Catch basin on street at entrance to
	Civili Brainage Catori Basin	Littine Oile	•	L/\	7	o i yeai	the parking lot is collapsed
	Civil/ Drainage - Site Drain	Entire Site	5	EA	6	10+ years	the parking lot to collapsed
	Civil/ Drainage - Site Manhole	Entire Site	14	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	5	0-1 year	Loose manhole cover
	Civili Brainage Cito Mannole	Emile Cité	•		J	o i youi	Loode marmore cover
_Fencina							
rending	Fencing - Chain Link	Entire Site	78	LF	7	10	
		Entire Site	20	LF	7 7	10+ years	
	Fencing - Chain Link		500	LF		10+ years	Correded demand old force
	Fencing - Chain Link	Entire Site		LF LF	5	2-5 years	Corroded, damaged old fence
	Fencing - New Standard Ornamental	Entire Site Entire Site	2,028 32	LF LF	6 5	10+ years	Draken fence penal demaged gets
	Fencing - New Standard Ornamental	Entire Site	32	LF	5	1-2 years	Broken fence, panel, damaged gate
_Landsca	ine						
	Landscape - Grass	Entire Site	164,665	SF	6	10+ years	
	Landscape - Grass	Entire Site	1,000	SF	5	1-2 years	Bare, damaged soil
	Landscape - Hardscape- Concrete	Entire Site	8,973	SF	6	10+ years	- s,g
	Lighting - Lighting	Entire Site	9	ĒΑ	6	10+ years	
	Lighting - Lighting	Entire Site	1	EA	6	1-2 years	Broken light fixture near door, one, at
	gggg		·		ŭ	/ ca.c	retaining wall
	Parkway trees	Entire Site	32	EA	6	10+ years	3
	Parkway trees	Entire Site	2	EA	4	1-2 years	Dead trees
	Planting Beds/ Area	Entire Site	5,000	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	8,444	SF	4	0-1 year	Badly damaged asphalt, large cracks,
	, , ,		,			,	alligatored throughout
	Retaining Wall - Concrete	Entire Site	800	SF	6	10+ years	S S
	Retaining Wall - Concrete	Entire Site	200	SF	5	1-2 years	Cracks at foundation walls
	-					•	
Parking					_		
	Concrete Curbs	South East	2,257	LF . –	6	10+ years	
	Concrete Curbs	South East	10	LF	6	1-2 years	Broken concrete
	Interior Plantings	South East	50	LF	6	10+ years	
	Surface - Asphalt	South East	19,468	SF	6	10+ years	
	Surface - Asphalt	South East	9,793	SF	5	6-10 years	Cracks throughout
	Trash Compactor	South East	1	EA	6	10+ years	
	Trash Enclosure - Chain Links	South East	226	SF	7	10+ years	
	Trash Enclosure - Masonry	South East	344	SF	7	10+ years	
	Trash Enclosure - Masonry	South East	25	SF	5	1-2 years	Open joints at coping
	Concrete Curbs	South West	657	LF	6	10+ years	
	Interior Plantings	South West	45	LF	6	10+ years	



Catego	ry : Site		В	uilding	: Site		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pole Mounted	South West	3	EA	7	10+ years	
	Lighting - Pole Mounted	South West	1	EA	7	10+ years	
	Surface - Asphalt	South West	10,739	SF	6	10+ years	
	Vehicular Screening	South West	210	LF	6	10+ years	
Playgrou	nd						
	Equipment - Combo 3-12	East	1	EA	6	10+ years	
	Equipment - Pre K 3-5	East	1	EA	6	10+ years	
	Surface - Poured Surface	East	2,718	SF	7	6-10 years	
	Surface - Poured Surface	East	10	SF	5	1-2 years	Broken, damage to the surface
Sidewalk	CS.						
	Sidewalks - Internal Walks	Entire Site	611	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	88	LF	4	0-1 year	Broken concrete
	Sidewalks - Perimeter Sidewalks	Entire Site	9,853	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	425	SF	5	1-2 years	Broken concrete, upheaved concrete
Signage							
- 5 - 5	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Building Mounted Back Lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	6	10+ years	
	Monument - Sign	Entire Site	1	EA	6	10+ years	No problems seen with masonry

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	<u> </u>	•	•	•		•		•	
Computer Lab	Fitness Room	2nd Floor	223	223	850	200	10	Y	Υ
Computer Lab	Regular Classroom	3rd Floor	325	313	940	156	21	Υ	Υ
Kindergarten	Kindergarten	1st Floor	113	113 / 115	1,365	266	16	Υ	Υ
Kindergarten	Regular Classroom	1st Floor	123	123	1,095	267	18	Υ	Υ
Music Room	Kindergarten	2nd Floor	207	203	720	63	27	Υ	N
Office	Regular Classroom	3rd Floor	321	321	720	178	8	Υ	N
Regular Classroom	Library	3rd Floor	323	323	1,116	267	18	Υ	N
Regular Classroom	Office	2nd Floor	229	213	720	104	14	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	109	103A	720	248	26	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	111	102	700	178	8	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	733	178	8	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	733	178	8	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	213	213	732	178	8	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	215	215	718	178	8	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	221	221	722	178	8	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	733	178	8	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	303	720	120	14	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	309	305	720	120	14	Y	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	731	178	8	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	313	313	731	178	8	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	315	315	731	178	8	Y	N
Regular Classroom	Regular Classroom	3rd Floor	317	307	720	120	14	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	319	309	720	120	14	Y	Υ
Store Room	Regular Classroom	3rd Floor	303	300	711	0	0	N	N
Building : Addition									
Art Room	Regular Classroom	3rd Floor	302	302	1,035	216	108	N	Υ
Kindergarten	Kindergarten	1st Floor	110	110	1,114	262	128	Y	Y
Kindergarten	Kindergarten	1st Floor	112	1-33	1,057	184	14	N	Y
Kindergarten	Kindergarten	1st Floor	118	118	1,153	262	72	Y	Y
Kindergarten	Regular Classroom	2nd Floor	114	114	1,040	304	152	N	Y
Pre School	Kindergarten	1st Floor	116	1-36	1,040	172	42	N	Y
Pre School	Kindergarten	1st Floor	120	1-39	1,057	194	35	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	885	140	28	N	Y
Regular Classroom	Regular Classroom	1st Floor	106	106	908	192	42	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	200	200	830	142	76	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	830	216	108	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	830	216	108	N	V





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	216	216	830	216	108	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	220	220	820	216	108	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	222	2-20	885	140	28	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	224	224	820	216	108	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	226	2-19	885	140	28	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	300	300	850	166	83	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	3-11	900	216	108	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	306	830	216	108	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	310	310	830	216	108	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	312	3-23	885	102	28	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	314	314	830	140	28	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	316	3-22	885	140	28	N	Y
Regular Classroom	Regular Classroom	3rd Floor	320	320	830	216	108	N	Y
Regular Classroom	Regular Classroom	3rd Floor	324	324	830	216	18	N	Υ
Science Classroom	Science Classroom	3rd Floor	322	3-19	1,610	194	35	N	Y
Special Education	Special Education	2nd Floor	210	2-23	585	92	7	N	Υ
Special Program	Special Program	2nd Floor	214	2-22	585	108	14	N	N
Special Program	Special Program	2nd Floor	218	2-21	585	86	21	N	N
Special Program	Special Program	3rd Floor	318	3-21	585	86	21	N	Y

Campus Name: Burbank Page : 58 of 58 Assessment Date: 10/10/2023