

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1917	3	54,590
Addition	1928	3	27,360
Branch	2021	1	10,468
Campus Total			92,418

Category : Exterior Building : Main

catego	ny. L∧tenon		D	unung			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Cell Equ					1141111		
OUI EQU	Cell Equipment - Antenna	Lower Roofs	1	EA	7	10+ years	
	Cell Equipment - Cabinets	Lower Roofs	1	EA	7	10+ years	
Entrance	9						
	Entrance Control - Audio and Video	Entrance 2-South	1	EA	7	6-10 years	
	Exterior Doors - Store Front	Entrance 2-South	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 2-South	4	EA	6	2-5 years	
	Exterior Stairs - Concrete	Entrance 2-South	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 2A-SE - Outside elevator machine room	1	EA	6	6-10 years	
	Exterior Stairs - Stone	Entrance 2A-SE - Outside elevator machine room	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 3A-East / Outside Yard Storage	2	EA	4	1-2 years	Corroded frame, damaged door
	Ramps - Concrete	Entrance 3A-East / Outside Yard Storage	6	LF	4	0-1 year	Ramp is sinking
	Exterior Doors - Exterior FRP Door	Entrance 4-East / Boiler Room	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 4-East / Boiler Room	1	EA	7	6-10 years	
	Exterior Doors - Transom Lite	Entrance 4-East / Boiler Room	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 6-West / Auditorium	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 6-West / Auditorium	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 6-West / Auditorium	36	LF	7	10+ years	





Catego	Category : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Entrance Control - Audio and Video	Entrance 8-NW	1	EA	7	10+ years	
	Exterior Doors - Store Front	Entrance 8-NW	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 8-NW	4	EA	7	10+ years	
	Exterior Stairs - Concrete	Entrance 8-NW	40	LF	6	10+ years	
	Entrance Control - Audio and Video	Exit 3-SE - Lunchroom/Kitchen Area	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Exit 3-SE - Lunchroom/Kitchen Area	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Exit 3-SE - Lunchroom/Kitchen Area	1	EA	7	6-10 years	
	Exterior Stairs - Concrete	Exit 3-SE - Lunchroom/Kitchen Area	25	LF	7	10+ years	
	Exterior Stairs - Stone	Exit 3-SE - Lunchroom/Kitchen Area	3	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Exit 3-SE - Lunchroom/Kitchen Area	14	LF	6	2-5 years	
	Entrance Control - Audio and Video	Main Entrance 1-SW	1	EA	6	2-5 years	
	Exterior Doors - Store Front	Main Entrance 1-SW	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Main Entrance 1-SW	4	EA	7	6-10 years	
	Power Door Operator and Controls	Main Entrance 1-SW	1	EA	7	2-5 years	
	•					-	
_Foundati	Foundation - Concrete	Entire Building	700	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	400	SF	6	0-1 year	Seepage at door 6, mold smell
	Superstructure - Concrete	Entire Building	1,500	SF	5	2-5 years	Cracked, sinking slab door 2
	Superstructure - Steel with Clay Tile Arch	Entire Building	79,300	SF	7	10+ years	Gracked, Siriking Slab accir 2
		g	. 0,000	О.	•	.e. yeare	
_Lighting_	Exterior Lighting - Wall Mounted	Entire Building	19	EA	7	10+ years	
	Exterior Lighting - wall wounted	Entire Building	19	EA	,	10+ years	
Roof Sys	stem						
•	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Access Ladder - Metal	Roof 1	1	EA	7	6-10 years	
	Coping - Clay Tile	Roof 1	65	LF	6	10+ vears	
	Coping - Stone	Roof 1	555	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	100	LF	6	2-5 years	
	Downspouts - Interior Downspouts	Roof 1	280	LF	6	2-5 years	
	Parapet - 16" - 30" Height	Roof 1	200	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 1	45	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 1	375	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	13,360	SF	7	10+ years	
	Roof Hatch - Metal	Roof 1		EA	7	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof 1	165	SF	7	10+ years	
	Concrete Topping					,	
	Roof Structure - Steel with Clay Tile Arch	Roof 1	13,195	SF	7	10+ years	
	Coping - Stone	Roof 3	340	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	290	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof 3	120	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof 3	30	LF	7	10+ years	
	,				-	,	







**Category: Exterior** 

Stairs

Emergency A/C Power - Lunchrooms

Emergency A/C Power - Students Toilets

_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet < 16" Height	Roof 3	310	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	10,805	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 3	10,805	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 4 - East	125	LF	6	10+ years	
	Coping - Clay Tile	Roof 4 - East	50	LF	6	10+ years	
	Coping - Stone	Roof 4 - East	185	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Roof 4 - East	65	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof 4 - East	235	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4 - East	4,200	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 4 - East	4,150	SF	6	10+ years	
Walls							
	Cornice - Cast Stone	Entire Building	445	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20,555	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	75	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	60	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	3,950	SF	6	10+ years	
Windows							
	Curtain wall - Insulated Panel	Entire Building	145	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	495	SF	6	6-10 years	
	Lintels - Steel	Entire Building	675	LF	7	6-10 years	
	Lintels - Stone	Entire Building	100	LF	6	10+ years	
	Windows - Louver	Entire Building	40	SF	6	6-10 years	
	Windows - Sash Aluminum	Entire Building	6,380	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	3	EA	6	10+ years	
	Security System - CCTV	Entire Building	54,590	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	54,590	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	6,846	SF	6	10+ years	
	Emergency A/C Power - Corridors and	Entire Building	11,317	SF	6	10+ years	

**Building: Main** 

**Entire Building** 

Entire Building

SF

SF

6

6

10+ years

10+ years

3,233

1,710



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Generator- Outdoor- Natural Gas - 60 - 100 KW	Site - East	1	EA	5	1-2 years	Serves main and addition buildings Issues with lighting.
/lain Sei	vice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	54,590	SF	5	6-10 years	Many rooms needs repair of speakers, connected to addition building.
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
			•				Old alastrias basely at failure and
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	4	2-5 years	Old, electrical breaker failure and doesn't reset. Dirt and dust in the breakers cause fluctuations in the power supply.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	,
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	2	EA	6	6-10 years	
atego	ry : Fire Protection		В	uilding	: Main		
_						Recommend	
<b>Froup</b> Tire Alar	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
II C Alai	Fire Alarm Panel	Mechanical Room	1	EA	6	6-10 years	Serves main and addition buildings
	Fire Alarm Strobe Lights	Mechanical Room	54,590	SF	6	6-10 years	
	Fire Alarm_System	Mechanical Room	54,590	SF	6	6-10 years	Connected to addition
atego	ry : Mechanical		В	uilding	: Main		
,	Hom Time	Logotion	Ouantitu	ПОМ	Donk	Recommend	Comments
iroup ir Hond	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
п папо	ling Systems						
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 1 serves auditorium
	Air Intake	Mechanical Room	1	EA	5	10+ years	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts	Mechanical Room	40	LF	6	10+ years	



Catego	Category : Mechanical		В	uilding	: Main		,		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 3		
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 2		
	Air Intake	Mechanical Room	2	EA	5	6-10 years			
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years			
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	5	6-10 years			
	Return Duct Work - Sheet Metal- Exterior	Mechanical Room	100	LF	6	6-10 years	Common return riser up		
	Vertical Shaft and Ducts		0.4	_ ^	•	0.40			
	Zone Dampers	Mechanical Room	24	EΑ	6	6-10 years			
	Zone Dampers	Mechanical Room	10	EA	6	6-10 years			
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	10+ years			
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	10+ years			
	Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM	Roof	1	EA	6	10+ years			
Boiler Sy	vstems								
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	6	6-10 years			
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years			
	Combustion Dampers	Boiler Room	3	EA	5	6-10 years			
	Condensate Pump	Boiler Room	1	EA	5	6-10 years			
	Condensate Pump	Boiler Room	1	EΑ	5	6-10 years			
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	6-10 years			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	6-10 years			
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	6-10 years			
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	6-10 years	Connected to addition building, there are a few pipe clamps		
	Steam Traps	Boiler Room	24	EA	5	6-10 years	are a rem pipe diampe		
Heating									
	Cabinet Heaters - With Steam Coil	1st Floor	1	EA	7	10+ years			
	Unit Heater - Gas	Entire Building	1	EA	5	6-10 years			
	Fin Tube - Steam	Entire Building	50	LF	6	6-10 years			
	Wall Heater - Electric	Entire Building	5	EA	5	6-10 years			
_Tempera	ature Control								
	DDC System	Entire Building	54,590	SF	6	6-10 years	New software installation in process		



Building : Main
Recommend
Quantity UOM Rank Replacement Comments
at the time of assessment.
ding 1 EA 5 6-10 years
ding 35 EA 6 6-10 years Serves 34 dampers for AHU 2 & AH 3. Serves AHU 1 single sone unit.
ding 3 EA 6 6-10 years
ding 100 LF 6 10+ years
ding 60 LF 5 6-10 years
ding 1 EA 2 0-1 year No fire suppression system
Building : Main
Recommend
Quantity UOM Rank Replacement Comments
al and Boiler Rooms 2 EA 6 6-10 years Serves main and addition buildings and Boiler Rooms 1 EA 6 6-10 years Domestic water heater serves kitche in main building
ding 54,590 SF 6 6-10 years There are a few more pipe clamps
ding 54,590 SF 6 6-10 years
Il Room 1 EA 6 6-10 years Serves main and addition buildings
ll Room 1 EA 6 6-10 years Under elevator
uilduilduildin n





Catego	Category : Room			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	302A	1	EA	5	2-5 years	
	Ceiling - Plaster/Drywall	302A	280	SF	6	10+ years	
	Doors - Transom Window	302A	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	302A	1	EA	6	10+ years	
	Floor - Tile	302A	280	SF	6	6-10 years	
	Lighting - Pendent/Surface	302A	6	ĒΑ	7	10+ years	
	Power Distribution	302A	4	EA	6	10+ years	
	Walls - Plaster/Drywall	302A	600	SF	6	10+ years	
	AC Unit	308A teachers lounge/storage	1	ĒΑ	5	6-10 years	
	Ceiling - Plaster/Drywall	308A teachers lounge/storage	300	SF	5	10+ years	
	Doors - Transom Window	308A teachers lounge/storage	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	308A teachers lounge/storage	1	ĒΑ	6	10+ years	
	Floor - Tile	308A teachers lounge/storage	300	SF	6	10+ years	
	Lighting - Pendent/Surface	308A teachers lounge/storage	4	ĒΑ	6	10+ years	
	Power Distribution	308A teachers lounge/storage	3	EA	7	10+ years	
	Walls - Plaster/Drywall	308A teachers lounge/storage	720	SF	5	10+ years	
	Work SInk	308A teachers lounge/storage	1	ĒΑ	5	10+ years	
	Ceiling - Plaster/Drywall	Custodian Office	203	SF	6	10+ years	
	Floor - Concrete	Custodian Office	203	SF	5	10+ years	
	Lighting - Pendent/Surface	Custodian Office	2	ĒA	6	10+ years	
	Power Distribution	Custodian Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Custodian Office	406	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer Office	90	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer Office	1	EA	6	10+ years	
	Floor - Concrete	Engineer Office	90	SF	5	10+ years	
	Lighting - Pendent/Surface	Engineer Office	1	EA	6	10+ years	
	Power Distribution	Engineer Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineer Office	343	SF	6	10+ years	
	Work SInk	Engineer Office	1	EA	5	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	272	SF	6	10+ years	
	Doors - Side-lite	Main Office	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Tile	Main Office	272	SF	6	6-10 years	
	Lighting - Pendent/Surface	Main Office	6	EA	6	6-10 years	
	Power Distribution	Main Office	12	EA	7	10+ years	
	Storage/ Closet	Main Office	168	SF	5	10+ years	
	Walls - Plaster/Drywall	Main Office	909	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Nurse room inside the auditorium	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Nurse room inside the auditorium	1	ĒΑ	7	6-10 years	
	Floor - Wood	Nurse room inside the auditorium	140	SF	7	10+ years	
	Lighting - Pendent/Surface	Nurse room inside the auditorium	4	ĒΑ	7	6-10 years	
	Power Distribution	Nurse room inside the auditorium	4	EA	7	6-10 years	



Catego	Category : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	Nurse room inside the auditorium	380	SF	7	6-10 years			
	AC Unit	Principals Office, in Main Office	1	EA	5	6-10 years			
	Ceiling - Plaster/Drywall	Principals Office, in Main Office	193	SF	6	10+ years			
	Doors - Side-lite	Principals Office, in Main Office	70	SF	6	10+ years			
	Doors - Transom Window	Principals Office, in Main Office	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Principals Office, in Main Office	1	EA	6	10+ years			
	Floor - Wood	Principals Office, in Main Office	193	SF	6	10+ years			
	Lighting - Pendent/Surface	Principals Office, in Main Office	2	EA	6	6-10 years			
	Power Distribution	Principals Office, in Main Office	6	EA	7	10+ years			
	Walls - Plaster/Drywall	Principals Office, in Main Office	498	SF	6	10+ years			
Auditoriu	um & Theater								
	Ceiling - Plaster/Drywall	1st Floor	6,846	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	12	ĒΑ	6	10+ years			
	Floor - Wood	1st Floor	6,576	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	76	ĒΑ	6	10+ years			
	Lighting - Wall Mounted	1st Floor	8	EΑ	6	10+ years			
	Main Floor Seating	1st Floor	825	EΑ	5	10+ years			
	Sound System	1st Floor	1	EΑ	5	10+ years			
	Stage	1st Floor	527	SF	6	10+ years			
	Stage Curtain	1st Floor	3	EA	5	10+ years			
	Stage Lift	1st Floor	1	EA	5	10+ years			
	Stage Lighting System	1st Floor	1	EA	5	10+ years			
	Stage-Stairs - Wood	1st Floor	10	LF	6	10+ years			
	Storage/ Closet	1st Floor	124	SF	5	10+ years			
	Walls - Plaster/Drywall	1st Floor	6,818	SF	6	10+ years			
	walls - Flastel/Drywall	ist Flooi	0,010	SF	O	10+ years			
Kitchen	AC Unit	In Lunchroom	1	EA	4	0-1 year	Not working		
			478	SF			Not working		
	Ceiling - Plaster/Drywall Floor - Tile	In Lunchroom		SF SF	7	10+ years			
		In Lunchroom	478		7	10+ years			
	Lighting - Pendent/Surface	In Lunchroom	5	EA	7	10+ years			
	Serving Line	In Lunchroom	20	LF	7	10+ years	5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	Storage/ Closet	In Lunchroom	120	SF	7	10+ years	Rank changed to update/correct to match current observation		
	Walls - Plaster/Drywall	In Lunchroom	550	SF	7	10+ years	Quantity changed to update/correct to match current observation		
Lunch &	Multipurpose Room								
	AC Unit	1st Floor	2	EA	7	6-10 years	Rank and quantity changed to update/correct to match current observation of new AC units		
	Ceiling - Plaster/Drywall	1st Floor	3,233	SF	7	10+ years			

Campus Name: Clay Page: 8 of 46 Assessment Date: 08/31/2023



Catego	ry : Room		В	uilding	: Main	-	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	3,233	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	39	EΑ	7	6-10 years	
	Serving Line	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	260	SF	7	10+ years	Rank changed to update/correct to
	-					-	match current observation
	Walls - Plaster/Drywall	1st Floor	1,910	SF	7	10+ years	Quantity changed to update/correct to
	·		,			,	match current observation
<u>Mechani</u>	cal/ Service Rooms						
	Air Intake Plenums	1st Floor	460	SF	5	10+ years	
	Air Tunnel	1st Floor	2,150	SF	5	10+ years	
	Boiler Room	1st Floor	1,790	SF	5	10+ years	
	Coal Room	1st Floor	605	SF	5	10+ years	
	Janitor's Closet	1st Floor	50	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	1,989	SF	5	10+ years	
	Janitor's Closet	2nd Floor	18	SF	5	10+ years	
	Janitor's Closet	3rd Floor	18	SF	5	10+ years	
						, , , , , ,	
Restroor	n						
	Accessories	1st Floor Boys	325	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boys	325	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Boys	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys	325	SF	6	10+ years	
	Floor Drain	1st Floor Boys	1	EA	7	10+ years	
	Hand Dryer	1st Floor Boys	2	EΑ	5	6-10 years	
	Lavatory	1st Floor Boys	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys	3	EA	6	10+ years	
	Partitions	1st Floor Boys	1	EΑ	5	6-10 years	
	Urinals	1st Floor Boys	4	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Boys	480	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor Boys	152	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boys	323	SF	6	10+ years	
	Water Closet	1st Floor Boys	1	EA	6	10+ years	
	Accessories	1st Floor Girls	225	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls	225	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Girls	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls	· · · · · · · · · · · · · · · · · · ·	SF	-		
	Floor - Tile Ceramic/ Porceiain Floor Drain		225	SF EA	6	10+ years	
		1st Floor Girls	1		7	10+ years	
	Hand Dryer	1st Floor Girls	2	EA	5	6-10 years	
	Lavatory	1st Floor Girls	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Girls	3	EΑ	6	10+ years	
	Partitions	1st Floor Girls	4	EA	5	6-10 years	
	Walls - Concrete Block	1st Floor Girls	139	SF	6	10+ years	





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor Girls	483	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Girls	300	SF	6	10+ years	
	Water Closet	1st Floor Girls	4	EΑ	6	10+ years	
	Accessories	2nd Floor Boys - next to classroom	325	SF	5	6-10 years	
		205					
	Ceiling - Plaster/Drywall	2nd Floor Boys - next to classroom	325	SF	6	10+ years	
		205					
	Doors - Transom Window	2nd Floor Boys - next to classroom	44	SF	6	10+ years	
		205					
	Doors - Wood Doors inclu hw	2nd Floor Boys - next to classroom	2	EΑ	6	10+ years	
		205					
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys - next to classroom	325	SF	6	10+ years	
		205					
	Floor Drain	2nd Floor Boys - next to classroom	1	EΑ	7	10+ years	
		205					
	Hand Dryer	2nd Floor Boys - next to classroom	2	EA	5	6-10 years	
		205					
	Lavatory	2nd Floor Boys - next to classroom	2	EA	6	10+ years	
		205					
	Lighting - Pendent/Surface	2nd Floor Boys - next to classroom	4	EA	7	10+ years	
		205					
	Partitions	2nd Floor Boys - next to classroom	3	EΑ	5	6-10 years	
		205					
	Urinals	2nd Floor Boys - next to classroom	8	EA	6	10+ years	
		205					
	Walls - Plaster/Drywall	2nd Floor Boys - next to classroom	690	SF	6	10+ years	
		205					
	Walls - Structural Glazed Tile	2nd Floor Boys - next to classroom	192	SF	6	10+ years	
		205					
	Walls - Structural Glazed Tile	2nd Floor Boys - next to classroom	285	SF	6	10+ years	
		205					
	Water Closet	2nd Floor Boys - next to classroom	3	EA	6	10+ years	
		205					
	Accessories	2nd Floor Girls	325	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls	325	SF	6	10+ years	
	Doors - Transom Window	2nd Floor Girls	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girls	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls	325	SF	6	10+ years	
	Floor Drain	2nd Floor Girls	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Girls	2	EA	5	6-10 years	
	Lavatory	2nd Floor Girls	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls	4	EA	7	10+ years	
	Partitions	2nd Floor Girls	2	ΕA	5	6-10 years	
	Walls - Plaster/Drywall	2nd Floor Girls	692	SF	6	10+ years	
					-	,	

Campus Name: Clay Page : 10 of 46 Assessment Date: 08/31/2023





Catego	ry : Room		В	uilding	: Main			
					_	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Structural Glazed Tile	2nd Floor Girls	369	SF	6	10+ years		
	Water Closet	2nd Floor Girls	2	EA	6	10+ years		
	Accessories	2nd flr Unisex staff restroom in girls restroom (under construction)	55	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd flr Unisex staff restroom in girls restroom (under construction)	55	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd flr Unisex staff restroom in girls restroom (under construction)	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd flr Unisex staff restroom in girls restroom (under construction)	55	SF	7	10+ years		
	Floor Drain	2nd flr Unisex staff restroom in girls restroom (under construction)	1	EA	7	10+ years		
	Lavatory	2nd flr Unisex staff restroom in girls restroom (under construction)	1	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd flr Unisex staff restroom in girls restroom (under construction)	1	EA	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd flr Unisex staff restroom in girls restroom (under construction)	330	SF	7	10+ years		
	Water Closet	2nd flr Unisex staff restroom in girls restroom (under construction)	1	EA	7	10+ years		
	Accessories	3rd Floor Boys - Across from Classroom 304	325	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor Boys - Across from Classroom 304	325	SF	6	10+ years		
	Doors - Transom Window	3rd Floor Boys - Across from Classroom 304	44	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor Boys - Across from Classroom 304	2	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor Boys - Across from Classroom 304	325	SF	6	10+ years		
	Floor Drain	3rd Floor Boys - Across from Classroom 304	1	EA	7	10+ years		
	Hand Dryer	3rd Floor Boys - Across from Classroom 304	2	EA	5	6-10 years		
	Lavatory	3rd Floor Boys - Across from Classroom 304	2	EA	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor Boys - Across from Classroom 304	3	EA	7	10+ years		
	Partitions	3rd Floor Boys - Across from Classroom 304	1	EA	5	6-10 years		
	Urinals	3rd Floor Boys - Across from Classroom 304	4	EA	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor Boys - Across from Classroom 304	730	SF	6	10+ years		





atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	3rd Floor Boys - Across from Classroom 304	437	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Boys - Across from Classroom 304	80	SF	6	10+ years	
	Water Closet	3rd Floor Boys - Across from Classroom 304	1	EA	6	10+ years	
	Accessories	3rd Floor Girls	325	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Girls	325	SF	6	10+ years	
	Doors - Transom Window	3rd Floor Girls	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Girls	2	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Girls	325	SF	6	10+ years	
	Floor Drain	3rd Floor Girls	1	EA	7	10+ years	
	Hand Dryer	3rd Floor Girls	2	EA	5	6-10 years	
	=		2	EA	6	-	
	Lavatory	3rd Floor Girls				10+ years	
	Lighting - Pendent/Surface	3rd Floor Girls	4	EΑ	7	10+ years	
	Partitions	3rd Floor Girls	7	EA	5	6-10 years	
	Walls - Plaster/Drywall	3rd Floor Girls	692	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Girls	196	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Girls	173	SF	6	10+ years	
	Water Closet	3rd Floor Girls	7	EA	6	10+ years	
	Accessories	3rd flr Unisex staff restroom in girls restroom	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd flr Unisex staff restroom in girls restroom	55	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd flr Unisex staff restroom in girls restroom	1	EA	4	0-1 year	Damaged
	Floor - Tile Ceramic/ Porcelain	3rd flr Unisex staff restroom in girls restroom	45	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd flr Unisex staff restroom in girls restroom	10	SF	4	1-2 years	Damaged
	Lavatory	3rd flr Unisex staff restroom in girls restroom	1	EA	6	10+ years	
	Lighting - Wall Mounted	3rd flr Unisex staff restroom in girls restroom	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd flr Unisex staff restroom in girls restroom	223	SF	6	10+ years	
	Water Closet	3rd flr Unisex staff restroom in girls restroom	1	EA	6	10+ years	
	Accessories	In 101 Classroom	22	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	In 101 Classroom	22	SF	5	6-10 years	
	Doors - Wood Doors inclu hw	In 101 Classroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	In 101 Classroom	22	SF	6	10+ years	
	Floor Drain	In 101 Classroom	1	EA	7	10+ years	
		In 101 Classroom	1	EA	6	•	
	Lavatory	111 101 01055100111	ı	EA	O	10+ years	





Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	In 101 Classroom	1	EA	6	10+ years	
	Walls - Plaster/Drywall	In 101 Classroom	210	SF	6	10+ years	
	Water Closet	In 101 Classroom	1	EA	6	10+ years	
	Accessories	Main Office	38	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Office	38	SF	6	10+ years	
	Lavatory	Main Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Main Office	1	EA	6	10+ years	
	Lighting - Wall Mounted	Main Office	1	EA	6	10+ years	
	Partitions	Main Office	1	EA	5	6-10 years	
	Walls - Plaster/Drywall	Main Office	138	SF	6	6-10 years	
	Water Closet	Main Office	1	EA	6	10+ years	
	Accessories	inside mechanical room	1	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	inside mechanical room	16	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	inside mechanical room	1	EA	7	6-10 years	
	Floor - Concrete	inside mechanical room	16	SF	7	6-10 years	
	Lighting - Wall Mounted	inside mechanical room	2	EA	7	6-10 years	
	Walls - Masonry	inside mechanical room	240	SF	7	10+ years	
	Water Closet	inside mechanical room	1	EΑ	7	6-10 years	
						- -	

Category : Classroom **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #101 (Music Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	AC Units	1st Floor	1	EA	5	2-5 years	Not working
	Casework	1st Floor	40	LF	6	10+ years	•
	Ceiling - Plaster/Drywall	1st Floor	864	SF	7	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	864	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,649	SF	7	10+ years	
_Classro	om #102 (Music Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	790	SF	7	10+ years	Quantity changed to update/correct to match current observation
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	

Campus Name: Clay Page : 13 of 46 Assessment Date: 08/31/2023





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Wood	1st Floor	790	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,323	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	850	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Transom Window	1st Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	 1	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,323	SF	7	10+ years	
lassroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	
Classroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	
Classroo	m #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	
laceroo	m #205 (Regular Classroom)						
1033100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	
	Work Sink	2nd Floor	1,323	EA	7	10+ years	
						,	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	





Catego	ry : Classroom		R	uilding	· Main		3231 S Burley AVENUE, Chicago, IL 60633
Julego				anding	· maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	14	ĹF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	6-10 years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	914	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	914	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	8	LF	7	10+ years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	6-10 years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	





Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,323	SF	6	10+ years	
Classroc	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,323	SF	6	10+ years	
Classroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	846	SF	6	10+ years	
	Floor - Wood	3rd Floor	4	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	Damageu
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,323	SF	6	10+ years	
Classroo	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood Doors inclu riw	3rd Floor	· · · · · · · · · · · · · · · · · · ·	SF	6	10+ years 10+ years	
			850				
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	





Catogo	ory : Classroom		P	uilding	· Main		3231 3 Bulley AVENUE, Chicago, IL 6063.
Calego	ory . Classicolli		В	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Storage/ Closet	3rd Floor	65	SF	7	10+ years	Comments
	Walls - Plaster/Drywall	3rd Floor	1,323	SF	6	10+ years	
	walls - Flastel/Drywall	314 F1001	1,323	SF	O	10+ years	
Classro	om #305 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	914	SF	6	10+ years	
	Chalk Board	3rd Floor	35	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	914	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,323	SF	6	10+ years	
	Wireless System	3rd Floor	, 1	ĒA	7	6-10 years	
	,					,	
Classroo	om #306 (Special Education)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,323	SF	6	10+ years	
Classro	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	4	SF	4	1-2 years	Damaged
	Floor - Wood	3rd Floor	846	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,323	SF	6	10+ years	
Classics	om #308 (Regular Classroom)						
Ciassio		Oud Ela		Г^	7	0.40	
	AC Units	3rd Floor	1	EA	7	6-10 years	





Category : Classroom

alegoi	y : Classroom			suliaing	: wain		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	7		6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14		6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	59	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,323	_	6	10+ years	
ategor	y : Interior		F	Building	· Main		
atogoi	y . III.C.101		-	Jananig	· Maiii	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	5,671	SF	7	10+ years	
	Doors - Store Front	1st Floor	8		7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	6-10 years	Rank changed to update/correct to
	gggg				·	,	match current observation
	Floor - Tile/Sheet	1st Floor	5,621	SF	7	10+ years	Rank changed to update/correct to
	Tidol Tile/Officet	13111001	3,021	O.	•	101 years	match current observation
	Floor - Tile/Sheet	1st Floor	50	SF	4	1-2 years	Floor tiles are cracked
	Floor - Tile/Sheet	1st Floor	60		4	1-2 years	Damaged
	Lighting - Pendent/Surface	1st Floor	40	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	8,675		7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,603	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4		5	6-10 years	
	Floor - Tile/Sheet	2nd Floor	2,603	SF	5	10+ years	
	Floor - Tile/Sheet	2nd Floor	140	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	2nd Floor	37	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5,695	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,603		6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2		7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	2	EA	5	2-5 years	
	Floor - Tile/Sheet	3rd Floor	2,603		5	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,003	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	3rd Floor	39	EA	7	•	Damaged
						10+ years	
	Stairs - Concrete Stairs	3rd Floor	12	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5,695	SF	6	10+ years	
afety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	Rank changed to update/correct to
	ŭ					,	match current observation
	Security Cameras	1st Floor	10	EA	7	6-10 years	Rank changed to update/correct to

**Building: Main** 

Campus Name: Clay Page: 19 of 46 Assessment Date: 08/31/2023



Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
			_			<u> </u>	match current observation
Stairs							
	Ceiling - Plaster/Drywall	Stairwell #2	1,306	SF	6	10+ years	
	Floor - Tile/Sheet	Stairwell #2	220	SF	7	10+ years	
	Handrails	Stairwell #2	480	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell #2	2	EA	7	10+ years	
	Lighting - Wall Mounted	Stairwell #2	2	EA	7	10+ years	
	Stairs - Asphalt	Stairwell #2	270	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell #2	5,446	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairwell #3	1,306	SF	6	6-10 years	
	Floor - Tile/Sheet	Stairwell #3	220	SF	5	10+ years	
	Handrails	Stairwell #3	480	LF	5	10+ years	
	Lighting - Pendent/Surface	Stairwell #3	2	EA	7	10+ years	
	Lighting - Wall Mounted	Stairwell #3	2	EA	7	10+ years	
	Stairs - Asphalt	Stairwell #3	270	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell #3	5,446	SF	6	10+ years	
Vertical (	Conveyance						
	Elevator - Hydraulic Elevator	Auditorium	1	EA	6	10+ years	
	Wheelchair Lift - Chair Lift	Auditorium	1	EA	7	6-10 years	



Category : Exterior Building : Addition

egor	y : Exterior	Building : Addition							
	H T	I a satism	0	11011	ъ	Recommend	0		
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
rance									
	Exterior Doors - Exterior Steel Door	3rd floor fire escape - Gym	1	EA	6	6-10 years			
	Exterior Doors - Store Front	Entrance 5-East	4	EA	6	6-10 years			
	Exterior Doors - Transom Lite	Entrance 5-East	4	EA	7	6-10 years			
	Exterior Doors - Transom Lite	Entrance 5-East	4	EA	6	6-10 years			
	Exterior Stairs - Concrete	Entrance 5-East	90	LF	6	10+ years			
	Exterior Stairs - Stone	Entrance 5-East	12	LF	6	10+ years			
	Exterior Doors - Store Front	Entrance 7-North	4	EA	6	6-10 years			
	Exterior Doors - Transom Lite	Entrance 7-North	4	EA	7	6-10 years			
	Exterior Doors - Transom Lite	Entrance 7-North	4	EA	6	6-10 years			
	Exterior Stairs - Concrete	Entrance 7-North	72	LF	6	10+ years			
	Ramp Handrail - Steel_Ramp Handrail	Entrance 7-North	150	LF	6	6-10 years			
	Ramps - Concrete	Entrance 7-North	75	LF	7	10+ years			
	Stair Handrail - Steel_Stair Handrail	Entrance 7-North	12	LF	5	2-5 years			
	Exterior Doors - Exterior FRP Door	Exit 5A-East / Inside 111 Classroom	1	EA	6	6-10 years			
	Exterior Doors - Transom Lite	Exit 5A-East / Inside 111 Classroom	1	ĒΑ	6	6-10 years			
	Exterior Stairs - Stone	Exit 5A-East / Inside 111 Classroom	12	LF	6	10+ years			
					-	, , , , , , , , , , , , , , , , , , , ,			
Esca	ne								
LSCO	Exterior Doors - Exterior Steel Door	North Façade	1	EA	6	6-10 years	Deadbolt lock on inside		
	Fire Escape	North Façade North Façade	113	LF	6	2-5 years	Deauboit lock on inside		
	Paints	North Façade	113	LF	3	1-2 years	Corroded		
	Fairits	North Façade	113	LF	3	1-2 years	Corroded		
undatio	Foundation - Concrete	Entire Duilding	220	1.5	7	40			
		Entire Building	330	LF	7	10+ years			
	Superstructure - Steel with Clay Tile Arch	Entire Building	27,360	SF	7	10+ years			
بم مناهما،									
hting	Exterior Lighting - Wall Mounted	Entire Building	9	EA	7	10+ years			
	Exterior Lighting - Wall Modified	Littile Building	9	LA	,	10+ years			
of Sys	em								
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years			
	Coping - Clay Tile	Roof 2	65	LF	7	10+ years			
	Coping - Stone	Roof 2	340	LF	7	10+ years			
	Downspouts - Interior Downspouts	Roof 2	280	LF	7	6-10 years			
	Parapet - 16" - 30" Height	Roof 2	65	LF	7	10+ years			
	Parapet - Parapet < 16" Height	Roof 2	100	LF	7	10+ years			
	Parapet - Parapet > 30"	Roof 2	340	LF	7	10+ years			
	Roof - Modified Bitumen	Roof 2	8,885	SF	7	10+ years			
	Roof Hatch - Metal	Roof 2	0,003	EA	3	2-5 years	Not used		
	11001 HatoH - Mctal	1,001 2			J	2-0 years	INOL USEU		
	Roof Structure - Steel with Clay Tile Arch	Roof 2	8,885	SF	7	10+ years			

Campus Name: Clay Page : 21 of 46 Assessment Date: 08/31/2023



Catego	ategory : Exterior			uilding	: Additi		
_	<del></del>		0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Walls							
	Cheek-Wall - Concrete	Entire Building	80	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	10	SF	5	2-5 years	
	Cornice - Cast Stone	Entire Building	140	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	12,155	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2,220	SF	6	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	360	SF	6	6-10 years	
	Guard - Guards wire guard	Entire Building	280	SF	6	6-10 years	
	Lintels - Steel	Entire Building	400	LF	6	6-10 years	
	Lintels - Stone	Entire Building	160	LF	7	10+ years	
	Windows - Sash Aluminum	Entire Building	4,910	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Addition	on	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	cy System						
	Security System - CCTV	Entire Building	27,360	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	27,360	SF	5	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,974	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	4,084	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	800	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years	Building served by emergency generator
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	Building served by emergency generator
	Emergency Battery Packs - Students Toilets	Entire Building	3	EA	6	6-10 years	generator
Main Sei	vice						
Maii Oci	PA System	Entire Building	27,360	SF	5	6-10 years	Connected to main building.
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Electrical Room and Loading Dock	4	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Electrical Room and Loading Dock	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	<b>~</b>						



Catego	ategory : Fire Protection			uilding	on		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	27,360	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	27,360	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	lling Systems	Location	Quantity	00111	Raine	Replacement	Commence
All Hallu	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	6	6-10 years	
	Steam Coils - 25001 - 35000 cfm	Wechanical Room	1	LA	O	0-10 years	
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Sheet Metal- Exterior	Mechanical Room	30	LF	6	6-10 years	
	Vertical Shaft and Ducts	Mechanical NOOH	30	L	U	0-10 years	
	Zone Dampers	Mechanical Room	19	EA	6	6-10 years	
	Outdoor Return Fans- Air Handling Unit	Roof	1	EA	6	10+ years	
	Type - Greater than 20000 CFM		•	_, .	Ü	10. 300.0	
Boiler Sy	vstems						
,	Condensate Pump	Entire Building	1	EA	5	6-10 years	Connected to main building
	Piping - Condensate Pipe- Steel	Entire Building	150	LF	6	10+ years	3
	Steam Traps	Entire Building	11	ĒΑ	6	6-10 years	
Heating	Devices						
J	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	
	Radiators - Steam	Entire Building	8	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	4	EA	6	10+ years	
Tempera	ature Control						
	DDC System	Entire Building	27,360	SF	6	6-10 years	New software installation in the
		-				-	process at the time of the
							assessment.
	Thermostats - DDC	Entire Building	19	EA	6	6-10 years	
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	6	10+ years	
	Roof Mounted Duct Work	Roof	20	LF	5	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additi	on	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



						Replacement
Piping						
	Domestic Piping-Hot Water Return Lines	Entire Building	27,360	SF	6	10+ years
	Domestic Piping-Hot Water Return Risers	Entire Building	27,360	SF	6	10+ years
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	27,360	SF	6	10+ years
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	27,360	SF	6	10+ years
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	27,360	SF	6	10+ years
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	27,360	SF	6	10+ years
	Sanitary Piping	Entire Building	27,360	SF	6	10+ years
	Storm Piping	Entire Building	27,360	SF	6	10+ years
	Vent Piping	Entire Building	27,360	SF	6	10+ years
Pumps						
•	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years

**Building: Addition** Category: Room

	. ,			۳۳			
_			0			Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	AC Unit	110 Attendance Office	1	EA	7	6-10 years	Rank changed to update/correct to match current observation
	Ceiling - Plaster/Drywall	110 Attendance Office	516	SF	7	10+ years	
	Doors - Transom Window	110 Attendance Office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	110 Attendance Office	1	EΑ	7	10+ years	
	Floor - Wood	110 Attendance Office	516	SF	7	10+ years	
	Lighting - Pendent/Surface	110 Attendance Office	6	EΑ	7	10+ years	
	Power Distribution	110 Attendance Office	10	EA	7	10+ years	
	Storage/ Closet	110 Attendance Office	120	SF	7	10+ years	Rank changed to update/correct to match current observation
	Walls - Plaster/Drywall	110 Attendance Office	1,545	SF	7	10+ years	
	Ceiling - Plaster/Drywall	110 Conference Room	175	SF	7	10+ years	
	Doors - Transom Window	110 Conference Room	16	SF	7	10+ years	Quantity changed to update/correct match current observation
	Doors - Wood Doors inclu hw	110 Conference Room	2	EA	7	10+ years	Quantity changed to update/correct match current observation
	Floor - Tile	110 Conference Room	173	SF	7	6-10 years	
	Floor - Tile	110 Conference Room	2	SF	5	1-2 years	Loose floor tiles
	Lighting - Pendent/Surface	110 Conference Room	2	EA	7	6-10 years	
	Power Distribution	110 Conference Room	10	EA	7	10+ years	
	Storage/ Closet	110 Conference Room	90	SF	7	10+ years	Rank changed to update/correct to match current observation
	Walls - Plaster/Drywall	110 Conference Room	692	SF	7	10+ years	

Campus Name: Clay Page : 24 of 46 Assessment Date: 08/31/2023



Catego	ry : Room		В	uilding	: Additi		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	314 gym office	200	SF	6	10+ years	
	Doors - Transom Window	314 gym office	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	314 gym office	1	EA	6	10+ years	
	Floor - Tile	314 gym office	200	SF	6	6-10 years	
	Lighting - Pendent/Surface	314 gym office	2	EA	6	10+ years	
	Power Distribution	314 gym office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	314 gym office	800	SF	6	10+ years	
	AC Unit	Assistant Principal's Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Assistant Principal's Office	429	SF	6	10+ years	
	Doors - Transom Window	Assistant Principal's Office	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal's Office	1	EA	6	10+ years	
	Floor - Tile	Assistant Principal's Office	429	SF	6	10+ years	
	Lighting - Pendent/Surface	Assistant Principal's Office	4	EA	6	10+ years	
	Power Distribution	Assistant Principal's Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Assistant Principal's Office	860	SF	7	10+ years	
_Gymnasi	ia						
	Ceiling - Plaster/Drywall	3rd Floor	4,084	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	110	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Wood	3rd Floor	4,084	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	3rd Floor	20	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	10+ years	
	Storage/ Closet	3rd Floor	240	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,753	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	100	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,791	SF	6	10+ years	
MDF ID	F						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Finishes	1st Floor	120	SF	5	10+ years	
	Window AC Unit	1st Floor	1	ĒΑ	5	10+ years	
Mechani	cal/ Service Rooms						
	Air Intake Plenums	1st Floor	350	SF	5	10+ years	
	Air Tunnel	1st Floor	620	SF	5	10+ years	
	Janitor's Closet	1st Floor	30	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	901	SF	5	10+ years	
	Janitor's Closet	2nd Floor	14	SF	5	10+ years	
	Janitor's Closet	3rd Floor	14	SF	5	10+ years	
	Storage Room	3rd Floor	14	SF	5	10+ years	
	- · · · · · · · · · · · · · · · · · · ·				-	,	







gor	y : Room		В	uilding	: Addition		
ın	Hom. Type	Location	Ougatitus	UOM	Donk	Recommend	Comments
ıp	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
room	1						
	Ceiling - Plaster/Drywall	2nd Floor - Girls next to room 210 (under construction)	400	SF	6	10+ years	
	Doors - Transom Window	2nd Floor - Girls next to room 210 (under construction)	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Girls next to room 210 (under construction)	1	EA	6	10+ years	
	Accessories	3rd Floor Boys - next to room 310 (Out of service) Under Construction	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor Boys - next to room 310 (Out of service) Under Construction	400	SF	7	10+ years	
	Doors - Transom Window	3rd Floor Boys - next to room 310 (Out of service) Under Construction	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Boys - next to room 310 (Out of service) Under Construction	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Boys - next to room 310 (Out of service) Under Construction	400	SF	7	10+ years	
	Floor Drain	3rd Floor Boys - next to room 310 (Out of service) Under Construction	1	EA	7	10+ years	
	Hand Dryer	3rd Floor Boys - next to room 310 (Out of service) Under Construction	1	EA	7	6-10 years	
	Lavatory	3rd Floor Boys - next to room 310 (Out of service) Under Construction	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor Boys - next to room 310 (Out of service) Under Construction	3	EA	7	10+ years	
	Partitions	3rd Floor Boys - next to room 310 (Out of service) Under Construction	4	EA	7	10+ years	
	Urinals	3rd Floor Boys - next to room 310 (Out of service) Under Construction	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Boys - next to room 310 (Out of service) Under Construction	1,135	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Boys - next to room 310 (Out of service) Under Construction	143	SF	7	10+ years	
	Water Closet	3rd Floor Boys - next to room 310 (Out of service) Under Construction	2	EA	7	10+ years	
	Accessories	Assistant Principals Office Restroom	50	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Assistant Principals Office Restroom	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principals Office Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Assistant Principals Office Restroom	50	SF	6	10+ years	
	Lavatory	Assistant Principals Office Restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Assistant Principals Office Restroom	1	EA	6	10+ years	
	Partitions	Assistant Principals Office Restroom	1	EA	5	6-10 years	
	Walls - Plaster/Drywall	Assistant Principals Office Restroom	120	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Additi	on	· · · · · · · · · · · · · · · · · · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	Assistant Principals Office Restroom	1	EA	6	10+ years	
	Accessories	In Room 110	47	SF	7	6-10 years	Rank changed to update/correct to match current observation
	Ceiling - Plaster/Drywall	In Room 110	47	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 110	1	EA	7	10+ years	
	Floor - Tile	In Room 110	47	SF	7	10+ years	
	Lavatory	In Room 110	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Room 110	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	In Room 110	263	SF	7	10+ years	
	Water Closet	In Room 110	1	EA	7	10+ years	
Catego	ory : Classroom		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	om #109 (Regular Classroom)	Location	Quantity	00111	Rain	Nopidoement	Comments
_Class100	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	850	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	16	SF	7	•	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years 10+ years	
	Floor - Wood Doors Inclu TW	1st Floor	850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
				LF	7	•	
	Marker Board Storage/ Closet	1st Floor 1st Floor	14 50	SF	7	6-10 years 10+ years	
	Walls - Plaster/Drywall	1st Floor	1,568	SF	7	10+ years	
Classra	·		,			,	
Classro	om #111 (Kindergarten)  AC Units	1st Floor	4	Ε.Δ	7	0.40	
	Casework		1 48	EA LF	7	6-10 years	
	Casework Ceiling - Plaster/Drywall	1st Floor 1st Floor	48 850	SF	6 7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years 10+ years	
	Floor - Wood Boots Incid Tiw	1st Floor	850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,629	SF	7	10+ years	
	vvalio i lactor/brywan	1001	1,020	O.	•	101 youro	
Classro	om #112 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	850	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,629	SF	7	10+ years	
Classroo	om #114 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	850	SF	7	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	•	
	Walls - Plaster/Drywall	1st Floor	1,629	SF	7	10+ years	
	Walls - Plaster/Drywall	ISI FIOOI	1,029	SF	,	10+ years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood Bools inclu hw	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	45	SF	7		
		2nd Floor 2nd Floor		SF SF	6	10+ years	
	Walls - Plaster/Drywall	2110 F100f	1,323	<b>5</b> F	О	10+ years	

Campus Name: Clay Page : 28 of 46 Assessment Date: 08/31/2023







Catego	ry : Classroom		В	uilding	: Additi		3231 3 Bulley AVENUE, Chicago, IL 60633
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	
Classroo	m #212,214 (Library)						
	AC Units	2nd Floor	2	EA	7	6-10 years	_
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,690	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,690	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,316	SF	6	10+ years	
_Classroc	m #213 (Faculty Lounge)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	6	10+ years	
Classroo	m #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	848	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	864	SF	6	10+ years	
	1 1001 - VV000	314 1 1001	004	OI.	U	10+ years	

Campus Name: Clay Page : 29 of 46 Assessment Date: 08/31/2023



Catego	ry : Classroom		В	uilding	: Addition	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	4	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,407	SF	6	10+ years	
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	833	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	833	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	41	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,374	SF	6	10+ years	

**Building: Addition** Category: Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	1,344	SF	7	10+ years	
	Doors - Store Front	1st Floor	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	5	1-2 years	Missing faucet
	Floor - Tile/Sheet	1st Floor	1,314	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	30	SF	4	1-2 years	Cracked floor tiles
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,544	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,038	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	5	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,038	SF	5	10+ years	
	Floor - Tile/Sheet	2nd Floor	60	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor	8	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,798	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,221	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	5	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,221	SF	5	10+ years	
	Floor - Tile/Sheet	3rd Floor	20	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	3rd Floor	4	EA	6	10+ years	-
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	6	10+ years	

Campus Name: Clay Page : 30 of 46 Assessment Date: 08/31/2023



Catego	ry : Interior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	2,852	SF	6	10+ years	
Safety							
•	Security Cameras	Entire building	5	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Stairwell #1	824	SF	6	10+ years	
	Floor - Tile/Sheet	Stairwell #1	225	SF	5	10+ years	
	Handrails	Stairwell #1	250	LF	5	10+ years	
	Lighting - Lay-in	Stairwell #1	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	Stairwell #1	2	EA	6	10+ years	
	Stairs - Asphalt	Stairwell #1	120	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell #1	1,865	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairwell #4	304	SF	6	10+ years	
	Floor - Tile/Sheet	Stairwell #4	146	SF	5	10+ years	
	Handrails	Stairwell #4	64	LF	5	10+ years	
	Lighting - Pendent/Surface	Stairwell #4	2	EA	7	10+ years	
	Stairs - Asphalt	Stairwell #4	30	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell #4	889	SF	6	10+ years	



Category : Exterior Building : Branch

						Doggmand	
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonto
•		Location	Quantity	OOW	Kalik	Replacement	Comments
ance							
	Exterior Doors - Exterior Steel Door	4NW Basement	1	EA	7	10+ years	
	Exterior Stairs - Concrete	4NW Basement	52	LF	7	10+ years	
	Entrance Control - Audio and Video	NE	1	EΑ	7	10+ years	
	Exterior Doors - Exterior FRP Door	NE	2	EA	7	10+ years	
	Exterior Doors - Side lite	NE	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	NE	1	EA	7	10+ years	
	Exterior Stairs - Concrete	NE	10	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	NE	50	LF	7	10+ years	
	Ramps - Concrete	NE	25	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	NE	12	LF	7	10+ years	
	Exterior Doors - Exterior Wood Door	NW - above Basement Stair	12	EA	7		
			-			10+ years	
	Exterior Stairs - Concrete	NW - above Basement Stair	12	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	SE	2	EΑ	7	10+ years	
	Exterior Doors - Side lite	SE	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	SE	1	EA	7	10+ years	
	Exterior Stairs - Concrete	SE	16	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	SE	8	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	SW	2	EA	7	10+ years	
	Exterior Stairs - Concrete	SW	48	LF	7	10+ years	
	Entrance Control - Audio and Video	South	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	South	4	EA	7	10+ years	
	Exterior Doors - Side lite	South	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	South	1	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	South	50	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	South	60	LF	7	10+ years	
	Ramps - Concrete	South	30	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail		8	LF	7	•	
	Stail Handrali - Steel_Stail Handrali	South	0	LF	7	10+ years	
dati	on						
<u>cm</u>	Foundation - Concrete	Entire Building	531	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	10,468	SF	7	10+ years	
	Caporoli dollaro Conordio	Entire ballaring	10,400	Oi.	•	ioi yeais	
ting							
•	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	10+ years	
		-				-	
of Sys							
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof 1 - See Roof Plan	45	LF	7	10+ years	
	Liner						
	Coping - Metal	Main Roof 1 - See Roof Plan	280	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Main Roof 1 - See Roof Plan	30	LF	7	10+ years	
	Roof - Modified Bitumen			SF			

Campus Name: Clay Page : 32 of 46 Assessment Date: 08/31/2023



Catego	ry : Exterior		В	uilding	: Brancl	h	
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Heavy Timber	Main Roof 1 - See Roof Plan	6,724	SF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 2	60	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 2	1,751	SF	7	10+ years	Not accessible under construction.
	Roof Structure - Heavy Timber	Roof 2	1,751	SF	7	10+ years	
	Chimney - Metal Flue	Roof 3	112	LF	7	10+ years	
	Coping - Metal	Roof 3	140	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	10	LF	7	10+ years	
	Roof - Asphalt Shingle	Roof 3	1,000	SF	7	10+ years	
	Roof - Modified Bitumen	Roof 3	2,224	SF	7	10+ years	Not accessible - under construction
	Roof Structure - Heavy Timber	Roof 3	3,224	SF	7	10+ years	
	Chimney - Metal Flue	Roof 4	28	LF	7	10+ years	
	Coping - Metal	Roof 4	155	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 4	12	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 4	1,340	SF	7	10+ years	Not accessible under construction.
	Roof Structure - Heavy Timber	Roof 4	1,340	SF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 5/Canopy - See Walls	10	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 5/Canopy - See Walls	200	SF	7	10+ years	Not accessible under construction.
	Roof Structure - Steel / Metal Deck/	Roof 5/Canopy - See Walls	200	SF	7	10+ years	
	Concrete Topping	.,				•	
alls							
	Canopy - Metal	Entire Building	200	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	1,625	SF	7	10+ years	
	Canopy - Metal	Entire Building	200	SF	7	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	200	SF	7	10+ years	
/indows							
	Clerestory - Glass Double-Pane	Entire Building	115	SF	7	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	2,240	SF	7	10+ years	
	Storefront Windows	Entire Building	500	SF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	30	SF	7	10+ years	
	pane	0.454	504	05	-	40	
	Curtain wall - Windows	South Entrances	504	SF	7	10+ years	
atego	ry : Electrical		В	uilding	: Brancl		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncy System						
v. gui	Security System - CCTV	1st Floor	10,468	SF	7	10+ years	
	Security System - Intrusion Detection	1st Floor	10,468	SF	7	10+ years	
	Coounty Cystem - Industrial Detection	1st Floor	1,500	SF	7	10+ years	
					,		
	Emergency A/C Power - Corridors and Stairs Emergency Battery Packs - Corridors and	13(1)001	1,000	O.	•	101 youro	



Catego	ry : Electrical		R	uildina	: Branc		3231 S Burley AVENUE, Chicago, IL 60633
Calego	ry . Liectricai			unung	. Diane	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs		•				
	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	7	10+ years	
Main Se							
	PA System	1st Floor	10,468	SF	7	10+ years	
	Main Electrical Service - 1200 A	Electrical Room	1	EA	7	10+ years	
	120/208/3PH	Floorisal Doors	4	_^	7	40	
	Independent Electrical Service for	Electrical Room	1	EA	7	10+ years	
	emergency power						
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp						
Catago	m Eiro Brotostion		ь	المانات م	. Branci	<b>L</b>	
Catego	ry : Fire Protection		ь	ullaing	: Branc	n Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar		Location	Quantity	00	rtaint	Replacement	Commonto
T II E Alai	Fire ALarm Anunciator	1st Floor	1	EA	7	10+ years	
	Fire Alarm Panel	1st Floor	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	1st Floor	1	SF	7	10+ years	
	Fire Alarm_System	1st Floor	1	SF	7	6-10 years	
	·					•	
Sprinkle	System						
	Sprinkler Heads	1st Floor	10,468	SF	7	10+ years	
	Sprinkler Piping	1st Floor	10,468	SF	7	10+ years	
	Wet Sprinkler System	1st Floor	10,468	SF	7	10+ years	
0-1	Markania		<b>-</b>		D	•	
Catego	ry : Mechanical		В	ullaing	: Branc		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Cond	· •	Location	Quantity	00111	Italik	Replacement	Comments
All Cono	Condensing Unit- Roof Mounted - Less	Roof	2	EA	7	6-10 years	
	than 5 tons	Rooi	۷	LA	,	0-10 years	
Air Hand	ling Systems						
	Air Handling Unit- Package Multi Zone-	Roof	2	EA	7	10+ years	
	Outdoor Roof Mounted- Hot Water and DX					•	
	Cooling Coils - 20001-30000 cfm						
	Air Intake	Roof	2	EA	7	10+ years	

Campus Name: Clay Page : 34 of 46 Assessment Date: 08/31/2023



Catego	ry : Mechanical		В	uilding	: Branc		oce of Bulley Avenue, emouge, in ecose
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Zone Dampers	Roof	9	EA	7	10+ years	
Boiler Sy	vstems						
	Boiler Auxiliary- Condensing Hot Water - Less than 500 HP	Basement	3	EA	7	10+ years	
	Chemical Pot Feeder	Basement	1	EA	7	10+ years	
	Condensing- Hot Water Boiler - Less than 500 MBH	Basement	3	EA	7	10+ years	
	Water Fill System	Basement	1	EA	7	10+ years	
_Heating	Devices						
· ·	Fin Tube - Hot Water	1st Floor	200	LF	7	10+ years	
	Cabinet Heaters - With Steam Coil	Entire Building	1	EA	7	10+ years	
_Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Basement	3	EA	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	500	LF	7	10+ years	
_Tempera	nture Control						
	DDC System	1st Floor	10,468	SF	7	10+ years	
	Electric Thermostat	1st Floor	1	EA	7	10+ years	
	Thermostats - DDC	1st Floor	9	EA	7	10+ years	
_Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & Remote Mounted Compressors	1st Floor	9	EA	7	10+ years	
_Ventilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Roof	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	7	EA	7	10+ years	
Catego	ry : Plumbing		В	uilding	: Branc	h	

	· y · · · · · · · · · · · · · · · · · ·					-	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Basement	2	EA	7	6-10 years	
Piping							
-, 5	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building	10,468 10,468	SF SF	7 7	10+ years 10+ years	

Campus Name: Clay Page : 35 of 46 Assessment Date: 08/31/2023



Catago	m Diumbina		D	ب الماني	. Dranal		SZOT & Bulley /(VEITOE, Chiloago, in 00000
Catego	ry : Plumbing		D	ullaing	: Brancl	1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(Horizontal Lines)					<u> </u>	
	Sanitary Piping	Entire Building	10,468	SF	7	10+ years	
	Storm Piping	Entire Building	10,468	SF	7	10+ years	
	Vent Piping	Entire Building	10,468	SF	7	10+ years	
_Pumps_							
<u> </u>	Pumps - Sump-Simplex	Basement	3	EA	7	10+ years	

Building : Branch Category : Room

Catego	ry : Room		В	uilding	: Branc	h	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	Coordinator Office 112	171	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Coordinator Office 112	1	EA	7	10+ years	
	Floor - Carpet	Coordinator Office 112	171	SF	7	6-10 years	
	Lighting - Lay-in	Coordinator Office 112	2	EA	7	10+ years	
	Power Distribution	Coordinator Office 112	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Coordinator Office 112	462	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Office	664	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Kitchen Office	664	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen Office	12	EΑ	7	10+ years	
	Power Distribution	Kitchen Office	12	EΑ	7	10+ years	
	Walls - Masonry	Kitchen Office	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Office	329	SF	7	10+ years	
	Ceiling - Lay-in	Main Office 110	171	SF	7	10+ years	
	Doors - Store Front	Main Office 110	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office 110	1	EΑ	7	10+ years	
	Floor - Carpet	Main Office 110	171	SF	7	6-10 years	
	Lighting - Lay-in	Main Office 110	2	EA	7	10+ years	
	Power Distribution	Main Office 110	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	Main Office 110	348	SF	7	10+ years	
Gvmnas	ia.						
,	Ceiling - Exposed	Lunch Multipurpose - 107	400	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Lunch Multipurpose - 107	1	ĒΑ	7	10+ years	
	Floor - Tile	Lunch Multipurpose - 107	400	SF	7	10+ years	
	Lighting - Pendent/Surface	Lunch Multipurpose - 107	9	ĒΑ	7	10+ years	
	Walls - Masonry	Lunch Multipurpose - 107	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Lunch Multipurpose - 107	600	SF	7	10+ years	
	Ceiling - Exposed	Lunch Multipurpose - 116	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Lunch Multipurpose - 116	10	ĒΑ	7	10+ years	
	Floor - Tile	Lunch Multipurpose - 116	800	SF	7	10+ years	

Campus Name: Clay Page : 36 of 46 Assessment Date: 08/31/2023



Catego	ry : Room		В	uilding	: Branc	h	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Lunch Multipurpose - 116	20	EΑ	7	10+ years	
	Storage/ Closet	Lunch Multipurpose - 116	50	SF	7	10+ years	
	Walls - Masonry	Lunch Multipurpose - 116	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Lunch Multipurpose - 116	600	SF	7	10+ years	
Kitchen							
	Ceiling - Exposed	Room 108	268	SF	7	10+ years	
	Ceiling - Lay-in	Room 108	300	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Room 108	3	EA	7	10+ years	
	Floor - Tile	Room 108	268	SF	7	10+ years	
	Floor - Tile Quarry	Room 108	300	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 108	6	ĒΑ	7	10+ years	
	Serving Line	Room 108	10	LF	7	10+ years	
	Walls - Plaster/Drywall	Room 108	800	SF	7	10+ years	
MDF_ID	F						
	Doors - Wood Doors inclu hw	112	1	EA	7	10+ years	
	Finishes	112	173	SF	7	10+ years	
	Other Cooling Unit	112	1	EA	7	10+ years	Ductless split system.
	Carlot Cooming Crini		•	_, 、	•	io. youro	2 dolloco opiit oyotoiii.
Mechani	cal/ Service Rooms						
	Janitor's Closet	106C Trash- Storage Room	38	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement B01	500	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement B02	205	SF	7	10+ years	
	Janitor's Closet	Janitor Closet 123	28	SF	7	10+ years	
Restroor	n						
	Accessories	101B	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	101B	52	SF	7	10+ years	
	Doors - Wood Doors inclu hw	101B	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	101B	52	SF	7	10+ years	
	Floor Drain	101B	1	ĒΑ	7	10+ years	
	Lavatory	101B	1	EΑ	7	10+ years	
	Lighting - Lay-in	101B	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	101B	25	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	101B	75	SF	7	10+ years	
	Water Closet	101B	1	EA	7	10+ years	
	Accessories	101B 102B	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	102B	52	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102B 102B	1	EA	7	10+ years 10+ years	
	Floor - Tile Ceramic/ Porcelain	102B 102B	52	SF	7		
					7	10+ years	
	Floor Drain Lavatory	102B 102B	1	EA EA	7 7	10+ years 10+ years	





Catego	ry : Room		В	uilding	: Branc	h	, , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	102B	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	102B	25	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	102B	75	SF	7	10+ years	
	Water Closet	102B	1	EA	7	10+ years	
	Accessories	103B	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	103B	52	SF	7	10+ years	
	Doors - Wood Doors inclu hw	103B	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	103B	52	SF	7	10+ years	
	Floor Drain	103B	1	EA	7	10+ years	
	Lavatory	103B	1	EA	7	10+ years	
	Lighting - Lay-in	103B	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	103B	25	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	103B	75	SF	7	10+ years	
	Water Closet	103B	1	EA	7	10+ years	
	Accessories	104B	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	104B	52	SF	7	10+ years	
	Doors - Wood Doors inclu hw	104B	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	104B	52	SF	7	10+ years	
	Floor Drain	104B	1	EA	7	10+ years	
	Lavatory	104B	1	EΑ	7	10+ years	
	Lighting - Lay-in	104B	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	104B	25	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	104B	75	SF	7	10+ years	
	Water Closet	104B	1	EA	7	10+ years	
	Accessories	105B	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	105B	52	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105B	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	105B	52	SF	7	10+ years	
	Floor Drain	105B	1	EA	7	10+ years	
	Lavatory	105B	1	EA	7	10+ years	
	Lighting - Lay-in	105B	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	105B	25	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	105B	75	SF	7	10+ years	
	Water Closet	105B	1	EA	7	10+ years	
	Accessories	103B 106B	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	106B	52	SF	7	10+ years	
	Doors - Wood Doors inclu hw	106B 106B	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	106B 106B	52	SF	7	10+ years 10+ years	
	Floor Drain	106B 106B	1	Sr EA	7	•	
	Lavatory	106B 106B	1	EA	7	10+ years 10+ years	
	,	106B 106B	1	EA EA	7		
	Lighting - Lay-in			SF		6-10 years	
	Walls - Plaster/Drywall	106B	25 75		7	10+ years	
	Walls - Tile Ceramic/ Porcelain	106B	75	SF	7	10+ years	
	Water Closet	106B	1	EA	7	10+ years	







Category: Room **Building: Branch** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Accessories 108A SF 6-10 years 57 7 108A 57 SF 7 Ceiling - Plaster/Drywall 10+ years Doors - Wood Doors inclu hw 108A FΑ 7 10+ years 1 Floor - Tile Ceramic/ Porcelain 57 SF 7 108A 10+ years Floor Drain 108A 1 EΑ 7 6-10 years 7 Lavatory 108A 1 EΑ 10+ years Lighting - Lay-in 108A EΑ 7 1 10+ years Walls - Tile Ceramic/ Porcelain SF 108A 108 7 10+ years Water Closet 108A 1 EΑ 7 10+ years SF Accessories Boys 115 186 7 2-5 years Boys 115 SF Ceiling - Plaster/Drywall 186 7 10+ years Floor - Tile Ceramic/ Porcelain **Boys 115** 186 SF 7 10+ years Floor Drain **Boys 115** EΑ 7 1 10+ years 7 Lavatory Boys 115 3 EΑ 10+ years **Boys 115** 8 7 Lighting - Lay-in EΑ 6-10 years Partitions 3 FΑ Boys 115 7 10+ years 2 Urinals Boys 115 EΑ 7 10+ years Walls - Tile Ceramic/ Porcelain Boys 115 432 SF 7 10+ years Water Closet **Bovs 115** 3 EΑ 7 10+ vears Accessories Girls 114 150 SF 7 6-10 years Ceiling - Plaster/Drywall Girls 114 150 SF 7 10+ years Floor - Tile Ceramic/ Porcelain SF 7 Girls 114 150 10+ years 2 7 Floor Drain Girls 114 EΑ 10+ years 3 7 Lavatory Girls 114 FΑ 10+ years Lighting - Lay-in Girls 114 8 EΑ 7 6-10 years 5 Partitions Girls 114 EΑ 7 10+ years Walls - Tile Ceramic/ Porcelain SF Girls 114 432 7 10+ years Water Closet Girls 114 5 EΑ 7 10+ years 57 SF Accessories Inside Kitchen 7 6-10 years Ceiling - Plaster/Drywall Inside Kitchen 57 SF 7 10+ years Doors - Wood Doors inclu hw 10+ years Inside Kitchen 1 EΑ 7 Floor - Tile Ceramic/ Porcelain Inside Kitchen 57 SF 7 10+ years FΑ 7 Floor Drain Inside Kitchen 10+ years Hand Drver FΑ 7 Inside Kitchen 1 10+ years Lavatory Inside Kitchen 1 EΑ 7 10+ years Lighting - Lay-in EΑ 7 Inside Kitchen 1 6-10 years Walls - Plaster/Drywall SF Inside Kitchen 20 7 10+ years Walls - Tile Ceramic/ Porcelain SF Inside Kitchen 88 7 10+ years Water Closet Inside Kitchen EΑ 7 10+ years Category: Classroom **Building: Branch** Recommend Location Item - Type Quantity UOM Rank Replacement Comments Classroom #101 (Kindergarten)



Catego	ry : Classroom		В	uilding	: Branc	h	
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	754	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	754	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	950	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #102 (Kindergarten)						
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	763	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	763	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	950	SF	7	•	
	Work Sink	1st Floor	2	EA	7	10+ years 10+ years	One sink one drinking fountain.
	WORK SILIK	151 11001	2	EA	,	10+ years	One sink one diffiking fountain.
Classroc	om #103 (Kindergarten)						
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	758	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	758	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	950	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #104 (Kindergarten)						
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	759	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	759	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	950	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
	Work Sirik	131 1 1001	ı	LA	,	10+ years	
Classroc	om #105 (Kindergarten)						
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	761	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	



Categor	ry : Classroom		В	uilding	: Branc	h	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	761	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	10+ years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	950	SF	7	10+ years	
	Work Sink	1st Floor	1	EΑ	7	10+ years	
01	"- "400 (Kindows atom)						
Classroo	m #106 (Kindergarten)						
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	734	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	734	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	950	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	

Category : Interior **Building: Branch** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	109	850	SF	7	10+ years	
	Doors - Wood Doors include hw	109	6	EA	7	10+ years	
	Drinking Fountains - Single Fountain	109	1	EA	7	10+ years	
	Floor - Tile/Sheet	109	850	SF	7	10+ years	
	Lighting - Lay-in	109	8	EA	7	10+ years	
	Walls - Plaster/Drywall	109	576	SF	7	10+ years	
	Ceiling - Exposed	Lobby 100	684	SF	7	10+ years	
	Drinking Fountains - Single Fountain	Lobby 100	3	EA	7	10+ years	
	Floor - Tile/Sheet	Lobby 100	684	SF	7	10+ years	
	Lighting - Lay-in	Lobby 100	12	EA	7	10+ years	
	Walls - Masonry	Lobby 100	712	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule 100A	108	SF	7	10+ years	
	Doors - Store Front	Vestibule 100A	8	EA	7	10+ years	
	Floor - Tile/Sheet	Vestibule 100A	108	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	Vestibule 100A	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Vestibule 100A	384	SF	7	10+ years	
	Ceiling - Exposed	Vestibule 107B	80	SF	7	10+ years	
	Doors - Wood Doors include hw	Vestibule 107B	1	EA	7	10+ years	
	Floor - Tile/Sheet	Vestibule 107B	80	SF	7	10+ years	
	Lighting - Lay-in	Vestibule 107B	1	EA	7	10+ years	
	Walls - Masonry	Vestibule 107B	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Vestibule 107B	172	SF	7	10+ years	
	Ceiling - Lay-in	Vestibule 109A	88	SF	7	10+ years	
	Doors - Store Front	Vestibule 109A	4	EA	7	10+ years	
	=		·	_, ,	•	is your	

Campus Name: Clay Page : 41 of 46 Assessment Date: 08/31/2023



Category: Interior

Floor - Tile/Sheet

Lighting - Chandelier, Incandescent Walls - Masonry

#### Henry Clay Elementary School 13231 S Burley AVENUE, Chicago, IL 60633

					Recommend	
Locat	ion	Quantity	UOM	Rank	Replacement	Comments
Vestik	oule 109A	88	SF	7	10+ years	
Incandescent Vestik	oule 109A	1	EA	7	10+ years	
Vestik	oule 109A	192	SF	7	10+ years	
Vestik	oule 109B	53	SF	7	10+ years	
Vestik	oule 109B	3	SF	4	0-1 year	Chipped.
Vestik	oule 109B	4	EA	7	10+ years	
	Vestik Incandescent Vestik Vestik Vestik Vestik Vestik	Location Vestibule 109A Incandescent Vestibule 109A Vestibule 109A Vestibule 109B Vestibule 109B Vestibule 109B Vestibule 109B	Vestibule 109A         88           Incandescent         Vestibule 109A         1           Vestibule 109A         192           Vestibule 109B         53           Vestibule 109B         3	Vestibule 109A         88         SF           Incandescent         Vestibule 109A         1         EA           Vestibule 109A         192         SF           Vestibule 109B         53         SF           Vestibule 109B         3         SF	Vestibule 109A         88         SF         7           Incandescent         Vestibule 109A         1         EA         7           Vestibule 109A         192         SF         7           Vestibule 109B         53         SF         7           Vestibule 109B         3         SF         4	Location         Quantity         UOM         Rank         Replacement           Vestibule 109A         88         SF         7         10+ years           Incandescent         Vestibule 109A         1         EA         7         10+ years           Vestibule 109A         192         SF         7         10+ years           Vestibule 109B         53         SF         7         10+ years           Vestibule 109B         3         SF         4         0-1 year

Vestibule 109B

Vestibule 109B

Vestibule 109B

Building: Branch

56

1

150

SF

EΑ

SF

7

7

7

10+ years

10+ years

10+ years

Campus Name: Clay Page: 42 of 46 Assessment Date: 08/31/2023





Category : Site **Building: Site** 

	y : Oile		_	ananig		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	item - Type	Location	Qualitity	OOW	Naiik	Replacement	Comments
nletic	0.1.1.1		4.500			0.40	
	Surface - Asphalt	West	4,500	SF	6	6-10 years	
vil/Drai	naga						
IVII/DI ai	•	Entire Site	6	ГΛ	7	6.10 voore	
	Civil/ Drainage - Catch Basin	Entire Site	6	EA EA	7 6	6-10 years	
	Civil/ Drainage - Catch Basin	Entire Site	8		7	6-10 years	
	Civil/ Drainage - Site Manhole		0	EA EA		6-10 years	Dualian asmanata
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	4	0-1 year	Broken concrete
encing							
· ·	Fencing - Guard Rail	Branch	150	LF	7	10+ years	
	Fencing - New Standard Ornamental	Branch	200	LF	7	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Branch	26	LF	7	10+ years	
	Fencing - Chain Link	Entire Site	320	LF	6	6-10 years	
	Fencing - Guard Rail	Entire Site	50	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	900	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	5	1-2 years	Bent
	Fencing - Old Standard Ornamental	Entire Site	595	LF	5	2-5 years	
	Ğ					•	
andscap							
	Landscape - Grass	Branch	5,000	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Branch	1,675	SF	7	10+ years	
	Parkway trees	Branch	3	EA	7	10+ years	
	Benches	Entire Site	3	EA	7	10+ years	
	Landscape - Grass	Entire Site	7,757	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	12,485	SF	6	6-10 years	
	Landscape - Hardscape- Asphalt	Entire Site	1,450	SF	4	1-2 years	Spalling, holes
	Landscape - Hardscape- Concrete	Entire Site	1,400	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	50	SF	5	2-5 years	
	Parkway trees	Entire Site	34	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	650	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	31,950	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	131	SF	4	1-2 years	Spalling
	Trash Receptacles	Entire Site	1	EΑ	7	10+ years	
Parking L							
	Surface - Asphalt	Branch	13,000	SF	4	0-1 year	Cracked/damaged.
	Surface - Asphalt	Southwest	51,375	SF	6	2-5 years	
	Surface - Asphalt	Southwest	26,068	SF	6	6-10 years	
	Trash Enclosure - Chain Links	Southwest	918	SF	6	6-10 years	
	Vehicular Screening	Southwest	140	LF	6	10+ years	




Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Playgrou	ınd						
, ,	Equipment - Combo 3-12	Branch	1	EA	7	10+ years	
	Surface - Poured Surface	Branch	2,140	SF	7	10+ years	
	Equipment - Combo 3-12	NE	1	EA	7	10+ years	
	Surface - Poured Surface	NE	3,200	SF	7	10+ years	
Sidewall	KS						
	Sidewalks - Internal Walks	Branch	100	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Branch	250	SF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	670	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	12,500	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	40	SF	5	2-5 years	Cracks
Signage							
	Flag Pole - Flag Pole	Branch	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Branch	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Branch	1	EA	6	10+ years	
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years	

1 It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").





Classroom Summary

Classroom Summary				Elsas Diss		01	0		
			Doom	Floor Plan Room	A ====	Glazed Window	Operable Window	Window	Smart-
Comment Hears	Intended Hears	Doom Location	Room		Area				
Current Usage Building : Main	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
	Describer Classes are	3rd Floor	205	205	04.4	400	40	l NI	
Computer Lab	Regular Classroom	1st Floor	305 101	305 101	914 864	180 119	48 70	N N	N Y
Music Room	Kindergarten								Y
Music Room	Regular Classroom	1st Floor	102	102	790	102	60	N	
Regular Classroom	Regular Classroom	1st Floor	107	107	850	102	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	850	180	48	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	850	180	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	850	180	48	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	850	180	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	850	180	45	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	850	180	45	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	914	180	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	850	102	60	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	850	180	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	850	180	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	850	180	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	850	180	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	850	180	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	850	180	48	N	N
Special Education	Regular Classroom	3rd Floor	306	306	850	180	48	N	N
Building : Addition									
Faculty Lounge	Regular Classroom	2nd Floor	213	213	850	180	48	N	N
Kindergarten	Regular Classroom	1st Floor	111	111	850	180	48	N	N
Kindergarten	Regular Classroom	1st Floor	112	112	850	180	48	N	Υ
Kindergarten	Regular Classroom	1st Floor	114	114	850	180	48	N	N
Library	Regular Classroom	2nd Floor	212,214	212	1,690	240	140	N	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	850	180	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	850	180	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	850	180	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	850	180	45	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	309	309	868	180	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	833	180	48	N	N
<u> </u>	, 9	,					-	1	
Building : Branch									
Kindergarten	Regular Classroom	1st Floor	101		754	100	75		
Kindergarten	Regular Classroom	1st Floor	102		763	250	100		
Kindergarten	Regular Classroom	1st Floor	103		758	100	75		
Kindergarten	Regular Classroom	1st Floor	104		759	100	75		





**Classroom Summary** 

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Kindergarten	Regular Classroom	1st Floor	105	Number	761	100	75	- Ciop	Doura
Kindergarten	Regular Classroom	1st Floor	106		734	100	75		

Campus Name: Clay Page : 46 of 46 Assessment Date: 08/31/2023