

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1905	3	45,675
Addition 1	1919	3	15,412
Addition 2	1919	3	26,452
Annex	1996	2	34,018
Campus Total			121,557

Category: Exterior Building: Main

Catego	ry : Exterior		Ь	ullaing	. IVIAIII		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	iipment						
	Cell Equipment - Antenna	Roof	4	EA	7	6-10 years	
	Cell Equipment - Cabinets	Roof	2	EA	7	6-10 years	
Entrance	9						
	Entrance Control - Audio and Video	Door 1 - South center	1	EA	7	10+ years	New
	Exterior Doors - Exterior Steel Door	Door 1 - South center	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 1 - South center	33	LF	6	10+ years	
	Exterior Stairs - Concrete	Door 1 - South center	9	LF	5	1-2 years	Cracks
	Stair Handrail - Steel_Stair Handrail	Door 1 - South center	14	LF	7	10+ years	New
	Exterior Doors - Exterior Steel Door	Door 2 - Southeast	3	EA	5	1-2 years	Rust on frame
	Exterior Stairs - Concrete	Door 2 - Southeast	42	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 2 - Southeast	10	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 4 - Northeast	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 4 - Northeast	22	LF	6	10+ years	Reconfigured
	Stair Handrail - Steel_Stair Handrail	Door 4 - Northeast	55	LF	7	10+ years	New
	Exterior Doors - Exterior Steel Door	Door 4.5 "A" - Auditorium East	2	EA	5	0-1 year	Door handle missing.
	Exterior Stairs - Concrete	Door 4.5 "A" - Auditorium East	6	LF	6	6-10 years	-
	Exterior Doors - Exterior Steel Door	Door 5 - Northwest	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 5 - Northwest	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 5.5 "A" - Auditorium west	2	EA	5	0-1 year	Door handle missing.
	Exterior Stairs - Concrete	Door 5.5 "A" - Auditorium west	6	LF	6	10+ years	•



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	Door 5.7 - North boiler	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door 5.7 - North boiler	1	EA	6	10+ years	
	Ramps - Concrete	Door 5.7 - North boiler	2	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 5.9 - Northwest	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 5.9 - Northwest	8	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 7 - Southwest	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 7 - Southwest	36	LF	7	10+ years	Divided out damaged areas and
						•	reassessed
	Exterior Stairs - Concrete	Door 7 - Southwest	6	LF	4	1-2 years	Spalled, cracked
	Stair Handrail - Steel_Stair Handrail	Door 7 - Southwest	10	LF	7	10+ years	•
Fire Esca	ape						
	Exterior Doors - Exterior Steel Door	East auditorium	2	EA	6	6-10 years	
	Fire Escape	East auditorium	14	LF	7	10+ years	
	Paints	East auditorium	14	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	West Auditorium	2	EA	6	6-10 years	
	Fire Escape	West Auditorium	14	LF	7	10+ years	
	Paints	West Auditorium	14	LF	5	6-10 years	
Foundati	ion						
	Foundation - Masonry	Entire Building	750	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	45,675	SF	7	10+ years	No exposed superstructure
Liahtina							
-0 0	Exterior Lighting - Wall Mounted	Entire Building	11	EA	7	10+ years	
Roof Sys	stem						
_	Access Ladder - Metal	Roof 1	2	EA	7	10+ years	
	Coping - Clay Tile	Roof 1	513	LF	7	10+ years	
	Coping - Terra Cotta	Roof 1	148	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	126	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 1	78	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 1	72	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 1	400	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 1	111	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 1	14,125	SF	7	10+ years	
	Roof Hatch - Metal	Roof 1	1 1,120	EA	7	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 1	14,125	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	2	EA	7	10+ years	New
	Coping - Terra Cotta	Roof 2	105	LF	7	10+ years	11011
	Downspouts - Exterior Downspouts	Roof 2	100	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof 2	35	LF	7	10+ years	
	Parapet - Parapet < 16 Height Parapet - Parapet > 30"	Roof 2	35 70	LF LF	7	•	
	raiapei - raiapei > 30	NUUI Z	70	ᆫ	1	10+ years	



atego	ry : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Roof 2	1,327	SF	7	6-10 years	
	Roof Hatch - Metal	Roof 2	1	EA	7	10+ years	New
	Roof Structure - Steel with Clay Tile Arch	Roof 2	1,327	SF	7	10+ years	
	Coping - Stone	Roof 3	56	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	35	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 3	56	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 3	800	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 3	800	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 4	65	LF	7	10+ years	
	Coping - Stone	Roof 4	82	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 4	70	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 4	82	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4	2.095	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 4	2,095	SF	7	10+ years	
	Coping - Terra Cotta	Roof 5	32	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 5	35	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 5	32	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 5	140	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 5	140	SF	7	10+ years	
alls_							
	Cornice - Terra Cotta	Entire Building	1,466	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	26,971	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	486	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,651	SF	7	10+ years	
indows	3						
	Guard - Guards perforated	Entire Building	740	SF	6	6-10 years	
	Lintels - Brick	Entire Building	4	LF	6	10+ years	
	Lintels - Steel	Entire Building	371	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	191	LF	6	10+ years	
	Windows - Louver	Entire Building	80	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,564	SF	7	6-10 years	
atego	ry : Electrical		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
merger	ncy System						
0 —	Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	Serves Main, Addition 1 and Addition 2. Fully operational but unit is over 60 years old and has exceeded its EUL.



Catego	ry : Electrical		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - CCTV	Entire Building	45,675	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	45,675	SF	5	6-10 years	
	Exit Signs - Auditoium	Entire Building	9	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	20	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	3	EA	2	0-1 year	Exit Sign has no backup battery and the school has no emergency generator.
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	1	EA	2	0-1 year	Exit Sign has no backup battery and the school has no emergency generator.
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	15	EA	6	6-10 years	Quantity changed based on current observations.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	15	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	1	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	6,291	SF	6	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,616	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	4,840	SF	6	10+ years	
Main Se	rvice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves Main, Addition 1 and Addition 2.
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	45,675	SF	5	6-10 years	Serves Main, Addition 1, Addition 2 and Annex.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	8	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	20	EA	6	10+ years	Quantity changed as total has been divided/aggregated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Serves Main, Addition 1 and Addition



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							 Rank, Reason and Priority Rep changed as the FACP was replaced since previous assessment. No CPS Asset Tag present.
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Annunciator
	Fire Alarm Strobe Lights	Entire Building	45,675	SF	7	10+ years	
	Fire Alarm_System	Entire Building	45,675	SF	7	10+ years	Rank, Reason and Priority Rep changed as the alarm system has been replaced since previous assessment.

Category : Mechanical **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	Iling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	EA	5	10+ years	AHU-2 serves gym, auditorium, and associated/adjacent spaces.
	Air Intake	Mechanical Room - AHU-2	1	EA	6	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-2	100	LF	5	10+ years	
	Zone Dampers	Mechanical Room - AHU-2	15	EA	6	6-10 years	Location changed for clarification. Rank changed based on the introduction of a DDC system in late 2022.
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	Mechanical Room - AHU-3	1	EA	5	6-10 years	AHU-3, serves Main and Addition 1
	Air Intake	Mechanical Room - AHU-3	1	EA	6	10+ years	
	Auxiliaries - 30001 - 45000 cfm	Mechanical Room - AHU-3	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-3	100	LF	5	6-10 years	
	Zone Dampers	Mechanical Room - AHU-3	17	EA	6	6-10 years	East plenum. Quantity changed based on current observations and per review with Building Engineer. Location changed for clarification. Rank changed based on the introduction of a DDC system in late 2022.
	Zone Dampers	Mechanical Room - AHU-3	10	EA	6	6-10 years	West plenum. Quantity changed based on current observations and per review with Building Engineer. Location changed for clarification. Rank changed based on the

Campus Name: Davis N Page : 5 of 59 Assessment Date: 11/06/2023



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							introduction of a DDC system in late 2022.
Boiler Sy	stems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 201 - 300 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Chemical Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Boiler Room	1	EA	5	6-10 years	B-1
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Boiler Room	1	EA	5	6-10 years	B-2
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	6	10+ years	
	Steam Traps	Boiler Room	29	EA	5	6-10 years	
Heating I	Devices						
ŭ	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Radiators - Steam	Entire Building	5	EA	3	0-1 year	Per review with Building Engineer, no radiators are in service at this school as they are not needed in the locations where they are installed; they are nonfunctional and they have been deemed obsolete. Rank, Reason and Priority Rep adjusted as this equipment has been abandoned in place.
	Radiators - Steam	Entire Building	18	EA	3	0-1 year	Per review with Building Engineer, no radiators are in service at this school as they are not needed in the locations where they are installed; they are nonfunctional and they have been deemed obsolete. Rank, Reason and Priority Rep established as this equipment has been abandoned in place.
	Wall Heater - Electric	Entire Building	8	EA	6	10+ years	
Tempera	ture Control						
	DDC System	Entire Building	45,675	SF	7	10+ years	



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Thermostats - DDC	Entire Building	49	EA	7	10+ years	Item Type changed to match current observations.
<u>Ventilation</u>	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	

Category : Plumbing **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Hot Wate	-		,			, and the second	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serves Main, Addition 1 and Addition 2.
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	4	2-5 years	Older unit, leak-free but has exceeded its EUL.
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	5	10+ years	Serves Main, Addition 1 and Addition 2.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	45,675	SF	4	2-5 years	Quantity changed as total has been divided/aggregated. Majority of piping is galvanized material over 60 years old and has exceeded its EUL. A number of pipe clamps are in place throughout the building.
	Domestic Piping-Hot Water Return Risers	Entire Building	45,675	SF	6	10+ years	Quantity changed as total has been divided/aggregated.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	45,675	SF	4	2-5 years	Quantity changed as total has been divided/aggregated. Majority of piping is galvanized material over 60 years old and has exceeded its EUL. A number of pipe clamps are in place throughout the building.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	45,675	SF	4	2-5 years	Quantity changed as total has been divided/aggregated. Majority of piping is galvanized material over 60 years old and has exceeded its EUL. A number of pipe clamps are in place throughout the building.
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	45,675	SF	4	2-5 years	Quantity changed as total has been divided/aggregated. Majority of

Campus Name: Davis N Page : 7 of 59 Assessment Date: 11/06/2023



Catego	ry : Plumbing		В	uilding	: Main		
0	Itama Tama	Lagation	Overetite	LIOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	piping is galvanized material over 60 years old and has exceeded its EUL. A number of pipe clamps are in place throughout the building.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	45,675	SF	4	2-5 years	Quantity changed as total has been divided/aggregated. Majority of piping is galvanized material over 60 years old and has exceeded its EUL. A number of pipe clamps are in place throughout the building.
	Sanitary Piping	Entire Building	45,675	SF	6	10+ years	
	Storm Piping	Entire Building	45,675	SF	6	10+ years	
	Vent Piping	Entire Building	45,675	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	5	6-10 years	Serves Main, Addition 1 and Addition 2.

Category : Room **Building: Main**

oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ative Suites/Offices	Location	Quantity	OOM	Italik	Replacement	Comments
шизи	Ceiling - Plaster/Drywall	1st floor Nurse	233	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor Nurse	1	EA	6	10+ years	
	Floor - Wood	1st floor Nurse	233	SF	6	10+ years	
	Lighting - Pendent/Surface	1st floor Nurse	3	EA	7	6-10 years	
	Power Distribution	1st floor Nurse	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor Nurse	300	SF	6	10+ years	
	Walls - Plaster/Drywall	1st floor Nurse	335	SF	6	10+ years	
	AC Unit	1st flr- Rm 111 Counselor	1	ĒΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr- Rm 111 Counselor	20	SF	6	10+ years	Peeling paint
	Ceiling - Plaster/Drywall	1st flr- Rm 111 Counselor	520	SF	6	10+ years	01
	Doors - Side-lite	1st flr- Rm 111 Counselor	50	SF	6	10+ years	
	Doors - Transom Window	1st flr- Rm 111 Counselor	3	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr- Rm 111 Counselor	1	EΑ	6	10+ years	
	Floor - Wood	1st flr- Rm 111 Counselor	540	SF	6	10+ years	
	Lighting - Pendent/Surface	1st flr- Rm 111 Counselor	9	EA	7	6-10 years	
	Power Distribution	1st flr- Rm 111 Counselor	8	EA	7	10+ years	
	Storage/ Closet	1st flr- Rm 111 Counselor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	1st flr- Rm 111 Counselor	851	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement Rm 010	251	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement Rm 010	2	EA	6	6-10 years	
	Floor - Carpet	Basement Rm 010	211	SF	6	6-10 years	
	Floor - Carpet	Basement Rm 010	40	SF	4	1-2 years	Torn carpet

Campus Name: Davis N Page : 8 of 59 Assessment Date: 11/06/2023



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Basement Rm 010	2	EA	7	6-10 years	
	Power Distribution	Basement Rm 010	2	EA	7	10+ years	
	Walls - Masonry	Basement Rm 010	440	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement engineer's office north	185	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement engineer's office north	1	EA	6	10+ years	
	Floor - Carpet	Basement engineer's office north	185	SF	6	2-5 years	
	Lighting - Pendent/Surface	Basement engineer's office north	3	EA	7	6-10 years	
	Power Distribution	Basement engineer's office north	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement engineer's office north	443	SF	6	6-10 years	
Auditoriu	m & Theater						
	Balcony Seating	1st Floor	105	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	6,291	SF	5	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	12	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	2,095	SF	5	2-5 years	
	Floor - Tile	1st Floor	183	SF	4	1-2 years	Cracked and damaged tile
	Floor - Wood	1st Floor	4,013	SF	6	10+ years	orached and damaged the
	Lighting - Pendent/Surface	1st Floor	37	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	12	EA	7	6-10 years	
	Main Floor Seating	1st Floor	416	EA	7	10+ years	
	Main Floor Seating	1st Floor	208	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	704	SF	6	10+ years	
	Stage Curtain	1st Floor	4	EA	7	10+ years	
	Stage Cultain Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Asphalt	1st Floor	4	LF	6	10+ years	
	Stairs - Asphalt	1st Floor	5	LF	6	•	
				SF		10+ years	
	Walls - Plaster/Dravall	1st Floor	100	SF SF	6 6	10+ years	
	Walls - Plaster/Drywall	1st Floor	10,012	SF	О	10+ years	
Gymnasi		0.151	4.040				
	Ceiling - Plaster/Drywall	3rd Floor	4,840	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Wood	3rd Floor	4,840	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Scoreboards	3rd Floor	1	EA	7	10+ years	
	Sound System	3rd Floor	1	EA	7	10+ years	
	Storage/ Closet	3rd Floor	738	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	38	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5,842	SF	6	10+ years	
Lunch &	Multipurpose Room						



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement -"A" Lunchroom	1,084	SF	6	10+ years	
	Floor - Tile	Basement -"A" Lunchroom	1,084	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement -"A" Lunchroom	7	EA	7	10+ years	
	Walls - Masonry	Basement -"A" Lunchroom	1,282	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement -"A" Lunchroom	641	SF	6	10+ years	
MDF ID	F						
<u> </u>	Doors - Steel Doors incl hw	Inside 206	1	EA	6	10+ years	
	Finishes	Inside 200 Inside 206	180	SF	5	2-5 years	
	Window AC Unit	Inside 200 Inside 206	180	EA	7	6-10 years	
	Willdow AC Offic	IIISIGE 200	ı	LA	,	0-10 years	
Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	12	SF	5	10+ years	
	Janitor's Closet	2nd Floor	18	SF	5	10+ years	
	Janitor's Closet	3rd Floor	12	SF	5	10+ years	
	Vaults	3rd Floor	100	SF	5	10+ years	
	Air Intake Plenums	Basement	1,158	SF	7	10+ years	
	Boiler Room	Basement	1,410	SF	5	10+ years	
	Coal Room	Basement	689	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	2,537	SF	5	10+ years	
	Storage Room	Basement	2,858	SF	5	10+ years	
Restroor	m						
	Accessories	1st FIr- Inside Main office	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FIr- Inside Main office	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FIr- Inside Main office	1	ĒΑ	6	10+ years	
	Floor - Tile	1st FIr- Inside Main office	45	SF	6	10+ years	
	Lavatory	1st FIr- Inside Main office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st FIr- Inside Main office	1	EΑ	7	6-10 years	
	Partitions	1st FIr- Inside Main office	1	EA	5	2-5 years	
	Walls - Plaster/Drywall	1st FIr- Inside Main office	98	SF	6	10+ years	
	Water Closet	1st FIr- Inside Main office	1	EA	6	10+ years	
	Accessories	3rd Floor - Gym	200	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor - Gym	200	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - Gym	1	EA	6	10+ years	
	Floor - Wood	3rd Floor - Gym	200	SF	6	10+ years	
	Lavatory	3rd Floor - Gym	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor - Gym	2	EA	7	10+ years	
	Partitions	3rd Floor - Gym	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - Gym	440	SF	6	10+ years	
	Water Closet	3rd Floor - Gym	440	SF EA	6		
	Accessories	Basement inside boiler room		SF		10+ years	
			16	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement inside boiler room	16	9F	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Basement inside boiler room	1	EA	5	1-2 years	Damaged door
	Floor - Concrete	Basement inside boiler room	16	SF	7	10+ years	
	Lavatory	Basement inside boiler room	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement inside boiler room	1	EA	7	6-10 years	
	Walls - Concrete Block	Basement inside boiler room	32	SF	5	6-10 years	
	Walls - Plaster/Drywall	Basement inside boiler room	10	SF	5	10+ years	Peeling paint
	Water Closet	Basement inside boiler room	1	EA	6	10+ years	
	Accessories	Basement next to engineer's office	88	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement next to engineer's office	88	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement next to engineer's office	1	EA	6	10+ years	
	Floor - Tile	Basement next to engineer's office	88	SF	6	10+ years	
	Floor Drain	Basement next to engineer's office	1	EA	7	10+ years	
	Lavatory	Basement next to engineer's office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement next to engineer's office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement next to engineer's office	212	SF	6	10+ years	
	Water Closet	Basement next to engineer's office	1	EA	6	10+ years	
	Accessories	Basement- Girls	776	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement- Girls	776	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement- Girls	4	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement- Girls	776	SF	5	6-10 years	
	Floor Drain	Basement- Girls	2	EA	7	10+ years	
	Lavatory	Basement- Girls	4	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement- Girls	12	EA	7	6-10 years	
	Partitions	Basement- Girls	10	EA	7	10+ years	
	Walls - Structural Glazed Tile	Basement- Girls	1,040	SF	5	2-5 years	
	Water Closet	Basement- Girls	3	EA	7	10+ years	
	Water Closet	Basement- Girls	7	EA	6	10+ years	

Category : Classroom

Croun	Itam Tuna	Location	Quantitu	LIOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	m #103 (Office)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,131	SF	6	10+ years	
	Doors - Transom Window	1st Floor	27	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Carpet	1st Floor	573	SF	6	6-10 years	
	Floor - Tile	1st Floor	558	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	15	EΑ	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Storage/ Closet	1st Floor	131	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,230	SF	6	10+ years	

Building: Main



Catego	ry : Classroom		В	uilding	: Main		3014 W 33111 EAGE, Officago, 12 00032
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	879	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	879	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	14	LF	7	6-10 years	
	Storage/ Closet	1st Floor	213	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,364	SF	6	10+ years	
_Classroo	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,131	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	1,131	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	, 21	ĒA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	185	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,145	SF	6	10+ years	
Classroo	om #106 (Music Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	65	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,508	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,131	SF	6	10+ years	
	Chalk Board	2nd Floor	25	LF	4	2-5 years	



Catego	ry : Classroom		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Transom Window	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,131	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	350	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	2,545	SF	6	6-10 years	
Classroo	om #204 (Regular Classroom)						
Oldooroc	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	15	SF	7	•	
	Ceiling - Plaster/Drywall	2nd Floor	864	SF		10+ years 10+ years	
	Chalk Board		25	LF	6	•	
		2nd Floor		SF	4	2-5 years	
	Doors - Transom Window	2nd Floor	24		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	879	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,364	SF	6	10+ years	
Classroo	om #205 (Computer Lab)						
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,121	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	['] 10	SF	5	1-2 years	Water damaged ceiling
	Chalk Board	2nd Floor	12	LF	4	2-5 years	3
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	. <u> </u>	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	10	SF	6	10+ years	
	Floor - Wood	2nd Floor	1,121	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	350	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,545	SF	6	6-10 years	
	Wireless System	2nd Floor	2,545	EA	7	10+ years	
	Wheless System	ZIIU FIOOI	1	EA	,	10+ years	
Classroo	om #206 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,092	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,092	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	2,444	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroc	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	593	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	493	SF	7	2-5 years	
	Floor - Tile	2nd Floor	100	SF	4	1-2 years	Cracked and damaged tile throughout
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	Cracked and damaged the imoughout
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall		1,049	SF	6	•	
	vvalis - Plaster/Drywali	2nd Floor	1,049	SF	б	10+ years	
Classroc	om #303 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,121	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,131	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	Not working
	Marker Board	3rd Floor	12	LF	7	6-10 years	3
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	12	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,418	SF	6	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	17	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	879	SF	6	10+ years	
	Doors - Transom Window			SF SF	6	,	
		3rd Floor	24			10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Wood	3rd Floor	879	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	17	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	



atego	ry : Classroom		В	uilding	: Main		
	_					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,364	SF	6	10+ years	
assroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	40	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,091	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,131	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	102	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,525	SF	6	10+ years	
assroo	m #306 (Science Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	36	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,084	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	8	SF	6	10+ years	
	Chalk Board	3rd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,092	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	Not working
	Marker Board	3rd Floor	8	LF	7	6-10 years	3
	Storage/ Closet	3rd Floor	180	SF	5	10+ years	Peeling paint on ceiling
	Walls - Plaster/Drywall	3rd Floor	2,434	SF	6	10+ years	31
	Walls - Plaster/Drywall	3rd Floor	10	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	10+ years	
assroo	m #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	736	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	6	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	1-2 years	Missing tile
	Doors - Side-lite	3rd Floor	70	SF	6	10+ years	



Category : Classroom

Nathan S Davis Elementary School 3014 W 39th PLACE, Chicago, IL 60632

						Recommend	
ıр	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	750	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	950	SF	6	10+ years	
tego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
rridor							
	Ceiling - Plaster/Drywall	1st Floor	2,582	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	ĒA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,582	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	28	ĒΑ	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	6,446	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,582	SF	6	6-10 years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,567	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	15	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	2nd Floor	29	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Not working
	Walls - Plaster/Drywall	2nd Floor	3,420	SF	6	6-10 years	J
	Ceiling - Plaster/Drywall	3rd Floor	15	SF	6	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	2,565	SF	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,574	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	6	SF	5	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	30	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	18	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	6,200	SF	6	10+ years	
	Ceiling - Exposed	Basement	1,527	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	823	SF	6	10+ years	
	Doors - Side-lite	Basement	12	SF	6	10+ years	
	Doors - Transom Window	Basement	90	SF	6	10+ years	
	Floor - Asphalt Floor	Basement	1,777	SF	6	10+ years	
	Floor - Terrazzo	Basement	573	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years	
	Lighting - Wall Mounted	Basement	2	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement	4	LF	5	6-10 years	
	Walls - Masonry	Basement	1,360	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	4,136	SF	6	10+ years	

Building: Main

Campus Name: Davis N Page : 16 of 59 Assessment Date: 11/06/2023



Catego	ry : Interior		В	uilding	: Main		
				Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Camera Viewing Station	1st Floor	3	EA	7	10+ years	
	Security Cameras	1st Floor	18	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Central Stairs- Basement to 1st Flr only	259	SF	6	10+ years	
	Handrails	Central Stairs- Basement to 1st Flr only	68	LF	7	10+ years	
	Stairs - Asphalt	Central Stairs- Basement to 1st Flr only	17	LF	5	10+ years	
	Walls - Plaster/Drywall	Central Stairs- Basement to 1st Flr only	777	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Interior Fire Escape stairwell- NW	438	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Interior Fire Escape stairwell- NW	8	SF	6	10+ years	
	Floor - Asphalt	Interior Fire Escape stairwell- NW	256	SF	5	2-5 years	
	Handrails	Interior Fire Escape stairwell- NW	132	LF	5	10+ years	
	Lighting - Pendent/Surface	Interior Fire Escape stairwell- NW	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	Interior Fire Escape stairwell- NW	1	EA	5	1-2 years	Not working
	Lighting - Wall Mounted	Interior Fire Escape stairwell- NW	4	EA	7	6-10 years	•
	Stairs - Asphalt	Interior Fire Escape stairwell- NW	264	LF	6	10+ years	Updated quantity
	Walls - Plaster/Drywall	Interior Fire Escape stairwell- NW	8	SF	6	10+ years	
	Walls - Plaster/Drywall	Interior Fire Escape stairwell- NW	932	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South East	892	SF	6	10+ years	
	Floor - Asphalt	South East	436	SF	6	10+ years	
	Handrails	South East	192	LF	7	10+ years	
	Lighting - Pendent/Surface	South East	6	EA	7	6-10 years	
	Stairs - Asphalt	South East	780	LF	6	10+ years	
	Walls - Plaster/Drywall	South East	1,822	SF	6	10+ years	
	Walls - Plaster/Drywall	South East	12	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South West	1,105	SF	6	10+ years	
	Floor - Asphalt	South West	645	SF	6	10+ years	
	Handrails	South West	218	LF	7	10+ years	
	Lighting - Pendent/Surface	South West	7	ĒΑ	7	6-10 years	
	Stairs - Asphalt	South West	910	LF	6	10+ years	
	Walls - Plaster/Drywall	South West	26	SF	6	10+ years	
	Walls - Plaster/Drywall	South West	2,034	SF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Door 3 - East	1	EA	7	10+ years	New
	Exterior Doors - Exterior Steel Door	Door 3 - East	3	EA	5	6-10 years	
	Exterior Stairs - Concrete	Door 3 - East	30	LF	7	10+ years	Rebuilt
	Ramp Handrail - Steel_Ramp Handrail	Door 3 - East	50	LF	7	10+ years	New
	Ramps - Concrete	Door 3 - East	25	LF	7	10+ years	New
	Stair Handrail - Steel_Stair Handrail	Door 3 - East	30	LF	7	10+ years	New
Foundati	on						
	Foundation - Masonry	Entire Building	191	LF	7	10+ years	No exposed foundation
	Superstructure - Steel with Clay Tile Arch	Entire Building	15,412	SF	7	10+ years	No exposed superstructure
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	6-10 years	
Roof Svs	stem .						
	Coping - Clay Tile	Main Roof	16	LF	7	10+ years	
	Coping - Terra Cotta	Main Roof	175	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	63	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Main Roof	101	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	90	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	3,853	SF	7	6-10 years	
	Roof Structure - Steel / Metal Deck/	Main Roof	3,853	SF	7	10+ years	
	Concrete Topping		3,000	σ.	·	.o. you.o	
Walls							
<u>-</u>	Cornice - Terra Cotta	Entire Building	586	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	10,724	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	750	SF	6	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	296	SF	6	6-10 years	
	Lintels - Steel	Entire Building	149	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	116	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,826	SF	7	6-10 years	
Catego	ry : Electrical		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergen	icy System						
	<u> </u>						

Campus Name: Davis N Page : 18 of 59 Assessment Date: 11/06/2023



Nathan S Davis Elementary School

Hegory: Electrical Building: Addition 1 Recommend
Location Quantity UOM Rank Replacement Comments Exit Signs - Corridors and Stairs Basement 1 EA 6 6-10 years Security System - CCTV Entire Building 15,412 SF 5 6-10 years Security System - Intrusion Detection Entire Building 15,412 SF 5 6-10 years Saturs Stairs Emergency A/C Power - Corridors and Entire Building 2,086 SF 6 10+ years Stairs Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years Stairs Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years Stairs Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years Stairs Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years Stairs Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years Served by Main. In Service PA System Entire Building 15,412 SF 5 6-10 years Served by Main. Wer Distribution Lighting and Power Panels - 100 A Entire Building 1 EA 6 6 10+ years Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6 10+ years Served by Main. Wer Distribution Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6 10+ years Served by Main. Wer Distribution Lighting and Power Panels - Move 100 A Entire Building 1 EA 6 6 10+ years Served by Main. Wer Distribution Lighting and Power Panels - 100 A Entire Building 1 EA 6 6 10+ years Served by Main. Wer Distribution Lighting and Power Panels - 100 A Entire Building 1 EA 7 6 6-10 years Served by Main. Recommend Replacement Comments Wer Distribution Lighting and Power Panels - 100 A Entire Building 15,412 SF 7 10+ years Pipe Alarm Strobe Lights Entire Building 15,412 SF 7 10+ years Pipe Alarm Strobe Lights Entire Building 15,412 SF 7 10+ years Pipe Alarm Strobe Lights Entire Building 15,412 SF 7 10+ years Pipe Alarm Strobe Lights Entire Building 15,412 SF 7 10+ years Pipe Alarm Strobe Lights Entire Building 15,412 SF 7 10+ years Pipe Alarm Strobe Lights Entire Building 15,412 SF 7 10+ years Pipe Alarm Strobe Lights Entire Building 15,412 SF 7 10+ years Pipe Alarm Strobe Lights Entire Building 15,412 SF 7 10+ yea
Extl Signs - Corridors and Stairs Security System - CCTV Security System - CCTV Security System - Intrusion Detection Stairs Emergency Battery Packs - Corridors and Stairs Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Corridors and Stairs Entire Building Stairs Emergency A/C Power - Lunchrooms Entire Building Stairs PA System Entire Building Stairs PA System Entire Building Security System Entire Building Security System Stairs Stairs Stairs PA System Entire Building Security System Security System Stairs Stairs Stairs Stairs Stairs PA System Entire Building Security System Security System Security System Stairs Stai
Security System - CCTV Security System - Intrusion Detection Entire Building Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Corridors and Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years Stairs Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years PA System Entire Building 1,303 SF 6 10+ years Entire Building 1,30
Security System - Intrusion Detection Entire Building 15,412 SF 5 6-10 years Chargenge pattery Packs - Corridors and Stairs Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Corridors and Entire Building 2,086 SF 6 10+ years Stairs Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years Served by Main. Service PA System Entire Building 15,412 SF 5 6-10 years Served by Main. Service PA System Entire Building 1 EA 6 10+ years Lighting and Power Panels - 100 A Entire Building 1 EA 6 6-10 years Served by Main. Server Distribution Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Served by Main. Setting Protection Building : Addition 1 Recommend Replacement Fire Alarm Strobe Lights Entire Building 15,412 SF 7 10+ years Served by Main. Fire Alarm Strobe Lights Entire Building 15,412 SF 7 10+ years Served by Main. Setting Building : Addition 1 Setting Building : Addition
Emergency Battery Packs - Corridors and Stairs Stairs Emergency A/C Power - Corridors and Entire Building Stairs Emergency A/C Power - Corridors and Entire Building Stairs Emergency A/C Power - Lunchrooms Entire Building Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years In Service PA System Entire Building PA System Entire Building 15,412 SF 5 6-10 years Etgory: Fire Protection Etgory: Fire Protection Etgory: Fire Protection Entire Building Entire Bui
Emergency Battery Packs - Corridors and Stairs Stairs Emergency A/C Power - Corridors and Entire Building Stairs Emergency A/C Power - Corridors and Entire Building Stairs Emergency A/C Power - Lunchrooms Entire Building Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years In Service PA System Entire Building PA System Entire Building 15,412 SF 5 6-10 years Etgory: Fire Protection Etgory: Fire Protection Etgory: Fire Protection Entire Building Entire Bui
Stairs Emergency A/C Power - Corridors and Entire Building 2,086 SF 6 10+ years Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years PA System Entire Building 15,412 SF 5 6-10 years Served by Main. Ver Distribution Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Lighting and Power Panels - 100 A Entire Building 1 EA 6 6-10 years Lighting and Power Panels - 100 A Entire Building 1 EA 6 6-10 years Lighting and Power Panels - 100 A Entire Building 1 EA 6 6-10 years Experiment I Experimen
Emergency A/C Power - Corridors and Stairs Stairs Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years In Service PA System Entire Building 15,412 SF 5 6-10 years Served by Main. Wer Distribution Lighting and Power Panels - 100 A Entire Building Lighting and Power Panels - Above 100 A Entire Building Lighting and Power Panels - Above 100 A Entire Building Entire Building Entire Building Emergency: Fire Protection Building: Addition 1 Recommend Replacement Fire Alarm Strobe Lights Fire Alarm_System Entire Building Entire Buildi
Stairs Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years PA System Entire Building 15,412 SF 5 6-10 years Served by Main. Ver Distribution Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 10+ years Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Elighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Elighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Elighting - Addition 1 Recommend Replacement Fire Alarm Strobe Lights Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Entire Building 15,412 SF 7 10+ years Fire Alarm Strobe Lights Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm Strobe Lights Fire Alarm Strobe
Emergency A/C Power - Lunchrooms Entire Building 1,303 SF 6 10+ years PA System Entire Building 15,412 SF 5 6-10 years Served by Main. Ver Distribution Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 10+ years Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years Location Quantity UOM Rank Replacement Report Comments Fire Alarm Strobe Lights Fire Alarm System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Panel Alarm System Interest Panel Building 15,412 SF 7 10+ years Panel Alarm System Replacement Panel Alarm System Interest Panel Building 15,412 SF 7 10+ years Panel Alarm System Replacement Panel Alarm System Replacement Panel Building 15,412 SF 7 10+ years Panel Alarm System Replacement Panel Alarm System Replacement Panel Alarm System Replacement Panel Recommend Replacement Panel Recommen
In Service PA System Part Panels - 100 A Entire Building Part Panels - Above 100 A Entire Building PA System PA Syst
PA System Entire Building 15,412 SF 5 6-10 years Served by Main. Part
PA System Entire Building 15,412 SF 5 6-10 years Served by Main. Part
Lighting and Power Panels - 100 A Entire Building 1 EA 6 10+ years 1 EA 6 6-10 years tegory : Fire Protection Building : Addition 1 Recommend Replacement Fire Alarm Strobe Lights Fire Alarm_System Entire Building 15,412 SF 7 10+ years 10+ years 15,412 SF 7 10+ years 10+ years 10+ years 15,412 SF 7 10+ years 10+ years 10+ years 15,412 SF 7 10+ years 10+ years 15,412 SF 7 10+ years 10+ years 15,412 SF 7 10+ years 10+ years 10+ years 15,412 SF 7 10+ years 10+ years 10+ years 15,412 SF 7 10+ years 10
Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years tegory : Fire Protection Building : Addition 1 The Alarm Strobe Lights Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years E
Lighting and Power Panels - Above 100 A Entire Building 1 EA 6 6-10 years tegory : Fire Protection Building : Addition 1 The Alarm Strobe Lights Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years E
tegory : Fire Protection Building : Addition 1 Recommend Replacement Alarm Fire Alarm Strobe Lights Fire Alarm_System Fire Alarm_System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Rank, Reason and Priority Rep changed as the Fire Alarm Syste has been replaced since previous assessment. Recommend Recommend Alarm_System Recommend Rec
Location Quantity UOM Rank Recommend Replacement Comments Co
Location Quantity UOM Rank Replacement Comments A Alarm Fire Alarm Strobe Lights Fire Alarm System Entire Building 15,412 SF 7 10+ years Fire Alarm_System Entire Building 15,412 SF 7 10+ years Rank, Reason and Priority Rep changed as the Fire Alarm System has been replaced since previous assessment. Building : Addition 1 Recommend Replacement Comments Pup Item - Type Location Quantity UOM Rank Replacement Comments Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years Entire Building TS LF 6 10+ years
Fire Alarm Strobe Lights Fire Alarm Strobe Lights Fire Alarm System Entire Building Fire Alarm Strobe Lights Fire Alarm System Entire Building Fire Alarm System Entire Building Fire Alarm System Entire Building Fire Alarm Strobe Lights Fire Alarm System Entire Building Fire Alarm Strobe Lights Fire Alarm System Entire Building Fire Alarm System Entire Build
Fire Alarm Strobe Lights Fire Alarm_System Entire Building 15,412 Fire Alarm_System Entire Building Fire Alarm Strobe Lights Fire Alarm_System Entire Building Entire Building Fire Alarm_System Entire Building Entire Building Fire Alarm_System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep Rank, Reason and Priority Rep Rank Building Rank Building Rank Building Rank
Fire Alarm Strobe Lights Fire Alarm_System Entire Building 15,412 Fire Alarm_System Entire Building Fire Alarm Strobe Lights Fire Alarm_System Entire Building Entire Building Fire Alarm_System Entire Building Entire Building Fire Alarm_System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep changed as the Fire Alarm System Rank, Reason and Priority Rep Rank, Reason and Priority Rep Rank Building Rank Building Rank Building Rank
Fire Alarm_System Entire Building 15,412 SF 7 10+ years Rank, Reason and Priority Rep changed as the Fire Alarm System has been replaced since previous assessment. Recommend Recommend Recommend Replacement Comments Piping - Condensate Pipe- Steel Entire Building T5 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building T5 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building T5 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building T5 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building T5 LF 6 10+ years
changed as the Fire Alarm System tegory : Mechanical Building : Addition 1 Recommend Pup Item - Type Location Quantity Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years Atting Devices
has been replaced since previous assessment. Recommend Pulp Item - Type
tegory : Mechanical Building : Addition 1 Recommend Pup Item - Type Location Quantity UOM Rank Replacement Comments Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building To the first second to the property of the pro
tegory : Mechanical Building : Addition 1 Recommend Pup Item - Type Location Quantity Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years The steam Pipe- Steel Entire Building Piping - Steam Pipe- Steel Entire Building
Piping - Condensate Pipe- Steel Entire Building 75 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years
bup Item - Type Location Quantity UOM Rank Replacement Comments Systems
ler Systems Piping - Condensate Pipe- Steel Entire Building 75 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years ating Devices
Piping - Condensate Pipe- Steel Entire Building 75 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years ating Devices
Piping - Condensate Pipe- Steel Entire Building 75 LF 6 10+ years Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years ating Devices
Piping - Steam Pipe- Steel Entire Building 75 LF 6 10+ years
ating Devices
Radiators - Steam Entire Building 4 EA 3 0-1 year Per review with Building Engineer
J
radiators are in service at this sch
as they are not needed in the
locations where they are installed
they are nonfunctional and they h
been deemed obsolete. Rank,
Reason and Priority Rep adjusted this equipment has been abandon

Campus Name: Davis N Page : 19 of 59 Assessment Date: 11/06/2023



Catego	ory : Mechanical		В	uilding	: Additi	on 1	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	in place. Quantity changed to match current observations. Priority Rep adjusted based on current observations and othe age of the equipment.
	Fin Tube - Steam	Entire Building	30	LF	3	0-1 year	Per review with Building Engineer, not fin tube heating is in service at this school as it is not needed in the locations where it is installed; it is nonfunctional and has been deemed obsolete. Rank, Reason and Priority Rep adjusted as this equipment has been abandoned in place.
Tempera	ature Control						
·	DDC System	Entire Building	15,412	SF	7	6-10 years	
	Thermostats - DDC	Entire Building	10	EA	7	6-10 years	Item Type changed to match current observations.
Ventilati							
	Exhaust Fans- Indoor - 500 - 1500 CFM Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building Entire Building	1 1	EA EA	6 6	10+ years 10+ years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen Type II Exhaust Hood- Warming Kitchen	Entire Building Entire Building	1 1	EA EA	2 6	0-1 year 10+ years	No fire suppression system present.
Catego	ory : Plumbing		В	uilding	: Additi	on 1	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping_	Domostic Dining Llot Weter Deturn Lines	Entire Duilding	15 440	SF	4	2 E vecre	Quantity shanged as total has been
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water from Risers to Fixtures	Entire Building Entire Building	15,412 15,412	SF	4	2-5 years 2-5 years	Quantity changed as total has been divided/aggregated. Majority of piping is galvanized material over 60 years old and has exceeded its EUL. A number of pipe clamps are in place throughout the building. Quantity changed as total has been divided/aggregated. Majority of piping is galvanized material over 60 years old and has exceeded its EUL. A number of pipe clamps are in place



Catego	ry : Plumbing		В	uilding	: Addition	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	15,412	SF	4	2-5 years	throughout the building. Quantity changed as total has been divided/aggregated. Majority of piping is galvanized material over 60 years old and has exceeded its EUL. A number of pipe clamps are in place throughout the building.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	15,412	SF	4	2-5 years	Quantity changed as total has been divided/aggregated. Majority of piping is galvanized material over 60 years old and has exceeded its EUL. A number of pipe clamps are in place throughout the building.
	Sanitary Piping Storm Piping Vent Piping	Entire Building Entire Building Entire Building	15,412 15,412 15,412	SF SF SF	6 6 6	10+ years 10+ years 10+ years	

Category : Room **Building: Addition 1**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	2nd Flr- Between 201 & 202	230	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Flr- Between 201 & 202	1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	2nd Flr- Between 201 & 202	225	SF	5	6-10 years	
	Floor - Concrete Epoxy/ Painted	2nd Flr- Between 201 & 202	5	SF	4	1-2 years	Damaged flooring
	Lighting - Pendent/Surface	2nd Flr- Between 201 & 202	2	EA	7	6-10 years	-
	Power Distribution	2nd Flr- Between 201 & 202	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Flr- Between 201 & 202	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd FIr- Between 301 & 302	230	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd FIr- Between 301 & 302	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd FIr- Between 301 & 302	230	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd FIr- Between 301 & 302	1	EA	7	6-10 years	
	Power Distribution	3rd FIr- Between 301 & 302	10	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd FIr- Between 301 & 302	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement- Kitchen Office	126	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement- Kitchen Office	1	EA	6	10+ years	
	Floor - Tile Quarry	Basement- Kitchen Office	126	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement- Kitchen Office	3	EA	7	6-10 years	
	Power Distribution	Basement- Kitchen Office	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	Basement- Kitchen Office	283	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement- Teacher lounge	395	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement- Teacher lounge	1	EA	6	10+ years	
	Floor - Tile	Basement- Teacher lounge	395	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement- Teacher lounge	4	EA	7	6-10 years	

Campus Name: Davis N Page : 21 of 59 Assessment Date: 11/06/2023



Catego	ry : Room		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Basement- Teacher lounge	6	EA	7	10+ years	
	Walls - Concrete Block	Basement- Teacher lounge	158	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement- Teacher lounge	563	SF	6	6-10 years	
Kitchen							
Tatonon	Ceiling - Plaster/Drywall	Basement	575	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile Quarry	Basement	575	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	7	6-10 years	
	Serving Line	Basement	22	LF	6	10+ years	
	Walls - Structural Glazed Tile	Basement	773	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain		386	SF	6		
	waiis - Tile Ceramic/ Porcelain	Basement	300	SF	О	10+ years	
Locker/S	Shower Room						
	Accessories	Basement- In Kitchen	80	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement- In Kitchen	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement- In Kitchen	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement- In Kitchen	80	SF	6	10+ years	
	Lavatory	Basement- In Kitchen	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	Basement- In Kitchen	2	EΑ	7	6-10 years	
	Partitions	Basement- In Kitchen	1	EΑ	7	10+ years	
	Student Lockers - One Tier	Basement- In Kitchen	7	EA	6	10+ years	
	Walls - Structural Glazed Tile	Basement- In Kitchen	188	SF	6	10+ years	
	Water Closet	Basement- In Kitchen	1	EA	6	10+ years	
_Lunch &	Multipurpose Room	D				0.10	
	Ceiling - Plaster/Drywall	Basement "B" Lunchroom	888	SF	6	6-10 years	
	Floor - Tile	Basement "B" Lunchroom	888	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement "B" Lunchroom	21	EA	7	6-10 years	
	Walls - Masonry	Basement "B" Lunchroom	1,195	SF	6	10+ years	
	Ceiling - Exposed	Basement- Servery	415	SF	6	10+ years	
	Floor - Terrazzo	Basement- Servery	335	SF	5	6-10 years	
	Floor - Terrazzo	Basement- Servery	80	SF	4	1-2 years	Pitted/cracked floor
	Lighting - Pendent/Surface	Basement- Servery	10	EA	7	6-10 years	
	Serving Line	Basement- Servery	28	LF	6	6-10 years	
	Walls - Structural Glazed Tile	Basement- Servery	700	SF	6	10+ years	
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	12	SF	5	10+ years	
	Janitor's Closet	2nd Floor	18	SF	5	10+ years	
	Janitor's Closet	3rd Floor	18	SF	5	10+ years	
Б.							
Restroor	n						

Campus Name: Davis N Page : 22 of 59 Assessment Date: 11/06/2023



Catego	ry : Room		В	uilding	: Additi	on 1	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st FIr- Next to 102	368	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FIr- Next to 102	368	SF	6	10+ years	
	Doors - Transom Window	1st FIr- Next to 102	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FIr- Next to 102	2	EA	6	10+ years	
	Floor - Terrazzo	1st FIr- Next to 102	356	SF	6	10+ years	
	Floor - Terrazzo	1st FIr- Next to 102	12	SF	5	2-5 years	
	Floor Drain	1st FIr- Next to 102	1	EA	7	10+ years	
	Hand Dryer	1st FIr- Next to 102	2	EA	7	6-10 years	
	Lavatory	1st FIr- Next to 102	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st FIr- Next to 102	5	EA	7	6-10 years	
	Partitions	1st FIr- Next to 102	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st FIr- Next to 102	223	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st FIr- Next to 102	522	SF	5	2-5 years	
	Walls - Tile Ceramic/ Porcelain	1st FIr- Next to 102	300	SF	7	10+ years	
	Water Closet	1st FIr- Next to 102	6	EA	6	10+ years	
	Accessories	2nd Flr- Next to 202	368	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Flr- Next to 202	368	SF	6	10+ years	
	Doors - Transom Window	2nd FIr- Next to 202	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd FIr- Next to 202	2	EA	6	10+ years	
	Floor - Terrazzo	2nd Flr- Next to 202	368	SF	6	10+ years	
	Floor Drain	2nd FIr- Next to 202	1	EA	7	10+ years	
	Hand Dryer	2nd FIr- Next to 202	2	EA	7	6-10 years	
	Lavatory	2nd FIr- Next to 202	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Flr- Next to 202	5	EA	7	6-10 years	
	Partitions	2nd Flr- Next to 202	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd FIr- Next to 202	511	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Flr- Next to 202	12	SF	5	1-2 years	Moisture damage
	Walls - Structural Glazed Tile	2nd Flr- Next to 202	522	SF	5	2-5 years	Ç
	Water Closet	2nd Flr- Next to 202	6	EA	6	10+ years	
	Accessories	3rd FIr- Next to 302	368	SF	5	1-2 years	Damaged accessories
	Ceiling - Plaster/Drywall	3rd FIr- Next to 302	348	SF	6	10+ years	C
	Ceiling - Plaster/Drywall	3rd FIr- Next to 302	20	SF	5	1-2 years	Water damaged ceiling
	Doors - Transom Window	3rd FIr- Next to 302	18	SF	6	10+ years	c c
	Doors - Wood Doors inclu hw	3rd FIr- Next to 302	2	EA	6	10+ years	
	Floor - Terrazzo	3rd FIr- Next to 302	368	SF	6	10+ years	
	Floor Drain	3rd FIr- Next to 302	1	EA	7	10+ years	
	Hand Dryer	3rd FIr- Next to 302	2	EA	7	6-10 years	
	Lavatory	3rd FIr- Next to 302	3	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Flr- Next to 302	5	EA	7	6-10 years	
	Partitions	3rd FIr- Next to 302	6	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Flr- Next to 302	518	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Flr- Next to 302	5	SF	5	1-2 years	Damage to wall
	Walls - Structural Glazed Tile	3rd Flr- Next to 302	522	SF	5	10+ years	. 9
	Water Closet	3rd Flr- Next to 302	6	ĒΑ	6	10+ years	
			-			,	

Campus Name: Davis N Page : 23 of 59 Assessment Date: 11/06/2023



Catego	ry : Room		В	uilding	: Additi	on 1	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	пеш - туре	Location	Quantity	UOW	Kalik	Replacement	Comments
Catego	ry : Classroom		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	m #101 (Library)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	130	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,444	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Wood	1st Floor	1,444	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	46	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,792	SF	6	10+ years	
Classroo	m #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood Bools Incid Hw	1st Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	44	SF	7	,	
				SF SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,508	SF	0	10+ years	
Classroo	m #200 (Special Education)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	536	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	527	SF	6	10+ years	
	Floor - Tile	2nd Floor	9	SF	4	1-2 years	Rust stained tile
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,100	SF	6	10+ years	
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
						·	

Campus Name: Davis N Page : 24 of 59 Assessment Date: 11/06/2023



Catego	ry : Classroom		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	14	SF	7	6-10 years	
	Floor - Wood	2nd Floor	806	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,508	SF	6	10+ years	
Classroo	nm #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor 2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	12	EA	6	-	
					_	10+ years	
	Floor - Wood	2nd Floor	806	SF	6	10+ years	
	Floor - Wood	2nd Floor	14	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	12	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,500	SF	6	10+ years	
Classroo	m #300 (Special Education)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	536	SF	6	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	8	SF	6	10+ years	
	Floor - Tile	3rd Floor	504	SF	6	10+ years	
	Floor - Tile	3rd Floor	24	SF	4	1-2 years	Damaged and cracked tile througho
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	Damaged and cracked the imought
	Lighting - Pendeni/Surface Lighting - Wall Mounted	3rd Floor	1	EA	7	10+ years	
	Marker Board	3rd Floor	•	LF	7		
			8			6-10 years	
	Walls - Plaster/Drywall	3rd Floor	856	SF	6	10+ years	
Classroc	om #301 (Store Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	806	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	14	SF	6	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	

Campus Name: Davis N Page : 25 of 59 Assessment Date: 11/06/2023



las	issroom			В	uilding	: Additi	on 1	
					_		Recommend	
	Type	Lo	ocation	Quantity	UOM	Rank	Replacement	Comments
s -	- Transom Window	3r	rd Floor	12	SF	6	10+ years	
s -	- Wood Doors inclu hw	3r	rd Floor	1	EA	6	10+ years	
٠ -	· Wood	3r	rd Floor	820	SF	6	10+ years	
er	r Board	3r	rd Floor	8	LF	7	6-10 years	
age	je/ Closet	3r	rd Floor	44	SF	7	10+ years	
3 -	- Plaster/Drywall	3rd	rd Floor	1,400	SF	6	10+ years	
2 ((Regular Classroom)							
	nits	3r	rd Floor	2	EA	7	6-10 years	
	vork	3r	rd Floor	10	LF	6	10+ years	
	g - Plaster/Drywall	3r	rd Floor	802	SF	6	10+ years	
	g - Plaster/Drywall	3r	rd Floor	18	SF	6	10+ years	
	Board	3r	rd Floor	36	LF	4	2-5 years	
s -	- Transom Window	3r	rd Floor	12	SF	6	10+ years	
s -	- Wood Doors inclu hw	3r	rd Floor	1	EA	6	10+ years	
	· Wood	3r	rd Floor	806	SF	6	10+ years	
٠_	· Wood	3r	rd Floor	14	SF	6	10+ years	
ing	g - Pendent/Surface	3r	rd Floor	14	EA	7	6-10 years	
	r Board	3r	rd Floor	6	LF	7	6-10 years	
age	je/ Closet	3r	rd Floor	44	SF	7	10+ years	
	- Plaster/Drywall	3r	rd Floor	5	SF	6	10+ years	
	- Plaster/Drywall	3r	rd Floor	1,505	SF	6	•	
	Sink	3r	rd Floor	1	EA	7	10+ years	
S				1		7		•

Building: Addition 1 Category : Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	227	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	200	SF	6	10+ years	Peeling paint
	Floor - Tile/Sheet	1st Floor	427	SF	7	10+ years	•
	Lighting - Pendent/Surface	1st Floor	4	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	786	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	427	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	427	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	786	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	427	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	427	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	786	SF	6	10+ years	
	Ceiling - Exposed	Basement	734	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	71	SF	6	6-10 years	
	Doors - Transom Window	Basement	9	SF	5	10+ years	

Campus Name: Davis N Page : 26 of 59 Assessment Date: 11/06/2023



Catego	ry : Interior		В	uilding	: Additi	on 1	,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors include hw	Basement	2	EΑ	5	10+ years	
	Doors - Wood Doors include hw	Basement	1	EA	5	0-1 year	Missing door
	Floor - Asphalt Floor	Basement	585	SF	5	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement	71	SF	5	6-10 years	
	Floor - Tile/Sheet	Basement	149	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	10	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement	4	LF	5	10+ years	
	Walls - Concrete Block	Basement	144	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	851	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	86	SF	5	10+ years	
	Walls - Structural Glazed Tile	Basement	270	SF	5	10+ years	
_Safetv							
,	Security Cameras	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	8	EA	7	6-10 years	



Catego	ry : Exterior		В	uilding	: Additi		
0	Ham Time	Laastian	O amtitu	HOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	Exterior Doors - Exterior Steel Door	Door 6 - West	3	EA	5	2-5 years	Repaired, but still rust on frame
	Exterior Stairs - Concrete	Door 6 - West	3 11	LF	5 6	2-5 years 10+ years	Repaired, but still rust on frame
	Exterior Stairs - Concrete	Door o - west	11	L	O	10+ years	
Foundati							
	Foundation - Masonry	Entire Building	290	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	26,452	SF	7	10+ years	No exposed superstructure
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	7	6-10 years	
Roof Sys	tem Access Ladder - Metal	Main Roof	2	EA	7	10+ years	
	Coping - Clay Tile	Main Roof	50	LF	7	10+ years	
	Coping - Terra Cotta	Main Roof	245	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	63	LF	6	6-10 years	
	Parapet - Parapet > 30"	Main Roof	295	LF	7	10+ years	Recombined quantities
	Roof - Modified Bitumen	Main Roof	6,613	SF	7	6-10 years	rtocomonica quantitico
	Roof Hatch - Metal	Main Roof	1	EA	7	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	6,613	SF	7	10+ years	
Valls							
wans -	Cornice - Terra Cotta	Entire Building	880	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	16,087	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,126	SF	6	10+ years	
Vindows							
	Guard - Guards perforated	Entire Building	444	SF	6	6-10 years	
	Lintels - Steel	Entire Building	223	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	175	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,738	SF	7	6-10 years	
Catego	ry : Electrical		В	uildina	: Additi	on 2	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
mergen	cy System						
	Security System - CCTV	Entire Building	26,452	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	26,452	SF	5	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	Rank changed based on current
							observations and per review with
							Building Engineer, as no Exit Sig

Campus Name: Davis N Page : 28 of 59 Assessment Date: 11/06/2023



Catego	ry : Electrical			uilding	. Additi		
Craun	Hom. Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity	UOW	Kank	Replacement	need to be added or moved.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	10	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,817	SF	6	6-10 years	arriadar aggregatoa.
Main Se	rvice						
	PA System	Entire Building	26,452	SF	6	6-10 years	Served by Main.
⊃ower D	vistribution						
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Entire Building Entire Building	1 3	EA EA	6 6	10+ years 10+ years	
Catego	ry : Fire Protection		В	uilding	: Additio	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	m						
ire Alar		F 41 B 11 11	00.450	~=			
Fire Alar	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	26,452 26,452	SF SF	7 7	6-10 years 6-10 years	Rank, Reason and Priority Rep changed as the Fire Alarm System has been replaced since previous assessment.
Fire Alar	Fire Alarm Strobe Lights		26,452	SF		6-10 years	changed as the Fire Alarm System has been replaced since previous
Catego	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical	Entire Building	26,452 B	SF uilding	7 : Additio	6-10 years on 2 Recommend	changed as the Fire Alarm System has been replaced since previous assessment.
Catego ∋roup	Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type		26,452	SF	7	6-10 years	changed as the Fire Alarm System has been replaced since previous assessment.
Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type tling Systems	Entire Building Location	26,452 B	SF uilding UOM	7 : Addition	6-10 years on 2 Recommend Replacement	changed as the Fire Alarm System has been replaced since previous assessment. Comments
Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type	Entire Building	26,452 B	SF uilding	7 : Additio	6-10 years on 2 Recommend	changed as the Fire Alarm System has been replaced since previous assessment.
Catego ∋roup	Fire Alarm Strobe Lights Fire Alarm_System Ty: Mechanical Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake	Location Mechanical Room - AHU-2 Mechanical Room - AHU-2	26,452 B Quantity	uilding UOM EA EA	7 : Addition Rank 5 6	6-10 years On 2 Recommend Replacement 6-10 years 10+ years	changed as the Fire Alarm System has been replaced since previous assessment. Comments
Catego Group	Fire Alarm Strobe Lights Fire Alarm_System Ty: Mechanical Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm	Location Mechanical Room - AHU-2 Mechanical Room - AHU-2 Mechanical Room - AHU-2 Mechanical Room - AHU-2	26,452 B Quantity 1 1 1 1	uilding UOM EA EA EA	7 : Addition Rank 5 6 5	6-10 years Pon 2 Recommend Replacement 6-10 years 10+ years 6-10 years	changed as the Fire Alarm System has been replaced since previous assessment. Comments
Catego Group	Fire Alarm Strobe Lights Fire Alarm_System Ty: Mechanical Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake	Location Mechanical Room - AHU-2 Mechanical Room - AHU-2	26,452 B Quantity 1 1	uilding UOM EA EA	7 : Addition Rank 5 6	6-10 years On 2 Recommend Replacement 6-10 years 10+ years	changed as the Fire Alarm System has been replaced since previous assessment. Comments
Catego ∋roup	Fire Alarm Strobe Lights Fire Alarm_System Ty: Mechanical Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft	Location Mechanical Room - AHU-2 Mechanical Room - AHU-2 Mechanical Room - AHU-2 Mechanical Room - AHU-2	26,452 B Quantity 1 1 1 1	uilding UOM EA EA EA	7 : Addition Rank 5 6 5	6-10 years Pon 2 Recommend Replacement 6-10 years 10+ years 6-10 years	changed as the Fire Alarm System has been replaced since previous assessment. Comments
Catego Group Air Hand	Fire Alarm Strobe Lights Fire Alarm_System Ty: Mechanical Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers	Location Mechanical Room - AHU-2	26,452 B Quantity 1 1 1 1 100	UOM EA EA EA EA EA	7 : Addition Rank 5 6 5 5 5	6-10 years Recommend Replacement 6-10 years 10+ years 6-10 years 6-10 years	changed as the Fire Alarm System has been replaced since previous assessment. Comments
Catego Group	Fire Alarm Strobe Lights Fire Alarm_System Ty: Mechanical Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers Vistems Piping - Condensate Pipe- Steel	Location Mechanical Room - AHU-2 Mechanical Room - AHU-2	26,452 B Quantity 1 1 1 1 100	UOM EA EA EA LF	7 : Addition Rank 5 6 5 5 5 6	6-10 years On 2 Recommend Replacement 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years	changed as the Fire Alarm System has been replaced since previous assessment. Comments
Catego Group Air Hand	Fire Alarm Strobe Lights Fire Alarm_System Ty: Mechanical Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers Vistems Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel	Location Mechanical Room - AHU-2 Mechanical Room - AHU-2	26,452 B Quantity 1 1 1 100 15	UOM EA EA EA LF LF LF	7 : Addition Rank 5 6 5 5 5	6-10 years On 2 Recommend Replacement 6-10 years 10+ years 6-10 years 6-10 years 6-10 years	changed as the Fire Alarm System has been replaced since previous assessment. Comments
Catego Group Air Hand	Fire Alarm Strobe Lights Fire Alarm_System Ty: Mechanical Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers Vistems Piping - Condensate Pipe- Steel	Location Mechanical Room - AHU-2 Mechanical Room - AHU-2	26,452 B Quantity 1 1 1 100 15	UOM EA EA EA LF	7 : Addition Rank 5 6 5 5 5 6	6-10 years On 2 Recommend Replacement 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years	changed as the Fire Alarm System has been replaced since previous assessment. Comments
Catego Group Air Hand Boiler Sy	Fire Alarm Strobe Lights Fire Alarm_System Ty: Mechanical Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers Vistems Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel	Location Mechanical Room - AHU-2 Mechanical Room - AHU-2	26,452 B Quantity 1 1 1 100 15 150 150	UOM EA EA EA LF LF LF	7 : Addition Rank	6-10 years On 2 Recommend Replacement 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	changed as the Fire Alarm System has been replaced since previous assessment. Comments

Campus Name: Davis N Page : 29 of 59 Assessment Date: 11/06/2023



Catego	Category : Mechanical			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	radiators are in service at this school as they are not needed in the locations where they are installed; they are nonfunctional and they have been deemed obsolete. Rank, Reason and Priority Rep adjusted as this equipment has been abandoned in place.
	Wall Heater - Electric Fin Tube - Steam	Entire Building Entire Building	2 30	EA LF	5 3	6-10 years 0-1 year	Per review with Building Engineer, no fin tube heating is in service at this school as it is not needed in the locations where it is installed; it is nonfunctional and has been deemed obsolete. Rank, Reason and Priority Rep adjusted as this equipment has been abandoned in place.
_Tempera	ature Control						
	DDC System Thermostats - DDC	Entire Building Entire Building	26,452 15	SF EA	6 6	6-10 years 6-10 years	
<u>Ventilation</u>	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	7	10+ years	

Category : Plumbing **Building: Addition 2**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	26,452	SF	4	2-5 years	All hot and cold domestic water is supplied by Main. Pipes are galvanized and over 60 years old with multiple pipe clamps.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	26,452	SF	4	2-5 years	All hot and cold domestic water is supplied by Main. Pipes are galvanized and over 60 years old with multiple pipe clamps.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	26,452	SF	4	2-5 years	All hot and cold domestic water is supplied by Main. Pipes are galvanized and over 60 years old with multiple pipe clamps.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	26,452	SF	4	2-5 years	All hot and cold domestic water is

Campus Name: Davis N Page : 30 of 59 Assessment Date: 11/06/2023



Catego	ry : Plumbing		Building : Addition 2						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	(from Risers to Fixtures)						supplied by Main. Pipes are galvanized and over 60 years old wit multiple pipe clamps.		
	Sanitary Piping	Entire Building	26,452	SF	5	6-10 years			
	Storm Piping	Entire Building	26,452	SF	5	6-10 years			
	Vent Piping	Entire Building	26,452	SF	5	6-10 years			
Catego	ry : Room		В	uilding	: Additi	on 2			
0	Name Tame	Lagathan	Overstites	LIOM	Danila	Recommend	0		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Administ	rative Suites/Offices								
	Ceiling - Exposed	070 - Basement Exterior Storage Space	85	SF	6	10+ years			
	Doors - Steel Doors incl hw	070 - Basement Exterior Storage Space	1	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	070 - Basement Exterior Storage Space	85	SF	5	10+ years			
	Lighting - Pendent/Surface	070 - Basement Exterior Storage Space	1	EA	7	6-10 years			
	Power Distribution	070 - Basement Exterior Storage Space	2	EA	7	10+ years			
	Walls - Plaster/Drywall	070 - Basement Exterior Storage Space	140	SF	6	6-10 years			
	AC Unit	Basement- Rm 030- Community outreach	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement- Rm 030- Community outreach	900	SF	6	10+ years			
	Doors - Transom Window	Basement- Rm 030- Community outreach	12	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Basement- Rm 030- Community outreach	1	EA	6	10+ years			
	Floor - Carpet	Basement- Rm 030- Community outreach	900	SF	7	6-10 years			
	Lighting - Pendent/Surface	Basement- Rm 030- Community outreach	12	EA	7	6-10 years			
	Power Distribution	Basement- Rm 030- Community outreach	14	EA	7	10+ years			
	Walls - Plaster/Drywall	Basement- Rm 030- Community outreach	1,480	SF	6	10+ years			
	Work Slnk	Basement- Rm 030- Community outreach	1	EA	7	10+ years			
	AC Unit	Basement- Rm 040- Counselors office	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement- Rm 040- Counselors	856	SF	6	6-10 years			

Campus Name: Davis N Page : 31 of 59 Assessment Date: 11/06/2023





Category : Room			В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	office Basement- Rm 040- Counselors office	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement- Rm 040- Counselors office	1	EA	6	10+ years	
	Floor - Wood	Basement- Rm 040- Counselors office	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement- Rm 040- Counselors office	12	EA	7	6-10 years	
	Power Distribution	Basement- Rm 040- Counselors office	14	EA	7	10+ years	
	Storage/ Closet	Basement- Rm 040- Counselors office	44	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement- Rm 040- Counselors office	1,380	SF	6	6-10 years	
	Work SInk	Basement- Rm 040- Counselors office	1	EA	7	10+ years	
	AC Unit	Basement- Rm 050- Community Resource Center	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement- Rm 050- Community Resource Center	812	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement- Rm 050- Community Resource Center	1	EA	6	10+ years	
	Floor - Tile	Basement- Rm 050- Community Resource Center	812	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement- Rm 050- Community Resource Center	12	EA	7	6-10 years	
	Power Distribution	Basement- Rm 050- Community Resource Center	10	EA	7	10+ years	
	Walls - Masonry	Basement- Rm 050- Community Resource Center	1,280	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement- Rm 050- Community Resource Center	420	SF	6	6-10 years	
	Work Sink	Basement- Rm 050- Community Resource Center	1	EA	7	10+ years	
_Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	12	SF	5	2-5 years	
	Janitor's Closet	2nd Floor	12	SF	5	2-5 years	
	Janitor's Closet	3rd Floor	15	SF	5	10+ years	
	Air Tunnel	Basement	205	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	767	SF	7	10+ years	
	Storage Room	Basement	304	SF	7	10+ years	



Category : Room			В	uilding	: Addition		
_						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
estroor	n						
	Accessories	1st Flr Women's Next to 106	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FIr Women's Next to 106	190	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st FIr Women's Next to 106	2	SF	5	1-2 years	Water damaged ceiling
	Doors - Wood Doors inclu hw	1st FIr Women's Next to 106	2	EA	6	10+ years	5 5
	Floor - Tile	1st FIr Women's Next to 106	187	SF	6	10+ years	
	Floor - Tile	1st FIr Women's Next to 106	5	SF	4	1-2 years	Damaged flooring
	Lavatory	1st FIr Women's Next to 106	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st FIr Women's Next to 106	4	EA	7	6-10 years	
	Lighting - Wall Mounted	1st FIr Women's Next to 106	1	EA	7	6-10 years	
	Partitions	1st FIr Women's Next to 106	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Flr Women's Next to 106	474	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Flr Women's Next to 106	4	SF	5	1-2 years	Damaged wall
	Water Closet	1st FIr Women's Next to 106	2	EA	6	10+ years	•
	Accessories	1st FIr- Boy's Next to 108	368	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FIr- Boy's Next to 108	368	SF	6	10+ years	
	Doors - Transom Window	1st Flr- Boy's Next to 108	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FIr- Boy's Next to 108	2	EA	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st FIr- Boy's Next to 108	348	SF	5	2-5 years	
	Floor - Concrete Epoxy/ Painted	1st FIr- Boy's Next to 108	20	SF	4	1-2 years	Worn finish
	Floor Drain	1st FIr- Boy's Next to 108	1	EA	7	10+ years	
	Hand Dryer	1st FIr- Boy's Next to 108	2	EA	7	6-10 years	
	Lavatory	1st FIr- Boy's Next to 108	4	EA	6	10+ years	
	Lighting - Pendent/Surface	1st FIr- Boy's Next to 108	6	EA	7	6-10 years	
	Partitions	1st FIr- Boy's Next to 108	3	EA	7	10+ years	
	Urinals	1st FIr- Boy's Next to 108	3	EA	6	10+ years	
	Walls - Plaster/Drywall	1st FIr- Boy's Next to 108	322	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st FIr- Boy's Next to 108	323	SF	5	2-5 years	
	Walls - Tile Ceramic/ Porcelain	1st FIr- Boy's Next to 108	200	SF	7	10+ years	
	Water Closet	1st FIr- Boy's Next to 108	3	EA	6	10+ years	
	Accessories	2nd FIr Next to 206	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd FIr Next to 206	192	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Flr Next to 206	2	EA	6	10+ years	
	Floor - Tile	2nd FIr Next to 206	192	SF	6	10+ years	
	Lavatory	2nd FIr Next to 206	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd FIr Next to 206	4	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd FIr Next to 206	1	EA	7	6-10 years	
	Partitions	2nd Flr Next to 206	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd FIr Next to 206	477	SF	6	10+ years	
	Water Closet	2nd Flr Next to 206	2	EA	6	10+ years	
	Accessories	2nd FIr- Boy's Next to 208	368	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd FIr- Boy's Next to 208	368	SF	6	10+ years	
	Doors - Transom Window	2nd FIr- Boy's Next to 208	18	SF	5	6-10 years	
	Doors - Wood Doors inclu hw	2nd Flr- Boy's Next to 208	2	ĒA	5	6-10 years	



Category : Room		Building : Addition 2						
_			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Concrete Epoxy/ Painted	2nd FIr- Boy's Next to 208	368	SF	7	10+ years		
	Floor Drain	2nd FIr- Boy's Next to 208	1	EA	7	10+ years		
	Hand Dryer	2nd FIr- Boy's Next to 208	2	EA	7	6-10 years		
	Lavatory	2nd FIr- Boy's Next to 208	2	EA	6	10+ years		
	Lighting - Pendent/Surface	2nd FIr- Boy's Next to 208	6	EA	7	6-10 years		
	Partitions	2nd FIr- Boy's Next to 208	1	EA	5	6-10 years		
	Partitions	2nd FIr- Boy's Next to 208	1	EA	4	1-2 years	Door over swung hinges	
	Urinals	2nd Flr- Boy's Next to 208	5	EA	6	10+ years		
	Walls - Plaster/Drywall	2nd FIr- Boy's Next to 208	322	SF	6	10+ years		
	Walls - Structural Glazed Tile	2nd FIr- Boy's Next to 208	323	SF	5	2-5 years		
	Water Closet	2nd FIr- Boy's Next to 208	2	EA	6	10+ years		
	Accessories	3rd Floor - Boy's Next to 308	368	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor - Boy's Next to 308	338	SF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor - Boy's Next to 308	30	SF	5	1-2 years	Damaged.	
	Doors - Transom Window	3rd Floor - Boy's Next to 308	18	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor - Boy's Next to 308	2	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	3rd Floor - Boy's Next to 308	368	SF	7	10+ years		
	Floor Drain	3rd Floor - Boy's Next to 308	1	EA	7	10+ years		
	Hand Dryer	3rd Floor - Boy's Next to 308	2	EA	7	6-10 years		
	Lavatory	3rd Floor - Boy's Next to 308	2	EA	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor - Boy's Next to 308	6	EA	7	6-10 years		
	Partitions	3rd Floor - Boy's Next to 308	2	EA	7	10+ years		
	Urinals	3rd Floor - Boy's Next to 308	5	EA	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor - Boy's Next to 308	382	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor - Boy's Next to 308	40	SF	5	1-2 years	Moisture damage	
	Walls - Structural Glazed Tile	3rd Floor - Boy's Next to 308	322	SF	5	10+ years		
	Walls - Structural Glazed Tile	3rd Floor - Boy's Next to 308	1	SF	4	1-2 years	Loose tile	
	Water Closet	3rd Floor - Boy's Next to 308	2	EA	6	10+ years		
	Accessories	3rd Flr Next to 306	192	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Flr Next to 306	190	SF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Flr Next to 306	2	SF	5	1-2 years	Water damaged ceiling	
	Doors - Wood Doors inclu hw	3rd Flr Next to 306	2	EA	6	10+ years		
	Floor - Tile	3rd Flr Next to 306	178	SF	6	10+ years		
	Floor - Tile	3rd Flr Next to 306	14	SF	4	1-2 years	Damaged tile	
	Lavatory	3rd Flr Next to 306	1	EA	6	10+ years		
	Lighting - Pendent/Surface	3rd Flr Next to 306	4	EA	7	6-10 years		
	Lighting - Wall Mounted	3rd Flr Next to 306	1	EA	7	6-10 years		
	Partitions	3rd Flr Next to 306	2	EA	7	10+ years		
	Walls - Plaster/Drywall	3rd Fir Next to 306	473	SF	6	10+ years	5	
	Walls - Plaster/Drywall	3rd Flr Next to 306	5	SF	5	1-2 years	Damaged.	
	Water Closet	3rd Flr Next to 306	2	EA	6	10+ years		
	Accessories	Basement- Boy's Next to 050	368	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement- Boy's Next to 050	368	SF	6	10+ years		
	Doors - Transom Window	Basement- Boy's Next to 050	18	SF	5	6-10 years		

Page : 34 of 59 Campus Name: Davis N Assessment Date: 11/06/2023



Category : Room			Building : Addition 2						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	Basement- Boy's Next to 050	1	EA	5	2-5 years			
	Doors - Wood Doors inclu hw	Basement- Boy's Next to 050	1	EA	4	0-1 year	Damaged door		
	Floor - Concrete Epoxy/ Painted	Basement- Boy's Next to 050	368	SF	5	6-10 years			
	Floor Drain	Basement- Boy's Next to 050	1	EA	7	10+ years			
	Hand Dryer	Basement- Boy's Next to 050	2	EA	7	6-10 years			
	Lavatory	Basement- Boy's Next to 050	2	EA	6	10+ years			
	Lighting - Pendent/Surface	Basement- Boy's Next to 050	6	EA	7	6-10 years			
	Partitions	Basement- Boy's Next to 050	2	EA	7	10+ years			
	Urinals	Basement- Boy's Next to 050	7	EA	6	10+ years			
	Walls - Plaster/Drywall	Basement- Boy's Next to 050	322	SF	6	10+ years			
	Walls - Structural Glazed Tile	Basement- Boy's Next to 050	323	SF	5	6-10 years			
	Water Closet	Basement- Boy's Next to 050	2	EA	6	10+ years			
Catego	ry : Classroom		В	uilding	: Additi	on 2			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Classroo	m #107 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	8	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,092	SF	6	10+ years			
	Chalk Board	1st Floor	8	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Wood	1st Floor	1,092	SF	5	2-5 years			
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Not working		
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Storage/ Closet	1st Floor	180	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	2,300	SF	6	10+ years			
Classroo	om #108 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	12	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	820	SF	5	10+ years			
	Chalk Board	1st Floor	6	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years			
	Floor - Wood	1st Floor	820	SF	5	2-5 years			
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years			
	Marker Board	1st Floor	8	LF	7	6-10 years			
	Storage/ Closet	1st Floor	45	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,392	SF	6	10+ years			



Category : Classroom			В	3014 W 33th 1 EAGE, Glildago, 12 00032			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	820	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	34	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,508	SF	6	10+ years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	17	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	820	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,342	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,092	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,092	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,300	SF	6	6-10 years	
Classroo	om #208 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	816	SF	6	10+ years	
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Chipped and damaged tile
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,405	SF	6	10+ years	
Classroc	om #209 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	10+ years	
	Chalk Board	2nd Floor	26	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,508	SF	6	6-10 years	
	valio i lactor/Drywan	2110 1 1001	1,000	O.	Ü	o ro youro	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	820	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,344	SF	6	10+ years	
Classroc	om #307 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,092	SF	6	10+ years	
	Chalk Board	3rd Floor	12	ĹF	4	2-5 years	
	Doors - Transom Window	3rd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	1,092	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,295	SF	6	•	
	Walls - Plaster/Drwwall		/ Jun	.>-	n	10+ years	

Campus Name: Davis N Page : 37 of 59 Assessment Date: 11/06/2023



Catego	ry : Classroom		В	uilding	: Addition		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	26	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	770	SF	5	10+ years	
	Floor - Wood	3rd Floor	50	SF	4	1-2 years	Areas of warped wood planking
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	Areas or warped wood planking
	Marker Board	3rd Floor	15	LF	7	6-10 years	
		3rd Floor	44	SF	7	•	
	Storage/ Closet			SF SF		10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,405	SF	6	10+ years	
Classroo	m #309 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	6	ĹF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,507	SF	6	10+ years	
Classroo	m #310 (Store Room)						
CIGSSI UU	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood Books including	3rd Floor	820	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,508	SF	6	10+ years	
	·	014 1 1001				•	
Catego	ry : Interior		В	uilding	: Addition		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor		2004.1311	Quantity	J J III	- Carric	. topiasomont	



Catego	Category : Interior			Building : Addition 2				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	1st Floor	473	SF	6	10+ years		
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	433	SF	7	10+ years		
	Floor - Tile/Sheet	1st Floor	40	SF	4	1-2 years	Cracked flooring	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	857	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	473	SF	6	10+ years		
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	473	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	6	EA	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	857	SF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	463	SF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damaged ceiling	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	473	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	857	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Basement	782	SF	6	10+ years		
	Doors - Wood Doors include hw	Basement	2	EA	6	10+ years		
	Floor - Asphalt Floor	Basement	782	SF	5	6-10 years		
	Lighting - Pendent/Surface	Basement	8	EA	7	6-10 years		
	Walls - Plaster/Drywall	Basement	1,158	SF	6	10+ years		
	Walls - Plaster/Drywall	Basement	12	SF	5	6-10 years		
Safety								
	Security Cameras	1st Floor	8	EA	7	6-10 years		
	Security Cameras	1st Floor	1	EA	7	6-10 years		
Stairs								
Otalis	Ceiling - Plaster/Drywall	West	1,083	SF	6	10+ years		
	Floor - Asphalt	West	616	SF	6	10+ years		
	Handrails	West	192	LF	7	10+ years		
	Lighting - Pendent/Surface	West	7	EΑ	7	6-10 years		
	Stairs - Asphalt	West	780	LF	5	10+ years		
	Walls - Plaster/Drywall	West	2,060	SF	6	10+ years		



Category : Exterior Building : Annex

tem - Type	Location	Quantity	UOM	Danie	Recommend	
теті - туре	Location	Quantity				Cammanta
			UCIVI	Rank	Replacement	Comments
Entrance Control - Audio and Video	Door A1 - South	1	EA	6	6-10 years	
Exterior Doors - Side lite	Door A1 - South	2	EA	6	6-10 years	
Exterior Doors - Store Front	Door A1 - South	2	EA	6	6-10 years	
Exterior Doors - Transom Lite	Door A1 - South	3	EA	6	6-10 years	
Exterior Doors - Exterior Steel Door	Door A10 - Southeast	1	EA	6	6-10 years	
Exterior Doors - Side lite	Door A2 - Southwest	2	EA	7	6-10 years	
Exterior Doors - Store Front	Door A2 - Southwest	1	EA	7	6-10 years	
Exterior Doors - Transom Lite	Door A2 - Southwest	2	EA	7		
Exterior Doors - Side lite	Door A3 - Southwest	2	EA	7		
Exterior Doors - Store Front	Door A3 - Southwest	1		7		
		2				
				7		
				-		
		•				
		•				
					•	
		•			,	
		3				
		1		_		
		•				
				_		
		•				
Power Door Operator and Controls	Door A9 - East center	1	EA	7	6-10 years	
1						
	Entire Buildina	594	LF	7	10+ vears	No exposed foundation
Superstructure - Steel		34,018	SF	7	10+ years	No exposed superstructure
•	-				•	
Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	6-10 years	
m						
	Main Roof	1	EA	7	6-10 years	
. •						
	Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Store Front Exterior Doors - Transom Lite Exterior Doors - Store Front Exterior Doors - Transom Lite Exterior Doors - Store Front Fower Door Operator and Controls Exterior Lighting - Wall Mounted	Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Store Front Exterior Doors - Side lite Exterior Doors - Store Front Exterior Doors - Transom Lite Exterior Doors - Transom Lite Exterior Doors - Store Front Exterior Doors - Store Front Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Side lite Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Side lite Exterior Doors - Exterior Steel Entire Building Exterior Lighting - Wall Mounted Entire Building Exterior Lighting - Wall Mounted Exterior Lighting - Store Exterior Doors - Store Exterior Lighting - Store	Exterior Doors - Exterior Steel Door	Exterior Doors - Exterior Steel Door Door A10 - Southeast 1 EA Exterior Doors - Side lite Door A2 - Southwest 2 EA Exterior Doors - Store Front Door A2 - Southwest 1 EA Exterior Doors - Store Front Door A2 - Southwest 2 EA Exterior Doors - Transom Lite Door A3 - Southwest 2 EA Exterior Doors - Stide lite Door A3 - Southwest 1 EA Exterior Doors - Store Front Door A3 - Southwest 1 EA Exterior Doors - Store Front Door A3 - Southwest 2 EA Exterior Doors - Store Front Door A3 - Southwest 2 EA Exterior Doors - Stide lite Door A4 - West center 2 EA Exterior Doors - Stide lite Door A4 - West center 1 EA Exterior Doors - Store Front Door A4 - West center 2 EA Exterior Doors - Store Front Door A4 - West center 2 EA Exterior Doors - Store Front Door A5 - Northwest 2 EA Exterior Doors - Store Front Door A5 - Northwest 1 EA Exterior Doors - Store Front Door A5 - Northwest 1 EA Exterior Doors - Store Front Door A6 - Northwest 2 EA Exterior Doors - Store Front Door A6 - Northwest 2 EA Exterior Doors - Store Front Door A6 - Northwest 2 EA Exterior Doors - Store Front Door A6 - Northwest 1 EA Exterior Doors - Store Front Door A6 - Northwest 1 EA Exterior Doors - Store Front Door A6 - Northwest 1 EA Exterior Doors - Store Front Door A6 - Northwest 1 EA Exterior Doors - Store Front Door A7 - North 1 EA Exterior Doors - Store Front Door A7 - North 1 EA Exterior Doors - Store Front Door A7 - North 1 EA Exterior Doors - Store Front Door A8 - Northeast 1 EA Exterior Doors - Store Front Door A9 - East center 1 EA Exterior Doors - Store Front Door A9 - East center 1 EA Exterior Doors - Store Front Door A9 - East center 1 EA Exterior Doors - Store Front Door A9 - East center 1 EA Exterior Doors - Store Front Door A9 - East center 1 EA Exterior Doors - Store Front Door A9 - East center 1 EA Exterior Doors - Store Front Door A9 - East center 1 EA Exterior Doors - Store Front Door A9 - East center 1 EA Exterior Lighting - Wall Mounte	Exterior Doors - Exterior Steel Door Door A10 - Southeast Door A2 - Southwest Exterior Doors - Side lite Door A2 - Southwest Door A2 - Southwest Exterior Doors - Store Front Door A2 - Southwest Exterior Doors - Transom Lite Door A2 - Southwest Door A3 - Southwest Exterior Doors - Side lite Door A3 - Southwest Exterior Doors - Side lite Door A3 - Southwest Exterior Doors - Side lite Door A3 - Southwest Exterior Doors - Transom Lite Door A3 - Southwest Exterior Doors - Side lite Door A3 - Southwest Exterior Doors - Side lite Door A4 - West center Exterior Doors - Side lite Door A4 - West center Exterior Doors - Side lite Door A4 - West center Exterior Doors - Side lite Door A4 - West center Exterior Doors - Side lite Door A5 - Northwest Exterior Doors - Side lite Door A5 - Northwest Exterior Doors - Side lite Door A5 - Northwest Exterior Doors - Side lite Door A5 - Northwest Exterior Doors - Side lite Door A6 - Northwest Exterior Doors - Side lite Door A6 - Northwest Exterior Doors - Side lite Door A6 - Northwest Exterior Doors - Side lite Door A6 - Northwest Exterior Doors - Side lite Door A6 - Northwest Exterior Doors - Side lite Door A6 - Northwest Exterior Doors - Side lite Door A7 - North Exterior Doors - Side lite Door A7 - North Exterior Doors - Exterior Steel Door Door A7 - North Door A8 - Northeast Exterior Doors - Exterior Steel Door Door A9 - East center Exterior Doors - Exterior Steel Door Door A9 - East center Exterior Doors - Side lite Door A9 - East center Exterior Doors - Side lite Door A9 - East center Exterior Doors - Side lite Door A9 - East center Exterior Doors - Side lite Door A9 - East center Exterior Doors - Side lite Door A9 - East center Exterior Doors - Side lite Door A9 - East center Exterior Doors - Side lite Door A9 - East center Exterior Doors - Side lite Door A9 - East center Exterior Doors - Side lite Door A9 - East center Exterior Doors - Side lite Exterior Doors - Side lite Door A9 - East center Ext	Exercisor Doors - Exterior Steel Door Door A10 - Southeast 1

Campus Name: Davis N Page : 40 of 59 Assessment Date: 11/06/2023



Catego	ry : Exterior		В	uilding	: Annex	,	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	Main Roof	582	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	12	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	17,090	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EΑ	7	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	17,090	SF	7	10+ years	
Walls							
	Canopy - Metal	Entire Building	50	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	15,882	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	5	2-5 years	Sealant issues
	Exterior Walls - Stone-Cast	Entire Building	550	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	1,188	SF	6	10+ years	
Windows	3						
	Curtain wall - Louver	Entire Building	256	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	2,432	SF	6	6-10 years	
	Lintels - Steel	Entire Building	625	LF	7	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	4,800	SF	6	6-10 years	

Category : Electrical **Building: Annex**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Emerge</u>	ncy System						
_	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
	Security System - CCTV	Entire Building	34,078	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	34,018	SF	5	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	9	EA	2	0-1 year	Not equipped with backup batteries and the building has no emergency generator. Quantity changed to match current observations.
	Exit Signs - Lunchroom	Entire Building	2	EA	2	0-1 year	Not equipped with backup batteries and the building has no emergency generator.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,041	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,135	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	752	SF	6	10+ years	
_Main Se	rvice						

Campus Name: Davis N Page : 41 of 59 Assessment Date: 11/06/2023



Catego	ry : Electrical		В	uilding	: Annex	(
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Electrical Room, Pump Room	1	EA	7	10+ years	Serves Annex EM circuits.
	Independent Electrical Service for emergency power	Electrical Room, Pump Room	1	EA	6	10+ years	Serves Annex fire pumps and sprinkler system.
	PA System	Entire Building	34,018	SF	5	6-10 years	Served by Main.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	EM fuse panel. Rank, Reason and Priority Rep changed as panel is missing an interior cover plate and has open fuse receptacles exposing live conductors and presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Located in the office of the lunchroom kitchen.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	Quantity changed based on current observations and as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	Some surface oxidation observed on the exterior and interior of the panels.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	Rank and Priority Rep adjusted based on current observations of surface oxidation on the panel.

Category: Fire Protection Building: Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Ala	,	Location	Quantity	OCIVI	Italik	Replacement	Comments
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Placed into service in October 2023.
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Annunciator.
	Fire Alarm Strobe Lights	Entire Building	34,018	SF	6	10+ years	
	Fire Alarm_System	Entire Building	34,018	SF	6	10+ years	Placed into service in October 2023.
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	
_Pump R	oom Assembly						
•	Fire Pump - 25-50 hp	Pump Room	1	EA	6	10+ years	Minor drip at pump seal.
	Jockey Pump	Pump Room	1	EA	6	10+ years	
Sprinkle	r Svstem						

Campus Name: Davis N Page : 42 of 59 Assessment Date: 11/06/2023



	ry : Fire Protection		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sprinkler Heads	Entire Building	34,018	SF	7	10+ years	
	Sprinkler Piping	Entire Building	34,018	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	34,018	SF	6	10+ years	
Catego	ry : Mechanical		В	uildina	: Annex		
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	litioning						
	Chemical Pot Feeder	Entire Building	1	EA	5	6-10 years	
	Chiller-Air Cooled-Scroll Type-Roof Mounted	Entire Building	1	EA	5	2-5 years	CH-1. Serves Annex. One air
	- 101 - 150 tons	-				-	conditioning circuit is down. Unit is
							original to the building and has reached the end of its EUL.
	Glycol Feed	Entire Building	1	EA	5	6-10 years	reactica the cha of its Loc.
	Pipes - Chilled Water Pipe- Copper	Entire Building	100	LF	6	10+ years	
	Pipes - Chilled Water Pipe- Galvanized	Entire Building	100	LF	6	10+ years	
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	7	6-10 years	Component of a ductless split system
	than 5 tons		·	_, ,	·	o to youro	serving the Annex MDF Room. Rank changed as unit has been replaced since last assessment. No CPS Asset Tag present on condensing un or fan coil unit.
Air Hanc	lling Systems						
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	13	EA	5	6-10 years	Associated with AHU-3.
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	9	EA	5	6-10 years	Associated with AHU-1.
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	4	EA	5	6-10 years	Associated with AHU-2.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-3, 16000 cfm, serves 2nd floor
		Mechanical Room	1	EA	6	10+ years	
	Air Intake				_	0.40	ALILLA AEOOO -f A-4 fl
	Air Intake Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	AHU-1, 15000 cfm, serves 1st floor
	Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils -	Mechanical Room - AHU-1 Mechanical Room - AHU-1	1	EA EA	5 6	6-10 years 10+ years	AHU-1, 15000 cfm, serves 1st floor
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm		·			•	AHU-2, 10000 cfm, serves 1st floor AHU-2, 10000 cfm, serves clinic, lunchroom, kitchen, and associated spaces on 1st floor.



Category : Mechanical		В	uilding	: Annex	(
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler S							
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Mechanical Room	2	EA	5	6-10 years	
	Chemical Pot Feeder	Mechanical Room	1	EA	5	6-10 years	
	Combustion Dampers	Mechanical Room	2	EA	6	10+ years	
	Hot Water Pump	Mechanical Room	2	EA	6	6-10 years	No CPS Asset Tags present.
	Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - 1001 - 2000 MBH	Mechanical Room	2	EA	5	6-10 years	BLR-1 and BLR-2
	Water Fill System	Mechanical Room	1	EA	5	10+ years	
_Heating	Devices						
	Fin Tube - Electric	1st Floor	3	LF	6	10+ years	Located at the east egress door in the clinic.
	Cabinet Heaters - With Hot Water Coil	1st Floor	2	EA	6	10+ years	Located in north and south egress vestibules.
	Unit Heater - Hot Water	Entire Building	1	EA	6	10+ years	
	Unit Heater - Hot Water	Entire Building	1	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Located in the kitchen area.
	Fin Tube - Hot Water	Entire Building	24	LF	6	10+ years	In student restrooms and Pump Room. Some enclosures are damaged and/or rusted.
Mechan	ical Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	500	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	100	LF	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	Associated with AHU-1.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	Associated with AHU-3.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	HWP-1. No CPS Asset Tag present.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	Associated with AHU-2.
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	HWP-2.
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	5	6-10 years	CHWP-2
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	5	6-10 years	CHWP-1
Tempera	ature Control						
	DDC System	Entire Building	34,018	SF	4	2-5 years	Unable to access the system due to outdated computer.
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	Quantity changed to match current observations.
	Thermostats - DDC	Entire Building	26	EA	6	10+ years	
Ventilati	on						

Campus Name: Davis N Page : 44 of 59 Assessment Date: 11/06/2023



							3014 W 33111 EAGE, Officago, IE 00032
Categor	y : Mechanical		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	5	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	
Categor	y : Plumbing		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Water	r						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	34,018	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	34,018	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	34,018	SF	6	10+ years	
	Fixtures	Ğ				•	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	34,018	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	34,018	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	34,018	SF	6	10+ years	
	Sanitary Piping	Entire Building	34,018	SF	6	10+ years	
	Storm Piping	Entire Building	34,018	SF	6	10+ years	
	Vent Piping	Entire Building	34,018	SF	6	10+ years	
oumps							
•	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	10+ years	Located at the bottom of the elevator pit. Inaccessible at the time of assessment. No CPS Asset Tag available. Condition verified by the Building Engineer.
Categor	y : Room		В	uilding	: Annex		
	_				_	Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administra	ative Suites/Offices						
	Ceiling - Lay-in	1st Flr- Asst Principal	102	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr- Asst Principal	1	EA	6	10+ years	
	Floor - Carpet	1st Flr- Asst Principal	102	SF	6	6-10 years	
	Lighting - Lay-in	1st Flr- Asst Principal	2	EA	7	6-10 years	
		1st Flr- Asst Principal	102	SF	6	•	

Campus Name: Davis N Page : 45 of 59 Assessment Date: 11/06/2023



Catego	ry : Room		В	uilding	: Annex		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	1st FIr- Asst Principal	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Flr- Asst Principal	269	SF	6	10+ years	
	Ceiling - Lay-in	1st Flr- Kitchen Office/Dry Storage	144	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Flr- Kitchen Office/Dry Storage	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Flr- Kitchen Office/Dry Storage	144	SF	5	6-10 years	
	Lighting - Lay-in	1st Flr- Kitchen Office/Dry Storage	4	EA	7	6-10 years	
	Power Distribution	1st Flr- Kitchen Office/Dry Storage	4	EA	7	10+ years	
	Walls - Concrete Block	1st Flr- Kitchen Office/Dry Storage	280	SF	6	10+ years	
	Ceiling - Lay-in	1st Flr- Work Room- In Main Office	376	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr- Work Room- In Main Office	2	EA	6	10+ years	
	Floor - Carpet	1st Flr- Work Room- In Main Office	310	SF	6	6-10 years	
	Floor - Tile	1st Flr- Work Room- In Main Office	66	SF	6	6-10 years	
	Lighting - Lay-in	1st FIr- Work Room- In Main Office	5	EA	7	6-10 years	
	Power Distribution	1st Flr- Work Room- In Main Office	14	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Flr- Work Room- In Main Office	698	SF	6	10+ years	
	Work SInk	1st Flr- Work Room- In Main Office	1	EA	7	10+ years	
	Ceiling - Lay-in	1st Flr-Principal	179	SF	6	6-10 years	
	Ceiling - Lay-in	1st Flr-Principal	4	SF	4	1-2 years	Water stain tile
	Doors - Wood Doors inclu hw	1st Flr-Principal	1	EA	6	10+ years	
	Floor - Carpet	1st Flr-Principal	183	SF	6	6-10 years	
	Lighting - Lay-in	1st Flr-Principal	3	EA	7	6-10 years	
	Power Distribution	1st Flr-Principal	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Flr-Principal	375	SF	6	10+ years	
	Ceiling - Lay-in	1st floor main office	537	SF	6	10+ years	
	Doors - Side-lite	1st floor main office	62	SF	6	10+ years	
	Doors - Transom Window	1st floor main office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor main office	1	EA	6	10+ years	
	Floor - Carpet	1st floor main office	388	SF	6	6-10 years	
	Floor - Tile	1st floor main office	149	SF	6	10+ years	
	Lighting - Lay-in	1st floor main office	10	EA	7	6-10 years	
	Power Distribution	1st floor main office	22	EA	7	10+ years	
	Storage/ Closet	1st floor main office	160	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor main office	1,000	SF	6	10+ years	
Clinic							
	Ceiling - Lay-in	1st Floor	1,700	SF	6	10+ years	
	Doors - Side-lite	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	12	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	1,700	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	29	EA	7	6-10 years	
	Storage/ Closet	1st Floor	26	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,690	SF	6	10+ years	



Catego	Category : Room		В	uilding	: Annex	(
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Kitchen	-		•			•	
	Ceiling - Lay-in	1st Floor	1,328	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,328	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	ΕA	7	6-10 years	
	Serving Line	1st Floor	20	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	2,364	SF	6	10+ years	
Library							
y	Casework	2nd Floor	63	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2,060	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	72	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Carpet	2nd Floor	2,060	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	31	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	2,087	SF	6	10+ years	
Lookor/S	Shower Room						
Locker/s		Ant the entire title little and		0.5	7	0.40	
	Accessories	1st floor inside kitchen	55	SF	7	6-10 years	
	Ceiling - Exposed	1st floor inside kitchen	55	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st floor inside kitchen	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st floor inside kitchen	55	SF	7	10+ years	
	Lavatory	1st floor inside kitchen	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st floor inside kitchen	1	EΑ	7	6-10 years	
	Student Lockers - Two Tier	1st floor inside kitchen	10	EA	6	10+ years	
	Walls - Concrete Block	1st floor inside kitchen	108	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Flr- Rm 123	1,135	SF	6	10+ years	
	Doors - Side-lite	1st Flr- Rm 123	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr- Rm 123	2	EA	6	10+ years	
	Floor - Tile	1st Flr- Rm 123	1,135	SF	6	10+ years	
	Lighting - Lay-in	1st Flr- Rm 123	16	EA	7	6-10 years	
	Walls - Concrete Block	1st Flr- Rm 123	1,377	SF	6	10+ years	
_MDF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	5	0-1 year	Missing handle
	Finishes	2nd Floor	47	SF	7	10+ years	3
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Ductless split system.



Category : Room		В	uilding	: Annex			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
/lechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	491	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	185	SF	5	10+ years	
	Storage Room	1st Floor	247	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	1,188	SF	7	10+ years	
	Storage Room	2nd Floor	50	SF	7	10+ years	
	5.5.1.g					, , , , , , , , , , , , , , , , , , , ,	
Restroo	m						
0011001	Accessories	1st FIr- Mens - Next to 126	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fir- Mens - Next to 126	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fir- Mens - Next to 126	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Fir- Mens - Next to 126	45	SF	6	10+ years	
	Floor Drain	1st Fir- Mens - Next to 126	1	EA	7	10+ years	
	Lavatory	1st Fir- Mens - Next to 126	1	EA	6	10+ years	
	Lighting - Lay-in	1st Fir- Mens - Next to 126	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Fir- Mens - Next to 126	118	SF	6	10+ years	
	Water Closet	1st Fir- Mens - Next to 126	1	EA	6	10+ years	
	Accessories	1st Fir- Mens - Next to 126	45	SF	7	6-10 years	
	Ceiling - Lay-in	1st Fir- Unisex -In Clinic	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fir- Unisex -In Clinic	1	EA	6	•	
	Floor - Tile	1st Fir- Unisex -In Clinic	45	SF	6	10+ years	
	Floor Drain	1st Fir- Unisex -In Clinic	45	EA	7	10+ years	
	Hand Dryer	1st Fir- Unisex -In Clinic	1	EA	7	10+ years	
			1			6-10 years	
	Lavatory	1st FIr- Unisex -In Clinic	•	EΑ	6	10+ years	
	Lighting - Lay-in	1st FIr- Unisex -In Clinic	1	EA SF	7	6-10 years	
	Walls - Plaster/Drywall	1st FIr- Unisex -In Clinic	108	SF SF	6	10+ years	Materialement
	Walls - Plaster/Drywall	1st FIr- Unisex -In Clinic	10		5	1-2 years	Water damage
	Water Closet	1st FIr- Unisex -In Clinic	1	EA	6	10+ years	
	Accessories	1st Fire Unisex -In Main Office	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FIr- Unisex -In Main Office	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FIr- Unisex -In Main Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FIr- Unisex -In Main Office	45	SF	6	10+ years	
	Floor Drain	1st FIr- Unisex -In Main Office	1	EA	7	10+ years	
	Lavatory	1st FIr- Unisex -In Main Office	1	EΑ	6	10+ years	
	Lighting - Lay-in	1st FIr- Unisex -In Main Office	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st FIr- Unisex -In Main Office	118	SF	6	10+ years	
	Water Closet	1st Flr- Unisex -In Main Office	1	EA	6	10+ years	
	Accessories	1st Fir- Womens - Next to 126	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fir- Womens - Next to 126	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr- Womens - Next to 126	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr- Womens - Next to 126	45	SF	6	10+ years	
	Floor Drain	1st FIr- Womens - Next to 126	1	EA	7	10+ years	
	Lavatory	1st FIr- Womens - Next to 126	1	EΑ	6	10+ years	



Catego	ry : Room		Building : Annex						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	1st FIr- Womens - Next to 126	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st FIr- Womens - Next to 126	118	SF	6	10+ years			
	Water Closet	1st FIr- Womens - Next to 126	1	EA	6	10+ years			
	Accessories	1st floor boys -Next to 126	188	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st floor boys -Next to 126	188	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st floor boys -Next to 126	188	SF	6	10+ years			
	Floor Drain	1st floor boys -Next to 126	1	EA	7	10+ years			
	Lavatory	1st floor boys -Next to 126	2	EA	6	10+ years			
	Lighting - Lay-in	1st floor boys -Next to 126	3	EA	7	6-10 years			
	Partitions	1st floor boys -Next to 126	1	EA	7	10+ years			
	Urinals	1st floor boys -Next to 126	3	EA	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st floor boys -Next to 126	427	SF	6	10+ years			
	Water Closet	1st floor boys -Next to 126	1	EA	6	10+ years			
	Accessories	1st floor girls- Next to 127	188	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st floor girls- Next to 127	188	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st floor girls- Next to 127	188	SF	6	10+ years			
	Floor Drain	1st floor girls- Next to 127	1	EA	7	10+ years			
	Lavatory	1st floor girls- Next to 127	2	EΑ	6	10+ years			
	Lighting - Lay-in	1st floor girls- Next to 127	2	EΑ	7	6-10 years			
	Partitions	1st floor girls- Next to 127	4	EA	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st floor girls- Next to 127	427	SF	6	10+ years			
	Water Closet	1st floor girls- Next to 127	4	EΑ	6	10+ years			
	Accessories	2nd floor boys -Next to 228	188	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd floor boys -Next to 228	188	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd floor boys -Next to 228	188	SF	6	10+ years			
	Floor Drain	2nd floor boys -Next to 228	1	EΑ	7	10+ years			
	Lavatory	2nd floor boys -Next to 228	2	EA	6	10+ years			
	Lighting - Lay-in	2nd floor boys -Next to 228	3	EA	7	6-10 years			
	Partitions	2nd floor boys -Next to 228	1	EA	7	10+ years			
	Urinals	2nd floor boys -Next to 228	3	EΑ	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	2nd floor boys -Next to 228	427	SF	6	10+ years			
	Water Closet	2nd floor boys -Next to 228	1	EA	6	10+ years			
	Accessories	2nd floor girls- Next to 229	188	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd floor girls- Next to 229	188	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd floor girls- Next to 229	188	SF	6	10+ years			
	Floor Drain	2nd floor girls- Next to 229	1	EA	7	10+ years			
	Lavatory	2nd floor girls- Next to 229	2	EA	6	10+ years			
	Lighting - Lay-in	2nd floor girls- Next to 229	2	EΑ	7	6-10 years			
	Partitions	2nd floor girls- Next to 229	4	EA	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	2nd floor girls- Next to 229	427	SF	6	10+ years			
	Water Closet	2nd floor girls- Next to 229	4	EA	6	10+ years			
	Accessories	In Rm 124	45	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	In Rm 124	45	SF	6	10+ years			
	Doors - Wood Doors inclu hw	In Rm 124	1	EA	6	10+ years			
					-	,			

Campus Name: Davis N Page : 49 of 59 Assessment Date: 11/06/2023



Catego	ry : Room		Building : Annex						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile Ceramic/ Porcelain	In Rm 124	45	SF	6	10+ years			
	Floor Drain	In Rm 124	1	EΑ	7	10+ years			
	Lavatory	In Rm 124	1	EA	6	10+ years			
	Lighting - Lay-in	In Rm 124	1	EΑ	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	In Rm 124	104	SF	6	10+ years			
	Water Closet	In Rm 124	1	EA	6	10+ years			
	Accessories	Shared by Rm126/125	45	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Shared by Rm126/125	45	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	Shared by Rm126/125	2	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Shared by Rm126/125	45	SF	6	6-10 years			
	Floor Drain	Shared by Rm126/125	1	EA	7	10+ years			
	Lavatory	Shared by Rm126/125	1	EA	6	6-10 years			
	Lighting - Lay-in	Shared by Rm126/125	1	EA	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	Shared by Rm126/125	104	SF	6	10+ years			
	Water Closet	Shared by Rm126/125	1	EA	7	10+ years			
	Accessories	Shared by Rm128/127	45	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Shared by Rm128/127	45	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Shared by Rm128/127	2	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Shared by Rm128/127	45	SF	6	10+ years			
	Floor Drain	Shared by Rm128/127	1	EA	7	10+ years			
	Lavatory	Shared by Rm128/127	1	EA	6	10+ years			
	Lighting - Lay-in	Shared by Rm128/127	1	EA	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	Shared by Rm128/127	94	SF	6	10+ years			
	Water Closet	Shared by Rm128/127	1	EΑ	6	10+ years			

Category: Classroom **Building: Annex**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #124 (Pre School)						
	Casework	1st Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,200	SF	6	10+ years	
	Doors - Side-lite	1st Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	6	10+ years	
	Floor - Tile	1st Floor	1,200	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	15	EΑ	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	695	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	695	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #125 (Pre School)						
	Casework	1st Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,200	SF	6	6-10 years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	

Campus Name: Davis N Page : 50 of 59 Assessment Date: 11/06/2023



Calego	ry : Classroom		В	uilding	: Annex		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Doors - Side-lite	1st Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,200	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	15	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	695	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	695	SF	6	6-10 years	
	Work Sink	1st Floor	2	EΑ	7	10+ years	
Classroc	om #126 (Pre School)						
CHOOLOG	Casework	1st Floor	63	LF	6	10+ years	
	Casework Ceiling - Lay-in	1st Floor	1,200	SF	6	10+ years	
	Chalk Board	1st Floor	1,200	LF	4	•	
	Doors - Side-lite	1st Floor	13	SF		2-5 years	
					6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,200	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	695	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	695	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #127 (Pre School)						
	Casework	1st Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	784	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	769	SF	6	10+ years	
	Floor - Tile	1st Floor	15	SF	4	1-2 vears	Cracked/chipped/missing tile
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	γγ 3
	Walls - Concrete Block	1st Floor	712	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	280	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #128 (Pre School)						
	Casework	1st Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	784	SF	6	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	13	EA	6	10+ years	
	Floor - Tile	1st Floor	784	SF	6		
		1st Floor		EA		10+ years	
	Lighting - Lay-in Walls - Concrete Block	1st Floor 1st Floor	12 520	SF	7 6	6-10 years 10+ years	
	WEARS - L ODCIDIO HIOCK	TST FIGUR	520	- 5F	h	IU+ Vears	



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	280	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #220 (Regular Classroom)						
	Casework	2nd Floor	48	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	856	SF	6	10+ years	
	Chalk Board	2nd Floor	26	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	856	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	703	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	295	SF	6	10+ years	
Classroc	nm #221 (Office)						
	Casework	2nd Floor	68	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	936	SF	6	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	916	SF	6	10+ years	
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Cracked tile
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	524	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	480	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroc	m #223 (Special Education)						
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	532	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	532	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	249	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	560	SF	6	10+ years	
Classroc	om #224 (Store Room)						
	Casework	2nd Floor	72	LF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Annex		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	1,040	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,040	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	544	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	520	SF	6	10+ years	
Classroc	om #226 (Multi Purpose Room)						
	Casework	2nd Floor	48	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	856	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	6	10+ years	
	Floor - Tile			SF	6		
		2nd Floor	856		_	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	408	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	580	SF	6	10+ years	
Classroc	om #227 (Kindergarten)						
	Casework	2nd Floor	72	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,200	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,180	SF	6	10+ years	
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Cracked tile
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	600	SF	6	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	10+ years	
_Classroc	om #228 (Regular Classroom)						
	Casework	2nd Floor	72	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,170	SF	6	10+ years	
	Chalk Board	2nd Floor	1,170	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	13	SF	6	-	
			13	EA	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor				10+ years	
	Floor - Tile	2nd Floor	1,170	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	600	SF	6	10+ years	

Campus Name: Davis N Page : 53 of 59 Assessment Date: 11/06/2023



atego	ry : Classroom		В	uilding	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	600	SF	6	10+ years	
assroc	om #229 (Regular Classroom)						
	Casework	2nd Floor	48	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	856	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	856	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	408	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	580	SF	6	10+ years	
assroc	om #230 (Regular Classroom)						
	Casework	2nd Floor	48	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	856	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	19	EA	6	10+ years	
	Floor - Tile	2nd Floor	856	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	408	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	580	SF	6	10+ years	
assroc	om #231 (Special Program)						
	Ceiling - Lay-in	2nd Floor	322	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Water damage tile
	Chalk Board	2nd Floor	8	LF	4	2-5 years	Trator damage the
	Doors - Side-lite	2nd Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	330	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	750	SF	6	10+ years	
atego	ry : Interior		В	uilding	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor			•				
midul	Ceiling - Lay-in	1st Floor	3,200	SF	6	10+ years	
	Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor		SF SF			
	Doors - Store Front	1st Floor 1st Floor	196 8	SF EA	6 6	10+ years	
	Doors - Store Linist	121 LIOOI	8	ĽA	О	10+ years	



Catego	ry : Interior		В	uilding	: Annex		-
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	74	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	196	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	3,200	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	38	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	2,880	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2,553	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	4	1-2 years	Damaged tile. Water stain
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,577	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	42	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	4,760	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	300	SF	6	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	5	EA	7	6-10 years	
Stairs							
	Floor - Tile	Stairwell #1 (near Main Office)	22	SF	6	10+ years	
	Handrails	Stairwell #1 (near Main Office)	50	LF	7	10+ years	
	Stairs - Rubber	Stairwell #1 (near Main Office)	24	LF	6	10+ years	
	Floor - Tile	Stairwell #2 (near Library)	44	SF	6	10+ years	
	Handrails	Stairwell #2 (near Library)	100	LF	7	10+ years	
	Stairs - Rubber	Stairwell #2 (near Library)	48	LF	6	10+ years	
_Vertical (Conveyance						
	Elevator - Hydraulic Elevator	Near room 126	1	EA	6	10+ years	

Campus Name: Davis N Page : 55 of 59 Assessment Date: 11/06/2023



Category : Site		В	uilding				
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	6	6-10 years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	6-10 years	
Fencing							
•	Fencing - Chain Link	Entire Site	180	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	80	LF	4	1-2 years	Damaged sections
	Fencing - Iron and Concrete Post	Entire Site	1,618	LF	6	6-10 years	•
	Fencing - Iron and Concrete Post	Entire Site	20	LF	4	1-2 years	Damaged sections
	Fencing - New Standard Ornamental	Entire Site	341	LF	7	6-10 years	· ·
_andsca	oe .						
	Benches	Entire Site	10	EA	7	10+ years	
	Irrigation	Entire Site	120	SF	7	10+ years	
	Landscape - Grass	Entire Site	25,718	SF	7	10+ years	
	Landscape - Grass	Entire Site	4,000	SF	4	1-2 years	Worn grass, exposed dirt
	Landscape - Hardscape- Asphalt	Entire Site	1,500	SF	7	10+ years	granes, express and
	Landscape - Hardscape- Asphalt	Entire Site	1,500	SF	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	978	SF	7	10+ years	
	Parkway trees	Entire Site	29	EA	6	10+ years	New trees added on north
	Parkway trees	Entire Site	6	EA	4	1-2 years	Missing
	Planting Beds/ Area	Entire Site	6,609	SF	6	10+ years	Missing
	Play Area - Synthetic Turf	Entire Site	5,962	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	452	SF	6	10+ years	Recombined quantities
					_		Recombined quantities
	Trash Receptacles	Entire Site	8	EA	7	10+ years	
arking I							
	Concrete Curbs	Entire Site	360	LF	7	10+ years	
	Interior Plantings	Entire Site	60	LF	7	10+ years	
	Lighting - Pole Mounted	Entire Site	1	EA	6	10+ years	2nd pole is not in use
	Surface - Asphalt	Entire Site	25,800	SF	5	6-10 years	Raveling and alligator cracking throughout. Recalculated quantity
	Surface - Asphalt	Entire Site	400	SF	4	1-2 years	Potholes, cracks, recalculated quantity
	Surface - Concrete	Entire Site	2,000	SF	7	10+ years	Recalculated quantity
	Trash Compactor	Entire Site	´ 1	EA	6	6-10 years	• •
	Trash Enclosure - Masonry	Entire Site	368	SF	5	10+ years	
	Vehicular Screening	Entire Site	105	LF	7	10+ years	
Plavarou	nd						
	Equipment - Combo 3-12	South	2	EA	7	10+ years	

Campus Name: Davis N Page : 56 of 59 Assessment Date: 11/06/2023



							OOT+ VV COUTT LATOL, OHIOUGO, IL COCOL
Catego	ry : Site		В	uilding	Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Poured Surface	South	3,180	SF	7	10+ years	
	Surface - Poured Surface	South	20	SF	4	0-1 year	Hole.
	Equipment - Pre K 3-5	West	2	EA	7	10+ years	
	Surface - Poured Surface	West	1,300	SF	7	10+ years	
_Sidewall	, e						
Oldewall	Sidewalks - Internal Walks	Entire Site	742	LF	7	10+ years	Recombined quantities
	Sidewalks - Perimeter Sidewalks	Entire Site	23,669	SF	7	10+ years	•
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	4	1-2 years	Cracked areas
_Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	6	6-10 years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Davis N Page: 57 of 59 Assessment Date: 11/06/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary		T							1
				Floor Plan		Glazed	Operable	100	
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		10.15			1 101		4.40		
Computer Lab	Regular Classroom	2nd Floor	205	205	1,131	280	140	N	N
Computer Lab	Regular Classroom	2nd Floor	206	206	1,092	160	80	N	N
Music Room	Regular Classroom	1st Floor	106	106	820	160	80	N	Y
Office	Regular Classroom	1st Floor	103	103	1,131	280	140	N	N
Regular Classroom	Library	1st Floor	105	105	1,131	200	100	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	879	280	140	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	1,131	280	140	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	879	280	140	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	593	96	32	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	303	1,131	120	36	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	879	280	140	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	305	1,131	120	36	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	311	NA	750	36	8	N	N
Science Classroom	Regular Classroom	3rd Floor	306	306	1,092	200	100	N	Υ
Building : Annex									
Kindergarten	Regular Classroom	2nd Floor	227	203	1,200	256	20	N	N
Multi Purpose Room	Regular Classroom	2nd Floor	226	211	856	192	15	N	N
Office	Computer Lab	2nd Floor	221	208	936	256	20	N	N
Pre School	Pre School	1st Floor	124	123	1,200	384	30	N	N
Pre School	Pre School	1st Floor	125	125	1,200	192	15	N	N
Pre School	Pre School	1st Floor	126	126	1,200	192	15	N	N
Pre School	Pre School	1st Floor	127	135	784	128	10	N	N
Pre School	Pre School	1st Floor	128	136	784	320	25	N	N
Regular Classroom	Regular Classroom	2nd Floor	220	210	856	192	15	N	N
Regular Classroom	Regular Classroom	2nd Floor	228	212	1,170	256	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	229	215	856	192	15	N	N
Regular Classroom	Regular Classroom	2nd Floor	230	216	856	192	15	N	N
Special Education	Regular Classroom	2nd Floor	223	207	532	128	10	N	N
Special Program	Office	2nd Floor	231	217	330	96	8	N	N
Store Room	Regular Classroom	2nd Floor	224	224	1,040	256	20	N	N
	1 - 3				.,				
Building : Addition 1									
Library	Kindergarten	1st Floor	101	101	1,444	320	160	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	820	240	120	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	820	240	120	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	820	240	120	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	820	240	120	N	N





Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Special Education	Office	2nd Floor	200	NA	536	120	80	N	Υ
Special Education	Office	3rd Floor	300	NA	536	120	80	Ν	N
Store Room	Regular Classroom	3rd Floor	301	301	820	120	36	Ν	N

Building : Addition 2									
Office	Regular Classroom	2nd Floor	208	208	820	240	120	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	1,092	280	60	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	820	240	120	N	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	820	240	120	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	820	240	120	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	1,092	240	120	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	820	240	120	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	820	240	120	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	1,092	240	120	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	308	820	240	120	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	820	120	36	N	N
Store Room	Regular Classroom	3rd Floor	310	310	820	120	36	N	N

Campus Name: Davis N Page : 59 of 59 Assessment Date: 11/06/2023