

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1900	3	71,361
Annex	1978	1	14,830
Campus Total			86,191

Category : Exterior Building : Main

Calego	Category . Exterior		D				
0	Manua Tama	ld	0	LIOM	Danila	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	# 4 S	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	# 4 S	6	LF	5	10+ years	
	Entrance Control - Audio and Video	#1 - Main N	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#1 - Main N	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 - Main N	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1 - Main N	12	LF	5	1-2 years	Broken
	Entrance Control - Audio and Video	#2 - E	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#2 - E	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2 - E	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#3 - SE	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#3 - SE	8	LF	5	1-2 years	Broken concrete
	Exterior Doors - Exterior Steel Door	#5 - S	1	EA	7	10+ years	New
	Exterior Doors - Transom Lite	#5 - S	1	EA	7	10+ years	
	Entrance Control - Audio	#6 - SW	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#6 - SW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#6 - SW	2	EA	6	6-10 years	
	Entrance Control - Audio	#7 - W	1	EA	5	2-5 years	
	Exterior Doors - Exterior FRP Door	#7 - W	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#7 - W	3	EA	5	2-5 years	
	Exterior Stairs - Concrete	#7 - W	10	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Fire Escapes	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Fire Escapes	2	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
0	Itama Tura	Lagation	O	11014	Devil	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Esca		0 11					
	Exterior Doors - Exterior Steel Door	South	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	South	2	EA	6	10+ years	
	Fire Escape	South	75	LF	6	6-10 years	0 11
	Fire Escape	South	10	LF	4	0-1 year	Several bent metal rods at stair
	Deinte	Cauth	0.5	LF	_	0.5.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	treads and fire escape run.
	Paints	South	85	LF	5	2-5 years	Minor corrosion
Foundati	on						
1 Odridati	Foundation - Concrete	Entire Building	20	LF	5	1-2 years	Are broken masonry at foundation,
	Touridation Concrete	Entire Ballating	20		J	1 Z yours	water pours into the basement
	Foundation - Masonry	Entire Building	645	LF	7	10+ years	water poure into the bacoment
	Superstructure - Heavy Timber	Entire Building	71,361	SF	7	10+ years	
	Superstructure - Slab on Grade	Entire Building	200	SF	5	2-5 years	This condition was not observed
	Superestructure Stab of Grade	Zitaro Danamg	200	O.	Ü	2 0 700.0	The condition was not observed
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	7	10+ years	
Roof Sys	stem						
,	Coping - Stone	Low South Roofs	419	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Low South Roofs	38	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Low South Roofs	195	LF	6	10+ years	
	Parapet - Parapet > 30"	Low South Roofs	224	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Low South Roofs	3,107	SF	5	1-2 years	Ponding,
	Roof - Asphalt Gravel Ballast	Low South Roofs	100	SF	4	1-2 years	Ponding
	Roof Structure - Steel / Metal Deck/	Low South Roofs	3,207	SF	7	10+ years	3
	Concrete Topping					•	
	Access Ladder - Metal	Main Roof	2	EΑ	5	2-5 years	
	Chimney - Brick Chimney- Stainless Steel	Main Roof	53	LF	6	10+ years	
	Liner					•	
	Chimney - Brick Chimney- Stainless Steel	Main Roof	10	LF	4	0-1 year	Open joints
	Liner						
	Coping - Metal	Main Roof	655	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Main Roof	240	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Main Roof	30	LF	5	2-5 years	
	Roof - Asphalt Shingle	Main Roof	26,038	SF	6	2-5 years	
	Roof - Asphalt Shingle	Main Roof	1,000	SF	3	1-2 years	Damaged tiles, curling, loose, missing
	Roof - Metal	Main Roof	200	SF	6	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	5	2-5 years	
	Roof Structure - Heavy Timber	Main Roof	27,238	SF	7	10+ years	
	Coping - Metal	Mid S Roofs	36	LF	5	2-5 years	
	Downspouts - Exterior Downspouts	Mid S Roofs	40	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Mid S Roofs	160	SF	5	1-2 years	Growing vegetation, blistering



atego	ry : Exterior		В	uilding	: Main		
_						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Heavy Timber	Mid S Roofs	160	SF	7	10+ years	
	•					·	
alls							
<u>uno</u>	Cornice - Cast Stone	Entire Building	665	LF	5	6-10 years	
	Cornice - Masonry Projecting Limestone	Entire Building	665	LF	6	10+ years	
	Cornice - Terra Cotta	Entire Building	665	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	25,433	SF	6	10+ years	Repaired
	Exterior Walls - Prefabricated Metal Panel	Entire Building	475	SF	6	6-10 years	Repaired
	Wall	Littire Building	475	Oi	O	0-10 years	
	Exterior Walls - Stone-Cast	Entire Building	6,555	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	100	SF	5	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	685	SF	5	10+ years	
	Exterior Walls Terra Gotta	Entire Building	000	Oi.	J	TOT years	
ndow	S						
	Guard - Guards wire guard	Entire Building	3,118	SF	5	2-5 years	
	Lintels - Brick	Entire Building	85	LF	6	10+ years	
	Lintels - Steel	Entire Building	366	LF	6	10+ years	
	Lintels - Stone	Entire Building	864	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	16	SF	4	1-2 years	Broken glass and corroded fram
	Skylite - Lexan	Entire Building	40	SF	4	1-2 years	Corroded frames, obsolete design
	Windows - Louver	Entire Building	48	SF	6	6-10 years	00.10000 110.1100, 0000.010 000.
	Windows - Sash Aluminum	Entire Building	252	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,242	SF	5	2-5 years	
	Windows - Sash Lexan	Entire Building	3,792	SF	5	2-5 years	
	Windows - Wood- Double-pane	Entire Building	864	SF	6	6-10 years	
	Windows - Wood- Single-pane	Entire Building	32	SF	6	6-10 years	
	vviildows vvood Olligic parie	Littile Building	02	O.	Ü	o ro years	
tego	ry : Electrical		В	uilding	: Main		
	Hom Type	Location	Ouantitu	UOM	Rank	Recommend	Comments
oup	Item - Type	Location	Quantity	UOIVI	Kalik	Replacement	Comments
erge	ncy System Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	Older than 30 years old.
	Security System - CCTV	Entire Building	71,361	SF	5	2-5 years 2-5 years	Cidel than 50 years old.
	Security System - CCTV Security System - Intrusion Detection	Entire Building	71,361 71,361	SF SF	5 6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building Entire Building	6,804	SF SF	6	6-10 years 6-10 years	
	Stairs	Little building		-	U	0-10 years	
	E A/O.D. O. I. (T.) (Entire Building	1,192	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets		11	EA	6	6-10 years	
	Emergency A/C Power - Students Tollets Emergency Battery Packs - Corridors and Stairs	Entire Building	• •				
	Emergency Battery Packs - Corridors and Stairs	· ·		ΕA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Entire Building	2	EA FA	6 6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms	Entire Building Entire Building	2 3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Entire Building	2				Incandescent bulbs



Catego	ry : Electrical		R	uilding	· Main		5415 S Union AVENUE, Chicago, IL 606
Jaicgo	ry : Electrical			unung	. IVICIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
лоцр	Exit Signs - Gym	Entire Building	3	EA	4	2-5 years	Incandescent bulbs
	Exit Signs - Lunchroom	Entire Building	3	EΑ	4	2-5 years	Incandescent bulbs
	Exit digits Editoritoditi	Entire Building	J		7	2 0 years	modrideseem builds
1ain Se	rvice						
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	
	emergency power	Floatrical Boom	1	ГΛ	6	6.10	
	Main Electrical Service - 1600 A	Electrical Room	1	EA	6	6-10 years	
	120/208/3PH	Entire Duilding	71.061	C.E.	6	6.10 , , , , , , , ,	
	PA System	Entire Building	71,361	SF	6	6-10 years	
ower D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Heavily rusted door and panel
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	ricarily racioa acci and panel
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	6	6-10 years	
	Main Distribution 1 and 3 400 000 amp	Entire Building	'	_/\	O	o ro years	
atego	ry : Fire Protection		В	uilding	: Main		
	N T	Laadlan	O	шом	Danila	Recommend	0
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m Fire Alarm Panel	Boiler Room		ГΛ	6	6.10 voore	
			1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Boiler Room	71,361	SF	6	6-10 years	
	Fire Alarm_System	Boiler Room	71,361	SF	5	6-10 years	
atego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ditioning						
Air Conc			1	EA	6	6-10 years	Serves MDF room.
Air Conc	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof		_, 、			
Air Conc	than 5 tons Condensing Unit- Roof Mounted - Less	Lower Roof	1	EA	6	6-10 years	
ir Conc	than 5 tons				6	6-10 years	



Category : Mechanical			В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone-	Entire Building	1	EA	5	2-5 years	Peeling paint, old motor
	Double Delivery- Steam Coils - 45001 -						
	60000 cfm						
	Air Intake	Entire Building	2	EA	5	10+ years	
	Auxiliaries - 45001 - 60000 cfm	Entire Building	1	EA	5	6-10 years	- -
	Zone Dampers	Entire Building	36	EA	5	6-10 years	Dated, no BAS control
D = !! = = O:							
Boiler Sy		Entire Duilding	2	ΕΛ		0.40	
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Entire Building	2	EA	6	6-10 years	
	Chemical Feed System	Entire Building	1	EA	6	6-10 years	
	Combustion Dampers	Entire Building	2	EA	5	2-5 years	
	Condensate Pump	Entire Building	1	EA	4	1-2 years	Leaking and corroded
	Condensate Pump	Entire Building	1	EA	4	1-2 years	Leaking and corroded
	Feed Water Pumps and Tank	Entire Building	1	EA	6	6-10 years	Leaking and corroded
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building		EA	5	2-5 years	
	Steam- Low Pressure Boiler - 101 - 150 HP	Entire Ballating	•	_/\	O	2 o youro	
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	5	2-5 years	
	Steam- Low Pressure Boiler - 101 - 150 HP	9	•			,	
	Piping - Condensate Pipe- Steel	Entire Building	200	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Entire Building	200	LF	6	6-10 years	
	Steam Traps	Entire Building	20	EA	6	2-5 years	
	Vacuum Pump	Entire Building	2	EA	4	1-2 years	Leaking and corroded
Heating I	Devices						
пеашу	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Radiators - Steam	Entire Building	10	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	5	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	5	6-10 years	
		9				- · · · , · · · ·	
Tempera	ture Control						
	Electric Thermostat	Entire Building	1	EA	5	6-10 years	
	Pneumatic System	Entire Building	71,361	SF	3	0-1 year	Not operational
	Thermostats - Pneumatic	Entire Building	36	EA	4	0-1 year	Not operational
Ventilatio	on.						
· Ommatic	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire building	1	EA	5	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire building	2	EA	6	10+ years	
	CFM	Ü				,	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire building	1	EA	4	0-1 year	Damaged.
	CFM	5				•	-



Catego	ry : Mechanical		В	uilding	: Main		
Grann	Itam Tuno	Logation				Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	Newly installed
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	71,361	SF	4	2-5 years	More than 50 years old.
	Domestic Piping-Hot Water Return Risers	Entire Building	71,361	SF	4	2-5 years	More than 50 years old.
	Domestic Piping-Hot Water from Risers to	Entire Building	71,361	SF	4	2-5 years	More than 50 years old.
	Fixtures	Little Ballaing	7 1,00 1	O.	7	2 0 yours	More than 50 years old.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	71,361	SF	4	2-5 years	More than 50 years old.
	(Horizontal Lines)	g	,		•	,	,
	Domestic Piping-Hot/Cold Water Supply	Entire Building	71,361	SF	4	2-5 years	More than 50 years old.
	(Risers)	Č	,			,	•
	Domestic Piping-Hot/Cold Water Supply	Entire Building	71,361	SF	4	2-5 years	More than 50 years old.
	(from Risers to Fixtures)	-	,			<u>,</u>	•
	Sanitary Piping	Entire Building	71,361	SF	5	10+ years	
	Storm Piping	Entire Building	71,361	SF	5	10+ years	
	Vent Piping	Entire Building	71,361	SF	5	10+ years	
_							
Pumps	D 0 1 D 1 D 0 1	Б ,				0.5	
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	5	2-5 years	
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	1.5 floor -Principal Office 106	1	EΑ	7	6-10 years	
	Ceiling - Splined	1.5 floor -Principal Office 106	314	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1.5 floor -Principal Office 106	2	EA	6	10+ years	
	Floor - Carpet	1.5 floor -Principal Office 106	314	SF	6	6-10 years	
	Lighting - Pendent/Surface	1.5 floor -Principal Office 106	6	ĒΑ	7	6-10 years	
	Power Distribution	1.5 floor -Principal Office 106	6	EA	6	10+ years	
	Storage/ Closet	1.5 floor -Principal Office 106	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1.5 floor -Principal Office 106	700	SF	6	10+ years	
	AC Unit	1.5 floor- Main Office 105	1	EA	7	6-10 years	
	Ceiling - Splined	1.5 floor- Main Office 105	380	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1.5 floor- Main Office 105	1	EA	6	10+ years	
	Floor - Tile	1.5 floor- Main Office 105	380	SF	6	10+ years	
			230	٥.	Ŭ	. o . youro	
	Jame: Dewey	Page : f					Assessment Date: 10/13/2023

Assessment Date: 10/13/2023 Campus Name: Dewey Page : 6 of 32



Catego	Category : Room Building : Main						
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1.5 floor- Main Office 105	6	EA	7	6-10 years	
	Power Distribution	1.5 floor- Main Office 105	9	EA	6	10+ years	
	Walls - Plaster/Drywall	1.5 floor- Main Office 105	610	SF	6	10+ years	
	AC Unit	207	1	EA	7	6-10 years	
	Ceiling - Splined	207	550	SF	6	10+ years	
	Doors - Wood Doors inclu hw	207	1	EA	6	10+ years	
	Floor - Tile	207	550	SF	6	10+ years	
	Lighting - Pendent/Surface	207	10	EΑ	7	6-10 years	
	Power Distribution	207	12	EA	6	10+ years	
	Walls - Plaster/Drywall	207	1,235	SF	6	10+ years	
	Ceiling - Plaster/Drywall	208 Dean's Office	235	SF	6	10+ years	
	Doors - Wood Doors inclu hw	208 Dean's Office	1	EA	6	10+ years	
	Floor - Tile	208 Dean's Office	235	SF	6	10+ years	
	Lighting - Pendent/Surface	208 Dean's Office	6	EΑ	7	6-10 years	
	Power Distribution	208 Dean's Office	6	EA	6	6-10 years	
	Storage/ Closet	208 Dean's Office	86	SF	7	10+ years	
	Walls - Plaster/Drywall	208 Dean's Office	280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement- Nurse's Office	301	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement- Nurse's Office	1	EA	6	10+ years	Cialian flags basels and assessing
	Floor - Tile	Basement- Nurse's Office	301	SF	4	0-1 year	Sinking floor, baseboard separating
	Lighting - Pendent/Surface	Basement- Nurse's Office	5	EA	7	6-10 years	from tiles, uneven floor
	Power Distribution	Basement- Nurse's Office	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Basement- Nurse's Office	842	SF	7	10+ years	
	Work Sink	Basement- Nurse's Office	1	EA	7	10+ years	
	Ceiling - Exposed	Basement- Teacher's Lounge	607	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement- Teacher's Lounge	1	EA	6	10+ years	
	Floor - Tile	Basement- Teacher's Lounge	607	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement- Teacher's Lounge	10	EA	7	6-10 years	
	Power Distribution	Basement- Teacher's Lounge	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Basement- Teacher's Lounge	1,095	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office	215	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	215	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	5	EA	7	6-10 years	
	Power Distribution	Engineer's Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	550	SF	6	10+ years	
	Work SInk	Engineer's Office	1	EA	7	10+ years	
	-	3	•		-	- ,	
Gymnas	ia						
•	AC Unit	Auditorium	4	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Auditorium	667	SF	6	10+ years	
	Ceiling - Splined	Auditorium	3,783	SF	5	1-2 years	Spline tiles missing, damage to
						•	plaster underneath

Campus Name: Dewey Page: 7 of 32 Assessment Date: 10/13/2023



Catego	ry : Room		В	uilding	: Main			
	_					Recommend		
∂roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Steel Doors incl hw	Auditorium	2	EA	6	10+ years		
	Doors - Wood Doors inclu hw	Auditorium	2	EA	6	10+ years		
	Floor - Wood	Auditorium	4,450	SF	6	10+ years		
	Lighting - Pendent/Surface	Auditorium	21	EΑ	7	6-10 years		
	Stage	Auditorium	568	SF	6	10+ years		
	Stage Curtain	Auditorium	2	EA	7	10+ years		
	Stage-Stairs - Tile	Auditorium	11	LF	6	10+ years	New metal material	
	Storage/ Closet	Auditorium	184	SF	7	10+ years		
	Walls - Plaster/Drywall	Auditorium	4,404	SF	6	10+ years		
Kitchen								
	Ceiling - Plaster/Drywall	Basement	330	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Basement	330	SF	6	10+ years		
	Lighting - Pendent/Surface	Basement	4	EA	7	6-10 years		
	Walls - Concrete Block	Basement	684	SF	6	10+ years		
unch &	Multipurpose Room							
	Ceiling - Splined	B12- Cafeteria	950	SF	6	10+ years		
	Doors - Wood Doors inclu hw	B12- Cafeteria	2	EA	6	10+ years		
	Floor - Tile	B12- Cafeteria	950	SF	6	10+ years		
	Lighting - Pendent/Surface	B12- Cafeteria	10	EA	6	6-10 years		
	Serving Line	B12- Cafeteria	25	LF	6	10+ years		
	Walls - Masonry	B12- Cafeteria	1,320	SF	6	10+ years		
	Walls - Metal Panel	B12- Cafeteria	660	SF	6	10+ years		
	Ceiling - Plaster/Drywall	B13- Basement	1,263	SF	6	10+ years		
	Doors - Wood Doors inclu hw	B13- Basement	4	EA	6	10+ years		
	Floor - Tile	B13- Basement	1,263	SF	6	10+ years		
	Lighting - Pendent/Surface	B13- Basement	26	EA	6	6-10 years		
	Storage/ Closet	B13- Basement	59	SF	5	10+ years		
	Storage/ Closet	B13- Basement	107	SF	5	10+ years		
	Walls - Plaster/Drywall	B13- Basement	1,474	SF	6	10+ years		
MDF ID	F							
<u></u>	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years		
	Finishes	Basement	117	SF	7	10+ years		
	Other Cooling Unit	Basement	1	EA	4	1-2 years	Not working. Ductless split system	
∕lechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	15	SF	5	10+ years		
	Storage Room	1st Floor	93	SF	7	10+ years		
	Janitor's Closet	2nd Floor	53	SF	5	10+ years		
	Storage Room	2nd Floor	96	SF	5	10+ years		

Campus Name: Dewey Page: 8 of 32 Assessment Date: 10/13/2023



Category : Room			В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	3rd Floor	10	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	10	SF	7	10+ years	
	Air Intake Plenums	Basement	232	SF	7	10+ years	
	Air Intake Plenums	Basement	56	SF	7	10+ years	
	Air Intake Plenums	Basement	56	SF	7	10+ years	
	Air Intake Plenums	Basement	232	SF	7	10+ years	
	Air Tunnel	Basement	40	SF	7	10+ years	
	Boiler Room	Basement	994	SF	5	10+ years	
	Coal Room	Basement	308	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	291	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	803	SF	7	10+ years	
	Storage Room	Basement	384	SF	7	10+ years	
	Storage Room	Basement	1,070	SF	7	10+ years	
	Storage Room	Basement	487	SF	5	10+ years	
_Restroo	m						
	Accessories	1st Floor	96	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	96	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	96	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	255	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	2nd Floor	255	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	255	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	255	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	5	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	262	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	325	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	2nd Floor	281	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	281	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	281	SF	6	10+ years	
	Floor Drain	2nd Floor	1	ĒΑ	7	10+ years	
						-	



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	5	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	270	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	325	SF	6	10+ years	
	Water Closet	2nd Floor	5	EA	6	10+ years	
	Accessories	2nd Floor	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Concrete	2nd Floor	60	SF	7	10+ years	
	Lavatory	2nd Floor	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	ΕA	7	6-10 years	
	Walls - Metal Panel	2nd Floor	33	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	97	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	6	10+ years	
	Accessories	2nd floor - Rm 208	47	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor - Rm 208	47	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor - Rm 208	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor - Rm 208	47	SF	6	10+ years	
		2nd floor - Rm 208	1	EA	6	•	
	Lavatory Lighting - Pendent/Surface	2nd floor - Rm 208	1	EA	7	10+ years	
	Partitions		1	EA	7	6-10 years	
		2nd floor - Rm 208	6	SF	6	10+ years	Dealing and aracking point
	Walls - Plaster/Drywall	2nd floor - Rm 208	_	SF SF	_	1-2 years	Peeling and cracking paint
	Walls - Plaster/Drywall	2nd floor - Rm 208	23		6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd floor - Rm 208	33	SF	6	10+ years	Tiles esissis a babis d'adist
	Walls - Tile Ceramic/ Porcelain	2nd floor - Rm 208	10	SF	4	1-2 years	Tiles missing behind toilet
	Water Closet	2nd floor - Rm 208	1	EA	6	10+ years	
	Accessories	Basement	390	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	390	SF	5	1-2 years	Cracking paint throughout
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	390	SF	6	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	Lavatory	Basement	4	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	10	EA	7	6-10 years	
	Partitions	Basement	4	EA	7	10+ years	
	Urinals	Basement	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	Basement	605	SF	6	10+ years	
	Water Closet	Basement	4	EA	6	10+ years	
	Accessories	Basement	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	266	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	266	SF	6	10+ years	

Campus Name: Dewey Page: 10 of 32 Assessment Date: 10/13/2023



Category: Room

Classroom #101 (Regular Classroom) AC Units

Ceiling - Splined

Doors - Transom Window

Dewey Elementary Academy of Fine Arts 5415 S Union AVENUE, Chicago, IL 60609

observations

- uning -	· y · · · · · · · · · · · · · · · · · ·		_			_	
Craun	Hom Type	Location	Ouantitu	ПОМ	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Basement	1	EΑ	7	10+ years	
	Hand Dryer	Basement	2	EΑ	7	6-10 years	
	Lavatory	Basement	4	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	6	EA	7	6-10 years	
	Partitions	Basement	5	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	517	SF	6	10+ years	
	Water Closet	Basement	5	EA	6	10+ years	
	Accessories	In Boiler Room	177	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	In Boiler Room	177	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Boiler Room	_2	EA	6	10+ years	
	Floor - Tile	In Boiler Room	77	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Boiler Room	100	SF	6	10+ years	
	Lavatory	In Boiler Room	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In Boiler Room	4	EA	6	6-10 years	
	Walls - Masonry	In Boiler Room	250	SF	6	10+ years	
	Walls - Masonry	In Boiler Room	17	SF	5	10+ years	
	Walls - Plaster/Drywall	In Boiler Room	151	SF	5	10+ years	
	Walls - Plaster/Drywall	In Boiler Room	50	SF	4	0-1 year	Spalling
	Water Closet	In Boiler Room	1	EA	7	6-10 years	Deficiency fixed
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #011 (Regular Classroom)						
	Ceiling - Splined	Basement	898	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	898	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	21	EA	7	6-10 years	
	Marker Board	Basement	20	LF	6	6-10 years	
	Storage/ Closet	Basement	207	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,240	SF	6	10+ years	Quantity updated to match current observations
	Walls - Plaster/Drywall	Basement	40	SF	5	1-2 years	Baseboard separating from the floor, quantity updated to match current

Building: Main

EΑ

SF

SF

1

9

837

7

6

6

6-10 years

10+ years

10+ years

Doors - Wood Doors inclu hw 1st Floor EΑ 6 10+ years 1 Floor - Tile 1st Floor 837 SF 10+ years 6 Lighting - Lay-in 6-10 years 1st Floor 7 14 EΑ Marker Board 1st Floor 28 LF 6-10 years

1st Floor

1st Floor

1st Floor

Campus Name: Dewey Page: 11 of 32 Assessment Date: 10/13/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,235	SF	6	10+ years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	837	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	831	SF	6	10+ years	
	Floor - Tile	1st Floor	6	SF	4	1-2 years	Cracks and buckling
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	ŭ
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Storage/ Closet	1st Floor	93	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,235	SF	6	10+ years	
_Classroo	om #103 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	837	SF	6	10+ years	
	Doors - Transom Window	1st Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	837	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	38	LF	6	6-10 years	
	Storage/ Closet	1st Floor	93	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,287	SF	6	10+ years	
Classroo	om #104 (Computer Lab)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	837	SF	6	10+ years	
	Doors - Transom Window	1st Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	837	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	14	LF	7	6-10 years	
	Storage/ Closet	1st Floor	93	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,287	SF	6	10+ years	
Classroo	om #108 (Library)						
	Ceiling - Lay-in	1st Floor	837	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	837	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Lighting 1 chachicounace	1301 1001	2	LA	,	o io yeais	



Catego	ry : Classroom		В	uilding	: Main		
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	93	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,235	SF	6	10+ years	
Classroo	m #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Splined	1st Floor	837	SF	6	10+ years	
	Doors - Transom Window	1st Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	837	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	14	LF	6	6-10 years	
	Storage/ Closet	1st Floor	93	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,235	SF	6	10+ years	
Classroo	m #110 (Regular Classroom)						
<u> </u>	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	960	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	960	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Storage/ Closet	1st Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	132	SF	6	10+ years	
Classroo	m #111 (Regular Classroom)						
Classioo		4-4-51	4		7	0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	960	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	960	SF	6	10+ years	
	Lighting Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Storage/ Closet	1st Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,322	SF	6	10+ years	
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	960	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	960	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,322	SF	6	10+ years	
lassroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Ceiling - Splined	2nd Floor	960	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	960	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,322	SF	6	10+ years	
assroc	om #203 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	1,088	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,070	SF	7	10+ years	
	Floor - Tile	2nd Floor	18	SF	4	1-2 years	Broken tile exposing subfloor,
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years	cracking tiles
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	240	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	864	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
assroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	837	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	837	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor 2nd Floor	93	SF	7		
				SF		10+ years	
	Walls - Plaster/Drywall Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,284 3	SF	6 5	10+ years 1-2 years	Bubbling, cracked paint
assroc	om #209 (Regular Classroom)						
200100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor 2nd Floor	837	SF	6	10+ years	
	Centring - Spillieu	ZHU FIOOI	637	SI-	U	10+ years	



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Hardware	2nd Floor	1	EΑ	6	1-2 years	Door knob plate is loose
	Doors - Transom Window	2nd Floor	36	SF	6	10+ years	·
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	837	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	93	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,287	SF	6	10+ years	
lassroo	nm #210 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	960	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	960	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	42	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,317	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Cracked paint and exposed plaste
	Work Sink	2nd Floor	1	EA	7	10+ years	Oracica paint and exposed plaste
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	960	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	960	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,322	SF	6	10+ years	
lassroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	960	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	960	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	136	SF	5	10+ years	Nonfunctional light
	Walls - Plaster/Drywall	3rd Floor	1,322	SF	6	10+ years	Normanicuonal light
	Walle Maciely 21, Wall	014 1 1001	1,022	O.	Ū	io. yeare	
lassroo	m #302 (Regular Classroom)						

Campus Name: Dewey Page : 15 of 32 Assessment Date: 10/13/2023



atego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	960	SF	6	10+ years	Updated quantity
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	- p
	Floor - Tile	3rd Floor	960	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	136	SF	5	6-10 years	Light nonfunctional
	Walls - Plaster/Drywall	3rd Floor	1,418	SF	6	10+ years	Light horiunctional
assroc	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	857	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	Sr EA		•	
			· · · · · · · · · · · · · · · · · · ·	SF	6	10+ years	
	Floor - Tile	3rd Floor	853		7	10+ years	Objection and demands
	Floor - Tile	3rd Floor	4	SF	4	1-2 years	Chipping and damage to edges
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	46	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	93	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,287	SF	6	10+ years	
assroc	om #308 (Music Room)						
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Ceiling - Splined	3rd Floor	857	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	847	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Chipping and broken edges of tile
	Lighting - Lay-in	3rd Floor	16	EΑ	7	6-10 years	ompring and broken bagos of an
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	93	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,287	SF	7	10+ years	
assroc	om #310 (Regular Classroom)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	948	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	940	SF	6	10+ years	
	Floor - Tile	3rd Floor	8	SF	4	0-1 year	Cracking, subfloor exposed
		3rd Floor	16	EA	7	,	Cracking, submoor exposed
	Lighting - Lay-in					6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,322	SF	6	10+ years	

Campus Name: Dewey Page : 16 of 32 Assessment Date: 10/13/2023



atego	ory : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassro	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	920	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	920	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EΑ	7	6-10 years	
	Storage/ Closet	3rd Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,322	SF	7	10+ years	
lassro	om #B-24 (Store Room)						
	Casework	Basement	8	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	1,100	SF	7	6-10 years	
	Chalk Board	Basement	26	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	6-10 years	
	Floor - Tile	Basement	1,100	SF	7	6-10 years	
	1:1:: D 1 1/0 f	Basement	22	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface				7	6-10 years	
	Lighting - Pendent/Surface Walls - Masonrv	Basement	1.176	SE	/	U-IU VEAIS	
	Lighting - Pendent/Surrace Walls - Masonry Walls - Plaster/Drywall	Basement Basement	1,176 150	SF SF	7	6-10 years	
atego	Walls - Masonry Walls - Plaster/Drywall		150	SF	7	•	
Catego	Walls - Masonry	Basement	150		7	•	
_	Walls - Masonry Walls - Plaster/Drywall		150	SF	7	6-10 years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall ory : Interior Item - Type	Basement	150 B	SF uilding	7 : Main	6-10 years Recommend	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall	Basement	150 B	SF uilding	7 : Main	6-10 years Recommend	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Pry: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain	Location 1st Floor 1st Floor	150 B Quantity	SF uilding UOM SF EA	7 : Main Rank	6-10 years Recommend Replacement	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall	Location 1st Floor	150 B Quantity	SF uilding UOM SF	7 : Main Rank	6-10 years Recommend Replacement 10+ years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Pry: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain	Location 1st Floor 1st Floor	150 B Quantity 1,820 1	SF uilding UOM SF EA	7 : Main Rank 6 7	Recommend Replacement 10+ years 10+ years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface	Location 1st Floor 1st Floor 1st Floor	150 B Quantity 1,820 1,820 1,820	SF uilding UOM SF EA SF	7 : Main Rank 6 7 6	Recommend Replacement 10+ years 10+ years 10+ years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	150 B Quantity 1,820 1,820 1,820 18	SF uilding UOM SF EA SF EA EA LF	7 : Main Rank 6 7 6 6 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface	Location 1st Floor	150 B Quantity 1,820 1,820 18 4	SF uilding UOM SF EA SF EA LF SF	7 : Main Rank 6 7 6 6 6 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs	Location 1st Floor	150 B Quantity 1,820 1,820 18 4 10	SF uilding UOM SF EA SF EA EA LF	7 : Main Rank 6 7 6 6 6 6 6 6 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall	Location 1st Floor	150 B Quantity 1,820 1,820 18 4 10 3,456	SF uilding UOM SF EA SF EA LF SF	7 : Main Rank 6 7 6 6 6 6 6 6 6 6 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain	Location 1st Floor 2nd Floor	150 B Quantity 1,820 1,820 18 4 10 3,456 1,820	SF uilding UOM SF EA SF EA LF SF SF	7 : Main Rank 6 7 6 6 6 6 6 6 6 6 6 6 6 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor	Location 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	150 B Quantity 1,820 1 1,820 18 4 10 3,456 1,820 1 1,820	SF uilding UOM SF EA SF EA LF SF SF EA SF SF SF	7 : Main Rank 6 7 6 6 6 6 6 6 6 7 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent	Location 1st Floor 2nd Floor	150 B Quantity 1,820 1 1,820 18 4 10 3,456 1,820 1 1,820 1 1,820 18	SF uilding UOM SF EA SF EA LF SF EA SF EA SF EA	7 : Main Rank 6 7 6 6 6 6 6 6 7 6 7 6 7	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface	Location 1st Floor 2nd Floor	150 B Quantity 1,820 18 4 10 3,456 1,820 1 1,820 1 1,820 1 1,820 18 4	SF uilding UOM SF EA SF EA LF SF EA SF EA LF SF EA EA	7 : Main Rank 6 7 6 6 6 6 7 6 7 7	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years	Comments
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Walls - Plaster/Drywall	Location 1st Floor 2nd Floor	150 B Quantity 1,820 18 4 10 3,456 1,820 1 1,820 1 1,820 1 3,453	SF uilding UOM SF EA SF EA LF SF EA SF EA SF EA SF EA SF EA	7 : Main Rank 6 7 6 6 6 6 7 6 7 7 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years	
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Walls - Plaster/Drywall Walls - Plaster/Drywall	Location 1st Floor 2nd Floor	150 B Quantity 1,820 18 4 10 3,456 1,820 1 1,820 1 3,453 3	SF uilding UOM SF EA SF EA LF SF EA	7 : Main Rank 6 7 6 6 6 6 7 6 7 7 6 5	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years	Comments Peeling paint
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Walls - Plaster/Drywall Walls - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	Location 1st Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor - North West	150 B Quantity 1,820 18 4 10 3,456 1,820 1 1,820 18 4 3,453 3 324	SF uilding UOM SF EA SF EA LF SF EA SF SF	7 : Main Rank 6 7 6 6 6 6 7 6 7 7 6 5 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	
roup	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Walls - Plaster/Drywall Walls - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Asphalt Floor	Location 1st Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor - North West 3rd Floor - North West	150 B Quantity 1,820 18 4 10 3,456 1,820 1 1,820 1 3,453 3 324 324	SF uilding UOM SF EA SF EA LF SF EA SF EA SF EA SF EA SF EA SF SF SF SF SF	7 : Main Rank 6 7 6 6 6 6 7 6 7 7 6 5 6 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Catego Group Corridor	Walls - Masonry Walls - Plaster/Drywall Ory: Interior Item - Type Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Triple Fountain Floor - Asphalt Floor Lighting - Chandelier, Incandescent Lighting - Pendent/Surface Walls - Plaster/Drywall Walls - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	Location 1st Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor - North West	150 B Quantity 1,820 18 4 10 3,456 1,820 1 1,820 18 4 3,453 3 324	SF uilding UOM SF EA SF EA LF SF EA SF SF	7 : Main Rank 6 7 6 6 6 6 7 6 7 7 6 5 6	Recommend Replacement 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor - South East	324	SF	6	10+ years	
	Floor - Asphalt Floor	3rd Floor - South East	324	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor - South East	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor - South East	540	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - North West	1,090	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement - North West	3	EA	6	10+ years	
	Doors - Transom Window	Basement - North West	27	SF	6	10+ years	
	Drinking Fountains - Double Fountain	Basement - North West	1	EA	5	10+ years	
	Floor - Asphalt Floor	Basement - North West	1,090	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	Basement - North West	10	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement - North West	9	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement - North West	4	LF	6	10+ years	
	Walls - Concrete Block	Basement - North West	218	SF	6	10+ years	
	Walls - Masonry	Basement - North West	123	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - North West	1,111	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - South East	1,190	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement - South East	3	EA	6	10+ years	
	Doors - Transom Window	Basement - South East	27	SF	6	10+ years	
	Drinking Fountains - Single Fountain	Basement - South East	1	EA	7	10+ years	
	Floor - Asphalt Floor	Basement - South East	1,190	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	Basement - South East	10	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement - South East	9	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement - South East	4	LF	6	10+ years	
	Walls - Concrete Block	Basement - South East	318	SF	6	10+ years	
	Walls - Masonry	Basement - South East	223	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - South East	1,211	SF	6	10+ years	
	Ceiling - Exposed	Basement - West	236	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement - West	4	EA	6	10+ years	
	Doors - Transom Window	Basement - West	24	SF	6	10+ years	
	Drinking Fountains - Single Fountain	Basement - West	1	EA	7	10+ years	
	Floor - Asphalt Floor	Basement - West	236	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - West	5	EA	7	6-10 years	
	Walls - Masonry	Basement - West	700	SF	6	10+ years	
	Walls - Masonry	Basement - West	20	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement - West	336	SF	6	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	8	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
	Coounty Cumeras	1001	2	L/\	,	o io years	
Stairs	0.11. Di . /D	O(: N (N (250	05			
	Ceiling - Plaster/Drywall	Stairs - North West	252	SF	6	10+ years	
	Floor - Asphalt	Stairs - North West	588	SF	6	10+ years	

Campus Name: Dewey Page : 18 of 32 Assessment Date: 10/13/2023



Catego	ry : Interior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Handrails	Stairs - North West	162	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairs - North West	9	EA	6	6-10 years	
	Stairs - Asphalt	Stairs - North West	80	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairs - North West	2,700	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairs - South East	252	SF	6	10+ years	
	Floor - Asphalt	Stairs - South East	588	SF	6	10+ years	
	Handrails	Stairs - South East	160	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairs - South East	9	EA	6	6-10 years	
	Stairs - Asphalt	Stairs - South East	80	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairs - South East	700	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	396	SF	6	10+ years	
	Floor - Terrazzo	West	396	SF	6	10+ years	
	Handrails	West	48	LF	7	10+ years	
	Lighting - Pendent/Surface	West	4	EA	7	6-10 years	
	Stairs - Asphalt	West	24	LF	6	10+ years	
	Walls - Plaster/Drywall	West	880	SF	6	10+ years	
_Vertical (Conveyance						
	Wheelchair Lift - Platform Lift	1st Floor	1	EA	7	10+ years	Under construction

Campus Name: Dewey Page: 19 of 32 Assessment Date: 10/13/2023



Exterior Walls - Stucco

Curtain wall - Louver

Windows

Catego	ry : Exterior		В	uilding	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance)						
	Entrance Control - Audio and Video	#1 Main - S	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#1 Main - S	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 Main - S	2	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#2- SW	2	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#3 - NW	2	EA	6	6-10 years	
	Entrance Control - Audio and Video	#4 - N	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#4 - N	4	EA	6	6-10 years	
oundat	on						
	Foundation - Concrete	Entire Building	494	LF	7	10+ years	
	Foundation - Concrete	Entire Building	12	LF	6	6-10 years	
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	14,830	SF	7	10+ years	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	16	EA	5	2-5 years	
Roof Sys	stem						
	Access Ladder - Metal	Main Roof	1	EA	7	6-10 years	
	Coping - Metal	Main Roof	506	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Main Roof	39	LF	6	6-10 years	
	Roof - Modified Bitumen	Main Roof	12,742	SF	5	2-5 years	Blistring, uneven surfaces, some ponding
	Roof Hatch - Metal	Main Roof	1	EA	5	1-2 years	damaged protection rails
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	12,742	SF	7	10+ years	01
	Downspouts - Exterior Downspouts	Upper Main Roof	6	LF	6	6-10 years	
	Roof - Modified Bitumen	Upper Main Roof	2,088	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Upper Main Roof	2,088	SF	7	10+ years	
Valls							
	Canopy - Concrete/ Stucco	Entire Building	529	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	5,823	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	209	SF	6	6-10 years	

249 SF

SF

6

312

6-10 years

6-10 years

Entire Building

Entire Building



ALL H							5415 S Union AVENUE, Chicago, IL 60609
Catego	ry : Exterior		Е	Building	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lintels - Steel	Entire Building	144	LF	6	10+ years	
	Windows - Sash Lexan	Entire Building	518	SF	4	0-1 year	Very old, opaque, worn out, lexan
							single pane
Catego	ry : Electrical		E	Building	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Emergency A/C Power - Corridors and	1st Floor	1,788	SF	6	6-10 years	
	Stairs					•	
	Emergency A/C Power - Multipurpose	1st Floor	1,956	SF	6	6-10 years	
	Room						
	Emergency A/C Power - Students Toilets	1st Floor	160	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and	1st Floor	3	EA	6	6-10 years	
	Stairs						
	Emergency Battery Packs - Multipurpose	1st Floor	2	EA	6	6-10 years	
	Room						
	Exit Signs - Corridors and Stairs	1st Floor	9	EA	4	2-5 years	Incandescent bulbs
	Exit Signs - Multipurpose Room	1st Floor	4	EA	4	2-5 years	Incandescent bulbs
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	14,830	SF	7	10+ years	
	Security System - Intrusion Detection	Entire Building	14,830	SF	6	6-10 years	
Main Se	rvice						
Wildin GO	PA System	1st Floor	14,830	SF	6	6-10 years	
	Main Electrical Service - 1200 A	Electrical Room	1-1,000	EA	6	6-10 years	
	120/208/3PH	Electrical Noom	•	L/ \	U	o io years	
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	
	emergency power	Elodillodi Noom	'		Ū	o ro youro	
	emergency perior						
Power D	istribution						
	Lighting and Power Panels - 100 A	1st Floor	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	1st Floor	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	1st Floor	1	EA	6	10+ years	
	•					·	
Catego	ry : Fire Protection		E	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Annunciator.
	Fire Alarm Strobe Lights	Entire Building	14,830	SF	6	10+ years	,ariolatori
			,000	٥.	Ŭ	. c . y care	

Campus Name: Dewey Page : 21 of 32 Assessment Date: 10/13/2023



Catego	ry : Fire Protection		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm_System	Entire Building	14,830	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems						
	Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - 11 - 20 tons	Roof	1	EA	5	1-2 years	Damaged irreparably rear housing door, coils and pan rusting heavily
Heating	Devices						
3	Wall Heater - Electric	Entire Building	16	EA	6	6-10 years	
	PTAC - Electric Heating and Self Contained Cooling	Entire Building	4	EA	6	6-10 years	
Tempera	ature Control						
	Electric Controls	Entire Building	14,830	SF	5	2-5 years	
	Electric Thermostat	Entire Building	3	EA	5	2-5 years	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	1st Floor	7	EA	5	2-5 years	
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	1st Floor	2	EA	4	0-1 year	Not operational
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	1st Floor	4	EA	4	0-1 year	Cooling not operational
Ventilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	6	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	
Catego	ry : Plumbing		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments

Campus Name: Dewey Page : 22 of 32 Assessment Date: 10/13/2023



					Replacement	
Hot Water						
Electric Heater - 20 - 50 KW	Mechanical Room	1	EA	6	10+ years	
Piping						
Domestic Piping-Hot Water Return Lines	Entire Building	14,830	SF	6	10+ years	
Domestic Piping-Hot/Cold Water Supply	Entire Building	14,830	SF	6	10+ years	
(Horizontal Lines)						
Sanitary Piping	Entire Building	14,830	SF	6	10+ years	
Storm Piping	Entire Building	14,830	SF	6	10+ years	
Vent Piping	Entire Building	14,830	SF	6	10+ years	
• •	· ·				•	

Category: Room **Building: Annex**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Lay-in	1st floor- Teacher's Room 119 on	441	SF	6	10+ years	
		plan					
	Doors - Wood Doors inclu hw	1st floor- Teacher's Room 119 on	2	EA	6	10+ years	
		plan					
	Floor - Carpet	1st floor- Teacher's Room 119 on	441	SF	6	10+ years	Updated material to match current
		plan					observations
	Lighting - Lay-in	1st floor- Teacher's Room 119 on	6	EA	7	6-10 years	
		plan					
	Power Distribution	1st floor- Teacher's Room 119 on	10	EA	6	10+ years	
		plan					
	Storage/ Closet	1st floor- Teacher's Room 119 on	11	SF	7	10+ years	
		plan					
	Walls - Concrete Block	1st floor- Teacher's Room 119 on	1,012	SF	6	10+ years	
	.	plan			_		
	Ceiling - Lay-in	1st floor- Teachers Lounge 401	429	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st floor- Teachers Lounge 401	2	EA	6	10+ years	
	Floor - Tile	1st floor- Teachers Lounge 401	426	SF	6	10+ years	
	Floor - Tile	1st floor- Teachers Lounge 401	3	SF	4	1-2 years	Tiles missing at base of AC
	Lighting - Lay-in	1st floor- Teachers Lounge 401	6	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st floor- Teachers Lounge 401	1	EA	7	6-10 years	
	Power Distribution	1st floor- Teachers Lounge 401	6	EA	7	10+ years	
	Walls - Concrete Block	1st floor- Teachers Lounge 401	1,384	SF	6	10+ years	
	Work SInk	1st floor- Teachers Lounge 401	1	EA	7	10+ years	
	AC Unit	404	1	EA	7	6-10 years	
	Ceiling - Lay-in	404	111	SF	6	10+ years	
	Doors - Steel Doors incl hw	404	1	EA	6	10+ years	
	Floor - Tile	404	111	SF	6	10+ years	
	Lighting - Lay-in	404	1	EΑ	7	6-10 years	
	Power Distribution	404	4	EA SF	7	10+ years	
	Walls - Concrete Block	404	295	5 F	6	10+ years	



Catego	ry : Room		В	uilding	: Annex	· •	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Conference Room 146 on Plan	113	SF	6	10+ years	
	Doors - Steel Doors incl hw	Conference Room 146 on Plan	1	EA	6	10+ years	
	Floor - Carpet	Conference Room 146 on Plan	113	SF	6	6-10 years	
	Lighting - Pendent/Surface	Conference Room 146 on Plan	1	EA	7	6-10 years	
	Power Distribution	Conference Room 146 on Plan	4	EA	7	10+ years	
	Walls - Concrete Block	Conference Room 146 on Plan	283	SF	6	10+ years	
	Ceiling - Lay-in	Main Office 400	717	SF	6	10+ years	
	Doors - Steel Doors incl hw	Main Office 400	1	EA	6	10+ years	
	Floor - Carpet	Main Office 400	478	SF	6	6-10 years	
	Floor - Tile Main Office 400		239	SF	6	6-10 years	
	Lighting - Lay-in	Main Office 400	7	EA	7	6-10 years	
	Power Distribution	Main Office 400	6	EΑ	7	10+ years	
	Walls - Concrete Block	Main Office 400	963	SF	6	10+ years	
	Ceiling - Lay-in	Parent Resource Room 138 on plan	1,050	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Parent Resource Room 138 on plan	1	EA	6	10+ years	
	Floor - Tile	Parent Resource Room 138 on plan	1,050	SF	6	10+ years	
	Lighting - Lay-in	Parent Resource Room 138 on plan	14	EA	7	6-10 years	
	Power Distribution	Parent Resource Room 138 on plan	22	EA	7	10+ years	
	Walls - Concrete Block	Parent Resource Room 138 on plan	1,350	SF	6	10+ years	
	Work Sink	Parent Resource Room 138 on plan	1	ĒΑ	7	10+ years	
	Ceiling - Lay-in	Resource Copy Room 145	157	SF	6	10+ years	
	Doors - Steel Doors incl hw	Resource Copy Room 145	1	ĒΑ	6	10+ years	
	Floor - Carpet	Resource Copy Room 145	157	SF	6	6-10 years	
	Lighting - Lay-in	Resource Copy Room 145	2	ĒΑ	7	6-10 years	
	Power Distribution	Resource Copy Room 145	6	EΑ	6	10+ years	
	Storage/ Closet	Resource Copy Room 145	8	SF	7	10+ years	
	Walls - Concrete Block	Resource Copy Room 145	450	SF	6	10+ years	
	Traile Control Diock	recourse copy recom the	100	O.	Ü	ioi youlo	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	1,161	SF	6	10+ years	
	Floor - Tile Quarry	1st Floor	1,161	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,180	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,956	SF	6	10+ years	No max occupancy sign
	Doors - Steel Doors incl hw			EA	6	10+ years	, -
	Floor - Tile	ors incl hw 1st Floor 1st Floor		SF	6	10+ years	
	Lighting - Lay-in 1st Floor		1,956 24	EA	7	6-10 years	
	Storage/ Closet	1st Floor	180	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,600	SF	6	10+ years	
_MDF_ID	<u>F</u>						

Campus Name: Dewey Page : 24 of 32 Assessment Date: 10/13/2023



Catego	ry : Room		В	uilding	: Annex	·	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	6	10+ years	
	Finishes	1st Floor	132	SF	7	10+ years	Update to match current observations
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	PTAC
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	27	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	87	SF	7	10+ years	Switch Gear Room 118
	Mechanical/ Service Rooms	1st Floor	40	SF	7	10+ years	Equipment Room 127
	Storage Room	1st Floor	116	SF	7	10+ years	Storage Room 104
	Storage Room	1st Floor	132	SF	7	10+ years	Room 405
	Storage Room	1st Floor	49	SF	7	10+ years	1100111 400
	Storage Room	1st Floor	30	SF	7	10+ years	
	Storage Room	1st Floor	184	SF	7	-	Gym Storage 114
	Vaults	1st Floor	99	SF	7	10+ years	Gym Storage 114
			72	SF		10+ years	
	Storage Room	Exterior Storage Closet	12	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor	47	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	47	SF	6	10+ years	
	Doors - Hardware	1st Floor	1	EA	6	1-2 years	Plate damaged, causing door to stick shut
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	onat
	Floor - Tile Ceramic/ Porcelain	1st Floor	47	SF	6	10+ years	
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	90	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor	47	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	47	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6		
			· · · · · · · · · · · · · · · · · · ·	SF	-	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	47		6	10+ years	
	Lavatory	1st Floor	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	90	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st floor - Main Office	29	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor - Main Office	29	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st floor - Main Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor - Main Office	29	SF	6	10+ years	
	Lavatory	1st floor - Main Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st floor - Main Office	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor - Main Office	92	SF	6	10+ years	
	Water Closet	1st floor - Main Office	1	EA	6	10+ years	
	Accessories	407	30	SF	7	6-10 years	

Campus Name: Dewey Page : 25 of 32 Assessment Date: 10/13/2023



Catego	ry : Room		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	407	30	SF	6	10+ years	
	Doors - Steel Doors incl hw	407	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	407	30	SF	6	10+ years	
	Lighting - Pendent/Surface	407	1	EA	7	6-10 years	
	Walls - Concrete Block	407	98	SF	6	10+ years	
	Water Closet	407	1	EA	7	10+ years	
	Accessories	408	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	408	30	SF	6	10+ years	
	Doors - Steel Doors incl hw	408	1	EA	6	10+ years	
	Floor - Tile	408	30	SF	6	10+ years	
	Lavatory	408	1	EA	7	10+ years	
	Lighting - Pendent/Surface	408	1	EA	7	6-10 years	
	Walls - Concrete Block	408	98	SF	6	10+ years	
	Water Closet	408	1	EA	7	10+ years	
	Accessories	409	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	409	30	SF	6	10+ years	
	Doors - Steel Doors incl hw	409	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	409	30	SF	6	10+ years	
	Lavatory	409	1	EA	7	10+ years	
	Lighting - Pendent/Surface	409	1	EA	7	6-10 years	
	Walls - Concrete Block	409	98	SF	6	10+ years	
	Water Closet	409	1	EA	7	10+ years	
	Accessories	Inside Teacher's Lounge 119	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside Teacher's Lounge 119	25	SF	6	10+ years	
	Doors - Steel Doors incl hw	Inside Teacher's Lounge 119	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside Teacher's Lounge 119	25	SF	6	10+ years	
	Lavatory	Inside Teacher's Lounge 119	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Inside Teacher's Lounge 119	1	EA	7	6-10 years	
	Walls - Concrete Block	Inside Teacher's Lounge 119	80	SF	6	10+ years	
	Water Closet	Inside Teacher's Lounge 119	1	EA	6	10+ years	
	Accessories	Outside Room 404	29	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Outside Room 404	29	SF	6	10+ years	
	Doors - Steel Doors incl hw	Outside Room 404	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Outside Room 404	29	SF	6	10+ years	
	Lavatory	Outside Room 404	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Outside Room 404	1	EA	7	6-10 years	
	Walls - Concrete Block	Outside Room 404	95	SF	6	10+ years	
	Water Closet	Outside Room 404	1	ĒΑ	6	10+ years	
	Accessories	RR Inside 411	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	RR Inside 411	30	SF	7	10+ years	
	Doors - Steel Doors incl hw	RR Inside 411	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	RR Inside 411	30	SF	7	10+ years	
	Lavatory	RR Inside 411	1	EA	7	10+ years	
	Lighting - Pendent/Surface	RR Inside 411	1	EΑ	7	6-10 years	
			•		•	3 .0 ,00.0	



Catego	egory : Room Building : Annex							
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	RR Inside 411	98	SF	7	10+ years		
	Water Closet	RR Inside 411	1	EA	7	10+ years		
	Accessories	RR inside 412	30	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	RR inside 412	30	SF	7	10+ years		
	Doors - Steel Doors incl hw	RR inside 412	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	RR inside 412	30	SF	6	10+ years		
	Lavatory	RR inside 412	1	EA	7	10+ years		
	Lighting - Pendent/Surface	RR inside 412	1	EA	7	6-10 years		
	Walls - Concrete Block	RR inside 412	98	SF	6	10+ years		
	Water Closet RR inside 412		1	EA	7	10+ years		
	Accessories	RR inside 413		SF	7	6-10 years		
	Ceiling - Plaster/Drywall	RR inside 413	30	SF	7	10+ years		
	Doors - Steel Doors incl hw	RR inside 413	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	RR inside 413	30	SF	7	10+ years		
	Lighting - Pendent/Surface	RR inside 413	1	EA	7	6-10 years		
	Walls - Concrete Block	RR inside 413	98	SF	7	10+ years		
	Water Closet	RR inside 413	1	EA	7	10+ years		
	Accessories	Staff RR inside Faculty Lounge 401	45	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Staff RR inside Faculty Lounge 401	45	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	Staff RR inside Faculty Lounge 401	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Staff RR inside Faculty Lounge 401	45	SF	6	10+ years		
	Lavatory	Staff RR inside Faculty Lounge 401	1	EA	6	10+ years		
	Lighting - Pendent/Surface	Staff RR inside Faculty Lounge 401		EA	7	6-10 years		
	Walls - Concrete Block	Staff RR inside Faculty Lounge 401	97	SF	6	10+ years		
	Water Closet	Staff RR inside Faculty Lounge 401	1	EA	6	10+ years		

Category: Classroom **Building: Annex**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	Classroom #407 (Pre School)						
	Casework	1st Floor	25	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	664	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	664	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	15	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor	936	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #408 (Kindergarten)						
	Casework	1st Floor	25	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	608	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	608	SF	6	10+ years	

Campus Name: Dewey Page : 27 of 32 Assessment Date: 10/13/2023



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	936	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #409 (Pre School)						
	Casework	1st Floor	25	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	752	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	737	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	15	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	985	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
	WOR SIIIK	151 11001	ı	LA	,	10+ years	
lassroo	m #411 (Kindergarten)						
	Casework	1st Floor	48	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	600	SF	6	10+ years	Corrected material
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water damage marks
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	608	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #412 (Pre School)						
	Casework	1st Floor	48	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	608	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	608	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	=		
	Work Sink	1st Floor	560 1	SF EA	6 5	10+ years	Motor otuals dripping
	WORK SITIK	ISI FIOOI	ı	EA	5	1-2 years	Water stuck, dripping
lassroo	m #413 (Pre School)						
	Casework	1st Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	608	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	608	SF	6	10+ years	

Campus Name: Dewey Page : 28 of 32 Assessment Date: 10/13/2023



Catego	ry : Classroom		В	uilding	: Annex			
	_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years		
	Storage/ Closet	1st Floor	30	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	560	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		

Building: Annex Category : Interior

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Corridor	· · · · · · · · · · · · · · · · · · ·	Location	Quantity	OCIVI	Italik	Replacement	Comments
Comdon	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor 1st Floor 1st Floor	1,772 16 8	SF SF EA	6 5 6	10+ years 1-2 years 10+ years	Cracking tiles around vent openings
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	Updated quantity and to match current observations
	Floor - Tile/Sheet	1st Floor	1,788	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	30	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,344	SF	6	10+ years	
Safety							
•	Camera Viewing Station	1st Floor	1	EΑ	7	6-10 years	
	Security Cameras	1st Floor	6	EA	1	6-10 years	





Category: Site Building: Site

				uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	East	3,450	SF	6	6-10 years	Verified dimensions
	Surface - Asphalt	East	2,300	SF	4	1-2 years	Alligatoredsurface, disintegrating
							surface
Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	6-10 years	
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	5	0-1 year	Large pothole around manhole. Top
							is sinking.
Fencing							
	Fencing - Chain Link	Entire Site	77	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	324	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	38	LF	4	1-2 years	Damage, posts and rails
	Fencing - Guard Rail	Entire Site	8	LF	7	10+ years	
	Fencing - Iron and Concrete Post	Entire Site	840	LF	6	10+ years	Confirmed that most posts and fence are in fair condition
	Fencing - Iron and Concrete Post	Entire Site	10	LF	4	1-2 years	Cracks at a concrete post, steel post out of alignment, bent fence
	Fencing - New Standard Ornamental	Entire Site	100	LF	6	6-10 years	out of anglimont, bont formed
Landscar	ne.						
Lanacou	Landscape - Grass	Entire Site	4,400	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	200	SF	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	200	SF	5	1-2 years	Area floodsduring heavy rains, and
	·					·	goes through the wall at courtyard. Broken concrete near door 1
	Parkway trees	Entire Site	9	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	500	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	17,250	SF	6	6-10 years	Verified dimension, more asphalt
						·	area given to the east parking lot. Potholes, alligatoredsurface,
							disintegrated surface.
	Play Area - Hardscape- Asphalt	Entire Site	6,566	SF	5	2-5 years	-
	Trash Receptacles	Entire Site	4	EA	6	6-10 years	
Parking L	ot						
	Surface - Asphalt	E Lot	3,000	SF	7	10+ years	Verified dimensions
	Surface - Asphalt	E Lot	7,000	SF	6	6-10 years	
	Surface - Asphalt	E Lot	21,000	SF	4	1-2 years	Potholes, alligatored surface,

Campus Name: Dewey Page : 30 of 32 Assessment Date: 10/13/2023



Catego	ry : Site		В	uilding	: Site		orro o omorrivertoe, omoago, ne oooo
o allogo	.,		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•			•				disintegrated surface. Verified dimension of area used for parking
	Surface - Asphalt	W Lot	6,886	SF	6	6-10 years	
	Surface - Asphalt	W Lot	500	SF	4	1-2 years	Potholes, alligatoredsurface, disintegrated surface
	Surface - Concrete	W Lot	1,000	SF	6	10+ years	G
Playgrou	ınd						
, ,	Equipment - Pre K 3-5	SW	1	EA	6	6-10 years	
	Surface - Poured Surface	SW	1,633	SF	6	6-10 years	
	Surface - Poured Surface	SW	5	SF	4	1-2 years	Tears in the surface volume down
Sidewall	KS						
	Sidewalks - Internal Walks	Entire Site	134	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	10	LF	4	1-2 years	Cracked concrete
	Sidewalks - Perimeter Sidewalks	Entire Site	14,542	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	400	SF	4	1-2 years	Cracked, sunken
Signage							
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	6-10 years	
	Flag Pole - Flag Pole	Entire Site	1	EA	6	6-10 years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	6-10 years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary	1			1			1	I	
			_	Floor Plan	_	Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			1	T			1	T	
Computer Lab	Computer Lab	2nd Floor	203	203	1,088	224	112	N	Υ
Computer Lab	Regular Classroom	1st Floor	104	104	837	201	77	N	N
Library	Regular Classroom	1st Floor	108	108	837	201	97	N	N
Music Room	Regular Classroom	3rd Floor	308	308	857	201	97	N	N
Office	Regular Classroom	1st Floor	103	103	837	201	97	N	N
Regular Classroom	Computer Lab	3rd Floor	310	310	948	238	89	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	837	238	89	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	837	238	89	N	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	837	201	97	N	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	960	135	68	N	Υ
Regular Classroom	Regular Classroom	1st Floor	111	111	960	238	89	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	960	238	89	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	960	238	89	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	837	201	97	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	837	201	97	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	960	238	89	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	960	238	89	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	960	238	89	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	960	150	89	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	857	126	69	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	920	238	89	N	N
Regular Classroom	Regular Classroom	Basement	011	011	898	132	66	N	N
Store Room	Regular Classroom	Basement	B-24	10	1,100	231	115	N	Υ
			*	*	•			•	•
Building : Annex									
Kindergarten	Kindergarten	1st Floor	408	123	608	72	0	N	Υ
Kindergarten	Kindergarten	1st Floor	411	411	608	46	23	N	Υ
Pre School	Kindergarten	1st Floor	409	121	752	72	0	N	N
Pre School	Pre School	1st Floor	407	126	664	72	0	N	N
Pre School	Pre School	1st Floor	412	412	608	46	23	N	Υ
Pre School	Pre School	1st Floor	413	413	608	46	23	N	Υ