



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1895	3	50,060
Campus Total			50,060

Category : Exterior Building : Main

	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	2nd & 3rd Floor Fire Escape Doors	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	2nd & 3rd Floor Fire Escape Doors	2	EA	6	10+ years	
	Exterior Stairs - Stone	2nd & 3rd Floor Fire Escape Doors	6	LF	6	10+ years	Not previously assessed
	Entrance Control - Audio and Video	Door 1 - South	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 1 - South	2	EA	6	10+ years	Changed to match current observations
	Exterior Doors - Side lite	Door 1 - South	2	EA	6	10 Lyone	observations
	Exterior Doors - Side life Exterior Doors - Transom Lite	Door 1 - South	<u>ک</u> ۱	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 1 - South	24	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 1 - South	21	LF	5	10+ years 6-10 years	Not secured to the wall.
	Ramps - Concrete	Door 1 - South	30	LF	6	10+ years	Not secured to the wall.
	Stair Handrail - Steel_Stair Handrail	Door 1 - South	60	LF	5	0-1 year	Not secured to the wall
	Exterior Doors - Exterior Steel Door	Door 10 - East	2	EA	6	6-10 years	Changed to match current
	Exterior Doors - Exterior Steel Door	Door 10 - East	2	LA	O	0-10 years	observations
	Exterior Doors - Exterior Steel Door	Door 11 - Southeast	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 2 - Southwest	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 2 - Southwest	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 3 South	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 4 - Northwest	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 4 - Northwest	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Door 5 - Northwest	1	EA	7	10+ years	Newly replaced
	Exterior Doors - Exterior AMP Door	Door 5 - Northwest	2	EA	6	10+ years	· · · ·
	Exterior Doors - Side lite	Door 5 - Northwest	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 5 - Northwest	4	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		•
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramp Handrail - Steel_Ramp Handrail	Door 5 - Northwest	40	LF	6	10+ years	
	Ramps - Concrete	Door 5 - Northwest	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 6 - Northeast	2	EA	6	10+ years	Changed to match current observations
	Exterior Doors - Side lite	Door 6 - Northeast	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 6 - Northeast	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	Door 6 - Northeast	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 7 - Northeast	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door 7 - Northeast	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 8 - Northeast	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 9 - East north	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 9 - East north	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Roof Access	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Roof Access	3	LF	5	0-1 year	Cracking. Quantity changed to match current observations
Fire Esc							
	Exterior Doors - Exterior Steel Door	East Façade	2	EA	6	10+ years	
	Fire Escape	East Façade	126	LF	6	6-10 years	
	Paints	East Façade	126	LF	5	2-5 years	
Foundati							
	Foundation - Masonry	Entire Building	465	LF	7	10+ years	
	Foundation - Masonry	Entire Building	40	LF	6	10+ years	Spalling. Quantity changed to match current observations
	Superstructure - Heavy Timber	Entire Building	50,060	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	22	EA	6	10+ years	
Roof Sys							
	Access Ladder - Metal	1	1	EA	7	10+ years	
	Coping - Terra Cotta	1	330	LF	5	6-10 years	Corrected Item Type
	Downspouts - Exterior Downspouts	1	120	LF	5	6-10 years	
	Parapet - Parapet > 30"	1	330	LF	6	6-10 years	
	Roof - Modified Bitumen	1	5,180	SF	4	1-2 years	Cracking/open seems
	Roof Hatch - Metal	1	1	EA	5	2-5 years	
	Roof Structure - Heavy Timber	1	5,180	SF	7	10+ years	
	Access Ladder - Metal	2	1	EA	7	10+ years	
	Access Ladder - Metal	2	2	EA	7	10+ years	
	Coping - Terra Cotta	2	160	LF	5	2-5 years	
	Downspouts - Exterior Downspouts Parapet - 16" - 30" Height	2 2	100	LF LF	5 6	6-10 years 2-5 years	
			160				



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	2	2,800	SF	4	1-2 years	Cracking/open seems
	Roof Hatch - Metal	2	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	2	2,800	SF	7	10+ years	
	Access Ladder - Metal	3	2	EA	7	10+ years	
	Coping - Clay Tile	3	160	LF	5	2-5 years	
	Downspouts - Exterior Downspouts	3	100	LF	5	6-10 years	
	Parapet - 16" - 30" Height	3	160	LF	5	6-10 years	
	Roof - Modified Bitumen	3	2,800	SF	4	0-1 year	Cracking/open seems
	Roof Hatch - Metal	3	1	ĒΑ	7	10+ years	3.1
	Roof Structure - Heavy Timber	3	2,800	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	4	80	LF	6	10+ years	
	Liner	•	33		·	ioi youlo	
	Chimney - Brick Chimney- Concrete/ Mortar	4	16	LF	4	1-2 years	Cracking/open joints
	Liner	•	10	<u>-</u> 1	7	i 2 yours	oraciding/open jointo
	Chimney - Metal Flue	4	32	LF	6	6-10 years	
	Coping - Clay Tile	4	292	LF	5	6-10 years	
	Downspouts - Exterior Downspouts	4	45	LF	5	6-10 years	
	Parapet - 16" - 30" Height	4	292	LF	5	•	
	Roof - Modified Bitumen	4	3,225	SF	4	2-5 years 1-2 years	Cracking/onen ecomo/bubbling
		4	3,225	SF SF	7		Cracking/open seems/bubbling.
	Roof Structure - Heavy Timber	5		SF LF		10+ years	Dueted
	Coping - Metal		19	LF LF	5	0-1 year	Rusted
	Downspouts - Exterior Downspouts	5	30		6	6-10 years	0
	Roof - Metal	5	61	SF	4	0-1 year	Open joints
	Roof Structure - Heavy Timber	5	61	SF	7	10+ years	
	Coping - Stone	6	32	LF	6	10+ years	
	Downspouts - Exterior Downspouts	6	30	LF	6	10+ years	
	Parapet - 16" - 30" Height	6	32	LF	6	10+ years	Changed to match current observations
	Roof - Modified Bitumen	6	145	SF	4	1-2 years	Cracking
	Roof Structure - Heavy Timber	6	145	SF	7	10+ years	3
	Coping - Stone	7	55	LF	5	10+ years	
	Downspouts - Exterior Downspouts	7	15	LF	6	10+ years	
	Parapet - 16" - 30" Height	7	33	LF	5	2-5 years	
	Parapet - Parapet < 16" Height	7	11	LF	5	2-5 years	
	Parapet - Parapet > 30"	7	11	LF	5	2-5 years	
	Roof - Metal	7	365	SF	5	1-2 years	Open joints
	Roof Structure - Heavy Timber	7	365	SF	7	10+ years	Open joints
	Roof Structure - Heavy Timber	1	303	SI	,	10+ years	
Valls	O i Milbir	F & D 3 P	4.000			40	
	Cornice - Metal Projecting	Entire Building	1,260	LF	6	10+ years	
	Cornice - Terra Cotta	Entire Building	154	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	25,300	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	500	SF	4	0-1 year	Cracking/open joints
	Exterior Walls - Stone-Cast	Entire Building	132	SF	4	1-2 years	Spalling/chipping



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Stone-Cut	Entire Building	4,920	SF	4	0-1 year	Spalling/chipping
Windows							
	Guard - Guards perforated	Entire Building	1,690	SF	6	10+ years	
	Lintels - Brick	Entire Building	82	LF	6	10+ years	
	Lintels - Steel	Entire Building	105	LF	6	10+ years	
	Lintels - Stone	Entire Building	315	LF	5	0-1 year	Spalling/chipping
	Lintels - Terra Cotta	Entire Building	240	LF	6	10+ years	-F
	Skylite - Glass Single-Pane	Entire Building	49	SF	6	2-5 years	Added to match current observations
	Skylite - Glass Single-Pane	Entire Building	40	SF	5	0-1 year	Cracking/leaking water
	Windows - Louver	Entire Building	6	SF	7	10+ years	Not previously assessed
	Windows - Sash Aluminum Double-pane	Entire Building	5,820	SF	6	6-10 years	Not previously assessed
		· ·	_			•	
Catego	ry : Electrical		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	cy System						
Lineigen	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	50,060	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	50,060	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	26	EA	6	6-10 years	
	Exit Signs - Comdors and Stairs Exit Signs - Gym	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	4	EA	6	6-10 years	
					_		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	26	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	8	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	7,581	SF	6	6-10 years	
	Stairs	Zittiro Ballaling	7,001	O.	Ü	o to youro	
	Emergency A/C Power - Gym	Entire Building	2,650	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,782	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose	Entire Building	490	SF	6	6-10 years	
	Room	g				5 . 5 , 5	
_Main Ser	vice						
Widin Oct	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	
	emergency power PA System	M : 0"	50,060	SF	_	0-1 year	Needs service. Making a rumbling
		Main Office	EU UEU	C.L	5	() 1 voor	Noode contico Making a rumbling



Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	22	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	6	6-10 years	
	amp	· ·				•	
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	6-10 years	
	amp	G				•	
`ataga	ry : Fire Protection		D	uilding	· Main		
aiego	ry . File Frotection		D	unung	. IVIAIII	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m		·			-	
	Fire ALarm Anunciator	Entire Building	2	EA	7	6-10 years	
	Fire Alarm Panel	Entire Building	1	EΑ	7	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	50,060	SF	6	10+ years	
	Fire Alarm_System	Entire Building	50,060	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
	The Fullip Controller	Entire Ballating	·	_, 、	Ü	Tot youro	
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Fire Pump Room	1	EA	6	6-10 years	
	Jockey Pump	Fire Pump Room	1	EA	6	6-10 years	
Sprinklou	r System						
phinkei	Combination Wet and Dry Sprinkler System	Entire Building	50,060	SF	6	6-10 years	
	Sprinkler Heads	Entire Building	50,060	SF	7	10+ years	
	Sprinkler Piping	Entire Building	50,060	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	50,060	SF	6	6-10 years	
	wet opinikier dystern	Little building	30,000	OI.	U	0-10 years	
atego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
		Location	Quantity	OOW	IVALIK	Replacement	Comments
air Cono	litioning Chamical Pet Fooder	Doof		EA	6	2 E voors	Minor correction, covered in the min
	Chemical Pot Feeder	Roof	1	ĽΑ	6	2-5 years	Minor corrosion, covered in chemic residue.
	Chiller-Air Cooled-Screw Type-Roof	Roof	1	EA	7	10+ years	New chiller installed.
	Mounted - 201 - 300 tons	1.001	'		,	TOT years	110W Offinior installed.
	Glycol Feed	Roof	1	EA	6	6-10 years	Glycol manually fed directly into po
	Giyeoi i eeu	NOOI	ı	LA	O	U-10 years	feeder
	Pipes - Dual Temperature Pipe- Galvanized	Roof	400	LF	6	6-10 years	ICCUCI
	Pressure Fill System	Roof	400	EA	6	6-10 years	Glycol feeds in the chiller directly



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	through dual temperature pumps Currently not operable. Work order in for repair. No asset visible.
Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric	2nd Floor	1	EA	6	6-10 years	Computer lab. No visible asset tag.
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Attic	1	EA	6	6-10 years	Compater last the violate accesting.
	Fan Coil Unit- Floor Mounted - Hot Water and Chilled Water	Entire Building	55	EA	6	10+ years	Combined total.
	Air Handling Unit- Package Multi Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	3	1-2 years	Rusty piping
	Chemical Pot Feeder	Boiler Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	Two combustion dampers visible upon observation. No visible asset tag
	Non Condensing- Scotch Marine- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	3	1-2 years	Shell casing rusty.
	Piping - Dual Temperature Pipes- Steel	Boiler Room	400	LF	6	6-10 years	
	Water Fill System	Boiler Room	1	EA	6	6-10 years	
Gas Boo	ster						
	Gas Booster	Boiler Room	2	EA	6	6-10 years	
Heating							
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	Per engineer, two electric unit heater in the building total
	Unit Heater - Hot Water	Entire Building	3	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	7	EA	6	6-10 years	
	Fin Tube - Hot Water	Entire Building	24	LF	6	6-10 years	
	Fin Tube - Hot Water	Entire Building	100	LF	6	6-10 years	
Mechani	cal Plumbing						
	Chilled Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Chilled Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Dual Temperature Pump - Less than 10	Boiler Room	1	EΑ	6	6-10 years	
	Dual Temperature Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	



	w. Machanical		В	الم ما أمانا	. Main		337 3 Fauillia 3 TREET, Chicago, IL 60009
Catego	ry : Mechanical		ь	uilding	: wam	Decemmend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Hot Water Pump - Less than 10	Boiler Room	Quantity 1	EA	6	6-10 years	Comments
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	600	LF	6	10+ years	
	Hydronic Supply and Return - Copper	Entire Building	600	LF	O	10+ years	
Tempera	ature Control						
	DDC System	Entire Building	50,060	SF	6	10+ years	
	Electric Thermostat	Entire Building	3	EA	6	6-10 years	
		Ü				,	
Ventilation							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof and Basement	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof and Basement	5	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Roof and Basement	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Itam Tuna	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity	UOW	Kank	Replacement	Comments
Hot Wate							
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	6	6-10 years	
Piping							
1 0	Domestic Piping-Hot Water Return Lines	Entire Building	50,060	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	50,060	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	50,060	SF	6	6-10 years	
	(Horizontal Lines)	3	,			, , , , , , , , , , , , , , , , , , , ,	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	50,060	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	50,060	SF	6	6-10 years	
	(from Risers to Fixtures)	Entire Duilding	F0.000	C.E.	_	C 40	
	Sanitary Piping	Entire Building	50,060	SF	6	6-10 years	
	Storm Piping	Entire Building	50,060	SF	6	6-10 years	
	Vent Piping	Entire Building	50,060	SF	6	6-10 years	
Pumps							
-	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Basement	2	EA	6	6-10 years	
	Pumps - Sump-Duplex	Basement	2	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	
						•	



Catego	ry : Room		В	uilding	: Main		
		•	0	11014		Recommend	•
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	Ceiling - Plaster/Drywall	103 B	113	SF	7	10+ years	
	Doors - Wood Doors inclu hw	103 B	1	EA	7	10+ years	
	Floor - Carpet	103 B	113	SF	6	6-10 years	
	Lighting - Pendent/Surface	103 B	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	103 B	1	EA	5	6-10 years	Missing cover
	Walls - Plaster/Drywall	103 B	551	SF	7	10+ years	
	Work SInk	103 B	1	EA	7	10+ years	
	Ceiling - Lay-in	106 Main Office	428	SF	7	10+ years	
	Doors - Transom Window	106 Main Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	106 Main Office	1	EA	7	10+ years	
	Floor - Carpet	106 Main Office	300	SF	7	6-10 years	
	Floor - Wood	106 Main Office	128	SF	7	10+ years	
	Lighting - Lay-in	106 Main Office	9	ĒΑ	7	6-10 years	
	Power Distribution	106 Main Office	8	EA	7	10+ years	
	Storage/ Closet	106 Main Office	7	SF	7	10+ years	
	Walls - Plaster/Drywall	106 Main Office	880	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd floor Office 201D- Next to	45	SF	7	10+ years	
	coming industry trans	Elevator		О.	-	,	
	Ceiling - Plaster/Drywall	2nd floor Office 201D- Next to	5	SF	6	10+ years	
	Coming Tractor, 21, Wan	Elevator	Ü	O.	Ū	ioi youro	
	Doors - Wood Doors inclu hw	2nd floor Office 201D- Next to	1	EA	7	10+ years	
	20010 11000 20010 111010 1111	Elevator	•		•	,	
	Floor - Tile/Sheet	2nd floor Office 201D- Next to	50	SF	7	10+ years	
	11001 1110,011001	Elevator	00	O.	•	ioi youro	
	Lighting - Pendent/Surface	2nd floor Office 201D- Next to	1	EA	7	6-10 years	
	Lighting Tondon Canada	Elevator	•	-/ \	•	o io jouio	
	Walls - Plaster/Drywall	2nd floor Office 201D- Next to	366	SF	7	10+ years	
	Wallo Tidotol/BryWall	Elevator	000	O.	•	101 youro	
	Walls - Plaster/Drywall	2nd floor Office 201D- Next to	5	SF	6	10+ years	
	Walls Flaster/DryWall	Elevator	9	Oi.	O	101 years	
	Ceiling - Plaster/Drywall	3rd floor Office 301D - Next to	50	SF	6	10+ years	
	Celling - Flaster/Drywall	Elevator	30	Oi	U	10+ years	
	Doors - Wood Doors inclu hw	3rd floor Office 301D - Next to	1	EA	7	10+ years	
	Doors - Wood Doors Incid IIW	Elevator	'	LA	'	10+ years	
	Floor - Tile/Sheet	3rd floor Office 301D - Next to	50	SF	7	6-10 years	
	Floor - Tile/Sileet	Elevator	50	SF	,	0-10 years	
	Lighting - Pendent/Surface	3rd floor Office 301D - Next to	1	EA	7	6-10 years	
	Lighting - Perident/Surface	Elevator	1	LA	,	0-10 years	
	Walls - Plaster/Drywall		274	℃ ⊏	7	101.40000	
	vvalis - Plastei/Drywali	3rd floor Office 301D - Next to	371	SF	7	10+ years	
	Coiling Lavin	Elevator	4 5 4	٥r	7	101.110000	
	Ceiling - Lay-in	Assistant Principals office in 106	154	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principals office in 106	2	EA	7	10+ years	
	Floor - Carpet	Assistant Principals office in 106	154	SF	7	6-10 years	



Category : Room			Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Lay-in	Assistant Principals office in 106	2	EA	7	6-10 years				
	Power Distribution	Assistant Principals office in 106	4	EA	7	10+ years				
	Walls - Plaster/Drywall	Assistant Principals office in 106	612	SF	7	10+ years				
	Ceiling - Lay-in	Basement - Engineer's Office	168	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Basement - Engineer's Office	1	EA	7	10+ years				
	Floor - Epoxy/ Painted	Basement - Engineer's Office	168	SF	7	10+ years				
	Lighting - Lay-in	Basement - Engineer's Office	2	EA	7	10+ years				
	Power Distribution	Basement - Engineer's Office	6	EA	7	10+ years				
	Walls - Masonry	Basement - Engineer's Office	110	SF	7	10+ years				
	Walls - Plaster/Drywall	Basement - Engineer's Office	217	SF	7	10+ years				
	Ceiling - Lay-in	Basement B-31 Teachers Lounge	565	SF	7	10+ years				
	Doors - Steel Doors incl hw	Basement B-31 Teachers Lounge	1	EA	7	10+ years				
	Doors - Wood Doors inclu hw	Basement B-31 Teachers Lounge	2	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	Basement B-31 Teachers Lounge	565	SF	7	10+ years				
	Lighting - Lay-in	Basement B-31 Teachers Lounge	11	EA	7	10+ years				
	Power Distribution	Basement B-31 Teachers Lounge	6	EA	7	10+ years				
	Storage/ Closet	Basement B-31 Teachers Lounge	40	SF	7	10+ years				
	Walls - Plaster/Drywall	Basement B-31 Teachers Lounge	1,070	SF	7	10+ years				
	Work SInk	Basement B-31 Teachers Lounge	1	EA	7	10+ years				
	Ceiling - Lay-in	Counselors office in Basement	184	SF	7	10+ years				
	Ceiling - Lay-in	Counselors office in Basement	4	SF	5	1-2 years	Water damaged			
	Doors - Wood Doors inclu hw	Counselors office in Basement	1	EA	7	10+ years				
	Floor - Carpet	Counselors office in Basement	188	SF	7	6-10 years				
	Lighting - Lay-in	Counselors office in Basement	4	EA	7	10+ years				
	Power Distribution	Counselors office in Basement	8	EA	7	10+ years				
	Walls - Plaster/Drywall	Counselors office in Basement	412	SF	7	10+ years				
	Ceiling - Plaster/Drywall	Gymnasium Office (Storage)	178	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Gymnasium Office (Storage)	1	EA	7	10+ years				
	Floor - Tile	Gymnasium Office (Storage)	178	SF	6	10+ years	Corrected item type			
	Lighting - Pendent/Surface	Gymnasium Office (Storage)	4	EA	7	6-10 years				
	Walls - Plaster/Drywall	Gymnasium Office (Storage)	350	SF	7	10+ years				
	Ceiling - Lay-in	Kitchen Manager	71	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Kitchen Manager	1	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	Kitchen Manager	56	SF	7	10+ years				
	Floor - Epoxy/ Painted	Kitchen Manager	15	SF	7	10+ years				
	Lighting - Lay-in	Kitchen Manager	2	EA	7	10+ years				
	Power Distribution	Kitchen Manager	8	EA	7	10+ years				
	Walls - Plaster/Drywall	Kitchen Manager	226	SF	7	10+ years				
	Ceiling - Lay-in	Principals Office inside 106	150	SF	7	10+ years				
	Ceiling - Lay-in	Principals Office inside 106	4	SF	4	0-1 year				
	Doors - Wood Doors inclu hw	Principals Office inside 106	1	EA	7	10+ years				
	Floor - Carpet	Principals Office inside 106	154	SF	7	6-10 years				
	Lighting - Lay-in	Principals Office inside 106	2	EA	7	6-10 years				
	Power Distribution	Principals Office inside 106	4	EA	7	10+ years				
		•				•				

Campus Name: Evergreen Page : 9 of 24 Assessment Date: 12/11/2023



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Principals Office inside 106	562	SF	7	10+ years	
Gymnasi	ia						
 	Ceiling - Plaster/Drywall	3rd Floor	2,650	SF	6	2-5 years	
	Doors - Side-lite	3rd Floor	36	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	24	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	6-10 years	
	Floor - Wood	3rd Floor	2,650	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	Changed Item type. Qty changed-lights observed
	Walls - Plaster/Drywall	3rd Floor	3,195	SF	6	6-10 years	lights observed
Kitchen							
	Ceiling - Lay-in	Basement	620	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	7	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	620	SF	7	10+ years	
	Lighting - Lay-in	Basement	15	EA	7	10+ years	
	Serving Line	Basement	26	LF	7	10+ years	
	Storage/ Closet	Basement	167	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	692	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	Lunchroom-A	1,120	SF	7	10+ years	
	Doors - Steel Doors incl hw	Lunchroom-A	1	EA	7	10+ years	
	Doors - Transom Window	Lunchroom-A	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Lunchroom-A	5	EA	7	10+ years	
	Floor - Epoxy/ Painted	Lunchroom-A	1,120	SF	7	10+ years	
	Lighting - Lay-in	Lunchroom-A	19	EA	7	10+ years	
	Walls - Plaster/Drywall	Lunchroom-A	1,096	SF	7	10+ years	
	Ceiling - Lay-in	Lunchroom-B	662	SF	7	10+ years	
	Doors - Steel Doors incl hw	Lunchroom-B	1	EA	7	10+ years	
	Doors - Transom Window	Lunchroom-B	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Lunchroom-B	3	ĒΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Lunchroom-B	637	SF	7	10+ years	
	Lighting - Lay-in	Lunchroom-B	12	EA	7	10+ years	
	Walls - Plaster/Drywall	Lunchroom-B	863	SF	7	10+ years	
	Ceiling - Lay-in	Multipurpose	490	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Multipurpose	5	EA	7	10+ years	
	Floor - Epoxy/ Painted	Multipurpose	490	SF	7	10+ years	Condition based on current observation
	Lighting - Lay-in	Multipurpose	15	EA	7	10+ years	ODSELVATION
	Market Board	Multipurpose	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	Multipurpose	686	SF	7	10+ years	
	vvalis - Flastel/DlyWall	wuiiipui pose	000	SF	1	TUT years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
MDE ID	-						
MDF_ID	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	311	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	Ductless split system
	Other Cooling Offic	151 11001	1	LA	,	0-10 years	Ductiess split system
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	24	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	12	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	36	SF	7	10+ years	
	Janitor's Closet	2nd Floor	26	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	12	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	27	SF	7	10+ years	
	Janitor's Closet	3rd Floor	20	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	35	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	12	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	24	SF	7	10+ years	
	Boiler Room	Basement	1,090	SF	7	10+ years	
	Boiler Room	Basement	150	SF	7	10+ years	
	Janitor's Closet	Basement	53	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	225	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,750	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	492	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	165	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	80	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	20	SF	5	10+ years	
	Storage Room	Basement	870	SF	7	10+ years	
	Storage Room	Basement	490	SF	7	10+ years	
_							
Restroor	n Accessories	Basement	215	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	215	SF	7	•	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
			=	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain Floor Drain	Basement	215	SF EA	7	10+ years	
		Basement	1		=	10+ years	
	Hand Dryer	Basement	2	EA EA	7	6-10 years	
	Lavatory	Basement	2 4		7	10+ years	
	Lighting - Pendent/Surface	Basement		EΑ	7	10+ years	
	Partitions	Basement	5	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement	177	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	423	SF	7	10+ years	
	Water Closet	Basement	5	EA	7	10+ years	
	Accessories	Basement	248	SF	7	6-10 years	



Category : Room			Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	Basement	248	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Basement	248	SF	7	10+ years			
	Floor Drain	Basement	1	EA	7	10+ years			
	Hand Dryer	Basement	2	EA	7	6-10 years			
	Lavatory	Basement	2	EA	7	10+ years			
	Lighting - Pendent/Surface	Basement	3	EA	7	10+ years			
	Partitions	Basement	1	EA	7	10+ years			
	Urinals	Basement	5	EA	7	10+ years			
	Walls - Plaster/Drywall	Basement	270	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement	555	SF	7	10+ years			
	Water Closet	Basement November 199	1	EA	7	10+ years			
	Accessories	Boys - Next to room 108	140	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Boys - Next to room 108	140	SF	7	10+ years			
	Doors - Transom Window	Boys - Next to room 108	6 1	SF EA	7	10+ years			
	Doors - Wood Doors inclu hw	Boys - Next to room 108		SF	7 7	10+ years			
	Floor - Tile Ceramic/ Porcelain Floor Drain	Boys - Next to room 108 Boys - Next to room 108	140	Sr EA	7	10+ years			
	Hand Dryer	Boys - Next to room 108	1 2	EA EA	7	10+ years			
	Lavatory	Boys - Next to room 108	2	EA	7	6-10 years 10+ years			
	Lighting - Pendent/Surface	Boys - Next to room 108	4	EA	7	10+ years			
	Partitions	Boys - Next to room 108	1	EA	7	10+ years			
	Urinals	Boys - Next to room 108	2	EA	7	10+ years			
	Walls - Plaster/Drywall	Boys - Next to room 108	297	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Boys - Next to room 108	295	SF	7	10+ years			
	Water Closet	Boys - Next to room 108	1	EA	7	10+ years			
	Accessories	Boys - Next to room 208	195	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Boys - Next to room 208	190	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Boys - Next to room 208	5	SF	6	10+ years	Chipping paint		
	Doors - Wood Doors inclu hw	Boys - Next to room 208	1	ĒΑ	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Boys - Next to room 208	195	SF	7	6-10 years			
	Floor Drain	Boys - Next to room 208	1	EA	7	10+ years			
	Hand Dryer	Boys - Next to room 208	2	EA	7	10+ years			
	Lavatory	Boys - Next to room 208	2	EA	7	10+ years			
	Lighting - Pendent/Surface	Boys - Next to room 208	5	EA	7	6-10 years			
	Partitions	Boys - Next to room 208	1	EA	7	10+ years			
	Urinals	Boys - Next to room 208	5	EA	7	10+ years			
	Walls - Plaster/Drywall	Boys - Next to room 208	348	SF	6	2-5 years			
	Walls - Tile Ceramic/ Porcelain	Boys - Next to room 208	348	SF	7	10+ years			
	Water Closet	Boys - Next to room 208	1	EA	7	10+ years			
	Accessories	Boys - Next to room 308	195	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Boys - Next to room 308	195	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Boys - Next to room 308	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Boys - Next to room 308	195	SF	7	6-10 years			

Campus Name: Evergreen Page : 12 of 24 Assessment Date: 12/11/2023



Category : Room			Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor Drain	Boys - Next to room 308	1	EA	7	10+ years			
	Hand Dryer	Boys - Next to room 308	2	EA	7	10+ years			
	Lavatory	Boys - Next to room 308	2	EA	7	10+ years			
	Lighting - Pendent/Surface	Boys - Next to room 308	5	EA	7	6-10 years	Good condition		
	Partitions	Boys - Next to room 308	1	EA	7	10+ years			
	Urinals	Boys - Next to room 308	5	EA	7	10+ years			
	Walls - Plaster/Drywall	Boys - Next to room 308	348	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Boys - Next to room 308	348	SF	7	10+ years			
	Water Closet	Boys - Next to room 308	1	EA	7	10+ years			
	Accessories	Girls - Next to room 104	228	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Girls - Next to room 104	228	SF	7	10+ years			
	Doors - Transom Window	Girls - Next to room 104	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Girls - Next to room 104	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Girls - Next to room 104	228	SF	7	10+ years			
	Floor Drain	Girls - Next to room 104	1	EA	7	10+ years			
	Lavatory	Girls - Next to room 104	2	EA	7	10+ years			
	Lighting - Pendent/Surface	Girls - Next to room 104	6	EA	7	10+ years			
	Partitions	Girls - Next to room 104	3	EA	7	10+ years			
	Walls - Plaster/Drywall	Girls - Next to room 104	368	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Girls - Next to room 104	368	SF	7	10+ years			
	Water Closet	Girls - Next to room 104	3	EA	7	10+ years			
	Accessories	Girls - Next to room 202	228	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Girls - Next to room 202	220	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Girls - Next to room 202	8	SF	5	10+ years	Water damage		
	Doors - Wood Doors inclu hw	Girls - Next to room 202	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Girls - Next to room 202	228	SF	7	10+ years			
	Floor Drain	Girls - Next to room 202	1	EA	7	10+ years			
	Hand Dryer	Girls - Next to room 202	2	EA	7	6-10 years			
	Lavatory	Girls - Next to room 202	2	EA	7	10+ years			
	Lighting - Pendent/Surface	Girls - Next to room 202	6	EA	7	10+ years			
	Partitions	Girls - Next to room 202	5	EA	7	10+ years			
	Walls - Plaster/Drywall	Girls - Next to room 202	368	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Girls - Next to room 202	368	SF	7	10+ years			
	Water Closet	Girls - Next to room 202	5	EA	7	10+ years			
	Accessories	Girls - Next to room 302	228	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Girls - Next to room 302	228	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Girls - Next to room 302	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Girls - Next to room 302	228	SF	7	6-10 years			
	Floor Drain	Girls - Next to room 302	1	EA	7	10+ years			
	Hand Dryer	Girls - Next to room 302	2	EA	7	10+ years			
	Lavatory	Girls - Next to room 302	2	EA	7	10+ years			
	Lighting - Pendent/Surface	Girls - Next to room 302	6		7	6-10 years	Qty updated 6 fixtures observed		
	Partitions	Girls - Next to room 302	4	EA		10+ years			
	Walls - Plaster/Drywall	Girls - Next to room 302	368	SF	7	10+ years			
	Lighting - Pendent/Surface Partitions	Girls - Next to room 302 Girls - Next to room 302	6 4	EA	7 7	6-10 years 10+ years	Qty upd		

Campus Name: Evergreen Page : 13 of 24 Assessment Date: 12/11/2023



Category : Room			Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Tile Ceramic/ Porcelain	Girls - Next to room 302	368	SF	7	10+ years		
	Water Closet	Girls - Next to room 302	4	EA	7	10+ years		
	Accessories	Inside Kitchen	35	SF	7	6-10 years		
	Ceiling - Lay-in	Inside Kitchen	35	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Inside Kitchen	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Inside Kitchen	35	SF	7	10+ years		
	Floor Drain	Inside Kitchen	1	EA	7	10+ years		
	Lavatory	Inside Kitchen	1	EA	7	10+ years		
	Lighting - Lay-in	Inside Kitchen	1	EA	7	10+ years		
	Walls - Plaster/Drywall	Inside Kitchen	25	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Inside Kitchen	113	SF	7	10+ years		
	Water Closet	Inside Kitchen	1	EA	7	10+ years		
	Accessories	Inside Main Office	35	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Inside Main Office	35	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Inside Main Office	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Inside Main Office	35	SF	7	10+ years		
	Floor Drain	Inside Main Office	1	EA	7	10+ years		
	Lavatory	Inside Main Office	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Inside Main Office	1	EA	7	10+ years		
	Walls - Plaster/Drywall	Inside Main Office	150	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Inside Main Office	150	SF	7	10+ years		
	Water Closet	Inside Main Office	1	EΑ	7	10+ years		
	Accessories	Mens in teachers Lounge	55	SF	7	6-10 years		
	Ceiling - Lay-in	Mens in teachers Lounge	55	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Mens in teachers Lounge	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Mens in teachers Lounge	55	SF	7	10+ years		
	Floor Drain	Mens in teachers Lounge	1	EA	7	10+ years		
	Lavatory	Mens in teachers Lounge	1	EA	7	10+ years		
	Lighting - Lay-in	Mens in teachers Lounge	1	EA	7	10+ years		
	Walls - Plaster/Drywall	Mens in teachers Lounge	62	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Mens in teachers Lounge	166	SF	7	10+ years		
	Water Closet	Mens in teachers Lounge	1	EA	7	10+ years		
	Accessories	Unisex bathroom	48	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Unisex bathroom	48	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Unisex bathroom	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Unisex bathroom	48	SF	7	10+ years		
	Floor Drain	Unisex bathroom	1	EA	7	10+ years		
	Lavatory	Unisex bathroom	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Unisex bathroom	1	EA	7	10+ years		
	Walls - Plaster/Drywall	Unisex bathroom	120	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Unisex bathroom	120	SF	7	10+ years		
	Water Closet	Unisex bathroom	_1	EA	7	10+ years		
	Accessories	Womens in Teachers Lounge	75	SF	7	6-10 years		
	Ceiling - Lay-in	Womens in Teachers Lounge	75	SF	7	10+ years		

Campus Name: Evergreen Page : 14 of 24 Assessment Date: 12/11/2023



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Womens in Teachers Lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Womens in Teachers Lounge	75	SF	7	10+ years	
	Floor Drain	Womens in Teachers Lounge	1	EA	7	10+ years	
	Lavatory	Womens in Teachers Lounge	1	EA	7	10+ years	
	Lighting - Lay-in	Womens in Teachers Lounge	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Womens in Teachers Lounge	70	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Womens in Teachers Lounge	190	SF	7	10+ years	
	Water Closet	Womens in Teachers Lounge	1	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	705	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	705	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,260	SF	7	10+ years	
Classroo	om #102 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	705	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	705	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,290	SF	7	10+ years	
Classro	om #103/105 Steam L (Laboratory/Shop)					•	
VIGSSIUL	Casework	1st Floor	60	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,622	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	1,622	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	36	EA	7	10+ years	
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,203	SF	7	10+ years	
Classroo	om #104 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	790	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	200.0 Handom Window	10(1100)	10	٥.	•	.o. youro	

Campus Name: Evergreen Page : 15 of 24 Assessment Date: 12/11/2023



Catego	ry : Classroom		В	uilding	: Main		, 3,
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	790	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,290	SF	7	10+ years	
Classroo	om #107 (Computer Lab)						
	Casework	1st Floor	7	LF	7	10+ years	New
	Ceiling - Plaster/Drywall	1st Floor	705	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	705	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,290	SF	7	10+ years	
			.,200	.	·	.o. you.o	
_Classroo	om #108 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	705	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	705	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,260	SF	7	10+ years	
_Classroo	om #201 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	695	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	Loose paint
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	702	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	3	SF	4	0-1 year	Open joints
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	opon journo
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,240	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	6	10+ years	Loose paint
	·		20	٥.	Ü	. o . youro	
Classroo	om #202 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	695	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	Loose paint
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	



	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	2nd Floor	705	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,285	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	6	10+ years	Loose paint
Classroo	m #203 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	6	10+ years	Cracks
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	Craoko
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	790	SF	7	6-10 years	
		2nd Floor	18	EA	7	•	
	Lighting - Pendent/Surface		_			6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,301	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	6	10+ years	Minor cracks
Classroo	m #204 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	790	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	18	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,321	SF	7	10+ years	
Classroo	m #205 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw		10	SF EA	7	10+ years 10+ years	
	Floor - Tile/Sheet	2nd Floor 2nd Floor		SF			
			790	_	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,321	SF	7	10+ years	
Classroo	m #206 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	peeling paint
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	790	SF	5	2-5 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,311	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	
Classroo	om #207 (Science Classroom)						
	Casework	2nd Floor	17	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	705	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet		· · · · · · · · · · · · · · · · · · ·	SF			
		2nd Floor	705		7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EΑ	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	226	SF	5	2-5 years	
	Walls - Plaster/Drywall	2nd Floor	1,290	SF	7	10+ years	
	Work Sink	2nd Floor	4	EA	7	10+ years	4 fixtures observed 3 in class and in storage closet
Classroc	om #208 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	705	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	705	SF	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
				SF	7	,	
	Walls - Plaster/Drywall	2nd Floor	1,250			6-10 years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	
Classroc	om #301 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	695	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	10+ years	Water staining
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	•
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	705	SF	7	6-10 years	Good condition
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	2004 CONTAINON
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,260	SF	7	10+ years	
Classroc	om #302 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	705	SF	7	10+ years	
	,			SF SF			
	Doors - Transom Window	3rd Floor	10	2F	7	10+ years	



Category : Classroom		В	uilding	: Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	705	SF	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,280	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	10	SF	6	10+ years		
Classroo	om #304 (Music Room)							
	Ceiling - Plaster/Drywall	3rd Floor	790	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years		
	Floor - Carpet	3rd Floor	790	SF	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,321	SF	7	10+ years		
	Walls - 1 laster/Drywall	310 1 1001	1,321	OI.	,	10+ years		
Classroc	om #306 (Other Instructional Use)	0.15						
	Casework	3rd Floor	3	LF	7	6-10 years	Not previously assessed	
	Ceiling - Plaster/Drywall	3rd Floor	790	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	790	SF	5	2-5 years		
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,321	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classroo	om #307 (Regular Classroom)							
	Ceiling - Plaster/Drywall	3rd Floor	705	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	705	SF	5	2-5 years		
	Lighting - Pendent/Surface	3rd Floor	15	ĒΑ	7	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,280	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	10	SF	6	10+ years	Chipping paint	
Classroo	om #308 (Regular Classroom)							
VICUSION	Ceiling - Plaster/Drywall	3rd Floor	695	SF	7	10+ years		
				SF SF		•		
	Ceiling - Plaster/Drywall	3rd Floor	10		6	10+ years		
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	705	SF	5	2-5 years		



Category : Classroom				Building : Main				
			Recommend					
Location	Quantity	UOM	Rank	Replacement	Comments			
Surface 3rd Floor	15	EA	7	6-10 years				
3rd Floor	16	LF	7	6-10 years				
vall 3rd Floor	1,260	SF	7	10+ years				
	Surface 3rd Floor 3rd Floor	LocationQuantitySurface3rd Floor153rd Floor16	LocationQuantityUOMSurface3rd Floor15EA3rd Floor16LF	LocationQuantityUOMRankSurface3rd Floor15EA73rd Floor16LF7	Recommend Location Quantity UOM Rank Replacement Surface 3rd Floor 15 EA 7 6-10 years 3rd Floor 16 LF 7 6-10 years			

Category: Interior Building: Main

tegui	y . IIILEITOI			unung	. Iviaiii		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
rridor							
	Ceiling - Plaster/Drywall	1st Floor	1,735	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Doors - Transom Window	1st Floor	140	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EA	7	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor	2	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	4	EA	7	6-10 years	Corrected type and quantity
	Floor - Wood	1st Floor	1,715	SF	6	6-10 years	
	Floor - Wood	1st Floor	20	SF	5	1-2 years	Damaged areas
	Lighting - Pendent/Surface	1st Floor	32	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	32	EA	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	192	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,465	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,735	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	140	SF	6	6-10 years	
	Doors - Wood Doors include hw	2nd Floor	4	EA	6	6-10 years	
	Drinking Fountains - Single Water Cooler	2nd Floor	4	EA	7	10+ years	Corrected type and quantity
	Floor - Wood	2nd Floor	1,735	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	203	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3,465	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	865	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	140	SF	6	6-10 years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	6	6-10 years	
	Drinking Fountains - Single Water Cooler	3rd Floor	4	EA	7	10+ years	Corrected type and quantity
	Floor - Wood	3rd Floor	865	SF	6	6-10 years	•
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	32	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,930	SF	7	10+ years	
	Ceiling - Exposed	Basement	172	SF	6	10+ years	
	Ceiling - Lay-in	Basement	910	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	6	EA	7	10+ years	
	Doors - Transom Window	Basement	40	SF	7	10+ years	
	Doors - Wood Doors include hw	Basement	4	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	Basement	2	EA	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	Basement	1,082	SF	5	10+ years	
	Lighting - Lay-in	Basement	27	EA	7	10+ years	

Campus Name: Evergreen Page : 20 of 24 Assessment Date: 12/11/2023



Catego	ry : Interior		Building : Main						
				Ĭ		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Walls - Masonry	Basement	970	SF	7	10+ years			
	Walls - Plaster/Drywall	Basement	2,992	SF	7	10+ years			
						-			
Safety									
•	Camera Viewing Station	Entire Building	2	EA	7	6-10 years			
	Metal Detector	Entire Building	2	EA	7	6-10 years			
	Security Cameras	Entire Building	29	EA	7	6-10 years			
Ctaina									
Stairs	Ceiling - Exposed	North	635	SF	6	6-10 years			
	Ceiling - Exposed Ceiling - Plaster/Drywall	North	625	SF	6	6-10 years			
	Floor - Concrete Epoxy/ Painted	North	882	SF	7	10+ years			
	Floor - Concrete Epoxy/ Painted	North	200	SF	4	0-1 year	Cracks in floor		
	Handrails	North	465	LF	7	10+ years			
	Lighting - Pendent/Surface	North	8	ĒΑ	7	6-10 years	8:fixtures observed		
	Stairs - Concrete	North	390	LF	7	10+ years	Corrected quantity		
	Stairs - Concrete	North	60	LF	5	1-2 years	Damaged at tread/riser		
	Walls - Masonry	North	384	SF	7	10+ years	3		
	Walls - Plaster/Drywall	North	635	SF	7	10+ years			
	Ceiling - Exposed	South	635	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	South	615	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	South	10	SF	5	1-2 years	Cracks		
	Floor - Epoxy/ Painted	South	282	SF	7	10+ years			
	Floor - Epoxy/ Painted	South	800	SF	4	0-1 year	Large Cracks at landings		
	Handrails	South	465	LF	7	10+ years			
	Lighting - Pendent/Surface	South	8	EA	7	6-10 years	8;fixtures observed		
	Stairs - Concrete	South	320	LF	6	10+ years	Corrected quantity		
	Stairs - Concrete	South	130	LF	5	10+ years	Cracks in finish		
	Walls - Masonry	South	384	SF	7	10+ years			
	Walls - Plaster/Drywall	South	635	SF	7	10+ years			
Vertical	Conveyance								
_ v CitiCai	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years			
	•					•			



Category : Site Building : Site

Category . Site							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	12	ĒΑ	6	10+ years	
	Civil, Drainage Cite mainten			_, .	ŭ	,	
Fencing							
	Fencing - Chain Link	Entire Site	20	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,102	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	8	LF	5	0-1 year	Broken panel
Landasa							
Landsca	Benches	Entire Site	9	EA	7	10+ years	
	Landscape - Grass	Entire Site	5,170	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,297	SF	7	10+ years	Replaced. Quantity changed to reflec
	Landscape - Hardscape- Concrete	Littile Site	1,237	31	,	10+ years	the new landscaping area
	Landscape - Hardscape- Concrete	Entire Site	1,160	SF	6	10+ years	
	Parkway trees	Entire Site	17	EΑ	6	10+ years	
	Parkway trees	Entire Site	2	EΑ	4	0-1 year	Missing
	Planting Beds/ Area	Entire Site	3,958	SF	6	10+ years	· ·
	Play Area - Poured Rubber Surface	Entire Site	840	SF	7	10+ years	New
	Play Area - Synthetic Turf	Entire Site	1,740	SF	7	10+ years	New
	Retaining Wall - Concrete	Entire Site	200	SF	6	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	6-10 years	
Parking I	ot						
Parking	Concrete Curbs	Parking Lot- East	725	LF	6	10+ years	
	Interior Plantings	Parking Lot- East	16	LF	6	10+ years	
	Surface - Asphalt	Parking Lot- East	2,050	SF	7	10+ years	Newly repaired
				SF	4		
	Surface - Asphalt	Parking Lot- East	11,880	SF SF		0-1 year	Cracking/potholes
	Surface - Concrete	Parking Lot- East	504		6	10+ years	
	Trash Enclosure - Masonry	Parking Lot- East	504	SF	6	10+ years	
	Vehicular Screening	Parking Lot- East	270	LF	6	10+ years	
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	185	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	4,200	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	2,800	SF	4	0-1 year	Cracking/sinking
0:							
Signage	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/	Entire Site	1	EA	6	10+ years	
	marquoo 1100 Startaing Back ngrited W/	2.10.000	ı	_/ \	J	ioi youis	



Evergreen Academy Middle School

3537 S Paulina STREET, Chicago, IL 60609

Category : Site			Building : Site				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	LED Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Evergreen Page: 23 of 24 Assessment Date: 12/11/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classiconi Summary				Floor Plan		Glazed	Operable	100	01
Current Usage	Intended Usage	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Window Stop	Smart- Board
Building : Main	,	-	•						
Computer Lab	Regular Classroom	1st Floor	107	1-09	705	160	60	N	N
Laboratory/Shop	Library	1st Floor	103/105 Steam L		1,622	280	140		N
Music Room	Music Room	3rd Floor	304	3-16	790	160	60	N	N
Other Instructional Use	Art Room	3rd Floor	306	3-15	790	160	60	N	Υ
Regular Classroom	Regular Classroom	1st Floor	101	1-01	705	190	65	N	N
Regular Classroom	Regular Classroom	1st Floor	102	1-11	705	160	60	N	N
Regular Classroom	Regular Classroom	1st Floor	104	1-13	790	160	60	N	N
Regular Classroom	Regular Classroom	1st Floor	108	1-22	705	190	74	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	2-01	705	190	74	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	2-12	705	160	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	2-06	790	160	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	2-14	790	160	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	2-07	790	160	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	2-15	790	160	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	2-17	705	190	74	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	3-01	705	190	74	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	3-18	705	160	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	3-11	705	160	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	3-13	705	190	74	N	N
Science Classroom	Science Lab Level 3	2nd Floor	207	2-01	705	160	60	N	N