

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1925	2	76,762
Modular 1 (4-Classroom)	2003	1	4,950
Campus Total			81,712

Category : Exterior Building : Main

	y . Extorior			anamg			
· ·	Hom Tune	Location	Overtitu	HOM	Donk	Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
intrance							
	Entrance Control - Audio and Video	#1- Main- SE	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#1- Main- SE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1- Main- SE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1- Main- SE	11	LF	6	10+ years	
	Exterior Stairs - Stone	#1- Main- SE	66	LF	4	1-2 years	Settlement
	Ramps - Concrete	#1- Main- SE	100	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1- Main- SE	24	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#10 - East	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#10 - East	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#10 - East	90	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#11 - East	1	EA	7	10+ years	Repaired/replaced
	Exterior Doors - Transom Lite	#11 - East	2	EA	6	6-10 years	
	Ramps - Concrete	#11 - East	35	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#12 - Fire Escape	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#12 - Fire Escape	6	LF	6	10+ years	
	Entrance Control - Audio and Video	#1B - Boiler House - West	1	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#1B - Boiler House - West	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#2 - South	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - South	1	EΑ	6	10+ years	
	Exterior Stairs - Stone	#2 - South	72	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#2B - Boiler House - North	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2B - Boiler House - North	1	EΑ	6	6-10 years	
	Exterior Stairs - Stone	#2B - Boiler House - North	3	LF	6	6-10 years	



Catego	Category : Exterior				: Main			
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Exterior Doors - Exterior Steel Door	#3 - South	2	EA	6	6-10 years		
	Exterior Stairs - Stone	#3 - South	70	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	#3 - South	5	LF	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#3B - Chiller - NW	1	EA	6	10+ years		
	Exterior Stairs - Concrete	#3B - Chiller - NW	3	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	#4 - SW	1	EA	6	6-10 years		
	Exterior Stairs - Steel or Aluminum	#4 - SW	20	LF	4	0-1 year	Corroded, bent	
	Exterior Stairs - Stone	#4 - SW	3	LF	6	6-10 years		
	Stair Handrail - Steel_Stair Handrail	#4 - SW	12	LF	4	0-1 year	Detached, loose, corroded	
	Exterior Doors - Exterior Steel Door	#4B - Chiller - NE	1	EA	6	10+ years		
	Exterior Stairs - Concrete	#4B - Chiller - NE	3	LF	6	10+ years		
	Entrance Control - Audio and Video	#5 - SW	1	EA	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#5 - SW	2	EA	6	6-10 years		
	Exterior Doors - Transom Lite	#5 - SW	1	EA	6	6-10 years		
	Exterior Stairs - Stone	#5 - SW	6	LF	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#5B - Boiler House - East	1	EA	5	2-5 years		
	Exterior Doors - Transom Lite	#5B - Boiler House - East	1	EA	6	6-10 years		
	Exterior Stairs - Concrete	#5B - Boiler House - East	3	LF	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#6 - West	2	EA	6	6-10 years		
	Exterior Doors - Transom Lite	#6 - West	1	EA	6	6-10 years		
	Exterior Stairs - Stone	#6 - West	6	LF	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#6.5 - Elevator - NW	1	EA	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#7 - NW	1	EA	6	6-10 years		
	Exterior Stairs - Steel or Aluminum	#7 - NW	20	LF	5	6-10 years		
	Stair Handrail - Steel_Stair Handrail	#7 - NW	12	LF	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#8 - North	2	EA	6	6-10 years		
	Exterior Stairs - Concrete	#8 - North	16	LF	6	10+ years		
	Ramp Handrail - Steel_Ramp Handrail	#8 - North	120	LF	6	6-10 years		
	Ramps - Concrete	#8 - North	60	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	#8 - North	18	LF	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#9 - NE	2	EA	6	6-10 years		
	Exterior Doors - Transom Lite	#9 - NE	1	EA	6	6-10 years		
	Exterior Stairs - Stone	#9 - NE	54	LF	6	10+ years		
Fire Esca	ane							
_ I IIC LOU	Exterior Doors - Exterior Steel Door	NW/SW	2	EA	6	10+ years		
	Fire Escape	NW/SW	35	LF	5	2-5 years		
	Fire Escape	NW/SW	30	LF	5	2-5 years 2-5 years		
	Fire Escape	NW/SW	5	LF	4	0-1 year	Loose, missing railing	
	Paints	NW/SW	70	LF	5	2-5 years	Loose, missing railing	
	i airits	1400/300	70	LF	5	2-5 years		
_Foundati								
	Foundation - Concrete	Entire Building	960	LF	7	10+ years		
	Foundation - Concrete	Entire Building	19	LF	6	10+ years		



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Superstructure - Concrete	Entire Building	76,762	SF	7	10+ years	
_Lighting_							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	20	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	6-10 years	
_Roof Sys							
	Chimney - Brick Chimney- Concrete/ Mortar	Boiler House	40	LF	6	10+ years	
	Liner				_		
	Chimney - Metal Flue	Boiler House	10	LF.	7	10+ years	
	Coping - Stone	Boiler House	210	LF	6	10+ years	
	Downspouts - Interior Downspouts	Boiler House	20	LF	6	6-10 years	
	Parapet - Parapet > 30"	Boiler House	210	LF	6	10+ years	
	Roof - Modified Bitumen	Boiler House	2,755	SF	6	6-10 years	
	Roof Structure - Concrete	Boiler House	2,755	SF	7	10+ years	
	Coping - Stone	Elevator NW	33	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Elevator NW	35	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Elevator NW	23	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Elevator NW	10	LF	6	10+ years	
	Roof - Modified Bitumen	Elevator NW	140	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Elevator NW	140	SF	6	10+ years	
	Concrete Topping					,	
	Coping - Stone	Low E	54	LF	6	10+ years	
	Parapet - Parapet > 30"	Low E	54	LF	6	10+ years	
	Roof - Metal	Low E	86	SF	5	2-5 years	
	Roof Structure - Concrete	Low E	86	SF	6	10+ years	
	Access Ladder - Metal	Main	4	EA	5	2-5 years	
	Coping - Metal	Main	28	LF	6	6-10 years	
	Coping - Stone	Main	951	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main	10	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Main	444	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main	40	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main	28	LF	6	10+ years	
	Parapet - Parapet > 30"	Main	911	LF	6	•	
	Roof - Modified Bitumen	Main	28,508	SF	5	10+ years	
			20,300	EA		2-5 years	
	Roof Hatch - Metal	Main	ı,		7	10+ years	
	Roof Structure - Concrete	Main	28,518	SF	7	10+ years	
Malla							
<u>Walls</u>	Cheek-Wall - Concrete	Entire Building	18	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building Entire Building	45	SF SF	6	10+ years 10+ years	
	Cheek-Wall - Stone			SF SF		•	
		Entire Building	76 979	SF LF	6	10+ years	
	Cornice - Cast Stone	Entire Building	979	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	33,895	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	4,118	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	130	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2,258	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,000	SF	5	10+ years	
Vindows	s						
	Curtain wall - Louver	Entire Building	7	SF	5	2-5 years	
	Guard - Guards perforated	Entire Building	351	SF	6	6-10 years	
	Lintels - Steel	Entire Building	601	LF	6	10+ years	
	Lintels - Steel	Entire Building	20	LF	5	6-10 years	
	Lintels - Stone	Entire Building	450	LF	6	10+ years	
	Skylite - Glass Double-Pane	Entire Building	24	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	378	SF	6	6-10 years	
				SF		•	
	Windows - Sash Aluminum Double-pane	Entire Building	5,796		6	6-10 years	
	Windows - Wood- Single-pane	Entire Building	136	SF	5	2-5 years	
atego	ry : Electrical		В	uilding	: Main		
<b></b>	Ham. Tura	Location	Overetite.	ПОМ	Dank	Recommend	Comments
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
:merge	ncy System						
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	76,762	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	76,762	SF	5	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	4	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,817	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,120	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	2,746	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	2,746 1,815	SF	6	6-10 years	
		3		EA		-	Comp of avit signs are sutdeted as
	Exit Signs - Auditoium	Entire Building	5	EA	5	2-5 years	Some of exit signs are outdated an working. Few of them recently replaced
					_	0.5	· op.aooa
	Exit Signs - Corridors and Stairs	Entire Building	21	FΑ	5	2-5 years	
	Exit Signs - Corridors and Stairs Exit Signs - Gym	Entire Building Entire Building	21 4	EA EA	5 5	2-5 years 2-5 years	
1ain Se	Exit Signs - Gym					-	
⁄/ain Se	Exit Signs - Gym  rvice  Independent Electrical Service for					-	
Main Se	Exit Signs - Gym	Entire Building	4	EA	5	2-5 years	



	y : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	120/208/3PH						
	PA System	Entire Building	76,762	SF	5	2-5 years	
	•	•				•	
Power Dis							
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	1-2 years	Old, rusty panel
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	4	6-10 years	Missing spare breaker slots
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
Catogor	v - Fire Protection		B	uilding	· Main		
Jalegui	y : Fire Protection			ununig	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarn			•			•	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	76,762	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	76,762	SF	6	6-10 years	
	The Alami_Oystem	Littile Building	70,702	Oi	U	0-10 years	
Categor	y : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Condit			<b></b>				
W Condi	Chemical Pot Feeder	Entire Building	4	EA	6	6-10 years	
			1		•	o io youio	
			1		5	6-10 years	
	Chiller-Air Cooled-Screw Type-Ground	Entire Building	1	EA	5	6-10 years	
	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons	Entire Building	·	EA		•	
	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper	Entire Building  Entire Building	400	EA LF	6	10+ years	
	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System	Entire Building  Entire Building Entire Building	400	EA LF EA	6	10+ years 6-10 years	
	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less	Entire Building  Entire Building	·	EA LF	6	10+ years	
	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System	Entire Building  Entire Building  Entire Building	400	EA LF EA	6	10+ years 6-10 years	
Air Handli	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons ing Systems	Entire Building Entire Building Entire Building Roof	400	EA LF EA EA	6 6 5	10+ years 6-10 years 6-10 years	
Air Handli	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons  ing Systems Air Handling Unit- Built Up- Single Zone w/	Entire Building  Entire Building  Entire Building	400	EA LF EA	6	10+ years 6-10 years	
Air Handli	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons  ing Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Less	Entire Building Entire Building Entire Building Roof	400 1 1	EA LF EA EA	6 6 5	10+ years 6-10 years 6-10 years	
Air Handli	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons  ing Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Less	Entire Building Entire Building Entire Building Roof	400 1 1	EA LF EA EA	6 6 5	10+ years 6-10 years 6-10 years	
Air Handli	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons  ing Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Less than 8000 cfm	Entire Building Entire Building Entire Building Roof	400 1 1	EA LF EA EA	6 6 5	10+ years 6-10 years 6-10 years 6-10 years	
Air Handli	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons  ing Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Less than 8000 cfm Air Intake	Entire Building Entire Building Entire Building Roof  Auditorium - AHU1	400 1 1	EA LF EA EA	6 6	10+ years 6-10 years 6-10 years 6-10 years	
Air Handli	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons  ing Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Less than 8000 cfm Air Intake Auxiliaries - Less than 8000 cfm	Entire Building Entire Building Entire Building Roof  Auditorium - AHU1 Auditorium - AHU1 Auditorium - AHU1	1 1 1	EA LF EA EA	6 6 5	10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	
Air Handli	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons  ing Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Less than 8000 cfm Air Intake Auxiliaries - Less than 8000 cfm Return Duct Work - Indoor- Vertical Shaft	Entire Building Entire Building Entire Building Roof  Auditorium - AHU1	400 1 1	EA LF EA EA	6 6	10+ years 6-10 years 6-10 years 6-10 years	
Air Handli	Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons Pipes - Chilled Water Pipe- Copper Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons  ing Systems Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Less than 8000 cfm Air Intake Auxiliaries - Less than 8000 cfm	Entire Building Entire Building Entire Building Roof  Auditorium - AHU1 Auditorium - AHU1 Auditorium - AHU1	1 1 1	EA LF EA EA	6 6 5	10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	5000 - 10000 CFM	F 0 B 1 P			_	0.40	
	Fan Coil Unit- Floor Mounted - Hot Water and Chilled Water	Entire Building	1	EA	5	6-10 years	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	Entire Ballaing	'	LA	3	0-10 years	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	3				,	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water						
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	F 6 B 11	4	_ ^	-	0.40	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	Entire Building	'	LA	5	0-10 years	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	g				,	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water						
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	5 d 5 d 2			_	0.40	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	Entire Ballaling	'	LA	3	0-10 years	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	g				,	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water						
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	F 6 B 11	4	_ ^	-	0.40	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	Entire Ballaling	'	LA	3	0-10 years	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	3				,	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water						
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	E 6 B 7 P		_ ^	-	0.40	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	i an con onne i looi mounted - i lot water	Entire Dulluling	'	LA	J	0-10 years	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	and Chilled Water	Fatina Buildina	4	_^	_	0.40	
	Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water Fan Coil Unit- Floor Mounted - Hot Water	Entire Building	1	EA	5	6-10 years	
	and Chilled Water	Entire Building	'	LA	3	0-10 years	
	Air Handling Unit- Built Up- Multi Zone- Dual	Gym - AHU4	1	EA	6	6-10 years	AHU - 4 serves gym
	Temperature Coils - Less than 8000 cfm	Cym 74104		L/ \	O	o to years	Allo 4 Scives gym
	Air Intake	Gym - AHU4	1	EA	6	6-10 years	
	Auxiliaries - Less than 8000 cfm	Gym - AHU4	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Gym - AHU4	200	LF	6	6-10 years	
	and Ducts	-,			-	,	
	Air Handling Unit- Built Up- Single Zone w/	North - AHU3	1	EA	6	6-10 years	AHU - 3
	Air Tunnel- Dual Temperature Coils - 15001					•	
	- 25000 cfm						
	Air Intake	North - AHU3	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	North - AHU3	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Hot	North - AHU3	6	EA	6	6-10 years	
	Water Coil						
	Return Duct Work - Indoor- Vertical Shaft	North - AHU3	200	LF	6	10+ years	
	and Ducts						
	Zone Dampers	North - AHU3	14	EA	5	6-10 years	
	Outdoor Return Fans- inline Centrifugal - 10001 - 20000 CFM	Roof	2	EA	6	6-10 years	REF2/3
	Outdoor Return Fans- inline Centrifugal -	Roof	1	EA	6	6-10 years	REF1
	5000 - 10000 CFM	0 4 41110	4	_ ^	•	0.40	ALULO
	Air Handling Unit- Built Up- Multi Zone- Dual	South - AHU2	1	EA	6	6-10 years	AHU-2
	Temperature Coils - 15001 - 25000 cfm Air Intake	South - AHU2	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	South - AHU2	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Hot	South - AHU2	7	EA	6	6-10 years	
	Water Coil	30uii - Ai 102	,	LA	U	0-10 years	
	Return Duct Work - Indoor- Vertical Shaft	South - AHU2	200	LF	6	10+ years	
	and Ducts				· ·	. o · you.o	
	Zone Dampers	South - AHU2	14	EA	6	6-10 years	
Boiler S	estems						
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	3	EA	6	6-10 years	
	Condensing- Hot Water Boiler - 1001 - 2000	Boiler Room	2	EA	6	10+ years	
	MBH	20.0	_	_, .	Ŭ	,	
Haatin	Davissa						
Heating	Devices						



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Fin Tube - Hot Water	Entire Building	56	LF	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	14	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	5	2-5 years	Wall heaters have been repaired
	Wall Heater - Electric	Entire Building	6	EA	5	6-10 years	
Mechani	cal Plumbing						
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	
	Dual Temperature Pump - Less than 10	Basement	1	EΑ	6	6-10 years	
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Chilled Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Chilled Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Condensate-Steel or Galvanized	Entire Building	100	LF	6	10+ years	
				LF	6		
	Hydronic Supply and Return - Copper	Entire Building	500	LF	ь	10+ years	
Tempera	ature Control						
	DDC System	Entire Building	76,762	SF	6	6-10 years	
	Electric Thermostat	Entire Building	10	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	52	EA	6	6-10 years	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Dual	2nd Floor	1	EA	5	6-10 years	
	Temperature Coils (Hot/Chilled) Water		·		· ·	0 10 ,00.0	
Ventilatio	on.						
v Gritilatic	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	5	6-10 years	
	CFM	Litale building	ı	LA	5	U-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	3	EA	6	6-10 years	
	CFM	Litale building	3	LA	O	U-10 years	
	Roof Mounted Duct Work	Entire Building	400	LF	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	400	EA	6	6-10 years	
	Type II Exhaust Hood- Warnling Kitchen	Entire building	1	EA	b	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main	D	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	5	6-10 years	



Catego	ry : Plumbing		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	76,762	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	76,762	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	76,762	SF	6	10+ years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	76,762	SF	6	10+ years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	76,762	SF	6	10+ years	
	(Risers)				_		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	76,762	SF	6	10+ years	
	(from Risers to Fixtures)		<b>70 700</b>	0.5	•	4.0	
	Sanitary Piping	Entire Building	76,762	SF	6	10+ years	
	Storm Piping	Entire Building	76,762	SF	6	10+ years	
	Vent Piping	Entire Building	76,762	SF	6	10+ years	
Dumno							
Pumps	Pumps - Domestic Booster Pump-Duplex	Basement and Boiler Room	1	EA	6	6-10 years	
	Pumps - Ejector-Simplex	Basement and Boiler Room	1	EA	6	2-5 years	
	Pumps - Sump-Duplex	Basement and Boiler Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement and Boiler Room	1	EA	6	6-10 years	Elevator pit pump
	r umps - oump-oimplex	Dasement and Doller Noon	ı	LA	U	0-10 years	Lievator pit pump
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Item - Type trative Suites/Offices	2 2 2 2 2	Quantity	UOM		Replacement	Comments
•	trative Suites/Offices  AC Unit	1st Floor	1	EA	7	6-10 years	Comments
•	trative Suites/Offices  AC Unit Ceiling - Lay-in	2 2 2 2 2	,	EA SF	7 7		Comments
•	trative Suites/Offices  AC Unit Ceiling - Lay-in Doors - Transom Window	1st Floor	1	EA SF SF	7	6-10 years	Comments
•	trative Suites/Offices  AC Unit Ceiling - Lay-in	1st Floor 1st Floor	1 282	EA SF SF EA	7 7	6-10 years 10+ years 10+ years 10+ years	Comments
•	trative Suites/Offices  AC Unit Ceiling - Lay-in Doors - Transom Window	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 282 9 1 85	EA SF SF EA SF	7 7 7 6 6	6-10 years 10+ years 10+ years	Comments
•	trative Suites/Offices  AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile	1st Floor 1st Floor 1st Floor 1st Floor	1 282 9 1	EA SF SF EA SF	7 7 7 6 6 6	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
•	trative Suites/Offices  AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 282 9 1 85 197 6	EA SF SF EA SF SF EA	7 7 7 6 6 6 6	6-10 years 10+ years 10+ years 10+ years 6-10 years	Comments
•	trative Suites/Offices  AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 282 9 1 85 197	EA SF SF EA SF SF EA EA	7 7 7 6 6 6 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
•	trative Suites/Offices  AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 282 9 1 85 197 6	EA SF SF EA SF EA EA SF	7 7 7 6 6 6 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years	Comments
•	trative Suites/Offices  AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution	1st Floor	1 282 9 1 85 197 6 14 792	EA SF SF EA SF SF EA EA	7 7 7 6 6 6 7 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years	Comments
•	AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in	1st Floor	1 282 9 1 85 197 6 14 792	EA SF SF EA SF EA EA SF	7 7 7 6 6 6 7 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	Comments
•	AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw	1st Floor	1 282 9 1 85 197 6 14 792 1 127	EA SF SF EA SF EA SF EA SF EA	7 7 7 6 6 6 7 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Comments
•	AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet	1st Floor	1 282 9 1 85 197 6 14 792 1	EA SF SF EA SF EA SF EA SF EA SF	7 7 7 6 6 6 7 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
•	AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in	1st Floor	1 282 9 1 85 197 6 14 792 1 127	EA SF SF EA SF EA SF EA SF EA	7 7 7 6 6 6 7 7 7 7 6 6	6-10 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Comments
•	AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in Power Distribution	1st Floor	1 282 9 1 85 197 6 14 792 1 127 1	EA SF SF EA SF EA SF EA SF EA SF EA	7 7 7 6 6 6 7 7 7 7 6 6 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
•	AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in Power Distribution Walls - Plaster/Drywall	1st Floor	1 282 9 1 85 197 6 14 792 1 127 1 127 2	EA SF SF EA SF EA SF EA SF EA SF EA SF EA SF	7 7 7 6 6 6 7 7 7 7 6 6 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Comments
•	AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in Power Distribution Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor	1 282 9 1 85 197 6 14 792 1 127 1 127 2 4	EA SF SF SF SF EA SF EA SF EA SF EA SF SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 6 6 6 7 7 7 7 6 6 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Comments
•	AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in Power Distribution Walls - Plaster/Drywall	1st Floor	1 282 9 1 85 197 6 14 792 1 127 1 127 2 4 506	EA SF SF EA SF EA SF EA SF EA SF EA SF EA SF	7 7 7 6 6 6 7 7 7 7 6 6 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	Comments
•	AC Unit Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in Power Distribution Walls - Plaster/Drywall AC Unit Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in Power Distribution Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor	1 282 9 1 85 197 6 14 792 1 127 1 127 2 4 506 171	EA SF SF SF SF EA SF EA SF EA SF EA SF SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 6 6 6 7 7 7 7 6 6 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	Comments



Catego	ry : Room		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	171	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EΑ	7	6-10 years	
	Power Distribution	1st Floor	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	682	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	421	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	411	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Power Distribution	2nd Floor	4	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	718	SF	6	10+ years	
	AC Unit	Boiler House	1	EA	5	1-2 years	Expose electrical wiring
	Ceiling - Plaster/Drywall	Boiler House	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boiler House	1	EA	7	10+ years	
	Floor - Tile	Boiler House	80	SF	7	6-10 years	
	Lighting - Lay-in	Boiler House	2	EA	7	6-10 years	
	Power Distribution	Boiler House	10	EΑ	7	6-10 years	
	Storage/ Closet	Boiler House	20	SF	7	6-10 years	
	Storage/ Closet	Boiler House	10	SF	5	1-2 years	Excessive peeling paint on back wall,
	Storage, Globat	Bollot House		O.	Ŭ	. L youro	falling on floor
	Walls - Plaster/Drywall	Boiler House	320	SF	7	10+ years	.ag
	Walls - Plaster/Drywall	Boiler House	10	SF	4	0-1 year	Plaster is damaged and deteriorating
	Traile Tractor/21/Trail	Dollor Floddo		O.	•	o i your	and falling to the floor
	Work Sink	Boiler House	1	EA	7	10+ years	and raining to the need
	Ceiling - Plaster/Drywall	In Room 109	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 109	1	ĒΑ	6	10+ years	
	Floor - Tile	In Room 109	100	SF	7	10+ years	
	Lighting - Pendent/Surface	In Room 109	1	ĒΑ	7	6-10 years	
	Power Distribution	In Room 109	2	EA	7	10+ years	
	Walls - Plaster/Drywall	In Room 109	302	SF	7	10+ years	
	vano i lactor/Brywan	iii Kooiii 100	002	O.	•	To Tyouro	
Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	81	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	4,067	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	7	EA	7	10+ years	
	Floor - Carpet	1st Floor	1,006	SF	6	6-10 years	
	Floor - Concrete	1st Floor	802	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	2,259	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Lighting - Fendent/Surface  Lighting - Wall Mounted	1st Floor	12	EA	7	6-10 years	
	Main Floor Seating	1st Floor	279	EA	7	10+ years	
		1st Floor	279	EA	7		
	Sound System					6-10 years	
	Ctooo						
	Stage Stage Curtain	1st Floor 1st Floor	395 8	SF EA	7 7	10+ years 10+ years	



Catego	ry : Room		В	uilding	: Main		-
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	28	LF	7	10+ years	
	Stairs - Terrazzo	1st Floor	176	LF	7	10+ years	
	Storage/ Closet	1st Floor	73	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	7,090	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	180	SF	7	10+ years	
Clinic							
Cirilo	Ceiling - Plaster/Drywall	110	171	SF	7	10+ years	
	Doors - Side-lite	110	9	SF	7	10+ years	Quantity changed to update/correct to match current observation
	Doors - Wood Doors inclu hw	110	1	EA	6	10+ years	
	Floor - Tile/Sheet	110	171	SF	7	10+ years	
	Lighting - Pendent/Surface	110	2	EA	7	6-10 years	Quantity changed to update/correct to
			2		-	•	match current observation
	Walls - Plaster/Drywall	110	806	SF	7	10+ years	
Gymnas	ia						
	Ceiling - Plaster/Drywall	1st Floor	2,746	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	2,746	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure	1st Floor	12	ĒΑ	6	6-10 years	
	Sodium				•	0 10 700.0	
	Walls - Masonry	1st Floor	3,806	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,806	SF	7	10+ years	
Kitchen							
Tatonon	Ceiling - Plaster/Drywall	1st Floor	502	SF	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	502	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	ĒΑ	7	6-10 years	
	Walls - Masonry	1st Floor	203	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	405	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	68	SF	7	10+ years	
	wans - viriyi Goaled Gypsum i anei	13111001	00	Oi	,	10+ years	
Library							
	Casework	205	60	LF	6	10+ years	
	Ceiling - Lay-in	205	1,473	SF	6	10+ years	
	Doors - Transom Window	205	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	205	2	EA	6	10+ years	
	Floor - Carpet	205	1,473	SF	6	6-10 years	
	Lighting - Pendent/Surface	205	24	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	205	1,895	SF	6	10+ years	



category : Room			В	uilding	Main		
				_		Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	_						
IDF_IDI		110					
	Doors - Steel Doors incl hw	110	1	EA	7	10+ years	
	Finishes	110	130	SF	7	6-10 years	
	Other Cooling Unit	110	1	EΑ	7	6-10 years	Split system fan coil unit
	Window AC Unit	110	1	EA	5	1-2 years	Missing cover and filter
lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	23	SF	7	6-10 years	
	Janitor's Closet	1st Floor	23	SF	7	6-10 years	
	Mechanical/ Service Rooms	1st Floor	165	SF	7	10+ years	Fan coil unit closets within
						•	classrooms/some rooms
	Storage Room	1st Floor	79	SF	7	10+ years	
	Janitor's Closet	2nd Floor	9	SF	7	10+ years	
	Janitor's Closet	2nd Floor	23	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	195	SF	7	10+ years	Fan coil unit closets within
						, , , , , ,	classrooms/some rooms
	Air Intake Plenums	Basement	349	SF	7	10+ years	
	Air Tunnel	Basement	206	SF	7	10+ years	
	Auditorium Plenums	Basement	2,500	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	3,145	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	10,124	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	164	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,782	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	848	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	541	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	324	SF	7	10+ years	
	Air Tunnel	Boiler House	240	SF	7	10+ years	
	Boiler Room	Boiler House	2,113	SF	7	10+ years	
	Coal Room	Boiler House	1,426	SF	7	10+ years	
	Mechanical/ Service Rooms	Boiler House	124	SF	5	10+ years	
	Mechanical/ Service Rooms	Boiler House	74	SF	5	10+ years	
	Storage Room	Boiler House	290	SF	5	10+ years	
	Vaults	Boiler House	146	SF	7	10+ years	
	vadito	Doller Flouse	140	OI.	,	10+ years	
estroon							
	Accessories	103	113	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	103	151	SF	7	10+ years	
	Doors - Side-lite	103	102	SF	7	10+ years	
	Doors - Wood Doors inclu hw	103	2	EA	6	10+ years	
	Floor - Terrazzo	103	103	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	103	48	SF	7	10+ years	
	Lavatory	103	2	EA	7	10+ years	



Catego	ry : Room	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	103	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	103	169	SF	6	10+ years	
	Walls - Plaster/Drywall	103	10	SF	5	0-1 year	Paint is peeling and falling to the floor
	Water Closet	103	1	EΑ	7	10+ years	
	Accessories	1st Floor	95	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	95	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	95	SF	7	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	1	EA	7	10+ years	
	Walls - Masonry	1st Floor	173	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	347	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	58	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	386	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	386	SF	7	10+ years	
	Doors - Transom Window	1st Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	386	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
		1st Floor	3	EA	7		
	Lavatory					10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EΑ	7	6-10 years	
	Partitions	1st Floor	7	EA	7	10+ years	
	Walls - Masonry	1st Floor	360	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	360	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	360	SF	7	10+ years	
	Water Closet	1st Floor	7	EA	7	10+ years	
	Accessories	1st Floor - NW	285	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - NW	270	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - NW	15	SF	5	0-1 year	Paint is peeling and falling to the floor
	Doors - Transom Window	1st Floor - NW	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - NW	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - NW	285	SF	7	10+ years	
	Floor Drain	1st Floor - NW	1	EA	7	10+ years	
	Hand Dryer	1st Floor - NW	2	EΑ	7	6-10 years	
	Lavatory	1st Floor - NW	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - NW	5	EA	7	6-10 years	
	Partitions	1st Floor - NW	1	EA	7	10+ years	
	Urinals	1st Floor - NW	5	EA	7	10+ years	
	Walls - Masonry	1st Floor - NW	312	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - NW	312	SF	7	10+ years	

Campus Name: Farnsworth Page: 13 of 32 Assessment Date: 10/12/2023



Catego	ry : Room	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	1st Floor - NW	312	SF	7	10+ years	
	Water Closet	1st Floor - NW	1	EA	7	10+ years	
	Accessories	1st Floor - SW	182	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - SW	182	SF	7	10+ years	
	Doors - Transom Window	1st Floor - SW	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - SW	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - SW	182	SF	7	10+ years	
	Floor Drain	1st Floor - SW	1	EA	7	10+ years	
	Hand Dryer	1st Floor - SW	2	EA	7	6-10 years	
	Lavatory	1st Floor - SW	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - SW	3	EA	7	6-10 years	
	Partitions	1st Floor - SW	1	EA	7	10+ years	
	Urinals	1st Floor - SW	2	ΕA	7	10+ years	
	Walls - Masonry	1st Floor - SW	218	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - SW	431	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - SW	79	SF	7	10+ years	
	Water Closet	1st Floor - SW	1	EA	7	10+ years	
	Accessories	2nd Floor	386	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	366	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	4		Damagad
	Doors - Transom Window	2nd Floor 2nd Floor	24	SF SF		0-1 year	Damaged
				Sr EA	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1		6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	386	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EΑ	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EΑ	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	5	EA	6	10+ years	
	Walls - Masonry	2nd Floor	240	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	240	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	240	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	2nd Floor - Men	140	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Men	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Men	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Men	140	SF	6	10+ years	
	Floor Drain	2nd Floor - Men	1	EA	7	10+ years	
	Lavatory	2nd Floor - Men	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Men	2	EA	7	6-10 years	
	Partitions	2nd Floor - Men	1	EA	7	10+ years	
	Walls - Masonry	2nd Floor - Men	146	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Men	146	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - Men	32	SF	6	10+ years	
	Olidotalai OldEdd I llo	2110 1 1001 1011	02	٥.	J	. o . youro	



Catego	ry : Room		Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Water Closet	2nd Floor - Men	1	EA	6	10+ years				
	Accessories	2nd Floor - NW	281	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor - NW	281	SF	6	10+ years				
	Doors - Transom Window	2nd Floor - NW	12	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor - NW	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor - NW	281	SF	6	10+ years				
	Floor Drain	2nd Floor - NW	1	EA	7	10+ years				
	Hand Dryer	2nd Floor - NW	2	EA	7	6-10 years				
	Lavatory	2nd Floor - NW	3	EA	6	10+ years				
	Lighting - Pendent/Surface	2nd Floor - NW	5	EA	7	6-10 years				
	Partitions	2nd Floor - NW	7	EA	7	10+ years				
	Walls - Masonry	2nd Floor - NW	240	SF	6	10+ years				
	Walls - Plaster/Drywall	2nd Floor - NW	240	SF	6	10+ years				
	Walls - Structural Glazed Tile	2nd Floor - NW	240	SF	7	10+ years				
	Water Closet	2nd Floor - NW	7	EA	6	10+ years				
	Accessories	2nd Floor - SW	182	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor - SW	182	SF	6	10+ years				
	Doors - Transom Window	2nd Floor - SW	12	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor - SW	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor - SW	182	SF	6	10+ years				
	Floor Drain	2nd Floor - SW	1	EA	7	10+ years				
	Hand Dryer	2nd Floor - SW	2	EA	7	6-10 years				
	Lavatory	2nd Floor - SW	2	EA	6	10+ years				
	Lighting - Pendent/Surface	2nd Floor - SW	3	EA	7	6-10 years				
	Partitions	2nd Floor - SW	4	EA	7	10+ years				
	Walls - Masonry	2nd Floor - SW	175	SF	6	10+ years				
	Walls - Plaster/Drywall	2nd Floor - SW	250	SF	6	10+ years				
	Walls - Structural Glazed Tile	2nd Floor - SW	75	SF	7	10+ years				
	Water Closet	2nd Floor - SW	4	EA	6	10+ years				
	Accessories	2nd Floor - Teacher's Lounge Women	74	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor - Teacher's Lounge Women	74	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor - Teacher's Lounge Women	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Teacher's Lounge Women	74	SF	6	10+ years				
	Hand Dryer	2nd Floor - Teacher's Lounge Women	1	EA	7	6-10 years				
	Lavatory	2nd Floor - Teacher's Lounge Women	1	EA	6	6-10 years				
	Lighting - Pendent/Surface	2nd Floor - Teacher's Lounge Women	1	EA	7	6-10 years				
	Lighting - Wall Mounted	2nd Floor - Teacher's Lounge	1	EA	6	6-10 years				

Campus Name: Farnsworth Page : 15 of 32 Assessment Date: 10/12/2023



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Women					
	Partitions	2nd Floor - Teacher's Lounge	2	EA	7	10+ years	
		Women			_		
	Walls - Masonry	2nd Floor - Teacher's Lounge	185	SF	6	10+ years	
		Women			_		
	Walls - Plaster/Drywall	2nd Floor - Teacher's Lounge	185	SF	6	10+ years	
		Women	_		_		
	Water Closet	2nd Floor - Teacher's Lounge	2	EA	6	10+ years	
		Women	40	05	_	0.40	
	Accessories	Boiler Room	18	SF	/	6-10 years	
	Ceiling - Plaster/Drywall	Boiler Room	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	6	6-10 years	
	Floor - Concrete	Boiler Room	18	SF	5	1-2 years	Cracks and broken sections of
	Linktin	Dellas Deess	4	_^	-	0.40	flooring
	Lighting - Pendent/Surface	Boiler Room	1	EA	7	6-10 years	Every site of a site of the si
	Walls - Plaster/Drywall	Boiler Room	180	SF	5	1-2 years	Excessive peeing paint and falling to the floor
	Water Closet	Boiler Room	1	EA	7	10+ years	
	Accessories	Principal's Office	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Office	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	7	10+ years	
	Floor - Tile	Principal's Office	25	SF	7	10+ years	
	Lavatory	Principal's Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Principal's Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Principal's Office	125	SF	7	10+ years	Quantity changed to update/correct to match current observation
	Water Closet	Principal's Office	1	EA	7	10+ years	
Catego	orv : Classroom		В	uildina	: Main		

Building : Main Category : Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #100 (Regular Classroom)						
	Casework	1st Floor	11	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years	
	Chalk Board	1st Floor	32	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	720	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,053	SF	6	10+ years	
_Classroo	om #101 (Regular Classroom)						
	Casework	1st Floor	73	LF	6	10+ years	

Campus Name: Farnsworth Page : 16 of 32 Assessment Date: 10/12/2023



Catego	ategory : Classroom		В	uilding	: Main			
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years		
	Doors - Transom Window	1st Floor	18	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years		
	Floor - Tile	1st Floor	720	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	16	LF	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,027	SF	6	10+ years		
Classroo	om #102 (Regular Classroom)							
<u> </u>	Casework	1st Floor	11	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years		
	Chalk Board	1st Floor	18	LF	4	2-5 years		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
			2	EA		•		
	Doors - Wood Doors inclu hw	1st Floor		SF	6	10+ years		
	Floor - Carpet	1st Floor	720		6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	6	LF	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,053	SF	6	10+ years		
_Classroo	m #103 (Special Program)							
	Casework	1st Floor	15	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	1,920	SF	7	10+ years		
	Doors - Transom Window	1st Floor	27	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years		
	Floor - Tile	1st Floor	1,920	SF	6	6-10 years	Quantity changed to update/correct to match current observation	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	materi current observation	
	Storage/ Closet	1st Floor	30	SF	7	10+ years		
	Storage/ Closet	1st Floor	128	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,938	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classroo	om #105 (Regular Classroom)							
	Casework	1st Floor	14	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years		
	Chalk Board	1st Floor	20	LF	4	2-5 years		
	Doors - Transom Window	1st Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Wood	1st Floor	720	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	28	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,167	SF	7	10+ years		
	vvalis - Flastel/Diywali	151 -1001	1,107	SF	,	10+ years		



Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	om #106 (Regular Classroom)								
	Casework	1st Floor	40	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	720	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years			
	Marker Board	1st Floor	10	LF	6	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,534	SF	6	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Classroo	om #107 (Regular Classroom)								
	Casework	1st Floor	14	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	670	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	50	SF	5	0-1 year	Excessive peeling paint and falling to the floor		
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	720	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	6-10 years			
	Marker Board	1st Floor	38	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,168	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	50	SF	5	0-1 year	Excessive peeling paint and falling to the floor		
Classias	om #108 (Regular Classroom)								
Classroc	` •	4 . 🖽				40			
	Casework	1st Floor	8	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years			
	Chalk Board	1st Floor	6	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	720	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years			
	Marker Board	1st Floor	20	LF	6	6-10 years			
	Walls - Metal Panel	1st Floor	1,227	SF	7	10+ years	Wood panels		
	Walls - Plaster/Drywall	1st Floor	306	SF	7	10+ years			
Classroo	om #109 (Other Instructional Use)								
	Ceiling - Plaster/Drywall	Mezzanine	396	SF	7	10+ years			
	Doors - Transom Window	Mezzanine	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Mezzanine	2	EA	6	10+ years			
	Floor - Tile	Mezzanine	396	SF	6	6-10 years			



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Mezzanine	5	EA	7	6-10 years	
	Marker Board	Mezzanine	6	LF	6	6-10 years	
	Walls - Masonry	Mezzanine	383	SF	7	10+ years	
	Walls - Plaster/Drywall	Mezzanine	382	SF	7	10+ years	
	Work Sink	Mezzanine	1	EA	7	10+ years	
Classroo	om #110 (Special Program)						
	Ceiling - Plaster/Drywall	1st Floor	315	SF	7	10+ years	
	Doors - Side-lite	1st Floor	20	SF	7	6-10 years	
	Doors - Transom Window	1st Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	315	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	313	EA	7	6-10 years	Quantity adjusted based on surrent
	-		_		•	6-10 years	Quantity adjusted based on current observation
	Walls - Plaster/Drywall	1st Floor	865	SF	7	10+ years	
Classroo	om #112 (Special Program)						
	Casework	1st Floor	39	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	785	SF	7	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Carpet	1st Floor	196	SF	6	6-10 years	
	Floor - Tile	1st Floor	765	SF	7	10+ years	Quantity changed to update/correct to
	11001 1110	1001	. 55	٥.	•	io. youro	match current observation
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Broken floor tiles
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	Broker noor thes
	Storage/ Closet	1st Floor	97	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,053	SF	7	10+ years	
	Work Sink	1st Floor	1,003	EA	7	10+ years	
	WOIR SIIIR	151 11001	1	EA	,	10+ years	
Classroo	om #114 (Regular Classroom)						
	Casework	1st Floor	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	720	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,218	SF	7	10+ years	
Classroo	om #200 (Regular Classroom)						
CILIONIO							

Campus Name: Farnsworth Page: 19 of 32 Assessment Date: 10/12/2023



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	11	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	714	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	32	SF	4	0-1 year	Damaged
	Chalk Board	2nd Floor	10	LF	4	2-5 years	•
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	746	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,391	SF	6	10+ years	
Classroc	om #201 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	688	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	32	SF	4	0-1 year	Water damaged
	Chalk Board	2nd Floor	30	ĹF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,347	SF	6	10+ years	
Classroc	om #202 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	703	SF	6	6-10 years	
	Chalk Board	2nd Floor	19	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	703	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,391	SF	6	10+ years	
Classroc	om #203 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
			<u> </u>		•	3 10 70010	



Catego	ategory : Classroom		В	uilding		5414 N LINGEL AVENUE, Chicago, IL 60	
	<b>,</b> 1 0 10 0 0 0 11 11		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #204 (Regular Classroom)		·			_	
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	7	10+ years	
Classroo	m #206 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	7	10+ years	
Classroo	m #207 (Science)						
	Casework	2nd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,060	SF	6	10+ years	
	Chalk Board	2nd Floor	11	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	1,045	SF	6	6-10 years	
	Floor - Tile	2nd Floor	15	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,482	SF	6	10+ years	
	Work Sink	2nd Floor	4	EA	5	1-2 years	Faucet handles removed and sink covered by board
Classroo	m #208 (Regular Classroom)						
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	



Catego	Category : Classroom		В	uilding	: Main				
_	_					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Marker Board	2nd Floor	36	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	7	10+ years			
Classroc	om #209 (Special Education)								
	Ceiling - Plaster/Drywall	Mezzanine	506	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Mezzanine	20	SF	4	0-1 year	Damaged		
	Doors - Side-lite	Mezzanine	16	SF	6	10+ years			
	Doors - Transom Window	Mezzanine	3	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Mezzanine	2	EA	6	10+ years			
	Floor - Terrazzo	Mezzanine	526	SF	6	10+ years			
	Lighting - Pendent/Surface	Mezzanine	9	EA	7	6-10 years			
	Walls - Plaster/Drywall	Mezzanine	694	SF	6	10+ years			
	Work Sink	Mezzanine	1	EA	7	6-10 years			
Classroo	om #210 (Regular Classroom)								
	Casework	2nd Floor	14	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	688	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	32	SF	4	0-1 year	Damaged		
	Chalk Board	2nd Floor	4	LF	4	2-5 years	Damagoa		
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Wood	2nd Floor	720	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	40	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	6	10+ years			
lassroo	om #212 (Regular Classroom)								
JIGGGIOC	Casework	2nd Floor	14	LF	6	10+ years			
	Casework Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years			
	Chalk Board	2nd Floor	8	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years			
			10	EA	6	•			
	Doors - Wood Doors inclu hw Floor - Wood	2nd Floor 2nd Floor	720	SF	6	10+ years			
				_	-	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	38	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,167	SF	6	10+ years			
Classroc	om #214 (Regular Classroom)								
	Casework	2nd Floor	11	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	746	SF	6	10+ years			
	Chalk Board	2nd Floor	8	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years			



Categor	y : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	746	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,020	SF	6	10+ years	
Categor	y : Interior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	71		,				
	Ceiling - Lay-in	1st Floor	5,080	SF	6	10+ years	
	Doors - Transom Window	1st Floor	360	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	14	ĒΑ	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EΑ	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	2	EΑ	5	1-2 years	Out of order
	Floor - Tile/Sheet	1st Floor	5,030	SF	7	10+ years	out of order
	Floor - Tile/Sheet	1st Floor	50	SF	4	1-2 years	Broken and cracked floor tiles
	Lighting - Lay-in	1st Floor	30	EA	7	6-10 years	Broker and ordered neer thee
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor	8	LF	7	10+ years	
	Student Lockers - One Tier	1st Floor	294	EA	6	10+ years	
	Walls - Masonry	1st Floor	3,531	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	70,590	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	30	SF	5	1-2 years	Plaster is damaged and deteriorating
	Ceiling - Lay-in	2nd Floor	5,040	SF	6	10+ years	and falling to the floor
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Drinking Fountains - Single Vater Cooler	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	5,030	SF	7	•	
	Floor - Tile/Sheet	2nd Floor	10	SF	4	10+ years	Domogod
	Lighting - Lay-in	2nd Floor	61	EA	6	1-2 years	Damaged
			306	EA	6	6-10 years	
	Student Lockers - One Tier Walls - Plaster/Drywall	2nd Floor 2nd Floor	8,976	SF	6	10+ years 10+ years	
Safety							
,	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	5	EΑ	7	6-10 years	Exterior
	Security Cameras	Entire Building	6	ĒĀ	7	6-10 years	Quantity changed to update/correct t match current observation
Stairs							
	Ceiling - Plaster/Drywall	North	252	SF	6	10+ years	
	Floor - Terrazzo	North	126	SF	7	10+ years	
	Handrails	North	72	LF	7	10+ years	



Catego	ry : Interior	В	uilding	: Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	North	2	EA	7	6-10 years	
	Stairs - Terrazzo	North	162	LF	6	10+ years	
	Walls - Plaster/Drywall	North	1,280	SF	6	10+ years	
	Walls - Plaster/Drywall	North	20	SF	4	0-1 year	Damaged
	Ceiling - Plaster/Drywall	North West	252	SF	6	10+ years	
	Floor - Terrazzo	North West	126	SF	7	10+ years	
	Handrails	North West	72	LF	7	10+ years	
	Lighting - Lay-in	North West	2	EA	7	6-10 years	
	Stairs - Terrazzo	North West	162	LF	6	10+ years	
	Walls - Plaster/Drywall	North West	1,300	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	236	SF	6	10+ years	
	Floor - Terrazzo	South	126	SF	7	10+ years	
	Handrails	South	72	LF	7	10+ years	
	Lighting - Lay-in	South	2	EA	7	6-10 years	
	Stairs - Terrazzo	South	162	LF	6	10+ years	
	Walls - Plaster/Drywall	South	1,290	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South West	252	SF	6	10+ years	
	Floor - Terrazzo	South West	126	SF	7	10+ years	
	Handrails	South West	72	LF	7	10+ years	
	Lighting - Lay-in	South West	2	EA	7	6-10 years	
	Stairs - Terrazzo	South West	162	LF	6	10+ years	
	Walls - Plaster/Drywall	South West	1,280	SF	6	10+ years	
	Walls - Plaster/Drywall	South West	20	SF	4	1-2 years	Damaged
_Vertical_	Conveyance						
	Elevator - Elevator- Machine Roomless	North	1	EA	6	10+ years	

Campus Name: Farnsworth Page : 24 of 32 Assessment Date: 10/12/2023



Catego	ry : Exterior		В	uilding	: Modul	ar 1 (4-Classro	om )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#1M - East	2	EA	6	6-10 years	
	Entrance Control - Audio and Video	#2M - West	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#2M - West	2	EA	6	6-10 years	
oundat	ion						
	Foundation - Masonry	Entire Building	282	LF	7	10+ years	
	Superstructure - Steel	Entire Building	4,950	SF	7	10+ years	
ighting							
<del></del>	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	5	2-5 years	
Roof Sy	stem						
	Coping - Metal	Entire Building	282	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Entire Building	52	LF	6	6-10 years	
	Roof - EPDM/ Synthetic Rubber	Entire Building	4,138	SF	5	2-5 years	
	Roof - EPDM/ Synthetic Rubber	Entire Building	812	SF	4	0-1 year	Leaks
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Entire Building	4,950	SF	7	10+ years	200.10
Walls							
	Exterior Walls - Precast Panel Wall	Entire Building	3,686	SF	6	6-10 years	
Window	3						
	Guard - Guards perforated	Entire Building	256	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	288	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Modul	ar 1 (4-Classro	om )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
-	Exit Signs - Corridors and Stairs	1st Floor	6	EA	5	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	6	EA	6	2-5 years	
	Security System - Intrusion Detection	Entire Building	5	SF	7	6-10 years	
Main Se	rvice						
	Main Electrical Service - 800 A and Less than 120/208/3PH	1st Floor	1	EA	6	6-10 years	

Campus Name: Farnsworth Page : 25 of 32 Assessment Date: 10/12/2023



	chools		<u> </u>	المائم م	. Madeel		5414 N Linder AVENUE, Chicago, IL 60
atego	ry : Electrical		В	uliaing	: woaul	ar 1 (4-Classro	oom j
2roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	PA System	Entire Building	4,950	SF	Rank 6	2-5 years	Connected to main building
	ra System	Entire Building	4,950	SI	Ü	2-5 years	Connected to main building
ower D	stribution						
	Lighting and Power Panels - 100 A	1st Floor	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	10+ years	
atego	ry : Fire Protection		В	uilding	: Modul	ar 1 (4-Classro	oom )
_				_		Recommend	·
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
3prinkler	System						
	Sprinkler Heads	Mechanical Room	4,950	SF	7	6-10 years	
	Sprinkler Piping	Mechanical Room	4,950	SF	6	6-10 years	
	Wet Sprinkler System	Mechanical Room	4,950	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (4-Classro	oom )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u> Tempera</u>	ture Control						
	Electric Thermostat	1st Floor	4	EA	5	6-10 years	
Jnit Ven	tilation						
	Unit Ventilators - Vertical Package Electric	Exterior	4	EA	5	2-5 years	
	Heat & Self Contained Cooling					,	
/entilatio	on.						
CHILICAN	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	1	EA	6	10+ years	
	CFM		•			, , , , , , , , , , , , , , , , , , , ,	
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	4	EA	5	6-10 years	
	CFM						
Catego	ry : Plumbing		В	uilding	: Modul	ar 1 (4-Classro	om )
~	Ham Time	Lagation	Ouent!te	HOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate						0.10	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	4,950	SF	6	10+ years	
	D (' D' ' 11 (/O 11)) ( O 1	Entire Building	4,950	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply						
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	3	,			-	
	(Horizontal Lines) Sanitary Piping	Entire Building	4,950	SF	6	10+ years	

Campus Name: Farnsworth Page : 26 of 32 Assessment Date: 10/12/2023



Catego	ry : Plumbing		Building : Modular 1 (4-Classroom )						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Storm Piping	Entire Building	4,950	SF	6	10+ years			
	Vent Piping	Entire Building	4,950	SF	6	10+ years			
Catego	ory : Classroom		В	uilding	: Modul	ar 1 (4-Classro	oom )		
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	om #115 (Regular Classroom)								
	Casework	1st Floor	3	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years			
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	812	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years			
	Storage/ Closet	1st Floor	92	SF	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	836	SF	6	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
	Tronk Silik	10011001	·	_, 、	•	io. youro			
Classroo	om #116 (Kindergarten)								
	Casework	1st Floor	3	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years			
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	812	SF	6	6-10 years			
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years			
	Storage/ Closet	1st Floor	92	SF	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	836	SF	6	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Classroo	om #117 (Kindergarten)								
	Casework	1st Floor	3	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years			
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	802	SF	6	6-10 years			
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Damaged		
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	Bamagoa		
	Storage/ Closet	1st Floor	92	SF	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	836	SF	6	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Closses	om #449 (Kindorgortor)								
Classio	om #118 (Kindergarten)	1et Floor		1 -		10			
	Casework	1st Floor	3	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years			



Categor	y : Classroom		В	uilding	: Modul	ar 1 (4-Classro	om )
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	812	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	18	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	92	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	836	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Categor	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	oom )
						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
√lechanic	cal/ Service Rooms						
	Mechanical/ Service Rooms	Room 115/117 Mechanical Closet	50	SF	7	10+ years	
Restroom							
	Accessories	1st Floor	162	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	162	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	162	SF	7	10+ years	
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Hand Dryer	1st Floor	1	EΑ	7	6-10 years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Partitions	1st Floor	2	EΑ	7	10+ years	
	Urinals	1st Floor	2	EA	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	300	SF	6	10+ years	
	Water Closet	1st Floor	2	EA	6	10+ years	
	Accessories	1st Floor	162	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	162	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	162	SF	7	10+ years	
	Floor Drain	1st Floor	102	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	6	10+ years	
				EA		,	
	Lighting - Pendent/Surface	1st Floor	2		7	6-10 years	
	Partitions Walls Vinul Coated Cynaum Banel	1st Floor	4	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	300	SF	6	10+ years	
	Water Closet	1st Floor	4	EA	6	10+ years	
Categor	y : Interior		В	uilding	: Modul	ar 1 (4-Classro	om )
			•			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Campus Name: Farnsworth Page : 28 of 32 Assessment Date: 10/12/2023



Catego	ry : Interior		В	uilding	: Modul	ar 1 (4-Classro	oom )	
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	1st Floor	432	SF	6	10+ years		
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years		
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	432	SF	7	10+ years		
	Floor - Tile/Sheet	1st Floor	64	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	992	SF	6	10+ years		
Safety								
,	Security Cameras	Exterior	1	EA	7	6-10 years		

Campus Name: Farnsworth Page : 29 of 32 Assessment Date: 10/12/2023



Categor	ry : Site	Building : Site

	y . Site		_	unung		D	
			<u> </u>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Synthetic	West	6,250	SF	7	10+ years	
	Surface - Asphalt	West	1,750	SF	7	10+ years	
			.,	-		, , , , , , , , , , , , , , , , , , , ,	
Civil/Draii	nage						
SIVII/ BIGII	Civil/ Drainage - Catch Basin	Entire Site	12	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	7	10+ years	
	Civili Dialilage - Site Marillole	Littile Site	0	LA	,	10+ years	
Fencina							
J	Fencing - Chain Link	Entire Site	165	LF	6	6-10 years	
	Fencing - Guard Rail	Entire Site	50	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	1,384	LF	6	6-10 years	
			1,00			,	
andscap	oe						
	Benches	Entire Site	11	EA	7	10+ years	
	Landscape - Grass	Entire Site	38,418	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	500	SF	5	2-5 years	
	Landscape - Hardscape- Pavers	Entire Site	1,200	SF	6	10+ years	
	Parkway trees	Entire Site	64	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	420	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	2,023	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	20,031	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	400	SF	6	10+ years	
	Trash Receptacles	Entire Site		EA		6-10 years	
			3		6		
	Walking Path - Crushed Stone	Entire Site	620	SF	7	10+ years	
Parking L	ot						
	Concrete Curbs	SW	212	LF	6	10+ years	
	Interior Plantings	SW	462	LF	6	10+ years	
	Surface - Asphalt	SW	10,776	SF	6	6-10 years	
	Trash Enclosure - Chain Links	SW	723	SF	5	6-10 years	
	Vehicular Screening	SW	14	LF	6	10+ years	
	Concrete Curbs	West	316	LF	6	10+ years	
	Surface - Asphalt	West	11,452	SF	6	6-10 years	
	Surface - Asphalt	West	100	SF	5	2-5 years	Patched
	очнасе - дэрнак	vvGol	100	OI.	3	2-0 years	i atorieu
⊇laygrour							
	Equipment - Combo 3-12	NE Lot	1	EA	7	10+ years	
	Equipment - Swingset	NE Lot	1	EA	7	10+ years	



Catego	ry : Site	В	Building : Site					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
_Sidewall	KS.							
	Sidewalks - Internal Walks	Entire Site	289	LF	7	10+ years		
	Sidewalks - Internal Walks	Entire Site	265	LF	6	10+ years		
	Sidewalks - Perimeter Sidewalks	Entire Site	1,750	SF	6	10+ years		
Signage								
0 0	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	6-10 years		
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years		
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years		

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Farnsworth Page: 31 of 32 Assessment Date: 10/12/2023

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main		•	•	•		•			
Other Instructional Use	Office	Mezzanine	109		396	36	18	N	N
Regular Classroom	Library	1st Floor	101	Library	720	128	78	N	Υ
Regular Classroom	Regular Classroom	1st Floor	100	106	720	180	78	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	107	720	128	78	N	Υ
Regular Classroom	Regular Classroom	1st Floor	105	104	720	185	85	N	Υ
Regular Classroom	Regular Classroom	1st Floor	106	116	720	128	78	N	Υ
Regular Classroom	Regular Classroom	1st Floor	107	105	720	185	85	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108	115	720	128	78	N	Υ
Regular Classroom	Regular Classroom	1st Floor	114	114	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	200	206	746	137	68	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	207	703	137	68	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	202	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	208	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	209	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	210	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	211	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	720	185	85	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	214	746	217	217	N	Υ
Science	Science	2nd Floor	207	205	1,060	197	85	N	N
Special Education	Lunch Room	Mezzanine	209	Teacher Lunch R	526	41	41	N	N
Special Program	Kindergarten	1st Floor	103	103	1,920	237	107	N	Υ
Special Program	Kindergarten	1st Floor	112	120	785	179	109	N	N
Special Program	Special Program	1st Floor	110	Clinic	315	65	35	N	N
Building : Modular 1 (4-Cla	ssroom)								
Kindergarten	Regular Classroom	1st Floor	116		812	64	28	N	N
Kindergarten	Regular Classroom	1st Floor	117		812	64	28	N	N
Vindorgorton	Describer Classers	4 a 4 🖺 a a u	440		040	C 4	20	N.I.	N.I

Building : Modular 1 (4-Classroom )										
Kindergarten	Regular Classroom	1st Floor	116	812	64	28	N	N		
Kindergarten	Regular Classroom	1st Floor	117	812	64	28	N	N		
Kindergarten	Regular Classroom	1st Floor	118	812	64	28	N	N		
Regular Classroom	Regular Classroom	1st Floor	115	812	64	28	N	N		

Campus Name: Farnsworth Page : 32 of 32 Assessment Date: 10/12/2023