

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1897	3	48,896
Addition	1910	3	36,905
Modular 1 (6-Classroom)	2003	1	6,676
Modular 2 (2-Classroom)	1990	1	2,100
Campus Total			94,577

atego	ry : Exterior		B	uilding	: Main		
iroup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ell Equ	ipment						
	Cell Equipment - Antenna	Main Roof	3	EA	7	10+ years	
Entrance							
_mance	Exterior Doors - Exterior Steel Door	#5 E	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6 E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 E	3	LF	4	1-2 years	Chipped, cracked
	Exterior Doors - Exterior FRP Door	#7 S	2	EA	7	10+ years	•••
	Exterior Stairs - Concrete	#7 S	6	LF	7	10+ years	Divided out damaged areas
	Exterior Stairs - Concrete	#7 S	7	LF	4	1-2 years	Chipped, cracked, Divided out damaged areas
	Exterior Doors - Exterior FRP Door	#8 S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 S	6	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 S	19	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#9 W	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#9 W	6	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 W	16	LF	6	10+ years	Divided out damaged areas
	Exterior Stairs - Concrete	#9 W	3	LF	5	6-10 years	Divided out damaged areas
Foundati	ion						
	Foundation - Masonry	Entire Building	424	LF	7	10+ years	



Fo Su Lighting Ex Roof System Do Ro Ro Ro	em - Type pundation - Masonry uperstructure - Heavy Timber xterior Lighting - Wall Mounted n ownspouts - Exterior Downspouts	Location Entire Building Entire Building Entire Building	Quantity 10 48,896 2	UOM LF SF	Rank 6 7	Recommend Replacement 10+ years 10+ years	Comments
Fo Su Lighting Ex Roof System Do Ro Ro Ro	oundation - Masonry uperstructure - Heavy Timber xterior Lighting - Wall Mounted	Entire Building Entire Building	10 48,896	LF SF	6	10+ years	Comments
Su Lighting Ex Roof System Do Ro Ro Ro	uperstructure - Heavy Timber xterior Lighting - Wall Mounted	Entire Building	48,896	SF			
Lighting Ex Roof System Do Ro Ro	xterior Lighting - Wall Mounted	Ū.			,	Tor years	
Ex Roof System Do Ro Ro Ro	n	Entire Building	2				
<u>Roof System</u> Do Ro Ro	n	Entire Building	2				
Do Ro Ro				EA	7	6-10 years	
Do Ro Ro							
Ro Ro		1 - Main Roof	555	LF	6	10+ years	Corrected quantity
Ro	oof - Asphalt Shingle	1 - Main Roof	10,546	SF	5	2-5 years	
	oof - Asphalt Shingle	1 - Main Roof	3,000	SF	4	0-1 year	Loose, missing shingles
	oof Hatch - Metal	1 - Main Roof	2	ĒA	7	10+ years	3 3 3
	oof Structure - Heavy Timber	1 - Main Roof	13,546	SF	7	10+ years	
	himney - Brick Chimney- Concrete/ Mortar	2 - East Lower Roof	10	LF	7	10+ years	
	ner						
	himney - Brick Chimney- Concrete/ Mortar ner	2 - East Lower Roof	90	LF	6	10+ years	
	oping - Metal	2 - East Lower Roof	50	LF	6	10+ years	
	oping - Stone	2 - East Lower Roof	95	LF	6	10+ years	
	oping - Stone	2 - East Lower Roof	70	LF	6	10+ years	
	ownspouts - Exterior Downspouts	2 - East Lower Roof	36	LF	6	10+ years	
	ownspouts - Interior Downspouts	2 - East Lower Roof	90	LF	6	10+ years	
	arapet - 16" - 30" Height	2 - East Lower Roof	105	LF	7	10+ years	
	arapet - Parapet < 16" Height	2 - East Lower Roof	110	LF	7	10+ years	
	oof - Metal	2 - East Lower Roof	880	SF	7	10+ years	
	oof - Modified Bitumen	2 - East Lower Roof	2,145	SF	7	10+ years	
	oof Structure - Steel / Metal Deck/	2 - East Lower Roof	3,025	SF	7	10+ years	
	oncrete Topping		0,020	0.		lor jouro	
/alls							
	ornice - Terra Cotta	Entire Building	868	LF	6	10+ years	
Ex	xterior Walls - Brick	Entire Building	21,236	SF	7	10+ years	
Ex	xterior Walls - Brick	Entire Building	3,200	SF	5	10+ years	
Ex	xterior Walls - Prefabricated Metal Panel	Entire Building	1,302	SF	6	10+ years	
Wa	/all	-					
Ex	xterior Walls - Stone-Cast	Entire Building	1,931	SF	6	10+ years	Recombined quantities
Ex	xterior Walls - Stone-Cast	Entire Building	500	SF	5	10+ years	
Ex	xterior Walls - Stone-Cut	Entire Building	1,870	SF	6	10+ years	
Ex	xterior Walls - Stone-Cut	Entire Building	300	SF	5	10+ years	
Vindows							
	uard - Guards perforated	Entire Building	1,150	SF	6	10+ years	
	ntels - Brick	Entire Building	125	LF	6	10+ years	
	ntels - Steel	Entire Building	200	LF	6	10+ years	



Category : Exterior Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lintels - Stone	Entire Building	105	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	70	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	5	SF	6	10+ years	
	Windows - Louver	Entire Building	8	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,108	SF	6	10+ years	

Category : Electrical			В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,956	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,314	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	Quantity changed to match current observations.
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	10	EA	2	0-1 year	Signs throughout Main have no backup batteries and the building has no emergency generator.
	Exit Signs - Lunchroom	Entire Building	2	EA	2	0-1 year	Quantity changed to match current observations. Signs have no backup batteries and the building has no emergency generator.
	Security System - CCTV	Entire Building	48,896	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	48,896	SF	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	4	0-1 year	Reason and Priority Rep adjusted as an opening in the front of the panel exposes live conductors presenting a live front condition. Serves Main and Addition.
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	48,896	SF	6	6-10 years	Served by Addition.
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	6-10 years	Quantity changed to match current observations and as the total has been divided/aggregated. A panel is secured shut for safety reasons and the condition was verified by the



Catego	ory : Electrical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							Building Engineer.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open fuse receptacles expose live conductors presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Openings expose live conductors presenting a live front condition.

Catego	Category : Fire Protection			uilding			
•	K		0			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Ala							
	Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Location changed for clarification.
	Fire Alarm Strobe Lights	Entire Building	48,896	SF	7	10+ years	
	Fire Alarm_System Fire Pump Controller	Entire Building	48,896	SF EA	7 7	10+ years	
		Entire Building	I	LA	Ĩ	6-10 years	Location changed for clarification. Controller is 60-plus years old with n appreciable signs of age-related degradation. Priority Rep adjusted based on current observations and o the age of the equipment.
Pump R	oom Assembly						
	Fire Pump - 25-50 hp	Pump Room	1	EA	5	6-10 years	
Sprinkle	r System						
-	Dry Sprinkler System	Entire Building	48,896	SF	6	6-10 years	
	Sprinkler Heads	Entire Building	48,896	SF	7	10+ years	
	Sprinkler Piping	Entire Building	48,896	SF	6	6-10 years	
Catego	ory : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	ditioning						
	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	6	6-10 years	Component of the ductless split system serving the MDF Room located inside Room 205.
Air Hand	dling Systems						
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	5	6-10 years	
			•		•	5.0,000	



Cateur	ory : Mechanical		B	uilding	: Main		
	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Steam Coils - 25001 - 35000 cfm						
	Air Intake	Mechanical Room	1	EA	5	6-10 years	Location changed for clarification.
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	100	LF	6	10+ years	
	and Ducts						
	Zone Dampers	Mechanical Room	15	EA	5	1-2 years	Location and quantity changed to match current observations. Dampers are functional but do not respond to controls and require manual adjustment.
	Zone Dampers	Mechanical Room	12	EA	3	1-2 years	Dampers are functional but do not respond to controls and require manual adjustment.
Boiler S	ystems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on repairs completed since previous assessment.
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	5	6-10 years	B-1, serves Main and Addition. Reason and Priority Rep changed based on current observations and per review with Building Engineer that the boiler is well-maintained older equipment that continues to function as intended.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	5	6-10 years	B-2, serves Main and Addition. Reason and Priority Rep changed based on current observations and per review with Building Engineer that the boiler is well-maintained older equipment that continues to function as intended.
	Piping - Condensate Pipe- Steel	Boiler Room	800	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	800	LF	6	6-10 years	
	Steam Traps	Boiler Room	16	EA	5	6-10 years	
Heating	Devices						
пеашу	Unit Heater - Gas	Boiler Room	1	EA	6	6-10 years	Misdocumented in previous



Catego	ry : Mechanical		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							assessment. Quantity changed to
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	match current observations.
	Wall Heater - Electric	Entire Building	4	EA	4	0-1 year	Missing cover exposes live
		Entre Banang	I I	L/\	т	0 i year	conductors presenting a live front
							condition and exposes heat-
							producing components and moving
							parts presenting a risk of personal
							injury.
Tempera	ture Control						
·	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Misdocumented in previous
							assessment. Quantity changed to
							match current observations. Located in the MDF Room inside Room 205.
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	In the MDF Room inside Room 205.
	Pneumatic System	Entire Building	48.896	SF	4	0-1 year	System serves Main and Addition.
		g	10,000	•	•	e i jeu.	Compressor replaced in 2020 but
							there are leaks throughout the system
							with less than a fourth of the devices
		Fating Duilding	47		4	0.4	responding to controls.
	Thermostats - Pneumatic	Entire Building	17	EA	4	0-1 year	Quantity changed as total has been divided/aggregated. Thermostats
							throughout the building are generally
							nonresponsive to controls due to
							leaks and contamination with oil.
/entilatio	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	6-10 years	
	CFM	, C					
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	6-10 years	Inaccessible in a safe manner at the
	CFM						time of assessment due to unreliable
							climbing means. Condition verified by current observations and per
							review with Building Engineer. Rank
							adjusted based on belt replacement
							and adjustments made since previous
					_		assessment.
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression system present.



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	ar Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	2-5 years	Rank adjusted based on current observations that the water heater i functional, leak-free, and shows no signs of undue age-related degradation. Reason and Priority Rep adjusted to establish that the u is 20-plus years old and has reached the end of its anticipated service life
Piping	Domestic Piping-Hot Water Return Lines	Entire Building	48,896	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	48,896	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	48,896	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	48,896	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	48,896	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	48,896	SF	6	6-10 years	
	Sanitary Piping	Entire Building	48,896	SF	6	6-10 years	
	Storm Piping	Entire Building	48,896	SF	6	6-10 years	
	Vent Piping	Entire Building	48,896	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	6	6-10 years	Serves Main and Addition
Catego	ry : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	104 Office Suite	1	EA	7	6-10 years	Moved from classrooms
	Ceiling - Lay-in	104 Office Suite	860	SF	7	10+ years	Moved from classrooms
	Doors - Transom Window	104 Office Suite	18	SF	7	10+ years	Moved from classrooms
	Doors - Wood Doors inclu hw	104 Office Suite	2	EA	7	10+ years	Moved from classrooms
	Floor - Wood	104 Office Suite	860	SF	5	10+ years	Worn finish. Moved from classroom
	Lighting - Lay-in	104 Office Suite	14	EA	7	6-10 years	Moved from classrooms
	Power Distribution	104 Office Suite	10	EA	7	10+ years	Moved from classrooms
	Walls - Plaster/Drywall	104 Office Suite	958	SF	7	10+ years	Moved from classrooms
		Asst principal	1	EA	7	6-10 years	
	AC Unit	7.55t principal				0 10 90010	
	Ceiling - Lay-in	Asst principal	480	SF	7	10+ years	



Category : Room

Matthew Gallistel Elementary Language Academy 10347 S Ewing AVENUE, Chicago, IL 60617

Recommend

Building : Main

Group Item - Type Location Quantity UOM Rank Replacement Comments Doors - Wood Doors inclu hw Asst principal EΑ 10+ vears 7 1 480 SF 7 Floor - Wood Asst principal 10+ vears Lighting - Lay-in Asst principal 6 FΑ 7 6-10 years Power Distribution Asst principal 6 ΕA 7 10+ years SF Storage/ Closet Asst principal 60 7 10+ years SF Walls - Plaster/Drywall 7 Asst principal 550 10+ years Walls - Plaster/Drywall Asst principal SF 5 10+ years 10 Water damage Ceiling - Exposed SF Copy room in basement 180 7 10+ years Doors - Wood Doors inclu hw Copy room in basement 1 EΑ 7 10+ years SF Floor - Tile Copy room in basement 176 7 10+ vears SF Floor - Tile Copy room in basement 4 4 1-2 vears Cracked tile Lighting - Pendent/Surface Copy room in basement 1 EΑ 7 6-10 years Power Distribution Copy room in basement 6 ΕA 7 10+ years SF 7 Walls - Plaster/Drywall Copy room in basement 400 10+ years Ceiling - Plaster/Drywall Engineer's office in basement SF 150 6 10+ years Peeling paint throughout Ceiling - Plaster/Drywall SF 5 Engineer's office in basement 10 10+ years Water damage Doors - Steel Doors incl hw 2 ΕA 7 Engineer's office in basement 10+ vears Floor - Concrete Epoxy/ Painted Engineer's office in basement 160 SF 7 10+ years Lighting - Pendent/Surface Engineer's office in basement 4 ΕA 7 6-10 vears Power Distribution Engineer's office in basement 6 EΑ 7 10+ years Storage/ Closet Engineer's office in basement 80 SF 7 10+ years Walls - Concrete Block SF 7 Engineer's office in basement 160 10+ years Walls - Plaster/Drvwall SF 7 Engineer's office in basement 360 10+ years SF 7 Ceiling - Plaster/Drywall Office at SW lunch room 252 10+ years Doors - Wood Doors inclu hw Office at SW lunch room ΕA 7 1 10+ years SF Floor - Tile Office at SW lunch room 252 7 10+ vears Lighting - Pendent/Surface Office at SW lunch room EΑ 7 6-10 years 7 **Power Distribution** Office at SW lunch room 6 ΕA 7 10+ years SF Walls - Masonry Office at SW lunch room 300 7 10+ years Walls - Plaster/Drywall Office at SW lunch room 220 SF 7 10+ years Kitchen Ceiling - Plaster/Drywall Basement 1,054 SF 7 10+ years Doors - Transom Window Basement 72 SF 7 10+ years Doors - Wood Doors inclu hw Basement 2 ΕA 7 10+ years Floor - Tile SF 7 Basement 1.014 10+ years SF Floor - Tile Basement 40 4 1-2 years Cracked tile Lighting - Pendent/Surface 8 FΑ 7 6-10 years Basement LF Serving Line Basement 22 7 10+ vears SF Storage/ Closet 7 10+ years Basement 210 Walls - Masonry 1,326 SF 7 **Basement** 10+ years Lunch & Multipurpose Room Ceiling - Plaster/Drywall North basement lunch 1,135 SF 7 10+ years



	ory : Room		В	uilding	: Main		
				J		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	North basement lunch	4	EA	7	10+ years	
	Floor - Tile	North basement lunch	1,135	SF	6	2-5 years	
	Lighting - Pendent/Surface	North basement lunch	17	EA	7	6-10 years	
	Walls - Concrete Block	North basement lunch	636	SF	7	10+ years	
	Walls - Masonry	North basement lunch	450	SF	7	10+ years	
	Walls - Plaster/Drywall	North basement lunch	300	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South East basement lunch	1,059	SF	6	10+ years	
	Floor - Tile	South East basement lunch	1,059	SF	7	10+ years	
	Lighting - Pendent/Surface	South East basement lunch	8	EA	7	6-10 years	
	Walls - Masonry	South East basement lunch	582	SF	7	10+ years	
	Walls - Plaster/Drywall	South East basement lunch	750	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South West basement lunch	1,120	SF	7	10+ years	
	Floor - Tile	South West basement lunch	1,120	SF	7	10+ years	
	Lighting - Pendent/Surface	South West basement lunch	5	EA	7	6-10 years	
	Walls - Masonry	South West basement lunch	1,816	SF	7	10+ years	
	Walls - Plaster/Drywall	South West basement lunch	300	SF	7	10+ years	
DF_ID							
	Doors - Wood Doors inclu hw	2nd FL - inside the library	1	EA	6	10+ years	
	Finishes	2nd FL - inside the library	175	SF	5	10+ years	
	Other Cooling Unit	2nd FL - inside the library	1	EA	7	6-10 years	Ductless split
echani	ical/ Service Rooms	1st Floor	12	05	7	40	
	Janitor's Closet			SF	7	10+ years	
	Janitor's Closet	2nd Floor	6	SF	7	10+ years	
	Janitor's Closet Janitor's Closet	2nd Floor 3rd Floor	6 6	SF SF	7 7	10+ years 10+ years	
	Janitor's Closet Janitor's Closet Air Intake Plenums	2nd Floor 3rd Floor Basement	6 6 1,000	SF SF SF	7 7 7	10+ years 10+ years 10+ years	
	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room	2nd Floor 3rd Floor Basement Basement	6 6 1,000 945	SF SF SF SF	7 7 7 5	10+ years 10+ years 10+ years 10+ years	
	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room	2nd Floor 3rd Floor Basement Basement Basement	6 6 1,000 945 235	SF SF SF SF SF	7 7 7 5 7	10+ years 10+ years 10+ years 10+ years 10+ years	
	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet	2nd Floor 3rd Floor Basement Basement Basement Basement	6 6 1,000 945 235 168	SF SF SF SF SF	7 7 5 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms	2nd Floor 3rd Floor Basement Basement Basement Basement Basement	6 6 1,000 945 235 168 1,063	SF SF SF SF SF SF	7 7 5 7 7 5	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years	
	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms Storage Room	2nd Floor 3rd Floor Basement Basement Basement Basement Basement Basement	6 6 1,000 945 235 168 1,063 530	SF SF SF SF SF SF SF	7 7 5 7 5 7 5 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years	
	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms	2nd Floor 3rd Floor Basement Basement Basement Basement Basement	6 6 1,000 945 235 168 1,063	SF SF SF SF SF SF	7 7 5 7 7 5	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years	Formerly listed as vault
estroo	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms Storage Room Storage Room	2nd Floor 3rd Floor Basement Basement Basement Basement Basement Basement	6 6 1,000 945 235 168 1,063 530	SF SF SF SF SF SF SF	7 7 5 7 5 7 5 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years	Formerly listed as vault
estroor	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms Storage Room Storage Room	2nd Floor 3rd Floor Basement Basement Basement Basement Basement Basement	6 6 1,000 945 235 168 1,063 530	SF SF SF SF SF SF SF	7 7 5 7 5 7 5 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years	Formerly listed as vault
estroor	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms Storage Room Storage Room	2nd Floor 3rd Floor Basement Basement Basement Basement Basement Basement	6 6 1,000 945 235 168 1,063 530 150	SF SF SF SF SF SF SF	7 7 5 7 7 5 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years	Formerly listed as vault
estroor	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms Storage Room Storage Room	2nd Floor 3rd Floor Basement Basement Basement Basement Basement Basement Basement Basement	6 6 1,000 945 235 168 1,063 530 150 341	SF SF SF SF SF SF SF SF	7 7 5 7 7 5 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years	Formerly listed as vault
estrooi	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms Storage Room Storage Room	2nd Floor 3rd Floor Basement Basement Basement Basement Basement Basement Basement Basement 2nd floor girls room 2nd floor girls room 2nd floor girls room	6 6 1,000 945 235 168 1,063 530 150 341 341 341 338	SF SF SF SF SF SF SF SF	7 7 5 7 7 5 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 10+ years	Formerly listed as vault
estrooi	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms Storage Room Storage Room M Accessories Ceiling - Lay-in Floor - Tile Ceramic/ Porcelain	2nd Floor 3rd Floor Basement Basement Basement Basement Basement Basement Basement Basement 2nd floor girls room 2nd floor girls room 2nd floor girls room 2nd floor girls room 2nd floor girls room	6 6 1,000 945 235 168 1,063 530 150 341 341	SF SF SF SF SF SF SF SF SF	7 7 5 7 7 5 7 7 7 7 7 6	10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	
estroo	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms Storage Room Storage Room M Accessories Ceiling - Lay-in Floor - Tile Ceramic/ Porcelain Floor - Tile Ceramic/ Porcelain Floor Drain	2nd Floor 3rd Floor Basement Basement Basement Basement Basement Basement Basement Basement Comment	6 6 1,000 945 235 168 1,063 530 150 341 341 341 338 3 1	SF SF SF SF SF SF SF SF SF	7 7 5 7 7 5 7 7 7 7 7 6 4	10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
estroor	Janitor's Closet Janitor's Closet Air Intake Plenums Boiler Room Coal Room Janitor's Closet Mechanical/ Service Rooms Storage Room Storage Room M Accessories Ceiling - Lay-in Floor - Tile Ceramic/ Porcelain Floor - Tile Ceramic/ Porcelain	2nd Floor 3rd Floor Basement Basement Basement Basement Basement Basement Basement Basement 2nd floor girls room 2nd floor girls room 2nd floor girls room 2nd floor girls room 2nd floor girls room	6 6 1,000 945 235 168 1,063 530 150 341 341 341 338 3	SF SF SF SF SF SF SF SF SF SF EA	7 7 5 7 7 5 7 7 7 7 7 7 6 4 7	10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	-



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd floor girls room	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor girls room	64	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd floor girls room	577	SF	7	10+ years	
	Water Closet	2nd floor girls room	6	EA	7	10+ years	
	Accessories	3rd floor girls room	341	SF	7	10+ years	
	Ceiling - Lay-in	3rd floor girls room	341	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor girls room	341	SF	6	10+ years	
	Floor Drain	3rd floor girls room	1	EA	7	10+ years	
	Hand Dryer	3rd floor girls room	2	EA	7	6-10 years	
	Lavatory	3rd floor girls room	3	EA	6	10+ years	
	Lighting - Lay-in	3rd floor girls room	6	EA	7	10+ years	
	Partitions	3rd floor girls room	6	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd floor girls room	64	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd floor girls room	577	SF	7	10+ years	
	Water Closet	3rd floor girls room	6	EA	7	10+ years	
	Accessories	Basement girls room	325	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement girls room	325	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement girls room	325	SF	7	10+ years	
	Floor Drain	Basement girls room	1	EA	7	10+ years	
	Hand Dryer	Basement girls room	2	EA	7	6-10 years	
	Lavatory	Basement girls room	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement girls room	5	EA	7	6-10 years	
	Partitions	Basement girls room	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement girls room	88	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement girls room	440	SF	7	10+ years	
	Water Closet	Basement girls room	10	EA	7	10+ years	
	Accessories	Boy's room in basement	243	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boy's room in basement	243	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boy's room in basement	243	SF	7	10+ years	
	Floor Drain	Boy's room in basement	1	EA	7	10+ years	
	Hand Dryer	Boy's room in basement	2	EA	7	6-10 years	
	Lavatory	Boy's room in basement	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Boy's room in basement	4	EA	7	6-10 years	
	Partitions	Boy's room in basement	2	EA	7	10+ years	
	Urinals	Boy's room in basement	7	EA	6	10+ years	
	Walls - Plaster/Drywall	Boy's room in basement	115	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boy's room in basement	565	SF	7	10+ years	
	Water Closet	Boy's room in basement	2	EA	7	10+ years	
	Accessories	Classroom 109	42	SF	7	6-10 years	
	Ceiling - Lay-in	Classroom 109	42	SF	7	10+ years	
	Floor - Tile	Classroom 109	35	SF	6	10+ years	
	Floor - Tile	Classroom 109	7	SF	4	0-1 year	Chipped
	Lavatory	Classroom 109	1	EA	7	10+ years	
	Lighting - Lay-in	Classroom 109	1	EA	5	2-5 years	



Catego	ry : Room		B	uilding	: Main	•	0347 S EWING AVEINDE, Chicago, IL 60617
Juicgo	,			anang	· man	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	Classroom 109	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Classroom 109	260	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Classroom 109	18	SF	7	10+ years	
	Water Closet	Classroom 109	1	EA	7	10+ years	
	Accessories	In engineers's office	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In engineers's office	51	SF	7	10+ years	
	Ceiling - Plaster/Drywall	In engineers's office	1	SF	6	1-2 years	Hole in ceiling
	Doors - Steel Doors incl hw	In engineers's office	1	EA	7	10+ years	·
	Floor - Concrete Epoxy/ Painted	In engineers's office	52	SF	5	10+ years	
	Lavatory	In engineers's office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In engineers's office	1	EA	7	6-10 years	
	Lighting - Wall Mounted	In engineers's office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	In engineers's office	240	SF	7	10+ years	
	Walls - Plaster/Drywall	In engineers's office	15	SF	6	10+ years	hairline crack
	Water Closet	In engineers's office	1	EA	7	10+ years	
	Accessories	In office at SW lunch room	49	SF	5	1-2 years	Restroom out of service
	Ceiling - Plaster/Drywall	In office at SW lunch room	49	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In office at SW lunch room	1	EA	7	10+ years	
	Floor - Tile	In office at SW lunch room	49	SF	4	1-2 years	Restroom out of service damaged and shifting tile
	Lavatory	In office at SW lunch room	1	EA	7	10+ years	5
	Lighting - Pendent/Surface	In office at SW lunch room	1	EA	7	6-10 years	
	Walls - Masonry	In office at SW lunch room	130	SF	7	10+ years	
	Walls - Plaster/Drywall	In office at SW lunch room	130	SF	6	10+ years	
	Water Closet	In office at SW lunch room	1	EA	4	1-2 years	Restroom out of service
	Accessories	In room 108	42	SF	7	6-10 years	
	Ceiling - Lay-in	In room 108	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In room 108	1	EA	7	10+ years	
	Floor - Tile	In room 108	21	SF	7	10+ years	
	Floor - Tile	In room 108	3	SF	4	0-1 year	Chipped
	Floor - Tile Ceramic/ Porcelain	In room 108	18	SF	7	10+ years	
	Floor Drain	In room 108	1	EA	7	10+ years	
	Lavatory	In room 108	1	EA	7	10+ years	
	Lighting - Lay-in	In room 108	1	EA	7	6-10 years	
	Partitions	In room 108	1	EA	7	10+ years	
	Walls - Plaster/Drywall	In room 108	201	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	In room 108	32	SF	7	10+ years	
	Water Closet	In room 108	1	EA	7	10+ years	
	Accessories	In vice principal's office	48	SF	7	6-10 years	
	Ceiling - Lay-in	In vice principal's office	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In vice principal's office	1	EA	7	10+ years	
	Floor - Tile	In vice principal's office	48	SF	7	10+ years	
	Lavatory	In vice principal's office	1	EA	7	10+ years	
	Lighting - Lay-in	In vice principal's office	1	EA	7	6-10 years	



Category : Classroom

10347 S Ewing AVENUE, Chicago, IL 60617

Catego	Category : Room			Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	In vice principal's office	1	EA	7	10+ years			
	Walls - Plaster/Drywall	In vice principal's office	180	SF	7	10+ years			
	Walls - Structural Glazed Tile	In vice principal's office	100	SF	7	10+ years			
	Water Closet	In vice principal's office	1	EA	6	10+ years			

Building : Main

Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Classroom #105 (Kindergarten) AC Units 1st Floor 1 ΕA 7 6-10 years 1st Floor 8 LF 7 10+ years Casework Ceiling - Lay-in 1st Floor 900 SF 7 10+ years Chalk Board LF 1st Floor 30 4 2-5 years Doors - Transom Window 1st Floor 9 SF 7 10+ years Corrected quantity ΕA 7 Doors - Wood Doors inclu hw 1st Floor 1 10+ years Floor - Wood 1st Floor 900 SF 7 10+ years 7 Lighting - Lay-in 1st Floor 16 EΑ 6-10 years Marker Board 1st Floor 30 LF 7 6-10 years Storage/ Closet 1st Floor 175 SF 7 10+ years Walls - Plaster/Drywall SF 1st Floor 1.264 7 10+ years Classroom #106 (Kindergarten) AC Units 1st Floor 1 ΕA 7 6-10 years Casework 1st Floor 8 LF 7 10+ years Ceiling - Lay-in 1st Floor 891 SF 7 10+ years Chalk Board LF 1st Floor 34 4 2-5 years Doors - Transom Window 1st Floor 9 SF 7 10+ years Corrected quantity Doors - Wood Doors inclu hw 7 1st Floor 1 EΑ 10+ years Floor - Wood SF 7 1st Floor 891 10+ years Lighting - Lay-in 1st Floor 16 EΑ 7 6-10 years Storage/ Closet 175 SF 7 1st Floor 10+ years Walls - Plaster/Drywall 1st Floor 1,074 SF 7 10+ years Classroom #107 (Regular Classroom) AC Units 1st Floor 1 ΕA 7 6-10 years

Casework	1st Floor	8	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
Chalk Board	1st Floor	60	LF	4	2-5 years	Corrected quantity
Doors - Transom Window	1st Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Wood	1st Floor	900	SF	6	10+ years	
Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
Storage/ Closet	1st Floor	175	SF	7	10+ years	



Catego	ry : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,264	SF	7	10+ years	
lassroc	om #108 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	860	SF	7	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	856	SF	6	10+ years	
	Floor - Tile	1st Floor	4	SF	4	1-2 years	Chipped
	Lighting - Chandelier, Incandescent	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	133	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	958	SF	7	10+ years	
				0.		for youro	
lassroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	52	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	895	SF	6	10+ years	
	Floor - Tile	1st Floor	5	SF	4	1-2 years	Cracked
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	130	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,264	SF	7	10+ years	
lassroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	860	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	6	10+ years	
	Floor - Wood	2nd Floor	860	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	958	SF	7	10+ years	
lassroo	om #205 (Library)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	900	SF	6	10+ years	
		21011001	9	0	0	io+ years	



Catego	ategory : Classroom		B	Building : Main					
						Recommend			
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	900	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	16	EA	7	10+ years			
	Walls - Metal Panel	2nd Floor	250	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	7	10+ years			
lassroo	m #206 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	860	SF	6	10+ years			
	Chalk Board	2nd Floor	18	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood	2nd Floor	860	SF	5	2-5 years			
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years			
	Marker Board	2nd Floor	4	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	175	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	958	SF	7	10+ years			
Classroo	m #207 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years			
	Chalk Board	2nd Floor	60	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood	2nd Floor	900	SF	5	2-5 years			
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years			
	Storage/ Closet	2nd Floor	175	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	7	10+ years			
Classroo	m #208 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	860	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood	2nd Floor	860	SF	5	2-5 years			
	Lighting - Lay-in	2nd Floor	16	EA	7	10+ years			
	Storage/ Closet	2nd Floor	175	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	958	SF	7	10+ years			



Catego	Category : Classroom			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	900	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	4	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	7	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Carpet	3rd Floor	720	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	11	EA	7	10+ years	
	Storage/ Closet	3rd Floor	175	SF	5	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	854	SF	7	10+ years	
Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years	
	Chalk Board	3rd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	900	SF	5	2-5 years	
	Lighting - Lay-in	3rd Floor	16	ĒA	7	10+ years	
	Storage/ Closet	3rd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,264	SF	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	682	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Carpet	3rd Floor	582	SF	6	6-10 years	
	Floor - Carpet	3rd Floor	100	SF	4	0-1 year	Torn
	Lighting - Lay-in	3rd Floor	8	EA	7	10+ years	
			0	LA	'	ior years	



Catego	Category : Classroom			uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	3rd Floor	1	EA	6	10+ years			
	Marker Board	3rd Floor	15	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	825	SF	7	10+ years			
Classroc	om #307 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years			
	Chalk Board	3rd Floor	40	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Wood	3rd Floor	900	SF	5	2-5 years			
	Lighting - Lay-in	3rd Floor	15	EA	7	10+ years			
	Storage/ Closet	3rd Floor	175	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,264	SF	7	10+ years			
Classroc	om #308 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	12	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	848	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	12	SF	5	1-2 years	Water damage		
	Chalk Board	3rd Floor	30	LF	4	2-5 years	Trater damage		
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Wood	3rd Floor	860	SF	5	2-5 years			
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years			
	Marker Board	3rd Floor	4	LF	7	2-5 years			
	Storage/ Closet	3rd Floor	175	SF	5	10+ years			
	Walls - Plaster/Drywall	3rd Floor	958	SF	7	10+ years			
Classroc	om #309 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years			
	Chalk Board	3rd Floor	10	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Wood	3rd Floor	900	SF	5	10+ years			
	Lighting - Lay-in	3rd Floor	15	EA	7	10+ years			
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	175	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,264	SF	7	10+ years			



Catego	Category : Classroom			uilding	: Main			
				Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	om #310 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	656	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	8	SF	5	1-2 years	stained tile	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Wood	3rd Floor	664	SF	6	6-10 years		
	Lighting - Lay-in	3rd Floor	10	EA	7	10+ years		
	Marker Board	3rd Floor	12	LF	6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	827	SF	7	10+ years		
Catego	ry : Interior		В	uilding	: Main			
						Recommend		

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	1,675	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Transom Window	1st Floor	48	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,675	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,412	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	4	1-2 years	Water damage
	Ceiling - Lay-in	2nd Floor	1,675	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	3	EA	6	10+ years	
	Floor - Asphalt Floor	2nd Floor	1,675	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	17	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,432	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,675	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	48	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	3	EA	6	10+ years	
	Floor - Asphalt Floor	3rd Floor	1,675	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	17	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,432	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	677	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	6	EA	6	10+ years	Corrected quantity
	Floor - Tile/Sheet	Basement	677	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	10	EA	7	6-10 years	
	Walls - Masonry	Basement	268	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	846	SF	6	10+ years	



Catego	ry : Interior	B	Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Safety								
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years		
	Security Cameras	1st Floor	5	EA	7	6-10 years		
	Security Cameras	1st Floor	7	EA	7	10+ years		
Stairs								
	Ceiling - Lay-in	North	396	SF	7	10+ years		
	Ceiling - Plaster/Drywall	North	384	SF	7	10+ years		
	Floor - Asphalt	North	576	SF	6	10+ years		
	Floor - Tile	North	51	SF	6	10+ years		
	Handrails	North	176	LF	7	10+ years		
	Lighting - Lay-in	North	3	EA	7	10+ years		
	Lighting - Pendent/Surface	North	4	EA	7	10+ years		
	Stairs - Asphalt	North	408	LF	6	10+ years	Corrected quantity	
	Walls - Plaster/Drywall	North	3,312	SF	7	10+ years		
	Ceiling - Lay-in	South	396	SF	7	10+ years		
	Ceiling - Plaster/Drywall	South	384	SF	7	10+ years		
	Floor - Asphalt	South	576	SF	6	10+ years		
	Floor - Tile	South	51	SF	6	10+ years		
	Handrails	South	176	LF	7	10+ years		
	Lighting - Lay-in	South	3	EA	7	10+ years		
	Lighting - Pendent/Surface	South	4	EA	7	10+ years		
	Stairs - Asphalt	South	408	LF	6	10+ years	Corrected quantity	
	Walls - Plaster/Drywall	South	3,312	SF	7	10+ years		



Catego	Category : Exterior			Building : Addition					
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Cell Equi									
	Cell Equipment - Antenna	Main Roof	1	EA	7	6-10 years			
	Cell Equipment - Cabinets	Main Roof	1	EA	7	10+ years			
Entrance	A CONTRACTOR OF								
	Entrance Control - Audio and Video	#1 W	1	EA	7	10+ years			
	Exterior Doors - Exterior FRP Door	#1 W	4	EA	6	10+ years			
	Exterior Doors - Transom Lite	#1 W	4	EA	6	10+ years			
	Exterior Stairs - Concrete	#1 W	6	LF	7	10+ years	Divided out damaged area		
	Exterior Stairs - Concrete	#1 W	7	LF	4	1-2 years	Spalled edge. Divided out damaged		
						,	area		
	Exterior Doors - Exterior FRP Door	#2 W	4	EA	6	6-10 years			
	Exterior Doors - Transom Lite	#2 W	4	EA	6	10+ years			
	Entrance Control - Audio and Video	#3 E	1	EA	7	10+ years			
	Exterior Doors - Exterior FRP Door	#3 E	2	EA	7	10+ years			
	Power Door Operator and Controls	#3 E	1	EA	7	10+ years			
	Entrance Control - Audio and Video	#4 E	1	EA	7	10+ years			
	Exterior Doors - Exterior FRP Door	#4 E	2	EA	6	10+ years			
Foundati									
<u>Foundati</u>	Foundation - Masonry	Entire Building	411	LF	7	10+ years			
	Superstructure - Steel with Clay Tile Arch	Entire Building		SF	7				
	Superstructure - Steel with Clay The Arch	Entire Building	36,905	35	1	10+ years			
Lighting									
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	7	6-10 years			
Roof Sys	stem								
,	Access Ladder - Metal	3 - Upper North Roof	2	EA	7	10+ years			
	Coping - Stone	3 - Upper North Roof	336	LF	6	10+ years			
	Downspouts - Interior Downspouts	3 - Upper North Roof	216	LF	6	10+ years			
	Parapet - 16" - 30" Height	3 - Upper North Roof	336	LF	7	10+ years			
	Roof - Modified Bitumen	3 - Upper North Roof	7,181	SF	6	10+ years			
	Roof Hatch - Metal	3 - Upper North Roof	2	EA	7	10+ years			
	Roof Structure - Steel with Clay Tile Arch	3 - Upper North Roof	7,181	SF	7	10+ years			
	Access Ladder - Metal	4 - Lower North Roof	2	EA	7	10+ years			
	Coping - Stone	4 - Lower North Roof	187	LF	6	10+ years			
	Coping - Stone	4 - Lower North Roof	117	LF	6	10+ years			
	Coping - Terra Cotta	4 - Lower North Roof	50	LF	6	10+ years			
	Downspouts - Exterior Downspouts	4 - Lower North Roof	45	LF	6	10+ years			
	Downspouts - Interior Downspouts	4 - Lower North Roof	133	LF	6	10+ years			
	Parapet - 16" - 30" Height	4 - Lower North Roof	304	LF	7	10+ years			



Catego	ry : Exterior		B	Building : Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Roof Hatch - Metal	4 - Lower North Roof	1	EA	7	10+ years			
	Roof Structure - Steel with Clay Tile Arch	4 - Lower North Roof	5,858	SF	7	10+ years			
/alls									
	Cornice - Terra Cotta	Entire Building	411	LF	7	10+ years			
	Exterior Walls - Brick	Entire Building	13,320	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	120	SF	5	10+ years	Open joints		
	Exterior Walls - Stone-Cast	Entire Building	2,421	SF	5	10+ years			
	Exterior Walls - Stone-Cut	Entire Building	1,230	SF	7	10+ years			
	Exterior Walls - Stone-Cut	Entire Building	825	SF	5	10+ years			
/indows									
	Guard - Guards perforated	Entire Building	410	SF	6	10+ years			
	Guard - Guards wire guard	Entire Building	36	SF	6	10+ years			
	Lintels - Steel	Entire Building	14	LF	5	2-5 years			
	Lintels - Stone	Entire Building	54	LF	6	10+ years			
	Lintels - Terra Cotta	Entire Building	132	LF	6	10+ years	Recombined quantities		
	Windows - Decorative	Entire Building	36	SF	6	10+ years	Recombined quantities		
			50	0	0	TOF years			
atego	ry : Electrical		В	uilding	: Additi				
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
•		Location	Quantity	0011	Kank	Replacement	Comments		
nerger	Cy System	Entire Building	7 002	0	6	6.10 years			
	Emergency A/C Power - Corridors and	Entire Building	7,803	SF	6	6-10 years			
	Stairs			~-					
	Emergency A/C Power - Multipurpose Room	Entire Building	5,191	SF	6	6-10 years	Location changed for clarification the Multipurpose Room occupies space on multiple floors of the building.		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	14	EA	6	6-10 years			
	Emergency Battery Packs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	Location changed for clarification the Multipurpose Room occupies space on multiple floors of the building.		
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	5		
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	2	0-1 year	Signs throughout Addition have n		
			12	LA	2	0-i yeai	backup batteries and the building no emergency generator.		
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	Quantity changed as total has be divided/aggregated. Rank, Reas and Priority Rep changed as sigr are equipped with backup batteri		



ry : Electrical Item - Type Exit Signs - Multipurpose Room	Location	B Quantity	UIDING	: Additio	Recommend	
		Quantity	LIOM	_		
		Quantity			Depleasest	Commonto
EXIL SIGHS - WUUUPUIPUSE KOOM		3	EA	Rank 2	Replacement 0-1 year	Comments Signs have no backup batteries and
	Entire Building			2	-	the building has no emergency generator.
Security System - CCTV	Entire Building	36,905	SF	6	6-10 years	
Security System - Intrusion Detection	Entire Building	36,905	SF	6	6-10 years	
rvice						
PA System	Entire Building	36,905	SF	6	6-10 years	Serves Addition and Main.
Distribution						
Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	Some panels in Addition are secured
						shut for safety reasons. Condition verified by Building Engineer.
Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	Some panels in Addition are secure
						shut for safety reasons. Condition verified by Building Engineer.
ry : Fire Protection		в	uildina	· Additio	n	
			unung	. Addition		
Item - Type	Location	Quantity	UOM	Rank		Comments
	Entire Building	36 905	SF.	6	6-10 years	
						FACP is in Main.
	Entire Dunaning	50,500	01	0	o ro years	
ry : Mechanical		В	uilding	: Additio	on	
					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Iling Systems						
Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Mechanical Room	1	EA	6	10+ vears	Location changed for clarification.
Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1				
Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	100		6		
and Ducts				-	,	
Zone Dampers	Mechanical Room	10	EA	4	1-2 years	Location and quantity changed to match current observations. Priority Rep adjusted based on current observations that Dampers are
	rvice PA System istribution Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A ry : Fire Protection Item - Type m Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts	Security System - Intrusion Detection Entire Building rvice PA System Entire Building PA System Entire Building Lighting and Power Panels - 100 A Entire Building Lighting and Power Panels - Above 100 A Entire Building ry : Fire Protection Location Item - Type Location Fire Alarm Strobe Lights Entire Building Fire Alarm_System Entire Building ry : Mechanical Location Item - Type Location M M Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room	Security System - Intrusion Detection Entire Building 36,905 rvice PA System Entire Building 36,905 PA System Entire Building 36,905 istribution	Security System - Intrusion Detection Entire Building 36,905 SF rvice PA System Entire Building 36,905 SF istribution	Security System - Intrusion Detection Entire Building 36,905 SF 6 rvice PA System Entire Building 36,905 SF 6 istribution Ighting and Power Panels - 100 A Entire Building 2 EA 6 Lighting and Power Panels - Above 100 A Entire Building 3 EA 6 ry : Fire Protection Building : Addition Item - Type Location Quantity UOM Rank m	Security System - Intrusion Detection Entire Building 36,905 SF 6 6-10 years pA System Entire Building 36,905 SF 6 6-10 years PA System Entire Building 36,905 SF 6 6-10 years Lighting and Power Panels - 100 A Entire Building 2 EA 6 6-10 years Lighting and Power Panels - Above 100 A Entire Building 3 EA 6 6-10 years ry : Fire Protection Building : Addition Recommend Item - Type Location Quantity VOM Rank Replacement m Fire Alarm Strobe Lights Entire Building 36,905 SF 6 6-10 years Fire Alarm_System Entire Building 36,905 SF 6 6-10 years ry : Mechanical Building : Addition Recommend Recommend Item - Type Location Quantity VOM Rank Replacement Iting Systems Air Handling Unit: Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Mechanical Room 1 EA 5 6-10 years



Catego	ry : Mechanical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Boiler Sy		Location	Quantity		Nalik	Replacement	Comments
	Condensate Pump	Entire Building	1	EA	7	10+ years	Rank, Reason and Priority Rep changed as the pump assembly has been replaced since previous assessment.
	Piping - Condensate Pipe- Steel	Entire Building	200	LF	6	6-10 years	Condensate piping returns back to Main.
	Piping - Steam Pipe- Steel	Entire Building	200	LF	6	6-10 years	Steam is piped in to Addition from Main.
	Steam Traps	Entire Building	16	EA	6	6-10 years	Quantity changed as total has been divided/aggregated; Rank adjusted as steam traps throughout Addition have been subject to upgrade since previous assessment.
Heating			-			- / -	
	Wall Heater - Electric Wall Heater - Electric	Entire Building Entire Building	3 1	EA EA	6 6	6-10 years 6-10 years	Rank, Reason and Priority Rep changed as cover has been replaced since previous assessment.
	Unit Heater - Steam	Entire Building	1	EA	6	6-10 years	
Tempera	ature Control						
•	Pneumatic System	Entire Building	36,905	SF	4	1-2 years	Served by Main. Leaks exist throughout the system with less than a fourth of the devices responding to controls.
	Thermostats - Pneumatic	Entire Building	14	EA	4	1-2 years	Quantity changed as total has been divided/aggregated. Thermostats throughout the building are generally nonresponsive to controls due to leaks and contamination with oil.
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	No visible dataplate. Rank, Reason and Priority Rep changed following repairs completed since previous assessment.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	6	6-10 years	Rank, Reason and Priority Rep changed following repairs completed since previous assessment.



Catego	ry : Plumbing		В	uilding	: Additi		0347 S Ewing AVENOE, Chicago, ie 00017
_						Recommend	
Group	ltem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	36,905	SF	6	6-10 years	Return hot water is piped back to
							Main.
	Domestic Piping-Hot Water from Risers to	Entire Building	36,905	SF	6	6-10 years	Domestic hot and cold water is piped
	Fixtures			0-		0.40	in from Main.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	36,905	SF	6	6-10 years	Domestic hot and cold water is piped
	(Horizontal Lines)	Entire Building	26.005	ог	6	6 10 10000	in from Main.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	36,905	SF	6	6-10 years	Domestic hot and cold water is piped in from Main.
	Sanitary Piping	Entire Building	36,905	SF	6	6-10 years	in nom wain.
	Storm Piping	Entire Building	36,905	SF	6	6-10 years	
	Vent Piping	Entire Building	36,905	SF	6	6-10 years	
	ventriping	Entire Building	30,905	36	0	0-10 years	
Catego	ry : Room		В	uilding	: Additi	on	
Ŭ	•			U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	Main office 1st floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	Main office 1st floor	476	SF	7	10+ years	
	Doors - Transom Window	Main office 1st floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main office 1st floor	1	EA	7	10+ years	
	Floor - Wood	Main office 1st floor	472	SF	6	6-10 years	
	Floor - Wood	Main office 1st floor	4	SF	4	0-1 year	Chipped
	Lighting - Lay-in	Main office 1st floor	8	EA	7	6-10 years	
	Power Distribution	Main office 1st floor	10	EA	7	10+ years	
	Storage/ Closet	Main office 1st floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	Main office 1st floor	710	SF	7	10+ years	
	AC Unit	Principals Office	1	EA	7	10+ years	
	Ceiling - Lay-in	Principals Office	272	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principals Office	1	EA	7	10+ years	
	Floor - Wood	Principals Office	272	SF	7	6-10 years	
	Lighting - Lay-in	Principals Office	5	EA	7	6-10 years	
	Power Distribution	Principals Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Principals Office	593	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Teachers aid break room	170	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Teachers aid break room	14	SF	6	10+ years	Peeling paint
	Doors - Wood Doors inclu hw	Teachers aid break room	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Teachers aid break room	184	SF	7	10+ years	
	Lindation of AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	Teachers aid break room	3	EA	7	6-10 years	
	Lighting - Wall Mounted						
	Power Distribution Walls - Concrete Block	Teachers aid break room Teachers aid break room Teachers aid break room	2 600	EA SF	7 7	10+ years 10+ years	

Gymnasia



Category : Room			Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Balcony Seating	Basement	107	EA	7	10+ years		
	Ceiling - Plaster/Drywall	Basement	5,191	SF	7	10+ years		
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years		
	Doors - Wood Doors inclu hw	Basement	3	EA	6	10+ years		
	Floor - Wood	Basement	5,191	SF	6	10+ years		
	Lighting - Metal Halide/ High Pressure Sodium	Basement	20	EA	7	6-10 years		
	Lighting - Pendent/Surface	Basement	20	EA	7	6-10 years		
	Sound System	Basement	1	EA	7	6-10 years		
	Stage	Basement	860	SF	6	10+ years		
	Stage Curtain	Basement	2	EA	7	10+ years		
	Stage Lighting System	Basement	1	EA	7	6-10 years		
	Stage-Stairs - Wood	Basement	12	LF	6	10+ years		
	Walls - Masonry	Basement	7,297	SF	7	10+ years		
Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	30	SF	7	10+ years		
	Storage Room	1st Floor	30	SF	7	10+ years		
	Vaults	1st Floor	130	SF	7	10+ years		
	Janitor's Closet	3rd Floor	6	SF	5	2-5 years		
	Air Intake Plenums	Basement	1,800	SF	7	10+ years		
	Storage Room	Basement	425	SF	5	10+ years		
Restroor	n							
	Accessories	2nd floor boy's room	242	SF	7	6-10 years		
	Ceiling - Lay-in	2nd floor boy's room	242	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd floor boy's room	242	SF	6	10+ years		
	Floor Drain	2nd floor boy's room	1	EA	7	10+ years		
	Hand Dryer	2nd floor boy's room	2	EA	7	6-10 years		
	Lavatory	2nd floor boy's room	3	EA	6	10+ years		
	Lighting - Lay-in	2nd floor boy's room	5	EA	7	10+ years		
	Partitions	2nd floor boy's room	6	EA	7	10+ years		
	Urinals	2nd floor boy's room	5	EA	6	10+ years		
	Walls - Plaster/Drywall	2nd floor boy's room	45	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd floor boy's room	404	SF	7	10+ years		
	Water Closet	2nd floor boy's room	5	EA	7	10+ years		
	Water Closet	2nd floor boy's room	1	EA	4	1-2 years	Out of order	
	Accessories	2nd floor unisex	. 84	SF	7	6-10 years		
	Ceiling - Lay-in	2nd floor unisex	84	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd floor unisex	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd floor unisex		SF	6	10+ years		
	Floor Drain	2nd floor unisex	1	EA	7	10+ years		
	Hand Dryer	2nd floor unisex	1	EA	7	6-10 years		



Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd floor unisex	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor unisex	60	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd floor unisex	300	SF	7	10+ years	
	Water Closet	2nd floor unisex	1	EA	6	10+ years	
	Accessories	3rd floor boy's room	242	SF	7	6-10 years	
	Ceiling - Lay-in	3rd floor boy's room	242	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boy's room	242	SF	6	10+ years	
	Floor Drain	3rd floor boy's room	1	EA	7	10+ years	
	Hand Dryer	3rd floor boy's room	2	EA	7	6-10 years	
	Lavatory	3rd floor boy's room	2	EA	6	10+ years	
	Lighting - Lay-in	3rd floor boy's room	5	EA	6	10+ years	
	Partitions	3rd floor boy's room	4	EA	7	10+ years	
	Urinals	3rd floor boy's room	4	EA	6	10+ years	
	Urinals	3rd floor boy's room	1	EA	5	1-2 years	Not working
	Walls - Plaster/Drywall	3rd floor boy's room	45	SF	7	10+ years	3
	Walls - Tile Ceramic/ Porcelain	3rd floor boy's room	404	SF	7	10+ years	
	Water Closet	3rd floor boy's room	4	EA	6	10+ years	
	Accessories	Basement unisex	84	SF	7	6-10 years	
	Ceiling - Lay-in	Basement unisex	84	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement unisex	84	SF	7	10+ years	
	Floor Drain	Basement unisex	1	EA	7	10+ years	
	Hand Dryer	Basement unisex	1	EA	7	6-10 years	
	Lavatory	Basement unisex	1	EA	7	10+ years	
	Lighting - Lay-in	Basement unisex	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement unisex	60	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement unisex	300	SF	7	10+ years	
	Water Closet	Basement unisex	1	EA	7	10+ years	
	Accessories	In Principal's Office	48	SF	7	6-10 years	
	Ceiling - Lay-in	In Principal's Office	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Principal's Office	1	EA	7	10+ years	
	Floor - Tile	In Principal's Office	48	SF	6	10+ years	
	Lavatory	In Principal's Office	1	EA	7	10+ years	
	Lighting - Lay-in	In Principal's Office	1	EA	7	6-10 years	
	Partitions	In Principal's Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	In Principal's Office	149	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	In Principal's Office	98	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	In Principal's Office	2	SF	4	0-1 year	Missing tiles
	Water Closet	In Principal's Office	1	EA	7	10+ years	
	Accessories	Teacher's restroom	30	SF	7	6-10 years	
	Ceiling - Lay-in	Teacher's restroom	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Teacher's restroom		EA	7	10+ years	
	Floor - Tile	Teacher's restroom	30	SF	7	10+ years	
	Lavatory	Teacher's restroom		EA	7	10+ years	
			1		1	io+ years	



Catego	ry : Room	В					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Teacher's restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Teacher's restroom	90	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Teacher's restroom	40	SF	7	10+ years	
	Water Closet	Teacher's restroom	1	EA	7	10+ years	

Category : Classroom Building : Addition							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #101 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	32	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	900	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,190	SF	7	10+ years	
Classroo	m #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	910	SF	7	10+ years	
	Chalk Board	1st Floor	26	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	906	SF	6	10+ years	
	Floor - Wood	1st Floor	4	SF	4	1-2 years	Loose boards
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,019	SF	7	10+ years	
Classroo	m #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	32	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	Not previously assessed
	Walls - Plaster/Drywall	1st Floor	1,190	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	• · · · · · · · · · · · · · · · · · · ·
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	910	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	910	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,019	SF	7	10+ years	
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	900	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,190	SF	7	10+ years	
Classroo	m #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	910	SF	7	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	910	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	6	10+ years	
	Marker Board	2nd Floor	4	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,019	SF	7	10+ years	
Classroo	m #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	900	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	900	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years	
		21011001	17	L/\	'	i er years	



Catego	ry : Classroom		В	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,190	SF	7	10+ years	
Classroo	om #300 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	910	SF	7	10+ years	
	Chalk Board	3rd Floor	36	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	910	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,019	SF	7	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	900	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	21	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,190	SF	7	10+ years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	910	SF	7	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	910	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	2	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,019	SF	7	10+ years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Floor - Tile	3rd Floor	5	SF	4	0-1 year	Cracked
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,187	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	3	SF	5	0-1 year	Hole
lassroc	m #Band Room (Music Room)						
	Casework	Basement	8	LF	6	10+ years	
	Ceiling - Lay-in	Basement	1,256	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	, 4	ĒA	6	10+ years	
	Floor - Tile	Basement	1,256	SF	6	10+ years	
	Lighting - Lay-in	Basement	15	EA	7	6-10 years	
	Lighting - Lay-in	Basement	3	EA	5	1-2 years	Lights covered
	Marker Board	Basement	4	LF	7	6-10 years	g
	Storage/ Closet	Basement	374	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,760	SF	7	10+ years	
		Dacomon	1,100	0.		let years	
Catego	ry : Interior		В	uilding	: Additi		
						Recommend	
-	Item Tune	Leastion	Quantity	LIOM	Dank	Deplesement	Commonto
-	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-							Comments
-	Ceiling - Lay-in	1st Floor	1,595	SF	7	10+ years	
-	Ceiling - Lay-in Doors - Transom Window	1st Floor 1st Floor	1,595 48	SF SF	7 7	10+ years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw	1st Floor 1st Floor 1st Floor	1,595 48 10	SF SF EA	7 7 7	10+ years 10+ years 10+ years	
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,595 48 10 1	SF SF EA EA	7 7 7 7	10+ years 10+ years 10+ years 6-10 years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,595 48 10 1,595	SF SF EA EA SF	7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,595 48 10 1,595 16	SF SF EA EA SF EA	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,595 48 10 1,595 16 1,779	SF SF EA EA SF EA SF	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,595 48 10 1,595 16 1,779 1,509	SF SF EA EA SF SF SF	7 7 7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor	1,595 48 10 1,595 16 1,779 1,509 1	SF SF EA SF EA SF SF EA	7 7 7 7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,595 48 10 1,595 16 1,779 1,509 1 1,509	SF SF EA SF EA SF EA SF SF	7 7 7 7 7 7 7 7 7 6	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 1,509 13	SF EA EA SF EA SF EA SF EA EA	7 7 7 7 7 7 7 7 7 6 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 1 1,509 13 1,657	SF SF EA SF EA SF EA SF EA SF EA	7 7 7 7 7 7 7 7 7 6 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 1,509 13	SF SF EA SF EA SF EA SF SF SF	7 7 7 7 7 7 7 7 7 6 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Water Cooler	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 13 1,657 1,509 2	SF EA EA SF EA SF EA SF EA SF EA	7 7 7 7 7 7 7 7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Not previously assessed
Group Corridor	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 13 1,657 1,509	SF SF EA SF EA SF EA SF SF SF	7 7 7 7 7 7 7 7 7 6 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 13 1,657 1,509 2 1,509 13	SF EA EA SF EA SF EA SF EA SF EA SF EA SF EA SF EA	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 13 1,657 1,509 2 1,509 13 1,657	SF SF EA SF EA SF SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 7 7 7 7 7 6	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 13 1,657 1,509 2 1,509 13	SF SF EA SF EA SF SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 13 1,657 1,509 2 1,509 13 1,657	SF SF EA SF EA SF SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 6 7 7 7 6 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor	1,595 48 10 1,595 16 1,779 1,509 1,509 13 1,657 1,509 2 1,509 13 1,657 2,794	SF SF EA SF EA SF SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 6 7 7 6 7 7 6	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	Not previously assessed Not previously assessed
-	Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Water Cooler Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Double Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in Drinking Fountains - Single Water Cooler Floor - Asphalt Floor Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Transom Window	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor	1,595 48 10 1,595 16 1,779 1,509 1 1,509 13 1,657 1,509 2 1,509 13 1,657 2,794 48	SF SFAAFAF SFAFAF SFAFAF SFAF SF SF	7 7 7 7 7 7 7 7 7 6 7 7 6 7 7 6 7	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	Not previously assessed Not previously assessed



Catego	ry : Interior	В	Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile/Sheet	Basement	2,594	SF	7	10+ years		
	Lighting - Pendent/Surface	Basement	25	EA	7	6-10 years		
	Stairs - Wood	Basement	10	LF	7	10+ years		
	Walls - Concrete Block	Basement	270	SF	7	10+ years		
	Walls - Masonry	Basement	1,736	SF	7	10+ years		
	Walls - Plaster/Drywall	Basement	1,682	SF	6	10+ years		
Safety								
,	Camera Viewing Station	East	2	EA	7	6-10 years		
	Security Cameras	East	8	EA	7	6-10 years		
	Security Cameras	East	6	EA	7	10+ years		
Stairs								
	Ceiling - Plaster/Drywall	North	258	SF	7	10+ years		
	Floor - Asphalt	North	516	SF	6	10+ years		
	Handrails	North	404	LF	7	10+ years		
	Lighting - Lay-in	North	2	EA	7	10+ years		
	Lighting - Pendent/Surface	North	2	EA	7	10+ years		
	Stairs - Asphalt	North	472	LF	6	10+ years		
	Walls - Plaster/Drywall	North	3,338	SF	7	10+ years		



Catego	ry : Exterior	В	Building : Modular 1 (6-Classroom)						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Entrance	9								
	Entrance Control - Audio and Video	#10 W	1	EA	7	6-10 years			
	Exterior Doors - Exterior Steel Door	#10 W	2	EA	5	2-5 years			
	Exterior Doors - Exterior Steel Door	#11 E	2	EA	4	0-1 year	Heavily corroded		
	Exterior Stairs - Steel or Aluminum	#11 E	34	LF	6	10+ vears	,		
	Stair Handrail - Steel_Stair Handrail	#11 E	30	LF	7	10+ years			
Foundat	ion								
	Foundation - Concrete	Entire Building	676	LF	6	10+ years			
	Superstructure - Steel	Entire Building	6,676	SF	7	10+ years			
Lighting									
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	1-2 years	Broken cover		
DeefOu									
Roof Sys	Downspouts - Exterior Downspouts	5 - Main Roof	222	LF	6	6.10 years	Corrected questity		
					6	6-10 years	Corrected quantity		
	Downspouts - Exterior Downspouts	5 - Main Roof	20	LF	4	0-1 year	Missing, corroded		
	Roof - EPDM/ Synthetic Rubber	5 - Main Roof	6,676	SF	5	2-5 years			
	Roof Structure - Steel / Metal Deck/ Concrete Topping	5 - Main Roof	6,676	SF	7	10+ years			
Walls									
	Exterior Walls - Hardie Board	Entire Building	2,712	SF	6	6-10 years			
	Exterior Walls - Wood Siding	Entire Building	1,120	SF	4	0-1 year	Holes, cracks		
Windows	8								
	Guard - Guards wire guard	Entire Building	128	SF	5	6-10 years			
	Windows - Sash Aluminum Double-pane	Entire Building	128	SF	6	10+ years			
Catego	ry : Electrical		В	uilding	: Modul	ar 1 (6-Classro	om)		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Emerger	ncy System								
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	6	6-10 years	Quantity changed to match current observations.		
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	Quantity changed to match current observations. Signs have no backup batteries and the building has no		
	Security System - CCTV	Entire Building	6,676	SF	6	6-10 years	emergency generator.		



Catego	ry : Electrical		В	uilding	: Modul	ar 1 (6-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - Intrusion Detection	Entire Building	6,676	SF	6	6-10 years	
<u> Main Se</u>	rvice						
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	6-10 years	
	PA System	Entire Building	6,676	SF	6	6-10 years	Served by Main.
Power D	listribution						
	Lighting and Power Panels - 100 A	1st Floor	3	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (6-Classro	oom)
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonto
Group Fire Alar		Location	Quantity	UCIW	Rank	Replacement	Comments
	Fire Alarm_System	Entire Building	6,676	SF	6	6-10 years	Sprinkler system flow sensor triggers fire alarm.
Sprinkle	r System						
1	Sprinkler Heads	1st Floor	6,676	SF	7	10+ years	
	Sprinkler Piping	1st Floor	6,676	SF	7	10+ years	
	Wet Sprinkler System	1st Floor	6,676	SF	7	10+ years	
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (6-Classro	pom)
Ŭ	•			Ŭ		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control						
	Electric Thermostat	1st Floor	6	EA	6	6-10 years	
Unit Ven	tilation						
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	1st Floor	3	EA	5	6-10 years	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	1st Floor	3	EA	5	6-10 years	Location changed for clarification. Quantity changed as total has been divided/aggregated.
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	7	EA	6	6-10 years	Roof was not directly accessible at the time of assessment due to unreliable climbing means. Rank, Reason and Priority Rep changed based on current observations and per Building Engineer that upgrades

	Schools						0347 S Ewing AVENUE, Chicago, IL 606		
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (6-Classro	om)		
_			•			Recommend	•		
Broup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments have been completed since previou assessment.		
Catego	ry : Plumbing		В	uilding	: Modul	ar 1 (6-Classro	om)		
					_	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
lot Wate									
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	6-10 years	Dataplate inaccessible due to positioning of the equipment. No leaks present. Condition verified b current observations and per review with Building Engineer.		
Piping									
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	6,676	SF	7	10+ years			
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	6,676	SF	7	10+ years			
	Sanitary Piping	Entire Building	6,676	SF	7	10+ years			
	Storm Piping	Entire Building	6,676	SF	6	6-10 years			
	Vent Piping	Entire Building	6,676	SF	7	10+ years			
Catego	ry : Classroom		Building : Modular 1 (6-Classroom)						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
lassroc	om #500 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	810	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Tile	1st Floor	806	SF	6	6-10 years			
	Floor - Tile	1st Floor	4	SF	4	1-2 years	Cracked tile		
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	3	EA	6	6-10 years	Not working		
	Marker Board	1st Floor	12	LF	6	6-10 years			
	Storage/ Closet	1st Floor	31	SF	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	922	SF	7	10+ years			
lassroc	om #501 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	810	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	ĒA	6	10+ years			
	Floor - Tile	1st Floor	798	SF	6	6-10 years			
		1st Floor	12	SF	4	1-2 years	Cracked tile		
	Floor - Tile	151 FIUUI	12	0.		1 2 youro			
	Floor - Tile Lighting - Lay-in	1st Floor	17	EA	7	10+ years			



Catego	ry : Classroom		Building : Modular 1 (6-Classroom)					
-	-			_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage/ Closet	1st Floor	81	SF	5	2-5 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	922	SF	7	10+ years		
lassroc	om #502 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	802	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	8	SF	5	1-2 years	Water stained tile	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years		
	Floor - Tile	1st Floor	700	SF	6	6-10 years		
	Floor - Tile	1st Floor	110	SF	5	1-2 years	Broken tile	
	Lighting - Lay-in	1st Floor	17	ĒA	7	10+ years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	78	SF	7	10+ years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	922	SF	7	10+ years		
lassroo	om #503 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	810	SF	7	10+ years		
	Chalk Board	1st Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years		
	Floor - Tile	1st Floor	780	SF	6	6-10 years		
	Floor - Tile	1st Floor	30	SF	5	1-2 years	Cracked tile	
	Lighting - Lay-in	1st Floor	15	EA	7	10+ years	Oracked life	
	Marker Board	1st Floor	12	LF	6	6-10 years		
	Storage/ Closet	1st Floor	64	SF	5	2-5 years	Stained tile	
	Walls - Plaster/Drywall	1st Floor		SF	5 7		Stamed the	
	Walls - Plastel/Drywall	IST FIOOI	922	эг	1	10+ years		
lassroc	m #504 (Regular Classroom)	. .						
	Ceiling - Lay-in	1st Floor	661	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	6	SF	5	1-2 years	Tile bent from exhaust fan	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	667	SF	6	2-5 years		
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	836	SF	7	10+ years		
assroc	m #505 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	667	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	617	SF	6	6-10 years		
	Floor - Tile	1st Floor	50	SF	4	1-2 years	Cracked tiles	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	836	SF	7	10+ years		



Catego	ry : Room		В	uilding	: Modul	ar 1 (6-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal/ Service Rooms						
	Mechanical/ Service Rooms	Inside the storage room in rm 500	50	SF	7	10+ years	
Restroor	n						
	Accessories	Boys	176	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys	176	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boys	1	EA	6	10+ years	
	Floor - Tile/Sheet	Boys	176	SF	5	6-10 years	
	Floor Drain	Boys	1	EA	4	1-2 years	Appears clogged
	Hand Dryer	Boys	1	EA	7	6-10 years	
	Lavatory	Boys	1	EA	6	10+ years	
	Lavatory	Boys	1	EA	5	1-2 years	Damaged faucet
	Lighting - Pendent/Surface	Boys	2	EA	7	10+ years	
	Partitions	Boys	2	EA	5	2-5 years	
	Urinals	Boys	2	EA	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Boys	429	SF	6	10+ years	
	Water Closet	Boys	1	EA	6	10+ years	
	Water Closet	Boys	1	EA	4	0-1 year	Toilet cracked
	Accessories	Girls	176	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls	176	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Girls	1	EA	6	10+ years	
	Floor - Tile/Sheet	Girls	176	SF	5	6-10 years	
	Floor Drain	Girls	1	EA	7	10+ years	
	Hand Dryer	Girls	1	EA	7	6-10 years	
	Lavatory	Girls	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girls	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls	1	EA	6	10+ years	
	Partitions	Girls	4	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Girls	429	SF	7	10+ years	
	Water Closet	Girls	4	EA	6	10+ years	
` otoro	ry . Intorior		Б	uildina	Modul	or 1 (6 Classic	nom)
Jaleyo	ry : Interior		D	unung	. wouu	ar 1 (6-Classro Recommend	
Crown	Itom - Typo	Location	Quantity		Pank		Commonto

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	728	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	708	SF	5	6-10 years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Cracked tile
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	868	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	6	SF	5	1-2 years	Damaged wall



Matthew Gallistel Elementary Language Academy

	SCHOOIS	10347 S Ewing AVENUE, Chicago, IL 60617					
Catego	ry : Interior	Building : Modular 1 (6-Classroom)					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Safety							
-	Security Cameras	1st Floor	2	EA	7	6-10 years	Corrected quantity
	-					-	




Catego	ry : Exterior	Building : Modular 2 (2-Classroom)						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance	9							
	Entrance Control - Audio and Video	#12 N	1	EA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	#12 N	2	EA	5	2-5 years	Panels added	
	Exterior Stairs - Wood	#12 N	46	LF	6	10+ years		
	Ramp Handrail - Steel_Ramp Handrail	#12 N	97	LF	6	10+ years		
	Ramp Handrail - Wood_Ramp Handrail	#12 N	125	LF	6	10+ years		
	Ramps - Wood Ramp	#12 N	60	LF	7	10+ years		
	Stair Handrail - Steel_Stair Handrail	#12 N	40	LF	7	10+ years		
	Stair Handrail - Wood_Stair Handrail	#12 N	17	LF	7	10+ years		
	Exterior Doors - Exterior Steel Door	#13 S	1	EA	6	6-10 years		
	Exterior Stairs - Wood	#13 S	20	LF	7	10+ years		
	Stair Handrail - Wood_Stair Handrail	#13 S	12	LF	7	10+ years		
	Exterior Doors - Exterior Steel Door	#14 S	1	EA	6	6-10 years		
	Exterior Stairs - Wood	#14 S	20	LF	7	10+ years		
	Stair Handrail - Wood_Stair Handrail	#14 S	12	LF	7	10+ years		
Foundat	ion							
	Foundation - Concrete	Entire Building	313	LF	7	10+ years		
	Superstructure - Steel	Entire Building	2,100	SF	7	10+ years		
Lighting								
0 0	Exterior Lighting - Wall Mounted	Entire Building	3	EA	5	2-5 years		
Roof Sys	stem							
,	Coping - Metal	6 - Main Roof	236	LF	6	10+ years		
	Downspouts - Exterior Downspouts	6 - Main Roof	178	LF	5	2-5 years	Corrected quantity	
	Roof - EPDM/ Synthetic Rubber	6 - Main Roof	3,131	SF	6	6-10 years		
	Roof Structure - Steel / Metal Deck/ Concrete Topping	6 - Main Roof	3,131	SF	7	10+ years		
Walls								
vallə	Exterior Walls - Wood Siding	Entire Building	2,401	SF	5	2-5 years		
	Exterior Walls - Wood Siding	Entire Building	2,401	SF	5 4	0-1 year	Deteriorated wood	
	Exterior Walls - Wood Siding		300	36	4	U-i yeai	Detenorated wood	
Windows	3							
	Guard - Guards wire guard	Entire Building	128	SF	5	2-5 years		
	Windows - Sash Aluminum Double-pane	Entire Building	128	SF	6	6-10 years		



Catego	ry : Electrical		Building : Modular 2 (2-Classroom)							
					_	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Emerger	ncy System									
	Emergency Battery Packs - Corridors and Stairs	1st Floor	1	EA	6	6-10 years	Quantity changed to match current observations that there is one emergency battery pack in the corridor space.			
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	2	0-1 year	Sign has no backup battery and the building has no emergency generato Quantity changed to match current observations that there is one exit sign in the corridor space.			
	Security System - Intrusion Detection	1st Floor	2,100	SF	6	6-10 years				
Main Se		Entiro Duilding	1	۲۸	6	6.10 years	Incoming clastrical power is fad from			
	Main Electrical Service - 800 A and Less than 120/208/3PH	Entire Building	1	EA	6	6-10 years	Incoming electrical power is fed from Modular 1.			
Power D	istribution									
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Quantity changed as total has been divided/aggregated. Rank, Reason and Priority Rep changed as open fuse receptacles expose live conductors presenting a live front condition.			
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years				
0-1	m. Fina Bratastian				. M					
Catego	ry : Fire Protection		В	unaing	: woau	ar 2 (2-Classro Recommend	om)			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Fire Alar			j							
	Fire Alarm Panel	Entire Building	1	EA	3	2-5 years	Rank, Reason and Priority Rep changed as the panel is 20-plus years old, is functional and passes inspection, but it is beyond its anticipated service life.			
	Fire Alarm_System	Entire Building	2,100	SF	4	2-5 years	Reason and Priority Rep changed as the system is 20-plus years old, is functional and passes inspection, but it is beyond its anticipated service life			



Catego	ry : Mechanical		Building : Modular 2 (2-Classroom)						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	ature Control	Location	Quantity		Nalik	Replacement	Comments		
Tempera	Electric Thermostat	1st Floor	4	EA	6	6-10 years	Quantity changed to match current observations.		
Unit Ver	tilation								
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	1st Floor	2	EA	6	6-10 years	Location changed for clarification.		
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	1st Floor	2	EA	6	6-10 years			
Ventilati	on								
	Exhaust Fans- Indoor - Less than 500 CFM Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building Entire Building	2 4	EA EA	6 6	6-10 years 6-10 years	Not directly accessible in a safe manner at the time of assessment due to unreliable climbing means. Condition verified by Building Engineer.		
Catego	ry : Plumbing		В	uilding	: Modul	ar 2 (2-Classro	pom)		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Hot Wat	er Electric Heater - Less than 20 KW	1st Floor	1	EA	6	6-10 years	Water heater was inaccessible at the time of assessment due to a large quantity of stored materials blocking the unit. No signs of leakage in the area around the unit. Heater is operational based on the availability of hot water; condition of the unit verified by Building Engineer.		
Piping					7	10+ years			
	Domestic Piping-Hot/Cold Water Supply	Entire Building	2,100	SF	7	TO+ years			
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	Entire Building	2,100 2,100	SF	7	10+ years			
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	-				-			
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping	Entire Building Entire Building Entire Building	2,100 2,100 2,100	SF SF SF	7 7 6	10+ years 10+ years 6-10 years			
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping Vent Piping	Entire Building	2,100 2,100 2,100 2,100	SF SF SF SF	7 7 6 7	10+ years 10+ years 6-10 years 10+ years			
Catego Group	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping Vent Piping	Entire Building Entire Building Entire Building	2,100 2,100 2,100 2,100	SF SF SF SF	7 7 6 7	10+ years 10+ years 6-10 years 10+ years ar 2 (2-Classro	oom) Comments		





Building : Modular 2 (2-Classroom) **Category : Classroom** Recommend Quantity Group Item - Type Location UOM Rank **Replacement** Comments Doors - Wood Doors inclu hw 1st Floor 2 ΕA 6 10+ years Floor - Tile 1st Floor 1.079 SF 6 10+ years Floor - Tile 1st Floor 31 SF 4 1-2 years Cracked and damaged tile Lighting - Lay-in 1st Floor 15 ΕA 7 10+ years Walls - Vinyl Coated Gypsum Panel SF 1st Floor 1,260 6 10+ years Work Sink 1st Floor ΕA 7 10+ years 1 Classroom #111 (Pre School) 1st Floor LF Casework 3 6 6-10 years SF Ceiling - Lay-in 1st Floor 1,110 6 10+ years Doors - Wood Doors inclu hw 1st Floor ΕA 6 10+ years 2 Floor - Tile 1st Floor 1,104 SF 6 10+ years SF Floor - Tile 1st Floor 1-2 years 6 4 Cracked and damaged tile Lighting - Lay-in 1st Floor 15 ΕA 7 10+ years Walls - Vinyl Coated Gypsum Panel 1.260 SF 10+ years 1st Floor 6 Work Sink 1st Floor ΕA 7 10+ years 1 **Category : Interior** Building : Modular 2 (2-Classroom) Recommend Location **Replacement** Comments Item - Type Quantity UOM Rank Group Corridor Ceiling - Lay-in 1st Floor SF 50 6 10+ years Floor - Tile/Sheet 1st Floor 50 SF 4 1-2 years Damaged tile 7 Lighting - Lay-in 1st Floor 1 EΑ 10+ years Walls - Vinyl Coated Gypsum Panel 1st Floor 200 SF 7 10+ years



Catego	ry : Site		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ivil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	7	10+ years	
	-					·	
Fencing							
	Fencing - Chain Link	Entire Site	286	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	615	LF	7	10+ years	
andsca	20						
_anusca	Benches	Entire Site	6	EA	7	10+ years	
	Landscape - Grass	Entire Site	3,197	SF	7	10+ years	
	Parkway trees	Entire Site	30	EA	6	10+ years	
	Parkway trees	Entire Site	3	EA	4	0-1 year	Missing
	Planting Beds/ Area	Entire Site	1,900	SF	6	10+ years	lineenig
	Play Area - Hardscape- Asphalt	Entire Site	9,308	SF	7	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	1,000	SF	5	2-5 years	
	Play Area - Synthetic Turf	Entire Site	5,000	SF	7	10+ years	New
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
			2	L/(Ū	for years	
Parking I							
	Concrete Curbs	Parking Lot- East	110	LF	7	10+ years	
	Interior Plantings	Parking Lot- East	80	LF	6	10+ years	
	Lighting - Pole Mounted	Parking Lot- East	6	EA	6	10+ years	
	Surface - Asphalt	Parking Lot- East	7,159	SF	6	6-10 years	Repaved, recombined quantities
	Trash Enclosure - Chain Links	Parking Lot- East	426	SF	7	10+ years	Recombined quantities
	Vehicular Screening	Parking Lot- East	30	LF	7	10+ years	Not previously assessed
Playgrou	ind						
	Equipment - Combo 3-12	Playground	1	EA	7	10+ years	New
	Equipment - School Age 5-12	Playground	1	EA	7	10+ years	New
	Surface - Poured Surface	Playground	3,500	SF	7	10+ years	New
Didawall							
Sidewalk		Easting Site	0.000	0-	0	10	
	Sidewalks - Perimeter Sidewalks	Entire Site	8,692	SF	6	10+ years	
Signage							
0 -0-	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back lighted w/	Entire Site	1	EA	7	6-10 years	
	LED				-		
	Monument - Building Mounted Cut Letter	Entire Site	1	EA	7	10+ years	
	Sign				-	· , · · · ·	

Chicago Public Schools		Matthew Gallistel Elementary Language Academy 10347 S Ewing AVENUE, Chicago, IL 60617
Category : Site		Building : Site
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Deem	Floor Plan	A	Glazed	Operable		Crossert
Current Usage	Intended Usage	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Window Stop	Smart- Board
Building : Main	Intended Usage	Room Location	Number	Number	(37)	Aled	Aled	Stop	Buaru
Kindergarten	Regular Classroom	1st Floor	105	105	900	138	69	N	Y
Kindergarten	Regular Classroom	1st Floor	106	106	891	138	69	N	Y
Library	Regular Classroom	2nd Floor	205	205	900	138	69	N	N
Office	Regular Classroom	1st Floor	104 -	104	860	184	92	N	Y
	rtegalar elacereent		Moved to	101	000	101	02		
Regular Classroom	Kindergarten	1st Floor	108	108	860	138	69	N	Y
Regular Classroom	Kindergarten	1st Floor	109	109	900	138	69	N	Y
Regular Classroom	Play Room	1st Floor	107	107	900	138	69	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	860	138	69	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	860	138	69	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	900	138	69	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	860	138	69	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	900	138	69	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	720	138	69	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	900	138	69	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	682	138	69	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	900	138	69	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	860	138	69	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	900	138	69	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	664	138	69	N	Y
Building : Addition				I		1	I		T
Kindergarten	Regular Classroom	1st Floor	101	101	900	210	155	Y	Y
Music Room	Music Room	Basement	Band Room	G127	1,256	0	0	N	Y
Regular Classroom	Regular Classroom	1st Floor	102	102	910	175	87	N	Y
Regular Classroom	Regular Classroom	1st Floor	103	103	900	210	155	N	Y
Regular Classroom	Regular Classroom	2nd Floor	200	200	910	175	87	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	900	210	155	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	910	175	87	N	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	900	210	155	N	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	910	175	87	N	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	900	210	155	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	910	175	87	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	900	210	155	Ν	Y
Building : Modular 2 (2-Cla	ssroom)								
Pre School	Pre School	1st Floor	110	West room	1,110	36	24	N	Y
Pre School	Pre School	1st Floor	111	East Room	1,110	36	24	N	Ý



Regular Classroom

Regular Classroom

Ν

Υ

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Modular 1 (6-Cla	ssroom)								
Regular Classroom	Regular Classroom	1st Floor	500	500	810	24	12	N	Y
Regular Classroom	Regular Classroom	1st Floor	501	501	810	24	12	N	Y
Regular Classroom	Regular Classroom	1st Floor	502	502	810	24	12	N	Y
Regular Classroom	Regular Classroom	1st Floor	503	503	810	24	12	N	Y
Regular Classroom	Regular Classroom	1st Floor	504	504	667	24	12	N	N

505

505

667

24

12

1st Floor