

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1895	3	41,588
Addition 1	1934	3	23,364
Addition 2	1967	3	48,387
Campus Total			113,339

Category : Exterior Building : Main

3	, <u> </u>					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	· ·		•			•	
	Exterior Doors - Exterior Steel Door	14	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	14	2	EA	6	6-10 years	
	Exterior Stairs - Stone	14	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	15	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	15	1	EA	6	6-10 years	
	Exterior Stairs - Stone	15	3	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	16	2	EA	5	6-10 years	
	Exterior Doors - Side lite	16	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	16	1	EA	6	6-10 years	
	Exterior Stairs - Stone	16	7	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	6	2	EA	5	2-5 years	
	Exterior Doors - Side lite	6	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	6	2	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	6.5	1	EA	4	0-1 year	Delaminating
	Exterior Doors - Transom Lite	6.5	1	EA	6	10+ years	· ·
	Exterior Doors - Overhead Rolling/ Garage Door	7	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	8	1	EA	6	10+ years	
	Exterior Stairs - Concrete	8	3	LF	5	2-5 years	Large crack and wearing downward towards crack
	Exterior Doors - Exterior Wood Door	9	1	EA	4	0-1 year	Delaminating, rusted frame
	Exterior Doors - Transom Lite	9	1	EA	4	0-1 year	Missing window, rusted frame and

Campus Name: Gresham Page : 1 of 49 Assessment Date: 10/30/2023



Catego	ry : Exterior		uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Stairs - Concrete	9	2	1.5	6	6.10 ,400 00	panel
	Exterior Stairs - Concrete  Exterior Doors - Exterior Steel Door	9 9.5 - Elev. Machine Rm	3	LF EA	_	6-10 years	
	Exterior Doors - Exterior Steel Door	9.5 - Elev. Machine Rm	1	EA	6	10+ years	
oundati	on						
	Foundation - Masonry	Entire Building	588	LF	7	10+ years	
	Foundation - Masonry	Entire Building	20	LF	5	2-5 years	Deteriorating mortar, open joints
	Superstructure - Steel with Clay Tile Arch	Entire Building	26,381	SF	7	10+ years	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	7	10+ years	Replaced
Roof Sys	stem						
	Access Ladder - Metal	A	2	EA	7	10+ years	
	Chimney - Brick Chimney- Stainless Steel	A	80	LF	6	10+ years	
	Liner						
	Coping - Clay Tile	A	279	LF	6	10+ years	
	Coping - Terra Cotta	A	99	LF	6	10+ years	
	Downspouts - Exterior Downspouts	A	122	LF	6	10+ years	
	Parapet - 16" - 30" Height	A	174	LF	7	10+ years	Repaired
	Parapet - Parapet < 16" Height	A	99	LF	7	10+ years	Repaired
	Parapet - Parapet > 30"	A	75	LF	7	10+ years	Repaired
	Roof - Modified Bitumen	A	7,533	SF	7	10+ years	Replaced
	Roof Hatch - Metal	A	1	EA	7	10+ years	Replaced
	Roof Structure - Steel with Clay Tile Arch	A	7,533	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	В	90	LF	6	10+ years	
	Chimney - Metal Flue	В	10	LF	7	10+ years	
	Coping - Stone	В	22	LF	7	10+ years	Repaired
	Coping - Terra Cotta	В	303	LF	7	10+ years	Repaired
	Downspouts - Exterior Downspouts	В	52	LF	6	10+ years	Repaired
	Parapet - Parapet < 16" Height	В	325	LF	7	10+ years	Repaired
	Roof - Modified Bitumen	В	3,350	SF	7	10+ years	Replaced
	Roof Structure - Steel with Clay Tile Arch	В	3,350	SF	7	-	Replaced
		E		SF LF	7	10+ years	Panlagad
	Coping - Metal		24			10+ years	Replaced
	Downspouts - Exterior Downspouts	E	72	LF CF	7	10+ years	Denlesed
	Roof - Modified Bitumen	E	432	SF	7	10+ years	Replaced
	Roof Structure - Steel with Clay Tile Arch	E	432	SF	7	10+ years	
Valls		E # D ##				0.40	
	Cornice - Metal Projecting	Entire Building	431	LF	5	6-10 years	<b>B</b> 11 1 200
	Exterior Walls - Brick	Entire Building	12,449	SF	7	10+ years	Recombined quantities
	Exterior Walls - Stone-Cut	Entire Building	2,410	SF	5	10+ years	



Catego	Category : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Window	e						
VVIIIGOVV	Guard - Guards perforated	Entire Building	398	SF	6	10+ years	
	Lintels - Steel	Entire Building	3	LF	6	10+ years	
	Lintels - Stone	Entire Building	307	LF	6	10+ years	
	Windows - Decorative	Entire Building	52	SF	6	10+ years	
		•	36	SF	6		
	Windows - Louver	Entire Building		_	-	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,306	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
Croun	Ham Tune	Location	Ouantitu	HOM	Donk	Recommend	Comments
Group	Item - Type ncy System	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	Emergency A/C Power - Corridors and	Entire Building	7,132	SF	6	6-10 years	Priority Rep adjusted based on
	Stairs	Littile building	1,132	OI.	O	0-10 years	current observations and per review
	Clairo						with Building Engineer.
	Exit Signs - Corridors and Stairs	Entire Building	15	EA	2	0-1 year	Not equipped with backup batteries,
	ZAR GIGITO GOTTAGIO ATTA GLATIO	Emile Bananig	.0	_, .	_	o i you	and the school has no emergency
							generator.
	Security System - CCTV	Entire Building	41,588	SF	5	6-10 years	generator.
	Security System - Intrusion Detection	Entire Building	41,588	SF	5	6-10 years	
			•	EA	6		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	13	EA	О	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years	
Main Se	rvice						
	Independent Electrical Service for	Basement	1	EA	6	6-10 years	Serves the fire pump and sprinkler
	emergency power					,	system.
	PA System	Entire Building	45,206	SF	4	2-5 years	Served by Addition 2. Reason and
	. A Cyclem	Emile Bananig	10,200	O.	•	2 o youro	Priority Rep adjusted to confirm that
							the system does not have reliable
							communication with all parts of the
							school.
Dover 5	Note in the second						
<u>Power L</u>	Distribution	Fating Duit !!				0.4	Deals December 151 11 5
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Rank , Reason and Priority Rep
							changed as missing interior cover
							plate exposes live conductors
							presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	6	6-10 years	Some panels secured shut for safety
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	6-10 years	Some panels secured shut for safety
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	·
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	

Campus Name: Gresham Page : 3 of 49 Assessment Date: 10/30/2023



Catego	ry : Electrical		E	Building	: Main		•
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Catego	ry : Fire Protection		Е	Building	: Main		
			0	11014	<b>5</b>	Recommend	•
Group Fire Alar	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
File Aldi	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	26,381 26,381	SF SF	6 6	6-10 years 6-10 years	FACP is in Addition 2. Priority Rep adjusted based on the age of the system.
	Fire Pump Controller	Entire Building	1	EA	4	2-5 years	Reason and Priority Rep adjusted to appropriately reflect that the equipment has exceeded its EUL.
Pump Ro	oom Assembly						
·	Fire Pump - 25-50 hp	Pump Room	1	EA	5	2-5 years	Antiquated equipment which is free of leaks and passes inspection but has exceeded its EUL.
Sprinkle	System						
	Dry Sprinkler System	Entire Building	41,588	SF	6	6-10 years	Location changed for clarification. Serves Main only.
	Sprinkler Heads Sprinkler Piping	Entire Building Entire Building	41,588 41,588	SF SF	7 6	2-5 years 6-10 years	Location changed for clarification.
Catego	ry : Mechanical		Е	Building	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	lling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Basement	1	EA	6	6-10 years	VS-1. Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment. Older, well- maintained equipment.
	Air Intake	Basement	1	EA	5	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment. Dampers upgraded since previous assessment.
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Return Duct Work - Masonry and Ducts-	Basement	100	LF	6	6-10 years	Rank, Reason and Priority Rep
Campus I	Name: Gresham		Page : 4 of 49				Assessment Date: 10/30/20



Catego	ategory : Mechanical		В	Building : Main			
			0		<b>.</b>	Recommend	•
Group	Item - Type Missing or Existing Shaft	Location	Quantity 16	<b>UOM</b> EA	Rank 5	Replacement	changed as there was no noteworthy issue observed at the time of assessment.
	Zone Dampers	Basement	16	EA	5	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment. The dampers are operational when adjusted manually.
Boiler Sv	vstems						
•	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Entire Building	2	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Chemical Feed System	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Combustion Dampers	Entire Building	2	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Condensate Pump	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Condensate Pump	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Feed Water Pumps and Tank	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Entire Building	1	EA	6	2-5 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Entire Building	1	EA	4	1-2 years	Currently offline, per engineer
	Piping - Condensate Pipe- Steel	Entire Building	300	LF	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.

Campus Name: Gresham Page : 5 of 49 Assessment Date: 10/30/2023



Catego	ry : Mechanical	_	В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Piping - Steam Pipe- Steel	Entire Building	300	LF	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Steam Traps	Entire Building	24	EA	6	6-10 years	
Heating	Devices						
	Unit Heater - Gas	Basement	1	EA	7	10+ years	
	Unit Heater - Gas	Basement	1	EA	2	0-1 year	Unit is nonfunctional.
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	6	EA	5	2-5 years	Quantity changed as total has been
		· ·	1		-	-	divided/aggregated.
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Quantity changed based on current observations and as total has been divided/aggregated. Rank, Reason and Priority Rep changed as the missing front cover exposes live conductors presenting a live front condition.
_Tempera	ture Control						
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	
	Pneumatic System	Entire Building	45,206	SF	3	0-1 year	Also intended to serve Addition 1.  System is nonfunctional.
	Thermostats - Pneumatic	Entire Building	9	EA	4	0-1 year	Reason and Priority Rep adjusted as all pneumatic thermostats are nonfunctional.
	Thermostats - Pneumatic	Entire Building	7	EA	4	0-1 year	Reason and Priority Rep adjusted as all pneumatic thermostats are nonfunctional.
Ventilation	n						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roofs	1	EA	7	6-10 years	Item Type changed to match current observations. Quantity changed as total has been divided/aggregated. Rank, Reason and Priority Rep changed as unit was replaced since previous assessment.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roofs	2	EA	6	6-10 years	Lower roofs were not accessible in a safe manner at the time of assessment due to unreliable climbing means. Condition of fans confirmed by Building Engineer.



Catego	ry : Mechanical		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Catego	ry : Plumbing		В	uilding	: Main		
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ioi vvaie	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Serves Main and Addition 1.
Piping							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	41,588	SF	4	2-5 years	Much of the the domestic piping shows signs of age-related degradation and has exceeded its EUL.
	Domestic Piping-Hot Water Return Risers	Entire Building	41,588	SF	4	2-5 years	Much of the the domestic piping shows signs of age-related degradation and has exceeded it EUL.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	41,588	SF	4	2-5 years	Much of the the domestic piping shows signs of age-related degradation and has exceeded it EUL.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	41,588	SF	4	2-5 years	Much of the the domestic piping shows signs of age-related degradation and has exceeded it EUL.
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	41,588	SF	4	2-5 years	Much of the the domestic piping shows signs of age-related degradation and has exceeded it EUL.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	41,588	SF	4	2-5 years	Much of the the domestic piping shows signs of age-related degradation and has exceeded it EUL.
	Sanitary Piping	Entire Building	41,588	SF	5	2-5 years	- <del>-</del>
	Storm Piping	Entire Building	41,588	SF	5	2-5 years	
	Vent Piping	Entire Building	41,588	SF	5	2-5 years	
oumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	5	6-10 years	
Catego	ry : Room		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Page: 7 of 49 Campus Name: Gresham Assessment Date: 10/30/2023



Catego	ry : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	AC Unit	007	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	007	572	SF	6	10+ years			
	Doors - Wood Doors inclu hw	007	1	EΑ	6	10+ years			
	Floor - Wood	007	572	SF	5	2-5 years	Floor heavily worn with no protective coating		
	Lighting - Pendent/Surface	007	8	EA	6	10+ years	•		
	Power Distribution	007	2	EA	7	10+ years			
	Walls - Masonry	007	791	SF	6	10+ years			
	Walls - Masonry	007	100	SF	5	1-2 years	Spalled broken motar		
Lunch &	Multipurpose Room								
	Ceiling - Plaster/Drywall	009	772	SF	7	10+ years			
	Floor - Wood	009	772	SF	7	10+ years			
	Lighting - Pendent/Surface	009	10	ĒΑ	7	6-10 years			
	Walls - Masonry	009	237	SF	7	10+ years			
	Walls - Masonry	009	130	SF	5	1-2 years	Damage across bottom third of masonry walls		
	Walls - Plaster/Drywall	009	309	SF	7	10+ years	masonly wans		
	Ceiling - Exposed	010 - Kitchen Storage	1,140	SF	7	6-10 years			
	Floor - Tile		,	SF	7				
	Floor - Tile Floor - Tile	010 - Kitchen Storage	990	SF SF		10+ years	Domogod tile		
		010 - Kitchen Storage	150		4	0-1 year	Damaged tile		
	Lighting - Pendent/Surface Walls - Masonry	010 - Kitchen Storage 010 - Kitchen Storage	15 1,142	EA SF	7 7	6-10 years 10+ years			
MDF ID	F								
	Doors - Wood Doors inclu hw	102	1	EA	7	10+ years			
	Finishes	102	303	SF	7	10+ years			
	Finishes	102	15	SF	5	1-2 years	Broken ceiling tiles		
	Window AC Unit	102	2	EA	7	6-10 years	Replaced		
Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	17	SF	5	10+ years	Damaged ceiling		
	Janitor's Closet	2nd Floor	17	SF	7	10+ years	3		
	Janitor's Closet	3rd Floor	17	SF	7	10+ years			
	Storage Room	3rd Floor	16	SF	7	10+ years			
	Air Intake Plenums	Basement	220	SF	7	10+ years			
	Boiler Room	Basement	1,241	SF	5	1-2 years	Spalling and missing mortar along exterior walls		
	Coal Room	Basement	495	SF	7	10+ years	EXIGNOL WAIIS		
	Mechanical/ Service Rooms			SF SF	7				
		Basement	765	SF SF		10+ years			
	Mechanical/ Service Rooms	Basement	74		7	10+ years			
	Mechanical/ Service Rooms	Basement	125	SF SF	7	10+ years 10+ years			
	Mechanical/ Service Rooms	Basement	225	CL	7				



Catego	ry : Room		В	uilding	: Main		
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	Basement	84	SF	7	10+ years	
	Storage Room	Basement	291	SF	7	10+ years	
estroor	n						
	Accessories	007A - Engineer's Toilet	100	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	007A - Engineer's Toilet	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	007A - Engineer's Toilet	1	EΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	007A - Engineer's Toilet	100	SF	7	10+ years	
	Lavatory	007A - Engineer's Toilet	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	007A - Engineer's Toilet	1	EA	5	6-10 years	Cover missing
	Partitions	007A - Engineer's Toilet	1	EA	5	6-10 years	3
	Walls - Plaster/Drywall	007A - Engineer's Toilet	82	SF	6	2-5 years	
	Walls - Plaster/Drywall	007A - Engineer's Toilet	70	SF	4	0-1 year	Damage to bottom half of wall throughout
	Water Closet	007A - Engineer's Toilet	1	EA	6	6-10 years	inoughout
	Accessories	2nd Floor - Unisex	300	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Unisex	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Unisex	290	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Unisex	10	SF	4	0-1 year	Missing tile
	Floor Drain	2nd Floor - Unisex	10	EA	7		Missing tile
	Hand Dryer	2nd Floor - Unisex	1	EA	7	10+ years	
					7	6-10 years	
	Lavatory	2nd Floor - Unisex	1	EΑ		6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Unisex	3	EΑ	7	6-10 years	
	Partitions	2nd Floor - Unisex	3	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Unisex	925	SF	7	10+ years	
	Water Closet	2nd Floor - Unisex	3	EA	7	10+ years	
	Accessories	3rd Floor - Unisex	300	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor - Unisex	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor - Unisex	300	SF	7	10+ years	
	Floor Drain	3rd Floor - Unisex	1	EA	7	10+ years	
	Hand Dryer	3rd Floor - Unisex	1	EA	7	6-10 years	
	Lavatory	3rd Floor - Unisex	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor - Unisex	4	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor - Unisex	920	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor - Unisex	5	SF	4	0-1 year	Missing tile
	Water Closet	3rd Floor - Unisex	1	EA	7	10+ years	
	Accessories	Basement - NW	662	SF	4	0-1 year	Removed
	Ceiling - Plaster/Drywall	Basement - NW	662	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - NW	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement - NW	662	SF	6	10+ years	
	Floor Drain	Basement - NW	2	EA	7	10+ years	
	Hand Dryer	Basement - NW	1	EA	7	6-10 years	



Catego	ry : Room	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Basement - NW	2	EA	4	0-1 year	Removed
	Lighting - Pendent/Surface	Basement - NW	9	EA	6	10+ years	
	Partitions	Basement - NW	4	EA	7	6-10 years	
	Urinals	Basement - NW	11	EA	6	6-10 years	
	Urinals	Basement - NW	1	EA	4	0-1 year	Removed
	Walls - Structural Glazed Tile	Basement - NW	1,400	SF	6	10+ years	
	Water Closet	Basement - NW	1	EA	6	6-10 years	
	Water Closet	Basement - NW	3	EA	4	0-1 year	Removed
	Accessories	Basement - SW	531	SF	7	6-10 years	
	Ceiling - Exposed	Basement - SW	531	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - SW	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement - SW	531	SF	6	10+ years	
	Floor Drain	Basement - SW	1	EA	7	10+ years	
	Hand Dryer	Basement - SW	1	EA	7	6-10 years	
	Lavatory	Basement - SW	5	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Basement - SW	6	EA	7	10+ years	
	Partitions	Basement - SW	11	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement - SW	1,068	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement - SW	77	SF	6	10+ years	
	Water Closet	Basement - SW	11	EΑ	6	6-10 years	

Category : Classroom **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #104 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,005	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,025	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,150	SF	7	10+ years	
_Classro	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,005	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,025	SF	7	10+ years	

Campus Name: Gresham Page : 10 of 49 Assessment Date: 10/30/2023



					: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	14	EΑ	7	6-10 years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Storage/ Closet	1st Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	946	SF	7	10+ years	
Classroc	om #106 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,005	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	7	10+ years	
	Chalk Board	1st Floor	28	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	1,008	SF	7	10+ years	
	Floor - Tile	1st Floor	12	SF	5	1-2 years	Damaged tile
	Lighting - Lay-in	1st Floor	14	EΑ	7	6-10 years	zamagea me
	Storage/ Closet	1st Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,150	SF	7	10+ years	
Classroo	om #107 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,005	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	1,025	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,150	SF	7	10+ years	
Classroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	963	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	1-2 years	Water damaged tile
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	7	10+ years	<del></del>
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,015	SF	7	10+ years	
	Floor - Tile	2nd Floor	10	SF	6	6-10 years	Repaired
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	Topanou



Catego	ry : Classroom		В	uilding	: Main		· · · · · · · · · · · · · · · · · · ·
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	170	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	1-2 years	Minor cracks on back wall
_Classroo	m #205 (Vacant)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	995	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	7	10+ years	
	Chalk Board	2nd Floor	12	ĹF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	1,025	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,150	SF	7	10+ years	
	Walls Tlaster/Bry Wall	2110 1 1001	1,100	O.	,	101 years	
Classroo	m #206 (Vacant)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	995	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,017	SF	7	10+ years	
	Floor - Tile	2nd Floor	. 8	SF	6	6-10 years	Repaired
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	•
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,150	SF	7	10+ years	
Classroo	m #207 (Vacant)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	995	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,025	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
		2110 1 1001	10		•	o lo youlo	



Catego	ory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage/ Closet	2nd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,150	SF	6	10+ years	
Classro	om #304 (Art Room)						
Oldooro	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	32	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	985	SF	7	6-10 years	
	Ceiling - Lay-iii Ceiling - Plaster/Drywall	3rd Floor	40	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6		
		3rd Floor		SF		10+ years	
	Floor - Tile		1,025		6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,150	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
Classro	om #305 (Play Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	985	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	40	SF	7	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,025	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,150	SF	7	10+ years	
Classro	om #306 (Play Room)						
J140010	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	985	SF	7	6-10 years	
	Ceiling - Lay-iii Ceiling - Plaster/Drywall	3rd Floor	40	SF	7	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years	
	Doors - Transom Window  Doors - Wood Doors inclu hw	3rd Floor	15	Sr EA	7		
	Floor - Tile	3rd Floor	1,025	SF	7	10+ years	
			•			10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,150	SF	7	10+ years	



Catego	ry : Classroom	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #307 (Store Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	985	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	40	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,005	SF	7	10+ years	
	Floor - Tile	3rd Floor	10	SF	5	1-2 years	Damaged tile
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,150	SF	7	10+ years	

**Category**: Interior **Building: Main** 

Juicgo.	y . IIII <del>e</del> i 101			ununng	. Iviaiii		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor	item - Type	Location	Quantity	OOW	Ivalik	Replacement	Comments
JOHNGOL	Ceiling - Plaster/Drywall	1st Floor	1,220	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1,220	EA	7	6-10 years	
	Floor - Wood	1st Floor	1,220	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1,220	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,655	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,220	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1,220	EA	7	6-10 years	
	Floor - Wood	2nd Floor	1,220	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	2,655	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	
	Floor - Wood	3rd Floor	1,220	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	2,655	SF	7	10+ years	
	Ceiling - Exposed	Basement - North	1,000	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement - North	1,000	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - North	10	ĒΑ	6	6-10 years	
	Walls - Masonry	Basement - North	780	SF	7	10+ years	
	Walls - Masonry	Basement - North	30	SF	5	1-2 years	Crack/damaged wall
	Walls - Plaster/Drywall	Basement - North	740	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - North	40	SF	4	0-1 year	Water Damaged wall
	Ceiling - Exposed	Basement - South	780	SF	7	10+ years	S
	Doors - Steel Doors incl hw	Basement - South	2	ĒΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement - South	780	SF	7	10+ years	

Campus Name: Gresham Page : 14 of 49 Assessment Date: 10/30/2023



Catego	ry : Interior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Basement - South	3	EA	7	6-10 years	
	Walls - Concrete Block	Basement - South	50	SF	7	10+ years	
	Walls - Masonry	Basement - South	470	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - South	370	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule - North East	92	SF	7	10+ years	
	Doors - Transom Window	Vestibule - North East	30	SF	6	10+ years	
	Doors - Wood Doors include hw	Vestibule - North East	4	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Vestibule - North East	92	SF	7	10+ years	
	Lighting - Pendent/Surface	Vestibule - North East	1	EA	6	6-10 years	
	Walls - Masonry	Vestibule - North East	230	SF	7	10+ years	
	Walls - Plaster/Drywall	Vestibule - North East	15	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule - South East (door 16)	100	SF	7	10+ years	
	Doors - Steel Doors incl hw	Vestibule - South East (door 16)	2	EA	7	10+ years	
	Doors - Transom Window	Vestibule - South East (door 16)	16	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Vestibule - South East (door 16)	100	SF	7	10+ years	
	Lighting - Pendent/Surface	Vestibule - South East (door 16)	1	EΑ	7	6-10 years	
	Walls - Masonry	Vestibule - South East (door 16)	450	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule - South West (door 6)	100	SF	7	10+ years	
	Doors - Steel Doors incl hw	Vestibule - South West (door 6)	2	EA	7	10+ years	
	Doors - Transom Window	Vestibule - South West (door 6)	16	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Vestibule - South West (door 6)	100	SF	7	10+ years	
	Lighting - Pendent/Surface	Vestibule - South West (door 6)	1	EA	7	6-10 years	
	Walls - Masonry	Vestibule - South West (door 6)	450	SF	7	10+ years	
Safety							
,	Security Cameras	1st Floor	5	EA	7	6-10 years	
Stairs							
_StallS	Ceiling - Exposed	North East	990	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North East	494	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	North East	950	SF	7	10+ years	
	Handrails	North East	162	LF	7	10+ years	
	Lighting - Pendent/Surface	North East	12	EA	7	6-10 years	
	Stairs - Tile	North East	540	LF	6	10+ years	
	Walls - Plaster/Drywall	North East	4,170	SF	7	10+ years	
	Ceiling - Exposed	South	850	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	340	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	South	450	SF	7	10+ years	
	Handrails	South	162	LF	7	10+ years	
	Lighting - Pendent/Surface	South	5	EA	7	6-10 years	
	Stairs - Tile	South	552	LF	6	10+ years	
	Walls - Plaster/Drywall	South	2,900	SF	7	10+ years	
	•						

Page : 15 of 49 Campus Name: Gresham Assessment Date: 10/30/2023





Category : Exterior **Building: Addition 1** 

				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance			•			<u>-</u>	
	Exterior Doors - Exterior Wood Door	10	1	EA	4	0-1 year	Heavily delaminated and warped
	Exterior Stairs - Concrete	10	12	LF	6	10+ years	, , , , , , , , , , , , , , , , , , , ,
	Exterior Stairs - Stone	10	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	11 - Fire Escape	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	12	1	EA	6	10+ years	
	Exterior Stairs - Concrete	12	10	LF	6	10+ years	
	Exterior Stairs - Stone	12	3	LF	6	10+ years	
	Entrance Control - Audio and Video	13	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	13	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	13	4	EA	6	10+ years	
	Exterior Stairs - Stone	13	6	LF	6	10+ years	
	Power Door Operator and Controls	13	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	13	40	LF	7	10+ years	
	Ramps - Concrete	13	20	LF	7	10+ years	
Fire Esca	ape						
	Exterior Doors - Exterior Steel Door	West end, South elevation	1	EA	6	10+ years	
	Fire Escape	West end, South elevation	47	LF	6	10+ years	Bottom section was formerly a swing section but is now fixed down
	Paints	West end, South elevation	47	LF	5	6-10 years	Section but is now liked down
Foundation	on						
	Foundation - Concrete	Entire Building	403	LF	7	10+ years	No exposed foundation
	Superstructure - Steel with Clay Tile Arch	Entire Building	18,825	SF	7	10+ years	No exposed superstructure
Liabtina							
Lighting	Exterior Lighting - Wall Mounted	Entire Building	2	EA	7	10+ years	New
	Exterior Lighting - Wall Mounted	Entire Building	7	EΑ	6	10+ years	11011
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	0-1 year	Broken
Roof Syst	tem						
TOOL CYO	Access Ladder - Metal	С	1	EA	3	10+ years	Only goes to attic now, hatch was
	Coping - Terra Cotta	С	271	LF	7	10+ years	removed Repaired
	Downspouts - Interior Downspouts	C	122	LF	6	10+ years	Repaired
	Parapet - 16" - 30" Height	C	271	LF	7	10+ years	Repaired
	Roof - Modified Bitumen	C	4,047	SF	7	10+ years	Replaced
	Roof Structure - Steel with Clay Tile Arch	C	4,047	SF	7	10+ years	Replaced
	Access Ladder - Metal	D	1,047	EA	7	10+ years	
	Coping - Terra Cotta	D	195	LF	7	10+ years	Repaired
	Downspouts - Interior Downspouts	D	108	LF	6	10+ years	Nopuliou

Campus Name: Gresham Page : 16 of 49 Assessment Date: 10/30/2023



	ry : Exterior		В	uilding	: Additi	on 1	
						Recommend	
<b>3roup</b>	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	D	195	LF	7	10+ years	Repaired
	Roof - Modified Bitumen	D	3,042	SF	7	10+ years	Replaced
	Roof Structure - Steel with Clay Tile Arch	D	3,042	SF	7	10+ years	
Valls							
	Cornice - Metal Projecting	Entire Building	1,084	LF	5	6-10 years	Rusted
	Exterior Walls - Brick	Entire Building	8,450	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	7,515	SF	6	10+ years	
Vindow	S						
	Guard - Guards perforated	Entire Building	232	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	50	SF	6	6-10 years	
	Lintels - Steel	Entire Building	12	LF	5	10+ years	
	Lintels - Stone	Entire Building	262	LF	6	10+ years	
	Windows - Decorative	Entire Building	188	SF	6	10+ years	
	Windows - Louver	Entire Building	24	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,855	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merge	ncy System						
				~-	_		
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,400	SF	6	6-10 years	
	Aisle Lighting Emergency Battery Packs - Auditoium and	Entire Building Entire Building	3,400 5	SF EA	6 6	6-10 years 6-10 years	Quantity changed based on curren observations.
	Aisle Lighting Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and	•				•	
	Aisle Lighting Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	5	EA	6	6-10 years	Auditorium balcony exit sign is
	Aisle Lighting Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs	Entire Building Entire Building	5	EA EA	6 6	6-10 years 6-10 years	Auditorium balcony exit sign is equipped with a backup battery. No backup batteries and school ha no emergency generator. Quantity changed as total has been
	Aisle Lighting Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Exit Signs - Auditoium	Entire Building Entire Building Entire Building	5 6 1	EA EA	6 6 6	6-10 years 6-10 years 6-10 years	Auditorium balcony exit sign is equipped with a backup battery. No backup batteries and school hano emergency generator. Quantity changed as total has been divided/aggregated. No backup batteries and school has
	Aisle Lighting Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Exit Signs - Auditoium  Exit Signs - Auditoium	Entire Building Entire Building Entire Building Entire Building	5 6 1 6	EA EA EA	6 6 6 2	6-10 years 6-10 years 6-10 years 0-1 year	Auditorium balcony exit sign is equipped with a backup battery. No backup batteries and school han o emergency generator. Quantity changed as total has been divided/aggregated. No backup batteries and school han o emergency generator. No backup batteries and school has been divided.
	Aisle Lighting Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Exit Signs - Auditoium  Exit Signs - Auditoium  Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building	5 6 1 6	EA EA EA	6 6 6 2	6-10 years 6-10 years 6-10 years 0-1 year	Auditorium balcony exit sign is equipped with a backup battery. No backup batteries and school hano emergency generator. Quantity changed as total has been divided/aggregated. No backup batteries and school has
<i>l</i> lain Se	Aisle Lighting Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Exit Signs - Auditoium  Exit Signs - Auditoium  Exit Signs - Corridors and Stairs  Exit Signs - Gym  Security System - CCTV	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	5 6 1 6	EA EA EA EA	6 6 6 2 2	6-10 years 6-10 years 6-10 years 0-1 year 0-1 year 0-1 year	Auditorium balcony exit sign is equipped with a backup battery. No backup batteries and school han o emergency generator. Quantity changed as total has been divided/aggregated. No backup batteries and school han o emergency generator. No backup batteries and school has been divided.

Campus Name: Gresham Page: 17 of 49 Assessment Date: 10/30/2023



Catego	ry : Electrical		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							with all parts of the school.
Power D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	2-5 years	Rank, Reason and Priority Rep adjusted based on current observations. Older panel which is fully operational with no signs of damage or a risk of fire or shock.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep adjusted based on current observations. Older panel which is fully operational with no signs of damage or a risk of fire or shock.

Building : Addition 1 **Category: Fire Protection** 

Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarm						
Fire Alarm Strobe Lights	Entire Building	23,364	SF	6	6-10 years	
Fire Alarm_System	Entire Building	23,364	SF	6	6-10 years	FACP is in Addition 2. Rank adjusted based on the age of the system.

**Building: Addition 1** Category : Mechanical

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	lling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Basement - VS1	1	EA	5	6-10 years	VS-1, serves auditorium and gym.
	Air Intake	Basement - VS1	1	EΑ	5	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Basement - VS1	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement - VS1	100	LF	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Zone Dampers	Basement - VS1	2	EA	5	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Basement - VS2	1	EA	5	6-10 years	VS-2, serves classrooms.
	Air Intake	Basement - VS2	1	EA	5	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Basement - VS2	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy

Campus Name: Gresham Page : 18 of 49 Assessment Date: 10/30/2023



Catego	ry : Mechanical		В	uilding	: Addition	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement - VS2	100	LF	6	6-10 years	issue observed at the time of assessment. Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment.
	Zone Dampers	Basement - VS2	8	EA	6	6-10 years	Rank, Reason and Priority Rep changed as there was no noteworthy issue observed at the time of assessment. The dampers are operational when adjusted manually
Boiler Sy	ystems						
	Piping - Condensate Pipe- Steel	Entire Building	200	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Entire Building	200	LF	5	6-10 years	
	Steam Traps	Entire Building	16	EA	6	6-10 years	
-leating	Devices						
· ·	Wall Heater - Electric	103C	1	EA	4	2-5 years	Quantity changed as the total may have been misidentified between Main and Addition 1 at previous assessment. Electrical cover missing dated.
	Unit Heater - Electric	Elevator Machine Room #1	1	EA	6	6-10 years	
	Radiators - Steam	Entire Building	14	EA	5	6-10 years	
Temper:	ature Control						
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	5	EA	4	0-1 year	Reason and Priority Rep adjusted as all pneumatic thermostats are nonfunctional.
	Thermostats - Pneumatic	Entire Building	5	EA	4	0-1 year	Reason and Priority Rep adjusted as all pneumatic thermostats are nonfunctional.
Catego	ry : Plumbing		В	uilding	: Addition	on 1	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping	Domestic Piping-Hot Water Return Lines	Entire Building	23,364	SF	4	2-5 years	Much of the the domestic piping shows signs of age-related

Campus Name: Gresham Page: 19 of 49 Assessment Date: 10/30/2023



Catego	Category : Plumbing			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	23,364	SF	4	2-5 years	Much of the the domestic piping shows signs of age-related degradation and has exceeded its EUL.
	Sanitary Piping	Entire Building	23,364	SF	5	2-5 years	
	Storm Piping	Entire Building	23,364	SF	5	2-5 years	
	Vent Piping	Entire Building	23,364	SF	5	2-5 years	

Category: Room **Building: Addition 1** 

	.,			, i		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Plaster/Drywall	005	512	SF	7	10+ years	
	Doors - Transom Window	005	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	005	1	ĒΑ	7	10+ years	
	Floor - Wood	005	512	SF	7	10+ years	
	Lighting - Pendent/Surface	005	5	ĒΑ	7	6-10 years	
	Power Distribution	005	4	EA	7	10+ years	
	Walls - Plaster/Drywall	005	990	SF	7	10+ years	
	Work Slnk	005	1	ĒΑ	7	10+ years	
	AC Unit	103	1	EA	7	6-10 years	
	Ceiling - Lay-in	103	215	SF	7	10+ years	
	Ceiling - Plaster/Drywall	103	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	103	1	EA	7	10+ years	
	Floor - Tile	103	230	SF	7	10+ years	
	Lighting - Lay-in	103	4	EA	7	6-10 years	
	Power Distribution	103	12	EA	7	10+ years	
	Walls - Plaster/Drywall	103	492	SF	7	10+ years	
	Ceiling - Lay-in	103A	154	SF	7	10+ years	
	Doors - Transom Window	103A	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	103A	1	EA	7	10+ years	
	Floor - Tile	103A	154	SF	7	10+ years	
	Lighting - Lay-in	103A	2	EA	7	6-10 years	
	Power Distribution	103A	4	EA	7	10+ years	
	Walls - Plaster/Drywall	103A	428	SF	7	10+ years	
	Ceiling - Lay-in	103C	206	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	103C	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	103C	1	EA	7	10+ years	
	Floor - Tile	103C	198	SF	7	10+ years	
	Floor - Tile	103C	8	SF	5	1-2 years	Damaged tile
	Lighting - Lay-in	103C	3	EA	7	6-10 years	•
	Power Distribution	103C	22	EA	7	10+ years	
	Storage/ Closet	103C	40	SF	5	10+ years	Light fixture cover missing
	Walls - Plaster/Drywall	103C	528	SF	7	10+ years	-

Campus Name: Gresham Page : 20 of 49 Assessment Date: 10/30/2023



Category : Room		В	uilding	: Additi	on 1		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Auditoriu	m & Theater						
	Balcony Seating	002	82	EΑ	7	10+ years	
	Ceiling - Plaster/Drywall	002	940	SF	7	10+ years	
	Ceiling - Splined	002	2,460	SF	7	10+ years	
	Doors - Wood Doors inclu hw	002	8	EA	7	10+ years	
	Floor - Carpet	002	800	SF	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	002	2,489	SF	7	10+ years	
	Floor - Terrazzo	002	86	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	002	25	SF	7	10+ years	
	Lighting - Pendent/Surface	002	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	002	14	EA	7	6-10 years	
	Lighting - Wall Mounted	002	16	EA	7	6-10 years	
	Main Floor Seating	002	131	EΑ	7	10+ years	
	Main Floor Seating	002	2	EΑ	5	1-2 years	Cracked/damaged seat
	Stage	002	420	SF	7	10+ years	Oracked/damaged Seat
	Stage Curtain	002	420	EA	7	•	
	Stage Curtain Stage Lift	002	1	EA	7	10+ years 10+ years	
			1		7	•	
	Stage Lighting System	002	· · · · · · · · · · · · · · · · · · ·	EA LF		6-10 years	
	Stage-Stairs - Wood	002	30		7	10+ years	
	Stairs - Terrazzo	002	175	LF	7	10+ years	
	Walls - Plaster/Drywall	002	5,500	SF	7	10+ years	
Symnasi	ia.						
,	Ceiling - Plaster/Drywall	208	2,730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	208	2	ĒA	7	10+ years	
	Floor - Wood	208	2,730	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	208	8	EA	7	6-10 years	
	Walls - Masonry	208	1,450	SF	6	10+ years	
	Walls - Plaster/Drywall	208	2,660	SF	7	10+ years	
1b:	aal/ Camilaa Daarra						
recnant	cal/ Service Rooms  Mechanical/ Service Rooms	Basement	1,530	SF	7	10+ years	
			,			,	
estroor		404A Unicar	400		7	6.40	
	Accessories	101A - Unisex	128	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	101A - Unisex	128	SF	7	10+ years	
	Doors - Wood Doors inclu hw	101A - Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	101A - Unisex	128	SF	7	10+ years	
	Floor Drain	101A - Unisex	1	EA	7	10+ years	
	Hand Dryer	101A - Unisex	1	EA	7	6-10 years	
	Lavatory	101A - Unisex	1	EA	7	10+ years	



Juicgo	ry : Room		В	uilding	: Additi		
	Na Tama	Laathan	0	LIOM	Danila	Recommend	0
Group	Item - Type Lighting - Pendent/Surface	Location 101A - Unisex	Quantity 2	<b>UOM</b> EA	Rank	Replacement	Comments
					7	6-10 years	
	Walls - Plaster/Drywall	101A - Unisex	220	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	101A - Unisex	170	SF	7	6-10 years	
	Water Closet	101A - Unisex	1	EA	7	10+ years	
	Accessories	103B - Unisex	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	103B - Unisex	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	103B - Unisex	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	103B - Unisex	35	SF	7	10+ years	
	Lavatory	103B - Unisex	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	103B - Unisex	1	EΑ	7	6-10 years	
	Lighting - Wall Mounted	103B - Unisex	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	103B - Unisex	150	SF	7	10+ years	
	Water Closet	103B - Unisex	1	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #101 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,435	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	62	SF	7	10+ years	
			V <u>-</u>				
	Doors - Transom Window	1st Floor	20	SF	7	10+ years	
		1st Floor 1st Floor			7 7	10+ years 10+ years	
	Doors - Transom Window		20 2	SF		10+ years	
	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile	1st Floor	20	SF EA SF	7 7	10+ years 10+ years	
	Doors - Transom Window Doors - Wood Doors inclu hw	1st Floor 1st Floor	20 2 1,500	SF EA	7	10+ years	
Classroo	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor	20 2 1,500 20	SF EA SF EA	7 7 7	10+ years 10+ years 6-10 years	
Classroo	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall om #201 (Music Room)	1st Floor 1st Floor 1st Floor 1st Floor	20 2 1,500 20 1,400	SF EA SF EA SF	7 7 7 7	10+ years 10+ years 6-10 years 10+ years	
Classroo	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall om #201 (Music Room) AC Units	1st Floor 1st Floor 1st Floor 1st Floor	20 2 1,500 20 1,400	SF EA SF EA SF	7 7 7 7	10+ years 10+ years 6-10 years 10+ years 6-10 years	
Classroo	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  om #201 (Music Room) AC Units Casework	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	20 2 1,500 20 1,400	SF EA SF EA SF	7 7 7 7 7	10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	
Classroc	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  om #201 (Music Room) AC Units Casework Ceiling - Lay-in	1st Floor	20 2 1,500 20 1,400	SF EA SF EA LF SF	7 7 7 7 7 7 7	10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 6-10 years	
Classroc	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  om #201 (Music Room) AC Units Casework Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor	20 2 1,500 20 1,400 1 7 800 35	SF EA SF EA LF SF SF	7 7 7 7 7 7 7	10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years	
Classroc	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  om #201 (Music Room)  AC Units Casework Ceiling - Lay-in Ceiling - Plaster/Drywall Chalk Board	1st Floor	20 2 1,500 20 1,400 1,400	SF EA SF EA LF SF LF	7 7 7 7 7 7 7 7	10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years	
Classroc	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  om #201 (Music Room) AC Units Casework Ceiling - Lay-in Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window	1st Floor	20 2 1,500 20 1,400 1,400	SF EA SF EA LF SF LF SF	7 7 7 7 7 7 7 7 4 7	10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years 10+ years	
Classroc	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  Dom #201 (Music Room)  AC Units Casework Ceiling - Lay-in Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw	1st Floor	20 2 1,500 20 1,400 1 7 800 35 20 10	SF EA SF EA LF SF LF SF EA	7 7 7 7 7 7 7 4 7	10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 10+ years 6-10 years 2-5 years 10+ years 10+ years	
Classroc	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  om #201 (Music Room)  AC Units Casework Ceiling - Lay-in Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile	1st Floor	20 2 1,500 20 1,400 1 7 800 35 20 10 1 835	SF EA SF EA LF SF LF SF EA SF	7 7 7 7 7 7 7 4 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Classroc	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  Dom #201 (Music Room)  AC Units Casework Ceiling - Lay-in Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	1st Floor	20 2 1,500 20 1,400 1 7 800 35 20 10 1 835 14	SF EA SF EA LF SF EA SF EA SF EA	7 7 7 7 7 7 7 4 7 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years	
Classroc	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  Dom #201 (Music Room)  AC Units Casework Ceiling - Lay-in Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board	1st Floor	20 2 1,500 20 1,400 1 7 800 35 20 10 1 835 14	SF EA SF EA LF SF EA SF EA LF	7 7 7 7 7 7 7 4 7 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years	
Classroc	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall  Dom #201 (Music Room)  AC Units Casework Ceiling - Lay-in Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	1st Floor	20 2 1,500 20 1,400 1 7 800 35 20 10 1 835 14	SF EA SF EA LF SF EA SF EA SF EA	7 7 7 7 7 7 7 4 7 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years	



Category : Classroom				Building : Addition 1				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	AC Units	2nd Floor	2	EΑ	7	6-10 years		
	Casework	2nd Floor	60	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	800	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	35	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years		
	Floor - Tile	2nd Floor	840	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	14	ĒΑ	7	6-10 years		
	Storage/ Closet	2nd Floor	185	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	912	SF	7	10+ years		
Classroo	m #301 (Other Instructional Use)							
2.00.00.00	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	7	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	800	SF	7	6-10 years		
	Ceiling - Lay-in Ceiling - Plaster/Drywall	3rd Floor	35	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	10	SF	7	•		
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years		
	Floor - Tile	3rd Floor	· · · · · · · · · · · · · · · · · · ·	SF	7	10+ years		
			835			10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	12	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	185	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	890	SF	7	10+ years		
Classroo	m #303 (Store Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	7	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	800	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	35	SF	7	10+ years		
	Chalk Board	3rd Floor	8	LF	4	2-5 years		
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Carpet	3rd Floor	835	SF	7	6-10 years		
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	12	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	185	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	890	SF	7	10+ years		
Catego	ry : Interior		В	uilding	: Additio	on 1		
	_					Recommend		
<b>Group</b> Corridor	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
JOHNOOL	Ceiling - Plaster/Drywall	1st Floor	1,050	SF	7	10+ years		
	Doors - Transom Window	1st Floor	32	SF	7	10+ years		



Catego	ry : Interior	В	uilding	: Additi	on 1	Ţ	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	1st Floor	216	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	930	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	6-10 years	Cover missing
	Walls - Plaster/Drywall	1st Floor	1,800	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,100	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	32	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	170	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	930	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,830	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,100	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	32	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,100	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,830	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,400	SF	7	10+ years	
	Doors - Transom Window	Basement	32	SF	7	10+ years	
	Doors - Wood Doors include hw	Basement	4	EΑ	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	Basement	870	SF	7	10+ years	
	Floor - Terrazzo	Basement	120	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	414	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	10	EA	7	6-10 years	
	Stairs - Terrazzo	Basement	143	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,900	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule - NE	100	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule - NE	10	SF	5	1-2 years	Heavy peeling
	Doors - Steel Doors incl hw	Vestibule - NE	2	EA	7	10+ years	
	Doors - Transom Window	Vestibule - NE	20	SF	7	10+ years	
	Doors - Wood Doors include hw	Vestibule - NE	2	EA	7	6-10 years	
	Floor - Terrazzo	Vestibule - NE	110	SF	7	10+ years	
	Lighting - Pendent/Surface	Vestibule - NE	1	EA	7	6-10 years	
	Walls - Masonry	Vestibule - NE	300	SF	7	10+ years	
Safety							
-	Security Cameras	1st Floor	17	EA	7	6-10 years	
Stairs							
StallS	Ceiling - Exposed	North	312	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North	460	SF	7	10+ years	
	Floor - Terrazzo	North	346	SF	7	10+ years	
	Handrails	North	136	LF	7	10+ years	
	Lighting - Pendent/Surface	North	4	ĒΑ	7	6-10 years	
	Stairs - Terrazzo	North	390	LF	6	10+ years	
						,	



Category : Interio	Category : Interior			Building : Addition 1					
Group Item - Ty	pe	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Walls - Pl	aster/Drywall	North	3,030	SF	7	10+ years			
Vertical Conveyance	9								
Elevator -	Hydraulic Elevator	South	1	EA	6	10+ years			

Page : 25 of 49 Campus Name: Gresham Assessment Date: 10/30/2023



Category : Exterior **Building: Addition 2** 

tem - Type	Location	Quantity	LION		Recommend	
tem - Type	Location				Danlasamant	Commonto
		Quantity	UOM	Rank	Replacement	Comments
Entrance Control - Audio and Video	1 - Main Entry	1	EA	7	10+ years	
Exterior Doors - Exterior FRP Door	1 - Main Entry	4	EA	7	10+ years	
Exterior Doors - Transom Lite	1 - Main Entry	4	EA	7	10+ years	
Exterior Stairs - Concrete		12	LF	7		
		1	EA	7	10+ years	
	1 - Main Entry	40		6	10+ years	
	1 - Main Entry	20		7	10+ years	
Exterior Doors - Exterior FRP Door	2	2	EA	6	10+ years	
Exterior Stairs - Concrete	2	18	LF	6	10+ years	
Entrance Control - Audio and Video	3	1	EA	7	6-10 years	
Exterior Doors - Exterior FRP Door	3	3	EA	7	10+ years	
Exterior Stairs - Concrete	3	9	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	4	1	EA	6	10+ years	
Exterior Doors - Transom Lite	4	1	EA	7		
	4	3	LF	6		
Exterior Doors - Exterior Steel Door	5	1	EA	6	•	
Exterior Doors - Transom Lite	5	1				
	5	3		-		
	C - Elevator Machine Rm	1		-		
		3				
					•	
		1		-	•	
		12		-		
tampo Concrete	County and B	12		Ū	101 youro	
- -oundation - Concrete	Entire Buildina	554	LF	7	10+ vears	No exposed foundation
Superstructure - Metal Deck/ Concrete				7		No exposed superstructure
Горріпд	3	-,			,	
		6	EA			
Exterior Lighting - Wall Mounted	Entire Building	8	EA	5	2-5 years	
m						
	F	62	LF	7	10+ vears	Replaced
						Topiaooa
					•	Replaced
	-					ποριασσα
	•	700	OI.	,	TOT years	
	Power Door Operator and Controls Ramp Handrail - Steel_Ramp Handrail Ramps - Concrete Exterior Doors - Exterior FRP Door Exterior Stairs - Concrete Entrance Control - Audio and Video Exterior Doors - Exterior FRP Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Stairs - Concrete Exterior Doors - Transom Lite Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door	Acomer Door Operator and Controls Acomp Handrail - Steel_Ramp Handrail Acomps - Concrete Acterior Doors - Exterior FRP Door Acterior Stairs - Concrete Acterior Doors - Exterior FRP Door Acterior Doors - Exterior Steel Door Acterior Doors - Exterior Steel Door Acterior Doors - Transom Lite Acterior Doors - Exterior Steel Door Acterior Stairs - Concrete Acterior Doors - Exterior Steel Door Acterior Stairs - Concrete Acterior Doors - Exterior Steel Door Acteri	Nower Door Operator and Controls   1 - Main Entry   1   1   1   1   1   1   1   1   1	Name   Door Operator and Controls   1 - Main   Entry   1	Dever Door Operator and Controls   1 - Main Entry   1	Dever Door Operator and Controls   1 - Main Entry   1



Catego	ry : Exterior		В	uilding	: Addition	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	G	1	EA	7	10+ years	
	Access Ladder - Metal	G	1	EA	7	10+ years	
	Chimney - Metal Flue	G	15	LF	6	10+ years	
	Coping - Metal	G	554	LF	7	10+ years	Replaced
	Downspouts - Exterior Downspouts	G	12	LF	7	10+ years	Not previously assessed
	Downspouts - Interior Downspouts	G	153	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	G	15,320	SF	7	10+ years	Replaced
	Roof Hatch - Metal	G	2	EA	7	10+ years	•
	Roof Structure - Steel with Clay Tile Arch	G	15,320	SF	7	10+ years	
<u> Walls</u>		<b>- -</b>					
	Exterior Walls - Brick	Entire Building	17,341	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	952	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	28	SF	5	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	150	SF	6	10+ years	
Vindows							
	Guard - Guards perforated	Entire Building	1,527	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,111	LF	6	10+ years	
	Skylite - Lexan	Entire Building	56	SF	6	10+ years	
	Windows - Louver	Entire Building	150	SF	6	10+ years	Not previously assessed
	Windows - Sash Aluminum	Entire Building	5,584	SF	6	10+ years	
Catego	ry : Electrical		R	uildina	: Additio	on 2	
Julogo				ununig	. / taaiti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Automatic Transfer Switch	Boiler Room	1	EA	6	2-5 years	
	Emergency A/C Power - Corridors and	Entire Building	8,596	SF	6	6-10 years	
	Stairs Exit Signs - Corridors and Stairs	Entire Building	22	EA	2	0-1 year	Not equipped with backup batterie
	Exit digital contacts and state	Entire Ballaning	22	_/\	_	o i you	and the school has no emergency
							generator.
	Exit Signs - Lunchroom	Entire Building	1	EA	2	0-1 year	Not equipped with backup batterie
							and the school has no emergency generator.
	Emergency Battery Packs - Corridors and	Entire Building	17	EA	6	6-10 years	generator.
	Stairs	· ·				-	
	Emergency Battery Packs - Students Toilets	Entire Building	10	EA	6	6-10 years	
	Security System - CCTV	Entire Building	48,387	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	48,387	SF	5	2-5 years	Older devices which have exceede



Main Servi	Item - Type ice Independent Electrical Service for emergency power Main Electrical Service - 2000 A 120/208/3PH PA System	Boiler Room Boiler Room Entire Building	Quantity  1 1 45,000	UOM  EA  EA  SF	<b>Rank</b> 6 7	Recommend Replacement  2-5 years  10+ years	Serves Addition 2, Main and Addition
Main Servi	Independent Electrical Service for emergency power Main Electrical Service - 2000 A 120/208/3PH	Boiler Room Boiler Room	1	EA EA	6	2-5 years	Serves Addition 2, Main and Addition
 	Independent Electrical Service for emergency power Main Electrical Service - 2000 A 120/208/3PH	Boiler Room	1	EA	7	•	·
(   1   .	emergency power Main Electrical Service - 2000 A 120/208/3PH	Boiler Room	1	EA	7	•	•
	120/208/3PH		·			10+ years	•
	PA System	Entire Building	45,000	SF	4		1.
					4	2-5 years	Also serves Main and Addition 1. Reason and Priority Rep adjusted to confirm that the system does not have reliable communication with all parts of the school.
Power Dist	stribution						
	Lighting and Power Panels - 100 A	Entire Building	9	EA	6	6-10 years	Rank, Reason and Priority Rep adjusted as the older panels are fully operational with no risk of fire or shock.
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
Category	: Fire Protection		В	uilding	Additio	on 2	
			_			Recommend	
Group I	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarm			•			•	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves Addition 2, Main, and Addition 1.
ı	Fire Alarm Strobe Lights	Entire Building	45,000	SF	6	6-10 years	
!	Fire Alarm_System	Entire Building	90,206	SF	6	6-10 years	
Category	/ : Mechanical		В	uilding	: Additio	on 2	
						Recommend	
Group I	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Handlir	ng Systems						
I	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm	Boiler Room	1	EA	4	0-1 year	Air handler is nonfunctional and out o service.
	Air Intake	Boiler Room	1	EA	5	2-5 years	
						,	
Boiler Syst							
1	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	1	EA	5	2-5 years	

Campus Name: Gresham Page : 28 of 49 Assessment Date: 10/30/2023



Catego	ry : Mechanical		В	uilding	: Additi	on 2	0324 O Orcent Other Ft, Omeago, in 00020
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	- Greater than 4000 MBH Combustion Dampers	Boiler Room	1	EA	4	2-5 years	Damper shows signs of age-related degradation and requires manual adjustment.
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - Greater than 4000 MBH	Boiler Room	1	EA	5	2-5 years	adjustificiti.
Heating	Devices						
	Unit Heater - Electric	Elevator Machine Room #2	1	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	20	EA	6	6-10 years	Rank, Reason and Priority Rep changed as all cabinet heaters throughout the building have been repaired since previous assessment and are fully operational.
	Fin Tube - Hot Water	Entire Building	36	LF	6	6-10 years	
Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as pumps have been upgraded since previous assessment and are fully operational.
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as pumps have been upgraded since previous assessment and are fully operational.
	Hydronic Supply and Return - Steel	Entire Building	200	LF	4	2-5 years	Rank, Reason and Priority Rep changed to clarify that the steel piping is over 40 years old and beyond its EUL.
Tempera	ature Control						
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Pneumatic System	Entire Building	45,000	SF	3	0-1 year	System is nonfunctional.
	Thermostats - Pneumatic	Entire Building	47	EA	4	0-1 year	All pneumatic thermostats are nonfunctional.
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	34	EA	6	2-5 years	Rank, Reason and Priority Rep changed as all unit ventilators have been upgraded since previous assessment and are fully operational.

Campus Name: Gresham Page : 29 of 49 Assessment Date: 10/30/2023



Catego	ry : Mechanical		В	uilding	: Additio		6524 S Green STREET, Chicago, IL 60620
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Ventilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	4	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	Exhaust hood has no fire suppression system.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additio	on 2	
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	45,000	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	45,000	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	45,000	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	45,000	SF	6	6-10 years	
	(Horizontal Lines)	· ·			O	o io years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	45,000	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	45,000	SF	6	6-10 years	
	Sanitary Piping	Entire Building	45,000	SF	6	10+ years	
	Storm Piping	Entire Building	45,000	SF	6	10+ years	
	Vent Piping	Entire Building	45,000	SF	6	10+ years	
Pumps		D. 1. D.				0.5	Will the later than the
	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	5	2-5 years	Well-maintained vintage equipment, operational and leak-free at the time of assessment, which has exceeded its EUL.



Category : Room			Building : Addition 2						
	,			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Administ	rative Suites/Offices					•			
	Ceiling - Plaster/Drywall	115A	94	SF	7	10+ years			
	Doors - Steel Doors incl hw	115A	1	EA	7	10+ years			
	Floor - Tile	115A	94	SF	6	10+ years			
	Lighting - Pendent/Surface	115A	2	EA	7	10+ years			
	Power Distribution	115A	3	EΑ	7	10+ years			
	Storage/ Closet	115A	6	SF	7	10+ years			
	Walls - Concrete Block	115A	114	SF	7	10+ years			
	Walls - Metal Panel	115A	119	SF	7	10+ years			
	Work Sink	115A	1	ĒΑ	7	6-10 years			
	Ceiling - Plaster/Drywall	116	145	SF	6	10+ years			
	Doors - Wood Doors inclu hw	116	1	ĒΑ	6	10+ years			
	Floor - Tile	116	145	SF	6	10+ years			
	Lighting - Lay-in	116	2	ĒΑ	6	10+ years			
	Power Distribution	116	6	EA	6	10+ years			
	Walls - Concrete Block	116	200	SF	6	10+ years			
	AC Unit	119	1	ĒΑ	7	6-10 years			
	Ceiling - Plaster/Drywall	119	321	SF	6	10+ years			
	Doors - Wood Doors inclu hw	119	2	ĒΑ	6	10+ years			
	Floor - Tile	119	321	SF	6	10+ years			
	Lighting - Pendent/Surface	119	6	ĒΑ	6	10+ years			
	Power Distribution	119	10	EA	7	10+ years			
	Storage/ Closet	119	21	SF	7	10+ years			
	Walls - Concrete Block	119	702	SF	6	10+ years			
	Ceiling - Plaster/Drywall	120	386	SF	7	10+ years			
	Doors - Side-lite	120	14	SF	6	10+ years			
	Doors - Store Front	120	1	ĒΑ	6	10+ years			
	Floor - Tile	120	386	SF	6	10+ years			
	Lighting - Pendent/Surface	120	9	ĒΑ	7	10+ years			
	Power Distribution	120	16	EA	6	10+ years			
	Storage/ Closet	120	90	SF	7	10+ years			
	Walls - Concrete Block	120	592	SF	6	10+ years			
	Ceiling - Plaster/Drywall	120 - Clerk's Office	165	SF	6	10+ years			
	Doors - Wood Doors inclu hw	120 - Clerk's Office	1	EA	6	10+ years			
	Floor - Tile	120 - Clerk's Office	165	SF	6	10+ years			
	Lighting - Pendent/Surface	120 - Clerk's Office	4	EA	7	10+ years			
	Power Distribution	120 - Clerk's Office	8	EA	6	10+ years			
	Storage/ Closet	120 - Clerk's Office	8	SF	7	10+ years			
	Walls - Concrete Block	120 - Clerk's Office	339	SF	6	10+ years			
	Ceiling - Plaster/Drywall	209	252	SF	7	10+ years			
	Doors - Wood Doors inclu hw	209	1	ĒΑ	7	10+ years			
	Floor - Tile	209	252	SF	7	10+ years			
	Lighting - Pendent/Surface	209	4	ĒΑ	7	10+ years			
	Power Distribution	209	6	EA	7	10+ years			



Category : Room			Building : Addition 2					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage/ Closet	209	10	SF	7	10+ years		
	Walls - Concrete Block	209	519	SF	7	10+ years		
	Ceiling - Plaster/Drywall	219	252	SF	7	10+ years		
	Doors - Wood Doors inclu hw	219	1	EA	7	10+ years		
	Floor - Tile	219	252	SF	7	10+ years		
	Lighting - Pendent/Surface	219	4	EA	7	10+ years		
	Power Distribution	219	18	EA	7	10+ years		
	Storage/ Closet	219	10	SF	7	10+ years		
	Walls - Concrete Block	219	519	SF	7	10+ years		
	Ceiling - Plaster/Drywall	222	308	SF	7	10+ years		
	Doors - Wood Doors inclu hw	222	2	EA	7	10+ years		
	Floor - Tile	222	308	SF	7	10+ years		
	Lighting - Pendent/Surface	222	5	EΑ	7	10+ years		
	Power Distribution	222	20	EA	7	10+ years		
	Walls - Concrete Block	222	670	SF	7	10+ years		
	Ceiling - Plaster/Drywall	309	252	SF	7	10+ years	Appears to have been corrected	
	Doors - Wood Doors inclu hw	309	1	EA	6	10+ years		
	Floor - Tile	309	252	SF	6	10+ years		
	Lighting - Pendent/Surface	309	4	EΑ	6	10+ years		
	Power Distribution	309	18	EA	6	10+ years		
	Storage/ Closet	309	10	SF SF	7	10+ years		
	Walls - Concrete Block	309	503		6	10+ years		
	Ceiling - Plaster/Drywall	319 310	252 1	SF	6	10+ years		
	Doors - Wood Doors inclu hw Floor - Tile	319	252	EA SF	6	10+ years		
		319 319	252 4	SF EA	6 7	10+ years		
	Lighting - Pendent/Surface Power Distribution	319	14	EA	7	10+ years		
	Storage/ Closet	319	8	SF	7	10+ years		
	Walls - Concrete Block	319	587	SF	7	10+ years		
	Ceiling - Plaster/Drywall	322	280	SF	6	10+ years		
	Doors - Wood Doors inclu hw	322	200	EA	7	10+ years 10+ years		
	Floor - Tile	322	280	SF	6	,		
	Lighting - Pendent/Surface	322	5	EA	6	10+ years 10+ years		
	Power Distribution	322	18	EA	6	10+ years		
	Walls - Concrete Block	322	549	SF	6	10+ years		
	Walls - Coliciete block	322	549	SF	O	10+ years		
_Kitchen								
	Ceiling - Plaster/Drywall	114	626	SF	7	10+ years		
	Doors - Steel Doors incl hw	114	1	EΑ	7	10+ years		
	Floor - Tile Quarry	114	626	SF	7	10+ years		
	Lighting - Lay-in	114	4	ĒΑ	7	10+ years		
	Lighting - Pendent/Surface	114	10	EA	7	10+ years		
	Serving Line	114	17	LF	7	6-10 years		
	Storage/ Closet	114	80	SF	7	10+ years		
	-					ŕ		



	Category : Room		В	uilding	0024 0 Green Officer, Officego, IE 00020			
Malls - Structural Glazed Tite	_	•						
Lunch & Multiourpose Room	Group		Location	Quantity		Rank		Comments
AC Unit 115		Walls - Structural Glazed Tile	114	793	SF	6	10+ years	
AC Unit 115								
Ceiling - Plaster/Dywall	Lunch &							
Doors - Wood Doors inclu hw   115							•	
Floor - Tile		Ceiling - Plaster/Drywall		· · · · · · · · · · · · · · · · · · ·			,	
Lighting - Pendent/Surface   115				3				
Mails - Concrete Block				1,602				
Dors - Steel Doors incl hw   217							10+ years	
Doors - Steel Doors incl hw Finishes		Walls - Concrete Block	115	1,105	SF	7	10+ years	
Doors - Steel Doors incl hw Finishes	MDE ID	Œ						
Mechanical/ Service Rooms	_WDF_ID		217	1	EA	7	10+ vears	
Mechanical/ Service Rooms								
Boiler Room								
Janitor's Closet	<u>Mechan</u>		4 . =				4.0	
Mechanical/ Service Rooms         1st Floor         45         SF         7         10+ years           Mechanical/ Service Rooms         1st Floor         105         SF         7         10+ years           Janitor's Closet         2nd Floor         36         SF         7         10+ years           Storage Room         2nd Floor         36         SF         7         10+ years           Janitor's Closet         3rd Floor         36         SF         7         10+ years           Janitor's Closet         3rd Floor         36         SF         7         10+ years           Janitor's Closet         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         301         SF         7         10+ years           Restroom         3rd Floor         36         SF         7         10+ years           Restroom         3rd Floor         3rd Floor         3rd Floor         3rd Floor         3rd Floor         3rd Floor         3rd Floor <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>•</td> <td></td>							•	
Mechanical/ Service Rooms								
Vaults         1st Floor         105         SF         7         10+ years           Janitor's Closet         2nd Floor         36         SF         7         10+ years           Janitor's Closet         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         36         SF         7         10+ years           Storage Room         3rd Floor         301         SF         7         10+ years           Celling - Plaster/Drywall         110A         24         SF         7         10+ years           Colling - Lavin         110A         1         EA         6         6-10 years           Walls - Concrete Block         110A         1								
Janitor's Closet   2nd Floor   36   SF   7   10+ years     Storage Room   2nd Floor   301   SF   7   10+ years     Janitor's Closet   3rd Floor   36   SF   7   10+ years     Storage Room   3rd Floor   301   SF   7   10+ years     Storage Room   3rd Floor   301   SF   7   10+ years     Storage Room   3rd Floor   301   SF   7   10+ years     Restroom								
Storage Room								
Janitor's Closet   3rd Floor   36   SF   7   10+ years								
Restroom		Storage Room						
Accessories				36			10+ years	
Accessories       110A       24       SF       7       6-10 years         Ceiling - Plaster/Drywall       110A       24       SF       7       10+ years         Doors - Wood Doors inclu hw       110A       1       EA       7       10+ years         Floor - Tile Ceramic/ Porcelain       110A       24       SF       6       10+ years         Floor Drain       110A       1       EA       7       10+ years         Lavatory       110A       1       EA       6       6-10 years         Lighting - Lay-in       110A       1       EA       6       6-10 years         Walls - Concrete Block       110A       169       SF       7       10+ years         Water Closet       110A       1       EA       6       6-10 years         Accessories       112A       42       SF       7       6-10 years         Ceiling - Plaster/Drywall       112A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       112A       42       SF       6       10+ years         Floor - Tile Ceramic/ Porcelain       112A       42       SF       6       10+ years         Floor Drain		Storage Room	3rd Floor	301	SF	7	10+ years	
Accessories       110A       24       SF       7       6-10 years         Ceiling - Plaster/Drywall       110A       24       SF       7       10+ years         Doors - Wood Doors inclu hw       110A       1       EA       7       10+ years         Floor - Tile Ceramic/ Porcelain       110A       24       SF       6       10+ years         Floor Drain       110A       1       EA       7       10+ years         Lavatory       110A       1       EA       6       6-10 years         Lighting - Lay-in       110A       1       EA       6       6-10 years         Walls - Concrete Block       110A       169       SF       7       10+ years         Water Closet       110A       1       EA       6       6-10 years         Accessories       112A       42       SF       7       6-10 years         Ceiling - Plaster/Drywall       112A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       112A       42       SF       6       10+ years         Floor - Tile Ceramic/ Porcelain       112A       42       SF       6       10+ years         Floor Drain	Restroo	m						
Ceiling - Plaster/Drywall       110A       24       SF       7       10+ years         Doors - Wood Doors inclu hw       110A       1       EA       7       10+ years         Floor - Tile Ceramic/ Porcelain       110A       24       SF       6       10+ years         Floor Drain       110A       1       EA       7       10+ years         Lavatory       110A       1       EA       6       6-10 years         Lighting - Lay-in       110A       1       EA       6       10+ years         Walls - Concrete Block       110A       169       SF       7       10+ years         Water Closet       110A       1       EA       6       6-10 years         Accessories       112A       42       SF       7       10+ years         Ceiling - Plaster/Drywall       112A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       112A       42       SF       6       10+ years         Floor - Tile Ceramic/ Porcelain       112A       42       SF       6       10+ years         Floor Drain       112A       1       EA       7       10+ years         Hand Dryer       112A<			110A	24	SF	7	6-10 years	
Doors - Wood Doors inclu hw         110A         1 EA         7 10+ years           Floor - Tile Ceramic/ Porcelain         110A         24 SF         6 10+ years           Floor Drain         110A         1 EA         7 10+ years           Lavatory         110A         1 EA         6 6-10 years           Lighting - Lay-in         110A         1 EA         6 10+ years           Walls - Concrete Block         110A         169 SF         7 10+ years           Water Closet         110A         1 EA         6 6-10 years           Accessories         112A         42 SF         7 6-10 years           Ceiling - Plaster/Drywall         112A         42 SF         7 10+ years           Doors - Wood Doors inclu hw         112A         42 SF         6 10 years           Floor - Tile Ceramic/ Porcelain         112A         42 SF         6 10+ years           Floor Drain         112A         42 SF         6 10+ years           Hand Dryer         112A         1 EA         7 6-10 years           Lavatory         112A         1 EA         7 6-10 years		Ceiling - Plaster/Drywall	110A		SF	7		
Floor - Tile Ceramic/ Porcelain       110A       24       SF       6       10+ years         Floor Drain       110A       1       EA       7       10+ years         Lavatory       110A       1       EA       6       6-10 years         Lighting - Lay-in       110A       1       EA       6       10+ years         Walls - Concrete Block       110A       169       SF       7       10+ years         Water Closet       110A       1       EA       6       6-10 years         Accessories       112A       42       SF       7       6-10 years         Ceiling - Plaster/Drywall       112A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       112A       1       EA       7       10+ years         Floor - Tile Ceramic/ Porcelain       112A       42       SF       6       10+ years         Floor Drain       112A       1       EA       7       10+ years         Hand Dryer       112A       1       EA       7       6-10 years         Lavatory       112A       1       EA       7       6-10 years								
Floor Drain       110A       1 EA 7 10+ years         Lavatory       110A       1 EA 6 6-10 years         Lighting - Lay-in       110A       1 EA 6 10+ years         Walls - Concrete Block       110A       169 SF 7 10+ years         Water Closet       110A       1 EA 6 6-10 years         Accessories       112A       42 SF 7 6-10 years         Ceiling - Plaster/Drywall       112A       42 SF 7 10+ years         Doors - Wood Doors inclu hw       112A       1 EA 7 10+ years         Floor - Tile Ceramic/ Porcelain       112A       42 SF 6 10+ years         Floor Drain       112A       1 EA 7 10+ years         Hand Dryer       112A       1 EA 7 6-10 years         Lavatory       112A       1 EA 7 6-10 years				24			•	
Lavatory       110A       1 EA 6 6-10 years         Lighting - Lay-in       110A       1 EA 6 10+ years         Walls - Concrete Block       110A       169 SF 7 10+ years         Water Closet       110A       1 EA 6 6-10 years         Accessories       112A       42 SF 7 6-10 years         Ceiling - Plaster/Drywall       112A       42 SF 7 10+ years         Doors - Wood Doors inclu hw       112A       1 EA 7 10+ years         Floor - Tile Ceramic/ Porcelain       112A       42 SF 6 10+ years         Floor Drain       112A       1 EA 7 10+ years         Hand Dryer       112A       1 EA 7 6-10 years         Lavatory       112A       1 EA 7 6-10 years							•	
Lighting - Lay-in       110A       1 EA 6 10+ years         Walls - Concrete Block       110A       169 SF 7 10+ years         Water Closet       110A       1 EA 6 6-10 years         Accessories       112A       42 SF 7 6-10 years         Ceiling - Plaster/Drywall       112A       42 SF 7 10+ years         Doors - Wood Doors inclu hw       112A       1 EA 7 10+ years         Floor - Tile Ceramic/ Porcelain       112A       42 SF 6 10+ years         Floor Drain       112A       1 EA 7 10+ years         Hand Dryer       112A       1 EA 7 6-10 years         Lavatory       112A       1 EA 7 6-10 years								
Walls - Concrete Block       110A       169       SF       7       10+ years         Water Closet       110A       1       EA       6       6-10 years         Accessories       112A       42       SF       7       6-10 years         Ceiling - Plaster/Drywall       112A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       112A       1       EA       7       10+ years         Floor - Tile Ceramic/ Porcelain       112A       42       SF       6       10+ years         Floor Drain       112A       1       EA       7       10+ years         Hand Dryer       112A       1       EA       7       6-10 years         Lavatory       112A       1       EA       7       6-10 years				1		_		
Water Closet       110A       1 EA 6 6-10 years         Accessories       112A       42 SF 7 6-10 years         Ceiling - Plaster/Drywall       112A       42 SF 7 10+ years         Doors - Wood Doors inclu hw       112A       1 EA 7 10+ years         Floor - Tile Ceramic/ Porcelain       112A       42 SF 6 10+ years         Floor Drain       112A       1 EA 7 10+ years         Hand Dryer       112A       1 EA 7 6-10 years         Lavatory       112A       1 EA 7 6-10 years				169			•	
Accessories       112A       42       SF       7       6-10 years         Ceiling - Plaster/Drywall       112A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       112A       1       EA       7       10+ years         Floor - Tile Ceramic/ Porcelain       112A       42       SF       6       10+ years         Floor Drain       112A       1       EA       7       10+ years         Hand Dryer       112A       1       EA       7       6-10 years         Lavatory       112A       1       EA       7       6-10 years							,	
Ceiling - Plaster/Drywall       112A       42 SF 7 10+ years         Doors - Wood Doors inclu hw       112A       1 EA 7 10+ years         Floor - Tile Ceramic/ Porcelain       112A       42 SF 6 10+ years         Floor Drain       112A       1 EA 7 10+ years         Hand Dryer       112A       1 EA 7 6-10 years         Lavatory       112A       1 EA 7 6-10 years							,	
Doors - Wood Doors inclu hw       112A       1 EA 7 10+ years         Floor - Tile Ceramic/ Porcelain       112A       42 SF 6 10+ years         Floor Drain       112A       1 EA 7 10+ years         Hand Dryer       112A       1 EA 7 6-10 years         Lavatory       112A       1 EA 7 6-10 years							•	
Floor - Tile Ceramic/ Porcelain       112A       42       SF       6       10+ years         Floor Drain       112A       1       EA       7       10+ years         Hand Dryer       112A       1       EA       7       6-10 years         Lavatory       112A       1       EA       7       6-10 years								
Floor Drain       112A       1 EA 7 10+ years         Hand Dryer       112A       1 EA 7 6-10 years         Lavatory       112A       1 EA 7 6-10 years								
Hand Dryer 112A 1 EA 7 6-10 years Lavatory 112A 1 EA 7 6-10 years								
Lavatory 112A 1 EA 7 6-10 years								
				•				
Lighting - Lay-in 112A 1 LA 1 TOT years								
		Lighting Lay in	11211	1	LA	,	TOT years	



Category : Room			Building : Addition 2				
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	112A	226	SF	7	10+ years	
	Water Closet	112A	1	EA	7	6-10 years	
	Accessories	114B	62	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	114B	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	114B	1	EA	6	10+ years	
	Floor - Tile Quarry	114B	62	SF	7	10+ years	
	Lavatory	114B	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	114B	1	EA	6	10+ years	
	Partitions	114B	1	EA	7	6-10 years	
	Student Lockers - One Tier	114B	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	114B	212	SF	6	10+ years	
	Water Closet	114B	1	ĒΑ	6	6-10 years	
	Accessories	118A	29	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	118A	29	SF	7	10+ years	
	Doors - Wood Doors inclu hw	118A	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	118A	29	SF	7	10+ years	
	Floor Drain	118A	1	EA	7	10+ years	
	Lavatory	118A	1	EΑ	7	6-10 years	
	Lighting - Lay-in	118A	i	EA	7	10+ years	
	Walls - Concrete Block	118A	226	SF	7	10+ years	
	Water Closet	118A	1	EA	7	6-10 years	
	Accessories	119	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	119	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	119	1	EA	6	10+ years	
	Floor - Tile	119	30	SF	6	10+ years	
	Lavatory	119	1	EA	6	6-10 years	
	Lighting - Lay-in	119	1	EA	6	10+ years	
	Walls - Concrete Block	119	155	SF	6	10+ years	
	Water Closet	119	100	EA	6	6-10 years	
	Accessories	120	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	120	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	120	1	EA	6	10+ years	
	Floor - Tile	120	30	SF	6	10+ years	
	Lavatory	120	1	EA	6	6-10 years	
	Lavatory Lighting - Lay-in	120	1	EA	6	•	
	Walls - Concrete Block	120		SF		10+ years	
	Water Closet	120	155 1	EA	6	10+ years	
				SF	6 7	6-10 years	
	Accessories	1st Floor	206 206	SF SF	7 6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor		SF EA		10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1		7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	206	SF	7	10+ years	
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Hand Dryer	1st Floor	2	EΑ	7	6-10 years	
	Lavatory	1st Floor	3	EA	6	6-10 years	



Category : Room		В	uilding	: Additi	. 5 :		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	10+ years	
	Partitions	1st Floor	2	EA	7	6-10 years	
	Urinals	1st Floor	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	14	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	508	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	6	6-10 years	
	Accessories	1st Floor	229	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	229	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	229	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	6	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	ĒΑ	6	10+ years	
	Partitions	1st Floor	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	14	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	490	SF	7	10+ years	
	Water Closet	1st Floor	4	EA	6	6-10 years	
	Water Closet	1st Floor	2	EΑ	4	0-1 year	Not in service
	Accessories	222A - Unisex	81	SF	7	6-10 years	1401 111 001 1100
	Ceiling - Plaster/Drywall	222A - Unisex	81	SF	7	10+ years	
	Doors - Wood Doors inclu hw	222A - Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	222A - Unisex	81	SF	7	10+ years	
	Floor Drain	222A - Unisex	1	EA	7	10+ years	
	Lavatory	222A - Unisex	1	EA	7	6-10 years	
	Lighting - Lay-in	222A - Unisex	1	EA	7	10+ years	
	Walls - Concrete Block	222A - Unisex	285	SF	7	10+ years	
	Water Closet	222A - Onisex 222A - Unisex	1	EA	7	10+ years	
	Accessories	2nd Floor	206	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	206	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	206	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	3 1	EA	7	10+ years	
	Lighting - Lay-III Lighting - Pendent/Surface	2nd Floor 2nd Floor	3	EA	7	10+ years	
	Partitions	2nd Floor	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	14	SF	7	10+ years	
	Walls - Plaster/Drywall Walls - Structural Glazed Tile	2nd Floor 2nd Floor	508	SF SF	7 7		
	Water Closet	2nd Floor 2nd Floor		SF EA		10+ years	
		∠nd Floor 2nd Floor	6 206	SF	7 7	6-10 years	
	Accessories	ZIIU FIUUI	206	SF	,	6-10 years	



Category : Room		В	uilding	: Addition			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	206	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	206	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years	
	Partitions	2nd Floor	2	EΑ	7	10+ years	
	Urinals	2nd Floor	4	ΕA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	14	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	498	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	10	SF	5	1-2 years	Cracks in block wall
	Water Closet	2nd Floor	2	EA	7	10+ years	Oracks in block wall
	Accessories	2nd Floor - East	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - East	45 45	SF	7		
			_	EA		10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - East	1		7	10+ years	
	Floor - Tile	2nd Floor - East	45	SF	6	10+ years	
	Lavatory	2nd Floor - East	1	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor - East	1	EA	7	10+ years	
	Partitions	2nd Floor - East	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor - East	231	SF	7	10+ years	
	Water Closet	2nd Floor - East	1	EA	7	10+ years	
	Accessories	322A - Unisex	81	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	322A - Unisex	81	SF	6	10+ years	
	Doors - Wood Doors inclu hw	322A - Unisex	1	EA	6	10+ years	
	Floor - Tile	322A - Unisex	77	SF	7	10+ years	
	Floor - Tile	322A - Unisex	4	SF	4	0-1 year	Damaged and missing 9x9
	Floor Drain	322A - Unisex	1	EA	7	10+ years	
	Lavatory	322A - Unisex	2	EA	6	6-10 years	
	Lighting - Lay-in	322A - Unisex	1	EA	6	10+ years	
	Partitions	322A - Unisex	2	EA	7	6-10 years	
	Walls - Concrete Block	322A - Unisex	285	SF	6	10+ years	
	Water Closet	322A - Unisex	2	EA	6	6-10 years	
	Accessories	3rd Floor	206	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	206	SF	6	10+ years	Repaired
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	- F
	Floor - Tile Ceramic/ Porcelain	3rd Floor	206	SF	6	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	6	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	10+ years	
	Lighting - Lay-in Lighting - Pendent/Surface	3rd Floor 3rd Floor	3	EA	6	10+ years 10+ years	
			2	EA	7		
	Partitions	3rd Floor	2	EA	1	6-10 years	

Page : 36 of 49 Campus Name: Gresham Assessment Date: 10/30/2023



Catego	Category : Room			uilding	: Addition	on 2	0024 O Orech OTNEET, Omeage, in 00020
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Urinals	3rd Floor	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	14	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	508	SF	6	10+ years	
	Water Closet	3rd Floor	2	EA	6	6-10 years	
	Accessories	3rd Floor	206	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	206	SF	6	10+ years	Repaired
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	206	SF	6	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	3	EA	6	10+ years	
	Partitions	3rd Floor	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	14	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	508	SF	7	10+ years	
	Water Closet	3rd Floor	5	EA	6	6-10 years	
	Water Closet	3rd Floor	1	EA	4	0-1 year	Out of service
	Accessories	3rd Floor - East	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor - East	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - East	1	EA	6	10+ years	
	Floor - Tile	3rd Floor - East	45	SF	6	10+ years	
	Lavatory	3rd Floor - East	1	EΑ	6	6-10 years	
	Lighting - Lay-in	3rd Floor - East	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor - East	1	EA	7	10+ years	
	Partitions	3rd Floor - East	1	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor - East	130	SF	7	10+ years	
	Water Closet	3rd Floor - East	1	EA	6	6-10 years	
	Accessories	Engineer's Toilet Room	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Toilet Room	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Toilet Room	1	EA	6	10+ years	
	Floor - Tile	Engineer's Toilet Room	17	SF	6	6-10 years	
	Floor - Tile	Engineer's Toilet Room	3	SF	4	1-2 years	Damaged tile on
	Lavatory	Engineer's Toilet Room	1	EA	6	6-10 years	
	Lighting - Lay-in	Engineer's Toilet Room	1	EA	6	10+ years	
	Lighting - Wall Mounted	Engineer's Toilet Room	1	EA	6	10+ years	
	Walls - Concrete Block	Engineer's Toilet Room	165	SF	6	10+ years	
	Water Closet	Engineer's Toilet Room	1	EA	6	6-10 years	
Catego	ry : Classroom		В	uildina	: Additio	on 2	
, , , , , , , , , , , , , , , , , , ,	•					Recommend	

Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #110 (Kind	ergarten)					
AC Units	1st Floor	1	EA	7	6-10 years	



Category : Classroom		В	uilding	on 2	-		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	35	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,168	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,165	SF	6	10+ years	
	Floor - Tile	1st Floor	3	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	1st Floor	27	EΑ	7	10+ years	zamagea me
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	43	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,071	SF	6	10+ years	
	Work Sink	1st Floor	1,071	EA	7	6-10 years	
	Work on K	13(1100)	'		,	o ro years	
Classroo	om #112 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	41	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,168	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,168	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EA	7	10+ years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	43	SF	7	10+ vears	
	Walls - Concrete Block	1st Floor	1,071	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classros	m #447 (Deculer Classroom)						
Classion	om #117 (Regular Classroom)	4 . 🖪				0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	31	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	863	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	863	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EΑ	7	10+ years	
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Storage/ Closet	1st Floor	7	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	949	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #118 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	28	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	1,258	SF	7		
						10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1 250	EA	7	10+ years	
	Floor - Tile	1st Floor	1,258	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	28	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	

Page : 38 of 49 Campus Name: Gresham Assessment Date: 10/30/2023



Category : Classroom			B	Building : Addition 2					
_				_		Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Storage/ Closet	1st Floor	42	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	1,320	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	6-10 years			
lassroc	m #210 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	35	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	870	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	870	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years			
	Marker Board	2nd Floor	28	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	949	SF	7	10+ years			
:lassroc	om #211 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	28	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	863	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	860	SF	7	10+ years			
	Floor - Tile	2nd Floor	5	SF	4	0-1 year	Damaged 9x9 tile		
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years	Damaged 9x9 tile		
	Lighting - Lay-iii Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years			
	Marker Board	2nd Floor 2nd Floor	28	LF	6	•			
	Walls - Concrete Block	2nd Floor 2nd Floor	949	SF	7	6-10 years			
	Walls - Concrete Block	ZIId Floor	949	SF	,	10+ years			
lassroc	om #212 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	35	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	863	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	863	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	949	SF	7	10+ years			
lassroo	nm #213 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	35	LF	7	10+ years			
	Casework Ceiling - Plaster/Drywall	2nd Floor	863	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	EA	7	10+ years			
	DO019 - MOOG DO019 HIGH HW	ZIIU FIOOI	ı	EA	,	10+ years			

Campus Name: Gresham Page : 39 of 49 Assessment Date: 10/30/2023



Catego	ry : Classroom		В	uilding	: Additi	on 2	
				Recom			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	2nd Floor	863	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Marker Board	2nd Floor	28	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	949	SF	7	10+ years	
	Walls Consider Block	2110 1 1001	040	O.	,	101 years	
Classroc	om #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	863	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	862	SF	7	10+ years	
	Floor - Tile	2nd Floor	1	SF	4	0-1 year	Damaged 9x9 tile
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years	Damagea 3x3 tile
	Lighting - Lay-iii Lighting - Pendent/Surface	2nd Floor 2nd Floor	20	EA	7		
						10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	949	SF	7	10+ years	
Classroc	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	864	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	-	
	Floor - Tile	2nd Floor 2nd Floor	863	SF	7	10+ years	
						10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Marker Board	2nd Floor	28	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	7	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	949	SF	7	10+ years	
lassroo	om #216 (Regular Classroom)						
21433100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	31	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	863	SF	7	•	
	Doors - Wood Doors inclu hw			_		10+ years	
		2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	863	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	7	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	949	SF	7	10+ years	
Classroo	om #217 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	7		
	Casework	ZIIU FIUUI	28	ᄕ	1	6-10 years	



Catego	ory : Classroom		В	Building : Addition 2				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	2nd Floor	863	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years		
	Floor - Tile	2nd Floor	863	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years		
	Marker Board	2nd Floor	30	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	7	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	949	SF	7	10+ years		
	Wireless System	2nd Floor	1	EA	7	6-10 years		
Classroo	om #218 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	35	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	870	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	2nd Floor	870	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years		
	Marker Board	2nd Floor	30	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	949	SF	7	10+ years		
Classroo	om #220 (Other Instructional Use)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	60	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	993	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Tile	2nd Floor	993	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	20	EΑ	7	10+ years		
	Marker Board	2nd Floor	28	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	1,013	SF	7	10+ years		
	Work Sink	2nd Floor	3	EA	7	10+ years		
Classroo	om #310 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	35	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	863	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	863	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	1	EA	7	10+ years		
	Lighting - Lay-in Lighting - Pendent/Surface	3rd Floor	20	EA	6	10+ years		
	Marker Board	3rd Floor	28	LF	7	6-10 years		
		3rd Floor	949	SF	7	•		
	Walls - Concrete Block	310 F100F	949	or.	1	10+ years		



Guicgo	Category : Classroom		B	uilding	: Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #311 (Library)						
	Casework	3rd Floor	35	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	893	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Carpet	3rd Floor	863	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	951	SF	6	10+ years	
Classroo	om #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	35	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	863	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	863	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	ĒA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	19	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	Not working
	Marker Board	3rd Floor	31	LF	6	6-10 years	. tot working
	Walls - Concrete Block	3rd Floor	949	SF	6	10+ years	
						,	
Classroc	m #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	35	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	850	SF	6	10+ years	Repaired
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	863	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	Repaired
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	949	SF	7	10+ years	
Classroo	om #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	35	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	870	SF	7	10+ years	Repaired
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	•
	Floor - Tile	3rd Floor	870	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	13	EA	7	10+ years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	7	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	949	SF	7	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	



Category : Classroom			В	Building : Addition 2					
<b>4</b>						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #315 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	31	LF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	863	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years			
	Floor - Tile	3rd Floor	863	SF	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	10+ years			
	Marker Board	3rd Floor	31	LF	6	6-10 years			
	Storage/ Closet	3rd Floor	7	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	949	SF	6	10+ years			
_Classroo	m #316 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	28	LF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	863	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile	3rd Floor	863	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	10+ years			
	Marker Board	3rd Floor	30	LF	6	6-10 years			
	Storage/ Closet	3rd Floor	7	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	949	SF	6	10+ years			
Classroo	m #317 (Regular Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Casework	3rd Floor	35	LF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	863	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	863	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	1	EA	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	10+ years			
	Marker Board	3rd Floor	28	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	90	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	974	SF	6	10+ years			
	Wireless System	3rd Floor	1	EA	7	6-10 years			
_Classroo	m #318 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	35	LF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	863	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	862	SF	6	10+ years			
	Floor - Tile	3rd Floor	1	SF	4	0-1 year	Damaged 9x9 tile		



Catego	В	Building : Addition 2					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	10+ years	
	Marker Board	3rd Floor	28	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	949	SF	7	10+ years	
_Classroo	m #320 (Science Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	60	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,000	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,000	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EΑ	6	10+ years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,013	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	

Category : Interior **Building: Addition 2** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Corridor</u>							
	Ceiling - Splined	1st Floor	2,775	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	8	EA	6	10+ years	
	Doors - Transom Window	1st Floor	24	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	72	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	2,767	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	5	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Lay-in	1st Floor	48	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	1,440	SF	6	10+ years	
	Walls - Masonry	1st Floor	108	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,420	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	2,277	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	4	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	2,275	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2	SF	4	1-2 years	Damaged 9x9 tile
	Lighting - Lay-in	2nd Floor	36	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	5	1-2 years	Not working
	Walls - Concrete Block	2nd Floor	780	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	786	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,417	SF	7	10+ years	
	Ceiling - Splined	3rd Floor	2,277	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	4	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	2,207	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	30	SF	5	1-2 years	Tile slightly separating

Campus Name: Gresham Page : 44 of 49 Assessment Date: 10/30/2023



Catego	ry : Interior		В	uilding	: Addition	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	36	EA	6	10+ years	
	Walls - Concrete Block	3rd Floor	780	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	786	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	2,417	SF	7	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	10+ years	
	Metal Detector	Entire Building	1	EA	7	10+ years	
	Security Cameras	Entire Building	3	EA	7	6-10 years	
_Stairs							
	Ceiling - Splined	East	786	SF	6	10+ years	
	Floor - Terrazzo	East	597	SF	7	10+ years	
	Handrails	East	104	LF	7	10+ years	
	Lighting - Lay-in	East	10	EΑ	7	10+ years	
	Lighting - Lay-in	East	1	EΑ	5	1-2 years	Not working
	Stairs - Terrazzo	East	220	LF	6	10+ years	_
	Walls - Structural Glazed Tile	East	1,883	SF	6	10+ years	
	Ceiling - Splined	West	804	SF	6	10+ years	
	Floor - Terrazzo	West	570	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	West	82	SF	7	10+ years	
	Handrails	West	104	LF	7	10+ years	
	Lighting - Lay-in	West	6	EA	7	10+ years	
	Lighting - Pendent/Surface	West	2	EΑ	7	10+ years	
	Lighting - Wall Mounted	West	1	EA	6	10+ years	
	Stairs - Terrazzo	West	219	LF	6	10+ years	
	Stairs - Terrazzo	West	1	LF	5	1-2 years	Damaged terrazzo
	Walls - Structural Glazed Tile	West	1,938	SF	7	10+ years	-
Vertical (	Conveyance						
	Elevator - Hydraulic Elevator	North East	1	EA	7	10+ years	





Category: Site Building: Site

atego	ry : Site		В	uilding	: Site		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
hletic							
	Surface - Natural	South	34,089	SF	6	10+ years	
	Surface - Asphalt	South	6,385	SF	5	6-10 years	
	Surface - Asphalt	South	7,000	SF	5	2-5 years	Potholes and cracks throughout
			,,,,,,			,	
ivil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	5	1-2 years	Sinking
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	Not previously assessed
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	6	10+ years	
encing	Fencing - Chain Link	Entire Site	628	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	8	LF	5	0-1 year	Broken section
	Fencing - Chain Link Fencing - New Standard Ornamental	Entire Site	889	LF	6	10+ years	DIOREIT SECTION
	Fencing - New Standard Ornamental	Entire Site	354	LF	5	6-10 years	
	i enong - New Standard Offiamental	ETILITE SILE	354	LF	ວ	o- 10 years	
andsca	oe .						
	Benches	Entire Site	4	EA	6	10+ years	
	Landscape - Grass	Entire Site	4,800	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	8,244	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	1,200	SF	6	10+ years	
	Parkway trees	Entire Site	41	ĒΑ	6	10+ years	
	Planting Beds/ Area	Entire Site	3,947	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	31,145	SF	5	1-2 years	Cracking throughout
	Trash Receptacles	Entire Site	2	EA	6	10+ years	oraciming unroughtout
Parking I	_ot Surface - Asphalt	West	21,648	SF	5	2-5 years	Raveling, alligator cracking
	Surface - Aspirali	44G91	∠1,0 <del>4</del> 0	SF.	5	2-5 years	throughout
	Surface - Asphalt	West	300	SF	4	0-1 year	Large potholes
	Surface - Concrete	West	930	SF	7	10+ years	Not previously assessed
	Trash Enclosure - Chain Links	West	1,040	SF	7	6-10 years	Installed in 2022
	Vehicular Screening	West	302	LF	6	10+ years	
						-	
laygrou	nd Equipment - Pre K 3-5	Southwest	1	EA	6	6-10 years	Not previously assessed
			1	EA EA			Not previously assessed
	Equipment - School Age 5-12	Southwest	1		6	6-10 years	
	Surface - Poured Surface	Southwest	3,572	SF	6	2-5 years	
Sidowall	•						
idewalk	5						



Category : Site			В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	365	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	10,989	SF	6	10+ years	Recombined quantities
Signage							
	Flag Pole - Flag Pole	East	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/	East	1	EA	7	10+ years	New
	LED						
	Monument - Building Mounted Cut Letter	East	1	EA	6	10+ years	
	Sign						

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Gresham Page: 47 of 49 Assessment Date: 10/30/2023

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	intollada coago	Noom 200anon	- Hambon	Traine or	(0. /	700	711.00	Clop	200.0
Art Room	Regular Classroom	3rd Floor	304	304	1,025	216	40	Υ	Y
Office	Regular Classroom	1st Floor	106	106	1,025	188	43	Y	N
Office	Regular Classroom	1st Floor	107	107	1,025	193	33	Y	N
Play Room	Regular Classroom	3rd Floor	305	305	1,025	216	40	Y	
Play Room	Regular Classroom	3rd Floor	306	306	1,025	256	48	Y	
Regular Classroom	Regular Classroom	1st Floor	105	105	1,025	193	33	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	1,025	148	33	Y	Y
Store Room	Art Room	1st Floor	104	104	1,025	148	33	Y	N
Store Room	Regular Classroom	3rd Floor	307	307	1,025	216	40	Y	
Vacant	Regular Classroom	2nd Floor	205	205	1,025	148	40	Y	N
Vacant	Regular Classroom	2nd Floor	206	206	1,025	188	40	Y	
Vacant	Regular Classroom	2nd Floor	207	207	1,025	148	40	Y	
radant	rtogalar Glacorcom	2.10 1 1001		20.	1,020	1.10	10		
Building : Addition 2									
Computer Lab	Computer Lab	2nd Floor	217	217	877	180	90		
Kindergarten	Kindergarten	1st Floor	110	110	1,211	270	135	N	Υ
Kindergarten	Kindergarten	1st Floor	112	112	1,211	270	135		Υ
Kindergarten	Kindergarten	1st Floor	118	118	1,300	270	135		Υ
Library	Regular Classroom	3rd Floor	311	311	900	180	90	N	N
Other Instructional Use	Regular Classroom	2nd Floor	220	220	993	180	90		Υ
Regular Classroom	Computer Lab	3rd Floor	317	317	863	180	90		Υ
Regular Classroom	Regular Classroom	1st Floor	117	117	863	180	90	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	870	180	90		Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	863	180	90		Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	863	180	90		Υ
Regular Classroom	Regular Classroom	2nd Floor	213	213	863	180	90		Υ
Regular Classroom	Regular Classroom	2nd Floor	214	214	863	180	90		Υ
Regular Classroom	Regular Classroom	2nd Floor	215	215	870	180	90		Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	870	180	90		Υ
Regular Classroom	Regular Classroom	2nd Floor	218	218	870	180	90		Υ
Regular Classroom	Regular Classroom	3rd Floor	310	310	863	180	90		Y
Regular Classroom	Regular Classroom	3rd Floor	312	312	863	126	53		Υ
Regular Classroom	Regular Classroom	3rd Floor	313	313	877	180	90		Y
Regular Classroom	Regular Classroom	3rd Floor	314	314	870	180	90		Y
Regular Classroom	Regular Classroom	3rd Floor	315	315	877	180	90		Υ
Regular Classroom	Regular Classroom	3rd Floor	316	316	877	180	90		Υ
Regular Classroom	Regular Classroom	3rd Floor	318	318	863	180	90		Υ
Science Classroom	Regular Classroom	3rd Floor	320	320	1,000	180	90		Υ



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Addition 1									
Music Room	Regular Classroom	1st Floor	201	201	835	226	53	Υ	Υ
Other Instructional Use	Regular Classroom	3rd Floor	301	301	835	216	49	Υ	
Store Room	Kindergarten	1st Floor	101	101	1,500	274	60	Υ	N
Store Room	Regular Classroom	2nd Floor	203	203	835	190	26	Υ	
Store Room	Regular Classroom	3rd Floor	303	303	835	216	49	Υ	