

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1937	3	57,758
Addition 1	1954	2	13,300
Addition 2	2016	3	37,761
Addition-Elevator Tower	2004	3	2,780
Campus Total			111,599

Category: Exterior Building: Main

Calego	iry . ⊑xterior	alegory . Exterior		Bulluling . Maili				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Cell Equ	-							
	Cell Equipment - Antenna	Main Roof	2	EA	7	10+ years	New	
	Cell Equipment - Cabinets	Main Roof	2	EA	7	10+ years	New	
Entrance	9							
	Entrance Control - Audio and Video	#1- Main Accessible- NE	1	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	#1- Main Accessible- NE	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	#1- Main Accessible- NE	2	EA	6	10+ years		
	Exterior Stairs - Concrete	#1- Main Accessible- NE	160	LF	6	10+ years		
	Exterior Stairs - Concrete	#1- Main Accessible- NE	5	LF	5	1-2 years	Cracked	
	Power Door Operator and Controls	#1- Main Accessible- NE	1	EA	7	10+ years		
	Ramp Handrail - Steel_Ramp Handrail	#1- Main Accessible- NE	145	LF	6	10+ years		
	Ramps - Concrete	#1- Main Accessible- NE	70	LF	7	10+ years	Repaired	
	Stair Handrail - Steel_Stair Handrail	#1- Main Accessible- NE	50	LF	6	10+ years		
	Exterior Doors - Exterior Wood Door	#12 - Boiler Room- SW	1	EA	5	1-2 years	Damaged	
	Exterior Doors - Transom Lite	#12 - Boiler Room- SW	1	EA	6	10+ years		
	Exterior Doors - Overhead Rolling/ Garage Door	#12.5 - NW	1	EA	6	6-10 years		
	Exterior Doors - Exterior Wood Door	#14 - NE	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	#14 - NE	1	EA	6	10+ years		
	Exterior Stairs - Stone	#14 - NE	53	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	#2 E	1	EA	6	10+ years		



Catego	ry : Exterior		В	uilding	: Main		
	-					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	#2 E	2	EA	6	10+ years	
	Exterior Stairs - Stone	#2 E	3	LF	7	10+ years	Not previously assessed
	Exterior Doors - Exterior Steel Door	#3- SE	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#3- SE	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#3- SE	40	LF	6	10+ years	
	Exterior Stairs - Stone	#3- SE	75	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#4- SE	2	EA	5	6-10 years	
	Exterior Doors - Transom Lite	#4- SE	2	EA	6	10+ years	
	Exterior Stairs - Stone	#4- SE	46	LF	6	10+ years	
Foundati	on						
	Foundation - Concrete	Entire Building	805	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	57,688	SF	7	10+ years	
l imbation o							
Lighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	19	EA	6	10+ years	
		9				, , , , , , , , , , , , , , , , , , , ,	
Roof Sys							
	Access Ladder - Metal	Boiler Room Roof	2	EA	7	10+ years	
	Coping - Terra Cotta	Boiler Room Roof	153	LF	6	10+ years	
	Downspouts - Interior Downspouts	Boiler Room Roof	38	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Boiler Room Roof	153	LF	6	10+ years	
	Roof - Modified Bitumen	Boiler Room Roof	1,453	SF	5	2-5 years	
	Roof Structure - Concrete	Boiler Room Roof	1,453	SF	7	10+ years	
	Coping - Terra Cotta	Low East Roofs	101	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low East Roofs	22	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low East Roofs	101	LF	6	10+ years	
	Roof - Modified Bitumen	Low East Roofs	310	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Low East Roofs	310	SF	7	10+ years	
	Coping - Metal	Low NW Courtyard Roof	70	LF	6	10+ years	
	Roof - Modified Bitumen	Low NW Courtyard Roof	278	SF	5	6-10 years	
	Roof Structure - Concrete	Low NW Courtyard Roof	278	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	5	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	5	10+ years	
	Chimney - Brick Chimney- Stainless Steel Liner	Main Roof	102	LF	6	10+ years	
	Coping - Terra Cotta	Main Roof	467	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	188	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	285	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	142	LF	6	10+ years	
	Parapet - Parapet > 30"	Main Roof	40	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	11,286	SF	5	2-5 years	Some repairs
	. 100. Modified Brighton		11,200	٥.	J	_ 0 youro	



atego	ry : Exterior		В	uilding	· Main		
atego	TY . Exterior			ananig	. Walli	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
лоцр	Roof Hatch - Metal	Main Roof	2	EA	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	11,286	SF	7	10+ years	
	Coping - Terra Cotta	N Auditorium Roof	385	LF	6	10+ years	
	Downspouts - Interior Downspouts	N Auditorium Roof	70	LF	6	10+ years	
	Parapet - Parapet < 16" Height	N Auditorium Roof	385	LF	6	10+ years	
	Roof - Modified Bitumen	N Auditorium Roof	5,469	SF	5	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	N Auditorium Roof		SF	7	•	
	Coping - Terra Cotta	S Gym Roof	5,469	LF	6	10+ years 10+ years	
		S Gym Roof	278 70	LF	6		
	Downspouts - Interior Downspouts	S Gym Roof	_	LF	_	10+ years	
	Parapet - 16" - 30" Height	S Gym Roof	203		6	10+ years	
	Parapet - Parapet < 16" Height	S Gym Roof	55	LF	6	10+ years	
	Parapet - Parapet > 30"	S Gym Roof	20	LF	6	10+ years	
	Roof - Modified Bitumen	S Gym Roof	3,458	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	S Gym Roof	3,458	SF	7	10+ years	
/alls							
	Cheek-Wall - Concrete	Entire Building	80	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	112	SF	5	10+ years	
	Cornice - Terra Cotta	Entire Building	845	LF	5	10+ years	
	Exterior Walls - Brick	Entire Building	23,846	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	295	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	845	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	6	SF	5	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,145	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	280	SF	5	10+ years	
/indows							
	Curtain wall - Louver	Entire Building	12	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	231	SF	6	10+ years	
	Lintels - Steel	Entire Building	609	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	30	LF	5	2-5 years	
	Skylite - Glass Single-Pane	Entire Building	90	SF	5	6-10 years	
	Windows - Casement Aluminum Double-	Entire Building	738	SF	5	6-10 years	
	pane	Little Ballaning	. 33	O.	Ŭ	o io jouio	
	Windows - Casement Steel	Entire Building	75	SF	4	1-2 years	Cracked, rusted
	Windows - Sash Aluminum Double-pane	Entire Building	4,066	SF	6	10+ years	Oracica, racica
otogo	ru . Electrical		P	uildina	. Main		
atego	ry : Electrical		В	uilding	. Wall	Recommend	
roup	- •	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and	Entire Building	2,682	SF	6	6-10 years	
		•	•			•	

Campus Name: Jamieson Page : 3 of 48 Assessment Date: 12/20/2023



atego	ry : Electrical		B	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Aisle Lighting						
	Exit Signs - Auditoium	Entire Building	6	EA	6	6-10 years	Location changed for clarification a the auditorium occupies space on multiple floors.
	Exit Signs - Corridors and Stairs	Entire Building	13	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Rank, Reason and Priority Rep adjusted based on current observations.
	Security System - CCTV	Entire Building	57,758	SF	6	6-10 years	All cameras in Main are exterior.
	Security System - Intrusion Detection	Entire Building	57,758	SF	6	6-10 years	
	Emergency Generator- Outdoor- Diesel - 101 - 150 KW	West Countyard	1	EA	6	6-10 years	
ain Se	rvice						
	Main Electrical Service - 1200 A 120/240/3PH	Electrical Room	1	EA	6	2-5 years	
	Main Electrical Service - 1200 A 120/240/3PH	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	57,758	SF	7	6-10 years	
ower D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	6-10 years	Quantity changed as total has bee divided/aggregated.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification. Rank, Reason and Priority Rep changed as open fuse receptacles expose live conductors presenting live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	11	EA	6	6-10 years	Quantity changed based on currer observations and as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification. Rank, Reason and Priority Rep changed as a missing interior cover plate exposes live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification. Rank, Reason and Priority Rep changed as open breaker slots expose live conductors presenting live front condition.



Catago	ry : Flootrical		D	uildina	· Main		6650 N Mozart STREET, Chicago, IL 60659
Catego	ry : Electrical		В	uilding	. wain	Recommend	
Craun	Itam Tuna	Location	Quantitu	ПОМ	Rank		Comments
Group	Item - Type Main Distribution Panels - 400 - 600 amp	Entire Building	Quantity 1	UOM EA	7	Replacement 10+ years	Comments
	•	Entire Building Entire Building	1	EA	6	•	
	Main Distribution Panels - Greater than 600	Entire building	ı	EA	O	6-10 years	
	amp Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	6-10 years	
	amp	Entire building	į	LA	O	0-10 years	
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	6-10 years	
	amp	Littile building	'	LA	U	0-10 years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	6-10 years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	6-10 years	
	174110101111010 120/210 120/200	Entire Ballating	•		Ū	o io youio	
Catego	ry : Fire Protection		В	uilding	: Main		
ou.ogo.			_	aag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	· ·		40.0		1141111		
LIIC Alai	Fire ALarm Anunciator	Entire Building	2	EA	6	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves Main and all Additions
	Fire Alarm Strobe Lights	Entire Building	57,758	SF	6	6-10 years	Gerves Main and an Additions
	Fire Alarm_System	Entire Building	57,758	SF	6	6-10 years	
	i no ruami_oyotom	Entire Ballating	01,100	O.	Ū	o io youio	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Indoor Return Fans- Centrifugal Squirrel	Basement	1	EΑ	6	10+ years	
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Basement	1	ΕA	6	10+ years	
		Basement Boiler Room	1	EA EA	6 6	10+ years 6-10 years	AHU-4, serves gym
	Cage - 10001 - 20000 CFM					•	AHU-4, serves gym
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone-					•	AHU-4, serves gym
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Boiler Room	1	EA	6	6-10 years	AHU-4, serves gym
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake	Boiler Room Boiler Room	1	EA EA	6 6	6-10 years	AHU-4, serves gym
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts	Boiler Room Boiler Room Boiler Room Boiler Room	1 1 1 100	EA EA LF	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone-	Boiler Room Boiler Room Boiler Room	1 1 1	EA EA EA	6 6 6	6-10 years 6-10 years 6-10 years	AHU-1, serves auditorium. Location
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	1 1 1 100	EA EA LF EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake	Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	1 1 1 100	EA EA LF EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	AHU-1, serves auditorium. Location changed for clarification.
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm	Boiler Room	1 1 100 1 1	EA EA LF EA EA	6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	AHU-1, serves auditorium. Location
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonry and Ducts-	Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	1 1 1 100	EA EA LF EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	AHU-1, serves auditorium. Location changed for clarification.
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Boiler Room	1 1 100 1 1	EA EA LF EA EA LF	6 6 6 6 6 5	6-10 years	AHU-1, serves auditorium. Location changed for clarification. Location changed for clarification.
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up- Single Zone w/	Boiler Room	1 1 100 1 1	EA EA LF EA EA	6 6 6 6 6	6-10 years	AHU-1, serves auditorium. Location changed for clarification. Location changed for clarification. AHU-3, serves south areas of Main.
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Boiler Room	1 1 100 1 1 1 100	EA EA LF EA EA LF	6 6 6 6 6 5	6-10 years	AHU-1, serves auditorium. Location changed for clarification. Location changed for clarification. AHU-3, serves south areas of Main. Location changed for clarification.
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up- Single Zone w/	Boiler Room	1 1 100 1 1 1 100	EA EA LF EA EA LF	6 6 6 6 6 5	6-10 years	AHU-1, serves auditorium. Location changed for clarification. Location changed for clarification. AHU-3, serves south areas of Main. Location changed for clarification. Quantity changed as total has been
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake	Boiler Room Mechanical Room	1 1 100 1 1 100 1	EA EA LF EA EA LF EA	6 6 6 6 6 6 6	6-10 years	AHU-1, serves auditorium. Location changed for clarification. Location changed for clarification. AHU-3, serves south areas of Main. Location changed for clarification. Quantity changed as total has been divided/aggregated.
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Boiler Room	1 1 100 1 1 1 100	EA EA LF EA EA LF	6 6 6 6 6 5	6-10 years	AHU-1, serves auditorium. Location changed for clarification. Location changed for clarification. AHU-3, serves south areas of Main. Location changed for clarification. Quantity changed as total has been divided/aggregated. Location changed for clarification.
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm Air Intake Auxiliaries - 4000 - 8000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake	Boiler Room Mechanical Room	1 1 100 1 1 100 1	EA EA LF EA EA LF EA	6 6 6 6 6 6 6	6-10 years	AHU-1, serves auditorium. Location changed for clarification. Location changed for clarification. AHU-3, serves south areas of Main. Location changed for clarification. Quantity changed as total has been divided/aggregated.

Campus Name: Jamieson Page : 5 of 48 Assessment Date: 12/20/2023



Catego	ry : Mechanical		В	uilding	: Main		•
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							divided/aggregated.
	Reheat Boxes - Reheat Boxes with Steam	Mechanical Room	5	EA	6	6-10 years	Quantity changed as total has been
	Coil		400	. –	•	0.40	divided/aggregated.
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	100	LF	6	6-10 years	Quantity changed as total has been
	and Ducts	Mechanical Room	10	EA	5	6.10 vooro	divided/aggregated.
	Zone Dampers	Mechanical Room	13	EA	5	6-10 years	Quantity changed as total has been divided/aggregated.
	Air Handling Unit- Built Up- Single Zone w/	Mechanical Room	1	EA	6	6-10 years	AHU-2, serves north areas of Main.
	Air Tunnel- Steam Coils - 15001 - 25000 cfm	Wednamear Room		L/ \	O	o io years	74 10 2, 3crvc3 florar areas or Main.
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EΑ	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam	Mechanical Room	4	EA	6	6-10 years	
	Coil					•	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	100	LF	6	6-10 years	
	and Ducts					-	
	Zone Dampers	Mechanical Room	13	EA	5	6-10 years	
_Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	6	6-10 years	
	Pressure Boiler - 76 - 100 HP						
	Chemical Feed System	Boiler Room	1	EA	5	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	10+ years	BLR-1
	Steam- Low Pressure Boiler - 76 - 100 HP						
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	10+ years	BLR-2
	Steam- Low Pressure Boiler - 76 - 100 HP				_		
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	6-10 years	
	Steam Traps	Boiler Room	62	EA	6	6-10 years	
Gas Boo		5 : 5				0.10	
	Gas Booster	Boiler Room	2	EA	5	6-10 years	
	.						
Heating		Dellan Dagar				0.40	
	Unit Heater - Gas	Boiler Room	2	EΑ	6	6-10 years	
	Radiators - Steam	Entire Building	18	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	5	EA	5	6-10 years	Quantity changed to match current
	Unit Haatar Floatria	Entiro Building	•	Ε^	6	6 10 40000	observations.
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	Location changed for clarification.
	Fin Tube - Steam	Entire Building	3	LF	7	6-10 years	

Campus Name: Jamieson Page : 6 of 48 Assessment Date: 12/20/2023



atego	ry : Mechanical		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•						<u> </u>	
empera	ature Control						
	DDC System	Entire Building	57,758	SF	6	6-10 years	
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	42	EA	6	6-10 years	
ntilati	22						
шшаш	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Location changed to match current
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	observations and per review with Building Engineer. Motor assembly not visible but unit was heard to be operating with no undue vibration, and the fan was successfully tested for functionality at the time of assessment using a piece of tissue paper. Quantity changed to match current observations and per review with Building Engineer.
atego	ry : Plumbing		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
t Wat	er						
.:	Gas Heater - Less than 150000 BTU/HR	Entire Building	2	EA	6	6-10 years	Priority Rep adjusted based on current observations and on the agof the equipment.
ing	Domestic Piping-Hot Water Return Lines	Entire Building	57,758	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	57,758	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	57,758	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	57,758	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	57,758	SF	6	6-10 years	
	(Risers)			~-	6	6-10 years	
	(Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	57,758	SF	O	5 . c , c c	
		Entire Building Entire Building	57,758 57,758	SF SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	-				-	

Campus Name: Jamieson Page : 7 of 48 Assessment Date: 12/20/2023



Catego	ry : Plumbing	ng				Building : Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
Pumps										
•	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	6-10 years				
	Pumps - Ejector-Duplex	Entire Building	1	EA	5	6-10 years				

Category : Room **Ruilding** : Main

Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	trative Suites/Offices						
	Ceiling - Plaster/Drywall	307 Special Education Room	281	SF	5	10+ years	
	Doors - Transom Window	307 Special Education Room	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	307 Special Education Room	1	EA	6	10+ years	
	Floor - Tile	307 Special Education Room	281	SF	6	6-10 years	
	Lighting - Pendent/Surface	307 Special Education Room	3	EA	7	6-10 years	
	Power Distribution	307 Special Education Room	6	EA	7	10+ years	
	Walls - Plaster/Drywall	307 Special Education Room	425	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Assistant Principals Office	200	SF	6	10+ years	
	Doors - Transom Window	Assistant Principals Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principals Office	2	EA	6	10+ years	
	Floor - Tile/Sheet	Assistant Principals Office	200	SF	7	6-10 years	
	Lighting - Pendent/Surface	Assistant Principals Office	2	EA	6	10+ years	
	Power Distribution	Assistant Principals Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Assistant Principals Office	520	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office - Basement	122	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office - Basement	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office - Basement	122	SF	5	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office - Basement	1	EA	6	6-10 years	
	Power Distribution	Engineer's Office - Basement	6	EA	6	6-10 years	
	Storage/ Closet	Engineer's Office - Basement	150	SF	5	10+ years	
	Walls - Plaster/Drywall	Engineer's Office - Basement	148	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office - Basement	10	SF	5	1-2 years	Damaged
	Ceiling - Plaster/Drywall	Janitor's Room - Basement	92	SF	5	10+ years	
	Doors - Wood Doors inclu hw	Janitor's Room - Basement	1	EA	6	10+ years	
	Floor - Concrete	Janitor's Room - Basement	92	SF	5	10+ years	
	Lighting - Pendent/Surface	Janitor's Room - Basement	1	EA	6	6-10 years	
	Power Distribution	Janitor's Room - Basement	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	Janitor's Room - Basement	120	SF	5	10+ years	
	AC Unit	Main Office Suite 1st floor 120	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office Suite 1st floor 120	500	SF	6	10+ years	
	Doors - Transom Window	Main Office Suite 1st floor 120	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office Suite 1st floor 120	2	EA	6	10+ years	
	Floor - Tile	Main Office Suite 1st floor 120	500	SF	6	10+ years	
	Lighting - Pendent/Surface	Main Office Suite 1st floor 120	4	EA	6	10+ years	
	Power Distribution	Main Office Suite 1st floor 120	8	EA	6	10+ years	
	Walls - Plaster/Drywall	Main Office Suite 1st floor 120	1,894	SF	6	10+ years	

Campus Name: Jamieson Page : 8 of 48 Assessment Date: 12/20/2023



Catego	Category : Room		В	uilding	: Main				
J				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	Nurse office inside classroom 104	200	SF	6	10+ years			
	Doors - Transom Window	Nurse office inside classroom 104	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Nurse office inside classroom 104	2	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Nurse office inside classroom 104	200	SF	6	6-10 years			
	Lighting - Pendent/Surface	Nurse office inside classroom 104	2	EA	7	10+ years			
	Power Distribution	Nurse office inside classroom 104	4	EA	7	10+ years			
	Storage/ Closet	Nurse office inside classroom 104	100	SF	7	10+ years			
	Walls - Plaster/Drywall	Nurse office inside classroom 104	470	SF	7	10+ years			
	Work SInk	Nurse office inside classroom 104	1	EA	7	6-10 years			
	AC Unit	Principals Office 1st Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	Principals Office 1st Floor	200	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Principals Office 1st Floor	1	EA	6	10+ years			
	Floor - Tile/Sheet	Principals Office 1st Floor	200	SF	7	6-10 years	Vinyl plank flooring		
	Lighting - Pendent/Surface	Principals Office 1st Floor	2	EA	6	10+ years			
	Power Distribution	Principals Office 1st Floor	6	EA	6	10+ years			
	Walls - Plaster/Drywall	Principals Office 1st Floor	520	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Room 109, Speech Room	105	SF	6	10+ years			
	Doors - Transom Window	Room 109, Speech Room	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Room 109, Speech Room	1	EA	6	10+ years			
	Floor - Wood	Room 109, Speech Room	105	SF	6	10+ years			
	Lighting - Pendent/Surface	Room 109, Speech Room	1	EA	7	10+ years			
	Power Distribution	Room 109, Speech Room	2	EA	6	10+ years			
	Walls - Plaster/Drywall	Room 109, Speech Room	131	SF	6	10+ years			
Auditoriu	m & Theater								
	Balcony Seating	1st Floor	90	EA	7	10+ years			
	Ceiling - Splined	1st Floor	2,682	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	9	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	1st Floor	80	SF	7	10+ years	Balcony		
	Floor - Tile	1st Floor	2,682	SF	6	10+ years	•		
	Lighting - Chandelier, Incandescent	1st Floor	8	EA	6	10+ years			
	Main Floor Seating	1st Floor	344	EA	7	10+ years			
	Sound System	1st Floor	1	EA	7	6-10 years			
	Stage	1st Floor	328	SF	6	10+ years			
	Stage Curtain	1st Floor	8	EA	7	6-10 years			
	Stage Lift	1st Floor	1	EA	7	10+ years			
	Stage Lighting System	1st Floor	1	EA	7	10+ years			
	Stage-Stairs - Terrazzo	1st Floor	48	LF	7	10+ years			
	Stage-Stairs - Wood	1st Floor	24	LF	6	10+ years			
	Stairs - Terrazzo	1st Floor	68	LF	6	10+ years			
	Storage/ Closet	1st Floor	100	SF	7	10+ years			
		1st Floor	80	SF	7	10+ years			
	Storage/ Closet	151 11001	80	SF	,	TOT years			



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Gymnas							
	Ceiling - Plaster/Drywall	1st Floor	2,393	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Wood	1st Floor	2,393	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	
	Scoreboards	1st Floor	1	EA	5	6-10 years	
	Sound System	1st Floor	1	EA	5	6-10 years	
	Walls - Masonry	1st Floor	3,589	SF	6	10+ years	
_MDF_ID	E						
_	Doors - Wood Doors inclu hw	In Room 205	1	EA	6	10+ years	
	Finishes	In Room 205	138	SF	5	10+ years	
	Window AC Unit	In Room 205	1	EA	7	6-10 years	
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	48	SF	5	10+ years	
	Storage Room	1st Floor	98	SF	5	10+ years	
	Janitor's Closet	2nd Floor	48	SF	5	10+ years	
	Storage Room	2nd Floor	90	SF	7	10+ years	
	Janitor's Closet	3rd Floor	48	SF	5	10+ years	
	Air Intake Plenums	Basement	2,000	SF	7	10+ years	
	Boiler Room	Basement	1,449	SF	5	10+ years	
	Coal Room	Basement	405	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	511	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	831	SF	5	10+ years	
	Storage Room	Basement	272	SF	7	10+ years	
	Storage Room	Basement	1,900	SF	5	10+ years	
Restroor	n						
	Accessories	1st Floor	262	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	262	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	262	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	10+ years	
	Partitions	1st Floor	9	EA	7	10+ years	
	Walls - Tile	1st Floor	832	SF	6	10+ years	
	Water Closet	1st Floor	9	ĒΑ	6	6-10 years	
	Accessories	1st Floor	262	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	262	SF	6	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	



Catego	Category : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	262	SF	6	6-10 years	
	Floor Drain	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
	Partitions	1st Floor	2	EA	7	6-10 years	
	Urinals	1st Floor	8	EA	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	832	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	110	SF	7	10+ years	
	Water Closet	1st Floor	2	ĒΑ	6	6-10 years	
	Accessories	2nd Floor	262	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	262	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	262	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	9	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	832	SF	6	,	
	Water Closet	2nd Floor 2nd Floor	9	EA	6	10+ years	
			262	SF		10+ years	
	Accessories	2nd Floor			7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	262	SF	5	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	262	SF	6	10+ years	
	Floor Drain	2nd Floor	2	EΑ	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years	
	Partitions	2nd Floor	3	EA	7	10+ years	
	Urinals	2nd Floor	7	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	832	SF	6	10+ years	
	Water Closet	2nd Floor	3	EA	7	10+ years	
	Accessories	3rd Floor	262	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	262	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	262	SF	6	10+ years	
	Floor Drain	3rd Floor	2	EA	7	10+ years	
	Lavatory	3rd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	8	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	752	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	80	SF	7	10+ years	
	Water Closet	3rd Floor	2	EA	6	10+ years	
						,	



Catego	Category : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	3rd Floor	262	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	262	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	262	SF	6	10+ years			
	Floor Drain	3rd Floor	1	EΑ	7	10+ years			
	Lavatory	3rd Floor	2	EA	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years			
	Partitions	3rd Floor	6	ĒΑ	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	832	SF	6	10+ years			
	Water Closet	3rd Floor	6	ĒΑ	6	10+ years			
	Accessories	Engineer's Office	28	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	Engineer's Office	28	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years			
	Floor - Tile/Sheet	Engineer's Office	28	SF	7	10+ years			
	Lavatory	Engineer's Office	1	EA	6	6-10 years			
	Lighting - Wall Mounted	Engineer's Office	1	EA	6	6-10 years			
	Walls - Plaster/Drywall	Engineer's Office	87	SF	6	10+ years			
	Water Closet	Engineer's Office	1	EA	6	10+ years			
				SF	7	,			
	Accessories Ceiling - Plaster/Drywall	Principals Office	50 50	SF SF	6	6-10 years			
	Doors - Wood Doors inclu hw	Principals Office	1	EA	6	10+ years			
		Principals Office	· · · · · · · · · · · · · · · · · · ·	SF	_	10+ years			
	Floor - Tile Ceramic/ Porcelain	Principals Office	50		6	10+ years			
	Lavatory	Principals Office	1	EΑ	6	6-10 years			
	Lighting - Pendent/Surface	Principals Office	1	EA	7	10+ years			
	Walls - Plaster/Drywall	Principals Office	260	SF	6	10+ years			
	Water Closet	Principals Office	1	EA	6	6-10 years			
	Accessories	Staff Room in Janitor's Room	28	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	Staff Room in Janitor's Room	28	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Staff Room in Janitor's Room	1	EA	6	10+ years			
	Floor - Epoxy/ Painted	Staff Room in Janitor's Room	28	SF	7	10+ years			
	Lavatory	Staff Room in Janitor's Room	1	EA	6	6-10 years			
	Lighting - Wall Mounted	Staff Room in Janitor's Room	1	EA	6	6-10 years			
	Walls - Plaster/Drywall	Staff Room in Janitor's Room	87	SF	6	10+ years			
	Water Closet	Staff Room in Janitor's Room	1	EA	6	10+ years			
	Accessories	Unisex Staff Room, 1st Floor	74	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Unisex Staff Room, 1st Floor	64	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Unisex Staff Room, 1st Floor	10	SF	4	1-2 years	Damaged		
	Doors - Wood Doors inclu hw	Unisex Staff Room, 1st Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Unisex Staff Room, 1st Floor	74	SF	6	10+ years			
	Lavatory	Unisex Staff Room, 1st Floor	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	Unisex Staff Room, 1st Floor	1	EA	7	10+ years			
	Partitions	Unisex Staff Room, 1st Floor	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	Unisex Staff Room, 1st Floor	93	SF	6	10+ years			
	Water Closet	Unisex Staff Room, 1st Floor	2	EA	6	6-10 years			

Campus Name: Jamieson Page : 12 of 48 Assessment Date: 12/20/2023



	ry : Room		R	uilding	: Main	•	6650 N Mozart STREET, Chicago, IL 60659
Calcyc	i y . Room			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Unisex Staff Room, 2nd Floor	74	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex Staff Room, 2nd Floor	74	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex Staff Room, 2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Staff Room, 2nd Floor	74	SF	7	10+ years	
	Floor Drain	Unisex Staff Room, 2nd Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	Unisex Staff Room, 2nd Floor	1	EA	7	6-10 years	
	Lavatory	Unisex Staff Room, 2nd Floor	1	EA	7	6-10 years	
	Lighting - Lay-in	Unisex Staff Room, 2nd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Unisex Staff Room, 2nd Floor	65	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Unisex Staff Room, 2nd Floor	93	SF	7	10+ years	
	Water Closet	Unisex Staff Room, 2nd Floor	1	ĒΑ	7	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
Cuarra	Hom. Tune	Location	Over the	ПОМ	Donle	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Regular Classroom)	4 . 5		Ε.Δ.		0.40	
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	732	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor	6 913	SF SF	5 6	10+ years 10+ years	
	·	13111001	313	O.	Ü	101 years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	735	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,458	SF	6	10+ years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	732	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	



Category : Classroom			В	uilding	: Main		· • • • · • · • · • · • · • · • · • · •
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	913	SF	6	10+ years	
Classroo	om #104 (Kindergarten)						
	AC Units	1st Floor	2	EA	5	6-10 years	
	Casework	1st Floor	64	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,032	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	1,032	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,809	SF	6	10+ years	
Classroo	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	732	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	913	SF	6	10+ years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	732	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	6	10+ years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	893	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	5	1-2 years	Damaged
Classroo	om #201 (Regular Classroom)						
<u></u>	AC Units	2nd Floor	1	EA	7	6-10 years	
			·			,	

Campus Name: Jamieson Page : 14 of 48 Assessment Date: 12/20/2023



Catego	ry : Classroom		В	uilding	: Main		5050 N MOZAIT OTNEET, Officago, IE 00055
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	913	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	913	SF	6	10+ years	
01	·					•	
_Classroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	910	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	6	10+ years	
	Chalk Board	2nd Floor	24	ĹF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	913	SF	6	10+ years	
	vvalis - i lastei/Diywali	2110 1 1001	913	Ji	U	TOT years	

Page : 15 of 48 Campus Name: Jamieson Assessment Date: 12/20/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
`laceroo	m #205 (Regular Classroom)						
JIASSIUU	AC Units	2nd Floor	1	ΕΛ	7	6 10 years	
	Casework	2nd Floor 2nd Floor	50	EA LF		6-10 years	
				SF	6	10+ years	
	Ceiling - Plaster/Drywall Doors - Transom Window	2nd Floor	732	SF SF	6	10+ years	
		2nd Floor	12		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	913	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroc	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	50	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	5	•	
	Walls - Plaster/Drywall		913	SF SF	6	10+ years	
	walls - Plaster/Drywall	2nd Floor	913	SF	б	10+ years	
lassroc	m #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	913	SF	6	10+ years	
lassroo	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	, 5	10+ years	
	Doors - Transom Window	2nd Floor 2nd Floor	12	SF SF	5 6		
			2		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	О	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	913	SF	6	10+ years	
Classroo	om #210 (Art Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	830	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	830	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,038	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6	SF	5	1-2 years	Damaged
	Work Sink	2nd Floor	1	EA	7	10+ years	Damaged
Classroo	om #300 (Regular Classroom)						
Classiu	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	730	SF	5	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	730	SF	6		
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
				LF		6-10 years	
	Marker Board	3rd Floor	22	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,458	5F	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	734	SF	5	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	734	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,458	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,458	SF	6	10+ years	
Classroo	om #303 (Science)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	33	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	738	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	738	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,238	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
_Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	7	ĹF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,458	SF	6	10+ years	
_Classroo	om #305 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	738	SF	6	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
						- ,	

Page: 18 of 48 Campus Name: Jamieson Assessment Date: 12/20/2023



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	638	SF	6	10+ years	
	Floor - Tile	3rd Floor	100	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	7	6-10 years	3.0
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,238	SF	6	10+ years	
lassroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	7.30	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood Doors inclu riw	3rd Floor	730	SF	6	10+ years	
		3rd Floor	12	EA	7		
	Lighting - Pendent/Surface Marker Board	3rd Floor	44	LF	6	6-10 years	
						6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,458	SF	6	10+ years	
atego	ry : Interior		В	uilding	: Main		
			0			Recommend	
•	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•			-			•	Comments
•	Ceiling - Plaster/Drywall	1st Floor	3,046	SF	6	10+ years	Comments
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	1st Floor 1st Floor	-	SF EA	6 6	10+ years 10+ years	Comments
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain	1st Floor	3,046	SF	6	10+ years	Comments
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	1st Floor 1st Floor	3,046	SF EA EA EA	6 6	10+ years 10+ years	Comments
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor	3,046 6 1	SF EA EA EA SF	6 6 5	10+ years 10+ years 10+ years	Comments
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler	1st Floor 1st Floor 1st Floor 1st Floor	3,046 6 1 3	SF EA EA EA SF SF	6 6 5 7	10+ years 10+ years 10+ years 10+ years	Comments
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,046 6 1 3 609	SF EA EA EA SF	6 6 5 7 6	10+ years 10+ years 10+ years 10+ years 10+ years	Damaged
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,046 6 1 3 609 2,407	SF EA EA EA SF SF	6 6 5 7 6 5	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 1-2 years	
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,046 6 1 3 609 2,407 30	SF EA EA SF SF SF	6 6 5 7 6 5	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier	1st Floor	3,046 6 1 3 609 2,407 30 35 176	SF EA EA SF SF SF EA EA	6 6 5 7 6 5 4 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,046 6 1 3 609 2,407 30 35 176 3,105	SF EA EA SF SF SF EA EA SF	6 6 5 7 6 5 4 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile	1st Floor	3,046 6 1 3 609 2,407 30 35 176 3,105 3,105	SF EA EA SF SF EA EA SF SF	6 6 5 7 6 5 4 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall	1st Floor	3,046 6 1 3 609 2,407 30 35 176 3,105	SF EA EA SF SF EA SF SF SF	6 6 5 7 6 5 4 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain	1st Floor 2nd Floor 2nd Floor	3,046 6 1 3 609 2,407 30 35 176 3,105 3,105 3,046 4	SF EA EA SF SF EA SF SF EA	6 6 5 7 6 5 4 6 6 6 6	10+ years	
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler	1st Floor 2nd Floor 2nd Floor 2nd Floor	3,046 6 1 3 609 2,407 30 35 176 3,105 3,105 3,046 4 2	SF EA EA SF SF EA SF EA SF EA	6 6 5 7 6 5 4 6 6 6 6 6 7 7	10+ years	
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	3,046 6 1 3 609 2,407 30 35 176 3,105 3,105 3,046 4 2 609	SF EA EA SF SF EA SF EA SF EA SF	6 6 5 7 6 5 4 6 6 6 6 6 7 7 6	10+ years	
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	3,046 6 1 3 609 2,407 30 35 176 3,105 3,105 3,046 4 2 609 2,427	SF EA EA SF SF EA SF EA SF EA SF EA SF	6 6 5 7 6 5 4 6 6 6 6 6 7 7	10+ years	Damaged
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet	1st Floor 2nd Floor	3,046 6 1 3 609 2,407 30 35 176 3,105 3,105 3,046 4 2 609 2,427 10	SF EA SF EA SF EA SF SF EA SF SF EA SF SF EA SF EA SF EA SF EA SF EA SF SF	6 6 5 7 6 5 4 6 6 6 6 6 7 7 6 5 4	10+ years	
corridor	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 2nd Floor	3,046 6 1 3 609 2,407 30 35 176 3,105 3,105 3,046 4 2 609 2,427 10 35	SFA EA SF SFA EA S	6 6 5 7 6 5 4 6 6 6 6 6 7 7 6 5 4 7	10+ years	Damaged
•	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet	1st Floor 2nd Floor	3,046 6 1 3 609 2,407 30 35 176 3,105 3,105 3,046 4 2 609 2,427 10	SF EA SF EA SF EA SF SF EA SF SF EA SF SF EA SF EA SF EA SF EA SF EA SF SF	6 6 5 7 6 5 4 6 6 6 6 6 7 7 6 5 4	10+ years	Damaged

Page: 19 of 48 Campus Name: Jamieson Assessment Date: 12/20/2023



Catego	Category : Interior			uilding	: Main		The second of th
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Walls - Structural Glazed Tile	2nd Floor	3,105	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,275	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	4	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	455	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,810	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	10	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	3rd Floor	30	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	89	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,548	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	2,548	SF	6	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
O							
_Stairs	Ceiling - Plaster/Drywall	North	456	SF	6	10+ years	
	Floor - Terrazzo	North	760	SF	6	10+ years	
	Handrails	North	128	LF	7	10+ years	
	Lighting - Pendent/Surface	North	8	EA	7	6-10 years	
	Stairs - Terrazzo	North	480	LF	6	10+ years	
	Walls - Plaster/Drywall	North	1,665	SF	6	10+ years	
	Walls - Structural Glazed Tile	North	1,665	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	464	SF	6	10+ years	
	Floor - Terrazzo	South	760	SF	6	10+ years	
	Handrails	South	128	LF	7	10+ years	
	Lighting - Pendent/Surface	South	8	EA	7	6-10 years	
	Stairs - Terrazzo	South	480	LF	6	10+ years	
	Walls - Plaster/Drywall	South	1,661	SF	6	10+ years	
	Walls - Plaster/Drywall	South	4	SF	5	1-2 years	Damaged
	Walls - Structural Glazed Tile	South	1,665	SF	6	10+ years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	
	Wheelchair Lift - Platform Lift	1st Floor	1	EA	7	10+ years	
						-	



Category : Exterior		В	uilding	: Additi			
_			<u> </u>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#13- W	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#13- W	20	LF	5	6-10 years	
	Exterior Stairs - Stone	#13- W	6	LF	6	10+ years	
oundati	on						
	Foundation - Concrete	Entire Building	372	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	13,300	SF	7	10+ years	No exposed superstructure
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EΑ	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Stone	Main Roof	372	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	58	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	70	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	302	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	6,648	SF	5	6-10 years	Repaired
	Roof Structure - Steel with Clay Tile Arch	Main Roof	6,648	SF	7	10+ years	Repaired
	,		2,010			, , , , , , , , , , , , , , , , , , , ,	
Walls							
	Exterior Walls - Brick	Entire Building	8,643	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	60	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	287	SF	6	10+ years	
Windows							
	Curtain wall - Louver	Entire Building	27	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	126	SF	6	10+ years	
	Lintels - Steel	Entire Building	287	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,132	SF	6	10+ years	
Catego	ry : Electrical		D	uildina	: Additi	on 1	
Caley0	ı y . Liectricai		D	unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	ncy System		•				
	Security System - Intrusion Detection	Entire Building	13,300	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	
	Č	3				,	



Catego	ry : Electrical	В	uilding	: Additi	on 1		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Main Se							
	PA System	Entire Building	13,300	SF	6	6-10 years	Served by Main.
Dower C	Distribution						
1 OWEI L	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	2-5 years	Some panels are secured shut for
	-		_				safety.
Catego	ry : Fire Protection		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alaı			•			•	
	Fire Alarm Strobe Lights	Entire Building	13,300	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	13,300	SF	6	6-10 years	
Catego	ory : Mechanical		В	uilding	: Additi	on 1	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	dling Systems						
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Roof	1	EA	7	10+ years	
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Roof	1	EA	7	10+ years	
Boiler S	vstems						
•	Piping - Steam Pipe- Steel	Boiler Room	200	LF	6	6-10 years	Piped in from Main.
	Steam Traps	Boiler Room	14	EA	6	6-10 years	•
Heating	Devices						
театту	Wall Heater - Electric	Entire Building	7	EA	6	6-10 years	Quantity and Rank changed to match current observations.
	Radiators - Steam	Entire Building	2	EA	5	6-10 years	Carrent observations.
Tempera	ature Control						
	DDC System	Entire Building	13,300	SF	5	6-10 years	
	Electric Thermostat	Entire Building	2	ĒΑ	6	6-10 years	116 214
	Thermostats - DDC	Entire Building	12	EA	6	6-10 years	
Unit Ver	ntilation						
	Unit Ventilators- Floor Mounted- Steam	Entire Building	12	EA	6	6-10 years	
		-				-	

Campus Name: Jamieson Page : 22 of 48 Assessment Date: 12/20/2023



Catego	Category : Mechanical			Building : Addition 1					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	Heating Coils Only								
_Ventilati	on								
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	6-10 years	Misidentified in previous assessment. Quantity changed to match current observations and per review with Building Engineer.		

Category: Plumbing Building: Addition 1

Group Piping	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Domestic Piping-Hot Water Return Lines	Entire Building	13,300	SF	6	6-10 years	Routed back to Main.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	13,300	SF	6	6-10 years	Domestic plumbing served by Main.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	13,300	SF	6	6-10 years	Domestic plumbing served by Main.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	13,300	SF	6	6-10 years	Domestic plumbing served by Main.
	Sanitary Piping	Entire Building	13,300	SF	6	6-10 years	
	Storm Piping	Entire Building	13,300	SF	6	6-10 years	
	Vent Piping	Entire Building	13,300	SF	6	6-10 years	

Building : Addition 1

Recommend Category: Room

						Recommena	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	AC Unit	211 Teachers Lounge	1	EA	7	6-10 years	
	Ceiling - Lay-in	211 Teachers Lounge	814	SF	7	10+ years	
	Doors - Wood Doors inclu hw	211 Teachers Lounge	1	EA	6	10+ years	
	Floor - Tile	211 Teachers Lounge	814	SF	6	10+ years	
	Lighting - Lay-in	211 Teachers Lounge	16	EA	7	6-10 years	
	Power Distribution	211 Teachers Lounge	8	EΑ	7	10+ years	
	Walls - Plaster/Drywall	211 Teachers Lounge	964	SF	6	10+ years	
	Work Sink	211 Teachers Lounge	1	EA	7	10+ years	
_Mechan	ical/ Service Rooms						
	Crawl Space - Unfinished	Basement	12,500	SF	7	10+ years	

Campus Name: Jamieson Page : 23 of 48 Assessment Date: 12/20/2023



Catego	ry : Classroom		В	uilding	: Additi		5000 W WOZAR OTKEET, Officago, in 00000
_				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #111 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	19	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	814	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	814	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,022	SF	6	10+ years	
Classroo	om #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	19	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	814	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	814	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,022	SF	6	10+ years	
Classroo	om #113 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	19	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	814	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	814	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,022	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
_Classroo	om #114 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	19	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	814	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	814	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,022	SF	6	10+ years	
_Classroo	om #115 (Library)						
	AC Units	1st Floor	2	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Additi	on 1	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	82	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,055	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	1,055	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	10+ years	
	Storage/ Closet	1st Floor	85	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,208	SF	6	10+ years	
Classroo	om #116 (Regular Classroom)						
	Casework	1st Floor	19	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	793	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	47	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	999	SF	6	10+ years	
	vvalis - Flastel/Diywali	151 11001	999	SI	O	10+ years	
Classroc	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	19	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	814	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	814	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	44	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	906	SF	6	10+ years	
Classroc	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	814	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	814	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	44	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	964	SF	6	10+ years	
:lassror	om #214 (Special Education)						
21400100	Casework	2nd Floor	16	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	20	SF	7	•	Repaired
				SF SF		10+ years	Nepalleu
	Ceiling - Lay-in	2nd Floor	716		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Carpet	2nd Floor	736	SF	6	6-10 years	

Campus Name: Jamieson Page : 25 of 48 Assessment Date: 12/20/2023



Catego	ry : Classroom		В	uilding	: Additi	on 1	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,320	SF	6	10+ years	
assroc	om #215 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	65	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,069	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	1,069	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	6-10 years	
	Marker Board	2nd Floor	9	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,128	SF	6	10+ years	
assroo	om #216 (Regular Classroom)						
<u> </u>	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	6	10+ years	
		2nd Floor	793	SF	6	-	
	Ceiling - Lay-in Chalk Board	2nd Floor	20	LF	4	10+ years	
		2nd Floor		EA	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	SF		10+ years	
	Floor - Tile		793		6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	27	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	899	SF	6	10+ years	
atego	ry : Interior		В	uilding	: Additi		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor		Location	Quantity	OCIVI	Italik	Kepiacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	748	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	728	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Damaged ceiling
	Lighting - Pendent/Surface	1st Floor	10	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	75	EA	6	10+ years	
	Student Lockers - One Tier	1st Floor	1	EA	4	0-1 year	Severely damaged door
	Walls - Plaster/Drywall	1st Floor	417	SF	6	10+ years	, 3
	Walls - Structural Glazed Tile	1st Floor	833	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	708	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	5	1-2 years	Peeling paint
	Floor - Tile/Sheet	2nd Floor	758	SF	5	10+ years	3 F
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Stairs - Terrazzo	2nd Floor	60	LF	6	10+ years	
	Student Lockers - One Tier	2nd Floor	76	EA	6	10+ years	
	Student Lockers - One Tier	Ziiu Fiooi	70	LA	Ü	10+ years	



Catego	ry : Interior		Building : Addition 1						
		Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	2nd Floor	417	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	833	SF	6	10+ years			
Stairs									
	Ceiling - Plaster/Drywall	West	224	SF	6	10+ years			
	Floor - Terrazzo	West	90	SF	6	10+ years			
	Handrails	West	94	LF	7	10+ years			
	Lighting - Pendent/Surface	West	3	EA	7	6-10 years			
	Stairs - Terrazzo	West	360	LF	6	10+ years			
	Walls - Plaster/Drywall	West	1,020	SF	6	10+ years			
	Walls - Structural Glazed Tile	West	1,020	SF	6	10+ years			



Category : Exterior **Building: Addition 2**

			_		Recommend	
ıp Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ance		•			•	
Exterior Doors - Exterior FRP Door	#10 NW	2	EA	7	10+ years	
Exterior Stairs - Concrete	#10 NW	18	LF	7	10+ years	
Stair Handrail - Steel_Stair Handrail	#10 NW	10	LF	7	10+ years	
Exterior Doors - Exterior FRP Door	#11 N	3	EA	7	10+ years	
Exterior Doors - Transom Lite	#11 N	3	EA	7	10+ years	
Exterior Stairs - Concrete	#11 N	16	LF	7	10+ years	
Ramp Handrail - Steel_Ramp Handrail	#11 N	131	LF	7	10+ years	
Ramps - Concrete	#11 N	51	LF	7	10+ years	
Stair Handrail - Steel_Stair Handrail	#11 N	8	LF	7	10+ years	
Entrance Control - Audio and Video	#5 SE	1	EA	7	10+ years	
Exterior Doors - Exterior FRP Door	#5 SE	2	EA	7	10+ years	
Exterior Doors - Transom Lite	#5 SE	2	EA	7	10+ years	
Power Door Operator and Controls	#5 SE	2	EA	7	10+ years	
Exterior Doors - Exterior FRP Door	#6 S	3	EA	7	10+ years	
Exterior Doors - Transom Lite	#6 S	3	EΑ	7	10+ years	
Exterior Stairs - Concrete	#6 S	60	LF	7	10+ years	
Ramp Handrail - Steel_Ramp Handrail	#6 S	65	LF	7	10+ years	
Ramps - Concrete	#6 S	45	LF	7	10+ years	
Stair Handrail - Steel_Stair Handrail	#6 S	30	LF	7	10+ years	
Exterior Doors - Exterior FRP Door	#7 SW	2	EA	7	10+ years	
Entrance Control - Audio and Video	#8 W	1	EA	7	10+ years	
Exterior Doors - Exterior FRP Door	#8 W	2	EA	7	10+ years	
Exterior Doors - Transom Lite	#8 W	2	EA	7	10+ years	
Exterior Doors - Exterior FRP Door	#9 W	2	EA	7	10+ years	
Exterior Doors - Transom Lite	#9 W	2	EA	7	10+ years	
dation						
Foundation - Concrete	Entire Building	563	LF	7	10+ years	
Superstructure - Metal Deck/ Concrete	Entire Building	20,622	SF	7	10+ years	
Topping	gg	20,022	٥.	•	.c. youro	
ng Exterior Lighting - Wall Mounted	Entire Building	15	EA	7	10+ years	
Extends Lighting Wall Woulded	Entire Building	10	L/ \	•	ioi youis	
ystem						
Coping - Metal	Low SE	25	LF	7	10+ years	
Downspouts - Interior Downspouts	Low SE	14	LF	7	10+ years	
Parapet - Parapet < 16" Height	Low SE	25	LF	7	10+ years	
Roof - Modified Bitumen	Low SE	105	SF	7	10+ years	
Roof Structure - Steel / Metal Deck/	Low SE	105	SF	7	10+ years	
Concrete Topping						



Catego	ry : Exterior		В	uilding	: Additi	on 2	·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Metal	Low West	157	LF	7	10+ years	
	Downspouts - Interior Downspouts	Low West	44	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Low West	157	LF	7	10+ years	
	Roof - Modified Bitumen	Low West	1,905	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Low West	1,905	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Main Roof	20	LF	7	10+ years	
	Coping - Metal	Main Roof	404	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	540	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	404	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	13,852	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Main Roof	13,852	SF	7	10+ years	
	Concrete Topping						
Walls							
	Exterior Walls - Brick	Entire Building	17,514	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	168	SF	7	10+ years	
Windows							
	Lintels - Steel	Entire Building	369	LF	7	10+ years	
	Storefront Windows	Entire Building	480	SF	7	10+ years	
	Windows - Decorative	Entire Building	128	SF	7	10+ years	
	Windows - Louver	Entire Building	10	SF	7	10+ years	Not previously assessed
	Windows - Sash Aluminum Double-pane	Entire Building	2,000	SF	7	10+ years	Not previously assessed
	Windows Gasir/Mariniani Boable pane	Little Building	2,000	O.	•	101 years	
Catego	ry : Electrical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Entire Building	1	EA	7	10+ years	
	Automatic Transfer Switch	Entire Building	1	EA	7	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	10	EA	7	10+ years	
	Exit Signs - Lunchroom	Entire Building	3	EΑ	7	10+ years	
	Security System - CCTV	Entire Building	37,761	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	37,761	SF	7	6-10 years	
_Main Se	rvice						
_iviaiii 3E	PA System	Entire Building	37,761	SF	7	10 L VOORO	Served by Main.
	Independent Electrical Service for	Entire Building Entire Building	37,761	SF EA	7	10+ years	Served by Main.
	•	Entire building	Į	EA	1	10+ years	
	emergency power Independent Electrical Service for	Entire Building	1	EA	7	10+ years	
	independent Liecthoal Service (Of	Little building	ı	ĽA	,	10+ years	

Page : 29 of 48 Campus Name: Jamieson Assessment Date: 12/20/2023



Catego	ry : Electrical		В	uildina	: Addition	on 2	
				9	. ,	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	emergency power		•			•	
	Main Electrical Service - 800 A and	Entire Building	1	EA	7	10+ years	
	277/480/3PH	<u> </u>				•	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	8	EA	7	10+ years	Quantity changed to match current
							observations.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live
							conductors presenting a live front
	11111 18 8 1 11 100 1		_		_	4.0	condition.
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	7	10+ years	Location changed for clarification.
	amp						Quantity changed to match current
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10	observations.
	Transformers - 277/460 - 120/206	Entire Building	1	EA	,	10+ years	
Catego	ry : Fire Protection		В	uilding	: Additio	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Sub-panel; primary FACP is located
		3				,	in Main.
	Fire Alarm Strobe Lights	Entire Building	37,761	SF	7	10+ years	
	Fire Alarm_System	Entire Building	37,761	SF	7	10+ years	
	Fire Pump Controller	Entire Building	1	EA	7	10+ years	
_							
Pump Ro	oom Assembly	F # B ##				0.40	
	Fire Pump - Less than 25hp	Entire Building	1	EΑ	6	6-10 years	
	Jockey Pump	Entire Building	1	EA	7	10+ years	
Snrinklar	System						
-ринкі с і	Sprinkler Heads	Entire Building	37,761	SF	7	10+ years	
	Sprinkler Piping	Entire Building	37,761	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	37,761	SF	7	10+ years	
		· · · · · · · · · · · · · · · · · · ·	22,1.0.		-	,	
Catego	ry : Mechanical		В	uilding	: Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Chiller-Air Cooled-Scroll Type-Ground	Entire Building	1	EA	7	10+ years	Location changed for clarification.
	Manuata d. 404 450 taua						
	Mounted - 101 - 150 tons						
	Glycol Feed	Entire Building	1	EA	7	10+ years	Location changed for clarification.

Page : 30 of 48 Campus Name: Jamieson Assessment Date: 12/20/2023



Catego	ry : Mechanical		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type Pipes - Chilled Water Pipe- Steel Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons	Location Entire Building Entire Building Entire Building	Quantity 650 1 1	LF EA EA	Rank 7 7 7	Replacement 10+ years 10+ years 10+ years	Location changed for clarification. SSAC-1; roof -mounted component of a ductless split system serving the fan coil unit in IDF Room 222. Dataplate extremely faded.
							Dataplate extremely laded.
Air Hand	lling Systems						
	Fan Power Box - Fan Power Box with Hot Water Coil	1st Floor	15	EA	7	10+ years	Located above the suspended ceiling grid and inaccessible at the time of assessment.
	Fan Power Box - Fan Power Box with Hot Water Coil	2nd Floor	7	EA	7	10+ years	Located above the suspended ceiling grid and inaccessible at the time of assessment.
	Fan Power Box - Fan Power Box with Hot Water Coil	3rd Floor	7	EA	7	10+ years	Located above the suspended ceiling grid and inaccessible at the time of assessment.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and Chilled Water Coils - 21 - 30 tons	Roof	1	EA	7	10+ years	AHU-1 - Dual Temp, not gas
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and Chilled Water Coils - 21 - 30 tons	Roof	1	EA	7	10+ years	AHU-3. Misidentified as a single- zone unit in previous assessment Dual Temp, not gas
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and Chilled Water Coils - 21 - 30 tons	Roof	1	EA	7	10+ years	AHU-2 - Dual Temp, not gas
_Boiler Sv	vstems						
	Boiler Auxiliary- Condensing Hot Water - Less than 500 HP	Mechanical Room	2	EA	7	10+ years	
	Chemical Pot Feeder	Mechanical Room	1	EA	7	10+ years	
	Condensing- Hot Water Boiler - Less than 500 MBH	Mechanical Room	2	EA	7	10+ years	
	Dual Temperature Pump	Mechanical Room	1	EA	7	10+ years	CPS Asset Tag not directly accessible in a safe manner due to unreliable climbing means at the time of assessment. Location changed to
	Dual Temperature Pump	Mechanical Room	1	EA	7	10+ years	match current observations. CPS Asset Tag not directly accessible in a safe manner due to unreliable climbing means at the time of assessment. Location changed to match current observations.
	Dual Temperature Pump	Mechanical Room	1	EA	7	10+ years	CPS Asset Tag not directly

Page : 31 of 48 Campus Name: Jamieson Assessment Date: 12/20/2023



Catego	ry : Mechanical		В	uilding	: Addition	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							accessible in a safe manner due to unreliable climbing means at the tim of assessment. Location changed to match current observations.
	Glycol Feed System	Mechanical Room	1	EA	7	10+ years	
	Piping - Dual Temperature Pipes- Copper	Mechanical Room	500	LF	7	10+ years	
	Water Fill System	Mechanical Room	1	EA	7	10+ years	
leating I	Devices						
	Wall Heater - Electric	1st Floor	2	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	7	10+ years	
	Unit Heater - Electric	Entire Building	1	EA	7	10+ years	Quantity changed to match current observations and per review with Building Engineer.
	Unit Heater - Hot Water	Entire Building	1	EA	7	10+ years	
	Radiator Panels - Hot Water	Entire Building	14	EA	7	6-10 years	+4
√echani	cal Plumbing						
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	7	10+ years	
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	7	10+ years	
Гетрега	ture Control						
	DDC System	Entire Building	37,761	SF	7	10+ years	
	Electric Thermostat	Entire Building	4	EA	7	10+ years	Quantity changed to match current observations.
	Thermostats - DDC	Entire Building	18	EA	7	10+ years	
/entilatio	n						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	7	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	7	10+ years	
Catego	ry : Plumbing		В	uilding	: Additio	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	7	6-10 years	Priority Rep adjusted based on

Campus Name: Jamieson Page : 32 of 48 Assessment Date: 12/20/2023



Catego	Category : Plumbing		В	uilding	·		
	<u>-</u>					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							current observations and on the age of the equipment.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	37,761	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	37,761	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	37,761	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	37,761	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	37,761	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	37,761	SF	7	10+ years	
	Sanitary Piping	Entire Building	37,761	SF	7	10+ years	
	Storm Piping	Entire Building	37,761	SF	7	10+ years	
	Vent Piping	Entire Building	37,761	SF	7	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	7	10+ years	

Category: Room **Building: Addition 2**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Lay-in	124 OFFICE	343	SF	6	6-10 years	
	Doors - Steel Doors incl hw	124 OFFICE	1	EΑ	6	10+ years	
	Floor - Tile	124 OFFICE	343	SF	6	10+ years	
	Lighting - Lay-in	124 OFFICE	6	EA	6	6-10 years	
	Power Distribution	124 OFFICE	4	EA	7	10+ years	
	Walls - Plaster/Drywall	124 OFFICE	1,200	SF	6	10+ years	
	Ceiling - Lay-in	135 Kitchen office	120	SF	6	6-10 years	
	Doors - Steel Doors incl hw	135 Kitchen office	1	EA	6	10+ years	
	Floor - Tile Quarry	135 Kitchen office	120	SF	6	10+ years	
	Lighting - Lay-in	135 Kitchen office	2	EA	6	6-10 years	
	Power Distribution	135 Kitchen office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	135 Kitchen office	220	SF	6	10+ years	
Kitchen							
	Ceiling - Lay-in	131 Kitchen / Servery	1,000	SF	6	6-10 years	
	Doors - Steel Doors incl hw	131 Kitchen / Servery	5	EA	6	10+ years	
	Floor - Tile Quarry	131 Kitchen / Servery	1,000	SF	6	10+ years	
	Lighting - Lay-in	131 Kitchen / Servery	30	EA	6	6-10 years	

Campus Name: Jamieson Page : 33 of 48 Assessment Date: 12/20/2023



Category : Room		В	uildina	: Additi	5000 N WOZAR OTNEET, Officago, in 00000		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Serving Line	131 Kitchen / Servery	1	LF	6	6-10 years	
	Storage/ Closet	131 Kitchen / Servery	400	SF	5	6-10 years	
	Walls - Metal Panel	131 Kitchen / Servery	800	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	131 Kitchen / Servery	1,200	SF	6	10+ years	
Lunch &	Multipurpose Room						
CUIICII G	Ceiling - Lay-in	128 Lunchroom	4,669	SF	6	10+ years	
	Doors - Steel Doors incl hw	128 Lunchroom	4,009	EA	6	10+ years	
	Floor - Tile	128 Lunchroom		SF	6	-	
		128 Lunchroom	4,669	EA		10+ years	
	Lighting - Lay-in		64	SF	6	6-10 years	
	Storage/ Closet	128 Lunchroom	600		5	10+ years	
	Walls - Plaster/Drywall	128 Lunchroom	8,000	SF	6	10+ years	
_MDF_ID							
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	214	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Split unit
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	·
Mechani	ical/ Service Rooms						
	Janitor's Closet	1st floor mechanical room	55	SF	7	10+ years	
	Mechanical/ Service Rooms	1st floor mechanical room	300	SF	7	10+ years	
	Mechanical/ Service Rooms	1st floor mechanical room	1,500	SF	7	10+ years	
	Mechanical/ Service Rooms	1st floor mechanical room	74	SF	7	10+ years	
	Mechanical/ Service Rooms	1st floor mechanical room	430	SF	7	10+ years	
	Mechanical/ Service Rooms	1st floor mechanical room	68	SF	7	10+ years	
	Janitor's Closet	2nd Floor	56	SF	5	10+ years	
	Janitor's Closet	3rd Floor	40	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	40	SF	5	10+ years	
	Storage Room	3rd Floor	228	SF	5	10+ years	
Postros	-					•	
_Restroor	Accessories	1st Floor	260	SF	7	6-10 years	
		1st Floor	260	SF SF	7	•	
	Ceiling - Plaster/Drywall Floor - Tile Ceramic/ Porcelain	1st Floor 1st Floor	260	SF SF	7	10+ years 10+ years	
						,	
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Hand Dryer	1st Floor	3	EΑ	7	6-10 years	
	Lavatory	1st Floor	3	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor	4	EΑ	7	10+ years	
	Partitions	1st Floor	2	EΑ	7	10+ years	
	Urinals	1st Floor	3	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	160	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	400	SF	7	10+ years	

Campus Name: Jamieson Page : 34 of 48 Assessment Date: 12/20/2023



Category : Room			Building : Addition 2				
2 2.10 90	,	Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor	260	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	260	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	260	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	3	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	10+ years	
	Partitions	1st Floor	5	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	160	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	400	SF	7	10+ years	
	Water Closet	1st Floor	5	EA	7	10+ years	
	Accessories	1st Floor Staff service corridor	77	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Staff service corridor	77	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor Staff service corridor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Staff service corridor	77	SF	7	10+ years	
	Floor Drain	1st Floor Staff service corridor	1	EA	7	10+ years	
	Hand Dryer	1st Floor Staff service corridor	1	EA	7	6-10 years	
	Lavatory	1st Floor Staff service corridor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Staff service corridor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Staff service corridor	70	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Staff service corridor	170	SF	7	10+ years	
	Water Closet	1st Floor Staff service corridor	1	EA	7	10+ years	
	Accessories	1st Floor Staff- in Service Corridor	77	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Staff- in Service Corridor	77	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor Staff- in Service Corridor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Staff- in Service Corridor	77	SF	7	10+ years	
	Floor Drain	1st Floor Staff- in Service Corridor	1	EA	7	10+ years	
	Hand Dryer	1st Floor Staff- in Service Corridor	1	EA	7	6-10 years	
	Lavatory	1st Floor Staff- in Service Corridor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Staff- in Service Corridor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Staff- in Service Corridor	70	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Staff- in Service Corridor	170	SF	7	10+ years	
	Water Closet	1st Floor Staff- in Service Corridor	1	EA	7	10+ years	
	Accessories	1st floor Staff in main corridor	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor Staff in main corridor	60	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st floor Staff in main corridor	1	EA	7	10+ years	
	Floor - Tile	1st floor Staff in main corridor	60	SF	7	10+ years	
	Floor Drain	1st floor Staff in main corridor	1	EA	7	10+ years	
	Hand Dryer	1st floor Staff in main corridor	1	EA	7	6-10 years	
	Lavatory	1st floor Staff in main corridor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st floor Staff in main corridor	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st floor Staff in main corridor	60	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor Staff in main corridor	180	SF	6	10+ years	

Campus Name: Jamieson Page : 35 of 48 Assessment Date: 12/20/2023



Comments
Comments



Catego	ry : Room	В						
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Water Closet	3rd Floor Staff	1	EA	7	10+ years		
	Accessories	3rd floor Boys	260	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd floor Boys	260	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd floor Boys	260	SF	7	10+ years		
	Floor Drain	3rd floor Boys	1	EA	7	10+ years		
	Hand Dryer	3rd floor Boys	3	EA	7	6-10 years		
	Lavatory	3rd floor Boys	3	EΑ	7	10+ years		
	Lighting - Lay-in	3rd floor Boys	4	EA	7	6-10 years		
	Partitions	3rd floor Boys	2	EA	7	10+ years		
	Urinals	3rd floor Boys	3	EA	7	10+ years		
	Walls - Plaster/Drywall	3rd floor Boys	120	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd floor Boys	560	SF	7	10+ years		
	Water Closet	3rd floor Boys	2	EA	7	10+ years		
	Accessories	3rd floor Girls	260	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd floor Girls	260	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd floor Girls	260	SF	7	10+ years		
	Floor Drain	3rd floor Girls	1	EA	7	10+ years		
	Hand Dryer	3rd floor Girls	3	EA	7	6-10 years		
	Lavatory	3rd floor Girls	3	EΑ	7	10+ years		
	Lighting - Lay-in	3rd floor Girls	4	EA	7	6-10 years		
	Partitions	3rd floor Girls	5	EA	7	10+ years		
	Walls - Plaster/Drywall	3rd floor Girls	120	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd floor Girls	560	SF	7	10+ years		
	Water Closet	3rd floor Girls	5	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd floor Girls	560	SF	7 7 7	10+ years 10+ years		

Category : Classroom **Building: Addition 2**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #223 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	715	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,600	SF	6	10+ years	
Classroc	m #224 (Science Classroom)						
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	994	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	994	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	91	SF	7	10+ years	
	-					•	

Campus Name: Jamieson Page : 37 of 48 Assessment Date: 12/20/2023



Catego	ry : Classroom		В	Building : Addition 2			
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
lassroc	om #225 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	727	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	727	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
lassroc	nm #226 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	728	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	728	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
lassroc	om #227 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	722	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	722	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
lassroc	om #228 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
lassroc	nm #229 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	726	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Carpet	2nd Floor	726	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	

Campus Name: Jamieson Page : 38 of 48 Assessment Date: 12/20/2023



Catego	ry : Classroom		Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	om #230 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	800	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	800	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	9	EΑ	7	6-10 years		
	Marker Board	2nd Floor	24	LF	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years		
	•					•		
Classroo	om #313 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	724	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	724	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	7	10+ years		
	•		,			,		
Classroo	om #315 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	724	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	724	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	7	10+ years		
Classroc	om #316 (Music Room)							
	Ceiling - Lay-in	3rd Floor	1,009	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years		
	Floor - Tile	3rd Floor	1,009	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Sound Panels	3rd Floor	22	EA	7	10+ years		
	Storage/ Closet	3rd Floor	130	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,270	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classes	om #317 (Regular Classroom)							
Ciassioo		3rd Floor	A	SF	7	10	Danairad	
	Ceiling - Lay-in		4		7	10+ years	Repaired	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	724	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	7	10+ years		



Catego	ry : Classroom		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
01							
Classroc	m #318 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	724	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	724	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	7	10+ years	
Classroo	m #319 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	728	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	728	SF	7	10+ years	
		3rd Floor	9	EA	7	•	
	Lighting - Lay-in		16			6-10 years	
	Marker Board	3rd Floor		LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	7	10+ years	
Classroo	m #320 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	724	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	724	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	9	ĒA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	7	10+ years	
Classroo	m #322 (Regular Classroom)						
JIASSIUC	Ceiling - Lay-in	3rd Floor	800	SF	7	10 L VOORO	
	Doors - Wood Doors inclu hw					10+ years	
		3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	800	SF	7	10+ years	
	Lighting Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Additi	on 2	
Group	Itom Tuno	Location	Quantity	UOM	Rank	Recommend	Comments
Corridor	Item - Type	Location	Quantity	OOW	Kalik	Replacement	Comments
JUHUUL	Ceiling - Lay-in	1st floor Corridor	1,052	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st floor Corridor	6	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st floor Corridor	3	EA	7	10+ years	
	Floor - Tile/Sheet	1st floor Corridor	1,052	SF	7	10+ years	
	Lighting - Lay-in	1st floor Corridor	17	EA	7	6-10 years	
	Stairs - Terrazzo	1st floor Corridor	60	LF	7	10+ years	



Catego	ategory : Interior			uilding	: Additi	on 2	•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st floor Corridor	2,000	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor Corridor	2,000	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor Corridor	1	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor Corridor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor Corridor	2,000	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor Corridor	17	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor Corridor	200	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Corridor	2,000	SF	7	10+ years	
	Ceiling - Lay-in	3rd floor Corridor	2,000	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd floor Corridor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd floor Corridor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd floor Corridor	2,000	SF	7	10+ years	
	Lighting - Lay-in	3rd floor Corridor	20	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd floor Corridor	200	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd floor Corridor	2,000	SF	6	10+ years	
	Ceiling - Lay-in	Service Corridor 1st Floor	298	SF	7	10+ years	
	Doors - Steel Doors incl hw	Service Corridor 1st Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	Service Corridor 1st Floor	298	SF	7	10+ years	
	Lighting - Lay-in	Service Corridor 1st Floor	8	EA	7	10+ years	
	Student Lockers - One Tier	Service Corridor 1st Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	Service Corridor 1st Floor	936	SF	7	10+ years	
Safety							
	Security Cameras	Entire Building	13	EA	7	6-10 years	
Stairs							
Otalis	Ceiling - Lay-in	North	630	SF	7	10+ years	
	Floor - Terrazzo	North	630	SF	6	10+ years	
	Handrails	North	140	LF	7	10+ years	
	Lighting - Lay-in	North	12	ĒΑ	7	6-10 years	
	Stairs - Terrazzo	North	520	LF	6	10+ years	
	Walls - Concrete Block	North	1,285	SF	7	10+ years	
	Ceiling - Lay-in	South	630	SF	7	10+ years	
	Floor - Terrazzo	South	630	SF	6	10+ years	
	Handrails	South	140	LF	7	10+ years	
	Lighting - Lay-in	South	12	ĒΑ	7	6-10 years	
	Stairs - Terrazzo	South	520	LF	6	10+ years	
	Walls - Concrete Block	South	1,285	SF	7	10+ years	
Vertical (Conveyance						
<u>v Gilleal l</u>	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	101.1/0070	
	Elevator - Hydraulic Elevator	191 [100]	1	EA	,	10+ years	



Jatego	ry : Exterior		В	ullaing	: Additio	on-Elevator To	wer
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonts
•	7 1	Location	Quantity	UOIVI	Naiik	Replacement	Comments
Foundat	Foundation - Concrete	Entire Building	140	LF	7	10	No exposed foundation
	Superstructure - Steel	Entire Building	2,780	SF	7 7	10+ years 10+ years	No exposed superstructure
	Superstructure - Steel	Entire building	2,700	SF	,	10+ years	No exposed superstructure
Roof Sy	stem						
	Coping - Stone	Low S Roof	10	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low S Roof	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low S Roof	10	LF	6	10+ years	
	Roof - Modified Bitumen	Low S Roof	100	SF	5	6-10 years	
	Roof Structure - Steel / Metal Deck/	Low S Roof	100	SF	7	10+ years	
	Concrete Topping	2011 6 11001		O.	•	ioi youro	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Stone	Main Roof	140	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	82	LF LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	62 140	LF LF	6		
						10+ years	
	Roof - Modified Bitumen	Main Roof	865	SF SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	865	SF	7	10+ years	
Nalls							
vvans	Exterior Walls - Brick	Entire Building	4,436	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	164	SF	6	10+ years	
		Ü				,	
Vindow							
	Guard - Guards perforated	Entire Building	5	SF	6	10+ years	
	Lintels - Steel	Entire Building	30	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	238	SF	6	10+ years	
Catego	ry : Electrical		В	uildina	: Additio	on-Elevator To	wer
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ncy System		,				
90	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Security System - CCTV	Entire Building	2,780	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	2,780	SF	6	6-10 years	
	Security System - Intrusion Detection	Little building	2,700	SI-	U	0-10 years	
Catego	ry : Fire Protection		Building : Addition-Elevator Tower				
Groven	Itam Tuna	Location	Ouantitu	UOM	Rank	Recommend Replacement	Commonto
Group	Item - Type	Location	Quantity	UUIVI	Rdilk	Replacement	Comments
Fire Alaı	m Fire Alarm Strobe Lights	Entire Building	2,760	SF	6	6-10 years	
	FIIE AIAIIII SUUDE LIUIUS	Entire building	2,760	ЭF	Ö	o- io years	

Campus Name: Jamieson Page : 42 of 48 Assessment Date: 12/20/2023



Minnie Mars Jamieson Elementary School

ver ver
ver
ver
0
Comments
ver
Commonto
Comments
Located in the bottom of the elevator pit. Inaccessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer.
ver
0
Comments
Comments
Comments
ver
ver
•



Catego	ry : Interior		Building : Addition-Elevator Tower					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	3rd Floor	577	SF	6	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	3	EA	6	10+ years		
	Floor - Tile/Sheet	3rd Floor	577	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	7	EΑ	7	6-10 years		
	Walls - Concrete Block	3rd Floor	1,114	SF	6	10+ years		
Stairs								
	Ceiling - Lay-in	South West	221	SF	6	10+ years		
	Floor - Terrazzo	South West	390	SF	6	10+ years		
	Handrails	South West	128	LF	7	10+ years		
	Lighting - Wall Mounted	South West	4	EA	7	6-10 years		
	Stairs - Terrazzo	South West	480	LF	6	10+ years		
	Walls - Concrete Block	South West	2,797	SF	6	10+ years		
Vertical (Conveyance							
•	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years		

Campus Name: Jamieson Page : 44 of 48 Assessment Date: 12/20/2023



Category : Site **Building: Site**

	ry . Site		ь				
	W	1	0			Recommend	•
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic							
	Surface - Synthetic	South	16,850	SF	7	10+ years	
	Surface - Asphalt	South	4,296	SF	7	10+ years	
Civil/Drai		o					
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	6	10+ years	
encina							
- 5	Fencing - Chain Link	Entire Site	25	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	1,834	LF	6	10+ years	
andscar	pe						
	Benches	Entire Site	4	EA	7	10+ years	
	Benches	Entire Site	12	EA	5	2-5 years	
	Landscape - Grass	Entire Site	37,008	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	333	SF	5	2-5 years	
	Parkway trees	Entire Site	46	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	1,200	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	9,607	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	270	SF	6	10+ years	
		Entire Site	4	EA	6		
	Trash Receptacles	Entire Site	4	EA	О	10+ years	
Parking L	ot						
	Surface - Asphalt	SE Lot	7,640	SF	6	10+ years	
	Surface - Asphalt	W Lot	8,641	SF	4	1-2 years	Cracking throughout
	Surface - Concrete	W Lot	1,126	SF	4	1-2 years	Cracking, crumbling throughout
	Trash Enclosure - Chain Links	W Lot	408	SF	6	10+ years	3, 11 3 3 113
Playgrou	nd						
, 9100	Equipment - Combo 3-12	SW Playground	1	EA	7	6-10 years	
	Equipment - School Age 5-12	SW Playground	1	EΑ	7	6-10 years	
	Surface - Poured Surface	SW Playground	3,770	SF	6	6-10 years	
	Ouriace - i Oureu Ouriace	Ovv i laygioullu	3,770	J ⁻	U	0-10 years	
Sidewalk							
	Sidewalks - Internal Walks	Entire Site	740	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	114	LF	5	1-2 years	Cracked, doesn't drain
			17,450	SF		10+ years	



Minnie Mars Jamieson Elementary School

5650 N Mozart STREET, Chicago, IL 60659

Catego	ry : Site		В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	375	SF	4	0-1 year	Cracked, crumbling
_Signage							
	Flag Pole - Flag Pole	East and Southeast	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/	East and Southeast	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Jamieson Page : 46 of 48 Assessment Date: 12/20/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				I					
			D	Floor Plan	A	Glazed	Operable	VACIONAL AND	0
0	1.4 1.111	B	Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Ant Document	01.51	040	040	000	400	40	l N	T NI
Art Room	Art Room	2nd Floor	210	210	830	122	40	N	N
Computer Lab	Regular Classroom	3rd Floor	305	305	738	114	30	Y	N
Kindergarten	Kindergarten	1st Floor	104	104	1,045	156	40	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	732	122	40	Y	N
Regular Classroom	Regular Classroom	1st Floor	102	102	732	122	40	Υ	N
Regular Classroom	Regular Classroom	1st Floor	103	103	732	122	40	Υ	N
Regular Classroom	Regular Classroom	1st Floor	105	105	732	122	40	Υ	N
Regular Classroom	Regular Classroom	1st Floor	110	110	732	122	40	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	732	122	40	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	732	122	40	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	732	122	40	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	732	122	40	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	732	122	40	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	732	122	40	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	732	122	40	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	732	122	40	Y	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	732	122	40	Y	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	732	122	40	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	732	122	40	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	730	122	40	Y	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	730	122	40	Y	N
Science	Library	3rd Floor	303	303	738	122	40	Y	N
	· · · · · ·	·						•	•
Building : Addition 1									
Kindergarten	Regular Classroom	1st Floor	113	113	814	200	80	N	N
Kindergarten	Regular Classroom	1st Floor	114	114	814	200	80	N	N
Library	Kindergarten	1st Floor	115	115	1,055	300	120	N	N
Office	Regular Classroom	1st Floor	111	111	814	200	80	N	N
Regular Classroom	Laboratory/Shop	2nd Floor	215	215	1,069	300	120	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	814	200	80	N	N
Regular Classroom	Regular Classroom	1st Floor	116	116	793	200	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	814	200	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	814	200	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	793	200	80	N	N
Special Education	Regular Classroom	2nd Floor	214	214	736	200	80	N	N
oposiai Eddodiioii	. togaiai oladdiddii	2110 1 1001						.,,	· · · · ·
Building : Addition 2									
Music Room	Music Room	3rd Floor	316	316	1,009	80	20	N	N
MIGGIO I COOTTI	WIGGIO I COOTTI	010 1 1001	1 310	1 010	1,000		40	I N	



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	223	223	715	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	225	225	727	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	728	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	227	227	722	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	725	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	229	229	726	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	230	230	800	80	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	724	80	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	315	315	724	80	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	317	317	724	80	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	724	80	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	319	319	728	80	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	320	320	724	80	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	322	322	800	80	40	N	N
Science Classroom	Science Classroom	2nd Floor	224	224	994	80	40	N	N