

5335 S Kenwood AVENUE, Chicago, IL 60615

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1954	2	29,338
Addition 1	2002	2	16,760
Addition 2	2002	2	27,886
Campus Total			73,984

Category : Exterior Building : Main

0	Name Trans	Lagation	0	шом	David	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance	9						
	Exterior Doors - Exterior Steel Door	"RAD" (Roof Access Door) - South end of "Main" South low roof access door	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	"RAD" - (Roof Access Door): North end of "Main" at Link Roof	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#2 Exit W	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#2 Exit W	33	LF	6	6-10 years	
	Exterior Stairs - Stone	#2 Exit W	12	LF	4	1-2 years	Broken, sped and cracked stone
	Exterior Doors - Exterior FRP Door	#3 W	3	EA	6	10+ years	·
	Exterior Doors - Side lite	#3 W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 W	96	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 W	40	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8.1 E	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#8.1 E	6	LF	6	10+ years	
	Entrance Control - Audio and Video	1W Main	1	EA	6	10+ years	
	Exterior Doors - Store Front	1W Main	4	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	1W Main	3	EΑ	6	10+ years	
	Power Door Operator and Controls	1W Main	1	EA	7	6-10 years	
Foundat	ion						
	Foundation - Concrete	Entire Building	416	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	29,338	SF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lighting							
Lighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	7	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	6-10 years	
Roof Sys	stem						
,	Access Ladder - Metal	Main Roof	7	EA	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Stainless Steel	Main Roof	28	LF	7	10+ years	
	Liner Chimney - Brick Chimney- Stainless Steel	Main Roof	12	LF	7	10+ years	
	Liner Coping - Metal	Main Roof	422	LF	7	10+ years	
	Coping - Stone	Main Roof	234	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	180	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	234	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	14,091	SF	6	2-5 years	
	Roof - Modified Bitumen	Main Roof	30	SF	4	1-2 years	Blistering
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	Verified new, larger hatch
	Roof Hatch - Metal	Main Roof	1	EA	3	0-1 year	Unused, heavy wood hatch
	Roof Structure - Concrete	Main Roof	14,121	SF	7	10+ years	Chacca, heary meet haten
	Coping - Stone	South Roof	119	LF	7	10+ years	
	Downspouts - Interior Downspouts	South Roof	76	LF	7	10+ years	
	Parapet - 16" - 30" Height	South Roof	119	LF	7	10+ years	
	Roof - Modified Bitumen	South Roof	2,599	SF	6	6-10 years	
	Roof Structure - Concrete	South Roof	2,599	SF	7	10+ years	
Walls							
_vvalis	Canopy - Concrete/ Stucco	Entire Building	400	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	10,034	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	5	1-2 years	Deteriorated sealant at control joint
	Exterior Walls - Stone-Cast	Entire Building	1,330	SF	7	10+ years	Tuck pointed
Windows	S						
	Curtain wall - Insulated Panel	Entire Building	750	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	1,520	SF	7	10+ years	
	Lintels - Steel	Entire Building	762	LF	7	10+ years	
	Windows - Decorative	Entire Building	45	SF	7	10+ years	
	Windows - Louver	Entire Building	72	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	252	SF	7	10+ years	
	Windows - Sash Lexan	Entire Building	2,940	SF	7	10+ years	

Campus Name: Murray Page : 2 of 38 Assessment Date: 02/05/2024



Catego	ry : Electrical		В	uilding	: Main		
0	Ham Time	Laastian	O	11014	Devil	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	2	0-1 year	Non-functional, batteries need to be replaced.
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	10+ years	Newly replaced. Not included in previous assessment.
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	2	0-1 year	Vintage units, non-functional, batteries need to be replaced.
	Security System - CCTV	Entire Building	29,338	SF	6	6-10 years	,
	Security System - Intrusion Detection	Entire Building	29,338	SF	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	1	SF	6	6-10 years	
	Stairs	9	•			5 . 5 <b>,</b> 5 5 5	
	Emergency A/C Power - Lunchrooms	Entire Building	18	SF	7	10+ years	
Main Se							
	PA System	Entire Building	29,338	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	UV-1 in janitors closet
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Unlabeled, 100 amp panel in boiler room office
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Unlabeled panel inside of teachers lounge
	Lighting and Power Panels - 100 A	Entire Building	3	EA	4	0-1 year	EM panel in boiler room Unlabeled load center panel outside of teachers lounge is live front UV-2 in second-floor storage closet
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	1T3 in MDF
	Lighting and Power Panels - Above 100 A  Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	PP-1B PP-1 UH-1
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	LP-1B
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	10+ years	Unlabeled panel near engineer's office
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	AC
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	PDP2
Catego	ry : Fire Protection		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator Fire Alarm Panel	Boiler Room Boiler Room	1	EA EA	7 6	10+ years 6-10 years	Serves main building, as well as

Campus Name: Murray Page : 3 of 38 Assessment Date: 02/05/2024



Catego	ry : Fire Protection		В	uilding	: Main		
_	W	1	0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alexan Ctrobe Limbte	Dailer Daam	20.220	C.E.	0	0.40	addition 1 and addition 2
	Fire Alarm Strobe Lights	Boiler Room	29,338	SF	6	6-10 years	Dust detector trouble ball silenced
	Fire Alarm_System	Boiler Room	29,338	SF	6	0-1 year	Duct detector trouble bell silenced
atego	ry : Mechanical		В	uilding	: Main		
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Cond	litioning						
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	6-10 years	Serves Liebert split AHU unit in MD room
	Chemical Pot Feeder	Roof	1	EA	6	6-10 years	Pot feeder in mechanical room of Southeast addition 2
	Chiller-Air Cooled-Scroll Type-Roof Mounted - 50 - 100 tons	Roof	1	EA	6	6-10 years	Coils recently cleaned in-house 202 after cooling season Serves main building and addition one, 75 tons More than 25 years old
	Glycol Feed	Roof	1	EA	6	6-10 years	Glycol manually added in southeas addition 2, no auto feed system
	Pipes - Chilled Water Pipe- Galvanized	Roof	500	LF	6	6-10 years	
ir Hand	lling Systems						
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 11 - 20 tons	Main Roof	1	EA	6	6-10 years	Serves lunchroom in main building tons
Boiler Sy	vstems						
,	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Feed System	Boiler Room	1	EA	7	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	7	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room		EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EΑ	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	6-10 years	B-2
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	6-10 years	B-1
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	6	6-10 years	
	Steam Traps	Boiler Room	44	EA	7	6-10 years	Steam trap survey recently comple two failed, two replaced

Campus Name: Murray Page : 4 of 38 Assessment Date: 02/05/2024



Catego	ry : Mechanical	·	В	uilding	: Main	·	·
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Radiators - Steam	Entire Building	10	EΑ	5	6-10 years	In cabinet
	Wall Heater - Electric	Entire Building	4	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	4	1-2 years	Deteriorating, non-functional Students and staff bathrooms
	Cabinet Heaters - With Steam Coil	Entire Building	1	EA	5	1-2 years	Noisy and needs to be adjusted
	Cabinet Heaters - With Steam Coil	Entire Building	8	EA	5	6-10 years	
	Fin Tube - Steam	Multipurpose Room	40	LF	5	6-10 years	
Tempera	ature Control						
·	DDC System	Entire Building	29,338	SF	6	6-10 years	Old Metasys system has been replaced with new DDC BAS in 2023. Installation and set up is not yet 100% complete.
	Thermostats - DDC	Entire Building	1	EA	6	6-10 years	
Unit Ven	ntilation						
	Unit Ventilators- Floor Mounted- Steam Heating & Chilled Water Coils	Entire Building	19	EA	5	6-10 years	
Ventilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	6-10 years	Classroom exhaust
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	6	6-10 years	Bathrooms and lunchroom exhaust

Category · Plumbing

**Building** · Main

ry : Plumbing		ь	unumg	. IVIAIII		
Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
er						
Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	6	6-10 years	
Domestic Piping-Hot Water Return Lines	Entire Building	29,328	SF	6	10+ years	
Domestic Piping-Hot Water Return Risers	Entire Building	29,328	SF	6	10+ years	
Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	29,328	SF	6	10+ years	
Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	29,328	SF	6	10+ years	1954 installation, good water, pressure and no pipe leaks throughout system
Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	29,328	SF	6	10+ years	
	Item - Type  er  Gas Heater - 150000 - 300000 BTU/HR Hot Water Storage Tank_Gas - Less than 200 Gallons  Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)  Domestic Piping-Hot/Cold Water Supply	Item - Type  Gas Heater - 150000 - 300000 BTU/HR Hot Water Storage Tank_Gas - Less than 200 Gallons  Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)  Domestic Piping-Hot/Cold Water Supply Entire Building  Entire Building Entire Building Entire Building	Item - Type  Gas Heater - 150000 - 300000 BTU/HR Hot Water Storage Tank_Gas - Less than 200 Gallons  Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)  Domestic Piping-Hot/Cold Water Supply Entire Building 29,328  Entire Building 29,328  Entire Building 29,328  Entire Building 29,328	Location   Quantity   UOM	Item - TypeLocationQuantityUOMRankerGas Heater - 150000 - 300000 BTU/HR Hot Water Storage Tank_Gas - Less than 200 GallonsBoiler Room1EA6Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Risers to Fixtures 	Item - TypeLocationQuantityUOMRankRecommend ReplacementGas Heater - 150000 - 300000 BTU/HR Hot Water Storage Tank_Gas - Less than 200 GallonsBoiler Room1EA66-10 yearsDomestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Risers Entire Building 29,328 SF 610+ yearsDomestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)Entire Building 29,328 SF 610+ yearsDomestic Piping-Hot/Cold Water Supply (Horizontal Lines)Entire Building 29,328 SF 610+ years

Campus Name: Murray Page : 5 of 38 Assessment Date: 02/05/2024



Catego	ry : Plumbing		В	uilding	: Main			-	
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	29,328	SF	6	10+ years			
	(from Risers to Fixtures)								
	Sanitary Piping	Entire Building	29,328	SF	6	10+ years			
	Storm Piping	Entire Building	29,328	SF	6	10+ years			
	Vent Piping	Entire Building	29,328	SF	6	10+ years			
Pumps									
	Pumps - Sump-Simplex	Boiler Room	1	EA	6	6-10 years			

Catego	ry : Room	Building : Main						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Administ	rative Suites/Offices							
	Ceiling - Lay-in	1st Flr Faculty Lounge	292	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Flr Faculty Lounge	1	EA	7	10+ years		
	Floor - Tile	1st Flr Faculty Lounge	292	SF	7	10+ years		
	Lighting - Lay-in	1st Flr Faculty Lounge	4	EA	7	10+ years		
	Power Distribution	1st Flr Faculty Lounge	4	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Flr Faculty Lounge	577	SF	7	10+ years		
	Work SInk	1st Flr Faculty Lounge	2	EA	7	10+ years		
	Ceiling - Plaster/Drywall	1st Flr Main Office	400	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Flr Main Office	1	EA	7	10+ years		
	Floor - Carpet	1st Flr Main Office	210	SF	7	6-10 years		
	Floor - Tile	1st Flr Main Office	190	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Flr Main Office	7	EA	7	10+ years		
	Power Distribution	1st Flr Main Office	6	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Flr Main Office	1,000	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Engineer's Office Partial Basement	80	SF	7	10+ years		
	Doors - Side-lite	Engineer's Office Partial Basement	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Engineer's Office Partial Basement	1	EA	4	1-2 years	Water damage	
	Floor - Tile	Engineer's Office Partial Basement	80	SF	7	6-10 years		
	Lighting - Pendent/Surface	Engineer's Office Partial Basement	2	EA	5	0-1 year	Does not work.	
	Power Distribution	Engineer's Office Partial Basement	6	EA	7	10+ years		
	Walls - Concrete Block	Engineer's Office Partial Basement	194	SF	7	10+ years		
	Ceiling - Lay-in	Principal's Office	380	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Principal's Office	2	EA	7	10+ years		
	Floor - Carpet	Principal's Office	380	SF	7	6-10 years		
	Lighting - Lay-in	Principal's Office	6	EA	7	10+ years		
	Power Distribution	Principal's Office	6	EA	7	10+ years		
	Storage/ Closet	Principal's Office	6	SF	7	10+ years		
	Walls - Plaster/Drywall	Principal's Office	720	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Room 200, Book / Resource Room	322	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Room 200, Book / Resource Room	1	EA	5	1-2 years	Door hardware missing, damaged door	

Campus Name: Murray Page : 6 of 38 Assessment Date: 02/05/2024



Catego	ry : Room		В	uilding	: Main	300			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Carpet	Room 200, Book / Resource Room	322	SF	6	2-5 years			
	Lighting - Pendent/Surface	Room 200, Book / Resource Room	4	EA	6	10+ years			
	Walls - Plaster/Drywall	Room 200, Book / Resource Room	593	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Room 210A	191	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Room 210A	1	EA	7	10+ years			
	Floor - Tile	Room 210A	191	SF	7	10+ years			
	Lighting - Lay-in	Room 210A	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	Room 210A	240	SF	7	10+ years			
	Work SInk	Room 210A	1	EA	7	10+ years			
	Ceiling - Plaster/Drywall	Room 210B Conference room	191	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Room 210B Conference room	1	EA	7	10+ years			
	Floor - Tile	Room 210B Conference room	191	SF	7	10+ years			
	Lighting - Lay-in	Room 210B Conference room	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	Room 210B Conference room	240	SF	7	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Splined	1st Floor Multipurpose Room	2,401	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor Multipurpose Room	4	ĒΑ	7	10+ years			
	Floor - Wood	1st Floor Multipurpose Room	2,401	SF	7	10+ years			
	Lighting - Lay-in	1st Floor Multipurpose Room	12	EA	7	10+ years			
	Storage/ Closet	1st Floor Multipurpose Room	120	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor Multipurpose Room	3,200	SF	7	10+ years			
_MDF_ID	F								
	Doors - Steel Doors incl hw	Room 209	1	EA	7	10+ years			
	Finishes	Room 209	322	SF	5	10+ years	Relamp 2 light fixtures		
	Other Cooling Unit	Room 209	1	EA	7	6-10 years	Fan Coil Unit		
Maahani	cal/ Service Rooms								
_иеспаш	Janitor's Closet	1st Floor	25	SF	5	10+ years			
	Storage Room	1st Floor	68	SF	5 5	10+ years			
	Boiler Room		898	SF	7	10+ years			
		Partial Basement Partial Basement	79	SF SF	7				
	Storage Room	Partial basement	79	SF	,	10+ years			
_Restrooi									
	Accessories	Boys next to 103	282	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Boys next to 103	250	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Boys next to 103	32	SF	5	1-2 years	Water damage		
	Doors - Side-lite	Boys next to 103	18	SF	7	10+ years			
	Doors - Steel Doors incl hw	Boys next to 103	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Boys next to 103	282	SF	7	10+ years			
	Floor Drain	Boys next to 103	1	EA	7	10+ years			
	Lavatory	Boys next to 103	2	EA	7	10+ years			

Campus Name: Murray Page: 7 of 38 Assessment Date: 02/05/2024



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Boys next to 103	4	EA	7	10+ years	
	Partitions	Boys next to 103	2	EA	7	10+ years	
	Urinals	Boys next to 103	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Boys next to 103	325	SF	7	10+ years	
	Walls - Structural Glazed Tile	Boys next to 103	325	SF	7	10+ years	
	Water Closet	Boys next to 103	2	EA	7	10+ years	
	Accessories	Boys next to 203	282	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys next to 203	282	SF	7	10+ years	
	Doors - Side-lite	Boys next to 203	18	SF	7	10+ years	
	Doors - Steel Doors incl hw	Boys next to 203	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys next to 203	282	SF	7	10+ years	
	Floor Drain	Boys next to 203	1	EA	7	10+ years	
	Lavatory	Boys next to 203	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys next to 203	4	EA	7	6-10 years	
	Partitions	Boys next to 203	2	EA	7	10+ years	
	Urinals	Boys next to 203	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Boys next to 203	325	SF	7	10+ years	
	Walls - Structural Glazed Tile	Boys next to 203	325	SF	7	10+ years	
	Water Closet	Boys next to 203	2	ĒA	7	10+ years	
	Accessories	Girls next to 107	298	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls next to 107	286	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Girls next to 107	12	SF	5	1-2 years	Water damage
	Doors - Side-lite	Girls next to 107	18	SF	7	10+ years	
	Doors - Steel Doors incl hw	Girls next to 107	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls next to 107	298	SF	7	10+ years	
	Floor Drain	Girls next to 107	1	ĒΑ	7	10+ years	
	Lavatory	Girls next to 107	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls next to 107	5	EA	7	10+ years	
	Partitions	Girls next to 107	5	EA	7	10+ years	
	Walls - Plaster/Drywall	Girls next to 107	325	SF	7	10+ years	
	Walls - Structural Glazed Tile	Girls next to 107	326	SF	7	10+ years	
	Water Closet	Girls next to 107	4	ĒΑ	7	10+ years	
	Water Closet	Girls next to 107	1	EA	6	1-2 years	Out of order
	Accessories	Girtls next to 207	298	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girtls next to 207	298	SF	6	10+ years	
	Doors - Side-lite	Girtls next to 207	18	SF	7	10+ years	
	Doors - Steel Doors incl hw	Girtls next to 207	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girtls next to 207	298	SF	7	10+ years	
	Floor Drain	Girtls next to 207	1	EA	7	10+ years	
	Lavatory	Girtls next to 207	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Girtls next to 207	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	Girtls next to 207	1	EA	5	1-2 years	Missing cover
	Partitions	Girtls next to 207	7	EA	7	10+ years	1111001119 00101
	Walls - Plaster/Drywall	Girtls next to 207	325	SF	7	10+ years	
		5	320	٥.	•	,	



Catego	ry : Room		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	Girtls next to 207	326	SF	7	10+ years	
	Water Closet	Girtls next to 207	7	EA	7	10+ years	
	Accessories	Toilet in Boiler area	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet in Boiler area	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Toilet in Boiler area	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet in Boiler area	42	SF	7	10+ years	
	Lavatory	Toilet in Boiler area	1	EA	5	1-2 years	Faucet dripping
	Lighting - Pendent/Surface	Toilet in Boiler area	1	EA	7	6-10 years	•
	Partitions	Toilet in Boiler area	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Toilet in Boiler area	93	SF	6	10+ years	
	Water Closet	Toilet in Boiler area	1	EA	7	10+ years	
	Accessories	Toilet in Kindergarten 104	21	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet in Kindergarten 104	21	SF	7	10+ years	
	Doors - Transom Window	Toilet in Kindergarten 104	1	SF	7	10+ years	
	Floor - Tile	Toilet in Kindergarten 104	21	SF	6	6-10 years	
	Lighting - Pendent/Surface	Toilet in Kindergarten 104	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Toilet in Kindergarten 104	72	SF	6	10+ years	
	Water Closet	Toilet in Kindergarten 104	1	EA	7	10+ years	
	Accessories	Toilet in Kindergarten 106	21	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Toilet in Kindergarten 106	21	SF	7	10+ years	
	Doors - Transom Window	Toilet in Kindergarten 106	1	SF	7	10+ years	
	Floor - Tile	Toilet in Kindergarten 106	21	SF	7	10+ years	
	Lavatory	Toilet in Kindergarten 106	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Toilet in Kindergarten 106	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Toilet in Kindergarten 106	52	SF	7	10+ years	
	Walls - Plaster/Drywall	Toilet in Kindergarten 106	21	SF	5	0-1 year	Damaged.
	Water Closet	Toilet in Kindergarten 106	1	EA	7	10+ years	3
	Accessories	Toilet in Kindergarten 108	21	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet in Kindergarten 108	21	SF	7	10+ years	
	Doors - Transom Window	Toilet in Kindergarten 108	1	SF	7	10+ years	
	Floor - Tile	Toilet in Kindergarten 108	21	SF	6	10+ years	
	Lighting - Pendent/Surface	Toilet in Kindergarten 108	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Toilet in Kindergarten 108	26	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Toilet in Kindergarten 108	26	SF	7	10+ years	
	Water Closet	Toilet in Kindergarten 108	1	ĒA	7	10+ years	
	Accessories	Toilet in Main Office Suite	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet in Main Office Suite	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Toilet in Main Office Suite	1	ĒΑ	7	10+ years	
	Floor - Tile	Toilet in Main Office Suite	40	SF	7	10+ years	
	Lavatory	Toilet in Main Office Suite	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	Toilet in Main Office Suite	1	EΑ	7	10+ years	
	Partitions	Toilet in Main Office Suite	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	Toilet in Main Office Suite	88	SF	7	10+ years	
	Water Closet	Toilet in Main Office Suite	1	EA	7	10+ years	
			•		•	121 ,00.0	



Catego	ry : Room		В	uilding	: Main		<u> </u>
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Croup	Accessories	Women's in Faculty Lounge	60	SF	7	6-10 years	Comments
	Ceiling - Plaster/Drywall	Women's in Faculty Lounge	60	SF	7	10+ years	
	Doors - Transom Window	Women's in Faculty Lounge	1	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's in Faculty Lounge	60	SF	7	10+ years	
	Floor Drain	Women's in Faculty Lounge	1	EA	7	10+ years	
	Lavatory	Women's in Faculty Lounge	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Women's in Faculty Lounge	1	EA	5	0-1 year	Does not work.
	Lighting - Wall Mounted	Women's in Faculty Lounge	1	EA	7	10+ years	Does not work.
	Partitions	Women's in Faculty Lounge	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Women's in Faculty Lounge	151	SF	6	10+ years	
	Water Closet	Women's in Faculty Lounge	1	EA	7	10+ years	
		Wellie III addity Louinge	·		-	ioi youlo	
Catego	ry : Classroom		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #103 (Regular Classroom)						
	Casework	1st Floor	28	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	747	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	747	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	20	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	865	SF	7	10+ years	
Classro	om #104 (Kindergarten)						
	Casework	1st Floor	72	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,182	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	. 1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,170	SF	7	10+ years	
	Floor - Tile	1st Floor	12	SF	4	1-2 years	Broken tiles
	Lighting - Lay-in	1st Floor	26	EA	7	10+ years	
	Storage/ Closet	1st Floor	47	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,243	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
_Classroo	om #105 (Regular Classroom)						
	Casework	1st Floor	23	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	747	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	747	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	865	SF	7	10+ years	
	<b>,</b>					<b>,</b>	

Campus Name: Murray Page : 10 of 38 Assessment Date: 02/05/2024



Catego	ry : Classroom		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #106 (Kindergarten)						
	Casework	1st Floor	72	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,182	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,182	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	47	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,243	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #107 (Regular Classroom)						
	Casework	1st Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	747	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	747	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	865	SF	7	10+ years	
Classes	om #108 (Pre School)						
Classion		1st Floor	70	LF		0.40.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Casework		72		6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,182	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1 100	EA	7	10+ years	
	Floor - Tile	1st Floor	1,182	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	26	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,243	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	747	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	747	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	19	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	6	6-10 years	
		2nd Floor	16	LF	7	6-10 years	
	Marker Board	ZIIU F1001	16	L-1	,	U-10 years	



Catego	ry : Classroom		В	uilding	: Main		-
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #202 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	764	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	764	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	19	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	966	SF	7	10+ years	
Classroo	om #203 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	747	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	747	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	966	SF	7	10+ years	
Classroo	nm #204 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	764	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	764	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	966	SF	7	10+ years	
Classroo	om #205 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	747	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	747	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	865	SF	6	10+ years	
Classroo	m #206 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	764	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	

Campus Name: Murray Page: 12 of 38 Assessment Date: 02/05/2024



atego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	759	SF	6	10+ years	
	Floor - Tile	2nd Floor	5	SF	4	1-2 years	Chipping tiles
	Lighting - Lay-in	2nd Floor	20	EΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	966	SF	7	10+ years	
assroo	m #207 (Regular Classroom)						
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	700	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	47	SF	5	1-2 years	Cracking plaster
	Chalk Board	2nd Floor	16	LF	4	2-5 years	ordermig practer
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile	2nd Floor	747	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	865	SF	7	10+ years	
	Walls - Flastel/Drywall	2110 11001	803	Si	,	10+ years	
lassroo	m #208 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	764	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	764	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	966	SF	7	10+ years	
lassroo	m #210 (Regular Classroom)						
	Casework	2nd Floor	26	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	755	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	8	SF	4	1-2 years	Missing tiles
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	mooning moo
	Floor - Tile	2nd Floor	763	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	966	SF	7	10+ years	
	vvalis - Flastel/DiyWall	ZIIU FIUUI	900	SF	,	TOT years	
atego	ry : Interior		В	uilding	: Main	D	
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor						•	
	Ceiling - Plaster/Drywall	1st Floor	3,249	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EΑ	7	10+ years	

Campus Name: Murray Page: 13 of 38 Assessment Date: 02/05/2024



Catego	ry : Interior		В	uilding	: Main		Tronwood TVEITGE, Glillouge, IE 000 I
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Drinking Fountains - Single Fountain	1st Floor	2	EΑ	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	3,249	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	36	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	2	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	158	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,934	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,934	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,249	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,249	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	40	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	146	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	1	EA	5	1-2 years	Missing locking mechanism
	Student Lockers - Two Tiers	2nd Floor	18	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,934	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,934	SF	7	10+ years	
_Safetv_							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	14	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	290	SF	7	10+ years	
	Floor - Terrazzo	North	290	SF	7	10+ years	
	Handrails	North	50	LF	7	10+ years	
	Lighting - Pendent/Surface	North	7	EA	7	6-10 years	
	Stairs - Terrazzo	North	27	LF	7	10+ years	
	Walls - Plaster/Drywall	North	360	SF	7	10+ years	
	Walls - Structural Glazed Tile	North	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	290	SF	7	10+ years	
	Floor - Terrazzo	South	290	SF	7	10+ years	
	Handrails	South	50	LF	7	10+ years	
	Lighting - Pendent/Surface	South	7	EA	7	6-10 years	
	Stairs - Terrazzo	South	22	LF	7	10+ years	
	Walls - Plaster/Drywall	South	360	SF	7	10+ years	
	Walls - Structural Glazed Tile	South	400	SF	7	10+ years	

Campus Name: Murray Page : 14 of 38 Assessment Date: 02/05/2024







Category : Exterior **Building: Addition 1** 

	y . Exterior			aag	. Additi	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•		Location	Qualitity	OOM	Naiik	Replacement	Comments
ance		#BAB# /B				10	
	Exterior Doors - Exterior Steel Door	"RAD" (Roof Access Door): South	1	EA	6	10+ years	
	E	side of Addition 1 at "Link Roof"		_^	•	40	
	Exterior Doors - Exterior Steel Door	#3.5 S	1	EA	6	10+ years	
	Ramps - Concrete	#3.5 S	15	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 S	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 Exit N	1	EA	6	10+ years	
	Entrance Control - Audio	#6 W	1	EA	6	10+ years	
	Exterior Doors - Store Front	#6 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 W	1	EA	6	10+ years	
	Power Door Operator and Controls	#6 W	1	EA	7	10+ years	
	Entrance Control - Audio	#7 N	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#7 N	2	EA	6	10+ years	
	Entrance Control - Audio	#8 E	1	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#8 E	2	EΑ	6	10+ years	
	Ramps - Concrete	#8 E	4	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	North Roof Entrance	1	EA	7	10+ years	
						•	
undati	on						
	Foundation - Concrete	Entire Building	555	LF	7	10+ years	
	Superstructure - Steel	Entire Building	16,760	SF	7	10+ years	
		<b>.</b>	-,			,	
hting							
- 0	Exterior Lighting - Wall Mounted	Entire Building	11	EA	6	6-10 years	
	3 3	Ç				•	
of Sys	tem						
	Coping - Stone	Link Roof	20	LF	6	10+ years	
	Downspouts - Interior Downspouts	Link Roof	24	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Link Roof	20	LF	6	10+ years	
	Roof - Modified Bitumen	Link Roof	540	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Link Roof	540	SF	7	10+ years	
	Concrete Topping					•	
	Coping - Stone	North Roof	195	LF	7	10+ years	
	Downspouts - Interior Downspouts	North Roof	45	LF	7	10+ years	
	Parapet - 16" - 30" Height	North Roof	195	LF	7	10+ years	
					7		
			-,		-	,	
	•	South Roof	1	FΑ	7	10+ years	
	Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/ Concrete Topping Access Ladder - Metal Chimney - Metal Flue Coping - Stone Downspouts - Interior Downspouts	North Roof North Roof South Roof South Roof South Roof South Roof	4,086 4,086 1 24 180 180	SF SF EA LF LF	6	2-5 years 10+ years 10+ years 6-10 years 10+ years 10+ years	

Campus Name: Murray Page : 15 of 38 Assessment Date: 02/05/2024



Category : Exterior

# Phillip Murray Elementary Language Academy 5335 S Kenwood AVENUE, Chicago, IL 60615

Recommend

**Building: Addition 1** 

Craus						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet > 30"	South Roof	422	LF	7	10+ years	
	Roof - Modified Bitumen	South Roof	10,335	SF	6	10+ years	
	Roof Hatch - Metal	South Roof	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	South Roof	10,335	SF	7	10+ years	
	Concrete Topping		,			,	
	9						
Walls							
vvalis	E W.II. B.: I	E (: D 11)	0.000			40	
	Exterior Walls - Brick	Entire Building	9,908	SF	6	10+ years	<b>5</b>
	Exterior Walls - Brick	Entire Building	100	SF	5	1-2 years	Deteriorated sealant at control joints
	Exterior Walls - Stone-Cast	Entire Building	2,460	SF	6	10+ years	
_Windows							
	Clerestory - Glass Double-Pane	Entire Building	504	SF	7	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	316	SF	7	10+ years	
	Curtain wall - Louver	Entire Building	72	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	599	SF	7	10+ years	
	Lintels - Steel	Entire Building	196	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	681	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	120	SF	7	10+ years	
	Timad No Gadii / Naminami Boabio pano	Emile Ballaning	.20	O.	•	ioi youlo	
Catego	y : Electrical		R	uildina	: Additi	on 1	
Gutogol	y 1 2100111041			anamg	. / taaiti	Recommend	
0	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group							Commonto
Group	· ·	Location	quantity			•	
•	cy System		, , , , , , , , , , , , , , , , , , ,			•	
•	cy System  Emergency Battery Packs - Corridors and	Entire Building	6	EA	6	6-10 years	
•	cy System  Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA		6-10 years	
•	cy System  Emergency Battery Packs - Corridors and		, , , , , , , , , , , , , , , , , , ,		6	•	Quantity updated to reflect observed
•	cy System  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Entire Building Entire Building	6 7	EA EA	6	6-10 years 6-10 years	Quantity updated to reflect observed conditions
•	cy System  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building	6 7 5	EA EA	6 6	6-10 years 6-10 years 6-10 years	• •
•	cy System  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym	Entire Building Entire Building Entire Building Entire Building	6 7 5 6	EA EA EA EA	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	• •
•	cy System  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV	Entire Building Entire Building Entire Building Entire Building Entire Building	6 7 5	EA EA	6 6	6-10 years 6-10 years 6-10 years	• •
•	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection	Entire Building	6 7 5 6	EA EA EA EA	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	• •
•	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection	Entire Building	6 7 5 6 16,760	EA EA EA EA SF	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	• •
•	cy System  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV	Entire Building Entire Building Entire Building Entire Building Entire Building	6 7 5 6 16,760 16,760	EA EA EA SF SF	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	• •
•	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs	Entire Building	6 7 5 6 16,760 16,760 1,878	EA EA EA SF SF SF	6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	• •
•	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym	Entire Building	6 7 5 6 16,760 16,760	EA EA EA SF SF	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	• •
•	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs	Entire Building	6 7 5 6 16,760 16,760 1,878 6,801	EA EA EA SF SF SF SF	6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	• •
Emergen	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets	Entire Building	6 7 5 6 16,760 16,760 1,878 6,801	EA EA EA SF SF SF SF	6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	• •
•	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets	Entire Building	6 7 5 6 16,760 16,760 1,878 6,801 878	EA EA EA SF SF SF SF	6 6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	conditions
Emergen	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets	Entire Building	6 7 5 6 16,760 16,760 1,878 6,801	EA EA EA SF SF SF SF	6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	• •
_Emergen	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets  vice PA System	Entire Building	6 7 5 6 16,760 16,760 1,878 6,801 878	EA EA EA SF SF SF SF	6 6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	conditions
Emergen	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets  vice PA System	Entire Building	6 7 5 6 16,760 16,760 1,878 6,801 878	EA EA EA SF SF SF SF	6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years	Served by main building PA system
_Emergen	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets  vice PA System  Stribution Lighting and Power Panels - Above 100 A	Entire Building	6 7 5 6 16,760 16,760 1,878 6,801 878	EA EA EA SF SF SF SF SF	6 6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Served by main building PA system  1A, 1D
_Emergen	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets  vice PA System	Entire Building	6 7 5 6 16,760 16,760 1,878 6,801 878	EA EA EA SF SF SF SF	6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years	Served by main building PA system
_Main Ser_	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym  Exit Signs - Corridors and Stairs Exit Signs - Gym Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets  vice PA System  Stribution Lighting and Power Panels - Above 100 A	Entire Building	6 7 5 6 16,760 16,760 1,878 6,801 878	EA EA EA SF SF SF SF SF	6 6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Served by main building PA system  1A, 1D



Catego	ry : Electrical		В	uilding	: Additio	on 1	
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Fire Protection		В	uilding	: Additio	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	16,760	SF	6	10+ years	
	Fire Alarm_System	Entire Building	16,760	SF	6	6-10 years	Served by main building system
Sprinkler	System						
	Sprinkler Heads	Entire Building	16,760	SF	7	10+ years	
	Sprinkler Piping	Entire Building	16,760	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	16,760	SF	6	10+ years	
Catego	ry : Mechanical		R	uildina	: Additio	on 1	
Calogo	. y · moonamou.		_	aag	. , , , , , , , , , , , , , , , , , , ,	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	5	1-2 years	Serve gymnasium, 2002 installation, belts are loose and need immediate replacement
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room - AHU1	1	EA	6	6-10 years	AHU1 installed in 2002, serves gymnasium, hot water, served by boilers in addition 2
	Air Intake	Mechanical Room - AHU1	1	EA	6	6-10 years	50.10.10 II. 6446.110.1. <u>-</u>
	VAV Box	Mechanical Room - AHU1	25	EA	6	6-10 years	Mounted in mechanical room ceiling
Heating	Devices						
	Cabinet Heaters - With Hot Water Coil	1st Floor	3	EA	6	6-10 years	
	Radiator Panels - Hot Water	1st Floor	4	EA	6	10+ years	
	Unit Heater - Hot Water	Entire Building	3	EA	6	6-10 years	Hot water served from Addition 2.
	Fin Tube - Hot Water	Entire Building	15	LF	6	10+ years	Hot water, fin tube, and second floor served by boilers, in addition 2
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	400	LF	7	10+ years	Pipes from boilers. In addition, number two are well labeled and only minor insulation Repairs are required
Tempera	ature Control						
	DDC System	Entire Building	16,760	SF	6	6-10 years	Johnson Controls, Metasys system replaced by new DDC BAS in main bldg

Campus Name: Murray Page : 17 of 38 Assessment Date: 02/05/2024



#### Phillip Murray Elementary Language Academy

Category : Mechanical			5335 S Kenwood AVENUE, Chicago, IL 60615 <b>Building: Addition 1</b>					
Jaiego	i y . Mechanicai		O O	unung				
Froup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Jioup	Electric Thermostat	Entire Building	3	EA	6	6-10 years	Serve unit heaters and fan coil units	
	Thermostats - DDC	Entire Building	15	EA	6	6-10 years		
		g			•	,		
entilatio	on							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof	2	EA	6	10+ years	Second floor, mechanical room, one ducted, one serves mechanical roor itself	
atego	ry : Plumbing		В	uilding	: Additi			
	_					Recommend		
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ot Wate								
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	Serves gym, and addition one, recirculator has been recently replaced	
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Mechanical Room	1	EA	6	6-10 years	Тергиоса	
iping								
	Domestic Piping-Hot Water Return Lines	Entire Building	16,760	SF	6	10+ years	2002 installation, inaccessible, in neaddition	
	Domestic Piping-Hot Water Return Risers	Entire Building	16,760	SF	6	10+ years	2002 installation, inaccessible, in neaddition	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	16,760	SF	6	10+ years	2002 installation, inaccessible, in neaddition	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	16,760	SF	6	10+ years	2002 installation, inaccessible, in neaddition	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	16,760	SF	6	10+ years	2002 installation, inaccessible, in neaddition	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	16,760	SF	6	10+ years	2002 installation, inaccessible, in neaddition	
	Sanitary Piping	Entire Building	16,760	SF	6	10+ years	2002 installation, inaccessible, in neaddition	
	Storm Piping	Entire Building	16,760	SF	7	10+ years		
	Vent Piping	Entire Building	16,760	SF	7	10+ years		
atego	ry : Room		В	uildina	: Additi	on 1		
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
dminist	rative Suites/Offices		<u> </u>					
	Ceiling - Lay-in	1st Floor Pantry/Lounge	256	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor Pantry/Lounge	8	SF	4	1-2 years	Missing tiles	
	Doors - Wood Doors inclu hw	1st Floor Pantry/Lounge	1	ĒΑ	7	10+ years	J	

Campus Name: Murray Page: 18 of 38 Assessment Date: 02/05/2024



Category : Room			В	uilding	: Additi	on 1	Building : Addition 1						
						Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments						
	Floor - Tile	1st Floor Pantry/Lounge	264	SF	7	10+ years							
	Lighting - Lay-in	1st Floor Pantry/Lounge	4	EA	7	10+ years							
	Power Distribution	1st Floor Pantry/Lounge	6	EA	7	10+ years							
	Walls - Concrete Block	1st Floor Pantry/Lounge	682	SF	7	10+ years							
	Work SInk	1st Floor Pantry/Lounge	1	EA	7	10+ years							
	Ceiling - Lay-in	Conference Room	330	SF	7	10+ years							
	Doors - Wood Doors inclu hw	Conference Room	1	EA	7	10+ years							
	Floor - Tile	Conference Room	330	SF	7	10+ years							
	Lighting - Lay-in	Conference Room	5	EA	7	10+ years							
	Lighting - Lay-in	Conference Room	1	EA	5	1-2 years	Missing cover						
	Power Distribution	Conference Room	8	EA	7	10+ years							
	Walls - Concrete Block	Conference Room	720	SF	7	10+ years							
	Ceiling - Lay-in	Gym Office	334	SF	7	10+ years							
	Ceiling - Lay-in	Gym Office	16	SF	4	1-2 years	Water damage, tiles near window						
	Doors - Side-lite	Gym Office	12	SF	7	10+ years							
	Doors - Steel Doors incl hw	Gym Office	1	EA	7	10+ years							
	Floor - Tile	Gym Office	350	SF	7	10+ years							
	Lighting - Lay-in	Gym Office	6	EA	7	10+ years							
	Power Distribution	Gym Office	10	EA	7	10+ years							
	Storage/ Closet	Gym Office	10	SF	7	10+ years							
	Walls - Concrete Block	Gym Office	527	SF	7	10+ years							
	Ceiling - Lay-in	Storage Used as Meeting Room	300	SF	7	10+ years							
	Doors - Wood Doors inclu hw	Storage Used as Meeting Room	1	EA	7	10+ years							
	Floor - Tile	Storage Used as Meeting Room	300	SF	7	10+ years							
	Lighting - Lay-in	Storage Used as Meeting Room	4	EA	7	10+ years							
	Power Distribution	Storage Used as Meeting Room	4	EA	7	10+ years							
	Walls - Concrete Block	Storage Used as Meeting Room	600	SF	7	10+ years							
_Gvmnas	ia												
•	Bleacher Seating	1st Floor	184	EA	7	10+ years	No maximum occupancy sign						
	Ceiling - Exposed	1st Floor	6,801	SF	7	10+ years	17 - 3						
	Doors - Steel Doors incl hw	1st Floor	6	ĒΑ	7	10+ years							
	Floor - Wood	1st Floor	6,801	SF	7	10+ years							
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years							
	Scoreboards	1st Floor	1	EA	7	6-10 years							
	Walls - Concrete Block	1st Floor	9,966	SF	7	10+ years							
_Locker/S	Shower Room												
	Accessories	1st Flr Men's Locker Room	439	SF	7	6-10 years							
	Benches, ped mounted	1st Flr Men's Locker Room	9	LF	7	10+ years							
	Ceiling - Plaster/Drywall	1st Fir Men's Locker Room	439	SF	7	10+ years							
	Doors - Wood Doors inclu hw	1st Fir Men's Locker Room	1	EA	7	10+ years							
	Floor - Terrazzo	1st Fir Men's Locker Room	439	SF	7	10+ years							
	Floor Drain	1st Fir Men's Locker Room	2	EA	7	10+ years							
	<del></del>	22 <u></u>	_		•	, , , , , , , , , ,							

Campus Name: Murray Page: 19 of 38 Assessment Date: 02/05/2024



Catego	Category : Room			Building : Addition 1				
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Hand Dryer	1st Flr Men's Locker Room	1	EA	7	6-10 years		
	Lavatory	1st Flr Men's Locker Room	1	EA	7	10+ years		
	Lighting - Lay-in	1st Flr Men's Locker Room	3	EA	7	10+ years		
	Partitions	1st Flr Men's Locker Room	2	EA	7	10+ years		
	Showers	1st Flr Men's Locker Room	1	EA	7	10+ years		
	Student Lockers - One Tier	1st Flr Men's Locker Room	3	EA	7	10+ years		
	Student Lockers - Two Tier	1st Flr Men's Locker Room	20	EA	7	10+ years		
	Urinals	1st Flr Men's Locker Room	2	EA	7	10+ years		
	Walls - Structural Glazed Tile	1st Flr Men's Locker Room	680	SF	7	10+ years		
	Water Closet	1st Flr Men's Locker Room	2	EA	7	10+ years		
	Accessories	1st Flr Women's Locker Room	439	SF	7	6-10 years		
	Benches, ped mounted	1st Flr Women's Locker Room	9	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Flr Women's Locker Room	439	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Flr Women's Locker Room	1	EA	7	10+ years		
	Floor - Terrazzo	1st Flr Women's Locker Room	439	SF	7	10+ years		
	Floor Drain	1st Flr Women's Locker Room	2	EA	7	10+ years		
	Hand Dryer	1st Flr Women's Locker Room	1	EA	7	6-10 years		
	Lavatory	1st Flr Women's Locker Room	2	EA	7	10+ years		
	Lighting - Lay-in	1st Flr Women's Locker Room	6	EA	7	10+ years		
	Partitions	1st Flr Women's Locker Room	3	EA	7	10+ years		
	Showers	1st Flr Women's Locker Room	1	EA	4	1-2 years	No longer in use	
	Student Lockers - One Tier	1st Flr Women's Locker Room	3	EA	7	10+ years	-	
	Student Lockers - Two Tier	1st Flr Women's Locker Room	20	EA	7	10+ years		
	Walls - Structural Glazed Tile	1st Flr Women's Locker Room	675	SF	7	10+ years		
	Water Closet	1st Flr Women's Locker Room	3	EA	7	10+ years		
Lunch &	Multipurpose Room							
	Ceiling - Lay-in	1st Floor	1,280	SF	7	10+ years		
	Ceiling - Lay in	1st Floor	10	SF	4	1-2 years	Water damage	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	Trator damage	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	1,290	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	22	EA	7	10+ years		
	Storage/ Closet	1st Floor	260	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	1,000	SF	7	10+ years		
	Walls Collecte Block	13111001	1,000	Oi	,	101 years		
_Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	68	SF	5	10+ years		
	Mechanical/ Service Rooms	2nd Floor	1,604	SF	7	10+ years		
	Storage Room	2nd Floor	315	SF	7	10+ years		
	Č					,		

Campus Name: Murray Page : 20 of 38 Assessment Date: 02/05/2024



Catego	ry : Interior	_	В	uilding	: Additi	on 1	-
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	<b>.</b>						
	Ceiling - Lay-in	1st Floor	1,898	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	1,898	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	23	EA	7	10+ years	
	Stairs - Terrazzo	1st Floor	4	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	3,000	SF	7	10+ years	
	Walls - Masonry	1st Floor	220	SF	7	10+ years	
Safety							
,	Security Cameras	Entire Building	8	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Mechanical Access Stair	405	SF	7	10+ years	
	Floor - Terrazzo	Mechanical Access Stair	405	SF	7	10+ years	
	Handrails	Mechanical Access Stair	128	ĹF	7	10+ years	
	Lighting - Pendent/Surface	Mechanical Access Stair	2	ĒΑ	6	10+ years	
	Stairs - Terrazzo	Mechanical Access Stair	64	LF	7	10+ years	
	Walls - Concrete Block	Mechanical Access Stair	800	SF	7	10+ years	
			300	•	•	,	







Category : Exterior **Building: Addition 2** 

atogo.	y . Exterior			unanig	. Additi		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
trance							
	Exterior Doors - Exterior Stainless Steel	"RAD" ( Roof Access Door): "East	1	EA	6	10+ years	
	Door	Roof" access door					
	Entrance Control - Audio and Video	#10 E	1	EA	7	6-10 years	
	Exterior Doors - Store Front	#10 E	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#10 E	1	EA	7	10+ years	
	Exterior Stairs - Concrete	#10 E	27	LF	7	10+ years	
	Exterior Stairs - Concrete	#10 E	3	LF	5	1-2 years	Cracked landing
	Power Door Operator and Controls	#10 E	1	EA	7	6-10 years	-
	Ramp Handrail - Steel_Ramp Handrail	#10 E	54	LF	6	10+ years	
	Ramps - Concrete	#10 E	17	LF	5	10+ years	
	Ramps - Concrete	#10 E	10	LF	5	1-2 years	Large cracks with corroding reinforcement
	Stair Handrail - Steel_Stair Handrail	#10 E	6	LF	6	10+ years	
	Entrance Control - Audio	#11 S	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#11 S	2	EΑ	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#11 S	54	LF	7	10+ years	
	Ramps - Concrete	#11 S	27	LF	6	10+ years	
	Entrance Control - Audio and Video	#9 N	1	EΑ	7	10+ years	
	Exterior Doors - Store Front	#9 N	2	ĒΑ	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#9 N	54	LF	7	10+ years	
	Ramps - Concrete	#9 N	27	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#9.1 N	1	ĒA	5	1-2 years	corroded frame
	Exterior Doors - Exterior Steel Door	#9.2 N	2	EA	4	1-2 years	Corroded door and frame
	Exterior Doors - Exterior Steel Door	#9.3	1	EA	4	1-2 years	Corroded door and frame
	Exterior Doors - Exterior Steel Door	West Roof Entrance Doors	2	EΑ	6	10+ years	correded door and name
		Wood Roof Entrance Books	2	LA	Ü	101 youro	
oundati							
	Foundation - Concrete	Entire Building	657	LF	7	10+ years	
	Superstructure - Steel	Entire Building	27,886	SF	7	10+ years	
ghting							
-	Exterior Lighting - Lighting	Entire Building	3	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	18	EA	7	6-10 years	
		•				-	
oof Sys							
	Coping - Stone	East Roof	264	LF	7	10+ years	
	Downspouts - Interior Downspouts	East Roof	60	LF	7	10+ years	
	Parapet - Parapet > 30"	East Roof	264	LF	7	10+ years	
	Roof - Modified Bitumen	East Roof	7,052	SF	7	10+ years	
		F4 D4	7.052	SF	7	10	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	East Roof	7,052	SF	7	10+ years	



Categor	y : Exterior		B	uilding	: Addition	on 2	
						Recommend	
<b>3roup</b>	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	High Roof	1	EΑ	7	10+ years	
	Chimney - Metal Flue	High Roof	36	LF	7	10+ years	
	Coping - Metal	High Roof	49	LF	7	10+ years	
	Coping - Stone	High Roof	265	LF	6	10+ years	
	Downspouts - Interior Downspouts	High Roof	90	LF	7	10+ years	
	Parapet - 16" - 30" Height	High Roof	265	LF	7	10+ years	
	Roof - Modified Bitumen	High Roof	4,257	SF	6	2-5 years	
	Roof Hatch - Metal	High Roof	1,207	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	High Roof	4,257	SF	7	10+ years	
	Concrete Topping	riigiriXoor	4,237	01	,	10+ years	
	•	South Roof	110	LF	7	10	
	Coping - Stone		-			10+ years	
	Parapet - 16" - 30" Height	South Roof	110	LF	7	10+ years	
	Roof - Modified Bitumen	South Roof	1,712	SF	6	10+ years	DII
	Roof - Modified Bitumen	South Roof	20	SF	5	1-2 years	Blistering
	Roof Structure - Steel / Metal Deck/	South Roof	1,732	SF	7	10+ years	
	Concrete Topping						
	Coping - Stone	West Roof	140	LF	7	10+ years	
	Downspouts - Exterior Downspouts	West Roof	30	LF	7	10+ years	
	Parapet - 16" - 30" Height	West Roof	140	LF	7	10+ years	
	Roof - Modified Bitumen	West Roof	827	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	West Roof	827	SF	7	10+ years	
	Concrete Topping					•	
Valls							
	Canopy - Concrete/ Stucco	Entire Building	108	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	16,230	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	100	SF	5	1-2 years	Deteriorated control joint sealant
	Exterior Walls - Stone-Cast	Entire Building	3,983	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	30	SF	5	1-2 years	Deteriorated control joint sealant
<u> Windows</u>	Curtain wall - Glazed Double Pane	Entire Duilding	F47		7	10	
		Entire Building	517	SF	7	10+ years	
	Curtain wall - Insulated Panel	Entire Building	12	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	978	SF	7	10+ years	
	Lintels - Steel	Entire Building	319	LF	7	10+ years	
	Windows - Louver	Entire Building	75	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	915	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	293	SF	7	10+ years	
Categor	y : Electrical		В	uildina	: Additio	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Campus Name: Murray Page : 23 of 38 Assessment Date: 02/05/2024



Catego	ry : Electrical		Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years		
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years		
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	2	0-1 year	Exit sign missing completely	
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	2	0-1 year	No battery, no generator.	
	Security System - CCTV	Entire Building	27,886	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	27,886	SF	6	6-10 years	Functional, 2002 installation.	
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,644	SF	6	10+ years	•	
	Emergency A/C Power - Students Toilets	Entire Building	973	SF	6	10+ years		
Main Se	rvice							
	Main Electrical Service - Greater than 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	New in 2002, serves all three buildings	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	Serves addition 2, two meters.	
	PA System	Entire Building	27,886	SF	6	6-10 years	Served by PA in main building front office	
Power D	istribution							
	Lighting and Power Panels - Above 100 A	1st floor, Electrical Room, Entire Building	7	EA	7	10+ years	1A, 1C, 1F in elec vault 1T1, 1-G in 1st floor elec closet 1T2 in 2nd flr ele closet 1K1 & 1K2 in kitchen	
	Main Distribution Panels - 400 - 600 amp	1st floor, Electrical Room, Entire Building	2	EA	7	10+ years	PDP1 in 1st flr elec closet PDP4 in electrical vault PDP2 serves main building, not accounted for here	
	Main Distribution Panels - Greater than 600 amp	1st floor, Electrical Room, Entire Building	1	EA	7	10+ years	PDP3 800A	
	Main Distribution Panels - Greater than 600 amp	1st floor, Electrical Room, Entire Building	1	EA	7	10+ years	MCC1	
Catego	ry : Fire Protection		В	uilding	: Additio			
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar	m							
	Fire Alarm Strobe Lights	Mechanical Room	27,866	SF	7	10+ years		
	Fire Alarm_System	Mechanical Room	27,866	SF	6	10+ years	2002 installation connected to main building fully functional	
	Fire Pump Controller	Mechanical Room	1	EA	6	10+ years		
⊇ump Ro	oom Assembly							
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	10+ years	2002 installation serves additions, one and two	

Campus Name: Murray Page : 24 of 38 Assessment Date: 02/05/2024



Category : Fire Protection			Building : Addition 2						
	,					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Jockey Pump	Mechanical Room	1	EA	6	10+ years			
Sprinkler									
	Sprinkler Heads	Entire Building	27,866	SF	7	10+ years			
	Sprinkler Piping	Entire Building	27,866	SF	6	10+ years			
	Wet Sprinkler System	Entire Building	27,866	SF	6	10+ years			
Categor	ry : Mechanical		В	uilding	: Additio	on 2			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Air Condi	tioning								
	Chemical Pot Feeder	Roof	1	EA	6	6-10 years			
	Chiller-Air Cooled-Scroll Type-Roof Mounted	Roof	1	EA	2	1-2 years	Abandoned in place, removed from		
	- 101 - 150 tons						chilled water loop.		
	Glycol Feed	Roof	1	EA	5	10+ years	Glycol manually added		
	Pipes - Chilled Water Pipe- Galvanized	Roof	500	LF	6	10+ years			
	Pressure Fill System	Roof	1	EA	5	6-10 years			
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	5	2-5 years	Liebert unit for MDF room in main		
	than 5 tons						building. Shows considerable		
							corrosion and age		
Air Hand	ling Systems								
	VAV Box	Entire Building	30	EA	6	6-10 years	Located above ceilings difficult to		
	23	g			Ū	0 .0 ,00.0	access.		
	Air Handling Unit- Package Multi Zone-	Mechanical Room	1	EA	5	6-10 years	AHU2 serves southeast edition new		
	Indoor- Hot Water and Chilled Water Coils -					<b>,</b>	in 2002		
	15001-20000 cfm								
	Air Intake	Mechanical Room	1	EA	6	6-10 years			
	Indoor Return Fans- Centrifugal Inline -	Mezzanine	1	EA	6	6-10 years			
	10001 - 20000 CFM								
Boiler Sy	stems								
y	Boiler Auxiliary- Non Condensing Hot Water	Mechanical Room	2	EA	6	6-10 years			
	- 1001 - 2000 MBH				-	<b>,</b>			
	Chemical Pot Feeder	Mechanical Room	1	EA	6	10+ years			
	Combustion Dampers	Mechanical Room	2	EA	7	6-10 years			
	Glycol Feed System	Mechanical Room	1	EA	6	6-10 years			
	Non Condensing- Water Tube- Flexible	Mechanical Room	1	EA	6	6-10 years			
	Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH					·			
	Non Condensing- Water Tube- Flexible	Mechanical Room	1	EA	6	6-10 years			
	Tube- Force Draft- Hot Water Boiler - 1001					,			
	- 2000 MBH								

Campus Name: Murray Page : 25 of 38 Assessment Date: 02/05/2024



Catego	ory : Mechanical		В	uilding	: Additi	on 2	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	Water Fill System	Mechanical Room	1	EA	6	6-10 years	
Heating	Devices						
ŭ	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	6-10 years	
	Radiator Panels - Hot Water	Entire Building	4	EA	6	10+ years	
	Unit Heater - Electric	Mechanical Room	1	EA	6	6-10 years	Electrical vault
	Unit Heater - Hot Water	Mechanical Room	3	EA	6	6-10 years	Quantity updated to reflect observed conditions; three hot water unit heaters in mechanical room
Mechan	ical Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	6-10 years	
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	7	6-10 years	P-8
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	P-7\nServes additions, one and 2\nVibration, isolators and valves are significantly corroded
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	Serve two buildings, addition one, and addition 2
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	Serve addition one, and addition 2
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	Circulating return pump serves boiler one
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	Circulating return pump serves boiler 2
Temper	ature Control						
	Electric Thermostat	Entire Building	4	EA	6	6-10 years	Serve to hot water, unit heaters and electric unit heater and exhaust fan in electric vault
	Thermostats - DDC	Entire Building	30	EA	6	6-10 years	electric vauit
Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	Elec vault Mech room Fire pump room Quantity updated to reflect observed conditions
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	observed conditions
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen Type II Exhaust Hood- Warming Kitchen	Entire Building Entire Building	1 2	EA EA	6 6	6-10 years 6-10 years	Inspected last year and functional

Campus Name: Murray Page : 26 of 38 Assessment Date: 02/05/2024



Categor	ry : Plumbing	В	uilding	: Additi			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	Paired with storage tank
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	1	EA	6	10+ years	2019 installation, electrical needs to be cleaned up.
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Mechanical Room	1	EA	6	6-10 years	·
_Piping							
. •	Domestic Piping-Hot Water Return Lines	Entire Building	27,886	SF	6	10+ years	2002 installation, inaccessible, in new addition
	Domestic Piping-Hot Water Return Risers	Entire Building	27,886	SF	6	10+ years	2002 installation, inaccessible, in new addition
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	27,886	SF	6	10+ years	2002 installation, inaccessible, in new addition
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	27,886	SF	6	10+ years	2002 installation, inaccessible, in new addition
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	27,886	SF	6	10+ years	2002 installation, inaccessible, in new addition
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	27,886	SF	6	10+ years	2002 installation, inaccessible, in new addition
	Sanitary Piping	Entire Building	27,886	SF	7	10+ years	
	Storm Piping	Entire Building	27,886	SF	7	10+ years	
	Vent Piping	Entire Building	27,886	SF	6	10+ years	Inaccessible, in addition
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room, 1st floor	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Mechanical Room, 1st floor	1	EA	5	6-10 years	Under elevator pit.

Category: Room **Building: Addition 2** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	111 Student Service	251	SF	7	10+ years	
	Doors - Side-lite	111 Student Service	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	111 Student Service	1	EA	7	10+ years	
	Floor - Carpet	111 Student Service	251	SF	7	6-10 years	
	Lighting - Lay-in	111 Student Service	3	EA	7	10+ years	
	Lighting - Lay-in	111 Student Service	1	EA	5	0-1 year	Does not work.
	Power Distribution	111 Student Service	6	EA	7	10+ years	
	Walls - Concrete Block	111 Student Service	410	SF	7	10+ years	
	Walls - Plaster/Drywall	111 Student Service	152	SF	7	10+ years	
	Ceiling - Lay-in	113 Asst. Principal	288	SF	7	10+ years	
	Ceiling - Lay-in	113 Asst. Principal	8	SF	4	1-2 years	Water damage

Campus Name: Murray Page : 27 of 38 Assessment Date: 02/05/2024



Category : Room			В	Building : Addition 2					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Side-lite	113 Asst. Principal	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	113 Asst. Principal	1	EA	7	10+ years			
	Floor - Carpet	113 Asst. Principal	296	SF	7	6-10 years			
	Lighting - Lay-in	113 Asst. Principal	4	EA	7	10+ years			
	Power Distribution	113 Asst. Principal	8	EA	7	10+ years			
	Walls - Concrete Block	113 Asst. Principal	466	SF	7	10+ years			
	Walls - Plaster/Drywall	113 Asst. Principal	172	SF	7	10+ years			
	Ceiling - Plaster/Drywall	114 Office	118	SF	7	10+ years			
	Doors - Transom Window	114 Office	1	SF	7	10+ years			
	Floor - Tile	114 Office	118	SF	7	10+ years			
	Lighting - Pendent/Surface	114 Office	2	EΑ	7	10+ years			
	Power Distribution	114 Office	2	EA	7	10+ years			
	Walls - Concrete Block	114 Office	284	SF	7	10+ years			
	Ceiling - Lay-in	Library Office 214 B	140	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Library Office 214 B	1	EA	7	10+ years			
	Floor - Tile	Library Office 214 B	140	SF	7	10+ years			
	Lighting - Lay-in	Library Office 214 B	3	EA	7	6-10 years			
	Lighting - Lay-in	Library Office 214 B	1	EA	5	0-1 year	Does not work.		
	Power Distribution	Library Office 214 B	2	EΑ	7	10+ years			
	Walls - Concrete Block	Library Office 214 B	290	SF	7	10+ years			
	Ceiling - Lay-in	Library Work Room 214A	140	SF	7	10+ years			
	Doors - Side-lite	Library Work Room 214A	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Library Work Room 214A	1	EA	7	10+ years			
	Floor - Tile	Library Work Room 214A	140	SF	6	6-10 years			
	Lighting - Lay-in	Library Work Room 214A	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	Library Work Room 214A	390	SF	6	10+ years			
	Work SInk	Library Work Room 214A	1	EA	7	10+ years	Updated quantity		
	Ceiling - Lay-in	Office in Kitchen	85	SF	7	10+ years			
	Doors - Side-lite	Office in Kitchen	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Office in Kitchen	1	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	Office in Kitchen	85	SF	7	10+ years			
	Lighting - Lay-in	Office in Kitchen	2	EA	7	10+ years			
	Power Distribution	Office in Kitchen	4	EA	7	10+ years			
	Walls - Concrete Block	Office in Kitchen	151	SF	7	10+ years			
<u>Kitchen</u>									
	Ceiling - Lay-in	112 Servery	880	SF	7	10+ years			
	Doors - Wood Doors inclu hw	112 Servery	2	EA	7	10+ years			
	Floor - Tile/Sheet	112 Servery	880	SF	7	10+ years			
	Lighting - Lay-in	112 Servery	12	EA	7	10+ years			
	Serving Line	112 Servery	40	LF	7	10+ years			
	Walls - Concrete Block	112 Servery	780	SF	7	10+ years			
	Walls - Masonry	112 Servery	260	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,922	SF	7	10+ years			

Campus Name: Murray Page : 28 of 38 Assessment Date: 02/05/2024



Catego	Category : Room		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,922	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	10+ years	
	Storage/ Closet	1st Floor	144	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,107	SF	7	10+ years	
	Ceiling - Lay-in	Dish Room in Servery Area	226	SF	7	10+ years	
	Doors - Steel Doors incl hw	Dish Room in Servery Area	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Dish Room in Servery Area	226	SF	7	10+ years	
	Lighting - Lay-in	Dish Room in Servery Area	3	EA	7	10+ years	
	Storage/ Closet	Dish Room in Servery Area	90	SF	7	10+ years	
	Walls - Concrete Block	Dish Room in Servery Area	490	SF	7	10+ years	
	Walls - Masonry	Dish Room in Servery Area	99	SF	7	10+ years	
_Library_							
	Casework	212/214 Media Center	67	LF	7	10+ years	
	Ceiling - Lay-in	212/214 Media Center	2,240	SF	7	10+ years	
	Doors - Side-lite	212/214 Media Center	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	212/214 Media Center	2	EA	7	10+ years	
	Floor - Carpet	212/214 Media Center	2,240	SF	6	6-10 years	
	Lighting - Lay-in	212/214 Media Center	32	EA	7	6-10 years	
	Walls - Concrete Block	212/214 Media Center	2,474	SF	6	10+ years	
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	80	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	218	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	66	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	140	SF	7	10+ years	
	Janitor's Closet	2nd Floor	80	SF	7	10+ years	Not accessible.
	Storage Room	2nd Floor	145	SF	7	10+ years	Not accessible.
Restroo	n						
	Accessories	117 Staff Toilet	58	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	117 Staff Toilet	58	SF	7	10+ years	
	Doors - Wood Doors inclu hw	117 Staff Toilet	1	ĒΑ	7	10+ years	
	Floor - Terrazzo	117 Staff Toilet	58	SF	7	10+ years	
	Floor Drain	117 Staff Toilet	1	ĒΑ	7	10+ years	
	Lavatory	117 Staff Toilet	1	EA	7	10+ years	
	Lighting - Wall Mounted	117 Staff Toilet	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	117 Staff Toilet	116	SF	7	10+ years	
	Water Closet	117 Staff Toilet	1	EA	7	10+ years	
	Accessories	217 Staff Toilet	58	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	217 Staff Toilet	58	SF	7	10+ years	
	Doors - Wood Doors inclu hw	217 Staff Toilet	1	EA	7	10+ years	

Campus Name: Murray Page : 29 of 38 Assessment Date: 02/05/2024



Catego	ry : Room		В	uilding	: Additi	on 2	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	217 Staff Toilet	58	SF	7	10+ years	
	Floor Drain	217 Staff Toilet	1	EA	7	10+ years	
	Lavatory	217 Staff Toilet	1	EA	7	10+ years	
	Lighting - Wall Mounted	217 Staff Toilet	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	217 Staff Toilet	116	SF	7	10+ years	
	Water Closet	217 Staff Toilet	1	EA	7	10+ years	
	Accessories	Boys next to 113	243	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys next to 113	243	SF	7	10+ years	
	Floor - Terrazzo	Boys next to 113	243	SF	7	10+ years	
	Floor Drain	Boys next to 113	1	ĒΑ	7	10+ years	
	Lavatory	Boys next to 113	3	EA	7	10+ years	
	Lighting - Lay-in	Boys next to 113	5	EΑ	7	10+ years	
	Partitions	Boys next to 113	2	EA	7	10+ years	
	Urinals	Boys next to 113	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	Boys next to 113	664	SF	7	10+ years	
	Water Closet	Boys next to 113	2	EA	7	10+ years	
	Accessories	Boys next to 213	243	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys next to 213	243	SF	7	10+ years	
	Floor - Terrazzo	Boys next to 213	243	SF	7	10+ years	
	Floor Drain	Boys next to 213	1	EA	7	,	
		Boys next to 213	3	EA	7	10+ years	
	Lavatory		5	EA	7	10+ years	
	Lighting - Lay-in	Boys next to 213		EA EA		6-10 years	
	Partitions	Boys next to 213	2 3	EA	7	10+ years	
	Urinals	Boys next to 213			7	10+ years	
	Walls - Structural Glazed Tile	Boys next to 213	664	SF	7	10+ years	
	Water Closet	Boys next to 213	1	EΑ	7	10+ years	David and dead
	Water Closet	Boys next to 213	1	EA	4	1-2 years	Bowl cracked
	Accessories	Girls next to 119	243	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls next to 119	243	SF	7	10+ years	
	Floor - Terrazzo	Girls next to 119	243	SF	7	10+ years	
	Floor Drain	Girls next to 119	1	EA	7	10+ years	
	Lavatory	Girls next to 119	3	EA	7	10+ years	
	Lighting - Lay-in	Girls next to 119	1	EA	7	10+ years	
	Lighting - Lay-in	Girls next to 119	4	EA	7	10+ years	
	Partitions	Girls next to 119	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	Girls next to 119	664	SF	7	10+ years	
	Water Closet	Girls next to 119	5	EA	7	10+ years	
	Accessories	Girls next to 219	243	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls next to 219	243	SF	7	10+ years	
	Floor - Terrazzo	Girls next to 219	243	SF	7	10+ years	
	Floor Drain	Girls next to 219	1	EA	7	10+ years	
	Lavatory	Girls next to 219	3	EA	7	10+ years	
	Lighting - Lay-in	Girls next to 219	5	EA	6	6-10 years	
	Partitions	Girls next to 219	5	EA	7	10+ years	
						•	

Campus Name: Murray Page : 30 of 38 Assessment Date: 02/05/2024



Catego	ry : Room		Building : Addition 2							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Structural Glazed Tile	Girls next to 219	664	SF	7	10+ years				
	Water Closet	Girls next to 219	5	EA	7	10+ years				
	Accessories	Toilet in Kitchen area	61	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Toilet in Kitchen area	61	SF	7	10+ years				
	Doors - Steel Doors incl hw	Toilet in Kitchen area	1	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	Toilet in Kitchen area	61	SF	7	10+ years				
	Floor Drain	Toilet in Kitchen area	1	EA	7	10+ years				
	Lavatory	Toilet in Kitchen area	1	EA	7	10+ years				
	Lighting - Wall Mounted	Toilet in Kitchen area	1	EΑ	7	10+ years				
	Walls - Concrete Block	Toilet in Kitchen area	148	SF	7	10+ years				
	Water Closet	Toilet in Kitchen area	1	ĒΑ	7	10+ years				
Catego	ry : Classroom		В	uildina	: Additi	on 2				
	<b>,</b> 1 0.000.00		_			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Classroc	m #116 (Science Classroom)									
	Casework	1st Floor	48	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years				
	Doors - Side-lite	1st Floor	6	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	890	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years				
	Marker Board	1st Floor	16	LF	7	6-10 years				
	Storage/ Closet	1st Floor	244	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	858	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	299	SF	7	10+ years				
	Work Sink	1st Floor	2	EA	7	10+ years				
Classroo	m #118 (Regular Classroom)									
	Casework	1st Floor	48	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years				
	Doors - Side-lite	1st Floor	6	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	5	1-2 years	Door splitting from base, cracked			
		4 . <del>-</del> !		o-	_	4.0	wood			
	Floor - Tile	1st Floor	890	SF	7	10+ years				
	Lighting Lay-in	1st Floor	16	EA	7	10+ years				
	Marker Board	1st Floor	30	LF	7	6-10 years				
	Storage/ Closet	1st Floor	3	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	858	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	299	SF	7	10+ years				
Classroo	m #119 (Other Instructional Use)									
	Casework	1st Floor	40	LF	7	10+ years				

Campus Name: Murray Page : 31 of 38 Assessment Date: 02/05/2024



Catego	ry : Classroom		В	uilding	: Additi		NO NETWOOD AVENUE, Officago, IE 00010
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	555	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	555	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
_Classroo	om #120 (Regular Classroom)						
	Casework	1st Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	3	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	985	SF	7	10+ years	
Classro	om #121 (Regular Classroom)						
Classion	Casework	1st Floor	36	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	421	SF			
	Doors - Side-lite	1st Floor	6	SF SF	7 7	10+ years	
						10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA SF	7	10+ years	
	Floor - Tile	1st Floor	421		7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Storage/ Closet	1st Floor	3	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	791	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	264	SF	7	10+ years	
Classroo	om #211 (Regular Classroom)						
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	380	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	380	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	225	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	75	SF	7	10+ years	
	•					-	

Campus Name: Murray Page : 32 of 38 Assessment Date: 02/05/2024



Category : Classroom			Building : Addition 2						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank		Comments		
	Work Sink	2nd Floor	1	EA	7	10+ years			
_Classroo	om #213 (Regular Classroom)								
	Casework	2nd Floor	6	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	362	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Carpet	2nd Floor	362	SF	6	6-10 years			
	Lighting - Lay-in	2nd Floor	6	EΑ	7	6-10 years			
	Marker Board	2nd Floor	6	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	570	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	290	SF	7	10+ years			
Closses	om #216 (Regular Classroom)								
_Ciassio0		2nd Floor	760	SF	7	10 L Voors			
	Ceiling - Lay-in Doors - Side-lite	2nd Floor 2nd Floor	760 6	SF SF	7 7	10+ years 10+ years			
						•			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	760	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	886	SF	7	10+ years			
Classroo	om #218 (Regular Classroom)								
	Casework	2nd Floor	12	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	760	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	2nd Floor	760	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	14	ĒΑ	7	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	886	SF	7	10+ years			
						•			
_Classroo	om #219 (Regular Classroom)								
	Casework	2nd Floor	46	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	882	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Water damage		
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	890	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	788	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	263	SF	6	10+ years			

Campus Name: Murray Page: 33 of 38 Assessment Date: 02/05/2024



		Building : Addition 2						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroor	m #221 (Other Instructional Use)							
	Casework	2nd Floor	26	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	505	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	505	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years		
	Marker Board	2nd Floor	28	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	663	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	221	SF	7	10+ years		
Categor	ry : Interior		R	uildina	: Additio	on 2		
outogo.	y : intorio:			unung	. / taaiti	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor						•		
	Ceiling - Lay-in	1st Floor	2,612	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years		
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	6-10 years		
	Floor - Terrazzo	1st Floor	2,612	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	31	EA	7	10+ years		
	Lighting - Wall Mounted	1st Floor	4	EA	7	10+ years		
	Student Lockers - One Tier	1st Floor	7	EA	7	10+ years		
	Student Lockers - Two Tiers	1st Floor	75	EΑ	7	10+ years		
	Walls - Concrete Block	1st Floor	5,156	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	2,312	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	2,012	EA	7	10+ years		
	Drinking Fountains - Triple Water Cooler	2nd Floor	1	EA	7	10+ years		
	Floor - Terrazzo	2nd Floor	2,312	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years		
	Stairs - Terrazzo	2nd Floor	5	LF	7	10+ years		
	Student Lockers - One Tier	2nd Floor	6	EA	7	10+ years		
	Student Lockers - One Tiers	2nd Floor	64	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor	4,656	SF	7	•		
	Walls - Concrete block	2110 F1001	4,000	SF	,	10+ years		
Safety								
-	Security Cameras	1st Floor	7	EA	7	6-10 years		
Stairs								
	Ceiling - Plaster/Drywall	Stair 1	314	SF	7	10+ years		
	Floor - Terrazzo	Stair 1	314	SF	7	10+ years		
	Handrails	Stair 1	54	LF	7	10+ years		
	Lighting - Pendent/Surface	Stair 1	3	EA	7	6-10 years		

Campus Name: Murray Page : 34 of 38 Assessment Date: 02/05/2024



Catego	ry : Interior	Building : Addition 2							
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Stairs - Terrazzo	Stair 1	26	LF	7	10+ years			
	Walls - Concrete Block	Stair 1	970	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Stair 2	406	SF	7	10+ years			
	Floor - Terrazzo	Stair 2	406	SF	7	10+ years			
	Handrails	Stair 2	108	LF	7	10+ years			
	Lighting - Pendent/Surface	Stair 2	11	EΑ	7	6-10 years			
	Rescue Panel	Stair 2	1	EA	7	10+ years			
	Stairs - Terrazzo	Stair 2	52	LF	7	10+ years			
	Walls - Concrete Block	Stair 2	700	SF	7	10+ years			
_Vertical (	Conveyance								
	Elevator - Hydraulic Elevator	All floors	1	EA	7	10+ years			

Campus Name: Murray Page : 35 of 38 Assessment Date: 02/05/2024





Category : Site **Building: Site** 

	ry : Site			ullaing		_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic							
	Surface - Asphalt	West	9,400	SF	7	10+ years	
	-1		-,			, , , , ,	
ivil/Draii	nage						
	Civil/ Drainage - Catch Basin	Entire Site	11	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EΑ	7	10+ years	
	on a company of the c		•		-	, , , , , , , , , , , , , , , , , , , ,	
encing							
	Fencing - Chain Link	Entire Site	25	LF	5	2-5 years	
	Fencing - New Standard Ornamental	Entire Site	1,251	LF	6	10+ years	
andscap	De Benches	Entire Site	3	EA	7	10+ years	
	Landscape - Grass	Entire Site Entire Site	6,001	SF	6	10+ years 10+ years	
			•	SF	6		Domoved 5700 for turf field
	Landscape - Grass	Entire Site	16,863	SF SF	_	10+ years	Removed 5700 for turf field
	Landscape - Hardscape- Concrete	Entire Site	1,587	SF SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	200		6	10+ years	
	Lighting - Pole Mounted	Entire Site	1	EA	6	6-10 years	
	Parkway trees	Entire Site	12	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	2,410	SF	7	10+ years	
	Planting Beds/ Area	Entire Site	90	SF	4	1-2 years	Wood planters decaying
	Play Area - Synthetic Turf	Entire Site	5,700	SF	7	10+ years	
	Trash Receptacles	Entire Site	5	EA	7	10+ years	
Parking L	ot						
arking L	Concrete Curbs	Southeast Courtyard	563	LF	7	10+ years	
	Lighting - Pole Mounted	Southeast Courtyard	4	ĒΑ	7	10+ years	
	Surface - Asphalt	Southeast Courtyard	8,018	SF	6	6-10 years	
	Surface - Asphalt	Southeast Courtyard	2,000	SF	4	1-2 years	Potholes, alligatored surface, crack
	Trash Compactor	Southeast Courtyard	2,000	EA	7	10+ years	1 otiloles, alligatored surface, crac
	Trash Enclosure - Chain Links	Southeast Courtyard	=	SF			
			385		7	10+ years	
	Trash Enclosure - Masonry	Southeast Courtyard	300	SF	7	10+ years	
	Vehicular Screening	Southeast Courtyard	340	LF	7	10+ years	
laygrour	nd						
-, -	Equipment - Combo 3-12	West Courtyard	1	EA	7	10+ years	
	Surface - Poured Surface	West Courtyard	3,700	SF	7	10+ years	Verified dimension
Sidewalks	s						
····	Sidewalks - Internal Walks	Entire Site	580	LF	7	10+ years	
	Sidewaiks - Iliterriai Waiks	Little Oile				IUT VUAIS	

Campus Name: Murray Page : 36 of 38 Assessment Date: 02/05/2024



#### **Phillip Murray Elementary Language Academy**

5335 S Kenwood AVENUE, Chicago, IL 60615

Category : Site			В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
_Signage								
0 0	Flag Pole - Flag Pole	Southwest Courtyard	1	EA	7	10+ years		
	Marquee - Free Standing Back Lighted	Southwest Courtyard	1	EA	7	6-10 years		
	Monument - Building Mounted Cut Letter Sign	Southwest Courtyard	3	EA	7	10+ years		

#### **Definitions**

- · Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Murray Page : 37 of 38 Assessment Date: 02/05/2024

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

,				Floor Plan		Glazed	Operable			
			Room	Room	Area	Window	Window	Window	Smart-	
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board	
Building : Main										
Kindergarten	Kindergarten	1st Floor	104	104	1,182	150	75	N	Υ	
Kindergarten	Kindergarten	1st Floor	106	106	1,182	150	75	N	Υ	
Pre School	Kindergarten	1st Floor	108	108	1,182	150	75	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	103	103	747	176	88	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	105	105	747	176	88	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	107	107	747	176	88	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	201	201	747	176	88	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	202	202	764	120	60	N	Y	
Regular Classroom	Regular Classroom	2nd Floor	203	203	747	176	88	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	204	204	764	120	60	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	205	205	747	176	88	N	Y	
Regular Classroom	Regular Classroom	2nd Floor	206	206	764	120	60	N	Y	
Regular Classroom	Regular Classroom	2nd Floor	207	207	747	176	88	N	Y	
Regular Classroom	Regular Classroom	2nd Floor	208	208	764	120	60	N	Y	
Regular Classroom	Regular Classroom	2nd Floor	210	210	763	120	60	N	Υ	
D. T. P A L P. C										
Building : Addition 2	T A + D	14.5	140	440	000	440	0.5			
Other Instructional Use	Art Room	1st Floor	119	119	890	112	35	N	Y	
Other Instructional Use	Regular Classroom	2nd Floor	221	221	505	64	20	ı	Y	
Regular Classroom	Art Room	1st Floor	121	121	421	80	25	N	Y	
Regular Classroom	Computer Lab	2nd Floor	216	216	760	160	48	Υ	Υ	
Regular Classroom	Faculty Lounge	2nd Floor	211	211	380	64	20	Y	Υ	
Regular Classroom	Office	2nd Floor	213	213	362	64	20	Y	Υ	
Regular Classroom	Regular Classroom	1st Floor	118	118	890	140	42	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	120	120	890	140	42	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	218	218	760	160	48	Y	Υ	
Regular Classroom	Regular Classroom	2nd Floor	219	219	890	144	40	Υ	Υ	
Science Classroom	Science Classroom	1st Floor	116	116	890	140	42	N	Υ	