

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1937	2	44,944
Addition	1959	2	30,232
Campus Total			75,176

Catego	ory : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	1	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	1	1	EA	7	10+ years	
	Exterior Stairs - Concrete	1	64	LF	7	10+ years	
	Exterior Stairs - Concrete	1	6	LF	5	1-2 years	Cracked concrete landing
	Power Door Operator and Controls	1	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	1	66	LF	5	1-2 years	Corroding rails
	Ramps - Concrete	1	53	LF	7	10+ years	
	Ramps - Concrete	1	10	LF	5	1-2 years	Quoting rails are breaking the concrete
	Stair Handrail - Steel_Stair Handrail	1	30	LF	5	1-2 years	Corroding rails
	Exterior Doors - Exterior FRP Door	2	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	2	2	EA	4	0-1 year	Rotting delaminated fascia
	Exterior Stairs - Stone	2	154	LF	6	10+ years	
	Exterior Stairs - Stone	2	6	LF	5	1-2 years	Cracked, broken
	Stair Handrail - Steel_Stair Handrail	2	24	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	2.1 Basement	1	EA	6	10+ years	
	Exterior Stairs - Concrete	2.1 Basement	55	LF	6	10+ years	
	Exterior Stairs - Concrete	2.1 Basement	5	LF	4	0-1 year	Broken stair with exposed reinforcement
	Stair Handrail - Steel_Stair Handrail	2.1 Basement	80	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	6.1	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	6.1	2	EA	5	1-2 years	Worn paint, exposed wood surface,



J -	ory : Exterior		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							beginning to delaminate
	Exterior Stairs - Concrete	6.1	56	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	6.1	144	LF	5	1-2 years	Corroding, posts and rails
	Ramps - Concrete	6.1	49	LF	5	1-2 years	Cracks across retaining wall
	Ramps - Concrete	6.1	20	LF	4	1-2 years	Broken, cracked concrete due to
		-	-			,	corroding posts
	Stair Handrail - Steel_Stair Handrail	6.1	30	LF	5	1-2 years	Corroding
						2	J. J
Foundat	ion						
	Foundation - Concrete	Entire Building	675	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	44,940	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	4	SF	5	1-2 years	Broken concrete beam with exposed
		Entrie Banang		0.	Ū	i 2 youro	reinforcement
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	6-10 years	
	Extend Eighting - wai mounted	Entire Building	0	LA	0	0-10 years	
Roof Sys	stem						
	Access Ladder - Metal	А	2	EA	5	2-5 years	No access
	Coping - Stone	A	622	LF	6	10+ years	
	Downspouts - Interior Downspouts	A	111	LF	6	10+ years	
	Parapet - 16" - 30" Height	A	441	LF	7	10+ years	
	Parapet - Parapet > 30"	А	171	LF	6	10+ years	
	Parapet - Parapet > 30"	A	10	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	A	13,650	SF	5	0-1 year	Some blistering.
	Roof Hatch - Metal	Δ	2	EA	4	1-2 years	Corroded
	Roof Structure - Concrete	Δ	13,650	SF	7	10+ years	Confeded
	Coping - Stone	В	56	LF	7	10+ years	
	Parapet - 16" - 30" Height	B	56	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	В	384	SF	4		Distoring growing moon throughout
					-	0-1 year	Blistering, growing moss throughout
	Roof Structure - Concrete	В	384	SF	7	10+ years	
	Access Ladder - Metal	С	1	EA	5	2-5 years	Obsolete, old rungs
	Chimney - Brick Chimney- Concrete/ Mortar	C	50	LF	6	10+ years	
		•	10	. –	~		
	Chimney - Brick Chimney- Concrete/ Mortar	C	10	LF	3	1-2 years	Open joints, loose bricks, leaning
		6	101	. –	0	10	chimney
	Coping - Stone	С	164	LF	6	10+ years	
	Downspouts - Interior Downspouts	С	60	LF	5	2-5 years	Older drain covers
	Parapet - 16" - 30" Height	С	164	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	С	4,641	SF	5	0-1 year	Some blistering, older, in fair condition



	ry : Exterior		B	uilding	· Main		700 W WIIIOW STREET, Chicago, IL 6061
Calego	ry. Exterior		D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	nem - Type	Location	Quantity		Marik	Replacement	Comments
Valls							
	Cheek-Wall - Concrete	Entire Building	120	SF	7	10+ years	
	Cheek-Wall - Stone	Entire Building	60	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	17,519	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,000	SF	4	1-2 years	Open joints, cracked brick
	Exterior Walls - Stone-Cut	Entire Building	1,599	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	300	SF	5	10+ years	
Vindow							
<u>vindow</u> ,	Guard - Guards perforated	Entire Building	2,112	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	12	SF	7	10+ years	
	Lintels - Steel	Entire Building	501	LF	6	10+ years	
	Windows - Louver	Entire Building	48	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,888	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
J	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Automatic Transfer Switch	Entire Building	2	EA	6	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	7	EA	6	6-10 years	
	Stairs						
	Security System - Intrusion Detection	Entire Building	44,944	SF	5	2-5 years	
			11,011				
<u> /ain Se</u>	rvice						
/lain Se	Main Electrical Service - 2001 to 3000 A	Electrical Room	1	EA	7	10+ years	
<u>/lain Se</u>	Main Electrical Service - 2001 to 3000 A 120/208/3PH		1			-	
<u>Main Se</u>	Main Electrical Service - 2001 to 3000 A 120/208/3PH Independent Electrical Service for	Electrical Room Electrical Room	· · · · · ·	EA EA	7 6	10+ years 10+ years	
<u>∕lain Se</u>	Main Electrical Service - 2001 to 3000 A 120/208/3PH		1			-	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH Independent Electrical Service for emergency power PA System	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH Independent Electrical Service for emergency power PA System	Electrical Room Entire Building	1 2 44,944	EA SF	6 6	10+ years 6-10 years	MDE-1
	Main Electrical Service - 2001 to 3000 A 120/208/3PH Independent Electrical Service for emergency power PA System histribution Lighting and Power Panels - 100 A	Electrical Room Entire Building Entire Building	1 2 44,944 1	EA SF EA	6 6 7	10+ years 6-10 years 10+ years	MDF-1 P-PR-A
	Main Electrical Service - 2001 to 3000 A 120/208/3PH Independent Electrical Service for emergency power PA System Distribution Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Electrical Room Entire Building Entire Building Entire Building	1 2 44,944	EA SF EA EA	6 6 7 7	10+ years 6-10 years 10+ years 10+ years	P-PR-A
	Main Electrical Service - 2001 to 3000 A 120/208/3PH Independent Electrical Service for emergency power PA System Distribution Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building	1 2 44,944 1 1 1	EA SF EA EA EA	6 6 7 7 3	10+ years 6-10 years 10+ years 10+ years 0-1 year	P-PR-A EM fuse panel is live front
	Main Electrical Service - 2001 to 3000 A 120/208/3PH Independent Electrical Service for emergency power PA System <u>vistribution</u> Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 2 44,944 1 1 1 1	EA SF EA EA EA EA	6 6 7 7 3 7	10+ years 6-10 years 10+ years 10+ years 0-1 year 10+ years	P-PR-A EM fuse panel is live front P-PR
	Main Electrical Service - 2001 to 3000 A 120/208/3PH Independent Electrical Service for emergency power PA System Distribution Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building	1 2 44,944 1 1 1	EA SF EA EA EA	6 6 7 7 3	10+ years 6-10 years 10+ years 10+ years 0-1 year	P-PR-A EM fuse panel is live front P-PR
	Main Electrical Service - 2001 to 3000 A 120/208/3PH Independent Electrical Service for emergency power PA System <u>vistribution</u> Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 2 44,944 1 1 1 1	EA SF EA EA EA EA	6 6 7 7 3 7	10+ years 6-10 years 10+ years 10+ years 0-1 year 10+ years	P-PR-A EM fuse panel is live front P-PR A/C panel in basement mechanica



Calego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	3	0-1 year	LPB inmech room with auxiliary boile equipment Door latch is missing and is live front
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	CPDP-1 400A
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	10+ years	MDP 1200A
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	EDPN-1 100A
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar	m		-				
	Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	Not included in previous assessment
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Entire Building	44,944	SF	6	10+ years	
	Fire Alarm_System	Entire Building	44,944	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	Iling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm	Attic space above gym vestibule	1	EA	6	10+ years	AHU-5 serves East gymnasium
	Indoor- Steam Coils - Less than 4000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm	Attic space above gym vestibule	1	EA	6	10+ years	AHU-5 serves East gymnasium AHU-4 serves west gymnasium
	Indoor- Steam Coils - Less than 4000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm Air Intake	Attic space above gym vestibule Attic space above gym vestibule	1	EA EA	6 7	10+ years 10+ years	
	Indoor- Steam Coils - Less than 4000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm Air Intake Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Attic space above gym vestibule Attic space above gym vestibule Basement	1 2 1	EA EA EA	6 7 5	10+ years 10+ years 10+ years	
	Indoor- Steam Coils - Less than 4000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm Air Intake Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake	Attic space above gym vestibule Attic space above gym vestibule Basement Basement	1 2 1 1	EA EA EA EA	6 7 5 5	10+ years 10+ years 10+ years 2-5 years	AHU-4 serves west gymnasium
	Indoor- Steam Coils - Less than 4000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm Air Intake Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Attic space above gym vestibule Attic space above gym vestibule Basement	1 2 1	EA EA EA	6 7 5	10+ years 10+ years 10+ years	
	Indoor- Steam Coils - Less than 4000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm Air Intake Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake	Attic space above gym vestibule Attic space above gym vestibule Basement Basement	1 2 1 1	EA EA EA EA EA	6 7 5 5	10+ years 10+ years 10+ years 2-5 years	AHU-4 serves west gymnasium Fan motor is in fan room, and
	Indoor- Steam Coils - Less than 4000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm Air Intake Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts-	Attic space above gym vestibule Attic space above gym vestibule Basement Basement Basement	1 2 1 1 1	EA EA EA EA	6 7 5 5 6	10+ years 10+ years 10+ years 2-5 years 10+ years	AHU-4 serves west gymnasium Fan motor is in fan room, and
	Indoor- Steam Coils - Less than 4000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm Air Intake Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers	Attic space above gym vestibule Attic space above gym vestibule Basement Basement Basement Basement	1 2 1 1 1 6	EA EA EA EA EA	6 7 5 6 6	10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years	AHU-4 serves west gymnasium Fan motor is in fan room, and
Boiler Sy	Indoor- Steam Coils - Less than 4000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm Air Intake Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers	Attic space above gym vestibule Attic space above gym vestibule Basement Basement Basement Basement Basement	1 2 1 1 1 6 50	EA EA EA EA EA LF	6 75 5 6 5	10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years	AHU-4 serves west gymnasium Fan motor is in fan room, and airstream



Catego	ry : Mechanical		В	uilding	: Main		
j	, · · · · · · · · · · · · · · · · · · ·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.00p	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Condensate Pump	Boiler Room	2	EA	6	10+ years	Quantity updated to reflect observed
	·				-	-	conditions
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	10+ years	B-2
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	10+ years	B-1
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Steam Traps	Boiler Room	29	EA	5	6-10 years	
	Vacuum Pump	Boiler Room	2	EA	6	10+ years	
			-	_ /(Ū	ier yeare	
Gas Boo	ster Gas Booster	Mechanical Room	2	EA	6	6-10 years	
	Gas Dooster		2	LA	0	0-10 years	
Heating I	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	5	2-5 years	
	Radiators - Steam	Entire Building	6	EA	6	6-10 years	Vintage, behind covers
	Cabinet Heaters - With Steam Coil	Kitchen	1	EA	6	10+ years	-
Tempera	ture Control						
-	DDC System	Entire Building	44,944	SF	6	10+ years	Serves main building and addition
	Electric Thermostat	Entire Building	· 1	EA	6	6-10 years	Serves unit/cabinet heaters
	Thermostats - DDC	Entire Building	28	EA	6	10+ years	
Ventilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Mechanical room, kitchen	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Mechanical room, kitchen	2	EA	5	1-2 years	Noisy and vibrating
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Mechanical room, kitchen	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Mechanical room, kitchen	1	EA	5	10+ years	
	Type I Exhaust Hood- Kitchen	Mechanical room, kitchen	1	EA	2	0-1 year	No fire, suppression, does not cover entire work surface of range
Catego	ry : Plumbing		R	uilding	• Main		
Jacyo				unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	5L						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	Serves addition and kitchen.



Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	1	EA	5	2-5 years	Older boiler style water heater serves main building and addition.
	Domestic Piping-Hot Water Return Lines	Entire Building	44,944	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	44,944	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	44,944	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	44,944	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	44,944	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	44,944	SF	6	10+ years	
	Sanitary Piping	Entire Building	44,944	SF	6	10+ years	
	Storm Piping	Entire Building	44,944	SF	6	10+ years	
	Vent Piping	Entire Building	44,944	SF	6	10+ years	
Pumps							
	Pumps - Ejector-Duplex	Mechanical Room	2	EA	6	6-10 years	
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	6-10 years	Elevator pit pump not accessible at time of assessment

Category : Room

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	rative Suites/Offices		,				
	Ceiling - Plaster/Drywall	2nd Floor Teacher's Lounge	288	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Teacher's Lounge	2	EA	6	10+ years	
	Floor - Wood	2nd Floor Teacher's Lounge	288	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Teacher's Lounge	2	EA	7	6-10 years	
	Power Distribution	2nd Floor Teacher's Lounge	4	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor Teacher's Lounge	534	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Storage/Office next to 207	277	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Storage/Office next to 207	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	2nd Storage/Office next to 207	277	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Storage/Office next to 207	5	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Storage/Office next to 207	717	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Clinic-Office 2nd floor	224	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Clinic-Office 2nd floor	1	EA	6	10+ years	
	Floor - Wood	Clinic-Office 2nd floor	224	SF	6	10+ years	
	Lighting - Pendent/Surface	Clinic-Office 2nd floor	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	Clinic-Office 2nd floor	537	SF	6	10+ years	

Building : Main



Cotogo		Building : Main				700 W WIIIOW STREET, Chicago, IL 60614	
Catego	ory : Room		В	unaing	: wain	December	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Work Sink	Clinic-Office 2nd floor	Quantity 1	EA	7	10+ years	Comments
	Ceiling - Plaster/Drywall	Gym Office	43	SF	6	10+ years	
	Doors - Side-lite	Gym Office		SF			
	Doors - Wood Doors inclu hw	Gym Office	10		6	10+ years	
			1	EA SF	6	10+ years	
	Floor - Wood	Gym Office	43		6	10+ years	
	Lighting - Pendent/Surface	Gym Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Gym Office	81	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Office	63	SF	6	10+ years	
	Doors - Steel Doors incl hw	Kitchen Office	1	EA	6	6-10 years	
	Floor - Tile Quarry	Kitchen Office	63	SF	6	10+ years	
	Lighting - Pendent/Surface	Kitchen Office	1	EA	7	6-10 years	
	Power Distribution	Kitchen Office	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Kitchen Office	132	SF	6	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Main Office	403	SF	6	10+ years	
	Doors - Transom Window	Main Office	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	2	EA	6	10+ years	
	Floor - Wood	Main Office	403	SF	6	10+ years	
	Lighting - Lay-in	Main Office	6	EA	7	6-10 years	
	Storage/ Closet	Main Office	48	SF	5	10+ years	
	Walls - Plaster/Drywall	Main Office	749	SF	6	10+ years	
	Work SInk	Main Office	1	EA	7	10+ years	
	AC Unit	Principal's Office-128	1	EA	7	6-10 years	
	Ceiling - Lay-in	Principal's Office-128	250	SF	6	10+ years	
	Doors - Transom Window	Principal's Office-128	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office-128	2	EA	6	10+ years	
	Floor - Wood	Principal's Office-128	250	SF	6	10+ years	
	Lighting - Lay-in	Principal's Office-128	5	ĒA	7	6-10 years	
	Power Distribution	Principal's Office-128	4	EA	6	10+ years	
	Storage/ Closet	Principal's Office-128	40	SF	5	10+ years	
	Walls - Plaster/Drywall	Principal's Office-128	562	SF	6	10+ years	
	Walls Tlaster/Drywall		002	01	0	ior years	
Gymnas	ia						
	Ceiling - Plaster/Drywall	Gymnasium 115	2,629	SF	7	10+ years	
	Doors - Steel Doors incl hw	Gymnasium 115	2,020	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Gymnasium 115	4	EA	6	10+ years	
	Floor - Wood	Gymnasium 115	2,629	SF	6	10+ years	
	Lighting - Lay-in	Gymnasium 115	2,029	EA	7	10+ years	
	Lighting - Lay-in	Gymnasium 115	5	EA	4	1-2 years	Issues with switch
	Lighting - Pendent/Surface	Gymnasium 115	2	EA	7	10+ years	
	Storage/ Closet	Gymnasium 115	2 114	SF	7		
	Walls - Structural Glazed Tile	Gymnasium 115	6,058	SF	7	10+ years 10+ years	
	vvaiis - Structural Glazeu The	Gymnasium 115	0,058	эг	1	iu+ years	

Kitchen



Catego	ry : Room		В	uilding	: Main			
				3		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	1st Floor	638	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	4	ËA	6	10+ years		
	Floor - Tile Quarry	1st Floor	638	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years		
	Storage/ Closet	1st Floor	114	SF	5	10+ years		
	Walls - Plaster/Drywall	1st Floor	866	SF	6	10+ years		
	- -					-		
1DF_ID	E Doors - Steel Doors incl hw	2nd floor in Teacher's Lounge	1	EA	7	10+ years		
	Finishes	2nd floor in Teacher's Lounge	137	SF	5	10+ years	Water damage to wall and ceilings	
	Window AC Unit	2nd floor in Teacher's Lounge	1	EA	7	6-10 years		
lechani	cal/ Service Rooms							
lecham	Janitor's Closet	1st Floor	50	SF	5	10+ years		
	Janitor's Closet	1st Floor	50	SF	5	10+ years		
	Janitor's Closet	1st Floor	20	SF	5	10+ years		
	Storage Room	1st Floor	78	SF	5	10+ years	Water damage to the walls	
	Storage Room	1st Floor	75	SF	5	10+ years	Water damage to the walls	
	Janitor's Closet	2nd Floor	47	SF	5	10+ years		
	Air Tunnel	Basement	2,175	SF	7			
	Boiler Room	Basement	1,479	SF	7	10+ years		
				SF		10+ years		
	Crawl Space - Unfinished	Basement	4,500		7	10+ years		
	Mechanical/ Service Rooms	Basement	252	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	231	SF	7	10+ years		
	Storage Room	Basement	200	SF	7	10+ years		
	Storage Room	Basement	589	SF	7	10+ years		
estroor	n							
	Accessories	106A	38	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	106A	38	SF	7	10+ years		
	Doors - Wood Doors inclu hw	106A	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	106A	38	SF	7	10+ years		
	Lavatory	106A	1	EA	6	10+ years		
	Lighting - Pendent/Surface	106A	1	EA	7	10+ years		
	Walls - Plaster/Drywall	106A	34	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	106A	33	SF	7	10+ years		
	Water Closet	106A	1	EA	6	10+ years		
	Accessories	1st Floor	207	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	207	SF	7	10+ years		
	Doors - Transom Window	1st Floor	32	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	207	SF	7			
			-			10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Hand Dryer	1st Floor	2	EA	7	6-10 years		



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Lavatorv 1st Floor 2 ΕA 6 10+ vears Lighting - Pendent/Surface 1st Floor ΕA 6 4 10+ years Partitions 1st Floor 5 FΑ 7 10+ years Walls - Plaster/Drywall SF 1st Floor 100 6 10+ years SF 7 Walls - Structural Glazed Tile 1st Floor 483 10+ years 5 ΕA 7 Water Closet 1st Floor 10+ years Accessories 1st Floor 218 SF 7 6-10 years SF Ceiling - Plaster/Drywall 1st Floor 218 7 10+ years SF Doors - Transom Window 1st Floor 32 6 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 1st Floor 218 10+ years Floor Drain 1st Floor 1 ΕA 7 10+ vears Hand Dryer 1st Floor 2 EΑ 7 10+ years Lavatory 3 ΕA 6 10+ years 1st Floor 7 Lighting - Pendent/Surface ΕA 1st Floor 4 10+ years 2 Partitions ΕA 7 1st Floor 10+ years 4 FΑ 7 Urinals 1st Floor 10+ years Walls - Structural Glazed Tile 569 SF 7 1st Floor 10+ years Water Closet 1st Floor 2 EΑ 7 10+ years SF Accessories 2nd Floor 208 7 6-10 years SF Ceiling - Plaster/Drywall 2nd Floor 208 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 ΕA 6 10+ years SF 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor 208 7 ΕA Floor Drain 2nd Floor 1 10+ years 2 7 Hand Dryer 2nd Floor FΑ 6-10 years 2 ΕA 6 10+ years Lavatorv 2nd Floor Lighting - Pendent/Surface 2nd Floor 4 ΕA 7 6-10 years 5 ΕA Partitions 2nd Floor 7 10+ years Walls - Structural Glazed Tile 2nd Floor 561 SF 6 10+ years Water Closet ΕA 2nd Floor 4 6 10+ years Water Closet 2nd Floor 1 ΕA 4 1-2 years Out of order SF 7 Accessories 2nd Floor 222 6-10 years SF Ceiling - Plaster/Drvwall 2nd Floor 222 6 10+ vears Doors - Wood Doors inclu hw FΑ 2nd Floor 6 10+ years 1 Floor - Tile Ceramic/ Porcelain 2nd Floor 222 SF 6 10+ years Floor Drain 7 2nd Floor 1 EΑ 10+ years Hand Dryer 2 ΕA 7 2nd Floor 6-10 years Lavatory 2nd Floor 3 ΕA 6 10+ years Lighting - Pendent/Surface 4 7 6-10 years 2nd Floor ΕA Partitions 2nd Floor 2 ΕA 7 10+ years 2nd Floor ΕA Urinals 4 6 10+ vears SF Walls - Structural Glazed Tile 2nd Floor 574 6 10+ years 2nd Floor 2 FΑ 6 Water Closet 10+ vears Accessories 2nd Floor Unisex @ Teachers 70 SF 7 6-10 years Lounge



							700 W Willow STREET, Chicago, IL 60614
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor Unisex @ Teachers	70	SF	6	10+ years	
		Lounge					
	Doors - Wood Doors inclu hw	2nd Floor Unisex @ Teachers	1	EA	6	10+ years	
		Lounge					
	Floor - Tile Ceramic/ Porcelain	2nd Floor Unisex @ Teachers	70	SF	6	10+ years	
		Lounge					
	Lavatory	2nd Floor Unisex @ Teachers	1	EA	6	10+ years	
		Lounge					
	Lighting - Pendent/Surface	2nd Floor Unisex @ Teachers	1	EA	7	6-10 years	
		Lounge					
	Partitions	2nd Floor Unisex @ Teachers	1	EA	7	10+ years	
		Lounge					
	Walls - Plaster/Drywall	2nd Floor Unisex @ Teachers	70	SF	6	10+ years	
		Lounge					
	Walls - Structural Glazed Tile	2nd Floor Unisex @ Teachers	26	SF	7	10+ years	Updated to match current
		Lounge					observations
	Water Closet	2nd Floor Unisex @ Teachers	1	EA	6	10+ years	
		Lounge					
	Accessories	Kitchen Restroom/Locker	71	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Kitchen Restroom/Locker	71	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Restroom/Locker	2	EA	6	10+ years	
	Floor - Tile Quarry	Kitchen Restroom/Locker	71	SF	6	10+ years	
	Lavatory	Kitchen Restroom/Locker	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Kitchen Restroom/Locker	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Kitchen Restroom/Locker	1	EA	7	6-10 years	
	Partitions	Kitchen Restroom/Locker	1	EA	5	10+ years	
	Student Lockers - One Tier	Kitchen Restroom/Locker	5	EA	6	10+ years	
	Walls - Plaster/Drywall	Kitchen Restroom/Locker	144	SF	6	10+ years	
	Water Closet	Kitchen Restroom/Locker	1	EA	6	10+ years	
	Accessories	Principal's Restroom	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Restroom	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Principal's Restroom	26	SF	6	10+ years	
	Lavatory	Principal's Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Principal's Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Principal's Restroom	50	SF	6	10+ years	
	Water Closet	Principal's Restroom	1	EA	6	10+ years	
•			_				
Catego	ry : Classroom		В	uilding	: Main	_	

		Banang . Man
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments
Classroom #101 (Regular Classroom)		
AC Units	1st Floor	2 EA 7 6-10 years
Casework	1st Floor	8 LF 7 10+ years



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	693	SF	6	10+ years	
	Chalk Board	1st Floor	22	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	693	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	956	SF	7	10+ years	
_Classroo	m #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	681	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	681	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	947	SF	7	10+ years	
Classroc	m #103 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	686	SF	7	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	686	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	968	SF	7		
	Walls - Plastel/Drywall	IST FIOOI	900	55	1	10+ years	
_Classroo	m #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	688	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	688	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	4	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	952	SF	7	10+ years	
Classroo	m #105 (Regular Classroom)						



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	750	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	750	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,001	SF	7	10+ years	
Classroo	om #106 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	869	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Carpet	1st Floor	150	SF	6	6-10 years	
	Floor - Wood	1st Floor	719	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	20	EA	7	10+ years	
	Storage/ Closet	1st Floor	58	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,020	SF	6	10+ years	
Classroo	om #107 (Office)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	684	SF	7	10+ years	
	Chalk Board	1st Floor	34	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	10+ years	
	Floor - Wood	1st Floor	684	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	949	SF	7	10+ years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	692	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	692	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
			20		-	,	



<u> </u>	Schools						700 W Willow STREET, Chicago, IL 60614
Catego	ry : Classroom		B	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	955	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	686	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	686	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	951	SF	7	10+ years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	681	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	681	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	947	SF	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	- 8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	694	SF	6	10+ years	
	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	694	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	4	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	957	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	671	SF	6	10+ years	
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	4	10+ years	
		211011001	0	0F	I	IUT years	



Catego	ry : Classroom		B	uilding	: Main		
J	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	671	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	888	SF	6	10+ years	
lassroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	686	SF	6	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	686	SF	4	0-1 year	Seal worn, wood discolored
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	951	SF	6	10+ years	
lassroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	671	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	671	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	888	SF	6	10+ years	
lassroc	m #205 (Faculty Lounge)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	686	SF	6	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	686	SF	4	0-1 year	Flooring worn.
	Lighting - Lay-in	2nd Floor	12	ĒA	7	6-10 years	5
	Walls - Plaster/Drywall	2nd Floor	951	SF	6	10+ years	
lassroc	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	671	SF	6	10+ years	



Group II (E E E E Classroom (C C C E E E E E E	y : Classroom			ununu	: Main		
Classroom Classroom Classroom Classroom C C C C C C C C C C C C C C C C C C						Recommend	
Classroom Classroom Classroom Classroom C C C C C C C C C C C C C C C C C C	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Elassroom (C) C) C) C) C) C) C) C) C) C) C) C) C) C	Chalk Board	2nd Floor	8	LF	4	2-5 years	
F L N V Lassroom C C C C C C C L L	Doors - Transom Window	2nd Floor	7	SF	7	10+ years	
L M V assroom A C C C C C F L L	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
M V Assroom C C C C C C C C C C C C C C C C C C	Floor - Wood	2nd Floor	671	SF	4	0-1 year	Seal worn, woodmdiscolored
N Assroom C C C C C C C C C C C C C C C C C C	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
assroom (((([F L	Marker Board	2nd Floor	20	LF	7	6-10 years	
4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Walls - Plaster/Drywall	2nd Floor	888	SF	6	10+ years	
((([[F L	n #207 (Regular Classroom)						
(([[F L	AC Units	2nd Floor	2	EA	7	6-10 years	
C C C F L	Casework	2nd Floor	8	LF	6	10+ years	
C C F L	Ceiling - Lay-in	2nd Floor	684	SF	6	10+ years	
[[F L	Chalk Board	2nd Floor	30	LF	4	2-5 years	
F	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
L	Doors - Wood Doors inclu hw	2nd Floor	1	EA	5	0-1 year	Loose hardware
L	Floor - Wood	2nd Floor	684	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	949	SF	6	10+ years	
assroom	n #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	690	SF	6	10+ years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	690	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
Ň	Walls - Plaster/Drywall	2nd Floor	954	SF	6	10+ years	
lassroom	n #209 (Regular Classroom)						
ł	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
(Ceiling - Lay-in	2nd Floor	686	SF	6	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
ſ	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
]	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Wood	2nd Floor	686	SF	4	0-1 year	Seal worn, floorboards getting discolored
I			10	EA	6	6-10 years	
	Lighting - Lav-in	2nd Floor			n		
V	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	12 8		6 7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #210 (Regular Classroom)					-	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	671	SF	6	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	, 1	EA	6	10+ years	
	Floor - Wood	2nd Floor	671	SF	4	0-1 year	Seal worn
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	Searwonn
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	859	SF	6	10+ years	
	Walls - Flastel/Drywall		009	36	0	TOT years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	44	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	689	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Wood	2nd Floor	689	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	953	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
•	• / •		_			,	
Catego	ry : Interior		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,016	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	5	6-10 years	
	Floor - Tile/Sheet	1st Floor	3,016	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	157	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,099	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,099	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,998	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2,000	SF	4	1-2 years	Cracking
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	5	1-2 years	Rusting through
	Floor - Tile/Sheet	2nd Floor	2,756	SF	7	10+ years	i taoting tinough
	Floor - Tile/Sheet	2nd Floor	2,750	SF	4	1-2 years	Cracking and chipping tile
			200	5.	•	;0010	



Catego	ry : Interior		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	50	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	112	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,830	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,830	SF	6	10+ years	
afety							
	Camera Viewing Station	Main Building	2	EA	7	6-10 years	
tairs							
	Ceiling - Lay-in	South (Stair 1)	214	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South (Stair 1)	128	SF	6	10+ years	
	Floor - Terrazzo	South (Stair 1)	130	SF	6	10+ years	
	Floor - Tile	South (Stair 1)	244	SF	6	10+ years	
	Handrails	South (Stair 1)	56	LF	7	10+ years	
	Lighting - Lay-in	South (Stair 1)	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	South (Stair 1)	3	EA	7	6-10 years	
	Stairs - Terrazzo	South (Stair 1)	106	LF	6	10+ years	
	Walls - Plaster/Drywall	South (Stair 1)	556	SF	6	10+ years	
	Walls - Structural Glazed Tile	South (Stair 1)	556	SF	7	10+ years	
	Ceiling - Lay-in	West (Stair 6)	422	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West (Stair 6)	326	SF	6	10+ years	
	Floor - Terrazzo	West (Stair 6)	148	SF	6	10+ years	
	Floor - Tile	West (Stair 6)	497	SF	6	10+ years	
	Handrails	West (Stair 6)	62	LF	7	10+ years	
	Lighting - Lay-in	West (Stair 6)	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	West (Stair 6)	5	EA	7	6-10 years	
	Stairs - Terrazzo	West (Stair 6)	118	LF	6	10+ years	
	Stairs - Terrazzo	West (Stair 6)	10	LF	4	1-2 years	Cracking step
	Walls - Plaster/Drywall	West (Stair 6)	555	SF	6	10+ years	
	Walls - Structural Glazed Tile	West (Stair 6)	555	SF	6	10+ years	
ertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	



Category : Exterior			В	uilding	: Additi	on	
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	3	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	3	4	EA	7	10+ years	
	Exterior Stairs - Concrete	3	128	LF	6	10+ years	
	Exterior Stairs - Concrete	3	12	LF	5	1-2 years	Cracked concrete steps
	Exterior Stairs - Stone	3	13	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	3	18	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	3.1	1	EA	6	10+ years	
	Exterior Stairs - Stone	3.1	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	3.2 - Yard Storage E & W	4	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	3.3 elevator machine room	1	EA	6	10+ years	
	Entrance Control - Audio and Video	4	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	4	2	EA	7	10+ years	
	Exterior Stairs - Concrete	4	51	LF	6	10+ years	
	Exterior Stairs - Concrete	4	5	LF	4	0-1 year	Cracked, broken, displaced
	Ramp Handrail - Steel_Ramp Handrail	4	132	LF	6	6-10 years	
	Ramps - Concrete	4	66	LF	5	1-2 years	Several cracks
	Stair Handrail - Steel_Stair Handrail	4	30	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	5	2	EA	6	10+ years	
	Exterior Stairs - Concrete	5	10	LF	7	10+ years	Repaired- new
	Exterior Stairs - Concrete	5	50	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	5	10	LF	6	6-10 years	
Foundati	on						
ounduu	Foundation - Concrete	Entire Building	445	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	30,232	SF	7	10+ years	
	Superstructure Scherete	Entre Banang	00,202	01	'	Tor years	
ighting							
2 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	7	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	6-10 years	
Roof Sys	stem						
	Access Ladder - Metal	D	2	EA	5	2-5 years	
	Coping - Stone	D	425	LF	7	10+ years	
	Downspouts - Interior Downspouts	D	90	LF	6	6-10 years	
	Parapet - 16" - 30" Height	D	425	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	D	12,317	SF	5	0-1 year	Some blistering, older, in fair
		-	12,011	0.	5	e . you	condition
	Roof Hatch - Metal	D	2	EA	4	1-2 years	Corroded hatch
	Roof Structure - Concrete	D	12.317	SF	7	10+ years	
	Coping - Stone	E - Lower North	21	LF	7	10+ years	
	Downspouts - Exterior Downspouts	E - Lower North	10	LF	6	10+ years	
			10		0	io+ years	



Catego	ry : Exterior		B	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	E - Lower North	21	LF	7	10+ years	
	Roof - EPDM/ Synthetic Rubber	E - Lower North	110	SF	5	0-1 year	Bubbling.
	Roof Structure - Concrete	E - Lower North	110	SF	7	10+ years	ů.
	Coping - Stone	Roof F	6	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof F	12	LF	4	0-1 year	Detached
	Parapet - Parapet < 16" Height	Roof F	8	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Roof F	60	SF	5	0-1 year	Blistering
	Roof Structure - Steel / Metal Deck/	Roof F	60	SF	7	10+ years	5
	Concrete Topping						
Valls							
	Cheek-Wall - Stone	Entire Building	120	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	7,856	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	3,000	SF	5	10+ years	Deteriorated mortar
	Exterior Walls - Brick	Entire Building	500	SF	4	1-2 years	Open joints, cracked and crumblin wall
	Exterior Walls - Stone-Cut	Entire Building	400	SF	7	10+ years	Wall
Vindows	3						
	Guard - Guards perforated	Entire Building	1,262	SF	6	6-10 years	
	Lintels - Steel	Entire Building	331	LF	6	6-10 years	
	Skylite - Lexan	Entire Building	240	SF	5	0-1 year	Cracked plexiglass
	Windows - Louver	Entire Building	6	SF	6	10+ years	1 0
	Windows - Sash Aluminum Double-pane	Entire Building	2,344	SF	6	10+ years	
	Windows - Wood- Single-pane	Entire Building	24	SF	4	0-1 year	Old wood window
atego	ry : Electrical		В	uilding	: Additi	on	
U						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System	Entire Duilding		EA	0	0.40	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	3	EA	4	1-2 years	Older units.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	9	EA	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	5	EA	6	6-10 years	
		Entire Building	11	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs						



Catego	ry : Electrical		В	uilding	: Additie	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	PA System	Entire Building	30,232	SF	6	6-10 years	Served by main
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	L-BNE P-FR-A Quantity updated to reflect observed conditions
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	EM fuse panel outside of room 112 live front
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	P-PF AC-P-2
	Lighting and Power Panels - Above 100 A	Entire Building	- 1	EA	6	6-10 years	Unlabeled panel outside of room 11
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Panel outside of room 214 is live fro
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uildina	: Additie	on	
outogo				anang	. / taanti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	30,232	SF	6	10+ years	
	Fire Alarm_System	Entire Building	30,232	SF	6	10+ years	
Catego			в	uilding	· Additi	on	
Catego	ry : Mechanical		В	uilding	: Additie		
Catego Group	ry : Mechanical	Location	B Quantity	uilding UOM	: Additio Rank	Recommend	Comments
Group	ry : Mechanical Item - Type	Location					Comments
Group	ry : Mechanical Item - Type Iling Systems		Quantity	UOM	Rank	Recommend Replacement	
Group	ry : Mechanical Item - Type	Location Basement				Recommend	
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM		Quantity	UOM EA	Rank	Recommend Replacement 1-2 years	Fan is non-functional, motor starts l trips, electrical motor control
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline -	Basement	Quantity 1	UOM	Rank	Recommend Replacement	Fan is non-functional, motor starts l trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Basement Basement - AHU-2	Quantity 1 1	UOM EA EA	Rank 5 5	Recommend Replacement 1-2 years 10+ years	Fan is non-functional, motor starts to trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and at condensate pump
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake	Basement Basement - AHU-2 Basement - AHU-2	Quantity 1 1	UOM EA EA EA	Rank 5 5 5	Recommend Replacement 1-2 years 10+ years 1-2 years	Fan is non-functional, motor starts b trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm	Basement Basement - AHU-2 Basement - AHU-2 Basement - AHU-2	Quantity 1 1 1 1	UOM EA EA EA EA	Rank 5 5 5 5 5 5 5 5	Recommend Replacement 1-2 years 10+ years 1-2 years 10+ years	Fan is non-functional, motor starts l trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and at condensate pump
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Steam Coil	Basement Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2	Quantity 1 1 1 1 1 4	UOM EA EA EA EA EA EA	Rank 5 5 5 5 6	Recommend Replacement 1-2 years 10+ years 1-2 years 10+ years 10+ years	Fan is non-functional, motor starts t trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and at condensate pump
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Steam	Basement Basement - AHU-2 Basement - AHU-2 Basement - AHU-2	Quantity 1 1 1 1	UOM EA EA EA EA	Rank 5 5 5 5 5 5 5 5	Recommend Replacement 1-2 years 10+ years 1-2 years 10+ years	Fan is non-functional, motor starts t trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and at condensate pump
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Indoor- Vertical Shaft	Basement Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2	Quantity 1 1 1 1 1 4	UOM EA EA EA EA EA EA	Rank 5 5 5 5 6	Recommend Replacement 1-2 years 10+ years 1-2 years 10+ years 10+ years	Fan is non-functional, motor starts to trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and at condensate pump Rusted and corroded
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2	Quantity 1 1 1 1 4 50	UOM EA EA EA EA EA LF	Rank 5 5 5 5 6 5 5	Recommend Replacement 1-2 years 10+ years 10+ years 10+ years 10+ years 10+ years	Fan is non-functional, motor starts I trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and at condensate pump Rusted and corroded Zone dampers are not visually accessible in reheat boxes Serves auditorium, unit is starting to show age, corrosion at base of unit
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers Air Handling Unit- Package Single Zone-	Basement Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2	Quantity 1 1 1 1 4 50 16	UOM EA EA EA EA EA LF EA	Rank 5 5 5 6 5 6	Recommend Replacement 1-2 years 10+ years 1-2 years 10+ years 10+ years 10+ years 10+ years	Fan is non-functional, motor starts I trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and at condensate pump Rusted and corroded Zone dampers are not visually accessible in reheat boxes Serves auditorium, unit is starting to
Group	ry : Mechanical Item - Type Iling Systems Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 12001-20000 cfm Air Intake	Basement Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2 Basement - AHU-2	Quantity 1 1 1 1 1 4 50 16 1	UOM EA EA EA EA LF EA EA	Rank 5 5 5 6 5 6 4	Recommend Replacement 1-2 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Fan is non-functional, motor starts I trips, electrical motor control AHU-2 serves addition. Steam/condensate leak in AHU and at condensate pump Rusted and corroded Zone dampers are not visually accessible in reheat boxes Serves auditorium, unit is starting to show age, corrosion at base of unit



Catego	ry : Mechanical		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Condensate Pump	Basement	1	EA	4	0-1 year	Corroded and leaking at pump seal.
	Piping - Condensate Pipe- Steel	Basement	470	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Basement	470	LF	6	10+ years	
	Steam Traps	Basement	22	EA	5	2-5 years	
	Vacuum Pump	Basement	2	EA	6	6-10 years	
eating	Devices						
•	Unit Heater - Electric	Elevator room	1	EA	5	1-2 years	Spider webs all over unit.
	Fin Tube - Steam	Entire Building	48	LF	5	10+ years	Counselors office on first floor
	Cabinet Heaters - With Steam Coil	Entire Building	6	EA	5	10+ years	Quantity updated to reflect observed conditions
empera	ature Control						
	DDC System	Entire Building	30,232	SF	5	6-10 years	Served by main building, BAS
	Electric Thermostat	Entire Building	3	EA	6	10+ years	
	Thermostats - DDC	Entire Building	17	EA	6	6-10 years	
ntilati	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	6-10 years	Serves elevator equipment room No included in previous assessment No accessible at time of assessment
	Exhaust Fans- Roof Mounted - Greater than	Roof	1	EA	6	6-10 years	

Catego	Category : Plumbing			uilding	: Additie	on	
Group Piping	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
грид	Domestic Piping-Hot Water Return Lines	Entire Building	30,232	SF	6	6-10 years	Domestic water pipe not visually accessible in addition
	Domestic Piping-Hot Water Return Risers	Entire Building	30,232	SF	6	6-10 years	Domestic water pipe not visually accessible in addition
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	30,232	SF	6	10+ years	Domestic water pipe not visually accessible in addition
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	30,232	SF	6	10+ years	Domestic water pipe not visually accessible in addition
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	30,232	SF	6	10+ years	Domestic water pipe not visually accessible in addition
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	30,232	SF	6	6-10 years	Domestic water pipe not visually accessible in addition
	Sanitary Piping	Entire Building	30,232	SF	6	10+ years	



Catego	ory : Plumbing		B	uildina	: Additi	on	700 W WINOW OTTEET, Officago, in 00014
ealege	, y i i iainaing		_	anang	.,	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.000	Storm Piping	Entire Building	30,232	SF	6	10+ years	
	Vent Piping	Entire Building	30,232	SF	6	10+ years	
	· · · · · · · · · · · · · · · · · · ·		00,202	•	Ū.	let yeare	
Catego	ory : Room		В	uildina	: Additi		
Ŭ				Ū		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	216 - Adjustment Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	216 - Adjustment Room	324	SF	6	10+ years	
	Doors - Wood Doors inclu hw	216 - Adjustment Room	1	EA	6	10+ years	
	Floor - Tile	216 - Adjustment Room	320	SF	6	10+ years	
	Floor - Tile	216 - Adjustment Room	4	SF	4	1-2 years	Broken tiles
	Lighting - Pendent/Surface	216 - Adjustment Room	8	EA	7	6-10 years	Dieken lies
	Power Distribution	216 - Adjustment Room	4	EA	6	10+ years	
	Walls - Concrete Block	216 - Adjustment Room	633	SF	6	10+ years	
	Work SInk	216 - Adjustment Room	1	EA	7	10+ years	
	AC Unit	Counselor office 114B	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Counselor office 114B	307	SF	7	•	
	Doors - Wood Doors inclu hw	Counselor office 114B		EA	6	10+ years	
			1	SF		6-10 years	
	Floor - Tile	Counselor office 114B	297	SF	6	10+ years	Chinned
	Floor - Tile	Counselor office 114B	10		4	0-1 year	Chipped
	Lighting - Pendent/Surface	Counselor office 114B	2	EA	7	10+ years	
	Walls - Concrete Block	Counselor office 114B	619	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office	243	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	243	SF	4	0-1 year	Damaged throughout
	Lighting - Pendent/Surface	Engineer's Office	4	EA	7	10+ years	
	Storage/ Closet	Engineer's Office	23	SF	7	10+ years	
	Walls - Concrete Block	Engineer's Office	277	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	277	SF	6	10+ years	
Auditori	um & Theater						
	Ceiling - Plaster/Drywall	113	3,130	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113	5,150	EA	6	10+ years	
	Floor - Concrete	113	2,275	SF	7	10+ years	
	Floor - Tile	113	855	SF	7	10+ years	
	Lighting - Lay-in	113	48	EA	7	10+ years	
	Lighting - Wall Mounted	113	48	EA	7	10+ years	
	Main Floor Seating	113	377	EA	7	10+ years	
	Stage	113	367	SF	6	10+ years	
	Stage Curtain	113	307 5	EA	6 7	10+ years	
	Stage Lighting System	113	5 1	EA	7	10+ years 10+ years	
				LF		•	
	Stage-Stairs - Asphalt	113	42		6	10+ years	
	Storage/ Closet	113	57	SF	7	10+ years	



Catego	ry : Room		В				
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	113	4,430	SF	7	10+ years	
Library							
	AC Unit	213	2	EA	7	6-10 years	
	Casework	213	78	LF	6	10+ years	
	Ceiling - Plaster/Drywall	213	1,112	SF	6	10+ years	
	Ceiling - Plaster/Drywall	213	10	SF	4	0-1 year	Water damage near light fixture
	Doors - Wood Doors inclu hw	213	2	EA	6	10+ years	
	Floor - Carpet	213	1,117	SF	6	6-10 years	
	Floor - Carpet	213	5	SF	4	1-2 years	Carpet tearing up
	Lighting - Pendent/Surface	213	25	EA	7	6-10 years	
	Storage/ Closet	213	8	SF	7	10+ years	
	Walls - Concrete Block	213	1,237	SF	7	10+ years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	48	SF	5	10+ years	
	Storage Room	1st Floor	20	SF	7	10+ years	
	Storage Room	1st Floor	100	SF	7	10+ years	
	Janitor's Closet	2nd Floor	48	SF	5	10+ years	
	Storage Room	2nd Floor	108	SF	5	10+ years	
	Air Tunnel	Basement	1,493	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	265	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	203 960	SF	4	0-1 year	water damage
	Mechanical/ Service Rooms	Basement	900 467	SF	4		
	Mechanical/ Service Rooms	Basement	407	ЪГ	4	0-1 year	Water damage.
Restroor	n						
	Accessories	114B	41	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	114B	41	SF	6	10+ years	
	Doors - Wood Doors inclu hw	114B	1	EA	6	10+ years	
	Floor - Tile	114B	41	SF	6	10+ years	
	Lavatory	114B	1	EA	6	10+ years	
	Lighting - Pendent/Surface	114B	1	EA	6	10+ years	
	Lighting - Pendent/Surface	114B	1	EA	5	0-1 year	Does not work.
	Partitions	114B	1	EA	7	10+ years	
	Walls - Concrete Block	114B	83	SF	7	10+ years	
	Water Closet	114B	1	EA	6	10+ years	
	Accessories	116A	29	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	116A	29	SF	7	10+ years	
	Doors - Wood Doors inclu hw	116A	1	EA	6	10+ years	
	Floor - Tile	116A	29	SF	7	10+ years	
	Lighting - Pendent/Surface	116A	25	EA	6	10+ years	
	Walls - Concrete Block	116A	51	SF	7	10+ years	
	Walls - Concrete Block Water Closet	116A	1	EA	6	-	
	Waler Cluser	IIOA	1	EA	O	10+ years	



Cotogo	ry : Room		D	uilding	: Additi	00	700 W WIIIOW STREET, Chicago, IL 60614
Calego	IY. ROOM		DI	unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Accessories	1st Floor North	274	SF	7	6-10 years	Comments
	Ceiling - Plaster/Drywall	1st Floor North	274	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor North	274	SF	7	10+ years	
	Floor Drain	1st Floor North	1	EA	7	10+ years	
	Hand Dryer	1st Floor North	2	EA	7	10+ years	
	Lavatory	1st Floor North	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor North	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor North	2	EA	5	0-1 year	Missing covers
	Partitions	1st Floor North	5	EA	7	10+ years	
	Walls - Concrete Block	1st Floor North	160	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor North	481	SF	7	10+ years	
	Water Closet	1st Floor North	5	EA	6	10+ years	
	Accessories	2nd Floor North	240	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor North	240	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor North	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor North	240	SF	6	10+ years	
	Floor Drain	2nd Floor North	1	EA	4	1-2 years	Drain cover damaged
	Hand Dryer	2nd Floor North	2	EA	7	6-10 years	Drain cover damaged
	Lavatory	2nd Floor North	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor North	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor North	2	EA	7	6-10 years	
	Partitions	2nd Floor North	1	EA	7	10+ years	
	Urinals	2nd Floor North	1	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor North	154	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor North	465	SF	7	10+ years	
	Water Closet	2nd Floor North	-00	EA	6	10+ years	
	Accessories	Auditorium Men's	100	SF	7	10+ years	Deficiency fixed
	Ceiling - Plaster/Drywall	Auditorium Men's	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Auditorium Men's	100	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Auditorium Men's	100	SF	7	10+ years	
	Lavatory	Auditorium Men's	100	EA	7	10+ years	
	Lighting - Lay-in	Auditorium Men's	1	EA	7	10+ years	
	Lighting - Wall Mounted	Auditorium Men's	1	EA	7	10+ years	
	Lighting - Wall Mounted	Auditorium Men's	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Auditorium Men's	245	SF	6	10+ years	
	Water Closet	Auditorium Men's	1	EA	7	10+ years	
	Accessories	Auditorium Women's	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Auditorium Women's	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Auditorium Women's	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Auditorium Women's	70	SF	7	10+ years	
	Lavatory	Auditorium Women's	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Auditorium Women's	2	EA	7	10+ years	
	Lighting - Wall Mounted	Auditorium Women's	2	EA	7	6-10 years	
	Partitions	Auditorium Women's	2	EA	7	10+ years	
			2		1	IUT years	



Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Auditorium Women's	146	SF	7	10+ years	
	Water Closet	Auditorium Women's	2	EA	6	10+ years	
	Accessories	Basement	57	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	57	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Concrete	Basement	57	SF	7	10+ years	
	Lavatory	Basement	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Basement	1	EA	7	6-10 years	
	Walls - Concrete Block	Basement	60	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	60	SF	7	10+ years	
	Water Closet	Basement	1	EA	6	10+ years	
	Accessories	Engineer's Toilet	46	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Toilet	46	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Toilet	1	EA	6	10+ years	
	Floor - Tile	Engineer's Toilet	46	SF	6	10+ years	
	Lavatory	Engineer's Toilet	1	EA	6	10+ years	
	Lighting - Lay-in	Engineer's Toilet	1	EA	5	6-10 years	
	Lighting - Wall Mounted	Engineer's Toilet	1	EA	6	6-10 years	
	Walls - Concrete Block	Engineer's Toilet	48	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Toilet	48	SF	7	10+ years	
	Water Closet	Engineer's Toilet	1	EA	6	10+ years	
Catego	Category : Classroom		В	uilding			
_				_	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #112 (Music Room)						
	AC Units	1st Floor	1	EA	7	6-10 vears	

AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	17	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	714	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	690	SF	7	10+ years	
Floor - Tile	1st Floor	24	SF	4	1-2 years	Chipped tiles
Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
Marker Board	1st Floor	6	LF	7	6-10 years	
Walls - Concrete Block	1st Floor	915	SF	7	10+ years	
Work Sink	1st Floor	1	EA	5	6-10 years	
om #114 (Other Instructional Use)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	17	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	726	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	726	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	on		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	924	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
lassroo	m #116 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	65	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,029	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒA	6	10+ years	
	Floor - Tile	1st Floor	1,029	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	ĒA	7	10+ years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,065	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
lassroo	m #117 (Regular Classroom)						
1000100	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	17	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	741	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	737	SF	7	10+ years	
	Floor - Tile	1st Floor	4	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	1st Floor	12	ĒA	7	10+ years	
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	935	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	17	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	728	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	718	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Chipping and broken throughout
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	926	SF	7	10+ years	
lassroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	17	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	731	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	



-	Schools						700 W Willow STREET, Chicago, IL 606
Catego	ry : Classroom		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	700	SF	6	10+ years	
	Floor - Tile	2nd Floor	31	SF	4	1-2 years	Tiles separating
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	928	SF	7	10+ years	
lassroo	om #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	5	0-1 year	Counter peeling
	Ceiling - Plaster/Drywall	2nd Floor	741	SF	6	10+ years	oodinter peeling
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	EA	4 6	10+ years	
	Floor - Tile	2nd Floor		SF	6		
			741		-	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Concrete Block Work Sink	2nd Floor 2nd Floor	935 1	SF EA	7 7	10+ years 10+ years	
lassroo	m #218 (Science Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	60	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,008	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,000	SF	6	10+ years	
	Floor - Tile	2nd Floor	8	SF	4	1-2 years	Missing tile edge around cabinetry
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor 2nd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor 2nd Floor	-	SF	7	•	
	Work Sink	2nd Floor	1,029 2	EA	7	10+ years 10+ years	
atego	ry : Interior		В	uildina	: Additi	on	
	· · · · · · · · · · · · · · · · · · ·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	2,287	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	12	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	6	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	5	1-2 years	Out of order
	Floor - Terrazzo	1st Floor	549	SF	7	10+ years	
		1 ot Floor	4 700		·	10+ years	

Floor - Tile/Sheet

Lighting - Pendent/Surface

SF

EΑ

5

7

1,738

23

10+ years

10+ years

1st Floor

1st Floor



Catego	ry : Interior		В	uilding	: Additi	on	
	-					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	1st Floor	101	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	535	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,604	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,640	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	18	SF	5	1-2 years	Water damage, cracking plaster
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,652	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	6	SF	4	0-1 year	Cracking tiles
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	65	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	596	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,788	SF	7	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	North (Stair 4)	262	SF	6	10+ years	
	Floor - Terrazzo	North (Stair 4)	277	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North (Stair 4)	62	SF	6	10+ years	
	Handrails	North (Stair 4)	48	LF	7	10+ years	
	Lighting - Pendent/Surface	North (Stair 4)	6	EA	6	6-10 years	
	Stairs - Terrazzo	North (Stair 4)	95	LF	6	10+ years	
	Walls - Concrete Block	North (Stair 4)	581	SF	7	10+ years	
	Walls - Structural Glazed Tile	North (Stair 4)	743	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South (Stair 5)	385	SF	6	10+ years	
	Floor - Terrazzo	South (Stair 5)	261	SF	6	10+ years	
	Floor - Tile	South (Stair 5)	70	SF	6	10+ years	
	Handrails	South (Stair 5)	48	LF	7	10+ years	
	Lighting - Pendent/Surface	South (Stair 5)	9	EA	6	6-10 years	
	Stairs - Terrazzo	South (Stair 5)	95	LF	6	10+ years	
	Walls - Concrete Block	South (Stair 5)	380	SF	7	10+ years	
	Walls - Structural Glazed Tile	South (Stair 5)	440	SF	7	10+ years	



Catego	ry : Site		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	7	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	2	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	7	10+ years	
Fencing							
0	Fencing - New Standard Ornamental	Entire Site	1,163	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	4	0-1 year	Bent
andsca	ne l						
	Benches	Entire Site	3	EA	7	10+ years	
	Benches	Entire Site	1	EA	5	1-2 years	Missing seats
	Landscape - Grass	Entire Site	9,384	SF	6	10+ years	Wildonig Coald
	Landscape - Hardscape- Asphalt	Entire Site	15,700	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	100	SF	4	0-1 year	Upheaved, cracked. Replaced 700 s
	Lanuscape - Haruscape Asphan	Linure Site	100	51	4	0-1 year	balance to rating #6, for several cracks that need repair near door 6.
	Landscape - Hardscape- Pavers	Entire Site	50	SF	6	10+ years	·
	Landscape - Mulch	Entire Site	300	SF	6	6-10 years	
	Parkway trees	Entire Site	28	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	1,538	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	9,234	SF	7	10+ years	
	Trash Receptacles	Entire Site	4	EA	6	10+ years	
Parking I	ot						
	Concrete Curbs	Site - North	286	LF	7	10+ years	
	Interior Plantings	Site - North	4	LF	7	10+ years	
	Surface - Asphalt	Site - North	10.020	SF	6	6-10 years	Verified areas in fair condition
	Surface - Asphalt	Site - North	2,500	SF	4	0-1 year	Alligator gets surface, disintegrating surface
	Trash Compactor	Site - North	1	EA	7	10+ years	
	Trash Enclosure - Chain Links	Site - North	20	SF	6	6-10 years	Verified in fair condition
	Trash Enclosure - Masonry	Site - North	80	SF	7	10+ years	
Playgrou	nd						
	Equipment - School Age 5-12	Entire Site	1	EA	6	2-5 years	
	Surface - Poured Surface	Entire Site	2,940	SF	4	0-1 year	Old/worn.
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	45	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	165.493	SF	6	10+ years	



Catego	ry : Site		В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	25	SF	4	1-2 years	Cracked, broken, shattered and upheaved concrete
Signage							
	Flag Pole - Building Mounted Flag Pole	Main Entry #1	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Main Entry #1	2	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			•					-	
Faculty Lounge	Regular Classroom	2nd Floor	205	205	686	120	60	N	Y
Kindergarten	Regular Classroom	1st Floor	106	106	869	160	80	N	Y
Office	Regular Classroom	1st Floor	107	107	684	120	60	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	693	120	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	102	102	681	120	60	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	686	120	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	688	120	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	105	105	750	120	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	108	108	692	120	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	109	109	686	120	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	110	110	681	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	694	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	671	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	686	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	671	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	671	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	684	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	690	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	686	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	671	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	211	211	689	120	60	Ν	Y
Building : Addition					1	•			
Kindergarten	Kindergarten	1st Floor	116	116	1,029	176	88	N	Y
Music Room	Regular Classroom	1st Floor	112	112	714	132	66	N	Y
Other Instructional Use	Regular Classroom	1st Floor	114	114	726	132	66	N	Y
Regular Classroom	Regular Classroom	1st Floor	117	117	741	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	728	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	731	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	217	217	741	132	66	N	Y
Science Classroom	Science Lab Level 3	2nd Floor	218	218	1,008	198	99	N	Y