

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1900	3	33,794
Addition	1936	3	15,869
Campus Total			49,663

Catego	ry : Exterior	B	uilding				
	H		Overstites		Daula	Recommend	0
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ell Equ							
	Cell Equipment - Antenna	Main Roof	1	EA	7	10+ years	
	Cell Equipment - Cabinets	Main Roof	2	EA	7	10+ years	
ntrance	<u>.</u>						
	Entrance Control - Audio and Video	#1 - Main - S	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#1 - Main - S	3	EA	6	6-10 years	No issues observed
	Exterior Doors - Side lite	#1 - Main - S	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 - Main - S	3	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3 - Southeast	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#3 - Southeast	6	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage Door	#3A - Southeast OVH	1	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#4 - N	1	EA	6	10+ years	Repaired
	Exterior Doors - Side lite	#4 - N	2	EA	6	10+ years	
	Exterior Stairs - Stone	#4 - N	6	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#5 - NW	3	EA	6	6-10 years	Repaired
	Exterior Doors - Side lite	#5 - NW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5 - NW	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5 - NW	12	LF	6	10+ years	
oundati	on						
	Foundation - Masonry	Entire Building	440	LF	7	10+ years	



Category : Exterior			Building : Main					
. .				J		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Superstructure - Heavy Timber	Entire Building	33,794	SF	7	10+ years	Corrected designation. No exposed superstructure	
ighting								
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	7	10+ years		
Roof Sys	tem							
,	Chimney - Metal Flue	Low roof #1	19	LF	6	6-10 years		
	Coping - Clay Tile	Low roof #1	135	LF	7	10+ years		
	Downspouts - Exterior Downspouts	Low roof #1	6	LF	7	6-10 years		
	Parapet - 16" - 30" Height	Low roof #1	80	LF	7	10+ years		
	Roof - Modified Bitumen	Low roof #1	781	SF	6	10+ years		
	Roof Structure - Steel / Metal Deck/	Low roof #1	781	SF	7	10+ years		
	Concrete Topping		-	-		-)		
	Chimney - Metal Flue	Low roof #2 - boiler room	58	LF	7	10+ years		
	Coping - Clay Tile	Low roof #2 - boiler room	68	LF	7	10+ years		
	Coping - Metal	Low roof #2 - boiler room	36	LF	7	6-10 years		
	Downspouts - Exterior Downspouts	Low roof #2 - boiler room	14	LF	6	6-10 years		
	Parapet - 16" - 30" Height	Low roof #2 - boiler room	68	LF	7	10+ years		
	Roof - Modified Bitumen	Low roof #2 - boiler room	1,007	SF	6	10+ years		
	Roof Structure - Steel / Metal Deck/	Low roof #2 - boiler room	1,007	SF	7	10+ years		
	Concrete Topping		,			-)		
	Access Ladder - Metal	Low roof #3	1	EA	7	10+ years	Verizon ladder	
	Coping - Clay Tile	Low roof #3	24	LF	7	10+ years		
	Coping - Stone	Low roof #3	26	LF	7	10+ years		
	Downspouts - Exterior Downspouts	Low roof #3	14	LF	7	6-10 years		
	Parapet - 16" - 30" Height	Low roof #3	50	LF	7	10+ years		
	Roof - Modified Bitumen	Low roof #3	406	SF	6	10+ years		
	Roof Structure - Steel with Clay Tile Arch	Low roof #3	406	SF	7	10+ years		
	Coping - Terra Cotta	Main Roof	441	LF	6	10+ years		
	Downspouts - Exterior Downspouts	Main Roof	60	LF	6	6-10 years		
	Parapet - 16" - 30" Height	Main Roof	101	LF	7	10+ years		
	Parapet - Parapet < 16" Height	Main Roof	163	LF	7	10+ years		
	Parapet - Parapet > 30"	Main Roof	177	LF	7	10+ years		
	Roof - Modified Bitumen	Main Roof	7,900	SF	6	10+ years		
	Roof Structure - Heavy Timber	Main Roof	7,900	SF	7	10+ years	Corrected designation	
Valls								
	Cornice - Masonry Projecting Limestone	Entire Building	263	LF	6	10+ years		
	Cornice - Metal Projecting	Entire Building	263	LF	6	10+ years		
	Exterior Walls - Brick	Entire Building	18,925	SF	6	10+ years		
	Exterior Walls - Stone-Cast	Entire Building	620	SF	6	10+ years		
	Exterior Walls - Stone-Cut	Entire Building	1,052	SF	6	10+ years		



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Vindow							
	Guard - Guards wire guard	Entire Building	783	SF	6	6-10 years	
	Lintels - Brick	Entire Building	47	LF	6	10+ years	
	Lintels - Steel	Entire Building	246	LF	6	10+ years	
	Lintels - Stone	Entire Building	72	LF	6	10+ years	
	Windows - Louver	Entire Building	9	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,429	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
5	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>- Emerger</u>	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	In 2002, intended to serve UPS whi was not installed.
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,786	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,200	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,936	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	14	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	Quantity changed based on curren
			0	EA	0	o to years	observations and per review with Building Engineer.
	Security System - Intrusion Detection	Entire Building	33,794	SF	6	6-10 years	
<u>//ain Se</u>	rvice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves Main and Addition.
	PA System	Entire Building	33,794	SF	5	6-10 years	Also serves Addition.
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	Quantity changed as total has beer divided/aggregated.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Open fuse receptacles expose live conductors presenting a live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live conductors presenting a live front



Catego	ry : Electrical		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
				- -			condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Missing interior cover plate exposes
							live conductors presenting a live front
	Lishting and Deven Develop Alberta 400 A	Fating Duilding		Ξ.	0	10	condition.
	Lighting and Power Panels - Above 100 A Main Distribution Panels - 400 - 600 amp	Entire Building Entire Building	1	EA	6	10+ years	Overtity and leasting sharped to
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	Quantity and location changed to match current observations. Located
							in MDF Room.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	Panel is fully operational with no
		Entire Building	1	LA	0		signs of age-related degradation.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	signs of age related degradation.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	õ	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live
		g		_/ `		e i jeu	conductors presenting a live front
							condition.
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	
	amp	C C				-	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	6-10 years	Panel is fully operational with no
	amp						signs of age-related degradation.
	Transformers - 120/240 - 120/208	Entire Building	1	EA	5	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	ſm						
	Fire Alarm Strobe Lights	Entire Building	33,794	SF	6	10+ years	
	Fire Alarm_System	Entire Building	33,794	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	5	6-10 years	Serves Main and Addition.
Pump R	oom Assembly	Pagamant	1		F	6 10 10000	
	Fire Pump - Less than 25hp	Basement	1	EA	5	6-10 years	
Sprinkle	r Svstem						
	Dry Sprinkler System	Entire Building	33,794	SF	6	10+ years	Serves Main and Addition.
	Sprinkler Heads	Entire Building	33,794	SF	7	10+ years	
	Sprinkler Piping	Entire Building	33,794	SF	4	1-2 years	A control valve shows signs of a leak.
		-					-
Catego	ory : Mechanical		В	uilding	: Main		
Crown	Hom Tune	Leastion	Quantitu		Donk	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	dling Systems	Deserve				0.40	
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EA	5	6-10 years	No CPS Asset Tag present. Located near kitchen/lunchroom. Serves



Catego	ry : Mechanical						
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							Rooms 007, 008, 009 and 010 located in Addition and controlled by electric thermostat located outside Room 009.
Boiler Sy	vstems						
,	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	5	10+ years	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Chemical Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Condensate Pump	Boiler Room	_ 1	EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	10+ years	B-1
	Steam- Low Pressure Boiler - 76 - 100 HP				-	-	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	10+ years	B-2
	Piping - Condensate Pipe- Steel	Boiler Room	1,000	LF	5	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	1,000	LF	5	10+ years	Missing steam piping insulation in boiler room.
	Steam Traps	Boiler Room	5	EA	7	10+ years	Quantity, Rank, Reason and Priorit Rep changed to match current observations and per review with Building Engineer. Steam traps we replaced in 2023.
Gas Boo	ster						
	Gas Booster	Boiler Room	2	EA	5	6-10 years	
leating I	Devices						
	Fin Tube - Electric	1st Floor	8	LF	5	6-10 years	
	Wall Heater - Electric	Basement	3	EA	5	6-10 years	Location changed for clarification. Quantity changed to match current
	Radiators - Steam	Entire Building	3	EA	5	6-10 years	observations.
Temnera	ature Control						
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Controls the Electrical Room exhau fan.
	Pneumatic System	Entire Building	33,794	SF	5	1-2 years	System is largely inoperative and most of the school requires manual temperature control by the Building Engineer.



Catego	ry : Mechanical		B	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Thermostats - Pneumatic	Entire Building	17	EA	5	1-2 years	System is largely inoperative and most of the school requires manual temperature control by the Building Engineer.
Ventilatio							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	4	2-5 years	Serves Main and Addition. Unit is operational and is free of leaks and undue corrosion or deterioration, but is 25 years old. Rank and Priority Rep adjusted as the water heater has exceeded its EUL.
Piping	Domestic Piping-Hot Water Return Lines	Entire Building	33,794	SF	6	10	Domestic water is piped in from
	Domestic Piping-Hot Water Return Lines	Entire Building	55,794	SF	0	10+ years	Addition.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	33,794	SF	6	10+ years	Domestic water is piped in from Addition.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	33,794	SF	6	10+ years	Domestic water is piped in from Addition.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	33,794	SF	6	10+ years	Domestic water is piped in from Addition.
	Sanitary Piping	Entire Building	33,794	SF	6	10+ years	
	Storm Piping	Entire Building	33,794	SF	6	10+ years	
	Vent Piping	Entire Building	33,794	SF	6	6-10 years	
Pumps							
·	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	5	6-10 years	Serves Main and Addition. Operational and free of leaks at the time of assessment. No CPS Asset Tag present.

Category : Room	Building : Main					
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments				
Administrative Suites/Offices						



Group

Category : Room

Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Ceiling - Plaster/Drvwall Gvm Office - 3rd floor 131 SF 6 10+ vears Doors - Wood Doors inclu hw Gvm Office - 3rd floor ΕA 6 1 10+ years Floor - Wood Gvm Office - 3rd floor 131 SF 6 10+ years Gym Office - 3rd floor ΕA 7 Lighting - Pendent/Surface 1 6-10 years 2 **Power Distribution** Gym Office - 3rd floor EΑ 7 10+ years SF Gym Office - 3rd floor Walls - Plaster/Drywall 225 6 10+ years Ceiling - Plaster/Drywall Office 302- previous Wardrobe 300 SF 7 10+ years Room in Classroom 301 Doors - Wood Doors inclu hw Office 302- previous Wardrobe 2 ΕA 7 10+ years Room in Classroom 301 Floor - Tile/Sheet Office 302- previous Wardrobe 300 SF 7 10+ years Room in Classroom 301 Office 302- previous Wardrobe 2 ΕA Lighting - Pendent/Surface 7 10+ years Room in Classroom 301 SF Walls - Plaster/Drywall Office 302- previous Wardrobe 870 7 10+ years Room in Classroom 301 Gvmnasia Ceiling - Plaster/Drywall 3rd Floor 2,332 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor ΕA 6 10+ years 4 SF Floor - Wood 3rd Floor 2.332 6 10+ years Lighting - Metal Halide/Sodium Vapor 3rd Floor 15 ΕA 7 6-10 years Stage SF 3rd Floor 396 6 10+ years Stage Curtain 3rd Floor ΕA 7 6 10+ vears Stage Lighting System 3rd Floor 2 EΑ 7 10+ years Walls - Plaster/Drywall 4,768 SF 6 10+ years 3rd Floor SF Ceiling - Splined Boy's Play Room in Basement 868 4 1-2 years **Displaced tiles** Floor - Sport Flooring Boy's Play Room in Basement SF 7 868 10+ years Lighting - Pendent/Surface Boy's Play Room in Basement FΑ 7 6 6-10 years SF Walls - Masonry Boy's Play Room in Basement 1.345 6 10+ years Kitchen Ceiling - Plaster/Drywall Basement 291 SF 6 10+ years Floor - Concrete Epoxy/ Painted Basement 291 SF 7 10+ years Lighting - Pendent/Surface Basement 2 ΕA 7 6-10 years LF Serving Line 12 6 10+ years Basement SF Walls - Masonrv Basement 562 6 10+ vears Walls - Plaster/Drywall Basement 100 SF 6 10+ years Lunch & Multipurpose Room Ceiling - Splined SF 6 Basement 1.936 10+ years Floor - Concrete Epoxy/ Painted Basement 1.936 SF 7 10+ years Lighting - Pendent/Surface Basement 28 ΕA 7 6-10 years

Building : Main



NOR S	cnools					1632 V	V Wrightwood AVENUE, Chicago, IL 60614
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Masonry	Basement	2,034	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	2,034	SF	6	10+ years	
						·	
MDF_ID							
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	
	Finishes	2nd Floor	198	SF	5	10+ years	
	Window AC Unit	2nd Floor	1	EA	5	6-10 years	
Mechani	cal/ Service Rooms						
	Boiler Room	NE corner of basement	979	SF	7	10+ years	
	Coal Room	NE corner of basement	362	SF	7	10+ years	
	Mechanical/ Service Rooms	NE corner of basement	506	SF	5	10+ years	
	Storage Room	NE corner of basement	318	SF	5	10+ years	
	Storage Room	Storeroom next to the gym	192	SF	5	10+ years	
			102	01	Ũ	ior youro	
Restroor							
	Accessories	Basement north end	253	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement north end	253	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement north end	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement north end	247	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement north end	6	SF	4	0-1 year	Missing tiles
	Floor Drain	Basement north end	1	EA	7	10+ years	
	Hand Dryer	Basement north end	2	EA	7	10+ years	
	Lavatory	Basement north end	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement north end	4	EA	6	6-10 years	
	Partitions	Basement north end	2	EA	7	10+ years	
	Urinals	Basement north end	5	EA	6	10+ years	
	Walls - Plaster/Drywall	Basement north end	224	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement north end	448	SF	6	10+ years	
	Water Closet	Basement north end	2	EA	6	10+ years	
^ atorio	ry : Classroom		в	uilding	• Main		
Jaicgo				unung	. Mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #001 (Kindergarten)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	688	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	2-5 years	
	Floor - Tile	Basement	688	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	6	6-10 years	
	Marker Board	Basement	10	LF	6	10+ years	
	Storage/ Closet	Basement	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	688	SF	6	10+ years	
		Basomon	000	5	U	ior yours	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	Basement	1	EA	7	6-10 years	
Nooroc	m #101 (Kindergarten)						
Jassioc		det Eleer	1		7	0.10	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,486	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroc	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	198	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,486	SF	6	10+ years	
laeeroc	m #103 (Kindergarten)						
21233100	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	900	EA	6	10+ years	
	Floor - Tile	1st Floor	•	SF	-		
	Lighting - Pendent/Surface	1st Floor	900 14	EA	6 7	10+ years 6-10 years	
	Marker Board	1st Floor	20		7		
		1st Floor	198	SF	7	6-10 years	
	Storage/ Closet			SF		10+ years	
	Walls - Plaster/Drywall	1st Floor	1,486	55	6	10+ years	
lassroc	m #104 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,486	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	1-2 years	Peeling paint
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	01
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,486	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,800	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor		SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,512	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	875	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	875	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,650	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor		EA	6	10+ years	
	Floor - Tile	2nd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	177	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,486	SF	6	•	
	vvans - Flastel/DiyWall		1,400	ЗГ	U	10+ years	
Classroo	m #301 (Regular Classroom)						
	AC Units Ceiling - Plaster/Drywall	3rd Floor	1	EA SF	7	6-10 years	
		3rd Floor	900		6	10+ years	



	Schools					1632 V	W Wrightwood AVENUE, Chicago, IL 60614
Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,486	SF	6	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	10+ years	
	Floor - Tile	3rd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	177	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,486	SF	6	10+ years	
Catego	ry : Interior		в	uilding	: Main		
calege	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor						•	
	Ceiling - Plaster/Drywall	1st Floor	1,706	SF	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	3	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,706	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,922	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,706	SF	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet						
		Znd Floor	1.706	S⊢	5	10+ vears	
		2nd Floor 2nd Floor	1,706 16	SF EA	5 6	10+ years 6-10 vears	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall	2nd Floor 2nd Floor	16 2,922	EA SF	6 6	6-10 years 10+ years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall	2nd Floor 2nd Floor 3rd Floor	16 2,922 713	EA SF SF	6 6 6	6-10 years 10+ years 10+ years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet	2nd Floor 2nd Floor 3rd Floor 3rd Floor	16 2,922 713 713	EA SF SF SF	6 6 7	6-10 years 10+ years 10+ years 10+ years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface	2nd Floor 2nd Floor 3rd Floor	16 2,922 713 713 5	EA SF SF	6 6 6	6-10 years 10+ years 10+ years 10+ years 6-10 years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall	2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor	16 2,922 713 713 5 1,682	EA SF SF EA SF	6 6 7 6 6	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed	2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	16 2,922 713 713 5	EA SF SF SF EA	6 6 7 6 6 6	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed Doors - Wood Doors include hw	2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor Basement	16 2,922 713 713 5 1,682 2,037 4	EA SF SF EA SF SF	6 6 7 6 6	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed Doors - Wood Doors include hw Floor - Concrete Epoxy/ Painted	2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor Basement Basement	16 2,922 713 713 5 1,682 2,037 4 2,037	EA SF SF EA SF EA SF SF	6 6 7 6 6 6 7	6-10 years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed Doors - Wood Doors include hw Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface	2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor Basement Basement Basement Basement	16 2,922 713 713 5 1,682 2,037 4 2,037 8	EA SF SF EA SF EA SF EA SF EA	6 6 7 6 6 6 7 6	6-10 years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed Doors - Wood Doors include hw Floor - Concrete Epoxy/ Painted	2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor Basement Basement Basement	16 2,922 713 713 5 1,682 2,037 4 2,037	EA SF SF EA SF EA SF SF	6 6 7 6 6 6 7	6-10 years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	

Stairs



Catego	Category : Interior			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	North	595	SF	6	10+ years	
	Floor - Tile	North	312	SF	6	10+ years	
	Handrails	North	204	LF	7	10+ years	
	Lighting - Pendent/Surface	North	7	EA	7	6-10 years	
	Stairs - Terrazzo	North	90	LF	6	10+ years	
	Walls - Plaster/Drywall	North	3,492	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	595	SF	6	10+ years	
	Floor - Tile	South	312	SF	6	10+ years	
	Handrails	South	204	LF	7	10+ years	
	Lighting - Pendent/Surface	South	7	EA	6	6-10 years	
	Stairs - Terrazzo	South	90	LF	6	10+ years	
	Walls - Plaster/Drywall	South	3,492	SF	6	10+ years	



Catego	ry : Exterior		В	uilding	on		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equi	pment						
	Cell Equipment - Antenna	N/A	9	EA	7	10+ years	
	Cell Equipment - Cabinets	N/A	7	EA	7	10+ years	
	Cell Equipment - Generator	N/A	1	EA	7	10+ years	
Entrance							
	Exterior Doors - Exterior Steel Door	#2 - E	2	EA	6	6-10 years	Repaired
	Exterior Doors - Exterior Steel Door	Fire escape Doors East	3	EA	6	6-10 years	Functioning normally, surface rust
Fire Esca							
	Exterior Doors - Exterior Steel Door	Southeast	3	EA	6	6-10 years	
	Fire Escape	Southeast	282	LF	6	6-10 years	Re-rated based on new system
	Paints	Southeast	282	LF	5	1-2 years	Missing paint, corrosion
		Council	202	<u> </u>	Ũ	1 2 youro	
Foundati	on						
	Foundation - Concrete	Entire Building	204	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	15,869	SF	7	10+ years	
Lighting	Exterior Lighting - Wall Mounted	Entire Building	5	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	5	2-5 years	
	Exterior Lighting - Wall Mounted	Entite Building	5	LA	5	2-5 years	
Roof Sys	tem						
,	Coping - Stone	Low E roof	84	LF	7	10+ years	
	Downspouts - Interior Downspouts	Low E roof	28	LF	7	10+ years	Repaired
	Parapet - 16" - 30" Height	Low E roof	84	LF	7	10+ years	•
	Roof - Modified Bitumen	Low E roof	793	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Low E roof	793	SF	7	10+ years	
	Coping - Stone	Low N roof	43	LF	7	10+ years	
	Downspouts - Interior Downspouts	Low N roof	28	LF	7	10+ years	
	Parapet - 16" - 30" Height	Low N roof	43	LF	7	10+ years	
	Roof - Modified Bitumen	Low N roof	470	SF	7	10+ years	No roof access
	Roof Structure - Steel with Clay Tile Arch	Low N roof	470	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	6-10 years	
	Access Ladder - Metal	Main Roof	1	EA	5	2-5 years	Insufficient clearance between lade and roof opening. Not previously assessed
	Coping - Terra Cotta	Main Roof	216	LF	6	10+ years	4000004
	Downspouts - Interior Downspouts	Main Roof	120	LF	6	6-10 years	
	Parapet - Parapet > 30"	Main Roof	216	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	3,534	SF	7	10+ years	
			5,554	3	1	IUT years	



Catego	ry : Exterior		В	uilding	: Additi		V Wrightwood AVENUE, Chicago, IL 60614
Ŭ	·			U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	3,534	SF	7	10+ years	
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	83	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	83	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	12,578	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	424	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	848	SF	7	10+ years	
Windows							
	Guard - Guards wire guard	Entire Building	435	SF	6	6-10 years	
	Lintels - Steel	Entire Building	224	LF	6	10+ years	
	Lintels - Stone	Entire Building	16	LF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	70	SF	7	6-10 years	Steel
	Windows - Sash Aluminum Double-pane	Entire Building	1,615	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding			
•	H (1) - (1)					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergen	cy System		-	Ξ.		0.40	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	1,489	SF	6	10+ years	
	Stairs						
	Security System - Intrusion Detection	Entire Building	15,869	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	Quantity changed as total has been
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	4	0-1 year	divided/aggregated. Exit Sign is functional but damaged.
		Entire Dunding	·	LA	-	0-1 year	
Main Ser							
	PA System	Entire Building	15,869	SF	5	6-10 years	Served by Main.
Power Di	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Misdocumented as a Main Distribution Panel in previous assessment.
Category : Fire Protection		В	Building : Addition				
Outegoi							



XCR Schools					1632 V	N Wrightwood AVENUE, Chicago, IL 60614
					Replacement	
ire Alarm						
Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
Fire Alarm Strobe Lights	Entire Building	15,869	SF	6	10+ years	
Fire Alarm_System	Entire Building	15,869	SF	5	10+ years	
prinkler System						
Sprinkler Heads	Entire Building	5,290	SF	7	6-10 years	
Sprinkler Piping	Entire Building	5,289	SF	6	6-10 years	
ategory : Mechanical		B	uilding	: Additi	on	
		-			Recommend	•
roup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Handling Systems						
Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Basement	1	EA	5	10+ years	Serves Addition and Main.
Air Intake	Basement	2	EA	6	10+ years	Location changed for clarification.
Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	6	6-10 years	Equipment is well- maintained and fully operational. Rank, Reason and Priority Rep adjusted based on current observations and per detaile review with Building Engineer.
Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	60	LF	6	10+ years	
Zone Dampers	Basement	32	EA	5	6-10 years	Seven zone dampers serve Addition and 25 zone dampers serve Main, operated manually in the absence or a functional temperature control system. Reason and Priority Rep adjusted to reflect that the dampers are in a condition such that they are able to be adjusted despite having n mechanical actuators.
leating Devices						
Unit Heater - Steam	Basement	1	EA	2	0-1 year	Based on current observations and per review with Building Engineer, unit is nonfunctional.
Radiators - Steam	Entire Building	6	EA	5	6-10 years	
Wall Heater - Electric	Entire Building	8	EA	5	2-5 years	Quantity changed based on current observations.
emperature Control						
Electric Thermostat	Entire Building	1	EA	6	10+ years	Controls the ceiling mounted fan coil unit in Main that serves Rooms 007, 008, 009 and 010.



Catego	Category : Mechanical			Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Pneumatic System	Entire Building	15,869	SF	5	1-2 years	Served by Main. System is largely inoperative and most of the school requires manual temperature control by the Building Engineer.	
	Thermostats - Pneumatic	Entire Building	15	EA	5	1-2 years	System is largely inoperative and most of the school requires manual temperature control by the Building Engineer. Reason and Priority Rep adjusted based on current observations and detailed review with the Building Engineer.	
Ventilatio	on							

Exhaust Fans- Roof Mounted - 1501 - 8000 ΕA 10+ years 1 6 Roof CFM

Category : P	lumbina
--------------	---------

Catego	Category : Plumbing			Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Domestic Piping-Hot Water Return Lines	Entire Building	15,869	SF	6	10+ years		
	Domestic Piping-Hot Water Return Risers	Entire Building	15,869	SF	6	10+ years		
	Domestic Piping-Hot Water from Risers to	Entire Building	15,869	SF	6	10+ years		
	Fixtures							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	15,869	SF	6	10+ years		
	(Horizontal Lines)							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	15,869	SF	6	10+ years		
	(Risers)							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	15,869	SF	6	10+ years		
	(from Risers to Fixtures)							
	Sanitary Piping	Entire Building	15,869	SF	6	10+ years		
	Storm Piping	Entire Building	15,869	SF	6	10+ years		
	Vent Piping	Entire Building	15,869	SF	6	6-10 years		

Category : Room			В					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Administrative Suites/Offices								
	AC Unit	1st flr Main Office Suite	2	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st flr Main Office Suite	1,060	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st flr Main Office Suite	6	EA	6	10+ years		
	Floor - Carpet	1st flr Main Office Suite	1,060	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st flr Main Office Suite	16	EA	7	6-10 years		



Category : Room

Group

Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Power Distribution 1st flr Main Office Suite 24 ΕA 6 10+ vears 1st flr Main Office Suite 70 SF 7 Storage/ Closet 10+ years Walls - Plaster/Drywall 1st flr Main Office Suite 2.754 SF 6 10+ years Ceiling - Exposed SF Basement NE corner, engineer's 133 6 10+ years office Doors - Wood Doors inclu hw Basement NE corner, engineer's 1 EΑ 6 10+ years office Floor - Tile/Sheet Basement NE corner, engineer's 133 SF 7 10+ years office Lighting - Pendent/Surface Basement NE corner, engineer's FΑ 1 6 6-10 years office Power Distribution Basement NE corner, engineer's 6 ΕA 6 10+ years office Storage/ Closet Basement NE corner, engineer's 22 SF 7 10+ years office Basement NE corner, engineer's SF Walls - Plaster/Drywall 560 6 10+ years office Work SInk Basement NE corner, engineer's 1 EΑ 7 10+ years office Ceiling - Exposed **Basement Teacher's Lounge** 825 SF 6 6-10 years Doors - Wood Doors inclu hw **Basement Teacher's Lounge** ΕA 5 6-10 years 1 Floor - Concrete Epoxy/ Painted SF 7 10+ years **Basement Teacher's Lounge** 825 Lighting - Pendent/Surface ΕA 7 **Basement Teacher's Lounge** 4 6-10 years 7 Power Distribution **Basement Teacher's Lounge** 4 FΑ 10+ years Walls - Masonry SF 6 **Basement Teacher's Lounge** 1.160 6-10 years Work SInk **Basement Teacher's Lounge** 1 FΑ 7 10+ years Mechanical/ Service Rooms Janitor's Closet 1st Floor SF 5 71 10+ years 2nd Floor SF 5 Janitor's Closet 71 10+ years SF Janitor's Closet 3rd Floor 71 7 10+ years SF Air Intake Plenums **Basement** 847 5 10+ vears SF Mechanical/ Service Rooms Basement 476 5 10+ years Storage Room Basement 699 SF 5 10+ years Restroom 1st Floor 273 SF 7 Accessories 6-10 vears Ceiling - Plaster/Drywall 1st Floor 273 SF 6 10+ years Floor - Tile Ceramic/ Porcelain 273 SF 6 1st Floor 10+ years 7 Floor Drain 1st Floor 1 EΑ 10+ years

Building : Addition

Hand Dryer

Lighting - Pendent/Surface

Lavatory

Partitions

1st Floor

1st Floor

1st Floor

1st Floor

2

2

3

6

ΕA

ΕA

ΕA

ΕA

7

7

7

7

6-10 years

10+ years

6-10 years

10+ years



Catego	ry : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	1st Floor	441	SF	6	10+ years			
	Water Closet	1st Floor	6	EA	6	10+ years			
	Accessories	1st flr inside principal's office	35	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st flr inside principal's office	35	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st flr inside principal's office	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st flr inside principal's office	35	SF	6	10+ years			
	Lavatory	1st flr inside principal's office	1	EA	6	10+ years			
	Lighting - Pendent/Surface	1st flr inside principal's office	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st flr inside principal's office	220	SF	6	10+ years			
	Water Closet	1st flr inside principal's office	1	EA	6	10+ years			
	Accessories	2nd Floor	273	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	273	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	268	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	5	SF	4	0-1 year	Broken/ missing tiles		
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	2	EA	7	6-10 years			
	Lavatory	2nd Floor	2	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years			
	Partitions	2nd Floor	4	EA	7	10+ years			
	Urinals	2nd Floor	3	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	442	SF	6	10+ years			
	Water Closet	2nd Floor	4	EA	7	10+ years			
	Accessories	2nd Floor	42	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	42	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	42	SF	6	10+ years			
	Lavatory	2nd Floor	1	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years			
	Partitions	2nd Floor	1	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	194	SF	6	10+ years			
	Water Closet	2nd Floor	1	EA	7	10+ years			
	Accessories	3rd Floor	273	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	273	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	273	SF	6	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	2	EA	7	6-10 years			
	Lavatory	3rd Floor	2	EA	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years			
	Partitions	3rd Floor	7	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	441	SF	6	10+ years			
	Water Closet	3rd Floor	7	EA	6	10+ years			
	Accessories	Basement NE Corner Office 005E	48	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement NE Corner Office 005E	48	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Basement NE Corner Office 005E	1	EA	7	10+ years			



Catego	ry : Room		Building : Addition					
				5		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	Basement NE Corner Office 005E	48	SF	6	10+ years		
	Lavatory	Basement NE Corner Office 005E	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Basement NE Corner Office 005E	1	EA	7	10+ years		
	Walls - Plaster/Drywall	Basement NE Corner Office 005E	308	SF	7	10+ years		
	Accessories	Basement inside Office 105E	22	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement inside Office 105E	22	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement inside Office 105E	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Basement inside Office 105E	22	SF	6	10+ years		
	Lighting - Pendent/Surface	Basement inside Office 105E	1	EA	6	6-10 years		
	Walls - Plaster/Drywall	Basement inside Office 105E	170	SF	7	10+ years		
	Water Closet	Basement inside Office 105E	1	EA	6	10+ years		
	Accessories	In Classroom 005	22	SF	7	6-10 years		
	Ceiling - Exposed	In Classroom 005	22	SF	6	10+ years		
	Doors - Wood Doors inclu hw	In Classroom 005	1	EA	6	10+ years		
	Floor - Tile	In Classroom 005	22	SF	6	6-10 years		
	Lighting - Pendent/Surface	In Classroom 005	1	EA	6	6-10 years		
	Walls - Masonry	In Classroom 005	44	SF	6	10+ years		
	Water Closet	In Classroom 005	1	EA	6	10+ years		
	Accessories	Restroom inside 101	5	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Restroom inside 101	19	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Restroom inside 101	19	SF	6	10+ years		
	Lighting - Pendent/Surface	Restroom inside 101	1	EA	6	6-10 years		
	Walls - Plaster/Drywall	Restroom inside 101	160	SF	6	10+ years		
	Water Closet	Restroom inside 101	1	EA	6	10+ years		
	Accessories	Unisex Room, 3rd Floor	42	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Unisex Room, 3rd Floor	42	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Unisex Room, 3rd Floor	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Unisex Room, 3rd Floor	42	SF	6	10+ years		
	Lavatory	Unisex Room, 3rd Floor	1	EA	6	10+ years		
	Lighting - Pendent/Surface	Unisex Room, 3rd Floor	1	EA	7	6-10 years		
	Partitions	Unisex Room, 3rd Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	Unisex Room, 3rd Floor	194	SF	6	10+ years		
	Water Closet	Unisex Room, 3rd Floor	1	EA	6	10+ years		
	Accessories	Women's Room, 1st Floor	42	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Women's Room, 1st Floor	42	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Women's Room, 1st Floor	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Women's Room, 1st Floor	42	SF	6	10+ years		
	Lavatory	Women's Room, 1st Floor	1	EA	6	10+ years		
	Lighting - Pendent/Surface	Women's Room, 1st Floor	1	EA	7	6-10 years		
	Partitions	Women's Room, 1st Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	Women's Room, 1st Floor	194	SF	6	10+ years		
	Water Closet	Women's Room, 1st Floor	1	EA	6	10+ years		
	Water Closet	Women's Room, 1st Floor	1	EA	6	10+ years		



Catego	Category : Classroom		В	uilding	: Additi		v wrightwood AVENUE, Chicago, IL 60614
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #005 (Multi Purpose Room)						
	Ceiling - Exposed	Basement	345	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	345	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	7	10+ years	
	Marker Board	Basement	8	LF	7	6-10 years	
	Storage/ Closet	Basement	24	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	814	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	6-10 years	
						-	
Classroo	om #007 (Multi Purpose Room)						
	AC Units	Basement	1	EA	7	2-5 years	
	Ceiling - Exposed	Basement	200	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	6-10 years	
	Floor - Concrete	Basement	200	SF	7	6-10 years	
	Lighting - Pendent/Surface	Basement	2	EA	7	6-10 years	
	Marker Board	Basement	24	LF	7	6-10 years	
	Walls - Masonry	Basement	200	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	200	SF	7	6-10 years	
Classro	om #008 (Special Program)						
	Ceiling - Plaster/Drywall	Basement	200	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Basement	200	EA	7	6-10 years	
	Floor - Tile/Sheet	Basement	200	SF	7	6-10 years	
	Lighting - Pendent/Surface	Basement	200	EA	7	10+ years	
	Marker Board	Basement	5	LA	7	6-10 years	
	Walls - Masonry	Basement	80	SF	7	10+ years	
	Walls - Metal Panel	Basement	200	SF	7	6-10 years	
	Walls - Plaster/Drywall	Basement	120	SF	7	10+ years	
	Wallo Thatton/Drywall	Dassmont	120	0.	,	lot youro	
Classroo	om #009 (Special Program)						
	Ceiling - Plaster/Drywall	Basement	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	6-10 years	
	Floor - Tile/Sheet	Basement	300	SF	7	6-10 years	
	Lighting - Pendent/Surface	Basement	3	EA	7	6-10 years	
	Walls - Masonry	Basement	120	SF	7	10+ years	
	Walls - Metal Panel	Basement	440	SF	7	6-10 years	
Classifi							
	om #010 (Special Program)					0.40	
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	200	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	6-10 years	
	Floor - Tile/Sheet	Basement	200	SF	7	6-10 years	



Catego	Category : Classroom			Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	Basement	2	EA	7	6-10 years		
	Walls - Masonry	Basement	240	SF	7	10+ years		
	Walls - Metal Panel	Basement	49	SF	7	6-10 years		
Classroc	om #106 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	816	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	ĒA	6	10+ years		
	Floor - Tile	1st Floor	816	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	ĒA	7	6-10 years		
	Marker Board	1st Floor	16	LF	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,300	SF	6	10+ years		
Classroo	om #107 (Regular Classroom)							
2.000100	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	816	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	816	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	12	LF	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,300	SF	6	10+ years		
Classroc	om #205 (Regular Classroom)							
Chiconot	AC Units	2nd Floor	2	EA	5	6-10 years		
	Casework	2nd Floor	- 8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years		
	Floor - Tile	2nd Floor	816	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	6	10+ years		
Classroo	om #206 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years		
	Floor - Tile	2nd Floor	816	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor 2nd Floor	12		6	,		
		2nd Floor 2nd Floor		SF	6	6-10 years		
	Walls - Plaster/Drywall	2110 11001	1,300	SF	O	10+ years		



Category : Classroom			В	Building : Addition						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
-	Work Sink	2nd Floor	1	EA	7	6-10 years				
Classroo	m #207 (Regular Classroom)									
	AC Units	2nd Floor	2	EA	5	6-10 years				
	Casework	2nd Floor	8	LF	6	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	716	SF	6	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	100	SF	6	1-2 years	Peeling paint			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years				
	Floor - Tile	2nd Floor	816	SF	6	10+ years				
	Lighting - Pendent/Surface	2nd Floor	12	ĒA	7	6-10 years				
	Marker Board	2nd Floor	16	LF	6	6-10 years				
	Walls - Plaster/Drywall	2nd Floor	1,298	SF	6	10+ years				
	Walls - Plaster/Drywall	2nd Floor	2	SF	6	1-2 years	Hole in wall			
	Walls Traster/Drywall	21011001	2	01	U					
Classroo	m #305 (Regular Classroom)									
	AC Units	3rd Floor	2	EA	7	6-10 years				
	Casework	3rd Floor	- 8	LF	6	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years				
	Floor - Tile	3rd Floor	816	SF	6	10+ years				
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years				
	Marker Board	3rd Floor	16	LF	6	6-10 years				
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	6	10+ years				
		314 1 1001	1,500	51	0	TOF years				
Classroo	m #306 (Regular Classroom)									
	AC Units	3rd Floor	2	EA	7	6-10 years				
	Casework	3rd Floor	8	LF	6	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	6	10+ years				
	Floor - Tile	3rd Floor	816	SF	6	10+ years				
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years				
	Marker Board	3rd Floor	16	LF	6	6-10 years				
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	6	10+ years				
	· ·	-	,		-	,				
Classroo	m #307 (Regular Classroom)									
	AC Units	3rd Floor	2	EA	7	6-10 years				
	Casework	3rd Floor	8	LF	6	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years				
	Floor - Tile	3rd Floor	816	SF	6	10+ years				
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years				
	Marker Board	3rd Floor	22	LF	6	6-10 years				



Catego	ry : Classroom	Building : Addition									
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
Catego	ry : Interior		В	Building : Addition							
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
Corridor											
	Ceiling - Plaster/Drywall	1st Floor	369	SF	6	10+ years					
	Doors - Wood Doors include hw	1st Floor	2	EA	6	10+ years					
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years					
	Floor - Tile/Sheet	1st Floor	369	SF	7	10+ years					
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years					
	Walls - Plaster/Drywall	1st Floor	1,200	SF	6	10+ years					
	Ceiling - Plaster/Drywall	2nd Floor	369	SF	6	10+ years					
	Doors - Wood Doors include hw	2nd Floor	2	EA	6	10+ years					
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years					
	Floor - Tile/Sheet	2nd Floor	369	SF	7	10+ years					
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years					
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	10+ years					
	Ceiling - Plaster/Drywall	3rd Floor	369	SF	6	10+ years					
	Doors - Wood Doors include hw	3rd Floor	2	EA	6	10+ years					
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years					
	Floor - Tile/Sheet	3rd Floor	369	SF	7	10+ years					
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years					
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years					
	Ceiling - Exposed	Basement	382	SF	6	10+ years					
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years					
	Floor - Concrete Epoxy/ Painted	Basement	387	SF	7	10+ years					
	Lighting - Pendent/Surface	Basement	5	EA	7	6-10 years					
	Stairs - Concrete Stairs	Basement	24	LF	6	10+ years					
	Walls - Masonry	Basement	1,161	SF	6	10+ years					



Category : Site			В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Synthetic	East	15,200	SF	7	10+ years	
						-	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	6-10 years	
Fencing							
	Fencing - Chain Link	Entire Site	77	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	558	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	8	LF	5	1-2 years	Dented
Landscap							
	Benches	Entire Site	3	EA	6	6-10 years	
	Landscape - Mulch	Entire Site	300	SF	7	2-5 years	
	Parkway trees	Entire Site	9	EA	6	10+ years	
	Parkway trees	Entire Site	1	EA	4	0-1 year	Missing
	Planting Beds/ Area	Entire Site	383	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	1,786	SF	4	0-1 year	Worn, uneven surface
.							
Parking L							
	Surface - Asphalt	Parking Lot- East	11,260	SF	6	6-10 years	Recalculated and recombined
							quantities. Rating based on current
							observations
	Trash Enclosure - Chain Links	Parking Lot- East	56	SF	7	6-10 years	
Dioversu	ad						
Playgrou	Equipment - Combo 3-12	North	1	EA	6	6-10 years	
	Surface - Poured Surface	North	2,678	SF	6	6-10 years	
	Surface - Foured Surface	North	2,070	36	0	0-10 years	
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	70	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	9,841	SF	6	10+ years	
						-	
Signage							
	Flag Pole - Flag Pole	Site East, South East and Entrance	1	EA	7	10+ years	
		1 & 2					
	Marquee - Free Standing Back Lighted	Site East, South East and Entrance	1	EA	6	6-10 years	
		1&2			-		
	Monument - Building Mounted Cut Letter	Site East, South East and Entrance	2	EA	6	10+ years	



						1002 1	
Category : Site			B				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sign	1 & 2					

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-	
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board	
Building : Main										
Kindergarten	Kindergarten	1st Floor	101	101	900	85	9	Y	N	
Kindergarten	Kindergarten	Basement	001	001	688	120	20	N	N	
Kindergarten	Regular Classroom	1st Floor	103	103	900	85	9	Y	N	
Kindergarten	Regular Classroom	1st Floor	104	104	900	121	15	Y	N	
Regular Classroom	Regular Classroom	1st Floor	102	102	900	85	9	Y	N	
Regular Classroom	Regular Classroom	2nd Floor	201	201	900	85	9	Y	N	
Regular Classroom	Regular Classroom	2nd Floor	202	202	1,800	136	6	N	N	
Regular Classroom	Regular Classroom	2nd Floor	203	202,203	875	150	75			
Regular Classroom	Regular Classroom	2nd Floor	204	204	900	121	15	Y	N	
Regular Classroom	Regular Classroom	3rd Floor	301	301	900	85	9	Y	N	
Regular Classroom	Regular Classroom	3rd Floor	304	304	900	121	15	Y	Ν	
Building : Addition										
Multi Purpose Room	Office	Basement	007	007	200	12	6			
Multi Purpose Room	Regular Classroom	Basement	005	005	345	32	16			
Regular Classroom	Library	2nd Floor	205	205	816	180	90	N	N	
Regular Classroom	Regular Classroom	1st Floor	106	106	816	180	90	N	N	
Regular Classroom	Regular Classroom	1st Floor	107	107	816	180	90	N	N	
Regular Classroom	Regular Classroom	2nd Floor	206	206	816	180	90	N	Ν	
Regular Classroom	Regular Classroom	2nd Floor	207	207	816	180	90	N	N	
Regular Classroom	Regular Classroom	3rd Floor	305	305	816	180	90	N	N	
Regular Classroom	Regular Classroom	3rd Floor	306	306	816	180	90	N	Ν	
Regular Classroom	Regular Classroom	3rd Floor	307	307	816	180	90	N	Ν	
Special Program	Regular Classroom	Basement	008	008	200	15	7			
Special Program	Regular Classroom	Basement	009	009	300	15	7			
Special Program	Regular Classroom	Basement	010	010	200	0	0			