

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1914	3	75,830
Linked Addition	1995	2	34,776
Modular 1 (2-Classroom)	2000	1	1,632
Modular 2 (2-Classroom)	2000	1	1,632
Campus Total			113,870

Category : Exterior Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance			•			•	
	Exterior Doors - Exterior Steel Door	10 SW - Main	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	10 SW - Main	4	EΑ	6	10+ years	
	Exterior Stairs - Concrete	10 SW - Main	72	LF	5	1-2 years	Cracked concrete steps and landing
	Stair Handrail - Steel_Stair Handrail	10 SW - Main	6	LF	6	10+ years	•
	Exterior Doors - Exterior Steel Door	6 SW - Main	4	EΑ	7	10+ years	New
	Exterior Doors - Transom Lite	6 SW - Main	4	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	6 SW - Main	154	LF	5	0-1 year	Broken concrete steps and landing, large cracks
	Stair Handrail - Steel_Stair Handrail	6 SW - Main	10	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	7 West - Main	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	7 West - Main	5	EA	6	6-10 years	
	Exterior Stairs - Concrete	7 West - Main	32	LF	7	10+ years	New
	Exterior Doors - Exterior Steel Door	8 N - Main	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	8 N - Main	2	EA	7	6-10 years	
	Exterior Stairs - Concrete	8 N - Main	6	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	9 NEMain	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	9 NEMain	5	EA	6	6-10 years	
	Exterior Stairs - Concrete	9 NEMain	32	LF	7	6-10 years	
_Foundat	ion						
	Foundation - Masonry	Entire Building	715	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Superstructure - Steel with Clay Tile Arch	Entire Building	75,830	SF	7	10+ years	
_Lighting					_		
	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	2-5 years	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	5	2-5 years	
Doof Co.							
Roof Sy:	Access Ladder - Metal	^	2	EA	7	10	Took one ladder off this list. One
		A	3		7	10+ years	ladder is for roof B
	Access Ladder - Metal	A	1	EA	4	0-1 year	Dangerous ladder, poorly attached to hatch support. One has to pull one self up at the hatch. There is no room for foothold because of the clay tile roof and the ladder rungs being so close together.
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Α	40	LF	6	10+ years	This chimney begins to occur at roof C
	Coping - Stone	A	503	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Α	74	LF	6	10+ years	
	Parapet - 16" - 30" Height	Α	503	LF	7	10+ years	
	Roof - Modified Bitumen	Α	18,920	SF	6	10+ years	
	Roof Hatch - Metal	A	2	ĒΑ	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	A	18,920	SF	7	10+ years	
	Access Ladder - Metal	В	1	EA	4	0-1 year	Ladder does not reach the floor/roof surface. one has to put a step ladder to access the building ladder
	Coping - Stone	В	235	LF	6	10+ years	
	Downspouts - Exterior Downspouts	В	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	В	235	LF	6	10+ years	No open joints were observed during this visit
	Parapet - Parapet > 30"	В	225	LF	6	10+ years	
	Roof - Modified Bitumen	В	4,788	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	В	4,788	SF	7	10+ years	
	Chimney - Metal Flue	С	40	LF	7	10+ years	
	Downspouts - Interior Downspouts	C	34	LF	6	10+ years	
	Roof - Modified Bitumen	C	3,127	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	C	3,127	SF	7	10+ years	
	Downspouts - Exterior Downspouts	D	24	LF	6	6-10 years	
	Roof - Metal	D	180	SF	6	10+ years	
	Roof - Modified Bitumen	D	1,003	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	D	1,183	SF	7	10+ years	
	Coping - Stone	E	35	LF	7	10+ years	
	Downspouts - Interior Downspouts	E	15	LF	6	6-10 years	
	Parapet - 16" - 30" Height	E	34	LF	7	10+ years	
	Tarapot 10 - 50 Height	L	34	LI	'	10+ years	



Catego	ry : Exterior		В	uilding	: Main		030 W School STREET, Chicago, ie 000 ii
Jaiogo	.y . =xtorio.		_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	E	288	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	E	288	SF	7	10+ years	
	Coping - Stone	F	34	LF	7	10+ years	
	Downspouts - Interior Downspouts	F	15	LF	6	6-10 years	
	Parapet - 16" - 30" Height	F	34	LF	7	10+ years	
	Roof - Modified Bitumen	F	288	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	F	288	SF	7	10+ years	
Walls							
vvans	Cheek-Wall - Stone	Entire Building	200	SF	5	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	906	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	600	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	16,882	SF	6	10+ years	
		Entire Building Entire Building	1,635	SF	6	,	
	Exterior Walls - Brick	Entire Building	1,033	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire building	144	SF	,	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	5	SF	7	6-10 years	
	Exterior Walls - Stone-Cut	Entire Building	3,810	SF	6	10+ years	
Windows	S						
	Guard - Guards perforated	Entire Building	2,323	SF	6	10+ years	
	Lintels - Steel	Entire Building	856	LF	6	10+ years	
	Lintels - Stone	Entire Building	30	LF	6	10+ years	
	Windows - Decorative	Entire Building	192	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	8,350	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
ou.ege	.,		_			Recommend	
Group		Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Boiler Room	1	EA	6	10+ years	
	Automatic Transfer Switch	Boiler Room	1	EA	4	1-2 years	Older, not reliable.
	Exit Signs - Auditoium	Entire Building	8	EA	6	2-5 years	
	Exit Signs - Corridors and Stairs	Entire Building	19	EA	6	2-5 years	
	Exit Signs - Gym	Entire Building	2	EA	6	2-5 years	
	Security System - CCTV	Entire Building	75,830	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	75,830	SF	5	2-5 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	5,530	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	15,126	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	3,146	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and	Entire Building	2,140	EA	6	2-5 years	
	Emergency battery r dotto - Additional and	Entire Ballating	2	L/ \	J	2 0 yours	



Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Aisle Lighting Emergency Generator- Outdoor- Natural Gas - Below 60 KW	Site North	1	EA	6	6-10 years	
∕lain Se	rvice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	75,830	SF	5	2-5 years	
Power D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	4	0-1 year	Live front or missing spare breake covers
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	6	6-10 years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ire Alaı		20041011	Quantity	COIII	rtanit	Ropidocinont	Comments
	Fire Alarm Strobe Lights	Entire Building	75,830	SF	6	2-5 years	
	Fire Alarm_System	Entire Building	75,830	SF	5	2-5 years	
Catego	ry : Mechanical		В	uilding	: Main		
Froup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	dling Systems						
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Attic	2	EA	6	10+ years	Difficult to access one fan
	Air Handling Unit- Built Up- Multi Zone-	Mechanical Room	1	EA	6	6-10 years	AHU1 Serves Main Building
	Double Delivery- Hot Water Coils - Greater than 60000 cfm						
	Double Delivery- Hot Water Coils - Greater than 60000 cfm Air Intake	Mechanical Room	1	ΕA	6	6-10 years	
	Double Delivery- Hot Water Coils - Greater than 60000 cfm Air Intake Auxiliaries - Greater than 60000 cfm	Mechanical Room	1	EA	7	6-10 years	
	Double Delivery- Hot Water Coils - Greater than 60000 cfm Air Intake					•	



Catego	ry : Mechanical		В	uilding	: Main		
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy							
	Boiler Auxiliary- Condensing Hot Water - 2001 - 3000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Condensing- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	10+ years	Serves Main Building, B2, B1
	Water Fill System	Boiler Room	1	EA	6	10+ years	
leating l	Devices						
J	Wall Heater - Electric	Entire Building	14	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	1	EA	6	10+ years	
	Unit Heater - Hot Water	Entire Building	1	EA	6	10+ years	
	Fin Tube - Hot Water	Entire Building	30	LF	5	2-5 years	Damaged/missing cover.
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	200	LF	7	10+ years	
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	10+ years	
	Hot Water Pump - Less than 10	Entire Building	1	EΑ	6	10+ years	
	Hot Water Pump - Less than 10	Entire Building	1	EΑ	6	10+ years	
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	10+ years	
Tempera	ture Control						
Опрои	DDC System	Entire Building	75,830	SF	6	6-10 years	
	Electric Thermostat	Entire Building	2	EΑ	6	6-10 years	
	Thermostats - DDC	Entire Building	46	EA	6	6-10 years	
/entilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	4	EA	7	10+ years	EF 1/2/4/5
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	7	10+ years	EF 3/6
	Roof Mounted Duct Work	Entire Building	125	LF	6	10+ years	
atego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
Piping							

Campus Name: Reilly Page : 5 of 53 Assessment Date: 08/16/2023



Catego	ry : Plumbing	Plumbing Building : Main							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Domestic Piping-Hot Water Return Risers	Entire Building	75,830	SF	6	6-10 years			
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	75,830	SF	6	6-10 years			
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	75,830	SF	6	6-10 years			
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	75,830	SF	6	6-10 years			
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	75,830	SF	6	6-10 years			
	Sanitary Piping	Entire Building	75,830	SF	6	6-10 years			
	Storm Piping	Entire Building	75,830	SF	6	6-10 years			
	Vent Piping	Entire Building	75,830	SF	6	6-10 years			
Pumps									
·	Pumps - Sump-Simplex	Boiler Room	1	EA	5	2-5 years			

Category: Room Building: Main

atego	ry : Room		Б	uliaing	: wain		Building: Main					
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments					
	trative Suites/Offices		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,									
	Ceiling - Plaster/Drywall	107 Support Services- under renovation to become classroom	635	SF	7	10+ years						
	Doors - Side-lite	107 Support Services- under renovation to become classroom	40	SF	7	10+ years						
	Doors - Wood Doors inclu hw	107 Support Services- under renovation to become classroom	1	EA	7	10+ years						
	Floor - Tile	107 Support Services- under renovation to become classroom	635	SF	7	10+ years						
	Lighting - Pendent/Surface	107 Support Services- under renovation to become classroom	7	EA	7	10+ years						
	Lighting - Pendent/Surface	107 Support Services- under renovation to become classroom	1	EA	5	0-1 year	Does not work.					
	Power Distribution	107 Support Services- under renovation to become classroom	5	EA	7	10+ years						
	Storage/ Closet	107 Support Services- under renovation to become classroom	125	SF	7	10+ years						
	Walls - Plaster/Drywall	107 Support Services- under renovation to become classroom	728	SF	7	10+ years						
	Ceiling - Plaster/Drywall	211	295	SF	6	6-10 years						
	Doors - Wood Doors inclu hw	211	1	EA	6	6-10 years						
	Floor - Tile	211	295	SF	4	1-2 years	Gouges in tiles throughout					
	Lighting - Pendent/Surface	211	3	EA	7	6-10 years	-					
	Power Distribution	211	10	EA	7	6-10 years						
	Walls - Plaster/Drywall	211	650	SF	6	6-10 years						

Campus Name: Reilly Page : 6 of 53 Assessment Date: 08/16/2023



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	301A Office (above stair)	202	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	301A Office (above stair)	1	EΑ	6	6-10 years	
	Floor - Wood	301A Office (above stair)	202	SF	6	6-10 years	
	Lighting - Pendent/Surface	301A Office (above stair)	2	EA	7	6-10 years	
	Power Distribution	301A Office (above stair)	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	301A Office (above stair)	510	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	302A Office (above stair)	202	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	302A Office (above stair)	1	ĒΑ	6	6-10 years	
	Floor - Wood	302A Office (above stair)	202	SF	6	6-10 years	
	Lighting - Pendent/Surface	302A Office (above stair)	1	ĒΑ	7	6-10 years	
	Power Distribution	302A Office (above stair)	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	302A Office (above stair)	505	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	310 Gym Office	655	SF	6	6-10 years	
	Doors - Transom Window	310 Gym Office	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	310 Gym Office	1	EA	6	6-10 years	
	Floor - Tile	310 Gym Office	625	SF	6	6-10 years	
	Floor - Tile	310 Gym Office	30	SF	6	6-10 years	
	Lighting - Pendent/Surface	310 Gym Office	5	EA	7	6-10 years	
	Power Distribution	310 Gym Office	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	310 Gym Office	1,100	SF	6	6-10 years	
	Walls - Plaster/Drywall	310 Gym Office	200	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	311 Copy Room + Office	295	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	311 Copy Room + Office	295	EA	6	6-10 years	
	Floor - Tile	311 Copy Room + Office	295	SF	6	6-10 years	
	Lighting - Pendent/Surface	311 Copy Room + Office	295	EA	7	,	
			_		7	6-10 years	
	Power Distribution	311 Copy Room + Office	10	EA SF		6-10 years	
	Walls - Plaster/Drywall	311 Copy Room + Office	850	SF SF	6	6-10 years	
	Ceiling - Plaster/Drywall	312 (Peer Jury)	440		7	10+ years	
	Doors - Transom Window	312 (Peer Jury)	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	312 (Peer Jury)	1	EA	6	6-10 years	
	Floor - Tile	312 (Peer Jury)	370	SF	6	6-10 years	
	Floor - Tile	312 (Peer Jury)	70	SF	6	6-10 years	
	Lighting - Pendent/Surface	312 (Peer Jury)	5	EA	6	6-10 years	
	Power Distribution	312 (Peer Jury)	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	312 (Peer Jury)	1,010	SF	6	6-10 years	
	Work SInk	312 (Peer Jury)	1	EA	7	6-10 years	
_Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	172	EA	7	6-10 years	
	Balcony Seating	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	5,360	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	16	EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	760	SF	7	6-10 years	
	Floor - Wood	1st Floor	3,000	SF	6	6-10 years	

Campus Name: Reilly Page: 7 of 53 Assessment Date: 08/16/2023



Catego	ry : Room		Bı	uilding	: Main		030 W Condition CTIVEET, Officago, IE 00010
Carogo	. y 1 1 1 0 0 11.			<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	1,600	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EΑ	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	12	EΑ	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	2	ΕA	7	6-10 years	
	Main Floor Seating	1st Floor	514	ΕA	7	6-10 years	
	Main Floor Seating	1st Floor	50	ΕA	7	6-10 years	
	Main Floor Seating	1st Floor	50	EA	7	6-10 years	
	Sound System	1st Floor	1	ΕA	7	6-10 years	
	Stage	1st Floor	1,010	SF	6	6-10 years	
	Stage Curtain	1st Floor	3	EA	7	6-10 years	
	Stage Curtain	1st Floor	1	EA	7	6-10 years	
	Stage Lighting System	1st Floor	1	EA	5	2-5 years	
	Stage-Stairs - Wood	1st Floor	25	LF	6	2-5 years	
	Walls - Plaster/Drywall	1st Floor	8,160	SF	6	6-10 years	
	Walls - Flaster/Drywall	13(1100)	0,100	Oi	O	0-10 years	
_Gymnas	ia						
	Bleacher Seating	3rd Floor	42	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	6	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	3,140	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years	
	Floor - Wood	3rd Floor	3,146	SF	6	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	[′] 16	EΑ	7	6-10 years	
	Scoreboards	3rd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4,450	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	50	SF	7	10+ years	
1.95							
Library	AC Unit	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor 2nd Floor	48	LF	6	6-10 years	
	Casework	2nd Floor	42	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	1,500	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	1,500	SF	6	•	
	Doors - Transom Window Doors - Transom Window	2nd Floor 2nd Floor	14	SF	6	6-10 years 6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	3	EA	6	6-10 years	
	Floor - Tile	2nd Floor 2nd Floor	_	SF	6	,	
			1,500			6-10 years	
	Lighting - Pendent/Surface	2nd Floor	19	EΑ	7	6-10 years	Dage not work
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	1	EA SF	5 7	0-1 year	Does not work.
	Storage/ Closet	2110 F1001	200	SF	/	6-10 years	



Catego	ory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	300	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	950	SF	6	6-10 years	
MDF ID)F						
	Doors - Wood Doors inclu hw	in Room 300 (former storage)	1	EA	6	6-10 years	
	Finishes	in Room 300 (former storage)	140	SF	7	6-10 years	
	Other Cooling Unit	in Room 300 (former storage)	1	EA	7	6-10 years	CRAC Unit.
Mechani	ical/ Service Rooms						
	Boiler Room	1st Floor	1,327	SF	5	6-10 years	
	Janitor's Closet	1st Floor	14	SF	5	6-10 years	
	Janitor's Closet	1st Floor	14	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	755	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	500	SF	5	6-10 years	
	Vaults	1st Floor	375	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	14	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	14	SF	5	6-10 years	
	Storage Room	2nd Floor	180	SF	5	6-10 years	
	Storage Room	2nd Floor	76	SF	5	6-10 years	
	Storage Room	2nd Floor	180	SF	5	6-10 years	
	Janitor's Closet	3rd Floor	14	SF	5	6-10 years	
	Janitor's Closet	3rd Floor	14	SF	5	6-10 years	
Restroo	m						
_176311001	Accessories	105A	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	105A	65	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	105A	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	105A	65	SF	6	6-10 years	
	Lavatory	105A	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	105A	1	EA	7	6-10 years	
	Partitions	105A	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	105A	125	SF	6	6-10 years	
	Water Closet	105A 105A	123	EA	6	6-10 years	
	Accessories	1st Floor	380	SF	7	6-10 years	
				SF	7	,	
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	1st Floor	380	SF EA		6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor 1st Floor	2	SF	6 6	6-10 years	
			380	_	_	6-10 years	
	Floor Drain	1st Floor	1	EΑ	7	6-10 years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EΑ	7	6-10 years	
	Partitions	1st Floor	2	EA	7	6-10 years	
	Urinals	1st Floor	5	EA	7	6-10 years	



Category : Room		В	uilding				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	280	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	230	SF	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	75	SF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	200	SF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	5	SF	6	6-10 years	
	Water Closet	1st Floor	2	EA	7	6-10 years	
	Accessories	1st Floor Girl's NW	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girl's NW	380	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor Girl's NW	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girl's NW	380	SF	6	6-10 years	
	Floor Drain	1st Floor Girl's NW	1	EA	7	6-10 years	
	Hand Dryer	1st Floor Girl's NW	1	EΑ	7	6-10 years	
	Lavatory	1st Floor Girl's NW	1	EΑ	7	6-10 years	
	Lavatory	1st Floor Girl's NW	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor Girl's NW	5	EΑ	7	6-10 years	
	Partitions	1st Floor Girl's NW	6	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor Girl's NW	230	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor Girl's NW	230	SF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor Girl's NW	10	SF SF	6	6-10 years	
	Walls - Structural Glazed Tile Water Closet	1st Floor Girl's NW	320	SF EA	6 7	6-10 years	
	Accessories	1st Floor Girl's NW	6 30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor NW Women 1st Floor NW Women	30	SF SF		6-10 years	
	Doors - Wood Doors inclu hw	1st Floor NW Women	1	Sr EA	6 6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st Floor NW Women	30	SF	7	6-10 years 6-10 years	
	Hand Dryer	1st Floor NW Women	1	EA	7	6-10 years	
	Lavatory	1st Floor NW Women	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor NW Women	1	EA	7	6-10 years	
	Partitions	1st Floor NW Women	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor NW Women	60	SF	6	6-10 years	
	Water Closet	1st Floor NW Women	1	EA	6	6-10 years	
	Accessories	211A Unisex Toilet	64	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	211A Unisex Toilet	64	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	211A Unisex Toilet	1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	211A Unisex Toilet	13	SF	7	6-10 years	
	Floor - Tile	211A Unisex Toilet	51	SF	6	6-10 years	
	Lavatory	211A Unisex Toilet	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	211A Unisex Toilet	1	EΑ	5	0-1 year	Does not work.
	Partitions	211A Unisex Toilet	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	211A Unisex Toilet	124	SF	6	6-10 years	
	Water Closet	211A Unisex Toilet	1	EΑ	6	6-10 years	
	Accessories	2nd Floor	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	380	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	6-10 years	
			_		-		

Campus Name: Reilly Page : 10 of 53 Assessment Date: 08/16/2023



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	380	SF	6	6-10 years			
	Floor Drain	2nd Floor	1	EA	7	6-10 years			
	Hand Dryer	2nd Floor	1	EA	7	6-10 years			
	Lavatory	2nd Floor	2	EA	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years			
	Partitions	2nd Floor	2	EA	7	6-10 years			
	Urinals	2nd Floor	5	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	280	SF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	230	SF	6	6-10 years			
	Walls - Structural Glazed Tile	2nd Floor	280	SF	6	6-10 years			
	Water Closet	2nd Floor	2	EA	7	6-10 years			
	Accessories	2nd Floor	380	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	380	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	380	SF	6	6-10 years			
	Floor Drain	2nd Floor	1	EA	7	6-10 years			
	Hand Dryer	2nd Floor	1	EA	7	6-10 years			
	Lavatory	2nd Floor	1	EΑ	6	6-10 years			
	Lavatory	2nd Floor	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years			
	Partitions	2nd Floor	6	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	230	SF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	230	SF	6	6-10 years			
	Walls - Structural Glazed Tile	2nd Floor	330	SF	6	6-10 years	Updated to have all structural tile in one line		
	Water Closet	2nd Floor	6	EA	6	6-10 years			
	Accessories	311A Unisex Toilet	64	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	311A Unisex Toilet	64	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	311A Unisex Toilet	1	EA	6	6-10 years			
	Floor - Tile	311A Unisex Toilet	64	SF	6	6-10 years			
	Lavatory	311A Unisex Toilet	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	311A Unisex Toilet	1	EA	7	6-10 years			
	Partitions	311A Unisex Toilet	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	311A Unisex Toilet	124	SF	6	6-10 years			
	Water Closet	311A Unisex Toilet	1	EA	6	6-10 years			
	Accessories	3rd Floor	380	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	380	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	380	SF	6	6-10 years			
	Floor Drain	3rd Floor	1	EA	7	6-10 years			
	Hand Dryer	3rd Floor	1	EA	7	6-10 years			
	Lavatory	3rd Floor	2	EA	7	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years			
	Partitions	3rd Floor	2	EA	7	6-10 years			



Category : Room			В	uilding	: Main					
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Urinals	3rd Floor	5	EΑ	7	6-10 years				
	Walls - Concrete Block	3rd Floor	280	SF	6	6-10 years				
	Walls - Plaster/Drywall	3rd Floor	330	SF	6	6-10 years				
	Walls - Structural Glazed Tile	3rd Floor	280	SF	6	6-10 years				
	Water Closet	3rd Floor	2	EA	7	6-10 years				
	Accessories	3rd Floor	380	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	3rd Floor	380	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years				
	Floor - Tile Ceramic/ Porcelain	3rd Floor	380	SF	6	6-10 years				
	Floor Drain	3rd Floor	1	EA	7	6-10 years				
	Hand Dryer	3rd Floor	1	EA	7	6-10 years				
	Lavatory	3rd Floor	2	EA	7	6-10 years				
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	6-10 years				
	Partitions	3rd Floor	6	EA	7	6-10 years				
	Walls - Concrete Block	3rd Floor	230	SF	6	6-10 years				
	Walls - Plaster/Drywall	3rd Floor	330	SF	6	6-10 years				
	Walls - Structural Glazed Tile	3rd Floor	30	SF	6	6-10 years				
	Walls - Structural Glazed Tile	3rd Floor	330	SF	6	6-10 years				
	Water Closet	3rd Floor	6	EA	7	6-10 years				
	Accessories	Basement North (Pump Room on plan) Toilet	25	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Basement North (Pump Room on plan) Toilet	25	SF	6	6-10 years				
	Doors - Transom Window	Basement North (Pump Room on plan) Toilet	10	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	Basement North (Pump Room on plan) Toilet	1	EA	6	6-10 years				
	Floor - Concrete Epoxy/ Painted	Basement North (Pump Room on plan) Toilet	25	SF	7	6-10 years				
	Lighting - Wall Mounted	Basement North (Pump Room on plan) Toilet	1	EA	6	6-10 years				
	Walls - Plaster/Drywall	Basement North (Pump Room on plan) Toilet	50	SF	6	6-10 years				
	Water Closet	Basement North (Pump Room on plan) Toilet	1	EA	7	6-10 years				
<u> </u>			_							

Category : Classroom

Building: Main

Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #101 (Band Room)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	9	LF	6	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	868	SF	7	6-10 years	
Chalk Board	1st Floor	20	LF	4	2-5 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	868	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	7	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,310	SF	6	6-10 years	
Classroo	om #102 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	868	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
					-		
	Floor - Tile	1st Floor	867	SF	6	6-10 years	Minates desired
	Floor - Tile	1st Floor	1	SF	4	0-1 year	Missing drain cover
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,310	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	815	SF	7	6-10 years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	7	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	. 1	EA	6	6-10 years	
	Floor - Tile	1st Floor	815	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	
	Marker Board	1st Floor	9	LF	7	6-10 years	
		1st Floor	60	SF	7		
	Storage/ Closet Walls - Plaster/Drywall			SF SF		6-10 years	
	Work Sink	1st Floor 1st Floor	1,100 1	SF EA	7 7	6-10 years 6-10 years	
0 1						·	
Jassroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	876	SF	7	6-10 years	
	Chalk Board	1st Floor	9	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	7	SF	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	876	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Does not work.
	Marker Board	1st Floor	9	LF	6	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,200	SF	6	6-10 years	
Classroc	om #105 (Dance Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	880	SF	7	6-10 years	
	Doors - Transom Window	1st Floor	7	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	880	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	13	EA	5	0-10 years 0-1 year	Does not work.
	Marker Board	1st Floor		LF	_		Does not work.
	Storage/ Closet	1st Floor	18 60	SF	7 7	6-10 years	
				SF SF		6-10 years	
	Wall Mirrors	1st Floor 1st Floor	18 1,100	SF SF	7 7	6-10 years	
	Walls - Plaster/Drywall	ISI FIOOI	1,100	SF	,	6-10 years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	855	SF	6	6-10 years	
	Chalk Board	1st Floor	9	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	7	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	855	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	19	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,220	SF	7	6-10 years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	868	SF	7	6-10 years	
	Doors - Transom Window	1st Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	14	EA	6	6-10 years	
	Floor - Tile	1st Floor	868	SF	6	-	
					7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	1	6-10 years	

Campus Name: Reilly Page : 14 of 53 Assessment Date: 08/16/2023



			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,310	SF	6	6-10 years	
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	852	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	14	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	6-10 years	
	Floor - Wood	2nd Floor	852	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	7	6-10 years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classron	m #202 (Regular Classroom)						
01000100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	852	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	14	EA	6	6-10 years	
	Floor - Wood Doors including	2nd Floor	852	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	•	
	Marker Board	2nd Floor 2nd Floor	10	LF	7	6-10 years	
		2nd Floor 2nd Floor	44	SF	7	6-10 years	
	Storage/ Closet Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,300	SF SF	7	6-10 years 6-10 years	
	·	2110 1 1001	1,000	O.	•	o lo youlo	
Classroo	m #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	873	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	873	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	58	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,196	SF	7	6-10 years	
Classroo	m #204 (Regular Classroom)						
<u>-</u>	AC Units	2nd Floor	1	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	14	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	880	SF	6	6-10 years	
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	880	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	7	6-10 years	
	Work Sink	2nd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	875	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	875	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface Lighting - Pendent/Surface	2nd Floor	13	EA	4	0-10 years 0-1 year	Lens loose from light
				LF		•	Lens loose from light
	Marker Board	2nd Floor	7		7	6-10 years	
	Storage/ Closet	2nd Floor	65	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,182	SF	6	6-10 years	
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	865	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	865	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,230	SF	6	6-10 years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	852	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	14	SF	6	<u>-</u>	
				SF EA		6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĽΑ	6	6-10 years	

Campus Name: Reilly Page : 16 of 53 Assessment Date: 08/16/2023



Catego	ory : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	852	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	7	6-10 years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	852	SF	7	6-10 years	
	Chalk Board	2nd Floor	24	ĹF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	2nd Floor	852	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	7	6-10 years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	6	6-10 years	
Classroo	om #212 (Regular Classroom)						
Classici	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	290	SF	7	6-10 years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	290	SF	4	1-2 years	Holes in tiles
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years	rioles in tiles
	Marker Board	2nd Floor	4	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	635	SF	7	6-10 years	
	walls - i laster/brywall	2110 1 1001	000	Oi	,	0-10 years	
Classroo	om #300 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	914	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	854	SF	6	6-10 years	
	Floor - Tile	3rd Floor	60	SF	4	1-2 years	Cracking and broken tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	82	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,500	SF	6	6-10 years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	



	ry : Classroom		В				
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	808	SF	6	6-10 years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	808	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	6-10 years	
_Classroc	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	808	SF	6	6-10 years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	3rd Floor	808	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	13	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,182	SF	6	6-10 years	
_Classroc	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	812	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	3rd Floor	812	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	6-10 years	
_Classroc	m #304 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	812	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	812	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	6-10 years	
	Work Sink	3rd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	812	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	812	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
				SF	7	,	
	Storage/ Closet Walls - Plaster/Drywall	3rd Floor 3rd Floor	60 1,282	SF SF	6	6-10 years 6-10 years	
	Walls - Flaster/Drywall	314 1 1001	1,202	01	U	0-10 years	
Classroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	812	SF	6	6-10 years	
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	812	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	6-10 years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	808	SF	7	6-10 years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	14	EA	6	6-10 years	
	Floor - Wood Doors Inclu hw	3rd Floor 3rd Floor	808	SF	6	6-10 years 6-10 years	
	FIGOT - VVOOO	310 F100f	808	O.F.	n	n= III VAAIS	



Category	y : Classroom		E	Building	: Main		
						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	7	6-10 years	
Classroon	n #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	808	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	14	SF	6		
			14			6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	808	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,270	SF	6	6-10 years	
Classroon	n #326 (Special Education)						
210331001	Ceiling - Plaster/Drywall	3rd Floor	330	SF	6	6 10 years	
	,				6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years	
	Floor - Tile	3rd Floor	330	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	660	SF	6	6-10 years	
Category	y : Interior		Е	Building	: Main		
	Many True	Landin	0	LIOM	DI-	Recommend	0
Group Corridor	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
20111001	Ceiling - Plaster/Drywall	2nd Floor	4,860	SF	6	6-10 years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	6-10 years	
	Drinking Fountains - Triple Fountain	2nd Floor	1	EA	7	6-10 years	Updated to match current observations
	Floor - Asphalt Floor	2nd Floor	4,860	SF	7	6-10 years	0000174410110
	Lighting - Pendent/Surface	2nd Floor	34	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	14	EA	6	10+ years	
	Student Lockers - Two Tiers	2nd Floor	80	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	7,530	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	4,866	SF	7	6-10 years	
	Drinking Fountains - Triple Fountain	3rd Floor	4,000	EA	7	6-10 years	
					7		
	Floor - Asphalt Floor	3rd Floor	4,866	SF	<i>'</i>	6-10 years	
		7rd -100r	33	EΑ	7	6-10 years	
	Lighting - Pendent/Surface Student Lockers - Two Tiers	3rd Floor 3rd Floor	158	EΑ	6	6-10 years	

Campus Name: Reilly Page : 20 of 53 Assessment Date: 08/16/2023



Catego	ry : Interior		В	uilding	: Main		· • • ·
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	7,880	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	NE Vestibule	50	SF	6	6-10 years	
	Doors - Transom Window	NE Vestibule	28	SF	6	6-10 years	
	Doors - Wood Doors include hw	NE Vestibule	4	EA	6	6-10 years	
	Floor - Tile Quarry	NE Vestibule	50	SF	6	6-10 years	
	Lighting - Pendent/Surface	NE Vestibule	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	NE Vestibule	22	SF	6	6-10 years	
	Walls - Structural Glazed Tile	NE Vestibule	60	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	NW Vestibule	50	SF	6	6-10 years	
	Doors - Transom Window	NW Vestibule	30	SF	6	6-10 years	
	Doors - Wood Doors include hw	NW Vestibule	4	EA	6	6-10 years	
	Floor - Tile Quarry	NW Vestibule	50	SF	6	6-10 years	
	Lighting - Pendent/Surface	NW Vestibule	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	NW Vestibule	25	SF	6	6-10 years	
	Walls - Structural Glazed Tile	NW Vestibule	55	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	SE Vestibule (Link to Annex)	200	SF	6	6-10 years	
	Doors - Side-lite	SE Vestibule (Link to Annex)	24	SF	6	6-10 years	
	Doors - Transom Window	SE Vestibule (Link to Annex)	64	SF	6	6-10 years	
	Doors - Wood Doors include hw	SE Vestibule (Link to Annex)	3	ĒΑ	6	6-10 years	
	Floor - Tile Quarry	SE Vestibule (Link to Annex)	200	SF	6	6-10 years	
	Lighting - Pendent/Surface	SE Vestibule (Link to Annex)	3	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	SE Vestibule (Link to Annex)	95	SF	6	6-10 years	
	Walls - Structural Glazed Tile	SE Vestibule (Link to Annex)	115	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	SW Vestibule	255	SF	6	6-10 years	
	Doors - Side-lite	SW Vestibule	24	SF	6	6-10 years	
	Doors - Transom Window	SW Vestibule	64	SF	6	6-10 years	
	Doors - Wood Doors include hw	SW Vestibule	3	EA	6	6-10 years	
	Floor - Tile Quarry	SW Vestibule	255	SF	6	6-10 years	
	Lighting - Pendent/Surface	SW Vestibule	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	SW Vestibule	115	SF	6	6-10 years	
	Walls - Structural Glazed Tile	SW Vestibule	160	SF	6	6-10 years	
	Trans Chactara Siazoa Ino	311 133113413	100	٥.	J	o lo youlo	
Safety							
	Metal Detector	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
O							
_Stairs	Coiling Plantar/Prevall	NE Stair	640	SF	7	6 10 4000	
	Ceiling - Plaster/Drywall	NE Stair	640		7	6-10 years	
	Floor - Asphalt	NE Stair	780 146	SF	7	6-10 years	
	Handrails	NE Stair	146	LF	7	6-10 years	
	Lighting - Pendent/Surface	NE Stair	5	EΑ	7	6-10 years	
	Lighting - Wall Mounted	NE Stair	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	NE Stair	2,800	SF	6	6-10 years	
	Walls - Plaster/Drywall	NE Stair	200	SF	6	6-10 years	

Campus Name: Reilly Page : 21 of 53 Assessment Date: 08/16/2023



Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	NW Stairs	650	SF	6	6-10 years	
	Floor - Asphalt	NW Stairs	800	SF	7	6-10 years	
	Handrails	NW Stairs	152	LF	7	6-10 years	
	Lighting - Pendent/Surface	NW Stairs	6	EA	7	6-10 years	
	Stairs - Asphalt	NW Stairs	425	LF	7	6-10 years	
	Walls - Plaster/Drywall	NW Stairs	3,000	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	SE Stairs	420	SF	6	6-10 years	
	Floor - Asphalt	SE Stairs	718	SF	7	6-10 years	
	Handrails	SE Stairs	62	LF	7	6-10 years	
	Lighting - Pendent/Surface	SE Stairs	10	EA	7	6-10 years	
	Stairs - Asphalt	SE Stairs	380	LF	7	6-10 years	
	Walls - Plaster/Drywall	SE Stairs	1,910	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	SW Stair	430	SF	6	6-10 years	
	Floor - Asphalt	SW Stair	735	SF	7	6-10 years	
	Handrails	SW Stair	65	LF	7	6-10 years	
	Lighting - Pendent/Surface	SW Stair	10	EA	7	6-10 years	
	Stairs - Asphalt	SW Stair	400	LF	7	6-10 years	
	Walls - Plaster/Drywall	SW Stair	2,000	SF	6	6-10 years	



Category: Exterior Building: Linked Addition

Catego	ry : Exterior		Б	ullaing	: Linked	Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 S - Addition	1	EA	7	6-10 years	
	Exterior Doors - Side lite	1 S - Addition	2	EA	6	6-10 years	
	Exterior Doors - Store Front	1 S - Addition	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	1 S - Addition	9	EA	6	6-10 years	
	Power Door Operator and Controls	1 S - Addition	1	EA	7	10+ years	
	Power Door Operator and Controls	1 S - Addition	1	EA	4	0-1 year	Door operator is not functioning for engineers information. Only the
	Futurion Doors - Futurion Otani Door	4.4	4	_^	•	0.40	exterior doors function.
	Exterior Doors - Exterior Steel Door	11	1	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	12 NE Addition	2	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	13 NE - Addition	1	EΑ	7	6-10 years	
	Exterior Doors - Exterior Steel Door	14	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	15 - 2nd Floor Fire Escape	1	EA	6	10+ years	Fire Escape
	Exterior Doors - Transom Lite	15 - 2nd Floor Fire Escape	1	ΕA	7	10+ years	Fire Escape
	Exterior Doors - Exterior Steel Door	16-Roof G	1	EA	6	10+ years	
	Exterior Doors - Store Front	2 W - Addition	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	2 W - Addition	6	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	3 NW - Addition	1	EA	6	6-10 years	Surface corrosion at base of frame
	Exterior Doors - Transom Lite	3 NW - Addition	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	4 N Addition	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	4 N Addition	1	EA	6	6-10 years	
	Entrance Control - Audio and Video	5 N - Addition	1	EA	7	6-10 years	
	Exterior Doors - Store Front	5 N - Addition	1	EA	6	6-10 years	
Fire Esca	ape						
	Exterior Doors - Exterior Steel Door	North Façade	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	North Façade	1	EA	7	10+ years	
	Fire Escape	North Façade	63	LF	6	6-10 years	House plants are being kept in the path of egress
	Paints	North Façade	63	LF	7	10+ years	•
Foundati	on						
	Foundation - Concrete	Entire Building	605	LF	7	10+ years	
	Foundation - Concrete	Entire Building	80	LF	4	0-1 year	Up-heaved slab, settlement of foundation wall in the cafeteria. Cracked walls.
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	1,130	SF	7	10+ years	
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	33,646	SF	7	10+ years	

Campus Name: Reilly Page : 23 of 53 Assessment Date: 08/16/2023



Category : Exterior			В	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	21	EA	6	6-10 years	
Roof Sys	stem						
	Access Ladder - Metal	G	1	EA	7	10+ years	
	Coping - Stone	G	648	LF	6	2-5 years	
	Downspouts - Interior Downspouts	G	153	LF	6	6-10 years	
	Parapet - 16" - 30" Height	G	648	LF	6	6-10 years	
	Roof - Modified Bitumen	G	16,808	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	G	16,808	SF	7	10+ years	
	Downspouts - Exterior Downspouts	Н	48	LF	6	10+ years	
	Roof - Metal	H	1,408	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Н	1,408	SF	7	10+ years	
	Downspouts - Exterior Downspouts	1	12	LF	6	6-10 years	
	Roof - Metal	i	264	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	İ	264	SF	7	10+ years	
	Downspouts - Exterior Downspouts	.I	12	LF	6	10+ years	
	Roof - Metal	Ĭ	288	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	J	288	SF	7	10+ years	
	Concrete Topping	·			-	•	
	Downspouts - Exterior Downspouts	K	16	LF	6	6-10 years	
	Roof - Metal	K	1,160	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	К	1,160	SF	7	10+ years	
Nalls							
	Exterior Walls - Concrete Block	Entire Building	1,173	SF	6	6-10 years	
	Exterior Walls - Concrete Block	Entire Building	10,000	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,700	SF	6	10+ years	
Vindows	3						
	Clerestory - Glass Double-Pane	Entire Building	640	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	3,158	SF	6	6-10 years	
	Lintels - Steel	Entire Building	846	ĹF	6	10+ years	
	Windows - Decorative	Entire Building	1,683	SF	6	10+ years	
	Windows - Louver	Entire Building	432	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,632	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Linked	I Addition	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



3CI 10013							650 W School STREET, Chicago, IL 6
_						Replacement	
mergency System							
	ransfer Switch	Electrical Room	1	EA	6	2-5 years	
	stem - CCTV	Entire Building	34,776	SF	6	6-10 years	
	stem - Intrusion Detection	Entire Building	34,776	SF	5	2-5 years	
Exit Signs -	Corridors and Stairs	Entire Building	10	EA	6	6-10 years	
Exit Signs -	Lunchroom	Entire Building	4	EΑ	6	6-10 years	
Emergency	Battery Packs - Corridors and	Entire Building	11	EA	6	6-10 years	
Stairs	•	S .				,	
Emergency	Battery Packs - Lunchrooms	Entire Building	3	EΑ	6	6-10 years	
	A/C Power - Corridors and	Entire Building	7,561	SF	6	10+ years	
Stairs		g	1,00		•	, , , , , , , , , , , , , , , , , , , ,	
	A/C Power - Lunchrooms	Entire Building	3,896	SF	6	10+ years	
ain Service							
	cal Service - 1200 A	Electrical Room	1	EA	7	10+ years	
120/208/3PI			·		•	. o . y cano	
	cal Service - 800 A and	Electrical Room	1	EA	7	10+ years	
277/480/3PI		2.00thodi 1.00th	·	_, 、	•	ioi youlo	
	t Electrical Service for	Electrical Room	1	EA	6	10+ years	
emergency		Licetical Room	· ·	L/\	O	101 years	
PA System	power	Entire Building	34,776	SF	6	6-10 years	
i A Oystein		Littile Ballaling	34,770	Oi	U	0-10 years	
wer Distribution							
Lighting and	Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Power Panels - 100 A	Entire Building	5	ΕA	6	10+ years	
	Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	
	ution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	rs - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
Hansionnei	13 - 211/400 - 120/200	Entire Ballating		LA	O	10+ years	
tegory : Fire Pro	tection		В	uilding	: Linked	Addition	
			0			Recommend	0
oup Item - Type		Location	Quantity	UOM	Rank	Replacement	Comments
e Alarm							
Fire Alarm F		Entire Building	1	EA	6	2-5 years	
	Strobe Lights	Entire Building	34,776	SF	4	0-1 year	None in classrooms
Fire Alarm_S		Entire Building	34,776	SF	5	2-5 years	
Fire Pump C	Controller	Entire Building	1	EA	5	2-5 years	
mp Room Assembly	V						
Fire Pump -	•	Basement	1	EA	5	2-5 years	
Jockey Pum		Basement	1	EΑ	6	2-5 years	
cono, i um	TF	_ 3.00	•		Ŭ	_ 5 ,00.0	
rinkler System							
Sprinkler He	eads	Entire Building	34,776	SF	7	6-10 years	



Catego	ry : Fire Protection		В	uildina	: Linked	d Addition	1650 W School STREET, Chicago, IL 60618
J 2 9 C			_	9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sprinkler Piping	Entire Building	34,776	SF	6	6-10 years	
	Wet Sprinkler System	Entire Building	34,776	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Chiller-Air Cooled-Screw Type-Roof Mounted - 101 - 200 tons	Entire Building	1	EA	6	10+ years	
	Glycol Feed	Entire Building	1	EA	6	6-10 years	
Air Hand	ling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Entire Building	1	EA	5	6-10 years	AHU1 Serves Addition
	Air Intake	Entire Building	1	EA	6	6-10 years	
	VAV Box	Entire Building	21	EA	6	6-10 years	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	5	6-10 years	
Boiler Sy	vstems						
	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Boiler Room	2	EA	6	2-5 years	
	Chemical Pot Feeder	Boiler Room	1	EA	5	2-5 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Dual Temperature Pump	Boiler Room	1	EA	5	2-5 years	
	Dual Temperature Pump	Boiler Room	1	EA	5	2-5 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	1	EA	5	6-10 years	
Heating	Devices						
	Fin Tube - Hot Water	Entire Building	170	LF	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	
Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	1,600	LF	6	10+ years	
	Dual Temperature Pump - Less than 10	Mechanical Room	1	EA	6	2-5 years	

Campus Name: Reilly Page : 26 of 53 Assessment Date: 08/16/2023



Catego	ry : Mechanical		В	uilding	: Linked	d Addition	<u> </u>
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Dual Temperature Pump - Less than 10	Mechanical Room	1	EA	6	2-5 years	
Tempera	ature Control						
•	DDC System	Entire Building	34,776	SF	5	6-10 years	
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	Serves unit heaters.
	Thermostats - DDC	Entire Building	21	EA	6	6-10 years	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water & Chilled Water Coils	Entire Building	19	EA	5	2-5 years	
_Ventilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	10+ years	

Category: Plumbing Building: Linked Addition

_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	34,776	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	34,776	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	34,776	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	34,776	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	34,776	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	34,776	SF	6	10+ years	
	Sanitary Piping	Entire Building	34,776	SF	6	10+ years	
	Storm Piping	Entire Building	34,776	SF	6	10+ years	
	Vent Piping	Entire Building	34,776	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	6	6-10 years	PB1

Page : 27 of 53 Campus Name: Reilly Assessment Date: 08/16/2023



Catego	ry : Plumbing		Ві	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pumps - Ejector-Duplex	Basement	1	EA	5	6-10 years	Mechanical Room
	Pumps - Sump-Duplex	Basement	1	EA	5	6-10 years	Mechanical Room
	Pumps - Sump-Simplex	Basement	1	EA	5	6-10 years	Under elevator

Catego	ry : Room		В	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	Ceiling - Lay-in	1st Floor Faculty Lounge	598	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor Faculty Lounge	1	EA	7	6-10 years	
	Floor - Tile	1st Floor Faculty Lounge	598	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor Faculty Lounge	6	EA	7	6-10 years	
	Power Distribution	1st Floor Faculty Lounge	15	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor Faculty Lounge	339	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor Faculty Lounge	798	SF	6	6-10 years	
	Work Sink	1st Floor Faculty Lounge	1	EA	7	6-10 years	
	Ceiling - Lay-in	221 - Office Second Floor	460	SF	6	6-10 years	
	Doors - Side-lite	221 - Office Second Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	221 - Office Second Floor	1	EA	6	6-10 years	
	Floor - Tile	221 - Office Second Floor	460	SF	7	6-10 years	
	Lighting - Lay-in	221 - Office Second Floor	6	EA	7	6-10 years	
	Power Distribution	221 - Office Second Floor	14	EA	7	6-10 years	
	Walls - Concrete Block	221 - Office Second Floor	512	SF	6	6-10 years	
	Walls - Plaster/Drywall	221 - Office Second Floor	352	SF	6	6-10 years	
	Ceiling - Lay-in	Assistant Principal's Office (119 on plan)	144	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Assistant Principal's Office (119 on plan)	1	EA	7	6-10 years	
	Floor - Tile	Assistant Principal's Office (119 on plan)	144	SF	7	6-10 years	
	Lighting - Lay-in	Assistant Principal's Office (119 on plan)	1	EA	7	6-10 years	
	Power Distribution	Assistant Principal's Office (119 on plan)	6	EA	7	6-10 years	
	Walls - Concrete Block	Assistant Principal's Office (119 on plan)	20	SF	6	6-10 years	
	Walls - Plaster/Drywall	Assistant Principal's Office (119 on plan)	259	SF	6	6-10 years	
	Ceiling - Lay-in	Basement Engineer's Office	60	SF	7	6-10 years	
	Doors - Steel Doors incl hw	Basement Engineer's Office	1	EΑ	7	6-10 years	
	Floor - Tile	Basement Engineer's Office	60	SF	7	6-10 years	
	Lighting - Lay-in	Basement Engineer's Office	1	EA	7	6-10 years	
	Power Distribution	Basement Engineer's Office	2	EΑ	7	6-10 years	
	Walls - Concrete Block	Basement Engineer's Office	198	SF	7	6-10 years	
		= 3.00 =g00. 0 000	.00		•	3 .0 ,00.0	



Catego	ry : Room		В	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Conference Room	292	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Conference Room	1	EA	6	6-10 years	
	Floor - Tile	Conference Room	292	SF	7	6-10 years	
	Lighting - Lay-in	Conference Room	3	EA	7	6-10 years	
	Power Distribution	Conference Room	8	EA	7	6-10 years	
	Walls - Concrete Block	Conference Room	120	SF	7	6-10 years	
	Walls - Plaster/Drywall	Conference Room	579	SF	7	6-10 years	
	Ceiling - Lay-in	Counselor's Office (121 on plan)	144	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Counselor's Office (121 on plan)	1	EA	6	6-10 years	
	Floor - Tile	Counselor's Office (121 on plan)	144	SF	7	6-10 years	
	Lighting - Lay-in	Counselor's Office (121 on plan)	1	EA	7	6-10 years	
	Power Distribution	Counselor's Office (121 on plan)	8	EA	7	6-10 years	
	Walls - Concrete Block	Counselor's Office (121 on plan)	20	SF	7	6-10 years	
	Walls - Plaster/Drywall	Counselor's Office (121 on plan)	459	SF	6	6-10 years	
	Ceiling - Lay-in	Kitchen Office	105	SF	6	6-10 years	
	Ceiling - Lay-in	Kitchen Office	8	SF	4	1-2 years	Water damage
	Doors - Steel Doors incl hw	Kitchen Office	1	EA	6	6-10 years	· ·
	Floor - Tile	Kitchen Office	113	SF	7	6-10 years	
	Lighting - Lay-in	Kitchen Office	2	EA	7	6-10 years	
	Power Distribution	Kitchen Office	6	EA	7	6-10 years	
	Walls - Concrete Block	Kitchen Office	263	SF	7	6-10 years	
	Ceiling - Lay-in	Main Office	503	SF	6	6-10 years	
	Doors - Store Front	Main Office	1	EA	6	6-10 years	
	Floor - Tile	Main Office	503	SF	6	6-10 years	
	Lighting - Lay-in	Main Office	6	EA	7	6-10 years	
	Power Distribution	Main Office	12	EA	7	6-10 years	
	Storage/ Closet	Main Office	12	SF	7	6-10 years	
	Walls - Concrete Block	Main Office	380	SF	6	6-10 years	
	Walls - Plaster/Drywall	Main Office	354	SF	6	6-10 years	
	Ceiling - Lay-in	Main Office - Vault/Work	158	SF	7	6-10 years	
	,	Room/Storage				•	
	Doors - Steel Doors incl hw	Main Office - Vault/Work	1	EA	7	6-10 years	
		Room/Storage				•	
	Floor - Tile	Main Office - Vault/Work	158	SF	7	6-10 years	
		Room/Storage				•	
	Lighting - Lay-in	Main Office - Vault/Work	3	EA	7	6-10 years	
		Room/Storage				•	
	Power Distribution	Main Office - Vault/Work	10	EA	7	6-10 years	
		Room/Storage				•	
	Walls - Concrete Block	Main Office - Vault/Work	395	SF	6	6-10 years	
		Room/Storage				•	
	Work SInk	Main Office - Vault/Work	1	EA	7	6-10 years	
		Room/Storage				,	
	Ceiling - Lay-in	Office 1 - Library Office / Work	142	SF	6	6-10 years	
	•	·				•	

Campus Name: Reilly Page : 29 of 53 Assessment Date: 08/16/2023



Catego	ry : Room		В	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Room					
	Doors - Wood Doors inclu hw	Office 1 - Library Office / Work	1	EA	7	6-10 years	
		Room			_		
	Floor - Tile	Office 1 - Library Office / Work	142	SF	7	6-10 years	
	Linkston Laurin	Room	0	_^	7	0.40	
	Lighting - Lay-in	Office 1 - Library Office / Work Room	2	EA	7	6-10 years	
	Power Distribution	Office 1 - Library Office / Work	6	EA	7	6-10 years	
	1 Ower Distribution	Room	U	LA	,	0-10 years	
	Walls - Concrete Block	Office 1 - Library Office / Work	104	SF	6	6-10 years	
	Traile Corlorate Blook	Room	101	O.	Ŭ	o io youio	
	Walls - Plaster/Drywall	Office 1 - Library Office / Work	100	SF	6	6-10 years	
	•	Room				,	
	Work SInk	Office 1 - Library Office / Work	1	EA	7	6-10 years	
		Room					
	Ceiling - Lay-in	Principal's Office (120 on plan)	144	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Principal's Office (120 on plan)	1	EA	7	6-10 years	
	Floor - Tile	Principal's Office (120 on plan)	144	SF	7	6-10 years	
	Lighting - Lay-in	Principal's Office (120 on plan)	1	EA	7	6-10 years	
	Power Distribution	Principal's Office (120 on plan)	8	EA	7	6-10 years	
	Walls - Concrete Block	Principal's Office (120 on plan)	20	SF	6	6-10 years	
	Walls - Plaster/Drywall	Principal's Office (120 on plan)	259	SF	6	6-10 years	
	Ceiling - Lay-in	Student Services	103	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Student Services	1	EA	6	6-10 years	
	Floor - Tile	Student Services	103	SF	7	6-10 years	
	Lighting - Lay-in	Student Services	1	EA	7	6-10 years	
	Power Distribution	Student Services	4	EA	7	6-10 years	
	Walls - Concrete Block	Student Services	219	SF	7	6-10 years	
	Walls - Plaster/Drywall	Student Services	59	SF	7	6-10 years	
	Work SInk	Student Services	1	EA	7	6-10 years	
						•	
Kitchen							
	Ceiling - Plaster/Drywall	First Floor near Mechanical Room	940	SF	7	6-10 years	
	Doors - Steel Doors incl hw	First Floor near Mechanical Room	3	EA	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	First Floor near Mechanical Room	940	SF	7	6-10 years	
	Lighting - Lay-in	First Floor near Mechanical Room	15	ĒΑ	7	6-10 years	
	Serving Line	First Floor near Mechanical Room	12	LF	7	6-10 years	
	Walls - Concrete Block	First Floor near Mechanical Room	1,550	SF	7	6-10 years	
			•			,	
Library							
•	Casework	2nd Floor	57	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,551	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	. 2	EA	7	6-10 years	
	Floor - Tile	2nd Floor	1,551	SF	6	6-10 years	
						-	



Catego	ry : Room		В	uilding	: Linked	d Addition	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Lay-in	2nd Floor	19	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor	160	SF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	526	SF	6	6-10 years	
				SF			
	Walls - Plaster/Drywall	2nd Floor	494	SF	6	6-10 years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,500	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	742	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	6-10 years	
				SF		•	
	Floor - Tile	1st Floor	2,000		7	6-10 years	0.14
	Floor - Tile	1st Floor	242	SF	4	0-1 year	Subfloor sinking and cracking
	Lighting - Lay-in	1st Floor	30	EA	7	6-10 years	
	Serving Line	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	982	SF	6	6-10 years	
	Walls - Metal Panel	1st Floor	702	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	470	SF	6	6-10 years	
	walls Tlastel/Diywall	13(1100)	470	O.	O	o ro years	
IDF_ID							
	Doors - Wood Doors inclu hw	Storage Room next to Classroom 114. Not in the Basement	1	EA	7	6-10 years	
	Finishes	Storage Room next to Classroom 114. Not in the Basement	22	SF	5	6-10 years	Missing ceiling tile.
	Other Cooling Unit	Storage Room next to Classroom 114. Not in the Basement	1	EA	7	6-10 years	
/lechan	ical/ Service Rooms						
ICCHAIL	Janitor's Closet	2nd Floor	15	SF	5	10	Motor domage to eailing
				SF SF		10+ years	Water damage to ceiling
	Mechanical/ Service Rooms	2nd Floor	425		7	10+ years	
	Storage Room	2nd Floor	30	SF	7	10+ years	
	Storage Room	2nd Floor	82	SF	7	10+ years	
	Janitor's Closet	Basement	30	SF	7	6-10 years	
	Janitor's Closet	Basement	16	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	208	SF	7	6-10 years	Electrical Room
	Mechanical/ Service Rooms	Basement	352	SF	7	6-10 years	Electrical Room
		Basement	31	SF	7	6-10 years	Elevator Equipment
	Machanical/Sarvica Doome				7 7		Main Basement
	Mechanical/ Service Rooms		E40			6-10 years	iviain basement
	Mechanical/ Service Rooms	Basement	510	SF		•	
	Mechanical/ Service Rooms Storage Room	Basement Basement	90	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement				•	
estroo	Mechanical/ Service Rooms Storage Room Storage Room	Basement Basement	90	SF	5	6-10 years	
estroo	Mechanical/ Service Rooms Storage Room Storage Room	Basement Basement	90	SF	5	6-10 years	



Catego	Category : Room			Building : Linked Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	111A- under renovation	1	EΑ	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	111A- under renovation	30	SF	7	6-10 years			
	Hand Dryer	111A- under renovation	1	EΑ	7	6-10 years			
	Lavatory	111A- under renovation	1	EΑ	7	6-10 years			
	Lighting - Pendent/Surface	111A- under renovation	1	EA	5	0-1 year	Switch panel loose and moves when		
	Malla Tila Carania/ Danadaia	4444		0.5	-	0.40	pressed		
	Walls - Tile Ceramic/ Porcelain	111A- under renovation	55	SF	7	6-10 years			
	Water Closet	111A- under renovation	1	EA	7	6-10 years			
	Accessories	113/112 Shared	57	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	113/112 Shared	57	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	113/112 Shared	2	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	113/112 Shared	57	SF	7	6-10 years			
	Lavatory	113/112 Shared	1	EΑ	7	6-10 years			
	Lighting - Pendent/Surface	113/112 Shared	2	EΑ	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	113/112 Shared	112	SF	7	6-10 years			
	Water Closet	113/112 Shared	1	EΑ	7	6-10 years			
	Accessories	114A	30	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	114A	30	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	114A	1	EA	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	114A	30	SF	7	6-10 years			
	Lavatory	114A	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	114A	1	EA	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	114A	55	SF	7	6-10 years			
	Water Closet	114A 114A		EA	7				
			1			6-10 years			
	Accessories	1st Floor Mens	131	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Mens	131	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor Mens	1	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Mens	131	SF	6	6-10 years			
	Floor Drain	1st Floor Mens	1	EA	7	6-10 years			
	Lavatory	1st Floor Mens	2	EΑ	7	6-10 years			
	Lighting - Lay-in	1st Floor Mens	2	EΑ	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor Mens	5	EΑ	7	6-10 years			
	Partitions	1st Floor Mens	1	EΑ	7	6-10 years			
	Urinals	1st Floor Mens	1	EΑ	7	6-10 years			
	Walls - Concrete Block	1st Floor Mens	294	SF	6	6-10 years			
	Walls - Tile Ceramic/ Porcelain	1st Floor Mens	117	SF	6	6-10 years			
	Water Closet	1st Floor Mens	1	ĒΑ	7	6-10 years			
	Accessories	1st Floor Womens	131	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Womens	131	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor Womens	131	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Womens	131	SF	7				
						6-10 years			
	Floor Drain	1st Floor Womens	1	EΑ	7	6-10 years			
	Lavatory	1st Floor Womens	2	EA	7	6-10 years			
	Lighting - Lay-in	1st Floor Womens	2	EA	7	6-10 years			

Campus Name: Reilly Page : 32 of 53 Assessment Date: 08/16/2023



Category : Room		В						
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	1st Floor Womens	4	EA	7	6-10 years		
	Partitions	1st Floor Womens	2	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor Womens	194	SF	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	1st Floor Womens	117	SF	7	6-10 years		
	Water Closet	1st Floor Womens	2	EA	6	6-10 years		
	Accessories	2nd Floor	262	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	262	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	262	SF	6	6-10 years		
	Floor Drain	2nd Floor	1	EA	7	6-10 years		
	Hand Dryer	2nd Floor	1	EA	7	6-10 years		
	Lavatory	2nd Floor	2	EA	6	6-10 years		
	Lighting - Lay-in	2nd Floor	4	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years		
	Partitions	2nd Floor	2	EA	7	6-10 years		
	Urinals	2nd Floor	4	EΑ	7	6-10 years		
	Walls - Concrete Block	2nd Floor	475	SF	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	250	SF	6	6-10 years		
	Water Closet	2nd Floor	2	EA	7	6-10 years		
	Accessories	2nd Floor	262	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	262	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	262	SF	7	6-10 years		
	Floor Drain	2nd Floor	1	EA	7	6-10 years		
	Hand Dryer	2nd Floor	1	EA	7	6-10 years		
	Lavatory	2nd Floor	2	EA	6	6-10 years		
	Lighting - Lay-in	2nd Floor 2nd Floor	5	EA	7	6-10 years		
	Lighting - Lay-iii Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years		
	Partitions	2nd Floor	5	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	279	SF	6			
	Walls - Concrete Block Walls - Tile Ceramic/ Porcelain	2nd Floor 2nd Floor	250	SF SF	6	6-10 years		
		2nd Floor		EA	7	6-10 years		
	Water Closet		5			6-10 years		
	Accessories	2nd Floor Unisex	73	SF SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor Unisex	73		7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor Unisex	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor Unisex	73	SF	7	6-10 years		
	Floor Drain	2nd Floor Unisex	1	EΑ	7	6-10 years		
	Hand Dryer	2nd Floor Unisex	1	EΑ	7	6-10 years		
	Lavatory	2nd Floor Unisex	1	EΑ	7	6-10 years		
	Lighting - Lay-in	2nd Floor Unisex	4	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor Unisex	42	SF	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor Unisex	65	SF	7	6-10 years		
	Water Closet	2nd Floor Unisex	1	EA	7	6-10 years		
	Accessories	Basement Engineer's Toilet Room	34	SF	7	6-10 years	Room not accessible, ranks based on	

Campus Name: Reilly Page : 33 of 53 Assessment Date: 08/16/2023



Category : Room		Building : Linked Addition						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
		NO ACCESS					previous assessment and Building Engineer.	
	Ceiling - Lay-in	Basement Engineer's Toilet Room NO ACCESS	34	SF	7	6-10 years	Room not accessible, ranks based on previous assessment and Building Engineer.	
	Doors - Steel Doors incl hw	Basement Engineer's Toilet Room NO ACCESS	1	EA	6	6-10 years	J	
	Floor - Tile	Basement Engineer's Toilet Room NO ACCESS	34	SF	7	6-10 years		
	Lavatory	Basement Engineer's Toilet Room NO ACCESS	1	EA	6	6-10 years		
	Lighting - Lay-in	Basement Engineer's Toilet Room NO ACCESS	1	EA	7	6-10 years		
	Walls - Concrete Block	Basement Engineer's Toilet Room NO ACCESS	31	SF	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	Basement Engineer's Toilet Room NO ACCESS	40	SF	6	6-10 years		
	Water Closet	Basement Engineer's Toilet Room NO ACCESS	1	EA	7	6-10 years		
	Accessories	Faculty Lounge Toilet	61	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Faculty Lounge Toilet	61	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	Faculty Lounge Toilet	1	EΑ	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Faculty Lounge Toilet	61	SF	7	6-10 years		
	Hand Dryer	Faculty Lounge Toilet	1	EΑ	7	6-10 years		
	Lavatory	Faculty Lounge Toilet	1	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	Faculty Lounge Toilet	2	EA	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	Faculty Lounge Toilet	127	SF	7	6-10 years		
	Water Closet	Faculty Lounge Toilet	1	EA	7	6-10 years		
	Accessories	Kitchen Women	102	SF	7	6-10 years		
	Ceiling - Lay-in	Kitchen Women	102	SF	6	6-10 years		
	Doors - Steel Doors incl hw	Kitchen Women	2	EA	6	6-10 years		
	Floor - Tile	Kitchen Women	102	SF	7	6-10 years		
	Floor Drain	Kitchen Women	1	EA	7	6-10 years		
	Lavatory	Kitchen Women	1	EA	7	6-10 years		
	Lighting - Lay-in	Kitchen Women	2	EA	7	6-10 years		
	Student Lockers - One Tier	Kitchen Women	8	EA	7	6-10 years		
	Student Lockers - Two Tiers	Kitchen Women	6	EA	7	6-10 years		
	Walls - Concrete Block	Kitchen Women	175	SF	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	Kitchen Women	175	SF	7	6-10 years		
	Water Closet	Kitchen Women	1	EA	7	6-10 years		
	Accessories	Main Office Toilet	48	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Main Office Toilet	48	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	Main Office Toilet	1	ĒΑ	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Main Office Toilet	48	SF	7	6-10 years		

Campus Name: Reilly Page : 34 of 53 Assessment Date: 08/16/2023



Category : Room		В	Building: Linked Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Hand Dryer	Main Office Toilet	1	EA	7	6-10 years		
	Lavatory	Main Office Toilet	1	EA	7	6-10 years		
	Lighting - Wall Mounted	Main Office Toilet	2	EA	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	Main Office Toilet	95	SF	7	6-10 years		
	Water Closet	Main Office Toilet	1	EA	7	6-10 years		
	water Gloset	Wall Office Tollet	ı	LA	,	0-10 years		
Catego	ry : Classroom		В	uilding	: Linked	d Addition		
0	Name Time	Laattan	0	HOM	Danila	Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	om #111 (Pre School)	-						
	Casework	1st Floor	50	LF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	1,130	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	6-10 years		
	Floor - Tile	1st Floor	1,130	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	125	SF	7	6-10 years		
	Student Lockers - One Tier	1st Floor	24	EA	7	6-10 years		
	Student Lockers - Two Tiers	1st Floor	4	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	735	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	10	SF	6	1-2 years	Cracking mortar	
	Walls - Plaster/Drywall	1st Floor	495	SF	7	10+ years	a rate and a second	
	Work Sink	1st Floor	3	ĒΑ	5	1-2 years	Strong smell coming from sink drain	
Classro	om #112 (Pre School)							
Classiu	Casework	1st Floor	61	LF	6	6-10 years		
	Ceiling - Lay-in	1st Floor	1,072	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years		
	Floor - Tile/Sheet	1st Floor	1,072	SF	7	6-10 years		
		1st Floor	1,072	EA	7			
	Lighting - Lay-in Marker Board	1st Floor	8	LF	7	6-10 years 6-10 years		
					-	•		
	Storage/ Closet	1st Floor	67	SF	7	6-10 years		
	Student Lockers - One Tier	1st Floor	5	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	745	SF	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	421	SF	6	10+ years		
	Work Sink	1st Floor	2	EA	7	6-10 years		
Classroo	om #113 (Kindergarten)							
	Casework	1st Floor	40	LF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	1,072	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years		
	Floor - Tile	1st Floor	1,072	SF	6	6-10 years		
	Lighting - Lay-in	1st Floor	1,072	EA	7	6-10 years		
	gg _~,		12		•	5 .5 jouro		

Campus Name: Reilly Page : 35 of 53 Assessment Date: 08/16/2023



Category : Classroom			В	Building : Linked Addition				
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage/ Closet	1st Floor	67	SF	7	6-10 years		
	Student Lockers - One Tier	1st Floor	1	EA	7	10+ years		
	Student Lockers - Two Tiers	1st Floor	4	EA	6	10+ years		
	Walls - Concrete Block	1st Floor	555	SF	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	654	SF	6	6-10 years		
	Work Sink	1st Floor	2	EA	7	6-10 years		
Classroc	om #114 (Kindergarten)							
	Casework	1st Floor	40	LF	6	6-10 years		
	Ceiling - Lay-in	1st Floor	1,075	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years		
	Floor - Tile	1st Floor	1,075	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	1,073	EA	7	6-10 years		
	Storage/ Closet	1st Floor	25	SF	7			
	Student Lockers - One Tier	1st Floor		EA		6-10 years		
			3		7	10+ years		
	Student Lockers - Two Tiers	1st Floor	4	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	550	SF	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	125	SF	6	6-10 years		
	Work Sink	1st Floor	2	EA	7	6-10 years		
Classroc	om #220 (Regular Classroom)							
	Casework	2nd Floor	35	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	40	SF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	660	SF	6	6-10 years		
	Chalk Board	2nd Floor	8	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Tile	2nd Floor	700	SF	6	6-10 years		
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	664	SF	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	342	SF	6	6-10 years		
	Work Sink	2nd Floor	1	ĒΑ	7	6-10 years		
Classroo	om #222 (Regular Classroom)							
	Casework	2nd Floor	42	LF	6	6-10 years		
	Casework Ceiling - Lay-in	2nd Floor	42	SF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	862	SF	6	6-10 years		
	•			SF LF				
	Chalk Board	2nd Floor	8		4	2-5 years		
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Tile	2nd Floor	866	SF	6	6-10 years		
	Lighting - Lay-in	2nd Floor	1	EΑ	7	6-10 years		



Catego	Category : Classroom			Building : Linked Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years			
	Marker Board	2nd Floor	8	LF	6	6-10 years			
	Student Lockers - One Tier	2nd Floor	2	EA	6	6-10 years			
	Student Lockers - Two Tiers	2nd Floor	4	EA	6	6-10 years			
	Walls - Concrete Block	2nd Floor	600	SF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	350	SF	6	6-10 years			
	Work Sink	2nd Floor	1	ĒΑ	7	10+ years			
Classroo	om #223 (Regular Classroom)								
	Casework	2nd Floor	42	LF	6	6-10 years			
	Ceiling - Lay-in	2nd Floor	866	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Tile	2nd Floor	866	SF	7	6-10 years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
			2	EA	7	-			
	Student Lockers - One Tier	2nd Floor				10+ years			
	Student Lockers - Two Tiers	2nd Floor	4	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	573	SF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	565	SF	6	6-10 years			
	Work Sink	2nd Floor	1	EA	7	10+ years			
Classroo	om #224 (Regular Classroom)								
	Casework	2nd Floor	42	LF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	12	SF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	854	SF	6	6-10 years			
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Tile	2nd Floor	866	SF	7	6-10 years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Student Lockers - One Tier	2nd Floor	· <u>-</u> 1	ĒΑ	7	6-10 years			
	Student Lockers - Two Tiers	2nd Floor	4	EΑ	7	6-10 years			
	Walls - Concrete Block	2nd Floor	455	SF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	662	SF	6	6-10 years			
	Work Sink	2nd Floor	1	EA	7	6-10 years			
Classes	om #225 (Regular Classroom)								
	,	2nd Floor	40	ır	6	6.10 years			
	Casework		42	LF CF	6	6-10 years			
	Ceiling - Lay-in	2nd Floor	6	SF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	860	SF	6	6-10 years			
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Tile	2nd Floor	866	SF	7	6-10 years			



	ry : Classroom		В	uildina	: Linked	d Addition	050 W SCHOOLSTREET, CHICAGO, IL 00016
5 4.590	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	2	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	12	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	640	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
_Classroo	om #226 (Regular Classroom)						
	Casework	2nd Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	866	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	866	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	10	ĒΑ	7	6-10 years	
	Lighting - Lay-in	2nd Floor	2	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	ĒΑ	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	662	SF	6	6-10 years	
	Work Sink	2nd Floor	1	ĒΑ	7	6-10 years	
_Classroo	om #227 (Regular Classroom)						
	Casework	2nd Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	40	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	826	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	866	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	662	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
_Classroo	om #228 (Regular Classroom)						
	Casework	2nd Floor	42	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	14	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	850	SF	6	6-10 years	
	,					,	



Catego	ry : Classroom		В	uildina	: Linked	d Addition	0000 W 3CH001 3TREET, CHICAGO, IE 000 10
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Side-lite	2nd Floor	11	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile	2nd Floor	864	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	EΑ	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor	785	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	296	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #229 (Regular Classroom)						
	Casework	2nd Floor	27	LF	6	6-10 years	
	Ceiling - Exposed	2nd Floor	187	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	15	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	810	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	1,012	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor	3	EΑ	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EΑ	7	10+ years	
	Walls - Concrete Block	2nd Floor	621	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	772	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #230 Computer Ro (Regular Classro	oom)					
	Casework	2nd Floor	72	LF	7	6-10 years	
	Casework	2nd Floor	70	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,100	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile	2nd Floor	1,100	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	500	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	609	SF	7	6-10 years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	



Catego	ry : Interior		В	Building : Linked Addition					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor			-			•			
	Ceiling - Exposed	1st Floor	200	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	1,832	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	1,991	SF	6	6-10 years			
	Doors - Store Front	1st Floor	9	EA	7	6-10 years			
	Drinking Fountains - Single Fountain	1st Floor	2	EΑ	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	290	SF	7	6-10 years			
	Floor - Tile/Sheet	1st Floor	3,733	SF	7	6-10 years			
	Lighting - Lay-in	1st Floor	24	EA	7	6-10 years			
	Lighting - Metal Halide/ High Pressure	1st Floor	6	EΑ	7	6-10 years			
	Sodium	10111001	· ·	_/、	,	o ro youro			
	Lighting - Pendent/Surface	1st Floor	70	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor	4,032	SF	7	6-10 years			
	Ceiling - Exposed	2nd Floor	1,124	SF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	1,210	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	950	SF	6	6-10 years			
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years			
	Floor - Tile/Sheet	2nd Floor	3,284	SF	7	6-10 years			
	Lighting - Lay-in	2nd Floor	40	EA	6	6-10 years			
	Lighting - Lay-III Lighting - Metal Halide/Sodium Vapor	2nd Floor	8	EA	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	70	EA	6	6-10 years			
	Walls - Concrete Block	2nd Floor		SF	6	•			
	Walls - Plaster/Drywall	2nd Floor	3,250 540	SF		6-10 years 6-10 years			
				SF SF	6		Organia a provincia finativa a		
	Walls - Plaster/Drywall	2nd Floor	20	SF SF	5	1-2 years	Cracking around fixtures		
	Ceiling - Lay-in	Admin Corridor	192		7	6-10 years			
	Doors - Wood Doors include hw	Admin Corridor	2	EA	7	6-10 years			
	Floor - Tile/Sheet	Admin Corridor	192	SF	7	6-10 years			
	Lighting - Lay-in	Admin Corridor	4	EA	7	6-10 years			
	Walls - Concrete Block	Admin Corridor	238	SF	7	6-10 years			
	Walls - Plaster/Drywall	Admin Corridor	234	SF	7	6-10 years			
_Safety									
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years			
	Security Cameras	1st Floor	3	EΑ	7	6-10 years			
			O .		•	o .o jouro			
Stairs									
	Ceiling - Lay-in	East Stair	277	SF	6	6-10 years			
	Floor - Rubber Floor	East Stair	56	SF	6	6-10 years			
	Handrails	East Stair	68	LF	7	6-10 years			
	Lighting - Lay-in	East Stair	4	EA	6	6-10 years			
	Stairs - Rubber	East Stair	126	LF	6	6-10 years			
	Walls - Concrete Block	East Stair	1,188	SF	6	6-10 years			
	Ceiling - Exposed	East Stair to Basement	155	SF	7	6-10 years			
	-					-			



Catego	Category : Interior		Building : Linked Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Concrete	East Stair to Basement	76	SF	7	6-10 years		
	Handrails	East Stair to Basement	48	LF	7	6-10 years		
	Lighting - Wall Mounted	East Stair to Basement	3	EA	7	6-10 years		
	Stairs - Concrete	East Stair to Basement	63	LF	6	6-10 years		
	Walls - Concrete Block	East Stair to Basement	929	SF	6	6-10 years		
	Ceiling - Lay-in	West Stair	272	SF	7	6-10 years		
	Floor - Rubber Floor	West Stair	92	SF	7	6-10 years		
	Handrails	West Stair	68	LF	7	6-10 years		
	Lighting - Lay-in	West Stair	4	EA	6	6-10 years		
	Stairs - Rubber	West Stair	196	LF	7	6-10 years		
	Walls - Concrete Block	West Stair	1,222	SF	6	6-10 years		
	Walls - Plaster/Drywall	West Stair	75	SF	6	6-10 years		
	Ceiling - Exposed	West Stair to Basement	59	SF	7	6-10 years		
	Floor - Concrete Epoxy/ Painted	West Stair to Basement	30	SF	7	6-10 years		
	Handrails	West Stair to Basement	48	LF	7	6-10 years		
	Lighting - Pendent/Surface	West Stair to Basement	2	EA	7	6-10 years		
	Stairs - Concrete	West Stair to Basement	72	LF	6	6-10 years		
	Walls - Concrete Block	West Stair to Basement	970	SF	6	6-10 years		
Vertical	Conveyance							
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years		





Category: Exterior Building: Modular 1 (2-Classroom) Recommend Location Replacement Item - Type Quantity **UOM** Comments Group Rank Entrance FΑ 7 Exterior Doors - Exterior Steel Door 4 1 6-10 years New under construction 50 LF 7 4 10+ years Exterior Stairs - Wood New under construction 25 LF 10+ years Stair Handrail - Steel Stair Handrail 4 7 New under construction Exterior Doors - Exterior Steel Door 5 1 EΑ 7 10+ years New construction in progress LF Exterior Stairs - Wood 5 20 7 10+ years New construction in progress 5 LF 10+ years Stair Handrail - Steel Stair Handrail 10 7 New construction in progress Exterior Doors - Exterior Steel Door 6 1 EΑ 6 6-10 years Ramp Handrail - Steel Ramp Handrail 6 50 LF 6 10+ vears LF Ramps - Wood Ramp 6 100 6 10+ years Foundation Foundation - Concrete LF 7 **Entire Building** 184 10+ years SF Superstructure - Steel with Clay Tile Arch **Entire Building** 1.632 7 10+ years Lighting Exterior Lighting - Wall Mounted 5 EΑ 7 **Entire Building** 10+ years New construction in progress Roof System LF 7 Downspouts - Exterior Downspouts **Entire Building** 24 10+ years New Roof - EPDM/ Synthetic Rubber Entire Building SF 7 1.632 6-10 years Repaired Roof Structure - Steel / Metal Deck/ **Entire Building** 1,632 SF 7 10+ years Concrete Topping Walls Exterior Walls - Prefabricated Metal Panel **Entire Building** 264 SF 7 10+ years New construction in progress Wall SF Exterior Walls - Wood Siding **Entire Building** 1,688 7 10+ years New construction in progress Windows Guard - Guards perforated **Entire Building** 256 SF 7 10+ years New construction in progress SF Windows - Sash Aluminum Double-pane **Entire Building** 256 7 10+ years New construction in progress Category: Electrical **Building: Modular 1 (2-Classroom)** Recommend Item - Type Location **UOM** Rank Replacement Comments Group Quantity Emergency System Exit Signs - Corridors and Stairs EΑ 7 **Entire Building** 1 10+ years Emergency Battery Packs - Corridors and **Entire Building** 1 EΑ 7 10+ years Stairs Emergency Battery Packs - Students Toilets **Entire Building** 2 EΑ 7 10+ years

Campus Name: Reilly Page: 42 of 53 Assessment Date: 08/16/2023



Catego	ry : Electrical		В	uilding	: Modul	ar 1 (2-Classro Recommend	oom)
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Main Sei	rvice						
viaiii Oei	PA System	Entire Building	1,632	SF	7	10+ years	
	Main Electrical Service - 800 A and 120/240/3PH	Exterior Wall	1,002	EA	6	2-5 years	
Power D	vistribution						
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (2-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	1,632	SF	7	10+ years	To be installed
	Fire Alarm_System	Entire Building	1,632	SF	7	10+ years	
Sprinkler	r System						
	Sprinkler Heads	Entire Building	1,632	SF	7	10+ years	
	Sprinkler Piping	Entire Building	1,632	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	1,632	SF	7	10+ years	
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (2-Classro	oom)
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ature Control	2004	Quantity	•	rtaint	rtopiacomont	Commonio
теттрета	Electric Thermostat	Entire Building	2	EA	7	10+ years	
Unit Ven	tilation						
	Unit Ventilators - Vertical Package Electric	Entire Building	2	EA	4	2-5 years	Older units. New units to on the way but not for awhile.
	Heat & Self Contained Cooling						but not for awnile.
Ventilatio	on						
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	7	10+ years	
Catego	ry : Plumbing		В	uilding	: Modul	ar 1 (2-Classro	oom)
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	7	10+ years	

Campus Name: Reilly Page : 43 of 53 Assessment Date: 08/16/2023



Category : Plumbing			Building : Modular 1 (2-Classroom)						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
огоир	nem - Type	Location	Quantity	CON	Italik	Replacement	Comments		
Piping									
	Domestic Piping-Hot Water Return Lines	Entire Building	1,632	SF	7	10+ years			
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	1,632	SF	7	10+ years			
	Sanitary Piping	Entire Building	1,632	SF	7	10+ years			
	Storm Piping	Entire Building	1,632	SF	7	10+ years			
	Vent Piping	Entire Building	1,632	SF	7	10+ years			
Catego	ry : Classroom		В	uilding	: Modul	ar 1 (2-Classro	om)		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #001 (Regular Classroom)								
	Ceiling - Plaster/Drywall	1st Floor	630	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	6-10 years			
	Floor - Tile	1st Floor	630	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years			
	Storage/ Closet	1st Floor	30	SF	7	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	770	SF	7	6-10 years			
21	#000 (Paradar Olasanasa)								
Classroo	m #002 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	9	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	621	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years			
	Floor - Tile	1st Floor	630	SF	7	2-5 years			
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years			
	Storage/ Closet	1st Floor	30	SF	7	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	770	SF	7	6-10 years			
Catego	ry : Room		В	uilding	: Modul	ar 1 (2-Classro	om)		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
√lechani	cal/ Service Rooms								
	Mechanical/ Service Rooms	1st Floor	60	SF	5	10+ years	Hole in ceiling.		
Restroor	n								
	Accessories	Unisex North	54	SF	7	6-10 years	Under construction		
	Ceiling - Lay-in	Unisex North	54	SF	5	0-1 year	Holes in ceiling.		
	Doors - Wood Doors inclu hw	Unisex North	1	EA	7	6-10 years	· · · · · - · · · · - · · · · · · · · · · · · · · · · · · ·		
	Floor - Tile	Unisex North	54	SF	7	6-10 years			
	1 1001 1 110			_	7	6-10 years			
	Floor Drain	Unisex North							
	Floor Drain Lavatory	Unisex North Unisex North	1	EA EA	7	6-10 years			



Catego	ry : Room		В	uilding	: Modul	ar 1 (2-Classro	oom)	
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	Unisex North	1	EA	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	Unisex North	124	SF	7	6-10 years		
	Water Closet	Unisex North	1	EA	7	6-10 years		
	Accessories	Unisex South	54	SF	7	6-10 years	Under construction	
	Ceiling - Plaster/Drywall	Unisex South	54	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	Unisex South	1	EA	7	6-10 years		
	Floor - Tile	Unisex South	54	SF	7	6-10 years		
	Floor Drain	Unisex South	1	EA	7	6-10 years		
	Lavatory	Unisex South	1	EA	7	6-10 years		
	Lighting - Pendent/Surface	Unisex South	1	EA	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	Unisex South	124	SF	7	6-10 years		
	Water Closet	Unisex South	1	EA	7	6-10 years		

Building: Modular 1 (2-Classroom) Category: Interior

				Ŭ		Recommend	,
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Corridor							
	Ceiling - Lay-in	1st Floor	105	SF	7	6-10 years	
	Doors - Wood Doors include hw	1st Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	105	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	6-10 years	





Category: Exterior Building: Modular 2 (2-Classroom) Recommend Location Replacement Item - Type Quantity **UOM** Comments Group Rank Entrance FΑ 7 Exterior Doors - Exterior Steel Door 1 1 10+ years New construction in progress LF 7 Ramp Handrail - Steel Ramp Handrail 100 10+ years New construction in progress 1 LF Ramps - Wood Ramp 1 50 7 10+ years New construction in progress Exterior Doors - Exterior Steel Door 2 EΑ 7 10+ years New construction in progress 1 LF Exterior Stairs - Wood 2 16 7 10+ years New construction in progress 2 LF Stair Handrail - Steel Stair Handrail 5 7 10+ years New construction in progress Exterior Doors - Exterior Steel Door 3 1 EΑ 7 10+ years New construction in progress Exterior Stairs - Wood 3 16 LF 7 10+ vears New construction in progress LF Stair Handrail - Steel_Stair Handrail 3 7 10+ years New construction in progress Foundation Foundation - Concrete LF 7 **Entire Building** 184 10+ years SF Superstructure - Steel **Entire Building** 1.632 7 10+ years Lighting 5 EΑ 7 Exterior Lighting - Wall Mounted **Entire Building** 10+ years New construction in progress Roof System LF Downspouts - Exterior Downspouts **Entire Building** 24 6 6-10 years Roof - EPDM/ Synthetic Rubber Entire Building SF 7 1.632 10+ years Patched and repaired, new gutter Roof Structure - Steel / Metal Deck/ **Entire Building** 1,632 SF 6 10+ years Concrete Topping Walls Exterior Walls - Prefabricated Metal Panel **Entire Building** 240 SF 7 New construction in progress 10+ years Wall SF Exterior Walls - Wood Siding **Entire Building** 1,528 7 10+ years New construction in progress Windows Guard - Guards perforated **Entire Building** 256 SF 7 10+ years New construction in progress SF Windows - Sash Aluminum Double-pane **Entire Building** 256 7 10+ years Category: Electrical Building: Modular 2 (2-Classroom) Recommend Location **UOM** Rank Replacement **Comments** Group Item - Type Quantity Emergency System Exit Signs - Corridors and Stairs EΑ 7 **Entire Building** 1 10+ years Under construction - being installed. Emergency Battery Packs - Corridors and **Entire Building** 1 EΑ 7 10+ years Stairs Emergency Battery Packs - Students Toilets **Entire Building** 2 EΑ 7 10+ years

Campus Name: Reilly Page: 46 of 53 Assessment Date: 08/16/2023



Catego	ry : Electrical		В	uilding	: Modul	ar 2 (2-Classro Recommend	oom)
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Main Ser	n doo						
viain Sei		Entire Building	1 622	C.E.	7	10	Under construction being installed
	PA System Main Electrical Service - 800 A and 120/208/3PH	Entire Building Exterior Wall	1,632 1	SF EA	7 6	10+ years 2-5 years	Under construction - being installed
	120/200/3FF						
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Modul	ar 2 (2-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	1,632	SF	7	10+ years	To be installed
	Fire Alarm_System	Entire Building	1,632	SF	7	10+ years	Under construction - to be installed
Sprinkler	System						
	Sprinkler Heads	Entire Building	1,632	SF	7	10+ years	
	Sprinkler Piping	Entire Building	1,632	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	1,632	SF	7	10+ years	
Catego	ry : Mechanical		В	uilding	: Modul	ar 2 (2-Classro	oom)
		1	0	11014	D	Recommend	•
•	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lempera	ture Control Electric Thermostat	Entire Duilding	2	EA	7	10	To be installed
	Electric Thermostat	Entire Building	2	EA	,	10+ years	TO be installed
Jnit Ven	tilation						
	Unit Ventilators - Vertical Package Electric	Entire Building	2	EA	4	2-5 years	Older units - New units on the way
	Heat & Self Contained Cooling						but not for awhile
√entilatio	on						
	Exhaust Fans- Roof Mounted - Less than	Roof	2	EA	7	10+ years	
	500 CFM					-	
Catego	ry : Plumbing		В	uilding	: Modul	ar 2 (2-Classro	oom)
	<u>-</u>			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
IUL VVale	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	7	10+ years	To be installed

Campus Name: Reilly Page : 47 of 53 Assessment Date: 08/16/2023



Catego	ry : Plumbing		В	Building : Modular 2 (2-Classroom)					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Piping									
	Domestic Piping-Hot Water Return Lines	Entire Building	1,632	SF	7	10+ years			
	Domestic Piping-Hot/Cold Water Supply	Entire Building	1,632	SF	7	10+ years			
	(Horizontal Lines)				_				
	Sanitary Piping	Entire Building	1,632	SF	7	10+ years			
	Storm Piping	Entire Building	1,632	SF	7	10+ years			
	Vent Piping	Entire Building	1,632	SF	7	10+ years			
Catego	ry : Classroom		В	uilding	: Modul	ar 2 (2-Classro	om)		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #003 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	630	SF	7	10+ years	Room Under Construction.		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	Not currently installed		
	Floor - Tile	1st Floor	630	SF	7	10+ years	Not currently installed		
	Lighting - Pendent/Surface	1st Floor	15	EA	7	10+ years	•		
	Storage/ Closet	1st Floor	30	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	770	SF	7	10+ years			
	·					•			
Classroo	m #004 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	630	SF	7	10+ years	Room Under Construction.		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	Not currently installed		
	Floor - Tile	1st Floor	630	SF	7	10+ years	Not currently installed		
	Lighting - Pendent/Surface	1st Floor	15	EΑ	7	10+ years			
	Storage/ Closet	1st Floor	30	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	770	SF	7	10+ years			
Catogo	ry : Room		B	uildina	· Modul	ar 2 (2-Classro	om)		
Catego	ry . Room		U U	unung	. Wodu	Recommend	om)		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	cal/ Service Rooms								
VICCITATIO	Mechanical/ Service Rooms	1st Floor	90	SF	7	10+ years			
	Wednamea, Cervice Reeme	10(1100)	00	O.	•	Tot youro			
Restroon	n								
	Accessories	Unisex North UNDER	54	SF	7	10+ years	Not currently installed		
	Calling Lawin	CONSTRUCTION	- 4	0.5	7	40			
	Ceiling - Lay-in	Unisex North UNDER	54	SF	7	10+ years			
	Deem Meed Deem' 1	CONSTRUCTION		_^	-	40	Nied erwannische Staat III. I		
	Doors - Wood Doors inclu hw	Unisex North UNDER	1	EA	7	10+ years	Not currently installed		
	Booto Wood Booto mola mi	CONICTOLICTION							
	Floor - Tile	CONSTRUCTION Unisex North UNDER	54	SF	7	10+ years			



Catego	ry : Room	Building : Modular 2 (2-Classroom)					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		CONSTRUCTION					
	Floor Drain	Unisex North UNDER	1	EA	7	10+ years	
		CONSTRUCTION					
	Lavatory	Unisex North UNDER	1	EA	7	10+ years	Not currently installed
		CONSTRUCTION					
	Lighting - Pendent/Surface	Unisex North UNDER	1	EA	7	10+ years	Not currently installed
		CONSTRUCTION					
	Walls - Vinyl Coated Gypsum Panel	Unisex North UNDER	114	SF	7	10+ years	
		CONSTRUCTION					
	Water Closet	Unisex North UNDER	1	EA	7	10+ years	Not currently installed
		CONSTRUCTION					
	Accessories	Unisex South UNDER	54	SF	7	10+ years	Not currently installed
		CONSTRUCTION					
	Ceiling - Lay-in	Unisex South UNDER	54	SF	7	10+ years	
		CONSTRUCTION			_		
	Doors - Wood Doors inclu hw	Unisex South UNDER	1	EA	7	10+ years	Not currently installed
		CONSTRUCTION			_		
	Floor - Tile	Unisex South UNDER	54	SF	7	10+ years	
		CONSTRUCTION			_		
	Floor Drain	Unisex South UNDER	1	EA	7	10+ years	
		CONSTRUCTION			_		
	Lavatory	Unisex South UNDER	1	EA	7	10+ years	Not currently installed
	1:1:: 5 1 1/0 (CONSTRUCTION	4	_^	-	0.40	No. of the second
	Lighting - Pendent/Surface	Unisex South UNDER	1	EA	7	6-10 years	Not currently installed
	W II V 10 1 10 B	CONSTRUCTION	444	05	-	40	
	Walls - Vinyl Coated Gypsum Panel	Unisex South UNDER	114	SF	7	10+ years	
	Water Olaret	CONSTRUCTION	4	_^	7	40	Not assume a the Sure to Head
	Water Closet	Unisex South UNDER	1	EA	7	10+ years	Not currently installed
		CONSTRUCTION					

Category: Interior Building: Modular 2 (2-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor Vestibule	140	SF	7	10+ years	Under construction.
	Drinking Fountains - Single Fountain	1st Floor Vestibule	2	EA	7	10+ years	
	Floor - Concrete	1st Floor Vestibule	140	SF	7	10+ years	Finish not installed
	Lighting - Lay-in	1st Floor Vestibule	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Vestibule	320	SF	7	10+ years	





Category : Site **Building: Site**

	ry . Site		_	unung	. 0	Recommend	
raun	Itom Type	Location	Quantity	UOM	Rank	Replacement	Comments
oup	Item - Type	Location	Quantity	UOW	Kalik	Replacement	Comments
/il/Drai						0.40	
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	6	6-10 years	
ncina							
- 5	Fencing - Chain Link	Entire Site	148	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	222	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site	54	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,231	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	170	LF	4	0-1 year	Wooden fence is rotting.
ndsca	pe						
	Landscape - Grass	Entire Site	2,350	SF	4	0-1 year	Area floods, the grass area near
							door, five and going east. It's not raining towards the catch basin.
	Landscape - Hardscape- Asphalt	Entire Site	1,500	SF	4	1-2 years	Damaged - New asphalt will be
	Landagana Hardagana Asabalt	Entire Cite	600	SF	4	0.1.400	installed at area of modular units
	Landscape - Hardscape- Asphalt	Entire Site	600		4	0-1 year	Potholes, alligators surface, large cracks in play area
	Landscape - Hardscape- Concrete	Entire Site	2,642	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	150	SF	4	0-1 year	Crushed, spalling concrete
	Landscape - Mulch	Entire Site	2,000	SF	6	6-10 years	
	Parkway trees	Entire Site	28	EA	6	6-10 years	
	Planting Beds/ Area	Entire Site	2,832	SF	5	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	13,403	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	4	SF	6	10+ years	Hairline cracks
	Retaining Wall - Concrete	Entire Site	249	SF	6	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	2-5 years	
ırking L	_ot						
<u> </u>	Concrete Curbs	North	160	LF	6	2-5 years	
	Interior Plantings	North	79	LF	6	6-10 years	
	Lighting - Lighting	North	3	EA	6	6-10 years	
	Surface - Asphalt	North	18,680	SF	7	6-10 years	
	Surface - Asphalt	North	150	SF	4	0-1 year	Large cracks in asphalt
	Surface - Asphalt	North	2,200	SF	4	0-1 year	Crushed, alligatored asphalt
	Trash Enclosure - Chain Links	North	1,078	SF	6	6-10 years	i i i i i i i i i i i i i i i i i i i
	Vehicular Screening	North	77	LF	6	6-10 years	
aygrou	ind						
, ,	Equipment - Pre K 3-5	West	1	EA	5	0-1 year	Broken chains, detachment from ground

Campus Name: Reilly Page : 50 of 53 Assessment Date: 08/16/2023



Frank W Reilly Elementary School

3650 W School STREET, Chicago, IL 60618

Catego	ry : Site		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Equipment - School Age 5-12	West	1	EA	6	6-10 years	
	Surface - Poured Surface	West	1,500	SF	7	10+ years	
_Sidewall	KS						
	Sidewalks - Internal Walks	Entire Site	240	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	7,899	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	4	0-1 year	Broken concrete
_Signage							
0 0	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	7	6-10 years	
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	7	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Reilly Page: 51 of 53 Assessment Date: 08/16/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Band Room R	Regular Classroom Regular Classroom Kindergarten	Room Location 1st Floor	Number	Number	(SF)		/\r_02	Stop	
Art Room R Band Room R	Regular Classroom					Area	Area	Зюр	Board
Band Room R	Regular Classroom		102	102	868	240	58	N	N
		1st Floor	101	101	868	240	58	N	Y
Dance Room K		1st Floor	105	105	880	240	58	N	Y
	Faculty Lounge	3rd Floor	301	301	808	240	58	N	N
	unch Room	1st Floor	108	108	868	240	58	N	Y
	Office	2nd Floor	201	201	852	240	58	N	Y
	Other Instructional Use	2nd Floor	203	203	873	240	58	N	Y
<u> </u>	Regular Classroom	1st Floor	103	103	815	240	58	N	Y
	Regular Classroom	1st Floor	104	104	876	240	58	N	Y
	Regular Classroom	1st Floor	106	106	855	240	58	N	Y
	Regular Classroom	2nd Floor	202	202	852	240	58	N	Y
	Regular Classroom	2nd Floor	204	204	880	240	58	N	Y
	Regular Classroom	2nd Floor	205	205	875	240	58	N	Y
	Regular Classroom	2nd Floor	206	206	865	240	58	N	Y
	Regular Classroom	2nd Floor	200	207	852	240	58	N	Y
			207	208	852	240	56 58	N N	Y
	Regular Classroom	2nd Floor 2nd Floor	208	212	290	60	30	IN	T
	Regular Classroom							N.I.	Υ
	Regular Classroom	3rd Floor	302	302	808	240	58	N	Y
	Regular Classroom	3rd Floor	303	303	812	240	50	N	
	Regular Classroom	3rd Floor	305	305	812	240	50	N	Y
	Regular Classroom	3rd Floor	306	306	812	240	50	N	
	Regular Classroom	3rd Floor	307	307	808	240	58	N	Y
	Regular Classroom	3rd Floor	308	308	808	320	58	N	Y
	Regular Classroom	3rd Floor	300	Household Arts	914	300	103	N	Y
Science Classroom R	Regular Classroom	3rd Floor	304	304	812	240	50	N	Υ
Special Education L	_aboratory/Shop	3rd Floor	326	Shop	330	80	16	N	N
Building : Linked Addition									
	Kindergarten	1st Floor	113	104	1,072	180	60	N	Υ
	Kindergarten	1st Floor	114	105	1,075	180	60	N	Υ
	Pre School	1st Floor	111	111	1,130	200	100	N	Υ
	Pre School	1st Floor	112	101	1,072	300	100	N	Υ
	Computer Lab	2nd Floor	230 Computer Ro	211	1,100	200	100	N	N
Regular Classroom R	Regular Classroom	2nd Floor	220	211	700	150	75	N	Υ
	Regular Classroom	2nd Floor	222	201	866	250	125	N	Y



Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	223	206	866	150	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	224	202	866	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	225	207	866	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	226	203	866	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	227	208	866	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	228	204	864	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	229	209	1,012	234	33	N	Υ
-	<u>-</u>	•	•	•	•	•	•	•	
Building - Modular 1 /2 Cla	aaraam l								

Building : Modular 1 (2-Classroom)									
Regular Classroom	Regular Classroom	1st Floor	001	001	630	52	25	N	N
Regular Classroom	Regular Classroom	1st Floor	002	002	630	52	25	N	N

Building : Modular 2 (2-Classroom)										
Regular Classroom	Regular Classroom	1st Floor	003	003	630	52	25	Ν	N	
Regular Classroom	Regular Classroom	1st Floor	004	004	630	52	25	Ν	N	

Campus Name: Reilly Page : 53 of 53 Assessment Date: 08/16/2023