

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1927	3	319,900
Campus Total			319,900

Recommend Replacement Comments 10+ years 10+ years
10+ years
10+ years
6-10 years
10+ years
10+ years



Cotoro			D	uilding	Main		436 W WIISON AVENUE, Chicago, IL 60625
Catego	ry : Exterior		D	uilding		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Exterior Stairs - Stone	#13 S	231	LF	6	10+ years	Comments
	Stair Handrail - Steel Stair Handrail	#13 S	40	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#14 E	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#14 E	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#14 E	12	LF	7	10+ years	
	Exterior Stairs - Stone	#14 E	72	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#14 E	35	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#15 E	2	EA	6	10+ years	
	Exterior Stairs - Stone	#15 E	59	LF	6	10+ years	
	Stair Handrail - Steel Stair Handrail	#15 E	14	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#16 E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#16 E	11	LF	6	10+ years	
	Exterior Stairs - Stone	#16 E	9	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#16 E	15	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#16.1 E Loading	2	EA	6	10+ years	
	Exterior Stairs - Stone	#16.1 E Loading	6	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#17 E	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#17 E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#17 E	10	LF	6	10+ years	
	Exterior Stairs - Stone	#17 E	24	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#17 E	12	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#17.1 E (Basement)	1	EA	4	0-1 year	Warped, damaged
	Exterior Doors - Side lite	#17.1 E (Basement)	1	EA	4	0-1 year	Deteriorated, holes
	Exterior Stairs - Concrete	#17.1 E (Basement)	64	LF	5	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#17.1 E (Basement)	16	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#18 E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#18 E	12	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#19 E	4	EA	6	10+ years	
	Exterior Stairs - Stone	#19 E	30	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#19 E	15	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#2 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 W	60	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2 W	18	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	#20 N OVH	1	EA	6	6-10 years	
	Door	#20 N OV/11	0	Γ Λ	<u>^</u>	10	
	Exterior Doors - Transom Lite	#20 N OVH	2	EA EA	6	10+ years	Corredod domograd
	Exterior Doors - Exterior Wood Door	#21 N Parking #21 N Parking	1	EA	4 6	0-1 year	Corroded, damaged
	Exterior Doors - Transom Lite		1			10+ years	
	Exterior Doors - Exterior FRP Door Exterior Stairs - Stone	#21.1 N #21.1 N	4	EA LF	6 6	10+ years	
	Exterior Doors - Exterior FRP Door	#21.1 N #21.2 N	4	EA	6	10+ years 10+ years	
	Exterior Stairs - Stone	#21.2 N #21.2 N	4		6	10+ years 10+ years	
	Exterior Doors - Exterior FRP Door	#21.2 N #22 S	4	EA	6	10+ years	
		<i>πLL</i> Ο	2	ĽA	0	ior years	



Catego	ry : Exterior		R	uilding	• Main	5	436 W Wilson AVENUE, Chicago, IL 60625
Oalcyo				unung	· main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Exterior Doors - Transom Lite	#22 S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#22 S	42	LF	6	10+ years	
	Exterior Stairs - Stone	#22 S	32	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#22 S	21	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#23 E Elevator Machine Rm	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#23 E Elevator Machine Rm	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#23 E Elevator Machine Rm	4	LF	6	10+ years	
	Exterior Doors - Store Front	#23.1 E Greenhouse	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#23.1 E Greenhouse	4	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#24 E	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#24 E	3	EA	6	10+ years	
	Exterior Stairs - Stone	#24 E	10	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#24 E	26	LF	7	10+ years	
	Ramps - Concrete	#24 E	11	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#25 E Courtyard	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#26 NW Courtyard	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#26 NW Courtyard	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#27 - Roof 1	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3 N	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 N	1	EA	6	10+ years	
	Exterior Stairs - Stone	#3 N	6	LF	6	10+ years	
	Entrance Control - Audio and Video	#4 N	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#4 N	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 N	3	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	#4.1 N (Basement)	1	EA	4	0-1 year	Damaged, screwed shut
	Exterior Stairs - Concrete	#4.1 N (Basement)	36	LF	6	10+ years	Patched
	Stair Handrail - Steel_Stair Handrail	#4.1 N (Basement)	18	LF	3	0-1 year	No handrails
	Exterior Doors - Exterior FRP Door	#5 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 W	1	EA	6	10+ years	
	Exterior Stairs - Stone	#5 W	72	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#5 W	12	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#5 W	8	LF	5	2-5 years	Leaning
	Exterior Doors - Exterior FRP Door	#6 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 W	1	EA	6	10+ years	
	Exterior Stairs - Stone	#6 W	46	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#6 W	12	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#7 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 W	1	EA	6	10+ years	
	Exterior Stairs - Stone	#7 W	85	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#7 W	12	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#8 S	6	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 S	9	EA	6	10+ years	
	Exterior Stairs - Stone	#8 S #8 S	180 30	LF LF	6 6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#0 3	30	LF	O	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
J				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Entrance Control - Audio and Video	#9 S	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#9 S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#9 S	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 S	8	LF	6	10+ years	
	Exterior Stairs - Stone	#9 S	88	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#9 S	135	LF	6	10+ years	
	Ramps - Concrete	#9 S	74	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#9 S	16	LF	6	10+ years	
Foundat	on						
	Foundation - Concrete	Entire Building	3,005	LF	7	10+ years	
	Foundation - Concrete	Entire Building	205	LF	6	10+ years	
	Superstructure - Concrete	Entire Building	318,900	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	1,000	SF	4	1-2 years	Cracking at floor structure causing tile
							damage in vestibule above
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	57 15	EA EA	7 7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	/	10+ years	
Roof Sys							
	Access Ladder - Metal	Roof #1 main	1	EA	7	10+ years	
	Access Ladder - Metal	Roof #1 main	11	EA	7	10+ years	
	Access Ladder - Wood	Roof #1 main	1	EA	4	0-1 year	Worn, thin
	Chimney - Metal Flue	Roof #1 main	10	LF	6	10+ years	
	Coping - Terra Cotta	Roof #1 main	2,153	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof #1 main	60	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #1 main	2,080	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof #1 main	1,650	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof #1 main	503	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #1 main	75,520	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof #1 main	100	SF	4	0-1 year	Water under membrane
	Roof - Modified Bitumen	Roof #1 main	100	SF	4	1-2 years	Soft spot, bubbling, East drain 23 and west roof
	Roof Hatch - Metal	Roof #1 main	6	EA	7	10+ years	
	Roof Structure - Concrete	Roof #1 main	75,720	SF	7	10+ years	
	Access Ladder - Metal	Roof #2 NW	2	EA	7	10+ years	
	Access Ladder - Metal	Roof #2 NW	2	EA	7	10+ years	
	Coping - Terra Cotta	Roof #2 NW	446	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof #2 NW	24	LF	6	10+ years	
	Downonouto Interior Downonouto	Roof #2 NW	385	LF	6	10+ years	
	Downspouts - Interior Downspouts				-	,	
	Parapet - 16" - 30" Height Roof - Modified Bitumen	Roof #2 NW Roof #2 NW	446 11,000	LF SF	6 6	10+ years 10+ years	



Catego	ry : Exterior		P	uilding	• Main	5	436 W Wilson AVENUE, Chicago, IL 60625
Jacyo			В	unung	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.000	Roof Hatch - Metal	Roof #2 NW	1	EA	7	10+ years	
	Roof Structure - Concrete	Roof #2 NW	11,000	SF	7	10+ years	
	Access Ladder - Metal	Roof #3 North & Boiler	3	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof #3 North & Boiler	100	LF	6	10+ years	
	Liner					5	
	Coping - Terra Cotta	Roof #3 North & Boiler	871	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof #3 North & Boiler	6	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #3 North & Boiler	350	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof #3 North & Boiler	871	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #3 North & Boiler	16,840	SF	6	10+ years	
	Roof - Modified Bitumen	Roof #3 North & Boiler	100	SF	5	6-10 years	
	Roof Structure - Concrete	Roof #3 North & Boiler	16,940	SF	7	10+ years	
	Access Ladder - Metal	Roof #4 NE	1	EA	7	10+ years	
	Coping - Terra Cotta	Roof #4 NE	419	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof #4 NE	3	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #4 NE	420	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof #4 NE	419	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #4 NE	12,586	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof #4 NE	200	SF	4	1-2 years	Bubbling, soft spots near light post
	Roof Structure - Concrete	Roof #4 NE	12,786	SF	7	10+ years	
Walls							
	Cheek-Wall - Concrete	Entire Building	300	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	45	SF	4	0-1 year	Cracking, separating door 9
	Exterior Walls - Brick	Entire Building	104,874	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,200	SF	4	0-1 year	Efflorescence at interior brick, roof 1 door access
	Exterior Walls - Brick	Entire Building	650	SF	4	0-1 year	Loose brick at column base
	Exterior Walls - Stone-Cut	Entire Building	19,985	SF	6	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	11,450	SF	6	10+ years	
	Lintels - Steel	Entire Building	2,945	LF	6	10+ years	
	Lintels - Stone	Entire Building	137	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	94	SF	7	10+ years	
	Skylite - Glass Single-Pane	Entire Building	50	SF	4	0-1 year	Cracked glazing, bent frames
	Windows - Casement Aluminum Double-	Entire Building	1,120	SF	6	10+ years	g.s, ~ c
	pane		.,.20	2.	÷		
	Windows - Louver	Entire Building	96	SF	5	2-5 years	
	Windows - Sash Aluminum Double-pane	Entire Building	30,280	SF	6	10+ years	
			,_00		-	. ,	



Catego	ry : Electrical		В	uilding	: Main			
						Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
merger	cy System							
	Emergency A/C Power - Auditoium and Aisle Lighting	1st, 2nd floor, Entire Building	9,402	SF	6	6-10 years	Location changed for clarification as the auditorium occupies space on multiple floors,	
	Emergency A/C Power - Corridors and Stairs	1st, 2nd floor, Entire Building	63,980	SF	6	6-10 years		
	Emergency A/C Power - Lunchrooms	1st, 2nd floor, Entire Building	1,275	SF	6	6-10 years		
	Emergency A/C Power - Pool	1st, 2nd floor, Entire Building	7,910	SF	6	10+ years		
	Automatic Transfer Switch	Electrical Room	1	EA	7	6-10 years		
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years		
	Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	Unit is 50-plus years old and emits ar audible sound consistent with an electrical disturbance. The switch has exceeded its anticipated service life.	
	Security System - CCTV	Entire Building	319,900	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	319,900	SF	6	6-10 years		
	Exit Signs - Auditoium	Entire Building	22	EA	7	6-10 years	Quantity changed as total has been divided/aggregated. Location changed for clarification as the auditorium occupies space on multiple floors,	
	Exit Signs - Corridors and Stairs	Entire Building	82	EA	7	6-10 years		
	Exit Signs - Gym	Entire Building	12	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on current observations that all gym exit signs are illuminated and legible as intended except one which has an expiring bulb which is flickering.	
	Exit Signs - Lunchroom	Entire Building	7	EA	6	6-10 years	Quantity changed to match current observations.	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	Location changed for clarification.	
	Exit Signs - Pool	Entire Building	2	EA	6	6-10 years	3	
	Emergency Generator- Outdoor- Diesel - 201 - 250 KW	North of Boiler Room Outdoors	1	EA	6	6-10 years		
lain Sei	vice							
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years		
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years		
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on current observations that the equipment is	



Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	PA System	Entire Building	319,900	SF	6	2-5 years	fully operational with no electrical disturbances, acute age-related deterioration, or safety hazards noted despite its age.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	14	EA	7	6-10 years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	38	EA	7	6-10 years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Opening in interior cover plate exposes live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open fuse receptacles and missing interior cover expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	0-1 year	Located near AHU-7 and AHU-5. Open breaker slot exposes live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	0-1 year	Open breaker slots expose live conductors presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	11	EA	7	10+ years	Location changed for clarification.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	2-5 years	Location changed for clarification. Panel is fully operational and presents no visible risk of shock or fire, bu it is approx. 50 years old and has been subject to a damp environment and prolonged exposure to steam in the boiler room. Rank, Reason and Priority Rep changed to recognize that the panel shows considerable signs of corrosion and has reached the end of its anticipated service life.
	Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	6	6-10 years	Quantity changed to match current observations. Location changed for clarification. Rank, Reason and Priority Rep changed based on current observations that the panels are intact and fully operational and do not pose a risk of fire, electric shock



Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Main Distribution Panels - Less than 400 amp	Entire Building	3	EA	7	10+ years	or personal injury.

Category	•	Fire	Protection
Galeuory		гие	FIDIECTION

Catego	ory : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Fire Alar</u>	Fire ALarm Anunciator	Entire Building	1	EA	3	2-5 years	Rank, Reason and Priority Rep changed as the system is functional and passes inspection but is 30-plus years old and has exceeded its anticipated service life.
	Fire Alarm Panel	Entire Building	1	EA	3	2-5 years	No CPS Asset Tag present. Panel in the midst of routine service on the day of assessment. Rank, Reason and Priority Rep changed as the panel is functional and passes inspection but is 30-plus years old and has exceeded its anticipated service life.
	Fire Alarm Strobe Lights	Entire Building	319,900	SF	6	2-5 years	Reason and Priority Rep changed as the system is functional and passes inspection but is 30-plus years old and has exceeded its anticipated service life.
	Fire Alarm_System	Entire Building	319,900	SF	4	2-5 years	Rank, Reason and Priority Rep changed as the system is functional and passes inspection but is 30-plus years old and has exceeded its anticipated service life.

Catego	ry : Mechanical	Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	AHU-1, serves the northwest "shops" wing. Item Type changed to match current observations.
	Air Intake	Mechanical Room - AHU-1	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	Item Type changed to match current observations.
	Reheat Boxes - Reheat Boxes with Steam	Mechanical Room - AHU-1	3	EA	6	6-10 years	Quantity changed to match current



Catago			Building : Main			436 W Wilson AVENUE, Chicago, IL 60625	
Catego	ry : Mechanical		В	uliaing	. wain	Decemana	
C	Kenne Tourse	Leastion	Oursetitur	UOM	Denk	Recommend	Commente
Group	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
	Coil Detum Duct Mark, Indeen Marting, Chaft	Machanical Deam ALUL 4	050	. –	7	10	observations.
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room - AHU-1	250	LF	7	10+ years	
	and Ducts	Machanical Deam ALUL 4	0		~	6.40	Quantity, Dessen and Driarity Dan
	Zone Dampers	Mechanical Room - AHU-1	6	EA	6	6-10 years	Quantity, Reason and Priority Rep changed to match current observations.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	EA	6	6-10 years	AHU-2, serves pool area and associated spaces.
	Air Intake	Mechanical Room - AHU-2	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room - AHU-2	150	LF	6	6-10 years	
	and Ducts						
	Zone Dampers	Mechanical Room - AHU-2	4	EA	6	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-3	1	EA	6	6-10 years	AHU-3, serves locker rooms, gyms and associated spaces.
	Air Intake	Mechanical Room - AHU-3	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-3	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room - AHU-3	75	LF	6	10+ years	
	and Ducts	Mechanical Room - AHU-3	10		6	6 10 10000	
	Zone Dampers Air Handling Unit- Built Up- Single Zone w/		10 1	EA EA	6 6	6-10 years	ALUL 4 comico want analogo of the
	Air Tunnel- Steam Coils - Greater than 35000 cfm	Mechanical Room - AHU-4		EA	0	6-10 years	AHU-4, serves west spaces of the building.
	Air Intake	Mechanical Room - AHU-4	1	EA	6	6-10 years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room - AHU-4	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam	Mechanical Room - AHU-4	12	EA	6	6-10 years	
	Coil				-	o ro youro	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-4	100	LF	6	6-10 years	
	Zone Dampers	Mechanical Room - AHU-4	38	EA	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-5	1	EA	6	6-10 years	AHU-5, serves east spaces of the building.
	Air Intake	Mechanical Room - AHU-5	1	EA	6	6-10 years	Schung.
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-5	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam	Mechanical Room - AHU-5	13	EA	6	6-10 years	
	Coil		15		-	0-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-5	100	LF	6	6-10 years	
	Zone Dampers	Mechanical Room - AHU-5	37	EA	5	2-5 years	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - Greater than 35000 cfm	Mechanical Room - AHU-6	1	EA	6	6-10 years	AHU-6, serves auditorium.
	Air Intake	Mechanical Room - AHU-6	1	EA	6	6-10 years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room - AHU-6	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room - AHU-6	100	LF	6	6-10 years	
	Retain Buot work indoor vortical Onalt		100	<u> </u>	U	5 10 90010	



Catego	ry : Mechanical		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	and Ducts Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Mechanical Room - AHU-7	1	EA	5	6-10 years	AHU-7, serves lunchroom, music suite, and associated spaces.		
	Air Intake	Mechanical Room - AHU-7	1	EA	6	6-10 years	Suite, and associated spaces.		
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room - AHU-7	1	EA	5	6-10 years			
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-7	75	LF	7	6-10 years			
	Zone Dampers	Mechanical Room - AHU-7	7	EA	6	6-10 years	Rank and Priority Rep adjusted based on current observations that the dampers respond to the temperature control system.		
	Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling Coil - Less than 6000 cfm	Roof	1	EA	6	6-10 years	MAU-1		
	Make Up Air Unit- Roof Mounted- Gas Heating - 6000 - 10,000 cfm	Roof	1	EA	6	6-10 years	MAU-2		
Boiler Sy									
	Boiler Auxiliary- Non Condensing Hot Water Boiler - Less than 500 MBH	Basement	1	EA	6	6-10 years			
	Non Condensing- Cast Iron- Atmospheric- Hot Water Boiler - Less than 500 MBH	Basement	1	EA	6	6-10 years			
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	6	10+ years	Item Type changed to match current observations. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that major repairs were completed since previous assessment.		
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	Priority Rep adjusted based on current observations.		
	Combustion Dampers	Boiler Room	2	EA	6	10+ years			
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Priority Rep adjusted based on current observations.		
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Priority Rep adjusted based on current observations.		
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Location changed for clarification. Priority Rep adjusted based on current observations.		
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Priority Rep adjusted based on current observations.		
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Priority Rep adjusted based on current observations.		
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Priority Rep adjusted based on		



Group

Category : Mechanical

Theodore Roosevelt High School 3436 W Wilson AVENUE, Chicago, IL 60625

Recommend Location Item - Type Quantity UOM Rank Replacement Comments current observations. ΕA Feed Water Pumps and Tank **Boiler Room** 6 6-10 years Priority Rep adjusted based on 1 current observations. ΕA 6 Non Condensing- Fire Tube- Scotch Marine-Boiler Room 1 10+ years B-1. Item Type changed to match Steam- Low Pressure Boiler - 101 - 150 HP current observations. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that major repairs were completed since previous assessment. Non Condensing- Fire Tube- Scotch Marine-B-2. Item Type changed to match Boiler Room 1 ΕA 6 10+ vears Steam- Low Pressure Boiler - 101 - 150 HP current observations. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that major repairs were completed since previous assessment. Actively in the midst of seasonal maintenance protocol at the time of assessment. Piping - Condensate Pipe- Steel Boiler Room 2,000 LF 5 6-10 years Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that the entire system has been made leak-free since previous assessment I Piping - Steam Pipe- Steel Boiler Room 2.000 LF 5 6-10 vears Steam Traps Boiler Room 102 ΕA 6 6-10 years Boiler Auxiliary- Scotch Marine- Steam Low **Boiler Room** ΕA 6 6-10 years 1 Item Type changed to match current Pressure Boiler - 50 - 75 HP observations. **Combustion Dampers** Boiler Room ΕA 6 6-10 years 1 Non Condensing- Fire Tube- Scotch Marine-Boiler Room 1 FΑ 6 10+ years B-3. Item Type changed to match Steam- Low Pressure Boiler - 50 - 75 HP current observations. Shares piping. condensate pumps, steam traps, and chemical feed system with B-1 and B-2. Heating Devices Unit Heater - Gas Boiler Room 3 FΑ 6 6-10 years Radiators - Steam Entire Building 32 ΕA 5 6-10 years LF Fin Tube - Steam Entire Building 450 6 6-10 years Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that all fin tube heating throughout the building is fully

Building : Main



atego	ry : Mechanical		В	uilding				
Ū				Ū		Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Wall Heater - Electric	Entire Building	20	EA	6	6-10 years	operational and responsive to temperature controls. Quantity changed to match current	
		Entro Danang	20	L /\	Ũ	o ro youro	observations.	
	Wall Heater - Electric	Entire Building	4	EA	4	0-1 year	Quantity changed to match current observations. Rank, Reason and Priority Rep changed based on current observations that the electrical compartment cover is missing which exposes live conductors presenting a live front condition.	
	Cabinet Heaters - With Steam Coil	Entire Building	10	EA	6	2-5 years		
empera	ature Control Electric Thermostat	Entire Building	1	EA	6	6-10 years		
	Pneumatic System	Entire Building	319,900	SF	7	6-10 years		
	Thermostats - Pneumatic	Entire Building	105	EA	6	6-10 years	Quantity changed as total has been	
						·	divided/aggregated. Priority Rep adjusted based on current observations and per review with Building Engineer.	
hit Ven						0.40		
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	4	EA	6	6-10 years	Rank and Priority Rep changed based on current observations and per review with Building Engineer tha the equipment is well maintained and has been upgraded since previous assessment.	
entilatio								
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years		
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years	Located in the Auditorium restrooms (2), Auditorium office (1), and Pool laundry room (1).	
	Exhaust Fans- Indoor - Greater than 8000 CFM	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations.	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Quantity changed to match current observations.	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	6	EA	5	6-10 years	Quantity changed to match current	



Catego	ry : Mechanical		В	Building : Main			
Julege	.,		_	anang	i ingini	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - Greater than	Entire Building	3	EA	6	6-10 years	
	8000 CFM	-				-	
	Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	6	6-10 years	Quantity and Priority Rep changed
	500 CFM			. –	0	0.40	based on current observations.
	Roof Mounted Duct Work	Entire Building	20	LF	6	6-10 years	Priority Rep adjusted based on current observations.
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression system provided.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	Quantity changed as one is located in the school kitchen area, however the other is located in a culinary arts lab; ref. Interiors.
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate							
	Steam Heat Exchanger	Boiler Room	1	EA	6	6-10 years	
	Electric Heater - Less than 20 KW	Room 167	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	319,900	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	319,900	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	319,900	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	319,900	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	319,900	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	319,900	SF	6	6-10 years	
	Sanitary Piping	Entire Building	319,900	SF	6	6-10 years	
	Storm Piping	Entire Building	319,900	SF	6	6-10 years	
	Vent Piping	Entire Building	319,900	SF	6	6-10 years	
Pool Svs	stems						
	Pool Drain Piping	Mechanical Room, Basement	100	LF	6	6-10 years	Priority Rep adjusted based on current observations and per review with Building Engineer that the system is well maintained, leak free,
	Pool Filtration System including Pump	Mechanical Room, Basement	1	EA	6	6-10 years	and is fully intact and operational. Priority Rep adjusted based on current observations and per review with Building Engineer that the



Catego	Category : Plumbing			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pool Hot Water Heater - Steam Heat Exchanger	Mechanical Room, Basement	1	EA	5	2-5 years	system is well maintained, leak free, and is fully intact and operational. Heat exchanger is functional and leak-free but is 50 years old and has reached the end of its anticipated service life.
	Pool Supply and Return Piping	Mechanical Room, Basement	300	LF	6	6-10 years	Rank, Reason and Priority Rep changed as the piping is leak-free and serves its intended purpose with no lack of integrity despite its age.
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Basement, Boiler Room, Mechanical Room	1	EA	6	2-5 years	
	Pumps - Sump-Duplex	Basement, Boiler Room, Mechanical Room	1	EA	6	2-5 years	
	Pumps - Sump-Duplex	Basement, Boiler Room, Mechanical Room	1	EA	6	2-5 years	No CPS Asset Tag present.
	Pumps - Sump-Duplex	Basement, Boiler Room, Mechanical Room	1	EA	6	2-5 years	
	Pumps - Sump-Duplex	Basement, Boiler Room, Mechanical Room	1	EA	6	2-5 years	
	Pumps - Sump-Duplex	Basement, Boiler Room, Mechanical Room	1	EA	6	2-5 years	
	Pumps - Sump-Duplex	Basement, Boiler Room, Mechanical Room	1	EA	4	1-2 years	Located in the sublevel below the boiler room. One of the pumps is off line. Priority Rep adjusted based on current observations that one pump is operational and serves its intended purpose.

Catego	Category : Room			uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	AC Unit	115	1	EA	7	6-10 years	
	Ceiling - Lay-in	115	195	SF	7	10+ years	
	Doors - Side-lite	115	11	SF	7	10+ years	
	Doors - Transom Window	115	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	115	2	EA	7	10+ years	
	Floor - Carpet	115	97	SF	7	6-10 years	
	Floor - Tile	115	98	SF	7	10+ years	
	Lighting - Lay-in	115	4	EA	7	6-10 years	
	Power Distribution	115	8	EA	7	10+ years	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Walls - Plaster/Drvwall 115 580 SF 10+ vears 6 SF 7 Ceiling - Lav-in 116 62 10+ years Doors - Wood Doors inclu hw 116 1 FΑ 7 10+ years Floor - Tile SF 7 116 62 10+ years Lighting - Lay-in 116 2 EΑ 7 10+ years 2 7 Power Distribution 116 EΑ 10+ years Walls - Plaster/Drywall SF 7 10+ years 116 130 AC Unit 123 - Main Office 2 ΕA 7 6-10 years Ceiling - Lav-in 123 - Main Office 1.409 SF 7 10+ years SF Doors - Transom Window 123 - Main Office 48 7 10+ vears Doors - Wood Doors inclu hw 123 - Main Office 6 ΕA 7 10+ vears Floor - Tile 123 - Main Office 1.379 SF 6 10+ years Floor - Tile SF 4 1-2 years 123 - Main Office 30 Cracked tile 7 Lighting - Lay-in 123 - Main Office 36 EA 6-10 years **Power Distribution** 7 123 - Main Office 14 EΑ 10+ years SF 7 Storage/ Closet 123 - Main Office 10 10+ years Walls - Plaster/Drvwall SF 123 - Main Office 2.310 7 10+ years AC Unit 123A - Assistant Principal #2 1 EΑ 7 6-10 years Ceiling - Lay-in SF 123A - Assistant Principal #2 200 7 10+ vears Doors - Side-lite SF 123A - Assistant Principal #2 38 7 10+ years Doors - Transom Window 123A - Assistant Principal #2 8 SF 7 10+ years 123A - Assistant Principal #2 7 Doors - Wood Doors inclu hw 1 EΑ 10+ years Floor - Tile SF 7 123A - Assistant Principal #2 190 10+ years SF Floor - Tile 123A - Assistant Principal #2 10 4 1-2 years Cracked tile Lighting - Lay-in 123A - Assistant Principal #2 3 ΕA 7 6-10 years Power Distribution 123A - Assistant Principal #2 6 ΕA 7 10+ vears SF Walls - Plaster/Drywall 123A - Assistant Principal #2 570 7 10+ years AC Unit 123B - Assistant Principal #1 ΕA 7 6-10 years 1 SF Ceiling - Lay-in 123B - Assistant Principal #1 110 7 10+ years Doors - Side-lite 123B - Assistant Principal #1 70 SF 7 10+ years SF Doors - Transom Window 123B - Assistant Principal #1 16 7 10+ vears Doors - Wood Doors inclu hw 123B - Assistant Principal #1 2 EΑ 7 10+ vears SF 10+ years Floor - Tile 123B - Assistant Principal #1 102 7 Floor - Tile 123B - Assistant Principal #1 8 SF 1-2 vears Cracked tile 4 3 7 Lighting - Lay-in 123B - Assistant Principal #1 EΑ 6-10 years ΕA 7 **Power Distribution** 123B - Assistant Principal #1 4 10+ years SF Walls - Plaster/Drywall 123B - Assistant Principal #1 430 7 10+ years 123C - Principal 7 6-10 years AC Unit EΑ 1 Ceiling - Lay-in 123C - Principal 200 SF 7 10+ years Doors - Side-lite SF 123C - Principal 70 7 10+ vears 123C - Principal SF Doors - Transom Window 16 7 10+ years 2 FΑ 7 Doors - Wood Doors inclu hw 123C - Principal 10+ vears Floor - Tile 123C - Principal 195 SF 7 10+ years Floor - Tile SF 123C - Principal 5 4 1-2 years Cracked tile



Category : Room **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Lighting - Lay-in 123C - Principal 6 ΕA 6-10 years 7 Power Distribution ΕA 7 123C - Principal 4 10+ vears Walls - Plaster/Drywall 123C - Principal 570 SF 7 10+ years ΕA 7 AC Unit 123D - Conference 1 6-10 years SF 7 Ceiling - Lay-in 123D - Conference 200 10+ years SF 7 Doors - Side-lite 123D - Conference 70 10+ years Doors - Transom Window SF 7 123D - Conference 16 10+ years 10+ years Doors - Wood Doors inclu hw 123D - Conference 2 EΑ 7 Floor - Tile 123D - Conference 192 SF 7 10+ years SF Floor - Tile 123D - Conference 8 4 1-2 vears Cracked tile Lighting - Lav-in 123D - Conference 6 ΕA 7 6-10 vears Power Distribution 123D - Conference 4 EΑ 7 10+ years Walls - Plaster/Drywall 570 SF 7 10+ years 123D - Conference 7 AC Unit 126 - Special Ed EA 6-10 years 1 Ceiling - Lay-in 126 - Special Ed SF 7 348 10+ years Doors - Transom Window SF 7 126 - Special Ed 9 10+ years ΕA 7 Doors - Wood Doors inclu hw 126 - Special Ed 1 10+ vears Floor - Tile Ceramic/ Porcelain 126 - Special Ed 348 SF 7 6-10 years ΕA Lighting - Lav-in 126 - Special Ed 9 7 10+ vears Power Distribution 126 - Special Ed 4 EΑ 7 10+ years Walls - Plaster/Drywall 126 - Special Ed 490 SF 7 10+ years Work SInk 7 10+ years 126 - Special Ed 1 EΑ 1st Floor - Engineer 7 AC Unit 1 EA 6-10 years SF 7 Ceiling - Plaster/Drywall 1st Floor - Engineer 600 10+ years Doors - Wood Doors inclu hw 1st Floor - Engineer ΕA 7 2 10+ years SF Floor - Tile 1st Floor - Engineer 600 7 6-10 years Lighting - Pendent/Surface 1st Floor - Engineer 8 EA 7 10+ years Lighting - Pendent/Surface 1st Floor - Engineer 4 ΕA 6 2-5 years Not working **Power Distribution** 7 1st Floor - Engineer 12 EΑ 10+ years Walls - Plaster/Drywall 1st Floor - Engineer 1,679 SF 7 10+ years SF Ceiling - Plaster/Drywall 1st Floor - Kitchen Manager 62 7 10+ vears SF Doors - Side-lite 1st Floor - Kitchen Manager 48 7 10+ vears 7 10+ years Doors - Wood Doors inclu hw 1st Floor - Kitchen Manager 1 FΑ Floor - Tile 1st Floor - Kitchen Manager 62 SF 6 10+ vears 2 7 Lighting - Pendent/Surface 1st Floor - Kitchen Manager EΑ 6-10 years 6 ΕA 7 **Power Distribution** 1st Floor - Kitchen Manager 10+ years 3 SF Storage/ Closet 1st Floor - Kitchen Manager 7 10+ years Walls - Plaster/Drywall 1st Floor - Kitchen Manager 252 SF 7 10+ years AC Unit 1st Flr - Asst Engineer Office 1 ΕA 7 6-10 years SF Ceiling - Plaster/Drvwall 1st Flr - Asst Engineer Office 600 7 10+ vears Doors - Wood Doors inclu hw 1st Flr - Asst Engineer Office ΕA 7 10+ years 1 1st Flr - Asst Engineer Office 600 SF 7 Floor - Concrete Epoxy/ Painted 6-10 years Lighting - Pendent/Surface 1st Flr - Asst Engineer Office 6 EA 7 6-10 years Power Distribution 1st Flr - Asst Engineer Office 12 EΑ 7 10+ years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Walls - Plaster/Drvwall 1st Flr - Asst Engineer Office 1.679 SF 10+ vears 7 Ceiling - Plaster/Drvwall SF 7 1st Flr - Pool Office 80 10+ years Doors - Side-lite 1st Flr - Pool Office 16 SF 7 10+ years Doors - Wood Doors inclu hw ΕA 7 1st Flr - Pool Office 1 10+ years SF Floor - Tile 1st Flr - Pool Office 80 7 6-10 years 2 ΕA 7 Lighting - Pendent/Surface 1st Flr - Pool Office 6-10 years **Power Distribution** 1st Flr - Pool Office ΕA 7 4 10+ years SF Walls - Plaster/Drywall 1st Flr - Pool Office 360 7 10+ years SF Ceiling - Plaster/Drywall 1st Flr - Weight Rm Office 205 7 10+ years Doors - Wood Doors inclu hw 1st Flr - Weight Rm Office ΕA 6 10+ vears 1 1st Flr - Weight Rm Office Floor - Concrete Epoxy/ Painted 205 SF 5 6-10 years Lighting - Pendent/Surface 1st Flr - Weight Rm Office 8 ΕA 7 10+ years **Power Distribution** 1st Flr - Weight Rm Office 2 ΕA 7 10+ years 270 SF Walls - Plaster/Drywall 1st Flr - Weight Rm Office 6 10+ years Walls - Structural Glazed Tile 1st Flr - Weight Rm Office SF 300 6 10+ years Ceiling - Plaster/Drywall SF 7 203 160 10+ years ΕA 7 Doors - Wood Doors inclu hw 203 1 10+ years Floor - Wood 203 160 SF 6 10+ years Lighting - Pendent/Surface 203 4 ΕA 7 10+ vears Power Distribution 203 4 EΑ 7 10+ years Walls - Plaster/Drywall 203 480 SF 7 10+ years SF 7 Ceiling - Plaster/Drywall 207 160 10+ years Doors - Wood Doors inclu hw 7 207 1 EA 10+ years SF Floor - Epoxy/ Painted 207 160 7 10+ years Lighting - Pendent/Surface EΑ 7 207 1 10+ years 2 Power Distribution 207 ΕA 7 10+ vears SF Walls - Plaster/Drywall 207 420 7 10+ years AC Unit 309 ΕA 7 6-10 years 1 Ceiling - Lay-in SF 309 144 7 10+ years Doors - Side-lite 309 32 SF 7 10+ years SF Doors - Transom Window 309 30 7 10+ vears Doors - Wood Doors inclu hw 309 1 EΑ 6 10+ vears SF 7 10+ years Floor - Wood 309 144 Lighting - Lay-in 309 ΕA 6 6-10 years 4 3 7 **Power Distribution** 309 EΑ 10+ years Walls - Plaster/Drywall SF 7 309 397 10+ years AC Unit 337 1 ΕA 7 6-10 years Ceiling - Lay-in 337 SF 148 7 10+ years SF Doors - Side-lite 337 28 7 10+ years SF Doors - Transom Window 337 28 7 10+ vears Doors - Wood Doors inclu hw 337 1 ΕA 7 10+ years 337 SF Floor - Wood 148 5 10+ vears Lighting - Lay-in 337 EA 6 6-10 years 4 337 8 7 Power Distribution EΑ 10+ years



	ry : Room		Building : Main				
Calego	ry . Room			unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ereup	Walls - Plaster/Drywall	337	490	SF	7	10+ years	
	AC Unit	3rd Floor - Boys' Gym Balcony	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor - Boys' Gym Balcony	187	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - Boys' Gym Balcony	1	ĒA	7	10+ years	
	Floor - Carpet	3rd Floor - Boys' Gym Balcony	187	SF	5	0-1 year	Loose and dirty carpet
	Lighting - Pendent/Surface	3rd Floor - Boys' Gym Balcony	3	EA	6	6-10 years	, i
	Power Distribution	3rd Floor - Boys' Gym Balcony	2	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - Boys' Gym Balcony	490	SF	7	10+ years	
	AC Unit	Rm 129 - Counselor Office	2	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 129 - Counselor Office	705	SF	7	10+ years	
	Doors - Transom Window	Rm 129 - Counselor Office	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 129 - Counselor Office	2	EA	7	10+ years	
	Floor - Tile	Rm 129 - Counselor Office	700	SF	7	6-10 years	
	Floor - Tile	Rm 129 - Counselor Office	5	SF	4	1-2 years	Cracking tile
	Lighting - Lay-in	Rm 129 - Counselor Office	21	EA	7	6-10 years	
	Power Distribution	Rm 129 - Counselor Office	16	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 129 - Counselor Office	840	SF	7	10+ years	
	AC Unit	Rm 131 - Counselor Office	2	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 131 - Counselor Office	705	SF	7	10+ years	
	Doors - Transom Window	Rm 131 - Counselor Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 131 - Counselor Office	1	EA	7	10+ years	
	Floor - Tile	Rm 131 - Counselor Office	705	SF	7	6-10 years	
	Lighting - Lay-in	Rm 131 - Counselor Office	18	EA	7	6-10 years	
	Lighting - Lay-in	Rm 131 - Counselor Office	3	EA	6	2-5 years	Not working
	Power Distribution	Rm 131 - Counselor Office	16	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 131 - Counselor Office	840	SF	7	10+ years	
	AC Unit	Rm 131A - Counselor Office	1	EA	7	6-10 years	
		Conference Rm			_		
	Ceiling - Lay-in	Rm 131A - Counselor Office	340	SF	7	10+ years	
		Conference Rm			_	4.0	
	Doors - Wood Doors inclu hw	Rm 131A - Counselor Office	1	EA	7	10+ years	
		Conference Rm	0.40	0-	•	0.40	
	Floor - Carpet	Rm 131A - Counselor Office	340	SF	6	6-10 years	
		Conference Rm	0	- ^	-	0.40	
	Lighting - Lay-in	Rm 131A - Counselor Office	8	EA	7	6-10 years	
		Conference Rm	0	- ^	0	0.5	
	Lighting - Lay-in	Rm 131A - Counselor Office	2	EA	6	2-5 years	Not working
	Device Distribution	Conference Rm	0	F A	7	10	
	Power Distribution	Rm 131A - Counselor Office	6	EA	7	10+ years	
	Malla Diastar/Drawall	Conference Rm	004	05	7	10	
	Walls - Plaster/Drywall	Rm 131A - Counselor Office	634	SF	7	10+ years	
		Conference Rm	4		7	6 10 1000	
	AC Unit	Rm 135 - Discipline Office	1 760	EA SF	7 7	6-10 years	
	Ceiling - Lay-in	Rm 135 - Discipline Office	760	эг	1	10+ years	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Doors - Transom Window Rm 135 - Discipline Office 9 SF 10+ vears 7 Doors - Wood Doors inclu hw Rm 135 - Discipline Office ΕA 7 1 10+ vears Floor - Tile Rm 135 - Discipline Office 760 SF 7 6-10 years Rm 135 - Discipline Office ΕA 7 Lighting - Lay-in 20 6-10 years Rm 135 - Discipline Office Lighting - Lay-in 1 EΑ 6 2-5 years Not working 7 Power Distribution Rm 135 - Discipline Office 12 EΑ 10+ years Walls - Plaster/Drywall Rm 135 - Discipline Office SF 7 10+ years 1,150 AC Unit Rm 135A - Attendance Office 1 EΑ 7 6-10 years Ceiling - Lav-in Rm 135A - Attendance Office 340 SF 7 10+ years Doors - Wood Doors inclu hw Rm 135A - Attendance Office ΕA 7 10+ vears 1 Floor - Tile Rm 135A - Attendance Office 340 SF 7 6-10 years Lighting - Lay-in Rm 135A - Attendance Office 9 ΕA 7 6-10 years **Power Distribution** Rm 135A - Attendance Office 6 ΕA 7 10+ years SF 7 Walls - Plaster/Drywall Rm 135A - Attendance Office 634 10+ years Rm 137 - Office ΕA 7 AC Unit 1 6-10 years Ceiling - Lay-in 187 SF 7 Rm 137 - Office 6-10 years SF 7 Doors - Transom Window Rm 137 - Office 9 10+ vears Doors - Wood Doors inclu hw Rm 137 - Office 1 EΑ 7 10+ years SF Floor - Tile Rm 137 - Office 187 7 6-10 years Lighting - Lay-in Rm 137 - Office 3 EΑ 7 6-10 years **Power Distribution** Rm 137 - Office 2 ΕA 7 10+ years SF 7 Walls - Plaster/Drywall Rm 137 - Office 490 10+ years 7 AC Unit Rm 142 - Office 1 EA 6-10 years SF 7 Ceiling - Plaster/Drywall Rm 142 - Office 126 10+ years Doors - Transom Window SF 7 Rm 142 - Office 9 10+ years Doors - Wood Doors inclu hw Rm 142 - Office 1 ΕA 7 10+ vears SF Floor - Tile Rm 142 - Office 126 7 6-10 years Lighting - Pendent/Surface Rm 142 - Office ΕA 7 6-10 years 4 Power Distribution 6 ΕA Rm 142 - Office 7 10+ years Storage/ Closet Rm 142 - Office 50 SF 7 10+ years SF Walls - Plaster/Drvwall Rm 142 - Office 466 7 10+ years SF Ceiling - Plaster/Drvwall Rm 205 - ROTC Army Instructor 320 7 10+ years Office Ceiling - Plaster/Drywall Rm 205 - ROTC Army Instructor 10 SF 5 Big chunks falling the engineer and 0-1 year Office the team lead was informed Rm 205 - ROTC Army Instructor Doors - Wood Doors inclu hw 1 EΑ 7 10+ years Office Floor - Wood Rm 205 - ROTC Army Instructor 330 SF 7 10+ years Office ΕA Lighting - Pendent/Surface Rm 205 - ROTC Army Instructor 5 7 6-10 years Office Power Distribution Rm 205 - ROTC Army Instructor FΑ 7 4 10+ years Office Walls - Plaster/Drywall Rm 205 - ROTC Army Instructor 490 SF 7 10+ years



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Office					
	AC Unit	Rm 209	1	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 209	148	SF	7	10+ years	
	Doors - Side-lite	Rm 209	28	SF	7	10+ years	
	Doors - Transom Window	Rm 209	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 209	1	EA	7	10+ years	
	Floor - Wood	Rm 209	148	SF	7	10+ years	
	Lighting - Lay-in	Rm 209	4	EA	7	6-10 years	
	Power Distribution	Rm 209	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 209	490	SF	7	10+ years	
	AC Unit	Rm 215 - Audio/Visual Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 215 - Audio/Visual Office	330	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 215 - Audio/Visual Office	1	EA	7	10+ years	
	Floor - Wood	Rm 215 - Audio/Visual Office	330	SF	7	10+ years	
	Lighting - Lay-in	Rm 215 - Audio/Visual Office	9	EA	7	6-10 years	
	Power Distribution	Rm 215 - Audio/Visual Office	5	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 215 - Audio/Visual Office	490	SF	7	10+ years	
	AC Unit	Rm 237 - Math office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 237 - Math office	148	SF	7	10+ years	
	Doors - Side-lite	Rm 237 - Math office	28	SF	7	10+ years	
	Doors - Transom Window	Rm 237 - Math office	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 237 - Math office	1	EA	7	10+ years	
	Floor - Wood	Rm 237 - Math office	148	SF	7	10+ years	
	Lighting - Lay-in	Rm 237 - Math office	4	EA	5	6-10 years	
	Power Distribution	Rm 237 - Math office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 237 - Math office	490	SF	7	10+ years	
	AC Unit	Rm 239B - Coaches Office (in Boys	-30	EA	7	6-10 years	
	AC ON	Gym)	1	LA	1	0-10 years	
	Ceiling - Plaster/Drywall	Rm 239B - Coaches Office (in Boys	110	SF	7	10+ years	
	Celling - Plaster/Drywall		148	ЗГ	7	10+ years	
	Doors - Side-lite	Gym) Bm 220B - Casabaa Offica (in Boug	20	SF	7	10	
	Doors - Side-life	Rm 239B - Coaches Office (in Boys	28	35	7	10+ years	
	Dears Weed Dears in the hou	Gym) Day 2000 - Os salvas Office (in Days		- ^	7	10	
	Doors - Wood Doors inclu hw	Rm 239B - Coaches Office (in Boys	1	EA	7	10+ years	
		Gym)		~-	_	o 40	
	Floor - Tile	Rm 239B - Coaches Office (in Boys	148	SF	7	6-10 years	
		Gym)	_		_		
	Lighting - Lay-in	Rm 239B - Coaches Office (in Boys	2	EA	7	6-10 years	
		Gym)					
	Power Distribution	Rm 239B - Coaches Office (in Boys	6	EA	7	10+ years	
		Gym)					
	Walls - Plaster/Drywall	Rm 239B - Coaches Office (in Boys	490	SF	7	10+ years	
		Gym)					
	AC Unit	Rm 242 - Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Rm 242 - Office	126	SF	7	10+ years	
						-	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Transom Window	Rm 242 - Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 242 - Office	1	EA	7	10+ years	
	Floor - Wood	Rm 242 - Office	126	SF	7	10+ years	
	Lighting - Lay-in	Rm 242 - Office	4	EA	7	6-10 years	
	Power Distribution	Rm 242 - Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Rm 242 - Office	460	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 218 Book Room	291	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 218 Book Room	1	EA	7	10+ years	
	Floor - Wood	Room 218 Book Room	291	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 218 Book Room	5	EA	7	6-10 years	
	Power Distribution	Room 218 Book Room	5	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 218 Book Room	450	SF	7	10+ years	
uditori	um & Theater						
	Balcony Seating	1st Floor	520	EA	7	10+ years	
	Ceiling - Lay-in	1st Floor	7,992	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,410	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	14	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	40	EA	7	10+ years	
	Floor - Carpet	1st Floor	2,350	SF	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st Floor	5,743	SF	5	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	5	SF	4	1-2 years	Damaged floor
	Floor - Tile	1st Floor	1,304	SF	7	10+ years	Damaged hoor
	Lighting - Lay-in	1st Floor	83	EA	7	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	63	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	58	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	34	EA	7	6-10 years	
	Main Floor Seating	1st Floor	1,232	EA	7	10+ years	
	Sound System	1st Floor	1,232	EA	7	6-10 years	
	Stage	1st Floor	3,020	SF	7	10+ years	
	Stage Curtain	1st Floor	5,020	EA	7	6-10 years	
	Stage Lift	1st Floor	0	EA	7		
	Stage Lift Stage Lighting System	1st Floor	3	EA	7	10+ years 6-10 years	
		1st Floor	42		7	•	
	Stage-Stairs - Wood Stairs - Asphalt			LF		10+ years	
	•	1st Floor	36		7	10+ years	
	Stairs - Terrazzo	1st Floor	816	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	13,432	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	200	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	651	SF	7	10+ years	
	AC Unit	Rm 249 - Little Theater	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Rm 249 - Little Theater	2,570	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Rm 249 - Little Theater	10	SF	4	0-1 year	Big chunk of drywall falling. Both

engineer and team lead were



Catago	Category : Room			uilding	Main		436 W Wilson AVENUE, Chicago, IL 60625
Categor	ry:Room		Building : Main			Decemand	
C	ltem. Tune	Leastion	Quantitu	UOM	Dank	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	Rm 249 - Little Theater	26	ог	7	10, 10,000	informed.
			36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 249 - Little Theater	5	EA SF	7	10+ years	
	Floor - Tile/Sheet	Rm 249 - Little Theater	2,570		7	6-10 years	
	Lighting - Pendent/Surface	Rm 249 - Little Theater	27	EA	7	6-10 years	
	Sound System	Rm 249 - Little Theater	1	EA	7	10+ years	
	Stage	Rm 249 - Little Theater	650	SF	7	10+ years	
	Stage Curtain	Rm 249 - Little Theater	3	EA	7	10+ years	
	Stage Lighting System	Rm 249 - Little Theater	1	EA	7	10+ years	
	Stage-Stairs - Wood	Rm 249 - Little Theater	6	LF	7	10+ years	
	Storage/ Closet	Rm 249 - Little Theater	8	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 249 - Little Theater	4,205	SF	7	10+ years	
Clinic							
	Ceiling - Exposed	Rm 166 - Heartland Heath Center	250	SF	7	10+ years	
	Ceiling - Lay-in	Rm 166 - Heartland Heath Center	1,250	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 166 - Heartland Heath Center	7	ĒA	7	10+ years	
	Floor - Carpet	Rm 166 - Heartland Heath Center	250	SF	7	6-10 years	
	Floor - Tile/Sheet	Rm 166 - Heartland Heath Center	1,250	SF	7	6-10 years	
	Lighting - Lay-in	Rm 166 - Heartland Heath Center	21	EA	7	6-10 years	
	Lighting - Lay-in	Rm 166 - Heartland Heath Center	1	EA	6	2-5 years	Not working
	Lighting - Pendent/Surface	Rm 166 - Heartland Heath Center	4	EA	7	6-10 years	
	Storage/ Closet	Rm 166 - Heartland Heath Center	8	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 166 - Heartland Heath Center	2,680	SF	7	10+ years	
Green Ho							
Greening	Finishes	1st Floor	540	SF	5	10+ years	
	Glazing	1st Floor	600	SF	6	6-10 years	Roof portion
	Glazing	1st Floor	350	SF	6	10+ years	Wall portion - recalculated quantities
	Mechanical	1st Floor	120	SF	7	10+ years	
	Plumbing	1st Floor	540	SF	7	10+ years	
Gymnasi	2						
	Bleacher Seating	2nd Flr - Boys' Gym Rm 241	176	EA	7	10+ years	
	Ceiling - Lay-in	2nd Flr - Boys' Gym Rm 241	9,585	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Flr - Boys' Gym Rm 241	6,000	EA	6	10+ years	
	Floor - Concrete	2nd Fir - Boys' Gym Rm 241	2,065	SF	7	10+ years	
	Floor - Wood	2nd Fir - Boys' Gym Rm 241	7,520	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure	2nd Fir - Boys' Gym Rm 241	24	EA	7	10+ years	
	Sodium		24		'	ior years	
	Scoreboards	2nd Flr - Boys' Gym Rm 241	1	EA	7	10+ years	
	Sound System	2nd Flr - Boys' Gym Rm 241	1	EA	7	10+ years	
					-		



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments 2nd Flr - Boys' Gym Rm 241 Walls - Plaster/Drvwall 7,205 SF 10+ vears 7 Walls - Structural Glazed Tile 2nd Flr - Boys' Gym Rm 241 SF 7 3.165 10+ years Ceiling - Lay-in 2nd Flr - Girls' Gym Rm 243 7.520 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Flr - Girls' Gym Rm 243 ΕA 7 4 10+ years SF Floor - Wood 2nd Flr - Girls' Gym Rm 243 7,520 7 10+ years 7 Lighting - Metal Halide/ High Pressure 2nd Flr - Girls' Gym Rm 243 20 EΑ 6-10 years Sodium SF Walls - Plaster/Drywall 2nd Flr - Girls' Gym Rm 243 4.685 7 10+ years Walls - Structural Glazed Tile 2nd Flr - Girls' Gym Rm 243 2,600 SF 7 10+ years SF Walls - Structural Glazed Tile 2nd Flr - Girls' Gym Rm 243 7 45 10+ years Kitchen 1,292 Ceiling - Plaster/Drywall 1st Floor SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 3 ΕA 7 10+ years Floor - Tile 1st Floor 1.267 SF 6 10+ vears Floor - Tile 1st Floor 25 SF 4 1-2 years Damaged tile 37 FΑ 7 Lighting - Pendent/Surface 1st Floor 6-10 years Walls - Structural Glazed Tile 1st Floor 1,588 SF 7 10+ years Library AC Unit 2nd Floor 2 ΕA 7 6-10 years LF Casework 2nd Floor 174 7 10+ years SF Ceiling - Lay-in 2nd Floor 2,232 7 10+ years Doors - Side-lite SF 7 2nd Floor 42 10+ years Doors - Transom Window 2nd Floor 14 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 ΕA 7 10+ years Floor - Wood 2nd Floor 2.232 SF 7 10+ years 2nd Floor 7 Lighting - Lay-in 66 ΕA 6-10 years Walls - Plaster/Drywall 2nd Floor 2.520 SF 7 10+ years Locker/Shower Room SF 7 Accessories 1st Floor 4,835 6-10 years Benches, ped mounted 1st Floor LF 6 6-10 years 110 SF Ceiling - Plaster/Drywall 1st Floor 4.835 6 10+ years ΕA 7 Doors - Wood Doors inclu hw 1st Floor 10+ years 2 Floor - Tile Ceramic/ Porcelain 1st Floor 4.805 SF 7 6-10 years SF Floor - Tile Ceramic/ Porcelain 1st Floor 30 4 1-2 years Misc damaged tile Floor Drain 1st Floor 2 ΕA 7 10+ years 2 ΕA 7 Lavatory 1st Floor 10+ years Lighting - Pendent/Surface 57 ΕA 7 6-10 years 1st Floor FΑ Lighting - Pendent/Surface 1st Floor 13 6 2-5 years Not working Partitions 1st Floor 2 FΑ 4 1-2 years Missing doors Showers 1st Floor 10 FΑ 7 10+ years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Student Lockers - Two Tier 1st Floor 271 ΕA 10+ vears 7 1st Floor ΕA 7 Urinals 3 10+ years Walls - Plaster/Drywall 1st Floor 700 SF 7 10+ years SF Walls - Plaster/Drywall 1st Floor 5 5 1-2 years Damaged plaster SF 7 Walls - Structural Glazed Tile 1st Floor 5,327 10+ years 7 Water Closet 1st Floor EΑ 10+ years 2 Accessories 1st Floor 72 SF 7 10+ years LF Benches, ped mounted 1st Floor 86 6 10+ years SF Ceiling - Plaster/Drvwall 1st Floor 4.272 7 10+ years Doors - Wood Doors inclu hw 1st Floor ΕA 7 10+ vears 5 Floor - Tile Ceramic/ Porcelain 1st Floor 4.242 SF 6 6-10 vears Floor - Tile Ceramic/ Porcelain 1st Floor 30 SF 4 1-2 years Misc cracked and damaged tile Floor Drain 23 ΕA 7 10+ years 1st Floor ΕA 7 Hand Dryer 1st Floor 3 10+ years 2 ΕA 7 Lavatory 1st Floor 10+ years Lighting - Pendent/Surface 91 FΑ 7 1st Floor 6-10 years Partitions 1st Floor 1 ΕA 7 1-2 years Damaged stall Partitions 1st Floor 39 ΕA 7 10+ years Showers 1st Floor 32 ΕA 7 10+ vears Storage/ Closet 1st Floor 188 SF 7 10+ years Student Lockers - Two Tier 1st Floor 192 ΕA 7 10+ years SF 7 Walls - Plaster/Drywall 1st Floor 1,075 10+ years Walls - Structural Glazed Tile SF 7 1st Floor 4.790 10+ years Water Closet 1st Floor FΑ 7 10+ years 7 Accessories 1st Flr - Boys' Pool Locker Rm SF 7 6-10 years 1.850 LF Benches, ped mounted 1st Flr - Bovs' Pool Locker Rm 16 7 10+ vears Ceiling - Plaster/Drywall SF 1st Flr - Boys' Pool Locker Rm 1,850 7 10+ years Doors - Steel Doors incl hw 1st Flr - Boys' Pool Locker Rm 2 ΕA 7 10+ years 1st Flr - Boys' Pool Locker Rm Doors - Wood Doors inclu hw 2 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 1st Flr - Boys' Pool Locker Rm 1,850 SF 7 6-10 years 1st Flr - Boys' Pool Locker Rm SF Floor - Tile Ceramic/ Porcelain 5 4 1-2 vears Damaged floor Floor Drain 1st Flr - Bovs' Pool Locker Rm 4 ΕA 7 10+ vears 1st Flr - Boys' Pool Locker Rm 4 FΑ 7 Hand Dryer 10+ vears 1st Flr - Boys' Pool Locker Rm 4 FΑ 7 10+ vears Lavatorv Lighting - Pendent/Surface 35 7 1st Flr - Boys' Pool Locker Rm ΕA 6-10 years 3 ΕA 7 Partitions 1st Flr - Boys' Pool Locker Rm 10+ years Showers 1st Flr - Boys' Pool Locker Rm 10 ΕA 7 10+ years Student Lockers - One Tier 1st Flr - Boys' Pool Locker Rm 130 ΕA 7 10+ years Urinals 1st Flr - Boys' Pool Locker Rm 8 EΑ 7 10+ years 1st Flr - Boys' Pool Locker Rm SF Walls - Plaster/Drvwall 700 7 10+ vears SF Walls - Structural Glazed Tile 1st Flr - Boys' Pool Locker Rm 4.537 7 10+ years 1st Flr - Boys' Pool Locker Rm 7 Water Closet FΑ 10+ years 1

Lunch & Multipurpose Room



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments AC Unit 117 2 ΕA 6-10 vears 7 1.237 SF 7 Ceiling - Lav-in 117 10+ years Doors - Transom Window 117 18 SF 7 10+ years ΕA 7 Doors - Wood Doors inclu hw 117 4 10+ years SF 7 Floor - Tile 117 1,237 6-10 years 7 Lighting - Lay-in 117 36 EΑ 6-10 years Market Board LF 7 6-10 years 117 6 SF Storage/ Closet 117 38 7 10+ years Walls - Plaster/Drvwall 117 1,158 SF 7 10+ years SF Ceiling - Lay-in 1st Floor 7.115 7 10+ years Doors - Steel Doors incl hw 1st Floor 7 ΕA 7 10+ vears Doors - Transom Window 1st Floor 52 SF 7 10+ years Doors - Wood Doors inclu hw 6 ΕA 7 10+ years 1st Floor SF Floor - Tile 1st Floor 7,103 6 10+ years Floor - Tile SF 1st Floor 12 4 1-2 years Damaged tiles Lighting - Pendent/Surface 79 ΕA 6 1st Floor 6-10 years Walls - Plaster/Drvwall SF 7 1st Floor 3.150 10+ years SF Walls - Structural Glazed Tile 1st Floor 6,300 7 10+ years SF Ceiling - Plaster/Drywall 1st Flr - Weight Rm between 2.065 7 10+ years Girls'/Boys' locker Rms Doors - Wood Doors inclu hw 1st Flr - Weight Rm between 3 ΕA 7 10+ years Girls'/Boys' locker Rms 1st Flr - Weight Rm between Floor - Tile Ceramic/ Porcelain 165 SF 7 6-10 years Girls'/Boys' locker Rms Floor - Weight/ Fitness Room Floor Matting 1st Flr - Weight Rm between SF 1.900 7 6-10 years Girls'/Bovs' locker Rms Lighting - Pendent/Surface 1st Flr - Weight Rm between ΕA 7 6-10 years 49 Girls'/Boys' locker Rms 1st Flr - Weight Rm between Storage/ Closet 200 SF 7 10+ years Girls'/Boys' locker Rms 1st Flr - Weight Rm between Walls - Plaster/Drywall 1,455 SF 7 10+ years Girls'/Bovs' locker Rms 1st Flr - Weight Rm between Walls - Structural Glazed Tile SF 1.600 7 10+ years Girls'/Bovs' locker Rms Ceiling - Lay-in Faculty Lunch Room (inside 435 SF 7 10+ years Cafeteria) Doors - Side-lite Faculty Lunch Room (inside 28 SF 7 10+ years Cafeteria) Doors - Wood Doors inclu hw Faculty Lunch Room (inside 1 EΑ 7 10+ years Cafeteria) Floor - Tile Faculty Lunch Room (inside 430 SF 6 10+ years Cafeteria) Floor - Tile Faculty Lunch Room (inside 5 SF Damaged tile 4 1-2 years Cafeteria)



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Faculty Lunch Room (inside FΑ Lighting - Pendent/Surface 4 6-10 vears 7 Cafeteria) Walls - Plaster/Drywall Faculty Lunch Room (inside 340 SF 7 10+ years Cafeteria) Walls - Structural Glazed Tile Faculty Lunch Room (inside 340 SF 7 10+ years Cafeteria) Ceiling - Lay-in Serving Room 1,682 SF 7 10+ years SF Doors - Transom Window Serving Room 36 7 10+ years Doors - Wood Doors inclu hw Serving Room 6 ΕA 7 10+ years Serving Room SF Floor - Tile 1.660 7 10+ years SF Floor - Tile Serving Room 22 4 1-2 vears Cracked and damaged tile Lighting - Lay-in Serving Room 43 EΑ 7 6-10 years Serving Line Serving Room 144 LF 7 10+ years Serving Room SF 7 Storage/ Closet 65 10+ years Walls - Plaster/Drywall Serving Room 360 SF 7 10+ years Walls - Structural Glazed Tile Serving Room SF 7 1,443 10+ years MDF IDF Doors - Steel Doors incl hw 118 7 1 EΑ 10+ years 118 320 SF 7 10+ years Finishes Window AC Unit 118 1 ΕA 7 6-10 years Mechanical/ Service Rooms Janitor's Closet 1st Floor 20 SF 5 10+ years Storage Room 1st Floor 820 SF 7 10+ years SF Storage Room 1st Floor 7 10+ years 117 SF Storage Room 1st Floor 130 5 2-5 years Janitor's Closet SF 5 2nd Floor 20 10+ years Mechanical/ Service Rooms 2nd Floor 40 SF 7 10+ years SF 7 Storage Room 2nd Floor 40 10+ years 140 SF 7 Storage Room 2nd Floor 10+ years SF 7 Storage Room 2nd Floor 100 10+ years Janitor's Closet SF 7 3rd Floor 10 10+ years Janitor's Closet 3rd Floor 10 SF 7 10+ years Janitor's Closet 3rd Floor 20 SF 5 10+ vears SF Janitor's Closet 3rd Floor 10 5 10+ years Mechanical/ Service Rooms 3rd Floor SF 7 460 10+ vears Mechanical/ Service Rooms 3rd Floor 10 SF 7 10+ years Mechanical/ Service Rooms 42 SF 5 3rd Floor 10+ years 7 SF Storage Room 3rd Floor 667 10+ years Air Intake Plenums SF 5 **Basement** 3,441 10+ years Air Tunnel 8,110 SF 7 10+ years Basement SF Auditorium Plenums Basement 9.402 7 10+ years Boiler Room Basement 5,500 SF 7 10+ years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Crawl Space - Unfinished **Basement** 35.050 SF 5 10+ vears Mechanical/ Service Rooms 22.585 SF 7 Basement 10+ years Mechanical/ Service Rooms Basement 20 SF 5 10+ years SF 7 Storage Room **Basement** 7.348 10+ years Pool & Natatorium Bleachers Seating/Plank Seating 1st Floor 43 EΑ 7 10+ years SF Ceiling - Lay-in 1st Floor 7.910 7 10+ years SF Ceiling - Lav-in 1st Floor 64 1-2 vears Missing tile 4 Doors - Wood Doors inclu hw 1st Floor 2 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 7,902 SF 7 6-10 years 1st Floor Floor - Tile Ceramic/ Porcelain 1st Floor 8 SF 4 1-2 years Damaged tile 1st Floor 43 ΕA 7 6-10 years Lighting - Lay-in Lighting - Lay-in 1st Floor 21 ΕA 6 2-5 years Not working Pool Basin SF 7 1st Floor 3.050 10+ years Pool Deck 1st Floor 4.400 SF 7 10+ years Pool Deck Drains FΑ 1st Floor 14 7 10+ years SF Walls - Structural Glazed Tile 1st Floor 13,416 7 10+ years Prep Room LF Casework 110A 20 7 10+ years SF Ceiling - Plaster/Drywall 110A 255 7 10+ years SF Doors - Side-lite 110A 32 7 10+ years Doors - Wood Doors inclu hw 2 ΕA 7 110A 10+ years Floor - Tile/Sheet 110A 255 SF 5 10+ years Lighting - Pendent/Surface 6 ΕA 6 6-10 years 110A Lighting - Pendent/Surface 110A 2 ΕA 6 2-5 years Not working Walls - Plaster/Drvwall 704 SF 7 110A 10+ years Work Sink FΑ 7 10+ years 110A 1 SF Ceiling - Plaster/Drywall 2nd flr - Sound Booth above 91 7 10+ years auditorium stage SF Ceiling - Plaster/Drywall 2nd flr - Sound Booth above 10 4 0-1 year Loose drywall ceiling auditorium stage Doors - Wood Doors inclu hw 2nd flr - Sound Booth above 2 EA 7 10+ years auditorium stage Floor - Concrete 101 SF 2nd flr - Sound Booth above 7 10+ years auditorium stage Lighting - Pendent/Surface 2nd flr - Sound Booth above 2 FΑ 7 6-10 years auditorium stage Walls - Plaster/Drywall 2nd flr - Sound Booth above 328 SF 6 10+ years auditorium stage Casework 306 LF 7 10+ years 49 SF Ceiling - Lay-in 306 138 7 10+ years Ceiling - Plaster/Drywall 306 40 SF 7 10+ years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Doors - Wood Doors inclu hw 306 3 ΕA 10+ years 7 306 40 SF 7 Floor - Tile 10+ years Floor - Tile 306 138 SF 7 10+ years Lighting - Pendent/Surface 306 5 ΕA 7 6-10 years SF Walls - Plaster/Drywall 306 356 7 10+ years 7 Work Sink 306 EΑ 10+ years 1 307 - Projection Room for SF 7 Ceiling - Plaster/Drywall 186 10+ years Auditorium Doors - Wood Doors inclu hw 307 - Projection Room for 1 ΕA 7 10+ years Auditorium Floor - Concrete 307 - Projection Room for 186 SF 7 10+ years Auditorium ΕA 5 Lighting - Pendent/Surface 307 - Projection Room for 1 6-10 years Auditorium SF Walls - Plaster/Drywall 307 - Projection Room for 513 7 10+ years Auditorium SF Ceiling - Lay-in 346 300 7 10+ years Doors - Steel Doors incl hw 346 1 ΕA 7 10+ years 9 SF Doors - Transom Window 346 7 10+ vears Doors - Wood Doors inclu hw 346 1 ΕA 7 10+ years Floor - Tile/Sheet 346 300 SF 7 10+ years ΕA 7 Lighting - Lay-in 346 3 6-10 years SF 7 Walls - Plaster/Drywall 346 638 10+ years Walls - Plaster/Drywall SF 346 20 4 0-1 year Water damage Work Sink 346 EΑ 7 1 10+ years LF Casework Rm 146 Prep Rm (shared by 144 & 30 7 10+ years 148) Rm 146 Prep Rm (shared by 144 & 300 SF 7 Ceiling - Lay-in 10+ years 148) Doors - Steel Doors incl hw Rm 146 Prep Rm (shared by 144 & 1 ΕA 7 10+ years 148) Doors - Transom Window Rm 146 Prep Rm (shared by 144 & 9 SF 7 10+ years 148) Doors - Wood Doors inclu hw Rm 146 Prep Rm (shared by 144 & FΑ 7 1 10+ years 148) Rm 146 Prep Rm (shared by 144 & SF Floor - Tile/Sheet 300 7 6-10 years 148) Rm 146 Prep Rm (shared by 144 & 6 EΑ 7 6-10 years Lighting - Lay-in 148) SF Walls - Plaster/Drywall Rm 146 Prep Rm (shared by 144 & 658 7 10+ years 148) Work Sink Rm 146 Prep Rm (shared by 144 & 2 FΑ 7 10+ years 148) Casework Rm 208A 20 LF 7 10+ years



3436 W Wilson AVENUE, Chicago, IL 60625 **Building : Main** Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Ceiling - Plaster/Drvwall Rm 208A 62 SF 6 10+ vears Doors - Wood Doors inclu hw Rm 208A ΕA 7 1 10+ vears Floor - Tile/Sheet Rm 208A 62 SF 7 6-10 years Lighting - Pendent/Surface Rm 208A ΕA 7 1 6-10 years SF Walls - Plaster/Drywall Rm 208A 124 7 10+ years Work Sink 7 Rm 208A EΑ 10+ years 1 Casework Rm 210A 20 LF 7 10+ years SF Ceiling - Lay-in Rm 210A 174 7 10+ years Doors - Wood Doors inclu hw Rm 210A 1 EΑ 7 10+ years SF Floor - Tile Rm 210A 174 7 6-10 years Lighting - Lav-in Rm 210A 6 ΕA 7 6-10 years Walls - Plaster/Drywall Rm 210A 530 SF 7 10+ years Work Sink Rm 210A ΕA 7 10+ years 1 SF 7 Ceiling - Lay-in Rm 219A - Library Work Room 262 10+ years Doors - Wood Doors inclu hw Rm 219A - Library Work Room ΕA 7 1 10+ years Floor - Wood Rm 219A - Library Work Room 262 SF 7 10+ years Rm 219A - Library Work Room ΕA 7 Lighting - Lay-in 4 6-10 years SF Walls - Plaster/Drywall Rm 219A - Library Work Room 743 7 10+ years Work Sink Rm 219A - Library Work Room ΕA 7 10+ vears 1 Restroom Accessories 1st Floor 318 SF 7 6-10 vears Ceiling - Plaster/Drvwall SF 1st Floor 318 7 10+ years Doors - Transom Window 1st Floor 18 SF 7 10+ vears Doors - Wood Doors inclu hw 1st Floor 2 ΕA 7 10+ years Floor - Tile Ceramic/ Porcelain 318 SF 7 10+ years 1st Floor 7 Floor Drain 1st Floor 1 EΑ 10+ years Hand Drver 7 1st Floor 1 EΑ 6-10 years FΑ 7 Lavatory 1st Floor 1 10+ years Lavatorv 1st Floor 1 ΕA 5 1-2 years Sink running Lighting - Pendent/Surface 1st Floor 7 ΕA 7 6-10 years 5 Partitions 1st Floor ΕA 7 10+ vears Urinals 1st Floor 7 EΑ 7 10+ years Walls - Plaster/Drywall 1st Floor 633 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 5 SF 5 1-2 years Water damaged 7 Walls - Structural Glazed Tile 213 SF 1st Floor 10+ years Water Closet 1st Floor 5 FΑ 6 10+ years Accessories 26 SF 7 6-10 years 1st Floor - 116 SF Ceiling - Lav-in 1st Floor - 116 26 7 10+ vears Doors - Wood Doors inclu hw EΑ 7 10+ years 1st Floor - 116 1 Floor - Tile Ceramic/ Porcelain 16 SF 1st Floor - 116 6 10+ years SF Floor - Tile Ceramic/ Porcelain 1st Floor - 116 10 4 1-2 years Missing tile Lavatory 1st Floor - 116 1 ΕA 6 10+ years 7 Lighting - Lay-in 1st Floor - 116 1 EΑ 6-10 years



Category : Room **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Walls - Plaster/Drvwall 1st Floor - 116 150 SF 10+ vears 7 Walls - Tile Ceramic/ Porcelain SF 7 1st Floor - 116 100 10+ vears Accessories 1st Floor - East 229 SF 7 6-10 years 229 SF 7 Ceiling - Plaster/Drywall 1st Floor - East 10+ years 7 Doors - Steel Doors incl hw 1st Floor - East 1 EΑ 10+ years SF 9 7 Doors - Transom Window 1st Floor - East 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor - East 229 SF 7 10+ years Floor Drain 1st Floor - East 1 ΕA 7 10+ years Hand Dryer 1st Floor - East 1 ΕA 7 10+ years 1st Floor - East 2 FΑ 7 10+ vears Lavatorv Lighting - Pendent/Surface 1st Floor - East 5 ΕA 7 6-10 years 5 Partitions 1st Floor - East EΑ 7 10+ years Walls - Plaster/Drywall 673 SF 6 1st Floor - East 10+ years Walls - Structural Glazed Tile SF 7 1st Floor - East 126 10+ years Water Closet 5 ΕA 7 1st Floor - East 10+ years 46 SF 7 Accessories 1st Floor - Engineer's Office 6-10 years 1st Floor - Engineer's Office SF 7 Ceiling - Plaster/Drvwall 46 10+ vears Doors - Wood Doors inclu hw 1st Floor - Engineer's Office 1 EΑ 7 10+ years 1st Floor - Engineer's Office SF Floor - Tile Ceramic/ Porcelain 46 6 6-10 vears 1st Floor - Engineer's Office Lavatory 1 EΑ 6 10+ years Lighting - Pendent/Surface 1st Floor - Engineer's Office 2 ΕA 7 10+ years 7 10+ years Partitions 1st Floor - Engineer's Office 1 EΑ SF 1st Floor - Engineer's Office 7 Walls - Plaster/Drywall 200 10+ years SF 7 Walls - Vinyl Coated Gypsum Panel 1st Floor - Engineer's Office 150 10+ years Water Closet 1st Floor - Engineer's Office ΕA 7 1 10+ years SF Accessories 1st Floor - Kitchen 41 7 6-10 vears SF Ceiling - Plaster/Drywall 1st Floor - Kitchen 41 7 10+ years Doors - Steel Doors incl hw ΕA 7 1st Floor - Kitchen 1 10+ years Floor - Tile SF 1st Floor - Kitchen 37 7 10+ years Floor - Tile 1st Floor - Kitchen 4 SF 4 1-2 years Missing tile 7 1st Floor - Kitchen 1 FΑ 10+ vears Lavatorv Lighting - Pendent/Surface 1st Floor - Kitchen 1 EΑ 7 6-10 vears Walls - Structural Glazed Tile SF 7 1st Floor - Kitchen 86 10+ years Water Closet FΑ 7 10+ years 1st Floor - Kitchen 1 200 SF 7 Accessories 1st Floor - Men's Across Main Office 6-10 years Ceiling - Plaster/Drywall SF 1st Floor - Men's Across Main Office 200 6 10+ years SF Doors - Transom Window 1st Floor - Men's Across Main Office 9 7 10+ years Doors - Wood Doors inclu hw 7 1st Floor - Men's Across Main Office 1 EA 10+ years SF Floor - Tile Ceramic/ Porcelain 1st Floor - Men's Across Main Office 200 6 10+ years ΕA 7 Floor Drain 1st Floor - Men's Across Main Office 1 10+ vears Hand Dryer 1st Floor - Men's Across Main Office 1 FΑ 5 1-2 years Not working FΑ 7 Lavatorv 1st Floor - Men's Across Main Office 1 10+ vears Lighting - Pendent/Surface 1st Floor - Men's Across Main Office 4 EΑ 7 6-10 years Partitions 1st Floor - Men's Across Main Office 1 EΑ 5 10+ years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Urinals 1st Floor - Men's Across Main Office 2 ΕA 10+ vears 7 347 SF 7 Walls - Plaster/Drvwall 1st Floor - Men's Across Main Office 10+ years Walls - Vinyl Coated Gypsum Panel 1st Floor - Men's Across Main Office 347 SF 7 10+ years Water Closet ΕA 7 1st Floor - Men's Across Main Office 1 10+ years SF 7 Accessories 1st Floor - Men's Auditorium Lobby 196 6-10 years SF 7 Ceiling - Plaster/Drywall 1st Floor - Men's Auditorium Lobby 196 10+ years Doors - Steel Doors incl hw 1st Floor - Men's Auditorium Lobby ΕA 7 10+ years 1 SF Floor - Tile Ceramic/ Porcelain 1st Floor - Men's Auditorium Lobby 196 6 10+ years Hand Drver 1st Floor - Men's Auditorium Lobby 1 EΑ 7 10+ years 1st Floor - Men's Auditorium Lobby 2 FΑ 7 10+ vears Lavatory Lighting - Pendent/Surface 1st Floor - Men's Auditorium Lobby 3 ΕA 7 6-10 years Partitions 1st Floor - Men's Auditorium Lobby 1 ΕA 7 10+ years 1st Floor - Men's Auditorium Lobby 3 ΕA 7 Urinals 10+ years SF 7 Walls - Plaster/Drywall 1st Floor - Men's Auditorium Lobby 357 10+ years 357 SF 7 Walls - Vinyl Coated Gypsum Panel 1st Floor - Men's Auditorium Lobby 10+ years Water Closet FΑ 7 1st Floor - Men's Auditorium Lobby 1 10+ years SF 7 Accessories 1st Floor - Women West 221 6-10 years SF Ceiling - Plaster/Drywall 1st Floor - Women West 221 7 10+ years SF Doors - Transom Window 1st Floor - Women West 9 7 10+ vears Doors - Wood Doors inclu hw 1st Floor - Women West 1 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor - Women West 201 SF 7 6-10 years 1st Floor - Women West SF Floor - Tile Ceramic/ Porcelain 20 4 1-2 years Crack 7 Floor Drain 1st Floor - Women West 1 EA 10+ years 7 Hand Dryer 1st Floor - Women West 1 FΑ 6-10 years 1st Floor - Women West 2 FΑ 7 10+ years Lavatory 5 Lighting - Pendent/Surface 1st Floor - Women West FΑ 7 10+ vears 3 Partitions 1st Floor - Women West ΕA 7 10+ years Walls - Plaster/Drywall 1st Floor - Women West 297 SF 7 10+ years SF Walls - Vinyl Coated Gypsum Panel 1st Floor - Women West 297 7 10+ years Water Closet 1st Floor - Women West 3 ΕA 7 10+ years SF Accessories 1st Floor - Women's in Auditorium 165 7 6-10 years Lobby SF 1st Floor - Women's in Auditorium 165 7 Ceiling - Plaster/Drywall 10+ years Lobby Doors - Steel Doors incl hw 1st Floor - Women's in Auditorium 1 EA 7 10+ years Lobby Floor - Tile Ceramic/ Porcelain 1st Floor - Women's in Auditorium 165 SF 6 10+ years Lobby Floor Drain 1st Floor - Women's in Auditorium 1 EΑ 7 10+ years Lobby Hand Dryer 1st Floor - Women's in Auditorium FΑ 7 10+ years 1 Lobby Lavatory 1st Floor - Women's in Auditorium 2 EA 7 10+ years Lobby



Catego	ry : Room		B				
Oalcyo				uilding	. wam	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor - Women's in Auditorium Lobby	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Women's in Auditorium Lobby	1	EA	6	2-5 years	Not working
	Partitions	1st Floor - Women's in Auditorium Lobby	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Women's in Auditorium Lobby	297	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor - Women's in Auditorium Lobby	297	SF	7	10+ years	
	Water Closet	1st Floor - Women's in Auditorium Lobby	2	EA	7	10+ years	
	Accessories	1st Fir - Inside 168	60	SF	7	6-10 years	
	Ceiling - Lay-in	1st Flr - Inside 168	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Flr - Inside 168	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr - Inside 168	60	SF	7	10+ years	
	Floor Drain	1st Flr - Inside 168	1	EA	7	10+ years	
	Hand Dryer	1st Flr - Inside 168	1	EA	7	6-10 years	
	Lavatory	1st Flr - Inside 168	1	EA	7	10+ years	
	Lighting - Lay-in	1st Flr - Inside 168	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Flr - Inside 168	224	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fir - Inside 168	96	SF	7	10+ years	
	Walls - The Ceramic/ Porcelain Water Closet	1st Fir - Inside 168		EA	7		
			1	SF		10+ years	
	Accessories	1st Flr - Inside Storage Rm 140 (not in use)	160		7	6-10 years	
	Ceiling - Plaster/Drywall	1st Flr - Inside Storage Rm 140 (not in use)	160	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FIr - Inside Storage Rm 140 (not in use)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FIr - Inside Storage Rm 140 (not in use)	160	SF	7	6-10 years	
	Floor Drain	1st Flr - Inside Storage Rm 140 (not in use)	1	EA	7	10+ years	
	Hand Dryer	1st Flr - Inside Storage Rm 140 (not in use)	1	EA	7	10+ years	
	Lavatory	1st Flr - Inside Storage Rm 140 (not in use)	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Flr - Inside Storage Rm 140 (not in use)	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st FIr - Inside Storage Rm 140 (not in use)	1	EA	6	2-5 years	Not working
	Partitions	1st Flr - Inside Storage Rm 140 (not in use)	1	EA	7	10+ years	
	Showers	1st Flr - Inside Storage Rm 140 (not	1	EA	7	10+ years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments in use) 1st Flr - Inside Storage Rm 140 (not ΕA Urinals 7 1 10+ years in use) SF Walls - Masonry 1st Flr - Inside Storage Rm 140 (not 15 4 1-2 years Missing marble panel in use) 1st Flr - Inside Storage Rm 140 (not SF Walls - Plaster/Drywall 338 7 10+ years in use) Walls - Structural Glazed Tile 1st Flr - Inside Storage Rm 140 (not 338 SF 7 10+ years in use) Water Closet 1st Flr - Inside Storage Rm 140 (not FΑ 7 1 10+ years Restroom not in use in use) Accessories 1st Flr- Inside 166 Health Clinic 60 SF 7 6-10 years 60 SF 6 10+ years Ceiling - Lay-in 1st Flr- Inside 166 Health Clinic Doors - Wood Doors inclu hw 1st Flr- Inside 166 Health Clinic 1 EA 6 10+ years Floor - Tile SF 7 1st Flr- Inside 166 Health Clinic 60 6-10 years Floor Drain FΑ 7 1st FIr- Inside 166 Health Clinic 1 10+ years Lavatorv 1st FIr- Inside 166 Health Clinic 1 EΑ 6 10+ years Lighting - Lay-in 1st FIr- Inside 166 Health Clinic 2 EΑ 7 6-10 years Walls - Plaster/Drvwall SF 1st FIr- Inside 166 Health Clinic 120 6 10+ vears Water Closet 1st FIr- Inside 166 Health Clinic 1 EA 6 10+ years Accessories 1st flr - Inside Asst Engineer's office 86 SF 7 6-10 years SF 7 Ceiling - Plaster/Drywall 1st flr - Inside Asst Engineer's office 86 10+ years Doors - Wood Doors inclu hw 1st flr - Inside Asst Engineer's office 1 EA 6 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 1st flr - Inside Asst Engineer's office 86 6-10 years Floor Drain 1st flr - Inside Asst Engineer's office FΑ 7 1 10+ years Lavatorv 1st flr - Inside Asst Engineer's office 1 FΑ 7 10+ vears Lighting - Pendent/Surface 2 1st flr - Inside Asst Engineer's office EA 7 6-10 years Partitions 1st flr - Inside Asst Engineer's office 1 ΕA 7 10+ years Showers 1st flr - Inside Asst Engineer's office 1 EΑ 7 10+ years Urinals 1st flr - Inside Asst Engineer's office 1 ΕA 7 6-10 years Walls - Plaster/Drvwall 1st flr - Inside Asst Engineer's office 200 SF 7 10+ vears SF Walls - Tile Ceramic/ Porcelain 1st flr - Inside Asst Engineer's office 320 7 10+ vears FΑ 7 Water Closet 1st flr - Inside Asst Engineer's office 1 10+ vears Accessories 1st flr - Next to 130 400 SF 7 6-10 years SF 7 Ceiling - Plaster/Drywall 1st flr - Next to 130 400 10+ years Doors - Transom Window SF 7 1st flr - Next to 130 9 10+ years Doors - Wood Doors inclu hw 1st flr - Next to 130 1 ΕA 7 10+ years 400 SF 7 Floor - Tile Ceramic/ Porcelain 1st flr - Next to 130 6-10 years Floor Drain 1st flr - Next to 130 1 ΕA 7 10+ years Hand Drver 1st flr - Next to 130 1 ΕA 7 10+ vears Lavatory 1st flr - Next to 130 2 FΑ 7 10+ years 7 FΑ 7 Lighting - Pendent/Surface 6-10 years 1st flr - Next to 130 Partitions 1st flr - Next to 130 10 EΑ 7 10+ years SF Walls - Plaster/Drywall 1st flr - Next to 130 784 7 10+ years



Category : Room **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments 1st flr - Next to 130 Walls - Structural Glazed Tile 26 SF 10+ vears 7 Water Closet ΕA 7 1st flr - Next to 130 11 10+ vears Accessories 2nd Floor - Boys' Gym 100 SF 7 6-10 years Ceiling - Plaster/Drywall SF 7 2nd Floor - Boys' Gym 100 10+ years Doors - Wood Doors inclu hw 2nd Floor - Boys' Gym 1 EΑ 7 10+ years SF 2nd Floor - Boys' Gym 7 Floor - Tile Ceramic/ Porcelain 100 10+ years Floor Drain 2nd Floor - Boys' Gym ΕA 7 1 10+ years Lavatory 2nd Floor - Boys' Gym 1 EΑ 7 10+ years Lighting - Lay-in 2nd Floor - Boys' Gym 2 ΕA 7 10+ years Showers 2nd Floor - Bovs' Gvm 1 FΑ 7 10+ vears Student Lockers - One Tier 2nd Floor - Bovs' Gvm 4 ΕA 7 10+ vears Walls - Plaster/Drywall 2nd Floor - Boys' Gym 93 SF 7 10+ years 2nd Floor - Boys' Gym 5 SF 6 1-2 years Walls - Plaster/Drywall **Big hole** 7 Walls - Structural Glazed Tile SF 2nd Floor - Boys' Gym 300 10+ years 2nd flr - Men's By 218 SF 7 Accessories 149 6-10 years Ceiling - Plaster/Drywall SF 7 2nd flr - Men's By 218 149 10+ years ΕA 7 Doors - Wood Doors inclu hw 2nd flr - Men's Bv 218 1 10+ vears Floor - Tile Ceramic/ Porcelain 2nd flr - Men's By 218 149 SF 7 6-10 years Floor Drain 2nd flr - Men's Bv 218 ΕA 7 10+ vears 1 2nd flr - Men's By 218 Hand Dryer 1 EΑ 7 10+ years Lavatory 2nd flr - Men's By 218 1 ΕA 7 10+ years 7 Lighting - Pendent/Surface 2nd flr - Men's By 218 4 EΑ 6-10 years SF 7 Walls - Plaster/Drvwall 2nd flr - Men's By 218 297 10+ years SF 7 Walls - Tile Ceramic/ Porcelain 2nd flr - Men's By 218 297 10+ years Water Closet ΕA 7 2nd flr - Men's By 218 1 10+ years SF Accessories 2nd flr - Next to 212 (not in use) 229 7 6-10 years SF Ceiling - Plaster/Drywall 2nd flr - Next to 212 (not in use) 229 6 10+ years Doors - Transom Window SF 6 2nd flr - Next to 212 (not in use) 14 10+ years ΕA Doors - Wood Doors inclu hw 2nd flr - Next to 212 (not in use) 3 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd flr - Next to 212 (not in use) 229 SF 6 10+ years Floor Drain FΑ 7 10+ vears 2nd flr - Next to 212 (not in use) 1 Lavatorv 2 ΕA 6 10+ vears 2nd flr - Next to 212 (not in use) 5 7 Lighting - Pendent/Surface 2nd flr - Next to 212 (not in use) FΑ 6-10 years Partitions 2nd flr - Next to 212 (not in use) 6 FΑ 7 6-10 years SF Walls - Plaster/Drywall 2nd flr - Next to 212 (not in use) 799 6 10+ years ΕA 6 Water Closet 2nd flr - Next to 212 (not in use) 6 10+ years SF Accessories 2nd flr - Next to 216 318 7 6-10 years Ceiling - Plaster/Drywall SF 2nd flr - Next to 216 318 7 10+ years SF Doors - Transom Window 2nd flr - Next to 216 7 7 10+ years Doors - Wood Doors inclu hw 2nd flr - Next to 216 1 ΕA 4 0-1 vear Door damaged SF Floor - Tile Ceramic/ Porcelain 2nd flr - Next to 216 318 7 6-10 years FΑ 7 Floor Drain 10+ vears 2nd flr - Next to 216 1 Hand Dryer 2nd flr - Next to 216 1 EΑ 7 10+ years Lavatory 2nd flr - Next to 216 2 EΑ 7 10+ years



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface 2nd flr - Next to 216 ΕA 6-10 years 7 7 5 ΕA 7 Partitions 2nd flr - Next to 216 10+ vears Urinals 2nd flr - Next to 216 7 FΑ 7 10+ years Walls - Plaster/Drywall SF 7 2nd flr - Next to 216 638 10+ years SF Walls - Structural Glazed Tile 2nd flr - Next to 216 213 7 10+ years ΕA 7 Water Closet 2nd flr - Next to 216 5 10+ years SF 7 6-10 years Accessories 2nd flr - Women's By 220 149 SF Ceiling - Plaster/Drywall 2nd flr - Women's By 220 149 7 10+ years SF Doors - Transom Window 2nd flr - Women's By 220 7 7 10+ years Doors - Wood Doors inclu hw 2nd flr - Women's By 220 1 FΑ 7 10+ vears Floor - Tile Ceramic/ Porcelain 2nd flr - Women's By 220 137 SF 7 6-10 vears Floor - Tile Ceramic/ Porcelain 2nd flr - Women's By 220 12 SF 4 1-2 years Crack Floor Drain 2nd flr - Women's By 220 ΕA 7 10+ years 1 7 Hand Dryer 2nd flr - Women's By 220 1 EΑ 10+ years 2nd flr - Women's By 220 2 ΕA 7 Lavatory 10+ years Lighting - Pendent/Surface 2nd flr - Women's By 220 5 FΑ 7 6-10 years 2 7 Partitions 2nd flr - Women's By 220 EΑ 10+ vears SF Walls - Plaster/Drvwall 2nd flr - Women's By 220 297 7 10+ years SF Walls - Tile Ceramic/ Porcelain 2nd flr - Women's By 220 297 7 10+ vears Water Closet 2nd flr - Women's By 220 2 EΑ 7 10+ years Accessories 2nd flr- In Rm 226 26 SF 7 6-10 years Ceiling - Plaster/Drywall SF 7 2nd flr- In Rm 226 26 10+ years 7 Doors - Wood Doors inclu hw 2nd flr- In Rm 226 1 EA 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 2nd flr- In Rm 226 26 6-10 years FΑ 7 Lavatorv 2nd flr- In Rm 226 1 10+ years Lighting - Wall Mounted 2nd flr- In Rm 226 1 FΑ 7 6-10 years Walls - Plaster/Drywall 50 SF 2nd flr- In Rm 226 7 10+ years Water Closet ΕA 7 2nd flr- In Rm 226 1 10+ years SF Accessories 2nd flr- Next to 228 400 7 6-10 years Ceiling - Plaster/Drywall 2nd flr- Next to 228 400 SF 7 10+ years Doors - Transom Window SF 2nd flr- Next to 228 9 7 10+ vears Doors - Wood Doors inclu hw 2nd flr- Next to 228 1 EΑ 7 10+ vears SF 7 Floor - Tile Ceramic/ Porcelain 400 6-10 years 2nd flr- Next to 228 Floor Drain FΑ 7 2nd flr- Next to 228 1 10+ years 7 Hand Dryer 2nd flr- Next to 228 1 EΑ 10+ years 2 ΕA 7 Lavatory 2nd flr- Next to 228 10+ years Lighting - Pendent/Surface 7 2nd flr- Next to 228 ΕA 7 6-10 years Partitions 2nd flr- Next to 228 11 EA 7 10+ years SF Walls - Plaster/Drywall 2nd flr- Next to 228 810 7 10+ years Water Closet 2nd flr- Next to 228 11 ΕA 7 10+ vears SF Accessories 3rd Floor 318 7 6-10 years SF 7 Ceiling - Plaster/Drywall 3rd Floor 318 10+ vears Doors - Steel Doors incl hw 3rd Floor EΑ 7 10+ years 1 SF Doors - Transom Window 3rd Floor 7 7 10+ years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Floor - Tile Ceramic/ Porcelain 3rd Floor 318 SF 10+ vears 7 Floor Drain 3rd Floor ΕA 7 1 10+ years Hand Drver 3rd Floor 1 FΑ 7 6-10 years 2 ΕA 7 Lavatory 3rd Floor 10+ years 7 Lighting - Pendent/Surface 3rd Floor EΑ 7 6-10 years 5 7 Partitions 3rd Floor EΑ 10+ years 3rd Floor 7 ΕA 7 10+ years Urinals SF Walls - Plaster/Drywall 3rd Floor 628 6 10+ years SF Walls - Plaster/Drvwall 3rd Floor 10 4 1-2 years Need to cover SF 7 Walls - Structural Glazed Tile 3rd Floor 213 10+ years Water Closet 3rd Floor 4 ΕA 7 10+ vears Water Closet 3rd Floor 1 EΑ 3 0-1 year Missing WC Accessories 229 SF 7 6-10 years 3rd Floor - East SF 7 Ceiling - Plaster/Drywall 3rd Floor - East 229 10+ years Doors - Transom Window SF 7 3rd Floor - East 14 10+ years Doors - Wood Doors inclu hw FΑ 7 3rd Floor - East 4 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 3rd Floor - East 219 10+ years SF Floor - Tile Ceramic/ Porcelain 3rd Floor - East 10 4 1-2 years Crack Floor Drain 3rd Floor - East 1 ΕA 7 10+ vears Hand Dryer 3rd Floor - East 1 ΕA 5 10+ years Lavatory 3rd Floor - East 2 ΕA 7 10+ years Lighting - Pendent/Surface 5 7 3rd Floor - East ΕA 6-10 years 6 ΕA 7 Partitions 3rd Floor - East 10+ years SF 7 Walls - Plaster/Drywall 3rd Floor - East 799 10+ years 6 ΕA 7 Water Closet 3rd Floor - East 10+ years SF Accessories 3rd Floor - West 400 7 6-10 years Ceiling - Plaster/Drywall SF 3rd Floor - West 400 7 10+ years Doors - Steel Doors incl hw 3rd Floor - West ΕA 7 1 10+ years SF Doors - Transom Window 3rd Floor - West 9 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Floor - West 400 SF 7 10+ years Floor Drain 3rd Floor - West FΑ 7 10+ vears 1 Hand Drver 3rd Floor - West 1 ΕA 5 0-1 vear Not working 2 7 3rd Floor - West FΑ 10+ years Lavatory Lighting - Pendent/Surface 3rd Floor - West 7 FΑ 7 6-10 years 7 Partitions 3rd Floor - West 11 ΕA 10+ years SF 7 Walls - Plaster/Drywall 3rd Floor - West 784 10+ years SF Walls - Structural Glazed Tile 3rd Floor - West 26 7 10+ years Water Closet ΕA 3rd Floor - West 11 7 10+ years **Category : Classroom Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Classroom #106 (Regular Classroom) AC Units 1st Floor 1 ΕA 7 6-10 vears



3436 W Wilson AVENUE, Chicago, IL 60625 **Building : Main** Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Casework LF 1st Floor 6 10+ years 7 Ceiling - Lav-in 1st Floor 408 SF 7 10+ years Doors - Transom Window 1st Floor 9 SF 7 10+ years Doors - Wood Doors inclu hw 1 ΕA 7 1st Floor 10+ years SF Floor - Tile/Sheet 1st Floor 378 7 10+ years SF Floor - Tile/Sheet 1st Floor 30 4 1-2 years Damaged flooring Lighting - Lay-in 1st Floor 8 ΕA 7 6-10 years LF Marker Board 1st Floor 12 7 6-10 years SF Walls - Plaster/Drywall 1st Floor 780 7 10+ years Classroom #108 (Other Instructional Use) AC Units 1st Floor 1 EΑ 7 6-10 years Casework 1st Floor 56 LF 10+ years 6 SF Ceiling - Lay-in 1st Floor 822 7 10+ years Chalk Board LF 1st Floor 18 4 2-5 years Doors - Transom Window 1st Floor 9 SF 7 10+ years FΑ Doors - Wood Doors inclu hw 1st Floor 1 7 10+ years Floor - Tile 1st Floor 822 SF 6 10+ years Lighting - Lay-in ΕA 1st Floor 24 7 6-10 years Marker Board 1st Floor LF 7 6-10 years 6 SF Walls - Plaster/Drywall 1st Floor 1.165 6 10+ years Work Sink 1st Floor 3 ΕA 7 10+ vears Classroom #110 (Science Lab Level 1) AC Units 1st Floor 1 EΑ 7 6-10 years Casework 1st Floor 70 LF 10+ years 6 SF Ceiling - Lay-in 1st Floor 1.128 7 10+ years Chalk Board LF 1st Floor 12 4 2-5 years Doors - Transom Window 1st Floor 18 SF 7 10+ years 2 FΑ Doors - Wood Doors inclu hw 1st Floor 7 10+ years Eve Wash Station 7 1st Floor 1 ΕA 10+ years Floor - Tile SF 7 1st Floor 1,128 10+ years Gas Line 1st Floor ΕA 7 10+ years 4 Lighting - Lay-in 1st Floor 33 EΑ 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years SF Science Lab Elements 1st Floor 1.128 7 10+ years Science Lab Fume Hood 1st Floor ΕA 7 10+ vears 1 Storage/ Closet 1st Floor 98 SF 7 10+ years Walls - Plaster/Drywall SF 7 1st Floor 1,410 10+ years ΕA Work Sink 1st Floor 3 5 10+ years Classroom #111 (Regular Classroom) AC Units ΕA 7 1st Floor 1 6-10 years



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Casework LF 1st Floor 11 10+ vears 7 Ceiling - Lav-in 1st Floor 720 SF 7 10+ years Doors - Transom Window 1st Floor 9 SF 7 10+ years Doors - Wood Doors inclu hw 2 ΕA 7 1st Floor 10+ years SF Floor - Wood 1st Floor 720 6 10+ years ΕA Lighting - Lay-in 1st Floor 21 6 6-10 years Marker Board 1st Floor 46 LF 7 6-10 years Walls - Plaster/Drywall SF 1st Floor 990 7 10+ years Classroom #112 (Regular Classroom) AC Units 1st Floor 1 ΕA 7 6-10 years Casework 1st Floor 11 LF 7 10+ years Ceiling - Lay-in 1st Floor 720 SF 7 10+ years SF Doors - Transom Window 1st Floor 9 7 10+ years Doors - Wood Doors inclu hw 1 ΕA 7 1st Floor 10+ years Floor - Wood 1st Floor 720 SF 6 10+ years FΑ Lighting - Lay-in 1st Floor 21 7 6-10 years Marker Board 1st Floor 46 LF 7 6-10 years SF Walls - Plaster/Drywall 1st Floor 990 7 10+ years Classroom #113 (Regular Classroom) AC Units 1st Floor 1 ΕA 7 6-10 years LF Casework 1st Floor 27 7 10+ years 1st Floor 720 SF 7 10+ years Ceiling - Lay-in Doors - Transom Window 1st Floor 9 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 ΕA 7 10+ years Floor - Wood 1st Floor 720 SF 6 10+ years ΕA 7 6-10 vears Lighting - Lay-in 1st Floor 21 Marker Board 1st Floor 40 LF 7 6-10 years SF Walls - Plaster/Drywall 1st Floor 990 7 10+ years Classroom #114 (Regular Classroom) AC Units 1st Floor ΕA 7 6-10 years 1 720 SF Ceiling - Lay-in 1st Floor 7 10+ years SF Doors - Transom Window 1st Floor 9 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 ΕA 7 10+ vears Floor - Tile 690 SF 1st Floor 7 10+ years Floor - Tile 1st Floor 30 SF 4 1-2 years Damaged floor 1st Floor 21 ΕA 7 6-10 years Lighting - Lay-in Marker Board 1st Floor 20 LF 7 6-10 years SF Walls - Plaster/Drywall 1st Floor 990 6 10+ years Classroom #116 (Office)



Category : Classroom

roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
P	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	490	SF	7	10+ years	
	Doors - Transom Window	1st Floor		SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile	1st Floor	450	SF	7	10+ years	
	Floor - Tile	1st Floor	430	SF	4	1-2 years	Damaged flooring
	Lighting - Lay-in	1st Floor	40	EA	6	6-10 years	Damaged hooring
	Marker Board	1st Floor	16		7		
		1st Floor		SF		6-10 years	
	Storage/ Closet		98		7	10+ years	
	Walls - Plaster/Drywall	1st Floor	880	SF	7	10+ years	
assroo	m #130 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	13	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	984	SF	7	10+ years	
	Chalk Board	1st Floor	3	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	974	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Damaged tile
	Lighting - Lay-in	1st Floor	27	EA	7	6-10 years	Damaged life
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor		SF			
		1st Floor	1,080	EA	7 7	10+ years 6-10 years	
	Wireless System		I	EA	1	6-10 years	
ssroo	m #132 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,128	SF	7	10+ years	
	Chalk Board	1st Floor	14	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,108	SF	6	6-10 years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	1st Floor	33	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,726	SF	7	10+ years	
	Wireless System	1st Floor	1,720	EA	7	6-10 years	
assroo	m #144 (Science Lab Level 2)						
	AC Units	1st Floor	1	EA	7	6-10 years	
		1st Floor	185	LF	7	10+ years	

Building : Main



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Ceiling - Lay-in 1st Floor 1.032 SF 10+ vears 7 Chalk Board 1st Floor 48 LF 2-5 years 4 Doors - Transom Window 1st Floor 18 SF 7 10+ years Doors - Wood Doors inclu hw 2 ΕA 7 1st Floor 10+ years 7 Eve Wash Station 1st Floor 1 ΕA 10+ years SF Floor - Tile/Sheet 1,032 7 1st Floor 10+ years Gas Line 1st Floor ΕA 7 10+ years 2 Lighting - Lay-in 1st Floor 30 ΕA 7 6-10 years Science Lab Elements 1st Floor 10 SF 7 10+ years SF Storage/ Closet 1st Floor 80 7 10+ years Walls - Plaster/Drvwall SF 1st Floor 1.140 7 10+ vears Work Sink 1st Floor 3 ΕA 7 10+ years Classroom #148 (Science Lab Level 2) AC Units 1st Floor ΕA 7 1 6-10 years Casework 1st Floor 90 LF 7 10+ years SF Ceiling - Lay-in 1st Floor 1.032 7 10+ years LF Chalk Board 1st Floor 12 4 2-5 years SF 7 Doors - Transom Window 1st Floor 18 10+ years Doors - Wood Doors inclu hw 1st Floor 2 ΕA 7 10+ years **Eve Wash Station** 1st Floor 1 ΕA 7 10+ years Floor - Tile/Sheet 1st Floor 1.002 SF 7 10+ vears Floor - Tile/Sheet SF 1st Floor 30 4 1-2 years Damaged tile 1st Floor 30 ΕA 7 6-10 vears Lighting - Lav-in Marker Board 1st Floor 12 LF 7 6-10 years Science Lab Elements 1st Floor 8 SF 7 10+ years SF 7 Storage/ Closet 1st Floor 80 10+ years Walls - Plaster/Drywall SF 7 1st Floor 1,140 10+ years Work Sink FΑ 5 Missing faucet 1st Floor 3 1-2 years Classroom #150 (Special Program) AC Units 1st Floor 1 EΑ 7 6-10 years Ceiling - Lay-in 1st Floor 720 SF 7 10+ years Doors - Transom Window 1st Floor 9 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 ΕA 7 10+ vears SF Floor - Tile 1st Floor 720 7 10+ years 1st Floor 21 ΕA 7 6-10 vears Lighting - Lay-in Marker Board 1st Floor 24 LF 7 6-10 years Walls - Plaster/Drywall 880 SF 7 1st Floor 10+ years Classroom #167 (Culinary) AC Units 1st Floor 2 ΕA 7 6-10 years SF Ceiling - Lay-in 1st Floor 1.600 7 10+ years



Catego	ry : Classroom		В	uilding	: Main		
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Culinary Exhaust Hood - Type I	1st Floor	3	EA	7	10+ years	
	Culinary Kitchen Equipment	1st Floor	5	EA	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	1,600	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	32	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,005	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,005	SF	7	10+ years	
	Work Sink	1st Floor	5	EA	7	10+ years	
lassroc	m #168 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	1,600	SF	4	2-5 years	Peeling paint throughout
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	314 43
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,600	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,010	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	350	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroc	m #169 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,180	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,180	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,730	SF	7	10+ years	
lassroc	m #204 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	69	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,420	SF	7	10+ years	
				LF	4	•	
	Chalk Board	2nd Eloor	<u>4</u>		4	Z-O VEAIS	
	Chalk Board Doors - Transom Window	2nd Floor 2nd Floor	4	SF	4 7	2-5 years 10+ years	



Catego	ry : Classroom		R	uilding	• Main		436 W Wilson AVENUE, Chicago, IL 6062
Surego				anang	· mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Floor - Tile	2nd Floor	1,416	SF	7	6-10 years	Commonto
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd Floor	40	EA	7	6-10 years	Clacked
	Storage/ Closet	2nd Floor	40 145	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,812	SF	7	10+ years	
	Walls - Plastel/Drywall	2110 11001	1,012	ЪГ	7	TO+ years	
lassroc	om #206 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,260	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,255	SF	7	6-10 years	
	Floor - Tile	2nd Floor	5	SF	4	1-2 years	Missing
	Lighting - Lay-in	2nd Floor	30	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	763	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,572	SF	7	10+ years	
Classroc	om #208 (Science Lab Level 1) AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	85	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	916	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Eve Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	916	SF	7	6-10 years	
	Gas Line	2nd Floor	5	ĒA	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	9	SF	7	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,512	SF	7	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
			0	L / (lot youro	
Classroc	m #210 (Science Lab Level 1)			 ^	7	0.40	
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	70	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,472	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	736	SF	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	2nd Floor	736	SF	4	0-1 year	Damaged cracked
	Lighting - Lay-in	2nd Floor	42	EA	7	6-10 years	
	Science Lab Elements	2nd Floor	12	SF	7	10+ years	
	Science Lab Elements	2nd Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,980	SF	7	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
lassroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	990	SF	7	10+ years	
lassroo	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	990	SF	7	10+ years	
lassroo	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	990	SF	7	10+ years	

_Classroom #214 (Regular Classroom)



<u> </u>					Mair	3	436 W Wilson AVENUE, Chicago, IL 60625
Catego	ry : Classroom		В	uilding	: Main	December	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	AC Units	2nd Floor	Quantity 1	EA	7	6-10 years	Comments
	Casework	2nd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	990	SF	7	10+ years	
		21011001	350	01	'	TOF years	
Classroo	om #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	680	SF	7	6-10 years	
	Floor - Tile	2nd Floor	40	SF	4	1-2 years	Missing and cracked with damaged
							subfloor
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	990	SF	7	10+ years	
Classroo	om #217A (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	27	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	789	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	789	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	27	ĒA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	10+ years	
Classror	om #217B (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	35		7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu hw	2nd Floor	720	SF	7	10+ years 10+ years	
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years	
	Lighting - Lay-in Lighting - Wall Mounted	2nd Floor	27	EA	7		
	Marker Board	2nd Floor	12	LF	7	6-10 years 6-10 years	
	IVIAINEI DUAIU		12	LF	1	o-ro years	



3436 W Wilson AVENUE, Chicago, IL 60625 **Building : Main** Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments SF Walls - Plaster/Drywall 2nd Floor 990 7 10+ vears Classroom #220 (Computer Lab) AC Units 2nd Floor 2 ΕA 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor 1,218 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor FΑ 7 2 10+ years Floor - Tile 2nd Floor 1.218 SF 7 6-10 years Lighting - Pendent/Surface 2nd Floor 21 ΕA 7 6-10 years LF Marker Board 2nd Floor 12 7 6-10 years SF Walls - Plaster/Drywall 2nd Floor 1,680 7 10+ years Wireless System 2nd Floor ΕA 7 1 10+ years Classroom #226 (Regular Classroom) AC Units 2nd Floor 1 EΑ 7 6-10 vears Ceiling - Plaster/Drywall SF 2nd Floor 336 7 10+ years Doors - Transom Window 2nd Floor 7 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 7 10+ years Floor - Tile SF 7 10+ years 2nd Floor 326 Floor - Tile SF 2nd Floor 0-1 year 10 4 Chipped Lighting - Pendent/Surface 2nd Floor 4 FΑ 7 6-10 years 8 LF Marker Board 2nd Floor 7 6-10 years SF Walls - Plaster/Drywall 2nd Floor 770 7 10+ years Classroom #228 (Regular Classroom) AC Units 2nd Floor 1 EΑ 7 6-10 vears Casework 2nd Floor 9 LF 7 10+ years 2nd Floor SF 7 Ceiling - Lav-in 720 10+ vears Doors - Transom Window SF 2nd Floor 9 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 7 10+ years 2nd Floor 720 SF 7 Floor - Wood 10+ years ΕA 7 6-10 years Lighting - Lay-in 2nd Floor 21 LF 7 Marker Board 2nd Floor 20 6-10 years Walls - Plaster/Drywall 897 SF 7 2nd Floor 10+ years Classroom #229 (Regular Classroom) AC Units 2nd Floor 7 6-10 years 1 EΑ LF Casework 2nd Floor 9 7 10+ years SF Ceiling - Lav-in 2nd Floor 720 7 10+ years SF Doors - Transom Window 2nd Floor 9 7 10+ years ΕA 7 Doors - Wood Doors inclu hw 2nd Floor 1 10+ vears Floor - Wood 2nd Floor 720 SF 7 10+ vears Lighting - Lay-in 2nd Floor 21 ΕA 7 6-10 years Marker Board LF 7 2nd Floor 32 6-10 years



y : Classroom			uilding			
					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Walls - Plaster/Drywall	2nd Floor	880	SF	7	10+ years	
m #230 (Regular Classroom)						
AC Units		1		7		
		9			10+ years	
	2nd Floor	720		7	10+ years	
Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Wood	2nd Floor	720	SF	7	•	
Lighting - Lav-in	2nd Floor	21	EA	7		
		1	EA	7		
		16				
Wallo T laston Drywall		000	01	,	ior youro	
m #231 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 vears	
					•	
				-		
		1				
		1 022		-	•	
				-		
Walls - Plaster/Drywall	2nd Floor	1,140	SF	1	10+ years	
m #232 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	9				
		720			-	
		-			,	
		-			•	
					-	
vvalis - Flastel/DiyWall		000	35	1	IUT years	
m #233 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 vears	
		-				
Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
			0.	'		
Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall m #230 (Regular Classroom) AC Units Casework Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Lighting - Vall Mounted Marker Board Walls - Plaster/Drywall m #231 (Regular Classroom) AC Units Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #232 (Regular Classroom) AC Units Casework Ceiling - Lay-in Marker Board Walls - Plaster/Drywall m #232 (Regular Classroom) AC Units Casework Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #233 (Regular Classroom)	Walls - Plaster/Drywall 2nd Floor AC Units 2nd Floor Casework 2nd Floor Casework 2nd Floor Coling - Lay-in 2nd Floor Doors - Transom Window 2nd Floor Doors - Wood Doors inclu hw 2nd Floor Lighting - Lay-in 2nd Floor Lighting - Lay-in 2nd Floor Lighting - Wall Mounted 2nd Floor Walls - Plaster/Drywall 2nd Floor Marker Board 2nd Floor Walls - Plaster/Drywall 2nd Floor Marker Board 2nd Floor Marker Board 2nd Floor Casework 2nd Floor Casework 2nd Floor Casework 2nd Floor Casework 2nd Floor Doors - Transom Window 2nd Floor Doors - Wood Doors inclu hw 2nd Floor Doors - Wood 2nd Floor Lighting - Lay-in 2nd Floor Marker Board 2nd Floor Marker Board 2nd Floor Marker Board 2nd Floor Marker Board 2nd Floor <t< td=""><td>Walls - Plaster/Drywall 2nd Floor 860 m #230 (Regular Classroom) </td><td>Walls - Plaster/Drywall 2nd Floor 860 SF m #230 (Regular Classroom) AC Units 2nd Floor 1 EA Casework 2nd Floor 9 LF Casework 2nd Floor 9 LF Coling - Lay-in 2nd Floor 9 SF Doors - Transom Window 2nd Floor 9 SF Doors - Wood Doors inclu hw 2nd Floor 1 EA Lighting - Lay-in 2nd Floor 720 SF Lighting - Lay-in 2nd Floor 21 EA Lighting - Lay-in 2nd Floor 1 EA Walls - Plaster/Drywall 2nd Floor 1 EA SF m#231 (Regular Classroom) </td><td>Walls - Plaster/Drywall 2nd Floor 880 SF 7 m #230 (Regular Classroom) AC Units 2nd Floor 1 EA 7 AC Units 2nd Floor 1 EA 7 Casework 2nd Floor 9 LF 7 Doors - Transom Window 2nd Floor 9 SF 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Wood Doors inclu hw 2nd Floor 1 EA 7 Lighting - Lay-in 2nd Floor 1 EA 7 Lighting - Lay-in 2nd Floor 1 EA 7 Marker Board 2nd Floor 1 EA 7 Walls - Plaster/Drywall 2nd Floor 1 EA 7 AC Units 2nd Floor 1 EA 7 Casework 2nd Floor 1 EA 7 Casework 2nd Floor 1 EA 7 Chalk Board 2nd Floor 1<</td><td>Walls - Plaster/Drywall 2nd Floor 880 SF 7 10+ years m #230 (Regular Classroom) </td></t<>	Walls - Plaster/Drywall 2nd Floor 860 m #230 (Regular Classroom)	Walls - Plaster/Drywall 2nd Floor 860 SF m #230 (Regular Classroom) AC Units 2nd Floor 1 EA Casework 2nd Floor 9 LF Casework 2nd Floor 9 LF Coling - Lay-in 2nd Floor 9 SF Doors - Transom Window 2nd Floor 9 SF Doors - Wood Doors inclu hw 2nd Floor 1 EA Lighting - Lay-in 2nd Floor 720 SF Lighting - Lay-in 2nd Floor 21 EA Lighting - Lay-in 2nd Floor 1 EA Walls - Plaster/Drywall 2nd Floor 1 EA SF m#231 (Regular Classroom)	Walls - Plaster/Drywall 2nd Floor 880 SF 7 m #230 (Regular Classroom) AC Units 2nd Floor 1 EA 7 AC Units 2nd Floor 1 EA 7 Casework 2nd Floor 9 LF 7 Doors - Transom Window 2nd Floor 9 SF 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Wood Doors inclu hw 2nd Floor 1 EA 7 Lighting - Lay-in 2nd Floor 1 EA 7 Lighting - Lay-in 2nd Floor 1 EA 7 Marker Board 2nd Floor 1 EA 7 Walls - Plaster/Drywall 2nd Floor 1 EA 7 AC Units 2nd Floor 1 EA 7 Casework 2nd Floor 1 EA 7 Casework 2nd Floor 1 EA 7 Chalk Board 2nd Floor 1<	Walls - Plaster/Drywall 2nd Floor 880 SF 7 10+ years m #230 (Regular Classroom)



Catego	ry : Classroom		D	uilding	·Main	0	436 W Wilson AVENUE, Chicago, IL 6062
Caleyo			B	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Floor - Wood	2nd Floor	715	SF	7	10+ years	Comments
	Floor - Wood	2nd Floor	5	SF	5	1-2 years	Big crack
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	2.9 0.001
	Marker Board	2nd Floor	45	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	880	SF	6	10+ years	
Classroc	m #235 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	- 1	ËA	7	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	21	ĒA	7	6-10 years	
	Marker Board	2nd Floor	35	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	880	SF	7	10+ years	
lassroo	m #244 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	32	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,265	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,165	SF	7	6-10 years	
	Floor - Tile	2nd Floor	100	SF	4	0-1 year	Cracked all over
	Lighting - Lay-in	2nd Floor	33	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,320	SF	6	10+ years	
	Work Sink	2nd Floor	<u>́</u> 1	EA	7	10+ years	
lassroo	m #248 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	973	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	953	SF	7	6-10 years	
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Chipped
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	7	10+ years	
	Work Sink	2nd Floor	· 1	EA	7	10+ years	



3436 W Wilson AVENUE, Chicago, IL 60625 **Building : Main** Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Classroom #250 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 years Casework 2nd Floor 29 LF 7 10+ years Ceiling - Lay-in 2nd Floor 984 SF 7 10+ years Doors - Transom Window 2nd Floor SF 7 18 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 FΑ 7 10+ years SF Floor - Wood 2nd Floor 984 7 10+ years ΕA Lighting - Lay-in 2nd Floor 27 7 6-10 years LF Marker Board 2nd Floor 16 7 6-10 years Walls - Plaster/Drywall 2nd Floor 1,080 SF 7 10+ years Work Sink 2nd Floor 1 EΑ 7 10+ years Classroom #306 (Science Lab Level 1) AC Units 3rd Floor 7 1 EΑ 6-10 years Casework 3rd Floor 150 LF 6 10+ years Ceiling - Lay-in 3rd Floor SF 7 916 10+ years Chalk Board 24 LF 2-5 years 3rd Floor 4 Doors - Transom Window SF 7 3rd Floor 14 10+ years Doors - Wood Doors inclu hw 3rd Floor 2 FΑ 7 10+ years Eve Wash Station 3rd Floor 1 FΑ 7 10+ years Floor - Tile/Sheet SF 3rd Floor 916 7 10+ years Gas Line 3rd Floor 5 EΑ 7 10+ years Lighting - Lay-in 27 7 6-10 years 3rd Floor EA Marker Board 3rd Floor 12 LF 7 6-10 years Science Lab Elements 3rd Floor 916 SF 7 10+ years Science Lab Fume Hood 3rd Floor FΑ 7 10+ years 1 3rd Floor ΕA 7 Science Lab Shower 10+ years 1 Walls - Plaster/Drywall 3rd Floor 1.034 SF 7 10+ years ΕA Work Sink 3rd Floor 7 7 10+ years Classroom #308 (Science) AC Units 3rd Floor FΑ 7 6-10 years 1 LF Casework 3rd Floor 16 7 10+ years SF Ceiling - Lay-in 3rd Floor 510 7 10+ years LF Chalk Board 3rd Floor 18 4 2-5 vears Doors - Transom Window SF 7 3rd Floor 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 ΕA 7 10+ years Floor - Tile/Sheet 3rd Floor SF 7 510 10+ years Gas Line 3rd Floor ΕA 7 10+ years 1 3rd Floor FΑ 7 Lighting - Lay-in 15 6-10 years Marker Board 3rd Floor 18 LF 7 6-10 years SF Walls - Plaster/Drywall 3rd Floor 885 7 10+ years



Catego	ry : Classroom		B	uilding	: Main		
5-	-			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	3rd Floor	1	EA	5	10+ years	
lassroc	m #310 (Science Lab Level 1)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	150	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	984	SF	7	10+ years	
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	984	SF	7	10+ years	
	Gas Line	3rd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	27	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Science Lab Elements	3rd Floor	984	SF	7	10+ years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,240	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
					-	, , , , , , , , , , , , , , , , , , ,	
Classroo	m #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	34	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	990	SF	7	10+ years	
lacorea	m #312 (Regular Classroom)						
1992100	AC Units	3rd Floor	1	EA	7	6-10 years	
		3rd Floor	11				
	Casework	3rd Floor 3rd Floor		SF	7	10+ years	
	Ceiling - Lay-in		720	SF LF	7	10+ years	
	Chalk Board	3rd Floor	28		4	2-5 years	
	Doors - Transom Window	3rd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	990	SF	7	10+ years	



Theodore Roosevelt High School 3436 W Wilson AVENUE, Chicago, IL 60625

Catego	ry : Classroom		В	uilding	: Main		Hoo W Wilson WENDE, Oniougo, ie 00020
Ū				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Chalk Board	3rd Floor	3	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	38	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	929	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1	SF	6	1-2 years	Big crack
Classroo	om #314 (Regular Classroom)			F •	_	0.40	
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	6	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	990	SF	7	10+ years	
Classroo	om #315 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	53	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	660	SF	7	10+ years	
	Floor - Tile	3rd Floor	60	SF	4	0-1 year	Cracked and chipped
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	990	SF	7	10+ years	
Classroo	om #316 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor		SF	7	10+ years	
				-		- ,	



<u> </u>	Schools ry : Classroom		P	uilding	• Main	5	436 W Wilson AVENUE, Chicago, IL 6062
Calego			B	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
5. 5 G P	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	670	SF	7	10+ years	
	Floor - Tile	3rd Floor	50	SF	4	0-1 year	Cracked
	Lighting - Lay-in	3rd Floor	21	ĒA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	990	SF	7	10+ years	
Classroo	om #317 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	13	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	909	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	909	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	27	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,210	SF	7	10+ years	
	Wireless System	3rd Floor	1,210	EA	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #318 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	624	SF	7	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	624	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	990	SF	7	10+ years	
Classroo	om #319 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	27	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,032	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,032	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	27	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,320	SF	7	10+ years	
	wans - riasici/Diywall		1,320	0	1	ior years	



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Classroom #320 (Regular Classroom) AC Units 3rd Floor 2 ΕA 7 6-10 years Ceiling - Plaster/Drywall 3rd Floor 1,205 SF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor SF 5 1-2 years 20 Peeling paint Doors - Wood Doors inclu hw 2 ΕA 7 10+ years 3rd Floor SF Floor - Tile 3rd Floor 1.225 6 10+ years Lighting - Pendent/Surface 3rd Floor 12 FΑ 7 6-10 years LF Marker Board 3rd Floor 12 7 6-10 years SF Walls - Plaster/Drywall 3rd Floor 1.575 7 10+ years Classroom #323 (Regular Classroom) AC Units 3rd Floor 2 ΕA 7 6-10 years LF Casework 3rd Floor 13 7 10+ years SF Ceiling - Lav-in 3rd Floor 1.032 7 10+ vears Chalk Board LF 3rd Floor 26 4 2-5 years Doors - Transom Window 3rd Floor 14 SF 7 10+ years 2 7 Doors - Wood Doors inclu hw 3rd Floor EΑ 10+ years Floor - Wood SF 6 10+ years 3rd Floor 1.032 Floor - Wood SF 3rd Floor 5 1-2 years 4 Big crack Lighting - Lay-in 3rd Floor 27 FΑ 7 6-10 years LF Marker Board 3rd Floor 22 7 6-10 years SF Walls - Plaster/Drvwall 3rd Floor 1.320 7 10+ years Work Sink 3rd Floor 1 EΑ 7 10+ years Classroom #326 (Regular Classroom) AC Units 3rd Floor 1 ΕA 7 6-10 years 3rd Floor 8 LF 7 Casework 10+ vears SF Ceiling - Lay-in 3rd Floor 720 7 10+ years Doors - Transom Window 3rd Floor 7 SF 7 10+ years Doors - Wood Doors inclu hw 1 7 3rd Floor EΑ 10+ years Floor - Wood SF 5 10+ years 3rd Floor 720 7 Lighting - Lay-in 3rd Floor 17 ΕA 6-10 years Marker Board 3rd Floor 44 LF 7 6-10 years Walls - Plaster/Drywall SF 3rd Floor 990 7 10+ years Classroom #328 (Regular Classroom) AC Units 3rd Floor 1 ΕA 7 6-10 years LF Casework 3rd Floor 9 7 10+ years SF 3rd Floor 720 7 10+ years Ceiling - Lay-in Doors - Transom Window SF 7 3rd Floor 9 10+ vears Doors - Wood Doors inclu hw 3rd Floor 1 ΕA 7 10+ years Floor - Wood 3rd Floor 720 SF 6 10+ years 7 Lighting - Lay-in 3rd Floor 21 EΑ 6-10 years



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	880	SF	7	10+ years	
lassror	m #329 (Computer Lab)						
01005100	AC Units	3rd Floor	3	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,032	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,032	SF	6	10+ years	
		3rd Floor	30	EA	7	6-10 years	
	Lighting - Lay-in				7		
	Marker Board	3rd Floor		SF		6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,139	SF	7	10+ years	Hele in well
	Walls - Plaster/Drywall	3rd Floor	1	SF EA	5 7	1-2 years	Hole in wall
	Wireless System	3rd Floor	1	EA	/	6-10 years	
Classroc	m #330 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Chalk Board	3rd Floor	31	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,420	SF	6	10+ years	
Classroc	m #331 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	730	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Cracked
	Floor - Tile/Sheet	3rd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,090	SF	6	10+ years	
			1,090	0	0	ior years	
lassroc	m #332 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Chalk Board	3rd Floor	21	LF	4	2-5 years	



	Schools					5	436 W Wilson AVENUE, Chicago, IL 60625
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	6	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	880	SF	7	10+ years	
Classroc	om #333 (Health)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	14	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	13	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	63	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	885	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
Classroo	om #335 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	880	SF	7	10+ years	
Classroo	om #344 (Art Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	35	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	984	SF	7	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	984	SF	6	10+ years	
	Kiln	3rd Floor	1	EA	7	6-10 years	
		3rd Floor	27	EA	7	6-10 years	
	Lighting - Lay-in		21				
	Lighting - Lay-in Marker Board	3rd Floor	20	LF	7	6-10 years	



3436 W Wilson AVENUE, Chicago, IL 60625 **Building : Main Category : Classroom** Recommend Quantity **Replacement** Comments Group Item - Type Location UOM Rank Work Sink ΕA 3rd Floor 2 7 10+ years Classroom #348 (Science Lab Level 1) AC Units 3rd Floor 1 ΕA 7 6-10 years Casework 3rd Floor 100 LF 7 10+ years Ceiling - Lay-in 3rd Floor SF 7 984 10+ years Doors - Transom Window 3rd Floor 18 SF 7 10+ years 2 ΕA Doors - Wood Doors inclu hw 3rd Floor 7 10+ years Eve Wash Station 3rd Floor 1 EΑ 7 10+ years Floor - Tile/Sheet SF 3rd Floor 974 7 10+ years Floor - Tile/Sheet 3rd Floor SF 0-1 year 10 4 Cracked Gas Line 3rd Floor 12 EΑ 7 10+ years Lighting - Lay-in 3rd Floor 15 ΕA 6-10 years 6 LF Marker Board 3rd Floor 20 7 6-10 years Science Lab Elements 3rd Floor 994 SF 7 10+ years Science Lab Fume Hood 3rd Floor 1 FΑ 7 10+ years Science Lab Shower 3rd Floor 1 FΑ 7 10+ years SF Walls - Plaster/Drywall 3rd Floor 1,080 7 10+ years Work Sink ΕA 3rd Floor 11 7 10+ years Classroom #350 (Art Room) AC Units 3rd Floor 1 ΕA 7 6-10 years 37 LF Casework 3rd Floor 7 10+ years Ceiling - Lay-in 3rd Floor 984 SF 7 10+ years Chalk Board 3rd Floor 3 LF 4 2-5 years SF Doors - Transom Window 3rd Floor 18 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 2 ΕA 7 10+ years Floor - Wood 3rd Floor 984 SF 6 10+ years Lighting - Lay-in 3rd Floor 27 FΑ 7 6-10 years Marker Board LF 3rd Floor 12 7 6-10 years Walls - Plaster/Drywall 3rd Floor 1,080 SF 7 10+ years Work Sink ΕA 7 3rd Floor 2 10+ years **Building : Main Category : Interior**

					Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor						
Ceiling - Lay-in	1st Floor	14,500	SF	6	10+ years	
Doors - Store Front	1st Floor	10	EA	7	10+ years	
Doors - Wood Doors include hw	1st Floor	18	EA	7	10+ years	
Drinking Fountains - Single Fountain	1st Floor	8	EA	7	10+ years	
Floor - Terrazzo	1st Floor	1,990	SF	6	10+ years	
Floor - Tile Ceramic/ Porcelain	1st Floor	1,240	SF	7	10+ years	



Category : Interior **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile/Sheet 1st Floor 11.245 SF 5 10+ vears Floor - Tile/Sheet SF 1-2 vears 1st Floor 25 4 Damaged tile Lighting - Lay-in 1st Floor 210 EΑ 7 6-10 years Lighting - Pendent/Surface 24 7 1st Floor EΑ 6-10 years Student Lockers - One Tier 1st Floor 580 EΑ 7 10+ years Walls - Plaster/Drywall SF 1st Floor 7,500 6 10+ years Walls - Structural Glazed Tile 1st Floor 7,500 SF 7 10+ years SF Ceiling - Lay-in 2nd Floor 11.820 7 10+ years Drinking Fountains - Single Fountain 2nd Floor 3 EΑ 7 10+ years Drinking Fountains - Single Fountain 2nd Floor 5 ΕA 7 10+ vears Floor - Terrazzo 2nd Floor 1.770 SF 7 10+ vears Floor - Tile/Sheet 2nd Floor 10.040 SF 7 6-10 years Floor - Tile/Sheet 2nd Floor SF 1-2 years 10 4 Cracked 7 Lighting - Lay-in 2nd Floor 146 EΑ 6-10 years Lighting - Pendent/Surface 7 2nd Floor 6 EΑ 6-10 years Student Lockers - One Tier 466 7 2nd Floor FΑ 10+ years SF Walls - Plaster/Drvwall 2nd Floor 12.260 7 10+ years SF Walls - Structural Glazed Tile 2nd Floor 12.260 7 10+ years SF Walls - Structural Glazed Tile 2nd Floor 4 5 1-2 vears Step crack SF Ceiling - Lay-in 3rd Floor 11,411 7 10+ years Ceiling - Plaster/Drywall 3rd Floor 409 SF 7 10+ years Drinking Fountains - Single Fountain 7 10+ years 3rd Floor 8 EΑ Floor - Terrazzo 1,770 SF 5 3rd Floor 10+ years Floor - Tile/Sheet SF 7 3rd Floor 10.050 10+ years Lighting - Lay-in ΕA 7 3rd Floor 146 6-10 years LF Stairs - Terrazzo 3rd Floor 9 7 10+ vears Student Lockers - One Tier 3rd Floor 438 EΑ 7 10+ years Walls - Plaster/Drywall 3rd Floor 12,260 SF 7 10+ years Walls - Structural Glazed Tile 12,260 SF 3rd Floor 7 10+ years Ceiling - Exposed **Basement** 11,732 SF 7 10+ years Floor - Concrete SF Basement 11.732 7 10+ vears Lighting - Pendent/Surface Basement 80 EΑ 7 10+ vears Stairs - Concrete Stairs LF Basement 20 6 10+ years Walls - Concrete Block SF 6 Basement 13.825 10+ years SF 7 Ceiling - Plaster/Drywall **Boiler House** 627 10+ years Doors - Steel Doors incl hw ΕA 7 **Boiler House** 2 10+ years **Boiler House** SF Floor - Concrete 627 7 10+ years Lighting - Pendent/Surface **Boiler House** 10 EA 7 10+ years LF Stairs - Concrete Stairs **Boiler House** 45 7 10+ years SF Walls - Plaster/Drvwall **Boiler House** 2.392 7 10+ years Safety **Camera Viewing Station** 1st Floor 2 ΕA 7 6-10 years Metal Detector 1st Floor 4 ΕA 7 6-10 years



Building : Main Category : Interior Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group Security Cameras 1st Floor 97 ΕA 7 6-10 years Stairs Ceiling - Plaster/Drywall #2 525 SF 7 10+ years Floor - Terrazzo #2 380 SF 7 10+ years Floor - Tile #2 SF 7 175 10+ years Handrails #2 112 LF 7 10+ years Lighting - Pendent/Surface #2 8 ΕA 7 10+ years LF Stairs - Rubber #2 408 7 10+ years SF Walls - Plaster/Drywall #2 1,295 7 10+ years Walls - Structural Glazed Tile #2 SF 7 1,280 10+ years Ceiling - Lay-in #2A 525 SF 7 10+ years Floor - Terrazzo #2A SF 7 380 10+ years Floor - Tile #2A 175 SF 7 10+ years LF 7 Handrails #2A 112 10+ years Lighting - Pendent/Surface #2A 8 EΑ 7 10+ years Stairs - Terrazzo LF #2A 408 7 10+ years SF Walls - Plaster/Drywall #2A 1,295 7 10+ years Walls - Structural Glazed Tile SF 7 #2A 1,280 10+ years Ceiling - Lay-in #3 205 SF 7 10+ years Ceiling - Plaster/Drywall SF #3 525 7 10+ years Floor - Terrazzo #3 380 SF 7 10+ vears SF Floor - Tile/Sheet #3 175 7 10+ years #3 LF 7 Handrails 112 10+ vears Lighting - Pendent/Surface #3 8 EΑ 6 6-10 years Stairs - Rubber #3 408 LF 7 10+ years SF 7 Walls - Plaster/Drywall #3 1,295 10+ years Walls - Structural Glazed Tile #3 SF 7 1,280 10+ years Ceiling - Plaster/Drywall #3A SF 7 525 10+ years Floor - Terrazzo SF #3A 380 7 10+ years SF Floor - Tile #3A 175 7 10+ years LF Handrails #3A 112 7 10+ vears Lighting - Pendent/Surface #3A 8 EΑ 7 10+ years Stairs - Terrazzo #3A 408 LF 7 10+ years Walls - Plaster/Drywall #3A 1,295 SF 7 10+ years Walls - Structural Glazed Tile #3A SF 7 1,280 10+ years Ceiling - Plaster/Drywall SF #3B 525 7 10+ years Floor - Terrazzo #3B 380 SF 7 10+ years SF Floor - Tile #3B 175 7 10+ vears LF Handrails #3B 7 10+ years 112 Lighting - Pendent/Surface #3B ΕA 7 8 10+ years Stairs - Terrazzo LF #3B 408 7 10+ years Walls - Plaster/Drywall #3B 1,295 SF 7 10+ years Walls - Structural Glazed Tile #3B 1,280 SF 7 10+ years



Category : Interior **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Ceiling - Plaster/Drywall #3C 525 SF 10+ vears 7 Floor - Terrazzo #3C SF 7 380 10+ years Floor - Tile #3C 175 SF 7 10+ years #3C LF 7 Handrails 112 10+ years Lighting - Pendent/Surface #3C 8 EΑ 7 10+ years LF Stairs - Terrazzo #3C 7 408 10+ years Walls - Plaster/Drywall #3C 1,295 SF 7 10+ years SF Walls - Structural Glazed Tile #3C 1,280 7 10+ years Ceiling - Lay-in #4 20 SF 7 10+ years Ceiling - Plaster/Drywall SF #4 525 7 10+ years SF Floor - Terrazzo #4 380 7 10+ vears Floor - Tile/Sheet #4 175 SF 7 10+ years #4 112 LF 7 10+ years Handrails ΕA 7 Lighting - Pendent/Surface #4 6 6-10 years Stairs - Rubber #4 LF 7 408 10+ years Walls - Plaster/Drywall #4 SF 7 1,295 10+ years Walls - Structural Glazed Tile SF 7 #4 1.280 10+ years SF Ceiling - Lay-in #5 205 7 10+ years Ceiling - Plaster/Drywall SF #5 525 7 10+ vears Floor - Terrazzo SF #5 380 7 10+ years Floor - Tile/Sheet #5 175 SF 7 6-10 years LF 7 Handrails #5 112 10+ years Lighting - Pendent/Surface #5 7 8 EΑ 6-10 years Stairs - Rubber LF #5 408 7 10+ years Walls - Plaster/Drvwall #5 1.300 SF 7 10+ years SF Walls - Structural Glazed Tile #5 1.275 7 10+ vears SF Ceiling - Lay-in #6 205 7 10+ years Ceiling - Plaster/Drywall #6 525 SF 7 10+ years Floor - Terrazzo SF #6 380 7 10+ years Floor - Tile #6 175 SF 7 10+ years LF Handrails #6 112 7 10+ years Lighting - Pendent/Surface #6 8 EΑ 7 10+ vears Stairs - Rubber LF 7 #6 408 10+ years Walls - Plaster/Drvwall #6 1.295 SF 7 10+ years Walls - Structural Glazed Tile SF 7 #6 1,280 10+ years SF 7 Ceiling - Lay-in #6A 205 10+ years Ceiling - Plaster/Drywall SF #6A 525 7 10+ years Floor - Terrazzo SF #6A 380 7 10+ years SF Floor - Tile/Sheet #6A 175 7 10+ years LF Handrails #6A 112 7 10+ vears Lighting - Pendent/Surface #6A 8 ΕA 7 6-10 years Stairs - Terrazzo 408 LF 7 #6A 10+ vears Walls - Plaster/Drywall #6A 1,295 SF 7 10+ years Walls - Structural Glazed Tile SF #6A 1,280 7 10+ years



Building : Main Category : Interior Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Ceiling - Plaster/Drywall #6B 525 SF 10+ vears 7 Floor - Terrazzo #6B 380 SF 7 10+ years Floor - Tile #6B 175 SF 7 10+ years #6B LF 7 Handrails 112 10+ years Lighting - Pendent/Surface #6B 8 EΑ 7 10+ years LF Stairs - Terrazzo 7 #6B 408 10+ years Walls - Plaster/Drywall #6B 1,295 SF 7 10+ years SF Walls - Structural Glazed Tile #6B 1.280 7 10+ years Ceiling - Plaster/Drvwall #7 525 SF 6 10+ years Floor - Terrazzo SF #7 380 7 10+ years LF Handrails #7 112 5 10+ vears Lighting - Pendent/Surface #7 4 ΕA 7 6-10 years Stairs - Rubber #7 333 LF 6 10+ years LF Stairs - Rubber #7 7 4 0-1 year Missing Walls - Plaster/Drvwall #7 SF 7 1,295 10+ years Walls - Structural Glazed Tile #7 SF 7 1,280 10+ years SF Ceiling - Exposed Basement 200 6 2-5 years Floor - Concrete SF Basement 50 7 10+ years LF Handrails 40 7 10+ vears Basement Lighting - Wall Mounted Basement 1 EΑ 6 2-5 years Not working Stairs - Concrete Basement 85 LF 7 10+ years SF 7 Walls - Masonry Basement 200 10+ years Ceiling - Lay-in SF 7 Lunchroom 85 10+ years SF Floor - Terrazzo 60 6 10+ years Lunchroom Handrails 57 LF 7 Lunchroom 10+ years Lighting - Pendent/Surface Lunchroom 3 ΕA 7 6-10 years LF Stairs - Terrazzo 108 6 10+ years Lunchroom Walls - Plaster/Drywall 119 SF 7 Lunchroom 10+ years Walls - Structural Glazed Tile SF Lunchroom 425 7 10+ years Ceiling - Plaster/Drywall Men's locker room to gym 120 SF 7 10+ years Floor - Terrazzo SF 10+ years Men's locker room to gym 75 7 Handrails LF 56 7 10+ vears Men's locker room to avm FΑ Lighting - Pendent/Surface 7 Men's locker room to gym 1 10+ years Lighting - Wall Mounted Men's locker room to avm 1 FΑ 7 10+ years Stairs - Terrazzo LF Men's locker room to gym 104 7 10+ years Walls - Plaster/Drywall SF 7 Men's locker room to gym 400 10+ years SF Walls - Structural Glazed Tile Men's locker room to gym 400 7 10+ years Vertical Conveyance Elevator - Hydraulic Elevator N/A ΕA 6 1 10+ years



Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Frame Press Box	Northeast	1	EA	7	10+ years	
	Goalpost	Northeast	2	EA	7	10+ years	
	Lighting	Northeast	4	EA	7	10+ years	
	Metal Bleachers	Northeast	525	LF	7	10+ years	
	Scoreboard	Northeast	1	EA	7	10+ years	
	Surface - Synthetic	Northeast	69,703	SF	7	10+ years	
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	11	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	24	EA	6	10+ years	
				_/ \	Ũ	.e. jeure	
Fencing							
	Fencing - Chain Link	Parking lot East, Northeast and Entire Site	1,146	LF	7	10+ years	
	Fencing - New Standard Ornamental	Parking lot East, Northeast and Entire Site	1,437	LF	7	10+ years	
Landsca	ре						
	Benches	Entire Site	7	EA	6	6-10 years	
	Benches	Entire Site	2	EA	4	0-1 year	Broken
	Landscape - Grass	Entire Site	76,430	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	580	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,282	SF	7	10+ years	Replaced
	Landscape - Hardscape- Concrete	Entire Site	12,288	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	1,400	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	35	SF	4	0-1 year	Loose
	Parkway trees	Entire Site	56	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	4,848	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	2,653	SF	6	10+ years	
	Trash Receptacles	Entire Site	4	EA	6	10+ years	
	Walking Path - Hardscape- Asphalt	Entire Site	150	SF	6	10+ years	
	5 1 1					,	
Parking I							
	Concrete Curbs	Parking Lot- North	160	LF	7	10+ years	
	Interior Plantings	Parking Lot- North	8,500	LF	7	10+ years	
	Surface - Asphalt	Parking Lot- North	39,900	SF	7	10+ years	
	Trash Compactor	Parking Lot- North	1	EA	6	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- North	125	SF	7	10+ years	
	Vehicular Screening	Parking Lot- North	500	LF	7		



Catego	ry : Site		Building : Site					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Sidewalk								
	Sidewalks - Internal Walks	Entire Site	950	LF	7	10+ years		
	Sidewalks - Perimeter Sidewalks	Entire Site	30,000	SF	6	10+ years		
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	4	0-1 year	Cracks, spalling	
Signage								
	Flag Pole - Flag Pole	Southeast site, Above exterior door #6W, 10S, 11S, 13S	1	EA	6	10+ years		
	Marquee - Free Standing Back lighted w/ LED	Southeast site, Above exterior door #6W, 10S, 11S, 13S	1	EA	6	10+ years		
	Monument - Building Mounted Cut Letter Sign	Southeast site, Above exterior door #6W, 10S, 11S, 13S	4	EA	6	10+ years		

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					(/				
Art Room	Regular Classroom	3rd Floor	344	344	984	102	17	Y	N
Art Room	Regular Classroom	3rd Floor	350	350	984	102	18	Y	N
Computer Lab	Faculty Lounge	2nd Floor	220	220	1,218	180	21	N	N
Computer Lab	Regular Classroom	1st Floor	130	130	984	102	18	Y	N
Computer Lab	Regular Classroom	1st Floor	132	132	1,128	102	25	Y	N
Computer Lab	Regular Classroom	3rd Floor	329	329	1,032	108	17	Y	Y
Culinary	Regular Classroom	1st Floor	167	167	1,600	102	17	Y	N
Health	Regular Classroom	3rd Floor	333	333	720	102	17	Y	N
Music Room	Regular Classroom	2nd Floor	204	204	1,420	108	18	Y	N
Music Room	Regular Classroom	2nd Floor	206	206	1,260	108	18	Y	N
Office	Regular Classroom	1st Floor	116	116	490	54	9	Y	N
Other Instructional Use	Regular Classroom	1st Floor	108	108	822	102	17	Y	N
Regular Classroom	Computer Lab	3rd Floor	317	317	909	108	17	Y	N
Regular Classroom	Gymnasium	3rd Floor	320	320	1,225	180	21	N	N
Regular Classroom	Multi Purpose Room	1st Floor	106	106	408	60	8	Y	N
Regular Classroom	Office	2nd Floor	226	226	336	36	6	Y	Y
Regular Classroom	Regular Classroom	1st Floor	111	111	720	102	17	Y	N
Regular Classroom	Regular Classroom	1st Floor	112	112	720	102	17	Y	N
Regular Classroom	Regular Classroom	1st Floor	113	113	720	102	17	Y	N
Regular Classroom	Regular Classroom	1st Floor	114	114	720	102	17	Y	N
Regular Classroom	Regular Classroom	1st Floor	168	168	1,600	102	17	Y	N
Regular Classroom	Regular Classroom	1st Floor	169	169	1,180	102	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	720	102	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	720	102	17	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	720	102	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	720	102	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	720	102	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	217A	217	789	108	17	N	N
Regular Classroom	Regular Classroom	2nd Floor	217B	217	720	108	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	720	102	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	229	229	720	102	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	230	230	720	102	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	231	231	1,032	108	17	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	232	232	720	102	17	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	233	233	720	102	17	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	235	235	720	102	17	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	244	244	1,265	102	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	248	246/248	973	102	18	Y	N



Classroom Summary

			Deem	Floor Plan	A.r.o.o.	Glazed	Operable	Window	Smort
Current Usage	Intended Usage	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	250	250	984	102	18	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	311	311	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	312	312	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	315	315	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	316	316	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	624	72	12	Y	N
Regular Classroom	Regular Classroom	3rd Floor	319	319	1,032	108	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	323	323	1,032	108	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	326	326	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	330	330	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	331	331	730	108	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	332	332	720	102	17	Y	N
Regular Classroom	Regular Classroom	3rd Floor	335	335	720	102	17	Y	N
Science	Science	3rd Floor	308	308	510	84	12	Y	N
Science Lab Level 1	Regular Classroom	1st Floor	110	110	1,128	102	17	Y	N
Science Lab Level 1	Science Lab Level 1	2nd Floor	208	208	916	108	17	Y	N
Science Lab Level 1	Science Lab Level 1	2nd Floor	210	210	1,472	240	32	Y	Ν
Science Lab Level 1	Science Lab Level 1	3rd Floor	306	306	916	108	17	Y	Y
Science Lab Level 1	Science Lab Level 1	3rd Floor	310	310	984	102	18	Y	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	348	348	984	102	18	Y	Ν
Science Lab Level 2	Regular Classroom	1st Floor	144	144	1,032	102	17	Y	N
Science Lab Level 2	Regular Classroom	1st Floor	148	148	1,032	102	17	Y	Ν
Special Program	Regular Classroom	1st Floor	150	150	720	102	17	Y	Ν