

1850 N Newland AVENUE, Chicago, IL 60707

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1930	3	79,775
Campus Total			79,775

Category: Exterior Building: Main

	Ty . Exterior			anamg		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Entrance Control - Audio and Video	1 - Main	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	1 - Main	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	1 - Main	2	EA	6	10+ years	
	Exterior Stairs - Concrete	1 - Main	88	LF	6	10+ years	
	Power Door Operator and Controls	1 - Main	2	EΑ	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	1 - Main	140	LF	6	10+ years	
	Ramps - Concrete	1 - Main	70	LF	5	0-1 year	Cracks and damaged.
	Stair Handrail - Steel_Stair Handrail	1 - Main	30	LF	6	10+ years	-
	Exterior Doors - Exterior Steel Door	10	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	10	10	LF	6	10+ years	Concrete landing ok
	Exterior Stairs - Concrete	10	35	LF	4	0-1 year	Broken
	Exterior Stairs - Stone	10	54	LF	4	0-1 year	Broken
	Stair Handrail - Steel_Stair Handrail	10	10	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	11	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	11	71	LF	6	10+ years	
	Exterior Stairs - Concrete	11	6	LF	5	1-2 years	Cracked concrete
	Stair Handrail - Steel_Stair Handrail	11	22	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	12	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	12	85	LF	6	10+ years	
	Exterior Stairs - Concrete	12	3	LF	5	1-2 years	Spalled, broken concrete
	Stair Handrail - Steel_Stair Handrail	12	20	LF	6	10+ years	•
	Exterior Doors - Exterior Steel Door	13 - Roof	2	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	2	1	EA	6	10+ years	
	Exterior Doors - Side lite	2	2	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	2	2	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	3	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	3	2	EA	6	10+ years	
	Exterior Stairs - Concrete	3	50	LF	6	10+ years	
	Exterior Stairs - Concrete	3	25	LF	5	1-2 years	Cracked concrete
	Stair Handrail - Steel_Stair Handrail	3	10	LF	6	10+ years	Repaired
	Stair Handrail - Steel_Stair Handrail	3	20	LF	6	10+ years	·
	Entrance Control - Audio and Video	4	1	EA	7	6-10 years	
	Exterior Doors - Exterior AMP Door	4	2	EA	6	10+ years	
	Exterior Stairs - Concrete	4	72	LF	6	10+ years	
	Power Door Operator and Controls	4	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	4	174	LF	6	10+ years	
	Ramps - Concrete	4	88	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	4	22	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	5	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	5	- 77	LF	6	10+ years	
	Stair Handrail - Steel Stair Handrail	5	24	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	6	1	EA	6	10+ years	
	Exterior Stairs - Concrete	6	75	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	6	13	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	7	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	8 - Yard Storage	2	EA	6	10+ years	
	Exterior Stairs - Concrete	8 - Yard Storage	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	9 - Boiler Room	1	EA	6	10+ years	
	Extend Bools Extend Gleet Bool	3 Bollet Room	•		O	101 years	
_Foundati	on						
	Foundation - Concrete	Entire Building	1,170	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	79,775	SF	7	10+ years	
		· ·				•	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	16	EA	6	10+ years	
_Roof Sys							
	Access Ladder - Metal	A - Main	5	EA	7	10+ years	
	Coping - Stone	A - Main	25	LF	6	10+ years	
	Coping - Terra Cotta	A - Main	612	LF	6	10+ years	
	Downspouts - Exterior Downspouts	A - Main	53	LF	6	6-10 years	
	Downspouts - Interior Downspouts	A - Main	185	LF	6	10+ years	
	Parapet - 16" - 30" Height	A - Main	25	LF	6	10+ years	
	Parapet - Parapet > 30"	A - Main	612	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	A - Main	18,174	SF	5	2-5 years	
	Roof - Metal	A - Main	110	SF	7	10+ years	
	Roof Hatch - Metal	A - Main	16	EA	7	10+ years	

Campus Name: Sayre Page : 2 of 29 Assessment Date: 01/09/2024



Category : Exterior		Building : Main						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Roof Structure - Concrete	A - Main	18,284	SF	7	10+ years		
	Access Ladder - Metal	B - West	1	EA	7	10+ years		
	Coping - Terra Cotta	B - West	329	LF	6	10+ years		
	Downspouts - Exterior Downspouts	B - West	100	LF	6	10+ years		
	Parapet - 16" - 30" Height	B - West	329	LF	6	10+ years		
	Roof - Asphalt Gravel Ballast	B - West	8,009	SF	5	2-5 years		
	Roof Structure - Concrete	B - West	8,009	SF	7	10+ years		
	Access Ladder - Metal	C - Boiler West	1	EA	7	10+ years		
	Chimney - Brick Chimney- Concrete/ Mortar Liner	C - Boiler West	120	LF	6	10+ years		
	Chimney - Brick Chimney- Concrete/ Mortar Liner	C - Boiler West	10	LF	5	1-2 years	Cracked brick	
	Coping - Terra Cotta	C - Boiler West	165	LF	6	10+ years		
	Downspouts - Interior Downspouts	C - Boiler West	108	LF	6	10+ years		
	Parapet - Parapet < 16" Height	C - Boiler West	165	LF	6	10+ years		
	Roof - Asphalt Gravel Ballast	C - Boiler West	3,025	SF	5	2-5 years		
	Roof Structure - Steel with Clay Tile Arch	C - Boiler West	3,025	SF	7	10+ years		
	Coping - Stone	D - Lower NW SW and greenhouse	16	LF	6	10+ years		
	Coping - Terra Cotta	D - Lower NW SW and greenhouse	150	LF	6	10+ years		
	Downspouts - Exterior Downspouts	D - Lower NW SW and greenhouse	145	LF	6	10+ years		
	Downspouts - Interior Downspouts	D - Lower NW SW and greenhouse	49	LF	6	10+ years		
	Parapet - 16" - 30" Height	D - Lower NW SW and greenhouse	16	LF	6	10+ years		
	Parapet - Parapet > 30"	D - Lower NW SW and greenhouse	150	LF	6	10+ years		
	Roof - Asphalt Gravel Ballast	D - Lower NW SW and greenhouse	1,240	SF	5	0-1 year	No access. Window inoperable. Vegetation growth.	
	Roof - Metal	D - Lower NW SW and greenhouse	20	SF	6	10+ years	3	
	Roof Structure - Concrete	D - Lower NW SW and greenhouse	1,260	SF	7	10+ years		
	Coping - Terra Cotta	E - Southwest	88	ĹF	6	10+ years		
	Downspouts - Interior Downspouts	E - Southwest	22	LF	6	10+ years		
	Parapet - Parapet < 16" Height	E - Southwest	88	LF	6	10+ years		
	Roof - Asphalt Gravel Ballast	E - Southwest	837	SF	5	2-5 years	No access	
	Roof Structure - Concrete	E - Southwest	837	SF	7	10+ years		
_Walls								
	Cheek-Wall - Concrete	Entire Building	103	SF	6	10+ years		
	Cheek-Wall - Stone	Entire Building	744	SF	6	10+ years		
	Cheek-Wall - Stone	Entire Building	144	SF	5	1-2 years	Missing stone	
	Exterior Walls - Brick	Entire Building	4,069	SF	6	10+ years		
	Exterior Walls - Brick	Entire Building	20	SF	3	1-2 years	Bulging brick pilaster with large crack	
	Exterior Walls - Stone-Cast	Entire Building	98	SF	6	10+ years	-	
	Exterior Walls - Stone-Cast	Entire Building	2	SF	3	1-2 years	Broken, missing stone	
	Exterior Walls - Terra Cotta	Entire Building	9,150	SF	6	10+ years	-	
_Windows	<u> </u>							

Campus Name: Sayre Page : 3 of 29 Assessment Date: 01/09/2024



Catego	ry : Exterior	gory : Exterior Building : Main					
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Guard - Guards perforated	Entire Building	2,706	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	21	SF	6	10+ years	
	Lintels - Steel	Entire Building	848	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	12	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	30	SF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	320	SF	6	10+ years	
	Storefront Windows	Entire Building	200	SF	6	10+ years	
	Windows - Louver	Entire Building	30	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	15,000	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Automatic Transfer Switch	Boiler Room	2	EA	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	4	EA	6	2-5 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	2-5 years	
	Exit Signs - Auditoium	Entire Building	11	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	26	EΑ	6	6-10 years	
	Exit Signs - Gym	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Security System - CCTV	Entire Building	79,775	SF	5	2-5 years	Only exterior cameras, bad quality
	, ,	3	,			·	feed
	Security System - Intrusion Detection	Entire Building	79,775	SF	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	8,756	SF	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	18,537	SF	6	6-10 years	
	Stairs Emergency A/C Power - Gym	Entire Building	2,885	SF	6	6-10 years	
Main Se	rvice						
_ IVIGITI OG	Main Electrical Service - 2001 to 3000 A	Electrical Room	1	EA	7	10+ years	
	120/208/3PH	• • • • • • • • • • • • • • • • • • • •	·		-	· ,	
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	
	emergency power					•	
	PA System	Entire Building	79,775	SF	6	2-5 years	
Dower D	istribution						
_FUWELD	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years 10+ years	
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Entire Building	10	EA	6	10+ years 10+ years	
	Lighting and rower rathers - 100 A	Little building	10	ĽA	U	10+ years	

Campus Name: Sayre Page : 4 of 29 Assessment Date: 01/09/2024



						100	50 N Newland AVENUE, Chicago, IL 60707
Catego	ry : Electrical		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp						
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	6	10+ years	
	amp						
Catego	ry : Fire Protection		В	uilding	: Main		
Juliogo			_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
1 110 7 1101	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	79,775	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	79,775	SF	6	6-10 years	
	i iie riidiii_Oysteiii	Little Building	10,110	Oi.	Ū	o io years	
Catego	ry : Mechanical		В	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems		•			•	
, <u>, , , , , , , , , , , , , , , , ,</u>	Air Handling Unit- Built Up- Single Zone w/	Basement - AHU1	1	EA	5	6-10 years	AHU-1
	Air Tunnel- Steam Coils - 25001 - 35000 cfm	Dascinett 7tho1		L/\	9	o to years	7410 1
	Air Intake	Basement - AHU1	1	EA	6	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Basement - AHU1	1	EA	5	2-5 years	
	Addition 2000 Figure 1	Dascincii 711101		L/\			
		Rasament - AHII1		FΔ	5	2-5 Vaare	
	Reheat Boxes - Reheat Boxes with Steam	Basement - AHU1	5	EA	5	2-5 years	
	Reheat Boxes - Reheat Boxes with Steam Coil		5			-	No return fan installed
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts-	Basement - AHU1 Basement - AHU1		EA LF	5 4	2-5 years 0-1 year	No return fan installed
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement - AHU1	5 50	LF	4	0-1 year	No return fan installed
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers	Basement - AHU1 Basement - AHU1	5 50 18	LF EA	4 5	0-1 year 2-5 years	
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/	Basement - AHU1	5 50	LF	4	0-1 year	No return fan installed AHU-2
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Basement - AHU1 Basement - AHU1 Basement - AHU2	5 50 18 1	LF EA EA	4 5 5	0-1 year 2-5 years 2-5 years	
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake	Basement - AHU1 Basement - AHU1 Basement - AHU2 Basement - AHU2	5 50 18 1	LF EA EA	4 5 5	0-1 year 2-5 years 2-5 years 6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm	Basement - AHU1 Basement - AHU1 Basement - AHU2 Basement - AHU2 Basement - AHU2	5 50 18 1 1	LF EA EA EA	4 5 5 6 5	0-1 years 2-5 years 2-5 years 6-10 years 2-5 years	
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam	Basement - AHU1 Basement - AHU1 Basement - AHU2 Basement - AHU2	5 50 18 1	LF EA EA	4 5 5	0-1 year 2-5 years 2-5 years 6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil	Basement - AHU1 Basement - AHU1 Basement - AHU2 Basement - AHU2 Basement - AHU2 Basement - AHU2	5 50 18 1 1 1 6	LF EA EA EA EA	4 5 5 6 5 5	0-1 years 2-5 years 2-5 years 6-10 years 2-5 years 2-5 years	AHU-2
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts-	Basement - AHU1 Basement - AHU1 Basement - AHU2 Basement - AHU2 Basement - AHU2	5 50 18 1 1	LF EA EA EA	4 5 5 6 5	0-1 years 2-5 years 2-5 years 6-10 years 2-5 years	
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement - AHU1 Basement - AHU1 Basement - AHU2	5 50 18 1 1 1 6 50	LF EA EA EA EA	4 5 5 6 5 5	0-1 years 2-5 years 2-5 years 6-10 years 2-5 years 2-5 years 0-1 year	AHU-2
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers	Basement - AHU1 Basement - AHU1 Basement - AHU2	5 50 18 1 1 1 6 50 20	LF EA EA EA EA LF	4 5 5 6 5 5 4	0-1 year 2-5 years 2-5 years 6-10 years 2-5 years 2-5 years 0-1 year 2-5 years	AHU-2 No return fan installed
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up-Multi Zone-	Basement - AHU1 Basement - AHU1 Basement - AHU2	5 50 18 1 1 1 6 50	LF EA EA EA EA	4 5 5 6 5 5	0-1 years 2-5 years 2-5 years 6-10 years 2-5 years 2-5 years 0-1 year	AHU-2
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Basement - AHU1 Basement - AHU1 Basement - AHU2	5 50 18 1 1 1 6 50 20 1	LF EA EA EA LF EA	4 5 5 6 5 5 4 5 5	0-1 years 2-5 years 2-5 years 6-10 years 2-5 years 2-5 years 0-1 year 2-5 years 2-5 years	AHU-2 No return fan installed
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake	Basement - AHU1 Basement - AHU1 Basement - AHU2 Basement - AHU3 Basement - AHU3	5 50 18 1 1 1 6 50 20 1	LF EA EA EA LF EA EA	4 5 5 6 5 4 5 6	0-1 year 2-5 years 2-5 years 6-10 years 2-5 years 2-5 years 0-1 year 2-5 years 2-5 years 6-10 years	AHU-2 No return fan installed
	Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Steam Coil Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Basement - AHU1 Basement - AHU1 Basement - AHU2	5 50 18 1 1 1 6 50 20 1	LF EA EA EA LF EA	4 5 5 6 5 5 4 5 5	0-1 years 2-5 years 2-5 years 6-10 years 2-5 years 2-5 years 0-1 year 2-5 years 2-5 years	AHU-2 No return fan installed



Catego	ry : Mechanical		В	uilding	: Main				
		1	0	11014	.	Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Missing or Existing Shaft Zone Dampers	Basement - AHU3	4	EA	5	2-5 years			
	Zone Dampers	Dasement - Anos	4	EA	5	2-5 years			
oiler Sy	estems								
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Entire Building	2	EA	6	6-10 years			
	Chemical Feed System	Entire Building	1	EA	5	6-10 years			
	Combustion Dampers	Entire Building	2	EA	6	6-10 years			
	Condensate Pump	Entire Building	1	EA	4	1-2 years	Corroded/deteriorated tank		
	Condensate Pump	Entire Building	1	EA	4	1-2 years	Corroded/deteriorated tank		
	Condensate Pump	Entire Building	1	EΑ	4	1-2 years	Corroded/deteriorated tank		
	Condensate Pump	Entire Building	1	EΑ	4	1-2 years	Corroded/deteriorated tank		
	Condensate Pump	Entire Building	1	EA	4	1-2 years	Corroded/deteriorated tank		
	Condensate Pump	Entire Building	1	EA	4	1-2 years	Corroded/deteriorated tank		
	Feed Water Pumps and Tank	Entire Building	1	EA	5	2-5 years			
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	10+ years			
	Steam- Low Pressure Boiler - 151 - 200 HP	Littine Building		LA		10+ years			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Entire Building	1	EA	6	10+ years			
	Piping - Condensate Pipe- Steel	Entire Building	900	LF	4	2-5 years	Old galvanized piping, deteriorating insulation		
	Piping - Steam Pipe- Steel	Entire Building	900	LF	4	2-5 years	Old galvanized piping, deteriorating insulation, a couple pipe clamps		
	Steam Traps	Entire Building	36	EA	6	6-10 years	insulation, a couple pipe clamps		
as Boo	ster								
	Gas Booster	Boiler Room	2	EA	5	6-10 years			
leating	Devices								
caung	Fin Tube - Steam	2nd Floor - Staff Restroom	2	LF	5	2-5 years			
	Radiators - Steam	Entire Building	27	EA	5	6-10 years			
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years			
	Unit Heater - Gas	Entire Building	2	ΕA	5	6-10 years			
	Wall Heater - Electric	Entire Building	15	EA	6	6-10 years			
	Wall Heater - Electric	Entire Building	3	EA	5	2-5 years	Dated parts		
	Wall Heater - Electric	Entire Building	3	EA	2	0-1 year	Front cover missing, corroded,		
	wan riedier Electric	Entire building	J	L/\	_	o i yeai	missing parts		
empera	iture Control								
	Electric Thermostat	Entire Building	6	EA	5	2-5 years	Unit heaters, MDF unit, and indoor exhaust fan		
	Pneumatic System	Entire Building	79,775	SF	5	6-10 years			
	Pneumatic System	Entire Building	50	SF	3	0-1 year	Abandoned compressor and lines		

Campus Name: Sayre Page : 6 of 29 Assessment Date: 01/09/2024



Category : Mechanical

Harriet E Sayre Elementary Language Academy 1850 N Newland AVENUE, Chicago, IL 60707

Recommend

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
o vou p	Thermostats - Pneumatic	Entire Building	42	EA	6	2-5 years	
		· ·				·	
Unit Ven							
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	103	1	EA	6	10+ years	
Ventilatio	on.						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	5	2-5 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No suppression system
Catego	ry : Plumbing		В	uilding	: Main		
			.			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	2-5 years	
	Electric Heater - Less than 20 KW	Kitchen	1	EA	5	2-5 years	Deteriorating
Piping							
тірінд	Domestic Piping-Hot Water Return Lines	Entire Building	79,775	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	79,775	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	79,775	SF	6	6-10 years	
	Fixtures	g		-	•	,	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	79,775	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	79,775	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	79,775	SF	6	6-10 years	
	Sanitary Piping	Entire Building	79,775	SF	6	6-10 years	
	Storm Piping	Entire Building	79,775	SF	6	6-10 years	
	Vent Piping	Entire Building	79,775	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	6	10+ years	New pump installed recently
	Pumps - Sump-Duplex	Basement	1	EA	5	2-5 years	
0	lame: Savre		Page : 7 of 29				Assessment Date: 01/09/202

Campus Name: Sayre Page: 7 of 29 Assessment Date: 01/09/2024



Harriet E Sayre Elementary Language Academy

1850 N Newland AVENUE, Chicago, IL 60707

Category : Plumbing Building : Main

Group Item - Type Location Quantity UOM Rank Replacement Comments
Pumps - Sump-Simplex Basement 1 EA 6 6-10 years Under elevator pit.

Category: Room Building: Main

Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Adminis	trative Suites/Offices								
	Ceiling - Plaster/Drywall	103A - Copy Room	156	SF	7	10+ years			
	Doors - Transom Window	103A - Copy Room	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	103A - Copy Room	2	EA	7	10+ years			
	Floor - Wood	103A - Copy Room	156	SF	7	10+ years			
	Lighting - Pendent/Surface	103A - Copy Room	2	EA	7	6-10 years			
	Power Distribution	103A - Copy Room	2	EA	7	10+ years			
	Walls - Plaster/Drywall	103A - Copy Room	373	SF	7	10+ years			
	Ceiling - Plaster/Drywall	103B Teachers' Lounge	218	SF	7	10+ years			
	Doors - Side-lite	103B Teachers' Lounge	24	SF	7	10+ years			
	Doors - Transom Window	103B Teachers' Lounge	28	SF	7	10+ years			
	Doors - Wood Doors inclu hw	103B Teachers' Lounge	2	EA	6	10+ years			
	Floor - Tile	103B Teachers' Lounge	218	SF	6	10+ years			
	Lighting - Pendent/Surface	103B Teachers' Lounge	3	EA	7	6-10 years			
	Power Distribution	103B Teachers' Lounge	4	EA	7	10+ years			
	Walls - Plaster/Drywall	103B Teachers' Lounge	570	SF	7	10+ years			
	Work SInk	103B Teachers' Lounge	1	EA	7	10+ years			
	AC Unit	103C COVID Room	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	103C COVID Room	260	SF	7	10+ years			
	Doors - Wood Doors inclu hw	103C COVID Room	2	EA	7	10+ years			
	Floor - Tile	103C COVID Room	260	SF	7	10+ years			
	Lighting - Pendent/Surface	103C COVID Room	3	EA	6	6-10 years			
	Power Distribution	103C COVID Room	4	EA	7	10+ years			
	Walls - Plaster/Drywall	103C COVID Room	523	SF	7	10+ years			
	Ceiling - Plaster/Drywall	110B Assistant Principal's Office	150	SF	7	10+ years			
	Doors - Transom Window	110B Assistant Principal's Office	16	SF	7	10+ years			
	Doors - Wood Doors inclu hw	110B Assistant Principal's Office	2	EA	6	10+ years			
	Floor - Carpet	110B Assistant Principal's Office	150	SF	6	6-10 years			
	Lighting - Pendent/Surface	110B Assistant Principal's Office	2	EA	7	6-10 years			
	Power Distribution	110B Assistant Principal's Office	4	EA	7	10+ years			
	Walls - Plaster/Drywall	110B Assistant Principal's Office	500	SF	7	10+ years			
	Ceiling - Plaster/Drywall	216 Teachers' Lounge	140	SF	6	10+ years			
	Doors - Wood Doors inclu hw	216 Teachers' Lounge	1	EΑ	7	10+ years			
	Floor - Tile/Sheet	216 Teachers' Lounge	140	SF	7	10+ years			
	Lighting - Pendent/Surface	216 Teachers' Lounge	3	EA	7	6-10 years			
	Power Distribution	216 Teachers' Lounge	2	EA	7	10+ years			
	Walls - Plaster/Drywall	216 Teachers' Lounge	306	SF	6	10+ years			
	Ceiling - Plaster/Drywall	217 Copy Room	140	SF	6	10+ years			
	Doors - Wood Doors inclu hw	217 Copy Room	1	EA	7	10+ years			

Campus Name: Sayre Page : 8 of 29 Assessment Date: 01/09/2024



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	217 Copy Room	140	SF	7	10+ years	
	Lighting - Pendent/Surface	217 Copy Room	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	217 Copy Room	1	EA	5	1-2 years	Missing cover
	Power Distribution	217 Copy Room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	217 Copy Room	300	SF	6	10+ years	
	AC Unit	Engineer's Office #1	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office #1	73	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office #1	15	SF	5	1-2 years	Water damage, chipping plaster.
	Doors - Side-lite	Engineer's Office #1	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office #1	1	EA	6	10+ years	
	Floor - Carpet	Engineer's Office #1	88	SF	6	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office #1	2	EA	7	6-10 years	
	Power Distribution	Engineer's Office #1	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office #1	221	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office #2	67	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office #2	1	ĒΑ	7	10+ years	
	Floor - Carpet	Engineer's Office #2	67	SF	6	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office #2	1	EA	7	6-10 years	
	Power Distribution	Engineer's Office #2	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office #2	156	SF	6	10+ years	
	AC Unit	Main Office	1	EA	5	2-5 years	
	Ceiling - Plaster/Drywall	Main Office	442	SF	7	10+ years	
	Doors - Transom Window	Main Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	2	EA	6	10+ years	
	Floor - Carpet	Main Office	332	SF	6	6-10 years	
	Floor - Wood	Main Office	110	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office	3	EA	7	6-10 years	
	Power Distribution	Main Office	4	EA	7	10+ years	
	Storage/ Closet	Main Office	12	SF	5	10+ years	
	Walls - Plaster/Drywall	Main Office	928	SF	7	10+ years	
	AC Unit	Office 204	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Office 204	325	SF	7	10+ years	
	Doors - Transom Window	Office 204	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office 204	2	EA	7	10+ years	
	Floor - Wood Doors inclu flw	Office 204	325	SF	7	10+ years	
	Lighting - Pendent/Surface	Office 204	11	EA	7	6-10 years	
	Power Distribution	Office 204	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Office 204	767	SF	7	10+ years	
	AC Unit	Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Office	150	SF	7	•	
	Doors - Wood Doors inclu hw			SF EA	<i>7</i> 6	10+ years	
		Principal's Office	1			10+ years	
	Floor - Carpet	Principal's Office	150	SF	6	6-10 years	
	Lighting - Pendent/Surface	Principal's Office	1	EA EA	7 7	6-10 years	
	Power Distribution	Principal's Office	4	EA	,	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Principal's Office	270	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office	10	SF	5	0-1 year	Spalling behind heater
Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	176	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	6,404	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	18	EA	6	10+ years	
	Floor - Concrete	1st Floor	1,186	SF	7	10+ years	
	Floor - Tile	1st Floor	5,198	SF	6	6-10 years	
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Chipped by side entrance
	Lighting - Chandelier, Incandescent	1st Floor	5	EA	6	6-10 years	,
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	21	EA	7	6-10 years	
	Main Floor Seating	1st Floor	514	EA	7	10+ years	
	Sound System	1st Floor	1	EΑ	7	10+ years	
	Stage	1st Floor	1,370	SF	7	10+ years	
	Stage Curtain	1st Floor	4	ĒΑ	7	10+ years	
	Stage Lift	1st Floor	1	EΑ	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	26	LF	7	10+ years	
	Storage/ Closet	1st Floor	244	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	500	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	6,341	SF	7	10+ years	
Green H	ouse						
	Finishes	2nd Floor	347	SF	7	10+ years	
	Glazing	2nd Floor	340	SF	7	10+ years	
	Mechanical	2nd Floor	347	SF	7	10+ years	
	Plumbing	2nd Floor	347	SF	7	10+ years	
Gvmnas	ia						
	Ceiling - Plaster/Drywall	1st Floor	2,885	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	6	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	2,885	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	8	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	4	EA	7	10+ years	
	Storage/ Closet	1st Floor	250	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,256	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,630	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	74	SF	5	1-2 years	Crack up wall, chipping paint and
				٠.	J	; 00.0	missing plaster behind hoops
Kitchen							

Campus Name: Sayre Page : 10 of 29 Assessment Date: 01/09/2024



Catego	ry : Room		В	uilding	: Main	· · · · · · · · · · · · · · · · · · ·		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	AC Unit	213	2	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	213	386	SF	7	10+ years		
	Doors - Transom Window	213	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	213	1	EΑ	7	10+ years		
	Floor - Tile/Sheet	213	386	SF	7	10+ years		
	Lighting - Pendent/Surface	213	6	EA	7	6-10 years		
	Serving Line	213	18	LF	7	10+ years		
	Walls - Plaster/Drywall	213	624	SF	6	10+ years		
Library								
	AC Unit	301 & 303	2	EA	7	6-10 years		
	Casework	301 & 303	50	LF	6	10+ years		
	Ceiling - Plaster/Drywall	301 & 303	1,452	SF	7	10+ years		
	Doors - Wood Doors inclu hw	301 & 303	2	ĒΑ	7	10+ years		
	Floor - Wood	301 & 303	1,452	SF	7	10+ years		
	Lighting - Pendent/Surface	301 & 303	28	ĒΑ	7	6-10 years		
	Storage/ Closet	301 & 303	32	SF	7	10+ years		
	Walls - Plaster/Drywall	301 & 303	2,210	SF	7	10+ years		
Locker/9	Shower Room							
LUCKGI/C	Accessories	Engineer's Locker Room -	100	SF	5	6-10 years		
	Accessories		100	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	Mezzanine (electrical room) Engineer's Locker Room -	100	SF	e	10		
	Ceiling - Plaster/Drywaii		100	SF	6	10+ years		
	B W IB : I I	Mezzanine (electrical room)		_ ^	•	40		
	Doors - Wood Doors inclu hw	Engineer's Locker Room -	2	EA	6	10+ years		
		Mezzanine (electrical room)			_			
	Floor - Concrete	Engineer's Locker Room -	100	SF	5	10+ years		
		Mezzanine (electrical room)						
	Lavatory	Engineer's Locker Room -	1	EA	4	0-1 year	Removed	
		Mezzanine (electrical room)						
	Lighting - Pendent/Surface	Engineer's Locker Room -	2	EA	5	6-10 years	Re-furbish fixture	
		Mezzanine (electrical room)						
	Walls - Plaster/Drywall	Engineer's Locker Room -	200	SF	5	1-2 years	Water damage.	
	·	Mezzanine (electrical room)				•	· ·	
	Walls - Tile Ceramic/ Porcelain	Engineer's Locker Room - ^	20	SF	6	10+ years		
		Mezzanine (electrical room)				,		
	Water Closet	Engineer's Locker Room -	1	EA	6	6-10 years	Does not work	
		Mezzanine (electrical room)	·		· ·	0 .0 ,00.0		
Lunch &	Multipurpose Room							
uiiui Q	AC Unit	212	2	EA	7	6-10 years	No max occupancy sign	
		212		SF			NO max occupancy sign	
	Ceiling - Plaster/Drywall		1,062		6	10+ years		
	Doors - Wood Doors inclu hw	212	2	EA	7	10+ years		



Catego	Category : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile/Sheet	212	1,062	SF	7	10+ years			
	Lighting - Pendent/Surface	212	20	EA	6	6-10 years			
	Storage/ Closet	212	90	SF	7	10+ years			
	Walls - Plaster/Drywall	212	1,235	SF	6	10+ years			
MDF_ID	F								
	Doors - Steel Doors incl hw	204A	1	EA	7	10+ years			
	Finishes	204A	90	SF	7	10+ years			
	Other Cooling Unit	204A	1	EA	7	6-10 years			
Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	50	SF	5	10+ years			
	Janitor's Closet	1st Floor	50	SF	5	10+ years			
	Mechanical/ Service Rooms	1st Floor	60	SF	7	10+ years			
	Janitor's Closet	2nd Floor	20	SF	5	10+ years	Damaged.		
	Janitor's Closet	2nd Floor	20	SF	5	10+ years	•		
	Storage Room	2nd Floor	93	SF	7	10+ years			
	Storage Room	2nd Floor	325	SF	5	10+ years			
	Janitor's Closet	3rd Floor	20	SF	5	10+ years			
	Janitor's Closet	3rd Floor	20	SF	5	10+ years			
	Storage Room	3rd Floor	86	SF	7	10+ years			
	Air Intake Plenums	Basement	4,440	SF	5	10+ years			
	Air Tunnel	Basement	2,136	SF	5	10+ years			
	Boiler Room	Basement	1,874	SF	7	10+ years			
	Coal Room	Basement	388	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	5,106	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	2,184	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	2,064	SF	7	10+ years			
	Storage Room	Basement	1,500	SF	7	10+ years			
	Storage Room	Basement	50	SF	5	10+ years			
Restroor	n								
	Accessories	107 Girls	250	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	107 Girls	250	SF	7	10+ years			
	Doors - Transom Window	107 Girls	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	107 Girls	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	107 Girls	250	SF	7	10+ years			
	Floor Drain	107 Girls	1	EA	7	10+ years			
	Lavatory	107 Girls	2	EA	7	10+ years			
	Lighting - Pendent/Surface	107 Girls	3	EA	7	6-10 years			
	Partitions	107 Girls	7	EA	7	10+ years			
	Walls - Plaster/Drywall	107 Girls	100	SF	7	10+ years			
	Walls - Structural Glazed Tile	107 Girls	132	SF	7	10+ years			

Campus Name: Sayre Page : 12 of 29 Assessment Date: 01/09/2024



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	107 Girls	200	SF	7	10+ years	
	Water Closet	107 Girls	7	EA	7	10+ years	
	Accessories	109 Boys	269	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	109 Boys	269	SF	7	10+ years	
	Doors - Transom Window	109 Boys	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109 Boys	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	109 Boys	269	SF	6	10+ years	
	Floor Drain	109 Boys	1	EA	7	10+ years	
	Hand Dryer	109 Boys	1	EA	7	10+ years	
	Lavatory	109 Boys	2	EA	7	10+ years	
	Lighting - Pendent/Surface	109 Boys	3	EA	7	6-10 years	
	Partitions	109 Boys	1	EA	7	10+ years	
	Urinals	109 Boys	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	109 Boys	258	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	109 Boys	200	SF	7	10+ years	
	Water Closet	109 Boys	1	ĒΑ	7	10+ years	
	Accessories	110C Principal's Toilet	23	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	110C Principal's Toilet	23	SF	7	10+ years	
	Doors - Wood Doors inclu hw	110C Principal's Toilet	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	110C Principal's Toilet	23	SF	7	10+ years	
	Lavatory	110C Principal's Toilet	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	110C Principal's Toilet	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	110C Principal's Toilet	48	SF	7	10+ years	
	Water Closet	110C Principal's Toilet	1	ĒΑ	7	10+ years	
	Accessories	115 All Gender	82	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	115 All Gender	82	SF	7	10+ years	
	Doors - Wood Doors inclu hw	115 All Gender	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	115 All Gender	82	SF	7	10+ years	
	Lavatory	115 All Gender	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	115 All Gender	2	EA	7	6-10 years	
	Partitions	115 All Gender	1	ΕA	7	10+ years	
	Walls - Plaster/Drywall	115 All Gender	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	115 All Gender	80	SF	7	10+ years	
	Water Closet	115 All Gender	1	ĒΑ	7	10+ years	
	Accessories	117 All Gender	82	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	117 All Gender	82	SF	7	10+ years	
	Doors - Wood Doors inclu hw	117 All Gender	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	117 All Gender	82	SF	7	10+ years	
	Lavatory	117 All Gender	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	117 All Gender	2	EA	7	6-10 years	
	Partitions	117 All Gender	- 1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	117 All Gender	88	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	117 All Gender	88	SF	7	10+ years	
	Water Closet	117 All Gender	1	EA	7	10+ years	
					•	,	

Campus Name: Sayre Page: 13 of 29 Assessment Date: 01/09/2024



Catego	Category : Room		В	uilding	: Main		· • • ·
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	211 Boys	269	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	211 Boys	269	SF	6	10+ years	
	Doors - Transom Window	211 Boys	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	211 Boys	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	211 Boys	264	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	211 Boys	5	SF	4	1-2 years	Missing tiles
	Floor Drain	211 Boys	1	EΑ	7	10+ years	
	Lavatory	211 Boys	1	EA	7	10+ years	
	Lighting - Pendent/Surface	211 Boys	3	EΑ	7	6-10 years	
	Partitions	211 Boys	1	EA	7	10+ years	
	Urinals	211 Boys	4	EΑ	6	10+ years	
	Walls - Structural Glazed Tile	211 Boys	258	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	211 Boys	200	SF	7	10+ years	
	Water Closet	211 Boys	1	EΑ	7	10+ years	
	Accessories	214 Girls	250	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	214 Girls	250	SF	6	10+ years	
	Doors - Transom Window	214 Girls	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	214 Girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	214 Girls	250	SF	6	10+ years	
	Floor Drain	214 Girls	1	EΑ	7	10+ years	
	Lavatory	214 Girls	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	214 Girls	3	EA	7	6-10 years	
	Partitions	214 Girls	7	EA	7	10+ years	
	Walls - Structural Glazed Tile	214 Girls	232	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	214 Girls	200	SF	7	10+ years	
	Water Closet	214 Girls	7	EΑ	7	10+ years	
	Accessories	216A Womens	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	216A Womens	65	SF	6	10+ years	
	Doors - Transom Window	216A Womens	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	216A Womens	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	216A Womens	65	SF	6	10+ years	
	Lavatory	216A Womens	1	EA	7	10+ years	
	Lighting - Pendent/Surface	216A Womens	1	EA	5	1-2 years	Missing cover
	Partitions	216A Womens	2	EA	7	10+ years	•
	Walls - Plaster/Drywall	216A Womens	72	SF	7	10+ years	
	Walls - Plaster/Drywall	216A Womens	10	SF	5	1-2 years	Water damage
	Walls - Tile Ceramic/ Porcelain	216A Womens	82	SF	7	10+ years	3
	Water Closet	216A Womens	2	EA	7	10+ years	
	Accessories	217A Mens	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	217A Mens	65	SF	7	10+ years	
	Doors - Transom Window	217A Mens	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	217A Mens	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	217A Mens	65	SF	6	10+ years	
	Lavatory	217A Mens	1	ĒΑ	7	10+ years	
	•		•			- ,	



Catego	ry : Room		В	uilding	: Main		Building : Main						
_				_		Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments						
	Lighting - Pendent/Surface	217A Mens	1	EA	7	6-10 years							
	Partitions	217A Mens	2	EA	7	10+ years							
	Walls - Plaster/Drywall	217A Mens	60	SF	7	10+ years							
	Walls - Structural Glazed Tile	217A Mens	82	SF	7	10+ years							
	Water Closet	217A Mens	2	EA	7	10+ years							
	Accessories	314 Girls	250	SF	7	6-10 years							
	Ceiling - Plaster/Drywall	314 Girls	250	SF	6	10+ years							
	Doors - Transom Window	314 Girls	8	SF	7	10+ years							
	Doors - Wood Doors inclu hw	314 Girls	1	EA	7	10+ years							
	Floor - Tile Ceramic/ Porcelain	314 Girls	250	SF	6	10+ years							
	Floor Drain	314 Girls	1	EA	7	10+ years							
	Lavatory	314 Girls	1	EA	7	10+ years							
	Lighting - Pendent/Surface	314 Girls	3	EA	7	6-10 years							
	Partitions	314 Girls	7	EA	7	10+ years							
	Walls - Structural Glazed Tile	314 Girls	8	SF	7	10+ years							
	Walls - Tile Ceramic/ Porcelain	314 Girls	400	SF	7	10+ years							
	Water Closet	314 Girls	7	EA	7	10+ years							
	Accessories	315 Boys	269	SF	7	6-10 years							
	Ceiling - Plaster/Drywall	315 Boys	269	SF	6	10+ years							
	Doors - Transom Window	315 Boys	8	SF	7	10+ years							
	Doors - Wood Doors inclu hw	315 Boys	1	EA	7	10+ years							
	Floor - Tile Ceramic/ Porcelain	315 Boys	269	SF	6	10+ years							
	Floor Drain	315 Boys	1	EA	7	10+ years							
	Lavatory	315 Boys	1	EA	7	10+ years							
	Lighting - Pendent/Surface	315 Boys	3	EA	7	6-10 years							
	Partitions	315 Boys	1	EA	7	10+ years							
	Urinals	315 Boys	4	EA	7	10+ years							
	Walls - Structural Glazed Tile	315 Boys	258	SF	7	10+ years							
	Walls - Tile Ceramic/ Porcelain	315 Boys	297	SF	7	10+ years							
	Walls - Tile Ceramic/ Porcelain	315 Boys	3	SF	4	1-2 years	Missing tiles						
	Water Closet	315 Boys	1	EA	7	10+ years							
	Accessories	Engineer Office #2	23	SF	5	6-10 years							
	Ceiling - Plaster/Drywall	Engineer Office #2	23	SF	6	10+ years							
	Doors - Wood Doors inclu hw	Engineer Office #2	1	EA	6	10+ years							
	Floor - Concrete	Engineer Office #2	23	SF	5	10+ years							
	Lavatory	Engineer Office #2	1	EA	7	10+ years							
	Lighting - Pendent/Surface	Engineer Office #2	1	EA	5	0-1 year	Does not work.						
	Walls - Plaster/Drywall	Engineer Office #2	30	SF	6	10+ years							
	Walls - Plaster/Drywall	Engineer Office #2	10	SF	5	0-1 year	Water damage						
	Walls - Tile Ceramic/ Porcelain	Engineer Office #2	20	SF	7	10+ years							
	Water Closet	Engineer Office #2	1	EA	3	1-2 years	Toilet does not work.						
	Accessories	Engineer's Office #1	23	SF	5	6-10 years							
	Ceiling - Plaster/Drywall	Engineer's Office #1	23	SF	6	10+ years							
	Doors - Wood Doors inclu hw	Engineer's Office #1	1	EA	6	10+ years							

Campus Name: Sayre Page : 15 of 29 Assessment Date: 01/09/2024



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Engineer's Office #1	23	SF	4	1-2 years	Missing tiles
	Lavatory	Engineer's Office #1	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office #1	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Engineer's Office #1	25	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Engineer's Office #1	20	SF	7	10+ years	
	Water Closet	Engineer's Office #1	1	EA	7	10+ years	Repaired.
	Accessories	Gym Boys	98	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym Boys	98	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Boys	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym Boys	98	SF	7	10+ years	
	Lavatory	Gym Boys	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Gym Boys	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Gym Boys	1	EA	6	6-10 years	
	Partitions	Gym Boys	1	EA	7	10+ years	
	Urinals	Gym Boys	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Gym Boys	69	SF	7	10+ years	
	Walls - Structural Glazed Tile	Gym Boys	50	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Gym Boys	38	SF	7	10+ years	
	Water Closet	Gym Boys	1	EΑ	7	10+ years	
	Accessories	Gym Girls	98	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym Girls	93	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym Girls	5	SF	5	1-2 years	Cracking.
	Doors - Wood Doors inclu hw	Gym Girls	1	EA	6	10+ years	-
	Floor - Tile Ceramic/ Porcelain	Gym Girls	97	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym Girls	1	SF	4	1-2 years	Missing tiles
	Lavatory	Gym Girls	1	EA	7	10+ years	-
	Lighting - Pendent/Surface	Gym Girls	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	Gym Girls	1	EΑ	5	0-1 year	Does not work.
	Partitions	Gym Girls	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym Girls	89	SF	7	10+ years	
	Walls - Structural Glazed Tile	Gym Girls	123	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Gym Girls	73	SF	7	10+ years	
	Water Closet	Gym Girls	1	EΑ	7	10+ years	
	Accessories	Inside 104	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 104	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 104	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 104	56	SF	7	10+ years	
	Floor Drain	Inside 104	2	EA	7	10+ years	
	Lavatory	Inside 104	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Inside 104	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Inside 104	95	SF	7	10+ years	
	Water Closet	Inside 104	1	ĒΑ	7	10+ years	
						- ,	



Catego	ry : Classroom		В	uilding	: Main		30 W Wewland AVENUE, Officago, 12 00707
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #100 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	6	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	728	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,134	SF	7	10+ years	
Classro	om #101 (Deguler Classroom)					•	
_Ciassio0	om #101 (Regular Classroom)	1st Floor	4	Г^	7	6.10	
	AC Units		1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	6	10+ years	
	Doors - Transom Window	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	728	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,134	SF	7	10+ years	
_Classroo	om #102 (Kindergarten)						
	AC Units	1st Floor	1	EΑ	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	7	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Tile	1st Floor	728	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,134	SF	7	10+ years	
_Classroo	om #103 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	17	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	802	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	777	SF	7	10+ years	
	Floor - Tile	1st Floor	25	SF	4	1-2 years	Chipping, cracked, and missing tiles.
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	omponing, oracinea, and missing tiles.
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Mantel Doald	1301 1001	0	LI	,	o- io yeais	

Campus Name: Sayre Page : 17 of 29 Assessment Date: 01/09/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	842	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #104 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,353	SF	7	10+ years	
	Doors - Transom Window	1st Floor	29	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Carpet	1st Floor	250	SF	7	6-10 years	
	Floor - Wood	1st Floor	1,103	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	22	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	210	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,688	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroc	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	7	10+ years	
	Doors - Transom Window	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	728	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,134	SF	6	10+ years	
Classroc	om #108 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	944	SF	7	10+ years	
	Chalk Board	1st Floor	26	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years	
	Floor - Tile	1st Floor	944	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Storage/ Closet	1st Floor	144	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,190	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain Work Sink	1st Floor	65	SF	7	10+ years	
		1st Floor	3	EA	7	6-10 years	

Campus Name: Sayre Page : 18 of 29 Assessment Date: 01/09/2024



Catego	ry : Classroom		В	uilding	: Main		50 W Newland AVENOE, Gilleago, IE 60707
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #111 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,093	SF	7	10+ years	
	Doors - Transom Window	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	1,093	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	22	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,135	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,274	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	19	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,274	SF	6	10+ years	
_Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	736	SF	6	10+ years	
						-	

Campus Name: Sayre Page: 19 of 29 Assessment Date: 01/09/2024



Recommend	Catego	ry : Classroom		В	uilding	: Main		
Lighting - Pendent/Surface	_				_			
Marker Board 2nd Floor 25	Group			Quantity		Rank		Comments
Storage/ Closet 2nd Floor 16 SF 7 10+ years		Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
Mails - Plaster/Drywall		Marker Board	2nd Floor	25	LF	7	6-10 years	
AC Units		Storage/ Closet	2nd Floor	16		7	10+ years	
AC Units		Walls - Plaster/Drywall	2nd Floor	1,274	SF	6	10+ years	
AC Units	Classroc	om #203 (Regular Classroom)						
Casework		, ,	2nd Floor	1	FA	7	6-10 years	
Ceiling - Plaster/Drywall								
Doors - Transom Window 2nd Floor 16 SF 7 10+ years								
Doors - Wood Doors inclu hw							•	
Floor - Wood								
Lighting - Pendent/Surface 2nd Floor 14 EA FA 7 6-10 years Marker Board 2nd Floor 30 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years Classroom #206 (Regular Classroom) 2nd Floor 1 EA 7 6-10 years AC Units 2nd Floor 12 LF 6 10+ years Casework 2nd Floor 740 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 740 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EA 7 10+ years Floor - Wood 2nd Floor 740 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 15 EF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1 EA 7 6-10 years Walls - Plaster/Drywall 2nd Floor 1 EA 7 6-10 years								
Marker Board								
Storage/Closet 2nd Floor 16 SF 7 10+ years								
Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years						-		
Classroom #206 (Regular Classroom)								
AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 12 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 740 SF 6 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Elgotro Plaster Board 2nd Floor 14 EA 7 6-10 years Lighting - Pendent/Surface 2nd Floor 25 LF 7 6-10 years Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years Casework 2nd Floor 1,274 SF 6 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Ploor - Wood 2nd Floor 2 EA 7 10+ years Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 15 SF 4 1-2 years Warping from water Storage/ Closet 2nd Floor 25 LF 7 6-10 years Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 15 SF 7 10+ years Placter Storage/ Closet 2nd Floor 15 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2nd Floor 16 SF 7 10+ years Placter Storage/ Closet 2		Walls - Flaster/Drywall	211d F1001	1,274	SI	O	10+ years	
Casework	Classroo							
Ceiling - Plaster/Drywall								
Doors - Transom Window 2nd Floor 16 SF 7 10+ years							•	
Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Floor - Wood 2nd Floor 740 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 16 SF 7 10+ years Storage/ Closet 2nd Floor 16 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years Walls - Plaster/Drywall 2nd Floor 1 EA 7 6-10 years Walls - Plaster/Drywall 2nd Floor 12 LF 6 10+ years Casework 2nd Floor 12 LF 6 10+ years Casework Ceiling - Plaster/Drywall 2nd Floor 740 SF 6 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Floor - Wood 2nd Floor 725 SF 6 10+ years Floor - Wood 2nd Floor 725 SF 6 10+ years Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 25 LF 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years Storage/ Closet 2nd Floor 16 SF 7 10+ years Storage/ Closet 2nd Floor 16 SF 7 10+ years Storage/ Closet 2nd Floor 16 SF 7 10+ years Storage/ Closet 2nd Floor 16 SF 7 10+ years Storage/ Closet 2nd Floor 20 EF 7 10+ years Storage/ Closet 2nd Floor 20 EF 7 10+ years Storage/ Closet 2nd Floor 2nd		Ceiling - Plaster/Drywall	2nd Floor	740			10+ years	
Floor - Wood				_				
Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years Classroom#208 (Regular Classroom) AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 12 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 740 SF 6 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Floor - Wood 2nd Floor 725 SF 6 10+ years Floor - Wood 2nd Floor 725 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years		Doors - Wood Doors inclu hw	2nd Floor	2				
Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years Classroom #208 (Regular Classroom) 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 12 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 740 SF 6 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Floor - Wood 2nd Floor 725 SF 6 10+ years Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7			2nd Floor		SF	6		
Storage/ Closet 2nd Floor 16 SF 7 10+ years							6-10 years	
Walls - Plaster/Drywall 2nd Floor 1,274 SF 6 10+ years Classroom #208 (Regular Classroom) AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 12 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 740 SF 6 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Floor - Wood 2nd Floor 725 SF 6 10+ years Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years								
AC Units 2nd Floor 1				16		7	10+ years	
AC Units 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3nd Floor 3		Walls - Plaster/Drywall	2nd Floor	1,274	SF	6	10+ years	
Casework 2nd Floor 12 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 740 SF 6 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Floor - Wood 2nd Floor 725 SF 6 10+ years Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years	Classroc	om #208 (Regular Classroom)						
Casework 2nd Floor 12 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 740 SF 6 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Floor - Wood 2nd Floor 725 SF 6 10+ years Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years		AC Units	2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall 2nd Floor 740 SF 6 10+ years Doors - Transom Window 2nd Floor 16 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years Floor - Wood 2nd Floor 725 SF 6 10+ years Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years				12			•	
Doors - Transom Window2nd Floor16SF710+ yearsDoors - Wood Doors inclu hw2nd Floor2EA710+ yearsFloor - Wood2nd Floor725SF610+ yearsFloor - Wood2nd Floor15SF41-2 yearsWarping from waterLighting - Pendent/Surface2nd Floor14EA76-10 yearsMarker Board2nd Floor25LF76-10 yearsStorage/ Closet2nd Floor16SF710+ years								
Doors - Wood Doors inclu hw2nd Floor2 EA7 10+ yearsFloor - Wood2nd Floor725 SF 6 10+ yearsFloor - Wood2nd Floor15 SF 4 1-2 years Warping from waterLighting - Pendent/Surface2nd Floor14 EA7 6-10 yearsMarker Board2nd Floor25 LF 7 6-10 yearsStorage/ Closet2nd Floor16 SF 7 10+ years								
Floor - Wood 2nd Floor 725 SF 6 10+ years Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years						7		
Floor - Wood 2nd Floor 15 SF 4 1-2 years Warping from water Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years						6	•	
Lighting - Pendent/Surface 2nd Floor 14 EA 7 6-10 years Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years								Warping from water
Marker Board 2nd Floor 25 LF 7 6-10 years Storage/ Closet 2nd Floor 16 SF 7 10+ years						7		1 3
Storage/ Closet 2nd Floor 16 SF 7 10+ years								
						-		
Classroom #210 (Regular Classroom)	Classroc	nm #210 (Regular Classroom)						

Campus Name: Sayre Page : 20 of 29 Assessment Date: 01/09/2024



Catego	ry : Classroom		В	uilding	: Main		30 N Newland Avenue, Officago, ie 60707
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,274	SF	6	10+ years	
Classroo	om #300 (Music Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	water damage
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood Bools Inclu IIW	3rd Floor	740	SF	6	10+ years	
		3rd Floor	14	EA	7	•	
	Lighting - Pendent/Surface Marker Board	3rd Floor	25	LF	7	6-10 years	
				SF		6-10 years	
	Storage/ Closet	3rd Floor	16		7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,274	SF	6	10+ years	
_Classroo	om #302 (Office)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Carpet	3rd Floor	740	SF	6	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,274	SF	6	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	740	SF	7	10+ years	
						,	

Campus Name: Sayre Page : 21 of 29 Assessment Date: 01/09/2024



Catego	ry : Classroom		В	uilding	: Main		-
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,274	SF	7	10+ years	
Classroo	m #305 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	740	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,264	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Damaged plaster
	Walls - Flaster/Drywall	314 1 1001	10	OI .	3	1-2 years	Damaged plaster
Classroo	m #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	742	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	742	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,274	SF	6	10+ years	
Classroo	m #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	740	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,274	SF	6	10+ years	
	vvalio - i lastel/Diywali	Jiu i looi	1,274	OI.	U	10+ years	
Classroo	m #308 (Regular Classroom)						

Campus Name: Sayre Page : 22 of 29 Assessment Date: 01/09/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Floor - Wood	3rd Floor	10	SF	4	1-2 years	Seal worn
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,269	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Damaged.
	vvalie i lactor/Dryvvali	01011001	O .	O.	Ü	1 2 youro	Damagoa.
Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,289	SF	7	10+ years	
Classro	om #310 (Regular Classroom)						
Classici	AC Units	3rd Floor	1	EA	7	6-10 years	
		3rd Floor	12	LF	6	<u>-</u>	
	Casework Ceiling - Plaster/Drywall	3rd Floor	740	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
				_		10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,274	SF	7	10+ years	
Classroo	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	20070 Harison William	010 1 1001	10	01	,	TOT years	

Campus Name: Sayre Page : 23 of 29 Assessment Date: 01/09/2024



	cnools					100	50 N Newland AVENUE, Chicago, IL 6070
Category : Classroom			Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	740	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,284	SF	6	10+ years	
Classroo	m #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood Boors inclu tiw	3rd Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	•	
				SF		6-10 years	
	Storage/ Closet	3rd Floor	16		7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,274	SF	6	10+ years	
lassroo	m #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	16	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,274	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	-						
ZI IIGOI	Ceiling - Plaster/Drywall	1st Floor	4,731	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	12	EA	6	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	4	EA	7	6-10 years	
	Floor - Terrazzo			SF	7	•	
		1st Floor	936	SF SF		10+ years	Cracking
	Floor - Terrazzo	1st Floor	50	SF	4	1-2 years	Cracking
			.) //[C. L	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,745				
	Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor	3,745 1 42	EA EA	7 7	6-10 years 6-10 years	

Campus Name: Sayre Page : 24 of 29 Assessment Date: 01/09/2024



Category : Interior		В	uilding	: Main		50 W Newland AVENUE, Officago, IE 00707	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	1st Floor	224	EA	7	10+ years	
	Walls - Masonry	1st Floor	3,730	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,536	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	192	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,303	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	1	EA	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	1,000	SF	4	0-1 year	Cracking.
	Floor - Tile/Sheet	2nd Floor	2,303	SF	5	10+ years	•
	Lighting - Pendent/Surface	2nd Floor	28	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	170	EA	7	10+ years	
	Walls - Masonry	2nd Floor	2,730	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,291	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	5	0-1 year	Damaged.
	Ceiling - Plaster/Drywall	3rd Floor	2,880	SF	6	10+ years	3.1
	Drinking Fountains - Single Fountain	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Terrazzo	3rd Floor	1,000	SF	4	0-1 year	Cracking.
	Floor - Tile/Sheet	3rd Floor	1,880	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd Floor	26	ĒΑ	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	155	ĒΑ	7	10+ years	
	Walls - Masonry	3rd Floor	2,460	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,952	SF	6	10+ years	
	, .		,			, , , , , ,	
Stairs							
	Ceiling - Plaster/Drywall	Stair A (South East)	427	SF	6	10+ years	
	Floor - Terrazzo	Stair A (South East)	323	SF	6	10+ years	
	Handrails	Stair A (South East)	106	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair A (South East)	2	EA	7	6-10 years	
	Stairs - Terrazzo	Stair A (South East)	270	LF	6	10+ years	
	Walls - Masonry	Stair A (South East)	1,101	SF	7	10+ years	
	Walls - Plaster/Drywall	Stair A (South East)	1,101	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair B (North East)	427	SF	6	10+ years	
	Floor - Terrazzo	Stair B (North East)	323	SF	6	10+ years	
	Handrails	Stair B (North East)	106	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair B (North East)	2	EA	7	6-10 years	
	Stairs - Terrazzo	Stair B (North East)	270	LF	6	10+ years	
	Walls - Masonry	Stair B (North East)	1,101	SF	7	10+ years	
	Walls - Plaster/Drywall	Stair B (North East)	1,136	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair C (North West)	427	SF	6	10+ years	
	Floor - Terrazzo	Stair C (North West)	323	SF	6	10+ years	
	Handrails	Stair C (North West)	106	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair C (North West)	2	EA	7	6-10 years	
	Stairs - Terrazzo	Stair C (North West)	270	LF	6	10+ years	
	Walls - Masonry	Stair C (North West)	1,101	SF	7	10+ years	
	•	,	,			·	

Campus Name: Sayre Page : 25 of 29 Assessment Date: 01/09/2024



Category : Interior			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Stair C (North West)	1,101	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair D (South West)	427	SF	6	10+ years	
	Floor - Terrazzo	Stair D (South West)	323	SF	6	10+ years	
	Handrails	Stair D (South West)	106	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair D (South West)	2	EA	7	6-10 years	
	Stairs - Terrazzo	Stair D (South West)	270	LF	6	10+ years	
	Walls - Masonry	Stair D (South West)	1,101	SF	7	10+ years	
	Walls - Plaster/Drywall	Stair D (South West)	1,101	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West Stairs - North Side of Gym	786	SF	7	10+ years	
	Floor - Terrazzo	West Stairs - North Side of Gym	638	SF	7	10+ years	
	Handrails	West Stairs - North Side of Gym	76	LF	7	10+ years	
	Lighting - Pendent/Surface	West Stairs - North Side of Gym	10	EA	6	6-10 years	
	Lighting - Wall Mounted	West Stairs - North Side of Gym	2	EA	7	6-10 years	
	Stairs - Terrazzo	West Stairs - North Side of Gym	400	LF	7	10+ years	
	Walls - Masonry	West Stairs - North Side of Gym	2,804	SF	7	10+ years	
	Walls - Plaster/Drywall	West Stairs - North Side of Gym	1,774	SF	6	10+ years	
	Walls - Plaster/Drywall	West Stairs - North Side of Gym	30	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	West Stairs - South Side of Gym	786	SF	6	10+ years	
	Floor - Terrazzo	West Stairs - South Side of Gym	638	SF	7	10+ years	
	Handrails	West Stairs - South Side of Gym	76	LF	7	10+ years	
	Lighting - Pendent/Surface	West Stairs - South Side of Gym	10	EA	6	6-10 years	
	Lighting - Wall Mounted	West Stairs - South Side of Gym	2	EA	7	6-10 years	
	Stairs - Terrazzo	West Stairs - South Side of Gym	400	LF	7	10+ years	
	Walls - Masonry	West Stairs - South Side of Gym	804	SF	7	10+ years	
	Walls - Plaster/Drywall	West Stairs - South Side of Gym	824	SF	6	10+ years	
Vertical (Conveyance						
	Elevator - Hydraulic Elevator	NA	1	EA	6	10+ years	
	Wheelchair Lift - Platform Lift	NA	1	EA	7	10+ years	

Campus Name: Sayre Page : 26 of 29 Assessment Date: 01/09/2024





Category: Site Building: Site

Catego	ry : Site	В	uilding				
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ivil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	10+ years	
	Q					•	
encina							
J	Fencing - Chain Link	Entire Site	102	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	380	LF	7	10+ years	New
	Fencing - New Standard Ornamental	Entire Site	357	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	849	LF	4	0-1 year	Corroding fence
	Fencing - New Standard Ornamental	Entire Site	1	LF	4	0-1 year	Corroded corner post
andsca	pe Benches	Entire Site	6	EA	7	10+ years	
	Landscape - Grass	Entire Site	156,860	SF	6	10+ years 10+ years	
	Landscape - Grass Landscape - Hardscape- Asphalt	Entire Site	25	SF	4	1-2 years	Large cracks
	Landscape - Hardscape- Asphali Landscape - Hardscape- Concrete	Entire Site	3,480	SF	6	6-10 years	Large cracks
	Landscape - Hardscape- Concrete Landscape - Hardscape- Pavers	Entire Site	1,125	SF	6	10+ years	Verified dimension
	Landscape - Hardscape- Pavers	Entire Site	25	SF	4	1-2 years	Upheaved pavers
	Parkway trees	Entire Site	53	EA	6	10+ years	Opneaved pavers
	Planting Beds/ Area	Entire Site	2,955	SF	6	•	
				SF SF		10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	25,075		6	6-10 years	
	Retaining Wall - Concrete	Entire Site	459	SF	6	10+ years	O
	Retaining Wall - Concrete	Entire Site	3	SF	5	1-2 years	Cracked concrete with large gap
	Trash Receptacles	Entire Site	4	EA	6	10+ years	
Parking I	_ot						
	Interior Plantings	Entire Site	4	LF	6	10+ years	
	Surface - Asphalt	Entire Site	21,900	SF	7	10+ years	Verified dimension
	Surface - Asphalt	Entire Site	100	SF	4	1-2 years	Potholes, large cracks
	Surface - Concrete	Entire Site	560	SF	6	10+ years	
	Trash Enclosure - Chain Links	Entire Site	560	SF	5	10+ years	
	Vehicular Screening	Entire Site	100	LF	7	10+ years	
Playgrou	nd						
, 91.00	Equipment - Pre K 3-5	West	1	EA	7	10+ years	
	Equipment - School Age 5-12	West	1	EA	7	10+ years	
	Surface - Poured Surface	West	6,200	SF	7	10+ years	
			0,200	σ.	•	,	
Sidewalk						10	
	Sidewalks - Internal Walks Sidewalks - Internal Walks	Entire Site Entire Site	143	LF LF	6	10+ years 1-2 years	Upheaved, cracked, spalled
			10		4	4 0	Illiana accept and alliant and alliant

Campus Name: Sayre Page : 27 of 29 Assessment Date: 01/09/2024



Category : Site			В	uilding							
					Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Sidewalks - Perimeter Sidewalks	Entire Site	20,450	SF	6	10+ years					
	Sidewalks - Perimeter Sidewalks	Entire Site	150	SF	4	1-2 years	Upheaved, cracked				
Signage											
	Flag Pole - Flag Pole	East	1	EA	6	10+ years					
	Marquee - Free Standing Back Lighted	East	1	EΑ	6	10+ years					
	Monument - Building Mounted Cut Letter Sign	East	1	EA	6	10+ years					

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Sayre Page: 28 of 29 Assessment Date: 01/09/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Olassi odni odnimary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					\-\-				
Art Room	Pre School	1st Floor	103	103	802	260	30	Υ	N
Kindergarten	Pre School	1st Floor	104	104	1,353	197	18	Y	N
Kindergarten	Regular Classroom	1st Floor	102	102	728	143	15	Υ	N
Kindergarten	Science Classroom	1st Floor	108	108	944	287	18	Υ	N
Music Room	Regular Classroom	3rd Floor	300	300	740	143	15	Υ	Y
Office	Regular Classroom	3rd Floor	302	302	740	143	15	Υ	N
Pre School	Kindergarten	1st Floor	111	111	1,093	234	27	Υ	N
Regular Classroom	Regular Classroom	1st Floor	100	100	728	143	15	Υ	N
Regular Classroom	Regular Classroom	1st Floor	101	101	728	143	15	Υ	N
Regular Classroom	Regular Classroom	1st Floor	106	106	728	143	18	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	740	143	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	740	143	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	736	143	15	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	740	143	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	740	143	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	740	143	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	740	143	15	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	740	143	15	Υ	Y
Regular Classroom	Regular Classroom	3rd Floor	306	306	742	143	15	Υ	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	740	143	15	Υ	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	740	143	15	Υ	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	740	143	15	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	740	143	15	Υ	Y
Regular Classroom	Regular Classroom	3rd Floor	311	311	740	156	15	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	312	312	740	143	15	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	740	156	15	Υ	N
Science Classroom	Regular Classroom	3rd Floor	305	305	740	143	15	Υ	Υ