

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1961	2	36,887
Modular 1 (2-Classroom )	2003	1	2,100
Campus Total			38,987

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Entance 1	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entance 1	2	EΑ	7	10+ years	
	Exterior Doors - Transom Lite	Entance 1	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 2	2	EA	5	1-2 years	Corroded door and frames
	Exterior Stairs - Concrete	Entrance 2	4	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 3	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 3	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 3	6	LF	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 3.5	1	EA	4	1-2 years	Corroded door
	Exterior Doors - Exterior FRP Door	Entrance 4	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 4	1	EΑ	7	10+ years	
	Exterior Stairs - Concrete	Entrance 4	6	LF	3	0-1 year	Broken concrete, settlement
	Entrance Control - Audio and Video	Entrance 5	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 5	2	EA	6	10+ years	
	Exterior Doors - Side lite	Entrance 5	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 5	3	EA	7	10+ years	
	Power Door Operator and Controls	Entrance 5	1	EA	7	10+ years	
	Ramps - Concrete	Entrance 5	15	LF	6	6-10 years	
	Entrance Control - Audio and Video	Entrance 6	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 6	2	EA	7	6-10 years	
	Exterior Doors - Side lite	Entrance 6	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 6	6	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 7	1	EA	7	10+ years	
						•	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Side lite	Entrance 7	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 7	1	EΑ	7	10+ years	
	Exterior Stairs - Concrete	Entrance 7	4	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 8	1	EA	7	6-10 years	
	Exterior Doors - Transom Lite	Entrance 8	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Entrance 8	4	LF	5	1-2 years	Spalled, broken concrete
_Foundati	ion						
	Foundation - Concrete	Entire Building	825	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	36,887	SF	7	10+ years	Recombined quantities
_Lighting_							
	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	6-10 years	
_Roof Sys							
	Access Ladder - Metal	Roof 1_Main	1	EA	7	10+ years	
	Coping - Metal	Roof 1_Main	612	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 1_Main	100	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 1_Main	612	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 1_Main	14,595	SF	4	2-5 years	Blistering throughout
	Roof Hatch - Metal	Roof 1_Main	1	EΑ	5	2-5 years	Missing handle, broken lock
	Roof Structure - Concrete	Roof 1_Main	14,595	SF	7	10+ years	
	Coping - Metal	Roof 2_Lower SE	390	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 2_Lower SE	25	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 2_Lower SE	4,425	SF	4	2-5 years	Ponding, blistering throughout
	Roof Structure - Concrete	Roof 2_Lower SE	4,425	SF	7	10+ years	
	Chimney - Metal Flue	Roof 3 _Lower NW	20	LF	7	10+ years	
	Coping - Metal	Roof 3 _Lower NW	190	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 3 _Lower NW	25	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 3 _Lower NW	190	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 3 _Lower NW	4,668	SF	5	2-5 years	Blistering throughout
	Roof Structure - Concrete	Roof 3 _Lower NW	4,668	SF	7	10+ years	
	Coping - Metal	Roof 4_Lower N	22	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 4_Lower N	23	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 4_Lower N	327	SF	4	2-5 years	Blistering throughout, growing vegetation
	Roof Structure - Concrete	Roof 4_Lower N	327	SF	7	10+ years	- <b>3</b>
	Coping - Metal	Roof 5_Lowest N	70	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 5_Lowest N	25	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 5 Lowest N	70	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 5_Lowest N	350	SF	5	2-5 years	Blistering throughout, growing
	Roof Structure - Concrete	Roof 5_Lowest N	350	SF	7	10+ years	vegetation

Campus Name: Shoesmith Page : 2 of 27 Assessment Date: 01/29/2024



	ry : Exterior		В	uilding	: Main	_	
Froup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Valls							
	Canopy - Concrete/ Stucco	Entire Building	336	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	14,144	SF	5	10+ years	Deteriorating mortar throughout
	Exterior Walls - Brick	Entire Building	800	SF	4	1-2 years	Open joints
	Exterior Walls - Concrete Block	Entire Building	75	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,796	SF	6	10+ years	
indows	;						
	Curtain wall - Glazed Double Pane	Entire Building	310	SF	7	10+ years	
	Curtain wall - Insulated Panel	Entire Building	672	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	3,188	SF	7	10+ years	
	Guard - Guards wire guard	Entire Building	516	SF	7	10+ years	
	Storefront Windows	Entire Building	75	SF	7	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	3,670	SF	7	10+ years	
	Windows - Louver	Entire Building	75	SF	6	10+ years	Not previously assessed
	Windows - Sash Aluminum Double-pane	Entire Building	516	SF	7	10+ years	,
tego	ry : Electrical		В	uilding	: Main		
						Recommend	
oun	Item - Tyne	Location	Quantity	HOM	Rank	Renlacement	Comments
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Item - Type  Icy System  Exit Signs - Corridors and Stairs	Location  Entire Building	Quantity 8	<b>UOM</b> EA	Rank 6	Replacement 6-10 years	Exit signs appear to have battery
	ncy System						Exit signs appear to have battery backup Exit signs appear to have battery
	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV	Entire Building Entire Building Entire Building	8 3 36,887	EA	6	6-10 years	Exit signs appear to have battery backup
	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV  Security System - Intrusion Detection	Entire Building Entire Building Entire Building Entire Building	8 3	EA EA	6	6-10 years	Exit signs appear to have battery backup Exit signs appear to have battery
	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV  Security System - Intrusion Detection  Emergency Battery Packs - Corridors and	Entire Building Entire Building Entire Building	8 3 36,887	EA EA SF	6 6 6	6-10 years 6-10 years 6-10 years	Exit signs appear to have battery backup Exit signs appear to have battery
	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building	36,887 36,887 36,887 8	EA EA SF SF	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	Exit signs appear to have battery backup Exit signs appear to have battery
	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Entire Building Entire Building Entire Building Entire Building Entire Building	8 3 36,887 36,887	EA EA SF SF EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Exit signs appear to have battery backup Exit signs appear to have battery
	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	36,887 36,887 8	EA EA SF SF EA	6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Exit signs appear to have battery backup Exit signs appear to have battery
	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Students Toilets	Entire Building	36,887 36,887 36,887 8	EA EA SF SF EA EA	6 6 6 6 6	6-10 years	Exit signs appear to have battery backup Exit signs appear to have battery
nerger	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Students Toilets	Entire Building	8 36,887 36,887 8 2 4 5,694	EA SF SF EA EA SF	6 6 6 6 6 6	6-10 years	Exit signs appear to have battery backup Exit signs appear to have battery
roup merger	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Students Toilets	Entire Building	8 36,887 36,887 8 2 4 5,694	EA SF SF EA EA SF	6 6 6 6 6 6	6-10 years	Exit signs appear to have battery backup Exit signs appear to have battery
nerger	Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Students Toilets	Entire Building	8 36,887 36,887 8 2 4 5,694 1,570	EA SF SF EA EA SF SF	6 6 6 6 6 6 7	6-10 years	Exit signs appear to have battery backup Exit signs appear to have battery

Campus Name: Shoesmith Page : 3 of 27 Assessment Date: 01/29/2024



Cateno	ry : Electrical		D	uilding	· Main		<u> </u>
Salego	ry . Electrical		D	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
. Сар					1141111		
ower D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	LP-BR
	Lighting and Power Panels - 100 A	Entire Building	2	ΕA	7	10+ years	1-CP-2 MDF-1
	Lighting and Power Panels - 100 A	Entire Building	_ 1	ΕA	7	10+ years	EM Panel
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	7	10+ years	ACP1 ACP2
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	7	10+ years	1-CP-1 2-CP-1 2CP-2
	Lighting and Power Panels - Above 100 A	Entire Building	10	EΑ	7	10+ years	LP-1
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	7	10+ years	LP-T
	Lighting and Power Panels - Above 100 A  Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Original unlabeled 200A power pane
		· ·	·			•	behind boiler
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	Original vintage panels
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	CDP-1
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EΑ	7	10+ years	PP-4 ACP3
	Main Distribution Panels - Greater than 600	Entire Building	1	EΑ	6	10+ years	Switchboard panel, part of non live
	amp	S				•	front in boiler room, ampacity unknown
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	10+ years	1600A Part of service entrance, switchboard panel
atego	ry : Fire Protection		В	uilding	: Main		
	W		0			Recommend	•
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar							
	Fire ALarm Anunciator	Entire Building		EA	7	10+ years	
			1				
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	No fire alarm valves have been silenced
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	
			•				
`atego	Fire Alarm Panel  Fire Alarm Strobe Lights  Fire Alarm_System	Entire Building Entire Building	36,887 36,887	EA SF SF	7 7 6	6-10 years 6-10 years	
;atego	Fire Alarm Panel Fire Alarm Strobe Lights	Entire Building Entire Building	36,887 36,887	EA SF	7 7 6	6-10 years 6-10 years 6-10 years	
	Fire Alarm Panel  Fire Alarm Strobe Lights  Fire Alarm_System  ry: Mechanical	Entire Building Entire Building Entire Building	36,887 36,887 B	SF SF uilding	7 7 6 : <b>Main</b>	6-10 years 6-10 years 6-10 years Recommend	silenced
Froup	Fire Alarm Panel  Fire Alarm Strobe Lights Fire Alarm_System  ry: Mechanical  Item - Type	Entire Building Entire Building	36,887 36,887	EA SF SF	7 7 6	6-10 years 6-10 years 6-10 years	
Froup	Fire Alarm Panel  Fire Alarm Strobe Lights Fire Alarm_System  Ty: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less	Entire Building Entire Building Entire Building	36,887 36,887 B	SF SF uilding	7 7 6 : <b>Main</b>	6-10 years 6-10 years 6-10 years Recommend	silenced
Group	Fire Alarm Panel  Fire Alarm Strobe Lights Fire Alarm_System  ry: Mechanical  Item - Type  ditioning	Entire Building Entire Building Entire Building Location	36,887 36,887 B Quantity	SF SF uilding	7 7 6 : Main Rank	6-10 years 6-10 years 6-10 years Recommend Replacement	Comments
roup	Fire Alarm Panel  Fire Alarm Strobe Lights Fire Alarm_System  Ty: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder	Entire Building Entire Building Entire Building Location	36,887 36,887 B Quantity	SF SF uilding	7 7 6 : Main Rank	6-10 years 6-10 years 6-10 years  Recommend Replacement  6-10 years  10+ years	Comments
roup	Fire Alarm Panel  Fire Alarm Strobe Lights Fire Alarm_System  Ty: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less than 5 tons	Entire Building Entire Building Entire Building Location Roof	36,887 36,887 <b>B</b> <b>Quantity</b>	SF SF uilding UOM	7 7 6 : Main Rank	6-10 years 6-10 years 6-10 years  Recommend Replacement  6-10 years	Comments  Serves MDF room  Building operator has only been on site for a few months, no knowledge
Froup	Fire Alarm Panel  Fire Alarm Strobe Lights Fire Alarm_System  Ty: Mechanical  Item - Type  Stitioning  Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons	Entire Building Entire Building Entire Building  Location  Roof Site South Site South	1 36,887 36,887 <b>B</b> Quantity 1 1	EA SF SF uilding UOM EA EA EA	7 7 6 : Main Rank 6 6 5	6-10 years 6-10 years 6-10 years  Recommend Replacement  6-10 years  10+ years 6-10 years	Comments  Serves MDF room  Building operator has only been on site for a few months, no knowledge
Group	Fire Alarm Panel  Fire Alarm Strobe Lights Fire Alarm_System  Ty: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons  Glycol Feed	Entire Building Entire Building Entire Building  Location  Roof Site South Site South	1 36,887 36,887 <b>B</b> Quantity 1 1	EA SF SF uilding UOM EA EA EA	7 7 6 : Main Rank 6 6 5	6-10 years 6-10 years 6-10 years  Recommend Replacement  6-10 years 10+ years 6-10 years	Comments  Serves MDF room  Building operator has only been on site for a few months, no knowledge
Froup	Fire Alarm Panel  Fire Alarm Strobe Lights Fire Alarm_System  Ty: Mechanical  Item - Type  Stitioning  Condensing Unit- Roof Mounted - Less than 5 tons Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons	Entire Building Entire Building Entire Building  Location  Roof Site South Site South	1 36,887 36,887 <b>B</b> Quantity 1 1	EA SF SF uilding UOM EA EA EA	7 7 6 : Main Rank 6 6 5	6-10 years 6-10 years 6-10 years  Recommend Replacement  6-10 years  10+ years 6-10 years	Comments Serves MDF room



Catego	ry : Mechanical		В	uilding	: Main		
	<del></del>		0	11014		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
/ WI - HANNA	Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM	Electrical Room	2	EA	6	10+ years	
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 6000- 10000 cfm	Gym Mechanical Room	1	EA	6	6-10 years	
	Air Intake	Gym Mechanical Room	1	EA	6	10+ years	
Boiler Sy	vstems						
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	2	EA	7	10+ years	Units for this are incorrect in FACTS
	Chemical Pot Feeder	Boiler Room	1	EA	7	10+ years	
	Combustion Dampers	Boiler Room	2	EA	7	6-10 years	
	Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	4	6-10 years	Boiler one has significant corrosion on top of shell and curb platform
	Condensing- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	1	EA	6	10+ years	Both boilers are fully functional
	Glycol Feed System	Boiler Room	1	EA	7	10+ years	
Heating I	Devices						
J	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	4	EA	6	6-10 years	Boiler room, exhaust fan rooms, and air handler room
	Cabinet Heaters - With Hot Water Coil	Entire Building	10	EA	6	2-5 years	
	Fin Tube - Hot Water	Entire Building	320	LF	6	6-10 years	
	Wall Heater - Electric	Entire Building	1	EA	4	1-2 years	Non-functional with cover off at time of assessment
Mechani	cal Plumbing						
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	1	EA	7	10+ years	
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	1	EA	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years	
Tempera	iture Control						
•	DDC System	Entire Building	36,887	SF	7	10+ years	
	Electric Thermostat	Entire Building	6	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	16	EA	6	10+ years	Unit Ventilators on BAS control
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	17	EA	6	6-10 years	



Catego	ry : Mechanical		B	uilding	· Main		1330 E 30(1131KEE1, Chicago, 1E 00013
Outogo	i y : iniconamoui			ananig	. Waiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. опр			- Laurency			Tio piaco in cinc	
_Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	5	2-5 years	MDF
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	10	EA	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	6	2-5 years	
_Piping_							
	Domestic Piping-Hot Water Return Lines	Entire Building	36,887	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	36,887	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	36,887	SF	6	10+ years	
	Fixtures	-				-	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	37,887	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	36,887	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	36,887	SF	6	10+ years	
	Sanitary Piping	Entire Building	36,887	SF	6	10+ years	
	Storm Piping	Entire Building	36,887	SF	6	10+ years	
	Vent Piping	Entire Building	36,887	SF	6	10+ years	
	1 3	J	,			,	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years	
	Pumps - Sump-Duplex	Entire Building	1	EA	6	10+ years	
	Pumps - Sump-Simplex	under elevator	1	EA	7	10+ years	Not accessible



Category : Room			В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lminist	rative Suites/Offices						
	Ceiling - Lay-in	1st Floor-113 Teacher's Workroom	682	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-113 Teacher's Workroom	2	EA	7	10+ years	
	Floor - Tile	1st Floor-113 Teacher's Workroom	682	SF	7	10+ years	
	Lighting - Lay-in	1st Floor-113 Teacher's Workroom	8	ĒΑ	6	6-10 years	
	Power Distribution	1st Floor-113 Teacher's Workroom	8	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-113 Teacher's Workroom	915	SF	7	10+ years	
	AC Unit	1st Floor-Assistant Principal	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor-Assistant Principal	185	SF	6	2-5 years	
	Doors - Side-lite	1st Floor-Assistant Principal	150	SF	6	10+ years	
	Doors - Transom Window	1st Floor-Assistant Principal	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Assistant Principal	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor-Assistant Principal	185	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Assistant Principal	2	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Assistant Principal	2	EA	6	6-10 years	Re-lamp fixture
	Power Distribution	1st Floor-Assistant Principal	6	ΕA	6	10+ years	
	Storage/ Closet	1st Floor-Assistant Principal	25	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-Assistant Principal	185	SF	6	10+ years	
	AC Unit	1st Floor-Engineers Office	1	ĒΑ	7	6-10 years	
	Ceiling - Splined	1st Floor-Engineers Office	85	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor-Engineers Office	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor-Engineers Office	85	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Engineers Office	1	ĒΑ	7	6-10 years	
	Power Distribution	1st Floor-Engineers Office	8	ΕA	6	10+ years	
	Walls - Concrete Block	1st Floor-Engineers Office	409	SF	6	10+ years	
	Ceiling - Splined	1st Floor-Gym Office	75	SF	7	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor-Gym Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Gym Office	75	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Gym Office	1	ĒΑ	6	6-10 years	
	Power Distribution	1st Floor-Gym Office	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Gym Office	350	SF	7	10+ years	
	Ceiling - Splined	1st Floor-Interim Principal's Office	80	SF	7	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor-Interim Principal's Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Interim Principal's Office	80	SF	7	10+ years	
	Lighting - Lay-in	1st Floor-Interim Principal's Office	1	EA	6	6-10 years	
	Power Distribution	1st Floor-Interim Principal's Office	2	ΕA	7	10+ years	
	Storage/ Closet	1st Floor-Interim Principal's Office	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-Interim Principal's Office	390	SF	7	10+ years	
	AC Unit	1st Floor-Main Office	2	EA	7	2-5 years	
	Ceiling - Splined	1st Floor-Main Office	560	SF	7	2-5 years	
	Doors - Side-lite	1st Floor-Main Office	130	SF	7	10+ years	
	Doors - Transom Window	1st Floor-Main Office	6	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	1st Floor-Main Office	1	EA	7	10+ years	
				SF	7	. J. Jours	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor-Main Office	7	EA	6	6-10 years	
	Power Distribution	1st Floor-Main Office	12	EA	7	10+ years	
	Storage/ Closet	1st Floor-Main Office	5	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-Main Office	1,015	SF	7	10+ years	
	AC Unit	1st Floor-Principal's Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Principal's Office	2	SF	5	1-2 years	Water damage
	Ceiling - Splined	1st Floor-Principal's Office	218	SF	7	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Principal's Office	220	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Principal's Office	5	EA	6	6-10 years	
	Power Distribution	1st Floor-Principal's Office	8	EA	7	10+ years	
	Storage/ Closet	1st Floor-Principal's Office	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-Principal's Office	388	SF	7	10+ years	
	AC Unit	1st Floor-Tutor's Office	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor-Tutor's Office	135	SF	7	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor-Tutor's Office	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Tutor's Office	135	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Tutor's Office	1	EA	6	6-10 years	
	Power Distribution	1st Floor-Tutor's Office	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Tutor's Office	225	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Tutor's Office	120	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor Area of Rescue	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Area of Rescue	1	EA	7	10+ years	
	Floor - Tile	2nd Floor Area of Rescue	72	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor Area of Rescue	1	EA	7	6-10 years	
	Power Distribution	2nd Floor Area of Rescue	4	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor Area of Rescue	97	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor Area of Rescue	5	SF	6	10+ years	Mortar cracks in corner
	Ceiling - Splined	Lunchroom Office	194	SF	6	10+ years	
	Doors - Side-lite	Lunchroom Office	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Lunchroom Office	2	ĒΑ	6	10+ years	
	Floor - Tile	Lunchroom Office	194	SF	6	10+ years	
	Lighting - Pendent/Surface	Lunchroom Office	4	ĒΑ	7	6-10 years	Quantity updated
	Lighting - Pendent/Surface	Lunchroom Office	1	EA	6	6-10 years	Re-lamp fixture
	Power Distribution	Lunchroom Office	6	EA	6	10+ years	
	Walls - Concrete Block	Lunchroom Office	524	SF	6	10+ years	
						,	
Green H	••••						
	Finishes	Site Northwest	425	SF	5	2-5 years	Not previously assessed
	Glazing	Site Northwest	1,100	SF	6	2-5 years	Not previously assessed
Gvmnas	ia						
Суппаз	Ceiling - Splined	1st Floor	3,771	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	7	EA	6	10+ years	
			,		Ŭ	,	

Campus Name: Shoesmith Page: 8 of 27 Assessment Date: 01/29/2024



Categor	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	110	SF	6	10+ years	
	Floor - Wood	1st Floor	3,771	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	1	EA	6	10+ years	Relamp
	Lighting - Pendent/Surface	1st Floor	23	EA	7	10+ years	Replaced
	Lighting - Pendent/Surface	1st Floor	1	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	435	SF	6	10+ years	
	Stage Curtain	1st Floor	6	EA	7	10+ years	
	Stage Lighting System	1st Floor	2	EA	7	6-10 years	
	Stage-Stairs - Tile	1st Floor	54	LF	6	10+ years	
	Storage/ Closet	1st Floor	365	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	5,513	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	558	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	558	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Serving Line	1st Floor	16	LF	6	10+ years	
	Storage/ Closet	1st Floor	85	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	245	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	545	SF	6	10+ years	
_Lunch &	Multipurpose Room						
	AC Unit	1st Floor	2	EA	7	6-10 years	
	AC Unit	1st Floor	3	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,260	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,251	SF	6	10+ years	
	Floor - Tile	1st Floor	9	SF	5	0-1 year	Cracks in tiles at entrance
	Lighting - Lay-in	1st Floor	35	ĒΑ	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,182	SF	7	10+ years	
_MDF_IDF	=						
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	132	SF	5	10+ years	Some water damage to ceiling
	Other Cooling Unit	2nd Floor	1	ĒΑ	7	6-10 years	Computer room cooling unit
Mechanic	cal/ Service Rooms						
	Boiler Room	1st Floor	855	SF	7	10+ years	Rank updated to match current observations
	Janitor's Closet	1st Floor	36	SF	5	10+ years	OD2EL AGUOLI2
	Mechanical/ Service Rooms	1st Floor	40	SF	5	10+ years	
			.0	٠.	J	,	

Campus Name: Shoesmith Page : 9 of 27 Assessment Date: 01/29/2024



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	1st Floor	110	SF	5	10+ years	
	Storage Room	1st Floor	35	SF	5	10+ years	
	Storage Room	1st Floor	135	SF	5	10+ years	Water damage
	Vaults	1st Floor	35	SF	7	10+ years	Not previously assessed
	Janitor's Closet	2nd Floor	36	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	220	SF	7	10+ years	
stroor	n						
	Accessories	1st Floor- Unisex Restroom by 101	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor- Unisex Restroom by 101	21	SF	7	10+ years	Type changed to match current observations
	Ceiling - Plaster/Drywall	1st Floor- Unisex Restroom by 101	4	SF	5	10+ years	Water damage
	Doors - Wood Doors inclu hw	1st Floor- Unisex Restroom by 101	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor- Unisex Restroom by 101	25	SF	7	10+ years	
	Floor Drain	1st Floor- Unisex Restroom by 101	1	EA	7	10+ years	
	Hand Dryer	1st Floor- Unisex Restroom by 101	1	EA	7	6-10 years	
	Lavatory	1st Floor- Unisex Restroom by 101	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor- Unisex Restroom by 101	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor- Unisex Restroom by 101	50	SF	7	•	
	Walls - Flaster/Drywaii Walls - Tile Ceramic/ Porcelain	1st Floor- Unisex Restroom by 101	150	SF	7	10+ years	
	Water Closet					10+ years	
		1st Floor- Unisex Restroom by 101	1	EA	7	10+ years	
	Accessories	1st Floor-100 Kindergarten Restroom	25	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-100 Kindergarten Restroom	21	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-100 Kindergarten Restroom	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-100 Kindergarten Restroom	1	EA	7	10+ years	
	Floor - Tile	1st Floor-100 Kindergarten Restroom	25	SF	7	10+ years	
	Lavatory	1st Floor-100 Kindergarten Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-100 Kindergarten Restroom	1	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor-100 Kindergarten Restroom	175	SF	7	10+ years	
	Water Closet	1st Floor-100 Kindergarten Restroom	1	EA	7	10+ years	
	Accessories	1st Floor-Assistant Principal Office	25	SF	7	6-10 years	
	Ceiling - Splined	1st Floor-Assistant Principal Office	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Assistant Principal Office	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Assistant Principal Office	25	SF	6	10+ years	
		1st Floor-Assistant Principal Office	1	EA	6	•	
	Lavatory	13t Floor-Assistant Fillicipal Office	ı	LA	U	10+ years	

Campus Name: Shoesmith Page : 10 of 27 Assessment Date: 01/29/2024



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Wall Mounted	1st Floor-Assistant Principal Office	1	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor-Assistant Principal Office	200	SF	6	10+ years	
	Water Closet	1st Floor-Assistant Principal Office	1	EA	6	10+ years	
	Accessories	1st Floor-Boiler Room	18	SF	7	6-10 years	
	Ceiling - Splined	1st Floor-Boiler Room	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Boiler Room	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Boiler Room	18	SF	6	10+ years	
	Lavatory	1st Floor-Boiler Room	1	EA	6	10+ years	
	Lighting - Wall Mounted	1st Floor-Boiler Room	1	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor-Boiler Room	110	SF	6	10+ years	
	Water Closet	1st Floor-Boiler Room	1	EA	7	6-10 years	
	Accessories	1st Floor-Boy's Restroom	225	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom	225	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	225	SF	7	10+ years	
	Floor Drain	1st Floor-Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Boy's Restroom	2	EA	7	6-10 years	
	Lavatory	1st Floor-Boy's Restroom	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Boy's Restroom	7	EA	7	10+ years	
	Partitions	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Urinals	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Boy's Restroom	40	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	500	SF	7	10+ years	
	Water Closet	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Accessories	1st Floor-Girl's Restroom	210	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Girl's Restroom	210	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom	210	SF	7	10+ years	
	Floor Drain	1st Floor-Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Girl's Restroom	2	EΑ	7	10+ years	
	Lavatory	1st Floor-Girl's Restroom	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Girl's Restroom	7	EA	7	10+ years	
	Partitions	1st Floor-Girl's Restroom	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Girl's Restroom	30	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom	500	SF	7	10+ years	
	Water Closet	1st Floor-Girl's Restroom	4	EA	7	10+ years	
	Accessories	1st Floor-Kitchen	48	SF	7	6-10 years	
	Ceiling - Splined	1st Floor-Kitchen	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Kitchen	1	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor-Kitchen	38	SF	6	10+ years	
	Floor - Tile Quarry	1st Floor-Kitchen	10	SF	5	0-1 year	Cracked tiles
	Lavatory	1st Floor-Kitchen	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Kitchen	1	EA	7	6-10 years	
	Partitions	1st Floor-Kitchen	1	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor-Kitchen	4	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Kitchen	319	SF	6	10+ years	

Campus Name: Shoesmith Page : 11 of 27 Assessment Date: 01/29/2024



Category : Room		В	uilding	: Main			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor-Kitchen	1	EA	6	10+ years	
	Accessories	1st Floor-Lunch room office	20	SF	7	6-10 years	
	Ceiling - Splined	1st Floor-Lunch room office	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Lunch room office	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Lunch room office	20	SF	6	10+ years	
	Lavatory	1st Floor-Lunch room office	1	EA	6	10+ years	
	Lighting - Wall Mounted	1st Floor-Lunch room office	1	EA	5	6-10 years	
	Walls - Concrete Block	1st Floor-Lunch room office	160	SF	6	10+ years	
	Water Closet	1st Floor-Lunch room office	1	EA	6	10+ years	
	Accessories	1st Floor-Mens Restroom	60	SF	7	6-10 years	
	Ceiling - Splined	1st Floor-Mens Restroom	60	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor-Mens Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Mens Restroom	60	SF	6	10+ years	
	Lavatory	1st Floor-Mens Restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Mens Restroom	1	EA	6	6-10 years	
	Partitions	1st Floor-Mens Restroom	1	EA	7	10+ years	
	Urinals	1st Floor-Mens Restroom	1	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Mens Restroom	160	SF	6	10+ years	
	Water Closet	1st Floor-Mens Restroom	1	EA	6	10+ years	
	Accessories	1st Floor-Principal's Office Restroom	25	SF	7	6-10 years	
	Ceiling - Splined	1st Floor-Principal's Office Restroom	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Principal's Office Restroom	25	SF	7	10+ years	
	Lavatory	1st Floor-Principal's Office Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Principal's Office Restroom	1	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor-Principal's Office Restroom	200	SF	7	10+ years	
	Water Closet	1st Floor-Principal's Office Restroom	1	ĒΑ	7	10+ years	
	Accessories	1st Floor-Women's Staff Restroom	60	SF	7	6-10 years	
	Ceiling - Splined	1st Floor-Women's Staff Restroom	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Women's Staff Restroom	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor-Women's Staff Restroom	60	SF	6	10+ years	
	Floor Drain	1st Floor-Women's Staff Restroom	1	ĒΑ	7	10+ years	
	Lavatory	1st Floor-Women's Staff Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Women's Staff Restroom	1	EA	5	6-10 years	
	Partitions	1st Floor-Women's Staff Restroom	2	EΑ	5	10+ years	
	Walls - Concrete Block	1st Floor-Women's Staff Restroom	330	SF	7	10+ years	
	Water Closet	1st Floor-Women's Staff Restroom	2	EA	7	10+ years	
	Accessories	2nd Floor-Boy's Restroom	225	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Boy's Restroom	225	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Boy's Restroom	1	EA	7	10+ years	
	Floor - Tile Quarry	2nd Floor-Boy's Restroom	225	SF	6	10+ years	
	Floor Drain	2nd Floor-Boy's Restroom	1	EA	7	10+ years	
	Lavatory	2nd Floor-Boy's Restroom	5	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor-Boy's Restroom	4	EA	7	6-10 years	
	Lighting Lay in	2.10 1 1001 20 9 0 11001100111	7	L, (	•	J 10 yours	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd Floor-Boy's Restroom	2	EA	7	10+ years	
	Urinals	2nd Floor-Boy's Restroom	4	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor-Boy's Restroom	535	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor-Boy's Restroom	5	SF	5	10+ years	Broken plaster
	Water Closet	2nd Floor-Boy's Restroom	2	EA	7	10+ years	
	Accessories	2nd Floor-Girl's Restroom	210	SF	7	6-10 years	
	Ceiling - Splined	2nd Floor-Girl's Restroom	210	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Girl's Restroom	1	EA	7	10+ years	
	Floor - Tile Quarry	2nd Floor-Girl's Restroom	210	SF	6	10+ years	
	Floor Drain	2nd Floor-Girl's Restroom	1	EA	7	10+ years	
	Lavatory	2nd Floor-Girl's Restroom	5	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor-Girl's Restroom	4	EA	7	6-10 years	
	Partitions	2nd Floor-Girl's Restroom	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor-Girl's Restroom	530	SF	7	10+ years	
	Water Closet	2nd Floor-Girl's Restroom	5	EA	7	10+ years	
	Accessories	2nd Floor-Staff Unisex Restroom	65	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor-Staff Unisex Restroom	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Staff Unisex Restroom	1	EA	7	10+ years	
	Floor - Tile	2nd Floor-Staff Unisex Restroom	65	SF	6	10+ years	
	Floor Drain	2nd Floor-Staff Unisex Restroom	1	EA	7	10+ years	
	Hand Dryer	2nd Floor-Staff Unisex Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-Staff Unisex Restroom	1	EA	5	10+ years	Continually dripping
	Lighting - Lay-in	2nd Floor-Staff Unisex Restroom	1	EA	7	6-10 years	· · · · · · ·
	Walls - Concrete Block	2nd Floor-Staff Unisex Restroom	295	SF	7	10+ years	
	Water Closet	2nd Floor-Staff Unisex Restroom	1	EA	6	10+ years	

Category : Classroom **Building: Main** 

						Recommena	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #100 (Kindergarten)						
	Casework	1st Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,140	SF	7	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,140	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	45	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,300	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	10	SF	6	10+ years	Peeling paint
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #102 (Special Program)						
	Casework	1st Floor	20	LF	7	10+ years	

Campus Name: Shoesmith Page : 13 of 27 Assessment Date: 01/29/2024



Catego	ry : Classroom		В	uilding			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	1st Floor	430	SF	7	2-5 years	
	Doors - Side-lite	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	430	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	655	SF	7	10+ years	
Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Splined	1st Floor	820	SF	6	2-5 years	
	Ceiling - Splined	1st Floor	10	SF	5	1-2 years	Water damage
	Doors - Transom Window	1st Floor	62	SF	6	10+ years	vvater damage
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	830	SF	6		
						10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	970	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Splined	1st Floor	790	SF	6	2-5 years	
	Ceiling - Splined	1st Floor	40	SF	5	0-1 year	Water damage
	Doors - Transom Window	1st Floor	62	SF	6	10+ years	•
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	970	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #105 (Regular Classroom)						
	Casework	1st Floor	26	LF	7	10+ years	
	Casework Ceiling - Splined	1st Floor	830	SF	6	2-5 years	
	Doors - Transom Window	1st Floor	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor		SF	6		
			830		_	10+ years	
	Lighting - Pendent/Surface	1st Floor	19	EΑ	6	6-10 years	De James fixture
	Lighting - Pendent/Surface Marker Board	1st Floor 1st Floor	1 20	EA LF	6 7	6-10 years 6-10 years	Re-lamp fixture



Category : Classroom		В	uilding	: Main			
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	970	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Splined	1st Floor	830	SF	6	2-5 years	
	Doors - Transom Window	1st Floor	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	970	SF	6	10+ years	
Classroo	om #107 (Regular Classroom)						
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Splined	1st Floor	810	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	20	SF	5	0-1 year	Water damaged
	Doors - Transom Window	1st Floor	62	SF	6	10+ years	water damaged
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	970	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
01	#400 (D I. Ol )						
Classroc	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Splined	1st Floor	820	SF	6	10+ years	
	Ceiling - Splined	1st Floor	10	SF	5	1-2 years	Water damage
	Doors - Transom Window	1st Floor	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	970	SF	6	10+ years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	406	SF	6	2-5 years	
	Ceiling - Splined	1st Floor	38	SF	5	0-1 year	Water damage



	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	445	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	5	6-10 years	Refurbish light fixture assemblies
	Marker Board	1st Floor	25	LF	7	6-10 years	-
	Walls - Concrete Block	1st Floor	645	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	80	SF	6	10+ years	
Classroc	om #200 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	800	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	800	SF	6	10+ years	
		2nd Floor	19	EA	7	•	
	Lighting - Pendent/Surface					6-10 years	Dalama
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	Relamp
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	890	SF	7	10+ years	
lassroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	830	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	970	SF	7	10+ years	
Classroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	830	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor		SF	6		
			830	_	_	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	970	SF	7	10+ years	
Classroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	830	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	830	SF	6	10+ years	

Campus Name: Shoesmith Page : 16 of 27 Assessment Date: 01/29/2024



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	Relamp
	Marker Board	2nd Floor	20	LF	6	6-10 years	·
	Walls - Concrete Block	2nd Floor	970	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
_Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	830	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	
	Lighting - Pendent/Surface  Lighting - Pendent/Surface	2nd Floor	19	EA	6		
				LF	_	6-10 years	
	Marker Board	2nd Floor	20		6	6-10 years	
	Walls - Concrete Block	2nd Floor	970	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #206 (Science Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	830	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EΑ	7	10+ years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	970	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #207 (Regular Classroom)						
	Casework	2nd Floor	28	LF	6	10+ years	
	Casework Ceiling - Splined	2nd Floor	820	SF	6	2-5 years	
	Ceiling - Splined	2nd Floor	10	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	water damage
	Floor - Tile	2nd Floor 2nd Floor	830	SF	6		
						10+ years	
	Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor	20 20	EA LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor 2nd Floor	970	SF	6 7	6-10 years 10+ years	
	vvalis - Colletete block	2110 I 1001	970	J.	,	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	830	SF	6	2-5 years	



Category : Classroom

# Beulah Shoesmith Elementary School 1330 E 50th STREET, Chicago, IL 60615

Group	Item - Type	Location	Quantity	UOM	Pank	Replacement	Comments
Joup	Doors - Wood Doors inclu hw	2nd Floor	Quantity 1	EA	Rank 7	10+ years	Comments
	Floor - Tile	2nd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA		6-10 years	
	Marker Board	2nd Floor 2nd Floor	20	LF	7 6		
				SF		6-10 years	
	Walls - Concrete Block	2nd Floor	970	5F	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	570	SF	6	10+ years	
	Ceiling - Splined	1st Floor	3,382	SF	6	10+ years	
	Doors - Side-lite	1st Floor	30	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	1	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,882	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	9	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	61	ΕA	6	6-10 years	
	Rescue Panel	1st Floor	1	ΕA	7	6-10 years	
	Walls - Concrete Block	1st Floor	7,060	SF	6	10+ years	
	Walls - Masonry	1st Floor	250	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	106	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	179	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,443	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	1,440	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,482	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	100	SF	5	1-2 years	Cracking
		2nd Floor		EA			Cracking
	Lighting - Lay-in	2nd Floor 2nd Floor	3	EA EA	7 7	6-10 years	
	Lighting - Pendent/Surface		22			6-10 years	Doom is used for store as as all-
	Rescue Panel	2nd Floor	1	EA	7	6-10 years	Room is used for storage and is inaccessible.
	Walls - Concrete Block	2nd Floor	2,910	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	10	SF	5	1-2 years	Cracking
	Walls - Masonry	2nd Floor	8	SF	7	10+ years	•
Safety							
Saicty	Camera Viewing Station	Entire Building	2	EA	7	10+ years	
	Security Cameras	Entire Building	4	EΑ	7	6-10 years	
	Security Cameras	Entire Building	6	EA	7	6-10 years	Previously deleted

**Building: Main** 

Recommend

Campus Name: Shoesmith Page: 18 of 27 Assessment Date: 01/29/2024



Catego	Category : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Stairs							
	Ceiling - Splined	East - adjacent to entrance 5	200	SF	6	10+ years	
	Floor - Tile	East - adjacent to entrance 5	70	SF	6	10+ years	
	Handrails	East - adjacent to entrance 5	45	LF	7	10+ years	
	Lighting - Lay-in	East - adjacent to entrance 5	2	EA	6	6-10 years	Relamp
	Lighting - Wall Mounted	East - adjacent to entrance 5	1	EA	7	6-10 years	
	Stairs - Rubber	East - adjacent to entrance 5	80	LF	6	10+ years	
	Stairs - Rubber	East - adjacent to entrance 5	20	LF	5	1-2 years	Tread cap damaged
	Walls - Concrete Block	East - adjacent to entrance 5	464	SF	7	10+ years	
	Ceiling - Lay-in	North	135	SF	7	10+ years	
	Floor - Tile	North	50	SF	7	10+ years	
	Handrails	North	30	LF	7	10+ years	
	Handrails	North	25	LF	5	1-2 years	End of handrail attachment is loose
	Lighting - Lay-in	North	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	North	1	EA	7	6-10 years	
	Stairs - Rubber	North	100	LF	6	10+ years	
	Walls - Concrete Block	North	225	SF	7	10+ years	
	Walls - Masonry	North	225	SF	7	10+ years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	North	1	EA	7	10+ years	





Category: Exterior Building: Modular 1 (2-Classroom) Recommend Location Replacement Comments Item - Type Quantity **UOM** Group Rank Entrance FΑ Exterior Doors - Exterior FRP Door Entrance 1 1 6 10+ years LF 7 Exterior Stairs - Steel or Aluminum Entrance 1 10 10+ years LF 7 Ramp Handrail - Steel\_Ramp Handrail Entrance 1 102 10+ years Ramps - Steel or Aluminum Entrance 1 50 LF 7 10+ years ΙF Stair Handrail - Steel Stair Handrail Entrance 1 7 10+ years Exterior Doors - Exterior Steel Door Entrance 2 1 EΑ 6 10+ years Exterior Stairs - Steel or Aluminum Entrance 2 6 LF 7 10+ years Stair Handrail - Steel Stair Handrail Entrance 2 14 LF 7 10+ years Exterior Doors - Exterior FRP Door Entrance 3 1 EΑ 6 10+ years Exterior Stairs - Steel or Aluminum LF 7 Entrance 3 6 10+ years 1 F Stair Handrail - Steel Stair Handrail Entrance 3 14 10+ years Foundation LF 7 Foundation - Concrete **Entire Building** 188 10+ years No exposed foundation Superstructure - Steel SF 7 **Entire Building** 2.100 No exposed superstructure 10+ years \_Lighting 2 FΑ Exterior Lighting - Wall Mounted **Entire Building** 6 10+ years Roof System Downspouts - Exterior Downspouts **Entire Building** 140 LF 6 10+ years LF **Downspouts - Exterior Downspouts** 5 **Entire Building** 26 0-1 year Disconnected downspout Roof - Metal Entire Building SF Corroded, metal roof, with open 2,100 4 0-1 year seams. Active leaks throughout. Roof Structure - Steel / Metal Deck/ 2,100 SF 7 10+ years **Entire Building** Concrete Topping Walls Exterior Walls - Stucco **Entire Building** SF 376 4 1-2 years Broken, damaged, stucco. Torn. SF Exterior Walls - Wood Siding **Entire Building** 1.479 1-2 years Rotted wood, damaged, trim Windows SF 6 Guard - Guards wire guard **Entire Building** 150 6-10 years Windows - Sash Aluminum Double-pane **Entire Building** 150 SF 6 6-10 years Category: Electrical Building: Modular 1 (2-Classroom) Recommend Location Replacement Comments Group Item - Type Quantity **UOM** Rank Emergency System Exit Signs - Corridors and Stairs 1st Floor 5 FΑ 6 6-10 years

Campus Name: Shoesmith Page: 20 of 27 Assessment Date: 01/29/2024



MY S							1330 E 50th STREET, Chicago, IL 60615			
Catego	ry : Electrical		Building : Modular 1 (2-Classroom )							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Emergency Battery Packs - Corridors and	1st Floor	4	EA	6	6-10 years				
	Stairs	4 . =			•	0.40				
	Emergency Battery Packs - Students Toilets	1st Floor	2	EA	6	6-10 years	Futurian COTV			
	Security System - CCTV	Entire Building		SF SF	7	10+ years	Exterior CCTV camera			
	Security System - Intrusion Detection	Entire Building	2,100	51	6	6-10 years				
Main Se	rvice									
	Main Electrical Service - 800 A and	exterior wall	1	EA	6	10+ years				
	120/208/3PH					•				
Power D	istribution									
Ower D	Lighting and Power Panels - 100 A	1st Floor	2	EA	6	10+ years				
Catama	w. Fire Dretection		D	به ما امان د	. Madul	or 1 (2 Classes				
Catego	ry : Fire Protection		Building : Modular 1 (2-Classroo			oom )				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
•	System	Location	Quantity	COM	Italik	Replacement	Comments			
Spilikiei	Sprinkler Heads	1st Floor	2,100	SF	7	10+ years				
	Sprinkler Piping	1st Floor	2,100	SF	7	10+ years				
	Wet Sprinkler System	1st Floor	2,100	SF	, 5	0-1 year	Fire sprinkler system was noted as			
	vet opiniker dystem	13(1)001	2,100	OI.	3	o i year	non-functional at time of last assessment.			
Catego	ry : Mechanical		В	uildina	: Modul	ar 1 (2-Classro	oom )			
	.,		_			Recommend	,			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Tempera	ature Control									
'	Electric Thermostat	1st Floor	2	EA	6	6-10 years				
Unit Ven										
	Unit Ventilators - Vertical Package Electric	Exterior Wall	1	EA	7	10+ years				
	Heat & Self Contained Cooling	Fastonian Mall	4	Ε.	_	10				
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	1	EA	5	10+ years				
/entilatio	on									
	Exhaust Fans- Roof Mounted - Less than	Roof	2	EA	5	6-10 years	Roof to modular, inaccessible at time			
	500 CFM				-	<b>,</b>	of assessment.			



Catego	ry : Plumbing		В	uilding	: Modul	ar 1 (2-Classro	oom )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Electric Heater - Less than 20 KW	1st Floor	1	EA	4	1-2 years	
Piping	Demostic Dining Hat Water from Discus to	4 at [] a a v	2.400			40	
	Domestic Piping-Hot Water from Risers to Fixtures	1st Floor	2,100	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	1st Floor	2,100	SF	6	10+ years	
	(Horizontal Lines)		_,	О.	· ·	.o. you.o	
	Domestic Piping-Hot/Cold Water Supply	1st Floor	2,100	SF	6	10+ years	
	(from Risers to Fixtures)	. <u>_</u> .					
	Sanitary Piping	1st Floor	2,100	SF	6	10+ years	
	Storm Piping	1st Floor	2,100	SF	6	10+ years	
Catego	ry : Classroom		В	uildina	: Modul	ar 1 (2-Classro	oom )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #M1 (Music Room)						
	Ceiling - Plaster/Drywall	1st Floor	630	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	5	10+ years	Water damage, bucket for catching water
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	water
	Floor - Tile	1st Floor	585	SF	6	6-10 years	
	Floor - Tile	1st Floor	60	SF	5	1-2 years	Cracking tiles
	Lighting - Pendent/Surface	1st Floor	20	EΑ	7	6-10 years	•
	Marker Board	1st Floor	14	LF	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	690	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	10	SF	5	2-5 years	Water damage
Claceroo	om #M2 (Art Room)						
Classioo	Ceiling - Plaster/Drywall	1st Floor	610	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	5	SF	6	10+ years	Hole through plaster from previous
	, ,		-	_	-	, , , , , ,	installation
	Ceiling - Plaster/Drywall	1st Floor	5	SF	6	10+ years	Painted
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	570	SF	6	6-10 years	
	Floor - Tile	1st Floor	50	SF	5	1-2 years	Cracking
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	-
	Marker Board	1st Floor	14	LF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	866	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	10	SF	5	10+ years	Damage
Catego	ry : Room		D	uildina	· Modul	ar 1 (2-Classro	nom )
	Item - Type	Location	Quantity	UOM		Recommend	•
Jioup	item - Type	Location	Quantity	UUIVI	Kalik	Recommend	Comments



					Replacement	
cal/ Service Rooms						
Janitor's Closet	1st Floor	30	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	26	SF	7	10+ years	
m						
Accessories	1st Floor-Staff Restroom near Counseling Office	50	SF	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor-Staff Restroom near Counseling Office	50	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor-Staff Restroom near Counseling Office	1	EA	6	10+ years	
Floor - Tile/Sheet	1st Floor-Staff Restroom near Counseling Office	50	SF	7	10+ years	
Lavatory	1st Floor-Staff Restroom near Counseling Office	1	EA	6	10+ years	
Lighting - Pendent/Surface	1st Floor-Staff Restroom near Counseling Office	1	EA	7	6-10 years	
Walls - Vinyl Coated Gypsum Panel	1st Floor-Staff Restroom near Counseling Office	226	SF	6	10+ years	
Water Closet	1st Floor-Staff Restroom near Counseling Office	1	EA	6	10+ years	
Accessories	1st Floor-Unisex near Art room	50	SF	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor-Unisex near Art room	50	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor-Unisex near Art room	1	EA	7	10+ years	
Floor - Tile/Sheet	1st Floor-Unisex near Art room	50	SF	7	10+ years	
Lavatory	1st Floor-Unisex near Art room	1	EA	6	10+ years	
Lighting - Pendent/Surface	1st Floor-Unisex near Art room	1	EA	7	6-10 years	
Walls - Vinyl Coated Gypsum Panel	1st Floor-Unisex near Art room	226	SF	6	10+ years	
Water Closet	1st Floor-Unisex near Art room	1	EA	6	10+ years	

**Category: Interior Building: Modular 1 (2-Classroom)** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	,,		•			•	
	Ceiling - Exposed	1st Floor	80	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	80	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	140	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	50	SF	4	0-1 year	Water damage leading to sagging and torn finishes
Safety							
	Security Cameras	Building exterior	2	EA	5	0-1 year	Doesn't appear to work



Building : Modular 1 (2-Classroom )
Recommend Category : Interior

Replacement Comments Group Item - Type Location Quantity UOM Rank

Campus Name: Shoesmith Page : 24 of 27 Assessment Date: 01/29/2024





Category: Site Building: Site

Category : Site		В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	6	10+ years	Engineer asserted that site is draining
		<b>-</b>	_		_		properly
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	7	10+ years	
<b></b>							
Fencing	Facility Obside Link	Fatina Cita	000			40	
	Fencing - Chain Link	Entire Site	290	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	115	LF	7	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	0	LF	6	2-5 years	
Landsca	pe						
	Benches	Entire Site	20	EA	6	6-10 years	
	Landscape - Grass	Entire Site	27,681	SF	7	10+ years	
	Landscape - Grass	Entire Site	1,600	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	9,500	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	1,900	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	1,029	SF	7	10+ years	
	Parkway trees	Entire Site	26	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	9,082	SF	7	6-10 years	
	Planting Beds/ Area	Entire Site	100	SF	4	0-1 year	Rotted wood containers
	Play Area - Hardscape- Asphalt	Entire Site	2,000	SF	7	10+ years	Reconfigured and replaced with new
	Tray Area Transcape Asphan	Entire Oile	2,000	Oi.	,	101 years	playground and planting containers
Parking	Lot						
9	Concrete Curbs	S Parking Lot	201	LF	7	10+ years	
	Concrete Curbs	S Parking Lot	476	LF	6	10+ years	
	Concrete Curbs	S Parking Lot	5	LF	5	1-2 years	Broken curb
	Interior Plantings	S Parking Lot	70	LF	7	6-10 years	
	Lighting - Lighting	S Parking Lot	4	EA	6	6-10 years	
	Surface - Asphalt	S Parking Lot	88,287	SF	6	10+ years	
	Surface - Asphalt	S Parking Lot	600	SF	5	1-2 years	Alligatored surface, potholes
	Trash Enclosure - Chain Links	S Parking Lot	544	SF	6	10+ years	,gatorea carrace, peniere
	Vehicular Screening	S Parking Lot	70	LF	7	10+ years	
Playgrou		N.D.				40	
	Equipment - School Age 5-12	N Playground	1	EA	7	10+ years	
	Surface - Poured Surface	N Playground	3,575	SF	7	10+ years	
Sidewall	(S						
	Sidewalks - Internal Walks	Entire Site	481	LF	7	10+ years	
						·	

Campus Name: Shoesmith Page : 25 of 27 Assessment Date: 01/29/2024



Category : Site			Building : Site				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	951	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	65	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	35	LF	4	0-1 year	Sunken settled, broken concrete
	Sidewalks - Perimeter Sidewalks	Entire Site	3,857	SF	7	10+ years	
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Shoesmith Page: 26 of 27 Assessment Date: 01/29/2024

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-	
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board	
Building : Main								•		
Kindergarten	Kindergarten	1st Floor	100	100	1,140	175	35	N	Υ	
Regular Classroom	Faculty Lounge	1st Floor	109		445	72	12	N	N	
Regular Classroom	Regular Classroom	1st Floor	103	103	830	120	24	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	104	104	830	120	24	N	Y	
Regular Classroom	Regular Classroom	1st Floor	105	105	830	120	24	N	Y	
Regular Classroom	Regular Classroom	1st Floor	106	106	830	120	24	N	Y	
Regular Classroom	Regular Classroom	1st Floor	107	107	830	120	24	N	Y	
Regular Classroom	Regular Classroom	1st Floor	108	108	830	120	24	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	200	200	800	160	36	N	N	
Regular Classroom	Regular Classroom	2nd Floor	202	202	830	160	36	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	203	206	830	160	36	N	N	
Regular Classroom	Regular Classroom	2nd Floor	204	204	830	160	36	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	205	205	830	160	36	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	207	207	830	160	36	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	208	208	830	160	36	N	Υ	
Science Classroom	Regular Classroom	2nd Floor	206	203	830	160	36	N	Y	
Special Program	Special Education	1st Floor	102	Adj. Serv.	430	110	36	N	N	
Building : Modular 1 (2-Classroom )										
Art Room	Regular Classroom	1st Floor	M2	-	620	54	27			
Music Room	Regular Classroom	1st Floor	M1	-	645	54	27	N	N	