

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1963	3	52,920
Campus Total			52,920

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1 - Main entrance SE	1	EA	7	10+ years	
	Exterior Doors - Store Front	#1 - Main entrance SE	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - Main entrance SE	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 - Main entrance SE	55	LF	6	10+ years	
	Exterior Stairs - Concrete	#1 - Main entrance SE	20	LF	5	1-2 years	Cracked concrete stairs and landing
	Power Door Operator and Controls	#1 - Main entrance SE	1	EΑ	7	10+ years	Repaired
	Ramp Handrail - Steel_Ramp Handrail	#1 - Main entrance SE	98	LF	6	6-10 years	·
	Ramps - Concrete	#1 - Main entrance SE	45	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 - Main entrance SE	15	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#2 - SE	1	EΑ	5	1-2 years	Rotting trim and frame
	Exterior Stairs - Concrete	#2 - SE	4	LF	7	10+ years	· ·
	Exterior Stairs - Stone	#2 - SE	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#3 - S	1	EΑ	5	1-2 years	Rotting trim and frame
	Exterior Stairs - Concrete	#3 - S	6	LF	7	10+ years	· ·
	Exterior Stairs - Stone	#3 - S	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 - SW	1	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#4 - SW	1	EA	6	10+ years	
	Ramps - Concrete	#4 - SW	100	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#4 - SW	8	LF	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#5 - SW	1	EA	4	1-2 years	Rotted trim and frame, wood door with corroded sheet metal face
	Exterior Stairs - Concrete	#5 - SW	6	LF	5	1-2 years	Cracked broken concrete with corroded rebar
	Exterior Stairs - Stone	#5 - SW	3	LF	7	10+ years	



Catego	Category : Exterior		Building : Main				·	
				Ŭ		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	Entrance Control - Audio and Video	#6 - W	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	#6 - W	2	EA	5	1-2 years	Corroded	
	Exterior Doors - Side lite	#6 - W	2	EΑ	5	1-2 years	Corroded	
	Power Door Operator and Controls	#6 - W	1	EΑ	7	10+ years	Concaca	
	Exterior Doors - Exterior Steel Door	#6.5 - yard storage - W	2	EA	4	1-2 years	Corroded door and frame	
	Ramps - Concrete	#6.5 - yard storage - W	6	LF	6	10+ years	Corroded door and frame	
	•	, ,	1		4		Varified that door frame in in fair	
	Exterior Doors - Exterior Wood Door	#7 - Boiler room - W	1	EA	4	1-2 years	Verified that door frame is in fair condition. Wood trim is rotting, door is delaminating	
	Exterior Doors - Transom Lite	#7 - Boiler room - W	1	EA	6	10+ years	G	
	Exterior Stairs - Concrete	#7 - Boiler room - W	6	LF	4	1-2 years	Broken concrete with exposed rebar, corrosion	
	Exterior Stairs - Stone	#7 - Boiler room - W	3	LF	6	10+ years		
	Entrance Control - Audio and Video	#8 - NE	1	EA	6	10+ years		
	Exterior Doors - Exterior FRP Door	#8 - NE	2	EΑ	6	6-10 years		
	Exterior Doors - Transom Lite	#8 - NE	2	EΑ	6	6-10 years		
	Ramps - Concrete	#8 - NE	8	LF	7	10+ years		
	Exterior Doors - Exterior Wood Door	#9 roof access door at gymnasium	1	EA	6	10+ years		
	Exterior Boors - Exterior Wood Boor	#3 1001 access door at gyrinasidiri	'	LA	U	10+ years		
Foundati								
	Foundation - Concrete	Entire Building	878	LF	7	10+ years		
	Foundation - Concrete	Entire Building	4	LF	5	1-2 years	Spalled, cracked off	
	Superstructure - Concrete	Entire Building	52,920	SF	7	10+ years		
Lighting								
0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	7	EA	6	6-10 years		
	Exterior Lighting - Wall Mounted	Entire Building	19	ΕA	6	6-10 years		
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	0-1 year	Head of lamp is detached from the body. Exposed wires	
Roof Sys	stem							
	Coping - Metal	Low NW roof	25	LF	6	6-10 years		
	Downspouts - Exterior Downspouts	Low NW roof	12	LF	6	6-10 years		
	Roof - Modified Bitumen	Low NW roof	148	SF	6	6-10 years		
	Roof Structure - Steel / Metal Deck/	Low NW roof	148	SF	7	10+ years		
	Concrete Topping					•		
	Access Ladder - Metal	Low SW roof	1	EA	7	10+ years		
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Low SW roof	5	LF	5	10+ years		
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Low SW roof	25	LF	2	0-1 year	Leaning top, loose bricks, open joints. Spalling and breaking-falling onto roof below	
	Chimney - Metal Flue	Low SW roof	15	LF	7		DOIOW	

Campus Name: Tanner Page : 2 of 30 Assessment Date: 05/09/2024



Catego	ry : Exterior		В	uilding	: Main		7000 0 Evans Avervoe, Omoago, 12 00010
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Metal	Low SW roof	289	LF	5	2-5 years	
	Downspouts - Interior Downspouts	Low SW roof	24	LF	5	6-10 years	
	Roof - Modified Bitumen	Low SW roof	6,088	SF	4	1-2 years	Open seams, blistering, ponding, soft spots, worn surface throughout
	Roof Structure - Concrete	Low SW roof	6,088	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	5	1-2 years	Corroded
	Coping - Metal	Main Roof	500	LF	6	10+ years	
	Coping - Metal	Main Roof	50	LF	5	2-5 years	Bent coping
	Downspouts - Interior Downspouts	Main Roof	140	LF	5	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	40	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	13,804	SF	4	1-2 years	Open seams, blistering, ponding, soft spots, worn surface throughout
	Roof Hatch - Metal	Main Roof	2	EA	3	1-2 years	Corroded
	Roof Structure - Concrete	Main Roof	13,528	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	276	SF	7	10+ years	
	Access Ladder - Metal	Mid S roof	1	EA	5	1-2 years	Corroded
	Coping - Metal	Mid S roof	260	LF	6	6-10 years	
	Coping - Metal	Mid S roof	10	LF	5	1-2 years	Bent, torn coping
	Downspouts - Interior Downspouts	Mid S roof	72	LF	5	6-10 years	
	Roof - Modified Bitumen	Mid S roof	5,838	SF	4	1-2 years	Open seams, blistering, ponding, soft spots, worn surface throughout
	Roof Structure - Concrete	Mid S roof	5,838	SF	7	10+ years	
_Walls							
	Canopy - Concrete/ Stucco	Entire Building	2,835	SF	5	6-10 years	
	Canopy - Concrete/ Stucco	Entire Building	169	SF	4	6-10 years	Cracked, broken corroding rebar
	Canopy - Metal	Entire Building	34	SF	6	1-2 years	Drywall damaged
	Exterior Walls - Brick	Entire Building	234	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	21,222	SF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	2,000	SF	5	10+ years	0 11 1
	Exterior Walls - Brick	Entire Building	200	SF	4	1-2 years	Spalled, open joints
_Window:							
	Curtain wall - Insulated Panel	Entire Building	432	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	96	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	3,071	SF	6	6-10 years	
	Lintels - Steel	Entire Building	840	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,209	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	414	SF	6	10+ years	

Campus Name: Tanner Page: 3 of 30 Assessment Date: 05/09/2024



Catego	Category : Electrical				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	4	1-2 years	Vintage, loud, not reliable, original to building
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,483	SF	6	6-10 years	·
	Emergency A/C Power - Gym	Entire Building	3,562	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,935	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,120	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	5	EΑ	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	6	6-10 years	Quantity updated to reflect observed conditions
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	1	EA	6	0-1 year	Not illuminated, quantity segregated
	Exit olgilo - Euriciilooni	Little building	'	LA	O	0-1 year	and updated to reflect observed conditions and quantities
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	Quantity segregated to reflect observe conditions
	Security System - CCTV	Entire Building	52,920	SF	5	1-2 years	No security cameras currently function since data system was updated.
	Security System - Intrusion Detection	Entire Building	52,920	SF	5	2-5 years	apaatoa.
Main Se	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	4	2-5 years	Original transfer switch beyond service life
	Main Electrical Service - 1000 A 120/208/3PH	Electrical Room	1	EA	4	1-2 years	Corroded, vintage, original to the building
	PA System	Entire Building	52,920	SF	6	2-5 years	•
Power D	istribution						
	Lighting and Power Panels - 100 A	Boiler Room, 1st & 2nd Floor, Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - 100 A	Boiler Room, 1st & 2nd Floor, Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Boiler Room, 1st & 2nd Floor, Entire Building	1	EA	4	0-1 year	EM fuse panel in main entrance with empty fuse socket presents live front condition.
	Lighting and Power Panels - 100 A	Boiler Room, 1st & 2nd Floor, Entire Building	1	EA	4	0-1 year	Room 307. Missing breaker presents live front condition.



ectrical		В	uilding	: Main		
			_		Recommend	
- Type	Location	Quantity	UOM	Rank	Replacement	Comments
ng and Power Panels - Above 100 A	Boiler Room, 1st & 2nd Floor, Entire Building	4	EA	6	6-10 years	
ng and Power Panels - Above 100 A	Boiler Room, 1st & 2nd Floor, Entire	7	EA	6	2-5 years	Vintage panels in corridors
ng and Power Panels - Above 100 A	Building Boiler Room, 1st & 2nd Floor, Entire	1	EA	4	0-1 year	Outside room 102 Missing breaker
Distribution Panels - 400 - 600 amp	Building Boiler Room, 1st & 2nd Floor, Entire Building	1	EA	6	10+ years	presents live condition
re Protection		В	uilding	: Main		
					Recommend	
- Type	Location	Quantity	UOM	Rank	Replacement	Comments
7.		-			•	
Larm Anunciator	Electrical Room	1	EA	6	10+ years	
Narm Panel	Electrical Room	1	EA	6	6-10 years	
	Electrical Room	•	SF	-		
Alarm Strobe Lights		52,920		6	6-10 years	
alarm_System	Electrical Room	52,920	SF	6	6-10 years	
echanical		В	uilding	: Main		
			_		Recommend	
- Туре	Location	Quantity	UOM	Rank	Replacement	Comments
stems					•	
r Return Fans- Centrifugal Squirrel - 5000 - 10000 CFM	Entire Building	1	EA	6	6-10 years	Item moved from ventilation exhaus fans, indoor to air handling systems return fans
andling Unit- Package Multi Zone-	Mechanical Room and Roof	1	EA	5	6-10 years	Serves gym and offices
r- Steam Coils - 15001-20000 cfm	Wednamear Room and Room	•	LA	3	0-10 years	Serves gym and onices
take	Mechanical Room and Roof	4	EA	6	6-10 years	
		1				Managel damage
Dampers	Mechanical Room and Roof	5	EA	6	6-10 years	Manual dampers
Auxiliary- Scotch Marine- Steam Low sure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	2-5 years	
nical Feed System	Boiler Room	1	EA	5	6-10 years	
nical Feeder	Boiler Room	1	EΑ	6	6-10 years	
pustion Dampers	Boiler Room	2	EA	6	6-10 years	
•	Boiler Room	2		5	2-5 years	
ensate Pump			EΑ		•	To see al for along difficult with
Water Pumps and Tank	Boiler Room	1	EA	4	0-1 year	Tagged for demolition with replacement of steam boilers for ne hot water system
Condensing- Fire Tube- Scotch Marine- n- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	2-5 years	B-2 scheduled for removal.
n Traps	Boiler Poom	12	FΔ	3	0-1 year	Tag for demolition with replacemen
	Boiler - 76 - 100 HP					Boiler - 76 - 100 HP Boiler Room 12 EA 3 0-1 year

Campus Name: Tanner Page : 5 of 30 Assessment Date: 05/09/2024



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							of steam boiler for new hot water
							boiler system
	Boiler Auxiliary- Condensing Hot Water - 2001 - 3000 HP	Boiler Room	2	EA	7	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	7	10+ years	
	Condensing- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	7	10+ years	Installed new in April 2024
	Glycol Feed System	Boiler Room	1	EA	7	10+ years	System will be manually fed
	Hot Water Pump	Boiler Room	2	EA	7	10+ years	,
	Piping - Dual Temperature Pipes- Steel	Boiler Room	40	LF	7	10+ years	
	Water Fill System	Boiler Room	1	EA	7	10+ years	
Heat Ex	changers						
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	1	EA	4	0-1 year	Original to the building, obsolete, all piping tagged green has been marked for demolition with installation of new hot water boilers.
Heating							
	Fin Tube - Steam	Entire Building	13	LF	5	2-5 years	Not included in previous assessment
	Cabinet Heaters - With Steam Coil	Entire Building	14	EA	5	6-10 years	Quantity updated to reflect observed conditions
	Wall Heater - Electric	Entire Building	4	EA	7	10+ years	
	Wall Heater - Electric	Entire Building	5	EA	5	2-5 years	
Mechani	ical Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Condensate-Steel or Galvanized	Entire Building	400	LF	4	0-1 year	Original to the building, obsolete, all piping has been tagged green, marked for demolition with installation of new hot water boilers.
	Hydronic Supply and Return - Steel	Entire Building	400	LF	4	0-1 year	Original to the building, obsolete, all piping tagged green has been marked for demolition with installation of new hot water boilers.
Tempera	ature Control						
	Pneumatic System	Entire Building	52,920	SF	4	0-1 year	Temperature control is not possible with existing controls, full system replacement scheduled for summer of 2024 with new boilers and pumps already on site.

Campus Name: Tanner Page : 6 of 30 Assessment Date: 05/09/2024



Henry O Tanner Elementary School 7350 S Evans AVENUE, Chicago, IL 60619

booster pump system and hot water

heaters

XY S	Schools						7350 S Evans AVENUE, Chicago, IL 6061
Catego	ry : Mechanical		В	uilding	: Main		
2roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Froup	Thermostats - Pneumatic	Entire Building	39	EA	6	6-10 years	Comments
	Thermostats - Pneumatic	Entire Building	6	EA	4	0-1 year	Devices removed
	o	g	· ·	`	•	o . you.	20110001011101
nit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	32	EA	5	2-5 years	
	. Isaamig cene cinj						
entilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Pre-K classroom
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Kitchen hood fan not included in previous assessment
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	2-5 years	Quantity updated to reflect observer conditions
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	2-5 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	3	0-1 year	Vintage, obsolete
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	5	2-5 years	Serves elevator shaft
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression system present
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	Previously served dishwasher, obsolete.
atego	ry : Plumbing		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	7	6-10 years	Two new water heaters installed in 2023
Piping							
-ping	Domestic Piping-Hot Water Return Lines	Entire Building	52,920	SF	6	10+ years	Domestic water pipes replaced new with 2023 installation of duplex booster pump system and hot wate
	Domestic Piping-Hot Water Return Risers	Entire Building	52,920	SF	6	10+ years	heaters Domestic water pipes replaced new
		=9	3_,3_0	٠.	· ·	,	with 2023 installation of duplex booster pump system and hot wate
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	52,920	SF	6	10+ years	heaters Domestic water pipes replaced new with 2023 installation of duplex
							hooster numn system and hot water

Campus Name: Tanner Page : 7 of 30 Assessment Date: 05/09/2024



Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	52,920	SF	6	10+ years	Domestic water pipes replaced new with 2023 installation of duplex booster pump system and hot water heaters
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	52,920	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	52,920	SF	6	10+ years	Domestic water pipes replaced new with 2023 installation of duplex booster pump system and hot water heaters
	Sanitary Piping	Entire Building	52,920	SF	6	6-10 years	
	Storm Piping	Entire Building	52,920	SF	6	6-10 years	
	Vent Piping	Entire Building	52,920	SF	6	6-10 years	
Pumps							
_	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	7	10+ years	Installed new in 2023
	Pumps - Sump-Duplex	Boiler Room	1	EA	6	6-10 years	Elevator pit pump not accessible at time of assessment

Category: Room **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	114A -Nurse's Office	225	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114A -Nurse's Office	3	EΑ	7	10+ years	
	Floor - Tile	114A -Nurse's Office	225	SF	7	10+ years	
	Lighting - Pendent/Surface	114A -Nurse's Office	3	EA	7	6-10 years	
	Power Distribution	114A -Nurse's Office	6	EA	7	10+ years	
	Storage/ Closet	114A -Nurse's Office	60	SF	7	10+ years	
	Walls - Concrete Block	114A -Nurse's Office	600	SF	7	10+ years	
	AC Unit	1st flr #102	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr #102	365	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr #102	1	EΑ	7	10+ years	
	Floor - Tile	1st flr #102	365	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr #102	8	EA	7	6-10 years	
	Power Distribution	1st flr #102	6	EA	7	10+ years	
	Walls - Concrete Block	1st flr #102	720	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st flr #114 Teacher Lounge	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr #114 Teacher Lounge	1	EA	7	10+ years	
	Floor - Tile	1st flr #114 Teacher Lounge	300	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr #114 Teacher Lounge	6	EA	7	6-10 years	
	Lighting - Wall Mounted	1st flr #114 Teacher Lounge	1	EA	7	6-10 years	
	Power Distribution	1st flr #114 Teacher Lounge	6	EA	7	10+ years	
	Walls - Concrete Block	1st flr #114 Teacher Lounge	560	SF	7	10+ years	
		-				,	

Campus Name: Tanner Page : 8 of 30 Assessment Date: 05/09/2024



Catego	ry : Room		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work SInk	1st flr #114 Teacher Lounge	1	EA	7	10+ years	
	AC Unit	1st flr Office 104A	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr Office 104A	235	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr Office 104A	1	EA	7	10+ years	
	Floor - Tile	1st flr Office 104A	235	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr Office 104A	4	EA	7	6-10 years	
	Power Distribution	1st flr Office 104A	6	EA	7	10+ years	
	Walls - Concrete Block	1st flr Office 104A	560	SF	7	10+ years	
	AC Unit	Basement engineer's office (boiler	1	EA	7	6-10 years	
	710 Onit	room)		L/ \	'	o to years	
	Ceiling - Plaster/Drywall	Basement engineer's office (boiler	121	SF	7	10+ years	
	Celling - Flaster/Drywali	· · · · · · · · · · · · · · · · · · ·	121	SF	,	10+ years	
	Deere Meed Deere include:	room)	4	Ε.	7	40	
	Doors - Wood Doors inclu hw	Basement engineer's office (boiler	1	EA	7	10+ years	
	E. T.	room)	404	0.5	_	4.0	
	Floor - Tile	Basement engineer's office (boiler	121	SF	7	10+ years	
		room)			_		
	Lighting - Pendent/Surface	Basement engineer's office (boiler	1	EA	7	6-10 years	
		room)					
	Power Distribution	Basement engineer's office (boiler	6	EA	7	10+ years	
		room)					
	Storage/ Closet	Basement engineer's office (boiler	15	SF	7	10+ years	
		room)					
	Walls - Concrete Block	Basement engineer's office (boiler	396	SF	7	10+ years	
		room)				•	
	AC Unit	Guidance Counselor's Office Room	1	EA	7	6-10 years	
		201A 2nd floor				- · · · · · · · · · · · · · · · · · · ·	
	Ceiling - Plaster/Drywall	Guidance Counselor's Office Room	312	SF	6	10+ years	
	coming induction bry wan	201A 2nd floor	0.2	0.	Ŭ	ioi youro	
	Doors - Wood Doors inclu hw	Guidance Counselor's Office Room	1	EA	6	10+ years	
	Doors - Wood Doors mold nw	201A 2nd floor	'	LA	U	10+ years	
	Floor - Tile	Guidance Counselor's Office Room	312	SF	6	10 L Vooro	
	Floor - Tile		312	SF	O	10+ years	
	Lighting Dandout/Confees	201A 2nd floor	4	Ε.	7	40	
	Lighting - Pendent/Surface	Guidance Counselor's Office Room	4	EA	7	10+ years	
	B. Branco	201A 2nd floor			_	4.0	
	Power Distribution	Guidance Counselor's Office Room	6	EA	7	10+ years	
		201A 2nd floor					
	Walls - Concrete Block	Guidance Counselor's Office Room	737	SF	6	10+ years	
		201A 2nd floor					
	Ceiling - Plaster/Drywall	Gym Office used as storage	91	SF	7	10+ years	
	Doors - Steel Doors incl hw	Gym Office used as storage	1	EA	7	10+ years	
	Floor - Tile	Gym Office used as storage	91	SF	7	10+ years	
	Lighting - Lay-in	Gym Office used as storage	1	EA	7	6-10 years	
	Power Distribution	Gym Office used as storage	2	EA	7	10+ years	
	Walls - Concrete Block	Gym Office used as storage	176	SF	7	10+ years	
		,		-		- ,	



Catego	ry : Room		В	uilding	: Main	•	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Kitchen Manager's Office	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Manager's Office	1	EA	7	10+ years	
	Floor - Tile	Kitchen Manager's Office	45	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen Manager's Office	1	EA	7	6-10 years	
	Power Distribution	Kitchen Manager's Office	2	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Manager's Office	98	SF	7	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	379	SF	7	10+ years	
	Doors - Side-lite	Main Office	28	SF	7	10+ years	
	Doors - Transom Window	Main Office	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years	
	Floor - Tile	Main Office	379	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office	6	EA	7	6-10 years	
	Power Distribution	Main Office	8	EA	7	10+ years	
	Storage/ Closet	Main Office	75	SF	7	10+ years	
	Walls - Concrete Block	Main Office	726	SF	7	10+ years	
	AC Unit	Office in Room 310	1	ĒΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	Office in Room 310	780	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office in Room 310	1	EA	6	10+ years	
	Floor - Tile	Office in Room 310	780	SF	6	10+ years	
	Lighting - Pendent/Surface	Office in Room 310	16	EΑ	7	10+ years	
	Power Distribution	Office in Room 310	12	EA	7	10+ years	
	Storage/ Closet	Office in Room 310	100	SF	7	10+ years	Updated square footage to match
	Storago, Glosot	Since in recoin ore	100	O.	•	io. youro	current observations
	Walls - Concrete Block	Office in Room 310	996	SF	6	10+ years	
	AC Unit	Office, Room 112A	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Office, Room 112A	189	SF	7	10+ vears	
	Doors - Wood Doors inclu hw	Office, Room 112A	1	EA	7	10+ years	
	Floor - Tile	Office, Room 112A	189	SF	7	10+ years	
	Lighting - Pendent/Surface	Office, Room 112A	6	EA	7	6-10 years	
	Power Distribution	Office, Room 112A	4	EA	7	10+ years	
	Walls - Concrete Block	Office, Room 112A	326	SF	7	10+ years	
	AC Unit	Room 100A Assistant Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 100A Assistant Principal's Office	162	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 100A Assistant Principal's Office	1	EA	7	10+ years	
	Floor - Tile	Room 100A Assistant Principal's Office	162	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 100A Assistant Principal's Office	2	EA	7	6-10 years	
	Power Distribution	Room 100A Assistant Principal's Office	6	EA	7	10+ years	

Campus Name: Tanner Page : 10 of 30 Assessment Date: 05/09/2024



Catego	ry : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Concrete Block	Room 100A Assistant Principal's Office	474	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Room 100B, Office, formerly restroom	40	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Room 100B, Office, formerly restroom	1	EA	7	10+ years			
	Floor - Tile	Room 100B, Office, formerly restroom	40	SF	7	10+ years			
	Lighting - Pendent/Surface	Room 100B, Office, formerly restroom	1	EA	7	6-10 years			
	Power Distribution	Room 100B, Office, formerly restroom	4	EA	7	10+ years			
	Walls - Concrete Block	Room 100B, Office, formerly restroom	98	SF	7	10+ years			
_Gymnasi	ia								
-	Ceiling - Plaster/Drywall	1st Floor	3,562	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years			
	Floor - Tile	1st Floor	3,562	SF	7	10+ years			
	Lighting - Metal Halide/Sodium Vapor	1st Floor	36	EA	7	6-10 years			
	Scoreboards	1st Floor	1	EΑ	7	6-10 years			
	Sound System	1st Floor	1	EA	7	6-10 years			
	Stage	1st Floor	638	SF	7	10+ years			
	Stage Curtain	1st Floor	2	EA	7	10+ years			
	Stage Lift	1st Floor	1	EA	7	10+ years			
	Stage Lighting System	1st Floor	1	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor	2,231	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	2,231	SF	7	10+ years			
_Kitchen									
	Ceiling - Plaster/Drywall	Room 110	1,014	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Room 110	2	EA	7	10+ years			
	Floor - Tile	Room 110	1,014	SF	6	10+ years			
	Lighting - Pendent/Surface	Room 110	17	EA	7	6-10 years			
	Serving Line	Room 110	18	LF	7	10+ years			
	Storage/ Closet	Room 110	97	SF	7	10+ years			
	Walls - Concrete Block	Room 110	846	SF	6	10+ years			
	Walls - Structural Glazed Tile	Room 110	1,128	SF	6	10+ years			
_Locker/S	Shower Room								
	Accessories	Basement inside boiler room	98	SF	7	6-10 years			
	Ceiling - Exposed	Basement inside boiler room	98	SF	7	6-10 years	Ceiling removed, type updated to match current observations		

Campus Name: Tanner Page : 11 of 30 Assessment Date: 05/09/2024



Category : Room		uilding	: Main				
				Recommend			
Type Location	Quantity	UOM	Rank	Replacement	Comments		
Wood Doors inclu hw Basement inside boiler room		EA	7	10+ years			
Concrete Epoxy/ Painted Basement inside boiler room		SF	7	10+ years			
ry Basement inside boiler room		EΑ	7	10+ years			
g - Pendent/Surface Basement inside boiler room	2	EΑ	7	6-10 years			
ns Basement inside boiler room	1	EΑ	7	10+ years			
t Lockers - One Tier Basement inside boiler room	3	EΑ	7	10+ years			
- Concrete Block Basement inside boiler room	360	SF	7	10+ years			
Closet Basement inside boiler room	1	EA	7	10+ years			
oose Room							
t 1st floor Room 111	3	EA	7	6-10 years			
- Plaster/Drywall 1st floor Room 111	2,935	SF	7	10+ years			
- Wood Doors inclu hw 1st floor Room 111	2,000	EA	7	10+ years			
Tile 1st floor Room 111	2,935	SF	7	10+ years			
g - Pendent/Surface 1st floor Room 111	60	EA	7	6-10 years			
Concrete Block 1st floor Room 111	3,984	SF	7	10+ years			
Concrete Block 15t 11001 K00111 111	3,904	SI	,	10+ years			
- Wood Doors inclu hw Room 201B 2nd floor	1	EA	6	10+ years			
Room 201B 2nd floor	96	SF	7	10+ years	Updated to match current observations		
v AC Unit Room 201B 2nd floor	1	EA	7	6-10 years			
ice Rooms							
Space - Unfinished 1st Floor	9,892	SF	7	10+ years			
s Closet 1st Floor	36	SF	5	10+ years	Rank updated to match current		
				, , , , ,	observations		
e Room 1st Floor	93	SF	7	10+ years	Quantity updated to match current observations		
1st Floor	79	SF	7	10+ years	obcorvations		
's Closet 2nd Floor	47	SF	5	10+ years	Water damage to ceiling around ligh		
3 Ološet 2110 i 1001	71	Oi	3	10+ years	fixture		
e Room 2nd Floor	55	SF	7	10+ years	iixtaro		
's Closet 3rd Floor	47	SF	7	10+ years			
e Room 3rd Floor	55	SF	7	10+ years			
Room Basement	1,028	SF	5		Rank updated to match current		
	,			10+ years	observations		
Space - Unfinished Basement	24,500	SF	7	10+ years			
nical/ Service Rooms Basement	309	SF	7	10+ years	Quantity updated to match current observations		
e Room Basement	89	SF	7	10+ years			
e Room	Basement	Basement 89	Basement 89 SF	Basement 89 SF 7	Basement 89 SF 7 10+ years		

Campus Name: Tanner Page: 12 of 30 Assessment Date: 05/09/2024



Category : Room		-	В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	220	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	220	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	546	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Water Closet	1st Floor	1	EA	3	0-1 year	Removed
	Accessories	1st Floor	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	220	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	220	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	546	SF	7	10+ years	
	Water Closet	1st Floor	6	EA	7	10+ years	
	Accessories	1st flr inside 104 women's	77	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr inside 104 women's	77	SF	6	6-10 years	Deficiency included in rank
	Doors - Wood Doors inclu hw	1st flr inside 104 women's	1	EA	7	10+ years	
	Floor - Tile	1st flr inside 104 women's	77	SF	7	10+ years	
	Lavatory	1st flr inside 104 women's	1	EA	7	6-10 years	Deficiency fixed
	Lighting - Pendent/Surface	1st flr inside 104 women's	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st flr inside 104 women's	1	EA	6	2-5 years	
	Partitions	1st flr inside 104 women's	2	EA	7	10+ years	
	Walls - Concrete Block	1st flr inside 104 women's	324	SF	7	10+ years	
	Water Closet	1st flr inside 104 women's	2	EA	7	10+ years	
	Accessories	1st flr inside 114 office women	53	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr inside 114 office women	53	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside 114 office women	1	EA	7	10+ years	
	Floor - Tile	1st flr inside 114 office women	53	SF	7	10+ years	
	Lavatory	1st flr inside 114 office women	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr inside 114 office women	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st flr inside 114 office women	1	EA	6	2-5 years	
	Walls - Concrete Block	1st flr inside 114 office women	288	SF	6	10+ years	
	Water Closet	1st flr inside 114 office women	1	ĒΑ	6	10+ years	
	Accessories	1st flr men's restroom in main lobby	103	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr men's restroom in main lobby	103	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr men's restroom in main lobby	1	ĒA	7	10+ years	

Campus Name: Tanner Page: 13 of 30 Assessment Date: 05/09/2024



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	1st flr men's restroom in main lobby	103	SF	7	10+ years	
	Lavatory	1st flr men's restroom in main lobby	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface Urinals	1st flr men's restroom in main lobby 1st flr men's restroom in main lobby	2 2	EA EA	7 7	6-10 years 10+ years	Quantity updated to match current
		·				•	observations
	Walls - Structural Glazed Tile	1st flr men's restroom in main lobby	376	SF	7	10+ years	
	Water Closet	1st flr men's restroom in main lobby	1	EA	7	10+ years	
	Accessories	1st flr next to children's restrooms, men's	37	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr next to children's restrooms, men's	37	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr next to children's restrooms, men's	1	EA	7	10+ years	
	Floor - Tile	1st flr next to children's restrooms, men's	37	SF	7	10+ years	
	Lavatory	1st flr next to children's restrooms, men's	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr next to children's restrooms, men's	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st flr next to children's restrooms, men's	1	EA	6	2-5 years	
	Partitions	1st flr next to children's restrooms, men's	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st flr next to children's restrooms, men's	216	SF	7	10+ years	
	Water Closet	1st flr next to children's restrooms, men's	1	EA	7	10+ years	
	Accessories	1st flr women's restroom in main lobby	113	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr women's restroom in main lobby	113	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr women's restroom in main lobby	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr women's restroom in main lobby	113	SF	7	10+ years	
	Lavatory	1st flr women's restroom in main lobby	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr women's restroom in main lobby	2	EA	7	6-10 years	
	Lighting - Wall Mounted	1st flr women's restroom in main lobby	2	EA	6	6-10 years	
	Partitions	1st flr women's restroom in main lobby	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st flr women's restroom in main	396	SF	7	10+ years	

Campus Name: Tanner Page: 14 of 30 Assessment Date: 05/09/2024



Catego	ry : Room	Building : Main								
_						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Mater Class	lobby	4	- ^	7	40				
	Water Closet	1st flr women's restroom in main	1	EA	7	10+ years				
	Accessories	lobby 2nd Floor	220	SF	7	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	220	SF	6	10+ years	Updated to match current			
	Ceiling - Plaster/Drywaii	2110 F1001	220	SF	O	10+ years	observations			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	observations			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	220	SF	6	10+ years				
	Floor Drain	2nd Floor	1	EA	7	10+ years				
	Hand Dryer	2nd Floor	1	EA	7	6-10 years				
	Lavatory	2nd Floor	3	EA	6	10+ years				
	Lighting - Lay-in	2nd Floor	3	EA	7	6-10 years				
	Partitions	2nd Floor	2	EA	7	10+ years				
	Urinals	2nd Floor	5	EA	6	10+ years 10+ years	Updated to match current			
						,	observations			
	Walls - Structural Glazed Tile	2nd Floor	546	SF	6	10+ years				
	Water Closet	2nd Floor	2	EA	6	10+ years				
	Accessories	2nd Floor	220	SF	7	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	220	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor	220	SF	6	10+ years				
	Floor Drain	2nd Floor	1	EA	7	10+ years				
	Hand Dryer	2nd Floor	1	EA	7	10+ years	Updated quantity			
	Lavatory	2nd Floor	3	EA	6	10+ years				
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years				
	Partitions	2nd Floor	6	EA	7	10+ years				
	Walls - Structural Glazed Tile	2nd Floor	546	SF	6	10+ years				
	Water Closet	2nd Floor	6	EA	6	10+ years	Updated to match current observations			
	Accessories	2nd Floor Staff in Counselor's Office	45	SF	7	10+ years	Updated to match current			
		201	.0	٠.	•	,	observations			
	Ceiling - Plaster/Drywall	2nd Floor Staff in Counselor's Office	95	SF	7	10+ years				
	,	201				,				
	Doors - Wood Doors inclu hw	2nd Floor Staff in Counselor's Office	1	EA	7	10+ years				
		201				,				
	Floor - Tile	2nd Floor Staff in Counselor's Office	95	SF	7	10+ years				
		201				•				
	Lavatory	2nd Floor Staff in Counselor's Office	1	EA	5	1-2 years	Stuck dripping			
	•	201				-	2			
	Lighting - Pendent/Surface	2nd Floor Staff in Counselor's Office	2	EA	7	6-10 years	Updated to match current			
		201				-	observations			
	Partitions	2nd Floor Staff in Counselor's Office	2	EA	7	10+ years				
		201				·				
	Walls - Concrete Block	2nd Floor Staff in Counselor's Office	213	SF	7	10+ years				
						•				

Campus Name: Tanner Page: 15 of 30 Assessment Date: 05/09/2024



Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Water Classi	201	0	_^	7	40				
	Water Closet	2nd Floor Staff in Counselor's Office 201	2	EA	7	10+ years				
	Accessories	201 2nd Floor Unisex Staff	37	SF	7	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor Unisex Staff	37	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor Unisex Staff	1	EA	6	10+ years				
	Floor - Tile	2nd Floor Unisex Staff	37	SF	6	10+ years				
	Lavatory	2nd Floor Unisex Staff	1	EA	6	10+ years				
	Lighting - Pendent/Surface	2nd Floor Unisex Staff	1	EΑ	7	10+ years				
	Partitions	2nd Floor Unisex Staff	1	EΑ	7	10+ years				
	Walls - Structural Glazed Tile	2nd Floor Unisex Staff	216	SF	6	10+ years				
	Water Closet	2nd Floor Unisex Staff	1	ĒΑ	6	10+ years				
	Accessories	3rd Floor	220	SF	7	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor	220	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	6-10 years	Updated to match current observations			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	220	SF	6	10+ years				
	Floor Drain	3rd Floor	1	EA	7	10+ years				
	Hand Dryer	3rd Floor	2	EA	7	6-10 years				
	Lavatory	3rd Floor	3	EA	6	10+ years				
	Lighting - Lay-in	3rd Floor	3	EA	7	10+ years				
	Partitions	3rd Floor	2	EA	7	10+ years				
	Urinals	3rd Floor	5	EA	7	10+ years				
	Walls - Structural Glazed Tile	3rd Floor	546	SF	6	10+ years				
	Water Closet	3rd Floor	2	EA	6	10+ years				
	Accessories	3rd Floor	220	SF	7	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor	220	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	3rd Floor	220	SF	6	10+ years				
	Floor Drain	3rd Floor	1	EA	7	10+ years				
	Hand Dryer	3rd Floor	2	EΑ	7	6-10 years	Updated quantity			
	Lavatory	3rd Floor	3	EΑ	6	10+ years				
	Lighting - Lay-in	3rd Floor	3	EΑ	7	10+ years				
	Partitions	3rd Floor	6	EA SF	7	10+ years	Undeted to metals accurate			
	Walls - Structural Glazed Tile	3rd Floor	546		6	10+ years	Updated to match current observations			
	Water Closet	3rd Floor	6	EA	6	10+ years				
	Accessories	3rd Floor Staff Restroom	37	SF	7	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor Staff Restroom	37	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor Staff Restroom	1	EA	6	10+ years				
	Floor - Tile	3rd Floor Staff Restroom	37	SF	6	10+ years	Updated to match current observations			
	Lavatory	3rd Floor Staff Restroom	1	EA	6	10+ years				
	Lighting - Pendent/Surface	3rd Floor Staff Restroom	1	EA	7	10+ years				

Campus Name: Tanner Page : 16 of 30 Assessment Date: 05/09/2024



Catego	ry : Room		Building : Main								
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Partitions	3rd Floor Staff Restroom	1	EA	7	10+ years					
	Walls - Structural Glazed Tile	3rd Floor Staff Restroom	216	SF	6	10+ years					
	Water Closet	3rd Floor Staff Restroom	1	EA	6	10+ years					
	Accessories	Basement inside engineer's office	33	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	Basement inside engineer's office	33	SF	7	6-10 years	Deficiency fixed				
	Doors - Wood Doors inclu hw	Basement inside engineer's office	1	EA	7	10+ years					
	Floor - Tile	Basement inside engineer's office	33	SF	7	10+ years					
	Lavatory	Basement inside engineer's office	1	EA	7	10+ years					
	Lighting - Pendent/Surface	Basement inside engineer's office	1	EΑ	7	6-10 years					
	Lighting - Wall Mounted	Basement inside engineer's office	1	EA	7	6-10 years	Deficiency fixed				
	Walls - Concrete Block	Basement inside engineer's office	216	SF	7	10+ years	•				
	Water Closet	Basement inside engineer's office	1	EA	7	6-10 years	Deficiency fixed				
	Accessories	In Kindergarten Room 103	55	SF	7	6-10 years	Quantity updated to match current observations				
	Ceiling - Plaster/Drywall	In Kindergarten Room 103	55	SF	7	10+ years	Quantity updated to match current observations				
	Doors - Wood Doors inclu hw	In Kindergarten Room 103	1	EA	7	10+ years					
	Floor - Tile Ceramic/ Porcelain	In Kindergarten Room 103	55	SF	7	10+ years	Quantity updated to match current observations				
	Lavatory	In Kindergarten Room 103	1	EA	7	10+ years	obool valions				
	Lighting - Lay-in	In Kindergarten Room 103	1	EA	7	6-10 years					
	Walls - Concrete Block	In Kindergarten Room 103	30	SF	7	10+ years	Quantity and type updated to match current observations				
	Walls - Plaster/Drywall	In Kindergarten Room 103	60	SF	7	10+ years	Quantity and type updated to match current observations				
	Walls - Tile Ceramic/ Porcelain	In Kindergarten Room 103	177	SF	7	10+ years	Quantity and type updated to match current observations				
	Water Closet	In Kindergarten Room 103	1	EA	7	10+ years	odironi obodivationo				
	Accessories	In Pre-school Room 105	55	SF	7	6-10 years	Quantity updated to match current				
						•	observations				
	Ceiling - Plaster/Drywall	In Pre-school Room 105	55	SF	7	10+ years	Quantity updated to match current observations				
	Doors - Wood Doors inclu hw	In Pre-school Room 105	1	EA	7	10+ years					
	Floor - Tile Ceramic/ Porcelain	In Pre-school Room 105	55	SF	7	10+ years	Quantity updated to match current observations				
	Lavatory	In Pre-school Room 105	1	EA	7	10+ years					
	Lighting - Lay-in	In Pre-school Room 105	1	EA	7	6-10 years					
	Walls - Plaster/Drywall	In Pre-school Room 105	40	SF	7	10+ years	Quantity and type updated to match current observations				
	Walls - Tile Ceramic/ Porcelain	In Pre-school Room 105	237	SF	7	10+ years	Quantity updated to match current observations				
	Water Closet	In Pre-school Room 105	1	EA	7	10+ years	220017000110				
	Accessories	Staff Restroom in Kitchen Manager's	25	SF	7	6-10 years					
	7.0000001100	Office	20	O.	•	5 To yours					

Campus Name: Tanner Page: 17 of 30 Assessment Date: 05/09/2024



Catego	ry : Room		Building : Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	Staff Restroom in Kitchen Manager's Office	25	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Staff Restroom in Kitchen Manager's Office	1	EA	7	10+ years		
	Floor - Tile	Staff Restroom in Kitchen Manager's Office	25	SF	7	10+ years		
	Lavatory	Staff Restroom in Kitchen Manager's Office	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Staff Restroom in Kitchen Manager's Office	1	EA	7	6-10 years		
	Lighting - Wall Mounted	Staff Restroom in Kitchen Manager's Office	1	EA	6	6-10 years	Rank updated to match current observations	
	Walls - Concrete Block	Staff Restroom in Kitchen Manager's Office	94	SF	7	10+ years		
	Water Closet	Staff Restroom in Kitchen Manager's Office	1	EA	7	10+ years		
	Accessories	Staff in Faculty Lounge Room 310	95	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Staff in Faculty Lounge Room 310	95	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Staff in Faculty Lounge Room 310	1	EA	6	10+ years		
	Floor - Tile	Staff in Faculty Lounge Room 310	95	SF	6	10+ years		
	Lavatory	Staff in Faculty Lounge Room 310	1	EA	6	10+ years		
	Lighting - Pendent/Surface	Staff in Faculty Lounge Room 310	1	EA	6	6-10 years		
	Lighting - Wall Mounted	Staff in Faculty Lounge Room 310	1	EA	6	6-10 years		
	Partitions	Staff in Faculty Lounge Room 310	2	EA	7	10+ years		
	Walls - Concrete Block	Staff in Faculty Lounge Room 310	213	SF	6	10+ years		
	Water Closet	Staff in Faculty Lounge Room 310	2	EA	6	10+ years		

Category: Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	28	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	36	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	996	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #103 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	

Campus Name: Tanner Page : 18 of 30 Assessment Date: 05/09/2024



atego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,130	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,130	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	34	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,462	SF	7	10+ years	
	Work Sink	1st Floor	1,402	EA	7	10+ years	
	WOIR SIIIR	151 11001	'	LA	,	10+ years	
lassroc	om #104 (Dance Room)						
	AC Units	1st Floor	1	EΑ	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	Rank updated to match current
	Lighting - Fendent/Surface	131 1 1001	10	LA	U	0-10 years	observations
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	48	SF	7	10+ years	
	Wall Mirrors	1st Floor	75	SF	4	0-1 year	Made out of foil
	Walls - Concrete Block	1st Floor	863	SF	7	10+ years	made cut of for
laceroe	om #105 (Pre School)						
iassiuc	,	1st Floor	4	ΓΛ	7	C 40	
	AC Units		1	EA	7	6-10 years	
	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,130	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,130	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	34	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,462	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
aceroo	om #106 (Music Room)						
ussiut	AC Units	1st Floor	1	EA	7	6 10 years	
					7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	48	SF	7	10+ years	

Campus Name: Tanner Page: 19 of 30 Assessment Date: 05/09/2024



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	863	SF	7	10+ years	
Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	48	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	874	SF	6	10+ years	
_Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	775	SF	6	10+ years	
	Floor - Tile	2nd Floor	5	SF	5	1-2 years	Cracking
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	ŭ
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	996	SF	6	10+ years	
_Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	23	LF	6	10+ years	
	Casework	2nd Floor	5	LF	5	1-2 years	Casework doors missing
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	G
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	48	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	874	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	

Campus Name: Tanner Page : 20 of 30 Assessment Date: 05/09/2024



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	775	SF	6	10+ years	
	Floor - Tile	2nd Floor	5	SF	5	1-2 years	Chipping
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	11 3
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	996	SF	6	10+ years	
:lassroo	om #204 (Regular Classroom)						
- IOOOI OX	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	770	SF	6	•	
	Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	10	SF SF	5	10+ years 1-2 years	Discoloration from water damage
							Discoloration from water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	48	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	874	SF	6	10+ years	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	2	EΑ	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	5	1-2 years	Door damaged
	Walls - Concrete Block	2nd Floor	996	SF	6	10+ years	Door damaged
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor 2nd Floor	16	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	780	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4		
						2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	770	SF	7	10+ years	One alsia a
	FIGOR - LIIA/Sheet	2nd Floor	10	SF	4	1-2 years	Cracking
	Floor - Tile/Sheet Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	• · · · · · · · · · · · · · · · · · · ·

Campus Name: Tanner Page : 21 of 30 Assessment Date: 05/09/2024



y : Classroom			uilding			
					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Marker Board	2nd Floor	16	LF	7	6-10 years	
				7	10+ years	
Walls - Concrete Block	2nd Floor	874	SF	6	10+ years	
n #207 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor		LF	6		
Ceiling - Plaster/Drywall	2nd Floor	780	SF	6		
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6		
Floor - Tile	2nd Floor	780	SF	6		
Lighting - Pendent/Surface	2nd Floor		EΑ	7		
	2nd Floor	4	EA	6		
		1		-		Relamp
					•	
Walls - Concrete Block	2nd Floor	996	SF	6	10+ years	
n #208 (Faculty Lounge)						
	2nd Floor	1	FA	7	10+ vears	
					-	
						Updated to match current
		ı			•	observations
		1				
Floor - Tile/Sheet	2nd Floor	780	SF	7	10+ years	Updated to match current observations
Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
• •						
	2nd Floor	48		7		
Walls - Concrete Block	2nd Floor	874	SF	6	10+ years	
n #209 (Special Program)						
	2nd Floor	2	EA	7	10+ vears	
Casework						
	2nd Floor	780	SF	6		
	2nd Floor	1	EA			
Floor - Tile	2nd Floor					
Lighting - Pendent/Surface			ĒΑ	7		
					-	
					•	
	AC Units Casework Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Lighting - Pendent/Surface Storage/ Closet Walls - Concrete Block 1 #208 (Faculty Lounge) AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Hardware Doors - Wood Doors inclu hw Floor - Tile/Sheet Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block 1 #209 (Special Program) AC Units Casework Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	Walls - Concrete Block 2nd Floor #207 (Regular Classroom) AC Units Casework 2nd Floor Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Malls - Concrete Block AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Hardware Doors - Wood Doors inclu hw Floor Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block 2nd Floor 2nd Floor Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block 2nd Floor 2nd Floor AC Units Casework 2nd Floor Ar Floor	Walls - Concrete Block 2nd Floor 874 n #207 (Regular Classroom) 1 2nd Floor 1 Casework 2nd Floor 28 2nd Floor 28 Ceiling - Plaster/Drywall 2nd Floor 780 1 780 1 1 780 1 2 1 1 2 1 1 1 2 1 1 2 1 1	Walls - Concrete Block 2nd Floor 874 SF 1#207 (Regular Classroom) AC Units 2nd Floor 1 EA Casework 2nd Floor 780 SF Doors - Wood Doors inclu hw 2nd Floor 1 EA Floor - Tile 2nd Floor 12 EA Lighting - Pendent/Surface 2nd Floor 12 EA Lighting - Pendent/Surface 2nd Floor 4 EA Lighting - Pendent/Surface 2nd Floor 4 EA Lighting - Pendent/Surface 2nd Floor 4 EA Lighting - Pendent/Surface 2nd Floor 36 SF Walls - Concrete Block 2nd Floor 36 SF Walls - Concrete Block 2nd Floor 996 SF 1#208 (Faculty Lounge) 2nd Floor 1 EA Casework 2nd Floor 1 EA Casework 2nd Floor 1 EA Call Kapart 2nd Floor 1 EA Lighting - Pendent/Sur	Walls - Concrete Block 2nd Floor 874 SF 6 1#207 (Regular Classroom) AC Units 2nd Floor 1 EA 7 Casework 2nd Floor 28 LF 6 Ceiling - Plaster/Drywall 2nd Floor 780 SF 6 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 Floor - Tile 2nd Floor 780 SF 6 Lighting - Pendent/Surface 2nd Floor 12 EA 7 Lighting - Pendent/Surface 2nd Floor 4 EA 6 Lighting - Pendent/Surface 2nd Floor 36 SF 7 Walls - Concrete Block 2nd Floor 36 SF 7 Walls - Concrete Block 2nd Floor 36 SF 7 Walls - Concrete Block 2nd Floor 1 EA 7 Casework 2nd Floor 1 EA 7 Casework 2nd Floor 8 LF 4 <td< td=""><td> Storage / Closet 2nd Floor 48 SF 7 10+ years </td></td<>	Storage / Closet 2nd Floor 48 SF 7 10+ years

Campus Name: Tanner Page : 22 of 30 Assessment Date: 05/09/2024



Category : Classroom			В	7350 S EVAITS AVENUE, CHICAGO, IL 60619			
3			_	3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #300 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	10+ years	
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	10+ years	
	Storage/ Closet	3rd Floor	48	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	874	SF	6	10+ years	
_Classroo	om #301 (Special Program)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	996	SF	6	10+ years	
_Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Chalk Board	3rd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	10+ years	
	Storage/ Closet	3rd Floor	48	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	874	SF	6	10+ years	
_Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	6-10 years	Relamp
	Marker Board	3rd Floor	16	LF	7	6-10 years	/
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
						·	

Campus Name: Tanner Page : 23 of 30 Assessment Date: 05/09/2024



Recommend	Category : Classroom			В		7000 0 Evans AVENOE, Officago, ie 0001		
Mails - Concrete Block 3rd Floor 996 SF 6 10+ years				_			Recommend	
AC Units	Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
AC Units 3rd Floor 1 EA 7 6-10 years Casework 3rd Floor 16 LF 6 10+ years Celing - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Chalk Board 3rd Floor 16 LF 4 2-5 years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 780 SF 7 10+ years Lighting - Pendent/Surface 3rd Floor 780 SF 7 10+ years Storage/ Closet 3rd Floor 16 EA 7 6-10 years Storage/ Closet 3rd Floor 24 LF 7 6-10 years Storage/ Closet 3rd Floor 874 SF 6 10+ years Walls - Concrete Block 3rd Floor 874 SF 6 10+ years Casework 3rd Floor 28 LF 6 10+ years Casework 3rd Floor 780 SF 6 10+ years Ploor - Tile/Sheet 3rd Floor 986 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Wood Doors and Floor 1 SF 6 10+ years Storage/ Closet 3rd Floor 996 SF 6 10+ years Storage/ Closet 3rd Floor 996 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 6-10 years Doors - Wood Doors inclu hw 3rd Floor 770 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 770 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 770 SF 7 10+ years Ploor - Tile/Sheet 3rd Floor 1 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 1 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 1 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 1 SF 5 1-2 years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Storage/ Closet 3rd	_	Walls - Concrete Block	3rd Floor	996	SF	6	10+ years	
AC Units 3rd Floor 1 EA 7 6-10 years Casework 3rd Floor 16 LF 6 10+ years Celing - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Chalk Board 3rd Floor 16 LF 4 2-5 years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 780 SF 7 10+ years Lighting - Pendent/Surface 3rd Floor 780 SF 7 10+ years Storage/ Closet 3rd Floor 16 EA 7 6-10 years Storage/ Closet 3rd Floor 24 LF 7 6-10 years Storage/ Closet 3rd Floor 874 SF 6 10+ years Walls - Concrete Block 3rd Floor 874 SF 6 10+ years Casework 3rd Floor 28 LF 6 10+ years Casework 3rd Floor 780 SF 6 10+ years Ploor - Tile/Sheet 3rd Floor 986 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Doors - Wood Doors and Floor 1 SF 6 10+ years Storage/ Closet 3rd Floor 996 SF 6 10+ years Storage/ Closet 3rd Floor 996 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 6-10 years Doors - Wood Doors inclu hw 3rd Floor 770 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 770 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 770 SF 7 10+ years Ploor - Tile/Sheet 3rd Floor 1 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 1 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 1 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 1 SF 5 1-2 years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Crack Storage/ Closet 3rd Floor 1 SF 5 7 10+ years Storage/ Closet 3rd	Classroo	m #304 (Regular Classroom)						
Casework		` •	3rd Floor	1	FA	7	6-10 years	
Ceiling - Plaster/Dywall 3rd Floor 780 SF 6 10+ years								
Chalk Board 3rd Floor 16 LF 4 2-5 years Doors - Wood Doors inclu hw 3rd Floor 7 16 LF 4 2-5 years Floor - Tile/Sheet 3rd Floor 780 SF 7 10+ years Lighting - Pendent/Surface 3rd Floor 12 LF 7 6-10 years Storage/Closet 3rd Floor 48 SF 7 10+ years Storage/Closet 3rd Floor 48 SF 7 10+ years Storage/Closet 3rd Floor 48 SF 7 10+ years Storage/Closet 3rd Floor 874 SF 6 10+ years Storage/Closet 3rd Floor 874 SF 6 10+ years Storage/Closet 3rd Floor 1 EA 7 10+ years Storage/Closet 3rd Floor 28 LF 6 10+ years Casework 3rd Floor 28 LF 6 10+ years Doors - Transom Window 3rd Floor 780 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years SF 6 10+ years SF 100+ Tile 3rd Floor 1 SF 6 10+ years SF 100+ Years Years SF 100+ Year							•	
Doors - Wood Doors inclu hw 3rd Floor 1								
Floor - Tile/Sheet								
Lighting - Pendent/Surface 3rd Floor 16 EA 7 6-10 years				· · · · · · · · · · · · · · · · · · ·		_	-	
Marker Board 3rd Floor 24 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years Walls - Concrete Block 3rd Floor 874 SF 6 10+ years Lassroom #305 (Regular Classroom) AC Units 3rd Floor 1 EA 7 10+ years Casework 3rd Floor 28 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Transom Window 3rd Floor 780 SF 6 10+ years Floor - Tile 3rd Floor 14 EA 7 10+ years Lighting - Pendent/Surface 3rd Floor 14 EA 7 10+ years Lighting - Pendent/Surface 3rd Floor 2 EA 6 6-10 years Marker Board 3rd Floor 3rd Floor 36 SF 7 10+ years Storage/ Closet 3rd Floor 1 EA 7 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Storage/ Closet 3rd Floor 48 SF 7 10+ years								
Ac Units								
AC Units 3rd Floor 1 EA 7 10+ years Casework 3rd Floor 28 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Floor - Tile 3rd Floor 780 SF 6 10+ years Updated to match current observations Lighting - Pendent/Surface 3rd Floor 14 EA 7 10+ years Lighting - Pendent/Surface 3rd Floor 2 EA 6 6-10 years Storage/ Closet 3rd Floor 20 LF 7 6-10 years Storage/ Closet 3rd Floor 36 SF 7 10+ years Walls - Concrete Block 3rd Floor 996 SF 6 10+ years Storage/ Closet 3rd Floor 996 SF 6 10+ years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 6 10+ years Storage/ Closet 3rd Floor 1 EA 6 10+ years Storage/ Cliffy Plaster/Drywall 3rd Floor 1 EA 6 10+ years Storage/ Cliffy Plaster/Drywall 3rd Floor 1 EA 6 10+ years Storage/ Cliffy Plaster/Drywall 3rd Floor 1 EA 6 10+ years Floor Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Fl								
AC Units 3rd Floor 1 EA 7 10+ years Casework 3rd Floor 28 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Transom Window 3rd Floor 1 SF 6 10+ years Floor - Tile 3rd Floor 780 SF 6 10+ years Updated to match current observations Lighting - Pendent/Surface 3rd Floor 14 EA 7 10+ years Lighting - Pendent/Surface 3rd Floor 2 EA 6 6-10 years Storage/ Closet 3rd Floor 20 LF 7 6-10 years Storage/ Closet 3rd Floor 36 SF 7 10+ years Walls - Concrete Block 3rd Floor 996 SF 6 10+ years Storage/ Closet 3rd Floor 996 SF 6 10+ years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 7 6-10 years Storage/ Closet 3rd Floor 1 EA 6 10+ years Storage/ Closet 3rd Floor 1 EA 6 10+ years Storage/ Cliffy Plaster/Drywall 3rd Floor 1 EA 6 10+ years Storage/ Cliffy Plaster/Drywall 3rd Floor 1 EA 6 10+ years Storage/ Cliffy Plaster/Drywall 3rd Floor 1 EA 6 10+ years Floor Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 16 EA 6 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Floor 19 EA 7 10+ years Storage/ Closet 3rd Fl	Classros	m #205 (Bagular Classroom)						
Casework	Ciassioo		2rd Floor	1	ΕΛ	7	10 L VOORO	
Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years							-	
Doors - Transom Window 3rd Floor 1 SF 6 10+ years Updated to match current							•	
Floor - Tile		Ceiling - Plaster/Drywali				-		
Lighting - Pendent/Surface 3rd Floor 14 EA 7 10+ years				· · · · · · · · · · · · · · · · · · ·				Hadatadta asatala asasat
Lighting - Pendent/Surface 3rd Floor 2 EA 6 6-10 years Marker Board 3rd Floor 20 LF 7 6-10 years Storage/ Closet 3rd Floor 36 SF 7 10+ years Walls - Concrete Block 3rd Floor 996 SF 6 10+ years Lassroom #306 (Regular Classroom) AC Units 3rd Floor 1 EA 7 6-10 years Casework 3rd Floor 16 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 770 SF 7 10+ years Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years		Floor - Tile	3ra Floor	780	5F	6	10+ years	•
Lighting - Pendent/Surface 3rd Floor 2 EA 6 6-10 years Marker Board 3rd Floor 20 LF 7 6-10 years Storage/ Closet 3rd Floor 36 SF 7 10+ years Walls - Concrete Block 3rd Floor 996 SF 6 10+ years Lassroom #306 (Regular Classroom) AC Units 3rd Floor 1 EA 7 6-10 years Casework 3rd Floor 16 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 770 SF 7 10+ years Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years		Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
Marker Board 3rd Floor 20 LF 7 6-10 years Storage/ Closet 3rd Floor 36 SF 7 10+ years Walls - Concrete Block 3rd Floor 996 SF 6 10+ years Lassroom #306 (Regular Classroom) 3rd Floor 1 EA 7 6-10 years Casework 3rd Floor 16 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 770 SF 7 10+ years Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Storage/ Closet Walls - Concrete Block 3rd Floor 36 SF 7 10+ years Iassroom #306 (Regular Classroom) AC Units 3rd Floor 1 EA 7 6-10 years Casework Casework 3rd Floor 16 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 770 SF 7 10+ years Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years			3rd Floor		LF	7		
Walls - Concrete Block 3rd Floor 996 SF 6 10+ years lassroom #306 (Regular Classroom) AC Units 3rd Floor 1 EA 7 6-10 years Casework 3rd Floor 16 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 770 SF 7 10+ years Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years		Storage/ Closet	3rd Floor	36	SF	7		
AC Units 3rd Floor 1 EA 7 6-10 years Casework 3rd Floor 16 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 770 SF 7 10+ years Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years								
AC Units 3rd Floor 1 EA 7 6-10 years Casework 3rd Floor 16 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 770 SF 7 10+ years Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years	Classroo	m #306 (Regular Classroom)						
Casework 3rd Floor 16 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 10+ years Floor - Tile/Sheet 3rd Floor 770 SF 7 10+ years Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years			3rd Floor		ΕA	7	6-10 years	
Ceiling - Plaster/Drywall3rd Floor780SF610+ yearsDoors - Wood Doors inclu hw3rd Floor1EA610+ yearsFloor - Tile/Sheet3rd Floor770SF710+ yearsFloor - Tile/Sheet3rd Floor10SF51-2 yearsCrackLighting - Pendent/Surface3rd Floor16EA610+ yearsMarker Board3rd Floor16LF76-10 yearsStorage/ Closet3rd Floor48SF710+ years								
Doors - Wood Doors inclu hw3rd Floor1EA610+ yearsFloor - Tile/Sheet3rd Floor770SF710+ yearsFloor - Tile/Sheet3rd Floor10SF51-2 yearsCrackLighting - Pendent/Surface3rd Floor16EA610+ yearsMarker Board3rd Floor16LF76-10 yearsStorage/ Closet3rd Floor48SF710+ years								
Floor - Tile/Sheet 3rd Floor 770 SF 7 10+ years Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years								
Floor - Tile/Sheet 3rd Floor 10 SF 5 1-2 years Crack Lighting - Pendent/Surface 3rd Floor 16 EA 6 10+ years Marker Board 3rd Floor 16 LF 7 6-10 years Storage/ Closet 3rd Floor 48 SF 7 10+ years				· ·				
Lighting - Pendent/Surface3rd Floor16EA610+ yearsMarker Board3rd Floor16LF76-10 yearsStorage/ Closet3rd Floor48SF710+ years						-	-	Crack
Marker Board3rd Floor16LF76-10 yearsStorage/ Closet3rd Floor48SF710+ years							•	J. 3311
Storage/ Closet 3rd Floor 48 SF 7 10+ years							,	
							•	
		•						
lassroom #307 (Regular Classroom)	Classroo	m #307 (Regular Classroom)						
AC Units 3rd Floor 1 EA 7 6-10 years	<u> </u>		3rd Floor	1	FΔ	7	6-10 years	
Casework 3rd Floor 28 LF 6 10+ years								
Casework Sid Floor 28 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 780 SF 6 10+ years							•	
Gening - Flaster/Drywaii Stull 1001 700 SF 0 10+ years		Centing - Flaster/Drywan	JIU I IOUI	700	J.	U	10+ years	



Category : Classroom		Building : Main					
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	1	SF	6	10+ years	
	Floor - Tile	3rd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	34	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	996	SF	6	10+ years	
assroc	om #308 (Computer Lab)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	780	SF	7	•	Undated to match current
	Floor - Tile/Sneet	310 11001	700	SF	,	10+ years	Updated to match current observations
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	48	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	874	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
	Wholese Cyclom	014 1 1001	•	L/ \	,	101 youro	
lassroc	om #309 (Faculty Lounge)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EΑ	6	6-10 years	Relamp
	Storage/ Closet	3rd Floor	34	SF	7	10+ years	rtolamp
	Walls - Concrete Block	3rd Floor	996	SF	6	10+ years	
atego	ry : Interior		В	Building : Main			
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•							
orridor	Ceiling - Plaster/Drywall	1st Floor	2,299	SF	7	10+ years	
	Ceiling - Splined	1st Floor	632	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	7	EA	7	•	
						10+ years	
	Drinking Fountains - Single Fountain Drinking Fountains - Single Fountain	1st Floor	2	EΑ	7	6-10 years	Drakan
	Drinking Fountains - Single Fountain	1st Floor	1	EA	5	1-2 years	Broken



Catego	Category : Interior		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	6-10 years			
	Floor - Terrazzo	1st Floor	632	SF	7	10+ years			
	Floor - Tile/Sheet	1st Floor	2,299	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	39	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor	1,515	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	3,030	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	2,036	SF	6	10+ years			
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	2,036	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	1,050	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	2,101	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	2,036	SF	6	10+ years			
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	7	10+ years			
	Floor - Tile/Sheet	3rd Floor	2,031	SF	7	10+ years			
	Floor - Tile/Sheet	3rd Floor	5	SF	5	1-2 years	Chipping		
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor	1,050	SF	6	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	2,100	SF	6	10+ years			
Safety									
Salety	Camera Viewing Station	Entire building	1	EA	5	0-1 year	School does not have access to		
	J	ŭ				,	camera footage. One viewing station observed.		
	Security Cameras	Entire building	3	EA	7	6-10 years			
	Security Cameras	Entire building	27	EA	7	6-10 years			
Stairs									
_Olalis	Ceiling - Plaster/Drywall	North	230	SF	6	10+ years			
	Floor - Terrazzo	North	240	SF	6	10+ years			
	Handrails	North	128	LF	7	10+ years			
	Lighting - Pendent/Surface	North	2	EA	7	10+ years			
	Lighting - Wall Mounted	North	2	EA	7	10+ years			
	Stairs - Terrazzo	North	60	LF	6	10+ years			
	Walls - Structural Glazed Tile	North	1,440	SF	6	10+ years			
	Ceiling - Plaster/Drywall	South	230	SF	6	10+ years			
	Floor - Terrazzo	South	240	SF	6	10+ years			
	Handrails	South	128	LF	7	10+ years			
	Lighting - Pendent/Surface	South	2	EA	7	10+ years			
	Stairs - Terrazzo	South	60	LF	6	10+ years			
	Walls - Structural Glazed Tile	South	1,840	SF	6	10+ years			
Vortical	Conveyance								
v c itical	Conveyance								

Campus Name: Tanner Page : 26 of 30 Assessment Date: 05/09/2024



Building: Main Category: Interior Recommend

Location Group Item - Type Quantity UOM Rank Replacement Comments Elevator - Elevator - Roped Holeless 1st through 3rd floor EΑ 10+ years 6

Hydraulic

Campus Name: Tanner Page : 27 of 30 Assessment Date: 05/09/2024



Category : Site Building : Site

Carogo	ry . Site			unung			
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	6-10 years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	1-2 years	Broken, missing steel
	1 1 3 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					,	3 · · · · · · · · · · · · · · · · · · ·
Fencina							
J	Fencing - Chain Link	Entire Site	858	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	168	LF	4	1-2 years	Bent, twisted, loose
	Fencing - New Standard Ornamental	Entire Site	158	LF	7	10+ years	,
	Fencing - New Standard Ornamental	Entire Site	2	LF	4	0-1 year	Will not latch. Latch is too narrow for
	· ····································		_		•	5 · J · 5 · ·	the post
Landsca	pe						
	Landscape - Grass	Entire Site	10,800	SF	6	6-10 years	
	Landscape - Grass	Entire Site	1,500	SF	5	1-2 years	Bare soil, depressions creating pools
	Parkway trees	Entire Site	26	EA	7	10+ years	
	Parkway trees	Entire Site	1	EA	4	1-2 years	One damaged tree
	Play Area - Hardscape- Asphalt	Entire Site	40,537	SF	6	6-10 years	•
	Play Area - Hardscape- Asphalt	Entire Site	1,200	SF	5	2-5 years	
	Trash Receptacles	Entire Site	2	ĒΑ	6	6-10 years	
	·					•	
Parking	Lot						
	Surface - Asphalt	Parking Lot- West	10,021	SF	6	10+ years	
	Surface - Asphalt	Parking Lot- West	1,000	SF	4	1-2 years	Alligatoring, ponding, cracks
	Surface - Concrete	Parking Lot- West	1,476	SF	6	6-10 years	0 0/1 0/
	Trash Enclosure - Chain Links	Parking Lot- West	150	SF	6	6-10 years	
Playgrou		NIT aita	4	ΕΛ	7	10	
	Equipment - Pre K 3-5	NE site	1	EΑ	7	10+ years	
	Equipment - School Age 5-12	NE site	1	EA	7	10+ years	
	Surface - Poured Surface	NE site	5,192	SF	7	10+ years	-
	Surface - Poured Surface	NE site	30	SF	4	1-2 years	Tears and holes
Sidewalk	(e						
Juewali	Sidewalks - Internal Walks	Entire Site	355	LF	6	6-10 years	
	Sidewalks - Internal Walks	Entire Site	20	LF	5	1-2 years	Upheaved, cracked
	Sidewalks - Perimeter Sidewalks	Entire Site	7,384	SF	7	10+ years	Opricaved, Glacked
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	5	1-2 years	Upheaved, sunken, broken
	Sidewains - I cillictel Sidewains	Little Oile	100	Ji	3	1-2 years	opileaved, sulkell, blokell
Signage							
990	Flag Pole - Flag Pole	SE site	1	EA	6	6-10 years	
	Marquee - Free Standing Back Lighted	SE site	1	EA	6	6-10 years	
	. 3					,	

Campus Name: Tanner Page : 28 of 30 Assessment Date: 05/09/2024



Building: Site Category: Site

						Recommena	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Monument - Building Mounted Cut Letter	SE site	1	EA	6	6-10 years	
	Sign						

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Tanner Page: 29 of 30 Assessment Date: 05/09/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	•								
Computer Lab	Computer Lab	3rd Floor	308	308	780	176	80	N	N
Dance Room	Regular Classroom	1st Floor	104	104	780	120	56	N	N
Faculty Lounge	Regular Classroom	2nd Floor	208	208	780	176	80	N	N
Faculty Lounge	Regular Classroom	3rd Floor	309	309	780	120	56	N	N
Kindergarten	Kindergarten	1st Floor	103	103	1,130	180	84	N	N
Music Room	Regular Classroom	1st Floor	106	106	780	176	80	N	Υ
Pre School	Pre School	1st Floor	105	105	1,130	180	84	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	780	120	56	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	780	120	56	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	780	120	56	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	780	176	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	780	120	56	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	780	176	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	780	120	56	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	780	120	56	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	780	120	56	N	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	780	176	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	780	176	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	780	120	56	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	780	176	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	780	120	56	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	780	176	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	780	120	56	N	N
Special Program	Regular Classroom	2nd Floor	209	209	780	120	56	N	Υ
Special Program	Regular Classroom	3rd Floor	301	301	780	120	56	N	Υ