

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1893	3	44,587
Addition 1	1925	2	44,037
Addition 2	1975	2	47,014
Campus Total			135,638

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Overhead Rolling/ Garage	#5.3- NW Overhead	1	EA	6	6-10 years	
	Door					•	
	Exterior Doors - Exterior Steel Door	#5.4- NW- Old B.R.	1	EA	4	0-1 year	Corroded frame, warped door
	Exterior Doors - Transom Lite	#5.4- NW- Old B.R.	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#5.4- NW- Old B.R.	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5.5- NW- Ct Yrd	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#5.5- NW- Ct Yrd	1	EA	6	10+ years	
	Exterior Stairs - Stone	#5.5- NW- Ct Yrd	3	LF	6	10+ years	Repaired
	Exterior Doors - Exterior Steel Door	#5.6- NW	2	EΑ	4	1-2 years	Warped doors
	Exterior Stairs - Concrete	#5.6- NW	6	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6- NW	4	EA	4	0-1 year	Corroded doors and frames
	Exterior Doors - Transom Lite	#6- NW	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6- NW	11	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6.1- NW	1	EA	5	0-1 year	Rusted.
	Exterior Doors - Exterior Steel Door	Fire Escape Doors	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Fire Escape Doors	2	EA	6	6-10 years	
Fire Esca	ape						
	Exterior Doors - Exterior Steel Door	FE 1	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	FE 1	2	EA	6	10+ years	
	Fire Escape	FE 1	110	LF	6	6-10 years	
	Paints	FE 1	110	LF	5	2-5 years	
						•	



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Foundati	on						
	Foundation - Concrete	Entire Building	50	LF	6	1-2 years	Seepage from the bottom of the foundation wall
	Foundation - Masonry	Entire Building	483	LF	7	10+ years	Touridation Wall
	Foundation - Masonry	Entire Building	15	LF	4	0-1 year	Leaks from foundation wall cracks
	Superstructure - Heavy Timber	Entire Building	44,587	SF	7	10+ years	
_ighting		E 2				0.5	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	5	2-5 years	Engineer has noted that there is not sufficient lighting
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	6-10 years	
Roof Sys	stem						
	Coping - Terra Cotta	Center roof	63	LF	5	6-10 years	
	Downspouts - Exterior Downspouts	Center roof	2	LF	6	10+ years	
	Parapet - 16" - 30" Height	Center roof	63	LF	6	10+ years	
	Roof - Modified Bitumen	Center roof	681	SF	5	0-1 year	Blistering, worn surface. Confirmed that this roof is not failing
	Roof Structure - Heavy Timber	Center roof	681	SF	7	10+ years	triat triis 1001 is not failing
	Coping - Stone	Elevator roof	53	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Elevator roof	20	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Elevator roof	53	LF	6	6-10 years	
	Roof - Modified Bitumen	Elevator roof	205	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Elevator roof	205	SF	7	10+ years	
	Concrete Topping	Lievator 1001	200	Oi	,	10+ years	
	Coping - Stone	Low NE roof	22	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low NE roof	10	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Low NE roof	22	LF	6	6-10 years	
	Roof - Modified Bitumen	Low NE roof	60	SF	6	2-5 years	
	Roof Structure - Heavy Timber	Low NE roof	60	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Low S roofs	75	LF	5	1-2 years	Open joints
	Liner	LOW 0 10013	70		J	1 2 years	Open Joints
	Chimney - Metal Flue	Low S roofs	26	LF	6	10+ years	
	Coping - Stone	Low S roofs	205	LF	7	10+ years	
	Coping - Terra Cotta	Low S roofs	43	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Low S roofs	51	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low S roofs	249	LF	6	6-10 years	
	Roof - Modified Bitumen	Low S roofs	3,166	SF	5	0-10 years 0-1 year	Blistering and soft spots, worn
	De et Otrocetore - Octobre to	Law Orașifa	0.400	05	7	40	surfaces
	Roof Structure - Concrete	Low S roofs	3,166	SF	7	10+ years	
	Access Ladder - Metal	Main - Upper W roof	1	EΑ	7	10+ years	
	Access Ladder - Wood	Main - Upper W roof	2	EA	4	0-1 year	Poorly designed. One cannot get his



Catego	ry : Exterior	-	В	uilding	: Main	-	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							toes into the rungs. Other word ladder
					_		is homemade design, coming apart
	Coping - Terra Cotta	Main - Upper W roof	224	LF	6	6-10 years	
	Coping - Terra Cotta	Main - Upper W roof	4	LF . –	4	1-2 years	Missing coping
	Downspouts - Exterior Downspouts	Main - Upper W roof	70	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main - Upper W roof	120	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main - Upper W roof	213	LF	6	10+ years	
	Roof - Modified Bitumen	Main - Upper W roof	4,300	SF	6	6-10 years	
	Roof - Modified Bitumen	Main - Upper W roof	390	SF	5	0-1 year	Soft spots, blistering
	Roof Hatch - Metal	Main - Upper W roof	1	EA	4	1-2 years	Corroding old hatch
	Roof Structure - Heavy Timber	Main - Upper W roof	4,690	SF	7	10+ years	
	Access Ladder - Wood	Upper E Roof	1	EA	4	1-2 years	Unsafe, homemade wooden ladder
	Coping - Stone	Upper E Roof	228	LF	6	6-10 years	
	Coping - Terra Cotta	Upper E Roof	200	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Upper E Roof	76	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Upper E Roof	115	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Upper E Roof	5	LF	4	0-1 year	Displaced parapet, open joints
	Parapet - Parapet > 30"	Upper E Roof	103	LF	6	10+ years	
	Roof - Modified Bitumen	Upper E Roof	4,690	SF	5	6-10 years	
	Roof Hatch - Metal	Upper E Roof	1	EA	4	1-2 years	Corroded old hatch
	Roof Structure - Heavy Timber	Upper E Roof	4,690	SF	7	10+ years	
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	498	LF	6	6-10 years	
	Cornice - Metal Projecting	Entire Building	197	LF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	28,493	SF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	90	SF	5	6-10 years	
	Exterior Walls - Brick	Entire Building	50	SF	4	1-2 years	Open joints
	Exterior Walls - Brick	Entire Building	65	SF	3	0-1 year	Cracked brick, bowing wall at lintels
	Exterior Walls - Stone-Cast	Entire Building	800	SF	6	6-10 years	
	Exterior Walls - Stone-Cut	Entire Building	799	SF	6	6-10 years	
	Exterior Walls - Stone-Cut	Entire Building	1	SF	3	1-2 years	Missing corner stone
_Windows							
_ vvii iuuw:	Guard - Guards perforated	Entire Building	1,240	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	6	SF	6	6-10 years	Repaired.
	Lintels - Brick	Entire Building Entire Building	249	LF	6	6-10 years	Nopulieu.
	Lintels - Brick Lintels - Steel	Entire Building Entire Building	10	LF	4	0-10 years 0-1 year	Displaced, lentils, bowing wall
	Lintels - Steel	Entire Building Entire Building	301	LF	6	6-10 years	Displaced, letitlis, bowling wall
	Windows - Louver	Entire Building	36	SF	6	10+ years	
	Windows - Louvei Windows - Sash Aluminum	Entire Building	320	SF SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,120	SF SF	5	0-10 years 0-1 year	20% of balances not working
	windows - Sasii Aluminum Double-pane	Littile building	5,120	SF	ວ	u-i yeai	properly.
							-



Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Exit Signs - Corridors and Stairs	Corridors and Stairs	13	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Corridors and Stairs	8	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,608	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	517	SF	6	6-10 years	
	Security System - CCTV	Entire Building	44,587	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	44,587	SF	6	6-10 years	
Main Sei	vice						
	Independent Electrical Service for emergency power	Basement	1	EA	6	6-10 years	For fire
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	44,587	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	4	EΑ	4	0-1 year	Older panels.
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Front cover loosening, exposing live parts
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	F ******
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Site	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Site	44,587	SF	6	6-10 years	
	Fire Alarm_System	Entire Site	44,587	SF	6	6-10 years	
	Fire Pump Controller	Entire Site	1	EA	6	6-10 years	
oump Ro	pom Assembly						
	Fire Pump - Less than 25hp	Fire Pump Room	1	EA	4	0-1 year	To be replaced soon, per engineer
		·				·	
Sprinkler	System	E B	44.55			0.40	
	Dry Sprinkler System	Entire Building	44,587	SF	5	6-10 years	D 4 1
	Sprinkler Heads	Entire Building	44,587	SF	4	1-2 years	Dated
	Sprinkler Piping	Entire Building	44,587	SF	6	6-10 years	



Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Catogo	ry : Mechanical		B	uilding	· Main	_	
Calego	ry . Wechanical		В	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ling Systems		,				
730 1 12110	Air Handling Unit- Built Up- Multi Zone- Double Delivery- Hot Water Coils - 15000 - 30000 cfm	Basement	1	EA	6	6-10 years	
	Air Intake	Basement	1	EΑ	5	6-10 years	
	Auxiliaries - 15000 - 30000 cfm	Basement	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	100	LF	5	6-10 years	
	Zone Dampers	Basement	30	EA	6	6-10 years	
	Outdoor Return Fans- Air Handling Unit	Roof	1	EA	5	6-10 years	
	Type - Greater than 20000 CFM					·	
Heating							
	Unit Heater - Hot Water	Basement	9	EA	6	6-10 years	
	Wall Heater - Electric	Basement	2	EA	6	6-10 years	
	Wall Heater - Electric	Basement	1	EA	4	0-1 year	Dated with front cover missing
	Fin Tube - Electric	Entire Building	120	LF	6	2-5 years	
	Fin Tube - Hot Water	Entire Building	16	LF	5	2-5 years	
	Cabinet Heaters - With Electric Coil	Stairway	2	EA	6	6-10 years	
Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Basement	1	EA	4	1-2 years	Dated, with heavy corrosion at piping connection
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	10+ years	
Tempera	ature Control						
	DDC System	Entire Building	44,587	SF	2	0-1 year	Not operational per engineer
	Electric Thermostat	Entire Building	2	EA	5	2-5 years	
	Thermostats - DDC	Entire Building	30	EA	6	6-10 years	
Ventilatio							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	5	0-1 year	Dented.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	1	EA	6	6-10 years	



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wat							
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	44,587	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	44,587	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	44,587	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	44,587	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	44,587	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	44,587	SF	6	6-10 years	
	Sanitary Piping	Entire Building	44,587	SF	5	6-10 years	
	Storm Piping	Entire Building	44,587	SF	5	6-10 years	
	Vent Piping	Entire Building	44,587	SF	5	6-10 years	
Pumps							
	Pumps - Ejector-Duplex	Boiler Room	1	EA	6	10+ years	

Category: Room **Building: Main** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	2nd Floor - Counselor Office next to 243	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Counselor Office next to 243	366	SF	6	10+ years	
	Doors - Side-lite	2nd Floor - Counselor Office next to 243	24	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor - Counselor Office next to 243	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor - Counselor Office next to 243	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor - Counselor Office next to 243	366	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Counselor Office next to 243	6	EA	7	6-10 years	
	Power Distribution	2nd Floor - Counselor Office next to 243	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Counselor Office next to 243	956	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Work Sink	2nd Floor - Counselor Office next to 243	1	EA	7	6-10 years	
MDF_ID	F						
_	Doors - Wood Doors inclu hw	2nd Floor - Room 233A	1	EA	6	6-10 years	
	Finishes	2nd Floor - Room 233A	160	SF	7	6-10 years	
Mechani	ical/ Service Rooms						
	Mechanical/ Service Rooms	3rd Floor	8	SF	7	10+ years	
	Boiler Room	Basement - Old Boiler Room	2,610	SF	5	10+ years	Water damage to parts of ceiling
Restroor	n						
	Accessories	3rd Floor Unisex Staff RR	96	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor Unisex Staff RR	96	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Unisex Staff RR	1	EA	7	6-10 years	
	Floor - Tile	3rd Floor Unisex Staff RR	96	SF	7	6-10 years	
	Floor Drain	3rd Floor Unisex Staff RR	1	EA	7	10+ years	
	Lavatory	3rd Floor Unisex Staff RR	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor Unisex Staff RR	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor Unisex Staff RR	172	SF	7	10+ years	
	Water Closet	3rd Floor Unisex Staff RR	1	ĒΑ	7	6-10 years	
	Accessories	Basement	316	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	316	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement	316	SF	6	10+ years	
	Floor Drain	Basement	1	EA	7	6-10 years	
	Hand Dryer	Basement	1	EA	7	6-10 years	
	Lavatory	Basement	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement	4	EA	7	6-10 years	
	Partitions	Basement	1	EA	7	6-10 years	
	Partitions	Basement	1	EA	5	0-10 years 0-1 year	Missing door
	Urinals	Basement	3	EA	7	6-10 years	wiissing door
	Walls - Concrete Block	Basement	84	SF	7	10+ years	
	Walls - Concrete Block Walls - Structural Glazed Tile	Basement	762	SF	7	10+ years 10+ years	
	Water Closet		2	Sr EA	7	6-10 years	
	Accessories	Basement		SF	7		
		Basement	201	SF SF	, 6	6-10 years	
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	Basement	201 1	SF EA	6	10+ years	
		Basement	=		-	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement	201	SF	6	10+ years	
	Floor Drain	Basement	1	EΑ	7	6-10 years	
	Hand Dryer	Basement	1	EΑ	7	6-10 years	
	Lavatory	Basement	4	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	Basement	7	EA	7	6-10 years	



Category : Room Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	Basement	4	EA	7	6-10 years	
	Partitions	Basement	1	EA	4	0-1 year	Missing door
	Walls - Concrete Block	Basement	87	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	448	SF	7	10+ years	
	Water Closet	Basement	5	EA	7	6-10 years	
Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #130 (Faculty Lounge)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	540	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	150	SF	5	0-1 year	Water damage
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,390	SF	6	10+ years	
_Classroo	om #131 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,378	SF	7	10+ years	
Classroo	om #133 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,378	SF	6	6-10 years	
	,		,		-	<b>,</b>	



Category : Classroom			В	uilding	: Main			
			•			Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	om #141 (Regular Classroom)							
CIGOSIOC	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	12	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	621	SF	6	10+ years		
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years		
	Floor - Wood	1st Floor	621	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years		
	Marker Board	1st Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,300	SF	6	10+ years		
Classroo	om #143 (Regular Classroom)							
المعادد	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	6	LF	6	6-10 years 6-10 years		
	Casework Ceiling - Plaster/Drywall	1st Floor	835	SF	6	10+ years		
	Chalk Board	1st Floor		LF	4	2-5 years		
	Doors - Transom Window	1st Floor	30 9	SF	6	•		
	Doors - Wood Doors inclu hw	1st Floor	9	SF EA	6	6-10 years 6-10 years		
		1st Floor	· · · · · · · · · · · · · · · · · · ·	SF	_	•		
	Floor - Wood		835		6	10+ years		
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Storage/ Closet	1st Floor	100	SF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,350	SF	6	10+ years		
Classroc	om #145 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	8	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	782	SF	6	10+ years		
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years		
	Floor - Wood	1st Floor	782	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years		
	Lighting - Wall Mounted	1st Floor	1	EA	5	6-10 years	Relamp	
	Marker Board	1st Floor	24	LF	7	6-10 years	1	
	Walls - Plaster/Drywall	1st Floor	1,430	SF	6	10+ years		
Classroo	om #147 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	8	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	782	SF	6	10+ years		
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years		
	Doors Wood Doors more nw	1301 1001	'	L/ \	U	o to yours		



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	782	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,430	SF	6	10+ years	
Classroc	om #149 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	835	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6		
				SF	6	6-10 years	
	Floor - Wood	1st Floor	835		-	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,482	SF	6	10+ years	
Classroc	om #230 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	615	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	35	SF	5	1-2 years	Water damage to plaster
	Chalk Board	2nd Floor	40	LF	4	2-5 years	3 1
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	6-10 years	
	Floor - Wood	2nd Floor	650	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	85	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,265	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Cracking plaster
Claseron	om #231 (Regular Classroom)						
CIASSIUC	AC Units	2nd Floor	A	Г^	7	6.10	
			1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	795	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	_ 1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	795	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	



	Classroom		D	uilding	. IVIAIII		
				_		Recommend	
	em - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	orage/ Closet	2nd Floor	138	SF	7	6-10 years	
W	alls - Plaster/Drywall	2nd Floor	1,410	SF	6	10+ years	
Classroom #	232 (Regular Classroom)						
AC	C Units	2nd Floor	1	EA	7	6-10 years	
Ca	asework	2nd Floor	4	LF	6	6-10 years	
Ce	eiling - Plaster/Drywall	2nd Floor	715	SF	6	10+ years	
	oors - Transom Window	2nd Floor	19	SF	6	6-10 years	
Do	oors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
Flo	oor - Wood	2nd Floor	715	SF	6	10+ years	
	ghting - Pendent/Surface	2nd Floor	15	EΑ	7	6-10 years	
	arker Board	2nd Floor	12	LF	7	6-10 years	
	orage/ Closet	2nd Floor	6	SF	7	6-10 years	
	alls - Plaster/Drywall	2nd Floor	1,336	SF	6	10+ years	
_Classroom #	233 (Regular Classroom)						
	C Units	2nd Floor	1	EA	7	6-10 years	
	asework	2nd Floor	4	LF	6	6-10 years	
	eiling - Plaster/Drywall	2nd Floor	670	SF	6	10+ years	
	oors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	oors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	oor - Wood	2nd Floor	670	SF	6	10+ years	
	ghting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	arker Board	2nd Floor	24	LF	7	6-10 years	
	orage/ Closet	2nd Floor	160	SF	7	6-10 years	
	alls - Plaster/Drywall	2nd Floor	1,295	SF	6	10+ years	
Classroom #	243 (Regular Classroom)						
	C Units	2nd Floor	1	EA	7	6-10 years	
	asework	2nd Floor	4	LF	6	6-10 years	
	eiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	
	halk Board	2nd Floor	20	LF	4	2-5 years	
	oors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	oors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	oor - Wood Doors Inclu IIW	2nd Floor 2nd Floor	825	SF	6	10+ years	
	ghting - Pendent/Surface	2nd Floor 2nd Floor	15	EA	7	6-10 years	
	arker Board	2nd Floor 2nd Floor	10	LF	7	6-10 years	
	orage/ Closet	2nd Floor 2nd Floor	96	SF	7	6-10 years	
	alls - Plaster/Drywall	2nd Floor	1,436	SF	6	10+ years	
Classroom #	245 (Regular Classroom)						
	C Units	2nd Floor	1	EA	7	6-10 years	
			4	LF	<i>7</i> 6	•	
Ca	asework	2nd Floor	4	LF	О	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		3314 O Bullalo AVENOE, Officago, IE 00017
<b>J</b>						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	52	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,388	SF	6	10+ years	
_Classroo	om #247 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	6	10+ years	
	Chalk Board	2nd Floor	42	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	800	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	156	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,414	SF	6	10+ years	
	Walls - Flastel/Drywall	2110 F1001	1,414	SF	O	10+ years	
Classroo	om #249 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	860	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	6-10 years	
	Floor - Wood	2nd Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	178	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,466	SF	6	10+ years	
Classroo	om #343 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	815	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	5	1-2 years	Water damage, cracking
	Chalk Board	3rd Floor	36	LF	4	2-5 years	vvator damage, cracking
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Doors - Wood Doors Inclu IIW	314 1 1001	ı	LA	U	0-10 years	

Campus Name: Thorp J Page : 12 of 53 Assessment Date: 10/02/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	835	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,456	SF	6	10+ years	
Classroc	om #345 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	772	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Cracking
	Chalk Board	3rd Floor	30	LF	4	2-5 years	Gradiang
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood Boors inclu riw	3rd Floor	782	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	•	
				LF		6-10 years	
	Marker Board	3rd Floor	18	SF	7	6-10 years	No door boadle
	Storage/ Closet	3rd Floor	175		5	6-10 years	No door handle
	Walls - Plaster/Drywall	3rd Floor	1,430	SF	6	10+ years	
Classroc	om #347 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	790	SF	6	10+ years	
	Chalk Board	3rd Floor	42	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	790	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	5	0-1 year	Relamp
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,397	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	8	SF	5	1-2 years	Cracking
Classroc	om #349 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	827	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	8	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	10	SF	6	6-10 years	vvater damaye
	Doors - Wood Doors inclu hw		10	_			
		3rd Floor	•	EA SF	6	6-10 years	
	Floor - Wood	3rd Floor	835	5F	6	10+ years	



ategoi	ry : Classroom		В	uilding	: Main		
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	192	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,439	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	6	SF	4	1-2 years	Cracking and broken plaster
ategoi	ry : Interior		В	uilding	: Main		
			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	3,220	SF	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Wood	1st Floor	3,220	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	37	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	3,302	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,902	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	100	SF	5	0-1 year	Water damage.
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	6-10 years	rrator damage.
	Floor - Wood	2nd Floor	2,002	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	6-10 years	
	Stairs - Wood	2nd Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor		SF	6	•	
			2,235 986			10+ years	
	Ceiling - Plaster/Drywall	3rd Floor		SF	6	10+ years	
	Floor - Wood	3rd Floor	986	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,948	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	1-2 years	Broken plaster
Stairs							
	Ceiling - Plaster/Drywall	Stair 1 (West)	345	SF	6	10+ years	
	Floor - Wood	Stair 1 (West)	200	SF	6	10+ years	
	Handrails	Stair 1 (West)	144	LF	7	6-10 years	
	Lighting - Pendent/Surface	Stair 1 (West)	3	EA	7	6-10 years	
	Stairs - Asphalt	Stair 1 (West)	72	LF	6	6-10 years	
	Walls - Plaster/Drywall	Stair 1 (West)	779	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair 2 (East)	345	SF	6	10+ years	
	Floor - Concrete	Stair 2 (East)	200	SF	7	10+ years	
	Handrails	Stair 2 (East)	144	LF	7	6-10 years	
	Lighting - Pendent/Surface	Stair 2 (East)	6	EΑ	7	6-10 years	
	Stairs - Concrete	Stair 2 (East)	72	LF	6	10+ years	
	Walls - Plaster/Drywall	Stair 2 (East)	679	SF	6	10+ years	

Campus Name: Thorp J Page : 14 of 53 Assessment Date: 10/02/2023



**Building: Main Category: Interior** 

Recommend Location UOM Group Item - Type Quantity Rank Replacement Comments Elevator - Hydraulic Elevator 1st Floor EΑ 10+ years 7

Campus Name: Thorp J Page : 15 of 53 Assessment Date: 10/02/2023





Category : Exterior **Building: Addition 1** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	• •		•			•	
	Entrance Control - Audio and Video	#1- NE- Main Accessible	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#1- NE- Main Accessible	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1- NE- Main Accessible	2	EΑ	6	6-10 years	
	Power Door Operator and Controls	#1- NE- Main Accessible	2	EA	7	10+ years	New
	Exterior Doors - Exterior Steel Door	#1.5- NE	6	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1.5- NE	3	EA	6	6-10 years	
	Exterior Stairs - Stone	#1.5- NE	113	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#5.1- NE	2	EA	5	6-10 years	Confirm that this is surface rust
	Exterior Doors - Transom Lite	#5.1- NE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5.1- NE	37	LF	6	10+ years	
	Exterior Stairs - Concrete	#5.1- NE	5	LF	3	0-1 year	Missing section of step, with cracked steps below
	Exterior Stairs - Stone	#5.1- NE	6	LF	6	6-10 years	•
	Exterior Doors - Exterior Steel Door	#5.2- NE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5.2- NE	4	LF	6	10+ years	
	Exterior Stairs - Concrete	#5.2- NE	4	LF	4	0-1 year	Cracked landing with exposed, corroding rebar
	Exterior Stairs - Steel or Aluminum	#5.2- NE	32	LF	6	6-10 years	3
	Stair Handrail - Steel_Stair Handrail	#5.2- NE	20	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6.2- N	4	EA	5	0-1 year	Corroding doors
	Exterior Doors - Transom Lite	#6.2- N	2	EA	6	6-10 years	· ·
	Entrance Control - Audio and Video	#7- N	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7- N	2	EA	5	0-1 year	Rusting.
	Exterior Doors - Transom Lite	#7- N	2	EA	6	6-10 years	•
	Exterior Stairs - Stone	#7- N	24	LF	6	10+ years	
	Exterior Stairs - Stone	#7- N	8	LF	4	0-1 year	Settlement of bottom step. Steps out of alignment.
	Exterior Doors - Exterior Steel Door	#8- NE	1	EA	6	6-10 years	ŭ
	Exterior Doors - Transom Lite	#8- NE	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#8- NE	12	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Fire Escape #2	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Fire Escape #2	1	EA	6	10+ years	
Fire Esca							
	Exterior Doors - Exterior Steel Door	Façade- NW	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Façade- NW	1	EA	7	10+ years	
	Fire Escape	Façade- NW	35	LF	6	1-2 years	Corroding steel, loose step
	Paints	Façade- NW	35	LF	3	1-2 years	Corroding, steel, missing paint
_Foundati	on						
canadu	Foundation - Concrete	Entire Building	782	LF	7	10+ years	
	1 dandalon Conordo	Entire Building	102	Li	•	101 yours	



Catego	ry : Exterior		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Foundation - Concrete	Entire Building	5	LF	5	0-1 year	Cracked concrete at window
	Superstructure - Concrete	Entire Building	44,037	SF	7	10+ years	
_ighting							
0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	8	EA	5	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	6-10 years	
Roof Sys	stem						
,	Coping - Stone	Low E roof	43	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low E roof	18	LF	6	6-10 years	
	Parapet - Parapet > 30"	Low E roof	43	LF	6	6-10 years	
	Roof - Modified Bitumen	Low E roof	134	SF	5	1-2 years	Vegetation growth, cracks on the
						·	surface
	Roof Structure - Concrete	Low E roof	134	SF	7	10+ years	
	Coping - Metal	Low NW Roof Bridge	50	LF	6	10+ years	
	Coping - Stone	Low NW Roof Bridge	65	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Low NW Roof Bridge	5	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Low NW Roof Bridge	115	LF	6	10+ years	
	Roof - Modified Bitumen	Low NW Roof Bridge	724	SF	5	2-5 years	
	Roof Structure - Concrete	Low NW Roof Bridge	724	SF	7	10+ years	
	Coping - Metal	Low S Roofs	20	LF	6	10+ years	
	Coping - Stone	Low S Roofs	20	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low S Roofs	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low S Roofs	20	LF	6	6-10 years	
	Roof - Modified Bitumen	Low S Roofs	376	SF	6	2-5 years	Vegetation growth
	Roof Structure - Concrete	Low S Roofs	376	SF	7	10+ years	vegetation growth
	Access Ladder - Wood	Main Roof	2	EA	4	0-1 year	Homemade ladder, disintegrating
		Main Roof		LF	6		nomemade ladder, disintegrating
	Chimney - Metal Flue		42		_	10+ years	
	Coping - Stone	Main Roof	752	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	222	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	100	LF	6	6-10 years	
	Parapet - Parapet > 30"	Main Roof	652	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	20,644	SF	4	1-2 years	Soft spots and blisters throughou
	Roof Hatch - Metal	Main Roof	2	EA	4	2-5 years	Corroded old hatch
	Roof Structure - Concrete	Main Roof	20,644	SF	7	10+ years	
Walls							
	Cheek-Wall - Concrete	Entire Building	56	SF	6	6-10 years	
	Cornice - Masonry Projecting Limestone	Entire Building	2,341	LF	6	6-10 years	
	Cornice - Masonry Projecting Limestone	Entire Building	20	LF	5	0-1 year	Cracking.
	Exterior Walls - Brick	Entire Building	23,557	SF	6	6-10 years	-
	Exterior Walls - Brick	Entire Building	200	SF	4	1-2 years	Open joints, cracked bricks
	Exterior Walls - Prefabricated Metal Panel	Entire Building	600	SF	6	6-10 years	, , , , , , , , , , , , , , , , , , , ,

Campus Name: Thorp J Page : 17 of 53 Assessment Date: 10/02/2023



Category : Exterior

### James N Thorp Elementary School 8914 S Buffalo AVENUE, Chicago, IL 60617

**Building: Addition 1** 

Recommend

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wall	Fades Dellates	0.450	05	_	0.40	
	Exterior Walls - Stone-Cast	Entire Building	3,158	SF	5	6-10 years	
Window							
	Curtain wall - Glazed Double Pane	Entire Building	100	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	1,015	SF	6	6-10 years	
	Guard - Guards wire guard	Entire Building	36	SF	6	10+ years	
	Lintels - Steel	Entire Building	139	LF	6	6-10 years	
	Lintels - Stone	Entire Building	309	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,607	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	34	SF	5	6-10 years	
Catego	ry : Electrical		F	Ruildina	: Additi	on 1	
Guiogo			-	, and ing	. / taaiti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
	Exit Signs - Auditoium	Entire Building	10	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	10	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,186	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,938	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	2.867	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,245	SF	6	6-10 years	
	Security System - CCTV	Entire Building	44,037	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	44,037	SF	6	6-10 years	
Main Se	ruico						
IVIAIII SE	PA System	Entire Building	44,037	SF	6	6-10 years	
Power P	istribution						
. OWOI L	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Exposed live parts
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	0-1 year	Exposed live parts and deteriorating
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	, ,
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Exposed live parts
^	Manager Theorem 1	•	Dans : 40 of 50			-	A D-t 40/00/0000

Campus Name: Thorp J Page : 18 of 53 Assessment Date: 10/02/2023



Jatego	ry : Electrical		В	uilding	: Addition	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	4	0-1 year	Deteriorated or exposing live par
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EΑ	6	6-10 years	Botonorated or exposing into par
	Wall Distribution Fallow 100 000 amp	Littiro Building	_		Ü	o ro youro	
atego	ry : Fire Protection		В	uilding	: Additi		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
re Alar			•			•	
10 7 1101	Fire Alarm Strobe Lights	Entire Building	44,037	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	44,037	SF	6	6-10 years	
	File Alaini_System	Entire Building	44,037	SF	O	0-10 years	
atego	ry : Mechanical		В	uilding	: Additi	on 1	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
r Hand	lling Systems						
	Air Handling Unit- Built Up- Single Zone w/	B1 - Basement	1	EA	5	2-5 years	AHU B1- Serves Classrooms
	Air Tunnel- Steam Coils - 15001 - 25000 cfm						
	Air Intake	B1 - Basement	1	EA	5	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	B1 - Basement	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam	B1 - Basement	7	EA	6	6-10 years	
	Coil					•	
	Return Duct Work - Indoor- Vertical Shaft	B1 - Basement	100	LF	5	6-10 years	
	and Ducts					,	
	Zone Dampers	B1 - Basement	20	EA	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone-	B2 - Auditorium	1	ĒΑ	6	6-10 years	AHU B2 serves the auditorium.
	Steam Coils - 15001 - 25000 cfm	BE /taattoriam	•		O	o to youro	74 TO BE COLVED THE deditoriani.
	Air Intake	B2 - Auditorium	1	EA	5	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	B2 - Auditorium	1	EA	5	2-5 years	
	Return Duct Work - Indoor- Vertical Shaft	B2 - Auditorium	100	LF	5		
		B2 - Auditorium	100	LF	3	6-10 years	
	and Ducts	D0 0	4	<b>-</b> ^	_	0.40	ALUL DO th
	Air Handling Unit- Built Up- Single Zone-	B3 - Gym	1	EA	5	6-10 years	AHU B3 - serves the gyms.
	Steam Coils - 4000 - 8000 cfm	B0 0			_	0.40	
	Air Intake	B3 - Gym	1	EA	5	6-10 years	
	Auxiliaries - 4000 - 8000 cfm	B3 - Gym	1	EA	5	2-5 years	
	Return Duct Work - Indoor- Vertical Shaft	B3 - Gym	100	LF	5	6-10 years	
	and Ducts						
	Outdoor Return Fans- Air Handling Unit	Roof	1	EA	6	6-10 years	
	Type - 10001 - 20000 CFM						
	Outdoor Return Fans- Air Handling Unit	Roof	1	EA	6	6-10 years	
	Type - 10001 - 20000 CFM		·		-		
	Outdoor Return Fans- Air Handling Unit	Roof	1	EA	6	6-10 years	
	Type - 5000 - 10000 CFM	· · · · · · · · ·	•		Ŭ	5 .5 ,500.0	

Campus Name: Thorp J Page: 19 of 53 Assessment Date: 10/02/2023



Catego	Category : Mechanical			Building : Addition 1				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Condensate Pump	Entire Building	1	EA	5	2-5 years		
	Piping - Condensate Pipe- Steel	Entire Building	500	LF	6	6-10 years		
	Piping - Steam Pipe- Steel	Entire Building	500	LF	6	6-10 years		
	Steam Traps	Entire Building	50	EA	6	6-10 years		
_Heating_	Devices							
J	Fin Tube - Electric	1st Floor	18	LF	5	2-5 years		
	Radiators - Steam	Entire Building	17	EA	6	6-10 years		
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years		
	Wall Heater - Electric	Entire Building	4	EA	6	6-10 years		
_Tempera	ture Control							
•	DDC System	Entire Building	44,037	SF	2	0-1 year	Not operational	
	Thermostats - DDC	Entire Building	22	EA	6	6-10 years	·	
_Ventilatio	on							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	5	2-5 years		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	3	EA	6	6-10 years		
	Roof Mounted Duct Work	Roof	120	LF	6	6-10 years		

Category : Plumbing			В				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Piping_	Demostic Dining Hot Water Deturn Lines	Entire Duilding	44.027	SF	6	2.5.40000	
	Domestic Piping-Hot Water Return Lines	Entire Building	44,037	_	_	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	44,037	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	44,037	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	44,037	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	44,037	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	44,037	SF	6	2-5 years	
	Sanitary Piping	Entire Building	44,037	SF	5	2-5 years	
	Storm Piping	Entire Building	44,037	SF	5	2-5 years	
	Vent Piping	Entire Building	44,037	SF	5	2-5 years	
_Pumps_							

Campus Name: Thorp J Page : 20 of 53 Assessment Date: 10/02/2023



**Building: Addition 1** Category : Plumbing

Recommend Item - Type Location Quantity UOM Rank Replacement Comments Group Pumps - Sump-Duplex 6-10 years Basement EΑ 6

Cotogony . Boom Duilding . Addition 1

Category : Room		Building : Addition 1								
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
_Administ	rative Suites/Offices									
	Ceiling - Plaster/Drywall	1st - 120A Supply Rm / 122 Security	576	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st - 120A Supply Rm / 122 Security	1	EA	6	6-10 years				
	Floor - Carpet	1st - 120A Supply Rm / 122 Security	532	SF	6	6-10 years				
	Floor - Terrazzo	1st - 120A Supply Rm / 122 Security	28	SF	6	10+ years				
	Floor - Terrazzo	1st - 120A Supply Rm / 122 Security	16	SF	6	10+ years				
	Lighting - Pendent/Surface	1st - 120A Supply Rm / 122 Security	7	EA	7	6-10 years				
	Power Distribution	1st - 120A Supply Rm / 122 Security	6	EA	6	6-10 years				
	Storage/ Closet	1st - 120A Supply Rm / 122 Security	171	SF	7	10+ years				
	Walls - Plaster/Drywall	1st - 120A Supply Rm / 122 Security	619	SF	6	10+ years				
	Walls - Structural Glazed Tile	1st - 120A Supply Rm / 122 Security	619	SF	7	10+ years				
	Work SInk	1st - 120A Supply Rm / 122 Security	2	EA	7	10+ years	Quantity updated to match current observations			
	AC Unit	1st - 123 Main Office	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st - 123 Main Office	326	SF	6	10+ years				
	Doors - Transom Window	1st - 123 Main Office	9	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st - 123 Main Office	1	EA	6	6-10 years				
	Floor - Tile	1st - 123 Main Office	326	SF	6	10+ years				
	Lighting - Pendent/Surface	1st - 123 Main Office	3	EA	7	6-10 years				
	Power Distribution	1st - 123 Main Office	8	EA	6	10+ years				
	Storage/ Closet	1st - 123 Main Office	157	SF	7	10+ years				
	Walls - Plaster/Drywall	1st - 123 Main Office	763	SF	7	10+ years				
	AC Unit	1st - 125 Principal Office	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st - 125 Principal Office	718	SF	6	10+ years				
	Doors - Transom Window	1st - 125 Principal Office	9	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st - 125 Principal Office	2	EA	6	6-10 years				
	Floor - Carpet	1st - 125 Principal Office	718	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st - 125 Principal Office	12	EA	7	6-10 years				
	Power Distribution	1st - 125 Principal Office	11	EA	6	10+ years				
	Walls - Plaster/Drywall	1st - 125 Principal Office	1,184	SF	6	10+ years				
	Ceiling - Plaster/Drywall	1st - Gym Office/storage 120S	116	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st - Gym Office/storage 120S	1	EA	6	6-10 years				
	Floor - Tile	1st - Gym Office/storage 120S	116	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st - Gym Office/storage 120S	2	EA	7	6-10 years				
	Power Distribution	1st - Gym Office/storage 120S	2	EA	6	6-10 years				
	Walls - Masonry	1st - Gym Office/storage 120S	153	SF	7	10+ years				
	Walls - Plaster/Drywall	1st - Gym Office/storage 120S	153	SF	5	0-1 year	Cracking throughout.			
	Ceiling - Plaster/Drywall	Office/Copy Room 121 inside Main	137	SF	6	10+ years				
		Office								



Catego	ry : Room		Building : Addition 1						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	Office/Copy Room 121 inside Main Office	1	EA	6	6-10 years			
	Floor - Tile	Office/Copy Room 121 inside Main Office	137	SF	6	6-10 years			
	Lighting - Pendent/Surface	Office/Copy Room 121 inside Main Office	1	EA	7	6-10 years			
	Power Distribution	Office/Copy Room 121 inside Main Office	2	EA	6	10+ years			
	Walls - Plaster/Drywall	Office/Copy Room 121 inside Main Office	307	SF	6	10+ years			
	AC Unit	Teacher Lunchroom 228	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Teacher Lunchroom 228	616	SF	6	10+ years			
	Doors - Transom Window	Teacher Lunchroom 228	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	Teacher Lunchroom 228	1	EA	6	6-10 years			
	Floor - Carpet	Teacher Lunchroom 228	616	SF	7	6-10 years			
	Lighting - Pendent/Surface	Teacher Lunchroom 228	10	EA	7	6-10 years			
	Power Distribution	Teacher Lunchroom 228	6	EA	6	6-10 years			
	Storage/ Closet	Teacher Lunchroom 228	425	SF	7	6-10 years			
	Walls - Plaster/Drywall	Teacher Lunchroom 228	1,059	SF	6	10+ years			
	Work Sink	Teacher Lunchroom 228		EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Teachers Lounge 287	168	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Teachers Lounge 287	1	EA	6	6-10 years			
	Floor - Tile	Teachers Lounge 287	168	SF	6	6-10 years			
	Lighting - Pendent/Surface	Teachers Lounge 287	4	EA	7	6-10 years			
	Power Distribution	Teachers Lounge 287	4	EA	6	6-10 years			
	Walls - Plaster/Drywall	Teachers Lounge 287	406	SF	6	10+ years			
_Auditoriu	um & Theater								
	Balcony Seating	1st Floor	175	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	3,626	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	12	EA	6	6-10 years			
	Floor - Terrazzo	1st Floor	440	SF	6	10+ years			
	Floor - Tile/Sheet	1st Floor	3,186	SF	7	6-10 years			
	Lighting - Metal Halide/ High Pressure Sodium	1st Floor	6	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years			
	Lighting - Wall Mounted	1st Floor	8	EA	7	6-10 years			
	Main Floor Seating	1st Floor	368	EA	7	6-10 years			
	Sound System	1st Floor	2	EA	7	6-10 years			
	Stage	1st Floor	759	SF	6	6-10 years			
	Stage Curtain	1st Floor	5	EA	7	6-10 years			
	Stage Lift	1st Floor	1	EA	7	6-10 years			
	Stage Lighting System	1st Floor	10	EA	7	6-10 years			

Campus Name: Thorp J Page : 22 of 53 Assessment Date: 10/02/2023



Category : Room			В	Building : Addition 1					
_			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Stage-Stairs - Wood	1st Floor	5	LF	6	10+ years			
	Stairs - Terrazzo	1st Floor	62	LF	6	10+ years			
	Storage/ Closet	1st Floor	106	SF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	7,486	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	45	SF	4	1-2 years	Missing plaster, spalling, and holes		
	, .					,	by stage and by fire extinguisher		
Gvmnasi	ia.								
,	Ceiling - Plaster/Drywall	1st - 115 Gymnasium	2,867	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st - 115 Gymnasium	4	ĒΑ	6	6-10 years			
	Floor - Wood	1st - 115 Gymnasium	2,867	SF	6	10+ years			
	Lighting - Metal Halide/ High Pressure	1st - 115 Gymnasium	2	EA	7	6-10 years			
	Sodium	13t 110 Gymnasiani	_		,	o ro years			
	Lighting - Pendent/Surface	1st - 115 Gymnasium	10	EA	5	0-1 year	Re-lamp fixture		
	Storage/ Closet	1st - 115 Gymnasium	91	SF	7	6-10 years			
	Walls - Concrete Block	1st - 115 Gymnasium	1,204	SF	7	10+ years			
	Walls - Plaster/Drywall	1st - 115 Gymnasium	2,593	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st - 115 Gymnasium	1,446	SF	7	10+ years			
	Walls - Structural Glazed The	13t - 113 Gymnasium	1,440	Oi	,	10+ years			
ibrary									
	AC Unit	2nd - 227 Library/Clinic	1	EA	7	6-10 years			
	Casework	2nd - 227 Library/Clinic	66	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd - 227 Library/Clinic	1,100	SF	6	10+ years			
	Doors - Transom Window	2nd - 227 Library/Clinic	18	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd - 227 Library/Clinic	2	EA	6	6-10 years			
	Floor - Carpet	2nd - 227 Library/Clinic	985	SF	6	6-10 years			
	Floor - Carpet	2nd - 227 Library/Clinic	115	SF	4	1-2 years	Tearing carpet		
	Lighting - Pendent/Surface	2nd - 227 Library/Clinic	20	EA	7	6-10 years	-		
	Walls - Plaster/Drywall	2nd - 227 Library/Clinic	1,810	SF	6	10+ years			
MDF ID	E								
	Doors - Wood Doors inclu hw	2nd - 227A inside Library	1	EA	6	6-10 years			
	Finishes	2nd - 227A inside Library	126	SF	5	1-2 years	Missing tiles, active construction		
	Window AC Unit	2nd - 227A inside Library	1	EA	7	6-10 years	•		
/lechani	cal/ Service Rooms								
	Janitor's Closet	2nd Floor	29	SF	5	6-10 years			
	Storage Room	2nd Floor	232	SF	5	6-10 years	Storage 286		
	Air Intake Plenums	Basement	367	SF	7	10+ years			
	Air Tunnel	Basement	2,460	SF	7	10+ years			
	Auditorium Plenums	Basement	4,270	SF	7	10+ years			
	Boiler Room	Basement	2,006	SF	7	10+ years			
			2,006 6,574	SF	7	,			
	Crawl Space - Unfinished	Basement	0,574	SF	,	10+ years			

Campus Name: Thorp J Page : 23 of 53 Assessment Date: 10/02/2023



Catego	ry : Room		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	Basement	5	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	3,226	SF	7	10+ years	
	Storage Room	Basement	543	SF	5	10+ years	
Restroo	m						
1100000	Accessories	1st - Auditorium Men's Restroom	95	SF	7	6-10 years	
	710003301103	(out of order)	30	Oi.	,	o to years	
	Ceiling - Plaster/Drywall	1st - Auditorium Men's Restroom	95	SF	6	10+ years	
	Coming Tractorizing wan	(out of order)	00	O.	Ü	ioi youio	
	Doors - Wood Doors inclu hw	1st - Auditorium Men's Restroom	1	EA	6	6-10 years	
	Doors Wood Doors mold riw	(out of order)	•	L/\	O	o to years	
	Floor - Tile Ceramic/ Porcelain	1st - Auditorium Men's Restroom	95	SF	6	10+ years	
	1 1001 - The Gerannic/ 1 dicelain	(out of order)	33	Oi	U	10+ years	
	Lavatory	1st - Auditorium Men's Restroom	1	EA	7	6-10 years	
	Lavalory	(out of order)	'	LA	,	0-10 years	
	Lighting - Pendent/Surface	1st - Auditorium Men's Restroom	2	EA	7	6-10 years	
	Lighting - Fendent/Surface	(out of order)	۷	LA	,	0-10 years	
	Partitions	1st - Auditorium Men's Restroom	1	EA	7	6-10 years	
	Faritions		I	EA	1	0-10 years	
	Lleinala	(out of order)	4	EA	_	4.0	Daga mat want
	Urinals	1st - Auditorium Men's Restroom	1	EA	5	1-2 years	Does not work
	\A/=II= \	(out of order)	00	0.5	•	40	
	Walls - Masonry	1st - Auditorium Men's Restroom	99	SF	6	10+ years	
	W II DI ( /D II	(out of order)	00	0-	•	40	
	Walls - Plaster/Drywall	1st - Auditorium Men's Restroom	99	SF	6	10+ years	
	W . O	(out of order)				4.0	5
	Water Closet	1st - Auditorium Men's Restroom	1	EA	4	1-2 years	Does not work
		(out of order)					
	Accessories	1st - Boys	279	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Boys	279	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - Boys	279	SF	6	10+ years	
	Floor Drain	1st - Boys	1	EA	7	6-10 years	
	Hand Dryer	1st - Boys	1	EA	7	6-10 years	
	Lavatory	1st - Boys	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st - Boys	5	EA	7	6-10 years	
	Partitions	1st - Boys	1	EA	7	6-10 years	
	Urinals	1st - Boys	5	EA	7	6-10 years	
	Walls - Masonry	1st - Boys	301	SF	6	10+ years	
	Walls - Plaster/Drywall	1st - Boys	301	SF	6	10+ years	
	Water Closet	1st - Boys	1	ĒΑ	7	6-10 years	
	Accessories	1st - Girls	302	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Girls	302	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - Girls	302	SF	6	10+ years	
	Floor Drain	1st - Girls	1	EA	7	6-10 years	
	Hand Dryer	1st - Girls	1	EA	7	6-10 years	
	riana Diyei	131 - 01113	1	$\vdash \land$	,	o- 10 years	

Campus Name: Thorp J Page : 24 of 53 Assessment Date: 10/02/2023



Catego	ry : Room	-	В	uilding	: Additi	on 1	
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st - Girls	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st - Girls	4	EA	7	6-10 years	
	Partitions	1st - Girls	5	EA	7	6-10 years	
	Walls - Masonry	1st - Girls	352	SF	6	10+ years	
	Walls - Plaster/Drywall	1st - Girls	352	SF	7	10+ years	
	Water Closet	1st - Girls	5	EA	7	6-10 years	
	Accessories	1st - Women's Auditorium	94	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Women's Auditorium	94	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - Women's Auditorium	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st - Women's Auditorium	94	SF	6	10+ years	
	Floor Drain	1st - Women's Auditorium	1	EA	7	6-10 years	
	Hand Dryer	1st - Women's Auditorium	1	EA	7	6-10 years	
	Lavatory	1st - Women's Auditorium	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st - Women's Auditorium	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st - Women's Auditorium	1	EA	5	0-1 year	Re-lamp fixture
	Partitions	1st - Women's Auditorium	i 1	ĒΑ	7	6-10 years	rto lamp intere
	Walls - Masonry	1st - Women's Auditorium	101	SF	6	10+ years	
	Walls - Plaster/Drywall	1st - Women's Auditorium	101	SF	7	10+ years	
	Water Closet	1st - Women's Auditorium	101	EA	7	6-10 years	
	Accessories	1st - inside Kindergarten 129	68	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - inside Kindergarten 129	68	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - inside Kindergarten 129	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st - inside Kindergarten 129	68	SF	6	10+ years	
	Hand Dryer	1st - Inside Kindergarten 129	1	EA	7	6-10 years	
		1st - inside Kindergarten 129	2	EA	6	<u>-</u>	
	Lavatory	1st - Inside Kindergarten 129	1	EA	-	10+ years	
	Lighting - Pendent/Surface Walls - Masonry		20	SF	6 7	6-10 years	
		1st - inside Kindergarten 129		SF SF		10+ years	Overetity considered to include heath
	Walls - Plaster/Drywall	1st - inside Kindergarten 129	64		6	10+ years	Quantity updated to include both items
	Walls - Plaster/Drywall	1st - inside Kindergarten 129	30	SF	5	1-2 years	Water damage
	Water Closet	1st - inside Kindergarten 129	1	EA	7	6-10 years	
	Accessories	1st - staff unisex	59	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - staff unisex	59	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st - staff unisex	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st - staff unisex	59	SF	6	10+ years	
	Floor Drain	1st - staff unisex	1	EA	7	6-10 years	
	Hand Dryer	1st - staff unisex	1	EA	7	6-10 years	
	Lavatory	1st - staff unisex	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st - staff unisex	1	EA	7	6-10 years	
	Walls - Masonry	1st - staff unisex	80	SF	6	10+ years	
	Walls - Plaster/Drywall	1st - staff unisex	84	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st - staff unisex	5	SF	7	10+ years	
	Water Closet	1st - staff unisex	1	EΑ	7	6-10 years	
	Accessories	2nd - Boys	304	SF	7	6-10 years	
			30 .	-	•	3 .0 ,00.0	

Campus Name: Thorp J Page : 25 of 53 Assessment Date: 10/02/2023



Category : Room			Building : Addition 1					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	2nd - Boys	304	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd - Boys	304	SF	6	10+ years		
	Floor Drain	2nd - Boys	1	EA	7	6-10 years		
	Hand Dryer	2nd - Boys	1	EA	7	6-10 years		
	Lavatory	2nd - Boys	4	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd - Boys	5	EA	7	6-10 years		
	Partitions	2nd - Boys	1	EA	7	6-10 years		
	Urinals	2nd - Boys	5	EA	7	6-10 years		
	Walls - Masonry	2nd - Boys	501	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd - Boys	501	SF	6	10+ years		
	Water Closet	2nd - Boys	1	EA	7	6-10 years		
	Accessories	2nd - Girls	350	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd - Girls	350	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd - Girls	350	SF	6	10+ years		
	Floor Drain	2nd - Girls	1	EA	7	6-10 years		
	Hand Dryer	2nd - Girls	1	EA	7	6-10 years		
	Lavatory	2nd - Girls	4	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd - Girls	4	EA	7	6-10 years		
	Partitions	2nd - Girls	5	EA	7	6-10 years		
	Walls - Masonry	2nd - Girls	513	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd - Girls	513	SF	7	10+ years		
	Water Closet	2nd - Girls	5	EA	7	6-10 years		
	Accessories	Inside 287 Teachers Lounge	76	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Inside 287 Teachers Lounge	76	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Inside 287 Teachers Lounge	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Inside 287 Teachers Lounge	60	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Inside 287 Teachers Lounge	16	SF	4	1-2 years	Cracking	
	Lavatory	Inside 287 Teachers Lounge	1	EA	7	6-10 years	•	
	Lighting - Pendent/Surface	Inside 287 Teachers Lounge	2	EA	7	6-10 years		
	Partitions	Inside 287 Teachers Lounge	2	EA	7	6-10 years		
	Walls - Plaster/Drywall	Inside 287 Teachers Lounge	72	SF	6	10+ years		
	Walls - Plaster/Drywall	Inside 287 Teachers Lounge	10	SF	5	1-2 years	Cracking	
	Walls - Tile Ceramic/ Porcelain	Inside 287 Teachers Lounge	76	SF	7	10+ years	3	
	Water Closet	Inside 287 Teachers Lounge	2	ĒΑ	7	6-10 years	Updated quantity	
	Accessories	Unisex 121 in Main Office	26	SF	7	6-10 years	- p	
	Ceiling - Plaster/Drywall	Unisex 121 in Main Office	26	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Unisex 121 in Main Office	1	ĒΑ	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Unisex 121 in Main Office	26	SF	6	10+ years		
	Lavatory	Unisex 121 in Main Office	1	EA	7	6-10 years		
	Lighting - Pendent/Surface	Unisex 121 in Main Office	1	EΑ	7	6-10 years		
	Walls - Plaster/Drywall	Unisex 121 in Main Office	85	SF	6	10+ years		
	Water Closet	Unisex 121 in Main Office	1	EA	7	6-10 years		
	114.5. 5.0001	STROOK 121 III Wall STROO		_, .	•	5 TO yours		

Campus Name: Thorp J Page : 26 of 53 Assessment Date: 10/02/2023



Catego	ry : Classroom		В	uilding	: Additi		914 3 Bullalo AVENDE, Chicago, il 60617
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #124 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	712	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	712	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	11	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,221	SF	7	10+ years	
_Classroo	om #126 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	722	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	717	SF	7	6-10 years	
	Floor - Tile	1st Floor	5	SF	4	0-1 year	Cracked and chipping
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	11 3
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,174	SF	7	10+ years	
_Classroo	om #127 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	32	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	1st Floor	768	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	19	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,281	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #129 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	19	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,194	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Terrazzo	1st Floor	99	SF	6	10+ years	
	1 1001 10110220	13.1 1001	33	01	U	ioi yeais	

Campus Name: Thorp J Page : 27 of 53 Assessment Date: 10/02/2023



Catego	ry : Classroom		В	uilding	: Addition	on 1	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	1,065	SF	6	6-10 years	
	Floor - Tile	1st Floor	30	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	11	LF	7	6-10 years	
	Storage/ Closet	1st Floor	247	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,247	SF	7	10+ years	
	Work Sink	1st Floor	3	ĒΑ	7	6-10 years	
Classroo	om #224 (Store Room)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	716	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	•	Undated quantity
	Doors - Steel Doors incl hw		2	EA		2-5 years	Updated quantity
		2nd Floor			6	6-10 years	
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,255	SF	7	10+ years	
Classroo	om #225 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	720	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	9	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	7	10+ years	
	Wireless System	2nd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #226 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	58	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	832	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	832	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,500	SF	7		
				SF SF		10+ years	Hala through placter
	Walls - Plaster/Drywall	2nd Floor	5		5	1-2 years	Hole through plaster
	Wireless System	2nd Floor	1	EA	7	6-10 years	

Campus Name: Thorp J Page : 28 of 53 Assessment Date: 10/02/2023



Catego	ory : Classroom		В	uilding	: Additi		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #227 (Art Room)						
Ciassiuc	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	649	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	75	SF	4	0-1 year	Water damage, crumbling plaster an
	Celling - Flaster/Drywall	2110 1 1001	73	OI.	7	0-1 year	paint
	Chalk Board	2nd Floor	46	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	706	SF	6	6-10 years	
	Floor - Tile	2nd Floor	18	SF	4	0-1 year	Damaged, subfloor exposed
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	- ag. a, a a ap. a a
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6	SF	5	1-2 years	Cracking and fallen plaster
	valle i lastel/Brywall	2110 1 1001	Ü	O.	Ü	1 2 youro	Cracking and ranon places
Classroc	om #229 (Office)						
	AC Units	2nd Floor	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	720	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	7	6-10 years	
Catego	ory : Interior		В	uildina	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	25	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,192	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	14	SF	6	6-10 years	
	Doors - Wood Doors include hw	1st Floor	11	EA	6	6-10 years	
	Drinking Fountains - Double Fountain	1st Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	183	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	3,034	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	40	EA	7	6-10 years	
			11	LF	7	10+ years	
	Stairs - Concrete Stairs	1st Floor				,	
	Stairs - Concrete Stairs Student Lockers - One Tier	1st Floor	57	EA	7	6-10 years	
	Stairs - Concrete Stairs Student Lockers - One Tier Walls - Concrete Block	1st Floor 1st Floor	57 1,025	EA SF	7 7	10+ years	
	Stairs - Concrete Stairs Student Lockers - One Tier Walls - Concrete Block Walls - Masonry	1st Floor	57	EA SF SF	7	10+ years 10+ years	
	Stairs - Concrete Stairs Student Lockers - One Tier Walls - Concrete Block	1st Floor 1st Floor	57 1,025	EA SF	7 7	10+ years	



Catego	Category : Interior			uilding	: Additi	on 1	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Water damage.
	Drinking Fountains - Double Fountain	2nd Floor	2	EΑ	7	6-10 years	
	Floor - Terrazzo	2nd Floor	2,364	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	158	SF	7	6-10 years	
	Lighting - Chandelier, Incandescent	2nd Floor	16	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EΑ	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	93	EΑ	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	11	EA	5	1-2 years	Lockers damaged so they will not close
	Walls - Concrete Block	2nd Floor	870	SF	7	10+ years	
	Walls - Masonry	2nd Floor	430	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,290	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Plaster damaged
Safety							
	Camera Viewing Station	Entire building	1	EA	7	6-10 years	
	Metal Detector	Entire building	1	EΑ	7	6-10 years	
	Security Cameras	Entire building	2	EA	7	6-10 years	
	Security Cameras	Entire building	6	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Stair 3 (North)	336	SF	6	10+ years	
	Floor - Terrazzo	Stair 3 (North)	112	SF	6	10+ years	
	Handrails	Stair 3 (North)	72	LF	7	6-10 years	
	Lighting - Pendent/Surface	Stair 3 (North)	2	EA	7	6-10 years	
	Stairs - Terrazzo	Stair 3 (North)	36	LF	7	10+ years	
	Walls - Plaster/Drywall	Stair 3 (North)	660	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair 4 (South East)	336	SF	6	10+ years	
	Floor - Terrazzo	Stair 4 (South East)	112	SF	6	10+ years	
	Handrails	Stair 4 (South East)	72	LF	7	6-10 years	
	Lighting - Pendent/Surface	Stair 4 (South East)	2	EA	7	6-10 years	
	Stairs - Terrazzo	Stair 4 (South East)	36	LF	6	10+ years	
	Walls - Plaster/Drywall	Stair 4 (South East)	660	SF	6	10+ years	

Campus Name: Thorp J Page : 30 of 53 Assessment Date: 10/02/2023





Category : Exterior **Building: Addition 2** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
- Entrance	·		•			•	
	Exterior Doors - Store Front	#2- SE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2- SE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2- SE	10	LF	5	10+ years	
	Exterior Stairs - Stone	#2- SE	6	LF	6	10+ years	
	Entrance Control - Audio and Video	#3- SE	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#3- SE	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#3- SE	3	LF	4	0-1 year	Broken step, some repair
	Exterior Stairs - Stone	#3- SE	13	LF	6	6-10 years	
	Power Door Operator and Controls	#3- SE	2	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#3- SE	55	LF	6	6-10 years	
	Ramps - Concrete	#3- SE	24	LF	6	6-10 years	
	Exterior Doors - Store Front	#4- S	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#4- S	10	LF	6	10+ years	
	Exterior Stairs - Stone	#4- S	9	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4.1- SW- L.R.	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#4.1- SW- L.R.	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#4.1- SW- L.R.	39	LF	6	10+ years	Repaired
	Stair Handrail - Steel_Stair Handrail	#4.1- SW- L.R.	55	LF	6	6-10 years	·
	Exterior Doors - Exterior Steel Door	#4.2- SW- B.R.	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#4.2- SW- B.R.	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#4.2- SW- B.R.	5	LF	5	1-2 years	Crack in the landing with moss growing
	Exterior Stairs - Concrete	#4.2- SW- B.R.	34	LF	5	6-10 years	3 - 3
	Stair Handrail - Steel Stair Handrail	#4.2- SW- B.R.	55	LF	6	6-10 years	
	Entrance Control - Audio and Video	#5- SW	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#5- SW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5- SW	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5- SW	18	LF	6	6-10 years	
	Exterior Stairs - Stone	#5- SW	6	LF	6	6-10 years	
Foundati	on						
	Foundation - Concrete	Entire Building	534	LF	7	10+ years	
	Foundation - Concrete	Entire Building	100	LF	6	1-2 years	boiler room is flooding from the slab
		Ç				•	below in from some cracks in the walls. Storage room has mold growing on the floor
	Superstructure - Concrete	Entire Building	47,014	SF	7	10+ years	
Lighting							
- 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	6-10 years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Addition	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	2-5 years	
Roof Sys	stem						
-	Access Ladder - Metal	Main Roof	2	EA	5	2-5 years	Old ladder does not go up to the top
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	36	LF	6	6-10 years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	4	LF	5	1-2 years	Open joints at top of chimney
	Coping - Metal	Main Roof	717	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Main Roof	96	LF	6	6-10 years	
	Roof - Modified Bitumen	Main Roof	19,556	SF	4	0-1 year	Blistering throughout, some soft spots, worn surfaces
	Roof Hatch - Metal	Main Roof	2	EA	5	2-5 years	Seals missing, hatch, beginning to corrode
	Roof Hatch - Metal	Main Roof	1	EA	3	2-5 years	Unused
	Roof Structure - Concrete	Main Roof	19,556	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	210	SF	6	10+ years	
	Canopy - Fabric	Entire Building	195	SF	7	10+ years	New
	Exterior Walls - Brick	Entire Building	3,252	SF	6	6-10 years	
	Exterior Walls - Stone-Cast	Entire Building	24	SF	5	10+ years	
Windows							
	Curtain wall - Louver	Entire Building	99	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	192	SF	6	6-10 years	
	Guard - Guards wire guard	Entire Building	60	SF	6	10+ years	
	Lintels - Steel	Entire Building	33	LF	6	6-10 years	
	Windows - Insulated Panel	Entire Building	784	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,184	SF	5	6-10 years	
Catego	ry : Electrical		В	uilding	: Additio	on 2	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncy System						
-merger	Automatic Transfer Switch	Electrical Room	4	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	6	6-10 years	
	Exit Signs - Corndors and Stairs  Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	4,744	SF	6	6-10 years	

Campus Name: Thorp J Page : 32 of 53 Assessment Date: 10/02/2023



Catego	ry : Electrical		В	uilding	: Additi	on 2	·	
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Stairs Emergency A/C Power - Lunchrooms	Entire Building	2,171	SF	6	6.10 , , , , , , , ,		
	Emergency A/C Power - Students Toilets		1,284	SF SF	6	6-10 years		
		Entire Building		SF SF		6-10 years		
	Security System - CCTV	Entire Building	47,014		6	6-10 years		
	Security System - Intrusion Detection	Entire Building	47,014	SF	6	6-10 years		
	Emergency Generator- Outdoor- Natural Gas - 101 - 150 KW	West Courtyard	1	EA	6	6-10 years		
Main Se	rvice							
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years		
	PA System	Entire Building	47,014	SF	3	0-1 year	Not working anywhere, obsolete system, not tied with main building	
Power D	istribution							
	Lighting and Power Panels - 100 A	Boiler Room and Basement	2	EA	7	10+ years		
	Lighting and Power Panels - 100 A	Boiler Room and Basement	2	EA	4	0-1 year	Deteriorated/rusting	
	Lighting and Power Panels - Above 100 A	Boiler Room and Basement	5	EA	7	10+ years		
	Lighting and Power Panels - Above 100 A	Boiler Room and Basement	2	EA	6	10+ years		
	Lighting and Power Panels - Above 100 A	Boiler Room and Basement	3	EA	4	0-1 year	Exposed live parts or deteriorated	
	Main Distribution Panels - 400 - 600 amp	Boiler Room and Basement	1	EA	7	10+ years		
	Main Distribution Panels - Less than 400 amp	Boiler Room and Basement	2	EA	4	1-2 years	Deteriorating	
Catego	ry : Fire Protection		Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar	m		· ·			•		
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years		
	Fire Alarm Strobe Lights	Entire Building	47,014	SF	6	6-10 years		
	Fire Alarm_System	Entire Building	47,014	SF	6	6-10 years		
Catego	ry : Mechanical		R	uildina	: Additi	on 2		
Calego	i y . Mechanicai			unung	. Additi	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	lling Systems		Sauriny	00111	- Carrit	. topiasomont		
	Air Handling Unit- Package Single Zone-	HVU1 - Crawl Space	1	EA	5	6 10 years	Coil leaking, rusting on interior.	
	Indoor- Steam Coils - 4000-8000 cfm	TIVOT - Clawi Space	1	EA	ວ	6-10 years	Serves cafeteria - HVU-1	
	Air Intake	HVU1 - Crawl Space	1	EA	5	6-10 years		
Boiler Sy	vstems							
	Boiler Auxiliary- Scotch Marine- Steam Low	Entire Building	2	EA	6	10+ years		

Campus Name: Thorp J Page : 33 of 53 Assessment Date: 10/02/2023



Catego	Category : Mechanical			Building : Addition 2					
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Pressure Boiler - 101 - 150 HP								
	Chemical Feed System	Entire Building	1	EA	5	0-1 year	Control heavily corroded		
	Chemical Feed System	Entire Building	1	EA	4	0-1 year	Glycol feed, currently not in use		
	Chemical Feeder	Entire Building	1	EA	5	2-5 years			
	Combustion Dampers	Entire Building	2	EA	6	6-10 years			
	Condensate Pump	Entire Building	1	EA	5	0-1 year	Piping corroding		
	Condensate Pump	Entire Building	1	EA	5	0-1 year	Piping corroding		
	Feed Water Pumps and Tank	Entire Building	1	EA	5	1-2 years	Tank leaking, piping corroding		
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	10+ years			
	Steam- Low Pressure Boiler - 101 - 150 HP	· ·				•			
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EΑ	6	10+ years			
	Steam- Low Pressure Boiler - 101 - 150 HP	3				,			
	Piping - Condensate Pipe- Steel	Entire Building	500	LF	6	10+ years			
	Piping - Steam Pipe- Steel	Entire Building	500	LF	6	10+ years			
	Steam Traps	Entire Building	44	EA	5	6-10 years			
	Vacuum Pump	Entire Building	2	EA	5	0-1 year	Piping corroding		
	vacaam vamp	Ziiiii o Dallallig	_	_, .	Ü	o i your	r iping corroanig		
Heat Exc	changers								
	Heat Exchanger - Steam to Hot Water Shell	Boiler Room	1	EA	6	6-10 years			
	Туре					•			
Heating	Devices								
	Unit Heater - Steam	Basement	3	EA	5	2-5 years			
	Fin Tube - Steam	Entire Building	4	LF	5	2-5 years			
	Cabinet Heaters - With Steam Coil	Entire Building	10	EA	6	6-10 years			
	Cabinet Heaters With Steam Con	Ziiiii o Dallallig	.0	_, .	Ü	o lo youro			
Mechani	cal Plumbing								
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	2-5 years			
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	2-5 years			
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	10+ years			
Tempera	ature Control								
· ompore	DDC System	Entire Building	47,014	SF	2	0-1 year	Not operational		
	Electric Thermostat	Entire Building	3	EA	5	2-5 years			
	Thermostats - DDC	Entire Building	35	EΑ	6	6-10 years			
		3				,			
Unit Ven									
	Unit Ventilators- Floor Mounted- Steam	Entire Building	34	EA	4	1-2 years	Over 25 years old with various issue		
	Heating Coils Only						throughout		
_Ventilatio	on								
ventuali	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof and Kitchen	1	EA	5	2-5 years			
	Extract and red mounted 1001 0000	rest and raterion	'		J	2 0 yours			

Campus Name: Thorp J Page : 34 of 53 Assessment Date: 10/02/2023



#### James N Thorp Elementary School

100	Schools					8	914 S Buffalo AVENUE, Chicago, IL 60617
Category : Mechanical			Building : Addition 2				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	CFM Exhaust Fans- Roof Mounted - 1501 - 8000	Roof and Kitchen	4	EA	5	6-10 years	
	CFM Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof and Kitchen	1	EA	3	0-1 year	Missing top cover and belt
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof and Kitchen	3	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Roof and Kitchen	1	EA	2	0-1 year	No fire suppression over open flame cookware
Category : Plumbing			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EΑ	6	10+ years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	10+ years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	47,014	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	47,014	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	47,014	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	47,014	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	47,014	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	47,014	SF	6	6-10 years	
	Sanitary Piping	Entire Building	47,014	SF	5	6-10 years	
	Storm Piping	Entire Building	47,014 47,014	SF SF	5	2-5 years	
	Vent Piping	Entire Building	47,014	SF	5	2-5 years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	6	10+ years	
	Pumps - Sump-Duplex	Basement	1	EΑ	5	2-5 years	Landad Scalauct St
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	Located in elevator pit.
Category : Room		Building : Addition 2					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administ	rative Suites/Offices		-				
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	1st Floor 100R Teacher's Lounge 1st Floor 100R Teacher's Lounge	158 1	SF EA	6 6	10+ years 6-10 years	



Category : Room			Building : Addition 2						
<u> </u>						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	1st Floor 100R Teacher's Lounge	158	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor 100R Teacher's Lounge	2	EΑ	7	6-10 years			
	Power Distribution	1st Floor 100R Teacher's Lounge	2	EA	6	6-10 years			
	Walls - Concrete Block	1st Floor 100R Teacher's Lounge	469	SF	7	10+ years			
	AC Unit	1st Floor 105 Main Office	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor 105 Main Office	856	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor 105 Main Office	1	EA	6	6-10 years			
	Floor - Tile	1st Floor 105 Main Office	856	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor 105 Main Office	16	EA	7	6-10 years			
	Power Distribution	1st Floor 105 Main Office	6	EA	6	6-10 years			
	Storage/ Closet	1st Floor 105 Main Office	46	SF	7	6-10 years			
	Walls - Concrete Block	1st Floor 105 Main Office	896	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor 105 Main Office	75	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor 105 Main Office	367	SF	7	10+ years			
	Work Sink	1st Floor 105 Main Office	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	200R Counselor's Office	6	SF	6	10+ years			
	Ceiling - Plaster/Drywall	200R Counselor's Office	112	SF	6	10+ years			
	Doors - Wood Doors inclu hw	200R Counselor's Office	1	EA	6	6-10 years			
	Floor - Tile	200R Counselor's Office	118	SF	6	6-10 years			
	Lighting - Pendent/Surface	200R Counselor's Office	2	EA	7	6-10 years			
	Power Distribution	200R Counselor's Office	4	EA	6	6-10 years			
	Walls - Concrete Block	200R Counselor's Office	425	SF	7	10+ years			
	Ceiling - Exposed	Basement - Kitchen Office	72	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Basement - Kitchen Office	1	EA	6	6-10 years			
	Floor - Tile	Basement - Kitchen Office	72	SF	6	6-10 years			
	Lighting - Pendent/Surface	Basement - Kitchen Office	1	EA	7	6-10 years			
	Power Distribution	Basement - Kitchen Office	2	EA	6	6-10 years			
	Walls - Concrete Block	Basement - Kitchen Office	70	SF	7	10+ years			
	Walls - Plaster/Drywall	Basement - Kitchen Office	70	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Engineer's Office	131	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Engineer's Office	1	EΑ	6	10+ years			
	Floor - Tile	Engineer's Office	131	SF	6	10+ years			
	Lighting - Pendent/Surface	Engineer's Office	2	EA	6	6-10 years			
	Power Distribution	Engineer's Office	4	EA	6	10+ years			
	Storage/ Closet	Engineer's Office	24	SF	7	10+ years			
	Walls - Concrete Block	Engineer's Office	265	SF	6	10+ years			
	Walls - Plaster/Drywall	Engineer's Office	105	SF	6	10+ years			
_Clinic									
CIIIIC	Ceiling - Plaster/Drywall	Nurse's Office 275	130	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Nurse's Office 275	14	SF	5	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	Nurse's Office 275	1	EA	6	6-10 years			
	Floor - Tile/Sheet	Nurse's Office 275	144	SF	7	6-10 years			
	Lighting - Pendent/Surface	Nurse's Office 275	1	EA	7	6-10 years			
						-			

Campus Name: Thorp J Page : 36 of 53 Assessment Date: 10/02/2023



Catego	ry : Room		В	uilding	: Addition	on 2	
						Recommend	
Group		Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Nurse's Office 275	1	EA	6	6-10 years	
	Walls - Concrete Block	Nurse's Office 275	278	SF	7	6-10 years	
Kitchen							
KITOI IOI I	Ceiling - Plaster/Drywall	Basement	553	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	2	ĒΑ	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement	1	ΕA	6	6-10 years	
	Floor - Tile	Basement	553	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement	9	ĒΑ	7	6-10 years	
	Serving Line	Basement	16	LF	7	6-10 years	
	Storage/ Closet	Basement	156	SF	7	6-10 years	
	Walls - Concrete Block	Basement	720	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	223	SF	7	10+ years	
	Walle Structural Clazed File	Bacoment	220	Oi	•	101 youro	
ocker/S	hower Room Accessories	Basement - inside kitchen	0.4	SF	7	6.10 veers	
			84	SF SF		6-10 years	
	Ceiling - Plaster/Drywall	Basement - inside kitchen	84		6	10+ years	
	Doors - Wood Doors inclu hw	Basement - inside kitchen	2	EA SF	6	6-10 years	
	Floor - Concrete	Basement - inside kitchen	84		5	6-10 years	
	Lavatory	Basement - inside kitchen	1	EA	7	6-10 years	
	Lighting - Lay-in	Basement - inside kitchen	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement - inside kitchen	1	ΕA	7	6-10 years	
	Student Lockers - One Tier	Basement - inside kitchen	8	EA	6	6-10 years	
	Walls - Concrete Block	Basement - inside kitchen	214	SF	7	10+ years	
	Accessories	Basement Locker Room Restroom	67	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement Locker Room Restroom	67	SF	7	6-10 years	Deficiency fixed
	Doors - Wood Doors inclu hw	Basement Locker Room Restroom	1	EA	6	10+ years	
	Floor - Concrete	Basement Locker Room Restroom	67	SF	5	10+ years	
	Lavatory	Basement Locker Room Restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement Locker Room Restroom	1	EA	6	6-10 years	
	Walls - Concrete Block	Basement Locker Room Restroom	161	SF	6	10+ years	
	Water Closet	Basement Locker Room Restroom	1	EA	6	10+ years	
unch &	Multipurpose Room						
	AC Unit	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	2,171	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	4	EA	6	6-10 years	
	Floor - Tile	Basement	2,171	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement	26	EA	7	6-10 years	
	Serving Line	Basement	6	LF	7	6-10 years	
	Storage/ Closet	Basement	373	SF	7	6-10 years	
	Walls - Concrete Block	Basement	1,203	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	720	SF	7	10+ years	

Campus Name: Thorp J Page : 37 of 53 Assessment Date: 10/02/2023



Catego	ry : Room		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	35	SF	5	6-10 years	
	Storage Room	1st Floor	44	SF	7	6-10 years	
	Janitor's Closet	2nd Floor	35	SF	5	6-10 years	
	Mechanical/ Service Rooms	2nd Floor	50	SF	5	10+ years	Elevator Machine Room inside 200R.
	Wednameal/ Gervice Rooms	2110 1 1001	00		0	101 years	water damage to ceiling
	Storage Room	2nd Floor	272	SF	7	6-10 years	
	Storage Room	2nd Floor	44	SF	5	6-10 years	Storage 272B, water damage to ceiling
	Boiler Room	Basement	2,610	SF	5	10+ years	35g
	Crawl Space - Unfinished	Basement	2,960	SF	5	10+ years	
	Janitor's Closet	Basement	65	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	2,390	SF	5	10+ years	
	Storage Room	Basement	4,612	SF	4	1-2 years	Water damage throughout.
	Glorage Room	Dasement	7,012	OI.	7	1-2 years	water damage imoughout.
Restroor							
	Accessories	1st Floor	306	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	298	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	8	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	306	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	6-10 years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	6-10 years	
	Urinals	1st Floor	5	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	758	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	6-10 years	
	Accessories	1st Floor	336	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	336	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	336	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	6-10 years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	•	
	Partitions	1st Floor	3 7	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	· · · · · · · · · · · · · · · · · · ·	SF	7	6-10 years	
	Walis - Structural Glazed Tile Water Closet	1st Floor 1st Floor	762 6	SF EA	7 7	10+ years	
						6-10 years	Not working
	Water Closet	1st Floor	1	EA	4	1-2 years	Not working
	Accessories	1st Floor	61	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	61	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	61	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Additi	on 2	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	94	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	37	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	54	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	6-10 years	
	Accessories	2nd Floor	61	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	61	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	61	SF	7	10+ years	
	Floor Drain	2nd Floor	1	ĒΑ	7	6-10 years	
	Lavatory	2nd Floor	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EΑ	5	1-2 years	Missing cover
	Walls - Concrete Block	2nd Floor	94	SF	7	10+ years	g cover
	Walls - Plaster/Drywall	2nd Floor	37	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	54	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	6-10 years	
	Accessories	2nd Floor	336	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	336	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	336	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	7	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	762	SF	7	10+ years	
	Water Closet	2nd Floor	702	EA	7	6-10 years	
	Accessories	2nd Floor	306	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	306	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	306	SF	6	10+ years	
	Floor Drain	2nd Floor	300	EA	7	6-10 years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	•	2nd Floor	3	EA	7		
	Lavatory Lighting - Pendent/Surface	2nd Floor 2nd Floor	3 5	EA EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7 7	6-10 years	
			5	EA		6-10 years	
	Urinals Walls Structural Clazed Tile	2nd Floor		SF	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	758 2	SF EA	7 7	10+ years	
	Water Closet	2nd Floor Basement Men's Locker Room	31	SF	<i>7</i> 5	6-10 years	
	Accessories		_	SF SF		6-10 years	Water damage
	Ceiling - Plaster/Drywall	Basement Men's Locker Room	31		4	0-1 year	Water damage
	Doors - Steel Doors incl hw	Basement Men's Locker Room	1	EA	6	10+ years	
	Floor - Concrete	Basement Men's Locker Room	31	SF	5	10+ years	
	Lavatory	Basement Men's Locker Room	1	EA	6	10+ years	

Campus Name: Thorp J Page : 39 of 53 Assessment Date: 10/02/2023



Catego	ry : Room		Building : Addition 2							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Wall Mounted	Basement Men's Locker Room	1	EA	6	6-10 years				
	Walls - Concrete Block	Basement Men's Locker Room	75	SF	6	10+ years				
	Water Closet	Basement Men's Locker Room	1	EA	6	6-10 years				
	Accessories	Engineer's Office	29	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Engineer's Office	29	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years				
	Floor - Tile	Engineer's Office	29	SF	7	6-10 years	Deficiency fixed			
	Lavatory	Engineer's Office	1	EA	7	6-10 years				
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	6-10 years				
	Walls - Concrete Block	Engineer's Office	30	SF	7	10+ years				
	Walls - Plaster/Drywall	Engineer's Office	41	SF	7	10+ years				
	Water Closet	Engineer's Office	1	EA	6	6-10 years				
	Accessories	Nurse Restroom 275	36	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Nurse Restroom 275	36	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	Nurse Restroom 275	1	EA	7	6-10 years				
	Floor - Tile	Nurse Restroom 275	30	SF	6	6-10 years				
	Floor - Tile	Nurse Restroom 275	6	SF	5	1-2 years	Broken and loose tiles, suspect asbestos tile			
	Lavatory	Nurse Restroom 275	1	EA	4	1-2 years	Hardware rusted			
	Lighting - Pendent/Surface	Nurse Restroom 275	1	EA	5	0-1 year	Relamp			
	Lighting - Wall Mounted	Nurse Restroom 275	1	EA	5	1-2 years	Missing cover, relamp			
	Partitions	Nurse Restroom 275	1	EA	5	1-2 years	Hardware missing			
	Walls - Concrete Block	Nurse Restroom 275	76	SF	7	6-10 years	· ·			
	Water Closet	Nurse Restroom 275	1	EA	7	6-10 years				
	Accessories	Restroom in 101	30	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Restroom in 101	30	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Restroom in 101	1	EA	6	6-10 years				
	Floor - Tile	Restroom in 101	30	SF	6	6-10 years				
	Lavatory	Restroom in 101	1	EA	7	6-10 years				
	Lighting - Pendent/Surface	Restroom in 101	1	EA	7	6-10 years				
	Walls - Concrete Block	Restroom in 101	74	SF	7	10+ years				
	Water Closet	Restroom in 101	1	EA	7	6-10 years				
	Accessories	Restroom in 103	30	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Restroom in 103	30	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Restroom in 103	1	EA	6	6-10 years				
	Floor - Tile	Restroom in 103	30	SF	6	6-10 years				
	Lavatory	Restroom in 103	1	EA	7	6-10 years				
	Lighting - Pendent/Surface	Restroom in 103	1	EA	7	6-10 years				
	Walls - Concrete Block	Restroom in 103	73	SF	7	10+ years				
	Water Closet	Restroom in 103	1	EA	7	6-10 years				
						- -				

Campus Name: Thorp J Page : 40 of 53 Assessment Date: 10/02/2023



Catego	ry : Classroom		В	uilding	: Additi		3314 G Bullalo AVENGE, Glileago, le 60017
				Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #100 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	896	SF	7	10+ years	
	Walls - Collete Block	13111001	090	OI.	,	10+ years	
Classroo	om #101 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,031	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,031	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	<sup>′</sup> 16	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	90	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,071	SF	7	10+ years	
	Work Sink	1st Floor	1	EΑ	7	6-10 years	
Classroo	om #102 (Kindergarten)						
Classion	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor		EA	7	6-10 years	
	Marker Board	1st Floor	16 18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	896	SF	7		
	Work Sink	1st Floor		EA	7	6-10 years	
	VVORK SINK	1St Floor	1	EA	7	10+ years	
_Classroo	om #103 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	856	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,050	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
		.555.	·		•	,	



Catego	ry : Classroom		В	uilding	: Additi	on 2	· •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #104 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	1st Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	896	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #106 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	896	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	879	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	879	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	890	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	75	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	816	SF	6	6-10 years	
	Floor - Tile	1st Floor	40	SF	4	1-2 years	Cracking and chipping tiles
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	7	6-10 years	3 3
	Marker Board	1st Floor	18	LF	7	6-10 years	
						-	



Catego	ry : Classroom		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	896	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	896	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	1st Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	896	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	6-10 years	
Classroo	om #111 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	856	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	821	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	75	SF	7	10+ years	
Classroo	om #112 (Regular Classroom)						
-	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Additi		914 3 Bullalo AVENOE, Chicago, IL 60617
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	896	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	Work sink observed
Classroo	om #113 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	856	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	46	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	896	SF	7	10+ years	
Classroo	om #200 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	26	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	821	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	75	SF	7	6-10 years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	820	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	75	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Cenning - Flaster/Drywan	ZHU FIOOI	000	J.	U	10+ years	



Catego	ry : Classroom		В	uilding	: Addition	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	820	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	76	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	850	SF	6	6-10 years	
	Floor - Tile	2nd Floor	6	SF	4	1-2 years	Tile missing
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	6-10 years	ŭ
	Lighting - Pendent/Surface	2nd Floor	3	EA	5	6-10 years	Loose and missing covers
	Marker Board	2nd Floor	20	LF	7	6-10 years	<b>G</b>
	Storage/ Closet	2nd Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	896	SF	7	10+ years	
Classroo	om #204 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	821	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	75	SF	7	10+ years	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	820	SF	7	10+ years	



Catego	ry : Classroom		В	uildina	: Additi		1914 3 Bullalo AVENOE, Chicago, il 60617
22.090						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	820	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	76	SF	7	10+ years	
_Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	879	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	6-10 years	
	Floor - Tile	2nd Floor	879	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	889	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	76	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	820	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	76	SF	7	10+ years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	879	SF	6	6-10 years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	879	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	46	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	881	SF	7	10+ years	



Category : Classroom  Group Item - Type Location		В	uilding	: Additi	on 2		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Plaster/Drywall	2nd Floor	75	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	2nd Floor	846	SF	6	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Missing tiles
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	wilcoming the co
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	820	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	76	SF	7	10+ years	
	vvalis - Flastei/Drywali	2110 11001	76	SF	,	10+ years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	856	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	821	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	75	SF	7	10+ years	
Classroo	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Chalk Board	2nd Floor	20	ĹF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	821	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	75	SF	7	10+ years	
Classro	om #213 (Faculty Lounge)						
CIASSIUC		2nd Floor	4	Г^	7	6.10	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	



Category: Classroom

#### James N Thorp Elementary School 8914 S Buffalo AVENUE, Chicago, IL 60617

**Building: Addition 2** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	19	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	821	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	75	SF	7	10+ years	
Classroo	m #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	821	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	35	SF	4	1-2 years	Water damage
	Chalk Board	2nd Floor	20	LF	4	2-5 years	3
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	820	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	367	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	76	SF	7	10+ years	
	•					-	
0-1	m lutanian		_	: 1 - 1 :	- A -I -I:4:	0	
Catego	ry : Interior		В	uilding	: Additi		
		Location				Recommend	Commonts
Group	ry : Interior Item - Type	Location	B Quantity	uilding UOM	: Addition		Comments
	Item - Type		Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type  Ceiling - Plaster/Drywall	1st Floor	Quantity 2,312	UOM SF	Rank 6	Recommend Replacement	Comments
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	1st Floor 1st Floor	<b>Quantity</b> 2,312 8	UOM SF EA	<b>Rank</b> 6 7	Recommend Replacement 10+ years 6-10 years	Comments
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain	1st Floor 1st Floor 1st Floor	2,312 8 2	UOM SF EA EA	<b>Rank</b> 6 7 7	Recommend Replacement 10+ years 6-10 years 6-10 years	Comments
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor	2,312 8 2 2,282	SF EA EA SF	6 7 7 7	Recommend Replacement  10+ years 6-10 years 6-10 years 6-10 years	
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain	1st Floor 1st Floor 1st Floor	2,312 8 2	UOM SF EA EA	<b>Rank</b> 6 7 7	Recommend Replacement 10+ years 6-10 years 6-10 years	Cracked and chipping tile between bathrooms
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor	2,312 8 2 2,282	SF EA EA SF SF	6 7 7 7	Recommend Replacement  10+ years 6-10 years 6-10 years 6-10 years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,312 8 2 2,282 30	SF EA EA SF SF	6 7 7 7 4	Recommend Replacement  10+ years 6-10 years 6-10 years 6-10 years 1-2 years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block	1st Floor	2,312 8 2 2,282 30 26 2,304	SF EA EA SF SF	6 7 7 4 7 7 7	Recommend Replacement  10+ years 6-10 years 6-10 years 1-2 years 6-10 years 10+ years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,312 8 2 2,282 30 26	SF EA EA SF SF	6 7 7 7 4 7	Recommend Replacement  10+ years 6-10 years 6-10 years 1-2 years 6-10 years 10+ years 10+ years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	2,312 8 2 2,282 30 26 2,304 2,312	UOM  SF EA EA SF SF EA SF SF	6 7 7 4 7 7 7 7	Recommend Replacement  10+ years 6-10 years 6-10 years 1-2 years 6-10 years 10+ years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet  Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor	2,312 8 2 2,282 30 26 2,304 2,312 2	UOM  SF EA SF SF EA SF SF EA	6 7 7 4 7 7 7 6	Recommend Replacement  10+ years 6-10 years 6-10 years 1-2 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet  Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	2,312 8 2 2,282 30 26 2,304 2,312 2 2 2,312	UOM  SF EA SF SF EA SF EA SF EA SF	Rank  6 7 7 4 7 7 6 7 7	Recommend Replacement  10+ years 6-10 years 6-10 years 1-2 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	2,312 8 2 2,282 30 26 2,304 2,312 2 2 2,312 26	UOM  SF EA SF SF EA SF SF EA EA	Rank  6 7 7 4 7 7 6 7 7 7	Recommend Replacement  10+ years 6-10 years 6-10 years 1-2 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet  Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	2,312 8 2 2,282 30 26 2,304 2,312 2 2 2,312	UOM  SF EA SF SF EA SF EA SF EA EA SF EA	Rank  6 7 7 4 7 7 6 7 7	Recommend Replacement  10+ years 6-10 years 6-10 years 1-2 years 6-10 years 10+ years 10+ years 6-10 years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet  Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Concrete Block	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	2,312 8 2 2,282 30 26 2,304 2,312 2 2 2,312 26 36 2,304	UOM  SF EA SF SF EA SF EA SF EA SF EA SF EA SF EA SF	Rank  6 7 7 4 7 7 6 7 7 7 7	Recommend Replacement  10+ years 6-10 years 6-10 years 6-10 years 1-2 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet  Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	2,312 8 2 2,282 30 26 2,304 2,312 2 2,312 26 36 2,304 12,844	UOM  SF EA SF SF EA SF E	Rank  6 7 7 4 7 7 6 7 7 7	Recommend Replacement  10+ years 6-10 years 6-10 years 6-10 years 1-2 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years	Cracked and chipping tile between
Group	Item - Type  Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Floor - Tile/Sheet  Lighting - Pendent/Surface Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Concrete Block Ceiling - Plaster/Drywall	1st Floor 2nd Floor Basement	2,312 8 2 2,282 30 26 2,304 2,312 2 2 2,312 26 36 2,304	UOM  SF EA SF SF EA SF EA SF EA SF EA SF EA SF EA SF	Rank  6 7 7 4 7 7 7 6 7 7 7 6	Recommend Replacement  10+ years 6-10 years 6-10 years 6-10 years 1-2 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	Cracked and chipping tile between



Category : Interior			Building : Addition 2					
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Stairs - Concrete Stairs	Basement	10	LF	7	10+ years		
	Walls - Concrete Block	Basement	3,358	SF	7	10+ years		
afety								
	Camera Viewing Station	1st Floor	3	EA	7	6-10 years		
	Security Cameras	1st Floor	6	EA	7	6-10 years		
airs								
	Ceiling - Plaster/Drywall	Stair 5 (North West)	144	SF	6	10+ years		
	Floor - Terrazzo	Stair 5 (North West)	40	SF	6	10+ years		
	Handrails	Stair 5 (North West)	72	LF	7	6-10 years		
	Lighting - Pendent/Surface	Stair 5 (North West)	2	EA	7	6-10 years		
	Stairs - Terrazzo	Stair 5 (North West)	36	LF	7	10+ years		
	Walls - Concrete Block	Stair 5 (North West)	380	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 6 (East)	144	SF	6	10+ years		
	Floor - Terrazzo	Stair 6 (East)	40	SF	7	10+ years		
	Handrails	Stair 6 (East)	72	LF	7	6-10 years		
	Lighting - Pendent/Surface	Stair 6 (East)	2	EA	7	6-10 years		
	Stairs - Terrazzo	Stair 6 (East)	36	LF	7	10+ years		
	Walls - Concrete Block	Stair 6 (East)	280	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 7 (South)	144	SF	6	10+ years		
	Floor - Terrazzo	Stair 7 (South)	40	SF	6	10+ years		
	Handrails	Stair 7 (South)	72	LF	7	6-10 years		
	Lighting - Pendent/Surface	Stair 7 (South)	2	EA	7	6-10 years		
	Stairs - Terrazzo	Stair 7 (South)	36	LF	7	10+ years		
	Walls - Concrete Block	Stair 7 (South)	280	SF	7	10+ years		
ertical	Conveyance							
	Elevator - Elevator- Roped Holeless Hydraulic	1st Floor	1	EA	7	10+ years		



Category : Site Building : Site

outego.	ry : Site	Building : Site							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
thletic									
	Surface - Asphalt	Basketball Court	8,383	SF	5	0-1 year	Cracking and vegetation growth.		
	•		•			,	3 3 3		
Civil/Drai	inage								
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	7	10+ years	Repaired		
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	6	6-10 years	·		
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	1-2 years	Rim is damaged at sinking asphalt		
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	6	6-10 years			
encing									
encing	Fencing - Chain Link	Entire Site	192	LF	6	6-10 years			
	Fencing - Chain Link	Entire Site	8	LF	5	1-2 years	Missing top rail, post out of plumb.		
	1 onling Official Entity	Zitaro otto	Ŭ		Ü	1 2 youro	Gate not secured		
	Fencing - New Standard Ornamental	Entire Site	1,378	LF	6	6-10 years			
	Fencing - New Standard Ornamental	Entire Site	25	LF	4	0-1 year	Missing gates, fence struck out of		
							plumB		
	Fencing - Old Standard Ornamental	Entire Site	417	LF	6	10+ years			
andsca	pe								
- GIIGOOG	Benches	Entire Site	1	EA	7	6-10 years			
	Landscape - Grass	Entire Site	52,962	SF	6	6-10 years			
	Landscape - Grass	Entire Site	1,000	SF	5	1-2 years	Bare soil		
	Landscape - Hardscape- Asphalt	Entire Site	2,482	SF	6	6-10 years			
	Landscape - Hardscape- Concrete	Entire Site	1,020	SF	6	6-10 years			
	Landscape - Hardscape- Concrete	Entire Site	12	SF	5	1-2 years	stone steps are out of alignment wi		
	Zandodapo Tiarabbapo Conorcio			O.	ŭ	. L youro	poor settlement		
	Landscape - Hardscape- Concrete	Entire Site	1,221	SF	4	0-1 year	Large cracks and missing chunks of		
			•			,	concrete, spalling		
	Landscape - Hardscape- Concrete	Entire Site	50	SF	4	1-2 years	Large, pothole, broken concrete		
	Parkway trees	Entire Site	55	EA	6	10+ years	3 71		
	Parkway trees	Entire Site	2	EA	4	1-2 years	Missing		
	Planting Beds/ Area	Entire Site	600	SF	6	6-10 years			
	Play Area - Hardscape- Asphalt	Entire Site	4,931	SF	4	0-1 year	Confirmed that there are some large		
	Tay Area Transcape Aspiran	Zitaro otto	1,001	O.	•	o i you	cracks.		
	Retaining Wall - Concrete	Entire Site	800	SF	6	6-10 years			
	Retaining Wall - Concrete	Entire Site	50	SF	5	1-2 years	Cracked foundation wall and beam		
	Retaining Wall - Concrete	Entire Site	70	SF	5	6-10 years			
	Trash Receptacles	Entire Site	4	EA	6	6-10 years			
arking I	ot								
- Suming I	Concrete Curbs	Entire Site	250	LF	6	6-10 years			
	Interior Plantings	Entire Site	105	LF	6	6-10 years			

Campus Name: Thorp J Page : 50 of 53 Assessment Date: 10/02/2023



#### **James N Thorp Elementary School**

8914 S Buffalo AVENUE, Chicago, IL 60617

Category : Site			В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Asphalt	Entire Site	20,497	SF	6	6-10 years	
	Surface - Asphalt	Entire Site	4,000	SF	4	1-2 years	Alligatored, potholes
	Surface - Concrete	Entire Site	1,125	SF	6	10+ years	
	Trash Enclosure - Chain Links	Entire Site	911	SF	4	0-1 year	Falling over.
Playgrou	und						
, 0	Equipment - Combo 3-12	Southeast	1	EA	6	6-10 years	
	Surface - Poured Surface	Southeast	2,535	SF	5	0-1 year	Cracking and holes.
Sidewall	KS						
	Sidewalks - Internal Walks	Entire Site	241	LF	6	6-10 years	
	Sidewalks - Internal Walks	Entire Site	30	LF	4	1-2 years	Upheaved, cracked sidewalk. Settlement of sidewalk does not meet perimeter sidewalk.
	Sidewalks - Internal Walks	Entire Site	15	LF	4	0-1 year	Spalled, broken concrete
	Sidewalks - Perimeter Sidewalks	Entire Site	250	SF	7	10+ years	Repaired, new
	Sidewalks - Perimeter Sidewalks	Entire Site	25,668	SF	6	6-10 years	•
Signage							
0 0	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	10+ years	
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Building Mounted Back Lighted	Entire Site	1	EA	6	6-10 years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Thorp J Page : 51 of 53 Assessment Date: 10/02/2023

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				Floor Plan		Clored	Onerchie		
			Room	Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	intended Osage	Room Location	Number	Number	(SF)	Alea	Alea	Stop	Doaru
Faculty Lounge	Regular Classroom	1st Floor	130	130	690	161	84	N	N
Office	Regular Classroom	2nd Floor	230	230	650	140	70	N	N
Regular Classroom	Other Instructional Use	3rd Floor	349	349	835	112	56	N	Y
		1st Floor	131	131	690	161			Y
Regular Classroom	Regular Classroom	1st Floor	133	133		115	84	N N	N
Regular Classroom	Regular Classroom				690		60		IN V
Regular Classroom	Regular Classroom	1st Floor	141	141	621	161	84	N	l I
Regular Classroom	Regular Classroom	1st Floor	143	143	835	92	48	N	Y
Regular Classroom	Regular Classroom	1st Floor	145	145	782	92	48	N	Y
Regular Classroom	Regular Classroom	1st Floor	147	147	782	92	48	N	Y
Regular Classroom	Regular Classroom	1st Floor	149	149	835	92	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	231	231	795	196	98	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	232	232	715	168	84	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	233	233	670	140	70	N	N
Regular Classroom	Regular Classroom	2nd Floor	243	243	825	112	56	N	Y
Regular Classroom	Regular Classroom	2nd Floor	245	245	770	112	56	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	247	247	800	112	56	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	249	249	860	112	56	N	Y
Regular Classroom	Regular Classroom	3rd Floor	343	343	835	92	48	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	345	345	782	92	48	N	Y
Regular Classroom	Regular Classroom	3rd Floor	347	347	790	112	56	N	Υ
Building : Addition 1					1	T	1	1	
Art Room	Regular Classroom	2nd Floor	227	217	724	150	75	N	N
Computer Lab	Regular Classroom	2nd Floor	225	219	720	150	75	N	N
Computer Lab	Regular Classroom	2nd Floor	226	216	832	205	102	N	N
Kindergarten	Kindergarten	1st Floor	129	119	1,194	357	178	N	N
Kindergarten	Regular Classroom	1st Floor	124	114	712	150	75	N	N
Kindergarten	Regular Classroom	1st Floor	126	116	722	210	105	N	Υ
Office	Regular Classroom	2nd Floor	229	223	720	150	75		
Regular Classroom	Special Education	1st Floor	127	117	768	150	75	N	Υ
Store Room	Regular Classroom	2nd Floor	224	214	716	150	75	N	N
Building : Addition 2									
Faculty Lounge	Regular Classroom	2nd Floor	213	213	856	179	72	N	N
Kindergarten	Kindergarten	1st Floor	101	101	1,031	344	158	N	N
Kindergarten	Regular Classroom	1st Floor	102	102	856	172	79	N	N
Kindergarten	Regular Classroom	1st Floor	103	103	856	30	20		
Kindergarten	Regular Classroom	1st Floor	104	104	856	172	79	N	N





**Classroom Summary** 

Classicom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Office	Regular Classroom	1st Floor	100	100	856	172	79	N	N
Office	Regular Classroom	1st Floor	106	106	856	172	79	Ν	N
Office	Regular Classroom	2nd Floor	204	204	856	179	72	Ν	N
Other Instructional Use	Other Instructional Use	2nd Floor	200	200	856	179	72	Ν	N
Regular Classroom	Art Room	1st Floor	112	112	856	172	79	Ν	N
Regular Classroom	Regular Classroom	1st Floor	107	107	879	129	59	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	856	172	79	Ν	N
Regular Classroom	Regular Classroom	1st Floor	109	109	856	172	79	Ν	N
Regular Classroom	Regular Classroom	1st Floor	110	110	856	172	79	N	N
Regular Classroom	Regular Classroom	1st Floor	111	111	856	172	79	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	856	172	79	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	856	179	72	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	856	179	72	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	856	120	57	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	856	179	72	Ν	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	879	129	59	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	856	179	72	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	879	129	59	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	856	179	72	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	856	172	79	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	856	179	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	856	179	72	N	N
Store Room	Regular Classroom	1st Floor	113	113	856	172	79	N	N