



Sep 10, 2024

BASS

1140 W 66TH ST, Chicago IL 60621.

Dear **BASS** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit www.cdc.gov/lead.

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



Sep 10, 2024

BASS

1140 W 66TH ST, Chicago IL 60621.

Estimadas familias de **BASS**:

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer
Director de Salud y Seguridad Ambientales
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Flush180	10-JUN-16	0.161	ppb
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Flush180	10-JUN-16	0.176	ppb
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Flush180	10-JUN-16	0.176	ppb
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Flush180	10-JUN-16	0.161	ppb
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Flush180	10-JUN-16	0.399	ppb
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Flush180	10-JUN-16	0.231	ppb
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Flush180	10-JUN-16	0.231	ppb
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Flush180	10-JUN-16	0.399	ppb
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Initial	10-JUN-16	0.510	ppb
51373	51373-ANX-2-HAL-F01	Annex- 2nd Floor Outside Toilets, Fountain	Initial	10-JUN-16	0.510	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Flush180	10-JUN-16	0.682	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Flush180	10-JUN-16	0.682	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Flush180	10-JUN-16	0.567	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Flush180	10-JUN-16	0.701	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Flush180	10-JUN-16	0.663	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Flush180	10-JUN-16	0.567	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Flush180	10-JUN-16	0.663	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Flush180	10-JUN-16	0.701	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Initial	10-JUN-16	0.451	ppb
51373	51373-ANX-1-110-S05	Annex- Inside Pre-Kindergarten Room 110, Sink	Initial	10-JUN-16	0.451	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Flush180	10-JUN-16	0.912	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Flush180	10-JUN-16	0.828	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Flush180	10-JUN-16	1.170	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Flush180	10-JUN-16	1.430	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Flush180	10-JUN-16	0.912	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Flush180	10-JUN-16	0.828	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Flush180	10-JUN-16	1.170	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Flush180	10-JUN-16	1.430	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Initial	10-JUN-16	0.826	ppb
51373	51373-ANX-1-112-S04	Annex- Inside Pre-Kindergarten Room 112, Sink	Initial	10-JUN-16	0.826	ppb
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Flush180	10-JUN-16	1.000	ppb
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Flush180	10-JUN-16	0.174	ppb
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Flush180	10-JUN-16	0.168	ppb
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Flush180	10-JUN-16	0.168	ppb
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Flush180	10-JUN-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Flush180	10-JUN-16	0.174	ppb
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Flush180	10-JUN-16	0.126	ppb
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Flush180	10-JUN-16	0.126	ppb
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Initial	10-JUN-16	0.294	ppb
51373	51373-ANX-1-KIT-KS01	Annex- Kitchen North Wall, East Sink	Initial	10-JUN-16	0.294	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Flush180	10-JUN-16	1.000	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Flush180	10-JUN-16	0.161	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Flush180	10-JUN-16	0.344	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Flush180	10-JUN-16	1.000	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Flush180	10-JUN-16	0.344	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Flush180	10-JUN-16	0.152	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Flush180	10-JUN-16	0.152	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Flush180	10-JUN-16	0.161	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Initial	10-JUN-16	0.435	ppb
51373	51373-ANX-1-KIT-KS02	Annex- Kitchen North Wall, West Sink	Initial	10-JUN-16	0.435	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Flush180	10-JUN-16	0.418	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Flush180	10-JUN-16	0.277	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Flush180	10-JUN-16	0.205	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Flush180	10-JUN-16	0.205	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Flush180	10-JUN-16	0.496	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Flush180	10-JUN-16	0.418	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Flush180	10-JUN-16	0.277	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Flush180	10-JUN-16	0.496	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Flush180	22-JUL-20	1.000	ug/L
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Initial	10-JUN-16	0.748	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Initial	10-JUN-16	0.748	ppb
51373	51373-ANX-1-HAL-F03	Annex- Outside Toilets, Fountain	Initial	22-JUL-20	1.400	ug/L
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Flush180	10-JUN-16	0.656	ppb
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Flush180	10-JUN-16	0.677	ppb
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Flush180	10-JUN-16	0.719	ppb
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Flush180	10-JUN-16	0.656	ppb
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Flush180	10-JUN-16	0.677	ppb
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Flush180	10-JUN-16	0.719	ppb
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Flush180	10-JUN-16	0.646	ppb
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Flush180	10-JUN-16	0.646	ppb
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Initial	10-JUN-16	0.906	ppb
51373	51373-1-HAL-F01	Main- Outside Principal's Office, North Fountain	Initial	10-JUN-16	0.906	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Flush180	10-JUN-16	0.989	ppb
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Flush180	10-JUN-16	0.988	ppb
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Flush180	10-JUN-16	0.989	ppb
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Flush180	10-JUN-16	0.841	ppb
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Flush180	10-JUN-16	0.841	ppb
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Flush180	10-JUN-16	0.852	ppb
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Flush180	10-JUN-16	0.988	ppb
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Flush180	10-JUN-16	0.852	ppb
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Initial	10-JUN-16	0.889	ppb
51373	51373-1-HAL-F02	Main- Outside Principal's Office, South Fountain	Initial	10-JUN-16	0.889	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Flush180	10-JUN-16	3.130	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Flush180	10-JUN-16	2.890	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Flush180	10-JUN-16	3.000	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Flush180	10-JUN-16	3.130	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Flush180	10-JUN-16	2.820	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Flush180	10-JUN-16	3.000	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Flush180	10-JUN-16	2.820	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Flush180	10-JUN-16	2.890	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Initial	10-JUN-16	3.090	ppb
51373	51373-B-HAL-F02	Main- Outside Room 008, North Center Fountain	Initial	10-JUN-16	3.090	ppb
51373	51373-B-HAL-F01	Main- Outside Room 008, North Fountain	Flush180	10-JUN-16	3.200	ppb
51373	51373-B-HAL-F01	Main- Outside Room 008, North Fountain	Flush180	10-JUN-16	2.940	ppb
51373	51373-B-HAL-F01	Main- Outside Room 008, North Fountain	Flush180	10-JUN-16	3.030	ppb
51373	51373-B-HAL-F01	Main- Outside Room 008, North Fountain	Flush180	10-JUN-16	2.850	ppb
51373	51373-B-HAL-F01	Main- Outside Room 008, North Fountain	Flush180	10-JUN-16	3.030	ppb
51373	51373-B-HAL-F01	Main- Outside Room 008, North Fountain	Flush180	10-JUN-16	3.200	ppb
51373	51373-B-HAL-F01	Main- Outside Room 008, North Fountain	Flush180	10-JUN-16	2.940	ppb
51373	51373-B-HAL-F01	Main- Outside Room 008, North Fountain	Initial	10-JUN-16	2.880	ppb
51373	51373-B-HAL-F01	Main- Outside Room 008, North Fountain	Initial	10-JUN-16	2.880	ppb
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Flush180	10-JUN-16	2.410	ppb
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Flush180	10-JUN-16	2.050	ppb
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Flush180	10-JUN-16	2.050	ppb
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Flush180	10-JUN-16	2.040	ppb
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Flush180	10-JUN-16	2.040	ppb
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Flush180	10-JUN-16	2.410	ppb
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Flush180	10-JUN-16	2.150	ppb
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Flush180	10-JUN-16	2.150	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F03	Center Fountain				
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Initial	10-JUN-16	2.650	ppb
51373	51373-B-HAL-F03	Main- Outside Room 008, South Center Fountain	Initial	10-JUN-16	2.650	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Flush180	10-JUN-16	2.000	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Flush180	10-JUN-16	1.760	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Flush180	10-JUN-16	1.770	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Flush180	10-JUN-16	1.880	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Flush180	10-JUN-16	2.000	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Flush180	10-JUN-16	1.880	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Flush180	10-JUN-16	1.770	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Flush180	10-JUN-16	1.760	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Flush180	22-JUL-20	1.820	ug/L
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Initial	10-JUN-16	2.190	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Initial	10-JUN-16	2.190	ppb
51373	51373-B-HAL-F04	Main- Outside Room 008, South Fountain	Initial	22-JUL-20	2.060	ug/L
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Flush180	10-JUN-16	0.460	ppb
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Flush180	10-JUN-16	0.505	ppb
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Flush180	10-JUN-16	0.586	ppb
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Flush180	10-JUN-16	0.631	ppb
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Flush180	10-JUN-16	0.631	ppb
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Flush180	10-JUN-16	0.505	ppb
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Flush180	10-JUN-16	0.460	ppb
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Flush180	10-JUN-16	0.586	ppb
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Initial	10-JUN-16	0.940	ppb
51373	51373-2-HAL-F01	Main- Outside Room 203, North Fountain	Initial	10-JUN-16	0.940	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Flush180	10-JUN-16	0.661	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Flush180	10-JUN-16	0.666	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Flush180	10-JUN-16	0.663	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Flush180	10-JUN-16	0.623	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Flush180	10-JUN-16	0.623	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Flush180	10-JUN-16	0.666	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Flush180	10-JUN-16	0.663	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Flush180	10-JUN-16	0.661	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Initial	10-JUN-16	0.589	ppb
51373	51373-2-HAL-F02	Main- Outside Room 203, South Fountain	Initial	10-JUN-16	0.589	ppb
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Flush180	10-JUN-16	1.000	ppb
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Flush180	10-JUN-16	1.020	ppb
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Flush180	10-JUN-16	1.020	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F01	Fountain				
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Flush180	10-JUN-16	1.100	ppb
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Flush180	10-JUN-16	1.000	ppb
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Flush180	10-JUN-16	1.020	ppb
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Flush180	10-JUN-16	1.020	ppb
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Flush180	10-JUN-16	1.100	ppb
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Initial	10-JUN-16	2.240	ppb
51373	51373-3-HAL-F01	Main- Outside Room 303, North Fountain	Initial	10-JUN-16	2.240	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Flush180	10-JUN-16	0.885	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Flush180	10-JUN-16	1.540	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Flush180	10-JUN-16	1.010	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Flush180	10-JUN-16	0.849	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Flush180	10-JUN-16	0.849	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Flush180	10-JUN-16	1.540	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Flush180	10-JUN-16	1.010	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Flush180	10-JUN-16	0.885	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Initial	10-JUN-16	2.020	ppb
51373	51373-3-HAL-F02	Main- Outside Room 303, South Fountain	Initial	10-JUN-16	2.020	ppb