



Sep 10, 2024

BENNETT

10115 S PRAIRIE AVE, Chicago IL 60628.

Dear **BENNETT** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit www.cdc.gov/lead.

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



Sep 10, 2024

BENNETT

10115 S PRAIRIE AVE, Chicago IL 60628.

Estimadas familias de **BENNETT**:

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer
Director de Salud y Seguridad Ambientales
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Flush180	15-JUN-16	0.849	ppb
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Flush180	15-JUN-16	0.771	ppb
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Flush180	15-JUN-16	0.708	ppb
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Flush180	15-JUN-16	0.822	ppb
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Flush180	15-JUN-16	0.708	ppb
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Flush180	15-JUN-16	0.771	ppb
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Flush180	15-JUN-16	0.822	ppb
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Flush180	15-JUN-16	0.849	ppb
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Initial	15-JUN-16	1.370	ppb
51424	51424-1-KIT-KS01	1st Floor Kitchen Sink	Initial	15-JUN-16	1.370	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Flush180	15-JUN-16	0.366	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Flush180	15-JUN-16	0.557	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Flush180	15-JUN-16	0.352	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Flush180	15-JUN-16	0.366	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Flush180	15-JUN-16	0.422	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Flush180	15-JUN-16	0.557	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Flush180	15-JUN-16	0.422	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Flush180	15-JUN-16	0.352	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Flush180	22-JUL-20	1.020	ug/L
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Initial	15-JUN-16	1.270	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Initial	15-JUN-16	1.270	ppb
51424	51424-1-HAL-F06	Across From Room 101 North, Fountain 1	Initial	22-JUL-20	1.970	ug/L
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Flush180	15-JUN-16	0.642	ppb
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Flush180	15-JUN-16	0.826	ppb
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Flush180	15-JUN-16	0.826	ppb
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Flush180	15-JUN-16	0.512	ppb
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Flush180	15-JUN-16	0.561	ppb
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Flush180	15-JUN-16	0.642	ppb
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Flush180	15-JUN-16	0.512	ppb
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Flush180	15-JUN-16	0.561	ppb
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Initial	15-JUN-16	2.120	ppb
51424	51424-1-HAL-F07	Across From Room 101 South, Fountain 2	Initial	15-JUN-16	2.120	ppb
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Flush180	15-JUN-16	0.554	ppb
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Flush180	15-JUN-16	0.420	ppb
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Flush180	15-JUN-16	0.452	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Flush180	15-JUN-16	0.563	ppb
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Flush180	15-JUN-16	0.563	ppb
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Flush180	15-JUN-16	0.420	ppb
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Flush180	15-JUN-16	0.452	ppb
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Flush180	15-JUN-16	0.554	ppb
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Initial	15-JUN-16	0.867	ppb
51424	51424-1-HAL-F04	Across From Room 104 North, Fountain 1	Initial	15-JUN-16	0.867	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Flush180	15-JUN-16	0.581	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Flush180	15-JUN-16	0.495	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Flush180	15-JUN-16	0.484	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Flush180	15-JUN-16	0.601	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Flush180	15-JUN-16	0.601	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Flush180	15-JUN-16	0.484	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Flush180	15-JUN-16	0.581	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Flush180	15-JUN-16	0.495	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Initial	15-JUN-16	0.789	ppb
51424	51424-1-HAL-F05	Across From Room 104 South, Fountain 2	Initial	15-JUN-16	0.789	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Flush180	15-JUN-16	0.379	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Flush180	15-JUN-16	0.368	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Flush180	15-JUN-16	0.393	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Flush180	15-JUN-16	0.368	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Flush180	15-JUN-16	0.393	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Flush180	15-JUN-16	0.370	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Flush180	15-JUN-16	0.379	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Flush180	15-JUN-16	0.370	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Initial	15-JUN-16	0.835	ppb
51424	51424-1-HAL-F09	Across From Room 107 East, Fountain 1	Initial	15-JUN-16	0.835	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Flush180	15-JUN-16	0.413	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Flush180	15-JUN-16	0.365	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Flush180	15-JUN-16	0.365	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Flush180	15-JUN-16	0.378	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Flush180	15-JUN-16	0.383	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Flush180	15-JUN-16	0.378	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Flush180	15-JUN-16	0.383	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Flush180	15-JUN-16	0.413	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Initial	15-JUN-16	0.494	ppb
51424	51424-1-HAL-F08	Across From Room 107 West, Fountain 2	Initial	15-JUN-16	0.494	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Flush180	15-JUN-16	0.855	ppb
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Flush180	15-JUN-16	1.020	ppb
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Flush180	15-JUN-16	0.978	ppb
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Flush180	15-JUN-16	0.855	ppb
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Flush180	15-JUN-16	0.926	ppb
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Flush180	15-JUN-16	1.020	ppb
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Flush180	15-JUN-16	0.978	ppb
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Flush180	15-JUN-16	0.926	ppb
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Initial	15-JUN-16	1.360	ppb
51424	51424-1-HAL-F11	Across From Room 110 East, Fountain 1	Initial	15-JUN-16	1.360	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Flush180	15-JUN-16	1.070	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Flush180	15-JUN-16	1.070	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Flush180	15-JUN-16	1.020	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Flush180	15-JUN-16	0.957	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Flush180	15-JUN-16	0.976	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Flush180	15-JUN-16	1.020	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Flush180	15-JUN-16	0.957	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Flush180	15-JUN-16	0.976	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Initial	15-JUN-16	1.180	ppb
51424	51424-1-HAL-F10	Across From Room 110 West, Fountain 2	Initial	15-JUN-16	1.180	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Flush180	15-JUN-16	0.608	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Flush180	15-JUN-16	0.589	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Flush180	15-JUN-16	0.596	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Flush180	15-JUN-16	0.608	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Flush180	15-JUN-16	0.596	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Flush180	15-JUN-16	0.589	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Flush180	15-JUN-16	0.555	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Flush180	15-JUN-16	0.555	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Initial	15-JUN-16	0.770	ppb
51424	51424-2-HAL-F01	Across From Room 204 North, Fountain 1	Initial	15-JUN-16	0.770	ppb
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Flush180	15-JUN-16	0.635	ppb
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Flush180	15-JUN-16	0.628	ppb
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Flush180	15-JUN-16	0.561	ppb
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Flush180	15-JUN-16	0.649	ppb
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Flush180	15-JUN-16	0.561	ppb
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Flush180	15-JUN-16	0.628	ppb
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Flush180	15-JUN-16	0.635	ppb
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Flush180	15-JUN-16	0.649	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F02	Fountain 2				
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Initial	15-JUN-16	1.430	ppb
51424	51424-2-HAL-F02	Across From Room 204 South, Fountain 2	Initial	15-JUN-16	1.430	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Flush180	15-JUN-16	0.670	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Flush180	15-JUN-16	0.793	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Flush180	15-JUN-16	0.623	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Flush180	15-JUN-16	0.793	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Flush180	15-JUN-16	0.714	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Flush180	15-JUN-16	0.623	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Flush180	15-JUN-16	0.714	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Flush180	15-JUN-16	0.670	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Initial	15-JUN-16	1.740	ppb
51424	51424-2-HAL-F03	Across From Room 205 North, Fountain 1	Initial	15-JUN-16	1.740	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Flush180	15-JUN-16	0.541	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Flush180	15-JUN-16	0.448	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Flush180	15-JUN-16	0.489	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Flush180	15-JUN-16	0.561	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Flush180	15-JUN-16	0.489	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Flush180	15-JUN-16	0.448	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Flush180	15-JUN-16	0.541	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Flush180	15-JUN-16	0.561	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Initial	15-JUN-16	0.923	ppb
51424	51424-2-HAL-F04	Across From Room 205 South, Fountain 2	Initial	15-JUN-16	0.923	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Flush180	15-JUN-16	1.030	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Flush180	15-JUN-16	1.030	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Flush180	15-JUN-16	1.130	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Flush180	15-JUN-16	1.080	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Flush180	15-JUN-16	1.040	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Flush180	15-JUN-16	1.080	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Flush180	15-JUN-16	1.040	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Flush180	15-JUN-16	1.130	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Initial	15-JUN-16	1.220	ppb
51424	51424-2-HAL-F08	Across From Room 210 East, Fountain 1	Initial	15-JUN-16	1.220	ppb
51424	51424-2-HAL-F07	Across From Room 210 West, Fountain 2	Flush180	15-JUN-16	1.280	ppb
51424	51424-2-HAL-F07	Across From Room 210 West, Fountain 2	Flush180	15-JUN-16	1.160	ppb
51424	51424-2-HAL-F07	Across From Room 210 West, Fountain 2	Flush180	15-JUN-16	1.180	ppb
51424	51424-2-HAL-F07	Across From Room 210 West, Fountain 2	Flush180	15-JUN-16	1.160	ppb
51424	51424-2-HAL-	Across From Room 210 West,	Flush180	15-JUN-16	1.310	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F07	Fountain 2				
51424	51424-2-HAL-F07	Across From Room 210 West, Fountain 2	Flush180	15-JUN-16	1.280	ppb
51424	51424-2-HAL-F07	Across From Room 210 West, Fountain 2	Flush180	15-JUN-16	1.180	ppb
51424	51424-2-HAL-F07	Across From Room 210 West, Fountain 2	Flush180	15-JUN-16	1.310	ppb
51424	51424-2-HAL-F07	Across From Room 210 West, Fountain 2	Initial	15-JUN-16	1.430	ppb
51424	51424-2-HAL-F07	Across From Room 210 West, Fountain 2	Initial	15-JUN-16	1.430	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Flush180	15-JUN-16	0.380	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Flush180	15-JUN-16	0.380	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Flush180	15-JUN-16	0.330	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Flush180	15-JUN-16	0.408	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Flush180	15-JUN-16	0.408	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Flush180	15-JUN-16	0.338	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Flush180	15-JUN-16	0.330	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Flush180	15-JUN-16	0.338	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Initial	15-JUN-16	0.545	ppb
51424	51424-2-HAL-F06	Across From Room 215 East, Fountain 1	Initial	15-JUN-16	0.545	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Flush180	15-JUN-16	0.491	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Flush180	15-JUN-16	0.377	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Flush180	15-JUN-16	0.491	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Flush180	15-JUN-16	0.377	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Flush180	15-JUN-16	0.332	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Flush180	15-JUN-16	0.342	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Flush180	15-JUN-16	0.342	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Flush180	15-JUN-16	0.332	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Initial	15-JUN-16	0.882	ppb
51424	51424-2-HAL-F05	Across From Room 215 West, Fountain 2	Initial	15-JUN-16	0.882	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Flush180	15-JUN-16	0.976	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Flush180	15-JUN-16	1.480	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Flush180	15-JUN-16	1.090	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Flush180	15-JUN-16	1.840	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Flush180	15-JUN-16	1.090	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Flush180	15-JUN-16	1.480	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Flush180	15-JUN-16	0.976	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Flush180	15-JUN-16	1.840	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Flush180	22-JUL-20	2.230	ug/L
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Initial	15-JUN-16	2.190	ppb
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Initial	22-JUL-20	2.120	ug/L
51424	51424-3-HAL-F01	Across From Room 304 North, Fountain 1	Initial	15-JUN-16	2.190	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Flush180	15-JUN-16	0.963	ppb
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Flush180	15-JUN-16	0.883	ppb
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Flush180	15-JUN-16	1.380	ppb
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Flush180	15-JUN-16	1.060	ppb
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Flush180	15-JUN-16	0.883	ppb
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Flush180	15-JUN-16	1.060	ppb
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Flush180	15-JUN-16	0.963	ppb
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Flush180	15-JUN-16	1.380	ppb
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Initial	15-JUN-16	1.630	ppb
51424	51424-3-HAL-F02	Across From Room 304 South, Fountain 2	Initial	15-JUN-16	1.630	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Flush180	15-JUN-16	1.540	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Flush180	15-JUN-16	1.490	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Flush180	15-JUN-16	1.540	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Flush180	15-JUN-16	1.550	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Flush180	15-JUN-16	1.550	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Flush180	15-JUN-16	1.550	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Flush180	15-JUN-16	1.490	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Flush180	15-JUN-16	1.550	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Initial	15-JUN-16	1.510	ppb
51424	51424-3-HAL-F03	Across From Room 305 North, Fountain 1	Initial	15-JUN-16	1.510	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Flush180	15-JUN-16	1.290	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Flush180	15-JUN-16	1.200	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Flush180	15-JUN-16	1.290	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Flush180	15-JUN-16	1.210	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Flush180	15-JUN-16	1.200	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Flush180	15-JUN-16	1.200	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Flush180	15-JUN-16	1.210	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Flush180	15-JUN-16	1.200	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Initial	15-JUN-16	1.430	ppb
51424	51424-3-HAL-F04	Across From Room 305 South, Fountain 2	Initial	15-JUN-16	1.430	ppb
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Flush180	15-JUN-16	0.179	ppb
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Flush180	15-JUN-16	0.199	ppb
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Flush180	15-JUN-16	1.000	ppb
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Flush180	15-JUN-16	0.179	ppb
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Flush180	15-JUN-16	1.000	ppb
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Flush180	15-JUN-16	1.000	ppb
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Flush180	15-JUN-16	1.000	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Flush180	15-JUN-16	0.199	ppb
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Initial	15-JUN-16	0.187	ppb
51424	51424-3-HAL-F05	Across From Room 307 North, Fountain 1	Initial	15-JUN-16	0.187	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Flush180	15-JUN-16	0.236	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Flush180	15-JUN-16	0.216	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Flush180	15-JUN-16	0.234	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Flush180	15-JUN-16	0.235	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Flush180	15-JUN-16	0.236	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Flush180	15-JUN-16	0.235	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Flush180	15-JUN-16	0.234	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Flush180	15-JUN-16	0.216	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Initial	15-JUN-16	0.198	ppb
51424	51424-3-HAL-F06	Across From Room 307 South, Fountain 2	Initial	15-JUN-16	0.198	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Flush180	15-JUN-16	1.080	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Flush180	15-JUN-16	0.731	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Flush180	15-JUN-16	0.640	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Flush180	15-JUN-16	1.640	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Flush180	15-JUN-16	1.640	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Flush180	15-JUN-16	1.080	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Flush180	15-JUN-16	0.731	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Flush180	15-JUN-16	0.640	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Initial	15-JUN-16	1.460	ppb
51424	51424-1-101-F03	Inside Pre-K Room 101 East, Fountain	Initial	15-JUN-16	1.460	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Flush180	15-JUN-16	0.635	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Flush180	15-JUN-16	0.657	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Flush180	15-JUN-16	0.657	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Flush180	15-JUN-16	0.655	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Flush180	15-JUN-16	0.655	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Flush180	15-JUN-16	0.642	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Flush180	15-JUN-16	0.642	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Flush180	15-JUN-16	0.635	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Initial	15-JUN-16	0.645	ppb
51424	51424-1-101-F02	Inside Pre-K Room 101 West, Fountain	Initial	15-JUN-16	0.645	ppb