



**Sep 10, 2024**

**LANE TECH HS**

**2501 W ADDISON ST, Chicago IL 60618.**

Dear **LANE TECH HS** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit [www.cdc.gov/lead](http://www.cdc.gov/lead).

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



**Sep 10, 2024**

**LANE TECH HS**

**2501 W ADDISON ST, Chicago IL 60618.**

Estimadas familias de **LANE TECH HS:**

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer  
Director de Salud y Seguridad Ambientales  
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-1-CAF-F15	Cafeteria, Northwest Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F15	Cafeteria, Northwest Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F15	Cafeteria, Northwest Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F15	Cafeteria, Northwest Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F15	Cafeteria, Northwest Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF12	Cafeteria, Southeast Bottle Filer	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF12	Cafeteria, Southeast Bottle Filer	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF12	Cafeteria, Southeast Bottle Filer	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF12	Cafeteria, Southeast Bottle Filer	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF12	Cafeteria, Southeast Bottle Filer	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F11	Cafeteria, Southeast Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F11	Cafeteria, Southeast Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F11	Cafeteria, Southeast Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F11	Cafeteria, Southeast Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF14	Cafeteria, Southwest Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF14	Cafeteria, Southwest Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF14	Cafeteria, Southwest Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF14	Cafeteria, Southwest Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-BF14	Cafeteria, Southwest Bottle Filler	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F13	Cafeteria, Southwest Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F13	Cafeteria, Southwest Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F13	Cafeteria, Southwest Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-CAF-F13	Cafeteria, Southwest Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-BF34	Girls Locker Room, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-BF34	Girls Locker Room, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-BF34	Girls Locker Room, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-BF34	Girls Locker Room, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-BF34	Girls Locker Room, Bottle Filler	Initial	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-RBF10	Main - Across From Room 222, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-RBF10	Main - Across From Room 222, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-RBF10	Main - Across From Room 222, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-RBF10	Main - Across From Room 222, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-RBF10	Main - Across From Room 222, Bottle Filler	Initial	30-JAN-2024	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-2-HAL-F18	Main - Across From Room 244, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F18	Main - Across From Room 244, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F18	Main - Across From Room 244, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F18	Main - Across From Room 244, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F18	Main - Across From Room 244, Left Fountain	Initial	30-JAN-2024	1.190	ug/L
51534	51534-2-HAL-F01	Main - Across From Room 249, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F01	Main - Across From Room 249, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F01	Main - Across From Room 249, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F01	Main - Across From Room 249, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F01	Main - Across From Room 249, Left Fountain	Initial	30-JAN-2024	2.190	ug/L
51534	51534-2-HAL-F02	Main - Across From Room 249, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F02	Main - Across From Room 249, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F02	Main - Across From Room 249, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F02	Main - Across From Room 249, Right Fountain	Initial	30-JAN-2024	3.350	ug/L
51534	51534-3-HAL-F21	Main- 3rd Floor Hallway, Across Gym 2 (#300)	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F21	Main- 3rd Floor Hallway, Across Gym 2 (#300)	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F21	Main- 3rd Floor Hallway, Across Gym 2 (#300)	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F21	Main- 3rd Floor Hallway, Across Gym 2 (#300)	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F21	Main- 3rd Floor Hallway, Across Gym 2 (#300)	Flush180	17-DEC-20	1.030	ug/L
51534	51534-3-HAL-F21	Main- 3rd Floor Hallway, Across Gym 2 (#300)	Initial	17-DEC-20	1.930	ug/L
51534	51534-3-HAL-F21	Main- 3rd Floor Hallway, Across Gym 2 (#300)	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-BF01	Main- Across From 107, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-BF01	Main- Across From 107, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-BF01	Main- Across From 107, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-BF01	Main- Across From 107, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC24B	Main- Across From 107, Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC24B	Main- Across From 107, Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC24B	Main- Across From 107, Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC24B	Main- Across From 107, Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC24B	Main- Across From 107, Bottle Filler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-BF01	Main- Across From 107, Bottle Filler	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC24A	Main- Across From 107, Water Cooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC24A	Main- Across From 107, Water Cooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC24A	Main- Across From 107, Water Cooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC24A	Main- Across From 107, Water Cooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC24A	Main- Across From 107, Water Cooler	Initial	04-OCT-16	1.000	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F29	Main- Across From 132, Left Fountain	Initial	30-JAN-2024	1.280	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush	30-JAN-2024	3.540	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush	30-JAN-2024	1.700	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush	30-JAN-2024	1.570	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush	30-JAN-2024	1.140	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush	29-FEB-2024	1.510	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush	29-FEB-2024	1.320	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush	29-FEB-2024	1.000	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush	29-FEB-2024	1.000	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Initial	30-JAN-2024	6.190	ug/L
51534	51534-1-HAL-F28	Main- Across From 132, Right Fountain	Initial	29-FEB-2024	1.400	ug/L
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Flush	30-JAN-2024	2.800	ug/L
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Flush	30-JAN-2024	3.220	ug/L
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Flush	30-JAN-2024	4.910	ug/L
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Flush	30-JAN-2024	2.870	ug/L
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Flush180	04-OCT-16	9.300	ppb
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F21	Main- Across From 135, Left Fountain	Initial	30-JAN-2024	4.050	ug/L
51534	51534-1-HAL-F37	Main- Across From 144, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F37	Main- Across From 144, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-	Main- Across From 144, Left Fountain	Flush	30-JAN-2024	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F37	Fountain				
51534	51534-1-HAL-F37	Main- Across From 144, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F37	Main- Across From 144, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F37	Main- Across From 144, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F37	Main- Across From 144, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F37	Main- Across From 144, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F37	Main- Across From 144, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F37	Main- Across From 144, Left Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F38	Main- Across From 144, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F38	Main- Across From 144, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F38	Main- Across From 144, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F38	Main- Across From 144, Right Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F20	Main- Across From Room 139, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F20	Main- Across From Room 139, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F20	Main- Across From Room 139, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F20	Main- Across From Room 139, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F20	Main- Across From Room 139, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F19	Main- Across From Room 149, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F19	Main- Across From Room 149, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F19	Main- Across From Room 149, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F19	Main- Across From Room 149, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F19	Main- Across From Room 149, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F19	Main- Across From Room 149, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F19	Main- Across From Room 149, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F19	Main- Across From Room 149, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F19	Main- Across From Room 149, Left Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Flush180	17-DEC-20	1.630	ug/L
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Initial	04-OCT-16	1.000	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F18	Right Fountain				
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Initial	17-DEC-20	1.370	ug/L
51534	51534-1-HAL-F18	Main- Across From Room 149, Right Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F06	Main- Across From Room 217, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F06	Main- Across From Room 217, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F06	Main- Across From Room 217, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F06	Main- Across From Room 217, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F06	Main- Across From Room 217, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F05	Main- Across From Room 217, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F05	Main- Across From Room 217, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F05	Main- Across From Room 217, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F05	Main- Across From Room 217, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F05	Main- Across From Room 217, Right Fountain	Initial	30-JAN-2024	1.370	ug/L
51534	51534-2-HAL-F04	Main- Across From Room 225, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F04	Main- Across From Room 225, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F04	Main- Across From Room 225, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F04	Main- Across From Room 225, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F04	Main- Across From Room 225, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F04	Main- Across From Room 225, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F04	Main- Across From Room 225, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F04	Main- Across From Room 225, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F04	Main- Across From Room 225, Left Fountain	Initial	30-JAN-2024	1.180	ug/L
51534	51534-2-HAL-F03	Main- Across From Room 225, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F03	Main- Across From Room 225, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F03	Main- Across From Room 225, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F03	Main- Across From Room 225, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F03	Main- Across From Room 225, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F03	Main- Across From Room 225, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F03	Main- Across From Room 225, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F03	Main- Across From Room 225, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F03	Main- Across From Room 225, Right Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Flush180	04-OCT-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F19	Main- Across From Room 244, Right Fountain	Initial	30-JAN-2024	1.120	ug/L
51534	51534-2-HAL-F02	Main- Across From Room 249, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F02	Main- Across From Room 249, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F02	Main- Across From Room 249, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F02	Main- Across From Room 249, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F02	Main- Across From Room 249, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F01	Main- Across From Room 249, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F01	Main- Across From Room 249, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F01	Main- Across From Room 249, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F01	Main- Across From Room 249, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F01	Main- Across From Room 249, Right Fountain	Initial	04-OCT-16	2.300	ppb
51534	51534-3-HAL-F11	Main- Across From Room 305, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F11	Main- Across From Room 305, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F11	Main- Across From Room 305, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F11	Main- Across From Room 305, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F11	Main- Across From Room 305, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Flush	30-JAN-2024	1.890	ug/L
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Flush	30-JAN-2024	1.810	ug/L
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Flush	30-JAN-2024	1.670	ug/L
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Flush	30-JAN-2024	1.210	ug/L
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F14	Main- Across From Room 307, Right Fountain	Initial	30-JAN-2024	1.630	ug/L
51534	51534-3-HAL-F03	Main- Across From Room 322, Left Fountain	Flush	30-JAN-2024	1.520	ug/L
51534	51534-3-HAL-F03	Main- Across From Room 322, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F03	Main- Across From Room 322, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F03	Main- Across From Room 322, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F03	Main- Across From Room 322, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F03	Main- Across From Room 322, Left Fountain	Flush180	04-OCT-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-3-HAL-F03	Main- Across From Room 322, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F03	Main- Across From Room 322, Left Fountain	Initial	04-OCT-16	2.400	ppb
51534	51534-3-HAL-F03	Main- Across From Room 322, Left Fountain	Initial	30-JAN-2024	1.050	ug/L
51534	51534-3-HAL-F04	Main- Across From Room 322, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F04	Main- Across From Room 322, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F04	Main- Across From Room 322, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F04	Main- Across From Room 322, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F04	Main- Across From Room 322, Right Fountain	Initial	30-JAN-2024	1.280	ug/L
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Initial	04-OCT-16	2.700	ppb
51534	51534-3-HAL-F18	Main- Across From Room 327, Left Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Flush	30-JAN-2024	1.040	ug/L
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Flush180	04-OCT-16	2.400	ppb
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F17	Main- Across From Room 327, Right Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F06	Main- Across From Room 346, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F06	Main- Across From Room 346, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F06	Main- Across From Room 346, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F06	Main- Across From Room 346, Left Fountain	Flush	30-JAN-2024	1.020	ug/L
51534	51534-3-HAL-F06	Main- Across From Room 346, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F06	Main- Across From Room 346, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F06	Main- Across From Room 346, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F06	Main- Across From Room 346, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F06	Main- Across From Room 346, Left Fountain	Initial	30-JAN-2024	1.430	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F06	Left Fountain				
51534	51534-3-HAL-F05	Main- Across From Room 346, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F05	Main- Across From Room 346, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F05	Main- Across From Room 346, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F05	Main- Across From Room 346, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F05	Main- Across From Room 346, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F05	Main- Across From Room 346, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F05	Main- Across From Room 346, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F05	Main- Across From Room 346, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F05	Main- Across From Room 346, Right Fountain	Initial	30-JAN-2024	1.060	ug/L
51534	51534-3-HAL-F19	Main- Across From Room 349, Left Foutnain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F19	Main- Across From Room 349, Left Foutnain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F19	Main- Across From Room 349, Left Foutnain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F19	Main- Across From Room 349, Left Foutnain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F19	Main- Across From Room 349, Left Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F19	Main- Across From Room 349, Left Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F19	Main- Across From Room 349, Left Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F19	Main- Across From Room 349, Left Foutnain	Initial	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F19	Main- Across From Room 349, Left Foutnain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F20	Main- Across From Room 349, Right Foutnain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F20	Main- Across From Room 349, Right Foutnain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F20	Main- Across From Room 349, Right Foutnain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F20	Main- Across From Room 349, Right Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F20	Main- Across From Room 349, Right Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F20	Main- Across From Room 349, Right Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F20	Main- Across From Room 349, Right Foutnain	Initial	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F20	Main- Across From Room 349, Right Foutnain	Initial	30-JAN-2024	1.230	ug/L
51534	51534-4-HAL-F07	Main- Across From Room 403, Left Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F07	Main- Across From Room 403, Left Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F07	Main- Across From Room 403, Left Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F07	Main- Across From Room 403, Left Foutnain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F07	Main- Across From Room 403, Left Foutnain	Initial	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F03	Main- Across From Room 432, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-4-HAL-	Main- Across From Room 432,	Flush	30-JAN-2024	1.000	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F03	Left Fountain				
51534	51534-4-HAL-F03	Main- Across From Room 432, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-4-HAL-F03	Main- Across From Room 432, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-4-HAL-F03	Main- Across From Room 432, Left Fountain	Initial	30-JAN-2024	1.080	ug/L
51534	51534-4-HAL-F03	Main- Across From Room 434, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F03	Main- Across From Room 434, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F03	Main- Across From Room 434, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F03	Main- Across From Room 434, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F04	Main- Across From Room 435, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-4-HAL-F04	Main- Across From Room 435, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-4-HAL-F04	Main- Across From Room 435, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-4-HAL-F04	Main- Across From Room 435, Right Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-4-HAL-F05	Main- Across From Room 435, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F05	Main- Across From Room 435, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F05	Main- Across From Room 435, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F05	Main- Across From Room 435, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F05	Main- Across From Room 435, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F06	Main- Across From Room 435, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F06	Main- Across From Room 435, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F06	Main- Across From Room 435, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F06	Main- Across From Room 435, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-HAL-F06	Main- Across From Room 435, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F17	Main- Cafeteria, Northeast Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F17	Main- Cafeteria, Northeast Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F17	Main- Cafeteria, Northeast Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F17	Main- Cafeteria, Northeast Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F17	Main- Cafeteria, Northeast Bottle Filler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC16	Main- Cafeteria, Northeast Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC16	Main- Cafeteria, Northeast Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC16	Main- Cafeteria, Northeast Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC16	Main- Cafeteria, Northeast Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC16	Main- Cafeteria, Northeast Watercooler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F15	Main- Cafeteria, Northwest Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F15	Main- Cafeteria, Northwest Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F15	Main- Cafeteria, Northwest Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F15	Main- Cafeteria, Northwest Bottle Filler	Flush180	04-OCT-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-1-CAF-F15	Main- Cafeteria, Northwest Bottle Filler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC14	Main- Cafeteria, Northwest Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC14	Main- Cafeteria, Northwest Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC14	Main- Cafeteria, Northwest Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC14	Main- Cafeteria, Northwest Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC14	Main- Cafeteria, Northwest Watercooler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F11	Main- Cafeteria, Southeast Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F11	Main- Cafeteria, Southeast Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F11	Main- Cafeteria, Southeast Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F11	Main- Cafeteria, Southeast Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F11	Main- Cafeteria, Southeast Bottle Filler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC10	Main- Cafeteria, Southeast Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC10	Main- Cafeteria, Southeast Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC10	Main- Cafeteria, Southeast Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC10	Main- Cafeteria, Southeast Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC10	Main- Cafeteria, Southeast Watercooler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F13	Main- Cafeteria, Southwest Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F13	Main- Cafeteria, Southwest Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F13	Main- Cafeteria, Southwest Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F13	Main- Cafeteria, Southwest Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-F13	Main- Cafeteria, Southwest Bottle Filler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC12	Main- Cafeteria, Southwest Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC12	Main- Cafeteria, Southwest Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC12	Main- Cafeteria, Southwest Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC12	Main- Cafeteria, Southwest Watercooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-CAF-WC12	Main- Cafeteria, Southwest Watercooler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Initial	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS02	Main- East Kitchen, West Wall, Center Sink	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Flush	30-JAN-2024	1.000	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Flush180	04-OCT-16	3.000	ppb
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Flush180	04-OCT-16	2.400	ppb
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Initial	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS01	Main- East Kitchen, West Wall, Left Sink	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Flush	30-JAN-2024	1.010	ug/L
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Flush180	04-OCT-16	11.000	ppb
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Flush180	04-OCT-16	2.200	ppb
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Initial	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS03	Main- East Kitchen, West Wall, Right Sink	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Flush180	04-OCT-16	4.200	ppb
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Flush180	04-OCT-16	2.900	ppb
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Initial	04-OCT-16	2.800	ppb
51534	51534-1-108G-F33	Main- Girls Locker, Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-4-444-F01	Main- Inside Room 444, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-444-F01	Main- Inside Room 444, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-444-F01	Main- Inside Room 444, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-444-F01	Main- Inside Room 444, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-4-444-F01	Main- Inside Room 444, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F35	Main- Next to 136, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F35	Main- Next to 136, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F35	Main- Next to 136, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F35	Main- Next to 136, Left Fountain	Flush180	04-OCT-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F35					
51534	51534-1-HAL-F35	Main- Next to 136, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F36	Main- Next to 136,Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F36	Main- Next to 136,Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F36	Main- Next to 136,Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F36	Main- Next to 136,Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F36	Main- Next to 136,Right Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Flush	30-JAN-2024	1.150	ug/L
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Flush180	04-OCT-16	2.100	ppb
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Flush180	04-OCT-16	2.900	ppb
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Flush180	04-OCT-16	2.600	ppb
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Initial	04-OCT-16	6.800	ppb
51534	51534-2-HAL-F09	Main- Next to Room 212, Right Fountain	Initial	30-JAN-2024	2.720	ug/L
51534	51534-2-HAL-RBF01	Main- Next to Room 213, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-RBF01	Main- Next to Room 213, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-RBF01	Main- Next to Room 213, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-RBF01	Main- Next to Room 213, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F08	Main- Next to Room 213, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F08	Main- Next to Room 213, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F08	Main- Next to Room 213, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F08	Main- Next to Room 213, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F08	Main- Next to Room 213, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-RBF01	Main- Next to Room 213, Left Fountain	Initial	30-JAN-2024	2.160	ug/L
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Flush	30-JAN-2024	1.040	ug/L
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Flush	30-JAN-2024	1.040	ug/L
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Initial	04-OCT-16	2.100	ppb
51534	51534-2-HAL-F07	Main- Next to Room 213, Right Fountain	Initial	30-JAN-2024	1.800	ug/L
51534	51534-2-HAL-	Main- Next to Room 214B, Left	Flush180	04-OCT-16	1.000	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F15	Fountain				
51534	51534-2-HAL-F15	Main- Next to Room 214B, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F15	Main- Next to Room 214B, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F15	Main- Next to Room 214B, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F15	Main- Next to Room 214B, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F16	Main- Next to Room 214B, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F16	Main- Next to Room 214B, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F16	Main- Next to Room 214B, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F16	Main- Next to Room 214B, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F16	Main- Next to Room 214B, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F14	Main- Next to Room 226, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F14	Main- Next to Room 226, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F14	Main- Next to Room 226, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F14	Main- Next to Room 226, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F14	Main- Next to Room 226, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F14	Main- Next to Room 226, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F14	Main- Next to Room 226, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F14	Main- Next to Room 226, Left Fountain	Initial	30-JAN-2024	1.180	ug/L
51534	51534-2-HAL-F13	Main- Next to Room 226, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F13	Main- Next to Room 226, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F13	Main- Next to Room 226, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F13	Main- Next to Room 226, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F13	Main- Next to Room 226, Right Fountain	Initial	30-JAN-2024	1.150	ug/L
51534	51534-2-HAL-F12	Main- Next to Room 233, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F12	Main- Next to Room 233, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F12	Main- Next to Room 233, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F12	Main- Next to Room 233, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F12	Main- Next to Room 233, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F11	Main- Next to Room 233, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F11	Main- Next to Room 233, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F11	Main- Next to Room 233, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F11	Main- Next to Room 233, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F11	Main- Next to Room 233, Left Fountain	Initial	30-JAN-2024	1.050	ug/L
51534	51534-2-HAL-F11	Main- Next to Room 233, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F11	Main- Next to Room 233, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F11	Main- Next to Room 233, Right Fountain	Flush180	04-OCT-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-2-HAL-F11	Main- Next to Room 233, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F11	Main- Next to Room 233, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-2-HAL-F12	Main- Next to Room 233, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F12	Main- Next to Room 233, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F12	Main- Next to Room 233, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F12	Main- Next to Room 233, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-2-HAL-F12	Main- Next to Room 233, Right Fountain	Initial	30-JAN-2024	1.490	ug/L
51534	51534-3-HAL-F16	Main- Next to Room 315A, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F16	Main- Next to Room 315A, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F16	Main- Next to Room 315A, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F16	Main- Next to Room 315A, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F16	Main- Next to Room 315A, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F16	Main- Next to Room 315A, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F16	Main- Next to Room 315A, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F16	Main- Next to Room 315A, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F16	Main- Next to Room 315A, Left Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC30	Main- Outside 114, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC30	Main- Outside 114, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC30	Main- Outside 114, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC30	Main- Outside 114, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC30	Main- Outside 114, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC30	Main- Outside 114, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC30	Main- Outside 114, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC30	Main- Outside 114, Left Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC31	Main- Outside 114, Right Fountain	Initial	30-JAN-2024	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-1-HAL-WC22	Main- Outside Auditorium, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC22	Main- Outside Auditorium, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC22	Main- Outside Auditorium, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC22	Main- Outside Auditorium, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC22	Main- Outside Auditorium, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC23	Main- Outside Auditorium, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC23	Main- Outside Auditorium, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC23	Main- Outside Auditorium, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC23	Main- Outside Auditorium, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC23	Main- Outside Auditorium, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC22	Main- Outside Pool, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC22	Main- Outside Pool, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC22	Main- Outside Pool, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC22	Main- Outside Pool, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC22	Main- Outside Pool, Left Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC23	Main- Outside Pool, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC23	Main- Outside Pool, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC23	Main- Outside Pool, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC23	Main- Outside Pool, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC23	Main- Outside Pool, Right Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-BF02	Main- Outside Room 104, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-BF02	Main- Outside Room 104, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-BF02	Main- Outside Room 104, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-BF02	Main- Outside Room 104, Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC25B	Main- Outside Room 104, Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC25B	Main- Outside Room 104, Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC25B	Main- Outside Room 104, Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC25B	Main- Outside Room 104, Bottle Filler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC25B	Main- Outside Room 104, Bottle Filler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-BF02	Main- Outside Room 104, Bottle Filler	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Flush180	04-OCT-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	WC25A	Cooler				
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-WC25A	Main- Outside Room 104, Water Cooler	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F27	Main- Outside Room 133, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F27	Main- Outside Room 133, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F27	Main- Outside Room 133, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F27	Main- Outside Room 133, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F27	Main- Outside Room 133, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-RBF01	Main- Outside Room 133, Left Retrofit BF	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-RBF01	Main- Outside Room 133, Left Retrofit BF	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-RBF01	Main- Outside Room 133, Left Retrofit BF	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-RBF01	Main- Outside Room 133, Left Retrofit BF	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F26	Main- Outside Room 133, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F26	Main- Outside Room 133, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F26	Main- Outside Room 133, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-HAL-F26	Main- Outside Room 133, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F26	Main- Outside Room 133, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F26	Main- Outside Room 133, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F26	Main- Outside Room 133, Right Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-1-HAL-F26	Main- Outside Room 133, Right Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Flush	29-FEB-2024	1.000	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Flush	29-FEB-2024	1.000	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Flush	29-FEB-2024	1.000	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Flush	29-FEB-2024	1.000	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Flush	30-JAN-2024	12.800	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Initial	29-FEB-2024	1.000	ug/L
51534	51534-3-HAL-RBF01	Main- Outside Room 306, Retrofit Bottle Filler, Left	Initial	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F13	Main- Outside Room 306, Right Fountain	Flush	30-JAN-2024	1.200	ug/L
51534	51534-3-HAL-F13	Main- Outside Room 306, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F13	Main- Outside Room 306, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F13	Main- Outside Room 306, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F13	Main- Outside Room 306, Right Fountain	Initial	30-JAN-2024	2.210	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F13	Fountain				
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Initial	04-OCT-16	1.000	ppb
51534	51534-3-HAL-F07	Main- Outside Room 326, Left Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F08	Main- Outside Room 326, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F08	Main- Outside Room 326, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F08	Main- Outside Room 326, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F08	Main- Outside Room 326, Right Fountain	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-F08	Main- Outside Room 326, Right Fountain	Initial	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-RBF02	Main- Outside Room 333, Retrofit Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-RBF02	Main- Outside Room 333, Retrofit Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-RBF02	Main- Outside Room 333, Retrofit Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-RBF02	Main- Outside Room 333, Retrofit Bottle Filler	Flush	30-JAN-2024	1.000	ug/L
51534	51534-3-HAL-RBF02	Main- Outside Room 333, Retrofit Bottle Filler	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-108-F32	Main- Pool Area, Fountain	Flush180	04-OCT-16	5.700	ppb
51534	51534-1-108-F32	Main- Pool Area, Fountain	Flush180	04-OCT-16	5.300	ppb
51534	51534-1-108-F32	Main- Pool Area, Fountain	Flush180	04-OCT-16	4.700	ppb
51534	51534-1-108-F32	Main- Pool Area, Fountain	Flush180	04-OCT-16	6.600	ppb
51534	51534-1-108-F32	Main- Pool Area, Fountain	Initial	04-OCT-16	7.600	ppb
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Initial	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS04	Main- West Kitchen, Island Sink	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS07	Main- West Kitchen, South Wall, Center Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS07	Main- West Kitchen, South Wall, Center Sink	Flush180	04-OCT-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-1-KIT-KS07	Main- West Kitchen, South Wall, Center Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS07	Main- West Kitchen, South Wall, Center Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS07	Main- West Kitchen, South Wall, Center Sink	Initial	04-OCT-16	2.700	ppb
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Flush180	04-OCT-16	3.000	ppb
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Initial	04-OCT-16	10.000	ppb
51534	51534-1-KIT-KS09	Main- West Kitchen, South Wall, First From Right S	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS05	Main- West Kitchen, South Wall, First Left Sink	Flush180	04-OCT-16	2.500	ppb
51534	51534-1-KIT-KS05	Main- West Kitchen, South Wall, First Left Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS05	Main- West Kitchen, South Wall, First Left Sink	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS05	Main- West Kitchen, South Wall, First Left Sink	Initial	04-OCT-16	3.500	ppb
51534	51534-1-KIT-KS06	Main- West Kitchen, South Wall, Second From Left S	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS06	Main- West Kitchen, South Wall, Second From Left S	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS06	Main- West Kitchen, South Wall, Second From Left S	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS06	Main- West Kitchen, South Wall, Second From Left S	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS06	Main- West Kitchen, South Wall, Second From Left S	Initial	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS08	Main- West Kitchen, South Wall, Second From Right	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS08	Main- West Kitchen, South Wall, Second From Right	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS08	Main- West Kitchen, South Wall, Second From Right	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS08	Main- West Kitchen, South Wall, Second From Right	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS08	Main- West Kitchen, South Wall, Second From Right	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS08	Main- West Kitchen, South Wall, Second From Right	Flush180	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS08	Main- West Kitchen, South Wall, Second From Right	Initial	04-OCT-16	1.000	ppb
51534	51534-1-KIT-KS08	Main- West Kitchen, South Wall, Second From Right	Initial	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS10	Main- West Kitchen, South Wall, Sprayer	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS10	Main- West Kitchen, South Wall, Sprayer	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS10	Main- West Kitchen, South Wall, Sprayer	Flush	30-JAN-2024	1.000	ug/L
51534	51534-1-KIT-KS10	Main- West Kitchen, South Wall, Sprayer	Flush	30-JAN-2024	1.000	ug/L

## Water Quality Assessment Albert G Lane Technical High School

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51534	51534-1-KIT-KS10	Main- West Kitchen, South Wall, Sprayer	Initial	30-JAN-2024	2.920	ug/L
54351	54351-1-HAL-F02	Annex- Drivers Ed Building, Fountain	Flush180	04-OCT-16	1.000	ppb
54351	54351-1-HAL-F02	Annex- Drivers Ed Building, Fountain	Flush180	04-OCT-16	1.000	ppb
54351	54351-1-HAL-F02	Annex- Drivers Ed Building, Fountain	Flush180	04-OCT-16	1.000	ppb
54351	54351-1-HAL-F02	Annex- Drivers Ed Building, Fountain	Flush180	04-OCT-16	1.000	ppb
54351	54351-1-HAL-F02	Annex- Drivers Ed Building, Fountain	Initial	04-OCT-16	1.000	ppb
54351	54351-1-HAL-F01	Annex- Football Stadium Next to Track, Fountain	Flush180	04-OCT-16	3.100	ppb
54351	54351-1-HAL-F01	Annex- Football Stadium Next to Track, Fountain	Flush180	04-OCT-16	1.000	ppb
54351	54351-1-HAL-F01	Annex- Football Stadium Next to Track, Fountain	Flush180	04-OCT-16	9.900	ppb
54351	54351-1-HAL-F01	Annex- Football Stadium Next to Track, Fountain	Flush180	04-OCT-16	3.700	ppb
54351	54351-1-HAL-F01	Annex- Football Stadium Next to Track, Fountain	Initial	04-OCT-16	7.600	ppb