



Sep 10, 2024

**PHOENIX MILITARY HS**

**145 S CAMPBELL AVE, Chicago IL 60612.**

Dear **PHOENIX MILITARY HS** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit [www.cdc.gov/lead](http://www.cdc.gov/lead).

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



**Sep 10, 2024**

**PHOENIX MILITARY HS**

**145 S CAMPBELL AVE, Chicago IL 60612.**

Estimadas familias de **PHOENIX MILITARY HS:**

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que iguallen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarle y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer  
Director de Salud y Seguridad Ambientales  
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51185	51185-1-HAL-F11		Flush180	27-OCT-16	13.000	ppb
51185	51185-1-HAL-F11		Flush180	27-OCT-16	15.000	ppb
51185	51185-1-HAL-F11		Flush180	27-OCT-16	15.000	ppb
51185	51185-1-HAL-F11		Flush180	27-OCT-16	14.000	ppb
51185	51185-1-HAL-F11		Flush180	10-JAN-17	1.000	ppb
51185	51185-1-HAL-F11		Flush180	10-JAN-17	1.000	ppb
51185	51185-1-HAL-F11		Flush180	10-JAN-17	1.000	ppb
51185	51185-1-HAL-F11		Flush180	10-JAN-17	2.100	ppb
51185	51185-1-HAL-F11		Initial	27-OCT-16	10.000	ppb
51185	51185-1-HAL-F11		Initial	10-JAN-17	1.000	ppb
51185	51185-1-HAL-RBF01	1st Floor Bottle Filler Left Side Outside Room 129	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-HAL-RBF01	1st Floor Bottle Filler Left Side Outside Room 129	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-HAL-RBF01	1st Floor Bottle Filler Left Side Outside Room 129	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-HAL-RBF01	1st Floor Bottle Filler Left Side Outside Room 129	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-HAL-RBF01	1st Floor Bottle Filler Left Side Outside Room 129	Initial	01-NOV-2023	1.000	ug/L
51185	51185-1-HAL-F07	1st Floor Fountain Across From Lunchroom 156	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F07	1st Floor Fountain Across From Lunchroom 156	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F07	1st Floor Fountain Across From Lunchroom 156	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F07	1st Floor Fountain Across From Lunchroom 156	Initial	27-OCT-16	1.000	ppb
51185	51185-1-169B-F17	1st Floor Fountain Boys Locker Room Left Side 169B	Flush	01-NOV-2023	1.130	ug/L
51185	51185-1-169B-F17	1st Floor Fountain Boys Locker Room Left Side 169B	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-169B-F17	1st Floor Fountain Boys Locker Room Left Side 169B	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-169B-F17	1st Floor Fountain Boys Locker Room Left Side 169B	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-169B-F17	1st Floor Fountain Boys Locker Room Left Side 169B	Initial	01-NOV-2023	2.870	ug/L
51185	51185-1-170B-F17	1st Floor Fountain Boys Locker Room Left Side 170B	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-170B-F17	1st Floor Fountain Boys Locker Room Left Side 170B	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-170B-F17	1st Floor Fountain Boys Locker Room Left Side 170B	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-170B-F17	1st Floor Fountain Boys Locker Room Left Side 170B	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-170B-F17	1st Floor Fountain Boys Locker Room Left Side 170B	Initial	27-OCT-16	1.000	ppb
51185	51185-1-173B-F15	1st Floor Fountain Boys Locker Room Left Side 173B	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-173B-F15	1st Floor Fountain Boys Locker Room Left Side 173B	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-173B-F15	1st Floor Fountain Boys Locker Room Left Side 173B	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-173B-F15	1st Floor Fountain Boys Locker Room Left Side 173B	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-173B-F15	1st Floor Fountain Boys Locker Room Left Side 173B	Initial	27-OCT-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51185	51185-1-165B-F22	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	17-MAY-23	1.210	ug/L
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	17-MAY-23	1.000	ug/L
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	17-MAY-23	1.000	ug/L
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	17-MAY-23	1.000	ug/L
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	17-MAY-23	1.000	ug/L
51185	51185-1-165B-F22	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-165B-F22	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-165B-F22	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-165B-F22	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-165B-F22	1st Floor Fountain Girls Locker Room Right Side 16	Initial	13-JUN-23	2.770	ug/L
51185	51185-1-165B-F22	1st Floor Fountain Girls Locker Room Right Side 16	Initial	17-MAY-23	8.570	ug/L
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Initial	17-MAY-23	2.790	ug/L
51185	51185-1-165B-F22	1st Floor Fountain Girls Locker Room Right Side 16	Initial	27-OCT-16	8.400	ppb
51185	51185-1-168B-F20	1st Floor Fountain Girls Locker Room Right Side 16	Initial	27-OCT-16	8.600	ppb
51185	51185-1-169A-F22	1st Floor Fountain Girls Locker Room Right Side 169A	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-169A-F22	1st Floor Fountain Girls Locker Room Right Side 169A	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-169A-F22	1st Floor Fountain Girls Locker Room Right Side 169A	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-169A-F22	1st Floor Fountain Girls Locker Room Right Side 169A	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-169A-F22	1st Floor Fountain Girls Locker Room Right Side 169A	Initial	01-NOV-2023	1.820	ug/L
51185	51185-1-GYM-F13	1st Floor Fountain Gym Left Side West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-GYM-F13	1st Floor Fountain Gym Left Side West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-GYM-F13	1st Floor Fountain Gym Left Side West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-GYM-F13	1st Floor Fountain Gym Left Side West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-GYM-F13	1st Floor Fountain Gym Left Side West Wall	Initial	27-OCT-16	1.000	ppb
51185	51185-1-GYM-F14	1st Floor Fountain Gym Right Side West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-GYM-F14	1st Floor Fountain Gym Right Side West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-GYM-F14	1st Floor Fountain Gym Right Side West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-GYM-F14	1st Floor Fountain Gym Right Side West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-GYM-F14	1st Floor Fountain Gym Right Side West Wall	Initial	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F09	1st Floor Fountain Left Side Outside Room 129	Flush	01-NOV-2023	1.010	ug/L
51185	51185-1-HAL-F09	1st Floor Fountain Left Side Outside Room 129	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-HAL-F09	1st Floor Fountain Left Side Outside Room 129	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-HAL-F09	1st Floor Fountain Left Side Outside Room 129	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-HAL-	1st Floor Fountain Left Side	Flush180	27-OCT-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F09	Outside Room 129				
51185	51185-1-HAL-F09	1st Floor Fountain Left Side Outside Room 129	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F09	1st Floor Fountain Left Side Outside Room 129	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F09	1st Floor Fountain Left Side Outside Room 129	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F09	1st Floor Fountain Left Side Outside Room 129	Initial	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F09	1st Floor Fountain Left Side Outside Room 129	Initial	01-NOV-2023	1.000	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	22-NOV-2023	24.800	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	22-NOV-2023	28.500	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	22-NOV-2023	31.100	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	22-NOV-2023	19.500	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	01-NOV-2023	130.00 0	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	01-NOV-2023	130.00 0	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	01-NOV-2023	83.100	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	01-NOV-2023	22.600	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	17-MAY-2024	10.100	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	17-MAY-2024	6.620	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	17-MAY-2024	5.150	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush	17-MAY-2024	2.670	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush180	27-OCT-16	4.100	ppb
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush180	27-OCT-16	3.000	ppb
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush180	27-OCT-16	3.800	ppb
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Flush180	27-OCT-16	3.200	ppb
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Initial	27-OCT-16	4.500	ppb
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Initial	22-NOV-2023	36.200	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Initial	01-NOV-2023	152.00 0	ug/L
51185	51185-1-HAL-F08	1st Floor Fountain Outside Room 132	Initial	17-MAY-2024	48.400	ug/L
51185	51185-1-HAL-F12	1st Floor Fountain Right Side Outside Network Offi	Flush180	27-OCT-16	11.000	ppb
51185	51185-1-HAL-F12	1st Floor Fountain Right Side Outside Network Offi	Flush180	27-OCT-16	12.000	ppb
51185	51185-1-HAL-F12	1st Floor Fountain Right Side Outside Network Offi	Flush180	27-OCT-16	14.000	ppb
51185	51185-1-HAL-F12	1st Floor Fountain Right Side Outside Network Offi	Flush180	27-OCT-16	13.000	ppb
51185	51185-1-HAL-F12	1st Floor Fountain Right Side Outside Network Offi	Initial	27-OCT-16	9.000	ppb
51185	51185-1-HAL-F10	1st Floor Fountain Right Side Outside Room 129	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F10	1st Floor Fountain Right Side Outside Room 129	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F10	1st Floor Fountain Right Side Outside Room 129	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F10	1st Floor Fountain Right Side Outside Room 129	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-HAL-F10	1st Floor Fountain Right Side Outside Room 129	Initial	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush	22-NOV-2023	3.870	ug/L
51185	51185-1-KIT-	1st Floor Kitchen Center Sink	Flush	22-NOV-2023	4.120	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	KS01					
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush	22-NOV-2023	4.430	ug/L
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush	22-NOV-2023	3.620	ug/L
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush	01-NOV-2023	29.000	ug/L
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush	01-NOV-2023	13.500	ug/L
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush	01-NOV-2023	9.750	ug/L
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush	01-NOV-2023	11.200	ug/L
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush180	27-OCT-16	2.100	ppb
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Initial	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Initial	22-NOV-2023	2.980	ug/L
51185	51185-1-KIT-KS01	1st Floor Kitchen Center Sink	Initial	01-NOV-2023	16.500	ug/L
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Initial	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS05	1st Floor Kitchen Sink Center East Wall	Initial	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS03	1st Floor Kitchen Sink East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS03	1st Floor Kitchen Sink East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS03	1st Floor Kitchen Sink East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS03	1st Floor Kitchen Sink East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS03	1st Floor Kitchen Sink East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS03	1st Floor Kitchen Sink East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS03	1st Floor Kitchen Sink East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS03	1st Floor Kitchen Sink East Wall	Initial	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS03	1st Floor Kitchen Sink East Wall	Initial	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Flush	01-NOV-2023	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Initial	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS04	1st Floor Kitchen Sink Left Side East Wall	Initial	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Initial	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS06	1st Floor Kitchen Sink Right Side East Wall	Initial	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS02	1st Floor Kitchen Sink West Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS02	1st Floor Kitchen Sink West Wall	Flush	01-NOV-2023	1.000	ug/L
51185	51185-1-KIT-KS02	1st Floor Kitchen Sink West Wall	Flush	01-NOV-2023	1.140	ug/L
51185	51185-1-KIT-KS02	1st Floor Kitchen Sink West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS02	1st Floor Kitchen Sink West Wall	Flush180	27-OCT-16	2.800	ppb
51185	51185-1-KIT-KS02	1st Floor Kitchen Sink West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS02	1st Floor Kitchen Sink West Wall	Flush180	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS02	1st Floor Kitchen Sink West Wall	Initial	27-OCT-16	1.000	ppb
51185	51185-1-KIT-KS02	1st Floor Kitchen Sink West Wall	Initial	01-NOV-2023	2.110	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	22-NOV-2023	34.300	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	22-NOV-2023	25.400	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	22-NOV-2023	23.100	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	22-NOV-2023	26.400	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	01-NOV-2023	77.200	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	01-NOV-2023	134.000	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	01-NOV-2023	126.000	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	01-NOV-2023	61.600	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	17-MAY-2024	34.100	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	17-MAY-2024	34.200	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	17-MAY-2024	35.500	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush	17-MAY-2024	39.100	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Initial	27-OCT-16	3.400	ppb
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Initial	22-NOV-2023	22.800	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Initial	01-NOV-2023	16.800	ug/L
51185	51185-2-HAL-F02	2nd Floor Fountain Across From Room 232	Initial	17-MAY-2024	9.660	ug/L
51185	51185-2-HAL-F01	2nd Floor Fountain Across From Room 239	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F01	2nd Floor Fountain Across From Room 239	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F01	2nd Floor Fountain Across From Room 239	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F01	2nd Floor Fountain Across From Room 239	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F01	2nd Floor Fountain Across From Room 239	Initial	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F03	2nd Floor Fountain Left Side Across From Room 229	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F03	2nd Floor Fountain Left Side Across From Room 229	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F03	2nd Floor Fountain Left Side Across From Room 229	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F03	2nd Floor Fountain Left Side Across From Room 229	Initial	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush	01-NOV-2023	1.260	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush	01-NOV-2023	4.430	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	11-JUL-23	3.150	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	11-JUL-23	2.380	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	11-JUL-23	1.600	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	11-JUL-23	1.000	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	17-MAY-23	21.700	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	17-MAY-23	10.200	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	13-JUN-23	6.050	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	13-JUN-23	3.090	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	13-JUN-23	6.960	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	13-JUN-23	1.880	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	17-MAY-23	9.340	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	17-MAY-23	7.830	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	27-OCT-16	3.100	ppb
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	27-OCT-16	5.000	ppb
51185	51185-2-HAL-	2nd Floor Fountain Left Side	Flush180	27-OCT-16	2.900	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F05	Across From Room 624				
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Flush180	27-OCT-16	6.000	ppb
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Initial	11-JUL-23	7.010	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Initial	13-JUN-23	10.400	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Initial	17-MAY-23	3.590	ug/L
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Initial	27-OCT-16	2.700	ppb
51185	51185-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 624	Initial	01-NOV-2023	2.610	ug/L
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Flush	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Flush	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Flush	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Flush	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Initial	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 229	Initial	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Flush	01-NOV-2023	7.930	ug/L
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Flush	01-NOV-2023	4.210	ug/L
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Flush	01-NOV-2023	2.350	ug/L
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Flush	01-NOV-2023	1.710	ug/L
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Flush180	27-OCT-16	2.300	ppb
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Flush180	27-OCT-16	2.800	ppb
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Flush180	27-OCT-16	2.000	ppb
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Flush180	27-OCT-16	1.000	ppb
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Initial	27-OCT-16	3.300	ppb
51185	51185-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 624	Initial	01-NOV-2023	2.830	ug/L
51185	51185-2-HAL-RBF01	2nd floor Bottle Filler Left Side Across From Room 229	Flush	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-RBF01	2nd floor Bottle Filler Left Side Across From Room 229	Flush	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-RBF01	2nd floor Bottle Filler Left Side Across From Room 229	Flush	01-NOV-2023	1.000	ug/L
51185	51185-2-HAL-RBF01	2nd floor Bottle Filler Left Side Across From Room 229	Initial	01-NOV-2023	1.100	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	22-NOV-2023	33.200	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	22-NOV-2023	61.400	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	22-NOV-2023	40.900	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	22-NOV-2023	28.300	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	01-NOV-2023	6.200	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From	Flush	01-NOV-2023	4.700	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F02	Room 332				
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	01-NOV-2023	5.070	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	01-NOV-2023	5.170	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	17-MAY-2024	5.720	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	17-MAY-2024	4.500	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	17-MAY-2024	8.070	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush	17-MAY-2024	20.300	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush180	27-OCT-16	2.600	ppb
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush180	27-OCT-16	2.800	ppb
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush180	27-OCT-16	2.400	ppb
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Flush180	27-OCT-16	2.100	ppb
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Initial	27-OCT-16	2.600	ppb
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Initial	22-NOV-2023	110.000	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Initial	01-NOV-2023	4.080	ug/L
51185	51185-3-HAL-F02	3rd Floor Fountain Across From Room 332	Initial	17-MAY-2024	15.400	ug/L
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Initial	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F01	3rd Floor Fountain Across From Room 338	Initial	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Flush	01-NOV-2023	1.380	ug/L
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Initial	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F03	3rd Floor Fountain Left Side Outside Room 329	Initial	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F05	3rd Floor Fountain Left Side Outside Room 724	Flush180	27-OCT-16	4.100	ppb
51185	51185-3-HAL-F05	3rd Floor Fountain Left Side Outside Room 724	Flush180	27-OCT-16	4.200	ppb
51185	51185-3-HAL-F05	3rd Floor Fountain Left Side Outside Room 724	Flush180	27-OCT-16	3.500	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51185	51185-3-HAL-F05	3rd Floor Fountain Left Side Outside Room 724	Flush180	27-OCT-16	4.600	ppb
51185	51185-3-HAL-F05	3rd Floor Fountain Left Side Outside Room 724	Initial	27-OCT-16	3.400	ppb
51185	51185-3-HAL-F04	3rd Floor Fountain Right Side Outside Room 329	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F04	3rd Floor Fountain Right Side Outside Room 329	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F04	3rd Floor Fountain Right Side Outside Room 329	Flush	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F04	3rd Floor Fountain Right Side Outside Room 329	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F04	3rd Floor Fountain Right Side Outside Room 329	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F04	3rd Floor Fountain Right Side Outside Room 329	Flush180	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F04	3rd Floor Fountain Right Side Outside Room 329	Initial	27-OCT-16	1.000	ppb
51185	51185-3-HAL-F04	3rd Floor Fountain Right Side Outside Room 329	Initial	01-NOV-2023	1.000	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	22-NOV-2023	8.840	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	22-NOV-2023	9.200	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	22-NOV-2023	9.950	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	22-NOV-2023	10.500	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	01-NOV-2023	32.900	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	01-NOV-2023	9.220	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	01-NOV-2023	8.730	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	01-NOV-2023	8.260	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	17-MAY-2024	5.200	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	17-MAY-2024	5.640	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	17-MAY-2024	5.620	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush	17-MAY-2024	5.430	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	11-JUL-23	8.110	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	11-JUL-23	37.600	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	11-JUL-23	72.400	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	11-JUL-23	60.800	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	13-JUN-23	9.470	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	13-JUN-23	8.780	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	13-JUN-23	7.880	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	13-JUN-23	6.980	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	17-MAY-23	7.420	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	17-MAY-23	7.620	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	17-MAY-23	6.930	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	17-MAY-23	7.020	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	27-OCT-16	12.000	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	27-OCT-16	12.000	ppb
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	27-OCT-16	13.000	ppb
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Flush180	27-OCT-16	14.000	ppb
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Initial	11-JUL-23	5.640	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Initial	13-JUN-23	56.600	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Initial	17-MAY-23	4.140	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Initial	27-OCT-16	5.800	ppb
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Initial	22-NOV-2023	16.300	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Initial	01-NOV-2023	28.400	ug/L
51185	51185-3-HAL-F06	3rd Floor Fountain Right Side Outside Room 724	Initial	17-MAY-2024	5.630	ug/L
51185	51185-4-HAL-RTBF01	4th Floor Fountain Left Side Outside Room 429	Flush	01-NOV-2023	3.050	ug/L
51185	51185-4-HAL-RTBF01	4th Floor Fountain Left Side Outside Room 429	Flush	01-NOV-2023	2.820	ug/L
51185	51185-4-HAL-RTBF01	4th Floor Fountain Left Side Outside Room 429	Flush	01-NOV-2023	2.810	ug/L
51185	51185-4-HAL-RTBF01	4th Floor Fountain Left Side Outside Room 429	Flush	01-NOV-2023	2.860	ug/L
51185	51185-4-HAL-F01	4th Floor Fountain Left Side Outside Room 429	Flush180	27-OCT-16	1.000	ppb
51185	51185-4-HAL-F01	4th Floor Fountain Left Side Outside Room 429	Flush180	27-OCT-16	1.000	ppb
51185	51185-4-HAL-F01	4th Floor Fountain Left Side Outside Room 429	Flush180	27-OCT-16	1.000	ppb
51185	51185-4-HAL-F01	4th Floor Fountain Left Side Outside Room 429	Initial	27-OCT-16	1.000	ppb
51185	51185-4-HAL-RTBF01	4th Floor Fountain Left Side Outside Room 429	Initial	01-NOV-2023	2.300	ug/L
51185	51185-4-HAL-F02	4th Floor Fountain Right Side Outside Room 429	Flush	01-NOV-2023	2.660	ug/L
51185	51185-4-HAL-F02	4th Floor Fountain Right Side Outside Room 429	Flush	01-NOV-2023	2.500	ug/L
51185	51185-4-HAL-F02	4th Floor Fountain Right Side Outside Room 429	Flush	01-NOV-2023	2.340	ug/L
51185	51185-4-HAL-F02	4th Floor Fountain Right Side Outside Room 429	Flush	01-NOV-2023	2.160	ug/L
51185	51185-4-HAL-F02	4th Floor Fountain Right Side Outside Room 429	Flush180	27-OCT-16	1.000	ppb
51185	51185-4-HAL-F02	4th Floor Fountain Right Side Outside Room 429	Flush180	27-OCT-16	1.000	ppb
51185	51185-4-HAL-F02	4th Floor Fountain Right Side Outside Room 429	Flush180	27-OCT-16	1.000	ppb
51185	51185-4-HAL-F02	4th Floor Fountain Right Side Outside Room 429	Initial	27-OCT-16	1.000	ppb
51185	51185-4-HAL-F02	4th Floor Fountain Right Side Outside Room 429	Initial	01-NOV-2023	1.730	ug/L