## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

22231 Alexander Graham Bell Elementary School 2270 School: **Oracle Unit: Building ID:** Address: 3730 N Oakley Avenue Region: 01 Mail Room: Asbestos Surveyor: Gonzalez, Sergio X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/11/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Skim Coat and Hard Coat YES 01 X NO Main Building No None Surface 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
02	2'x4' Ceiling Tile			Throughout		Miscellaneous	Yes	Unknown			YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	Ü											
2017 - Spring	g: No Change				1							
Comments:												
2017 - Fall: N	lo Change				=							
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				=							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Carpet Mastic	72000	SF	Throughout		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" White w/ Gray Vinyl Floor Tile	200	SF	Janitor's Closets on the 1st, 2nd & 3rd Floors by Boy's & Girl's Toilets		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	•	•	•	]	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9"x9" Gray Vinyl Floor Tile	400	SF	200E, Book Rm by Balcony, 1st Fl Toilet by 101		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
08	Green Linoleum	900	SF	Kindergarten (112)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				1							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change				=							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" White w/ Gray Vinyl Floor Tile Mastic	200	SF	Janitor's Closets on the 1st, 2nd & 3rd Floors by Boy's & Girl's Toilets		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
10	9"x9" Gray Vinyl Floor Tile Mastic	400	SF	200E, Book Rm by Balcony, 1st Fl Toilet by 107		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change			•	- 1	•	-	•	•	•	•	
Comments												
2017 - Spr	ring: No Change											
Comments	S:				_							
2017 - Fall	I: No Change				]							
Comments	S:				_							
2018 - Spr	ring : No Change				<u> </u>							
Comments	S:			·								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	9"x9" Brown Vinyl Floor Tile	360	SF	Room 307, 309 (Under Carpet)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	9"x9" Brown Vinyl Floor Tile Mastic	360	SF	Room 307, 309 (Under Carpet)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Beige Vinyl Floor Tile	1500	SF	Engineers Office, Lunchroom Toilet, Rooms 304 and 314		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Beige Vinyl Floor Tile Mastic	1500	SF	Engineers Office, Lunchroom Toilet, Rooms 304 and 314		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change			· 					·		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Brown Linoleum	60	SF	Main Office Closet, Phone Booths		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 7

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
17	Brown Linoleum Mastic	60	SF	Main Office Closet, Phone Booths		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:	•				1							
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:					=							
2018 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	o Change											
Comments:					-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9'x9" Beige w/ Brown Streaks VFT NOT OBSERVED	600	SF	1st Floor Former Teachers Lunchroom Under the Carpet (Rm 105)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
19	9'x9" Beige w/ Brown Streaks VFT Mastic NOT OBSERVED	600	SF	1st Floor Former Teachers Lunchroom Under the Carpet (Rm 105)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
:	20	9"x9" Light Tan VFT - NOT OBSERVED	80	SF	Lunchroom North and South Storage Rooms, now under HA# 06, HA# 09 - NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

21	9"x9" Light Tan VFT Mastic - NOT OBSERVED			Lunchroom North and South Storage Rooms - NOT OBSERVED							YES	X NO
2016 - Fa	all: No Change				7							
Commen					1							
2017 - Sp	oring: No Change											
Commen	ts:											
2017 - Fa	all: No Change											
Comment	ts:											
2018 - Sp	oring : No Change											
Comment	ts:				4							
2018 - Fa	all: No Change											
Commen	ts:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
			1	†		1		1			Ì	

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

1500

SF

Lunchroom

HA No

22

Material Description

12"x12" White w/ Green

Specks VFT

Material

Units

Material

Quantity

Material Location

Lunghroom North and

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" White w/ Green Specks VFT Mastic	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	1 x 1 ft Ceiling Tiles	1000	SF	Students Lunch Room		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"X12" White w/ Blue Specks VFT	800	SF	Lunch Room		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12" X 12" Gray/Blue w/Gray Specks	300	SF	Lunch Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"X12" Tan w/Brown Specks	100	SF	Lunch Room		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"X12" Pink w/White- Marbled VFT	100	SF	Lunch Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		
29	12"X12" Yellow w/White- Marbled VFT	100	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprii	2017 - Spring: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:												

Material

Friable

Damage

Damage

Asbestos

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Mastic associated with the new HA numbers 25, 26, 27, 28, and 29.	1400	SF	Lunch Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
31	12" X 12" light beige with beige-and-white streaks, VFT	800	SF	Room 314 B		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•	•	~	1	•	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31A	12" X 12" light beige with beige-and-white streaks, Mastic	800	SF	Room 314 B		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" X 12" white with black specks, VFT	1100	SF	Rm 312		Miscellaneous	No	None	0		YES X NO

		II.
_	 	
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32A	12" X 12" white with black specks, Mastic	1100	SF	Rm 312		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Page 16

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	18 " X 18" brown VFT	500	SF	3rd floor toilet by Rm 312; 2nd floor toilet by Rm 212		Miscellaneous	No	None	0		YES X NO
2016 Fall N	o Chongo										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	18" X 18" brown, Mastic	500	SF	3rd floor toilet by Rm 312; 2nd floor toilet by Rm 212		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Mudded joint packing on fiberglass runs	50	LF	Attic, 3rd floor corridor above ceiling tiles, Auditorium vestibules, Book Room by balcony 200S.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Decorative plaster	2500	SF	Auditorium and balcony		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

36	1'x1' Ceiling Tile			Rooms 317 and 105		Miscellaneous	Yes	Unknown			YES	X NO
2016 - Fall:	No Change				1							
Comments:												
	No Change	]										
Comments:					_							
	ng: No Change											
Comments:												
2018 - Fall: No Change												
Comments:												
2018 - Spring : No Change												
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36A	1'x1' Ceiling Tile Mastic			Rooms 317 and 105		Miscellaneous	No	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
С	Aircell Pipe Insulation	600	LF	1st Floor Assembly Vestibule (5 LF); Throughout Attic (95 LF)		Miscellaneous	Yes	Dist	100		YES	X NO
2016 - Fall: No Change						•			•	•	•	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Preformed Pipe Insulation	530	LF	2nd & 3rd Fl Boys and Girls Pipe Chases, Attic		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 20

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Alexander Graham Bell Elementary School
Date:1/11/2019
<del></del>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 22231

SCHOOL'S ASBESTOS MANAGEMENT PLAN.