

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2015 - Fall

**School:** Phoebe Apperson Hearst School  
**Address:** 4640 S. Lamon

**Oracle Unit:** 23671  
**Region:** 04

**Building ID:** 3890  
**Mail Room:** 44

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Byrne, Miss Erin Bridget  
**Survey Date:** 11/6/2015  
**Email Address:** ebbyrne@cps.edu

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 *Each child's backpack*   
 *Notice printed in school's newsletter*   
 *Notice printed in school's calendar*   
 *Other*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Boiler Gaskets on Boiler #1			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	Refractory Cement in Boiler #1 Doors			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	Boiler Gaskets on Boiler #2			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	Refractory Cement in Boiler #2 Doors			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Fire Brick in Boiler #1			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	Fire Brick in Boiler #2			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Fire Brick in Incinerator			Elementary School		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	Interior Brick			1951 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Interior Brick Mortar - not AHERA			1951 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Terrazzo Wall Panels			1st Floor Boy's and Girl's Washrooms, Custodian's Lounge		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Spray-On Ceiling Material			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Multi-Brown Ceramic Tile Grout			Elementary School - Entrances and Washrooms of 1951 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Marble Stone Mortar			Elementary School - Gym Foyer and Auditorium		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	9" x 9" Lt Brown Floor Tile w/ Brn & White Strks	1250	SF	Elementary School - Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9" x 9" Lt Brn Floor Tile w/ Brn & Wh Strks Mastic	1250	SF	Elementary School - Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9" x 9" Olive Floor Tile	5250	SF	Elementary School - Rooms 113, 118-121, 214-221, 2nd Floor Hallways and Janitor's Closets		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9" x 9" Olive Floor Tile Mastic	5250	SF	Elementary School - Rooms 118-121, 214-221, 2nd Floor Hallways and Janitor's Closets		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9" x 9" Light Brown Floor Tile	5250	SF	Elementary School - Rooms 118-121, 214-221, 2nd Floor Hallways and Janitor's Closets		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9" x 9" Light Brown Floor Tile Mastic	5250	SF	Elementary School - Rooms 113, 118-121, 214-221, 2nd Floor Hallways and Janitor's Closets		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" Brown w/ White Streaks Floor Tile	10	SF	Elementary School - Room 121		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12" x 12" Brown w/ White Streaks Floor Tile Mastic	10	SF	Elementary School - Room 121		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9" x 9" Gray Floor Tile w/White Streaks			Elementary School - Room 102		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9" x 9" Gray Floor Tile w/ White Streaks Mastic			Elementary School - Room 102		Miscellaneous		Unknown			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9" x 9" Flesh Colored Floor Tile			Elementary School - Room 102		Miscellaneous		Unknown			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9" x 9" Flesh Colored Floor Tile Mastic			Elementary School - Room 102		Miscellaneous		Unknown			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Beige w/Brown & White Specks Floor Tile	250	SF	Elementary School - Room Behind Stage, Patches by Room 102 in Hallway, Rm 108 in Hallway		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Beige w/Brown & White Specks FT Mastic	250	SF	Elementary School - Room Behind Stage		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" Blue Swirled Floor Tile	5250	SF	Elementary School - Office, 105, 107, 110, 112, Teachers Lounge, 208-213, 1st & 2nd Floor Halls		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" x 12" Blue Swirled Floor Tile Mastic	5250	SF	Elementary School - Office, 105, 107, 110, 112, Teachers Lounge, 208-213, 1st & 2nd Floor Halls		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Light Brown Swirled Floor Tile	5250	SF	Elementary School - Office, 105, 110, 112, 113, Teachers Lounge, 208-213, 1st & 2nd Floor Halls		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" Light Brown Swirled Floor Tile Mastic	5250	SF	Elementary School - Office, 105, 107,109, 110, 112, 113, Teachers Lounge, 208-213, 1st & 2nd Floor Halls		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" Gray Floor Tile	350	SF	Elementary School - Room 104		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12" x 12" Gray Floor Tile Mastic	350	SF	Elementary School - Room 104		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" Blue Floor Tile	350	SF	Elementary School - Room 104		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12" x 12" Blue Floor Tile Mastic	350	SF	Elementary School - Room 104		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12" x 12" Brown Floor Tile w/Brown & White Specks	700	SF	Elementary School - 2nd Floor Hall, Rm 109		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12" x 12" Brown FT w/Brown & White Specks Mastic	1300	SF	Elementary School - 2nd Floor Hall & Room 109		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12" x 12" Dark Brown Floor Tile	85	SF	Elementary School - Language Arts, 215, and as Patches in 2nd Flr Hall & Hall Across From 120		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" Dark Brown Floor Tile Mastic	85	SF	Elementary School - Language Arts, 215, and as Patches in 2nd Flr Hall & Hall Across From 120		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" Gray Floor Tile	1600	SF	Elementary School - Language Arts, 215, and as Patches in 2nd Flr Hall & Hall Across From 120		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Gray Floor Tile Mastic	1600	SF	Elementary School - Language Arts, 215, and as Patches in 2nd Flr Hall & Hall Across From 120		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Beige Floor Tile w/ Brown Specs	100	SF	Elementary School - Teacher's Washrooms and Hall in Front of 114		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Beige Floor Tile w/ Brown Specks Mastic	100	SF	Elementary School - Teacher's Washrooms and Hall in Front of 114		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12" x 12" Multi-Brown Floor Tile	600	SF	Elementary School - Room 114		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" x 12" Multi-Brown Floor Tile Mastic	600	SF	Elementary School - Room 114		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" x 12" Light Green Floor Tile	1200	SF	Elementary School - Cafeteria		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12" x 12" Light Green Floor Tile Mastic	1200	SF	Elementary School - Cafeteria		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12" x 12" Brown Floor Tile	800	SF	Elementary School - Kitchen		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" x 12" Brown Floor Tile Mastic	800	SF	Elementary School - Kitchen		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" x 12" White Floor Tile	800	SF	Elementary School - Kitchen		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" x 12" White Floor Tile Mastic	800	SF	Elementary School - Kitchen		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12" x 12" Multi-Brown Floor Tile	400	SF	Elementary School - Kitchen		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12" x 12" Multi-Brown Floor Tile Mastic	400	SF	Elementary School - Kitchen		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	Terrazzo Flooring and Stairs			Stairways of 1951 Construction (Elementary School)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Terrazzo Flooring and Stairs			Stairways of 1958 Construction (Elementary School)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Glazed Brick Mortar			Throughout 1951 Construction (Elementary)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Glazed (Finished) Brick Mortar			Throughout 1958 Construction (Elementary School)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	(Wall) Caulk			Elementary School - 2nd Floor Wall Where 1951 and 1958 Buildings Meet		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Plaster			Throughout 1951 Construction (Elementary)		Surface					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Plaster			Throughout 1958 Construction (Elementary School)		Surface					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Cinder Block Mortar			Throughout 1958 Construction (Elementary School)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	4" Black Vinyl Baseboard			Throughout 1958 Construction (Elementary School)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	4" Black Vinyl Baseboard Mastic			Throughout 1958 Construction (Elementary School)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	Interior Window Caulk			Throughout 1958 Construction (Elementary School)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Window Caulk			Throughout 1951 Construction (Elementary)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	Non-Skid Strips			Elementary School - Stairs to Basement		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Window Caulk			Elementary School - Cafeteria		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	Ceiling Panels	2000	SF	Elementary School - Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12" x 12" Ceiling Tile			Elementary School - Kitchen		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12" x 12" Ceiling Tile Adhesive			Elementary School - Kitchen							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Brown/White Ceramic Tile Grout	50	SF	Elementary School - As Patches in 1951 Construction Washrooms (Boys)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	Multi-Brown Ceramic Tile Grout	200	SF	Entrances and Washrooms in 1958 Construction (Elementary School)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Blue Carpet Mastic	2000	SF	Elementary School - Office, 103, 118		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	Exterior Brick - Not AHERA			1951 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Exterior Brick Mortar - Not AHERA			1951 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	Exterior Brick - not AHERA			1958 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	Exterior Brick Mortar - not AHERA			1958 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	Exterior Door Caulk - Not AHERA			1951 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Exterior Door Caulk - Non-AHERA	80	LF	1958 Construction - Door Entrances		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	Exterior Window Caulk - Not AHERA			1951 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	Exterior Window Caulk - not AHERA			1958 Construction		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	Roofing Material - Non-AHERA			1951 Construction		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	Roofing Material - Non-AHERA			1958 Construction		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	Roof Flashing - Non-AHERA			1951 Construction		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Roof Flashing - Non-AHERA			1958 Construction		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	2' x 4' Ceiling Panels			Throughout Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	12" x 12" Fissured Ceiling Tile			Primary Annex - Gym & Gym Foyer		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	12" x 12" Fissured Ceiling Tile Adhesive	2030	SF	Primary Annex - Gym Foyer		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	12" x 12" Fissured Ceiling Tile (Replacement Tile)			Primary Annex - Gym Foyer		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	12"x12" Fissured Replacement Ceiling Tile Adhesive	50	SF	Primary Annex - Gym Foyer		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	12" x 12" Gray Floor Tile			Throughout Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	12" x 12" Gray Floor Tile Mastic			Throughout Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12" x 12" Black Floor Tile			Throughout Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	12" x 12" Black Floor Tile Mastic			Throughout Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	12" x 12" White Floor Tile			Primary Annex - Hallways		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	12" x 12" White Floor Tile Mastic			Throughout Primary Annex Corridors		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	Multi-Brown Ceramic Tile Grout	600	SF	Primary Annex - Washrooms and Entrances		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	Cinder Block Mortar			Throughout Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	Glazed Brick Mortar			Primary Annex - 402, Various Washrooms		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	Plaster			Primary Annex - Throughout Facility		Surface					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Linoleum			Primary Annex - Ledges Above AH Units in Classrooms		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	Vibration Collars			Primary Annex - Fan Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Interior Brick			Primary Annex - Fan Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	Interior Brick Mortar			Primary Annex - Fan Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Window Caulk			Primary Annex - Throughout Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	White/Rust/Brown Terrazzo			Primary Annex - Gym Foyer, Stairways and Landings		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	Yellow Terrazzo			Primary Annex - Gym Foyer		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Interior Door Caulk			Throughout Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	Hard (Old Type) Boiler Gasket - Boiler #1			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	Fluffy (new Type) Boiler Gasket on Boiler #1			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	Refractory Cement in Boiler #1 Doors			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	Fire Brick in Boiler #1			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	Boiler Gasket - Boiler #2			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	Refractory Cement in Doors on Boiler #2			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	Fire Brick in Boiler #2			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	9" x 9" Tan Floor Tile - ABATED	0	SF	Primary Annex - Boiler Room Storage Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119	9" x 9" Tan Floor Tile Mastic - ABATED	0	SF	Primary Annex - Boiler Room Storage Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	Material in Fire Block - Boiler #2			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121	Material in Vault Door	36	SF	Primary Annex - Stairway Vault		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	Insulation in Firedoors	30	SF	Primary Annex - Entrances and Exits, Boiler Room Door		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123	Exterior Brick - not AHERA			Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	Exterior Brick Mortar - Not AHERA			Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
125	Exterior Window Caulk - Not AHERA			Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	Exterior Door Caulk - Not AHERA			Primary Annex		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
127	Roof Material - Non-AHERA			Primary Annex		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	Roof Flashing - Non-AHERA			Primary Annex - Roof		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
129	Insulation Inside Fire Doors	336	SF	Elementary School - Entrances and Exits		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
130	Block Mortar			Elementary School - Gym		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
131	12" x 12" Brown Floor Tile w/ White & Brown Streak	350	SF	Elementary School - Room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
132	12" x 12" Brn Floor Tile w/ Wh & Brn Streak Mastic	0	SF	Elementary School - Room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
133	12" x 12" Grey Floor Tile w/Brown Streaks	350	SF	Elementary School - Room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
134	12" x 12" Grey Floor Tile w/Brown Streaks Mastic	350	SF	Elementary School - Room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
135	Countertop Laminate	250	SF	Elementary School - Room 113, 114, 115, 117, 119, 121, 214, 215, 217, 219, 221, 220		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
136	Countertop Laminate Mastic	250	SF	Elementary School - Rooms 114, 115, 117, 119, 121, 214, 215, 217, and 219		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
137	12" x 12" Beige Floor Tile w/White Specks	700	SF	Elementary School - Room 109		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
138	12" x 12" Beige Floor Tile w/ White Specks Mastic	700	SF	Elementary School - Room 109		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
139	Sink Undercoating	20	SF	Primary Annex - Rooms 303-306		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
140	Blackboards	1100	SF	Primary Annex: Rooms 400-408		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
141	12"x12" White w/Black Floor Tile	250	SF	1st Floor Hall by Rooms 114-117		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
142	12"x12" White w/Black Floor Tile-Mastic	250	SF	1st Floor Hall by Rooms 114-117		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
143	12"x12" Purple Brown Mix Floor Tile	430	SF	1st Floor Hall by Rooms 114-117, Kitchen/Café		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
144	12"x12" Purple Brown Mix Floor Tile Mastic	430	SF	1st Floor Hall by Rooms 114-117, Kitchen/Café		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
145	12"x12" Taupe Mix Floor Tile	40	SF	2nd Floor Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
146	12"x12" Taupe Mix Floor Tile Mastic	40	SF	2nd floor hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
147	12"x12"Hazel Mix Floor Tile	10	SF	2nd Floor Drinking Fountain area by 217 (patch)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
148	12"x12"Hazel Mix Floor Tile Mastic	10	SF	2nd Floor Drinking Fountain area by 217 (patch)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
149	12"x12" Brown Mix Floor Tile	80	SF	2nd Floor Drinking Fountain area by 217, Cafeteria (patch)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
150	12"x12" Brown Mix Floor Tile Mastic	80	SF	2nd Floor Drinking Fountain area by 217, Cafeteria (patch)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
151	12"x12" White w/Brown Floor Tile	60	SF	1st Floor Drinking Fountains		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
152	12"x12" White w/Brown Floor Tile Mastic	60	SF	1st Floor Drinking Fountains		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
153	Purple Carpet Adhesive	430	SF	Main Office		Miscellaneous	No	Loc	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
154	12"x12" Gray w/Brown Floor Tile	700	SF	Hallway from Room 117 to Stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
155	12"x12" Gray w/Brown Floor Tile Mastic	700	SF	Hallway from Room 117 to Stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
156	Grey Mix Terrazzo	6000	SF	Stairwells		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
157	9" x 9" Tan w/ Browht & White Floor Tile	600	SF	Room 204		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
158	9" x 9" Tan w/ Brown & White floor Tile Mastic	600	SF	Room 204		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
159	12" x 12" Bluish Grey Floor tile	400	SF	Room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
160	12" x 12" bluish grey floor tile mastic	400	SF	room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
161	12" x 12" Lt. Bluish Grey Floor Tile	400	SF	Room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
162	12" x 12" Lt. Bluish Grey Floor Tile Mastic	400	SF	Room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
163	Green Carpet Adhesive	400	SF	Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
164	Blue Carpet Adhesive	300	SF	Room 118		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
165	12" x 12" Lt. Grey w/ White Floor Tile	40000	SF	Annex Hallways, Classrooms, and Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
166	12" x 12" Lt. Grey w/ White Floor Tile Mastic	40000	SF	Annex Hallways, Classrooms, auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
167	12" x 12" Black w/ White Floor Tile	5000	SF	annex Hallway & Classrooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
168	12" x 12" Black w/ White Floor Tile Mastic	5000	SF	Annex Hallways and classrooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
169	12" x 12" White w/ Grey Floor Tile	5000	SF	Annex Hallways & Classrooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
170	12" x 12" White w/ grey Floor Tile Mastic	5000	SF	Annex Hallways & Classrooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
171	2' x 4' Ceiling Tile - white	40000	SF	annex - throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
172	1' x 1' Ceiling Tile - White	4000	SF	annex entrance and auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
173	12" x 12" Green Floor Tile	120	SF	annex engineer's office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
174	12" x 12" Green Floor Tile Mastic	120	sf	annex engineer's office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
175	12"x12" FT Dark Grey with Dark spots	350	SF	Bathrooms 105, 107, 114		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
176	12"x12" Dark Grey with Dark Spots FT Mastic	350	SF	Bathrooms 105, 107, 114		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
177	12"x12" Black with White Spots FT	3000	SF	Kitchen, Lunch Room, Elevator Lobby, Basement, 1st-2nd Floor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
178	12"x12" Black with White Spots FT	3000	SF	Kitchen, Lunch Room, Elevator Lobby, Basement, 1st-2nd Floor Mastic		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
179	12"x12" Blue with White Streaks FT	200	SF	Lobby 126		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
180	12"x12" Blue with White Streaks FT Mastic	200	SF	Lobby 126		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
181	Black Baseboard Glue	500	LF	Kitchen, Lunch Room, Elevator, Lobby, Basement 1st 2nd Floor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
182	12"x12" Beige with Dark spots Tile	200	SF	Lobby 136		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
183	12"x12" Beige with Dark Spots Mastic	200	SF	Lobby 136		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
184	2x4 Ceiling Tile	400	SF	Basement,Elevator Lobby, Library, Reception		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
185	Glue Under Blue with Beige Carpet	400	SF	Main Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
186	Glue Under Grey with White Marks, Carpet	700	SF	Library 200 -202		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
187	Drywall/Drywall Tile	1000	SF	Elevator Lobby Annex 1st, 2nd Floor, Elevator Lobby on Basement, 1st, 2nd Floor.		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
188	12"x12" Yellow with Red Spots FT	200	SF	Lobby 136		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
189	12"x12" Yellow with Red Spots FT Mastic	200	SF	Lobby 136		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
190	12"x12" Blue with White Streaks FT	200	SF	Lobby 136		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
191	12"x12" Blue with White Streaks FT Mastic	200	SF	Lobby 136		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Insulation on Boiler #1 - ABATED	0	SF	Elementary School - Boiler Room		TSI		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Insulation on Boiler #2 - ABATED	0	SF	Elementary School - Boiler Room		TSI		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Fiberglass Pipe Insulation			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Insulation on Top Tank			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Insulation on Bottom Tank			Elementary School - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Insulation Under Metal Jacket of Incinerator			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Aircell Pipe Insulation	6000	LF	Elementary School - Basement, Rm behind Stage, Library Mech		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Cementitious Joint Insulation off Aircell Lines	550	LF	Elementary School - Basement, Rm behind Stage, Library Mech		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Mag-Block Insulation - ABATED	0	LF	Elementary School - Boiler Room		TSI					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Boiler Flue Insulation on Small Boiler - ABATED	0	LF	Elementary School - Boiler Room		TSI		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Fiberglass Pipe Insulation			Primary Annex - Boiler Room, 2nd Floor Fan Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Cementitious Pipe Joint Insulation	63	LF	Primary Annex - 2nd Floor Fan Room		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	Cementitious Pipe Joint Insulation	42	LF	Primary Annex - Crawlspace		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Duct Insulation			Primary Annex - 2nd Floor Fan Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
O	Wrap Around Duct Insulation			Primary Annex - 2nd Floor Fan Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
P	Insulation Under Steel Jacket on Boiler #1			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Insulation Under Steel Jacket on Boiler #2			Primary Annex - Boiler Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	Tank Insulation - ABATED			Elementary School - Boiler Room		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

  

---

Lynn A. Crivello

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Phoebe Apperson Hearst School

Date: 11/6/2015

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**