

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Manierre School
Address 1420 N. Hudson Avenue

Oracle Unit 24311 **Building ID** 4580
Region 2 **General Services Route** 33

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	9"x9" Tan w/ Brown and Green Streaks Floor Tile	4500	SF	Rooms 214-218, 219, 221, 119 & Storage, 116-115, 1st & 2nd Fl Cor, 2nd Fl Men's and Women's Toilets - 1961	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
<small>Comments: Room 214 abated summer 2010 by GSG</small>											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
<small>Comments:</small>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 24311

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	9"x9" Tan w/ Brown and Green Streaks Floor Tile Mastic	4500	SF	Rooms 214-218, 219, 221, 119 & Storage, 116-115, 1st & 2nd Fl Cor, 2nd Fl Men's and Women's Toilets - 1961	Chrysotile	MISC	No	None	0	SF	

3YR Inspector Comments:

Condition Changed in Fall 2010		SF		Chrysotile	MISC					SF	
--------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments: Room 214 abated summer 2010 by GSG

Condition Not Changed in Spring 2011		SF		Chrysotile	MISC					SF	
--------------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments:

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" Tan w/ Beige Streaks Floor Tile	3100	SF	Rooms 201, 202, 203, 204, 205, 102, 104, 101, 103, 1st Fl Teachers Restroom - 1951	Chrysotile	MISC	No	None	0	SF	

3YR Inspector Comments:

Condition Changed in Fall 2010		SF		Chrysotile	MISC					SF	
--------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments: Teahcers restroom abates summer 2010 by GSG

Condition Not Changed in Spring 2011		SF		Chrysotile	MISC					SF	
--------------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments:

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Tan w/ Beige Streaks Floor Tile Mastic	3100	SF	Rooms 201, 202, 203, 204, 205, 102, 104, 101, 103, 1st Fl Teachers Restroom - 1951	Chrysotile	MISC	No	None	0	SF	

3YR Inspector Comments:

Condition Changed in Fall 2010		SF		Chrysotile	MISC					SF	
--------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments: Teahcers restroom abates summer 2010 by GSG

Condition Not Changed in Spring 2011		SF		Chrysotile	MISC					SF	
--------------------------------------	--	----	--	------------	------	--	--	--	--	----	--

Comments:

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Royal Blue w/ Light Blue Speckles Floor Tile	2200	SF	1st & 2nd Fl Corridor, Main Office & Storage - 1946	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Royal Blue w/ Lt Blue Speckles Floor Tile Mastic	2200	SF	1st & 2nd Fl Corridor, Main Office & Storage - 1946	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Hard Coat Plaster	20000	SF	Throughout 1951	Assumed	SURFACE	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Hard Coat Plaster	20000	SF	Throughout 1946	Assumed	SURFACE	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	9"x9" Brown w/ Beige Streak Floor Tile	1800	SF	1st & 2nd Fl Corridor, 115 Entrance - 1961	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Brown w/ Beige Streak Floor Tile Mastic	1800	SF	1st & 2nd Fl Corridor, 115 Entrance - 1961	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9"x9" Peach w/ White, Blue, & Brown Streaks Floor Tile	7000	SF	214, 215, 217, 219, 221, 218, 216, 119, 116, 2nd Fl Teach. Rest Rm & Toilet - 1961	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments: Room 214 abated by GSG Summer 2010											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"x9" Peach w/ White, Bl. & Brn Streaks Floor Tile Mastic	7000	SF	214, 215, 217, 219, 221, 218, 216, 119, 116, 2nd Fl Teach. Rest Rm & Toilet - 1961	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: Room 214 abated by GSG summer 2010											
Condition Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments: room 214 ws abated by GSG Summer 2010											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Off White w/ Brown & White Streaks Floor Tile	2400	SF	116, 119, 1st Fl Corridor By 117 & 119 - 1961	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Off White w/ Brn & White Strks Floor Tile Mastic	2400	SF	116, 119, 1st Fl Corridor By 117 & 119 - 1961	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Coffee w/ Brown & White Specks Floor Tile	1560	SF	Rooms 117, Lunch Room Office - 1961	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Coffee w/ Brown & White Specks Floor Tile Mastic	1560	SF	Rooms 117, Lunch Room Office - 1961	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Tan w/ White Specks Floor Tile Mastic	750	SF	Rm 116 - 1961	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Beige w/ Gray Specks Floor Tile	80	SF	1st Floor Women's Toilet - 1961	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Beige w/ Gray Specks Floor Tile Mastic	80	SF	1st Floor Women's Toilet -1961	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Tan w/ White & Brown Speckles Floor Tile	2500	SF	Lunchroom- 1961	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Tan w/ White & Brown Speckles Floor Tile Mastic	2500	SF	Lunchroom -1961	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Gray w/ Black & Beige Streaks Floor Tile	2400	SF	201, 104, 102, 103, 101, 203, 202, 1st FI Teachers Restroom - 1951	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Gray w/ Black & Beige Streaks Floor Tile Mastic	2400	SF	201, 104, 102, 103, 101, 203, 202, 1st FI Teachers Restroom - 1951	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Royal Blue w/ Light Blue Floor Tile	1300	SF	1st FI Corridor - 1951	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Royal Blue w/ Light Blue Floor Tile Mastic	1300	SF	1st FI Corridor - 1951	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12" x 12" Light Blue Floor Tile	800	SF	2nd Floor Corridor - 1946	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12" x 12" Light Blue Floor Tile Mastic	800	SF	2nd Floor Corridor - 1946	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" Light Blue Floor Tile	800	SF	2nd Floor Corridor - 1951	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" Light Blue Floor Tile Mastic	800	SF	2nd Floor Corridor - 1951	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12x12 Cream with Brown Specks Floor Tile	1000	SF	Room 118	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Previously carpeted area											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12x12 Cream with Brown Specks Floor Tile Mastic	1000	SF	Room 118	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Previously carpeted area											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
45	Steel Blue Carpet Mastic	1800	SF	Room 114 (Library) and Main Office	Assumed	MISC	No	None	0	SF		
3YR Inspector Comments: New HA - Recently installed												
Condition Changed in Fall 2010			SF		Assumed	MISC				SF		
Comments: Library floor abated by GSG summer 2010												
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF		
Comments:												
Fall 2011											YES	NO
Comment:												

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.

Lynn A. Crivello

Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 24311

Page 13

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125