

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2015 - Fall

**School:** Maria Saucedo Scholastic Academy  
**Address:** 2850 W. 24th Blvd.

**Oracle Unit:** 29151  
**Region:** 03

**Building ID:** 4250  
**Mail Room:** 39

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Moore, Mr. Kevin H  
**Survey Date:** 11/5/2015  
**Email Address:** khmoore@cps.edu

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 *Each child's backpack*     *Notice printed in school's newsletter*     *Notice printed in school's calendar*     *Other*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7A	12" x 12" Light Brown w/Specks Floor Tile			Room 228		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
 Comments:

2014 - Fall: No Change  
 Comments:

2014- Spring: No Change  
 Comments:

2015- Spring: No Change  
 Comments:

2015 - Fall: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7B	12" x 12" Light Tan w/Specks Floor Tile			Room 228		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7C	12" x 12" Peach w/Brown Specks Floor Tile	5000	SF	Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: Damaged  
Comments: Tiles are breaking apart due to cleaning equipment

2015 - Fall: Abated  
Comments: original mastic in place

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7D	12" x 12" Grey w/Brown & White Streaks Floor Tile	100	SF	Patches in Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:original mastic in place

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7E	12" x 12" Brown w/Specks Floor Tile	100	SF	Patches in Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:original mastic in place

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7F	12" x 12" Tan w/Specks Floor Tile	100	SF	Patches in Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: Damaged  
Comments: Tiles are breaking due to cleaning equipment

2015 - Fall: Abated  
Comments: original mastic in place

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7G	12" x 12" Peach w/Black & White Streaks Floor Tile	34000	SF	Corridors Throughout, Womens Teacher Restroom		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments: original mastic in place, Womens Teachers no chang

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7H	12" x 12" Tan w/Red & Brown Streaks Floor Tile	34000	SF	Corridors Throughout		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:original mastic in place

2015- Spring: Damaged  
Comments:Tiles are breaking due to cleaning equipment

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7I	12" x 12" Tan w/Brown & White Specks Floor Tile	2700	SF	Rooms 304,305 and 309		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Other  
Comments:10% replaced during 2015 Renovations

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7J	12" x 12' Off-white w/Grey Specks Floor Tile	1800	SF	Room 304 and 306		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: Other  
Comments:10% replaced during 2015 Renovations

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7K	12" x 12"Dark Green Floor Tile w/Dark Green Specks	100	SF	Room 144 office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7L	12" x 12" White Floor Tile w/blue Specks	2000	SF	Room 144		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8A	9"x9" Grey w/Black & White Streaks Floor Tile	80	SF	Lunchroom Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8B	9" x 9" Peach w/Brown & White Streaks Floor Tile	8000	SF	Rooms 143, 122		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: Deteriorated  
Comments:50 SF delaminating in female custodial locker room

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8C	9" x 9" Brown w/White Streaks Floor Tile	4000	SF	Rooms 143, 121		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8D	9" x 9" Dark Green w/White Streaks Floor Tile	8000	SF	Library and Main Office		Miscellaneous	No	Loc	50		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: Damaged  
Comments:9 x 9 tiles are broken

2014 - Fall: Damaged  
Comments:50 SF in Main Office Area, 6 SF in Library

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:(partial in Main Office)original mastic in place

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8E	9" x 9" Light Green w/White Streaks Floor Tile	150	SF	Library		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8F	9"x9"Brown w/White & Dark Brown Streaks Floor Tile	1800	SF	Women's Restroom Next to Room 213, Kitchen Locker Room, Various Locations		Miscellaneous	No	None	150		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: Damaged  
Comments:150 SF in exit hall by entrance B2

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8G	9"x9" Tan w/Dark Brown & White Streaks Floor Tile	1800	SF	Kitchen Locker Room, 128, 128b		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8H	9" x 9" Brown w/Black & White Specks Floor Tile	670	SF	Room 121		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9A	Brown Linoleum			Library Storage Closets		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9B	Marbled Grey Linoleum			Room 317		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	12" x 12" Light Brown w/Specks Floor Tile Mastic	900	SF	Room 228		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments: Duplicate

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20B	12" x 12" Light Tan w/Specks Floor Tile Mastic	900	SF	Room 228		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:Duplicate

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20C	12" x 12" Peach w/Brown Specks Floor Tile Mastic	5000	SF	Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:original mastic in place

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20D	12" x 12" Grey w/Brown & White Streaks FT Mastic	100	SF	Patches in Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: Abated  
Comments:original mastic in place

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20E	12" x 12" Brown w/Specks Floor Tile Mastic	100	SF	Patches in Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:original mastic in place

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20F	12" x 12" Tan w/Specks Floor Tile Mastic	80	SF	Patches in Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:original mastic in place

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20G	12" x 12" Peach w/Black & White Floor Tile Mastic	34000	SF	Corridors Throughout, and women teacher's restroom on the Second Floor		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: Abated  
Comments:original mastic in place Womens teachers no change

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20H	12"x12"Tan w/Red & Brown Streaks Floor Tile Mastic	34000	SF	Corridors Throughout, and women teachers restrooms on the Second Floor		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:original mastic in place Womens teachers no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20I	12"x12"Tan w/Brown/ White Specks Floor Tile Mastic	270	SF	Rooms 302, 309 and 335		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: Other  
Comments:10% replaced during 2015 Renovations

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20J	12" x 12"Off-white w/Grey Specks Floor Tile Mastic	900	SF	Room 304		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: Other  
Comments:10% replaced during 2015 Renovations

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20K	12" x 12" White with blue streaks Tile Mastic	2000	SF	Room 304		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	9"x9"Grey w/Black & White Streak Floor Tile Mastic	80	SF	Lunchroom Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21B	9"x9"Peach w/Brown/White Streaks Floor Tile Mastic	5000	SF	Room 143, 128, 128b, 2nd floor engineers office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21C	9" x 9" Brown w/White Streaks Floor Tile Mastic	2700	SF	Rooms 143, 144, 121, 1st floor engineers office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21D	9"x9" Dark Green w/White Streaks Floor Tile Mastic	3000	SF	Library(207) and Main Office(209)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21E	9"x9"Light Green w/White Streaks Floor Tile Mastic	150	SF	Library		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21F	9"x9"Brown w/White & Dark Brown Streaks Checkerboard FT	1500	SF	Kitchen Locker Room, Various Locations		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21G	9" x 9" Tan w/Dark Brown & White Streaks Checkerboard FT Mastic	1500	SF	Kitchen Locker Room, 128, 128b		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21H	9" x 9" Brown w/Black & White Floor Tile	670	SF	Room 121		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Terrazzo Wall Panels - REMOVED			Washroom in Room 111							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30A	Brown Linoleum Mastic			Library Storage Closets		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30B	Marbled Grey Linoleum Mastic			Room 317		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Beige Baseboard			Rooms 202 and 206		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Beige Baseboard Mastic			Rooms 202 and 206		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Dark Brown Baseboard			Lunchroom		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:2015 Renovations

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Dark Brown Baseboard Mastic			Lunchroom		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:2015 Renovations

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	6" Black Baseboard			2nd Floor Corridor, Kitchen, and Locker Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:Locker room no changed

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	6" Black Baseboard Mastic			2nd Floor Corridor, Kitchen, and Locker Room		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:Locker room no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Interior Window Glazing	500	LF	Library		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Lab Countertop	12	EA	Rooms 216, 218, 220, and 224		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Blackboard			Rooms 215, 221, and 225		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Black Transite Desktop			Room 309		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: Other  
Comments:no longer in building

2015- Spring: No Change  
Comments:

2015 - Fall: Other  
Comments:No longer in room

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Black Lab Countertop	730	SF	Rooms 302, 304, 305, and 309		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Green Sink and Countertop			Rooms 313 and 315		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Beige Sink and Countertop			Room 313		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Brown Countertop			Room 332		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Brick - Not AHERA			Building Exterior		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Repaired  
Comments:2015 Renovations

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Brick Mortar - Not AHERA			Building Exterior		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Repaired  
Comments:2015 Renovations

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Window Caulk - Not AHERA			Building Exterior		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Window Glaze - Not AHERA			Building Exterior		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Door Caulk - Not AHERA			Building Exterior		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:2015 Renovations

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	1' x 1' White w/Dots Ceiling Tile	10000	SF	Lunch Room, Rooms 119 and 117		Miscellaneous	Yes	None	50		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: Deteriorated  
Comments:50 SF missing from cafeteria

2015- Spring: Other  
Comments:Tiles have fallen/broken/then repalced

2015 - Fall: Abated  
Comments:Lunchroom & 119, 117 untouched

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Brown Carpet Mastic	2750	SF	Main Office, Principal's Office and Auditorium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	2x2 ceiling tile	4500	SF	Library and 209		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12x12 white with blue floor tile	100	SF	womens restroom next to 213 and corridors		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:Womens restroom no change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12x12 red floor tile	60	SF	womens restroom next to 213, NE stair landing		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:Womens restroom no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12x12 pink floor tile	60	SF	womens restroom next to 213, NE stair landing		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:Womens restroom no change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12x12 light blue floor tile	1600	SF	Room 106		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12x12 light blue floor tile mastic	1600	SF	Room 106		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12" x 12" cream floor tile with brown mottle	770	SF	Room 109		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Mastic for 12" x 12" cream floor tile w/ brown mottle	770	SF	Room 109		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	12" x 12" tan mottle floor tile	1800	SF	Rooms 313, 314		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12" x 12" tan mottle floor tile mastic	1800	SF	Rooms 313,314,315		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	12 x 12 tan and light tan floor tile in checkarboard pattern	1250	SF	Rooms 321,323,327,332,334		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Mastic for HA 62	1250	SF	Room 332		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	9" x 9" floor tile in checkerboard pattern	1500	SF	Room 117 and 119		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	9"x9" Floor Tile in Checkerboard Pattern	1500	SF	Room 117 and 119		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12" x 12" lt tan mottle floor tile	700	SF	Room 339		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Mastic for HA 66	700	SF	Room 339		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12 x 12 off white with gray mottle floor tile	1000	SF	Rooms 304,305 and 309		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Other  
Comments:10% replaced during 2015 Renovations

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12"x12" Off White w/ Grey Mottle Floor Tile	1000	SF	Room 304, 305 and 309		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Other  
Comments:10% replaced during 2015 Renovations

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	12"x12" White w/ Grey VFT	900	SF	Room 315		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12"x12" White w/ Grey VFT Mastic	900	SF	Room 315		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12"x12" White w/ Small Brown Specks VFT	1800	SF	Rooms 335 and 336		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12"x12" White w/ Small Brown Specks VFT Mastic	1800	SF	Rooms 335 and 336		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	Light Brown Carpet Mastic Adhesive	2000	SF	Front Offices		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	White Sink Insulation	4	EA	Rooms 118 and 130		TSI	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Tank Packing Material	15	CF	Boiler Room		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Aircell Duct Insulation	800	SF	Engine Rooms, Basement and 1st Floor		TSI	Yes	Loc	25		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: Damaged  
Comments:20 SF in supply room, 5 SF in room 128/129

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Tank Packing Insulation	20	CF	Boiler Room		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Tank Packing	300	SF	Attic		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Joint Insulation on Fiberglass Pipe Insulation	375	LF	Throughout Main Building		TSI	Yes	Loc	28		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: Damaged  
Comments: 28 lf Damaged total. locations: 1st Fl JC - 1 lf, 1st fl cust. locker rm - 1 lf, Rm 118 - 1 lf, Rm 122 - 1 lf, grls lckr rm - 2 lf, 3rd fl NE JC - 2 lf, all bath pipe chases (20 lf total)

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Preformed Mag-Block Pipe Insulation	575	LF	Throughout 1st Floor and Attic, Room 128, Locker Room and Locker Room Shower		TSI	Yes	Loc	55		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: Repaired  
Comments:Boys Locker Room

2014 - Fall: Damaged  
Comments:55 LF Damaged Total. Locations: Boys locker room above ceiling - 40 lf, Supply rm - 10 lf, Burnout Rm - 5 lf, Rm 128B - open seams

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:in attic only, others unchanged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Joint Insulation on Preformed Pipe Insulation	50	LF	1st Floor and Attic		TSI	Yes	Dist	12		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: Abated  
Comments:in attic only, others unchanged

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	Cardboard Pipe Insulation	200	LF	Throughout		TSI	Yes	Dist	46		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: Damaged  
Comments:46 LF Damaged total. Locations: Boys locker room above ceiling - 40 lf, Supply rm - 5 lf, 2nd Floor NW JC - 1 lf

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Cardboard Pipe Joint Insulation	500	LF	Main Building		TSI	Yes	Dist	125		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
O	Aircell Pipe Insulation	950	LF	Throughout Main Building		TSI	Yes	Dist	23		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: Damaged  
Comments:23 LF Damaged total. Locations: Rm128/129 - 10 lf, Supply Rm - 10 lf, Room 144 - 3 lf, Boys Locker Room (old gym locker room) - 3 lf, room 143 - Open Ends

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
P	Aircell Joint Insulation	190	LF	Throughout Main Building		TSI	Yes	Dist	47		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Aircell Duct Insulation	400	LF	1st Floor Corridor, Basement		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T	Pre-formed Pipe Insulation	100	LF	Tunnels		TSI	Yes	Dist	25		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated  
Comments: Summer construction

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	Joint Insulation on Pre-formed Pipe Insulation			Tunnels		TSI					<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated  
Comments: Summer construction

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
V	Cardboard Pipe Insulation			Tunnels		TSI					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
W	Joint Insulation on Cardboard Pipe Insulation			Tunnels		TSI					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
X	Aircell Pipe Insulation			Tunnels		TSI					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Y	Joint Insulation on Aircell Pipe Insulation			Tunnels		TSI					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Lynn A. Crivello*

---

Lynn A. Crivello

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***



NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Maria Saucedo Scholastic Academy

Date: 11/5/2015

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

**CHECK ONE**

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***