

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2015 - Fall

**School:** John Hay Community Academy School  
**Address:** 1018 N. Laramie Avenue

**Oracle Unit:** 31111  
**Region:** 02

**Building ID:** 3840  
**Mail Room:** 36

**Asbestos Surveyor:** Zagotta, Mr. Vincent James  
**Survey Date:** 11/10/2015  
**Email Address:** vzagotta@cps.edu

**CHECK HERE IF NO CHANGE TO ASBESTOS**

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Hard Plaster	276000	SF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments: good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Dark Brown Floor Tile - NOT OBSERVED	2200	SF	Room 204 & 205 (Library)		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" White Floor Tile	2200	SF	Vestibule to 400 N & Gym, 3rd Floor Corridor, Room 309, Principals Office, Main Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:some tiles need replacement

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Gray Linoleum	1500	SF	Lunchroom/Kitchen, Room 206		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9"x9" Dark Brown Floor Tile Mastic - NOT OBSERVED	2200	SF	Room 204 & 205 (Library)		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" White Floor Tile Mastic	2200	SF	Vestibule to 400 N & Gym, 3rd Floor Corridor, Room 309		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Gray Linoleum Mastic	2500	SF	Lunchroom/Kitchen, Room 206		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Troweled-On Ceiling Plaster	1200	SF	Boys and Girls Bathrooms		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	9"x9" Green Floor Tile	1300	SF	Rooms 400N, 400S, & Assistant Principal's Office(under carpet)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	9"x9" Green Floor Tile Mastic	1300	SF	Rooms 400N, 400S, & Assistant Principal's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	9"x9" White Floor Tile	1600	SF	Rooms Closet 207 & 208		Miscellaneous	No	None	1		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	9"x9" White Floor Tile Mastic	1600	SF	Rooms 207 & 208		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:some tiles are chip

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	9"x 9" White w/ Green Streaks Floor Tile	800	SF	Room 209		Miscellaneous	No	Loc	3		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:some tiles are chip

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	9"x9" White w/ Green Streaks Floor Tile Mastic	800	SF	Room 209		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:some tiles are chip

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Tan Floor Tile	4100	SF	2nd Floor Corridor & Stairwell Landings		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" Tan Floor Tile Mastic	4100	SF	2nd Floor Corridor & Stairwell Landings		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Beige Floor Tile Not Observed	1200	SF	Auditorium (under carpet)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"x12" Beige Floor Tile Mastic Not Observed			Auditorium, Room 104		Miscellaneous		None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Interior Caulk	5344	LF	Interior Windows		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12 x 12 inch White w/Red & Grey Speckles Floor Tile	1000	SF	Rooms: 104 and 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42 A	12 x 12 inch White w/Red & Grey Speck Floor Tile Mastic	1000	SF	Rooms: 104 and 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Clay Red w/Yellow Streaks Floor Tile	400	SF	Room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43 A	12 x 12 inch Clay Red w/Yellow Streaks Floor Tile Mastic	400	SF	Room 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12 x 12 inch Cream w/Red & Grey Speckles Floor Tile - ABATED	0	SF	Room 104		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44A	12 x 12 inch Cream w/Red & Grey Speck Floor Tile Mastic - ABATED	400	SF	Room 104		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Terrazzo	3000	SF	1st Floor Corridors, Auditorium Foyer, Boy's and Girl's, and Teachers Wash Rms 1st and 2nd Flrs		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" Tan w/Streaks Floor Tile	2200	SF	Rooms 204 & 205		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12"x12" Tan w/Streaks Floor Tile Mastic	2200	SF	Rooms 204 & 205		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Black Vinyl Baseboard	8	LF	2nd Floor Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Black Vinyl Baseboard Mastic	8	LF	2nd Floor Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	MJP E/F/V on Aircell Pipe Insulation	12	LF	Attic Area		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Aircell Pipe Insulation	600	LF	Attic Area		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	12 "x 12 "VFT - Beige with Tan Streaks	600	SF	4th Level - New ADA Bathrooms @ #400 North and #400 South.		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	12"x 12"VFT Mastic	600	SF	4th Level New ADA Bathrooms #400 North #400 South		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Drywall	1200	SF	4th Level New ADA Bathrooms #400 N. #400 S.		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Drywall Compound	400	SF	4th Level New ADA Washrooms #400 N. #400 S.		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Vinyl Baseboard	250	SF	4th Level New ADA Washrooms #400 N. #400 S.		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Vinyl BB Mastic	250	SF	New 4th Level ADA Washrooms #400 N. #400 S.		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Wall Board White Textured	200	SF	New Washrooms in - ADA #107, #104		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Wall Board Adhesive	200	SF	New ADA Washrooms in #104 in #107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Spray on - Undersink Coating Gray	12	SF	New ADA Washrooms #104, #107		Miscellaneous		None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	2'x4" Ceiling Tile White	80	SF	#104 #107 New ADA Washrooms		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	12"X 12"VFT RED	1200	SF	Main Office, Principals Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	12"x 12" RED VFT - Mastic	1200	SF	Main Office; Principal's Office		Miscellaneous		None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
O	Spray-on-Under Sink Coating Black	6	SF	Asst Principal's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
P	Fire Rated Stage Draperies Curtains	300	SF	Auditorium/Assembly Hall Platform Stage		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:good

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



*ALL LEA Responsibilities, for this school, will be met.*

*Lynn A. Crivello*

---

Lynn A. Crivello

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John Hay Community Academy School

Date: 11/10/2015

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**