

Chicago Public Schools

6 Month Asbestos Surveillance

2015 - Fall

School: William Jones College Prep High School
Address: 606 S. State

Oracle Unit: 47021
Region: 03

Building ID: 1060
Mail Room: 38

Asbestos Surveyor: Casasanto, Mr. Daniel Edward

Survey Date: 11/10/2015

Email Address: decasasanto@cps.edu

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 1 | Hard Plaster | | | 3rd Through 5th Floor Corridors | | Surface | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5A | 12"x12" Brown w/Beige Floor Tile | 6600 | SF | Performing Arts Foyer, 221 & Office, 224, Lecture Hall & Stage, Theater, | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: Abated
Comments:rehalb/1998

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5B | 12" x 12" White Floor Tile | | | Corridors Throughout | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:good

2014- Spring: Abated
Comments:renovation

2015- Spring: Abated
Comments:rehalb /1998

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5E | 12" x 12" White & Gray Floor Tile | 990 | SF | Classrooms 600 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:good

2015 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:rehalb/1998

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6 | 9" x 9" Tan Floor Tile | | | North Stair Landings | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:good

2015- Spring: Abated
Comments:rehalb/1998

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 | 9" x 9" White Floor Tile Mastic | | | Basement Corridor and Elevator Lobby | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:replaced

2015- Spring: Abated
Comments:rehalb1998

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11 | 2' x 4' White (Wormy) Ceiling Tile | | | Rooms 600, 601, and 606 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:replaced

2015- Spring: Abated
Comments:rehalb/1998

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12 | Brown Baseboard | | | Throughout School | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:replaced

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13 | Brown Baseboard Mastic | | | Throughout Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:replaced

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14 | Black Baseboard | | | Room 403 and 402 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15 | Black Baseboard Mastic | | | Classrooms 402 & 403 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16 | Carpet Mastic | | | Faculty Lunchroom, Library Room (500), Rooms 604 & 606 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:replaced11/29/99

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17 | Brown Linoleum | | | Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18 | Brown Linoleum Mastic | | | Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19 | Drywall | | | Throughout School | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20 | Exterior Brick - Not AHERA | | | Throughout Exterior of Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 | Exterior Brick Mortar - Not AHERA | | | Exterior of Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22 | Exterior Joint Compound | | | Exterior of School | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23 | Roof Flashing - Not AHERA | | | Roof, 6th Floor | | Miscellaneous | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Other
Comments:new roof reovation/7/1/13

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:7/1/14

2015- Spring: Abated
Comments:rehab/2014

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 | Roof Core - Not AHERA | | | Roof Above Rooms 600-608 | | Miscellaneous | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Other
Comments:new roof/renovation7/1/13

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:7/1/14

2015- Spring: Abated
Comments:rehalb/2014

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25 | Insulation Inside Fire Doors | 2750 | SF | Throughout School | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26 | Vibration Damper | 100 | SF | 7th Floor Mechanical Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:good

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27 | Roof Flashing - Not AHERA | | | Above the 7th Floor | | Miscellaneous | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Other
Comments:new roof/renovation 7/1/13

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:07/1/14

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28 | Roof Core - Not AHERA | | | Above the 7th Floor Mechanical Room | | Miscellaneous | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Other
Comments:new roof/renovatio 7/1/13

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:7/1/14

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29 | Linoleum | 4500 | SF | Rooms 601, 604, and 605 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30 | Linoleum Mastic | 4500 | SF | Rooms 600, 601, 608, 604, and 605 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31 | 12" x 12" Brown Floor Tile w/White & Brown Specks | | | Room 606 | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:rehalb/1998

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32 | 12" x 12" Brn Floor Tile w/Wh & Brn Specks Mastic | | | Room 606 | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:rehalb/1998

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33 | Brown Linoleum | 5600 | SF | Classrooms 601 - 606 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34 | Brown Linoleum Adhesive | 5600 | SF | Classrooms 601 - 606 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35 | Black Lab Counters and Sinks | 800 | SF | Classrooms 603 - 606 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36 | Black Lab Tables | 340 | SF | Classrooms 604 - 606 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37 | Fume Hood Interior Materials | 120 | SF | Classrooms 601A, 604A, 605A | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38 | Gray Lab Counters and Sinks | 480 | SF | Classrooms 601 - 602 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 | Gray Lab Tables | 260 | SF | Classrooms 601 - 602 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40 | 12" x 12" White w/Brown Streaks Floor Tile | 26750 | SF | Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507 and 2, 3, 4, 5, 6,d | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41 | 12" x 12" White w/Brown Streaks Floor Tile Mastic | 26750 | SF | Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507, 1, 2, 3, 4, 5, 6 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42 | 12" x 12" Brown Mix Floor Tile | 5152 | SF | Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401 - 403, 405 - 407, 501 - 507 and 1,2, 3, 4, 5, 6 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43 | 12" x 12" Brown Mix Floor Tile Mastic | 5152 | SF | Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401 - 403, 405 - 407, 501 - 507, and 2, 3, 4, 5, 6 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 | 12" x 12" Yellow Mix Floor Tile | 1500 | SF | Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45 | 12" x 12" Yellow Mix Floor Tile Mastic | 1500 | SF | Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46 | 12" x 12" Beige w/Brown Streaks Floor Tile | 16 | SF | 221 Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47 | 12" x 12" Beige w/Brown Streaks Floor Tile Mastic | 16 | SF | 221 Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48 | 12" x 12" White w/Medium Brown Specks Floor Tile | 500 | SF | AuditoriumExits by stairs,Café.Mgr.Off. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49 | 12" x 12" White w/Medium Brown Specks FT Mastic | 500 | SF | Auditorium Exits by stairs, Cafeteria/Foyer, Kitchen Corridor/Lower Stairs, Perf. Arts Stairway, Café. Mgr. Off. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50 | 12" x 12" Brown w/Specks Floor Tile | 2700 | SF | Auditorium and Stage, Kitchen Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51 | 12" x 12" Brown w/Specks Floor Tile Mastic | 2700 | SF | Auditorium and Stage & Kitchen Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52 | 12" x 12" Beige w/Gray Floor Tile | 1200 | SF | Corridor to Performing Arts Wing | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53 | 12" x 12" Beige w/Gray Floor Tile Mastic | 600 | SF | Corridor to Cafeteria, Stair Landings, Corridor to Performing Arts Wing | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54 | 12" X 12" Dark Gray w/Light Gray Floor Tile | 1150 | SF | Engineer's Office, 105I, 105J | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55 | 12" X 12" Dark Gray w/Light Gray Floor Tile Mastic | 1150 | SF | Engineer's Office, 105I, 105J | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56 | 12" x 12" White w/Gray Patches Floor Tile | 554 | SF | As Patches in Cafeteria, Kitchen Storage and Elevators | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:rehab/1998

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57 | 12" x 12" White w/Gray Patches Floor Tile Mastic | 554 | SF | As Patches in Cafeteria, Kitchen Storage and Elevators | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:rehab/1998

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58 | 4" Gray Vinyl Baseboard | 116 | LF | Engineer's Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59 | 4" Gray Vinyl Baseboard Adhesive | 116 | LF | Engineer's Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60 | 4" Brown Vinyl Baseboard | 68 | LF | 605A | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61 | 4" Brown Vinyl Baseboard Adhesive | 68 | LF | 605A | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62 | 4" Beige Vinyl Baseboard | 950 | LF | Office Area and Classrooms 600, 604, 604A | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63 | 4" Beige Vinyl Baseboard Adhesive | 950 | LF | Office Area and Classrooms 600, 604, 604A | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64 | 4" Yellow Vinyl Baseboard | 280 | LF | Classrooms 601, 602 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65 | 4" Yellow Vinyl Baseboard Adhesive | 280 | LF | Classrooms 601, 602 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66 | 4" Cream Vinyl Baseboard | 4100 | LF | Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5,6 | | Miscellaneous | No | None | 0 | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Other
Comments:replaced renovation 7/1/13

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:rehab/2014

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 67 | 4" Cream Vinyl Baseboard Adhesive | 4100 | LF | Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5, 6 | | Miscellaneous | No | None | 0 | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Other
Comments:replaced -renovation 7/1/13

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:rehab/2014

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 68 | 4" Gray Vinyl Baseboard | 400 | LF | 2nd-6th Floor Corridors, Classroom 404 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 69 | 4" Gray Vinyl Baseboard Adhesive | 400 | LF | 2nd-6th Floor Corridors, Classroom 404 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 70 | Marker Board Adhesive | 1000 | SF | Classrooms 201, 301, 304-308, 401-407, 501-507, 601, 602, 604-606 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 71 | Poster Board Adhesive | 440 | LF | Classrooms 201, 202, 204-207, 307, 308, 604, 605 and the 3rd and 6th Floor Corridors, 601, 602 | | Miscellaneous | No | None | 0 | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Repaired
Comments:renovation 7/1/13

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 72 | Stair Treads | 630 | SF | Rear Stairway | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 73 | Stair Tread Adhesive | 630 | SF | Rear Stairway | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 74 | 2' x 4' Lay-in Ceiling Panels | 87000 | SF | 1st - 6th Floor Classrooms, Library, Offices, Corridors | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 75 | Gray Rubber Flooring Adhesive | 600 | SF | Shipping/Receiving Dock | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Other
Comments:removed

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 76 | Gray Carpet Adhesive | 1144 | SF | Classroom 404 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:rehalb/2014

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 77 | Brown/Gray Carpet Adhesive | 7000 | SF | 1st Floor Offices, Library | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:rehalb/2014

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 78 | Drywall | 12000 | SF | 1st - 6th Floor Classrooms, Library, Offices, Corridors | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 79 | Drywall Compound | 12000 | SF | 1st - 6th Floor Classrooms, Library, Offices, Corridors | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 80 | Chalk Board Adhesive | 700 | SF | Classrooms 201, 202, 204-207 | | Miscellaneous | No | None | 0 | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Abated
Comments:renovation 7/1/13

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 102 | 12" x 12" Blue and White Tile | 6400 | SF | Kitchen Supply Room, Cafeteria, Stair Landing & Entrance | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 102M | 12 x 12 Blue & White Tile Mastic | 6400 | Sf | Kitchen Supply Room, Cafeteria, Stairs, Entrance, Stair Landing | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 103 | Terrazo Floor | 18500 | SF | Throughout Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 104 | Ceramic Tile and Grout | 3072 | SF | All Bathroom Walls and Floors | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 104M | Ceramic Tile Mastic | 3072 | SF | All Bathrooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 105 | 12 x 12 White w/ Specs Floor Tile | 108 | SF | Kitchen Storage | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 105M | 12 x 12 White w/Specs Floor Tile Mastic | 108 | SF | Kitchen Storage | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 106 | Window Expansion Caulk | 15000 | LF | Throughout Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8B | 12" x 12" White Floor Tile Mastic | | | 1st Floor Corridor & Locker Room, 3rd & 5th Floors Lobby Areas, 304A & 504A (Alcove) | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:good

2014- Spring: Abated
Comments:renovation

2015- Spring: Abated
Comments:rehalb/1998

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8D | 12" x 12" Gray w/White Floor Tile Mastic | | | Classroom 504 | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:good

2014- Spring: Abated
Comments:renovation

2015- Spring: Abated
Comments:rehalb/1998

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8E | 12"x 12" White w/Gray Floor Tile Mastic | 500 | SF | Classrooms 600 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:good

2015- Spring: Abated
Comments:rehalb/1998

2015 - Fall: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8F | 12" x 12" Orange Floor Tile Mastic | | | Gymnasium | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Other
Comments:renovation

2014 - Fall: Abated
Comments:replaced

2015- Spring: Abated
Comments:rhalb/1998

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9 | 9" x 9" Tan Floor Tile Mastic | | | North Stair Landings | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2014 - Fall: Abated
Comments:replaced

2015- Spring: Abated
Comments:rehab/1998

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B | Elbows on Fiberglass Pipe Runs | 65 | LF | 7th Floor Mechanical Room | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D | Elbows on Fiberglass Pipe Runs | 250 | LF | Throughout School | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E | Breeching Duct Insulation | | | Boiler Room and Chiller Area | | TSI | Yes | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: Abated
Comments:7/1/14

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G | Tank Insulation (Tar Paper) | | | Boiler Room and Chiller Room | | TSI | Yes | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: Abated
Comments:7/1/14

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H | Pipe Insulation Tar Paper | | | Boiler Room | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014 - Fall: Abated
Comments:7/1/14

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------|--|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| HA-100 | 1'x1' grooved splined white Ceiling Tile | 2000 | SF | Two floors of the building | | Miscellaneous | Yes | None | 0 | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Abated
Comments:renovation 10/1/13

2014- Spring: Abated
Comments:renovation

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------|-------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| HA-101 | Gray coating inder the Kitchen sink | 5 | SF | Kitchen and Office Area | | Miscellaneous | No | None | 0 | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Abated
Comments:renovation/10/1/13

2014 - Fall: No Change
Comments:

2014- Spring: Abated
Comments:renovation

2015- Spring: No Change
Comments:

2015 - Fall: Other
Comments:rehab

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I | Boiler Gasket Insulation | | | Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J | Tank Insulation | 250 | SF | Mechanical Area by Kitchen | | Miscellaneous | Yes | None | 0 | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

2013 - Fall: Abated
Comments:renovation 10/1/13

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: Other
Comments:rehab

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

Lynn A. Crivello

Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William Jones College Prep High School

Date: 11/12/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.