

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1941	3	521,300	\$11,463,477
Addition 1	1943	2	64,000	\$3,042,970
Addition 2 - Anthony Wing	1943	2	72,628	\$3,153,181
Hangar Building	1941	1	26,320	\$1,926,242
SITE				\$3,679,710
Campus Total			684,248	\$23,265,580

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments				
Entranc	Entrance										
	Entrance Control - Audio and Video	#30 N	1	EA	6	\$702					
	Entrance Control - Audio and Video	#32 N	1	EA	6	\$702					
	Entrance Control - Audio and Video	#4 SW	1	EA	6	\$702					
	Entrance Control - Audio and Video	#7 S Main Entrance	1	EA	6	\$702					
	Exterior Doors - Exterior Steel Door	#17 N	1	EA	6	\$481					
	Exterior Doors - Exterior Steel Door	#18 N	1	EA	6	\$481					
	Exterior Doors - Exterior Steel Door	#20 BSMT N	1	EA	6	\$481					
	Exterior Doors - Exterior Steel Door	#23 N	1	EA	6	\$481					
	Exterior Doors - Exterior Steel Door	#25 N	1	EA	6	\$481					
	Exterior Doors - Exterior Steel Door	#27 N	1	EA	6	\$481					
	Exterior Doors - Exterior Steel Door	#28 N	2	EA	6	\$961					
	Exterior Doors - Exterior Steel Door	#29 Exit N	2	EA	6	\$961					
	Exterior Doors - Exterior Steel Door	#30 N	1	EA	6	\$481					
	Exterior Doors - Exterior Steel Door	#31 Exit N	1	EA	6	\$481					
	Exterior Doors - Exterior Steel Door	#34 West Courtyard Exit	1	EA	6	\$481					
	Exterior Doors - Exterior Steel Door	#35 Central Courtyard	2	EA	6	\$961					
	Exterior Doors - Exterior Steel Door	#36 East Courtyard	2	EA	6	\$961					



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran	ce de la constante de la const						
	Exterior Doors - Exterior Steel Door	#38 N	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#39 N	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#40 N	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#41 N	1	EA	4	\$3,823	Damaged and rusted at the bottom/door
	Exterior Doors - Exterior Steel Door	#42 N	2	EA	6	\$961	
	Exterior Doors - Overhead Rolling/ Garage Door	#19 OHD N	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	#22 OHD N	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	#24 OHD N	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	#26 OHD N	1	EA	6	\$1,433	Graffiti
	Exterior Doors - Side lite	#17 N	1	EA	6	\$313	
	Exterior Doors - Side lite	#18 N	1	EA	6	\$313	
	Exterior Doors - Side lite	#31 Exit N	1	EA	6	\$313	
	Exterior Doors - Store Front	#10 E	3	EA	6	\$1,638	
	Exterior Doors - Store Front	#21 E	2	EA	6	\$1,092	
	Exterior Doors - Store Front	#32 N	2	EA	6	\$1,092	
	Exterior Doors - Store Front	#33 West Courtyard	2	EA	6	\$1,092	
	Exterior Doors - Store Front	#4 SW	3	EA	6	\$1,638	
	Exterior Doors - Store Front	#5 S Auditorium	6	EA	6	\$3,276	
	Exterior Doors - Store Front	#6 S	3	EA	6	\$1,638	
	Exterior Doors - Store Front	#7 S Main Entrance	3	EA	6	\$1,638	
	Exterior Doors - Store Front	#8 S	3	EA	6	\$1,638	
	Exterior Doors - Store Front	#9 S Gym	6	EA	6	\$3,276	
	Exterior Doors - Transom Lite	#10 E	6	EA	6	\$1,880	
	Exterior Doors - Transom Lite	#17 N	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#21 E	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#28 N	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#30 N	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#32 N	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#33 West Courtyard	3	EA	6	\$940	
	Exterior Doors - Transom Lite	#35 Central Courtyard	3	EA	6	\$940	
	Exterior Doors - Transom Lite	#36 East Courtyard	3	EA	6	\$940	
	Exterior Doors - Transom Lite	#39 N	2	EA	6	\$627	Metal panels
	Exterior Doors - Transom Lite	#4 SW	6	EA	6	\$1,880	
	Exterior Doors - Transom Lite	#6 S	6	EA	6	\$1,880	
	Exterior Doors - Transom Lite	#7 S Main Entrance	6	EA	6	\$1,880	
	Exterior Doors - Transom Lite	#8 S	6	EA	6	\$1,880	
	Exterior Stairs - Concrete	#17 N	10	LF	6	\$818	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	e						
	Exterior Stairs - Concrete	#20 BSMT N	66	LF	6	\$5,397	
	Exterior Stairs - Concrete	#21 E	60	LF	6	\$4,906	
	Exterior Stairs - Concrete	#28 N	6	LF	5	\$657	Cracks
	Exterior Stairs - Concrete	#30 N	30	LF	6	\$2,453	
	Exterior Stairs - Concrete	#33 West Courtyard	40	LF	6	\$3,271	
	Exterior Stairs - Concrete	#35 Central Courtyard	40	LF	6	\$3,271	
	Exterior Stairs - Concrete	#36 East Courtyard	20	LF	6	\$1,635	
	Exterior Stairs - Concrete	#38 N	3	LF	5	\$329	spalling
	Exterior Stairs - Concrete	#39 N	6	LF	5	\$657	spalling
	Exterior Stairs - Concrete	#4 SW	160	LF	6	\$13,083	
	Exterior Stairs - Concrete	#40 N	3	LF	5	\$329	Spalling
	Exterior Stairs - Concrete	#41 N	3	LF	6	\$245	
	Exterior Stairs - Concrete	#42 N	6	LF	5	\$657	spalling
	Exterior Stairs - Concrete	#5 S Auditorium	700	LF	6	\$57,237	
	Exterior Stairs - Concrete	#6 S	80	LF	6	\$6,541	
	Exterior Stairs - Concrete	#7 S Main Entrance	96	LF	6	\$7,850	
	Exterior Stairs - Concrete	#8 S	80	LF	6	\$6,541	
	Exterior Stairs - Concrete	#9 S Gym	700	LF	6	\$57,237	
	Power Door Operator and Controls	#32 N	1	EA	6	\$0	
	Power Door Operator and Controls	#4 SW	1	EA	6	\$0	
	Ramp Handrail - Steel_Ramp Handrail	#36 East Courtyard	90	LF	6	\$780	
	Ramp Handrail - Steel_Ramp Handrail	#4 SW	120	LF	6	\$1,040	
	Ramps - Concrete	#27 N	15	LF	6	\$2,254	
	Ramps - Concrete	#36 East Courtyard	40	LF	6	\$6,009	
	Ramps - Concrete	#4 SW	60	LF	6	\$9,014	
	Stair Handrail - Steel_Stair Handrail	#17 N	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	#20 BSMT N	28	LF	6	\$243	
	Stair Handrail - Steel_Stair Handrail	#21 E	40	LF	6	\$347	
	Stair Handrail - Steel_Stair Handrail	#30 N	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	#33 West Courtyard	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	#35 Central Courtyard	30	LF	6	\$260	
	Stair Handrail - Steel_Stair Handrail	#36 East Courtyard	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	#4 SW	40	LF	6	\$347	
	Stair Handrail - Steel_Stair Handrail	#5 S Auditorium	120	LF	6	\$1,040	
	Stair Handrail - Steel_Stair Handrail	#6 S	40	LF	6	\$347	
	Stair Handrail - Steel_Stair Handrail	#7 S Main Entrance	32	LF	5	\$368	
	Stair Handrail - Steel_Stair Handrail	#8 S	50	LF	6	\$433	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand							
	Stair Handrail - Steel_Stair Handrail	#9 S Gym	120	LF	6	\$1,040	
Founda	41am						
Founda		Entire Duilding	4.405		7	¢ 0	
	Foundation - Concrete	Entire Building	4,105	LF LF	7	\$0 \$110 287	Creake and looking
	Foundation - Concrete	Entire Building	200		5		Cracks and leaking
	Superstructure - Steel with Clay Tile Arch	Entire Building	521,300	SF	7	\$0	
Lightin	g						
	Exterior Lighting - Wall Mounted	Entire Building	66	EA	6	\$19,057	
Roof S	vstem						
<u> </u>	Chimney - Metal Flue	Boiler Room Roof	32	LF	6	\$5,061	
	Coping - Stone	Boiler Room Roof	373	LF	6	\$11,980	
	Coping - Stone	North Low Roof	1,566	LF	6	\$50,296	
	Coping - Stone	South High Roof	2,390	LF	6	\$76,762	
	Downspouts - Interior Downspouts	Boiler Room Roof	76	LF	6	\$2,526	
	Downspouts - Interior Downspouts	North Low Roof	290	LF	6	\$9,638	
	Downspouts - Interior Downspouts	South High Roof	465	LF	6	\$15,453	
	Parapet - 16" - 30" Height	South High Roof	1,793	LF	6	\$71,638	
	Parapet - Parapet > 30"	Boiler Room Roof	373	LF	6	\$23,843	
	Parapet - Parapet > 30"	North Low Roof	1,566	LF	6	\$100,100	
	Parapet - Parapet > 30"	South High Roof	598	LF	6	\$38,225	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Boiler Room Roof	9,414	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	North Low Roof	58,579	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	South High Roof	65,842	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Boiler Room Roof	9,414	SF	6	\$95,715	
	Roof - Asphalt Gravel Ballast	North Low Roof	58,579	SF	6	\$595,590	
	Roof - Asphalt Gravel Ballast	South High Roof	41,917	SF	6	\$426,183	
	Roof - Metal	South High Roof	3,224	SF	6	\$43,199	
	Roof - Modified Bitumen	South High Roof	23,925	SF	6	\$225,120	
Walls							
	Canopy - Fabric	Entire Building	75	SF	6	\$1,152	
	Cheek-Wall - Concrete	Entire Building	160	SF	6	\$1,640	
	Exterior Walls - Brick	Entire Building	112,222	SF	6	\$754,244	
	Exterior Walls - Stone-Cast	Entire Building	33,647	SF	6	\$226,141	
Window		-				·	
	Guard - Guards wire guard	Entire Building	1,650	SF	6	\$21,070	
	Lintels - Steel	Entire Building		LF	7	¢21,010 \$0	
			.,===	-		÷°	



Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Window	/S						
	Skylite - Glass Double-Pane	Entire Building	925	SF	6	\$22,103	
	Windows - Casement Aluminum Double-pane	Entire Building	3,630	SF	5	\$195,541	Don't operate well
	Windows - Casement Aluminum Double-pane	Entire Building	3,630	SF	6	\$27,096	
	Windows - Decorative	Entire Building	1,464	SF	6	\$10,928	
	Windows - Sash Aluminum Double-pane	Entire Building	4,226	SF	6	\$31,545	
	Windows - Sash Aluminum Double-pane	Entire Building	4,226	SF	5	\$227,647	Don't operate well
Build	ng Exterior Subtotal:			\$3	3,694,625		

Building Exterior Subtotal:

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	Automatic Transfer Switch	Basement	1	EA	4	\$8,200	Transfer switch has over 40 years of service and is significantly deteriorated. Serves main and additions 1.
	Automatic Transfer Switch	Basement	5	EA	6	\$2,040	Transfer switches have over 40 years of service. Serves main and additions 1.
	Automatic Transfer Switch	Basement	4	EA	7	\$0	Serves main and additions 1.
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building / 1st Floor	7,224	SF	6	\$3,822	
	Emergency A/C Power - Corridors and Stairs	Entire Building	59,926	SF	6	\$17,996	
	Emergency A/C Power - Gym	Entire Building / 2nd Floor	15,470	SF	6	\$5,752	
	Emergency A/C Power - Lunchrooms	Entire Building / 1st Floor	17,634	SF	6	\$6,556	
	Emergency A/C Power - Pool	Entire Building / 1st Floor	5,907	SF	6	\$2,196	
	Emergency A/C Power - Students Toilets	Entire Building	3,300	SF	6	\$1,227	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building / 1st Floor	40	EA	6	\$8,100	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	15	EA	7	\$0	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	86	EA	6	\$17,415	
	Emergency Battery Packs - Gym	Entire Building / 2nd Floor	22	EA	6	\$4,455	
	Emergency Battery Packs - Lunchrooms	Entire Building / 1st Floor	9	EA	6	\$1,823	
	Emergency Battery Packs - Pool	Entire Building / 1st Floor	11	EA	6	\$2,228	
	Emergency Generator- Outdoor- Diesel - 151 - 200 KW	Courtyard	1	EA	7	\$0	Serves main and additions.
	Exit Signs - Auditoium	Entire Building / 1st Floor	29	EA	7	\$0	
	Exit Signs - Corridors and Stairs	Entire Building	7	EA	7	\$0	
	Exit Signs - Corridors and Stairs	Entire Building	55	EA	7	\$0	
	Exit Signs - Gym	Entire Building / 2nd Floor	20	EA	7	\$0	
	Exit Signs - Lunchroom	Entire Building / 1st Floor	4	EA	7	\$0	
	Exit Signs - Pool	Entire Building / 1st Floor	11	EA	7	\$0	



Category: Electrical System

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	ency System	Location	quantity	Unit	Nalik	CUSI	- Commenta
Lineige	Security System - CCTV	Entire Building	521,300	SF	6	\$156,546	
	Security System - Intrusion Detection	Entire Building	521,300	SF	6	\$130,340	
	Security System - Initiasion Delection	Entire Building	521,500	01	0	ψ104,100	
Main Se	ervice						
	Main Electrical Service - 1200 A 120/240/3PH	Entire Building	9	EA	6	\$45,699	Serves main and additions 1.
	Main Electrical Service - 1200 A 120/240/3PH	Entire Building	1	EA	7	\$0	Serves main and additions 1.
	Main Electrical Service - 1600 A 120/240/3PH	Entire Building	1	EA	6	\$5,641	Serves main and additions 1.
	Main Electrical Service - 2001 to 3000 A 277/480/3PH	Entire Building / Electrical Room	1	EA	7	\$0	Serves main and additions 1.
	Main Electrical Service - 800 A and Less than 120/240/3PH	Entire Building	3	EA	6	\$10,839	Serves main and additions 1.
	PA System	Entire Building	521,300	SF	6	\$171,456	System does not communicate with Addition 1.
Power I	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	9	EA	4	\$43,644	Panels have over 40 years of service and are old and deteriorated.
	Lighting and Power Panels - 100 A	Entire Building	12	EA	7	\$0	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	4	\$9,699	Panels have over 40 years of service and are live front, old and deteriorated.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	\$0	Emergency fuse panel
	Lighting and Power Panels - 100 A	Entire Building	9	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	\$497	Emergency fuse panel
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	\$6,578	Emergency fuse panel is live front, old and deteriorated.
	Lighting and Power Panels - Above 100 A	Entire Building	17	EA	4	\$111,822	Panels have over 40 years of service and are old and deteriorated.
	Lighting and Power Panels - Above 100 A	Entire Building	19	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	33	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	\$6,578	Panels has over 40 years of service and is live front, old and deteriorated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	4	\$27,388	Panels have over 40 years of service and are old and deteriorated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	10	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building	6	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Entire Building	12	EA	7	\$0	
	Main Distribution Panels - Less than 400 amp	Entire Building	3	EA	7	\$0	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	4	\$8,819	Panel has over 40 years of service and is old and deteriorated.
	Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	7	\$0	
	Transformers - 120/240 - 120/208	Entire Building	9	EA	7	\$0	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	\$0	



Building: Main

Category: Electrical System

Group Item - Type	Location	Quantity Unit Rank	Cost Comments	
Power Distribution				
Transformers - 277/480 - 120/240	Entire Building	8 EA 7	\$0	
Transformers - 277/480 - 120/240	Entire Building	6 EA 7	\$0	
Transformers - 277/480 - 120/240	Entire Building	7 EA 7	\$0	
Electrical System Subtotal:	5	\$82	21,199	

Electrical System Subtotal:

Building: Main

Category: Safty System

roup Item - Type	Location	Quantity U	nit	Rank	Cost	Comments
ire Alarm						
Fire Alarm Panel	Mechanical Room	1 E	A	6	\$6,406	Serves Main and Additions only.
Fire Alarm Strobe Lights	Mechanical Room / Entire Building	521,300 \$	SF	6	\$186,365	
Fire Alarm_System	Mechanical Room / Entire Building	521,300 \$	SF	5	\$581,458	System trips frequently on ground fault.

Safty System Subtotal:

\$774,229

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Con	ditioning						
	Chemical Pot Feeder	Boiler Room	1	EA	6	\$725	
	Chiller-Water Cooled- Cetrifugal - 201-300 tons	Boiler Room	2	EA	7	\$0	Serves main and additions.
	Condensing Unit- Ground Mounted - Less than 5 tons	Central Courtyard	1	EA	7	\$0	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	4	\$11,133	Condenser is not working, in poor condition and not cost effective for repairs.
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	4	\$11,133	Condenser is not working, in poor condition and not cost effective for repairs.
	Cooling Tower - Closed Cell	Boiler Room / Roof	2	EA	7	\$0	
	Glycol Feed	Boiler Room	1	EA	6	\$490	
	Pipes - Dual Temperature Pipe- Copper	Boiler Room / Entire Building	10,000	LF	7	\$0	
	Pressure Fill System	Boiler Room	1	EA	6	\$1,405	
Air Han	dling Systems						
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	AHU-8 serves large gym and small gym.
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	7	\$0	AHU-7 serves pool and locker rooms



Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - Less than 8000 cfm	Mechanical Room	1	EA	7	\$0	AHU-12 serves West Science Hall (Addition 1)
	Air Handling Unit- Built Up- Single Zone- Daul Temperature Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	AHU-1 serves Auditorium
	Air Handling Unit- Built Up- Single Zone- Daul Temperature Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	AHU-4 serves Cafeteria
	Air Handling Unit- Built Up- Single Zone- Daul Temperature Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	AHU-2 serves West Wing (Addition 1)
	Air Handling Unit- Built Up- Single Zone- Daul Temperature Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	7	\$0	AHU-3 serves North Wing
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Daul Temperature Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	AHU-5
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Daul Temperature Coils - Greater than 35000 cfm	Mechanical Room	1	EA	7	\$0	AHU-6
	Air Intake	Mechanical Room / Central Courtyard	1	EA	7	\$0	
	Air Intake	Mechanical Room / North Courtyard Facades	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	AHU-5 shares intake with AHU-1
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	AHU-6 shares intake with AHU-7
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room / Mechanical Building/Central Plant	1	EA	7	\$0	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	7	\$0	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	7	\$0	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	7	\$0	
	Auxiliaries - Less than 8000 cfm	Mechanical Room	1	EA	7	\$0	
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Attic	1	EA	7	\$0	RF-6
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Attic	1	EA	7	\$0	RF-5
	Outdoor Return Fans- inline Centrifugal - 5000 - 10000 CFM	Roof	1	EA	7	\$0	RF-3
	Outdoor Return Fans- inline Centrifugal - Greater than 20000 CFM	Roof	1	EA	7	\$0	RF-4
	Outdoor Return Fans- inline Centrifugal - Less than 5000 CFM	Roof	1	EA	7	\$0	RF-12
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical Room / Plenum	11	EA	6	\$10,841	



Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
-	Air Handling Systems									
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical Room / Plenum	9	EA	6	\$8,870				
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room / Plenum	100	LF	7	\$0				
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room / Plenum	100	LF	7	\$0				
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	100	LF	7	\$0				
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	100	LF	7	\$0				
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	100	LF	7	\$0				
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	100	LF	7	\$0				
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	100	LF	7	\$0	AHU-5 shares return ductwork with AHU-1			
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	100	LF	7	\$0				
	Zone Dampers	Mechanical Room / Plenum	2	EA	5	\$3,827				
	Zone Dampers	Mechanical Room / Plenum	6	EA	6	\$4,998				
	Zone Dampers	Mechanical Room / Plenum	6	EA	7	\$0				
	Zone Dampers	Mechanical Room / Plenum	46	EA	7	\$0				
	Zone Dampers	Mechanical Room / Plenum	37	EA	7	\$0				
Boiler 9	Systems									
Boller C	Boiler Auxiliary- Condensing Hot Water - More than 4000 HP	Boiler Room	5	EA	7	\$0				
	Chemical Feed System	Boiler Room	3	EA	7	\$0 \$0				
	Chemical Pot Feeder	Boiler Room	3 1	EA	6	پ 0 \$725				
	Combustion Dampers	Boiler Room	6	EA	7	\$0				
	Condensing- Hot Water Boiler - Greater 4000 MBH	Boiler Room	5	EA	7	\$0 \$0	Serves main and additions.			
	Water Fill System	Boiler Room	1	EA	6	₄₀ \$1,168				
				2/1	0	ψ1,100				
Heating) Devices									
	Cabinet Heaters - With Hot Water Coil	Entire Building	11	EA	7	\$0				
	Duct Heater - Electric	Mechanical Room	2		7	\$0				
	Fin Tube - Hot Water	Entire Building	394	LF	7	\$0				
	Unit Heater - Electric	Electrical Room	1	EA	6	\$278				
	Unit Heater - Hot Water	Entire Building	63	EA	7	\$0				
	Wall Heater - Electric	Entire Building	4	EA	7	\$0				
	Wall Heater - Electric	Entire Building	3	EA	4	\$3,248	Missing cover, wires exposed.			
Mechar	nical Plumbing									
	Condenser Pump - 10 - 20 HP	Boiler Room	1	EA	7	\$0				
	Condenser Pump - 21 - 50 HP	Boiler Room	2	EA	7	\$0				
	Daul Temperature Pump - Greater than 50 HP	Entire Building / Boiler Room	3	EA	7	\$0				
	Daul Temperature Pump - Less than 10	Entire Building / Mechanical Room	4	EA	7	\$0				
	Daul Temperature Pump - Less than 10	Entire Building / Mechanical Room	4	EA	7	\$0				
	Daul Temperature Pump - Less than 10	Entire Building / Mechanical Room	1	EA	7	\$0				



Building: Main

Category: Mechanical System

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
echai	nical Plumbing						
	Daul Temperature Pump - Less than 10	Entire Building / Mechanical Room	1	EA	7	\$0	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	\$1,111	
	Hydronic Supply and Return - Copper	Entire Building	7,500	LF	7	\$0	
	Hydronic Supply and Return - Galvanized	Entire Building	2,500	LF	7	\$0	
empe	rature Control						
	DDC System	Entire Building	521,300	SF	7	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	74	EA	7	\$0	
	Thermostats - DDC	Entire Building	96	EA	7	\$0	
nit Ve	ntilation						
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	17	EA	7	\$0	
entila	tion						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building / 1st Floor	1	EA	6	\$592	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	4	EA	7	\$0	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / Basement	1	EA	4	\$4,245	Exhaust fan is not working.
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	10	EA	6	\$5,924	
	Exhaust Fans- Indoor - Greater than 8000 CFM	Entire Building / Attic	1	EA	7	\$0	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	1	EA	6	\$296	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	2	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	7	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building / Roof	1	EA	7	\$0	
	Lab Exhaust Hood	Entire Building / 3rd Floor	2	EA	6	\$2,495	
	Lab Exhaust Hood	Entire Building / 3rd Floor	2	EA	7	\$0	
	Roof Mounted Duct Work	Entire Building / Roof	800	LF	7	\$0	
	Type I Exhaust Hood- Kitchen	Entire Building / 1st Floor	1	EA	6	\$1,248	
	Type II Exhaust Hood- Warming Kitchen	Entire Building / Basement	1	EA	6	\$920	
	anical System Subtotal:					\$110,853	

	Group	Item - Type	
--	-------	-------------	--

Quantity Unit Rank

Cost Comments

Location



Category: Plumbing System

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ot Wa	ter						
	Gas Heater - Greater than 600000 BTU/HR	Boiler Room	2	EA	7	\$0	Serves main and additions.
	Hot Water Storage Tank_Electric - 501 - 1000 Gallons	Boiler Room	1	EA	7	\$0	Serves main and additions.
ping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	521,300	SF	6	\$104,364	Piping is old and deteriorated
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	104,260	SF	7	\$0	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	417,040	SF	6	\$101,382	Piping is old and deteriorated
	Domestic Piping-Cold Water Risers	Entire Building	521,300	SF	6	\$96,910	Piping is old and deteriorated
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	521,300	SF	6	\$82,000	Piping is old and deteriorated
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	104,260	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	417,040	SF	6	\$77,528	Piping is old and deteriorated
	Domestic Piping-Hot Water Return Lines	Entire Building	521,300	SF	6	\$74,546	Piping is old and deteriorated
	Domestic Piping-Hot Water Return Risers	Entire Building	521,300	SF	6	\$74,546	Piping is old and deteriorated
	Sanitary Piping	Entire Building	469,170	SF	6	\$429,384	
	Sanitary Piping	Entire Building	52,130	SF	6	\$47,709	Piping is old and deteriorated
	Storm Piping	Entire Building	521,300	SF	6	\$454,730	Piping is old and deteriorated
	Vent Piping	Entire Building	521,300	SF	6	\$350,366	
ool Sy	/stems						
	Pool Drain Piping	Mechanical Room	20	LF	3	\$2,026	Main Drain is PVC - Remainder is Galvanized a it is unusable.
	Pool Filtration System including Pump	Mechanical Room	1	EA	4	\$162,839	Pump is removed and awaiting a new replacement
	Pool Hot Water Heater - Gas Fired	Mechanical Room	1	EA	7	\$0	
	Pool Supply and Return Piping	Mechanical Room	75	LF	4	\$12,453	Piping is galvinized and substantially corroded
imps							
	Pumps - Domestic Booster Pump-Duplex	Basement / Mechanical Room	1	EA	7	\$0	Serves main and additions.
	Pumps - Ejector-Duplex	Basement	1	EA	7	\$0	
	Pumps - Sump-Duplex	Basement	11	EA	7	\$0	
	Pumps - Sump-Simplex	Basement	1	EA	6	\$745	Elevator sump pit
um	hing System Subtetal				¢	0 071 500	
Plumbing System Subtotal: \$2,071,528							

Category: Classrooms			
Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Classroom #002 (Regular Classroom)			
Ceiling - Lay-in	1st Floor	2,750 SF 6	\$8,258



Category:	Classrooms
-----------	------------

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	om #002 (Regular Classroom)						
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	2,750	SF	6	\$6,017	
	Lighting - Lay-in	1st Floor	46	EA	7	\$0	
	Walls - Masonry	1st Floor	1,741	SF	6	\$5,477	
lassro	om #004 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	650	SF	6	\$1,952	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	650	SF	6	\$4,582	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	90	SF	5	\$459	Pieces of wall missing
	Walls - Plaster/Drywall	1st Floor	996	SF	6	\$2,749	
lassro	om #008 (Vacant)						
	AC Units	1st Floor	3	EA	4	\$18,259	Not working
	Ceiling - Lay-in	1st Floor	1,970	SF	6	\$5,916	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,970	SF	6	\$4,310	
	Lighting - Pendent/Surface	1st Floor	30	EA	7	\$0	
	Walls - Masonry	1st Floor	1,741	SF	6	\$5,477	
lassro	om #009 (Science Classroom)						
	Casework	1st Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	1st Floor	985	SF	6	\$2,958	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	985	SF	6	\$986	
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,460	SF	6	\$4,029	
	Work Sink	1st Floor	2	EA	6	\$758	
lassro	om #010 (Science Classroom)						
	Casework	1st Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	1st Floor	985	SF	6	\$2,958	
	Chalk Board	1st Floor	30	LF	4	\$2,754	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	985	SF	6	\$986	
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-		Location	Qualitity	Unit	Nailk	COST	Comments
	om #010 (Science Classroom) Walls - Plaster/Drywall	1st Floor	1,460	SF	6	\$4,029	
	Work Sink	1st Floor	1,400	EA	6	\$4,029 \$379	
	WOR SINK	IST FIOOI	I	EA	0	φ379	
lassroc	om #011 (Regular Classroom)						
	Casework	1st Floor	40	LF	6	\$1,010	
	Ceiling - Lay-in	1st Floor	503	SF	6	\$1,511	
	Chalk Board	1st Floor	9	LF	4	\$826	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	503	SF	6	\$504	
	Lighting - Lay-in	1st Floor	8	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	987	SF	6	\$2,724	
assroc	om #012 (Science Classroom)						
	Casework	1st Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	1st Floor	985	SF	6	\$2,958	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	985	SF	6	\$986	
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,460	SF	6	\$4,029	
	Work Sink	1st Floor	2	EA	6	\$758	
assroc	om #013 (Science Classroom)						
	Casework	1st Floor	90	LF	6	\$2,273	
	Ceiling - Lay-in	1st Floor	985	SF	6	\$2,958	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	985	SF	6	\$986	
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	8	LF	6	\$171	
	Walls - Plaster/Drywall	1st Floor	987	SF	6	\$2,724	
assroc	om #014 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	735	SF	6	\$2,207	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	735	SF	6	\$5,182	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	1st Floor	1,214	SF	6	\$3,351	

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #016 & 018 (Laboratory/Shop)						
	Ceiling - Exposed	1st Floor	6,820	SF	6	\$10,143	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Concrete	1st Floor	6,820	SF	6	\$3,608	
	Lighting - Pendent/Surface	1st Floor	100	EA	7	\$0	
	Walls - Masonry	1st Floor	8,284	SF	6	\$26,061	
assro	om #019 (Science Lab Level 3)						
	Casework	1st Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	1st Floor	1,001	SF	6	\$3,006	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	1,001	SF	6	\$1,002	
	Lighting - Lay-in	1st Floor	20	EA	6	\$2,380	
	Walls - Plaster/Drywall	1st Floor	1,487	SF	6	\$4,104	
assro	om #020 (Regular Classroom)						
	Casework	1st Floor	40	LF	6	\$1,010	
	Ceiling - Lay-in	1st Floor	503	SF	6	\$1,511	
	Chalk Board	1st Floor	9	LF	4	\$826	
	Doors - Transom Window	1st Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	503	SF	6	\$504	
	Lighting - Lay-in	1st Floor	8	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	987	SF	6	\$2,724	
assro	om #021 (Regular Classroom)						
	Casework	1st Floor	4	LF	6	\$101	
	Ceiling - Lay-in	1st Floor	503	SF	6	\$1,511	
	Chalk Board	1st Floor	9	LF	4	\$826	
	Doors - Transom Window	1st Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	503	SF	6	\$504	
	Lighting - Lay-in	1st Floor	8	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	987	SF	6	\$2,724	
assro	om #022 (Science Lab Level 3)						
	Casework	1st Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	1st Floor	1,002	SF	6	\$3,009	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	



Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #022 (Science Lab Level 3)		quantity			0001	
	Floor - Tile/Sheet	1st Floor	1,002	SF	6	\$1,003	
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,424	SF	6	\$3,930	
	Work Sink	1st Floor	1	EA	6	\$379	
assroc	om #023 (Science Lab Level 3)						
	Casework	1st Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	1st Floor	1,002	SF	6	\$3,009	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	1,002	SF	6	\$1,003	
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,424	SF	6	\$3,930	
	Work Sink	1st Floor	6	EA	6	\$2,274	
assroc	om #024 (Science Lab Level 3)						
	Casework	1st Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	1st Floor	1,002	SF	6	\$3,009	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	1,002	SF	6	\$1,003	
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,424	SF	6	\$3,930	
	Work Sink	1st Floor	1	EA	6	\$379	
ssroc	om #116 (Regular Classroom)						
	Casework	1st Floor	5	LF	6	\$126	
	Ceiling - Plaster/Drywall	1st Floor	496	SF	6	\$1,716	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	496	SF	6	\$496	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,315	SF	6	\$3,629	
ssroc	om #120 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	1,317	SF	6	\$3,955	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	1,317	SF	6	\$1,318	
	Lighting - Lay-in	1st Floor	32	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	30	SF	5	\$153	Peeling paint
	Walls - Plaster/Drywall	1st Floor	1,777	SF	6	\$4,904	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #121 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	735	SF	6	\$2,207	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	735	SF	6	\$5,182	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	1st Floor	1,214	SF	6	\$3,351	
Classro	oom #123 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	735	SF	6	\$2,207	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	735	SF	6	\$5,182	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	1st Floor	1,214	SF	6	\$3,351	
Classro	oom #136 (Science Lab Level 2)						
	Casework	1st Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	1st Floor	1,002	SF	6	\$3,009	
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Eye Wash Station	1st Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	1st Floor	1,002	SF	6	\$1,003	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Science Lab Elements	1st Floor	8	SF	6	\$54	
	Walls - Plaster/Drywall	1st Floor	1,434	SF	6	\$3,958	
	Work Sink	1st Floor	3	EA	6	\$1,137	
Classro	oom #139 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	760	SF	6	\$2,282	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	760	SF	6	\$761	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,212	SF	6	\$3,345	
Classro	oom #140 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	



Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	bom #140 (Regular Classroom)	Loodion	Quantity	onit	. ann	0031	
	Ceiling - Lay-in	1st Floor	780	SF	6	\$2,342	
	Chalk Board	1st Floor	30	LF	4	\$2,754	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	780	SF	6	\$5,499	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,254	SF	6	\$3,461	
Classro	oom #141 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	760	SF	6	\$2,282	
	Doors - Transom Window	1st Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	760	SF	6	\$761	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,212	SF	6	\$3,345	
lassro	oom #142 (Other Instructional Use)						
	Ceiling - Exposed	1st Floor	2,759	SF	6	\$4,103	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Concrete	1st Floor	2,759	SF	6	\$1,460	
	Lighting - Pendent/Surface	1st Floor	40	EA	7	\$0	
	Walls - Masonry	1st Floor	3,924	SF	6	\$12,345	
assro	oom #144 (Carpentry)						
	Ceiling - Exposed	1st Floor	2,759	SF	6	\$4,103	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Concrete	1st Floor	2,759	SF	6	\$1,460	
	Lighting - Pendent/Surface	1st Floor	40	EA	7	\$0	
	Walls - Masonry	1st Floor	3,924	SF	6	\$12,345	
lassro	oom #145 (Science Lab Level 2)						
	Casework	1st Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	1st Floor	1,002	SF	6	\$3,009	
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Transom Window	1st Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Eye Wash Station	1st Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	1st Floor	1,002	SF	6	\$1,003	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #145 (Science Lab Level 2)		•				
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Science Lab Elements	1st Floor	8	SF	6	\$54	
	Walls - Plaster/Drywall	1st Floor	1,434	SF	6	\$3,958	
	Work Sink	1st Floor	8	EA	6	\$3,032	
Classro	om #219 (Store Room)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	1,053	SF	6	\$3,162	Water stains
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	Wood paenl
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,050	SF	6	\$7,402	
	Floor - Wood	2nd Floor	3	SF	5	\$59	Buckling of wood planks
	Lighting - Lay-in	2nd Floor	24	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,230	SF	6	\$3,395	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	\$51	Falling of plaster and peeling paint
	Work Sink	2nd Floor	1	EA	6	\$379	
Classro	om #221 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	732	SF	6	\$2,198	
	Chalk Board	2nd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	2nd Floor	1	SF	6	\$17	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Floor - Wood	2nd Floor	732	SF	6	\$5,161	
	Lighting - Lay-in	2nd Floor	27	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	6	\$2,848	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	Peeling paint
Classro	om #222 (Store Room)						
	Casework	2nd Floor	3	LF	6	\$76	
	Ceiling - Lay-in	2nd Floor	1,386	SF	6	\$4,162	Water stain
	Chalk Board	2nd Floor	18	LF	4	\$1,653	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	\$903	
	Floor - Tile/Sheet	2nd Floor	1,380	SF	6	\$1,381	
	Floor - Tile/Sheet	2nd Floor	6	SF	6	\$12	Damaged tiles
	Lighting - Lay-in	2nd Floor	24	EA	7	\$0	
	Storage/ Closet	2nd Floor	331	SF	6	\$2,400	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	\$51	Peeling paint



Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	oom #222 (Store Room)						
	Walls - Plaster/Drywall	2nd Floor	1,713	SF	6	\$4,728	
	Work Sink	2nd Floor	1	EA	6	\$379	
assro	oom #223 (Vacant)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	732	SF	6	\$2,198	
	Chalk Board	2nd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	732	SF	6	\$5,161	
	Lighting - Lay-in	2nd Floor	27	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,030	SF	6	\$2,843	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	\$15	Peeling paint
assro	oom #225 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	680	SF	5	\$4,045	
	Chalk Board	2nd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	wood panel
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	680	SF	6	\$4,794	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	949	SF	6	\$2,619	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	Peeling paint
assro	oom #226 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	\$152	
	Ceiling - Lay-in	2nd Floor	1,792	SF	6	\$5,381	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	1,792	SF	6	\$12,633	
	Lighting - Lay-in	2nd Floor	27	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	4	SF	5	\$20	Peeling paint
	Walls - Plaster/Drywall	2nd Floor	1,496	SF	6	\$4,129	
assro	oom #228 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	1,050	SF	6	\$3,153	

Building: Main

•			-			-	•
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #228 (Regular Classroom)						
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,050	SF	6	\$7,402	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
	Storage/ Closet	2nd Floor	304	SF	6	\$2,204	
	Walls - Plaster/Drywall	2nd Floor	1,124	SF	6	\$3,102	
	Work Sink	2nd Floor	1	EA	6	\$379	
Classro	om #230 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	1,050	SF	6	\$3,153	Water stain
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	2nd Floor	2	SF	5	\$9	Loose tiles
	Floor - Wood	2nd Floor	1,048	SF	6	\$7,388	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,122	SF	6	\$3,097	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	Peeling paint
Classro	om #234 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	1,000	SF	6	\$3,003	
	Chalk Board	2nd Floor	50	LF	4	\$4,590	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,000	SF	6	\$7,050	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,195	SF	6	\$3,298	
	Walls - Plaster/Drywall	2nd Floor	5	SF	6	\$19	
Classro	om #236 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	1,000	SF	6	\$3,003	
	Chalk Board	2nd Floor	44	LF	4	\$4,039	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,000	SF	6	\$7,050	



-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #236 (Regular Classroom)			•			
143510	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	\$3,312	
	Work Sink	2nd Floor	.,_00	EA	6	\$379	
					-		
lassro	oom #238 (Other Instructional Use)						
	Casework	2nd Floor	6	LF	6	\$152	
	Ceiling - Splined	2nd Floor	2,048	SF	6	\$1,669	
	Ceiling - Splined	2nd Floor	2	SF	5		Water damage
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	2,050	SF	6	\$14,452	
	Lighting - Pendent/Surface	2nd Floor	34	EA	7	\$0	
	Storage/ Closet	2nd Floor	43	SF	6	\$312	
	Walls - Plaster/Drywall	2nd Floor	2,078	SF	6	\$5,735	
lassro	oom #239 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	732	SF	6	\$2,198	
	Chalk Board	2nd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	732	SF	6	\$5,161	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	6	\$2,848	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	Peeling paint
lassro	oom #241 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	732	SF	6	\$2,198	
	Chalk Board	2nd Floor	32	LF	6	\$714	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	732	SF	6	\$5,161	
	Lighting - Lay-in	2nd Floor	27	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,033	SF	6	\$2,851	
lassro	oom #242 (Store Room)						
	Casework	2nd Floor	12	LF	6	\$303	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #242 (Store Room)						
	Ceiling - Lay-in	2nd Floor	1,000	SF	6	\$3,003	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	997	SF	6	\$7,029	
	Floor - Wood	2nd Floor	3	SF	4	\$125	Buckling of planks
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,195	SF	6	\$3,298	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	\$26	Peeling/bubbling paint
Classro	oom #243 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	688	SF	6	\$2,066	
	Chalk Board	2nd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	Wood panel
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	688	SF	6	\$4,850	
	Lighting - Lay-in	2nd Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	2nd Floor	898	SF	6	\$2,478	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	Peeling paint
Classro	oom #244 (Vacant)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	1,000	SF	6	\$3,003	
	Chalk Board	2nd Floor	10	LF	4	\$918	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	998	SF	6	\$7,036	
	Floor - Wood	2nd Floor	2	SF	5	\$39	Buckling of wood planks
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	18	LF	6	\$386	
	Storage/ Closet	2nd Floor	2	SF	6	\$15	
	Walls - Plaster/Drywall	2nd Floor	1,195	SF	6	\$3,298	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	\$26	Peeling paint
Classro	oom #245 (Vacant)						
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	2nd Floor	688	SF	6	\$2,066	
	Chalk Board	2nd Floor	32	LF	4	\$2,938	



Building: Main

-	· -		•				
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #245 (Vacant)						
	Doors - Transom Window	2nd Floor	1	SF	6	\$17	
	Doors - Transom Window	2nd Floor	8	SF	6		wood panel
	Floor - Wood	2nd Floor	688	SF	6	\$4,850	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	898	SF	6	\$2,478	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	Peeling paint
assroo	om #317 Band room (Music Room)						
	Casework	3rd Floor	42	LF	6	\$1,061	
	Ceiling - Plaster/Drywall	3rd Floor	2,666	SF	6	\$9,226	
	Chalk Board	3rd Floor	50	LF	4	\$4,590	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	\$602	
	Doors - Transom Window	3rd Floor	20	SF	6		Metal panel
	Floor - Wood	3rd Floor	2,666	SF	6	\$18,795	
	Lighting - Pendent/Surface	3rd Floor	49	EA	7	\$0	
	Sound Panels	3rd Floor	352	EA	6	\$1,419	
	Storage/ Closet	3rd Floor	581	SF	6	\$4,212	
	Walls - Plaster/Drywall	3rd Floor	2,950	SF	6	\$8,142	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5		Peeling paint
	om #320 (Store Room)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	1,386	SF	6	\$4,162	
	Chalk Board	3rd Floor	6	LF	4	\$551	
	Doors - Transom Window	3rd Floor	16	SF	6		Wood panel
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd Floor	1,383	SF	6	\$1,384	
	Floor - Tile/Sheet	3rd Floor	3	SF	5		Damaged tiles
	Lighting - Lay-in	3rd Floor	13	EA	7	\$0	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	\$0 \$0	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	\$26	Peeling paint
	Walls - Plaster/Drywall	3rd Floor	1,713	SF	6	_{\$20} \$4,728	
	Work Sink	3rd Floor	1,713	EA	6	\$379	
			I		0	ψ019	
assroo	om #321 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	735	SF	6	\$2,207	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	



-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	om #321 (Regular Classroom)						
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	735	SF	6	\$5,182	
	Lighting - Lay-in	3rd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	820	SF	6	\$2,263	
lassro	oom #323 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	735	SF	6	\$2,207	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	735	SF	6	\$5,182	
	Lighting - Lay-in	3rd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	819	SF	6	\$2,260	
	Walls - Plaster/Drywall	3rd Floor	1	SF	5	\$5	Bubbling/peeling paint
lassro	oom #325 (Store Room)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	704	SF	6	\$2,114	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	wood panel
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	704	SF	6	\$4,963	
	Lighting - Lay-in	3rd Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	3rd Floor	918	SF	6	\$2,534	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	\$10	Peeling paint
lassro	oom #326 (Choral Room)						
	Casework	3rd Floor	22	LF	6	\$556	
	Ceiling - Splined	3rd Floor	1,687	SF	6	\$1,375	Missing tile
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	\$903	
	Floor - Tile/Sheet	3rd Floor	1,687	SF	6	\$1,689	Water on floor
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,864	SF	6	\$5,144	
	Walls - Plaster/Drywall	3rd Floor	15	SF	5	\$77	Peeling paint
lassro	oom #327 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	664	SF	6	\$1,994	



Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #327 (Regular Classroom)		•				
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	664	SF	6	\$4,681	
	Lighting - Lay-in	3rd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	854	SF	6	\$2,357	
	Walls - Plaster/Drywall	3rd Floor	1	SF	5	\$5	Peeling paint
Classro	oom #328 (Other Instructional Use)						
	Casework	3rd Floor	15	LF	6	\$379	
	Ceiling - Splined	3rd Floor	1,026	SF	6	\$836	
	Chalk Board	3rd Floor	6	LF	4	\$551	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	Wood panel
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,026	SF	6	\$7,233	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	\$2,478	
	Marker Board	3rd Floor	40	LF	6	\$857	
	Walls - Plaster/Drywall	3rd Floor	1,380	SF	6	\$3,809	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	\$26	Peeling paint
	Work Sink	3rd Floor	1	EA	6	\$379	
Classro	oom #329 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	698	SF	6	\$2,096	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	698	SF	6	\$4,921	
	Lighting - Lay-in	3rd Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	3rd Floor	915	SF	6	\$2,525	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	\$26	Peeling paint
Classro	oom #330 (Vacant)						
	Casework	3rd Floor	15	LF	6	\$379	
	Ceiling - Lay-in	3rd Floor	1,026	SF	6	\$3,081	Loose tile
	Chalk Board	3rd Floor	26	LF	4	\$2,387	
	Doors - Transom Window	3rd Floor	16	SF	6	\$271	
	Doors - Transom Window	3rd Floor	16	SF	6	\$271	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #330 (Vacant)						
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,026	SF	6	\$7,233	
	Lighting - Lay-in	3rd Floor	20	EA	6	\$2,380	
	Walls - Plaster/Drywall	3rd Floor	1,380	SF	6	\$3,809	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	\$26	Peeling paint
	Work Sink	3rd Floor	1	EA	6	\$379	
Classrc	oom #331 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	750	SF	6	\$2,252	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	749	SF	6	\$5,280	
	Floor - Wood	3rd Floor	1	SF	5	\$20	Damaged
	Lighting - Lay-in	3rd Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	3rd Floor	975	SF	6	\$2,691	
Classrc	oom #333 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	695	SF	6	\$2,087	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	695	SF	6	\$4,900	
	Lighting - Lay-in	3rd Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	3rd Floor	919	SF	6	\$2,536	
	Walls - Plaster/Drywall	3rd Floor	1	SF	5	\$5	Peeling paint
Classrc	oom #334 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	5	\$3,652	Poor support
	Casework	3rd Floor	32	LF	6	\$808	
	Ceiling - Splined	3rd Floor	1,026	SF	6	\$836	
	Chalk Board	3rd Floor	10	LF	4	\$918	
	Doors - Transom Window	3rd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,026	SF	6	\$7,233	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	\$2,230	
	Walls - Plaster/Drywall	3rd Floor	1,380	SF	6	\$3,809	



Building: Main

Categ	ory: Classrooms	
Group	Item - Type	

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #334 (Regular Classroom)						
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	\$26	Peeling paint
	Work Sink	3rd Floor	1	EA	6	\$379	
lassro	oom #335 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	664	SF	6	\$1,994	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	664	SF	6	\$4,681	
	Lighting - Lay-in	3rd Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	3rd Floor	855	SF	6	\$2,360	
assro	oom #336 (Regular Classroom)						
	Casework	3rd Floor	36	LF	6	\$909	
	Ceiling - Lay-in	3rd Floor	1,026	SF	6	\$3,081	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	Wood panel
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,026	SF	6	\$7,233	
	Lighting - Lay-in	3rd Floor	20	EA	6	\$2,380	
	Walls - Plaster/Drywall	3rd Floor	1,384	SF	6	\$3,820	
	Walls - Plaster/Drywall	3rd Floor	1	SF	5	\$5	Peeling paint
	Work Sink	3rd Floor	1	EA	6	\$379	
assro	oom #337 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	704	SF	6	\$2,114	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	704	SF	6	\$4,963	
	Lighting - Lay-in	3rd Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	3rd Floor	920	SF	6	\$2,539	
assro	oom #338 (Computer Lab)						
	AC Units	3rd Floor	2	EA	5	\$3,652	Poor support
	Casework	3rd Floor	10	LF	6	\$253	



Building: Main

Classroom #338 (Computer Lab) Std Floor 2,106 SF 6 \$6,324 Chalk Board 3rd Floor 31 LF 4 \$2,846 Doors - Transom Window 3rd Floor 24 SF 6 \$406 Doors - Transom Window 3rd Floor 24 SF 6 \$406 Doors - Transom Window 3rd Floor 24 SF 6 \$406 Doors - Wood Doors inclu hw 3rd Floor 2,106 SF 6 \$406 Floor - Tile/Sheet 3rd Floor 2,106 SF 6 \$2,108 Lighting - Lay-in 3rd Floor 20 EA 6 \$2,380 Marker Board 3rd Floor 26 LF 6 \$557 Walls - Plaster/Drywall 3rd Floor 1,597 SF 6 \$4,408 Walls - Plaster/Drywall 3rd Floor 6 SF 5 \$31 Cracks in wall and bubbling/pet Casework 3rd Floor 8 LF 6 \$2,207 Ceiling - Lay-in 3rd Floor 735 SF 6 \$2,203	ling paint
Chalk Board3rd Floor3rd Floor3rd Floor4rd Floor\$2,846Doors - Transom Window3rd Floor24\$F6\$406Doors - Wood Doors inclu hw3rd Floor3EA6\$903Floor - Tile/Sheet3rd Floor2,106\$F6\$2,108Lighting - Lay-in3rd Floor20EA6\$2,380Marker Board3rd Floor26LF6\$557Walls - Plaster/Drywall3rd Floor1,597\$F6\$44,408Walls - Plaster/Drywall3rd Floor1,597\$F6\$311Casework3rd Floor8LF6\$2,207Casework3rd Floor735\$F6\$2,207Ceiling - Lay-in3rd Floor3rd Floor32LF4\$2,938	ling paint
Doors - Transom Window3rd Floor24SF6\$406Doors - Wood Doors inclu hw3rd Floor3rd Floor3EA6\$903Floor - Tile/Sheet3rd Floor2,106SF6\$2,108Lighting - Lay-in3rd Floor20EA6\$2,380Marker Board3rd Floor26LF6\$557Walls - Plaster/Drywall3rd Floor1,597SF6\$4,408Walls - Plaster/Drywall3rd Floor6SF5\$311Cracks in wall and bubbling/peeCasework3rd Floor8LF6\$202Ceiling - Lay-in3rd Floor8SF6\$2,207Chalk Board3rd Floor32LF4\$2,938	ling paint
Doors - Wood Doors inclu hw3rd Floor3rd Floor3rd Floor2,1065F6\$903Floor - Tile/Sheet3rd Floor2,106SF6\$2,108111 <t< td=""><td>ling paint</td></t<>	ling paint
Floor - Tile/Sheet3rd Floor2,106SF6\$2,108Lighting - Lay-in3rd Floor20EA6\$2,380Marker Board3rd Floor26LF6\$557Walls - Plaster/Drywall3rd Floor1,597SF6\$4,408Walls - Plaster/Drywall3rd Floor6SF5\$31Cracks in wall and bubbling/peeClassroomCasework3rd Floor8LF6\$202Casework3rd Floor735SF6\$2,207Chalk Board3rd Floor32LF4\$2,938	ling paint
Lighting - Lay-in3rd Floor20EA6\$2,380Marker Board3rd Floor26LF6\$557Walls - Plaster/Drywall3rd Floor1,597SF6\$4,408Walls - Plaster/Drywall3rd Floor6SF5\$31Cracks in wall and bubbling/peeClassroom #339 (Regular Classroom)Casework3rd Floor8LF6\$202Casework3rd Floor735SF6\$2,207Ceiling - Lay-in3rd Floor3rd Floor32LF4\$2,938	ling paint
Marker Board3rd Floor26LF6\$557Walls - Plaster/Drywall3rd Floor1,597SF6\$4,408Walls - Plaster/Drywall3rd Floor6SF5\$31Cracks in wall and bubbling/peeClassroom #339 (Regular Classroom)Casework3rd Floor8LF6\$202Ceiling - Lay-in3rd Floor735SF6\$2,207Chalk Board3rd Floor32LF4\$2,938	ling paint
Walls - Plaster/Drywall3rd Floor1,597SF6\$4,408Walls - Plaster/Drywall3rd Floor6SF5\$31Cracks in wall and bubbling/peeClassroom #339 (Regular Classroom)Casework3rd Floor8LF6\$202Ceiling - Lay-in3rd Floor3rd Floor32LF4\$2,938Chalk Board3rd Floor32LF4\$2,938	ling paint
Walls - Plaster/Drywall3rd Floor6SF5\$31Cracks in wall and bubbling/peeClassroom #339 (Regular Classroom)Casework3rd Floor8LF6\$202Ceiling - Lay-in3rd Floor735SF6\$2,207Chalk Board3rd Floor32LF4\$2,938	ling paint
ClassroomCasework3rd Floor8LF6\$202Ceiling - Lay-in3rd Floor735SF6\$2,207Chalk Board3rd Floor32LF4\$2,938	ling paint
Casework 3rd Floor 8 LF 6 \$202 Ceiling - Lay-in 3rd Floor 735 SF 6 \$2,207 Chalk Board 3rd Floor 32 LF 4 \$2,938	
Ceiling - Lay-in 3rd Floor 735 SF 6 \$2,207 Chalk Board 3rd Floor 32 LF 4 \$2,938	
Chalk Board 3rd Floor 32 LF 4 \$2,938	
Doors - Transom Window3rd Floor8SF6\$135	
Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 \$301	
Floor - Wood 3rd Floor 735 SF 6 \$5,182	
Lighting - Lay-in 3rd Floor 12 EA 6 \$1,428	
Walls - Plaster/Drywall3rd Floor818SF6\$2,258	
Walls - Plaster/Drywall3rd Floor2SF5\$10Peeling paint	
Classroom #341 (Vacant)	
Casework 3rd Floor 8 LF 6 \$202	
Ceiling - Lay-in 3rd Floor 735 SF 6 \$2,207	
Chalk Board 3rd Floor 32 LF 4 \$2,938	
Doors - Wood Doors inclu hw 3rd Floor 1 EA 6 \$301	
Floor - Wood 3rd Floor 735 SF 6 \$5,182	
Lighting - Lay-in 3rd Floor 12 EA 7 \$0	
Walls - Plaster/Drywall3rd Floor818SF6\$2,258	
Walls - Plaster/Drywall3rd Floor2SF5\$10Peeling paint	
Classroom #342 (Vacant)	
Casework 2nd Floor 12 LF 6 \$303	
Ceiling - Lay-in 2nd Floor 1,145 SF 6 \$3,438	
Ceiling - Lay-in 2nd Floor 4 SF 5 \$32 Missing tiles	
Chalk Board 2nd Floor 16 LF 4 \$1,469	
Doors - Transom Window 2nd Floor 8 SF 6 \$135	
Doors - Transom Window2nd Floor8SF6\$135Wood panel	
Doors - Wood Doors inclu hw2nd Floor2EA6\$602	



Building: Main

Category: Classrooms

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #342 (Vacant)						
Floor - Wood	2nd Floor	1,149	SF	6	\$8,100	
Lighting - Lay-in	2nd Floor	13	EA	7	\$0	
Lighting - Pendent/Surface	2nd Floor	12	EA	6	\$1,487	
Walls - Plaster/Drywall	2nd Floor	6	SF	5	\$45	Damaged walls
Walls - Structural Glazed Tile	2nd Floor	1,860	SF	6	\$5,852	
Work Sink	2nd Floor	1	EA	6	\$379	
Classroom #344 (Regular Classroom)						
Casework	3rd Floor	8	LF	6	\$202	
Ceiling - Splined	3rd Floor	1,718	SF	6	\$1,400	
Chalk Board	3rd Floor	30	LF	4	\$2,754	
Doors - Transom Window	3rd Floor	8	SF	6	\$135	
Doors - Transom Window	3rd Floor	8	SF	6	\$135	Wood panel
Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
Floor - Wood	3rd Floor	1,718	SF	6	\$12,112	
Lighting - Lay-in	3rd Floor	28	EA	6	\$3,331	
Walls - Plaster/Drywall	3rd Floor	1,940	SF	6	\$5,354	
Walls - Plaster/Drywall	3rd Floor	5	SF	5	\$26	Damaged walls

Classrooms Subtotal:

\$1,030,887

Building: Main

oup li	tem - Type	Location	Quantity	Unit	Rank	Cost	Comments
ministr	rative Suites/Offices						
A	AC Unit	219A Discipline	1	EA	5	\$1,826	Not per CPS standards
(Ceiling - Lay-in	219A Discipline	410	SF	6	\$1,231	Few tiles missing
[Doors - Transom Window	219A Discipline	8	SF	6	\$135	
[Doors - Transom Window	219A Discipline	1	SF	6	\$17	
F	Floor - Tile/Sheet	219A Discipline	410	SF	6	\$410	
L	_ighting - Lay-in	219A Discipline	6	EA	7	\$0	
F	Power Distribution	219A Discipline	6	EA	7	\$0	
٧	Nalls - Plaster/Drywall	219A Discipline	2	SF	5	\$10	Peeling paint
٧	Nalls - Plaster/Drywall	219A Discipline	798	SF	6	\$2,202	
A	AC Unit	221A Office	1	EA	5	\$1,826	Not per CPS standards
(Ceiling - Plaster/Drywall	221A Office	262	SF	5	\$2,402	Peeling paint
0	Doors - Transom Window	221A Office	8	SF	6	\$135	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	trative Suites/Offices						
	Doors - Transom Window	221A Office	1	SF	6	\$17	
	Floor - Tile/Sheet	221A Office	262	SF	6	\$262	
	Lighting - Pendent/Surface	221A Office	4	EA	7	\$0	
	Power Distribution	221A Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	221A Office	835	SF	6	\$2,305	
	AC Unit	232 Asst. Principal	1	EA	5	\$1,826	Poor support
	Ceiling - Lay-in	232 Asst. Principal	460	SF	6	\$1,381	
	Doors - Side-lite	232 Asst. Principal	24	SF	6	\$401	
	Doors - Transom Window	232 Asst. Principal	24	SF	6	\$406	
	Doors - Wood Doors inclu hw	232 Asst. Principal	1	EA	6	\$301	
	Floor - Tile/Sheet	232 Asst. Principal	460	SF	6	\$460	
	Lighting - Pendent/Surface	232 Asst. Principal	6	EA	6	\$743	
	Power Distribution	232 Asst. Principal	6	EA	7	\$0	
	Walls - Plaster/Drywall	232 Asst. Principal	860	SF	6	\$2,374	
	Ceiling - Plaster/Drywall	246 Gym office	5	SF	5	\$62	Holes in Ceiling
	Ceiling - Plaster/Drywall	246 Gym office	3,236	SF	6	\$11,199	
	Doors - Transom Window	246 Gym office	8	SF	6	\$135	
	Floor - Tile/Sheet	246 Gym office	331	SF	6	\$331	Missing one tile
	Lighting - Pendent/Surface	246 Gym office	6	EA	7	\$0	
	Power Distribution	246 Gym office	6	EA	7	\$0	
	Storage/ Closet	246 Gym office	79	SF	6	\$573	
	Walls - Plaster/Drywall	246 Gym office	904	SF	6	\$2,495	
	AC Unit	2nd floor room 241A nurse's office	1	EA	5	\$1,826	Poor support
	Ceiling - Plaster/Drywall	2nd floor room 241A nurse's office	786	SF	6	\$2,720	
	Ceiling - Plaster/Drywall	2nd floor room 241A nurse's office	2	SF	5	\$25	Peeling paint
	Doors - Transom Window	2nd floor room 241A nurse's office	8	SF	6	\$135	wood panel
	Doors - Wood Doors inclu hw	2nd floor room 241A nurse's office	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd floor room 241A nurse's office	1	SF	5	\$6	Damaged tile
	Floor - Tile/Sheet	2nd floor room 241A nurse's office	788	SF	6	\$789	
	Lighting - Pendent/Surface	2nd floor room 241A nurse's office	8	EA	7	\$0	
	Power Distribution	2nd floor room 241A nurse's office	6	EA	7	\$0	
	Walls - Plaster/Drywall	2nd floor room 241A nurse's office	1,710	SF	6	\$4,719	
	Work SInk	2nd floor room 241A nurse's office	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	2nd floor gym office next to gym 247	331	SF	6	\$1,145	
	Doors - Wood Doors inclu hw	2nd floor gym office next to gym 247	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd floor gym office next to gym 247	331	SF	6	\$331	
	Lighting - Pendent/Surface	2nd floor gym office next to gym 247	6	EA	6	\$743	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Power Distribution	2nd floor gym office next to gym 247	6	EA	7	\$0	
	Walls - Plaster/Drywall	2nd floor gym office next to gym 247	904	SF	6	\$2,495	
	Ceiling - Plaster/Drywall	319A Counselor Office	1	SF	5	\$12	Hole in ceiling
	Ceiling - Plaster/Drywall	319A Counselor Office	268	SF	6	\$927	
	Doors - Transom Window	319A Counselor Office	8	SF	6	\$135	wood panel
	Doors - Wood Doors inclu hw	319A Counselor Office	1	EA	6	\$301	
	Floor - Tile/Sheet	319A Counselor Office	269	SF	6	\$269	
	Lighting - Lay-in	319A Counselor Office	4	EA	7	\$0	
	Power Distribution	319A Counselor Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	319A Counselor Office	839	SF	6	\$2,316	
	Ceiling - Plaster/Drywall	322 Office	306	SF	6	\$1,059	
	Doors - Transom Window	322 Office	8	SF	6	\$135	Wood panel
	Doors - Wood Doors inclu hw	322 Office	1	EA	6	\$301	
	Floor - Tile/Sheet	322 Office	306	SF	6	\$306	
	Lighting - Pendent/Surface	322 Office	6	EA	7	\$0	
	Power Distribution	322 Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	322 Office	830	SF	6	\$2,291	
	Walls - Plaster/Drywall	322 Office	6	SF	5	\$31	Peeling paint and plaster
	Ceiling - Lay-in	332 Counselor Office	340	SF	6	\$1,021	
	Doors - Side-lite	332 Counselor Office	24	SF	6	\$401	
	Doors - Transom Window	332 Counselor Office	24	SF	6	\$406	
	Doors - Wood Doors inclu hw	332 Counselor Office	1	EA	6	\$301	
	Floor - Tile/Sheet	332 Counselor Office	337	SF	6	\$337	
	Floor - Tile/Sheet	332 Counselor Office	3	SF	5	\$17	Damaged tiles
	Lighting - Pendent/Surface	332 Counselor Office	6	EA	7	\$0	
	Power Distribution	332 Counselor Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	332 Counselor Office	800	SF	6	\$2,208	
	Ceiling - Plaster/Drywall	339A P.E. Office	210	SF	6	\$727	
	Doors - Transom Window	339A P.E. Office	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	339A P.E. Office	1	EA	6	\$301	
	Floor - Tile/Sheet	339A P.E. Office	210	SF	6	\$210	
	Lighting - Pendent/Surface	339A P.E. Office	2	EA	6	\$248	
	Power Distribution	339A P.E. Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	339A P.E. Office	780	SF	6	\$2,153	
	Ceiling - Lay-in	340 Athletic Director	308	SF	6	\$925	
	Doors - Transom Window	340 Athletic Director	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	340 Athletic Director	1	EA	6	\$301	
	Ceiling - Lay-in Doors - Transom Window	340 Athletic Director 340 Athletic Director	308 8	SF SF	6 6	\$925 \$135	



Group I	tem - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administr	rative Suites/Offices						
F	Floor - Wood	340 Athletic Director	308	SF	6	\$2,171	
l	_ighting - Lay-in	340 Athletic Director	6	EA	7	\$0	
F	Power Distribution	340 Athletic Director	7	EA	7	\$0	
١	Nalls - Plaster/Drywall	340 Athletic Director	1	SF	5	\$5	Peeling paint
١	Nalls - Plaster/Drywall	340 Athletic Director	839	SF	6	\$2,316	
(Ceiling - Plaster/Drywall	Game room in Gym	390	SF	6	\$1,350	
Γ	Doors - Steel Doors incl hw	Game room in Gym	2	EA	6	\$602	
F	Floor - Wood	Game room in Gym	390	SF	6	\$2,749	
l	_ighting - Pendent/Surface	Game room in Gym	6	EA	6	\$743	
F	Power Distribution	Game room in Gym	4	EA	7	\$0	
١	Walls - Metal Panel	Game room in Gym	798	SF	6	\$5,957	
١	Walls - Plaster/Drywall	Game room in Gym	5	SF	5	\$38	Damaged plaster
1	AC Unit	Main office from 135	2	EA	4	\$12,173	not working
(Ceiling - Plaster/Drywall	Main office from 135	797	SF	6	\$2,758	
[Doors - Wood Doors inclu hw	Main office from 135	2	EA	6	\$602	
F	Floor - Tile/Sheet	Main office from 135	797	SF	6	\$798	
l	Lighting - Lay-in	Main office from 135	6	EA	7	\$0	
F	Power Distribution	Main office from 135	8	EA	7	\$0	
١	Walls - Plaster/Drywall	Main office from 135	1,510	SF	6	\$4,167	
١	Walls - Plaster/Drywall	Main office from 135	10	SF	5	\$51	Peeling paint
(Ceiling - Lay-in	Office in 317	235	SF	6	\$706	
(Ceiling - Lay-in	Office in 317	3	SF	5	\$24	Missing tiles
[Doors - Wood Doors inclu hw	Office in 317	1	EA	6	\$301	
F	Floor - Wood	Office in 317	238	SF	6	\$1,678	
l	Lighting - Pendent/Surface	Office in 317	3	EA	7	\$0	
F	Power Distribution	Office in 317	4	EA	7	\$0	
١	Nalls - Plaster/Drywall	Office in 317	703	SF	6	\$1,940	
(Ceiling - Plaster/Drywall	Office room 010A	461	SF	6	\$1,595	
Γ	Doors - Wood Doors inclu hw	Office room 010A	1	EA	6	\$301	
F	Floor - Tile/Sheet	Office room 010A	461	SF	6	\$461	
l	Lighting - Pendent/Surface	Office room 010A	3	EA	7	\$0	
F	Power Distribution	Office room 010A	4	EA	7	\$0	
١	Walls - Plaster/Drywall	Office room 010A	1,025	SF	6	\$2,829	
(Ceiling - Plaster/Drywall	Office room 012A	461	SF	6	\$1,595	
[Doors - Wood Doors inclu hw	Office room 012A	1	EA	6	\$301	
F	Floor - Tile/Sheet	Office room 012A	461	SF	6	\$461	
l	_ighting - Pendent/Surface	Office room 012A	3	EA	7	\$0	



oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dmini	strative Suites/Offices						
	Power Distribution	Office room 012A	4	EA	7	\$0	
	Walls - Plaster/Drywall	Office room 012A	1,025	SF	6	\$2,829	
	Ceiling - Plaster/Drywall	Office room 122A	461	SF	6	\$1,595	
	Doors - Wood Doors inclu hw	Office room 122A	1	EA	6	\$301	
	Floor - Tile/Sheet	Office room 122A	461	SF	6	\$461	
	Lighting - Pendent/Surface	Office room 122A	3	EA	7	\$0	
	Power Distribution	Office room 122A	4	EA	7	\$0	
	Walls - Plaster/Drywall	Office room 122A	1,025	SF	6	\$2,829	
	Ceiling - Lay-in	Room 119 Counselor's Office	1,516	SF	6	\$4,553	
	Doors - Wood Doors inclu hw	Room 119 Counselor's Office	2	EA	6	\$602	
	Floor - Wood	Room 119 Counselor's Office	1,516	SF	6	\$10,688	
	Lighting - Pendent/Surface	Room 119 Counselor's Office	28	EA	7	\$0	
	Power Distribution	Room 119 Counselor's Office	29	EA	7	\$0	
	Walls - Plaster/Drywall	Room 119 Counselor's Office	1,486	SF	6	\$4,101	
	AC Unit	Room 125 conference room	3	EA	5	\$5,477	Poor support
	Ceiling - Splined	Room 125 conference room	1,314	SF	6	\$1,071	
	Doors - Wood Doors inclu hw	Room 125 conference room	2	EA	6	\$602	
	Floor - Carpet	Room 125 conference room	1,314	SF	6	\$2,800	
	Lighting - Lay-in	Room 125 conference room	22	EA	7	\$0	
	Power Distribution	Room 125 conference room	8	EA	7	\$0	
	Walls - Plaster/Drywall	Room 125 conference room	1,784	SF	6	\$4,924	
	AC Unit	Room 126 social room	2	EA	4	\$12,173	Not working
	Ceiling - Plaster/Drywall	Room 126 social room	1,020	SF	6	\$3,530	
	Doors - Wood Doors inclu hw	Room 126 social room	2	EA	6	\$602	
	Floor - Carpet	Room 126 social room	1,020	SF	6	\$2,173	
	Lighting - Pendent/Surface	Room 126 social room	20	EA	7	\$0	
	Power Distribution	Room 126 social room	14	EA	7	\$0	
	Walls - Plaster/Drywall	Room 126 social room	3,456	SF	6	\$9,538	
	Ceiling - Plaster/Drywall	Room 127 Main Attendance Office	1,020	SF	6	\$3,530	
	Doors - Wood Doors inclu hw	Room 127 Main Attendance Office	2	EA	6	\$602	
	Floor - Carpet	Room 127 Main Attendance Office	1,020	SF	6	\$2,173	
	Lighting - Pendent/Surface	Room 127 Main Attendance Office	20	EA	7	\$0	
	Power Distribution	Room 127 Main Attendance Office	14	EA	7	\$0	
	Walls - Plaster/Drywall	Room 127 Main Attendance Office	3,456	SF	6	\$9,538	
	Ceiling - Plaster/Drywall	Room 128 discipline room	1,027	SF	6	\$3,554	
	Doors - Wood Doors inclu hw	Room 128 discipline room	2	EA	6	\$602	
	Floor - Tile/Sheet	Room 128 discipline room	1,027	SF	6	\$1,028	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dmini	istrative Suites/Offices						
	Lighting - Pendent/Surface	Room 128 discipline room	20	EA	7	\$0	
	Power Distribution	Room 128 discipline room	30	EA	7	\$0	
	Walls - Plaster/Drywall	Room 128 discipline room	1,500	SF	6	\$4,140	
	AC Unit	Room 133	1	EA	4	\$6,086	Not working
	Ceiling - Plaster/Drywall	Room 133	234	SF	6	\$810	
	Doors - Wood Doors inclu hw	Room 133	1	EA	6	\$301	
	Floor - Carpet	Room 133	234	SF	6	\$499	
	Lighting - Pendent/Surface	Room 133	3	EA	7	\$0	
	Power Distribution	Room 133	6	EA	7	\$0	
	Walls - Plaster/Drywall	Room 133	745	SF	6	\$2,056	
	AC Unit	Room 134 A, Asst Principal's office	1	EA	4	\$6,086	Not working
	Ceiling - Plaster/Drywall	Room 134 A, Asst Principal's office	329	SF	6	\$1,139	
	Doors - Wood Doors inclu hw	Room 134 A, Asst Principal's office	1	EA	6	\$301	
	Floor - Carpet	Room 134 A, Asst Principal's office	329	SF	6	\$701	
	Lighting - Pendent/Surface	Room 134 A, Asst Principal's office	4	EA	7	\$0	
	Power Distribution	Room 134 A, Asst Principal's office	6	EA	7	\$0	
	Walls - Plaster/Drywall	Room 134 A, Asst Principal's office	595	SF	6	\$1,642	
	AC Unit	Room 135A office	2	EA	4	\$12,173	not working
	Ceiling - Lay-in	Room 135A office	310	SF	6	\$931	
	Doors - Wood Doors inclu hw	Room 135A office	1	EA	6	\$301	
	Floor - Carpet	Room 135A office	310	SF	6	\$661	
	Lighting - Pendent/Surface	Room 135A office	6	EA	7	\$0	
	Power Distribution	Room 135A office	6	EA	7	\$0	
	Walls - Plaster/Drywall	Room 135A office	645	SF	6	\$1,780	
	Ceiling - Plaster/Drywall	Room 137 business manager's office	190	SF	6	\$658	
	Doors - Wood Doors inclu hw	Room 137 business manager's office	1	EA	6	\$301	
	Floor - Tile/Sheet	Room 137 business manager's office	190	SF	6	\$190	
	Lighting - Pendent/Surface	Room 137 business manager's office	3	EA	7	\$0	
	Power Distribution	Room 137 business manager's office	4	EA	7	\$0	
	Walls - Plaster/Drywall	Room 137 business manager's office	679	SF	6	\$1,874	
	Ceiling - Plaster/Drywall	Room 143 CPD office	257	SF	6	\$889	
	Doors - Wood Doors inclu hw	Room 143 CPD office	1	EA	6	\$301	
	Floor - Carpet	Room 143 CPD office	257	SF	6	\$548	
	Lighting - Pendent/Surface	Room 143 CPD office	3	EA	7	\$0	
	Power Distribution	Room 143 CPD office	6	EA	7	\$0	
	Walls - Plaster/Drywall	Room 143 CPD office	535	SF	6	\$1,477	
	Ceiling - Lay-in	Third floor west end room 318	300	SF	6	\$901	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Doors - Wood Doors inclu hw	Third floor west end room 318	1	EA	6	\$301	
	Floor - Tile/Sheet	Third floor west end room 318	300	SF	6	\$300	
	Lighting - Pendent/Surface	Third floor west end room 318	6	EA	6	\$743	
	Walls - Plaster/Drywall	Third floor west end room 318	840	SF	6	\$2,318	
	Ceiling - Lay-in	Third floor west end teachers work room	320	SF	6	\$961	
	Doors - Wood Doors inclu hw	Third floor west end teachers work room	1	EA	6	\$301	
	Floor - Tile/Sheet	Third floor west end teachers work room	320	SF	6	\$320	
	Lighting - Pendent/Surface	Third floor west end teachers work room	6	EA	6	\$743	
	Walls - Plaster/Drywall	Third floor west end teachers work room	840	SF	6	\$2,318	
Auditor	ium & Theater						
	Balcony Seating	1st Floor	150	EA	6	\$26,087	
	Ceiling - Splined	1st Floor	7,224	SF	6	\$5,888	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	
	Floor - Carpet	1st Floor	7,224	SF	6	\$15,392	
	Lighting - Chandelier, Incandescent	1st Floor	6	EA	7	\$0	
	Main Floor Seating	1st Floor	652	EA	6	\$113,394	
	Sound System	1st Floor	1	EA	6	\$10,721	
	Stage Curtain	1st Floor	14	EA	6	\$0	
	Stage Lighting System	1st Floor	1	EA	6	\$8,077	
	Walls - Plaster/Drywall	1st Floor	9,817	SF	6	\$46,748	
Gymna	sia						
	Bleacher Seating	247 Gymnasium	400	EA	6	\$11,577	
	Ceiling - Plaster/Drywall	247 Gymnasium	10,798	SF	6	\$59,603	
	Ceiling - Splined	247 Gymnasium	2	SF	5	\$14	damaged
	Doors - Wood Doors inclu hw	247 Gymnasium	4	EA	6	\$1,204	
	Floor - Wood	247 Gymnasium	10,800	SF	6	\$76,139	
	Lighting - Pendent/Surface	247 Gymnasium	42	EA	7	\$0	
	Scoreboards	247 Gymnasium	2	EA	6	\$4,489	
	Sound System	247 Gymnasium	1	EA	6	\$41,654	
	Storage/ Closet	247 Gymnasium	193	SF	6	\$1,399	
	Walls - Structural Glazed Tile	247 Gymnasium	11,210	SF	6	\$35,267	
	Walls - Structural Glazed Tile	247 Gymnasium	6	SF	4	\$734	Evidence on movement (Major cracks)
	Ceiling - Plaster/Drywall	2nd floor room 246	5	SF	5	\$100	Peeling paint and water stains
	Ceiling - Plaster/Drywall	2nd floor room 246	1,860	SF	6	\$10,267	
	Doors - Transom Window	2nd floor room 246	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd floor room 246	2	EA	6	\$602	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Gymnasia							
	Floor - Wood	2nd floor room 246	1,865	SF	6	\$13,148	
	Lighting - Metal Halide/Sodium Vapor	2nd floor room 246	12	EA	7	\$0	
	Walls - Structural Glazed Tile	2nd floor room 246	3,051	SF	6	\$9,598	
Kitcher	1						
	Ceiling - Splined	1st Floor	3,788	SF	6	\$3,088	
	Floor - Tile Ceramic/ Porcelain	1st Floor	3,788	SF	6	\$8,017	
	Lighting - Pendent/Surface	1st Floor	26	EA	7	\$0	
	Walls - Structural Glazed Tile	1st Floor	4,520	SF	6	\$14,220	
Library							
,	Casework	231 Library	250	LF	6	\$6,313	
	Ceiling - Splined	231 Library	3,053	SF	6	\$2,489	
	Doors - Wood Doors inclu hw	231 Library	4	EA	6	\$1,204	
	Floor - Carpet	231 Library	3,053	SF	6	\$6,505	
	Lighting - Pendent/Surface	231 Library	39	EA	7	\$0	
	Storage/ Closet	231 Library	126	SF	6	\$914	
	Walls - Plaster/Drywall	231 Library	4,294	SF	6	\$11,851	
	AC Unit	Room 237 Library Work/Book room	1	EA	5	\$1,826	Not per CPS standards
	Ceiling - Plaster/Drywall	Room 237 Library Work/Book room	682	SF	6	\$2,360	
	Doors - Transom Window	Room 237 Library Work/Book room	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	Room 237 Library Work/Book room	1	EA	6	\$301	
	Floor - Carpet	Room 237 Library Work/Book room	682	SF	6	\$1,453	
	Lighting - Pendent/Surface	Room 237 Library Work/Book room	9	EA	7	\$0	
	Walls - Plaster/Drywall	Room 237 Library Work/Book room	1,149	SF	6	\$3,171	
	Walls - Plaster/Drywall	Room 237 Library Work/Book room	1	SF	5	\$5	Crack in wall
Locker	/Shower Room						
	Accessories	1st floor boys' room by the swimming pool	2,429	SF	6	\$9,517	
	Benches, ped mounted	1st floor boys' room by the swimming pool	18	LF	6	\$1,960	
	Ceiling - Exposed	1st floor boys' room by the swimming pool	2,328	SF	6	\$3,462	
	Doors - Wood Doors inclu hw	1st floor boys' room by the swimming pool	2	EA	6	\$602	
	Floor Drain	1st floor boys' room by the swimming pool	5	EA	6	\$5,296	
	Floor - Tile Ceramic/ Porcelain	1st floor boys' room by the swimming pool	2,328	SF	6	\$4,927	



up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ker/S	Shower Room						
	Hand Dryer	1st floor boys' room by the swimming pool	4	EA	6	\$920	
	Lavatory	1st floor boys' room by the swimming pool	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st floor boys' room by the swimming pool	30	EA	7	\$0	
	Partitions	1st floor boys' room by the swimming pool	3	EA	6	\$891	
	Showers	1st floor boys' room by the swimming pool	5	EA	6	\$1,557	
	Student Lockers - One Tier	1st floor boys' room by the swimming pool	256	EA	6	\$23,766	
	Urinals	1st floor boys' room by the swimming pool	7	EA	6	\$2,352	
	Walls - Structural Glazed Tile	1st floor boys' room by the swimming pool	4,329	SF	6	\$13,619	
	Water Closet	1st floor boys' room by the swimming pool	3	EA	6	\$1,008	
	Benches, ped mounted	1st floor girls' room by the swimming pool	36	LF	6	\$3,920	
	Ceiling - Exposed	1st floor girls' room by the swimming pool	2,429	SF	6	\$3,612	
	Doors - Steel Doors incl hw	1st floor girls' room by the swimming pool	2	EA	6	\$602	
	Floor Drain	1st floor girls' room by the swimming pool	5	EA	6	\$5,296	
	Floor - Tile Ceramic/ Porcelain	1st floor girls' room by the swimming pool	2,429	SF	6	\$5,141	
	Hand Dryer	1st floor girls' room by the swimming pool	4	EA	6	\$920	
	Lavatory	1st floor girls' room by the swimming pool	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st floor girls' room by the swimming pool	24	EA	7	\$0	
	Partitions	1st floor girls' room by the swimming pool	6	EA	6	\$1,782	
	Showers	1st floor girls' room by the swimming pool	5	EA	6	\$1,557	
	Student Lockers - One Tier	1st floor girls' room by the swimming pool	139	EA	6	\$12,904	
	Walls - Structural Glazed Tile	1st floor girls' room by the swimming pool	4,530	SF	6	\$14,251	
	Water Closet	1st floor girls' room by the swimming pool	6	EA	6	\$2,016	
	Accessories	1st floor inside auto shop 016 & 018	1,030	SF	6	\$4,036	
	Ceiling - Exposed	1st floor inside auto shop 016 & 018	1,030	SF	6	\$1,532	
	Floor Drain	1st floor inside auto shop 016 & 018	4	EA	6	\$4,237	
	Floor - Concrete	1st floor inside auto shop 016 & 018	1,030	SF	6	\$545	
	Hand Dryer	1st floor inside auto shop 016 & 018	2	EA	6	\$460	
	Lavatory	1st floor inside auto shop 016 & 018	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st floor inside auto shop 016 & 018	8	EA	6	\$991	
	Partitions	1st floor inside auto shop 016 & 018	2	EA	6	\$594	
	Showers	1st floor inside auto shop 016 & 018	2	EA	6	\$623	



Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/Shower Room						
Student Lockers - One Tier	1st floor inside auto shop 016 & 018	48	EA	6	\$4,456	
Urinals	1st floor inside auto shop 016 & 018	4	EA	6	\$1,344	
Walls - Structural Glazed Tile	1st floor inside auto shop 016 & 018	1,300	SF	6	\$4,090	
Water Closet	1st floor inside auto shop 016 & 018	2	EA	6	\$672	
Accessories	2nd floor girls' locker inside gym	143	SF	6	\$560	
Ceiling - Plaster/ Drywall	2nd floor girls' locker inside gym	143	SF	6	\$495	
Doors - Wood Doors inclu hw	2nd floor girls' locker inside gym	1	EA	5	\$1,174	
Floor Drain	2nd floor girls' locker inside gym	2	EA	6	\$2,118	
Floor - Tile Ceramic/ Porcelain	2nd floor girls' locker inside gym	143	SF	6	\$303	
Hand Dryer	2nd floor girls' locker inside gym	1	EA	6	\$230	
Lavatory	2nd floor girls' locker inside gym	1	EA	6	\$320	
Lighting - Pendent/Surface	2nd floor girls' locker inside gym	3	EA	6	\$372	
Partitions	2nd floor girls' locker inside gym	1	EA	6	\$297	
Showers	2nd floor girls' locker inside gym	1	EA	6	\$311	
Student Lockers - One Tier	2nd floor girls' locker inside gym	8	EA	6	\$743	
Walls - Structural Glazed Tile	2nd floor girls' locker inside gym	500	SF	6	\$1,573	
Water Closet	2nd floor girls' locker inside gym	1	EA	6	\$336	
Lunch & Multipurpose Room						
Ceiling - Splined	1st Floor	17,634	SF	6	\$14,373	
Doors - Steel Doors incl hw	1st Floor	10	EA	6	\$3,010	
Floor - Tile/Sheet	1st Floor	17,634	SF	6	\$17,652	
Lighting - Lay-in	1st Floor	98	EA	7	\$0	
Serving Line	1st Floor	160	LF	6	\$9,523	
Walls - Plaster/Drywall	1st Floor	5,428	SF	6	\$14,981	
Walls - Structural Glazed Tile	1st Floor	1,357	SF	6	\$4,269	
Ceiling - Lay-in	Teacher's Lunchroom 008	950	SF	6	\$2,853	
Doors - Steel Doors incl hw	Teacher's Lunchroom 008	2	EA	6	\$602	
Floor - Tile	Teacher's Lunchroom 008	950	SF	6	\$2,079	
Lighting - Pendent/Surface	Teacher's Lunchroom 008	18	EA	6	\$2,230	
Walls - Plaster/Drywall	Teacher's Lunchroom 008	2,500	SF	6	\$6,900	
MDF_IDF						
AC Unit	240 MDF	1	EA	5	\$1,826	Not per CPS standards
Doors - Transom Window	240 MDF	8	SF	6	\$135	
Doors - Wood Doors inclu hw	240 MDF	1	EA	6	\$301	
Finishes	240 MDF	862	SF	6	\$6,151	Painted plaster



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechar	nical/ Service Rooms						
	Mechanical/ Service Rooms	1st floor Outside	432	SF	6	\$3,095	Switchgear room next to ComEd vault
	Janitor's Closet	2nd Floor	165	SF	6	\$1,182	
	Storage Room	2nd Floor	785	SF	6	\$5,624	Gym Storage/Equipment and storage
	Janitor's Closet	3rd Floor	140	SF	6	\$1,003	
	Mechanical/ Service Rooms	3rd Floor	1,852	SF	6	\$13,268	Fan room, Damper room
	Storage Room	3rd Floor	516	SF	6	\$3,697	Located behind South balcony in gym
	Storage Room	3rd Floor	789	SF	6	\$5,653	#319 Band Storage
	Mechanical/ Service Rooms	Attic	8,163	SF	6	\$58,482	
	Boiler Room	Basement	4,200	SF	6	\$30,090	
	Crawl Space - Unfinished	Basement	30,000	SF	6	\$185,757	
	Mechanical/ Service Rooms	Basement	5,000	SF	6	\$35,822	
	Storage Room	Basement	916	SF	6	\$6,562	
Pool &	Natatorium						
	Accessories	1st Floor	5,907	SF	6	\$4,055	
	Bleachers Seating/Plank Seating	1st Floor	44	EA	6	\$1,274	
	Ceiling - Plaster/ Drywall	1st Floor	5,907	SF	6	\$32,605	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
	Floor - Tile Ceramic/ Porcelain	1st Floor	5,907	SF	6	\$12,502	
	Lighting - Pendent/Surface	1st Floor	60	EA	7	\$0	
	Pool Basin	1st Floor	3,713	SF	6	\$125,625	
	Pool Deck	1st Floor	1,924	SF	6	\$18,269	
	Pool Deck Drains	1st Floor	10	EA	6	\$4,221	
	Walls - Plaster/Drywall	1st Floor	24,000	SF	6	\$74,474	
Restro	om						
	Accessories	1st floor boys' room	341	SF	6	\$3,145	
	Ceiling - Plaster/Drywall	1st floor boys' room	341	SF	6	\$1,180	
	Doors - Wood Doors inclu hw	1st floor boys' room	1	EA	6	\$301	
	Floor Drain	1st floor boys' room	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor boys' room	341	SF	6	\$722	
	Hand Dryer	1st floor boys' room	2	EA	6	\$460	
	Lavatory	1st floor boys' room	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st floor boys' room	4	EA	6	\$496	
	Partitions	1st floor boys' room	3	EA	6	\$891	
	Urinals	1st floor boys' room	5	EA	6	\$1,680	
	Walls - Structural Glazed Tile	1st floor boys' room	957	SF	6	\$3,011	
	Water Closet	1st floor boys' room	3	EA	6	\$1,008	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Accessories	1st floor women's staff restroom	215	SF	6	\$1,983	
	Ceiling - Plaster/Drywall	1st floor women's staff restroom	215	SF	6	\$744	
	Doors - Wood Doors inclu hw	1st floor women's staff restroom	1	EA	6	\$301	
	Floor - Tile/Sheet	1st floor women's staff restroom	215	SF	6	\$215	
	Lavatory	1st floor women's staff restroom	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st floor women's staff restroom	2	EA	6	\$248	
	Partitions	1st floor women's staff restroom	3	EA	6	\$891	
	Walls - Concrete Block	1st floor women's staff restroom	795	SF	6	\$2,331	
	Water Closet	1st floor women's staff restroom	4	EA	6	\$1,344	
	Accessories	2nd floor boys east next to 239	376	SF	6	\$3,468	
	Ceiling - Plaster/Drywall	2nd floor boys east next to 239	376	SF	6	\$1,301	
	Doors - Wood Doors inclu hw	2nd floor boys east next to 239	1	EA	6	\$301	
	Floor Drain	2nd floor boys east next to 239	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys east next to 239	376	SF	6	\$796	
	Hand Dryer	2nd floor boys east next to 239	2	EA	6	\$460	
	Lavatory	2nd floor boys east next to 239	3	EA	6	\$959	
	Lighting - Pendent/Surface	2nd floor boys east next to 239	5	EA	6	\$619	
	Partitions	2nd floor boys east next to 239	3	EA	6	\$891	
	Urinals	2nd floor boys east next to 239	4	EA	6	\$1,344	
	Walls - Structural Glazed Tile	2nd floor boys east next to 239	954	SF	6	\$3,001	
	Water Closet	2nd floor boys east next to 239	3	EA	6	\$1,008	
	Accessories	2nd floor boys wesrt next to 223	376	SF	6	\$3,468	
	Ceiling - Plaster/Drywall	2nd floor boys wesrt next to 223	375	SF	6	\$1,298	
	Ceiling - Plaster/Drywall	2nd floor boys wesrt next to 223	1	SF	5	\$12	Peeling plaster
	Doors - Transom Window	2nd floor boys wesrt next to 223	1	SF	6	\$17	
	Floor Drain	2nd floor boys wesrt next to 223	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys wesrt next to 223	376	SF	6	\$796	
	Hand Dryer	2nd floor boys wesrt next to 223	2	EA	6	\$460	
	Lavatory	2nd floor boys wesrt next to 223	3	EA	6	\$959	
	Lighting - Pendent/Surface	2nd floor boys wesrt next to 223	5	EA	7	\$0	
	Partitions	2nd floor boys wesrt next to 223	3	EA	6	\$891	
	Urinals	2nd floor boys wesrt next to 223	5	EA	6	\$1,680	
	Walls - Structural Glazed Tile	2nd floor boys wesrt next to 223	954	SF	6	\$3,001	
	Water Closet	2nd floor boys wesrt next to 223	3	EA	6	\$1,008	
	Ceiling - Plaster/Drywall	2nd floor East of Gym (next to Exit 7)	142	SF	6	\$491	
	Doors - Wood Doors inclu hw	2nd floor East of Gym (next to Exit 7)	1	EA	6	\$301	
	Floor Drain	2nd floor East of Gym (next to Exit 7)	1	EA	6	\$1,059	



up I	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
troon	n						
ſ	Floor - Tile Ceramic/ Porcelain	2nd floor East of Gym (next to Exit 7)	142	SF	6	\$301	
ľ	Hand Dryer	2nd floor East of Gym (next to Exit 7)	2	EA	6	\$460	
ľ	Lavatory	2nd floor East of Gym (next to Exit 7)	2	EA	6	\$639	
ľ	Lighting - Pendent/Surface	2nd floor East of Gym (next to Exit 7)	2	EA	6	\$248	
ľ	Partitions	2nd floor East of Gym (next to Exit 7)	2	EA	6	\$594	
ľ	Urinals	2nd floor East of Gym (next to Exit 7)	2	EA	6	\$672	
,	Walls - Plaster/Drywall	2nd floor East of Gym (next to Exit 7)	220	SF	6	\$607	
,	Walls - Tile Ceramic/ Porcelain	2nd floor East of Gym (next to Exit 7)	543	SF	6	\$1,227	
,	Water Closet	2nd floor East of Gym (next to Exit 7)	3	EA	6	\$1,008	
1	Accessories	2nd floor girls across from library	324	SF	6	\$2,988	
(Ceiling - Plaster/Drywall	2nd floor girls across from library	324	SF	6	\$1,121	
ſ	Floor Drain	2nd floor girls across from library	1	EA	6	\$1,059	
ſ	Floor - Tile Ceramic/ Porcelain	2nd floor girls across from library	324	SF	6	\$686	
ſ	Hand Dryer	2nd floor girls across from library	2	EA	6	\$460	
ſ	Lavatory	2nd floor girls across from library	2	EA	6	\$639	
ſ	Lighting - Pendent/Surface	2nd floor girls across from library	5	EA	6	\$619	
ſ	Partitions	2nd floor girls across from library	6	EA	6	\$1,782	
Ţ	Walls - Plaster/Drywall	2nd floor girls across from library	200	SF	6	\$552	
Ţ	Walls - Tile Ceramic/ Porcelain	2nd floor girls across from library	1,066	SF	6	\$2,409	
Ţ	Water Closet	2nd floor girls across from library	6	EA	6	\$2,016	
	Accessories	2nd floor NE end Girl's next to 232	322	SF	6	\$2,970	
1	Ceiling - Plaster/Drywall	2nd floor NE end Girl's next to 232	320	SF	6	\$1,107	
ſ	Doors - Wood Doors inclu hw	2nd floor NE end Girl's next to 232	2	EA	6	\$602	
ſ	Floor Drain	2nd floor NE end Girl's next to 232	1	EA	6	\$1,059	
ſ	Floor - Tile Ceramic/ Porcelain	2nd floor NE end Girl's next to 232	322	SF	6	\$681	
ſ	Floor - Tile Ceramic/ Porcelain	2nd floor NE end Girl's next to 232	2	SF	5	\$42	Missing tiles
ſ	Hand Dryer	2nd floor NE end Girl's next to 232	2	EA	6	\$460	
ſ	Lavatory	2nd floor NE end Girl's next to 232	2	EA	6	\$639	
I	Lighting - Pendent/Surface	2nd floor NE end Girl's next to 232	5	EA	6	\$619	
I	Partitions	2nd floor NE end Girl's next to 232	6	EA	6	\$1,782	
,	Walls - Plaster/Drywall	2nd floor NE end Girl's next to 232	251	SF	6	\$693	
,	Walls - Structural Glazed Tile	2nd floor NE end Girl's next to 232	737	SF	6	\$2,319	
,	Water Closet	2nd floor NE end Girl's next to 232	6	EA	6	\$2,016	
	Accessories	2nd flr men's west of library next to 221A	138	SF	6	\$1,273	
1	Ceiling - Plaster/Drywall	2nd flr men's west of library next to 221A	138	SF	6	\$478	
	Doors - Transom Window	2nd flr men's west of library next to 221A	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd flr men's west of library next to 221A	1	EA	6	\$301	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Floor Drain	2nd flr men's west of library next to 221A	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd flr men's west of library next to 221A	138	SF	6	\$292	
	Lavatory	2nd flr men's west of library next to 221A	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd flr men's west of library next to 221A	1	EA	6	\$124	
	Partitions	2nd flr men's west of library next to 221A	1	EA	6	\$297	
	Urinals	2nd flr men's west of library next to 221A	1	EA	5	\$1,344	Does not work
	Walls - Plaster/Drywall	2nd flr men's west of library next to 221A	575	SF	6	\$1,587	
	Walls - Plaster/Drywall	2nd flr men's west of library next to 221A	5	SF	5	\$26	Peel paint
	Water Closet	2nd flr men's west of library next to 221A	1	EA	6	\$336	
	Accessories	2nd flr Womens Staff across from library	324	SF	6	\$2,988	
	Ceiling - Plaster/Drywall	2nd flr Womens Staff across from library	322	SF	6	\$1,114	
	Ceiling - Plaster/Drywall	2nd flr Womens Staff across from library	6	SF	5	\$75	Peeling paint
	Doors - Wood Doors inclu hw	2nd flr Womens Staff across from library	1	EA	6	\$301	
	Floor Drain	2nd flr Womens Staff across from library	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd flr Womens Staff across from library	328	SF	6	\$694	
	Hand Dryer	2nd flr Womens Staff across from library	1	EA	5	\$590	
	Lavatory	2nd flr Womens Staff across from library	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd flr Womens Staff across from library	5	EA	6	\$619	
	Partitions	2nd flr Womens Staff across from library	2	EA	6	\$594	
	Walls - Plaster/Drywall	2nd flr Womens Staff across from library	1,048	SF	6	\$2,892	
	Water Closet	2nd flr Womens Staff across from library	2	EA	6	\$672	
	Accessories	3rd floor Boy's next to 321	338	SF	6	\$3,118	
	Ceiling - Plaster/Drywall	3rd floor Boy's next to 321	338	SF	6	\$1,170	
	Doors - Wood Doors inclu hw	3rd floor Boy's next to 321	1	EA	6	\$301	
	Floor Drain	3rd floor Boy's next to 321	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd floor Boy's next to 321	338	SF	6	\$715	
	Hand Dryer	3rd floor Boy's next to 321	2	EA	6	\$460	
	Lavatory	3rd floor Boy's next to 321	3	EA	6	\$959	
	Lighting - Pendent/Surface	3rd floor Boy's next to 321	5	EA	6	\$619	
	Partitions	3rd floor Boy's next to 321	3	EA	6	\$891	
	Urinals	3rd floor Boy's next to 321	5	EA	6	\$1,680	
	Walls - Structural Glazed Tile	3rd floor Boy's next to 321	846	SF	6	\$2,662	
	Water Closet	3rd floor Boy's next to 321	3	EA	6	\$1,008	
	Accessories	3rd floor Boy's next to 339	338	SF	6	\$3,118	
	Ceiling - Plaster/Drywall	3rd floor Boy's next to 339	338	SF	6	\$1,170	
	Doors - Wood Doors inclu hw	3rd floor Boy's next to 339	1	EA	6	\$301	
	Floor Drain	3rd floor Boy's next to 339	1	EA	6	\$1,059	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Floor - Tile Ceramic/ Porcelain	3rd floor Boy's next to 339	338	SF	6	\$715	
	Hand Dryer	3rd floor Boy's next to 339	2	EA	6	\$460	
	Lavatory	3rd floor Boy's next to 339	3	EA	6	\$959	
	Lighting - Pendent/Surface	3rd floor Boy's next to 339	5	EA	6	\$619	
	Partitions	3rd floor Boy's next to 339	3	EA	6	\$891	
	Urinals	3rd floor Boy's next to 339	4	EA	6	\$1,344	
	Walls - Structural Glazed Tile	3rd floor Boy's next to 339	846	SF	6	\$2,662	
	Water Closet	3rd floor Boy's next to 339	3	EA	6	\$1,008	
	Accessories	3rd Floor E end Men's Facility across from 326	140	SF	6	\$1,291	
	Ceiling - Plaster/Drywall	3rd Floor E end Men's Facility across from 326	140	SF	6	\$484	
	Doors - Transom Window	3rd Floor E end Men's Facility across from 326	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor E end Men's Facility across from 326	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	3rd Floor E end Men's Facility across from 326	140	SF	6	\$296	
	Lavatory	3rd Floor E end Men's Facility across from 326	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd Floor E end Men's Facility across from 326	1	EA	6	\$124	
	Partitions	3rd Floor E end Men's Facility across from 326	1	EA	6	\$297	
	Urinals	3rd Floor E end Men's Facility across from 326	1	EA	6	\$336	
	Walls - Plaster/Drywall	3rd Floor E end Men's Facility across from 326	498	SF	6	\$1,374	
	Walls - Plaster/Drywall	3rd Floor E end Men's Facility across from 326	2	SF	5	\$10	Cracks and peeling paint
	Water Closet	3rd Floor E end Men's Facility across from 326	1	EA	6	\$336	
	Accessories	3rd floor NE end Girl's next to 332	322	SF	6	\$2,970	
	Ceiling - Plaster/Drywall	3rd floor NE end Girl's next to 332	322	SF	6	\$1,114	
	Doors - Wood Doors inclu hw	3rd floor NE end Girl's next to 332	2	EA	6	\$602	
	Floor Drain	3rd floor NE end Girl's next to 332	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd floor NE end Girl's next to 332	322	SF	6	\$681	
	Hand Dryer	3rd floor NE end Girl's next to 332	2	EA	6	\$460	
	Lavatory	3rd floor NE end Girl's next to 332	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd floor NE end Girl's next to 332	5	EA	6	\$619	
	Partitions	3rd floor NE end Girl's next to 332	6	EA	6	\$1,782	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Walls - Plaster/Drywall	3rd floor NE end Girl's next to 332	251	SF	6	\$693	
	Walls - Structural Glazed Tile	3rd floor NE end Girl's next to 332	737	SF	6	\$2,319	Missing tile
	Water Closet	3rd floor NE end Girl's next to 332	6	EA	6	\$2,016	
	Ceiling - Plaster/Drywall	3rd floor North balcony for Gym	142	SF	5	\$1,302	Damaged plaster
	Doors - Wood Doors inclu hw	3rd floor North balcony for Gym	1	EA	5	\$1,174	
	Floor Drain	3rd floor North balcony for Gym	1	EA	5	\$2,094	
	Floor - Tile Ceramic/ Porcelain	3rd floor North balcony for Gym	142	SF	6	\$301	
	Lavatory	3rd floor North balcony for Gym	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd floor North balcony for Gym	2	EA	5	\$365	Does not work
	Partitions	3rd floor North balcony for Gym	2	EA	6	\$594	
	Urinals	3rd floor North balcony for Gym	2	EA	6	\$672	
	Walls - Plaster/Drywall	3rd floor North balcony for Gym	220	SF	6	\$607	
	Walls - Tile Ceramic/ Porcelain	3rd floor North balcony for Gym	543	SF	6	\$1,227	
	Water Closet	3rd floor North balcony for Gym	2	EA	5	\$2,688	Does not work
	Accessories	3rd Flr East end women's across from 344	195	SF	6	\$1,799	
	Ceiling - Plaster/Drywall	3rd Flr East end women's across from 344	195	SF	5	\$1,787	
	Doors - Wood Doors inclu hw	3rd Flr East end women's across from 344	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	3rd Flr East end women's across from 344	195	SF	6	\$413	
	Lavatory	3rd Flr East end women's across from 344	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd Flr East end women's across from 344	2	EA	6	\$248	
	Partitions	3rd Flr East end women's across from 344	2	EA	6	\$594	
	Walls - Plaster/Drywall	3rd Flr East end women's across from 344	130	SF	6	\$359	
	Walls - Structural Glazed Tile	3rd Flr East end women's across from 344	575	SF	6	\$1,809	
	Water Closet	3rd Flr East end women's across from 344	2	EA	6	\$672	
	Accessories	3rd Flr NE end Women's Faculty next to exit #5	322	SF	6	\$2,970	
	Benches	3rd FIr NE end Women's Faculty next to exit #5	6	LF	6	\$87	
	Ceiling - Plaster/Drywall	3rd FIr NE end Women's Faculty next to exit #5	322	SF	6	\$1,114	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo							
	Doors - Transom Window	3rd FIr NE end Women's Faculty next to exit #5	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd FIr NE end Women's Faculty next to exit #5	1	EA	6	\$301	
	Floor Drain	3rd FIr NE end Women's Faculty next to exit #5	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd FIr NE end Women's Faculty next to exit #5	322	SF	6	\$681	
	Hand Dryer	3rd FIr NE end Women's Faculty next to exit #5	1	EA	6	\$230	
	Lavatory	3rd FIr NE end Women's Faculty next to exit #5	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd FIr NE end Women's Faculty next to exit #5	5	EA	7	\$0	
	Partitions	3rd FIr NE end Women's Faculty next to exit #5	2	EA	6	\$594	
	Student Lockers - One Tier	3rd FIr NE end Women's Faculty next to exit #5	1	EA	6	\$93	
	Walls - Plaster/Drywall	3rd FIr NE end Women's Faculty next to exit #5	818	SF	6	\$2,258	
	Water Closet	3rd FIr NE end Women's Faculty next to exit #5	2	EA	6	\$672	
	Accessories	Basement rec room north	113	SF	6	\$1,042	
	Ceiling - Exposed	Basement rec room north	113	SF	6	\$168	
	Doors - Wood Doors inclu hw	Basement rec room north	1	EA	6	\$301	
	Floor - Tile/Sheet	Basement rec room north	113	SF	6	\$113	
	Lavatory	Basement rec room north	1	EA	6	\$320	
	Lighting - Pendent/Surface	Basement rec room north	1	EA	6	\$124	
	Partitions	Basement rec room north	1	EA	6	\$297	
	Walls - Concrete Block	Basement rec room north	500	SF	6	\$1,466	
	Water Closet	Basement rec room north	1	EA	6	\$336	
	Accessories	Basement rec room- south	152	SF	6	\$1,402	
	Ceiling - Exposed	Basement rec room- south	152	SF	6	\$226	
	Floor - Tile Ceramic/ Porcelain	Basement rec room- south	152	SF	6	\$322	
	Lavatory	Basement rec room- south	1	EA	6	\$320	
	Lighting - Pendent/Surface	Basement rec room- south	1	EA	6	\$124	
	Partitions	Basement rec room- south	1	EA	6	\$297	
	Walls - Concrete Block	Basement rec room- south	550	SF	6	\$1,612	
	Water Closet	Basement rec room- south	1	EA	6	\$336	
	Accessories	Girls room 1st floor	331	SF	6	\$3,053	



roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
estroom						
Ceiling - Lay-in	Girls room 1st floor	331	SF	6	\$994	
Doors - Wood Doors inclu hw	Girls room 1st floor	1	EA	6	\$301	
Floor Drain	Girls room 1st floor	2	EA	6	\$2,118	
Floor - Tile Ceramic/ Porcelain	Girls room 1st floor	331	SF	6	\$701	
Hand Dryer	Girls room 1st floor	2	EA	6	\$460	
Lavatory	Girls room 1st floor	2	EA	6	\$639	
Lighting - Pendent/Surface	Girls room 1st floor	4	EA	6	\$496	
Partitions	Girls room 1st floor	6	EA	6	\$1,782	
Walls - Structural Glazed Tile	Girls room 1st floor	826	SF	6	\$2,599	
Water Closet	Girls room 1st floor	7	EA	6	\$2,352	
Accessories	In main office	45	SF	6	\$415	
Ceiling - Plaster/Drywall	In main office	45	SF	6	\$156	
Doors - Wood Doors inclu hw	In main office	1	EA	6	\$301	
Floor - Tile Ceramic/ Porcelain	In main office	45	SF	6	\$95	
Lavatory	In main office	1	EA	6	\$320	
Lighting - Pendent/Surface	In main office	1	EA	6	\$124	
Walls - Plaster/Drywall	In main office	225	SF	6	\$621	
Water Closet	In main office	1	EA	6	\$336	
Accessories	In swimming pool area	134	SF	6	\$1,236	
Ceiling - Plaster/Drywall	In swimming pool area	134	SF	6	\$464	
Doors - Wood Doors inclu hw	In swimming pool area	1	EA	6	\$301	
Floor Drain	In swimming pool area	1	EA	6	\$1,059	
Floor - Tile Ceramic/ Porcelain	In swimming pool area	134	SF	6	\$284	
Lavatory	In swimming pool area	1	EA	6	\$320	
Lighting - Pendent/Surface	In swimming pool area	3	EA	6	\$372	
Showers	In swimming pool area	1	EA	6	\$311	
Student Lockers - One Tier	In swimming pool area	5	EA	6	\$464	
Walls - Structural Glazed Tile	In swimming pool area	385	SF	6	\$1,211	
Water Closet	In swimming pool area	1	EA	6	\$336	
Accessories	Men's room in auditorium	116	SF	6	\$1,070	
Ceiling - Plaster/Drywall	Men's room in auditorium	116	SF	6	\$401	
Doors - Wood Doors inclu hw	Men's room in auditorium	1	EA	6	\$301	
Floor Drain	Men's room in auditorium	1	EA	6	\$1,059	
Floor - Tile Ceramic/ Porcelain	Men's room in auditorium	116	SF	6	\$246	
Lavatory	Men's room in auditorium	2	EA	6	\$639	
Lighting - Pendent/Surface	Men's room in auditorium	2	EA	6	\$248	
Partitions	Men's room in auditorium	1	EA	6	\$297	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	m						
	Urinals	Men's room in auditorium	2	EA	6	\$672	
	Walls - Plaster/Drywall	Men's room in auditorium	320	SF	6	\$883	
	Water Closet	Men's room in auditorium	1	EA	6	\$336	
	Accessories	Staff restroom in room 143	111	SF	6	\$1,024	
	Ceiling - Plaster/Drywall	Staff restroom in room 143	111	SF	6	\$384	
	Doors - Wood Doors inclu hw	Staff restroom in room 143	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Staff restroom in room 143	111	SF	6	\$235	
	Lavatory	Staff restroom in room 143	1	EA	6	\$320	
	Lighting - Pendent/Surface	Staff restroom in room 143	1	EA	6	\$124	
	Student Lockers - One Tier	Staff restroom in room 143	4	EA	6	\$371	
	Urinals	Staff restroom in room 143	1	EA	6	\$336	
	Walls - Plaster/Drywall	Staff restroom in room 143	347	SF	6	\$958	
	Water Closet	Staff restroom in room 143	1	EA	6	\$336	
	Accessories	Staff restroom in room 241A	141	SF	6	\$1,301	
	Ceiling - Plaster/Drywall	Staff restroom in room 241A	140	SF	6	\$484	
	Ceiling - Plaster/Drywall	Staff restroom in room 241A	1	SF	5	\$12	Peeling plaster
	Doors - Wood Doors inclu hw	Staff restroom in room 241A	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Staff restroom in room 241A	141	SF	6	\$298	
	Hand Dryer	Staff restroom in room 241A	1	EA	6	\$230	
	Lavatory	Staff restroom in room 241A	1	EA	6	\$320	
	Lighting - Pendent/Surface	Staff restroom in room 241A	1	EA	6	\$124	
	Partitions	Staff restroom in room 241A	1	EA	6	\$297	
	Walls - Plaster/Drywall	Staff restroom in room 241A	459	SF	6	\$1,267	
	Walls - Tile Ceramic/ Porcelain	Staff restroom in room 241A	90	SF	6	\$203	
	Water Closet	Staff restroom in room 241A	1	EA	6	\$336	
	Accessories	Staff restroom in room 339A	100	SF	6	\$922	
	Ceiling - Plaster/Drywall	Staff restroom in room 339A	100	SF	5	\$917	Peeling paint
	Doors - Wood Doors inclu hw	Staff restroom in room 339A	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Staff restroom in room 339A	100	SF	6	\$212	
	Lavatory	Staff restroom in room 339A	1	EA	6	\$320	
	Lighting - Pendent/Surface	Staff restroom in room 339A	1	EA	7	\$0	
	Partitions	Staff restroom in room 339A	1	EA	6	\$297	
	Urinals	Staff restroom in room 339A	1	EA	6	\$336	
	Walls - Plaster/Drywall	Staff restroom in room 339A	418	SF	6	\$1,154	
	Walls - Plaster/Drywall	Staff restroom in room 339A	2	SF	5	\$10	Peeling paint
	Water Closet	Staff restroom in room 339A	1	EA	6	\$336	
	Accessories	Toilet in 246 Gym Office	90	SF	6	\$830	



Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	m						
	Ceiling - Plaster/Drywall	Toilet in 246 Gym Office	90	SF	6	\$311	
	Doors - Transom Window	Toilet in 246 Gym Office	8	SF	6	\$135	Wood panel
	Doors - Wood Doors inclu hw	Toilet in 246 Gym Office	1	EA	6	\$301	
	Floor Drain	Toilet in 246 Gym Office	1	EA	6	\$1,059	
	Floor - Tile	Toilet in 246 Gym Office	90	SF	6	\$197	
	Lavatory	Toilet in 246 Gym Office	1	EA	6	\$320	
	Lighting - Pendent/Surface	Toilet in 246 Gym Office	1	EA	6	\$124	
	Partitions	Toilet in 246 Gym Office	1	EA	6	\$297	
	Showers	Toilet in 246 Gym Office	1	EA	6	\$311	
	Walls - Plaster/Drywall	Toilet in 246 Gym Office	475	SF	6	\$1,311	
	Water Closet	Toilet in 246 Gym Office	1	EA	5	\$1,344	Does not work
	Accessories	Women's room in auditorium	116	SF	6	\$1,070	
	Ceiling - Plaster/Drywall	Women's room in auditorium	116	SF	6	\$401	
	Doors - Wood Doors inclu hw	Women's room in auditorium	1	EA	6	\$301	
	Floor Drain	Women's room in auditorium	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Women's room in auditorium	116	SF	6	\$246	
	Lavatory	Women's room in auditorium	2	EA	6	\$639	
	Lighting - Pendent/Surface	Women's room in auditorium	2	EA	6	\$248	
	Partitions	Women's room in auditorium	1	EA	6	\$297	
	Walls - Plaster/Drywall	Women's room in auditorium	465	SF	6	\$1,283	
	Water Closet	Women's room in auditorium	2	EA	6	\$672	

Rooms (Other Than Classrooms) Subtotal:

\$1,946,187

Building: Main

Category: Building Interior

roup Ite	m - Type	Location	Quantity	Unit	Rank	Cost	Comments
orridor							
Ce	iling - Lay-in	1st Floor	8	SF	5	\$71	Damaged ceiling tiles
Ce	iling - Lay-in	1st Floor	19,830	SF	6	\$59,549	
Ce	iling - Plaster/Drywall	1st Floor	198	SF	6	\$1,226	
Dri	inking Fountains - Double Water Cooler	1st Floor	6	EA	6	\$2,262	
Dri	inking Fountains - Single Fountain	1st Floor	2	EA	5	\$2,360	Does not work
Flo	por - Terrazzo	1st Floor	4,915	SF	7	\$0	
Flo	por - Tile/Sheet	1st Floor	8	SF	5	\$46	Damaged floor tiles
Flo	por - Tile/Sheet	1st Floor	17,630	SF	6	\$9,580	
Lig	yhting - Lay-in	1st Floor	128	EA	6	\$15,229	



Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	pr						
	Lighting - Pendent/Surface	1st Floor	2	EA	7	\$0	
	Student Lockers - One Tier	1st Floor	1,276	EA	6	\$118,458	
	Walls - Plaster/Drywall	1st Floor	13,120	SF	6	\$58,161	
	Walls - Structural Glazed Tile	1st Floor	15,320	SF	6	\$48,197	
	Ceiling - Lay-in	2nd Floor	17,638	SF	6	\$52,967	
	Ceiling - Plaster/Drywall	2nd Floor	98	SF	6	\$607	
	Ceiling - Splined	2nd Floor	1,408	SF	6	\$4,067	
	Drinking Fountains - Double Water Cooler	2nd Floor	3	EA	6	\$1,131	
	Drinking Fountains - Double Water Cooler	2nd Floor	1	EA	5	\$4,515	Does not work
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	6	\$276	
	Floor - Tile/Sheet	2nd Floor	8	SF	5	\$46	Damaged floor tiles
	Floor - Tile/Sheet	2nd Floor	17,630	SF	6	\$9,580	
	Lighting - Lay-in	2nd Floor	68	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	\$248	
	Student Lockers - One Tier	2nd Floor	1,200	EA	6	\$111,403	
	Walls - Plaster/Drywall	2nd Floor	15,320	SF	6	\$67,914	
	Walls - Structural Glazed Tile	2nd Floor	13,120	SF	6	\$41,276	
	Ceiling - Lay-in	3rd Floor	17,638	SF	6	\$52,967	
	Ceiling - Plaster/Drywall	3rd Floor	98	SF	6	\$607	
	Ceiling - Splined	3rd Floor	1,400	SF	6	\$4,044	
	Ceiling - Splined	3rd Floor	8	SF	6	\$32	Missing tiles
	Drinking Fountains - Double Water Cooler	3rd Floor	4	EA	6	\$1,508	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	6	\$317	
	Floor - Tile/Sheet	3rd Floor	3	SF	5	\$17	Missing tiles
	Floor - Tile/Sheet	3rd Floor	17,635	SF	6	\$9,583	
	Lighting - Lay-in	3rd Floor	48	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	2	EA	6	\$248	
	Student Lockers - One Tier	3rd Floor	1,200	EA	6	\$111,403	
	Walls - Plaster/Drywall	3rd Floor	15,320	SF	6	\$67,914	
	Walls - Structural Glazed Tile	3rd Floor	13,120	SF	6	\$41,276	
Safety							
	Camera Viewing Station	Entire Building / 1st Floor	4	EA	6	\$2,730	
	Metal Dedector	Entire Building / 1st Floor	3	EA	6	\$2,642	
	Security Cameras	Entire Building	30	EA	6	\$5,821	
	Security Cameras	Entire Building	7	EA	7	\$0	
	•	- 5					



Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Ceiling - Plaster/Drywall	Stair by 128	281	SF	6	\$2,057	
	Floor - Terrazzo	Stair by 128	281	SF	7	\$0	
	Handrails	Stair by 128	96	LF	6	\$832	
	Lighting - Pendent/Surface	Stair by 128	4	EA	6	\$496	
	Stairs - Terrazzo	Stair by 128	48	LF	7	\$0	
	Walls - Structural Glazed Tile	Stair by 128	2,736	SF	6	\$8,607	
	Ceiling - Plaster/Drywall	Stair by 134	281	SF	6	\$2,057	
	Floor - Terrazzo	Stair by 134	281	SF	7	\$0	
	Handrails	Stair by 134	96	LF	6	\$832	
	Lighting - Pendent/Surface	Stair by 134	4	EA	6	\$496	
	Stairs - Terrazzo	Stair by 134	48	LF	7	\$0	
	Walls - Structural Glazed Tile	Stair by 134	2,736	SF	6	\$8,607	
	Ceiling - Plaster/Drywall	Stair by Assembly Hall	506	SF	6	\$3,705	
	Floor - Terrazzo	Stair by Assembly Hall	506	SF	7	\$0	
	Handrails	Stair by Assembly Hall	96	LF	6	\$832	
	Lighting - Pendent/Surface	Stair by Assembly Hall	2	EA	6	\$248	
	Stairs - Terrazzo	Stair by Assembly Hall	50	LF	7	\$0	
	Walls - Structural Glazed Tile	Stair by Assembly Hall	4,320	SF	6	\$13,591	
	Ceiling - Plaster/Drywall	Stair by room 123	350	SF	6	\$2,563	
	Floor - Terrazzo	Stair by room 123	350	SF	7	\$0	
	Handrails	Stair by room 123	96	LF	6	\$832	
	Lighting - Pendent/Surface	Stair by room 123	4	EA	6	\$496	
	Stairs - Terrazzo	Stair by room 123	48	LF	7	\$0	
	Walls - Structural Glazed Tile	Stair by room 123	3,240	SF	6	\$10,193	
	Ceiling - Plaster/Drywall	Stair by room 141	350	SF	6	\$2,563	
	Floor - Terrazzo	Stair by room 141	350	SF	7	\$0	
	Handrails	Stair by room 141	96	LF	6	\$832	
	Lighting - Pendent/Surface	Stair by room 141	4	EA	6	\$496	
	Stairs - Terrazzo	Stair by room 141	48	LF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	Stair by room 141	3,240	SF	6	\$10,193	
	Ceiling - Plaster/Drywall	Stair by room 144	329	SF	6	\$2,409	
	Floor - Terrazzo	Stair by room 144	329	SF	7	\$0	
	Handrails	Stair by room 144	96	LF	6	\$832	
	Lighting - Pendent/Surface	Stair by room 144	4	EA	6	\$496	
	Stairs - Terrazzo	Stair by room 144	48	LF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	Stair by room 144	3,240	SF	6	\$10,193	



Category: Building Interior Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments	
Vertical Conveyance			•			••••••	
Elevator - Hydraulic Elevator	1st Floor	1	EA	6	\$19,238		
Building Interior Subtotal:				\$1	I,013,968		
Total Building Cost				\$11	1,463,477		

Building: Addition 1

Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance						
Entrance Control - Audio and Video	#1 W	1	EA	6	\$702	
Exterior Doors - Exterior Wood Door	#2 W	1	EA	4	\$3,823	Damaged
Exterior Doors - Store Front	#1 W	1	EA	6	\$546	
Exterior Doors - Store Front	#3 W	2	EA	6	\$1,092	
Exterior Doors - Transom Lite	#1 W	2	EA	6	\$627	
Exterior Doors - Transom Lite	#3 W	2	EA	6	\$627	
Exterior Stairs - Concrete	#3 W	18	LF	6	\$1,472	
Power Door Operator and Controls	#1 W	1	EA	6	\$0	
Foundation						
Foundation - Concrete	Entire Building	1,546	LF	7	\$0	
Superstructure - Concrete	Entire Building	64,000	SF	7	\$0	
ighting						
Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
Roof System						
Coping - Stone	Main Roof	1,796	LF	6	\$57,684	
Downspouts - Interior Downspouts	Main Roof	280	LF	6	\$9,305	
Parapet - 16" - 30" Height	Main Roof	898	LF	6	\$35,879	
Parapet - Parapet > 30"	Main Roof	898	LF	6	\$57,401	
Roof Structure - Concrete	Main Roof	45,273	SF	7	\$0	
Roof - Asphalt Gravel Ballast	Main Roof	45,273	SF	6	\$460,304	
Nalls						
Exterior Walls - Brick	Entire Building	52,066	SF	6	\$349,936	
Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	5,658	SF	6	\$32,121	
Exterior Walls - Stone-Cast	Entire Building	8,176	SF	6	\$54,951	



Building: Addition 1

Category: Building Exterior

pup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ndows						
Guard - Guards wire guard	Entire Building / 1st Floor	360	SF	6	\$4,597	
Lintels - Steel	Entire Building	688	LF	7	\$0	
Windows - Casement Aluminum Double-pane	Entire Building	2,430	SF	6	\$18,139	
Windows - Casement Aluminum Double-pane	Entire Building	2,430	SF	5	\$130,899	Not operating well
Windows - Sash Aluminum Double-pane	Entire Building	698	SF	5	\$37,600	Not operating well
Windows - Sash Aluminum Double-pane	Entire Building	698	SF	6	\$5,210	
ilding Exterior Subtotal:				\$	1,264,358	

Building: Addition 1

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	Emergency A/C Power - Corridors and Stairs	Entire Building	18,200	SF	6	\$5,465	
	Emergency A/C Power - Lunchrooms	Entire Building / 1st Floor	2,795	SF	6	\$1,039	
	Emergency A/C Power - Students Toilets	Entire Building	1,462	SF	6	\$544	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	45	EA	6	\$9,113	
	Exit Signs - Corridors and Stairs	1st floor, Entire Building / Entire Building	24	EA	7	\$0	
	Exit Signs - Lunchroom	1st floor, Entire Building / 1st Floor	4	EA	7	\$0	Culinary Arts cafeteria
	Security System - CCTV	Entire Building	64,000	SF	6	\$19,219	
	Security System - Intrusion Detection	Entire Building	64,000	SF	6	\$16,474	
Main Se	rvice						
	PA System	Entire Building	64,000	SF	5	\$43,930	PA system is not connected with Main service. Control console located in Main.
Power D	listribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	\$4,849	Emergency fuse panel has over 40 years of service and is significantly deteriorated.
	Lighting and Power Panels - 100 A	Entire Building	5	EA	4	\$24,247	Panela have over 40 years of service and are significantly deteriorated.
	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	4	\$65,778	Panela have over 40 years of service and are significantly deteriorated.
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	18	EA	7	\$0	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	\$3,021	



roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lectrical System Subtotal:					\$193,679	
uilding: Addition 1						
ategory: Safty System						
roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ire Alarm						
Fire Alarm Strobe Lights	Entire Building	64,000	SF	6	\$22,880	
Fire Alarm_System	Entire Building	64,000	SF	6	\$31,117	Panel located in Main.
afty System Subtotal:					\$53,997	
uilding: Addition 1						
ategory: Mechanical System						
roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ir Conditioning						
Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	\$3,334	
Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	4	\$11,133	Condenser is not working, in poor condition an
Condensing Unit- Roof Mounted - Less than 5 tons		1	EA	4	\$11,133	Condenser is not working, in poor condition at not cost effective for repairs.
Condensing Unit- Roof Mounted - Less than 5 tons	Roof					
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Roof Attic	1	EA	7	\$0	not cost effective for repairs.
Condensing Unit- Roof Mounted - Less than 5 tons	Roof Attic				\$0	
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self	Roof Attic Roof	1	EA	7	\$0 \$0	not cost effective for repairs.
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - 10,001 - 20,000 cfm Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling	Roof Attic Roof Roof	1	EA EA	7 7	\$0 \$0	not cost effective for repairs. MAU-1
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - 10,001 - 20,000 cfm Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling	Roof Attic Roof Roof	1 1 6	EA EA EA	7 7 7	\$0 \$0 \$0 \$0	not cost effective for repairs. MAU-1 RTU-1, -2, -3, -4, -5, -10
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - 10,001 - 20,000 cfm Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling	Roof Attic Roof Roof Roof	1 1 6 1	EA EA EA	7 7 7 7	\$0 \$0 \$0 \$0 \$0	not cost effective for repairs. MAU-1 RTU-1, -2, -3, -4, -5, -10 RTU-7
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - 10,001 - 20,000 cfm Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling	Roof Attic Roof Roof Roof	1 1 6 1 1	EA EA EA EA	7 7 7 7 7 7	\$0 \$0 \$0 \$0 \$0	not cost effective for repairs. MAU-1 RTU-1, -2, -3, -4, -5, -10 RTU-7 RTU-6
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - 10,001 - 20,000 cfm Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Roof Attic Roof Roof Roof	1 1 6 1 1	EA EA EA EA	7 7 7 7 7 7	\$0 \$0 \$0 \$0 \$0	not cost effective for repairs. MAU-1 RTU-1, -2, -3, -4, -5, -10 RTU-7 RTU-6
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - 10,001 - 20,000 cfm Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Roof Attic Roof Roof Roof	1 1 6 1 1 1	EA EA EA EA EA	7 7 7 7 7 7 7	\$0 \$0 \$0 \$0 \$0 \$0 \$0	not cost effective for repairs. MAU-1 RTU-1, -2, -3, -4, -5, -10 RTU-7 RTU-6
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - 10,001 - 20,000 cfm Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Roof Attic Roof Roof Roof Roof Entire Building	1 1 6 1 1 1 1	EA EA EA EA EA	7 7 7 7 7 7 7 7	\$0 \$0 \$0 \$0 \$0 \$0 \$0	not cost effective for repairs. MAU-1 RTU-1, -2, -3, -4, -5, -10 RTU-7 RTU-6
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - 10,001 - 20,000 cfm Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Reating Devices Cabinet Heaters - With Hot Water Coil Fin Tube - Electric	Roof Attic Roof Roof Roof Roof Roof Roof Roof Entire Building Entire Building Entire Building	1 1 6 1 1 1 1 2 15	EA EA EA EA EA EA LF	7 7 7 7 7 7 7 7 7	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	not cost effective for repairs. MAU-1 RTU-1, -2, -3, -4, -5, -10 RTU-7 RTU-6
Condensing Unit- Roof Mounted - Less than 5 tons ir Handling Systems Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - 10,001 - 20,000 cfm Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating And DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating And DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating And DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating And DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof M	Roof Attic Roof Roof Roof Roof Roof Roof Roof Roo	1 1 1 1 1 1 1 2 15 420	EA EA EA EA EA EA LF LF	7 7 7 7 7 7 7 7 7 7 7	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	not cost effective for repairs. MAU-1 RTU-1, -2, -3, -4, -5, -10 RTU-7 RTU-6



Building: Addition 1

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechan	ical Plumbing						
	Hydronic Supply and Return - Galvanized	Entire Building	300	LF	7	\$0	
Temper	ature Control						
	DDC System	Entire Building	64,000	SF	7	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	27	EA	7	\$0	
	Thermostats - DDC	Entire Building	46	EA	7	\$0	
Ventilat	ion						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building / Attic	1	EA	7	\$0	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	3	EA	7	\$0	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building / Roof	1	EA	7	\$0	
	Lab Exhaust Hood	Entire Building / 2nd Floor	1	EA	5	\$2,950	Sash is damaged and off center. Stops appear to be non-functional.
	Roof Mounted Duct Work	Entire Building / Roof	250	LF	7	\$0	
	Type I Exhaust Hood- Culinary Arts	Entire Building / 1st Floor	1	EA	7	\$0	
	Type II Exhaust Hood- Warming Kitchen	Entire Building / 1st Floor	1	EA	7	\$0	

Mechanical System Subtotal:

\$18,010

Building: Addition 1

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lot Wat	er						
	Electric Heater - 20 - 50 KW	Basement	1	EA	6	\$682	Serves cosmetology shop. Operational but past useful life. Consider replacement.
piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	64,000	SF	6	\$12,813	Piping is old and deteriorated.
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	12,800	SF	7	\$0	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	51,200	SF	6	\$12,447	Piping is old and deteriorated.
	Domestic Piping-Cold Water Risers	Entire Building	64,000	SF	6	\$11,898	Piping is old and deteriorated.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	64,000	SF	6	\$10,067	Piping is old and deteriorated.
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	12,800	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	51,200	SF	6	\$9,518	Piping is old and deteriorated.
	Domestic Piping-Hot Water Return Lines	Entire Building	64,000	SF	6	\$9,152	Piping is old and deteriorated.
	Domestic Piping-Hot Water Return Risers	Entire Building	64,000	SF	6	\$9,152	Piping is old and deteriorated.



Building: Addition 1

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water Return Risers	Entire Building	64,000	SF	6	\$9,152	Piping is old and deteriorated.
	Sanitary Piping	Entire Building	64,000	SF	6	\$58,573	Piping is old and deteriorated.
	Storm Piping	Entire Building	64,000	SF	6	\$55,827	
	Vent Piping	Entire Building	64,000	SF	6	\$43,014	
Pumps							
	Pumps - Sump-Duplex	Basement	1	EA	6	\$1,387	
Plum	bing System Subtotal:				:	\$243,682	

Building: Addition 1

Category: Classrooms

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assroom #101 (Regular Classroom)						
AC Units	1st Floor	1	EA	4	\$6,086	Not working
Casework	1st Floor	10	LF	6	\$253	
Ceiling - Lay-in	1st Floor	647	SF	6	\$1,943	
Doors - Transom Window	1st Floor	8	SF	6	\$135	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Wood	1st Floor	647	SF	6	\$4,561	
Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
Walls - Plaster/Drywall	1st Floor	996	SF	6	\$2,749	
assroom #102 (Regular Classroom)						
AC Units	1st Floor	1	EA	4	\$6,086	Not working
Casework	1st Floor	10	LF	6	\$253	
Ceiling - Lay-in	1st Floor	647	SF	6	\$1,943	
Doors - Transom Window	1st Floor	8	SF	6	\$135	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Wood	1st Floor	647	SF	6	\$4,561	
Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
Walls - Plaster/Drywall	1st Floor	996	SF	6	\$2,749	
assroom #103A (Regular Classroom)						
Ceiling - Lay-in	1st Floor	843	SF	6	\$2,532	
Doors - Transom Window	1st Floor	8	SF	6	\$135	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	843	SF	6	\$844	

Category:	Classrooms
-----------	------------

Item - Type	Location	Quantity	Unit	Rank	Cost	Comment
oom #103A (Regular Classroom)						
Lighting - Lay-in	1st Floor	15	EA	6	\$1,785	
Marker Board	1st Floor	24	LF	6	\$514	
Walls - Masonry	1st Floor	550	SF	6	\$1,730	
Walls - Plaster/Drywall	1st Floor	556	SF	6	\$1,535	
oom #103B (Regular Classroom)						
Ceiling - Lay-in	1st Floor	843	SF	6	\$2,532	
Doors - Transom Window	1st Floor	8	SF	6	\$135	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	843	SF	6	\$844	
Lighting - Lay-in	1st Floor	15	EA	6	\$1,785	
Marker Board	1st Floor	24	LF	6	\$514	
Walls - Masonry	1st Floor	550	SF	6	\$1,730	
Walls - Plaster/Drywall	1st Floor	556	SF	6	\$1,535	
oom #104 cosmotology (Other Instructional Use)	1					
AC Units	1st Floor	5	EA	4	\$30,431	Not working
Ceiling - Lay-in	1st Floor	2,794	SF	6	\$8,390	
Cosmetology Station	1st Floor	42	EA	6	\$30,389	
Doors - Transom Window	1st Floor	16	SF	6	\$271	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
Floor - Tile/Sheet	1st Floor	2,794	SF	6	\$2,797	
Lighting - Lay-in	1st Floor	46	EA	6	\$5,473	
Walls - Masonry	1st Floor	1,741	SF	6	\$5,477	
Work Sink	1st Floor	6	EA	6	\$2,274	
room #105 (Regular Classroom)						
Casework	1st Floor	25	LF	6	\$631	
Ceiling - Exposed	1st Floor	2,803	SF	6	\$4,169	
Doors - Transom Window	1st Floor	8	SF	6	\$135	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	2,803	SF	6	\$2,806	
Lighting - Pendent/Surface	1st Floor	56	EA	6	\$6,938	
Marker Board	1st Floor	10	LF	6	\$214	
Walls - Masonry	1st Floor	1,741	SF	6	\$5,477	
Work Sink	1st Floor	1	EA	6	\$379	
oom #106 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	2,795	SF	6	\$8,393	

Category:	Classrooms
-----------	------------

Group	Itom - Typo	Location	Quantity	Unit	Dank	Cast	Commonts
-	Item - Type	Location	Quantity	Unit	Rank	COST	Comments
Classroo	om #106 (Regular Classroom)			05	0	M405	
	Doors - Transom Window	1st Floor	8	SF	6	\$135 \$204	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	2,795	SF	6	\$2,798	
	Lighting - Lay-in	1st Floor	46	EA	6	\$5,473	
	Walls - Masonry	1st Floor	1,741	SF	6	\$5,477	
	Work Sink	1st Floor	4	EA	6	\$1,516	
Classroo	om #107 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	650	SF	6	\$1,952	
	Chalk Board	1st Floor	13	LF	4	\$1,193	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	650	SF	6	\$4,582	
	Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	1st Floor	996	SF	6	\$2,749	
Classroo	om #108 (Other Instructional Use)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	640	SF	6	\$1,922	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	640	SF	6	\$4,512	
	Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
	Marker Board	1st Floor	9	LF	6	\$193	
	Walls - Plaster/Drywall	1st Floor	996	SF	6	\$2,749	
Classro	om #109 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	\$631	
	Ceiling - Lay-in	1st Floor	2,803	SF	6	\$8,417	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	2,803	SF	6	\$6,133	
	Lighting - Pendent/Surface	1st Floor	56	EA	6	\$6,938	
	Walls - Masonry	1st Floor	1,741	SF	6	\$5,477	
Classro	om #110 (Other Instructional Use)						
	Casework	1st Floor	39	LF	6	\$985	
	Ceiling - Lay-in	1st Floor	1,526	SF	6	\$4,583	
	Doors - Transom Window	1st Floor	16	SF	6	\$271	

Category:	Classrooms
-----------	------------

-					_		_
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	oom #110 (Other Instructional Use)						
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	1,526	SF	6	\$1,528	
	Lighting - Lay-in	1st Floor	16	EA	6	\$1,904	
	Marker Board	1st Floor	8	LF	6	\$171	
	Walls - Masonry	1st Floor	2,348	SF	6	\$7,387	
assro	oom #111 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	650	SF	6	\$1,952	
	Chalk Board	1st Floor	26	LF	4	\$2,387	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	650	SF	6	\$4,582	
	Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	1st Floor	996	SF	6	\$2,749	
assro	oom #114 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	844	SF	6	\$2,921	
	Doors - Transom Window	1st Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	844	SF	6	\$845	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	\$1,982	
	Walls - Masonry	1st Floor	1,276	SF	6	\$4,014	
	Walls - Plaster/Drywall	1st Floor	369	SF	6	\$1,018	
assro	oom #201 (Regular Classroom)					. ,	
400.0	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	650	SF	6	\$1,952	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	Metal panel
	Floor - Wood	2nd Floor	650	SF	6	\$4,582	
	Lighting - Lay-in	2nd Floor	12	EA	6	\$1,428	
	Marker Board	2nd Floor	20	LF	6	\$428	
	Walls - Plaster/Drywall	2nd Floor	996	SF	6	\$2,749	
assro	oom #202 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	2	SF	5		Missing tile and water stains
	Ceiling - Lay-in	2nd Floor	648	SF	6	\$1,946	
			0+0	0.	Ŭ	ψ1,0-τ0	

Category: C	lassrooms
-------------	-----------

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #202 (Regular Classroom)	Losaion	Quantity	U.III	Runk	0031	Common to
0103310	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	8	SF	6		Metal panel
	Floor - Wood	2nd Floor	650	SF	6	\$4,582	
	Lighting - Lay-in	2nd Floor	12	EA	6	\$1,428	
	Marker Board	2nd Floor	12	LF	6	\$257	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	Peeling paint
	Walls - Plaster/Drywall	2nd Floor	995	SF	6	\$2,746	
	·			0.	Ũ	<i><i><i><i>ϕ</i>=,</i></i></i>	
Classro	oom #203 (Computer Lab)						
	Ceiling - Plaster/Drywall	2nd Floor	2,792	SF	6	\$9,662	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	6	\$1,204	
	Doors - Transom Window	2nd Floor	40	SF	6	\$677	
	Floor - Wood	2nd Floor	2,792	SF	6	\$19,683	
	Lighting - Pendent/Surface	2nd Floor	79	EA	6	\$9,788	
	Marker Board	2nd Floor	30	LF	6	\$643	
	Storage/ Closet	2nd Floor	70	SF	6		#203S
	Walls - Masonry	2nd Floor	3,565	SF	6	\$11,215	
	Walls - Plaster/Drywall	2nd Floor	810	SF	6	\$2,236	
Classro	oom #204A (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	843	SF	6	\$2,532	
	Doors - Side-lite	2nd Floor	8	SF	6	\$134	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	843	SF	6	\$844	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	\$1,487	
	Marker Board	2nd Floor	20	LF	6	\$428	
	Walls - Masonry	2nd Floor	674	SF	6	\$2,120	
	Walls - Masonry	2nd Floor	2	SF	5	\$114	Water damage
	Walls - Plaster/Drywall	2nd Floor	676	SF	6	\$1,866	
Classro	oom #204B (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	843	SF	6	\$2,532	
	Doors - Side-lite	2nd Floor	8	SF	6	\$134	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	843	SF	6	\$844	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	\$1,487	
	Marker Board	2nd Floor	20	LF	6	\$428	
	Walls - Masonry	2nd Floor	676	SF	6	\$2,127	
	Walls - Plaster/Drywall	2nd Floor	676	SF	6	\$1,866	



F

Building: Addition 1						
Category: Classrooms						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #204B (Regular Classroom)						
Classroom #205B (Computer Lab)						
Casework	2nd Floor	10	LF	6	\$253	
Ceiling - Lay-in	2nd Floor	2	SF	5	\$16	Missing tiles and water stains
Ceiling - Lay-in	2nd Floor	1,244	SF	6	\$3,736	
Doors - Side-lite	2nd Floor	8	SF	6	\$134	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Tile/Sheet	2nd Floor	1,244	SF	6	\$1,245	
Lighting - Lay-in	2nd Floor	24	EA	6	\$2,855	
Marker Board	2nd Floor	12	LF	6	\$257	
Walls - Masonry	2nd Floor	1,550	SF	6	\$4,876	
Walls - Plaster/Drywall	2nd Floor	1,550	SF	6	\$4,278	
Classroom #205C (Other Instructional Use)						
Casework	4th Floor	10	LF	6	\$253	
Ceiling - Lay-in	4th Floor	843	SF	6	\$2,532	
Doors - Side-lite	4th Floor	8	SF	6	\$134	
Doors - Wood Doors inclu hw	4th Floor	1	EA	6	\$301	
Floor - Tile/Sheet	4th Floor	843	SF	6	\$844	
Lighting - Lay-in	4th Floor	15	EA	6	\$1,785	
Marker Board	4th Floor	12	LF	6	\$257	
Walls - Masonry	4th Floor	550	SF	6	\$1,730	
Walls - Plaster/Drywall	4th Floor	556	SF	6	\$1,535	
Classroom #207 (Regular Classroom)						
Casework	2nd Floor	10	LF	6	\$253	
Ceiling - Lay-in	2nd Floor	2	SF	5	\$16	Loose tiles and water stains
Ceiling - Lay-in	2nd Floor	648	SF	6	\$1,946	
Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
Doors - Transom Window	2nd Floor	8	SF	6	\$135	Metal panel
Floor - Wood	2nd Floor	650	SF	6	\$4,582	
Lighting - Lay-in	2nd Floor	12	EA	6	\$1,428	
Marker Board	2nd Floor	15	LF	6	\$321	
Walls - Plaster/Drywall	2nd Floor	996	SF	6	\$2,749	
Classroom #208A (Science Lab Level 1)						
Casework	2nd Floor	24	LF	6	\$606	
Ceiling - Lay-in	2nd Floor	2,674	SF	6	\$8,030	

Ceiling - Plaster/Drywall

120 SF 6

\$415

2nd Floor

Building: Addition 1

Category: Classrooms

oun Item - Type	Location	Quantity	l Ini+	Pank	Cost	Comments
oup Item - Type	LUCATION	Quantity	Unit	rank	COSt	Comments
assroom #208A (Science Lab Level 1) Doors - Steel Doors incl hw	2nd Floor	4	EA	6	\$1,204	
Doors - Transom Window	2nd Floor	4 40	SF	6		Metal panel
Eye Wash Station	2nd Floor	2	EA	6	\$672	
Floor - Tile/Sheet	2nd Floor	2,794	SF	6	\$2,797	
Fume Hood	2nd Floor	2,794	EA	6	\$816	
Gas Line	2nd Floor	26	EA	6	\$13,237	
Lighting - Lay-in	2nd Floor	42	EA	6	\$13,237 \$4,997	
	2nd Floor	42	EA	6	\$4,997 \$124	
Lighting - Pendent/Surface		-				
Marker Board	2nd Floor	24		6	\$514	
Science Lab Elements	2nd Floor	2,794	SF	5	\$94,092	
Science Lab Shower	2nd Floor	2	EA	6	\$758	
Storage/ Closet	2nd Floor	131	SF	6	\$950	
Walls - Plaster/Drywall	2nd Floor	1,984	SF	6	\$5,476	
Work Sink	2nd Floor	10	EA	6	\$3,790	
ssroom #209A (Regular Classroom)						
Casework	2nd Floor	10	LF	6	\$253	
Ceiling - Lay-in	2nd Floor	2,792	SF	6	\$8,384	
Doors - Steel Doors incl hw	2nd Floor	4	EA	6	\$1,204	
Doors - Transom Window	2nd Floor	40	SF	6	\$677	Metal panel
Floor - Wood	2nd Floor	2,792	SF	6	\$19,683	
Lighting - Lay-in	2nd Floor	48	EA	6	\$5,711	
Marker Board	2nd Floor	12	LF	6	\$257	
Storage/ Closet	2nd Floor	35	SF	6	\$254	
Walls - Masonry	2nd Floor	3,565	SF	6	\$11,215	
Walls - Plaster/Drywall	2nd Floor	810	SF	6	\$2,236	
ssroom #210 (Vacant)						
Casework	2nd Floor	10	LF	6	\$253	
Ceiling - Lay-in	2nd Floor	650	SF	6	\$1,952	
Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
Doors - Transom Window	2nd Floor	8	SF	6		Metal panel
Floor - Wood	2nd Floor	650	SF	6	\$4,582	
Lighting - Lay-in	2nd Floor	12	EA	6	\$1,428	
Marker Board	2nd Floor	16	LF	6	\$343	
Walls - Plaster/Drywall	2nd Floor	996	SF	6	\$2,749	
ssroom #211 (Regular Classroom)					•	
Casework	2nd Floor	10	LF	6	\$253	
	Dogo 6	1 of 97				Assessment Date: 10/23

-			-			-	
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #211 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	650	SF	6	\$1,952	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	Metal panel
	Floor - Wood	2nd Floor	650	SF	6	\$4,582	
	Lighting - Lay-in	2nd Floor	12	EA	6	\$1,428	
	Marker Board	2nd Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	\$15	Peeling paint
	Walls - Plaster/Drywall	2nd Floor	993	SF	6	\$2,741	
Classro	oom #212 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	839	SF	6	\$2,520	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	Metal panel
	Floor - Wood	2nd Floor	839	SF	6	\$5,915	
	Lighting - Lay-in	2nd Floor	15	EA	6	\$1,785	
	Marker Board	2nd Floor	30	LF	6	\$643	
	Walls - Plaster/Drywall	2nd Floor	1,394	SF	6	\$3,847	
Classro	oom #213A (Science Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	1,080	SF	6	\$3,243	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	1,080	SF	6	\$1,081	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	\$1,858	
	Marker Board	2nd Floor	18	LF	6	\$386	
	Walls - Masonry	2nd Floor	620	SF	6	\$1,951	
	Walls - Plaster/Drywall	2nd Floor	795	SF	6	\$2,194	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	\$189	
	Work Sink	2nd Floor	1	EA	6	\$379	
lassro	oom #213B (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	1,124	SF	6	\$3,375	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	1,124	SF	6	\$7,924	
	Lighting - Lay-in	2nd Floor	15	EA	6	\$1,785	
	Marker Board	2nd Floor	18	LF	6	\$386	
	Walls - Masonry	2nd Floor	681	SF	6	\$2,142	
						. ,	

Categ	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #213B (Regular Classroom)						
	Walls - Plaster/Drywall	2nd Floor	890	SF	6	\$2,456	
	Walls - Tile	2nd Floor	60	SF	6	\$131	
Classro	oom #214 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Splined	2nd Floor	3	SF	5	\$29	Missing tiles
	Ceiling - Splined	2nd Floor	714	SF	6	\$582	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	Metal panel
	Floor - Tile/Sheet	2nd Floor	3	SF	4	\$44	Damaged tiles
	Floor - Tile/Sheet	2nd Floor	714	SF	6	\$715	
	Lighting - Lay-in	2nd Floor	12	EA	6	\$1,428	
	Marker Board	2nd Floor	20	LF	6	\$428	
	Walls - Masonry	2nd Floor	50	SF	5	\$2,859	Peeling paint
	Walls - Masonry	2nd Floor	1,249	SF	6	\$3,929	
	Walls - Plaster/Drywall	2nd Floor	388	SF	6	\$1,071	
Classro	oom #215A (Art Room)						
	Casework	2nd Floor	54	LF	6	\$1,364	
	Ceiling - Lay-in	2nd Floor	1,233	SF	6	\$3,703	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	Metal panel
	Floor - Tile/Sheet	2nd Floor	1,233	SF	6	\$1,234	
	Lighting - Lay-in	2nd Floor	12	EA	6	\$1,428	
	Marker Board	2nd Floor	24	LF	6	\$514	
	Storage/ Closet	2nd Floor	451	SF	6	\$3,270	#2165A and upstair
	Walls - Concrete Block	2nd Floor	389	SF	6	\$1,140	
	Walls - Masonry	2nd Floor	1,099	SF	6	\$3,457	
	Walls - Plaster/Drywall	2nd Floor	627	SF	6	\$1,730	
	Work Sink	2nd Floor	2	EA	6	\$758	
Classro	oom #215B (Art Room)						
	Casework	2nd Floor	75	LF	6	\$1,894	
	Ceiling - Lay-in	2nd Floor	1,233	SF	6	\$3,703	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	Metal panel
	Floor - Wood	2nd Floor	1,233	SF	6	\$8,693	
	Kiln	2nd Floor	1	EA	6	\$2,321	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	



Building: Addition 1

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #215B (Art Room)						
	Marker Board	2nd Floor	24	LF	6	\$514	
	Storage/ Closet	2nd Floor	38	SF	6	\$276	
	Walls - Concrete Block	2nd Floor	389	SF	6	\$1,140	
	Walls - Metal Panel	2nd Floor	1,099	SF	6	\$8,204	
	Walls - Plaster/Drywall	2nd Floor	627	SF	6	\$1,730	
	Work Sink	2nd Floor	2	EA	6	\$758	
Classro	oom #216A (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	656	SF	6	\$1,970	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	10	SF	6	\$169	Metal panel
	Floor - Tile/Sheet	2nd Floor	656	SF	6	\$657	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	\$1,487	
	Marker Board	2nd Floor	16	LF	6	\$343	
	Walls - Structural Glazed Tile	2nd Floor	1,021	SF	6	\$3,212	
	Work Sink	2nd Floor	1	EA	6	\$379	
Classro	oom #216B (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	656	SF	6	\$1,970	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	Metal panel
	Floor - Tile/Sheet	2nd Floor	656	SF	6	\$657	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	\$1,487	
	Marker Board	2nd Floor	16	LF	6	\$343	
	Storage/ Closet	2nd Floor	40	SF	6	\$290	
	Walls - Plaster/Drywall	2nd Floor	1,021	SF	6	\$2,818	

Classrooms Subtotal:

\$756,021

Building: Addition 1

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Plaster/Drywall	200 Assistant Principal office	377	SF	6	\$1,305	
	Doors - Steel Doors incl hw	200 Assistant Principal office	1	EA	6	\$301	
	Doors - Transom Window	200 Assistant Principal office	8	SF	6	\$135	Metal panel



Building: Addition 1

ıp l	tem - Type	Location	Quantity	Unit	Rank	Cost	Comments
inist	rative Suites/Offices						
F	Floor - Wood	200 Assistant Principal office	377	SF	6	\$2,658	
I	Lighting - Pendent/Surface	200 Assistant Principal office	6	EA	6	\$743	
F	Power Distribution	200 Assistant Principal office	10	EA	6	\$21,249	
١	Walls - Plaster/Drywall	200 Assistant Principal office	1,396	SF	6	\$3,853	
(Ceiling - Lay-in	205A Planning Center	276	SF	6	\$829	
ſ	Doors - Side-lite	205A Planning Center	16	SF	6	\$267	
ſ	Doors - Wood Doors inclu hw	205A Planning Center	2	EA	6	\$602	
F	Floor - Tile/Sheet	205A Planning Center	276	SF	6	\$276	
I	Lighting - Lay-in	205A Planning Center	2	EA	6	\$238	
F	Power Distribution	205A Planning Center	6	EA	7	\$0	
١	Walls - Plaster/Drywall	205A Planning Center	540	SF	6	\$1,490	
(Ceiling - Lay-in	205B Stem Data Lab Area	128	SF	6	\$384	
I	Doors - Steel Doors incl hw	205B Stem Data Lab Area	4	EA	6	\$1,204	
I	Doors - Transom Window	205B Stem Data Lab Area	40	SF	6	\$677	Metal panel
I	Floor - Tile/Sheet	205B Stem Data Lab Area	128	SF	6	\$128	
I	Lighting - Lay-in	205B Stem Data Lab Area	8	EA	6	\$952	
	Power Distribution	205B Stem Data Lab Area	6	EA	7	\$0	
١	Walls - Plaster/Drywall	205B Stem Data Lab Area	1,244	SF	6	\$3,433	
١	Walls - Structural Glazed Tile	205B Stem Data Lab Area	220	SF	6	\$692	
(Ceiling - Lay-in	214A Office	275	SF	6	\$826	
I	Doors - Steel Doors incl hw	214A Office	1	EA	6	\$301	
I	Doors - Transom Window	214A Office	8	SF	6	\$135	Metal panel
I	Floor - Wood	214A Office	275	SF	6	\$1,939	
I	Lighting - Pendent/Surface	214A Office	3	EA	6	\$372	
ſ	Power Distribution	214A Office	8	EA	7	\$0	
١	Walls - Plaster/Drywall	214A Office	856	SF	6	\$2,362	
(Ceiling - Lay-in	214B Office	275	SF	6	\$826	
ſ	Doors - Steel Doors incl hw	214B Office	1	EA	6	\$301	
F	Floor - Tile/Sheet	214B Office	275	SF	6	\$275	
I	Lighting - Pendent/Surface	214B Office	3	EA	6	\$372	
F	Power Distribution	214B Office	8	EA	7	\$0	
١	Walls - Plaster/Drywall	214B Office	856	SF	6	\$2,362	
(Ceiling - Plaster/Drywall	2nd floor conference room 209C	651	SF	6	\$2,253	
ſ	Doors - Wood Doors inclu hw	2nd floor conference room 209C	1	EA	6	\$301	
F	Floor - Tile/Sheet	2nd floor conference room 209C	1	SF	5	\$6	Damaged tiles
F	Floor - Tile/Sheet	2nd floor conference room 209C	650	SF	6	\$651	
		2nd floor conference room 209C	11	EA	6	\$1,363	



Building: Addition 1

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Power Distribution	2nd floor conference room 209C	4	EA	7	\$0	
	Walls - Plaster/Drywall	2nd floor conference room 209C	1,074	SF	6	\$2,964	
	AC Unit	First floor north end office	1	EA	5	\$1,826	Poor support
	Ceiling - Plaster/Drywall	First floor north end office	377	SF	6	\$1,305	
	Doors - Wood Doors inclu hw	First floor north end office	1	EA	6	\$301	
	Floor - Wood	First floor north end office	377	SF	6	\$2,658	
	Lighting - Pendent/Surface	First floor north end office	6	EA	6	\$743	
	Power Distribution	First floor north end office	10	EA	7	\$0	
	Walls - Plaster/Drywall	First floor north end office	1,396	SF	6	\$3,853	
	Ceiling - Lay-in	North end of the building room 103C	154	SF	6	\$462	
	Doors - Wood Doors inclu hw	North end of the building room 103C	1	EA	6	\$301	
	Floor - Tile/Sheet	North end of the building room 103C	154	SF	6	\$154	
	Lighting - Lay-in	North end of the building room 103C	3	EA	6	\$357	
	Power Distribution	North end of the building room 103C	6	EA	7	\$0	
	Walls - Plaster/Drywall	North end of the building room 103C	460	SF	6	\$1,270	
	Ceiling - Lay-in	Office 213C	140	SF	6	\$420	
	Doors - Side-lite	Office 213C	8	SF	6	\$134	
	Doors - Steel Doors incl hw	Office 213C	1	EA	6	\$301	
	Floor - Tile/Sheet	Office 213C	140	SF	6	\$140	
	Lighting - Lay-in	Office 213C	2	EA	7	\$0	
	Power Distribution	Office 213C	6	EA	7	\$0	
	Walls - Plaster/Drywall	Office 213C	468	SF	6	\$1,292	
	Ceiling - Lay-in	Office 213D	140	SF	6	\$420	
	Doors - Side-lite	Office 213D	8	SF	6	\$134	
	Doors - Wood Doors inclu hw	Office 213D	1	EA	6	\$301	
	Floor - Tile/Sheet	Office 213D	140	SF	6	\$140	
	Lighting - Lay-in	Office 213D	2	EA	6	\$238	
	Power Distribution	Office 213D	6	EA	7	\$0	
	Walls - Plaster/Drywall	Office 213D	468	SF	6	\$1,292	
Kitchen							
NICHE	Ceiling - Lay-in	First floor south end room 113	3,178	SF	6	\$9,544	
	Doors - Steel Doors incl hw	First floor south end room 113	3,178	EA	6	\$9,544 \$602	
	Doors - Transom Window	First floor south end room 113	2 16	SF	6	\$002 \$271	
	Floor - Tile/Sheet	First floor south end room 113		SF	6		
			3,178			\$3,181 \$4,584	
	Lighting - Pendent/Surface	First floor south and room 113	37	EA	6	\$4,584	
	Walls - Concrete Block	First floor south and room 113	2,602	SF	6	\$7,628	
	Walls - Structural Glazed Tile	First floor south end room 113	534	SF	6	\$1,680	



Building: Addition 1

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Kitchen							
Locker/	Shower Room						
	Accessories	2nd floor south end Partial locker use as Storage	235	SF	6	\$921	
	Accessories	2nd floor south end Partial locker use as Storage	207	SF	6	\$811	
	Ceiling - Plaster/ Drywall	2nd floor south end Partial locker use as Storage	235	SF	6	\$813	
	Ceiling - Plaster/ Drywall	2nd floor south end Partial locker use as Storage	207	SF	6	\$716	
	Doors - Wood Doors inclu hw	2nd floor south end Partial locker use as Storage	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	2nd floor south end Partial locker use as Storage	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd floor south end Partial locker use as Storage	207	SF	6	\$438	
	Floor - Tile Ceramic/ Porcelain	2nd floor south end Partial locker use as Storage	235	SF	6	\$497	
	Lighting - Pendent/Surface	2nd floor south end Partial locker use as Storage	3	EA	6	\$372	
	Lighting - Pendent/Surface	2nd floor south end Partial locker use as Storage	4	EA	6	\$496	
	Student Lockers - One Tier	2nd floor south end Partial locker use as Storage	1	EA	6	\$93	
	Student Lockers - One Tier	2nd floor south end Partial locker use as Storage	1	EA	6	\$93	
	Student Lockers - Two Tier	2nd floor south end Partial locker use as Storage	19	EA	6	\$882	
	Student Lockers - Two Tier	2nd floor south end Partial locker use as Storage	19	EA	6	\$882	
	Walls - Structural Glazed Tile	2nd floor south end Partial locker use as Storage	699	SF	6	\$2,199	
	Walls - Structural Glazed Tile	2nd floor south end Partial locker use as Storage	689	SF	6	\$2,168	
	Water Closet	2nd floor south end Partial locker use as Storage	2	EA	6	\$672	
	Water Closet	2nd floor south end Partial locker use as Storage	2	EA	6	\$672	
	Accessories	First floor between room 104 & 106	74	SF	6	\$290	
	Ceiling - Exposed	First floor between room 104 & 106	709	SF	6	\$1,054	
	Floor Drain	First floor between room 104 & 106	2	EA	6	\$2,118	
	Floor - Concrete	First floor between room 104 & 106	709	SF	6	\$375	
	Lavatory	First floor between room 104 & 106	2	EA	6	\$639	



Building: Addition 1

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/	Shower Room						
	Lighting - Pendent/Surface	First floor between room 104 & 106	9	EA	6	\$1,115	
	Student Lockers - One Tier	First floor between room 104 & 106	202	EA	6	\$18,753	
	Walls - Concrete Block	First floor between room 104 & 106	1,134	SF	6	\$3,324	
	Water Closet	First floor between room 104 & 106	2	EA	6	\$672	
	Accessories	Old Girl's Locker room	682	SF	5	\$5,959	Does not work
	Benches, ped mounted	Old Girl's Locker room	24	LF	6	\$2,613	
	Ceiling - Exposed	Old Girl's Locker room	525	SF	6	\$781	Metal deck (SF)
	Ceiling - Plaster/ Drywall	Old Girl's Locker room	157	SF	6	\$543	
	Doors - Wood Doors inclu hw	Old Girl's Locker room	2	EA	6	\$602	
	Floor Drain	Old Girl's Locker room	2	EA	6	\$2,118	
	Floor - Concrete Epoxy/ Painted	Old Girl's Locker room	525	SF	6	\$278	
	Floor - Tile Ceramic/ Porcelain	Old Girl's Locker room	157	SF	5	\$2,508	Water damaged
	Lavatory	Old Girl's Locker room	3	EA	5	\$11,289	Does not work
	Lighting - Pendent/Surface	Old Girl's Locker room	8	EA	6	\$991	
	Partitions	Old Girl's Locker room	2	EA	6	\$594	
	Showers	Old Girl's Locker room	2	EA	5	\$5,429	Does not work
	Student Lockers - One Tier	Old Girl's Locker room	90	EA	5	\$12,614	Broken
	Walls - Structural Glazed Tile	Old Girl's Locker room	650	SF	6	\$2,045	
	Water Closet	Old Girl's Locker room	2	EA	5	\$7,788	Does not work
Lunch a	& Multipurpose Room						
	Ceiling - Exposed	First floor south end room 118 &115 restaurant	2,795	SF	6	\$4,157	
	Doors - Wood Doors inclu hw	First floor south end room 118 &115 restaurant	2	EA	6	\$602	
	Floor - Tile/Sheet	First floor south end room 118 &115 restaurant	2,795	SF	6	\$2,798	
	Lighting - Pendent/Surface	First floor south end room 118 &115 restaurant	28	EA	6	\$3,469	
	Walls - Concrete Block	First floor south end room 118 &115 restaurant	3,668	SF	6	\$10,753	
Mechar	nical/ Service Rooms						
	Janitor's Closet	2nd Floor	70	SF	6	\$502	Located in 205B
	Storage Room	2nd Floor	367	SF	6	\$2,629	Next to #213A and next to room 218
Prep Ro	bom						
-	Casework	Prep room in 208A	40	LF	6	\$1,010	
	Ceiling - Plaster/Drywall	Prep room in 208A	352	SF	6	\$1,218	
	Doors - Wood Doors inclu hw	Prep room in 208A	1	EA	6	\$301	



Building: Addition 1

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Prep Ro	oom						
	Floor - Tile/Sheet	Prep room in 208A	352	SF	6	\$352	
	Lighting - Pendent/Surface	Prep room in 208A	4	EA	6	\$496	Missing lens
	Walls - Plaster/Drywall	Prep room in 208A	920	SF	6	\$2,539	
Restroo	om						
	Accessories	2nd floor north end girl's next to 203	447	SF	6	\$4,123	
	Ceiling - Plaster/Drywall	2nd floor north end girl's next to 203	447	SF	6	\$1,547	
	Doors - Wood Doors inclu hw	2nd floor north end girl's next to 203	1	EA	6	\$301	
	Floor Drain	2nd floor north end girl's next to 203	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	2nd floor north end girl's next to 203	447	SF	6	\$946	
	Hand Dryer	2nd floor north end girl's next to 203	2	EA	6	\$460	
	Lavatory	2nd floor north end girl's next to 203	4	EA	6	\$1,278	
	Lighting - Pendent/Surface	2nd floor north end girl's next to 203	6	EA	6	\$743	
	Partitions	2nd floor north end girl's next to 203	6	EA	6	\$1,782	
	Walls - Plaster/Drywall	2nd floor north end girl's next to 203	660	SF	6	\$1,822	
	Water Closet	2nd floor north end girl's next to 203	7	EA	6	\$2,352	
	Accessories	2nd floor south end boys next to 216A	284	SF	6	\$2,619	
	Ceiling - Plaster/Drywall	2nd floor south end boys next to 216A	284	SF	6	\$983	
	Doors - Wood Doors inclu hw	2nd floor south end boys next to 216A	1	EA	6	\$301	
	Floor Drain	2nd floor south end boys next to 216A	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd floor south end boys next to 216A	284	SF	6	\$601	
	Hand Dryer	2nd floor south end boys next to 216A	2	EA	6	\$460	
	Lavatory	2nd floor south end boys next to 216A	3	EA	6	\$959	
	Lighting - Pendent/Surface	2nd floor south end boys next to 216A	6	EA	6	\$743	
	Partitions	2nd floor south end boys next to 216A	3	EA	6	\$891	
	Urinals	2nd floor south end boys next to 216A	3	EA	6	\$1,008	
	Walls - Structural Glazed Tile	2nd floor south end boys next to 216A	460	SF	6	\$1,447	
	Water Closet	2nd floor south end boys next to 216A	3	EA	6	\$1,008	
	Accessories	Bathroom in room 208A Prep Area	47	SF	6	\$434	
	Ceiling - Plaster/Drywall	Bathroom in room 208A Prep Area	47	SF	6	\$163	
	Doors - Wood Doors inclu hw	Bathroom in room 208A Prep Area	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Bathroom in room 208A Prep Area	47	SF	6	\$99	
	Lavatory	Bathroom in room 208A Prep Area	1	EA	6	\$320	
	Lighting - Pendent/Surface	Bathroom in room 208A Prep Area	1	EA	6	\$124	
	Lighting - Wall Mounted	Bathroom in room 208A Prep Area	2	EA	6	\$248	
	Showers	Bathroom in room 208A Prep Area	1	EA	6	\$311	Tub
	Walls - Plaster/Drywall	Bathroom in room 208A Prep Area	98	SF	6	\$270	
	Walls - Tile Ceramic/ Porcelain	Bathroom in room 208A Prep Area	144	SF	6	\$325	



Building: Addition 1

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Water Closet	Bathroom in room 208A Prep Area	1	EA	6	\$336	
	Accessories	First floor in restaurant on the south end women's	35	SF	6	\$323	
	Ceiling - Plaster/Drywall	First floor in restaurant on the south end women's	35	SF	6	\$121	
	Doors - Wood Doors inclu hw	First floor in restaurant on the south end women's	1	EA	6	\$301	
	Floor - Tile/Sheet	First floor in restaurant on the south end women's	35	SF	6	\$35	
	Lavatory	First floor in restaurant on the south end women's	1	EA	6	\$320	
	Lighting - Wall Mounted	First floor in restaurant on the south end women's	2	EA	6	\$248	
	Walls - Plaster/Drywall	First floor in restaurant on the south end women's	210	SF	6	\$580	
	Water Closet	First floor in restaurant on the south end women's	1	EA	6	\$336	
	Accessories	First floor in restaurant on south ends mens	35	SF	6	\$323	
	Ceiling - Plaster/Drywall	First floor in restaurant on south ends mens	35	SF	6	\$121	
	Doors - Wood Doors inclu hw	First floor in restaurant on south ends mens	1	EA	6	\$301	
	Floor - Tile/Sheet	First floor in restaurant on south ends mens	35	SF	6	\$35	
	Lavatory	First floor in restaurant on south ends mens	1	EA	6	\$320	
	Lighting - Wall Mounted	First floor in restaurant on south ends mens	2	EA	6	\$248	
	Walls - Plaster/Drywall	First floor in restaurant on south ends mens	210	SF	6	\$580	
	Water Closet	First floor in restaurant on south ends mens	1	EA	6	\$336	
	Accessories	First floor north end girls	447	SF	6	\$4,123	
	Ceiling - Plaster/Drywall	First floor north end girls	447	SF	6	\$1,547	
	Floor Drain	First floor north end girls	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	First floor north end girls	447	SF	6	\$946	
	Hand Dryer	First floor north end girls	2	EA	6	\$460	
	Lavatory	First floor north end girls	4	EA	6	\$1,278	
	Lighting - Pendent/Surface	First floor north end girls	6	EA	6	\$743	
	Partitions	First floor north end girls	7	EA	6	\$2,078	
	Walls - Plaster/Drywall	First floor north end girls	660	SF	6	\$1,822	



Building: Addition 1

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Water Closet	First floor north end girls	7	EA	6	\$2,352	
	Accessories	First floor south end boys'	284	SF	6	\$2,619	
	Ceiling - Plaster/Drywall	First floor south end boys'	284	SF	6	\$983	
	Doors - Wood Doors inclu hw	First floor south end boys'	1	EA	6	\$301	
	Floor Drain	First floor south end boys'	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	First floor south end boys'	284	SF	6	\$601	
	Hand Dryer	First floor south end boys'	2	EA	6	\$460	
	Lavatory	First floor south end boys'	3	EA	6	\$959	
	Lighting - Pendent/Surface	First floor south end boys'	6	EA	6	\$743	
	Partitions	First floor south end boys'	3	EA	6	\$891	
	Urinals	First floor south end boys'	3	EA	6	\$1,008	
	Walls - Structural Glazed Tile	First floor south end boys'	460	SF	6	\$1,447	
	Water Closet	First floor south end boys'	3	EA	6	\$1,008	
	Accessories	Toilet in room 214A	35	SF	6	\$323	
	Ceiling - Plaster/Drywall	Toilet in room 214A	35	SF	6	\$121	
	Doors - Wood Doors inclu hw	Toilet in room 214A	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Toilet in room 214A	35	SF	6	\$74	
	Lavatory	Toilet in room 214A	1	EA	6	\$320	
	Lighting - Pendent/Surface	Toilet in room 214A	1	EA	6	\$124	
	Walls - Plaster/Drywall	Toilet in room 214A	228	SF	6	\$629	
	Water Closet	Toilet in room 214A	1	EA	6	\$336	
	Accessories	Toilet in room 214B	35	SF	6	\$323	
	Ceiling - Plaster/Drywall	Toilet in room 214B	5	SF	5	\$54	Peeling paint
	Ceiling - Plaster/Drywall	Toilet in room 214B	30	SF	6	\$104	
	Doors - Wood Doors inclu hw	Toilet in room 214B	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Toilet in room 214B	35	SF	6	\$74	
	Lavatory	Toilet in room 214B	1	EA	6	\$320	
	Lighting - Pendent/Surface	Toilet in room 214B	1	EA	6	\$124	
	Partitions	Toilet in room 214B	1	EA	6	\$297	
	Walls - Plaster/Drywall	Toilet in room 214B	228	SF	6	\$629	
	Water Closet	Toilet in room 214B	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$304,546

Building: Addition 1				
Category: Building Interior				
Group Item - Type	Location	Quantity Unit Rank	Cost Comments	



Building: Addition 1

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Ceiling - Lay-in	1st Floor	9,220	SF	6	\$27,688	
	Floor - Terrazzo	1st Floor	1,378	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	6,942	SF	6	\$3,772	
	Lighting - Lay-in	1st Floor	42	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	5,146	SF	6	\$22,812	
	Walls - Structural Glazed Tile	1st Floor	10,575	SF	6	\$33,269	
	Ceiling - Lay-in	2nd Floor	8,320	SF	6	\$24,985	
	Floor - Tile/Sheet	2nd Floor	7,840	SF	6	\$4,260	
	Floor - Tile/Sheet	2nd Floor	2	SF	5	\$12	Damaged tiles
	Lighting - Lay-in	2nd Floor	33	EA	6	\$3,926	
	Student Lockers - One Tier	2nd Floor	158	EA	6	\$14,668	
	Walls - Plaster/Drywall	2nd Floor	4,117	SF	6	\$18,251	
	Walls - Structural Glazed Tile	2nd Floor	8,375	SF	6	\$26,348	
afety							
	Security Cameras	Entire Building	10	EA	6	\$1,940	
	Security Cameras	Entire Building	3	EA	6	\$582	
tairs							
	Ceiling - Plaster/Drywall	Stair by room 111	330	SF	6	\$2,416	
	Floor - Terrazzo	Stair by room 111	330	SF	7	\$0	
	Handrails	Stair by room 111	64	LF	6	\$555	
	Lighting - Pendent/Surface	Stair by room 111	3	EA	6	\$372	
	Stairs - Terrazzo	Stair by room 111	32	LF	7	\$0	
	Walls - Structural Glazed Tile	Stair by room 111	3,096	SF	6	\$9,740	
	Ceiling - Plaster/Drywall	Stairs by 101	330	SF	6	\$2,416	
	Floor - Terrazzo	Stairs by 101	330	SF	7	\$0	
	Handrails	Stairs by 101	64	LF	6	\$555	
	Lighting - Pendent/Surface	Stairs by 101	3	EA	6	\$372	
	Stairs - Terrazzo	Stairs by 101	32	LF	7	\$0	
	Walls - Structural Glazed Tile	Stairs by 101	3,096	SF	6	\$9,740	
3uildi	ng Interior Subtotal:				\$208,678		
otal I	Building Cost			\$3	3,042,970		

Building: Addition 2 - Anthony Wing



Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	ce						
	Exterior Doors - Exterior Steel Door	#15 W	2	EA	6	\$961	
	Exterior Doors - Overhead Rolling/ Garage Door	#12 OHD NE	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	#16 W	1	EA	6	\$1,433	
	Exterior Doors - Store Front	#11 SE	2	EA	6	\$1,092	
	Exterior Doors - Store Front	#13 NE	3	EA	6	\$1,638	
	Exterior Doors - Transom Lite	#11 SE	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#13 NE	6	EA	6	\$1,880	
	Exterior Stairs - Concrete	#11 SE	36	LF	6	\$2,944	
	Exterior Stairs - Concrete	#13 NE	180	LF	6	\$14,718	
	Exterior Stairs - Concrete	#15 W	36	LF	6	\$2,944	
	Stair Handrail - Steel_Stair Handrail	#11 SE	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	#13 NE	30	LF	6	\$260	
	Stair Handrail - Steel_Stair Handrail	#15 W	30	LF	6	\$260	
Founda	tion						
	Foundation - Concrete	Entire Building	1,627	LF	7	\$0	
	Superstructure - Concrete	Entire Building	71,628	SF	7	\$0	
Lighting	9						
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	\$3,465	
Roof Sy	ystem						
	Coping - Stone	Main Roof	1,566	LF	6	\$50,296	
	Downspouts - Interior Downspouts	Main Roof	240	LF	6	\$7,976	
	Parapet - 16" - 30" Height	Main Roof	1,566	LF	6	\$62,568	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	35,230	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Main Roof	35,230	SF	6	\$358,194	
Walls							
	Cheek-Wall - Concrete	Entire Building	40	SF	6	\$410	
	Exterior Walls - Brick	Entire Building	43,663	SF	6	\$293,459	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	5,791	SF	6	\$32,876	
	Exterior Walls - Stone-Cast	Entire Building	11,167	SF	6	\$75,053	
Window	vs						
	Guard - Guards wire guard	Entire Building / 1st Floor	111	SF	6	\$1,417	
	Lintels - Steel	Entire Building	683	LF	7	\$0	
	Windows - Casement Aluminum Double-pane	Entire Building	1,140	SF	6	\$8,510	
	Windows - Casement Aluminum Double-pane	Entire Building	1,140	SF	5	\$61,410	Not operating well



oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
uildi	ng Exterior Subtotal:					\$985,999	
uildi	ng: Addition 2 - Anthony Wing						
atego	ory: Electrical System						
oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
nerge	ncy System						
	Automatic Transfer Switch	Entire Building	1	EA	4	\$8,200	Switch has over 40 years of service and show signs of significant deterioration.
	Automatic Transfer Switch	Entire Building	1	EA	6	\$408	
	Emergency A/C Power - Corridors and Stairs	Entire Building	13,942	SF	6	\$4,187	
	Emergency A/C Power - Gym	Entire Building / 2nd Floor	5,666	SF	6	\$2,107	
	Emergency A/C Power - Students Toilets	Entire Building	205	SF	6	\$76	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	32	EA	6	\$6,480	Needs batteries.
	Exit Signs - Corridors and Stairs	Entire Building	24	EA	7	\$0	
	Security System - CCTV	Entire Building	72,628	SF	6	\$21,810	
	Security System - Intrusion Detection	Entire Building	72,628	SF	6	\$18,694	
ain Se	rvice						
	Main Electrical Service - 2000 A 120/240/3PH	Entire Building / Electrical Room	1	EA	4	\$86,527	Panel has over 40 years of service and shows signs of significant deterioration.
	Main Electrical Service - 2000 A 120/240/3PH	Entire Building / Electrical Room	1	EA	4	\$86,527	Panel has over 40 years of service and shows signs of significant deterioration.
	Main Electrical Service - 800 A and 277/480/3PH	Entire Building / Electrical Room	1	EA	7	\$0	
	Main Electrical Service - 800 A and Less than 277/480/3PH	Entire Building / Electrical Room	1	EA	7	\$0	
	PA System	Entire Building	72,628	SF	6	\$23,887	Serves main and additions. Control console located in main.
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	4	\$19,397	Panels have over 40 years of service and sho signs of significant deterioration.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	\$299	Emergency fuse panel
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	\$0	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	4	\$19,733	Panels have over 40 years of service and sho signs of significant deterioration.
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	\$13,694	Panel has over 40 years of service and shows signs of significant deterioration.
	Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	4	\$63,313	-



Building: Addition 2 - Anthony Wing

Category:	Electrical	System
-----------	------------	--------

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution						
Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	7	\$0	
Transformers - 120/240 - 120/208	Entire Building	1	EA	6	\$3,021	
Transformers - 277/480 - 120/240	Entire Building	1	EA	6	\$1,019	
Transformers - 277/480 - 120/240	Entire Building	3	EA	6	\$3,058	
Transformers - 277/480 - 120/240	Entire Building	1	EA	6	\$1,019	
Electrical System Subtotal:					\$383,458	

Electrical System Subtotal:

Building: Addition 2 - Anthony Wing

Category:	Safty	System	
-----------	-------	--------	--

pup Item - Type	Location	Quantity Unit Rank	Cost Comments
e Alarm			
Fire Alarm Strobe Lights	Entire Building	72,628 SF 6	\$25,965
Fire Alarm_System	Entire Building	72.628 SF 6	\$35,312 Panel located in Main.

Safty System Subtotal:

Building: Addition 2 - Anthony Wing

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
ir Han	r Handling Systems								
	Air Handling Unit- Built Up- Single Zone- Daul Temperature Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0	AHU-9 serves make-up air to East Wing		
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765			
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	7	\$0			
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	60	LF	6	\$0			
leating	Devices								
	Cabinet Heaters - With Hot Water Coil	Entire Building	3	EA	7	\$0			
	Fin Tube - Hot Water	Entire Building	322	LF	7	\$0			
	Unit Heater - Hot Water	Entire Building	25	EA	7	\$0			
	Wall Heater - Electric	1st Floor	1	EA	7	\$0			
lechar	ical Plumbing								
	Daul Temperature Pump - Less than 10	Mechanical Room	1	EA	7	\$0			
	Hydronic Supply and Return - Copper	Entire Building	5,500	LF	7	\$0			
	Hydronic Supply and Return - Galvanized	Entire Building	1,000	LF	7	\$0			



Building: Addition 2 - Anthony Wing

Category: M	echanical	System
-------------	-----------	--------

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Femperature Control						
DDC System	Entire Building	72,628	SF	7	\$0	
Electric Thermostat	Entire Building	25	EA	7	\$0	
Thermostats - DDC	Entire Building	46	EA	7	\$0	
/entilation						
Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	7	\$0	
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	7	\$0	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	3	EA	7	\$0	
lechanical System Subtotal:					\$5,765	

Building: Addition 2 - Anthony Wing

Category: Plumbing System

up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ing							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	72,628	SF	4	\$51,929	Piping is old and deteriorated.
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	58,102	SF	4	\$83,917	Piping is old and deteriorated.
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	14,526	SF	7	\$0	
	Domestic Piping-Cold Water Risers	Entire Building	72,628	SF	4	\$58,161	Piping is old and deteriorated.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	72,628	SF	4	\$39,466	Piping is old and deteriorated.
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	14,526	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	58,102	SF	4	\$74,777	Piping is old and deteriorated.
	Domestic Piping-Hot Water Return Lines	Entire Building	72,628	SF	4	\$62,315	Piping is old and deteriorated.
	Domestic Piping-Hot Water Return Risers	Entire Building	72,628	SF	4	\$35,312	Piping is old and deteriorated.
	Sanitary Piping	Entire Building	72,628	SF	4	\$252,375	Piping is old and deteriorated.
	Storm Piping	Entire Building	72,628	SF	6	\$63,353	
	Vent Piping	Entire Building	72,628	SF	6	\$48,813	
nps							
	Pumps - Sump-Duplex	Basement	2	EA	6	\$2,774	
	Pumps - Sump-Simplex	Basement	1	EA	6	\$745	Elevator sump pit
	ing System Subtotal:					\$773,937	

Group Item - Type

Location

Quantity Unit Rank

Cost Comments



Category: C	lassrooms
-------------	-----------

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	bom #149 (Regular Classroom)	Location	Quantity	Onit	Nank	0031	oonimenta .
0103510	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	679	SF	6	\$2,039	
	Chalk Board	1st Floor	24	LF	4	\$2,039 \$2,203	
	Doors - Transom Window	1st Floor	8	SF	6	\$2,203 \$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	679	SF	6	\$301 \$4,787	
		1st Floor		EA			
	Lighting - Lay-in	1st Floor	12	SF	6	\$1,428	
	Walls - Plaster/Drywall	1 St Floor	1,020	SF	6	\$2,815	
Classro	oom #151 (Regular Classroom)						
	Ceiling - Splined	1st Floor	2,813	SF	6	\$2,293	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Concrete	1st Floor	2,813	SF	6	\$1,488	
	Lighting - Pendent/Surface	1st Floor	60	EA	6	\$7,434	
	Walls - Masonry	1st Floor	4,322	SF	6	\$13,597	
Classro	oom #153 (Regular Classroom)						
	Casework	1st Floor	40	LF	6	\$1,010	
	Ceiling - Plaster/Drywall	1st Floor	2,813	SF	6	\$9,735	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	2,813	SF	6	\$2,816	
	Lighting - Pendent/Surface	1st Floor	60	EA	6	\$7,434	
	Walls - Masonry	1st Floor	4,322	SF	6	\$13,597	
Classro	oom #154 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	635	SF	6	\$1,907	
	Chalk Board	1st Floor	20	LF	6	\$446	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	635	SF	6	\$4,477	
	Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	1st Floor	1,014	SF	6	\$2,799	
Classro	oom #155 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	660	SF	6	\$1,982	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	



atego	ory: Classrooms						
oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	oom #155 (Regular Classroom)						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	660	SF	6	\$4,653	
	Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	1st Floor	919	SF	6	\$2,536	
assro	oom #156 (Store Room)						
	Ceiling - Plaster/Drywall	1st Floor	2,825	SF	6	\$9,776	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Concrete	1st Floor	2,825	SF	6	\$1,495	
	Lighting - Pendent/Surface	1st Floor	56	EA	6	\$6,938	
	Walls - Masonry	1st Floor	3,245	SF	6	\$10,209	
assro	oom #157 (Other Instructional Use)						
	Ceiling - Lay-in	1st Floor	2,800	SF	6	\$8,408	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	2,800	SF	6	\$2,803	
	Lighting - Pendent/Surface	1st Floor	28	EA	6	\$3,469	
	Walls - Masonry	1st Floor	1,690	SF	6	\$5,317	
assro	oom #247 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	679	SF	6	\$2,039	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	Metal panel
	Floor - Wood	2nd Floor	679	SF	6	\$4,787	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	\$26	Peeling paint
	Walls - Plaster/Drywall	2nd Floor	1,015	SF	6	\$2,801	
assro	oom #250 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	2,808	SF	6	\$8,432	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	Metal panel
	Floor - Tile/Sheet	2nd Floor	2,808	SF	6	\$2,811	
	Lighting - Lay-in	2nd Floor	24	EA	6	\$2,855	
	Storage/ Closet	2nd Floor	438	SF	6	\$3,176	
	Walls - Masonry	2nd Floor	5	SF	5	\$286	Peeling paint
	Walls - Masonry	2nd Floor	2,395	SF	6	\$7,535	



tegory: Clas		1 d	0		Baul	0	0
oup Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
	egular Classroom)						
Work Sink		2nd Floor	1	EA	6	\$379	
ssroom #254 (Re	egular Classroom)						
Casework		2nd Floor	10	LF	6	\$253	
Ceiling - La	ay-in	2nd Floor	663	SF	6	\$1,991	
Doors - Ste	el Doors incl hw	2nd Floor	1	EA	6	\$301	
Doors - Tra	nsom Window	2nd Floor	8	SF	6	\$135	Metal panel
Floor - Woo	bd	2nd Floor	663	SF	6	\$4,674	
Lighting - L	_ay-in	2nd Floor	12	EA	6	\$1,428	
Marker Boa	Ird	2nd Floor	16	LF	6	\$343	
Walls - Pla	ster/Drywall	2nd Floor	1,020	SF	6	\$2,815	
ssroom #255 (Re	egular Classroom)						
Casework	· ·	2nd Floor	10	LF	6	\$253	
Ceiling - La	ay-in	2nd Floor	660	SF	6	\$1,982	
•	el Doors incl hw	2nd Floor	1	EA	6	\$301	
Doors - Tra	ansom Window	2nd Floor	8	SF	6		Metal panel
Floor - Tile/	'Sheet	2nd Floor	2	SF	5		Missing tiles
Floor - Tile/		2nd Floor	659	SF	6	\$660	
Lighting - L		2nd Floor	12	EA	6	\$1,428	
Marker Boa		2nd Floor	15	LF	6	\$321	
Walls - Pla		2nd Floor	919	SF	6	\$2,536	
	Regular Classroom)						
Ceiling - E		2nd Floor	1,199	SF	6	\$1 783	Clay ceiling
Ceiling - La		2nd Floor	1,580	SF	6	\$4,745	.,
-	el Doors incl hw	2nd Floor	4	EA	6	\$1,204	
	ansom Window	2nd Floor	38	SF	6		Metal panel
Floor - Tile/		2nd Floor	2,759	SF	6	\$2,762	
	Pendent/Surface	2nd Floor	42	EA	6	\$5,204	
Marker Boa		2nd Floor	24	LF	6	\$514	
Storage/ Cl		2nd Floor	110	SF	6		#256C, 256S
Walls - Mas		2nd Floor	3,526	SF	6	\$11,093	
Walls - Pla	-	2nd Floor	805	SF	6	\$2,222	
	Regular Classroom)		500		-	÷ -, -	
Ceiling - E		2nd Floor	1,199	SF	6	\$1 782	Clay ceiling
Ceiling - La	•	2nd Floor	1,601	SF	6	\$1,763	City Celling
0	el Doors incl hw	2nd Floor	1,001	EA	6	\$4,808 \$602	
DOOLS - Ste			2	EA	0	Φ00Z	



Building: Addition 2 - Anthony Wing

Category: Classrooms	Categor	y: Cl	lassro	oms
----------------------	---------	-------	--------	-----

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ssroom #257A (Regular Classroom)						
Doors - Transom Window	2nd Floor	38	SF	6	\$643	Metal panel
Floor - Tile/Sheet	2nd Floor	2,800	SF	6	\$2,803	
Lighting - Lay-in	2nd Floor	48	EA	6	\$5,711	
Marker Board	2nd Floor	24	LF	6	\$514	
Storage/ Closet	2nd Floor	403	SF	6	\$2,922	#257C and upstair
Walls - Masonry	2nd Floor	1,690	SF	6	\$5,317	

Building: Addition 2 - Anthony Wing

up Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
ninistrative Suite	es/Offices						
Ceiling - Pla	aster/Drywall	248 Counselor Office	1,794	SF	5	\$16,444	Peeling paint
Doors - Stee	el Doors incl hw	248 Counselor Office	4	EA	6	\$1,204	
Doors - Trar	nsom Window	248 Counselor Office	32	SF	6	\$542	metal panel
Floor - Tile/S	Sheet	248 Counselor Office	1,794	SF	6	\$1,796	
Lighting - P	endent/Surface	248 Counselor Office	40	EA	6	\$4,956	
Power Distri	bution	248 Counselor Office	6	EA	7	\$0	
Storage/ Clo	oset	248 Counselor Office	35	SF	6	\$254	
Walls - Mas	onry	248 Counselor Office	2,026	SF	5	\$83,729	Peeling paint
Ceiling - La	y-in	252A Office	301	SF	6	\$904	
Doors - Trar	nsom Window	252A Office	8	SF	6	\$135	
Doors - Woo	od Doors inclu hw	252A Office	1	EA	6	\$301	
Floor - Carp	et	252A Office	301	SF	6	\$641	
Lighting - P	endent/Surface	252A Office	2	EA	6	\$248	
Power Distri	bution	252A Office	2	EA	7	\$0	
Walls - Plas	ter/Drywall	252A Office	811	SF	6	\$2,238	
Ceiling - Pla	aster/Drywall	253A Office	270	SF	6	\$934	
Doors - Trar	nsom Window	253A Office	8	SF	6	\$135	
Doors - Woo	od Doors inclu hw	253A Office	1	EA	6	\$301	
Floor - Tile/S	Sheet	253A Office	270	SF	6	\$270	
Lighting - P	endent/Surface	253A Office	2	EA	6	\$248	
Power Distri	bution	253A Office	4	EA	7	\$0	
Storage/ Clo	oset	253A Office	4	SF	6	\$29	
Walls - Plas	ter/Drywall	253A Office	2	SF	5	\$10	Bubbling paint
Walls - Plas	ter/Drywall	253A Office	1,228	SF	6	\$3,389	



Building: Addition 2 - Anthony Wing

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Plaster/Drywall	253B JROTC Office	652	SF	6	\$2,256	
	Doors - Transom Window	253B JROTC Office	18	SF	6	\$305	Metal panel
	Doors - Wood Doors inclu hw	253B JROTC Office	2	EA	6	\$602	
	Floor - Carpet	253B JROTC Office	250	SF	6	\$533	
	Floor - Tile/Sheet	253B JROTC Office	452	SF	6	\$452	
	Lighting - Lay-in	253B JROTC Office	10	EA	6	\$1,190	
	Lighting - Pendent/Surface	253B JROTC Office	7	EA	6	\$867	
	Power Distribution	253B JROTC Office	4	EA	7	\$0	
	Storage/ Closet	253B JROTC Office	4	SF	6	\$29	
	Walls - Plaster/Drywall	253B JROTC Office	4	SF	5	\$20	Peeling paint
	Walls - Plaster/Drywall	253B JROTC Office	1,604	SF	6	\$4,427	
	Work SInk	253B JROTC Office	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	253C JROTC Staff Office	247	SF	6	\$855	
	Doors - Transom Window	253C JROTC Staff Office	8	SF	6	\$135	Wood panel
	Doors - Wood Doors inclu hw	253C JROTC Staff Office	1	EA	6	\$301	
	Floor - Wood	253C JROTC Staff Office	247	SF	6	\$1,741	
	Lighting - Pendent/Surface	253C JROTC Staff Office	3	EA	6	\$372	
	Power Distribution	253C JROTC Staff Office	6	EA	7	\$0	
	Storage/ Closet	253C JROTC Staff Office	4	SF	6	\$29	
	Walls - Plaster/Drywall	253C JROTC Staff Office	680	SF	6	\$1,877	
	Ceiling - Plaster/Drywall	Office 153A	330	SF	6	\$1,142	
	Doors - Wood Doors inclu hw	Office 153A	1	EA	6	\$301	
	Floor - Carpet	Office 153A	330	SF	6	\$703	
	Lighting - Pendent/Surface	Office 153A	6	EA	7	\$0	
	Walls - Plaster/Drywall	Office 153A	560	SF	6	\$1,546	
Gymna	sia						
	Ceiling - Plaster/Drywall	251 Gym	2,833	SF	6	\$15,638	
	Ceiling - Plaster/Drywall	251 Gym	3	SF	5		Damaged plaster
	Doors - Steel Doors incl hw	251 Gym	4	EA	6	\$1,204	
	Doors - Transom Window	251 Gym	32	SF	6	\$542	Metal panel
	Floor - Sport Flooring	251 Gym	2,833	SF	6	\$6,117	
	Lighting - Pendent/Surface	251 Gym	15	EA	6	\$1,858	
	Storage/ Closet	251 Gym	438	SF	6	\$3,176	
	Walls - Masonry	251 Gym	3,740	SF	6	\$11,766	
	Ceiling - Plaster/Drywall	253 Wrestling Gym	3	SF	5		Damaged plaster
	Ceiling - Plaster/Drywall	253 Wrestling Gym	2,833	SF	6	\$15,638	- ·
	Doors - Steel Doors incl hw	253 Wrestling Gym	4	EA	6	\$1,204	
		5 ,				. ,	



Building: Addition 2 - Anthony Wing

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ymnasi	ia						
	Doors - Transom Window	253 Wrestling Gym	32	SF	6	\$542	Metal panel
	Floor - Tile/Sheet	253 Wrestling Gym	2,833	SF	6	\$2,836	
	Lighting - Pendent/Surface	253 Wrestling Gym	15	EA	6	\$1,858	
	Storage/ Closet	253 Wrestling Gym	35	SF	6	\$254	
	Walls - Masonry	253 Wrestling Gym	3,738	SF	6	\$11,760	
	Walls - Masonry	253 Wrestling Gym	2	SF	5	\$114	Peeling paint
	Ceiling - Plaster/Drywall	Room 150 Weight Room	2,825	SF	6	\$15,593	
	Doors - Wood Doors inclu hw	Room 150 Weight Room	2	EA	6	\$602	
	Floor - Weight/ Fitness Room Floor Matting	Room 150 Weight Room	2,825	SF	6	\$14,785	
	Lighting - Pendent/Surface	Room 150 Weight Room	56	EA	6	\$6,938	
	Walls - Masonry	Room 150 Weight Room	3,245	SF	6	\$10,209	
ocker/S	Shower Room						
	Accessories	Old locker room	315	SF	6	\$1,234	Does not work
	Ceiling - Exposed	Old locker room	244	SF	6	\$363	Metal ceiling
	Ceiling - Plaster/ Drywall	Old locker room	71	SF	6	\$246	-
	Doors - Steel Doors incl hw	Old locker room	1	EA	6	\$301	
	Floor - Concrete Epoxy/ Painted	Old locker room	244	SF	6	\$129	
	Floor - Tile/Sheet	Old locker room	71	SF	6	\$71	
	Lavatory	Old locker room	3	EA	5	\$11,289	Does not work
	Lighting - Pendent/Surface	Old locker room	3	EA	6	\$372	
	Partitions	Old locker room	1	EA	6	\$297	
	Student Lockers - One Tier	Old locker room	23	EA	5	\$3,224	Damaged
	Urinals	Old locker room	2	EA	5	\$7,788	Does not work
	Walls - Structural Glazed Tile	Old locker room	720	SF	6	\$2,265	
	Walls - Tile Ceramic/ Porcelain	Old locker room	98	SF	6	\$221	
	Water Closet	Old locker room	1	EA	6	\$336	
	Accessories	Old men locker in 250	575	SF	5	\$5,024	Does not work
	Benches, ped mounted	Old men locker in 250	16	LF	6	\$1,742	
	Ceiling - Exposed	Old men locker in 250	447	SF	6	\$665	Metal deck (SF)
	Ceiling - Plaster/ Drywall	Old men locker in 250	128	SF	6	\$443	
	Doors - Wood Doors inclu hw	Old men locker in 250	1	EA	6	\$301	
	Floor Drain	Old men locker in 250	3	EA	6	\$3,177	
	Floor - Concrete Epoxy/ Painted	Old men locker in 250	447	SF	6	\$237	
	Floor - Tile Ceramic/ Porcelain	Old men locker in 250	128	SF	6	\$271	
	Lavatory	Old men locker in 250	2	EA	5	\$7,526	Does not work
	Lighting - Pendent/Surface	Old men locker in 250	8	EA	6	\$991	-
					-	+ ·	



Building: Addition 2 - Anthony Wing

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker	Shower Room						
	Urinals	Old men locker in 250	2	EA	5	\$7,788	Does not work
	Walls - Masonry	Old men locker in 250	389	SF	6	\$1,224	
	Walls - Plaster/Drywall	Old men locker in 250	154	SF	6	\$425	
	Walls - Structural Glazed Tile	Old men locker in 250	650	SF	6	\$2,045	
	Water Closet	Old men locker in 250	1	EA	5	\$3,894	Does not work
	Accessories	Old men locker in 251	575	SF	5	\$5,024	Does not work
	Benches, ped mounted	Old men locker in 251	16	LF	6	\$1,742	
	Ceiling - Exposed	Old men locker in 251	447	SF	6	\$665	Metal deck (SF)
	Ceiling - Plaster/ Drywall	Old men locker in 251	128	SF	6	\$443	
	Doors - Wood Doors inclu hw	Old men locker in 251	1	EA	6	\$301	
	Floor Drain	Old men locker in 251	3	EA	6	\$3,177	
	Floor - Concrete Epoxy/ Painted	Old men locker in 251	447	SF	6	\$237	
	Floor - Tile Ceramic/ Porcelain	Old men locker in 251	128	SF	6	\$271	
	Lavatory	Old men locker in 251	3	EA	5	\$11,289	Does not work
	Lighting - Pendent/Surface	Old men locker in 251	8	EA	6	\$991	
	Showers	Old men locker in 251	2	EA	5	\$5,429	Does not work
	Student Lockers - One Tier	Old men locker in 251	29	EA	6	\$2,692	
	Urinals	Old men locker in 251	4	EA	5	\$15,576	Does not work
	Walls - Masonry	Old men locker in 251	389	SF	6	\$1,224	
	Walls - Plaster/Drywall	Old men locker in 251	154	SF	6	\$425	
	Walls - Structural Glazed Tile	Old men locker in 251	650	SF	6	\$2,045	
	Water Closet	Old men locker in 251	2	EA	5	\$7,788	Does not work
Mecha	nical/ Service Rooms						
	Janitor's Closet	1st Floor	55	SF	6	\$394	
	Storage Room	1st Floor	115	SF	6	\$824	
	Janitor's Closet	2nd Floor	55	SF	6	\$394	
	Storage Room	2nd Floor	115	SF	6	\$824	
Restro	om						
	Accessories	Room 153 Men's Room	195	SF	6	\$1,799	
	Ceiling - Plaster/Drywall	Room 153 Men's Room	205	SF	6	\$709	
	Doors - Wood Doors inclu hw	Room 153 Men's Room	1	EA	6	\$301	
	Floor Drain	Room 153 Men's Room	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	Room 153 Men's Room	205	SF	6	\$434	
	Lavatory	Room 153 Men's Room	2	EA	6	\$639	
	Lighting - Pendent/Surface	Room 153 Men's Room	3	EA	6	\$372	
	Showers	Room 153 Men's Room	1	EA	6	\$311	



Building: Addition 2 - Anthony Wing

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Walls - Plaster/Drywall	Room 153 Men's Room	560	SF	6	\$1,546	
	Water Closet	Room 153 Men's Room	1	EA	6	\$336	
	Accessories	Room 153 Women's room	205	SF	6	\$1,891	
	Ceiling - Plaster/Drywall	Room 153 Women's room	205	SF	6	\$709	
	Doors - Wood Doors inclu hw	Room 153 Women's room	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Room 153 Women's room	205	SF	6	\$434	
	Lavatory	Room 153 Women's room	1	EA	6	\$320	
	Lighting - Pendent/Surface	Room 153 Women's room	1	EA	6	\$124	
	Partitions	Room 153 Women's room	1	EA	6	\$297	
	Student Lockers - One Tier	Room 153 Women's room	36	EA	6	\$3,342	
	Walls - Plaster/Drywall	Room 153 Women's room	560	SF	6	\$1,546	
	Water Closet	Room 153 Women's room	1	EA	6	\$336	
	Accessories	Toilet #1 in 253B	67	SF	6	\$618	
	Ceiling - Plaster/Drywall	Toilet #1 in 253B	67	SF	6	\$232	
	Doors - Wood Doors inclu hw	Toilet #1 in 253B	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Toilet #1 in 253B	67	SF	6	\$142	
	Lavatory	Toilet #1 in 253B	1	EA	6	\$320	
	Lighting - Pendent/Surface	Toilet #1 in 253B	1	EA	6	\$124	
	Partitions	Toilet #1 in 253B	1	EA	6	\$297	
	Walls - Plaster/Drywall	Toilet #1 in 253B	1	SF	6	\$4	Bubbling paint
	Walls - Plaster/Drywall	Toilet #1 in 253B	369	SF	6	\$1,018	
	Water Closet	Toilet #1 in 253B	1	EA	6	\$336	
	Accessories	Toilet #2 in 253B	67	SF	6	\$618	
	Ceiling - Plaster/Drywall	Toilet #2 in 253B	67	SF	6	\$232	
	Doors - Wood Doors inclu hw	Toilet #2 in 253B	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Toilet #2 in 253B	67	SF	6	\$142	
	Lavatory	Toilet #2 in 253B	1	EA	6	\$320	
	Lighting - Pendent/Surface	Toilet #2 in 253B	1	EA	6	\$124	
	Partitions	Toilet #2 in 253B	1	EA	6	\$297	
	Walls - Plaster/Drywall	Toilet #2 in 253B	370	SF	6	\$1,021	
	Water Closet	Toilet #2 in 253B	1	EA	6	\$336	
	Accessories	Toilet in 253C	60	SF	6	\$553	
	Ceiling - Plaster/Drywall	Toilet in 253C	60	SF	6	\$208	
	Doors - Wood Doors inclu hw	Toilet in 253C	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Toilet in 253C	60	SF	6	\$127	
	Lavatory	Toilet in 253C	1	EA	6	\$320	
	Lighting - Pendent/Surface	Toilet in 253C	1	EA	6	\$124	
					U U	÷.=!	



Building: Addition 2 - Anthony Wing

Category: Rooms (Other Than Classrooms)

m Partitions Toilet in 253C	1				
Partitions Toilet in 253C	1				
		EA	6	\$297	
Walls - Plaster/DrywallToilet in 253C	1	SF	5	\$5	Peeling paint
Walls - Plaster/Drywall Toilet in 253C	369	SF	6	\$1,018	
Water Closet Toilet in 253C	1	EA	6	\$336	

Building: Addition 2 - Anthony Wing

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or a second s						
	Ceiling - Lay-in	1st Floor	2	SF	5	\$18	Missing tiles
	Ceiling - Lay-in	1st Floor	7,485	SF	6	\$22,477	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	6	\$317	
	Floor - Tile/Sheet	1st Floor	7	SF	5	\$40	Damaged floor tiles
	Floor - Tile/Sheet	1st Floor	7,480	SF	6	\$4,065	
	Lighting - Lay-in	1st Floor	58	EA	7	\$0	
	Student Lockers - One Tier	1st Floor	209	EA	6	\$19,403	
	Walls - Plaster/Drywall	1st Floor	7,387	SF	6	\$32,747	
	Walls - Structural Glazed Tile	1st Floor	12,484	SF	6	\$39,275	
	Ceiling - Lay-in	2nd Floor	5,890	SF	6	\$17,688	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	6	\$317	
	Floor - Tile/Sheet	2nd Floor	5,890	SF	6	\$3,201	
	Floor - Tile/Sheet	2nd Floor	3	SF	5	\$17	Damaged floor tiles
	Lighting - Lay-in	2nd Floor	38	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	151	EA	6	\$14,018	
	Walls - Plaster/Drywall	2nd Floor	7,387	SF	6	\$32,747	
	Walls - Structural Glazed Tile	2nd Floor	9,885	SF	6	\$31,098	
	Ceiling - Lay-in	2nd Floor	3	SF	5	\$27	Missing tiles
Safety							
	Security Cameras	Entire Building	10	EA	6	\$1,940	
	Security Cameras	Entire Building	1	EA	6	\$194	
Stairs							
	Ceiling - Plaster/Drywall	North	281	SF	6	\$2,057	
	Floor - Terrazzo	North	281	SF	7	\$0	
	Handrails	North	96	LF	6	\$832	



Building: Addition 2 - Anthony Wing

outogory. Bunning interior	Category	: Building In	terior
----------------------------	----------	---------------	--------

outog	ery: Banang moner						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Lighting - Pendent/Surface	North	4	EA	6	\$496	
	Stairs - Terrazzo	North	48	LF	7	\$0	
	Walls - Structural Glazed Tile	North	2,736	SF	6	\$8,607	
	Ceiling - Plaster/Drywall	South	281	SF	6	\$2,057	
	Floor - Terrazzo	South	281	SF	7	\$0	
	Handrails	South	64	LF	6	\$555	
	Lighting - Pendent/Surface	South	3	EA	6	\$372	
	Stairs - Terrazzo	South	32	LF	7	\$0	
	Walls - Structural Glazed Tile	South	2,736	SF	6	\$8,607	
/ertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	\$19,238	
Buildi	ng Interior Subtotal:					\$262,409	
Total	Building Cost				\$	3,153,181	
Buildi	ng: Hangar Building						
Categ	ory: Building Exterior						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	ce in the second se						
	Exterior Doors - Exterior Steel Door	#43 SE	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#44 SW	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#45 SW	1	EA	6	\$481	

	Exterior Doors - Overhead Rolling/ Garage Door	#46 OHD SW	1	EA	5	\$3,942	Damaged
	Exterior Doors - Overhead Rolling/ Garage Door	#49 OHD NE	1	EA	6	\$1,433	
	Exterior Stairs - Concrete	#43 SE	6	LF	6	\$491	
Found	ation						
	Foundation - Concrete	Entire Building	626	LF	7	\$0	
	Superstructure - Heavy Timber	Entire Building	26,320	SF	7	\$0	
Lightin	g						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	6	\$4,829	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	\$2,599	

ΕA

ΕA

6

6

6

\$481

\$481

\$481

1

1

1 EA

#47 SW

#48 NE

#50 NE

Exterior Doors - Exterior Steel Door

Exterior Doors - Exterior Steel Door

Exterior Doors - Exterior Steel Door



Building: Hangar Building

Category: Building Exterior

	Kom Tuno	Leastic	Oursetter	l la it	Denla	Oraci	Commonto
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ighting]						
oof Sy	stem						
	Chimney - Metal Flue	SE Low Roof	21	LF	6	\$3,321	
	Coping - Metal	Main Roof	334	LF	5	\$14,118	Rust
	Coping - Stone	Main Roof	254	LF	5	\$27,815	Need tuck pointing
	Coping - Stone	NW Low Roof	175	LF	5	\$19,164	
	Coping - Stone	SE Low Roof	175	LF	5	\$19,164	Need tuck pointing
	Downspouts - Interior Downspouts	Main Roof	120	LF	6	\$3,988	
	Downspouts - Interior Downspouts	NW Low Roof	40	LF	5	\$8,852	
	Downspouts - Interior Downspouts	SE Low Roof	40	LF	5	\$8,852	
	Parapet - 16" - 30" Height	Main Roof	588	LF	5	\$101,733	Need tuck pointing
	Parapet - 16" - 30" Height	NW Low Roof	175	LF	5	\$30,278	
	Parapet - 16" - 30" Height	SE Low Roof	175	LF	5	\$30,278	
	Roof Structure - Heavy Timber	Main Roof	21,446	SF	7	\$0	
	Roof Structure - Heavy Timber	NW Low Roof	2,980	SF	7	\$0	
	Roof Structure - Heavy Timber	SE Low Roof	3,038	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	NW Low Roof	2,980	SF	4	\$83,523	Worn and leaking
	Roof - Asphalt Gravel Ballast	SE Low Roof	3,038	SF	4	\$85,149	Worn and leaking
	Roof - Modified Bitumen	Main Roof	21,446	SF	4	\$587,901	Worn and leaking
alls							
	Exterior Walls - Brick	Entire Building	13,935	SF	5	\$247,693	Ned tuck pointing
indow	/S						
	Clerestory - Glass Single-Pane	Entire Building	420	SF	4	\$63,555	Rotted and broken
	Lintels - Steel	Entire Building	284	LF	7	\$0	
	Lintels - Stone	Entire Building	212	LF	6	\$0	
	Windows - Sash Lexan	Entire Building	416	SF	6	\$3,105	
uildi	ng Exterior Subtotal:				\$	1,355,150	
Buildi	ng: Hangar Building						
Catego	ory: Electrical System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
merge	ncy System						
	Emergency Battery Packs - Multipurpose Room	Entire Building	5	EA	6	\$1,013	

Exit Signs - Multipurpose Room

Security System - Intrusion Detection

5 EA

26,320 SF

2

6

\$6,775

Entire Building

Entire Building

\$2,727 Exit signs have no emergency backup power.



Building: Hangar Building

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Main Se	ervice						
	Main Electrical Service- Live Front - 800 A and Less than 277/480/3PH	Mechanical Room	1	EA	7	\$0	
Power I	Distribution						
	Lighting and Power Panels - 100 A	Electrical and Mechanical Rooms / Electrical Room	1	EA	4	\$4,849	Emergency fuse panel has more than 45 years of service and is significantly deteriorated.
	Lighting and Power Panels - 100 A	Electrical and Mechanical Rooms / Mechanical Room	1	EA	4	\$4,849	Panel has more than 45 years of service and is significantly deteriorated.
	Lighting and Power Panels - 100 A	Electrical and Mechanical Rooms / Mechanical Room	3	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Electrical and Mechanical Rooms / Mechanical Room	3	EA	2	\$19,733	Panels have more than 55 years of service and are substantially deteriorated.
	Lighting and Power Panels - Above 100 A	Electrical and Mechanical Rooms / Mechanical Room	1	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Electrical and Mechanical Rooms / Electrical Room	1	EA	7	\$0	
	Transformers - 277/480 - 120/208	Electrical and Mechanical Rooms / Electrical Room	1	EA	6	\$1,265	

\$41,212

Electrical System Subtotal:

Building: Hangar Building Category: Safty System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ire Alarm						
Fire Alarm Panel	Boiler Room	1	EA	3	\$49,477	Fire Panel was installed over 55 years ago and is not working.
Fire Alarm_System	Boiler Room / Entire Building	26,320	SF	4	\$52,316	Fire protection system is not working and has no functioning panel.
Safty System Subtotal:					\$101,793	

Safty System Subtotal:

Building: Hangar Building

Group Item - Type	Location	Quantity Unit Rank	Cost	Comments
Boiler Systems				
Boiler Auxiliary- Steam Boiler - 50 - 75 HP	Boiler Room	2 EA 6	\$4,093	
Chemical Feed System	Boiler Room	1 EA 4	\$6,987	Chemicals are poured in manually into the boiler feed water tank.
Combustion Dampers	Boiler Room	2 EA 5	\$5,104	
Condensate Pump	Boiler Room / 1st Floor	1 EA 6	\$2,021	



Building: Hangar Building

Category: Mechanical System

Group							
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler S	systems						
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	\$2,545	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Steam Boiler - 50 - 75 HP	Boiler Room	2	EA	6	\$4,093	
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	400	LF	6	\$755	
	Steam Traps	Boiler Room / Entire Building	17	EA	5	\$22,353	
Heating	Devices						
	Radiators - Steam	Entire Building	3	EA	5	\$5,026	Manual control.
	Unit Heater - Steam	Entire Building	13	EA	6	\$3,611	
	Wall Heater - Electric	Entire Building	2	EA	6	\$278	
Mechan	ical Plumbing						
	Condensate-Steel or Galvanized	Entire Building	400	LF	6	\$30,711	
Temper	ature Control						
	Electric Controls	Entire Building	26,320	SF	6	\$0	
	Electric Thermostat	Entire Building	13	EA	6	\$0	Thermostats control unit heaters
Jnit Ve	ntilation						
	Unit Ventilators- Ceiling Mounted- Electric Heating & DX Cooling Coil	Office / 2nd Floor	1	EA	6	\$1,248	
	W/ Self Contained Compressor						
/entilat	·						
Ventilat	·	Roof	2	EA	4	\$12,784	Fans are deteriorating and running loud.
Ventilat Mecha	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	4		Fans are deteriorating and running loud.
	ion	Roof	2	EA	4	\$12,784 \$101,609	Fans are deteriorating and running loud.
Mecha	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	4		Fans are deteriorating and running loud.
Mecha Buildi	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal: ng: Hangar Building	Roof	2	EA	4		Fans are deteriorating and running loud.
Mecha Buildi Categ	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal:	Roof	2 Quantity			\$101,609	Fans are deteriorating and running loud.
Mecha Buildi Categ Group	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal: ng: Hangar Building ory: Plumbing System Item - Type					\$101,609	
Mecha Buildi Categ Group	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal: ng: Hangar Building ory: Plumbing System Item - Type					\$101,609	
Mecha Buildi Categ Group Hot Wat	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal: ng: Hangar Building ory: Plumbing System Item - Type ter	Location	Quantity	Unit	Rank	\$101,609 Cost	
Mecha Buildi Categ Group Hot Wat	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal: ng: Hangar Building ory: Plumbing System Item - Type ter	Location	Quantity	Unit	Rank	\$101,609 Cost	
Mecha Buildi Categ	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal: ng: Hangar Building ory: Plumbing System Item - Type ter Gas Heater - Less than 150000 BTU/HR	Location Boiler Room	Quantity 1	Unit EA	Rank	\$101,609 Cost \$310	
Mecha Buildi Categ Group Hot Wat	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal: ng: Hangar Building ory: Plumbing System Item - Type ter Gas Heater - Less than 150000 BTU/HR Domestic Piping-Cold Water Horizontal Lines	Location Boiler Room Entire Building	Quantity 1 26,320	Unit EA SF	Rank 6	\$101,609 Cost \$310 \$6,398	
Mecha Buildi Categ Group Hot Wat	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal: ng: Hangar Building ory: Plumbing System Item - Type ter Gas Heater - Less than 150000 BTU/HR Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Horizontal Lines	Location Boiler Room Entire Building Entire Building	Quantity 1 26,320 26,320	Unit EA SF SF	Rank 6 6 6 6	\$101,609 Cost \$310 \$6,398 \$6,398	
Mecha Buildi Categ Group Hot Wat	ion Exhaust Fans- Roof Mounted - 1501 - 8000 CFM anical System Subtotal: ng: Hangar Building ory: Plumbing System Item - Type ter Gas Heater - Less than 150000 BTU/HR Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Hot Water Return Lines	Location Boiler Room Entire Building Entire Building Entire Building	Quantity 1 26,320 26,320 26,320	Unit EA SF SF SF	Rank 6 6 6 6 6	\$101,609 Cost \$310 \$310 \$6,398 \$6,398 \$3,764	



Building: Hangar Building

Category: Plumbing System Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Piping Vent Piping	Entire Building	26,320 SF 6	\$17,690
Plumbing System Subtotal:		\$1	05,695

Building: Hangar Building

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Lay-in	2nd Floor	716	SF	6	\$2,150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Carpet	2nd Floor	716	SF	6	\$1,526	
	Lighting - Lay-in	2nd Floor	5	EA	6	\$595	
	Power Distribution	2nd Floor	2	EA	7	\$0	
	Walls - Masonry	2nd Floor	625	SF	6	\$1,966	
	Walls - Plaster/Drywall	2nd Floor	1,231	SF	6	\$3,397	
Mechar	nical/ Service Rooms						
	Boiler Room	1st Floor	893	SF	6	\$6,398	
	Mechanical/ Service Rooms	1st Floor	20,535	SF	6	\$147,119	Hanger area
	Mechanical/ Service Rooms	1st Floor	279	SF	6	\$1,999	Switchgear
	Storage Room	1st Floor	2,855	SF	6	\$20,454	Yard Storage, Key room, #4, #7
	Storage Room	2nd Floor	2,148	SF	6	\$15,389	#5, #6 #10
Restro	om						
	Accessories	Men's Toilet	211	SF	6	\$1,946	
	Benches	Men's Toilet	6	LF	6	\$87	
	Ceiling - Plaster/Drywall	Men's Toilet	211	SF	6	\$730	
	Doors - Wood Doors inclu hw	Men's Toilet	1	EA	6	\$301	
	Floor - Tile/Sheet	Men's Toilet	211	SF	6	\$211	
	Lavatory	Men's Toilet	3	EA	6	\$959	
	Lighting - Pendent/Surface	Men's Toilet	4	EA	6	\$496	
	Partitions	Men's Toilet	3	EA	6	\$891	
	Urinals	Men's Toilet	2	EA	6	\$672	
	Walls - Tile Ceramic/ Porcelain	Men's Toilet	577	SF	6	\$1,304	
	Water Closet	Men's Toilet	3	EA	6	\$1,008	
	Accessories	Women's Toilet	246	SF	6	\$2,269	
	Benches	Women's Toilet	6	LF	6	\$87	
	Ceiling - Plaster/Drywall	Women's Toilet	246	SF	6	\$851	



Building: Hangar Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost Comments			
Restro	stroom								
	Doors - Wood Doors inclu hw	Women's Toilet	1	EA	6	\$301			
	Floor - Tile/Sheet	Women's Toilet	246	SF	6	\$246			
	Lavatory	Women's Toilet	3	EA	6	\$959			
	Lighting - Pendent/Surface	Women's Toilet	4	EA	6	\$496			
	Partitions	Women's Toilet	3	EA	6	\$891			
	Student Lockers - One Tier	Women's Toilet	2	EA	6	\$186			
	Urinals	Women's Toilet	2	EA	6	\$672			
	Walls - Tile Ceramic/ Porcelain	Women's Toilet	658	SF	6	\$1,487			
	Water Closet	Women's Toilet	3	EA	6	\$1,008			

Rooms (Other Than Classrooms) Subtotal:

\$219,350

Building: Hangar Building

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Floor - Tile/Sheet	1st Floor	36	SF	6	\$20	
	Handrails	1st Floor	18	LF	6	\$156	
	Stairs - Tile	1st Floor	17	LF	6	\$158	
	Walls - Masonry	1st Floor	350	SF	6	\$1,101	
Buildir	ng Interior Subtotal:					\$1,434	
Total E	Building Cost				\$1	,926,242	
SITE							

Category: Site

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
hletic						
Surface - Natural	East Courtyard	97,259	SF	6	\$80,667	
vil/Drainage						
Civil/ Drainage - Catch Basin	Entire Site	18	EA	6	\$19,689	
Civil/ Drainage - Site Drain	Entire Site	3	EA	6	\$931	
Civil/ Drainage - Site Manhole	Entire Site	57	EA	6	\$85,087	



SITE

Category: Site

ncing							Comments
	Fencing - Chain Link	Entire Site	5,781	LF	6	\$108,543	
	Fencing - New Standard Ornamental	Entire Site	1,847	LF	6	\$58,925	South perimeter
ndsca	pe						
	Benches	Entire site / Central Courtyard	4	EA	6	\$1,720	
	Landscape - Grass	Entire site	313,779	SF	6	\$260,248	
	Landscape - Hardscape- Concrete	Entire site	32,833	SF	6	\$169,494	
	Landscape - Hardscape- Pavers	Entire site / Central Courtyard	298	SF	6	\$1,688	
	Parkway trees	Entire site	54	EA	6	\$35,642	
	Planting Beds/ Area	Entire site	6,580	SF	6	\$10,821	
	Retaining Wall - Concrete	Entire site / West Entrances	154	SF	6	\$3,609	
	Trash Receptacles	Entire site	2	EA	6	\$625	
rking l	Lot						
	Lighting - Pole Mounted	Parking Lot- North	2	EA	6	\$2,905	
	Surface - Asphalt	Parking Lot- North	76,382	SF	4	\$602,929	Cracks and potholes
	Surface - Concrete	Parking Lot- North	44,089	SF	5	\$483,573	Cracks
	Surface - Concrete	Parking Lot- North	98,685	SF	4	\$1,456,354	Major cracks
	Trash Compactor	Parking Lot- North	1	EA	6	\$0	West of boiler house
dewalk	S						
	Sidewalks - Internal Walks	Entire Site	689	LF	6	\$8,276	
	Sidewalks - Internal Walks	Entire Site	425	LF	4	\$33,536	Major cracks and displacements
	Sidewalks - Perimeter Sidewalks	Entire Site	71,462	SF	6	\$142,045	
	Sidewalks - Perimeter Sidewalks	Entire Site	8,600	SF	4	\$112,404	Major cracks and displacements
gnage							
	Flag Pole - Flag Pole	Entire Site / South Courtyard	1	EA	7	\$0	
	Marquee - Free Standing Back Lighted	Entire Site / South East	1	EA	6	\$0	
	Marquee - Free Standing Back lighted w/ LED	Entire Site / South Courtyard	1	EA	6	\$0	
ite Su	ibtotal:				\$	3,679,710	
otal S	ite Cost				\$	3,679,710	
<u></u>	us Total ^{2 3}				¢72	265,580	



¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main														1
Carpentry	Other Instructional Use	1st Floor	144	144	2,759	0	0	6	665	133	40	Ν	Ν	Ν
Choral Room	Choral Room	3rd Floor	326	326	1,687	1	2	10	204	193	40	Ν	Ν	N
Computer Lab	Computer Lab	1st Floor	120	120	1,317	1	30	66	280	50	40	Ν	Y	Y
Computer Lab	Regular Classroom	3rd Floor	338	338	2,106	0	6	22	180	159	40	Ν	Ν	N
Laboratory/Shop	Laboratory/Shop	1st Floor	016 & 018	016 & 018	6,820	3	12	80	900	450	40	Ν	Ν	N
Music Room	Music Room	3rd Floor	317 Band room	317	2,666	0	0	7	228	208	40	Ν	Y	N
Other Instructional Use	Other Instructional Use	1st Floor	142	142	2,759	1	0	6	665	133	40	Ν	Ν	N
Other Instructional Use	Regular Classroom	2nd Floor	238	238	2,050	2	28	60	216	208	40	Ν	Ν	Y
Other Instructional Use	Other Instructional Use	3rd Floor	328	328	1,026	1	2	66	144	136	40	Ν	Ν	N
Regular Classroom	Regular Classroom	1st Floor	002	002	2,750	0	0	158	308	116	40	Ν	Ν	Y
Regular Classroom	Regular Classroom	1st Floor	004	004	650	4	4	10	59	75	40	Ν	Ν	N
Regular Classroom	Regular Classroom	1st Floor	011	011	503	1	2	6	105	21	40	Ν	Ν	N
Regular Classroom	Regular Classroom	1st Floor	014	014	735	1	18	36	175	35	40	Ν	Y	N
Regular Classroom	Regular Classroom	1st Floor	020	020	503	1	2	6	105	21	40	Ν	N	N
Regular Classroom	Regular Classroom	1st Floor	021	021	503	1	2	6	105	21	40	Ν	Ν	Ν
Regular Classroom	Store Room	1st Floor	116	storeroom	496	1	3	10	81	73	40	Ν	N	N
Regular Classroom	Regular Classroom	1st Floor	121	121	735	1	18	36	175	35	40	Ν	Y	N
Regular Classroom	Regular Classroom	1st Floor	123	123	735	1	18	36	175	35	40	Ν	Y	N
Regular Classroom	Regular Classroom	1st Floor	139	139	760	1	2	15	175	35	40	Ν	Y	Y
Regular Classroom	Regular Classroom	1st Floor	140	140	780	1	2	10	140	28	40	Ν	Ν	N
Regular Classroom	Regular Classroom	1st Floor	141	141	760	1	2	15	175	35	40	Ν	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	221	221	732	2	8	30	110	65	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	225	225	680	2	8	30	110	65	40	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	1,792	2	28	60	350	200	40	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	1,050	2	12	30	300	150	40	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	230	230	1,050	2	12	30	300	150	40	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	234	234	1,000	2	12	36	180	90	40	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	236	236	1,000	2	12	36	180	90	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	239	239	732	2	8	30	110	65	40	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	241	241	732	2	8	30	110	65	40	Ν	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	243	243	688	2	8	30	110	65	40	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	321	321	735	1	2	9	79	34	40	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	323	321	735	1	2	9	79	34	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	327	327	664	1	2	10	75	70	40	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	329	329	698	1	1	10	75	70	40	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	331	331	750	1	2	10	75	70	40	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	333	333	695	1	2	10	75	70	40	Ν	N	Ν



Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main	+	-					1	•		ł	4	ł		+
Regular Classroom	Regular Classroom	3rd Floor	334	334	1,026	0	16	46	144	136	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	335	335	664	1	2	10	75	70	40	Ν	Ν	Ν
Regular Classroom	Art Room	3rd Floor	336	336	1,026	0	6	22	144	136	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	337	337	704	1	1	8	75	70	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	339	339	735	1	2	9	79	34	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	344	344	1,718	1	1	18	48	45	40	Ν	Ν	Ν
Science Classroom	Science	1st Floor	009	009	985	1	2	10	210	42	40	N	Ν	Ν
Science Classroom	Science	1st Floor	010	010	985	1	2	10	210	42	40	Ν	Ν	Ν
Science Classroom	Science	1st Floor	012	012	985	1	2	10	210	42	40	N	Ν	Ν
Science Classroom	Science Classroom	1st Floor	013	013	985	1	2	30	210	42	40	N	Ν	Ν
Science Lab Level 2	Science Lab Level 2	1st Floor	136	136	1,002	1	0	18	171	36	40	N	Ν	Ν
Science Lab Level 2	Science Lab Level 2	1st Floor	145	145	1,002	1	0	18	171	36	40	N	Ν	Ν
Science Lab Level 3	Science Lab Level 3	1st Floor	019	019	1,001	0	1	10	210	42	40	Ν	Y	Ν
Science Lab Level 3	Science Lab Level 3	1st Floor	022	022	1,002	1	2	10	210	42	40	N	Ν	Ν
Science Lab Level 3	Science Lab Level 3	1st Floor	023	023	1,002	1	2	10	210	42	40	N	Ν	Ν
Science Lab Level 3	Science Lab Level 3	1st Floor	024	024	1,002	1	2	10	210	42	40	N	Ν	Ν
Store Room	Regular Classroom	2nd Floor	219	219	1,053	2	12	30	132	78	40	N	Ν	Ν
Store Room	Computer Lab	2nd Floor	222	222	1,386	1	6	60	132	78	40	N	Ν	Ν
Store Room	Regular Classroom	2nd Floor	242	242	1,000	2	12	36	180	90	40	Ν	Ν	Ν
Store Room	Regular Classroom	3rd Floor	320	320	1,386	1	3	12	132	78	40	Ν	Ν	Ν
Store Room	Regular Classroom	3rd Floor	325	325	704	1	2	10	75	70	40	Ν	Ν	Ν
Vacant	Regular Classroom	1st Floor	008	008	1,970	0	0	158	308	116	40	Ν	Ν	Ν
Vacant	Regular Classroom	2nd Floor	223	223	732	2	8	30	110	65	40	Ν	Ν	Ν
Vacant	Regular Classroom	2nd Floor	244	244	1,000	2	12	36	180	90	40	Ν	Ν	Ν
Vacant	Regular Classroom	2nd Floor	245	245	688	2	8	30	110	65	40	Ν	Ν	Ν
Vacant	Regular Classroom	3rd Floor	330	330	1,026	1	2	9	144	136	40	Ν	Ν	Ν
Vacant	Regular Classroom	3rd Floor	341	341	735	1	2	9	79	34	40	Ν	Ν	Ν
Vacant	Health	2nd Floor	342	342	1,149	0	0	14	215	0	40	Ν	Ν	Ν
Addition 1														
Art Room	Art Room	2nd Floor	215A	512	1,233	1	4	16	99	44	40	Ν	Ν	Ν
Art Room	Art Room	2nd Floor	215B	215	1,233	1	4	16	99	44	40	Ν	Ν	Ν
Computer Lab	Computer Lab	2nd Floor	203	203	2,792	2	15	60	840	320	40	Ν	Ν	Ν
Computer Lab	Regular Classroom	2nd Floor	205B	205	1,244	1	8	26	480	160	40	Ν	Ν	Y
Other Instructional Use	Cosmetology	1st Floor	104 cosmotology	104	2,794	0	0	158	308	116	40	N	Ν	Y
Other Instructional Use	Regular Classroom	1st Floor	108	110	640	1	8	21	60	83	40	N	Ν	N
Other Instructional Use	Other Instructional Use	1st Floor	110	112	1,526	0	0	14	142	75	40	Ν	Ν	Ν



Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Addition 1				*										+
Other Instructional Use	Regular Classroom	4th Floor	205C	205	843	1	8	26	480	160	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	101	101	647	4	4	10	59	75	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	102	102	647	4	4	10	59	75	40	Ν	Ν	Ν
Regular Classroom	Other Instructional Use	1st Floor	103A	103	843	1	8	26	178	83	40	Ν	Ν	Ν
Regular Classroom	Other Instructional Use	1st Floor	103B	103	843	1	7	26	160	75	40	Ν	Ν	Ν
Regular Classroom	Other Instructional Use	1st Floor	105	105	2,803	0	31	64	338	158	40	Ν	Y	Ν
Regular Classroom	Other Instructional Use	1st Floor	106	108	2,795	0	0	26	338	158	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	107	107	650	1	8	21	60	83	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	109	109	2,803	0	31	64	338	158	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	111	111	650	1	8	21	60	83	40	Ν	Ν	Ν
Regular Classroom	Other Instructional Use	1st Floor	114	116	844	1	8	32	142	128	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	201	201	650	1	8	21	140	83	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	202	202	650	1	8	21	140	83	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	204A	204/206	843	1	6	30	162	75	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	204B	204/206	843	1	6	30	162	75	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	207	207	650	1	8	21	140	83	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	209A	209	2,792	2	16	26	840	320	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	211	211	650	1	8	21	140	83	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	212	212	839	1	8	21	196	116	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	213B	213	1,124	1	8	26	480	160	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	214	214	717	1	8	21	140	83	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	216A	216	656	1	8	16	99	44	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	216B	216	656	1	8	16	99	44	40	Ν	Ν	Ν
Science Classroom	Science Classroom	2nd Floor	213A	213	1,080	1	8	26	480	160	40	Ν	Ν	Ν
Science Lab Level 1	Science Lab Level 1	2nd Floor	208A	208	2,794	2	16	60	308	150	40	Ν	Ν	Y
Vacant	Regular Classroom	2nd Floor	210	210	650	1	8	21	140	83	40	Ν	Ν	Ν
Addition 2 - Antho	ony Wing													
Other Instructional Use	Other Instructional Use	1st Floor	157	157	2,800	1	8	24	900	133	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	149	149	679	1	8	22	140	28	50	N	Ν	N
Regular Classroom	Regular Classroom	1st Floor	151	151	2,813	1	4	30	665	133	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	153	153	2,813	1	8	30	665	133	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	154	154	635	1	6	16	175	35	50	Ν	Y	N
Regular Classroom	Regular Classroom	1st Floor	155	155	660	1	8	24	175	35	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	247	249	679	1	8	22	140	28	50	N	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	250	250	2,808	1	1	16	770	154	50	N	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	254	254	663	1	8	22	175	35	50	N	Ν	N



Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Addition 2 - Antho	Addition 2 - Anthony Wing													
Regular Classroom	Regular Classroom	2nd Floor	255	255	660	1	6	22	175	35	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	256A	256	2,759	1	1	8	665	133	50	Ν	Ν	Ν
Regular Classroom	Other Instructional Use	2nd Floor	257A	257	2,800	1	8	34	950	133	50	Ν	Ν	Ν
Store Room	Regular Classroom	1st Floor	156	156	2,825	1	8	16	665	133	50	N	Y	Ν