

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1934	4	384,200	\$13,752,211
6-Classroom Modular	0	1	7,060	\$240,971
6-Classroom Modular	0	1	7,060	\$240,759
SITE				\$1,849,288
Campus Total			398,320	\$16,083,228

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
	Entrance Control - Audio and Video	#1- E- Main	1	EA	6	\$702	
	Entrance Control - Audio and Video	#7- NW	1	EA	6	\$702	
	Exterior Doors - Exterior AMP Door	#1- E- Main	6	EA	6	\$4,044	
	Exterior Doors - Exterior AMP Door	#18- SE	2	EA	6	\$1,348	
	Exterior Doors - Exterior AMP Door	#2- NE	2	EA	6	\$1,348	
	Exterior Doors - Exterior FRP Door	#10- SW	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#11- SW	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#12- S	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#17- S	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#3- N	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#4- NE	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#5- NE- BR	1	EA	6	\$631	
	Exterior Doors - Exterior FRP Door	#6- NW	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#7- NW	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#8- NW	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#9- W	2	EA	6	\$1,263	
	Exterior Doors - Exterior Steel Door	#4.2- Garage	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Roof access doors	5	EA	6	\$2,403	

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
	Exterior Doors - Overhead Rolling/ Garage Door	#2.5- N- Book Rm #115	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	#4.1- Garage	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	#4.3- Garage	1	EA	6	\$1,433	
	Exterior Doors - Side lite	#5- NE- BR	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#1- E- Main	6	EA	6	\$1,880	
	Exterior Doors - Transom Lite	#10- SW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#11- SW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#12- S	4	EA	6	\$1,253	
	Exterior Doors - Transom Lite	#17- S	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#18- SE	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#2- NE	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#2.5- N- Book Rm #115	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#3- N	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#4- NE	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#6- NW	4	EA	6	\$1,253	
	Exterior Doors - Transom Lite	#7- NW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#8- NW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#9- W	4	EA	6	\$1,253	
	Exterior Stairs - Concrete	#1- E- Main	370	LF	6	\$30,254	
	Exterior Stairs - Concrete	#18- SE	128	LF	6	\$10,466	
	Exterior Stairs - Concrete	#2- NE	48	LF	6	\$3,925	
	Exterior Stairs - Concrete	#2- NE	80	LF	5	\$8,766	spalling
	Exterior Stairs - Concrete	#3- N	10	LF	5	\$1,096	cracks
	Exterior Stairs - Stone	#1- E- Main	24	LF	6	\$2,712	
	Exterior Stairs - Stone	#17- S	88	LF	5	\$23,863	open joints & cracks
	Exterior Stairs - Stone	#18- SE	6	LF	6	\$678	
	Exterior Stairs - Stone	#2- NE	6	LF	6	\$678	
	Exterior Stairs - Stone	#3- N	80	LF	6	\$9,039	
	Stair Handrail - Steel_Stair Handrail	#1- E- Main	100	LF	6	\$867	
	Stair Handrail - Steel_Stair Handrail	#17- S	10	LF	6	\$87	
	Stair Handrail - Steel_Stair Handrail	#18- SE	33	LF	6	\$286	
	Stair Handrail - Steel_Stair Handrail	#2- NE	32	LF	6	\$277	
	Stair Handrail - Steel_Stair Handrail	#3- N	8	LF	6	\$69	
Foundation							
	Foundation - Concrete	Entire Building	2,050	LF	7	\$0	
	Foundation - Concrete	Entire Building	20	LF	6	\$3,884	Seepage
	Foundation - Concrete	Entire Building	40	LF	6	\$7,769	Seepage

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Foundation							
	Foundation - Concrete	Entire Building	10	LF	6	\$0	Seepage
	Foundation - Concrete	Entire Building	10	LF	6	\$0	Seepage
	Superstructure - Steel with Clay Tile Arch	Entire Building	384,120	SF	7	\$0	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	13	EA	6	\$6,975	
	Exterior Lighting - Wall Mounted	Entire Building	44	EA	6	\$12,705	
Roof System							
	Cell Tower	N Roof	1	EA	6	\$736	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	N Roof	140	LF	6	\$133,656	No liner, has straps
	Coping - Metal	Service Garage Roof	116	LF	6	\$3,726	
	Coping - Stone	Center Roof	408	LF	6	\$13,104	
	Coping - Stone	E Roof	335	LF	6	\$10,759	
	Coping - Stone	Green House Roof	110	LF	6	\$3,533	
	Coping - Stone	Low S Roof	50	LF	6	\$1,606	
	Coping - Stone	N Roof	1,078	LF	6	\$34,623	
	Coping - Stone	S Roof	1,080	LF	6	\$34,687	
	Coping - Stone	W Roof	805	LF	6	\$25,855	
	Downspouts - Exterior Downspouts	Service Garage Roof	10	LF	6	\$332	
	Downspouts - Interior Downspouts	Center Roof	208	LF	6	\$6,913	
	Downspouts - Interior Downspouts	E Roof	256	LF	6	\$8,508	
	Downspouts - Interior Downspouts	Green House Roof	34	LF	6	\$1,130	
	Downspouts - Interior Downspouts	Low S Roof	10	LF	6	\$332	
	Downspouts - Interior Downspouts	N Courtyard Roof	40	LF	6	\$1,329	
	Downspouts - Interior Downspouts	N Roof	312	LF	6	\$10,369	
	Downspouts - Interior Downspouts	S Courtyard Roof	40	LF	6	\$1,329	
	Downspouts - Interior Downspouts	S Roof	312	LF	6	\$10,369	
	Downspouts - Interior Downspouts	W Roof	384	LF	6	\$12,762	
	Parapet - 16" - 30" Height	Center Roof	408	LF	6	\$16,301	
	Parapet - 16" - 30" Height	E Roof	305	LF	6	\$12,186	
	Parapet - 16" - 30" Height	Green House Roof	110	LF	6	\$4,395	
	Parapet - 16" - 30" Height	Low S Roof	50	LF	6	\$1,998	
	Parapet - 16" - 30" Height	N Roof	968	LF	6	\$38,676	
	Parapet - 16" - 30" Height	S Roof	970	LF	6	\$38,756	
	Parapet - 16" - 30" Height	W Roof	665	LF	6	\$26,570	
	Parapet - Parapet > 30"	E Roof	30	LF	6	\$1,918	
	Parapet - Parapet > 30"	N Roof	110	LF	6	\$7,031	

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof System							
	Parapet - Parapet > 30"	S Roof	110	LF	6	\$7,031	
	Parapet - Parapet > 30"	W Roof	140	LF	6	\$8,949	
	Roof Structure - Steel with Clay Tile Arch	Center Roof	10,110	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	E Roof	6,167	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Green House Roof	690	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Low S Roof	136	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	N Courtyard Roof	1,782	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	N Roof	27,158	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	S Courtyard Roof	1,782	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	S Roof	25,926	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Service Garage Roof	835	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	W Roof	25,055	SF	7	\$0	
	Roof - Modified Bitumen	Center Roof	10,110	SF	6	\$95,129	
	Roof - Modified Bitumen	E Roof	6,167	SF	6	\$58,028	
	Roof - Modified Bitumen	Green House Roof	690	SF	6	\$6,492	Not accessible
	Roof - Modified Bitumen	Low S Roof	136	SF	6	\$1,280	Not accessible
	Roof - Modified Bitumen	N Courtyard Roof	1,782	SF	6	\$16,768	
	Roof - Modified Bitumen	N Roof	27,158	SF	6	\$255,540	Some minor water ponding
	Roof - Modified Bitumen	S Courtyard Roof	1,782	SF	6	\$16,768	Off Room 227
	Roof - Modified Bitumen	S Roof	25,926	SF	6	\$243,948	
	Roof - Modified Bitumen	Service Garage Roof	835	SF	6	\$7,857	
	Roof - Modified Bitumen	W Roof	25,055	SF	6	\$235,753	Some water ponding
Walls							
	Cheek-Wall - Concrete	Entire Building	64	SF	6	\$656	
	Cheek-Wall - Concrete	Entire Building	32	SF	6	\$328	
	Cheek-Wall - Concrete	Entire Building	32	SF	6	\$328	
	Cheek-Wall - Stone	Entire Building	80	SF	5	\$1,904	Gaps
	Cheek-Wall - Stone	Entire Building	80	SF	6	\$820	
	Cheek-Wall - Stone	Entire Building	208	SF	6	\$2,133	
	Cheek-Wall - Stone	Entire Building	80	SF	6	\$820	
	Cheek-Wall - Stone	Entire Building	80	SF	6	\$820	
	Cornice - Masonry Projecting Limestone	Entire Building	2,050	LF	6	\$71,089	
	Exterior Walls - Brick	Entire Building	4	SF	5	\$95	Vertical cracking at pler
	Exterior Walls - Brick	Entire Building	106,600	SF	6	\$716,459	
	Exterior Walls - Stone-Cast	Entire Building	4,100	SF	6	\$27,556	Some open joints
	Exterior Walls - Stone-Cast	Entire Building	4	SF	4	\$726	Spalling
	Exterior Walls - Stone-Cut	Entire Building	2,900	SF	6	\$19,491	Stone sills at windows

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Walls							
Windows							
	Guard - Guards perforated	Entire Building / 1st Floor	9,548	SF	6	\$121,927	Some rust occurring
	Lintels - Steel	Entire Building	3,388	LF	6	\$98,350	
	Lintels - Stone	Entire Building	696	LF	6	\$0	
	Skylite - Glass Double-Pane	Entire Building	450	SF	6	\$10,753	
	Skylite - Glass Single-Pane	Entire Building	190	SF	6	\$4,540	
	Skylite - Glass Single-Pane	Entire Building	168	SF	6	\$4,014	
	Windows - Decorative	Entire Building	260	SF	6	\$1,941	
	Windows - Sash Aluminum Double-pane	Entire Building	31,467	SF	6	\$234,889	
	Windows - Wood- Double-pane	Entire Building	912	SF	6	\$6,808	

Building Exterior Subtotal:

\$2,908,678

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System							
	Automatic Transfer Switch	Basement	1	EA	6	\$408	Location: Storage Room
	Automatic Transfer Switch	Basement	1	EA	6	\$408	Location: Storage Room
	Emergency A/C Power - Auditorium and Aisle Lighting	Entire Building / 1st Floor	2,711	SF	6	\$1,434	
	Emergency A/C Power - Corridors and Stairs	Entire Building	53,790	SF	6	\$16,153	
	Emergency A/C Power - Gym	Entire Building / 3rd Floor	16,526	SF	6	\$6,144	
	Emergency A/C Power - Lunchrooms	Entire Building / 1st Floor	9,933	SF	6	\$3,693	
	Emergency A/C Power - Multipurpose Room	Entire Building / 1st Floor	1,226	SF	6	\$456	
	Emergency A/C Power - Pool	Entire Building / 2nd Floor	3,176	SF	6	\$1,181	
	Emergency A/C Power - Students Toilets	Entire Building	4,003	SF	6	\$1,488	
	Emergency Battery Packs - Auditorium and Aisle Lighting	1st, 2nd and 3rd Floor / 1st Floor	14	EA	6	\$2,835	Non Functional When Tested (Includes Auditorium & 2nd Floor Balcony)
	Emergency Battery Packs - Gym	1st, 2nd and 3rd Floor / 3rd Floor	3	EA	6	\$608	Non Functional When Tested
	Emergency Battery Packs - Pool	1st, 2nd and 3rd Floor / 2nd Floor	2	EA	6	\$405	
	Emergency Generator- Outdoor- Diesel - 60 - 100 KW	North Courtyard / North Courtyard	1	EA	7	\$0	
	Exit Signs - Auditorium	Entire Building / 1st Floor	9	EA	7	\$0	Included Auditorium & 2nd Floor Balcony (Bulb Out 1st Floor in one sign)
	Exit Signs - Corridors and Stairs	Entire Building	28	EA	7	\$0	
	Exit Signs - Gym	Entire Building / 3rd Floor	7	EA	7	\$0	One Lens Broken
	Exit Signs - Gym	Entire Building / 3rd Floor	1	EA	6	\$157	One Lens Broken
	Exit Signs - Lunchroom	Entire Building / 1st Floor	4	EA	7	\$0	Includes Serving Area

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System							
	Exit Signs - Multipurpose Room	Entire Building / 1st Floor	6	EA	7	\$0	
	Exit Signs - Pool	Entire Building / 2nd Floor	2	EA	2	\$1,136	Non Functional When Tested
	Security System - CCTV	Entire Building	384,200	SF	6	\$115,375	
	Security System - Intrusion Detection	Entire Building	384,200	SF	5	\$384,584	
Main Service							
	Independent Electrical Service for emergency power	Basement and 1st Floor / 1st Floor	1	EA	7	\$0	Location: Electrical Room
	Independent Electrical Service for emergency power	Basement and 1st Floor / Basement	1	EA	7	\$0	Location: Electrical Room
	Main Electrical Service - 1600 A 120/208/3PH	Basement	1	EA	6	\$5,641	
	Main Electrical Service - 1600 A 277/480/3PH	Basement	1	EA	7	\$0	
	Main Electrical Service - 2001 to 3000 A 120/240/3PH	Basement	1	EA	6	\$10,867	
	PA System	Entire Building	384,200	SF	6	\$126,363	
Power Distribution							
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Corridor (Main)
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Room 225
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Room 216
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	4	\$4,849	Location: Main Corridor
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Room 214
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Main Corridor
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Girl's Gym
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	4	\$4,849	Location: Room 316
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Main Corridor
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	4	\$4,849	Location: Room 323
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Main Corridor
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	4	\$4,849	Location: Room 320
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	4	\$4,849	Location: Room 314
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Girl's Gym
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Chase
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Storage Room
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Chase
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Chase
	Lighting and Power Panels - 100 A	Entire Building / Boiler Room	1	EA	4	\$4,849	
	Lighting and Power Panels - 100 A	Entire Building / Boiler Room	1	EA	4	\$4,849	
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Room 114
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Room 112
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Corridor (Main) CCT: 13 & 14 Blank Covers Missing

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution							
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Room 122
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Corridor (Main)
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Corridor (Main)
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	4	\$6,578	Location: Kitchen
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Room 114
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Corridor (Main)
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	4	\$6,578	Location: Kitchen
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	4	\$6,578	Location: Kitchen
	Lighting and Power Panels - Above 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Pool
	Lighting and Power Panels - Above 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / Basement	1	EA	6	\$497	Location: Mechanical Chase (CCT No. 2 & No. 8 Tripped)
	Lighting and Power Panels - Above 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / Boiler Room	1	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building / Boiler Room	1	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building / Electrical Room	1	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building / Electrical Room	1	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building / Electrical Room	1	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Chase
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Storage Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	6	\$528	Location: Mechanical Chase
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	6	\$528	Location: Mechanical Chase (Side Cover Off & Wires are Exposed)
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Chase
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Chase
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Chase
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Chase
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Boiler Room	1	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building / Boiler Room	1	EA	4	\$13,694	
	Main Distribution Panels - Less than 400 amp	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Chase
	Main Distribution Panels - Less than 400 amp	Entire Building / Mechanical Room	1	EA	7	\$0	
	Main Distribution Panels - Less than 400 amp	Entire Building / Mechanical Room	1	EA	7	\$0	
	Transformers - 120/240 - 120/208	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution							
	Transformers - 120/240 - 120/208	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Transformers - 120/240 - 120/208	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room

Electrical System Subtotal:

\$748,263

Building: Main

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm							
	Fire Alarm Panel	Basement	1	EA	4	\$49,477	Services & Links all three buildings together
	Fire Alarm Strobe Lights	Basement / Entire Building	384,200	SF	4	\$521,936	
	Fire Alarm_System	Basement / Entire Building	384,200	SF	4	\$763,674	

Safty System Subtotal:

\$1,335,087

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Conditioning							
	Chemical Pot Feeder	Mechanical Room and Roof / Mechanical Room	1	EA	6	\$725	Location: Upper Level - Boiler Room
	Chiller-Water Cooled- Cetrifugal - 100-200 tons	Mechanical Room and Roof / Mechanical Room	1	EA	6	\$9,010	Location: Upper Level - Boiler Room
	Chiller-Water Cooled- Cetrifugal - 100-200 tons	Mechanical Room and Roof / Mechanical Room	1	EA	6	\$9,010	Location: Upper Level - Boiler Room
	Condensing Unit- Roof Mounted - 11-20 tons	Lower Roof	1	EA	5	\$11,065	
	Condensing Unit- Roof Mounted - 11-20 tons	Lower Roof	1	EA	5	\$11,065	
	Condensing Unit- Roof Mounted - 5-10 tons	Lower Roof	1	EA	5	\$9,590	Serves: ROTC (Room 128)
	Cooling Tower - Closed Cell	Mechanical Room and Roof / Roof	2	EA	6	\$9,938	201 to 300 Tons
	Glycol Feed	Mechanical Room and Roof / Mechanical Room	1	EA	6	\$490	Location: Upper Level - Boiler Room
	Pipes - Chilled Water Pipe- Steel	Mechanical Room and Roof / Entire Building	895	LF	6	\$1,689	Location: Upper Level - Boiler Room
	Pressure Fill System	Mechanical Room and Roof / Mechanical Room	1	EA	6	\$1,405	Location: Upper Level - Boiler Room

Air Handling Systems

	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
--	---	----------	---	----	---	---------	--

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Handling Systems							
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 25001 - 35000 cfm	Basement	1	EA	6	\$6,511	
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 25001 - 35000 cfm	Basement	1	EA	6	\$6,511	
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 25001 - 35000 cfm	Basement	1	EA	6	\$6,511	
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 25001 - 35000 cfm	Basement	1	EA	6	\$6,511	
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 8001 - 15000 cfm	Basement	1	EA	6	\$4,341	
	Air Handling Unit- Built Up- Multi Zone- Daul Temperature Coils - 8001 - 15000 cfm	Basement	1	EA	6	\$4,341	
	Air Intake	Basement / Roof	11	EA	6	\$63,411	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	\$5,788	
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	6	\$6,511	
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	6	\$6,511	
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	6	\$6,511	
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	6	\$6,511	
	Auxiliaries - 8001 - 15000 cfm	Basement	1	EA	6	\$4,341	
	Auxiliaries - 8001 - 15000 cfm	Basement	1	EA	6	\$4,341	
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	3	EA	4	\$27,448	
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Boiler Room	1	EA	6	\$2,433	
	Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM	Boiler Room	1	EA	6	\$1,282	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	\$1,591	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	\$1,591	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	\$1,591	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	\$1,591	

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Handling Systems							
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	\$1,591	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	\$1,591	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement / Entire Building	350	LF	6	\$0	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 31 - 45 tons	Roof	1	EA	7	\$0	Condensate Drain Frozen, No Trap & No Drain Line
	Zone Dampers	Basement	127	EA	6	\$105,795	
Boiler Systems							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	6	\$2,545	
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	6	\$2,545	
	Chemical Feed System	Boiler Room	1	EA	6	\$1,078	
	Combustion Dampers	Boiler Room	3	EA	6	\$1,227	
	Condensate Pump	Boiler Room / Basement	1	EA	6	\$2,021	Location: Passage Way
	Condensate Pump	Boiler Room / Entire Building	5	EA	6	\$10,105	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	\$2,545	
	Feed Water Pumps and Tank	Boiler Room	1	EA	4	\$92,964	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	6	\$2,545	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	6	\$2,545	
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	2,000	LF	5	\$29,973	
	Steam Traps	Boiler Room / Basement	170	EA	5	\$223,533	Leaking & Malfunctioning
Heat Exchangers							
	Heat Exchanger - Steam to Hot Water Shell Type	Mechanical Room	1	EA	6	\$0	MBH = 4078
Heating Devices							
	Cabinet Heaters - With Steam Coil	Entire Building	4	EA	4	\$15,405	
	Cabinet Heaters - With Steam Coil	Entire Building	6	EA	6	\$2,140	
	Fin Tube - Hot Water	Entire Building / 1st Floor	4	LF	4	\$643	
	Fin Tube - Hot Water	Entire Building	68	LF	6	\$642	
	Radiators - Steam	Entire Building	2	EA	5	\$3,351	Leaking & Corrosion Present
	Radiators - Steam	Entire Building	73	EA	6	\$20,280	
	Unit Heater - Electric	Entire Building	5	EA	6	\$1,389	Yard Storage
	Wall Heater - Electric	Entire Building	30	EA	4	\$32,476	Includes: Restrooms, Storage Rooms, Electrical/Mechanical Rooms, Kitchen etc.
Mechanical Plumbing							
	Chilled Water Pump - 21 - 50 HP	Mechanical Room	2	EA	6	\$2,485	

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechanical Plumbing							
	Condensate-Steel or Galvanized	Entire Building	1,890	LF	4	\$616,297	
	Condenser Pump - 21 - 50 HP	Mechanical Room	2	EA	6	\$2,485	
	Daul Temperature Pump - 10 - 20 HP	Basement and Mechanical Room / Basement	9	EA	6	\$11,181	
	Daul Temperature Pump - 21 - 50 HP	Basement and Mechanical Room / Mechanical Room	2	EA	6	\$2,485	
	Hydronic Supply and Return - Steel	Entire Building	3,976	LF	6	\$305,264	
Temperature Control							
	DDC System	Entire Building	384,200	SF	6	\$219,762	
	Thermostats - DDC	Entire Building	101	EA	7	\$0	
Ventilation							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	\$592	Under Roof Deck
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Lower Roof	1	EA	6	\$592	Above: Boiler Room
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Lower Roof	1	EA	6	\$592	Above: Boiler Room
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Lower Roof	1	EA	4	\$4,245	Unit Disconnected (No Longer Used)
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Lower Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	2	EA	6	\$1,185	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	6	\$592	
	Lab Exhaust Hood	Entire Building / 1st Floor	2	EA	7	\$0	Location: Room 114
	Lab Exhaust Hood	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Room 320
	Roof Mounted Duct Work	Entire Building / Roof	30	LF	6	\$11,371	
	Type I Exhaust Hood- Culinary Arts	Entire Building / 1st Floor	1	EA	6	\$1,248	Kitchen Hood
	Type I Exhaust Hood- Kitchen	Entire Building / 1st Floor	1	EA	6	\$1,248	Diswasher Hood

Mechanical System Subtotal:

\$2,033,396

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Water							
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	\$682	Kitchen
	Gas Heater - 150000 - 300000 BTU/HR	1st Floor and Boiler Room / 1st Floor	1	EA	6	\$310	Location: Kitchen
	Gas Heater - 300001 - 600000 BTU/HR	1st Floor and Boiler Room / Boiler Room	2	EA	7	\$0	Location: Boiler Room
	Gas Heater - Less than 150000 BTU/HR	1st Floor and Boiler Room / 1st Floor	1	EA	6	\$310	Location: Kitchen (Pwr Vent: U9E75334 PVC Vent)
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	1st Floor and Boiler Room / Boiler Room	2	EA	7	\$0	Approx: 250/Tank

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	384,200	SF	6	\$76,917	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	384,200	SF	6	\$93,399	
	Domestic Piping-Cold Water Risers	Entire Building	384,200	SF	6	\$71,423	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	384,200	SF	6	\$60,435	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	384,200	SF	6	\$71,423	
	Domestic Piping-Hot Water Return Lines	Entire Building	384,200	SF	6	\$54,941	
	Domestic Piping-Hot Water Return Risers	Entire Building	384,200	SF	6	\$54,941	
	Sanitary Piping	Entire Building	384,200	SF	6	\$351,620	
	Storm Piping	Entire Building	384,200	SF	6	\$335,138	
	Vent Piping	Entire Building	384,200	SF	6	\$258,221	

Pool Systems

	Pool Drain Piping	Basement	100	LF	6	\$2,863	Leaking & Corrosion Present
	Pool Filtration System including Pump	Basement	1	EA	6	\$12,330	Leaking & Corrosion Present
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	6	\$310	
	Pool Supply and Return Piping	Basement	200	LF	6	\$9,610	Leaking & Corrosion Present

Pumps

	Pumps - Domestic Booster Pump-Duplex	Basement, Boiler Room, Mechanical Room / Mechanical Room	1	EA	6	\$1,977	Location: Pump Room
	Pumps - Sump-Simplex	Basement, Boiler Room, Mechanical Room / Basement	1	EA	6	\$745	Location: Mechanical Chase
	Pumps - Sump-Simplex	Basement, Boiler Room, Mechanical Room / Boiler Room	1	EA	6	\$745	
	Pumps - Sump-Simplex	Basement, Boiler Room, Mechanical Room / Mechanical Room	1	EA	6	\$745	Location: Pump Room

Plumbing System Subtotal:

\$1,459,082

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #101 (Regular Classroom)							
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	742	SF	6	\$2,228	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	742	SF	6	\$5,231	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #101 (Regular Classroom)							
	Lighting - Pendent/Surface	1st Floor	15	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,188	SF	5	\$9,004	damage throughout
Classroom #103 (Regular Classroom)							
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	729	SF	6	\$2,189	
	Doors - Transom Window	1st Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	729	SF	6	\$5,139	
	Lighting - Lay-in	1st Floor	15	EA	7	\$0	
	Marker Board	1st Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,028	SF	6	\$2,837	
Classroom #105 (Regular Classroom)							
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	756	SF	6	\$2,270	
	Doors - Transom Window	1st Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	756	SF	6	\$5,330	
	Lighting - Lay-in	1st Floor	15	EA	7	\$0	
	Marker Board	1st Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,030	SF	6	\$2,843	
Classroom #107 (Regular Classroom)							
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	727	SF	6	\$2,183	
	Doors - Transom Window	1st Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	727	SF	6	\$5,125	
	Lighting - Lay-in	1st Floor	15	EA	7	\$0	data boxes coming off wall
	Marker Board	1st Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,033	SF	6	\$2,851	
Classroom #109 (Regular Classroom)							
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	724	SF	6	\$2,174	
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	cracks / stains
	Doors - Transom Window	1st Floor	16	SF	6	\$271	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #109 (Regular Classroom)							
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	729	SF	6	\$5,139	
	Lighting - Lay-in	1st Floor	15	EA	7	\$0	
	Marker Board	1st Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,028	SF	6	\$2,837	
Classroom #111 (Regular Classroom)							
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	918	SF	6	\$2,757	
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	stained
	Doors - Transom Window	1st Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	923	SF	6	\$6,507	
	Lighting - Lay-in	1st Floor	15	EA	7	\$0	
	Marker Board	1st Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,169	SF	6	\$3,226	
Classroom #112 (Science Lab Level 1)							
	Casework	1st Floor	133	LF	6	\$3,359	
	Ceiling - Lay-in	1st Floor	1,148	SF	6	\$3,447	
	Doors - Transom Window	1st Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Eye Wash Station	1st Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	1st Floor	1,138	SF	6	\$1,139	
	Floor - Tile/Sheet	1st Floor	10	SF	5	\$58	bubbling up / loose
	Fume Hood	1st Floor	1	EA	6	\$816	
	Gas Line	1st Floor	8	EA	6	\$4,073	
	Lighting - Lay-in	1st Floor	1	EA	4	\$336	not workig
	Lighting - Lay-in	1st Floor	23	EA	7	\$0	
	Marker Board	1st Floor	10	LF	7	\$0	
	Science Lab Shower	1st Floor	1	EA	6	\$379	
	Walls - Plaster/Drywall	1st Floor	1,190	SF	6	\$3,284	
	Work Sink	1st Floor	10	EA	6	\$3,790	
Classroom #113 (Computer Lab)							
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Splined	1st Floor	767	SF	6	\$625	
	Ceiling - Splined	1st Floor	6	SF	5	\$58	water damaged

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #113 (Computer Lab)							
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Concrete	1st Floor	773	SF	6	\$409	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	\$0	
	Marker Board	1st Floor	6	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	380	SF	6	\$1,049	
	Walls - Structural Glazed Tile	1st Floor	1,404	SF	6	\$4,417	
	Work Sink	1st Floor	1	EA	6	\$379	
Classroom #114 (Science Lab Level 1)							
	Casework	1st Floor	123	LF	6	\$3,106	
	Ceiling - Lay-in	1st Floor	1,100	SF	6	\$3,303	
	Doors - Transom Window	1st Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Eye Wash Station	1st Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	1st Floor	1,100	SF	6	\$1,101	
	Fume Hood	1st Floor	1	EA	6	\$816	
	Gas Line	1st Floor	23	EA	6	\$11,710	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	10	LF	7	\$0	
	Science Lab Shower	1st Floor	1	EA	6	\$379	
	Walls - Plaster/Drywall	1st Floor	1,145	SF	6	\$3,160	
	Walls - Plaster/Drywall	1st Floor	5	SF	5	\$26	hole
	Work Sink	1st Floor	14	EA	6	\$5,306	
Classroom #115 (Store Room)							
	Ceiling - Splined	1st Floor	1,489	SF	6	\$1,214	
	Doors - Transom Window	1st Floor	1,489	SF	6	\$25,211	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Concrete	1st Floor	1,489	SF	6	\$788	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Walls - Structural Glazed Tile	1st Floor	2,728	SF	6	\$8,582	
Classroom #116 (Regular Classroom)							
	Casework	1st Floor	6	LF	6	\$152	
	Ceiling - Lay-in	1st Floor	540	SF	6	\$1,622	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	540	SF	6	\$1,181	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #116 (Regular Classroom)							
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	15	LF	6	\$321	
	Walls - Plaster/Drywall	1st Floor	807	SF	6	\$2,227	
	Walls - Plaster/Drywall	1st Floor	5	SF	5	\$26	cracks / holes
Classroom #121 JROTC (Other Instructional Use)							
	Casework	1st Floor	12	LF	6	\$303	
	Ceiling - Lay-in	1st Floor	1,333	SF	6	\$4,003	
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	water damaged
	Doors - Transom Window	1st Floor	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	
	Floor - Wood	1st Floor	1,338	SF	6	\$9,433	
	Lighting - Lay-in	1st Floor	26	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	525	SF	6	\$1,449	
	Walls - Plaster/Drywall	1st Floor	1	SF	6	\$4	NO OCCUPANCY PLACARD CARD POSTED
	Walls - Structural Glazed Tile	1st Floor	1,050	SF	6	\$3,303	
Classroom #127 (Computer Lab)							
	Ceiling - Splined	1st Floor	932	SF	6	\$760	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	
	Floor - Tile	1st Floor	15	SF	5	\$86	damaged
	Floor - Tile	1st Floor	932	SF	6	\$2,039	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	\$0	
	Marker Board	1st Floor	3	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,433	SF	6	\$3,955	
	Walls - Structural Glazed Tile	1st Floor	192	SF	6	\$604	
Classroom #130 (Regular Classroom)							
	Casework	5th Floor	8	LF	6	\$202	
	Ceiling - Lay-in	5th Floor	732	SF	6	\$2,198	
	Ceiling - Lay-in	5th Floor	10	SF	5	\$80	stained / cracked
	Chalk Board	5th Floor	8	LF	4	\$734	
	Doors - Transom Window	5th Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	5th Floor	2	EA	6	\$602	
	Floor - Tile	5th Floor	737	SF	6	\$1,612	
	Floor - Tile	5th Floor	5	SF	5	\$29	cracked / missing tiles
	Lighting - Lay-in	5th Floor	15	EA	7	\$0	outlet junction box damaged
	Marker Board	5th Floor	22	LF	7	\$0	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #130 (Regular Classroom)							
	Walls - Plaster/Drywall	5th Floor	1,071	SF	6	\$2,956	
Classroom #132 (Regular Classroom)							
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	787	SF	6	\$2,363	
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	cracked
	Doors - Transom Window	1st Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	792	SF	6	\$1,733	
	Lighting - Lay-in	1st Floor	1	EA	4	\$336	Not working
	Lighting - Lay-in	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,079	SF	6	\$2,978	
Classroom #201 (Computer Lab)							
	AC Units	2nd Floor	2	EA	6	\$991	
	AC Units	2nd Floor	2	EA	4	\$12,173	missing covers & not working
	Casework	2nd Floor	64	LF	6	\$1,616	
	Ceiling - Splined	2nd Floor	1,489	SF	6	\$1,214	
	Doors - Transom Window	2nd Floor	27	SF	6	\$457	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	\$903	
	Floor - Tile	2nd Floor	1,489	SF	6	\$3,258	
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	2,272	SF	6	\$6,270	
Classroom #202 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	742	SF	6	\$1,623	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,188	SF	6	\$3,279	
Classroom #203 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #203 (Regular Classroom)							
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	742	SF	6	\$1,623	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	damaged
	Walls - Plaster/Drywall	2nd Floor	1,187	SF	6	\$3,276	
Classroom #204 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,176	SF	6	\$3,246	
Classroom #205 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	7	\$0	
Classroom #206 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,188	SF	6	\$3,279	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #207 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	\$3,312	
Classroom #208 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,188	SF	6	\$3,279	
Classroom #209 (Computer Lab)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	\$3,312	
Classroom #211 (Computer Lab)							
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Lay-in	2nd Floor	1,155	SF	6	\$3,468	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	394	SF	6	\$862	
	Floor - Wood	2nd Floor	761	SF	6	\$5,365	
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	\$183	not working
	Marker Board	2nd Floor	6	LF	7	\$0	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #211 (Computer Lab)							
	Storage/ Closet	2nd Floor	120	SF	5	\$1,936	ceiling has water damage
	Walls - Plaster/Drywall	2nd Floor	1,585	SF	6	\$4,374	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	\$26	wall is damaged where room was opened up to adjoining room
	Work Sink	2nd Floor	1	EA	6	\$379	skreen printing sink
Classroom #212 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	742	SF	6	\$2,568	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	717	SF	6	\$1,569	
	Floor - Tile	2nd Floor	25	SF	5	\$144	damaged
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,460	SF	6	\$4,029	
Classroom #213 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	3	SF	5	\$24	water stains
	Ceiling - Lay-in	2nd Floor	739	SF	6	\$2,219	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	\$3,312	
Classroom #214 (Science)							
	Casework	2nd Floor	18	LF	6	\$455	
	Ceiling - Lay-in	2nd Floor	1,065	SF	6	\$3,198	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	1,065	SF	6	\$1,066	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,441	SF	6	\$3,977	
	Work Sink	2nd Floor	3	EA	6	\$1,137	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #215 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	\$3,312	
Classroom #216 (Science)							
	Casework	2nd Floor	64	LF	6	\$1,616	
	Ceiling - Lay-in	2nd Floor	1,039	SF	6	\$3,120	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	2nd Floor	1,039	SF	6	\$1,040	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	30	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,095	SF	6	\$3,022	
	Work Sink	2nd Floor	3	EA	6	\$1,137	
Classroom #218 (Regular Classroom)							
	Casework	2nd Floor	6	LF	6	\$152	
	Ceiling - Lay-in	2nd Floor	550	SF	6	\$1,652	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	550	SF	6	\$1,203	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,034	SF	6	\$2,854	
Classroom #220 (Computer Lab)							
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Lay-in	2nd Floor	925	SF	6	\$2,778	
	Chalk Board	2nd Floor	3	LF	4	\$275	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	925	SF	6	\$2,024	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #220 (Computer Lab)							
	Marker Board	2nd Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,381	SF	6	\$3,811	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	\$51	damaged
Classroom #221 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	\$3,312	
Classroom #222 (Computer Lab)							
	AC Units	2nd Floor	1	EA	4	\$6,086	no cover
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Chalk Board	2nd Floor	8	LF	4	\$734	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	\$3,312	
Classroom #224 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	\$3,312	
Classroom #225 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #225 (Regular Classroom)							
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	742	SF	6	\$1,623	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,188	SF	6	\$3,279	
Classroom #226 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	4	\$6,086	no cover
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	2	SF	5	\$16	water damage
	Ceiling - Lay-in	2nd Floor	740	SF	6	\$2,222	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	\$3,312	
Classroom #227 (Computer Lab)							
	AC Units	2nd Floor	1	EA	6	\$496	
	Ceiling - Lay-in	2nd Floor	1,084	SF	6	\$3,255	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,084	SF	6	\$7,642	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	936	SF	6	\$2,583	
	Walls - Structural Glazed Tile	2nd Floor	900	SF	6	\$2,831	
	Wireless System	2nd Floor	1	EA	6	\$372	
Classroom #228 (Computer Lab)							
	AC Units	2nd Floor	1	EA	6	\$496	
	Ceiling - Lay-in	2nd Floor	1,084	SF	6	\$3,255	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,084	SF	6	\$7,642	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	936	SF	6	\$2,583	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #228 (Computer Lab)							
	Walls - Structural Glazed Tile	2nd Floor	800	SF	6	\$2,517	
	Wireless System	2nd Floor	1	EA	6	\$372	
Classroom #300 (Computer Lab)							
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	22	LF	6	\$556	
	Ceiling - Lay-in	3rd Floor	1,016	SF	6	\$3,051	
	Chalk Board	3rd Floor	4	LF	4	\$367	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	1,016	SF	6	\$7,163	
	Lighting - Lay-in	3rd Floor	24	EA	7	\$0	
	Marker Board	3rd Floor	14	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,413	SF	6	\$3,900	
Classroom #301 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	2	SF	5	\$16	Cracks
	Ceiling - Lay-in	3rd Floor	728	SF	6	\$2,186	
	Chalk Board	3rd Floor	5	LF	4	\$459	
	Doors - Transom Window	3rd Floor	10	SF	5	\$423	Broken, missing glass panel
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	730	SF	6	\$5,146	
	Lighting - Lay-in	3rd Floor	15	EA	6	\$1,785	
	Marker Board	3rd Floor	23	LF	7	\$0	
	Storage/ Closet	3rd Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	3rd Floor	1,188	SF	6	\$3,279	
Classroom #302 (Regular Classroom)							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	3rd Floor	3	SF	5	\$24	water damaged
	Ceiling - Lay-in	3rd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	\$3,312	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #303 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	550	SF	6	\$1,652	
	Doors - Transom Window	3rd Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	550	SF	6	\$3,877	
	Lighting - Lay-in	3rd Floor	15	EA	6	\$1,785	
	Marker Board	3rd Floor	23	LF	7	\$0	
	Storage/ Closet	3rd Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	3rd Floor	1,030	SF	6	\$2,843	
Classroom #304 (Regular Classroom)							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	3rd Floor	742	SF	6	\$2,228	
	Chalk Board	3rd Floor	6	LF	4	\$551	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	30	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,186	SF	6	\$3,273	
	Walls - Plaster/Drywall	3rd Floor	14	SF	5	\$71	efflorecense & damaged
Classroom #305 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	8	SF	5	\$64	Cracks
	Ceiling - Lay-in	3rd Floor	542	SF	6	\$1,628	
	Doors - Transom Window	3rd Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	550	SF	6	\$3,877	
	Lighting - Lay-in	3rd Floor	13	EA	6	\$1,547	
	Storage/ Closet	3rd Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	3rd Floor	1,030	SF	6	\$2,843	
Classroom #306 (Regular Classroom)							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	3rd Floor	742	SF	6	\$2,228	
	Ceiling - Lay-in	3rd Floor	5	SF	5	\$40	water damaged
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #306 (Regular Classroom)							
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	\$3,312	
Classroom #307 (Regular Classroom)							
	Casework	3rd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	3rd Floor	550	SF	6	\$1,903	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Floor - Wood	3rd Floor	550	SF	6	\$3,877	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	\$0	
	Marker Board	3rd Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	\$3,287	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	24	SF	6	\$54	backsplash
	Work Sink	3rd Floor	1	EA	6	\$379	
Classroom #308 (Regular Classroom)							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	3rd Floor	742	SF	6	\$2,228	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	48	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	6	SF	5	\$31	cracked
	Walls - Plaster/Drywall	3rd Floor	1,194	SF	6	\$3,295	
Classroom #310 (Regular Classroom)							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	3rd Floor	742	SF	6	\$2,228	
	Ceiling - Lay-in	3rd Floor	22	SF	5	\$176	water damaged
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,980	SF	6	\$5,465	
	Walls - Plaster/Drywall	3rd Floor	20	SF	5	\$102	water damaged

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #311 (Art Room)							
	AC Units	3rd Floor	1	EA	4	\$6,086	cover missing
	Casework	3rd Floor	42	LF	6	\$1,061	
	Ceiling - Plaster/Drywall	3rd Floor	1,255	SF	5	\$11,504	peeling throughout
	Chalk Board	3rd Floor	10	LF	4	\$918	
	Doors - Transom Window	3rd Floor	9	SF	5	\$381	glass is broken
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	15	SF	5	\$86	missing tiles
	Floor - Tile	3rd Floor	1,255	SF	6	\$2,746	
	Instructional Surface	3rd Floor	18	LF	6	\$606	
	Kiln	3rd Floor	2	EA	6	\$4,642	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	3	SF	5	\$15	crack
	Walls - Plaster/Drywall	3rd Floor	1,797	SF	6	\$4,960	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	40	SF	6	\$90	backsplash
	Work Sink	3rd Floor	1	EA	6	\$379	
Classroom #312 (Regular Classroom)							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	742	SF	6	\$2,568	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	742	SF	5	\$3,332	damaged throughout
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,417	SF	6	\$3,911	
Classroom #313 (Art Room)							
	Casework	3rd Floor	34	LF	6	\$859	
	Ceiling - Lay-in	3rd Floor	855	SF	6	\$2,568	
	Chalk Board	3rd Floor	15	LF	4	\$1,377	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	855	SF	6	\$6,028	
	Lighting - Lay-in	3rd Floor	20	EA	7	\$0	
	Marker Board	3rd Floor	6	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,308	SF	6	\$3,610	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	12	SF	6	\$27	backsplash

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #313 (Art Room)							
	Work Sink	3rd Floor	1	EA	6	\$379	
Classroom #314 (Science)							
	Casework	3rd Floor	18	LF	6	\$455	
	Ceiling - Lay-in	3rd Floor	1,059	SF	6	\$3,180	
	Ceiling - Plaster/Drywall	3rd Floor	6	SF	5	\$55	water damaged
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	3rd Floor	1,065	SF	6	\$1,066	
	Lighting - Lay-in	3rd Floor	21	EA	7	\$0	
	Lighting - Wall Mounted	3rd Floor	1	EA	5	\$169	approx 10-12 outlets don't work
	Marker Board	3rd Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,441	SF	6	\$3,977	
	Work Sink	3rd Floor	3	EA	6	\$1,137	
Classroom #315 (Art Room)							
	Casework	3rd Floor	34	LF	6	\$859	
	Ceiling - Lay-in	3rd Floor	855	SF	6	\$2,568	
	Ceiling - Lay-in	3rd Floor	10	SF	5	\$80	water damaged
	Chalk Board	3rd Floor	15	LF	4	\$1,377	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	855	SF	6	\$6,028	
	Lighting - Lay-in	3rd Floor	20	EA	7	\$0	
	Marker Board	3rd Floor	6	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,308	SF	6	\$3,610	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	12	SF	6	\$27	sink backsplash
	Work Sink	3rd Floor	1	EA	6	\$379	
Classroom #316 (Science)							
	Casework	3rd Floor	64	LF	6	\$1,616	
	Ceiling - Lay-in	3rd Floor	1,039	SF	6	\$3,120	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	3rd Floor	1,039	SF	6	\$1,040	
	Lighting - Lay-in	3rd Floor	21	EA	7	\$0	
	Lighting - Wall Mounted	3rd Floor	1	EA	5	\$169	Of 56 outlets on the desk, only 8 of them work

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #316 (Science)							
	Walls - Plaster/Drywall	3rd Floor	1,463	SF	6	\$4,038	
	Work Sink	3rd Floor	3	EA	6	\$1,137	
Classroom #318 (Regular Classroom)							
	Casework	3rd Floor	6	LF	6	\$152	
	Ceiling - Lay-in	3rd Floor	550	SF	6	\$1,652	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	550	SF	6	\$1,203	
	Lighting - Lay-in	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,034	SF	6	\$2,854	
Classroom #319 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	15	LF	6	\$379	
	Ceiling - Lay-in	3rd Floor	710	SF	6	\$2,132	
	Chalk Board	3rd Floor	4	LF	4	\$367	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	710	SF	5	\$3,188	damaged throughout
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	13	SF	5	\$66	damaged
	Walls - Plaster/Drywall	3rd Floor	1,320	SF	6	\$3,643	
Classroom #320 (Science)							
	Casework	3rd Floor	50	LF	6	\$1,263	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	\$125	water damaged
	Ceiling - Plaster/Drywall	3rd Floor	908	SF	6	\$3,142	
	Chalk Board	3rd Floor	36	LF	4	\$3,305	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Tile	3rd Floor	908	SF	6	\$1,987	
	Floor - Tile	3rd Floor	10	SF	5	\$58	damaged
	Gas Line	3rd Floor	3	EA	6	\$1,527	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	\$0	
	Storage/ Closet	3rd Floor	100	SF	6	\$725	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #320 (Science)							
	Walls - Plaster/Drywall	3rd Floor	1,616	SF	6	\$4,460	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	\$10	damaged
	Work Sink	3rd Floor	3	EA	6	\$1,137	1 sink has a broken faucet
Classroom #321 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	705	SF	6	\$2,117	
	Ceiling - Lay-in	3rd Floor	10	SF	5	\$80	Water damage
	Doors - Transom Window	3rd Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	715	SF	6	\$5,041	
	Lighting - Chandelier, Incandescent	3rd Floor	15	EA	6	\$7,163	
	Marker Board	3rd Floor	23	LF	7	\$0	
	Storage/ Closet	3rd Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	3rd Floor	1,150	SF	6	\$3,174	
	Walls - Plaster/Drywall	3rd Floor	25	SF	5	\$128	Water damage, peeling
Classroom #322 (Science Classroom)							
	AC Units	3rd Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	3rd Floor	1,072	SF	6	\$3,710	
	Chalk Board	3rd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	3rd Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	1,072	SF	6	\$1,073	
	Lighting - Chandelier, Incandescent	3rd Floor	20	EA	6	\$9,551	
	Storage/ Closet	3rd Floor	66	SF	6	\$479	
	Walls - Plaster/Drywall	3rd Floor	1,310	SF	6	\$3,615	
	Work Sink	3rd Floor	2	EA	6	\$758	
Classroom #323 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	725	SF	6	\$2,177	
	Doors - Transom Window	3rd Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	725	SF	6	\$5,111	
	Lighting - Lay-in	3rd Floor	15	EA	6	\$1,785	
	Marker Board	3rd Floor	23	LF	7	\$0	
	Storage/ Closet	3rd Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	3rd Floor	1,185	SF	6	\$3,270	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #325 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	1,086	SF	6	\$3,261	
	Chalk Board	3rd Floor	36	LF	4	\$3,305	
	Doors - Transom Window	3rd Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,086	SF	6	\$7,656	
	Lighting - Lay-in	3rd Floor	23	EA	6	\$2,736	
	Marker Board	3rd Floor	13	LF	7	\$0	
	Storage/ Closet	3rd Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	3rd Floor	1,450	SF	6	\$4,002	
Classroom #326 (Computer Lab)							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	22	LF	6	\$556	
	Ceiling - Lay-in	3rd Floor	3	SF	5	\$24	water damage on ceiling
	Ceiling - Lay-in	3rd Floor	827	SF	6	\$2,483	
	Chalk Board	3rd Floor	16	LF	4	\$1,469	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	830	SF	6	\$5,851	
	Lighting - Lay-in	3rd Floor	16	EA	7	\$0	
	Marker Board	3rd Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	4	SF	5	\$20	damaged
	Walls - Plaster/Drywall	3rd Floor	1,309	SF	6	\$3,613	
Classroom #328 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	6	\$991	
	Ceiling - Lay-in	3rd Floor	1,100	SF	6	\$3,303	
	Doors - Transom Window	3rd Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd Floor	1,100	SF	6	\$1,101	
	Lighting - Chandelier, Incandescent	3rd Floor	30	EA	6	\$14,327	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Storage/ Closet	3rd Floor	30	SF	6	\$218	
	Walls - Plaster/Drywall	3rd Floor	146	SF	6	\$403	
Classroom #330 (Computer Lab)							
	Ceiling - Lay-in	3rd Floor	1,100	SF	6	\$3,303	
	Doors - Transom Window	3rd Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #330 (Computer Lab)							
	Floor - Wood	3rd Floor	1,100	SF	6	\$7,755	
	Lighting - Lay-in	3rd Floor	24	EA	6	\$2,855	
	Marker Board	3rd Floor	23	LF	7	\$0	
	Storage/ Closet	3rd Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	3rd Floor	1,460	SF	6	\$4,029	
	Wireless System	3rd Floor	1	EA	6	\$372	
Classroom #332 (Regular Classroom)							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	3rd Floor	2	SF	5	\$16	damaged
	Ceiling - Lay-in	3rd Floor	740	SF	6	\$2,222	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	742	SF	6	\$5,231	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	15	SF	5	\$77	damaged
	Walls - Plaster/Drywall	3rd Floor	1,185	SF	6	\$3,270	
Classroom #333 (Computer Lab)							
	AC Units	3rd Floor	1	EA	6	\$496	
	Ceiling - Lay-in	3rd Floor	645	SF	6	\$1,937	
	Doors - Transom Window	3rd Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	645	SF	6	\$4,547	
	Lighting - Lay-in	3rd Floor	16	EA	6	\$1,904	
	Walls - Plaster/Drywall	3rd Floor	1,112	SF	6	\$3,069	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	\$26	Water damage
	Wireless System	3rd Floor	1	EA	6	\$372	
Classroom #353 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	550	SF	6	\$1,652	
	Doors - Transom Window	3rd Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	550	SF	6	\$3,877	
	Lighting - Lay-in	3rd Floor	12	EA	6	\$1,428	
	Storage/ Closet	3rd Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	3rd Floor	1,030	SF	6	\$2,843	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #355 (Regular Classroom)							
	Casework	3rd Floor	6	LF	6	\$152	
	Ceiling - Lay-in	3rd Floor	550	SF	6	\$1,652	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	550	SF	6	\$3,877	
	Lighting - Lay-in	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	996	SF	6	\$2,749	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	27	SF	6	\$61	
Classroom #357 (Art Room)							
	Casework	3rd Floor	6	LF	6	\$152	
	Ceiling - Plaster/Drywall	3rd Floor	515	SF	6	\$1,782	
	Ceiling - Plaster/Drywall	3rd Floor	35	SF	5	\$437	peeling & water damaged
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	550	SF	6	\$3,877	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,213	SF	6	\$3,348	
	Walls - Plaster/Drywall	3rd Floor	3	SF	5	\$15	damaged
Classroom #399 (Computer Lab)							
	AC Units	3rd Floor	1	EA	6	\$496	
	Ceiling - Lay-in	3rd Floor	950	SF	6	\$2,853	
	Chalk Board	3rd Floor	4	LF	4	\$367	
	Doors - Transom Window	3rd Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	950	SF	6	\$6,697	
	Lighting - Lay-in	3rd Floor	24	EA	6	\$2,855	
	Marker Board	3rd Floor	14	LF	7	\$0	
	Storage/ Closet	3rd Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	3rd Floor	1,356	SF	6	\$3,742	
	Wireless System	3rd Floor	1	EA	6	\$372	
Classroom #400 (Music Room)							
	Casework	4th Floor	30	LF	6	\$758	
	Ceiling - Lay-in	4th Floor	1,800	SF	6	\$5,405	
	Chalk Board	4th Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #400 (Music Room)							
	Floor - Wood	4th Floor	1,800	SF	6	\$12,690	
	Lighting - Lay-in	4th Floor	35	EA	7	\$0	
	Marker Board	4th Floor	32	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	2,249	SF	6	\$6,207	
Classroom #401 (Music Room)							
	Casework	4th Floor	30	LF	6	\$758	
	Ceiling - Lay-in	4th Floor	1,800	SF	6	\$5,405	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Tile	4th Floor	1,796	SF	6	\$3,929	
	Floor - Tile	4th Floor	4	SF	5	\$23	damaged
	Lighting - Lay-in	4th Floor	35	EA	7	\$0	
	Marker Board	4th Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	2,249	SF	6	\$6,207	

Classrooms Subtotal:

\$1,037,457

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	AC Unit	1st - 102 Principle	1	EA	6	\$496	
	Ceiling - Lay-in	1st - 102 Principle	373	SF	6	\$1,120	
	Doors - Wood Doors inclu hw	1st - 102 Principle	1	EA	6	\$301	
	Floor - Carpet	1st - 102 Principle	373	SF	6	\$795	
	Lighting - Lay-in	1st - 102 Principle	9	EA	7	\$0	5 - recessed cans
	Power Distribution	1st - 102 Principle	2	EA	6	\$4,250	
	Storage/ Closet	1st - 102 Principle	7	SF	6	\$51	
	Walls - Plaster/Drywall	1st - 102 Principle	625	SF	6	\$1,725	
	Walls - Plaster/Drywall	1st - 102 Principle	260	SF	6	\$851	wood paneling
	AC Unit	1st - 104 Main Office	2	EA	6	\$991	
	Ceiling - Lay-in	1st - 104 Main Office	898	SF	6	\$2,697	
	Doors - Side-lite	1st - 104 Main Office	40	SF	6	\$669	
	Doors - Transom Window	1st - 104 Main Office	48	SF	6	\$813	
	Doors - Wood Doors inclu hw	1st - 104 Main Office	2	EA	6	\$602	
	Floor - Carpet	1st - 104 Main Office	688	SF	6	\$1,466	
	Floor - Tile	1st - 104 Main Office	210	SF	6	\$459	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Lighting - Lay-in	1st - 104 Main Office	18	EA	7	\$0	
	Power Distribution	1st - 104 Main Office	8	EA	6	\$16,999	
	Storage/ Closet	1st - 104 Main Office	34	SF	6	\$247	
	Walls - Plaster/Drywall	1st - 104 Main Office	2,266	SF	6	\$6,254	
	AC Unit	1st - 104A	2	EA	6	\$991	
	Ceiling - Lay-in	1st - 104A	415	SF	6	\$1,246	
	Doors - Transom Window	1st - 104A	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st - 104A	1	EA	6	\$301	
	Floor - Carpet	1st - 104A	415	SF	6	\$884	
	Lighting - Lay-in	1st - 104A	6	EA	7	\$0	
	Power Distribution	1st - 104A	12	EA	6	\$25,499	
	Storage/ Closet	1st - 104A	31	SF	6	\$225	
	Walls - Plaster/Drywall	1st - 104A	1,558	SF	6	\$4,300	
	Work Sink	1st - 104A	1	EA	6	\$508	
	AC Unit	1st - 106A-B	1	EA	6	\$496	
	Ceiling - Lay-in	1st - 106A-B	305	SF	6	\$916	
	Doors - Transom Window	1st - 106A-B	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st - 106A-B	1	EA	6	\$301	
	Floor - Carpet	1st - 106A-B	305	SF	6	\$650	
	Lighting - Lay-in	1st - 106A-B	7	EA	7	\$0	
	Power Distribution	1st - 106A-B	12	EA	6	\$25,499	
	Storage/ Closet	1st - 106A-B	3	SF	6	\$22	
	Walls - Plaster/Drywall	1st - 106A-B	1,050	SF	6	\$2,898	
	Ceiling - Lay-in	1st - 112A inside 112	304	SF	6	\$913	
	Doors - Wood Doors inclu hw	1st - 112A inside 112	2	EA	6	\$602	
	Floor - Tile/Sheet	1st - 112A inside 112	304	SF	6	\$304	
	Lighting - Lay-in	1st - 112A inside 112	7	EA	7	\$0	
	Power Distribution	1st - 112A inside 112	20	EA	6	\$42,498	
	Storage/ Closet	1st - 112A inside 112	46	SF	6	\$334	
	Walls - Plaster/Drywall	1st - 112A inside 112	755	SF	6	\$2,084	
	Work Sink	1st - 112A inside 112	1	EA	6	\$508	
	Ceiling - Lay-in	1st - 114A inside 114	127	SF	6	\$381	
	Doors - Wood Doors inclu hw	1st - 114A inside 114	1	EA	6	\$301	
	Floor - Tile/Sheet	1st - 114A inside 114	127	SF	6	\$127	
	Lighting - Lay-in	1st - 114A inside 114	3	EA	7	\$0	
	Power Distribution	1st - 114A inside 114	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st - 114A inside 114	329	SF	6	\$908	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Work Slnk	1st - 114A inside 114	1	EA	6	\$508	
	AC Unit	1st - 118	1	EA	6	\$496	
	Ceiling - Lay-in	1st - 118	726	SF	6	\$2,180	
	Doors - Transom Window	1st - 118	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	1st - 118	2	EA	6	\$602	
	Floor - Carpet	1st - 118	726	SF	6	\$1,547	
	Lighting - Lay-in	1st - 118	16	EA	7	\$0	
	Power Distribution	1st - 118	8	EA	6	\$16,999	
	Storage/ Closet	1st - 118	89	SF	6	\$645	
	Walls - Plaster/Drywall	1st - 118	1,209	SF	6	\$3,337	radiator coming off wall
	Ceiling - Lay-in	1st - 120A	188	SF	6	\$565	
	Doors - Transom Window	1st - 120A	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st - 120A	1	EA	6	\$301	
	Floor - Carpet	1st - 120A	188	SF	6	\$401	
	Lighting - Lay-in	1st - 120A	4	EA	7	\$0	
	Power Distribution	1st - 120A	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st - 120A	627	SF	6	\$1,730	
	Ceiling - Lay-in	1st - 120B	210	SF	6	\$631	
	Doors - Transom Window	1st - 120B	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st - 120B	1	EA	6	\$301	
	Floor - Carpet	1st - 120B	210	SF	6	\$447	
	Lighting - Lay-in	1st - 120B	4	EA	7	\$0	
	Power Distribution	1st - 120B	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	1st - 120B	639	SF	6	\$1,764	
	AC Unit	1st - Assistant Principle 1 inside 120A	1	EA	6	\$496	
	Ceiling - Lay-in	1st - Assistant Principle 1 inside 120A	93	SF	6	\$279	
	Doors - Wood Doors inclu hw	1st - Assistant Principle 1 inside 120A	1	EA	6	\$301	
	Floor - Carpet	1st - Assistant Principle 1 inside 120A	93	SF	6	\$198	
	Lighting - Lay-in	1st - Assistant Principle 1 inside 120A	2	EA	7	\$0	
	Power Distribution	1st - Assistant Principle 1 inside 120A	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st - Assistant Principle 1 inside 120A	443	SF	6	\$1,223	
	AC Unit	1st - Assistant Principle 2 inside 120A	1	EA	6	\$496	
	Ceiling - Lay-in	1st - Assistant Principle 2 inside 120A	96	SF	6	\$288	
	Doors - Wood Doors inclu hw	1st - Assistant Principle 2 inside 120A	1	EA	6	\$301	
	Floor - Carpet	1st - Assistant Principle 2 inside 120A	96	SF	6	\$205	
	Lighting - Lay-in	1st - Assistant Principle 2 inside 120A	2	EA	7	\$0	
	Power Distribution	1st - Assistant Principle 2 inside 120A	2	EA	6	\$4,250	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Walls - Plaster/Drywall	1st - Assistant Principle 2 inside 120A	448	SF	6	\$1,236	
	Ceiling - Lay-in	1st - Assistant Principle inside 120B	108	SF	6	\$324	
	Doors - Side-lite	1st - Assistant Principle inside 120B	30	SF	6	\$502	
	Doors - Wood Doors inclu hw	1st - Assistant Principle inside 120B	1	EA	6	\$301	
	Floor - Carpet	1st - Assistant Principle inside 120B	108	SF	6	\$230	
	Lighting - Lay-in	1st - Assistant Principle inside 120B	2	EA	7	\$0	
	Power Distribution	1st - Assistant Principle inside 120B	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	1st - Assistant Principle inside 120B	294	SF	6	\$811	
	AC Unit	1st - Attendance Office inside 106A-B	1	EA	6	\$496	
	Ceiling - Lay-in	1st - Attendance Office inside 106A-B	251	SF	6	\$754	
	Doors - Wood Doors inclu hw	1st - Attendance Office inside 106A-B	1	EA	6	\$301	
	Floor - Carpet	1st - Attendance Office inside 106A-B	251	SF	6	\$535	
	Lighting - Lay-in	1st - Attendance Office inside 106A-B	4	EA	7	\$0	
	Power Distribution	1st - Attendance Office inside 106A-B	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st - Attendance Office inside 106A-B	476	SF	6	\$1,314	
	Walls - Plaster/Drywall	1st - Attendance Office inside 106A-B	225	SF	6	\$737	wood paneling
	AC Unit	1st - Principle Assistant	1	EA	6	\$496	
	Ceiling - Lay-in	1st - Principle Assistant	192	SF	6	\$577	
	Doors - Wood Doors inclu hw	1st - Principle Assistant	2	EA	6	\$602	
	Floor - Carpet	1st - Principle Assistant	192	SF	6	\$409	
	Lighting - Lay-in	1st - Principle Assistant	4	EA	7	\$0	
	Power Distribution	1st - Principle Assistant	5	EA	6	\$10,624	
	Storage/ Closet	1st - Principle Assistant	18	SF	6	\$131	
	Walls - Plaster/Drywall	1st - Principle Assistant	587	SF	6	\$1,620	
	AC Unit	1st- Rm 199A- Special Ed Meeting Rm	1	EA	4	\$6,086	cover missing
	Ceiling - Lay-in	1st- Rm 199A- Special Ed Meeting Rm	102	SF	6	\$306	
	Ceiling - Lay-in	1st- Rm 199A- Special Ed Meeting Rm	6	SF	5	\$48	water damaged
	Doors - Wood Doors inclu hw	1st- Rm 199A- Special Ed Meeting Rm	1	EA	6	\$301	
	Floor - Tile	1st- Rm 199A- Special Ed Meeting Rm	108	SF	6	\$236	
	Lighting - Lay-in	1st- Rm 199A- Special Ed Meeting Rm	4	EA	7	\$0	
	Power Distribution	1st- Rm 199A- Special Ed Meeting Rm	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st- Rm 199A- Special Ed Meeting Rm	468	SF	6	\$1,292	
	AC Unit	1st- 108	2	EA	6	\$991	
	Ceiling - Lay-in	1st- 108	1,160	SF	6	\$3,483	
	Doors - Transom Window	1st- 108	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	1st- 108	2	EA	6	\$602	
	Floor - Carpet	1st- 108	1,160	SF	6	\$2,472	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Lighting - Lay-in	1st- 108	25	EA	7	\$0	
	Power Distribution	1st- 108	20	EA	6	\$42,498	
	Storage/ Closet	1st- 108	9	SF	6	\$65	
	Walls - Plaster/Drywall	1st- 108	472	SF	6	\$1,546	interior wall partitions with wood paneling
	Walls - Plaster/Drywall	1st- 108	1,611	SF	6	\$4,446	
	AC Unit	1st- 127A- Teacher Work Room	4	EA	6	\$1,982	
	Ceiling - Splined	1st- 127A- Teacher Work Room	2,003	SF	6	\$1,633	
	Ceiling - Splined	1st- 127A- Teacher Work Room	30	SF	5	\$290	damaged
	Doors - Transom Window	1st- 127A- Teacher Work Room	1	SF	6	\$17	
	Doors - Wood Doors inclu hw	1st- 127A- Teacher Work Room	2	EA	6	\$602	
	Floor - Tile	1st- 127A- Teacher Work Room	2,033	SF	6	\$4,448	
	Lighting - Pendent/Surface	1st- 127A- Teacher Work Room	22	EA	7	\$0	
	Power Distribution	1st- 127A- Teacher Work Room	22	EA	6	\$46,747	
	Walls - Plaster/Drywall	1st- 127A- Teacher Work Room	2,624	SF	6	\$7,242	
	Walls - Structural Glazed Tile	1st- 127A- Teacher Work Room	924	SF	6	\$2,907	
	Ceiling - Splined	1st- Kitchen Manager's Office	111	SF	6	\$90	
	Doors - Side-lite	1st- Kitchen Manager's Office	9	SF	6	\$150	
	Doors - Transom Window	1st- Kitchen Manager's Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st- Kitchen Manager's Office	1	EA	6	\$301	
	Floor - Tile	1st- Kitchen Manager's Office	111	SF	6	\$243	
	Lighting - Pendent/Surface	1st- Kitchen Manager's Office	2	EA	7	\$0	
	Power Distribution	1st- Kitchen Manager's Office	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st- Kitchen Manager's Office	546	SF	6	\$1,507	
	Ceiling - Lay-in	1st- Rm 100A- Police Office	239	SF	6	\$718	
	Doors - Wood Doors inclu hw	1st- Rm 100A- Police Office	1	EA	6	\$301	
	Floor - Carpet	1st- Rm 100A- Police Office	239	SF	6	\$509	
	Lighting - Pendent/Surface	1st- Rm 100A- Police Office	3	EA	7	\$0	
	Power Distribution	1st- Rm 100A- Police Office	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st- Rm 100A- Police Office	1,137	SF	6	\$3,138	
	Ceiling - Lay-in	1st- Rm 100B- Security Office	239	SF	6	\$718	
	Doors - Wood Doors inclu hw	1st- Rm 100B- Security Office	1	EA	6	\$301	
	Floor - Carpet	1st- Rm 100B- Security Office	239	SF	6	\$509	
	Lighting - Pendent/Surface	1st- Rm 100B- Security Office	3	EA	7	\$0	
	Power Distribution	1st- Rm 100B- Security Office	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st- Rm 100B- Security Office	1,137	SF	6	\$3,138	
	AC Unit	1st- Rm 113A- Lab office	1	EA	6	\$496	
	Ceiling - Splined	1st- Rm 113A- Lab office	8	SF	5	\$77	appears to be water damaged

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Ceiling - Splined	1st- Rm 113A- Lab office	405	SF	6	\$330	
	Doors - Wood Doors inclu hw	1st- Rm 113A- Lab office	1	EA	6	\$301	
	Floor - Concrete	1st- Rm 113A- Lab office	413	SF	6	\$219	
	Lighting - Pendent/Surface	1st- Rm 113A- Lab office	8	EA	7	\$0	
	Power Distribution	1st- Rm 113A- Lab office	8	EA	6	\$16,999	
	Storage/ Closet	1st- Rm 113A- Lab office	377	SF	6	\$2,733	
	Walls - Plaster/Drywall	1st- Rm 113A- Lab office	410	SF	6	\$1,132	
	Walls - Plaster/Drywall	1st- Rm 113A- Lab office	10	SF	5	\$51	appears to be water damaged
	Walls - Structural Glazed Tile	1st- Rm 113A- Lab office	916	SF	6	\$2,882	
	AC Unit	1st- Rm 123- ROTC Office	1	EA	6	\$496	
	Ceiling - Lay-in	1st- Rm 123- ROTC Office	138	SF	6	\$414	
	Doors - Wood Doors inclu hw	1st- Rm 123- ROTC Office	2	EA	6	\$602	
	Floor - Wood	1st- Rm 123- ROTC Office	138	SF	6	\$973	
	Lighting - Lay-in	1st- Rm 123- ROTC Office	2	EA	7	\$0	
	Power Distribution	1st- Rm 123- ROTC Office	8	EA	6	\$16,999	
	Storage/ Closet	1st- Rm 123- ROTC Office	36	SF	6	\$261	
	Walls - Metal Panel	1st- Rm 123- ROTC Office	320	SF	6	\$2,389	wood panel
	Walls - Plaster/Drywall	1st- Rm 123- ROTC Office	160	SF	6	\$442	
	Ceiling - Splined	1st- Rm 124B- Vacant Office	154	SF	6	\$126	
	Doors - Wood Doors inclu hw	1st- Rm 124B- Vacant Office	1	EA	6	\$301	
	Floor - Carpet	1st- Rm 124B- Vacant Office	129	SF	6	\$275	
	Floor - Tile	1st- Rm 124B- Vacant Office	25	SF	6	\$55	
	Lighting - Chandelier, Incandescent	1st- Rm 124B- Vacant Office	2	EA	7	\$0	ceiling fans with lights
	Power Distribution	1st- Rm 124B- Vacant Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st- Rm 124B- Vacant Office	780	SF	6	\$2,153	
	Work Slnk	1st- Rm 124B- Vacant Office	1	EA	6	\$508	
	AC Unit	1st- Rm 125- Engineer's Office	1	EA	4	\$6,086	missing cover
	Ceiling - Plaster/Drywall	1st- Rm 125- Engineer's Office	349	SF	6	\$1,208	
	Doors - Wood Doors inclu hw	1st- Rm 125- Engineer's Office	2	EA	6	\$602	
	Floor - Concrete	1st- Rm 125- Engineer's Office	122	SF	6	\$65	
	Floor - Wood	1st- Rm 125- Engineer's Office	227	SF	6	\$1,600	
	Lighting - Pendent/Surface	1st- Rm 125- Engineer's Office	4	EA	7	\$0	
	Power Distribution	1st- Rm 125- Engineer's Office	8	EA	6	\$16,999	
	Storage/ Closet	1st- Rm 125- Engineer's Office	11	SF	6	\$80	
	Walls - Plaster/Drywall	1st- Rm 125- Engineer's Office	1,259	SF	6	\$3,475	
	Ceiling - Plaster/Drywall	1st- Rm 136A	81	SF	6	\$280	
	Doors - Wood Doors inclu hw	1st- Rm 136A	1	EA	6	\$301	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Floor - Tile	1st- Rm 136A	81	SF	6	\$177	
	Lighting - Pendent/Surface	1st- Rm 136A	1	EA	7	\$0	
	Power Distribution	1st- Rm 136A	2	EA	6	\$4,250	
	Storage/ Closet	1st- Rm 136A	294	SF	6	\$2,132	The part on map labeled as Rm 136 is actually storage.
	Walls - Plaster/Drywall	1st- Rm 136A	450	SF	6	\$1,242	
	Ceiling - Plaster/Drywall	1st- Rm 136B	81	SF	6	\$280	
	Doors - Wood Doors inclu hw	1st- Rm 136B	1	EA	6	\$301	
	Floor - Tile	1st- Rm 136B	81	SF	6	\$177	
	Lighting - Pendent/Surface	1st- Rm 136B	1	EA	7	\$0	
	Power Distribution	1st- Rm 136B	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	1st- Rm 136B	450	SF	6	\$1,242	
	AC Unit	1st- Rm 167- Parent's Room	2	EA	6	\$991	
	Ceiling - Splined	1st- Rm 167- Parent's Room	16	SF	5	\$155	water stained tiles
	Ceiling - Splined	1st- Rm 167- Parent's Room	400	SF	6	\$326	
	Doors - Wood Doors inclu hw	1st- Rm 167- Parent's Room	1	EA	6	\$301	
	Floor - Tile	1st- Rm 167- Parent's Room	416	SF	6	\$910	
	Lighting - Pendent/Surface	1st- Rm 167- Parent's Room	4	EA	7	\$0	
	Power Distribution	1st- Rm 167- Parent's Room	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st- Rm 167- Parent's Room	637	SF	6	\$1,758	
	Walls - Structural Glazed Tile	1st- Rm 167- Parent's Room	180	SF	6	\$566	
	AC Unit	1st- Rm 177- Utility	2	EA	6	\$991	
	Ceiling - Splined	1st- Rm 177- Utility	416	SF	6	\$339	
	Floor - Tile	1st- Rm 177- Utility	416	SF	6	\$910	
	Lighting - Pendent/Surface	1st- Rm 177- Utility	4	EA	7	\$0	
	Power Distribution	1st- Rm 177- Utility	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st- Rm 177- Utility	637	SF	6	\$1,758	
	Walls - Plaster/Drywall	1st- Rm 177- Utility	5	SF	5	\$26	peeling & a hole
	Walls - Structural Glazed Tile	1st- Rm 177- Utility	180	SF	6	\$566	
	Ceiling - Lay-in	1st- Rm 199- Special Ed	475	SF	6	\$1,426	
	Doors - Transom Window	1st- Rm 199- Special Ed	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st- Rm 199- Special Ed	1	EA	6	\$301	
	Floor - Tile	1st- Rm 199- Special Ed	25	SF	5	\$144	cracked
	Floor - Tile	1st- Rm 199- Special Ed	450	SF	6	\$985	
	Lighting - Lay-in	1st- Rm 199- Special Ed	10	EA	7	\$0	
	Power Distribution	1st- Rm 199- Special Ed	10	EA	6	\$21,249	
	Walls - Plaster/Drywall	1st- Rm 199- Special Ed	963	SF	6	\$2,658	
	Ceiling - Plaster/Drywall	1st- Student Services	270	SF	6	\$934	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Doors - Wood Doors inclu hw	1st- Student Services	2	EA	6	\$602	
	Floor - Tile	1st- Student Services	5	SF	5	\$29	damaged
	Floor - Tile	1st- Student Services	265	SF	6	\$580	
	Lighting - Lay-in	1st- Student Services	4	EA	7	\$0	recessed cans
	Lighting - Pendent/Surface	1st- Student Services	4	EA	7	\$0	
	Power Distribution	1st- Student Services	10	EA	6	\$21,249	
	Storage/ Closet	1st- Student Services	364	SF	6	\$2,639	
	Walls - Plaster/Drywall	1st- Student Services	786	SF	6	\$2,169	
	Ceiling - Plaster/Drywall	2nd Floor - Coach's Office	302	SF	6	\$1,045	
	Doors - Wood Doors inclu hw	2nd Floor - Coach's Office	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor - Coach's Office	302	SF	6	\$302	
	Lighting - Pendent/Surface	2nd Floor - Coach's Office	2	EA	6	\$248	
	Power Distribution	2nd Floor - Coach's Office	6	EA	6	\$12,749	
	Storage/ Closet	2nd Floor - Coach's Office	30	SF	6	\$218	
	Walls - Plaster/Drywall	2nd Floor - Coach's Office	903	SF	6	\$2,492	
	Ceiling - Lay-in	2nd Floor - Pool Office	155	SF	6	\$465	
	Doors - Steel Doors incl hw	2nd Floor - Pool Office	1	EA	6	\$301	
	Floor - Tile	2nd Floor - Pool Office	155	SF	6	\$339	
	Lighting - Lay-in	2nd Floor - Pool Office	2	EA	6	\$238	
	Power Distribution	2nd Floor - Pool Office	4	EA	6	\$8,500	
	Walls - Structural Glazed Tile	2nd Floor - Pool Office	400	SF	6	\$1,258	
	AC Unit	2nd- Rm 211A- Digital Media Office	1	EA	4	\$6,086	not on a dedicated circuit
	Ceiling - Lay-in	2nd- Rm 211A- Digital Media Office	274	SF	6	\$823	
	Doors - Side-lite	2nd- Rm 211A- Digital Media Office	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd- Rm 211A- Digital Media Office	1	EA	6	\$301	
	Floor - Wood	2nd- Rm 211A- Digital Media Office	274	SF	6	\$1,932	
	Lighting - Lay-in	2nd- Rm 211A- Digital Media Office	2	EA	7	\$0	
	Power Distribution	2nd- Rm 211A- Digital Media Office	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	2nd- Rm 211A- Digital Media Office	731	SF	6	\$2,017	
	Ceiling - Lay-in	2nd- Rm 219- Art Therapy	367	SF	6	\$1,102	
	Doors - Transom Window	2nd- Rm 219- Art Therapy	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- Rm 219- Art Therapy	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd- Rm 219- Art Therapy	3	SF	5	\$17	damaged
	Floor - Tile/Sheet	2nd- Rm 219- Art Therapy	364	SF	6	\$364	
	Lighting - Lay-in	2nd- Rm 219- Art Therapy	8	EA	7	\$0	
	Power Distribution	2nd- Rm 219- Art Therapy	18	EA	6	\$38,248	
	Walls - Plaster/Drywall	2nd- Rm 219- Art Therapy	1,027	SF	6	\$2,834	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	AC Unit	2nd- Rm 220A- Social Studies Office	1	EA	6	\$496	
	Ceiling - Lay-in	2nd- Rm 220A- Social Studies Office	338	SF	6	\$1,015	
	Ceiling - Lay-in	2nd- Rm 220A- Social Studies Office	8	SF	6	\$33	water stained
	Doors - Transom Window	2nd- Rm 220A- Social Studies Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- Rm 220A- Social Studies Office	1	EA	6	\$301	
	Floor - Tile	2nd- Rm 220A- Social Studies Office	13	SF	5	\$75	damaged
	Floor - Tile	2nd- Rm 220A- Social Studies Office	333	SF	6	\$729	
	Lighting - Lay-in	2nd- Rm 220A- Social Studies Office	5	EA	7	\$0	
	Power Distribution	2nd- Rm 220A- Social Studies Office	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	2nd- Rm 220A- Social Studies Office	1,027	SF	6	\$2,834	
	Ceiling - Plaster/Drywall	2nd- Rm 224A- EFI Office	214	SF	6	\$741	
	Doors - Transom Window	2nd- Rm 224A- EFI Office	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd- Rm 224A- EFI Office	2	EA	6	\$602	
	Floor - Tile	2nd- Rm 224A- EFI Office	214	SF	6	\$468	
	Lighting - Pendent/Surface	2nd- Rm 224A- EFI Office	2	EA	7	\$0	
	Power Distribution	2nd- Rm 224A- EFI Office	6	EA	6	\$12,749	
	Storage/ Closet	2nd- Rm 224A- EFI Office	144	SF	6	\$1,044	121SqFt was a restroom, but plumbing has been dismantled & room is used for storage
	Walls - Plaster/Drywall	2nd- Rm 224A- EFI Office	949	SF	6	\$2,619	
	AC Unit	2nd- Rm 229- Social Work Office	1	EA	4	\$6,086	not on a dedicated circuit
	Ceiling - Lay-in	2nd- Rm 229- Social Work Office	8	SF	5	\$64	damaged
	Ceiling - Lay-in	2nd- Rm 229- Social Work Office	306	SF	6	\$919	
	Doors - Transom Window	2nd- Rm 229- Social Work Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- Rm 229- Social Work Office	1	EA	6	\$301	
	Floor - Tile	2nd- Rm 229- Social Work Office	314	SF	6	\$687	
	Lighting - Lay-in	2nd- Rm 229- Social Work Office	6	EA	7	\$0	
	Power Distribution	2nd- Rm 229- Social Work Office	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	2nd- Rm 229- Social Work Office	864	SF	6	\$2,385	
	AC Unit	2nd- Rm 230- Teacher Work Room	1	EA	4	\$6,086	cover missing
	Ceiling - Lay-in	2nd- Rm 230- Teacher Work Room	367	SF	6	\$1,102	
	Doors - Transom Window	2nd- Rm 230- Teacher Work Room	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- Rm 230- Teacher Work Room	1	EA	6	\$301	
	Floor - Tile	2nd- Rm 230- Teacher Work Room	4	SF	5	\$23	damaged
	Floor - Tile	2nd- Rm 230- Teacher Work Room	363	SF	6	\$794	
	Lighting - Lay-in	2nd- Rm 230- Teacher Work Room	6	EA	7	\$0	
	Power Distribution	2nd- Rm 230- Teacher Work Room	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	2nd- Rm 230- Teacher Work Room	1,027	SF	6	\$2,834	
	Ceiling - Plaster/Drywall	3rd- 2nd Boy's PE Office (331A)	204	SF	6	\$706	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Doors - Side-lite	3rd- 2nd Boy's PE Office (331A)	18	SF	6	\$301	
	Doors - Wood Doors inclu hw	3rd- 2nd Boy's PE Office (331A)	1	EA	6	\$301	
	Floor - Tile	3rd- 2nd Boy's PE Office (331A)	204	SF	5	\$916	damaged throughout
	Lighting - Pendent/Surface	3rd- 2nd Boy's PE Office (331A)	2	EA	7	\$0	
	Power Distribution	3rd- 2nd Boy's PE Office (331A)	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	3rd- 2nd Boy's PE Office (331A)	675	SF	6	\$1,863	
	Work Slnk	3rd- 2nd Boy's PE Office (331A)	1	EA	5	\$1,508	not working
	Ceiling - Plaster/Drywall	3rd- Boy's PE Office	2	SF	5	\$25	peeling
	Ceiling - Plaster/Drywall	3rd- Boy's PE Office	275	SF	6	\$952	
	Doors - Side-lite	3rd- Boy's PE Office	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd- Boy's PE Office	2	EA	6	\$602	
	Floor - Wood	3rd- Boy's PE Office	277	SF	6	\$1,953	
	Lighting - Pendent/Surface	3rd- Boy's PE Office	2	EA	7	\$0	
	Power Distribution	3rd- Boy's PE Office	10	EA	6	\$21,249	
	Walls - Plaster/Drywall	3rd- Boy's PE Office	675	SF	6	\$1,863	
	Ceiling - Plaster/Drywall	3rd- Girls Gym Office/Kitchen	201	SF	6	\$696	
	Doors - Side-lite	3rd- Girls Gym Office/Kitchen	18	SF	6	\$301	
	Doors - Wood Doors inclu hw	3rd- Girls Gym Office/Kitchen	1	EA	6	\$301	
	Floor - Wood	3rd- Girls Gym Office/Kitchen	201	SF	6	\$1,417	
	Lighting - Pendent/Surface	3rd- Girls Gym Office/Kitchen	2	EA	7	\$0	
	Power Distribution	3rd- Girls Gym Office/Kitchen	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	3rd- Girls Gym Office/Kitchen	585	SF	6	\$1,615	
	Work Slnk	3rd- Girls Gym Office/Kitchen	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	3rd- Girl's PE Office	20	SF	5	\$250	peeling
	Ceiling - Plaster/Drywall	3rd- Girl's PE Office	257	SF	6	\$889	
	Doors - Side-lite	3rd- Girl's PE Office	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd- Girl's PE Office	2	EA	6	\$602	
	Floor - Wood	3rd- Girl's PE Office	277	SF	6	\$1,953	
	Lighting - Pendent/Surface	3rd- Girl's PE Office	2	EA	7	\$0	
	Power Distribution	3rd- Girl's PE Office	14	EA	6	\$29,748	
	Walls - Plaster/Drywall	3rd- Girl's PE Office	675	SF	6	\$1,863	
	Ceiling - Plaster/Drywall	3rd- Rm 309- Art Work Room	367	SF	6	\$1,270	
	Doors - Transom Window	3rd- Rm 309- Art Work Room	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd- Rm 309- Art Work Room	1	EA	6	\$301	
	Floor - Tile	3rd- Rm 309- Art Work Room	367	SF	5	\$1,648	damaged throughout
	Lighting - Pendent/Surface	3rd- Rm 309- Art Work Room	4	EA	7	\$0	
	Power Distribution	3rd- Rm 309- Art Work Room	6	EA	5	\$23,110	outlets not working

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Power Distribution	3rd- Rm 309- Art Work Room	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	3rd- Rm 309- Art Work Room	1,027	SF	6	\$2,834	
	AC Unit	3rd- Rm 319A- Math Office	1	EA	4	\$6,086	not on a dedicated circuit
	Ceiling - Lay-in	3rd- Rm 319A- Math Office	368	SF	6	\$1,105	
	Doors - Transom Window	3rd- Rm 319A- Math Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd- Rm 319A- Math Office	1	EA	6	\$301	
	Floor - Tile	3rd- Rm 319A- Math Office	368	SF	5	\$1,652	damaged throughout
	Lighting - Lay-in	3rd- Rm 319A- Math Office	5	EA	7	\$0	
	Power Distribution	3rd- Rm 319A- Math Office	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	3rd- Rm 319A- Math Office	864	SF	6	\$2,385	
	Ceiling - Lay-in	4th- Rm 400A- Orchestra Office	167	SF	6	\$502	
	Floor - Tile	4th- Rm 400A- Orchestra Office	167	SF	6	\$365	
	Lighting - Lay-in	4th- Rm 400A- Orchestra Office	4	EA	7	\$0	
	Power Distribution	4th- Rm 400A- Orchestra Office	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	4th- Rm 400A- Orchestra Office	530	SF	6	\$1,463	
	Work Sink	4th- Rm 400A- Orchestra Office	1	EA	6	\$508	
	Ceiling - Lay-in	4th- Rm 401A- Band Office	167	SF	6	\$502	
	Floor - Tile	4th- Rm 401A- Band Office	167	SF	6	\$365	
	Lighting - Lay-in	4th- Rm 401A- Band Office	4	EA	7	\$0	
	Power Distribution	4th- Rm 401A- Band Office	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	4th- Rm 401A- Band Office	530	SF	6	\$1,463	
	Work Sink	4th- Rm 401A- Band Office	1	EA	6	\$508	
	Ceiling - Plaster/Drywall		106	SF	6	\$367	
	Doors - Steel Doors incl hw		2	EA	6	\$602	
	Floor - Tile		106	SF	6	\$232	
	Lighting - Pendent/Surface		1	EA	6	\$124	
	Power Distribution		4	EA	6	\$8,500	
	Walls - Plaster/Drywall		535	SF	6	\$1,477	
Auditorium & Theater							
	Ceiling - Lay-in	1st- Rm 122 Small Auditorium	1,570	SF	6	\$4,715	
	Ceiling - Lay-in	1st- Rm 122 Small Auditorium	10	SF	5	\$80	water stained
	Ceiling - Plaster/Drywall	1st- Rm 122 Small Auditorium	5	SF	5	\$158	water damaged above stage
	Ceiling - Plaster/Drywall	1st- Rm 122 Small Auditorium	620	SF	6	\$5,169	
	Ceiling - Splined	1st- Rm 122 Small Auditorium	500	SF	6	\$408	
	Ceiling - Splined	1st- Rm 122 Small Auditorium	6	SF	5	\$58	water damaged
	Doors - Wood Doors inclu hw	1st- Rm 122 Small Auditorium	4	EA	6	\$1,204	
	Floor - Carpet	1st- Rm 122 Small Auditorium	2,086	SF	6	\$4,445	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Auditorium & Theater							
	Floor - Wood	1st- Rm 122 Small Auditorium	625	SF	6	\$4,406	stage & hallway
	Lighting - Chandelier, Incandescent	1st- Rm 122 Small Auditorium	5	EA	7	\$0	
	Lighting - Lay-in	1st- Rm 122 Small Auditorium	32	EA	7	\$0	
	Lighting - Pendent/Surface	1st- Rm 122 Small Auditorium	2	EA	7	\$0	
	Lighting - Wall Mounted	1st- Rm 122 Small Auditorium	36	EA	7	\$0	cove lighting
	Main Floor Seating	1st- Rm 122 Small Auditorium	142	EA	6	\$24,696	
	Sound System	1st- Rm 122 Small Auditorium	1	EA	6	\$10,721	
	Stage	1st- Rm 122 Small Auditorium	425	SF	6	\$2,455	
	Stage Curtain	1st- Rm 122 Small Auditorium	4	EA	6	\$0	
	Stage Lighting System	1st- Rm 122 Small Auditorium	1	EA	6	\$8,077	
	Stage-Stairs - Wood	1st- Rm 122 Small Auditorium	20	LF	6	\$235	
	Walls - Concrete Block	1st- Rm 122 Small Auditorium	1	SF	5	\$10	NO OCCUPANCY PLACARD POSTED
	Walls - Plaster/Drywall	1st- Rm 122 Small Auditorium	5,406	SF	6	\$25,743	
Clinic							
	Ceiling - Lay-in	1st- Rm 119- Nurse	415	SF	6	\$1,246	
	Doors - Transom Window	1st- Rm 119- Nurse	9	SF	5	\$381	glass is broken
	Doors - Wood Doors inclu hw	1st- Rm 119- Nurse	1	EA	5	\$1,174	door hinges are broken & need replacing
	Floor - Tile/Sheet	1st- Rm 119- Nurse	415	SF	6	\$415	
	Lighting - Lay-in	1st- Rm 119- Nurse	10	EA	7	\$0	
	Walls - Plaster/Drywall	1st- Rm 119- Nurse	907	SF	6	\$2,503	
Gymnasia							
	Ceiling - Plaster/Drywall	2nd Floor - Weigh Room	2,302	SF	6	\$12,707	
	Doors - Steel Doors incl hw	2nd Floor - Weigh Room	2	EA	6	\$602	
	Floor - Weight/ Fitness Room Floor Matting	2nd Floor - Weigh Room	2,302	SF	6	\$12,048	
	Lighting - Pendent/Surface	2nd Floor - Weigh Room	30	EA	6	\$3,717	
	Storage/ Closet	2nd Floor - Weigh Room	195	SF	6	\$1,414	
	Walls - Structural Glazed Tile	2nd Floor - Weigh Room	2,495	SF	6	\$7,849	
	Ceiling - Plaster/Drywall	3rd- Rm 331	100	SF	5	\$2,003	peeling
	Ceiling - Plaster/Drywall	3rd- Rm 331	10,535	SF	6	\$58,151	
	Doors - Transom Window	3rd- Rm 331	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	3rd- Rm 331	2	EA	6	\$602	
	Floor - Concrete	3rd- Rm 331	3,425	SF	6	\$1,812	balcony
	Floor - Terrazzo	3rd- Rm 331	99	SF	6	\$217	
	Floor - Wood	3rd- Rm 331	7,110	SF	6	\$50,125	
	Lighting - Metal Halide/Sodium Vapor	3rd- Rm 331	15	EA	7	\$0	
	Lighting - Pendent/Surface	3rd- Rm 331	21	EA	7	\$0	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Gymnasia							
	Scoreboards	3rd- Rm 331	1	EA	6	\$2,244	
	Stage-Stairs - Terrazzo	3rd- Rm 331	25	LF	6	\$191	stairs to balcony
	Storage/ Closet	3rd- Rm 331	404	SF	5	\$6,517	peeling paint
	Storage/ Closet	3rd- Rm 331	404	SF	6	\$2,929	
	Walls - Plaster/Drywall	3rd- Rm 331	1	SF	5	\$8	Bench seating in balcony is for 228 people. Occupancy card says 187 people may occupy balcony.
	Walls - Structural Glazed Tile	3rd- Rm 331	7,014	SF	6	\$22,066	
	Bleacher Seating	3rd- Rm 334	88	EA	6	\$2,547	Room for 88 people on balcony benches-occupany card allows up to 93.
	Ceiling - Plaster/Drywall	3rd- Rm 334	5,488	SF	6	\$30,293	
	Ceiling - Plaster/Drywall	3rd- Rm 334	25	SF	5	\$501	water damage
	Doors - Wood Doors inclu hw	3rd- Rm 334	2	EA	6	\$602	
	Floor - Concrete	3rd- Rm 334	1,450	SF	6	\$767	balcony floor
	Floor - Wood	3rd- Rm 334	4,063	SF	6	\$28,644	
	Lighting - Metal Halide/Sodium Vapor	3rd- Rm 334	8	EA	7	\$0	
	Lighting - Pendent/Surface	3rd- Rm 334	8	EA	7	\$0	
	Lighting - Pendent/Surface	3rd- Rm 334	1	EA	6	\$124	cover missing
	Scoreboards	3rd- Rm 334	1	EA	6	\$2,244	
	Storage/ Closet	3rd- Rm 334	328	SF	6	\$2,378	Room is on otherside of hall. Minor peeling on ceiling
	Walls - Structural Glazed Tile	3rd- Rm 334	5,740	SF	6	\$18,058	
	Ceiling - Plaster/Drywall	3rd- Rm 336	3,378	SF	6	\$18,646	
	Doors - Wood Doors inclu hw	3rd- Rm 336	2	EA	6	\$602	
	Floor - Wood	3rd- Rm 336	3,378	SF	6	\$23,815	
	Lighting - Metal Halide/Sodium Vapor	3rd- Rm 336	8	EA	7	\$0	
	Lighting - Pendent/Surface	3rd- Rm 336	3	EA	7	\$0	
	Storage/ Closet	3rd- Rm 336	181	SF	6	\$1,312	door is broken
	Walls - Structural Glazed Tile	3rd- Rm 336	5,148	SF	6	\$16,196	
Kitchen							
	Ceiling - Lay-in	1st- Dishwashing Rm	766	SF	6	\$2,300	
	Doors - Transom Window	1st- Dishwashing Rm	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st- Dishwashing Rm	2	EA	6	\$602	
	Floor - Weight/ Fitness Room Floor Matting	1st- Dishwashing Rm	766	SF	6	\$4,009	Rubber Floor Tiles
	Lighting - Lay-in	1st- Dishwashing Rm	12	EA	7	\$0	
	Walls - Structural Glazed Tile	1st- Dishwashing Rm	1,111	SF	6	\$3,495	
	Ceiling - Lay-in	1st Floor	1,693	SF	6	\$5,084	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Kitchen							
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	1,693	SF	6	\$3,704	
	Lighting - Lay-in	1st Floor	26	EA	7	\$0	
	Storage/ Closet	1st Floor	569	SF	6	\$4,125	
	Walls - Structural Glazed Tile	1st Floor	1,750	SF	6	\$5,506	
Library							
	AC Unit	2nd Floor	3	EA	6	\$1,487	
	Casework	2nd Floor	144	LF	6	\$3,637	
	Ceiling - Plaster/Drywall	2nd Floor	3	SF	5	\$37	water damage
	Ceiling - Plaster/Drywall	2nd Floor	357	SF	6	\$1,235	
	Ceiling - Splined	2nd Floor	2,130	SF	6	\$1,736	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Carpet	2nd Floor	2,202	SF	6	\$4,692	
	Floor - Tile	2nd Floor	144	SF	5	\$647	damaged throughout
	Lighting - Pendent/Surface	2nd Floor	56	EA	7	\$0	
	Storage/ Closet	2nd Floor	146	SF	6	\$1,059	
	Walls - Plaster/Drywall	2nd Floor	2,723	SF	6	\$7,515	
Locker/Shower Room							
	Accessories	1st- Kitchen Staff Locker Rm	96	SF	6	\$376	
	Ceiling - Exposed	1st- Kitchen Staff Locker Rm	143	SF	6	\$213	
	Ceiling - Plaster/ Drywall	1st- Kitchen Staff Locker Rm	138	SF	6	\$478	
	Doors - Wood Doors inclu hw	1st- Kitchen Staff Locker Rm	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	1st- Kitchen Staff Locker Rm	96	SF	6	\$203	
	Floor - Tile/Sheet	1st- Kitchen Staff Locker Rm	185	SF	6	\$185	
	Lavatory	1st- Kitchen Staff Locker Rm	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st- Kitchen Staff Locker Rm	4	EA	7	\$0	
	Partitions	1st- Kitchen Staff Locker Rm	1	EA	6	\$297	
	Student Lockers - One Tier	1st- Kitchen Staff Locker Rm	16	EA	6	\$1,485	
	Walls - Plaster/Drywall	1st- Kitchen Staff Locker Rm	1,129	SF	6	\$3,116	
	Walls - Plaster/Drywall	1st- Kitchen Staff Locker Rm	15	SF	5	\$77	water damaged
	Walls - Tile Ceramic/ Porcelain	1st- Kitchen Staff Locker Rm	18	SF	6	\$121	
	Walls - Tile Ceramic/ Porcelain	1st- Kitchen Staff Locker Rm	78	SF	6	\$176	Stone
	Water Closet	1st- Kitchen Staff Locker Rm	1	EA	6	\$336	
	Ceiling - Plaster/ Drywall	1st- Rm 129- Custodial Staff Locker Room	314	SF	6	\$1,087	
	Doors - Transom Window	1st- Rm 129- Custodial Staff Locker Room	9	SF	6	\$152	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/Shower Room							
	Doors - Wood Doors inclu hw	1st- Rm 129- Custodial Staff Locker Room	1	EA	6	\$301	
	Floor - Concrete	1st- Rm 129- Custodial Staff Locker Room	314	SF	6	\$166	
	Lavatory	1st- Rm 129- Custodial Staff Locker Room	1	EA	4	\$7,342	missing
	Lighting - Pendent/Surface	1st- Rm 129- Custodial Staff Locker Room	3	EA	7	\$0	
	Partitions	1st- Rm 129- Custodial Staff Locker Room	2	EA	5	\$1,502	missing doors
	Student Lockers - One Tier	1st- Rm 129- Custodial Staff Locker Room	4	EA	6	\$371	
	Student Lockers - Two Tier	1st- Rm 129- Custodial Staff Locker Room	40	EA	6	\$1,857	
	Walls - Plaster/Drywall	1st- Rm 129- Custodial Staff Locker Room	877	SF	6	\$2,420	
	Walls - Tile Ceramic/ Porcelain	1st- Rm 129- Custodial Staff Locker Room	75	SF	6	\$169	stone
	Walls - Tile Ceramic/ Porcelain	1st- Rm 129- Custodial Staff Locker Room	36	SF	6	\$241	
	Water Closet	1st- Rm 129- Custodial Staff Locker Room	2	EA	4	\$15,339	missing
	Accessories	2nd Floor	5,010	SF	6	\$19,630	
	Accessories	2nd Floor	1,650	SF	6	\$6,465	
	Benches, ped mounted	2nd Floor	50	LF	6	\$5,444	
	Benches, ped mounted	2nd Floor	315	LF	6	\$34,297	
	Ceiling - Plaster/ Drywall	2nd Floor	5,010	SF	6	\$17,338	peeling
	Ceiling - Plaster/ Drywall	2nd Floor	1,650	SF	6	\$5,710	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor Drain	2nd Floor	32	EA	6	\$33,893	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	5,010	SF	6	\$10,603	
	Floor - Tile/Sheet	2nd Floor	1,650	SF	6	\$1,652	
	Lighting - Pendent/Surface	2nd Floor	34	EA	6	\$4,212	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	\$1,982	
	Showers	2nd Floor	56	EA	6	\$17,439	
	Storage/ Closet	2nd Floor	250	SF	6	\$1,813	
	Student Lockers - One Tier	2nd Floor	476	EA	6	\$44,190	
	Student Lockers - One Tier	2nd Floor	1,358	EA	6	\$126,071	
	Walls - Structural Glazed Tile	2nd Floor	3,680	SF	6	\$11,577	
	Walls - Structural Glazed Tile	2nd Floor	2,112	SF	6	\$6,644	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/Shower Room							
	Accessories	3rd- Boy's PE Coach Locker Rm	127	SF	6	\$498	
	Ceiling - Plaster/ Drywall	3rd- Boy's PE Coach Locker Rm	127	SF	5	\$1,213	peeling
	Doors - Wood Doors inclu hw	3rd- Boy's PE Coach Locker Rm	1	EA	6	\$301	
	Floor Drain	3rd- Boy's PE Coach Locker Rm	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	3rd- Boy's PE Coach Locker Rm	127	SF	6	\$269	
	Lavatory	3rd- Boy's PE Coach Locker Rm	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd- Boy's PE Coach Locker Rm	1	EA	7	\$0	
	Partitions	3rd- Boy's PE Coach Locker Rm	1	EA	5	\$751	door is delaminating
	Showers	3rd- Boy's PE Coach Locker Rm	1	EA	6	\$311	
	Student Lockers - One Tier	3rd- Boy's PE Coach Locker Rm	8	EA	6	\$743	
	Urinals	3rd- Boy's PE Coach Locker Rm	1	EA	6	\$336	
	Walls - Plaster/Drywall	3rd- Boy's PE Coach Locker Rm	330	SF	5	\$2,501	peeling
	Walls - Tile Ceramic/ Porcelain	3rd- Boy's PE Coach Locker Rm	117	SF	6	\$264	stone
	Walls - Tile Ceramic/ Porcelain	3rd- Boy's PE Coach Locker Rm	3	SF	5	\$63	stone- damaged
	Water Closet	3rd- Boy's PE Coach Locker Rm	1	EA	6	\$336	
	Accessories	3rd- Girl's PE Coach Locker Rm	127	SF	6	\$498	
	Ceiling - Plaster/ Drywall	3rd- Girl's PE Coach Locker Rm	125	SF	6	\$433	
	Ceiling - Plaster/ Drywall	3rd- Girl's PE Coach Locker Rm	2	SF	5	\$26	water damaged
	Doors - Wood Doors inclu hw	3rd- Girl's PE Coach Locker Rm	1	EA	6	\$301	
	Floor Drain	3rd- Girl's PE Coach Locker Rm	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	3rd- Girl's PE Coach Locker Rm	126	SF	6	\$267	
	Floor - Tile Ceramic/ Porcelain	3rd- Girl's PE Coach Locker Rm	1	SF	5	\$21	hole in floor
	Lavatory	3rd- Girl's PE Coach Locker Rm	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd- Girl's PE Coach Locker Rm	1	EA	7	\$0	
	Partitions	3rd- Girl's PE Coach Locker Rm	1	EA	6	\$297	
	Showers	3rd- Girl's PE Coach Locker Rm	1	EA	6	\$311	
	Student Lockers - One Tier	3rd- Girl's PE Coach Locker Rm	5	EA	6	\$464	
	Walls - Plaster/Drywall	3rd- Girl's PE Coach Locker Rm	330	SF	6	\$911	
	Walls - Tile Ceramic/ Porcelain	3rd- Girl's PE Coach Locker Rm	120	SF	6	\$271	stone
	Water Closet	3rd- Girl's PE Coach Locker Rm	1	EA	6	\$336	
Lunch & Multipurpose Room							
	Ceiling - Splined	1st Floor	5,424	SF	6	\$4,421	
	Ceiling - Splined	1st Floor	79	SF	5	\$764	missing &/or water damaged
	Doors - Wood Doors inclu hw	1st Floor	11	EA	6	\$3,311	
	Floor - Tile	1st Floor	5,503	SF	6	\$12,040	
	Lighting - Pendent/Surface	1st Floor	48	EA	6	\$5,947	
	Walls - Plaster/Drywall	1st Floor	1,930	SF	6	\$5,327	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lunch & Multipurpose Room							
	Walls - Structural Glazed Tile	1st Floor	1,930	SF	6	\$6,072	
	Ceiling - Lay-in	1st- Rm 128- Alumni Hall	4	SF	5	\$32	water stains on tile
	Ceiling - Lay-in	1st- Rm 128- Alumni Hall	1,222	SF	6	\$3,670	
	Doors - Wood Doors inclu hw	1st- Rm 128- Alumni Hall	2	EA	6	\$602	
	Floor - Carpet	1st- Rm 128- Alumni Hall	1,226	SF	6	\$2,612	
	Lighting - Lay-in	1st- Rm 128- Alumni Hall	51	EA	7	\$0	mix of lay-in & recessed cans
	Lighting - Wall Mounted	1st- Rm 128- Alumni Hall	32	EA	7	\$0	cove lights
	Storage/ Closet	1st- Rm 128- Alumni Hall	193	SF	6	\$1,399	
	Walls - Metal Panel	1st- Rm 128- Alumni Hall	1,212	SF	6	\$9,047	Wood panel
	Walls - Plaster/Drywall	1st- Rm 128- Alumni Hall	606	SF	6	\$1,672	
	Ceiling - Lay-in	1st- Servery	1,015	SF	6	\$3,048	
	Ceiling - Splined	1st- Servery	2,695	SF	6	\$2,197	
	Doors - Transom Window	1st- Servery	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st- Servery	4	EA	6	\$1,204	
	Floor - Tile	1st- Servery	3,710	SF	6	\$8,117	
	Lighting - Lay-in	1st- Servery	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st- Servery	56	EA	7	\$0	
	Serving Line	1st- Servery	180	LF	6	\$10,713	
	Walls - Plaster/Drywall	1st- Servery	876	SF	6	\$2,418	
	Walls - Structural Glazed Tile	1st- Servery	1,752	SF	6	\$5,512	
	Ceiling - Splined	1st- Teacher Lunchroom	720	SF	6	\$587	
	Doors - Side-lite	1st- Teacher Lunchroom	240	SF	6	\$4,012	
	Doors - Transom Window	1st- Teacher Lunchroom	135	SF	6	\$2,286	
	Doors - Wood Doors inclu hw	1st- Teacher Lunchroom	3	EA	6	\$903	
	Floor - Tile	1st- Teacher Lunchroom	720	SF	6	\$1,575	
	Lighting - Pendent/Surface	1st- Teacher Lunchroom	8	EA	7	\$0	
	Walls - Plaster/Drywall	1st- Teacher Lunchroom	352	SF	6	\$971	
	Walls - Structural Glazed Tile	1st- Teacher Lunchroom	705	SF	6	\$2,218	
MDF_IDF							
	AC Unit	1st- Rm 126	1	EA	4	\$6,086	missing cover
	Doors - Wood Doors inclu hw	1st- Rm 126	1	EA	6	\$301	
	Finishes	1st- Rm 126	265	SF	6	\$1,891	
	AC Unit	2nd- IDF inside room 220	1	EA	6	\$496	
	Doors - Wood Doors inclu hw	2nd- IDF inside room 220	2	EA	6	\$602	
	Finishes	2nd- IDF inside room 220	174	SF	6	\$1,242	some floor ties missing or damaged

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechanical/ Service Rooms							
	Janitor's Closet	1st Floor	73	SF	6	\$523	
	Mechanical/ Service Rooms	1st Floor	310	SF	6	\$2,221	
	Mechanical/ Service Rooms	1st Floor	366	SF	5	\$5,904	Rm 117 Freight Elevator room has water damage & peeling paint.
	Storage Room	1st Floor	703	SF	6	\$5,037	
	Vaults	1st Floor	664	SF	6	\$4,757	inside 104A & 113A & ROTC
	Janitor's Closet	2nd Floor	21	SF	6	\$150	
	Janitor's Closet	2nd Floor	51	SF	5	\$823	water damaged ceiling
	Mechanical/ Service Rooms	2nd Floor	116	SF	6	\$831	elec closets
	Mechanical/ Service Rooms	2nd Floor	366	SF	5	\$5,904	Rm 217 Freight Elevator room has water damage & peeling paint, plus door jamb & transom are broken.
	Storage Room	2nd Floor	206	SF	6	\$1,476	
	Vaults	2nd Floor	148	SF	6	\$1,060	rm 216/214
	Air Intake Plenums	3rd Floor	23	SF	6	\$142	FAI
	Boiler Room	3rd Floor	1,231	SF	6	\$8,819	Chiller Room above Boiler Rm
	Janitor's Closet	3rd Floor	91	SF	6	\$652	
	Mechanical/ Service Rooms	3rd Floor	366	SF	5	\$5,904	Rm 317 Freight Elevator room has water damage & peeling paint & floor needs refinishing
	Mechanical/ Service Rooms	3rd Floor	116	SF	6	\$831	Elec closet
	Storage Room	3rd Floor	171	SF	6	\$1,225	
	Vaults	3rd Floor	148	SF	6	\$1,060	Rm 316/314
	Air Intake Plenums	4th Floor	516	SF	6	\$3,195	Fan room : located off balcony for Gym 331
	Mechanical/ Service Rooms	4th Floor	41	SF	5	\$661	Electric Closet by Rm 400 - damaged plaster
	Vaults	4th Floor	43	SF	6	\$308	by Rm 401
	Air Intake Plenums	Basement	1,193	SF	6	\$7,387	
	Air Tunnel	Basement	11,589	SF	6	\$71,758	several water stains along walls / floors
	Auditorium Plenums	Basement	2,021	SF	6	\$12,514	
	Boiler Room	Basement	3,434	SF	6	\$24,602	
	Crawl Space - Unfinished	Basement	22,595	SF	6	\$139,906	
	Interior Stairs	Basement	80	LF	6	\$722	concrete / steel
	Mechanical/ Service Rooms	Basement	27,124	SF	5	\$437,521	Switch Board room ceiling damaged / walls peeling all over
	Storage Room	Basement	3,711	SF	6	\$26,587	
	Storage Room	Basement	1,727	SF	6	\$12,373	ROTC old rifle range (now storage) has minor peeling at stairs wall & ceiling
Pool & Natatorium							
	Bleachers Seating/Plank Seating	2nd Floor	5	EA	6	\$145	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Pool & Natatorium							
	Ceiling - Lay-In	2nd Floor	3,176	SF	6	\$9,538	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Concrete	2nd Floor	3,176	SF	6	\$1,680	
	Lighting - Lay-in	2nd Floor	12	EA	6	\$1,428	
	Pool Deck	2nd Floor	1,666	SF	6	\$15,819	
	Pool Deck Drains	2nd Floor	6	EA	6	\$2,532	
	Walls - Structural Glazed Tile	2nd Floor	2,705	SF	6	\$8,510	
Prep Room							
	Ceiling - Lay-in	3rd- Rm 314A	144	SF	6	\$432	
	Doors - Side-lite	3rd- Rm 314A	9	SF	6	\$150	
	Doors - Steel Doors incl hw	3rd- Rm 314A	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd- Rm 314A	144	SF	6	\$144	
	Lighting - Lay-in	3rd- Rm 314A	2	EA	7	\$0	
	Walls - Plaster/Drywall	3rd- Rm 314A	545	SF	6	\$1,504	
	Work Sink	3rd- Rm 314A	1	EA	6	\$379	
	Ceiling - Lay-in	3rd- Rm 316A	144	SF	6	\$432	
	Doors - Side-lite	3rd- Rm 316A	9	SF	6	\$150	
	Doors - Steel Doors incl hw	3rd- Rm 316A	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd- Rm 316A	144	SF	6	\$144	
	Lighting - Lay-in	3rd- Rm 316A	2	EA	7	\$0	
	Walls - Plaster/Drywall	3rd- Rm 316A	545	SF	6	\$1,504	
	Work Sink	3rd- Rm 316A	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	3rd- Rm 320A	197	SF	5	\$1,806	damaged
	Doors - Side-lite	3rd- Rm 320A	40	SF	6	\$669	
	Doors - Wood Doors inclu hw	3rd- Rm 320A	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd- Rm 320A	197	SF	6	\$197	
	Lighting - Pendent/Surface	3rd- Rm 320A	4	EA	7	\$0	
	Walls - Plaster/Drywall	3rd- Rm 320A	728	SF	6	\$2,009	
	Work Sink	3rd- Rm 320A	1	EA	6	\$379	
Restroom							
	Accessories	1st- Boy's NE	223	SF	6	\$2,057	
	Ceiling - Plaster/Drywall	1st- Boy's NE	223	SF	6	\$772	
	Floor Drain	1st- Boy's NE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st- Boy's NE	223	SF	6	\$472	
	Hand Dryer	1st- Boy's NE	1	EA	6	\$230	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Lavatory	1st- Boy's NE	1	EA	6	\$320	
	Lighting - Pendant/Surface	1st- Boy's NE	4	EA	7	\$0	
	Partitions	1st- Boy's NE	1	EA	5	\$751	door missing
	Urinals	1st- Boy's NE	5	EA	6	\$1,680	
	Walls - Plaster/Drywall	1st- Boy's NE	153	SF	6	\$422	
	Walls - Tile Ceramic/ Porcelain	1st- Boy's NE	606	SF	6	\$1,369	
	Water Closet	1st- Boy's NE	1	EA	6	\$336	
	Accessories	1st- Boy's SE	223	SF	6	\$2,057	
	Ceiling - Plaster/Drywall	1st- Boy's SE	223	SF	6	\$772	
	Floor Drain	1st- Boy's SE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st- Boy's SE	223	SF	6	\$472	
	Hand Dryer	1st- Boy's SE	1	EA	6	\$230	
	Lavatory	1st- Boy's SE	1	EA	6	\$320	
	Lighting - Pendant/Surface	1st- Boy's SE	4	EA	7	\$0	
	Partitions	1st- Boy's SE	2	EA	6	\$594	
	Urinals	1st- Boy's SE	5	EA	6	\$1,680	
	Walls - Plaster/Drywall	1st- Boy's SE	153	SF	6	\$422	
	Walls - Tile Ceramic/ Porcelain	1st- Boy's SE	606	SF	6	\$1,369	
	Water Closet	1st- Boy's SE	2	EA	6	\$672	
	Accessories	1st- Engineer Office	149	SF	6	\$1,374	
	Ceiling - Plaster/Drywall	1st- Engineer Office	149	SF	6	\$516	
	Doors - Wood Doors inclu hw	1st- Engineer Office	1	EA	6	\$301	
	Floor Drain	1st- Engineer Office	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	1st- Engineer Office	149	SF	6	\$315	
	Lavatory	1st- Engineer Office	1	EA	6	\$320	
	Lighting - Pendant/Surface	1st- Engineer Office	2	EA	7	\$0	
	Lighting - Wall Mounted	1st- Engineer Office	1	EA	7	\$0	
	Partitions	1st- Engineer Office	1	EA	6	\$297	
	Showers	1st- Engineer Office	1	EA	6	\$311	
	Walls - Plaster/Drywall	1st- Engineer Office	475	SF	6	\$1,311	
	Walls - Tile	1st- Engineer Office	120	SF	6	\$263	Stone
	Walls - Tile Ceramic/ Porcelain	1st- Engineer Office	42	SF	6	\$95	
	Water Closet	1st- Engineer Office	1	EA	6	\$336	
	Accessories	1st- Girl's NE	294	SF	6	\$2,712	
	Ceiling - Plaster/Drywall	1st- Girl's NE	294	SF	6	\$1,017	
	Floor Drain	1st- Girl's NE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st- Girl's NE	294	SF	6	\$622	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Hand Dryer	1st- Girl's NE	2	EA	6	\$460	
	Lavatory	1st- Girl's NE	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st- Girl's NE	5	EA	7	\$0	
	Partitions	1st- Girl's NE	6	EA	6	\$1,782	
	Walls - Plaster/Drywall	1st- Girl's NE	5	SF	5	\$26	water damaged
	Walls - Plaster/Drywall	1st- Girl's NE	195	SF	6	\$538	
	Walls - Tile Ceramic/ Porcelain	1st- Girl's NE	586	SF	6	\$1,324	
	Water Closet	1st- Girl's NE	7	EA	6	\$2,352	
	Accessories	1st- Girl's SE	294	SF	6	\$2,712	
	Ceiling - Plaster/Drywall	1st- Girl's SE	294	SF	6	\$1,017	
	Floor Drain	1st- Girl's SE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st- Girl's SE	294	SF	6	\$622	
	Hand Dryer	1st- Girl's SE	2	EA	6	\$460	
	Lavatory	1st- Girl's SE	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st- Girl's SE	7	EA	7	\$0	
	Partitions	1st- Girl's SE	5	EA	6	\$1,485	
	Walls - Plaster/Drywall	1st- Girl's SE	246	SF	6	\$679	
	Walls - Tile Ceramic/ Porcelain	1st- Girl's SE	607	SF	6	\$1,371	
	Water Closet	1st- Girl's SE	6	EA	6	\$2,016	
	Accessories	1st- inside 102 Principle	119	SF	6	\$1,098	
	Ceiling - Plaster/Drywall	1st- inside 102 Principle	119	SF	6	\$412	
	Doors - Wood Doors inclu hw	1st- inside 102 Principle	1	EA	6	\$301	
	Floor - Carpet	1st- inside 102 Principle	119	SF	6	\$254	
	Lavatory	1st- inside 102 Principle	1	EA	6	\$320	
	Lighting - Lay-in	1st- inside 102 Principle	2	EA	7	\$0	recessed cans
	Walls - Plaster/Drywall	1st- inside 102 Principle	64	SF	6	\$177	
	Walls - Tile Ceramic/ Porcelain	1st- inside 102 Principle	106	SF	6	\$239	
	Water Closet	1st- inside 102 Principle	1	EA	6	\$336	
	Accessories	1st- Men's (across from Auditorium)	105	SF	6	\$968	
	Ceiling - Plaster/Drywall	1st- Men's (across from Auditorium)	105	SF	6	\$363	
	Doors - Wood Doors inclu hw	1st- Men's (across from Auditorium)	2	EA	6	\$602	
	Floor - Tile	1st- Men's (across from Auditorium)	105	SF	6	\$230	
	Floor - Tile Ceramic/ Porcelain	1st- Men's (across from Auditorium)	170	SF	6	\$360	
	Hand Dryer	1st- Men's (across from Auditorium)	1	EA	6	\$230	
	Lavatory	1st- Men's (across from Auditorium)	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st- Men's (across from Auditorium)	3	EA	7	\$0	
	Partitions	1st- Men's (across from Auditorium)	2	EA	6	\$594	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Urinals	1st- Men's (across from Auditorium)	2	EA	6	\$672	
	Walls - Plaster/Drywall	1st- Men's (across from Auditorium)	975	SF	6	\$2,691	
	Walls - Tile Ceramic/ Porcelain	1st- Men's (across from Auditorium)	172	SF	6	\$389	Stone
	Water Closet	1st- Men's (across from Auditorium)	2	EA	6	\$672	
	Accessories	1st- Men's (by EngineerOffice)	112	SF	6	\$1,033	
	Ceiling - Plaster/Drywall	1st- Men's (by EngineerOffice)	112	SF	6	\$388	
	Doors - Wood Doors inclu hw	1st- Men's (by EngineerOffice)	1	EA	6	\$301	
	Floor Drain	1st- Men's (by EngineerOffice)	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st- Men's (by EngineerOffice)	112	SF	6	\$237	
	Lavatory	1st- Men's (by EngineerOffice)	1	EA	6	\$320	
	Lighting - Pendant/Surface	1st- Men's (by EngineerOffice)	1	EA	7	\$0	
	Partitions	1st- Men's (by EngineerOffice)	1	EA	6	\$297	
	Walls - Plaster/Drywall	1st- Men's (by EngineerOffice)	611	SF	6	\$1,686	
	Water Closet	1st- Men's (by EngineerOffice)	1	EA	6	\$336	
	Accessories	1st- Men's in Fire Panel Room	26	SF	6	\$240	paper towel holder falling off wall
	Ceiling - Plaster/Drywall	1st- Men's in Fire Panel Room	26	SF	6	\$90	
	Doors - Wood Doors inclu hw	1st- Men's in Fire Panel Room	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st- Men's in Fire Panel Room	26	SF	6	\$55	
	Lavatory	1st- Men's in Fire Panel Room	1	EA	6	\$320	
	Lighting - Pendant/Surface	1st- Men's in Fire Panel Room	1	EA	7	\$0	
	Lighting - Wall Mounted	1st- Men's in Fire Panel Room	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st- Men's in Fire Panel Room	240	SF	6	\$662	
	Water Closet	1st- Men's in Fire Panel Room	1	EA	6	\$336	
	Accessories	1st- Women's (across from Auditorium)	105	SF	6	\$968	
	Ceiling - Plaster/Drywall	1st- Women's (across from Auditorium)	275	SF	6	\$952	
	Doors - Wood Doors inclu hw	1st- Women's (across from Auditorium)	2	EA	6	\$602	
	Floor - Tile	1st- Women's (across from Auditorium)	101	SF	6	\$221	
	Floor - Tile	1st- Women's (across from Auditorium)	4	SF	5	\$23	damaged
	Floor - Tile Ceramic/ Porcelain	1st- Women's (across from Auditorium)	170	SF	6	\$360	
	Hand Dryer	1st- Women's (across from Auditorium)	1	EA	6	\$230	
	Lavatory	1st- Women's (across from Auditorium)	2	EA	6	\$639	
	Lighting - Pendant/Surface	1st- Women's (across from Auditorium)	3	EA	7	\$0	
	Partitions	1st- Women's (across from Auditorium)	2	EA	6	\$594	
	Walls - Plaster/Drywall	1st- Women's (across from Auditorium)	975	SF	6	\$2,691	
	Walls - Tile Ceramic/ Porcelain	1st- Women's (across from Auditorium)	172	SF	6	\$389	Stone
	Water Closet	1st- Women's (across from Auditorium)	2	EA	6	\$672	
	Accessories	1st- Women's (by EngineerOffice)	207	SF	6	\$1,909	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Ceiling - Plaster/Drywall	1st- Women's (by EngineerOffice)	207	SF	6	\$716	
	Doors - Wood Doors inclu hw	1st- Women's (by EngineerOffice)	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st- Women's (by EngineerOffice)	207	SF	6	\$438	
	Lavatory	1st- Women's (by EngineerOffice)	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st- Women's (by EngineerOffice)	2	EA	7	\$0	
	Partitions	1st- Women's (by EngineerOffice)	2	EA	6	\$594	
	Walls - Plaster/Drywall	1st- Women's (by EngineerOffice)	845	SF	6	\$2,332	
	Water Closet	1st- Women's (by EngineerOffice)	2	EA	6	\$672	
	Accessories	2nd- Boy's NE	223	SF	6	\$2,057	
	Ceiling - Plaster/Drywall	2nd- Boy's NE	223	SF	6	\$772	
	Floor Drain	2nd- Boy's NE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd- Boy's NE	223	SF	6	\$472	
	Hand Dryer	2nd- Boy's NE	1	EA	6	\$230	
	Lavatory	2nd- Boy's NE	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd- Boy's NE	4	EA	7	\$0	
	Partitions	2nd- Boy's NE	1	EA	5	\$751	door missing
	Urinals	2nd- Boy's NE	5	EA	6	\$1,680	
	Walls - Plaster/Drywall	2nd- Boy's NE	153	SF	6	\$422	
	Walls - Tile Ceramic/ Porcelain	2nd- Boy's NE	606	SF	6	\$1,369	
	Water Closet	2nd- Boy's NE	1	EA	6	\$336	
	Accessories	2nd- Boy's SE	223	SF	6	\$2,057	
	Ceiling - Plaster/Drywall	2nd- Boy's SE	223	SF	6	\$772	
	Floor Drain	2nd- Boy's SE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd- Boy's SE	223	SF	6	\$472	
	Hand Dryer	2nd- Boy's SE	1	EA	6	\$230	
	Lavatory	2nd- Boy's SE	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd- Boy's SE	4	EA	7	\$0	
	Partitions	2nd- Boy's SE	2	EA	6	\$594	
	Urinals	2nd- Boy's SE	5	EA	6	\$1,680	
	Walls - Plaster/Drywall	2nd- Boy's SE	153	SF	6	\$422	
	Walls - Tile Ceramic/ Porcelain	2nd- Boy's SE	606	SF	6	\$1,369	
	Water Closet	2nd- Boy's SE	1	EA	6	\$336	
	Water Closet	2nd- Boy's SE	1	EA	5	\$1,344	toilet out of order
	Accessories	2nd Floor - Girl's Locker Room Restroom	282	SF	6	\$2,601	
	Ceiling - Plaster/Drywall	2nd Floor - Girl's Locker Room Restroom	282	SF	6	\$976	
	Doors - Steel Doors incl hw	2nd Floor - Girl's Locker Room Restroom	1	EA	6	\$301	
	Floor Drain	2nd Floor - Girl's Locker Room Restroom	1	EA	6	\$1,059	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Floor - Tile	2nd Floor - Girl's Locker Room Restroom	282	SF	6	\$617	
	Hand Dryer	2nd Floor - Girl's Locker Room Restroom	2	EA	6	\$460	
	Lavatory	2nd Floor - Girl's Locker Room Restroom	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor - Girl's Locker Room Restroom	4	EA	6	\$496	
	Partitions	2nd Floor - Girl's Locker Room Restroom	4	EA	6	\$1,188	
	Walls - Structural Glazed Tile	2nd Floor - Girl's Locker Room Restroom	875	SF	6	\$2,753	
	Water Closet	2nd Floor - Girl's Locker Room Restroom	4	EA	6	\$1,344	
	Accessories	2nd Floor- Hair Drying Room in Locker Room	252	SF	6	\$2,324	
	Benches	2nd Floor- Hair Drying Room in Locker Room	15	LF	6	\$217	
	Ceiling - Plaster/Drywall	2nd Floor- Hair Drying Room in Locker Room	252	SF	6	\$872	
	Doors - Steel Doors incl hw	2nd Floor- Hair Drying Room in Locker Room	1	EA	6	\$301	
	Floor - Tile	2nd Floor- Hair Drying Room in Locker Room	252	SF	6	\$551	
	Hand Dryer	2nd Floor- Hair Drying Room in Locker Room	14	EA	6	\$3,221	
	Lighting - Pendent/Surface	2nd Floor- Hair Drying Room in Locker Room	2	EA	6	\$248	
	Walls - Plaster/Drywall	2nd Floor- Hair Drying Room in Locker Room	825	SF	6	\$2,277	
	Accessories	2nd Floor	123	SF	6	\$1,134	
	Accessories	2nd Floor	118	SF	6	\$1,088	
	Accessories	2nd Floor	340	SF	6	\$3,136	
	Ceiling - Plaster/Drywall	2nd Floor	340	SF	6	\$1,177	
	Ceiling - Plaster/Drywall	2nd Floor	123	SF	6	\$426	
	Ceiling - Plaster/Drywall	2nd Floor	118	SF	6	\$408	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor Drain	2nd Floor	4	EA	6	\$4,237	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor - Tile	2nd Floor	340	SF	6	\$744	
	Floor - Tile	2nd Floor	123	SF	6	\$269	
	Floor - Tile	2nd Floor	118	SF	6	\$258	
	Hand Dryer	2nd Floor	2	EA	6	\$460	
	Hand Dryer	2nd Floor	1	EA	6	\$230	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Hand Dryer	2nd Floor	1	EA	6	\$230	
	Lavatory	2nd Floor	2	EA	6	\$639	
	Lavatory	2nd Floor	3	EA	6	\$959	
	Lavatory	2nd Floor	2	EA	6	\$639	
	Lighting - Lay-in	2nd Floor	1	EA	6	\$119	
	Lighting - Lay-in	2nd Floor	1	EA	6	\$119	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	\$496	
	Partitions	2nd Floor	2	EA	6	\$594	
	Partitions	2nd Floor	1	EA	6	\$297	
	Partitions	2nd Floor	2	EA	6	\$594	
	Showers	2nd Floor	16	EA	6	\$4,983	
	Urinals	2nd Floor	3	EA	6	\$1,008	
	Urinals	2nd Floor	1	EA	6	\$336	
	Walls - Plaster/Drywall	2nd Floor	288	SF	6	\$795	
	Walls - Plaster/Drywall	2nd Floor	285	SF	6	\$787	
	Walls - Structural Glazed Tile	2nd Floor	958	SF	6	\$3,014	
	Walls - Structural Glazed Tile	2nd Floor	288	SF	6	\$906	
	Walls - Structural Glazed Tile	2nd Floor	285	SF	6	\$897	
	Water Closet	2nd Floor	2	EA	6	\$672	
	Water Closet	2nd Floor	2	EA	6	\$672	
	Water Closet	2nd Floor	1	EA	6	\$336	
	Accessories	2nd- Girl's NE	294	SF	6	\$2,712	
	Ceiling - Plaster/Drywall	2nd- Girl's NE	294	SF	6	\$1,017	
	Floor Drain	2nd- Girl's NE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd- Girl's NE	294	SF	6	\$622	
	Hand Dryer	2nd- Girl's NE	2	EA	6	\$460	
	Lavatory	2nd- Girl's NE	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd- Girl's NE	5	EA	7	\$0	
	Partitions	2nd- Girl's NE	6	EA	6	\$1,782	
	Walls - Plaster/Drywall	2nd- Girl's NE	200	SF	6	\$552	
	Walls - Tile Ceramic/ Porcelain	2nd- Girl's NE	586	SF	6	\$1,324	
	Water Closet	2nd- Girl's NE	7	EA	6	\$2,352	
	Accessories	2nd- Girl's SE	294	SF	6	\$2,712	
	Ceiling - Plaster/Drywall	2nd- Girl's SE	294	SF	6	\$1,017	
	Floor Drain	2nd- Girl's SE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd- Girl's SE	294	SF	6	\$622	
	Hand Dryer	2nd- Girl's SE	2	EA	6	\$460	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Lavatory	2nd- Girl's SE	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd- Girl's SE	7	EA	7	\$0	
	Partitions	2nd- Girl's SE	5	EA	6	\$1,485	
	Walls - Plaster/Drywall	2nd- Girl's SE	246	SF	6	\$679	
	Walls - Tile Ceramic/ Porcelain	2nd- Girl's SE	607	SF	6	\$1,371	
	Water Closet	2nd- Girl's SE	6	EA	6	\$2,016	
	Accessories	2nd- Inside Rm 229	60	SF	6	\$553	
	Ceiling - Plaster/Drywall	2nd- Inside Rm 229	60	SF	6	\$208	
	Doors - Wood Doors inclu hw	2nd- Inside Rm 229	1	EA	6	\$301	
	Floor Drain	2nd- Inside Rm 229	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd- Inside Rm 229	60	SF	6	\$127	
	Lavatory	2nd- Inside Rm 229	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd- Inside Rm 229	1	EA	7	\$0	
	Partitions	2nd- Inside Rm 229	1	EA	6	\$297	
	Walls - Plaster/Drywall	2nd- Inside Rm 229	255	SF	6	\$704	
	Walls - Tile Ceramic/ Porcelain	2nd- Inside Rm 229	96	SF	6	\$217	
	Water Closet	2nd- Inside Rm 229	1	EA	6	\$336	
	Accessories	3rd- Boy's Gym Toilet	107	SF	6	\$987	
	Ceiling - Plaster/Drywall	3rd- Boy's Gym Toilet	107	SF	6	\$370	
	Doors - Wood Doors inclu hw	3rd- Boy's Gym Toilet	1	EA	6	\$301	
	Floor Drain	3rd- Boy's Gym Toilet	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd- Boy's Gym Toilet	107	SF	6	\$226	
	Lavatory	3rd- Boy's Gym Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd- Boy's Gym Toilet	1	EA	7	\$0	
	Partitions	3rd- Boy's Gym Toilet	1	EA	5	\$751	door is missing
	Urinals	3rd- Boy's Gym Toilet	2	EA	6	\$672	
	Walls - Plaster/Drywall	3rd- Boy's Gym Toilet	295	SF	6	\$814	
	Walls - Tile Ceramic/ Porcelain	3rd- Boy's Gym Toilet	120	SF	6	\$271	stone
	Water Closet	3rd- Boy's Gym Toilet	1	EA	6	\$336	
	Accessories	3rd- Boy's NE	223	SF	6	\$2,057	
	Ceiling - Plaster/Drywall	3rd- Boy's NE	223	SF	6	\$772	
	Floor Drain	3rd- Boy's NE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd- Boy's NE	223	SF	6	\$472	
	Hand Dryer	3rd- Boy's NE	1	EA	6	\$230	
	Lavatory	3rd- Boy's NE	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd- Boy's NE	4	EA	7	\$0	
	Partitions	3rd- Boy's NE	1	EA	5	\$751	door missing

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Urinals	3rd- Boy's NE	5	EA	6	\$1,680	
	Walls - Plaster/Drywall	3rd- Boy's NE	153	SF	6	\$422	
	Walls - Tile Ceramic/ Porcelain	3rd- Boy's NE	606	SF	6	\$1,369	
	Water Closet	3rd- Boy's NE	1	EA	6	\$336	
	Accessories	3rd- Boy's SE	223	SF	6	\$2,057	
	Ceiling - Plaster/Drywall	3rd- Boy's SE	223	SF	6	\$772	
	Floor Drain	3rd- Boy's SE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd- Boy's SE	223	SF	6	\$472	
	Hand Dryer	3rd- Boy's SE	1	EA	6	\$230	
	Lavatory	3rd- Boy's SE	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd- Boy's SE	4	EA	7	\$0	
	Partitions	3rd- Boy's SE	2	EA	6	\$594	
	Urinals	3rd- Boy's SE	5	EA	6	\$1,680	
	Walls - Plaster/Drywall	3rd- Boy's SE	153	SF	6	\$422	
	Walls - Tile Ceramic/ Porcelain	3rd- Boy's SE	606	SF	6	\$1,369	
	Water Closet	3rd- Boy's SE	2	EA	6	\$672	
	Accessories	3rd- Girl's NE	294	SF	6	\$2,712	
	Ceiling - Plaster/Drywall	3rd- Girl's NE	294	SF	6	\$1,017	
	Floor Drain	3rd- Girl's NE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd- Girl's NE	294	SF	6	\$622	
	Hand Dryer	3rd- Girl's NE	2	EA	6	\$460	
	Lavatory	3rd- Girl's NE	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd- Girl's NE	5	EA	7	\$0	
	Partitions	3rd- Girl's NE	6	EA	6	\$1,782	
	Walls - Plaster/Drywall	3rd- Girl's NE	200	SF	6	\$552	
	Walls - Tile Ceramic/ Porcelain	3rd- Girl's NE	586	SF	6	\$1,324	
	Water Closet	3rd- Girl's NE	7	EA	6	\$2,352	
	Accessories	3rd- Girl's SE	294	SF	6	\$2,712	
	Ceiling - Plaster/Drywall	3rd- Girl's SE	294	SF	6	\$1,017	
	Floor Drain	3rd- Girl's SE	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd- Girl's SE	294	SF	6	\$622	
	Hand Dryer	3rd- Girl's SE	2	EA	6	\$460	
	Lavatory	3rd- Girl's SE	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd- Girl's SE	7	EA	7	\$0	
	Partitions	3rd- Girl's SE	5	EA	6	\$1,485	
	Walls - Plaster/Drywall	3rd- Girl's SE	246	SF	6	\$679	
	Walls - Tile Ceramic/ Porcelain	3rd- Girl's SE	607	SF	6	\$1,371	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Water Closet	3rd- Girl's SE	6	EA	6	\$2,016	
	Accessories	3rd- Men's	127	SF	6	\$1,171	
	Ceiling - Plaster/Drywall	3rd- Men's	126	SF	6	\$436	
	Ceiling - Plaster/Drywall	3rd- Men's	1	SF	6	\$5	peeling
	Doors - Transom Window	3rd- Men's	1	SF	6	\$17	
	Doors - Wood Doors inclu hw	3rd- Men's	1	EA	6	\$301	
	Floor Drain	3rd- Men's	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd- Men's	127	SF	6	\$269	
	Lavatory	3rd- Men's	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd- Men's	1	EA	7	\$0	
	Lighting - Wall Mounted	3rd- Men's	1	EA	7	\$0	
	Partitions	3rd- Men's	2	EA	6	\$594	
	Urinals	3rd- Men's	1	EA	6	\$336	
	Walls - Plaster/Drywall	3rd- Men's	494	SF	6	\$1,363	
	Walls - Tile Ceramic/ Porcelain	3rd- Men's	18	SF	6	\$41	
	Water Closet	3rd- Men's	2	EA	6	\$672	
	Accessories	3rd- Women's	196	SF	6	\$1,808	
	Ceiling - Plaster/Drywall	3rd- Women's	196	SF	6	\$678	
	Doors - Transom Window	3rd- Women's	1	SF	6	\$17	
	Doors - Wood Doors inclu hw	3rd- Women's	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	3rd- Women's	196	SF	6	\$415	
	Lavatory	3rd- Women's	1	EA	6	\$320	
	Lighting - Pendent/Surface	3rd- Women's	2	EA	7	\$0	
	Lighting - Wall Mounted	3rd- Women's	1	EA	7	\$0	
	Partitions	3rd- Women's	2	EA	6	\$594	
	Walls - Plaster/Drywall	3rd- Women's	557	SF	6	\$1,537	
	Walls - Vinyl Coated Gypsum Panel	3rd- Women's	60	SF	6	\$166	Stone
	Water Closet	3rd- Women's	2	EA	6	\$672	

Rooms (Other Than Classrooms) Subtotal:

\$3,171,126

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	11,547	SF	6	\$34,676	
	Ceiling - Plaster/Drywall	1st Floor	7,444	SF	6	\$46,093	

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	\$174	
	Doors - Transom Window	1st Floor	156	EA	6	\$2,641	
	Doors - Wood Doors include hw	1st Floor	30	EA	6	\$9,030	
	Drinking Fountains - Single Fountain	1st Floor	15	EA	6	\$4,136	
	Floor - Terrazzo	1st Floor	5,114	SF	6	\$42,927	
	Floor - Tile/Sheet	1st Floor	30	SF	5	\$173	
	Floor - Tile/Sheet	1st Floor	14,033	SF	6	\$7,626	
	Lighting - Lay-in	1st Floor	80	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	111	EA	7	\$0	
	Student Lockers - One Tier	1st Floor	645	EA	6	\$59,879	
	Walls - Plaster/Drywall	1st Floor	14,740	SF	6	\$65,342	
	Walls - Plaster/Drywall	1st Floor	5	SF	5	\$50	
	Walls - Structural Glazed Tile	1st Floor	15,313	SF	6	\$48,175	
	Walls - Tile Ceramic/ Porcelain	1st Floor	1,332	SF	6	\$4,190	
	Ceiling - Lay-in	2nd Floor	10,624	SF	6	\$31,904	
	Ceiling - Lay-in	2nd Floor	30	SF	5	\$268	
	Ceiling - Plaster/Drywall	2nd Floor	3,012	SF	6	\$18,650	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	64	EA	6	\$1,084	
	Doors - Wood Doors include hw	2nd Floor	8	EA	6	\$2,408	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	5	\$1,180	
	Drinking Fountains - Single Fountain	2nd Floor	13	EA	6	\$3,585	
	Floor - Terrazzo	2nd Floor	1,500	SF	6	\$12,591	
	Floor - Tile/Sheet	2nd Floor	20	SF	5	\$115	
	Floor - Tile/Sheet	2nd Floor	14,160	SF	6	\$7,695	
	Lighting - Lay-in	2nd Floor	80	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	907	EA	6	\$84,202	
	Walls - Plaster/Drywall	2nd Floor	14,697	SF	6	\$65,152	
	Walls - Structural Glazed Tile	2nd Floor	14,959	SF	6	\$47,061	
	Ceiling - Lay-in	3rd Floor	11,231	SF	6	\$33,727	
	Ceiling - Lay-in	3rd Floor	10	SF	5	\$89	
	Ceiling - Plaster/Drywall	3rd Floor	5,390	SF	6	\$33,374	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	\$87	
	Doors - Transom Window	3rd Floor	64	EA	6	\$1,084	
	Doors - Wood Doors include hw	3rd Floor	12	EA	6	\$3,612	
	Drinking Fountains - Single Fountain	3rd Floor	11	EA	6	\$3,033	

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	5	\$1,180	
	Floor - Terrazzo	3rd Floor	2,161	SF	6	\$18,140	
	Floor - Tile/Sheet	3rd Floor	14,465	SF	6	\$7,860	
	Floor - Tile/Sheet	3rd Floor	10	SF	5	\$58	
	Lighting - Lay-in	3rd Floor	25	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	174	EA	7	\$0	
	Student Lockers - One Tier	3rd Floor	835	EA	6	\$77,518	
	Student Lockers - Two Tiers	3rd Floor	80	EA	6	\$3,713	
	Walls - Plaster/Drywall	3rd Floor	13,259	SF	6	\$58,777	
	Walls - Structural Glazed Tile	3rd Floor	14,589	SF	6	\$45,897	
	Ceiling - Lay-in	4th Floor	60	SF	6	\$180	Only outside of Rm 400 & 401
	Floor - Tile/Sheet	4th Floor	60	SF	6	\$33	
	Lighting - Lay-in	4th Floor	2	EA	6	\$238	
	Walls - Plaster/Drywall	4th Floor	500	SF	6	\$2,217	
Safety							
	Camera Viewing Station	1st Floor	5	EA	6	\$3,413	IDF/MDF/Asst Principal/Security Desk/Principal
	Metal Dedector	1st Floor	3	EA	6	\$2,642	2 at Main entrance & 1 at entrance by Rm127
	Security Cameras	1st Floor	8	EA	5	\$5,502	Interior, Not working
	Security Cameras	1st Floor	128	EA	6	\$24,837	13 exterior & 115 interior
	Security Cameras	1st Floor	14	EA	6	\$2,717	Exterior
	Security Cameras	1st Floor	4	EA	5	\$2,751	Exterior, Not working
Stairs							
	Ceiling - Plaster/Drywall	Interior North of Balcony	433	SF	6	\$3,170	
	Floor - Terrazzo	Interior North of Balcony	162	SF	6	\$1,360	
	Handrails	Interior North of Balcony	113	LF	6	\$979	
	Lighting - Pendent/Surface	Interior North of Balcony	4	EA	7	\$0	
	Stairs - Terrazzo	Interior North of Balcony	55	LF	6	\$510	
	Walls - Plaster/Drywall	Interior North of Balcony	659	SF	6	\$1,819	
	Walls - Structural Glazed Tile	Interior North of Balcony	659	SF	6	\$2,073	
	Ceiling - Plaster/Drywall	Interior South of Balcony	433	SF	6	\$3,170	
	Floor - Terrazzo	Interior South of Balcony	271	SF	6	\$2,275	
	Handrails	Interior South of Balcony	113	LF	6	\$979	
	Lighting - Pendent/Surface	Interior South of Balcony	4	EA	7	\$0	
	Stairs - Terrazzo	Interior South of Balcony	55	LF	6	\$510	
	Walls - Plaster/Drywall	Interior South of Balcony	659	SF	6	\$1,819	
	Walls - Structural Glazed Tile	Interior South of Balcony	659	SF	6	\$2,073	

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Ceiling - Plaster/Drywall	NE of Boys Gym	211	SF	6	\$1,545	
	Floor - Terrazzo	NE of Boys Gym	191	SF	6	\$1,603	
	Handrails	NE of Boys Gym	174	LF	6	\$1,508	
	Lighting - Pendent/Surface	NE of Boys Gym	2	EA	7	\$0	
	Lighting - Wall Mounted	NE of Boys Gym	4	EA	7	\$0	
	Stairs - Terrazzo	NE of Boys Gym	90	LF	6	\$835	
	Walls - Plaster/Drywall	NE of Boys Gym	595	SF	6	\$1,642	
	Walls - Structural Glazed Tile	NE of Boys Gym	1,190	SF	6	\$3,744	
	Ceiling - Plaster/Drywall	North of Main Vestibule	529	SF	6	\$3,873	
	Floor - Terrazzo	North of Main Vestibule	366	SF	6	\$3,072	
	Handrails	North of Main Vestibule	180	LF	6	\$1,560	
	Lighting - Pendent/Surface	North of Main Vestibule	6	EA	7	\$0	
	Stairs - Terrazzo	North of Main Vestibule	80	LF	6	\$742	
	Walls - Plaster/Drywall	North of Main Vestibule	1,149	SF	6	\$3,171	
	Walls - Structural Glazed Tile	North of Main Vestibule	1,149	SF	6	\$3,615	
	Ceiling - Plaster/Drywall	North	433	SF	6	\$3,170	
	Floor - Terrazzo	North	271	SF	6	\$2,275	
	Handrails	North	113	LF	6	\$979	
	Lighting - Pendent/Surface	North	4	EA	7	\$0	
	Stairs - Terrazzo	North	55	LF	6	\$510	
	Walls - Plaster/Drywall	North	659	SF	6	\$1,819	
	Walls - Structural Glazed Tile	North	659	SF	6	\$2,073	
	Ceiling - Plaster/Drywall	NW of Boys Gym	92	SF	6	\$674	
	Floor - Tile	NW of Boys Gym	92	SF	6	\$50	
	Handrails	NW of Boys Gym	68	LF	6	\$589	
	Lighting - Pendent/Surface	NW of Boys Gym	2	EA	7	\$0	
	Stairs - Terrazzo	NW of Boys Gym	34	LF	6	\$316	
	Walls - Plaster/Drywall	NW of Boys Gym	320	SF	6	\$883	
	Walls - Structural Glazed Tile	NW of Boys Gym	1,020	SF	6	\$3,209	
	Ceiling - Plaster/Drywall	SE of Girls Gym	211	SF	6	\$1,545	
	Floor - Terrazzo	SE of Girls Gym	191	SF	6	\$1,603	
	Handrails	SE of Girls Gym	174	LF	6	\$1,508	
	Lighting - Pendent/Surface	SE of Girls Gym	2	EA	7	\$0	
	Lighting - Wall Mounted	SE of Girls Gym	4	EA	7	\$0	
	Stairs - Terrazzo	SE of Girls Gym	90	LF	6	\$835	
	Walls - Plaster/Drywall	SE of Girls Gym	595	SF	6	\$1,642	
	Walls - Structural Glazed Tile	SE of Girls Gym	1,190	SF	6	\$3,744	

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Ceiling - Plaster/Drywall	South	433	SF	6	\$3,170	
	Floor - Terrazzo	South	271	SF	6	\$2,275	
	Handrails	South	113	LF	6	\$979	
	Lighting - Pendent/Surface	South	4	EA	7	\$0	
	Ceiling - Plaster/Drywall	South of Main Vestibule	529	SF	6	\$3,873	
	Floor - Terrazzo	South of Main Vestibule	366	SF	6	\$3,072	
	Handrails	South of Main Vestibule	180	LF	6	\$1,560	
	Lighting - Pendent/Surface	South of Main Vestibule	6	EA	7	\$0	
	Stairs - Terrazzo	South of Main Vestibule	80	LF	6	\$742	
	Walls - Plaster/Drywall	South of Main Vestibule	1,149	SF	6	\$3,171	
	Walls - Structural Glazed Tile	South of Main Vestibule	1,149	SF	6	\$3,615	
	Stairs - Terrazzo	South	55	LF	6	\$510	
	Walls - Plaster/Drywall	South	659	SF	6	\$1,819	
	Walls - Structural Glazed Tile	South	659	SF	6	\$2,073	
	Ceiling - Plaster/Drywall	SW of Girls Gym	56	SF	6	\$410	
	Floor - Terrazzo	SW of Girls Gym	56	SF	6	\$470	
	Handrails	SW of Girls Gym	18	LF	6	\$156	
	Lighting - Pendent/Surface	SW of Girls Gym	1	EA	7	\$0	
	Stairs - Terrazzo	SW of Girls Gym	14	LF	6	\$130	
	Walls - Plaster/Drywall	SW of Girls Gym	240	SF	6	\$662	
	Walls - Structural Glazed Tile	SW of Girls Gym	680	SF	6	\$2,139	

Vertical Conveyance

	Elevator - Freight Elevator		1	EA	6	\$19,238	
--	-----------------------------	--	---	----	---	----------	--

Building Interior Subtotal:

\$1,059,122

Total Building Cost

\$13,752,211

Building: 6-Classroom Modular

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#13 - N	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#13 - N	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#14 - N	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#14 - N	2	EA	6	\$961	

Building: 6-Classroom Modular

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#15 - S	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#15 - S	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#16 - S	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#16 - S	2	EA	6	\$961	
	Exterior Stairs - Concrete	#15 - S	15	LF	6	\$1,227	
	Exterior Stairs - Concrete	#15 - S	15	LF	6	\$1,227	
	Exterior Stairs - Concrete	#16 - S	15	LF	6	\$1,227	
	Exterior Stairs - Concrete	#16 - S	15	LF	6	\$1,227	
Foundation							
	Foundation - Masonry	Entire Building	340	LF	7	\$0	
	Foundation - Masonry	Entire Building	340	LF	7	\$0	
	Foundation - Masonry	Entire Building	340	LF	7	\$0	
	Foundation - Masonry	Entire Building	340	LF	7	\$0	
	Superstructure - Steel	Entire Building	7,060	SF	7	\$0	
	Superstructure - Steel	Entire Building	7,060	SF	7	\$0	
	Superstructure - Steel	Entire Building	7,060	SF	7	\$0	
	Superstructure - Steel	Entire Building	7,060	SF	7	\$0	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	4	\$10,301	Replace fixtures-not working
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	4	\$10,301	Replace fixtures-not working
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	4	\$10,301	Replace fixtures-not working
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	4	\$10,301	Replace fixtures-not working
Roof System							
	Coping - Metal	Main Roof	340	LF	6	\$10,920	
	Coping - Metal	Main Roof	340	LF	6	\$10,920	
	Coping - Metal	Main Roof	340	LF	6	\$10,920	
	Coping - Metal	Main Roof	340	LF	6	\$10,920	
	Downspouts - Exterior Downspouts	Main Roof	52	LF	6	\$1,728	
	Downspouts - Exterior Downspouts	Main Roof	52	LF	6	\$1,728	
	Downspouts - Exterior Downspouts	Main Roof	52	LF	6	\$1,728	
	Downspouts - Exterior Downspouts	Main Roof	52	LF	6	\$1,728	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	7,060	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	7,060	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	7,060	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	7,060	SF	7	\$0	
	Roof - PVC Membrane	Main Roof	7,060	SF	6	\$58,354	Some water ponding

Building: 6-Classroom Modular

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof System							
	Roof - PVC Membrane	Main Roof	7,060	SF	6	\$58,354	Some water ponding
	Roof - PVC Membrane	Main Roof	7,060	SF	6	\$58,354	Some water ponding
	Roof - PVC Membrane	Main Roof	7,060	SF	6	\$58,354	Some water ponding
Walls							
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	4,420	SF	6	\$25,093	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	4,420	SF	6	\$25,093	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	4,420	SF	6	\$25,093	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	4,420	SF	6	\$25,093	
Windows							
	Guard - Guards perforated	Entire Building	320	SF	6	\$4,086	Rusting
	Guard - Guards perforated	Entire Building	320	SF	6	\$4,086	Rusting
	Guard - Guards perforated	Entire Building	320	SF	6	\$4,086	Rusting
	Guard - Guards perforated	Entire Building	320	SF	6	\$4,086	Rusting
	Windows - Sash Aluminum Double-pane	Entire Building	320	SF	6	\$2,389	
	Windows - Sash Aluminum Double-pane	Entire Building	320	SF	6	\$2,389	
	Windows - Sash Aluminum	Entire Building	320	SF	6	\$2,389	
	Windows - Sash Aluminum	Entire Building	320	SF	6	\$2,389	

Building Exterior Subtotal:

\$464,077

Building: 6-Classroom Modular

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System							
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	6	\$608	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	6	\$608	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	6	\$608	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	6	\$608	
	Exit Signs - Corridors and Stairs	1st Floor	2	EA	7	\$0	
	Exit Signs - Corridors and Stairs	1st Floor	2	EA	7	\$0	
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	7	\$0	
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	7	\$0	
Main Service							
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	7	\$0	
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	7	\$0	

Building: 6-Classroom Modular

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Main Service							
	PA System	Entire Building	7,060	SF	6	\$2,322	Location: Main Office (Serves all three buildings)
	PA System	Entire Building	7,060	SF	6	\$2,322	Location: Main Office (Serves all three buildings)
	PA System	Entire Building	7,060	SF	6	\$2,322	Location: Main Office (Serves all three buildings)
	PA System	Entire Building	7,060	SF	6	\$2,322	Location: Main Office (Serves all three buildings)
Power Distribution							
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 604
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 605
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 605
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: IDF Room 602 (Storage Closet)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: IDF Room 602 (Storage Closet)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 601
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 601
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 603
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 603
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 501
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 501
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 502
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 604
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 504
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: MDF Room 502, Storage Closet
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: MDF Room 502, Storage Closet
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 506
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 506
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 505
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 502
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 504
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 602
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 503
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 503
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 606
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 606
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 602
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	\$0	Location: Classroom 505

Electrical System Subtotal:

\$11,718

Building: 6-Classroom Modular

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm							
	Fire Alarm Panel	1st Floor	1	EA	6	\$6,406	Services & Links all three buildings together
	Fire Alarm Panel	1st Floor	1	EA	6	\$6,406	Services & Links all three buildings together
	Fire Alarm Panel	1st Floor	1	EA	6	\$6,406	Services & Links all three buildings together
	Fire Alarm Panel	1st Floor	1	EA	6	\$6,406	Services & Links all three buildings together
	Fire Alarm Strobe Lights	1st Floor / Entire Building	7,060	SF	6	\$2,524	
	Fire Alarm Strobe Lights	1st Floor / Entire Building	7,060	SF	6	\$2,524	
	Fire Alarm Strobe Lights	1st Floor / Entire Building	7,060	SF	6	\$2,524	
	Fire Alarm Strobe Lights	1st Floor / Entire Building	7,060	SF	6	\$2,524	
	Fire Alarm_System	1st Floor / Entire Building	7,060	SF	6	\$3,433	
	Fire Alarm_System	1st Floor / Entire Building	7,060	SF	6	\$3,433	
	Fire Alarm_System	1st Floor / Entire Building	7,060	SF	6	\$3,433	
	Fire Alarm_System	1st Floor / Entire Building	7,060	SF	6	\$3,433	

Sprinkler System

	Sprinkler Heads	Entire Building	7,060	SF	7	\$0	
	Sprinkler Heads	Entire Building	7,060	SF	7	\$0	
	Sprinkler Heads	Entire Building	7,060	SF	7	\$0	
	Sprinkler Heads	Entire Building	7,060	SF	7	\$0	
	Sprinkler Piping	Entire Building	7,060	SF	6	\$1,312	
	Sprinkler Piping	Entire Building	7,060	SF	6	\$1,312	
	Sprinkler Piping	Entire Building	7,060	SF	6	\$1,312	
	Sprinkler Piping	Entire Building	7,060	SF	6	\$1,312	
	Wet Sprinkler System	Entire Building	7,060	SF	6	\$1,817	
	Wet Sprinkler System	Entire Building	7,060	SF	6	\$1,817	
	Wet Sprinkler System	Entire Building	7,060	SF	6	\$1,817	
	Wet Sprinkler System	Entire Building	7,060	SF	6	\$1,817	

Safty System Subtotal:

\$61,968

Building: 6-Classroom Modular

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Temperature Control							
	Electric Thermostat	Entire Building	6	EA	6	\$0	
	Electric Thermostat	Entire Building	6	EA	6	\$0	
	Electric Thermostat	Entire Building	6	EA	6	\$0	
	Electric Thermostat	Entire Building	6	EA	6	\$0	

Building: 6-Classroom Modular

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Unit Ventilation							
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior walls	6	EA	6	\$0	One/Classroom
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior walls	6	EA	6	\$0	One/Classroom
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior walls	6	EA	6	\$0	One/Classroom
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior walls	6	EA	6	\$0	One/Classroom
Ventilation							
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	7	EA	6	\$4,147	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	7	EA	6	\$4,147	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	6	\$1,185	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	6	\$1,185	

Mechanical System Subtotal:

\$10,663

Building: 6-Classroom Modular

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Water							
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Location: Storage Room
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Location: Storage Room
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Location: Storage Room
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Location: Storage Room
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	7,060	SF	6	\$1,413	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	7,060	SF	6	\$1,413	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	7,060	SF	6	\$1,413	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	7,060	SF	6	\$1,413	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	7,060	SF	6	\$1,716	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	7,060	SF	6	\$1,716	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	7,060	SF	6	\$1,716	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	7,060	SF	6	\$1,716	
	Domestic Piping-Cold Water Risers	Entire Building	7,060	SF	6	\$1,312	
	Domestic Piping-Cold Water Risers	Entire Building	7,060	SF	6	\$1,312	
	Domestic Piping-Cold Water Risers	Entire Building	7,060	SF	6	\$1,312	
	Domestic Piping-Cold Water Risers	Entire Building	7,060	SF	6	\$1,312	

Building: 6-Classroom Modular

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	7,060	SF	6	\$1,111	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	7,060	SF	6	\$1,111	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	7,060	SF	6	\$1,111	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	7,060	SF	6	\$1,111	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	7,060	SF	6	\$1,312	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	7,060	SF	6	\$1,312	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	7,060	SF	6	\$1,312	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	7,060	SF	6	\$1,312	
	Domestic Piping-Hot Water Return Lines	Entire Building	7,060	SF	6	\$1,010	
	Domestic Piping-Hot Water Return Lines	Entire Building	7,060	SF	6	\$1,010	
	Domestic Piping-Hot Water Return Lines	Entire Building	7,060	SF	6	\$1,010	
	Domestic Piping-Hot Water Return Lines	Entire Building	7,060	SF	6	\$1,010	
	Domestic Piping-Hot Water Return Risers	Entire Building	7,060	SF	6	\$1,010	
	Domestic Piping-Hot Water Return Risers	Entire Building	7,060	SF	6	\$1,010	
	Domestic Piping-Hot Water Return Risers	Entire Building	7,060	SF	6	\$1,010	
	Domestic Piping-Hot Water Return Risers	Entire Building	7,060	SF	6	\$1,010	
	Sanitary Piping	Entire Building	7,060	SF	6	\$6,461	
	Sanitary Piping	Entire Building	7,060	SF	6	\$6,461	
	Sanitary Piping	Entire Building	7,060	SF	6	\$6,461	
	Sanitary Piping	Entire Building	7,060	SF	6	\$6,461	
	Storm Piping	Entire Building	7,060	SF	6	\$6,158	
	Storm Piping	Entire Building	7,060	SF	6	\$6,158	
	Storm Piping	Entire Building	7,060	SF	6	\$6,158	
	Storm Piping	Entire Building	7,060	SF	6	\$6,158	
	Vent Piping	Entire Building	7,060	SF	6	\$4,745	
	Vent Piping	Entire Building	7,060	SF	6	\$4,745	
	Vent Piping	Entire Building	7,060	SF	6	\$4,745	
	Vent Piping	Entire Building	7,060	SF	6	\$4,745	

Plumbing System Subtotal:

\$107,725

Building: 6-Classroom Modular

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #501 (Office)							
	Casework	1st Floor	22	LF	6	\$556	
	Casework	1st Floor	22	LF	6	\$556	

Building: 6-Classroom Modular

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #501 (Office)							
	Ceiling - Lay-in	1st Floor	816	SF	6	\$2,450	
	Ceiling - Lay-in	1st Floor	816	SF	6	\$2,450	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	816	SF	6	\$1,785	
	Floor - Tile	1st Floor	816	SF	6	\$1,785	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Storage/ Closet	1st Floor	71	SF	6	\$515	
	Storage/ Closet	1st Floor	71	SF	6	\$515	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	845	SF	6	\$2,332	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	845	SF	6	\$2,332	
Classroom #502 (Computer Lab)							
	Ceiling - Lay-in	1st Floor	812	SF	6	\$2,438	
	Ceiling - Lay-in	1st Floor	812	SF	6	\$2,438	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	812	SF	6	\$1,777	
	Floor - Tile	1st Floor	812	SF	6	\$1,777	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	79	SF	6	\$573	IDP
	Storage/ Closet	1st Floor	79	SF	6	\$573	IDP
	Walls - Vinyl Coated Gypsum Panel	1st Floor	842	SF	6	\$2,324	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	842	SF	6	\$2,324	
Classroom #503 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	812	SF	6	\$2,438	
	Ceiling - Lay-in	1st Floor	812	SF	6	\$2,438	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	812	SF	6	\$1,777	
	Floor - Tile	1st Floor	812	SF	6	\$1,777	

Building: 6-Classroom Modular

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #503 (Regular Classroom)							
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Storage/ Closet	1st Floor	73	SF	6	\$529	1 cracked ceiling tile
	Storage/ Closet	1st Floor	73	SF	6	\$529	1 cracked ceiling tile
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	839	SF	6	\$2,316	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	839	SF	6	\$2,316	
Classroom #504 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	stains
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	stains
	Ceiling - Lay-in	1st Floor	807	SF	6	\$2,423	
	Ceiling - Lay-in	1st Floor	807	SF	6	\$2,423	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	812	SF	6	\$1,777	
	Floor - Tile	1st Floor	812	SF	6	\$1,777	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Storage/ Closet	1st Floor	81	SF	6	\$587	
	Storage/ Closet	1st Floor	81	SF	6	\$587	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	839	SF	6	\$2,316	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	839	SF	6	\$2,316	
Classroom #505 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	819	SF	6	\$2,459	
	Ceiling - Lay-in	1st Floor	819	SF	6	\$2,459	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	814	SF	6	\$1,781	
	Floor - Tile	1st Floor	814	SF	6	\$1,781	

Building: 6-Classroom Modular

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #505 (Regular Classroom)							
	Floor - Tile	1st Floor	5	SF	5	\$29	damaged - cracked / holes
	Floor - Tile	1st Floor	5	SF	5	\$29	damaged - cracked / holes
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	5	SF	5	\$37	corner damaged / unfinished
	Walls - Vinyl Coated Gypsum Panel	1st Floor	5	SF	5	\$37	corner damaged / unfinished
	Walls - Vinyl Coated Gypsum Panel	1st Floor	839	SF	6	\$2,316	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	839	SF	6	\$2,316	
Classroom #506 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	819	SF	6	\$2,459	
	Ceiling - Lay-in	1st Floor	819	SF	6	\$2,459	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	\$1,174	doesn't close properly
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	\$1,174	doesn't close properly
	Floor - Tile	1st Floor	819	SF	6	\$1,792	
	Floor - Tile	1st Floor	819	SF	6	\$1,792	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	843	SF	6	\$2,327	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	843	SF	6	\$2,327	
Classroom #601 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	stains
	Ceiling - Lay-in	1st Floor	812	SF	6	\$2,438	
	Ceiling - Lay-in	1st Floor	812	SF	6	\$2,438	
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	stains
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	

Building: 6-Classroom Modular

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #601 (Regular Classroom)							
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Storage/ Closet	1st Floor	70	SF	6	\$508	
	Storage/ Closet	1st Floor	70	SF	6	\$508	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	839	SF	6	\$2,316	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	839	SF	6	\$2,316	
Classroom #602 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	817	SF	6	\$2,453	
	Ceiling - Lay-in	1st Floor	817	SF	6	\$2,453	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	8	LF	7	\$0	
	Marker Board	1st Floor	8	LF	7	\$0	
	Storage/ Closet	1st Floor	82	SF	6	\$595	IDP - Stain at ceiling
	Storage/ Closet	1st Floor	82	SF	6	\$595	IDP - Stain at ceiling
	Walls - Vinyl Coated Gypsum Panel	1st Floor	838	SF	6	\$2,313	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	838	SF	6	\$2,313	
Classroom #603 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	811	SF	6	\$2,435	
	Ceiling - Lay-in	1st Floor	811	SF	6	\$2,435	
	Ceiling - Lay-in	1st Floor	6	SF	5	\$48	stained / cracked tiles
	Ceiling - Lay-in	1st Floor	6	SF	5	\$48	stained / cracked tiles
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	

Building: 6-Classroom Modular

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #603 (Regular Classroom)							
	Storage/ Closet	1st Floor	70	SF	6	\$508	
	Storage/ Closet	1st Floor	70	SF	6	\$508	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	844	SF	6	\$2,329	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	844	SF	6	\$2,329	
Classroom #604 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	807	SF	6	\$2,423	
	Ceiling - Lay-in	1st Floor	10	SF	5	\$80	stained
	Ceiling - Lay-in	1st Floor	10	SF	5	\$80	stained
	Ceiling - Lay-in	1st Floor	807	SF	6	\$2,423	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Storage/ Closet	1st Floor	83	SF	6	\$602	ceiling tiles missing / stained
	Storage/ Closet	1st Floor	83	SF	6	\$602	ceiling tiles missing / stained
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	840	SF	6	\$2,318	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	840	SF	6	\$2,318	
Classroom #605 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	817	SF	6	\$2,453	
	Ceiling - Lay-in	1st Floor	817	SF	6	\$2,453	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	

Building: 6-Classroom Modular

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #605 (Regular Classroom)							
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Student Lockers - Two Tiers	1st Floor	30	EA	6	\$1,393	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	841	SF	6	\$2,321	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	841	SF	6	\$2,321	
Classroom #606 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	812	SF	6	\$2,438	
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	stains
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	stains
	Ceiling - Lay-in	1st Floor	812	SF	6	\$2,438	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Floor - Tile	1st Floor	817	SF	6	\$1,788	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Lighting - Lay-in	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Student Lockers - Two Tiers	1st Floor	10	EA	6	\$464	
	Student Lockers - Two Tiers	1st Floor	10	EA	6	\$464	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	845	SF	6	\$2,332	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	845	SF	6	\$2,332	
Classrooms Subtotal:						\$197,129	

Building: 6-Classroom Modular

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechanical/ Service Rooms							
	Mechanical/ Service Rooms	1st Floor	104	SF	6	\$745	
	Mechanical/ Service Rooms	1st Floor	104	SF	6	\$745	
	Mechanical/ Service Rooms	1st Floor	110	SF	6	\$788	
	Mechanical/ Service Rooms	1st Floor	110	SF	6	\$788	
Restroom							
	Accessories	1st - Mens	154	SF	6	\$1,420	
	Accessories	1st - Mens	154	SF	6	\$1,420	
	Accessories	1st - Mens	154	SF	6	\$1,420	

Building: 6-Classroom Modular

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Accessories	1st - Mens	154	SF	6	\$1,420	
	Ceiling - Plaster/Drywall	1st - Mens	149	SF	6	\$516	Vinyl Coated
	Ceiling - Plaster/Drywall	1st - Mens	154	SF	6	\$533	Vinyl coated
	Ceiling - Plaster/Drywall	1st - Mens	5	SF	5	\$62	stained
	Ceiling - Plaster/Drywall	1st - Mens	149	SF	6	\$516	Vinyl Coated
	Ceiling - Plaster/Drywall	1st - Mens	5	SF	5	\$62	stained
	Ceiling - Plaster/Drywall	1st - Mens	154	SF	6	\$533	Vinyl coated
	Doors - Wood Doors inclu hw	1st - Mens	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st - Mens	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st - Mens	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st - Mens	1	EA	6	\$301	
	Floor Drain	1st - Mens	1	EA	6	\$1,059	
	Floor Drain	1st - Mens	1	EA	6	\$1,059	
	Floor Drain	1st - Mens	1	EA	6	\$1,059	
	Floor Drain	1st - Mens	1	EA	6	\$1,059	
	Floor - Tile/Sheet	1st - Mens	154	SF	6	\$154	
	Floor - Tile/Sheet	1st - Mens	154	SF	6	\$154	
	Floor - Tile/Sheet	1st - Mens	154	SF	6	\$154	
	Floor - Tile/Sheet	1st - Mens	154	SF	6	\$154	
	Hand Dryer	1st - Mens	1	EA	6	\$230	
	Hand Dryer	1st - Mens	1	EA	6	\$230	
	Hand Dryer	1st - Mens	1	EA	6	\$230	
	Hand Dryer	1st - Mens	1	EA	6	\$230	
	Lavatory	1st - Mens	2	EA	6	\$639	
	Lavatory	1st - Mens	2	EA	6	\$639	
	Lavatory	1st - Mens	2	EA	6	\$639	
	Lavatory	1st - Mens	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st - Mens	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st - Mens	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st - Mens	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st - Mens	1	EA	7	\$0	
	Partitions	1st - Mens	1	EA	6	\$297	
	Partitions	1st - Mens	1	EA	6	\$297	
	Partitions	1st - Mens	1	EA	6	\$297	
	Partitions	1st - Mens	1	EA	6	\$297	
	Urinals	1st - Mens	2	EA	5	\$2,688	damaged - covered
	Urinals	1st - Mens	2	EA	5	\$2,688	damaged - covered

Building: 6-Classroom Modular

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Urinals	1st - Mens	1	EA	5	\$1,344	Damaged / covered
	Urinals	1st - Mens	1	EA	5	\$1,344	Damaged / covered
	Urinals	1st - Mens	1	EA	6	\$336	
	Urinals	1st - Mens	1	EA	6	\$336	
	Walls - Vinyl Coated Gypsum Panel	1st - Mens	436	SF	6	\$1,203	
	Walls - Vinyl Coated Gypsum Panel	1st - Mens	436	SF	6	\$1,203	
	Walls - Vinyl Coated Gypsum Panel	1st - Mens	436	SF	6	\$1,203	
	Walls - Vinyl Coated Gypsum Panel	1st - Mens	436	SF	6	\$1,203	
	Water Closet	1st - Mens	2	EA	6	\$672	
	Water Closet	1st - Mens	2	EA	6	\$672	
	Water Closet	1st - Mens	2	EA	6	\$672	
	Water Closet	1st - Mens	2	EA	6	\$672	
	Accessories	1st - Womens	176	SF	6	\$1,623	
	Accessories	1st - Womens	176	SF	6	\$1,623	
	Accessories	1st - Womens	176	SF	6	\$1,623	
	Accessories	1st - Womens	176	SF	6	\$1,623	
	Ceiling - Plaster/Drywall	1st - Womens	176	SF	6	\$609	Vinyl Coated
	Ceiling - Plaster/Drywall	1st - Womens	176	SF	6	\$609	Vinyl Coated
	Ceiling - Plaster/Drywall	1st - Womens	176	SF	6	\$609	Vinyl Coated
	Ceiling - Plaster/Drywall	1st - Womens	176	SF	6	\$609	Vinyl Coated
	Doors - Wood Doors inclu hw	1st - Womens	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st - Womens	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st - Womens	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st - Womens	1	EA	6	\$301	
	Floor Drain	1st - Womens	1	EA	6	\$1,059	
	Floor Drain	1st - Womens	1	EA	6	\$1,059	
	Floor Drain	1st - Womens	1	EA	6	\$1,059	
	Floor Drain	1st - Womens	1	EA	6	\$1,059	
	Floor - Tile/Sheet	1st - Womens	176	SF	6	\$176	
	Floor - Tile/Sheet	1st - Womens	176	SF	6	\$176	
	Floor - Tile/Sheet	1st - Womens	176	SF	6	\$176	
	Floor - Tile/Sheet	1st - Womens	176	SF	6	\$176	
	Hand Dryer	1st - Womens	1	EA	6	\$230	
	Hand Dryer	1st - Womens	1	EA	6	\$230	
	Hand Dryer	1st - Womens	1	EA	6	\$230	
	Hand Dryer	1st - Womens	1	EA	6	\$230	
	Lavatory	1st - Womens	2	EA	6	\$639	

Building: 6-Classroom Modular

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Lavatory	1st - Womens	2	EA	6	\$639	
	Lavatory	1st - Womens	2	EA	6	\$639	
	Lavatory	1st - Womens	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st - Womens	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st - Womens	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st - Womens	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st - Womens	2	EA	7	\$0	
	Partitions	1st - Womens	3	EA	6	\$891	
	Partitions	1st - Womens	3	EA	6	\$891	
	Partitions	1st - Womens	3	EA	6	\$891	
	Partitions	1st - Womens	3	EA	6	\$891	
	Walls - Vinyl Coated Gypsum Panel	1st - Womens	471	SF	6	\$1,300	
	Walls - Vinyl Coated Gypsum Panel	1st - Womens	471	SF	6	\$1,300	
	Walls - Vinyl Coated Gypsum Panel	1st - Womens	468	SF	6	\$1,292	
	Walls - Vinyl Coated Gypsum Panel	1st - Womens	468	SF	6	\$1,292	
	Water Closet	1st - Womens	4	EA	6	\$1,344	
	Water Closet	1st - Womens	4	EA	6	\$1,344	
	Water Closet	1st - Womens	4	EA	6	\$1,344	
	Water Closet	1st - Womens	4	EA	6	\$1,344	

Rooms (Other Than Classrooms) Subtotal: \$70,602

Building: 6-Classroom Modular

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	5	SF	5	\$45	
	Ceiling - Lay-in	1st Floor	5	SF	5	\$45	
	Ceiling - Lay-in	1st Floor	988	SF	6	\$2,967	
	Ceiling - Lay-in	1st Floor	993	SF	6	\$2,982	
	Ceiling - Lay-in	1st Floor	993	SF	6	\$2,982	
	Ceiling - Lay-in	1st Floor	988	SF	6	\$2,967	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	6	\$551	

Building: 6-Classroom Modular

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Drinking Fountains - Single Fountain	1st Floor	2	EA	6	\$551	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	6	\$551	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	6	\$551	
	Floor - Tile/Sheet	1st Floor	993	SF	6	\$540	
	Floor - Tile/Sheet	1st Floor	993	SF	6	\$540	
	Floor - Tile/Sheet	1st Floor	993	SF	6	\$540	
	Floor - Tile/Sheet	1st Floor	993	SF	6	\$540	
	Lighting - Lay-in	1st Floor	10	EA	7	\$0	
	Lighting - Lay-in	1st Floor	10	EA	7	\$0	
	Lighting - Lay-in	1st Floor	10	EA	7	\$0	
	Lighting - Lay-in	1st Floor	10	EA	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,520	SF	6	\$4,195	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,520	SF	6	\$4,195	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	5	SF	5	\$38	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	5	SF	5	\$38	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,520	SF	6	\$4,195	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,520	SF	6	\$4,195	
Safety							
	Security Cameras	Entire Building	2	EA	6	\$388	
	Security Cameras	Entire Building	2	EA	6	\$388	
	Security Cameras	Entire Building	2	EA	6	\$388	
	Security Cameras	Entire Building	2	EA	6	\$388	

Building Interior Subtotal: \$39,575

Total Building Cost \$963,458

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Athletic							
	Metal Bleachers	East	30	LF	6	\$1,338	
	Surface - Natural	East	20,778	SF	6	\$17,233	SE
	Surface - Natural	East	30,086	SF	5	\$45,604	Cinder, grass on the track, damaged curb
	Surface - Natural	East	8,790	SF	6	\$8,422	NE
	Surface - Natural	East	102,830	SF	6	\$85,287	

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Athletic							
Civil/Drainage							
	Civil/ Drainage - Catch Basin	Entire Site	14	EA	7	\$0	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	5	\$1,379	SW basement well; clogged
	Civil/ Drainage - Site Drain	Entire Site	3	EA	6	\$931	Basement wells
	Civil/ Drainage - Site Manhole	Entire Site	24	EA	7	\$0	
Fencing							
	Fencing - Chain Link	Entire Site	378	LF	6	\$7,097	Baseball diamonds
	Fencing - Guard Rail	Entire Site	50	LF	6	\$578	
	Fencing - New Standard Ornamental	Entire Site	6	LF	5	\$0	NW at parking lot; bent
	Fencing - New Standard Ornamental	Entire Site	3,160	LF	6	\$100,814	
Landscape							
	Benches	Entire Site	6	EA	6	\$2,580	E
	Irrigation	Entire Site	139,780	SF	4	\$629,639	Numerous leaks
	Landscape - Grass	Entire Site	102,045	SF	6	\$84,636	
	Landscape - Hardscape- Asphalt	Entire Site	15,878	SF	5	\$72,431	SW; cracks
	Landscape - Hardscape- Concrete	Entire Site	13,020	SF	6	\$67,213	E
	Parkway trees	Entire Site	58	EA	7	\$0	
	Planting Beds/ Area	Entire Site	1,150	SF	6	\$1,891	
	Retaining Wall - Concrete	Entire Site	1,200	SF	5	\$88,220	SW basement wells; spalling, cracks
	Retaining Wall - Concrete	Entire Site	10,338	SF	6	\$242,299	
	Trash Receptacles	Entire Site	10	EA	6	\$3,123	
Parking Lot							
	Concrete Curbs	N Lot	15	LF	6	\$193	
	Concrete Curbs	NW Lot	90	LF	6	\$1,156	
	Lighting - Pole Mounted	N Lot	10	EA	6	\$14,525	E site
	Surface - Asphalt	N Lot	14,064	SF	6	\$33,988	
	Surface - Asphalt	W Lot	22,181	SF	4	\$175,088	Deterioration numerous alligator cracking was occurring
	Surface	NW Lot	18,859		6	\$0	
	Trash Compactor	W Lot	2	EA	6	\$0	
	Trash Enclosure - Chain Links	W Lot	392	SF	5	\$12,416	Loose poles
	Trash Enclosure - Masonry	W Lot	1,188	SF	6	\$46,871	
	Vehicular Screening	N Lot	15	LF	6	\$1,181	
	Vehicular Screening	NW Lot	90	LF	6	\$7,086	

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Playground							
	Equipment - Pre K 3-5	NE	1	EA	6	\$3,546	
	Equipment - Swingset	NE	1	EA	6	\$1,182	
	Surface - Wood Chips	NE	3,480	SF	6	\$7,017	
Service Garage							
	Service Garage - Free-Standing	NE	831	SF	6	\$7,629	
Sidewalks							
	Sidewalks - Internal Walks	Entire Site	805	LF	6	\$9,670	
	Sidewalks - Internal Walks	Entire Site	155	LF	5	\$7,725	Exit 7; water ponding, pitting
	Sidewalks - Internal Walks	Entire Site	110	LF	5	\$6,355	Main entrance; water ponding
	Sidewalks - Internal Walks	Entire Site	50	LF	5	\$2,889	SW; cracks, pitting
	Sidewalks - Internal Walks	Entire Site	10	LF	5	\$578	SW site; cracks
	Sidewalks - Perimeter Sidewalks	Entire Site	23,225	SF	6	\$46,164	
Signage							
	Flag Pole - Flag Pole	Entire Site	2	EA	6	\$3,314	
	Monument - Building Mounted Cut Letter Sign	Entire Site	4	EA	6	\$0	Door #1, Door #3, Door #8, Door #10

Site Subtotal: **\$1,849,288**

Total Site Cost **\$1,849,288**

Campus Total ^{2 3}	\$16,564,957
------------------------------------	---------------------

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.

-
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
 - **Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
 - **For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
 - **Campus Total** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.
-

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
Main														
Art Room	Art Room	3rd Floor	311	311	1,255	1	10	26	216	84	40	Y	Y	Y
Art Room	Art Room	3rd Floor	313	313	855	1	3	26	240	25	40	Y	Y	Y
Art Room	Art Room	3rd Floor	315	315	855	1	3	26	240	25	40	Y	Y	N
Art Room	Art Room	3rd Floor	357	307	550	1	3	16	108	42	40	Y	Y	N
Computer Lab	Laboratory/Shop	1st Floor	113	113	773	1	23	34	132	44	40	Y	Y	N
Computer Lab	Lunch Room	1st Floor	127	127	932	4	12	26	0	0	40	N	Y	N
Computer Lab	Library	2nd Floor	201	201	1,489	2	180	150	240	72	40	Y	Y	Y
Computer Lab	Regular Classroom	2nd Floor	209	209	742	1	3	40	144	56	40	Y	Y	N
Computer Lab	Art Room	2nd Floor	211	211	1,155	1	29	116	204	72	40	Y	Y	Y
Computer Lab	Regular Classroom	2nd Floor	220	220	925	1	16	74	168	58	40	Y	Y	Y
Computer Lab	Other Instructional Use	2nd Floor	222	202	742	1	3	40	144	56	40	Y	Y	Y
Computer Lab	Other Instructional Use	2nd Floor	227	227	1,084	1	3	30	144	56	40	Y	Y	Y
Computer Lab	Gymnasium	2nd Floor	228	228	1,084	1	3	50	144	56	40	Y	Y	Y
Computer Lab	Multi Purpose Room	3rd Floor	300	300	1,016	1	14	62	85	30	40	Y	Y	Y
Computer Lab	Regular Classroom	3rd Floor	326	326	830	1	55	110	156	52	40	Y	Y	Y
Computer Lab	Regular Classroom	3rd Floor	330	330	1,100	1	3	64	192	96	40	Y	Y	Y
Computer Lab	Multi Purpose Room	3rd Floor	333	300	645	1	26	44	75	38	40	Y	Y	Y
Computer Lab	Regular Classroom	3rd Floor	399	300	950		13	60	150	75	40	Y	Y	Y
Music Room	Music Room	4th Floor	400	400	1,800	3	3	34	310	103	40	N	N	Y
Music Room	Music Room	4th Floor	401	401	1,800	3	3	34	310	103	40	N	N	Y
Other Instructional Use	Special Program	1st Floor	121 JROTC	ROTC	1,338		14	30	0	0	40	N	Y	Y
Regular Classroom	Regular Classroom	1st Floor	101	101	742	1	3	22	108	44	40	Y	Y	Y
Regular Classroom	Regular Classroom	1st Floor	103	103	729	11	4	2,218	188	94	40	N	N	Y
Regular Classroom	Regular Classroom	1st Floor	105	105	756	2	4	26	188	94	40	N	Y	Y
Regular Classroom	Regular Classroom	1st Floor	107	107	727	1	4	22	188	94	40	N	Y	Y
Regular Classroom	Regular Classroom	1st Floor	109	109	729	2	4	18	188	94	40	N	Y	Y
Regular Classroom	Regular Classroom	1st Floor	111	111	923	2	4	20	188	94	40	N	Y	Y
Regular Classroom	Regular Classroom	1st Floor	116	116	540	1	2	6	141	70	40	N	Y	N
Regular Classroom	Regular Classroom	5th Floor	130	130	742	1	2	26	188	94	40	N	Y	Y
Regular Classroom	Regular Classroom	1st Floor	132	132	792	6	3	24	188	94	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	742	1	3	40	144	56	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	742	1	3	22	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	742	1	3	22	144	56	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	742	1	3	22	144	56	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	742	1	3	22	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	742	1	3	22	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	742	1	3	22	144	56	40	Y	Y	Y

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
Main														
Regular Classroom	Regular Classroom	2nd Floor	212	212	742	1	3	22	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	213	213	742	1	3	22	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	215	215	742	1	11	22	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	218	218	550	1	1	8	108	42	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	221	221	742	1	3	22	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	224	224	742	1	3	40	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	225	225	742	1	3	40	144	56	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	742	1	3	22	144	56	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	730	1	4	26	192	96	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	302	302	742	1	4	26	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	550	1	3	48	144	72	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	304	304	742	1	4	26	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	305	305	550	1	3	28	144	75	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	306	306	742	1	4	26	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	550	1	3	22	108	42	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	742	1	4	26	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	310	310	742	1	3	26	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	312	312	742	1	3	22	144	56	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	550	1	2	8	108	42	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	319	319	710	4	15	22	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	321	321	715	1	3	26	192	96	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	323	323	725	1	3	28	192	96	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	325	325	1,086	1	5	16	192	96	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	1,100	1	3	32	288	144	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	332	332	742	1	3	26	144	56	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	353	303	550	1	3	108	144	72	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	355	305	550	1	2	24	108	42	40	Y	Y	Y
Science	Science	2nd Floor	214	214	1,065	2	5	74	180	70	40	Y	Y	Y
Science	Science	2nd Floor	216	216	1,039	2	3	74	216	84	40	Y	Y	Y
Science	Science	3rd Floor	314	314	1,065	2	5	74	180	70	40	Y	Y	N
Science	Science	3rd Floor	316	316	1,039	2	3	74	216	84	40	Y	Y	Y
Science	Science	3rd Floor	320	320	918	1	3	54	180	70	40	Y	Y	N
Science Classroom	Science Classroom	3rd Floor	322	322	1,072	1	2	12	240	120	40	N	N	N
Science Lab Level 1	Science Lab Level 1	1st Floor	112	112	1,148	0	10	60	282	141	40	N	Y	N
Science Lab Level 1	Science Lab Level 1	1st Floor	114	114	1,100	1	5	68	282	141	40	N	N	Y
Store Room	Regular Classroom	1st Floor	115	115	1,489	2	180	150	240	72	40	Y	Y	N

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
6-Classroom Modular														
Computer Lab	Regular Classroom	1st Floor	502	-	812	0	0	10	64	32	40	N	Y	N
Office	Regular Classroom	1st Floor	501	-	816	6	1	10	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	503	-	812	0	0	12	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	504	-	812	0	1	12	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	505	-	819	4	1	12	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	506	-	819	6	0	13	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	601	-	817	1	0	12	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	602	-	817	23	1	24	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	603	-	817	2	1	12	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	604	-	817	4	0	12	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	605	-	817	2	0	12	64	32	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	606	-	817	2	1	12	64	32	40	N	Y	N