

## Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition<sup>1</sup>. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at [http://www.cps.edu/About\\_CPS/Policies\\_and\\_guidelines/Pages/facilitystandards.aspx](http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx). Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1930	4	248,453	\$9,939,486
SITE				\$256,957
<b>Campus Total</b>			<b>248,453</b>	<b>\$10,196,443</b>

### Building: Main

#### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Entrance Control - Audio and Video	#B W	1	EA	6	\$702	
	Entrance Control - Audio and Video	#F E	1	EA	6	\$702	
	Exterior Doors - Exterior AMP Door	#A W	4	EA	6	\$2,696	
	Exterior Doors - Exterior AMP Door	#B W	3	EA	6	\$2,022	
	Exterior Doors - Exterior AMP Door	#C W	3	EA	6	\$2,022	
	Exterior Doors - Exterior AMP Door	#D W	3	EA	6	\$2,022	
	Exterior Doors - Exterior AMP Door	#E E	2	EA	6	\$1,348	
	Exterior Doors - Exterior AMP Door	#F E	4	EA	6	\$2,696	
	Exterior Doors - Exterior AMP Door	#G E	2	EA	6	\$1,348	
	Exterior Doors - Exterior AMP Door	#H Exit E	2	EA	6	\$1,348	
	Exterior Doors - Exterior AMP Door	#J N	2	EA	6	\$1,348	
	Exterior Doors - Exterior Steel Door	#E.5 Exit E Basement level	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#I N	1	EA	6	\$481	
	Exterior Doors - Overhead Rolling/ Garage Door	#H.5 E	1	EA	6	\$1,433	
	Exterior Doors - Transom Lite	#F E	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#G E	1	EA	6	\$313	
	Exterior Stairs - Concrete	#A W	135	LF	6	\$11,039	
	Exterior Stairs - Concrete	#B W	90	LF	6	\$7,359	
	Exterior Stairs - Concrete	#C W	306	LF	6	\$25,021	
	Exterior Stairs - Concrete	#D W	225	LF	6	\$18,398	
	Exterior Stairs - Concrete	#E E	72	LF	6	\$5,887	

**Building: Main**

**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Exterior Stairs - Concrete	#F E	90	LF	6	\$7,359	
	Exterior Stairs - Concrete	#G E	60	LF	6	\$4,906	
	Exterior Stairs - Concrete	#H Exit E	72	LF	6	\$5,887	
	Exterior Stairs - Concrete	#J N	72	LF	6	\$5,887	
	Power Door Operator and Controls	#B W	1	EA	6	\$0	
	Power Door Operator and Controls	#F E	2	EA	6	\$0	
	Ramp Handrail - Steel_Ramp Handrail	#B W	84	LF	6	\$728	
	Ramp Handrail - Steel_Ramp Handrail	#F E	100	LF	6	\$867	
	Ramps - Concrete	#B W	42	LF	6	\$6,310	
	Ramps - Concrete	#F E	50	LF	6	\$7,512	
	Stair Handrail - Steel_Stair Handrail	#A W	50	LF	5	\$575	Peeling paint
	Stair Handrail - Steel_Stair Handrail	#B W	40	LF	5	\$460	Peeling paint
	Stair Handrail - Steel_Stair Handrail	#C W	102	LF	5	\$1,173	peeling paint
	Stair Handrail - Steel_Stair Handrail	#D W	80	LF	5	\$920	Peeling paint
	Stair Handrail - Steel_Stair Handrail	#E E	3	LF	5	\$34	Damaged -Bent Middle rail and peeling paint
	Stair Handrail - Steel_Stair Handrail	#E E	27	LF	5	\$310	Peeling paint
	Stair Handrail - Steel_Stair Handrail	#F E	30	LF	5	\$345	Peeling paint
	Stair Handrail - Steel_Stair Handrail	#G E	30	LF	5	\$345	Peeling paint
	Stair Handrail - Steel_Stair Handrail	#H Exit E	30	LF	5	\$345	Peeling paint
	Stair Handrail - Steel_Stair Handrail	#J N	30	LF	5	\$345	Peeling paint
<b>Foundation</b>							
	Foundation - Concrete	Entire Building	50	LF	6	\$9,711	Leaks throughout
	Foundation - Concrete	Entire Building	1,930	LF	7	\$0	
	Superstructure - Concrete	Entire Building	248,453	SF	7	\$0	
<b>Lighting</b>							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building / Roof	37	EA	6	\$19,852	
	Exterior Lighting - Wall Mounted	Entire Building	20	EA	6	\$5,775	
<b>Roof System</b>							
	Chimney - Brick Chimney- Concrete/ Mortar Liner	North Roof	42	LF	6	\$40,097	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	North Roof	30	LF	6	\$28,640	
	Coping - Metal	Main Roof	102	LF	6	\$3,276	
	Coping - Terra Cotta	Main Roof	783	LF	6	\$25,148	
	Coping - Terra Cotta	North Roof	598	LF	6	\$19,206	
	Coping - Terra Cotta	South Roof	630	LF	6	\$20,234	
	Downspouts - Interior Downspouts	Main Roof	370	LF	6	\$12,296	
	Downspouts - Interior Downspouts	North Roof	225	LF	6	\$7,477	

**Building: Main**

**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Roof System</b>							
	Downspouts - Interior Downspouts	South Roof	225	LF	6	\$7,477	
	Parapet - 16" - 30" Height	Main Roof	368	LF	6	\$14,703	
	Parapet - 16" - 30" Height	North Roof	149	LF	6	\$5,953	
	Parapet - 16" - 30" Height	South Roof	157	LF	6	\$6,273	
	Parapet - Parapet < 16" Height	Main Roof	148	LF	6	\$3,153	
	Parapet - Parapet > 30"	Main Roof	368	LF	6	\$23,523	
	Parapet - Parapet > 30"	North Roof	449	LF	6	\$28,701	
	Parapet - Parapet > 30"	South Roof	473	LF	6	\$30,235	
	Roof Structure - Concrete	Main Roof	21,403	SF	7	\$0	
	Roof Structure - Concrete	North Roof	21,131	SF	7	\$0	
	Roof Structure - Concrete	South Roof	22,886	SF	7	\$0	
	Roof - Modified Bitumen	Main Roof	21,403	SF	6	\$201,389	
	Roof - Modified Bitumen	North Roof	21,131	SF	6	\$198,830	
	Roof - Modified Bitumen	South Roof	22,886	SF	6	\$215,344	
<b>Walls</b>							
	Canopy - Fabric	Entire Building	164	SF	6	\$2,519	
	Cheek-Wall - Concrete	Entire Building	440	SF	6	\$4,511	
	Exterior Walls - Brick	Entire Building	92,992	SF	6	\$624,999	
	Exterior Walls - Stone-Cast	Entire Building	1,190	SF	6	\$7,998	
	Exterior Walls - Terra Cotta	Entire Building	3,489	SF	6	\$23,450	
<b>Windows</b>							
	Guard - Guards perforated	Entire Building / 1st Floor	5,037	SF	6	\$64,322	
	Guard - Guards wire guard	Entire Building	3,269	SF	6	\$41,745	
	Guard - Guards wire guard	Entire Building / South Façade	396	SF	6	\$5,057	
	Lintels - Steel	Entire Building	141	LF	7	\$0	
	Lintels - Terra Cotta	Entire Building	2,219	LF	6	\$0	
	Skylite - Glass Double-Pane	Entire Building / Roof	2,831	SF	6	\$67,648	
	Windows - Decorative	Entire Building / South Façade	396	SF	6	\$2,956	
	Windows - Sash Aluminum Double-pane	Entire Building	23,577	SF	6	\$175,993	
	Windows - Sash Aluminum	Entire Building	275	SF	5	\$9,875	poorly insulated
	Windows - Sash Aluminum	Entire Building / Roof	64	SF	6	\$478	
	Windows - Sash Lexan	Entire Building / Penthouse	26	SF	6	\$194	

**Building Exterior Subtotal:**

**\$2,093,119**

**Building: Main**

## Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Automatic Transfer Switch	Electrical Room	1	EA	6	\$408	
	Emergency A/C Power - Auditorium and Aisle Lighting	Entire Building / 1st Floor	6,421	SF	4	\$28,464	Many of the emergency lights are not working
	Emergency A/C Power - Corridors and Stairs	Entire Building	34,935	SF	6	\$10,491	
	Emergency A/C Power - Gym	Entire Building	13,506	SF	5	\$0	
	Emergency A/C Power - Lunchrooms	Entire Building / 3rd Floor	4,175	SF	5	\$0	
	Emergency A/C Power - Pool	Entire Building / 1st Floor	3,346	SF	6	\$1,244	
	Emergency A/C Power - Students Toilets	Entire Building	4,695	SF	6	\$1,746	
	Emergency Battery Packs - Auditorium and Aisle Lighting	1st, 2nd and 3rd floor / 1st Floor	8	EA	2	\$4,631	Batteries are very old and show signs of acid corrosion
	Emergency Battery Packs - Auditorium and Aisle Lighting	1st, 2nd and 3rd floor / 1st Floor	2	EA	6	\$405	
	Emergency Battery Packs - Corridors and Stairs	1st, 2nd and 3rd floor / 1st Floor	1	EA	4	\$579	
	Emergency Battery Packs - Gym	1st, 2nd and 3rd floor	2	EA	2	\$1,158	Batteries are very old and show signs of acid corrosion
	Exit Signs - Auditorium	1st, 2nd, 3rd floor, Entire building / 1st Floor	15	EA	2	\$8,182	Exit signs have no battery back-up power
	Exit Signs - Corridors and Stairs	1st, 2nd, 3rd floor, Entire building / Entire Building	35	EA	2	\$19,092	Exit signs have no battery back-up power
	Exit Signs - Gym	1st, 2nd, 3rd floor, Entire building	4	EA	2	\$2,313	Exit signs have no battery back-up power
	Exit Signs - Lunchroom	1st, 2nd, 3rd floor, Entire building / 3rd Floor	3	EA	2	\$1,636	Exit signs have no battery back-up power
	Exit Signs - Pool	1st, 2nd, 3rd floor, Entire building / 1st Floor	1	EA	2	\$568	Exit signs have no battery back-up power
	Security System - CCTV	Entire Building	248,453	SF	6	\$74,610	
	Security System - Intrusion Detection	Entire Building	248,453	SF	6	\$63,952	
<b>Main Service</b>							
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	
	Main Electrical Service- Live Front - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	4	\$128,955	deteriorated, live, exposed bus bars, not locked
	PA System	Entire Building	248,453	SF	6	\$81,716	
<b>Power Distribution</b>							
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	\$1,196	Emergency fuse panels
	Lighting and Power Panels - 100 A	Entire Building	18	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	\$13,156	Panels are live front
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	28	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building	5	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Entire Building / Electrical Room	7	EA	6	\$5,111	
	Main Distribution Panels - Less than 400 amp	Entire Building / Basement	1	EA	4	\$8,819	

**Building: Main**

**Category: Electrical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Electrical System Subtotal:</b>						<b>\$461,354</b>	

**Building: Main**

**Category: Safty System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Fire Alarm</b>							
	Fire Alarm Panel	Basement	1	EA	6	\$6,406	
	Fire Alarm Strobe Lights	Basement / Entire Building	248,453	SF	6	\$88,822	
	Fire Alarm_System	Basement / Entire Building	248,453	SF	6	\$120,798	
<b>Safty System Subtotal:</b>						<b>\$216,026</b>	

**Building: Main**

**Category: Mechanical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Air Handling Systems</b>							
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils and Chilled Water Coils - 25001 - 35000 cfm	mechanical room 5 / Mechanical Room	1	EA	5	\$69,685	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	mechanical room 1 / Mechanical Room	1	EA	5	\$44,262	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	mechanical room 8 / Mechanical Room	1	EA	5	\$44,262	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical room 4 / Mechanical Room	1	EA	5	\$55,649	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 8001 - 15000 cfm	Mechanical room 2 / Mechanical Room	1	EA	5	\$34,007	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000	Mechanical room 3 / Mechanical Room	1	EA	5	\$66,438	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000	Mechanical room 6 / Mechanical Room	1	EA	5	\$66,438	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000	Mechanical room 7 / Mechanical Room	1	EA	5	\$78,608	
	Air Intake	mechanical room 1 / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical room 2 / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical room 3 / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical room 4 / Roof	1	EA	6	\$5,765	
	Air Intake	mechanical room 5 / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical room 6 / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical room 7 / Roof	1	EA	6	\$5,765	
	Air Intake	mechanical room 8 / Roof	1	EA	6	\$5,765	
	Auxiliaries - 15001 - 25000 cfm	Mechanical room 3 / Mechanical Room	1	EA	6	\$5,788	

## Building: Main

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Air Handling Systems</b>							
	Auxiliaries - 15001 - 25000 cfm	Mechanical room 6 / Mechanical Room	1	EA	6	\$5,788	
	Auxiliaries - 15001 - 25000 cfm	mechanical room 8 / Mechanical Room	1	EA	5	\$14,899	
	Auxiliaries - 25001 - 35000 cfm	Mechanical room 4 / Mechanical Room	1	EA	5	\$16,577	
	Auxiliaries - 25001 - 35000 cfm	mechanical room 5 / Mechanical Building/Central Plant	1	EA	6	\$6,511	
	Auxiliaries - 25001 - 35000 cfm	Mechanical room 7 / Mechanical Room	1	EA	5	\$16,577	
	Auxiliaries - 8001 - 15000 cfm	Mechanical room 2 / Mechanical Room	1	EA	6	\$4,341	
	Auxiliaries	mechanical room 1 / Mechanical Room	1	EA	5	\$0	
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Mechanical Room	1	EA	5	\$16,255	AH-2 Has RA Fan but it discharges into common plenum for AH-4 as well.
	Reheat Boxes	mechanical room 1 / Plenum	4	EA	5	\$0	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical room 2 / Plenum	3	EA	6	\$3,153	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical room 4 / Plenum	4	EA	6	\$4,204	
	Reheat Boxes - Reheat Boxes with Steam Coil	mechanical room 5 / Plenum	5	EA	6	\$5,256	
	Reheat Boxes - Reheat Boxes with Steam Coil	mechanical room 8 / Plenum	3	EA	6	\$3,153	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical room 2 / Entire Building	100	LF	7	\$0	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical room 3 / Entire Building	100	LF	7	\$0	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical room 4 / Entire Building	166	LF	7	\$0	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	mechanical room 5 / Mechanical Room	100	LF	7	\$0	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical room 6 / Entire Building	100	LF	7	\$0	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical room 7 / Entire Building	100	LF	7	\$0	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	mechanical room 8 / Entire Building	100	LF	7	\$0	
	Return Duct Work	mechanical room 1 / Entire Building	100	LF	7	\$0	
	Zone Dampers	Mechanical room 3 / Mechanical Room	8	EA	6	\$6,664	
	Zone Dampers	Mechanical room 6 / Mechanical Room	9	EA	6	\$7,497	
	Zone Dampers	Mechanical room 7 / Mechanical Room	13	EA	5	\$24,876	
	Zone Dampers	mechanical room 1 / Plenum	16	EA	6	\$13,329	
	Zone Dampers	Mechanical room 2 / Plenum	10	EA	6	\$8,330	
	Zone Dampers	Mechanical room 4 / Plenum	16	EA	6	\$13,329	
	Zone Dampers	mechanical room 5 / Plenum	20	EA	6	\$16,661	
	Zone Dampers	mechanical room 8 / Plenum	12	EA	6	\$9,996	
<b>Boiler Systems</b>							
	Boiler Auxiliary- Steam Boiler - Greater than 200 HP	Boiler Room	3	EA	6	\$6,139	
	Chemical Feed System	Boiler Room / Mechanical Room	1	EA	6	\$1,078	
	Combustion Dampers	Boiler Room	1	EA	6	\$409	serves domestic hot water heaters
	Combustion Dampers	Boiler Room	3	EA	6	\$1,227	
	Condensate Pump	Boiler Room / Basement	7	EA	6	\$14,148	

## Building: Main

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Boiler Systems</b>							
	Feed Water Pumps and Tank	Boiler Room / Basement	1	EA	5	\$36,450	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Steam Boiler - Greater than 200 HP	Boiler Room	3	EA	4	\$98,584	
	Piping - Condensate Pipe- Steel	Boiler Room / Entire Building	1,000	LF	6	\$1,888	See Mech. piping
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	1,000	LF	6	\$1,888	Piping is old, worn out and has several clamps installed.
	Steam Traps	Boiler Room / Entire Building	170	EA	5	\$223,533	
<b>Heating Devices</b>							
	Cabinet Heaters - With Steam Coil	Entire Building	8	EA	5	\$14,103	
	Radiators - Steam	Entire Building	76	EA	5	\$127,324	
	Unit Heater - Electric	Mechanical Room, 4th floor, Boiler Room / 4th Floor	1	EA	6	\$278	
	Unit Heater - Gas	Mechanical Room, 4th floor, Boiler Room / Boiler Room	1	EA	5	\$1,527	
	Unit Heater - Steam	Mechanical Room, 4th floor, Boiler Room / Mechanical Room	3	EA	6	\$833	
	Wall Heater - Electric	Entire Building	6	EA	5	\$3,220	
<b>Temperature Control</b>							
	Electric Thermostat	Entire Building	13	EA	6	\$0	Controls cabinet heaters and unit heaters.
	Pneumatic System	Entire Building	248,453	SF	4	\$1,293,248	System has over 30 years of service and very few of the controls work. (Most damper and valve actuators are not working, not all sensors are responding, most dampers and valves are operating in manual mode, temperatures are not maintained).
	Thermostats - Pneumatic	Entire Building	120	EA	4	\$88,468	Thermostats are overheated by a failed pneumatics and are shutting down fans.
<b>Ventilation</b>							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Attic, 3rd floor, roof, 4th floor, Entire Building / 4th Floor	2	EA	6	\$1,185	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Attic, 3rd floor, roof, 4th floor, Entire Building / Attic	1	EA	4	\$6,392	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Attic, 3rd floor, roof, 4th floor, Entire Building / 3rd Floor	1	EA	4	\$4,245	
	Exhaust Fans- Indoor - Greater than 8000 CFM	Attic, 3rd floor, roof, 4th floor, Entire Building / Attic	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Attic, 3rd floor, roof, 4th floor, Entire Building / Roof	8	EA	6	\$4,739	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Attic, 3rd floor, roof, 4th floor, Entire Building / Roof	3	EA	6	\$1,777	

**Building: Main**

**Category: Mechanical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Ventilation</b>							
	Lab Exhaust Hood	Attic, 3rd floor, roof, 4th floor, Entire Building / Entire Building	3	EA	5	\$8,851	
	Lab Exhaust Hood	Attic, 3rd floor, roof, 4th floor, Entire Building / Entire Building	3	EA	6	\$3,743	
	Type I Exhaust Hood- Kitchen	Attic, 3rd floor, roof, 4th floor, Entire Building / 3rd Floor	1	EA	6	\$1,248	
	Type II Exhaust Hood- Warming Kitchen	Attic, 3rd floor, roof, 4th floor, Entire Building / 3rd Floor	1	EA	6	\$920	

**Mechanical System Subtotal:**

**\$2,656,687**

**Building: Main**

**Category: Plumbing System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Hot Water</b>							
	Gas Heater - Greater than 600000 BTU/HR	Boiler Room	2	EA	6	\$620	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room / Basement	4	EA	7	\$0	
<b>Piping</b>							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	238,453	SF	7	\$0	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	10,000	SF	7	\$0	Piping is old galvanized steel, wornout, and prone to new leaks
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	248,453	SF	6	\$60,399	
	Domestic Piping-Cold Water Risers	Entire Building	238,453	SF	7	\$0	
	Domestic Piping-Cold Water Risers	Entire Building	10,000	SF	6	\$1,859	Piping is old galvanized steel, wornout, and prone to new leaks
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	248,453	SF	7	\$0	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	10,000	SF	6	\$1,573	Piping is old galvanized steel, wornout, and prone to new leaks
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	248,453	SF	6	\$46,187	
	Domestic Piping-Hot Water Return Lines	Entire Building	238,453	SF	6	\$34,099	
	Domestic Piping-Hot Water Return Risers	Entire Building	238,453	SF	7	\$0	
	Domestic Piping-Hot Water Return Risers	Entire Building	10,000	SF	6	\$1,430	Piping is old galvanized steel, wornout, and prone to new leaks
	Sanitary Piping	Entire Building	248,453	SF	6	\$227,384	
	Storm Piping	Entire Building	248,453	SF	6	\$216,726	
	Vent Piping	Entire Building	248,453	SF	6	\$166,985	

**Pool Systems**

	Pool Drain Piping	Mechanical Room	25	LF	4	\$2,532	
--	-------------------	-----------------	----	----	---	---------	--



**Building: Main**

**Category: Plumbing System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Pool Systems</b>							
	Pool Filtration System including Pump	Mechanical Room	1	EA	5	\$19,025	
	Pool Hot Water Heater - Gas Fired	Mechanical Room	1	EA	6	\$310	
	Pool Supply and Return Piping	Mechanical Room	100	LF	4	\$16,604	
<b>Pumps</b>							
	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	7	\$0	
	Pumps - Ejector-Duplex	Basement	1	EA	7	\$0	
	Pumps - Sump-Duplex	Basement	4	EA	6	\$5,548	
	Pumps - Sump-Simplex	Basement	2	EA	6	\$1,490	serve elevator pits

**Plumbing System Subtotal: \$802,771**

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #101 (Regular Classroom)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	724	SF	6	\$2,174	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	wood panel at one door
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Terrazzo	1st Floor	6	SF	6	\$13	at one entry
	Floor - Terrazzo	1st Floor	1	SF	5	\$45	cracked at one entry
	Floor - Wood	1st Floor	723	SF	6	\$5,097	
	Lighting - Lay-in	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	883	SF	6	\$2,437	
	Walls - Structural Glazed Tile	1st Floor	26	SF	6	\$82	at one entry door
<b>Classroom #102 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	730	SF	6	\$2,192	
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	Wood paneling at one door
	Doors - Transom Window	1st Floor	18	SF	6	\$305	wire glass

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #102 (Regular Classroom)</b>							
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Terrazzo	1st Floor	7	SF	6	\$15	at one entry door
	Floor - Wood	1st Floor	723	SF	6	\$5,097	
	Lighting - Lay-in	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	18	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	998	SF	6	\$2,754	
	Walls - Plaster/Drywall	1st Floor	6	SF	5	\$31	Damaged and peeling paint
	Walls - Structural Glazed Tile	1st Floor	26	SF	6	\$82	at one entry door
<b>Classroom #104 (Regular Classroom)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	725	SF	6	\$2,177	
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	Wood paneling at one door
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Terrazzo	1st Floor	7	SF	6	\$15	at one entry door
	Floor - Wood	1st Floor	725	SF	6	\$5,111	
	Lighting - Lay-in	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	883	SF	6	\$2,437	
	Walls - Structural Glazed Tile	1st Floor	26	SF	6	\$82	at one entry door
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #106 (Regular Classroom)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	780	SF	6	\$2,342	
	Chalk Board	1st Floor	32	LF	4	\$2,938	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	wire glass
	Doors - Transom Window	1st Floor	9	SF	6	\$152	Wood paneling at one entry door
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Terrazzo	1st Floor	7	SF	7	\$0	at one entry
	Floor - Tile	1st Floor	780	SF	6	\$1,707	
	Lighting - Lay-in	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,077	SF	6	\$2,972	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #106 (Regular Classroom)</b>							
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #116 (Computer Lab)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	896	SF	6	\$2,691	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	wood panel at one door
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Terrazzo	1st Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	1st Floor	896	SF	6	\$6,317	
	Lighting - Lay-in	1st Floor	27	EA	7	\$0	
	Marker Board	1st Floor	6	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,014	SF	6	\$2,799	
	Walls - Structural Glazed Tile	1st Floor	26	SF	6	\$82	at one entry door
<b>Classroom #118 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	7	LF	6	\$177	
	Ceiling - Lay-in	1st Floor	496	SF	6	\$1,489	
	Chalk Board	1st Floor	11	LF	4	\$1,010	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	wood panel
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	496	SF	6	\$1,085	
	Lighting - Lay-in	1st Floor	8	EA	7	\$0	
	Marker Board	1st Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	688	SF	6	\$1,899	
<b>Classroom #120 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	7	LF	6	\$177	
	Ceiling - Lay-in	1st Floor	496	SF	6	\$1,489	
	Chalk Board	1st Floor	11	LF	4	\$1,010	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	Wood panel
	Doors - Transom Window	1st Floor	9	SF	6	\$152	wire glass
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Terrazzo	1st Floor	7	SF	7	\$0	at entry

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #120 (Regular Classroom)</b>							
	Floor - Tile	1st Floor	496	SF	6	\$1,085	
	Lighting - Lay-in	1st Floor	10	EA	7	\$0	
	Marker Board	1st Floor	18	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	688	SF	6	\$1,899	
<b>Classroom #122 (Regular Classroom)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	11	LF	6	\$278	
	Ceiling - Lay-in	1st Floor	962	SF	6	\$2,889	
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	wood panel at one entry door
	Doors - Transom Window	1st Floor	18	SF	6	\$305	wire glass
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Terrazzo	1st Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	1st Floor	962	SF	6	\$2,105	
	Lighting - Lay-in	1st Floor	27	EA	7	\$0	
	Marker Board	1st Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,001	SF	6	\$2,763	
	Walls - Structural Glazed Tile	1st Floor	26	SF	6	\$82	at one entry door
<b>Classroom #124 (Store Room)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	11	LF	6	\$278	
	Ceiling - Lay-in	1st Floor	1,017	SF	6	\$3,054	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	wire glass
	Doors - Transom Window	1st Floor	9	SF	6	\$152	Wood panel at one entry door
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Terrazzo	1st Floor	7	SF	7	\$0	at one door entry
	Floor - Wood	1st Floor	1,017	SF	6	\$7,170	
	Lighting - Lay-in	1st Floor	18	EA	7	\$0	
	Marker Board	1st Floor	21	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,033	SF	6	\$2,851	
	Walls - Structural Glazed Tile	1st Floor	26	SF	6	\$82	at one entry door
<b>Classroom #201 (Regular Classroom)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	720	SF	6	\$2,162	
	Chalk Board	2nd Floor	30	LF	4	\$2,754	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #201 (Regular Classroom)</b>							
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	wire glass
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Wood panel
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at door entry
	Floor - Wood	2nd Floor	720	SF	6	\$5,076	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	883	SF	6	\$2,437	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at entry door
<b>Classroom #202 (Regular Classroom)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	730	SF	6	\$2,192	
	Chalk Board	2nd Floor	30	LF	6	\$669	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	wire glass
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Wood panel
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at entry door
	Floor - Wood	2nd Floor	730	SF	6	\$5,146	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	6	\$343	
	Walls - Plaster/Drywall	2nd Floor	1,004	SF	6	\$2,771	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at entry door
<b>Classroom #204 (Regular Classroom)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	718	SF	6	\$2,156	
	Ceiling - Lay-in	2nd Floor	2	SF	5	\$16	water stain
	Chalk Board	2nd Floor	26	LF	4	\$2,387	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at one door entry
	Floor - Wood	2nd Floor	720	SF	6	\$5,076	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #204 (Regular Classroom)</b>							
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	879	SF	6	\$2,426	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	Peeling paint
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	damaged on exterior wall above electrical panel
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #206 (Regular Classroom)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	716	SF	6	\$2,150	
	Chalk Board	2nd Floor	37	LF	4	\$3,397	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at one entry door
	Floor - Tile/Sheet	2nd Floor	716	SF	6	\$717	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	6	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	883	SF	6	\$2,437	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #209 (Regular Classroom)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	703	SF	6	\$2,111	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	wood panels
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	2nd Floor	703	SF	6	\$1,538	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	867	SF	6	\$2,393	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #210 (Regular Classroom)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	26	LF	6	\$657	
	Ceiling - Lay-in	2nd Floor	726	SF	6	\$2,180	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #210 (Regular Classroom)</b>							
	Chalk Board	2nd Floor	38	LF	4	\$3,489	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	Wood panel at one door
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	2nd Floor	726	SF	6	\$5,118	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	881	SF	6	\$2,431	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	Cracks in plaster and peeling paint
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #211 (Vacant)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	720	SF	6	\$2,162	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	Wood panels
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	2nd Floor	720	SF	6	\$1,575	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	883	SF	6	\$2,437	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #212 (Vacant)</b>							
	AC Units	2nd Floor	3	EA	6	\$1,487	
	Casework	2nd Floor	26	LF	6	\$657	
	Ceiling - Lay-in	2nd Floor	1,109	SF	6	\$3,330	
	Ceiling - Lay-in	2nd Floor	8	SF	5	\$64	water stain one ceiling tile
	Chalk Board	2nd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	Wood panels
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	2nd Floor	1,115	SF	6	\$2,440	
	Floor - Tile	2nd Floor	2	SF	5	\$12	two damaged tiles
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,118	SF	6	\$3,086	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	Peeling paint
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one entry door

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #213 (Computer Lab)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	11	LF	6	\$278	
	Ceiling - Lay-in	2nd Floor	716	SF	6	\$2,150	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	wood panels
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at door entry
	Floor - Tile	2nd Floor	716	SF	6	\$1,567	
	Lighting - Lay-in	2nd Floor	18	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	883	SF	6	\$2,437	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at door entry
<b>Classroom #214 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	430	SF	6	\$1,291	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	wood panel
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at door entry
	Floor - Tile	2nd Floor	430	SF	6	\$941	
	Lighting - Lay-in	2nd Floor	6	EA	6	\$714	
	Walls - Plaster/Drywall	2nd Floor	618	SF	6	\$1,706	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at door entry
<b>Classroom #215 (Science Lab Level 2)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	20	LF	6	\$505	
	Ceiling - Lay-in	2nd Floor	1,095	SF	6	\$3,288	
	Chalk Board	2nd Floor	48	LF	4	\$4,407	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Wood panel
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Eye Wash Station	2nd Floor	1	EA	6	\$336	
	Floor - Tile	2nd Floor	1,095	SF	6	\$2,396	
	Gas Line	2nd Floor	5	EA	6	\$2,546	
	Lighting - Lay-in	2nd Floor	22	EA	7	\$0	
	Lighting - Terrazzo	2nd Floor	7	SF	7	\$0	at one door entry
	Science Lab Elements	2nd Floor	1,095	SF	6	\$7,422	



**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #215 (Science Lab Level 2)</b>							
	Walls - Plaster/Drywall	2nd Floor	1,119	SF	6	\$3,088	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one door entry
	Work Sink	2nd Floor	3	EA	6	\$1,137	
<b>Classroom #216 (Vacant)</b>							
	AC Units	2nd Floor	3	EA	6	\$1,487	
	Casework	2nd Floor	14	LF	6	\$354	
	Ceiling - Lay-in	2nd Floor	1,185	SF	6	\$3,559	
	Chalk Board	2nd Floor	48	LF	4	\$4,407	
	Doors - Transom Window	2nd Floor	27	SF	6	\$457	wood panels
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at one door entry
	Floor - Tile	2nd Floor	1,185	SF	6	\$2,593	
	Lighting - Lay-in	2nd Floor	33	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,159	SF	6	\$3,199	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one door entry
<b>Classroom #217 (Vacant)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	24	LF	6	\$606	
	Ceiling - Lay-in	2nd Floor	745	SF	6	\$2,237	
	Chalk Board	2nd Floor	26	LF	4	\$2,387	
	Doors - Transom Window	2nd Floor	1	SF	6	\$17	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Wood panel
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at door entry
	Floor - Tile	2nd Floor	745	SF	6	\$1,630	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,034	SF	6	\$2,854	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at door entry
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #218 (Vacant)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	787	SF	6	\$2,363	
	Chalk Board	2nd Floor	8	LF	4	\$734	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #218 (Vacant)</b>							
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	7	SF	7	\$0	at one door entry
	Floor - Wood	2nd Floor	787	SF	6	\$5,548	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	34	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,077	SF	6	\$2,972	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one door entry
<b>Classroom #219 (Vacant)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	3	LF	6	\$76	
	Ceiling - Lay-in	2nd Floor	720	SF	6	\$2,162	
	Chalk Board	2nd Floor	26	LF	4	\$2,387	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	wood panel
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at door entry
	Floor - Tile	2nd Floor	720	SF	6	\$1,575	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	883	SF	6	\$2,437	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at door entry
<b>Classroom #220 (Vacant)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	11	LF	6	\$278	
	Ceiling - Lay-in	2nd Floor	962	SF	6	\$2,889	
	Chalk Board	2nd Floor	26	LF	4	\$2,387	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Only one door
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	962	SF	6	\$6,782	
	Lighting - Lay-in	2nd Floor	18	EA	7	\$0	
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	\$2,763	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #222 (Vacant)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	11	LF	6	\$278	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #222 (Vacant)</b>							
	Ceiling - Lay-in	2nd Floor	972	SF	6	\$2,919	
	Chalk Board	2nd Floor	16	LF	4	\$1,469	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	972	SF	6	\$6,853	
	Lighting - Lay-in	2nd Floor	18	EA	7	\$0	
	Marker Board	2nd Floor	30	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,012	SF	6	\$2,793	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	Peeling paint and plaster under window sill
<b>Classroom #224 (Vacant)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	29	LF	6	\$732	
	Ceiling - Lay-in	2nd Floor	1,078	SF	6	\$3,237	
	Ceiling - Lay-in	2nd Floor	8	SF	4	\$112	one ceiling tile missing
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Wood panel at one entry door
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	2nd Floor	1,085	SF	6	\$7,649	
	Lighting - Lay-in	2nd Floor	22	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,119	SF	6	\$3,088	
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #301 (Regular Classroom)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	720	SF	6	\$2,162	
	Chalk Board	3rd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	Wood panel
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at door entry
	Floor - Wood	3rd Floor	720	SF	6	\$5,076	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	950	SF	6	\$2,622	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #301 (Regular Classroom)</b>							
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at door entry
<b>Classroom #302 (Regular Classroom)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	720	SF	6	\$2,162	
	Chalk Board	3rd Floor	25	LF	4	\$2,295	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	Wood panel
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at door entry
	Floor - Wood	3rd Floor	720	SF	6	\$5,076	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	706	SF	6	\$1,948	
	Walls - Plaster/Drywall	3rd Floor	244	SF	6	\$799	FRP panel
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at door entry
<b>Classroom #303 (Choral Room)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	1,148	SF	7	\$0	Wood frame/glass skylights
	Ceiling - Splined	3rd Floor	383	SF	6	\$312	
	Chalk Board	3rd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	3rd Floor	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,531	SF	6	\$10,793	
	Lighting - Pendent/Surface	3rd Floor	24	EA	6	\$2,973	
	Risers	3rd Floor	224	LF	6	\$5,042	
	Sound System	3rd Floor	1	EA	6	\$1,442	
	Walls - Plaster/Drywall	3rd Floor	1,764	SF	6	\$4,868	Splined panels
<b>Classroom #304 (Regular Classroom)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	720	SF	6	\$2,162	
	Chalk Board	3rd Floor	6	LF	4	\$551	
	Doors - Transom Window	3rd Floor	28	SF	6	\$474	Wood panels
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one door entry
	Floor - Wood	3rd Floor	720	SF	6	\$5,076	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #304 (Regular Classroom)</b>							
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	706	SF	6	\$1,948	
	Walls - Plaster/Drywall	3rd Floor	244	SF	6	\$799	splined panels
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one door entry
<b>Classroom #305 (Band Room)</b>							
	AC Units	3rd Floor	3	EA	6	\$1,487	
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	3rd Floor	1,754	SF	6	\$5,267	
	Chalk Board	3rd Floor	4	LF	4	\$367	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	Wood panel on interior door
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,754	SF	6	\$12,366	
	Instrument Storage Casework	3rd Floor	100	LF	6	\$0	
	Lighting - Lay-in	3rd Floor	24	EA	7	\$0	
	Marker Board	3rd Floor	4	LF	7	\$0	
	Sound System	3rd Floor	1	EA	6	\$1,442	
	Walls - Plaster/Drywall	3rd Floor	1,680	SF	6	\$4,637	
<b>Classroom #306 (Faculty Lounge)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	720	SF	6	\$2,162	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile	3rd Floor	720	SF	6	\$1,575	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	950	SF	6	\$2,622	
	Work Sink	3rd Floor	1	EA	6	\$379	
<b>Classroom #309 (Science Lab Level 3)</b>							
	AC Units	3rd Floor	3	EA	6	\$1,487	
	Ceiling - Lay-in	3rd Floor	1,075	SF	6	\$3,228	
	Chalk Board	3rd Floor	16	LF	4	\$1,469	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #309 (Science Lab Level 3)</b>							
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one door entry
	Floor - Tile	3rd Floor	1,075	SF	6	\$2,352	
	Fume Hood	3rd Floor	1	EA	6	\$816	
	Gas Line	3rd Floor	18	EA	6	\$9,164	
	Lighting - Lay-in	3rd Floor	17	EA	7	\$0	
	Marker Board	3rd Floor	32	LF	7	\$0	
	Science Lab Elements	3rd Floor	1,075	SF	6	\$7,287	
	Science Lab Shower	3rd Floor	1	EA	6	\$379	
	Storage/ Closet	3rd Floor	72	SF	6	\$522	Inside of Prep Room
	Walls - Plaster/Drywall	3rd Floor	1,240	SF	6	\$3,422	
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one door entry
	Work Sink	3rd Floor	9	EA	6	\$3,411	
<b>Classroom #310 (Regular Classroom)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	3rd Floor	720	SF	6	\$2,162	
	Chalk Board	3rd Floor	40	LF	4	\$3,672	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one door entry
	Floor - Wood	3rd Floor	720	SF	6	\$5,076	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	950	SF	6	\$2,622	
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one door entry
<b>Classroom #312 (Science Lab Level 3)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Ceiling - Lay-in	2nd Floor	1,107	SF	6	\$3,324	
	Chalk Board	2nd Floor	50	LF	6	\$1,115	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Eye Wash Station	2nd Floor	1	EA	6	\$336	
	Floor - Terrazzo	2nd Floor	7	SF	7	\$0	at one door entry

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #312 (Science Lab Level 3)</b>							
	Floor - Wood	2nd Floor	1,107	SF	6	\$7,804	
	Gas Line	2nd Floor	5	EA	6	\$2,546	
	Lighting - Lay-in	2nd Floor	22	EA	7	\$0	
	Marker Board	2nd Floor	30	LF	7	\$0	
	Science Lab Elements	2nd Floor	1,107	SF	6	\$7,503	
	Walls - Plaster/Drywall	2nd Floor	1,229	SF	6	\$3,392	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	Missing plaster at door frame
	Walls - Structural Glazed Tile	2nd Floor	26	SF	6	\$82	at one door entry
	Work Sink	2nd Floor	6	EA	6	\$2,274	
<b>Classroom #313 (Science Lab Level 3)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Ceiling - Lay-in	3rd Floor	1,075	SF	6	\$3,228	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	Wood panel at one door
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	3rd Floor	1,075	SF	6	\$2,352	
	Lighting - Lay-in	3rd Floor	33	EA	6	\$3,926	Lens loose
	Science Lab Elements	3rd Floor	1,075	SF	6	\$7,287	
	Walls - Plaster/Drywall	3rd Floor	1,240	SF	6	\$3,422	
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one entry door
	Work Sink	3rd Floor	2	EA	6	\$758	
<b>Classroom #314 (Special Education)</b>							
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	426	SF	6	\$1,279	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	426	SF	6	\$932	
	Lighting - Lay-in	3rd Floor	6	EA	7	\$0	
	Marker Board	3rd Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	770	SF	6	\$2,125	
<b>Classroom #315 (Science Lab Level 3)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #315 (Science Lab Level 3)</b>							
	Ceiling - Lay-in	3rd Floor	1,075	SF	6	\$3,228	
	Doors - Transom Window	3rd Floor	16	SF	6	\$271	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	3rd Floor	1,075	SF	6	\$2,352	
	Gas Line	3rd Floor	5	EA	6	\$2,546	
	Lighting - Lay-in	3rd Floor	31	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Science Lab Elements	3rd Floor	1,075	SF	6	\$7,287	
	Storage/ Closet	3rd Floor	35	SF	6	\$254	
	Walls - Plaster/Drywall	3rd Floor	1,240	SF	6	\$3,422	
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one entry door
	Work Sink	3rd Floor	3	EA	6	\$1,137	
<b>Classroom #316 (Regular Classroom)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	3rd Floor	1,107	SF	6	\$3,324	
	Chalk Board	3rd Floor	50	LF	6	\$1,115	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	Wood panel at one door
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	3rd Floor	1,107	SF	6	\$7,804	
	Lighting - Lay-in	3rd Floor	22	EA	7	\$0	
	Marker Board	3rd Floor	30	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,230	SF	6	\$3,395	
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one entry door
	Work Sink	3rd Floor	2	EA	6	\$758	
<b>Classroom #317 (Regular Classroom)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	704	SF	6	\$2,114	
	Ceiling - Lay-in	3rd Floor	16	SF	5	\$128	water stains on two tiles
	Chalk Board	3rd Floor	50	LF	4	\$4,590	



**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #317 (Regular Classroom)</b>							
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	3rd Floor	720	SF	6	\$5,076	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	950	SF	6	\$2,622	
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #318 (Regular Classroom)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	30	LF	6	\$758	
	Ceiling - Lay-in	3rd Floor	720	SF	6	\$2,162	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	3rd Floor	720	SF	6	\$5,076	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	950	SF	6	\$2,622	
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #319 (Regular Classroom)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	720	SF	6	\$2,162	
	Chalk Board	3rd Floor	50	LF	4	\$4,590	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	Wood panel at one door
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	3rd Floor	720	SF	6	\$5,076	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	950	SF	6	\$2,622	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #319 (Regular Classroom)</b>							
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #320 (Regular Classroom)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	20	LF	6	\$505	
	Ceiling - Lay-in	3rd Floor	800	SF	6	\$2,402	
	Chalk Board	3rd Floor	12	LF	4	\$1,102	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Transom Window	3rd Floor	16	SF	6	\$271	Wood panel at one door
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	3rd Floor	800	SF	6	\$5,640	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,019	SF	6	\$2,812	
	Walls - Plaster/Drywall	3rd Floor	1	SF	5	\$5	Crack in wall
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one entry door
<b>Classroom #322 (Art Room)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	50	LF	6	\$1,263	
	Ceiling - Lay-in	3rd Floor	1,075	SF	6	\$3,228	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Transom Window	3rd Floor	27	SF	6	\$457	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	\$903	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	3rd Floor	1,075	SF	6	\$7,579	
	Lighting - Lay-in	3rd Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,199	SF	6	\$3,309	
	Walls - Plaster/Drywall	3rd Floor	1	SF	5	\$5	Hole in plaster
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one entry door
	Work Sink	3rd Floor	2	EA	6	\$758	
<b>Classroom #324 (Other Instructional Use)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	40	LF	6	\$1,010	
	Ceiling - Lay-in	3rd Floor	1,075	SF	6	\$3,228	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	wood panel at one door

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #324 (Other Instructional Use)</b>							
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Terrazzo	3rd Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	3rd Floor	1,075	SF	6	\$7,579	
	Lighting - Lay-in	3rd Floor	20	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Storage/ Closet	3rd Floor	362	SF	6	\$2,625	Shared between 324, 322
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	\$3,312	
	Walls - Structural Glazed Tile	3rd Floor	26	SF	6	\$82	at one entry door
	Work Sink	3rd Floor	4	EA	6	\$1,516	
<b>Classroom #409 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	25	LF	6	\$631	
	Ceiling - Lay-in	4th Floor	972	SF	6	\$2,919	
	Chalk Board	4th Floor	56	LF	4	\$5,141	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	at one door
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	
	Floor - Tile/Sheet	4th Floor	972	SF	6	\$973	
	Fume Hood	4th Floor	1	EA	6	\$816	
	Lighting - Lay-in	4th Floor	18	EA	7	\$0	
	Science Lab Elements	4th Floor	972	SF	6	\$6,588	
	Walls - Plaster/Drywall	4th Floor	1,086	SF	6	\$2,997	
	Walls - Structural Glazed Tile	4th Floor	26	SF	6	\$82	at one entry door
	Work Sink	4th Floor	1	EA	6	\$379	
<b>Classroom #410 (Regular Classroom)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	20	LF	6	\$505	
	Ceiling - Lay-in	4th Floor	720	SF	6	\$2,162	
	Chalk Board	4th Floor	20	LF	6	\$446	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	wood panel at one door
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	4th Floor	720	SF	6	\$5,076	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #410 (Regular Classroom)</b>							
	Lighting - Lay-in	4th Floor	14	EA	7	\$0	
	Marker Board	4th Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	950	SF	6	\$2,622	
	Walls - Structural Glazed Tile	4th Floor	26	SF	6	\$82	at one entry door
<b>Classroom #412 (Regular Classroom)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	20	LF	6	\$505	
	Ceiling - Lay-in	4th Floor	720	SF	6	\$2,162	
	Chalk Board	4th Floor	20	LF	4	\$1,836	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	wood panel at one door
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	4th Floor	720	SF	6	\$5,076	
	Lighting - Lay-in	4th Floor	14	EA	7	\$0	
	Marker Board	4th Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	950	SF	6	\$2,622	
	Walls - Structural Glazed Tile	4th Floor	6	SF	6	\$19	
<b>Classroom #413 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	5	\$3,652	Not per CPS support standards
	Ceiling - Lay-in	4th Floor	972	SF	6	\$2,919	
	Chalk Board	4th Floor	30	LF	4	\$2,754	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	wood panel at one door
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	at one entry door
	Floor - Tile/Sheet	4th Floor	972	SF	6	\$973	
	Fume Hood	4th Floor	2	EA	6	\$1,631	
	Gas Line	4th Floor	14	EA	6	\$7,128	
	Lighting - Lay-in	4th Floor	18	EA	7	\$0	
	Marker Board	4th Floor	10	LF	7	\$0	
	Science Lab Elements	4th Floor	972	SF	6	\$6,588	
	Science Lab Shower	4th Floor	1	EA	6	\$379	
	Walls - Plaster/Drywall	4th Floor	1,086	SF	6	\$2,997	
	Walls - Structural Glazed Tile	4th Floor	26	SF	6	\$82	at one entry door

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #413 (Science Lab Level 1)</b>							
	Work Sink	4th Floor	10	EA	6	\$3,790	
<b>Classroom #414 (Regular Classroom)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	8	LF	6	\$202	
	Ceiling - Lay-in	4th Floor	598	SF	6	\$1,796	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	wood panel at one door
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	4th Floor	598	SF	6	\$1,308	
	Lighting - Lay-in	4th Floor	11	EA	7	\$0	
	Marker Board	4th Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	910	SF	6	\$2,512	
	Walls - Structural Glazed Tile	4th Floor	26	SF	6	\$82	at one entry door
<b>Classroom #416 (Regular Classroom)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	8	LF	6	\$202	
	Ceiling - Lay-in	4th Floor	598	SF	6	\$1,796	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	wood panel
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	4th Floor	598	SF	6	\$1,308	
	Lighting - Lay-in	4th Floor	11	EA	7	\$0	
	Marker Board	4th Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	910	SF	6	\$2,512	
	Walls - Structural Glazed Tile	4th Floor	6	SF	6	\$19	at one entry door
<b>Classroom #418 (Regular Classroom)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Ceiling - Lay-in	4th Floor	720	SF	6	\$2,162	
	Chalk Board	4th Floor	20	LF	4	\$1,836	
	Doors - Transom Window	4th Floor	8	SF	6	\$135	wood panel at one door
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	4th Floor	720	SF	6	\$5,076	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #418 (Regular Classroom)</b>							
	Lighting - Lay-in	4th Floor	14	EA	7	\$0	
	Marker Board	4th Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	950	SF	6	\$2,622	
	Walls - Structural Glazed Tile	4th Floor	26	SF	6	\$82	at one entry door
<b>Classroom #419 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Ceiling - Lay-in	4th Floor	1,075	SF	6	\$3,228	
	Chalk Board	4th Floor	16	LF	4	\$1,469	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	wood panel at one door
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	4th Floor	1,075	SF	6	\$2,352	
	Gas Line	4th Floor	6	EA	6	\$3,055	
	Lighting - Lay-in	4th Floor	33	EA	7	\$0	
	Walls - Plaster/Drywall	4th Floor	1,330	SF	6	\$3,671	
	Walls - Structural Glazed Tile	4th Floor	26	SF	6	\$82	at one entry door
	Work Sink	4th Floor	3	EA	6	\$1,137	
<b>Classroom #420 (Regular Classroom)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	8	LF	6	\$202	
	Ceiling - Lay-in	4th Floor	720	SF	6	\$2,162	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	wood panel at one door
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	at one entry door
	Floor - Wood	4th Floor	720	SF	6	\$5,076	
	Lighting - Lay-in	4th Floor	14	EA	7	\$0	
	Marker Board	4th Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	950	SF	6	\$2,622	
	Walls - Structural Glazed Tile	4th Floor	26	SF	6	\$82	at one entry door
<b>Classroom #421 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Ceiling - Lay-in	4th Floor	1,075	SF	6	\$3,228	
	Chalk Board	4th Floor	16	LF	4	\$1,469	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #421 (Science Lab Level 1)</b>							
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	wood panel at one door
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Terrazzo	4th Floor	7	SF	7	\$0	at one entry door
	Floor - Tile	4th Floor	1,075	SF	6	\$2,352	
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	32	EA	6	\$16,292	
	Lighting - Lay-in	4th Floor	33	EA	7	\$0	
	Science Lab Elements	4th Floor	1,075	SF	6	\$7,287	
	Science Lab Shower	4th Floor	1	EA	6	\$379	
	Walls - Plaster/Drywall	4th Floor	1,240	SF	6	\$3,422	
	Walls - Structural Glazed Tile	4th Floor	26	SF	6	\$82	at one entry door
	Work Sink	4th Floor	22	EA	6	\$8,338	

**Classrooms Subtotal:**

**\$911,145**

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Plaster/Drywall	200 Nurse's Office	157	SF	6	\$543	
	Ceiling - Plaster/Drywall	200 Nurse's Office	2	SF	5	\$25	Peeling paint
	Doors - Wood Doors inclu hw	200 Nurse's Office	1	EA	6	\$301	
	Floor - Tile	200 Nurse's Office	159	SF	6	\$348	
	Lighting - Pendent/Surface	200 Nurse's Office	2	EA	6	\$248	
	Power Distribution	200 Nurse's Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	200 Nurse's Office	690	SF	6	\$1,904	
	AC Unit	203A Conf. room	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	203A Conf. room	165	SF	6	\$571	
	Ceiling - Plaster/Drywall	203A Conf. room	2	SF	5	\$25	Water stain
	Doors - Transom Window	203A Conf. room	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	203A Conf. room	1	EA	6	\$301	
	Floor - Concrete Epoxy/ Painted	203A Conf. room	167	SF	6	\$88	
	Lighting - Pendent/Surface	203A Conf. room	2	EA	6	\$248	
	Power Distribution	203A Conf. room	4	EA	6	\$8,500	
	Storage/ Closet	203A Conf. room	12	SF	6	\$87	Shelves

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Plaster/Drywall	203A Conf. room	792	SF	6	\$2,186	
	AC Unit	203B office	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	203B office	113	SF	6	\$391	
	Doors - Transom Window	203B office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	203B office	1	EA	6	\$301	
	Floor - Tile	203B office	113	SF	6	\$247	
	Lighting - Pendent/Surface	203B office	1	EA	7	\$0	
	Power Distribution	203B office	4	EA	7	\$0	
	Storage/ Closet	203B office	9	SF	6	\$65	
	Walls - Plaster/Drywall	203B office	549	SF	6	\$1,515	
	AC Unit	203C Counselor Office	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	203C Counselor Office	173	SF	6	\$599	
	Doors - Wood Doors inclu hw	203C Counselor Office	1	EA	6	\$301	
	Floor - Tile	203C Counselor Office	173	SF	6	\$379	
	Lighting - Pendent/Surface	203C Counselor Office	2	EA	7	\$0	
	Power Distribution	203C Counselor Office	12	EA	7	\$0	
	Storage/ Closet	203C Counselor Office	9	SF	6	\$65	
	Walls - Plaster/Drywall	203C Counselor Office	650	SF	6	\$1,794	
	AC Unit	208 Case Manager Office	1	EA	6	\$496	
	Ceiling - Lay-in	208 Case Manager Office	402	SF	6	\$1,207	
	Doors - Transom Window	208 Case Manager Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	208 Case Manager Office	1	EA	6	\$301	
	Floor - Tile	208 Case Manager Office	402	SF	6	\$880	
	Lighting - Lay-in	208 Case Manager Office	6	EA	7	\$0	
	Power Distribution	208 Case Manager Office	7	EA	7	\$0	
	Walls - Plaster/Drywall	208 Case Manager Office	624	SF	6	\$1,722	
	Ceiling - Lay-in	208B office next to Faculty Toilet	111	SF	6	\$333	
	Doors - Transom Window	208B office next to Faculty Toilet	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	208B office next to Faculty Toilet	1	EA	6	\$301	
	Floor - Wood	208B office next to Faculty Toilet	111	SF	6	\$783	
	Lighting - Lay-in	208B office next to Faculty Toilet	2	EA	7	\$0	
	Power Distribution	208B office next to Faculty Toilet	4	EA	7	\$0	
	Walls - Plaster/Drywall	208B office next to Faculty Toilet	470	SF	6	\$1,297	
	Ceiling - Plaster/Drywall	213A Computer Equipment Rm	332	SF	6	\$1,149	
	Doors - Transom Window	213A Computer Equipment Rm	9	SF	6	\$152	Wood panel
	Doors - Wood Doors inclu hw	213A Computer Equipment Rm	1	EA	6	\$301	
	Floor - Tile	213A Computer Equipment Rm	332	SF	6	\$726	



**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Lighting - Lay-in	213A Computer Equipment Rm	5	EA	7	\$0	
	Power Distribution	213A Computer Equipment Rm	6	EA	7	\$0	
	Storage/ Closet	213A Computer Equipment Rm	39	SF	6	\$283	
	Walls - Plaster/Drywall	213A Computer Equipment Rm	822	SF	6	\$2,269	
	Ceiling - Lay-in	223B Office	147	SF	6	\$441	
	Doors - Side-lite	223B Office	8	SF	6	\$134	
	Doors - Side-lite	223B Office	8	SF	6	\$134	
	Doors - Transom Window	223B Office	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	223B Office	1	EA	6	\$301	
	Floor - Tile	223B Office	147	SF	6	\$322	
	Lighting - Pendent/Surface	223B Office	2	EA	7	\$0	
	Power Distribution	223B Office	2	EA	7	\$0	
	Walls - Plaster/Drywall	223B Office	658	SF	6	\$1,816	
	Work Sink	223B Office	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	223D East Gym office	9,147	SF	6	\$31,654	
	Doors - Side-lite	223D East Gym office	40	SF	6	\$669	
	Doors - Transom Window	223D East Gym office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	223D East Gym office	1	EA	6	\$301	
	Floor - Wood	223D East Gym office	149	SF	6	\$1,050	
	Lighting - Pendent/Surface	223D East Gym office	2	EA	7	\$0	
	Power Distribution	223D East Gym office	4	EA	7	\$0	
	Walls - Plaster/Drywall	223D East Gym office	600	SF	6	\$1,656	
	Work Sink	223D East Gym office	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	223F Office	120	SF	6	\$415	
	Doors - Transom Window	223F Office	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	223F Office	1	EA	6	\$301	
	Floor - Wood	223F Office	120	SF	6	\$846	
	Lighting - Pendent/Surface	223F Office	2	EA	6	\$248	
	Power Distribution	223F Office	2	EA	7	\$0	
	Walls - Plaster/Drywall	223F Office	549	SF	6	\$1,515	
	AC Unit	226 Assistant Principal	1	EA	5	\$1,826	Not per CPS support standards
	Ceiling - Lay-in	226 Assistant Principal	364	SF	6	\$1,093	
	Doors - Transom Window	226 Assistant Principal	9	SF	6	\$152	Wood panel
	Doors - Wood Doors inclu hw	226 Assistant Principal	1	EA	6	\$301	
	Floor - Wood	226 Assistant Principal	364	SF	6	\$2,566	
	Lighting - Lay-in	226 Assistant Principal	6	EA	7	\$0	
	Power Distribution	226 Assistant Principal	10	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Plaster/Drywall	226 Assistant Principal	800	SF	6	\$2,208	
	Ceiling - Plaster/Drywall	275 Light and Sound	122	SF	6	\$422	
	Ceiling - Plaster/Drywall	275 Light and Sound	3	SF	5	\$37	Plaster missing
	Doors - Steel Doors incl hw	275 Light and Sound	1	EA	6	\$301	
	Floor - Weight/ Fitness Room Floor Matting	275 Light and Sound	125	SF	6	\$654	
	Lighting - Pendent/Surface	275 Light and Sound	2	EA	7	\$0	
	Power Distribution	275 Light and Sound	6	EA	7	\$0	
	Walls - Plaster/Drywall	275 Light and Sound	428	SF	6	\$1,181	
	Ceiling - Lay-in	2nd Flr West Gym office in Gym	104	SF	6	\$312	
	Doors - Wood Doors inclu hw	2nd Flr West Gym office in Gym	1	EA	6	\$301	
	Floor - Wood	2nd Flr West Gym office in Gym	104	SF	6	\$733	
	Lighting - Lay-in	2nd Flr West Gym office in Gym	2	EA	7	\$0	
	Power Distribution	2nd Flr West Gym office in Gym	4	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Flr West Gym office in Gym	532	SF	6	\$1,468	
	Work Slnk	2nd Flr West Gym office in Gym	1	EA	6	\$508	
	Ceiling - Lay-in	307 Office in Lunchroom	120	SF	6	\$360	
	Doors - Side-lite	307 Office in Lunchroom	40	SF	6	\$669	
	Doors - Wood Doors inclu hw	307 Office in Lunchroom	1	EA	6	\$301	
	Floor - Tile	307 Office in Lunchroom	120	SF	6	\$263	
	Lighting - Lay-in	307 Office in Lunchroom	1	EA	7	\$0	
	Power Distribution	307 Office in Lunchroom	4	EA	7	\$0	
	Walls - Plaster/Drywall	307 Office in Lunchroom	160	SF	6	\$442	
	Walls - Structural Glazed Tile	307 Office in Lunchroom	160	SF	6	\$503	
	AC Unit	308 Office	1	EA	6	\$496	
	Ceiling - Lay-in	308 Office	365	SF	6	\$1,096	
	Doors - Transom Window	308 Office	9	SF	6	\$152	
	Doors - Transom Window	308 Office	9	SF	6	\$152	wood panel
	Doors - Wood Doors inclu hw	308 Office	1	EA	6	\$301	
	Floor - Terrazzo	308 Office	7	SF	7	\$0	at door entry
	Floor - Tile	308 Office	365	SF	6	\$799	
	Lighting - Lay-in	308 Office	6	EA	7	\$0	
	Power Distribution	308 Office	2	EA	7	\$0	
	Walls - Plaster/Drywall	308 Office	800	SF	6	\$2,208	
	Walls - Structural Glazed Tile	308 Office	276	SF	6	\$868	at door entry
	Ceiling - Lay-in	308B Assistant Principal	140	SF	6	\$420	
	Doors - Transom Window	308B Assistant Principal	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	308B Assistant Principal	1	EA	6	\$301	

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Floor - Tile	308B Assistant Principal	140	SF	6	\$306	
	Lighting - Lay-in	308B Assistant Principal	2	EA	7	\$0	
	Power Distribution	308B Assistant Principal	4	EA	7	\$0	
	Walls - Plaster/Drywall	308B Assistant Principal	480	SF	6	\$1,325	
	Ceiling - Lay-in	313A office in 313	170	SF	6	\$511	
	Doors - Side-lite	313A office in 313	30	SF	6	\$502	
	Doors - Wood Doors inclu hw	313A office in 313	1	EA	6	\$301	
	Floor - Tile	313A office in 313	170	SF	6	\$372	
	Lighting - Lay-in	313A office in 313	3	EA	7	\$0	
	Power Distribution	313A office in 313	4	EA	7	\$0	
	Walls - Plaster/Drywall	313A office in 313	480	SF	6	\$1,325	
	Work Slnk	313A office in 313	1	EA	6	\$508	
	Ceiling - Lay-in	315A Stor./Office in 315	170	SF	6	\$511	
	Doors - Side-lite	315A Stor./Office in 315	30	SF	6	\$502	
	Doors - Wood Doors inclu hw	315A Stor./Office in 315	1	EA	6	\$301	
	Floor - Tile	315A Stor./Office in 315	170	SF	6	\$372	
	Lighting - Lay-in	315A Stor./Office in 315	3	EA	7	\$0	
	Power Distribution	315A Stor./Office in 315	4	EA	7	\$0	
	Walls - Plaster/Drywall	315A Stor./Office in 315	480	SF	6	\$1,325	
	Work Slnk	315A Stor./Office in 315	2	EA	6	\$1,016	
	AC Unit	Rm 103A- Engineer Office	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	Rm 103A- Engineer Office	138	SF	6	\$478	
	Doors - Side-lite	Rm 103A- Engineer Office	24	SF	6	\$401	
	Doors - Transom Window	Rm 103A- Engineer Office	24	SF	6	\$406	
	Doors - Wood Doors inclu hw	Rm 103A- Engineer Office	1	EA	6	\$301	
	Floor - Tile	Rm 103A- Engineer Office	138	SF	6	\$302	
	Lighting - Pendent/Surface	Rm 103A- Engineer Office	2	EA	7	\$0	
	Power Distribution	Rm 103A- Engineer Office	4	EA	7	\$0	
	Storage/ Closet	Rm 103A- Engineer Office	12	SF	6	\$87	
	Walls - Plaster/Drywall	Rm 103A- Engineer Office	534	SF	6	\$1,474	
	AC Unit	Rm 103B- Asst Engineer Office	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	Rm 103B- Asst Engineer Office	112	SF	6	\$388	
	Doors - Side-lite	Rm 103B- Asst Engineer Office	24	SF	6	\$401	
	Doors - Transom Window	Rm 103B- Asst Engineer Office	24	SF	6	\$406	
	Doors - Wood Doors inclu hw	Rm 103B- Asst Engineer Office	1	EA	6	\$301	
	Floor - Tile	Rm 103B- Asst Engineer Office	112	SF	6	\$245	
	Lighting - Pendent/Surface	Rm 103B- Asst Engineer Office	2	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Power Distribution	Rm 103B- Asst Engineer Office	4	EA	7	\$0	
	Storage/ Closet	Rm 103B- Asst Engineer Office	12	SF	6	\$87	
	Walls - Plaster/Drywall	Rm 103B- Asst Engineer Office	522	SF	6	\$1,441	
	Walls - Plaster/Drywall	Rm 103B- Asst Engineer Office	12	SF	5	\$61	water damage
	Ceiling - Lay-in	Rm 108- Security Office- 1st flr	134	SF	6	\$402	
	Doors - Transom Window	Rm 108- Security Office- 1st flr	9	SF	6	\$152	
	Doors - Transom Window	Rm 108- Security Office- 1st flr	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	Rm 108- Security Office- 1st flr	1	EA	6	\$301	
	Floor - Tile	Rm 108- Security Office- 1st flr	134	SF	6	\$293	
	Lighting - Lay-in	Rm 108- Security Office- 1st flr	2	EA	7	\$0	
	Power Distribution	Rm 108- Security Office- 1st flr	4	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 108- Security Office- 1st flr	423	SF	6	\$1,167	
	AC Unit	Rm 109- Counselors Office- 1st flr	1	EA	6	\$496	
	Ceiling - Lay-in	Rm 109- Counselors Office- 1st flr	223	SF	6	\$670	
	Doors - Transom Window	Rm 109- Counselors Office- 1st flr	9	SF	6	\$152	
	Doors - Transom Window	Rm 109- Counselors Office- 1st flr	9	SF	6	\$152	wood panel
	Doors - Wood Doors inclu hw	Rm 109- Counselors Office- 1st flr	1	EA	6	\$301	
	Floor - Carpet	Rm 109- Counselors Office- 1st flr	223	SF	6	\$475	
	Floor - Terrazzo	Rm 109- Counselors Office- 1st flr	7	SF	6	\$15	at door entry
	Lighting - Lay-in	Rm 109- Counselors Office- 1st flr	4	EA	7	\$0	
	Power Distribution	Rm 109- Counselors Office- 1st flr	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	Rm 109- Counselors Office- 1st flr	307	SF	6	\$847	
	Walls - Structural Glazed Tile	Rm 109- Counselors Office- 1st flr	26	SF	6	\$82	at door entry
	Ceiling - Lay-in	Rm 109A- Counselor- 1st flr	100	SF	6	\$300	
	Doors - Side-lite	Rm 109A- Counselor- 1st flr	20	SF	6	\$334	
	Doors - Transom Window	Rm 109A- Counselor- 1st flr	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	Rm 109A- Counselor- 1st flr	2	EA	6	\$602	
	Floor - Carpet	Rm 109A- Counselor- 1st flr	100	SF	6	\$213	
	Lighting - Lay-in	Rm 109A- Counselor- 1st flr	3	EA	7	\$0	
	Power Distribution	Rm 109A- Counselor- 1st flr	2	EA	7	\$0	
	Walls - Metal Panel	Rm 109A- Counselor- 1st flr	184	SF	6	\$1,373	wood partition wall
	Walls - Plaster/Drywall	Rm 109A- Counselor- 1st flr	220	SF	6	\$607	
	Ceiling - Lay-in	Rm 109B- Counselor- 1st flr	167	SF	6	\$502	
	Doors - Wood Doors inclu hw	Rm 109B- Counselor- 1st flr	1	EA	6	\$301	
	Floor - Carpet	Rm 109B- Counselor- 1st flr	167	SF	6	\$356	
	Lighting - Lay-in	Rm 109B- Counselor- 1st flr	2	EA	7	\$0	
	Power Distribution	Rm 109B- Counselor- 1st flr	2	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Metal Panel	Rm 109B- Counselor- 1st flr	208	SF	6	\$1,553	wood partition wall
	Walls - Plaster/Drywall	Rm 109B- Counselor- 1st flr	250	SF	6	\$690	
	Ceiling - Lay-in	Rm 109C- Counselor- 1st flr	107	SF	6	\$321	
	Doors - Side-lite	Rm 109C- Counselor- 1st flr	20	SF	6	\$334	
	Doors - Wood Doors inclu hw	Rm 109C- Counselor- 1st flr	1	EA	6	\$301	
	Floor - Carpet	Rm 109C- Counselor- 1st flr	107	SF	6	\$228	
	Lighting - Lay-in	Rm 109C- Counselor- 1st flr	3	EA	7	\$0	
	Power Distribution	Rm 109C- Counselor- 1st flr	2	EA	7	\$0	
	Walls - Metal Panel	Rm 109C- Counselor- 1st flr	184	SF	6	\$1,373	wood partition wall
	Walls - Plaster/Drywall	Rm 109C- Counselor- 1st flr	220	SF	6	\$607	
	Ceiling - Lay-in	Rm 109D- Counselor- 1st flr	120	SF	6	\$360	
	Doors - Side-lite	Rm 109D- Counselor- 1st flr	20	SF	6	\$334	
	Doors - Wood Doors inclu hw	Rm 109D- Counselor- 1st flr	1	EA	6	\$301	
	Floor - Carpet	Rm 109D- Counselor- 1st flr	120	SF	6	\$256	
	Lighting - Lay-in	Rm 109D- Counselor- 1st flr	2	EA	7	\$0	
	Power Distribution	Rm 109D- Counselor- 1st flr	2	EA	7	\$0	
	Walls - Metal Panel	Rm 109D- Counselor- 1st flr	184	SF	6	\$1,373	wood partition wall
	Walls - Plaster/Drywall	Rm 109D- Counselor- 1st flr	220	SF	6	\$607	
	AC Unit	Rm 110- Student Services	2	EA	5	\$3,652	Not per CPS support standards
	Ceiling - Lay-in	Rm 110- Student Services	724	SF	6	\$2,174	
	Doors - Transom Window	Rm 110- Student Services	9	SF	6	\$152	wood panel at door
	Doors - Transom Window	Rm 110- Student Services	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	Rm 110- Student Services	2	EA	6	\$602	
	Floor - Terrazzo	Rm 110- Student Services	7	SF	7	\$0	at one door reentry
	Floor - Wood	Rm 110- Student Services	724	SF	6	\$5,104	
	Lighting - Lay-in	Rm 110- Student Services	11	EA	7	\$0	
	Power Distribution	Rm 110- Student Services	10	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 110- Student Services	1,104	SF	6	\$3,047	
	Walls - Plaster/Drywall	Rm 110- Student Services	2	SF	5	\$10	peeling
	Walls - Structural Glazed Tile	Rm 110- Student Services	26	SF	6	\$82	at one door entry
	Ceiling - Lay-in	Rm 110A- Dean's Office	169	SF	6	\$508	
	Doors - Side-lite	Rm 110A- Dean's Office	13	SF	6	\$217	
	Doors - Wood Doors inclu hw	Rm 110A- Dean's Office	1	EA	6	\$301	
	Floor - Wood	Rm 110A- Dean's Office	169	SF	6	\$1,191	
	Lighting - Lay-in	Rm 110A- Dean's Office	3	EA	7	\$0	
	Power Distribution	Rm 110A- Dean's Office	4	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 110A- Dean's Office	472	SF	6	\$1,303	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	AC Unit	Rm 111- Discipline office- 1st flr	1	EA	6	\$496	
	Ceiling - Lay-in	Rm 111- Discipline office- 1st flr	473	SF	6	\$1,420	
	Doors - Transom Window	Rm 111- Discipline office- 1st flr	9	SF	6	\$152	wood panel at one door
	Doors - Transom Window	Rm 111- Discipline office- 1st flr	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	Rm 111- Discipline office- 1st flr	2	EA	6	\$602	
	Floor - Carpet	Rm 111- Discipline office- 1st flr	766	SF	6	\$1,632	
	Floor - Terrazzo	Rm 111- Discipline office- 1st flr	7	SF	7	\$0	at one door entry
	Lighting - Lay-in	Rm 111- Discipline office- 1st flr	7	EA	7	\$0	
	Power Distribution	Rm 111- Discipline office- 1st flr	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	Rm 111- Discipline office- 1st flr	600	SF	6	\$1,656	
	Walls - Structural Glazed Tile	Rm 111- Discipline office- 1st flr	26	SF	6	\$82	at one door entry
	Ceiling - Lay-in	Rm 111A- Counselor Office- 1st Flr	120	SF	6	\$360	
	Doors - Side-lite	Rm 111A- Counselor Office- 1st Flr	22	SF	6	\$368	
	Doors - Wood Doors inclu hw	Rm 111A- Counselor Office- 1st Flr	1	EA	6	\$301	
	Floor - Carpet	Rm 111A- Counselor Office- 1st Flr	120	SF	6	\$256	
	Lighting - Lay-in	Rm 111A- Counselor Office- 1st Flr	3	EA	7	\$0	
	Power Distribution	Rm 111A- Counselor Office- 1st Flr	2	EA	7	\$0	
	Walls - Metal Panel	Rm 111A- Counselor Office- 1st Flr	184	SF	6	\$1,373	wood partition wall
	Walls - Plaster/Drywall	Rm 111A- Counselor Office- 1st Flr	230	SF	6	\$635	
	Ceiling - Lay-in	Rm 111B- Asst Principal- 1st flr	120	SF	6	\$360	
	Doors - Side-lite	Rm 111B- Asst Principal- 1st flr	22	SF	6	\$368	
	Doors - Wood Doors inclu hw	Rm 111B- Asst Principal- 1st flr	1	EA	6	\$301	
	Floor - Carpet	Rm 111B- Asst Principal- 1st flr	120	SF	6	\$256	
	Lighting - Lay-in	Rm 111B- Asst Principal- 1st flr	4	EA	7	\$0	
	Power Distribution	Rm 111B- Asst Principal- 1st flr	2	EA	7	\$0	
	Walls - Metal Panel	Rm 111B- Asst Principal- 1st flr	184	SF	6	\$1,373	wood partition walls
	Walls - Plaster/Drywall	Rm 111B- Asst Principal- 1st flr	230	SF	6	\$635	
	AC Unit	Rm 112- Community Room- 1st flr	2	EA	6	\$991	
	Ceiling - Lay-in	Rm 112- Community Room- 1st flr	815	SF	6	\$2,447	
	Doors - Transom Window	Rm 112- Community Room- 1st flr	9	SF	6	\$152	wood panel at door
	Doors - Transom Window	Rm 112- Community Room- 1st flr	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	Rm 112- Community Room- 1st flr	2	EA	6	\$602	
	Floor - Terrazzo	Rm 112- Community Room- 1st flr	7	SF	7	\$0	at one door entry
	Floor - Wood	Rm 112- Community Room- 1st flr	815	SF	6	\$5,746	
	Lighting - Pendant/Surface	Rm 112- Community Room- 1st flr	14	EA	7	\$0	
	Power Distribution	Rm 112- Community Room- 1st flr	8	EA	7	\$0	
	Storage/ Closet	Rm 112- Community Room- 1st flr	23	SF	6	\$167	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Plaster/Drywall	Rm 112- Community Room- 1st flr	1,380	SF	6	\$3,809	
	Walls - Structural Glazed Tile	Rm 112- Community Room- 1st flr	26	SF	6	\$82	at one door entry
	AC Unit	Rm 113- Main Office- 1st Flr	1	EA	6	\$496	
	Ceiling - Lay-in	Rm 113- Main Office- 1st Flr	242	SF	6	\$727	
	Ceiling - Splined	Rm 113- Main Office- 1st Flr	330	SF	6	\$269	
	Doors - Side-lite	Rm 113- Main Office- 1st Flr	28	SF	6	\$468	
	Doors - Transom Window	Rm 113- Main Office- 1st Flr	34	SF	6	\$576	
	Doors - Wood Doors inclu hw	Rm 113- Main Office- 1st Flr	2	EA	6	\$602	
	Floor - Carpet	Rm 113- Main Office- 1st Flr	310	SF	6	\$661	
	Floor - Tile	Rm 113- Main Office- 1st Flr	262	SF	6	\$573	
	Lighting - Lay-in	Rm 113- Main Office- 1st Flr	12	EA	7	\$0	
	Lighting - Pendent/Surface	Rm 113- Main Office- 1st Flr	3	EA	7	\$0	
	Power Distribution	Rm 113- Main Office- 1st Flr	8	EA	7	\$0	
	Storage/ Closet	Rm 113- Main Office- 1st Flr	5	SF	6	\$36	
	Walls - Plaster/Drywall	Rm 113- Main Office- 1st Flr	1,214	SF	6	\$3,351	
	Ceiling - Lay-in	Rm 113A- Office- 1st Flr	107	SF	6	\$321	
	Doors - Side-lite	Rm 113A- Office- 1st Flr	23	SF	6	\$384	
	Doors - Wood Doors inclu hw	Rm 113A- Office- 1st Flr	1	EA	6	\$301	
	Floor - Carpet	Rm 113A- Office- 1st Flr	107	SF	6	\$228	
	Lighting - Lay-in	Rm 113A- Office- 1st Flr	2	EA	7	\$0	
	Power Distribution	Rm 113A- Office- 1st Flr	4	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 113A- Office- 1st Flr	420	SF	6	\$1,159	
	AC Unit	Rm 113D- Principal- 1st Flr	1	EA	6	\$496	
	Ceiling - Lay-in	Rm 113D- Principal- 1st Flr	309	SF	6	\$928	
	Doors - Side-lite	Rm 113D- Principal- 1st Flr	14	SF	6	\$234	
	Doors - Transom Window	Rm 113D- Principal- 1st Flr	25	SF	6	\$423	
	Doors - Wood Doors inclu hw	Rm 113D- Principal- 1st Flr	2	EA	6	\$602	
	Floor - Carpet	Rm 113D- Principal- 1st Flr	309	SF	6	\$658	
	Lighting - Lay-in	Rm 113D- Principal- 1st Flr	6	EA	7	\$0	
	Power Distribution	Rm 113D- Principal- 1st Flr	6	EA	7	\$0	
	Storage/ Closet	Rm 113D- Principal- 1st Flr	23	SF	6	\$167	
	Walls - Plaster/Drywall	Rm 113D- Principal- 1st Flr	780	SF	6	\$2,153	
	Ceiling - Lay-in	Rm 114B- Test Coordinators Office- 1st flr	144	SF	6	\$432	
	Doors - Side-lite	Rm 114B- Test Coordinators Office- 1st flr	20	SF	6	\$334	
	Doors - Transom Window	Rm 114B- Test Coordinators Office- 1st flr	27	SF	6	\$457	One transom window and two transom borrowed lites



## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Doors - Wood Doors inclu hw	Rm 114B- Test Coordinators Office- 1st flr	1	EA	6	\$301	
	Floor - Tile	Rm 114B- Test Coordinators Office- 1st flr	144	SF	6	\$315	
	Lighting - Lay-in	Rm 114B- Test Coordinators Office- 1st flr	1	EA	7	\$0	
	Power Distribution	Rm 114B- Test Coordinators Office- 1st flr	2	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 114B- Test Coordinators Office- 1st flr	475	SF	6	\$1,311	
	AC Unit	Rm- 115A- Business Manager Office	1	EA	6	\$496	
	Ceiling - Lay-in	Rm- 115A- Business Manager Office	263	SF	6	\$790	
	Doors - Wood Doors inclu hw	Rm- 115A- Business Manager Office	1	EA	6	\$301	
	Floor - Tile	Rm- 115A- Business Manager Office	263	SF	6	\$575	
	Lighting - Lay-in	Rm- 115A- Business Manager Office	4	EA	7	\$0	
	Power Distribution	Rm- 115A- Business Manager Office	4	EA	7	\$0	
	Walls - Plaster/Drywall	Rm- 115A- Business Manager Office	650	SF	6	\$1,794	
	Walls - Plaster/Drywall	Rm- 115A- Business Manager Office	4	SF	5	\$20	crack
	Work Slnk	Rm- 115A- Business Manager Office	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	Rm 121B- PE Office	188	SF	6	\$651	
	Doors - Wood Doors inclu hw	Rm 121B- PE Office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Rm 121B- PE Office	188	SF	6	\$398	
	Lighting - Pendent/Surface	Rm 121B- PE Office	2	EA	7	\$0	
	Power Distribution	Rm 121B- PE Office	4	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 121B- PE Office	361	SF	6	\$996	
	Walls - Structural Glazed Tile	Rm 121B- PE Office	361	SF	6	\$1,136	
	Ceiling - Splined	Rm 123A- Pool Office	58	SF	6	\$47	
	Doors - Side-lite	Rm 123A- Pool Office	41	SF	6	\$685	
	Floor - Tile Ceramic/ Porcelain	Rm 123A- Pool Office	58	SF	6	\$123	
	Power Distribution	Rm 123A- Pool Office	2	EA	7	\$0	
	Walls - Structural Glazed Tile	Rm 123A- Pool Office	200	SF	6	\$629	
	Ceiling - Lay-in	Rm 125A- PE Office	249	SF	6	\$748	
	Doors - Wood Doors inclu hw	Rm 125A- PE Office	1	EA	6	\$301	
	Floor - Tile	Rm 125A- PE Office	249	SF	6	\$545	
	Lighting - Lay-in	Rm 125A- PE Office	4	EA	7	\$0	
	Power Distribution	Rm 125A- PE Office	4	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 125A- PE Office	667	SF	6	\$1,841	
	AC Unit	Rm 126- Computer Dept Workroom	1	EA	6	\$496	
	Ceiling - Lay-in	Rm 126- Computer Dept Workroom	494	SF	6	\$1,483	



## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Doors - Wood Doors inclu hw	Rm 126- Computer Dept Workroom	1	EA	6	\$301	
	Floor - Tile	Rm 126- Computer Dept Workroom	494	SF	5	\$2,218	cracked VCT throughout
	Lighting - Pendent/Surface	Rm 126- Computer Dept Workroom	12	EA	7	\$0	
	Power Distribution	Rm 126- Computer Dept Workroom	8	EA	7	\$0	
	Storage/ Closet	Rm 126- Computer Dept Workroom	84	SF	6	\$609	
	Walls - Plaster/Drywall	Rm 126- Computer Dept Workroom	885	SF	6	\$2,443	
	Work Slnk	Rm 126- Computer Dept Workroom	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	Rm 126A Technology Director's Office	90	SF	6	\$311	
	Doors - Side-lite	Rm 126A Technology Director's Office	10	SF	6	\$167	
	Doors - Transom Window	Rm 126A Technology Director's Office	21	SF	6	\$356	
	Doors - Wood Doors inclu hw	Rm 126A Technology Director's Office	1	EA	6	\$301	
	Floor - Tile	Rm 126A Technology Director's Office	90	SF	6	\$197	
	Lighting - Pendent/Surface	Rm 126A Technology Director's Office	1	EA	7	\$0	
	Power Distribution	Rm 126A Technology Director's Office	4	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 126A Technology Director's Office	326	SF	6	\$900	
	AC Unit	Rm 126D- Copy/Workroom	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	Rm 126D- Copy/Workroom	497	SF	6	\$1,720	
	Doors - Transom Window	Rm 126D- Copy/Workroom	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	Rm 126D- Copy/Workroom	1	EA	6	\$301	
	Floor - Tile	Rm 126D- Copy/Workroom	497	SF	5	\$2,232	cracked throughout
	Lighting - Pendent/Surface	Rm 126D- Copy/Workroom	21	EA	7	\$0	
	Power Distribution	Rm 126D- Copy/Workroom	8	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 126D- Copy/Workroom	982	SF	6	\$2,710	
	Ceiling - Plaster/Drywall	Rm 127- Yearbook office	696	SF	6	\$2,409	
	Doors - Transom Window	Rm 127- Yearbook office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	Rm 127- Yearbook office	1	EA	6	\$301	
	Floor - Concrete	Rm 127- Yearbook office	125	SF	5	\$215	missing ceramic tile
	Floor - Tile Ceramic/ Porcelain	Rm 127- Yearbook office	571	SF	6	\$1,208	
	Lighting - Pendent/Surface	Rm 127- Yearbook office	8	EA	7	\$0	
	Power Distribution	Rm 127- Yearbook office	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	Rm 127- Yearbook office	1,462	SF	6	\$4,035	
	Walls - Structural Glazed Tile	Rm 127- Yearbook office	594	SF	6	\$1,869	
	Ceiling - Exposed	Rm B7B- Basement Laundry room	488	SF	6	\$726	
	Doors - Wood Doors inclu hw	Rm B7B- Basement Laundry room	2	EA	6	\$602	
	Floor - Concrete	Rm B7B- Basement Laundry room	488	SF	6	\$258	
	Lighting - Pendent/Surface	Rm B7B- Basement Laundry room	8	EA	7	\$0	
	Power Distribution	Rm B7B- Basement Laundry room	6	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Plaster/Drywall	Rm B7B- Basement Laundry room	710	SF	6	\$1,960	
	Walls - Plaster/Drywall	Rm B7B- Basement Laundry room	6	SF	5	\$31	crack
	Ceiling - Exposed	Rm B9A- Basement Custodial WkRm	1,186	SF	6	\$1,764	
	Ceiling - Exposed	Rm B9A- Basement Custodial WkRm	15	SF	5	\$58	cracked
	Doors - Wood Doors inclu hw	Rm B9A- Basement Custodial WkRm	1	EA	6	\$301	
	Floor - Concrete	Rm B9A- Basement Custodial WkRm	1,201	SF	6	\$635	
	Lighting - Pendent/Surface	Rm B9A- Basement Custodial WkRm	8	EA	7	\$0	
	Power Distribution	Rm B9A- Basement Custodial WkRm	12	EA	7	\$0	
	Storage/ Closet	Rm B9A- Basement Custodial WkRm	117	SF	6	\$848	
	Walls - Plaster/Drywall	Rm B9A- Basement Custodial WkRm	1,148	SF	6	\$3,168	
	Walls - Plaster/Drywall	Rm B9A- Basement Custodial WkRm	6	SF	5	\$31	cracked
	Ceiling - Plaster/Drywall	Room 408, North book storage	180	SF	6	\$623	
	Doors - Transom Window	Room 408, North book storage	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	Room 408, North book storage	1	EA	6	\$301	
	Floor - Wood	Room 408, North book storage	180	SF	6	\$1,269	
	Lighting - Pendent/Surface	Room 408, North book storage	4	EA	7	\$0	
	Walls - Plaster/Drywall	Room 408, North book storage	560	SF	6	\$1,546	
	Ceiling - Lay-in	Room 419A	143	SF	6	\$429	
	Doors - Side-lite	Room 419A	30	SF	6	\$502	
	Doors - Wood Doors inclu hw	Room 419A	1	EA	6	\$301	
	Floor - Tile	Room 419A	143	SF	6	\$313	
	Lighting - Lay-in	Room 419A	2	EA	7	\$0	
	Walls - Plaster/Drywall	Room 419A	360	SF	6	\$994	
	Work Sink	Room 419A	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	Room 419B	70	SF	6	\$242	
	Doors - Steel Doors incl hw	Room 419B	1	EA	6	\$301	
	Floor - Tile	Room 419B	70	SF	6	\$153	
	Lighting - Pendent/Surface	Room 419B	1	EA	7	\$0	
	Power Distribution	Room 419B	2	EA	7	\$0	
	Walls - Plaster/Drywall	Room 419B	170	SF	6	\$469	
	Work Sink	Room 419B	1	EA	6	\$508	
	Ceiling - Lay-in	Room 421A	212	SF	6	\$637	
	Doors - Side-lite	Room 421A	6	SF	6	\$100	
	Doors - Wood Doors inclu hw	Room 421A	1	EA	6	\$301	
	Floor - Tile	Room 421A	212	SF	6	\$464	
	Lighting - Lay-in	Room 421A	4	EA	7	\$0	
	Walls - Plaster/Drywall	Room 421A	440	SF	6	\$1,214	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Work Slnk	Room 421A	2	EA	6	\$1,016	
<b>Auditorium &amp; Theater</b>							
	Balcony Seating	1st Floor	232	EA	6	\$40,349	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	5	\$630	damaged plaster
	Ceiling - Plaster/Drywall	1st Floor	2,366	SF	6	\$19,725	
	Ceiling - Splined	1st Floor	4,035	SF	6	\$3,289	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	16	EA	6	\$4,816	
	Floor - Carpet	1st Floor	4,035	SF	6	\$8,597	
	Floor - Carpet	1st Floor	1,286	SF	5	\$7,558	balcony floor is pulling, worn & stained
	Floor - Concrete Epoxy/ Painted	1st Floor	97	SF	6	\$51	projection room on balcony
	Floor - Terrazzo	1st Floor	206	SF	7	\$0	side stage halls
	Floor - Tile	1st Floor	797	SF	6	\$1,744	floor under main level seats
	Lighting - Chandelier, Incandescent	1st Floor	10	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	49	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	18	EA	7	\$0	
	Main Floor Seating	1st Floor	420	EA	6	\$73,045	
	Sound System	1st Floor	1	EA	6	\$10,721	
	Stage	1st Floor	940	SF	6	\$5,431	
	Stage Curtain	1st Floor	8	EA	6	\$0	
	Stage Lighting System	1st Floor	1	EA	6	\$8,077	
	Stage-Stairs - Wood	1st Floor	8	LF	6	\$94	
	Stairs - Terrazzo	1st Floor	8	LF	6	\$61	
	Walls - Plaster/Drywall	1st Floor	8,722	SF	6	\$41,533	
	Walls - Plaster/Drywall	1st Floor	25	SF	5	\$282	peeling paint (in side stage hallway) & cracks on projection room wall (inside & out)
	Walls - Tile Ceramic/ Porcelain	1st Floor	386	SF	6	\$872	marble 2' high around base of wall
<b>Gymnasia</b>							
	Bleacher Seating	221/223 West Gym Boys	56	EA	6	\$1,621	
	Bleacher Seating	221/223 West Gym Boys	55	EA	5	\$2,797	Wall anchors are not secured, seating is pulling away from wall
	Ceiling - Lay-in	221/223 West Gym Boys	5,982	SF	6	\$17,964	
	Doors - Wood Doors inclu hw	221/223 West Gym Boys	4	EA	6	\$1,204	
	Floor - Wood	221/223 West Gym Boys	5,982	SF	6	\$42,173	
	Lighting - Metal Halide/ High Pressure Sodium	221/223 West Gym Boys	18	EA	7	\$0	
	Scoreboards	221/223 West Gym Boys	1	EA	6	\$2,244	
	Sound System	221/223 West Gym Boys	1	EA	6	\$41,654	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Gymnasia</b>							
	Storage/ Closet	221/223 West Gym Boys	47	SF	6	\$341	
	Walls - Structural Glazed Tile	221/223 West Gym Boys	7,916	SF	6	\$24,904	
	Ceiling - Lay-in	225 East Gym Girls	5,995	SF	6	\$18,003	
	Doors - Transom Window	225 East Gym Girls	30	SF	6	\$508	Wood panels
	Doors - Wood Doors inclu hw	225 East Gym Girls	4	EA	6	\$1,204	
	Floor - Wood	225 East Gym Girls	5,995	SF	7	\$0	
	Lighting - Metal Halide/ High Pressure Sodium	225 East Gym Girls	18	EA	7	\$0	
	Scoreboards	225 East Gym Girls	1	EA	6	\$2,244	
	Sound System	225 East Gym Girls	1	EA	6	\$41,654	
	Storage/ Closet	225 East Gym Girls	47	SF	6	\$341	
	Walls - Structural Glazed Tile	225 East Gym Girls	7,944	SF	6	\$24,992	
	Ceiling - Lay-in	323 Small Gym	1,529	SF	6	\$4,592	
	Doors - Transom Window	323 Small Gym	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	323 Small Gym	2	EA	6	\$602	
	Floor - Sport Flooring	323 Small Gym	1,529	SF	7	\$0	
	Lighting - Pendent/Surface	323 Small Gym	12	EA	7	\$0	
	Storage/ Closet	323 Small Gym	172	SF	6	\$1,247	
	Walls - Plaster/Drywall	323 Small Gym	6	SF	5	\$31	Peeling paint/damaged at the window
	Walls - Plaster/Drywall	323 Small Gym	1,689	SF	6	\$4,661	
<b>Kitchen</b>							
	Ceiling - Plaster/Drywall	307 Lunchroom/Serving Line 307B	783	SF	6	\$2,710	
	Doors - Wood Doors inclu hw	307 Lunchroom/Serving Line 307B	2	EA	6	\$602	
	Floor - Tile	307 Lunchroom/Serving Line 307B	1,083	SF	6	\$2,369	
	Lighting - Pendent/Surface	307 Lunchroom/Serving Line 307B	45	EA	7	\$0	
	Serving Line	307 Lunchroom/Serving Line 307B	120	LF	6	\$7,142	
	Walls - Plaster/Drywall	307 Lunchroom/Serving Line 307B	930	SF	5	\$7,048	
	Walls - Structural Glazed Tile	307 Lunchroom/Serving Line 307B	930	SF	6	\$2,926	
	Ceiling - Plaster/Drywall	307A Kitchen	740	SF	6	\$2,561	
	Doors - Transom Window	307A Kitchen	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	307A Kitchen	1	EA	6	\$301	
	Floor - Tile	307A Kitchen	740	SF	6	\$1,619	
	Lighting - Pendent/Surface	307A Kitchen	12	EA	7	\$0	
	Storage/ Closet	307A Kitchen	32	SF	6	\$232	
	Walls - Plaster/Drywall	307A Kitchen	760	SF	6	\$2,098	
	Walls - Structural Glazed Tile	307A Kitchen	760	SF	6	\$2,391	
	Ceiling - Plaster/Drywall	307C Kitchen	470	SF	6	\$1,626	
	Doors - Transom Window	307C Kitchen	9	SF	6	\$152	

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Kitchen</b>							
	Floor - Tile	307C Kitchen	470	SF	6	\$1,028	
	Lighting - Pendent/Surface	307C Kitchen	4	EA	7	\$0	
	Walls - Structural Glazed Tile	307C Kitchen	1,020	SF	6	\$3,209	
	Ceiling - Plaster/Drywall	307F Bakery	236	SF	6	\$817	
	Doors - Transom Window	307F Bakery	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	307F Bakery	1	EA	6	\$301	
	Floor - Terrazzo	307F Bakery	276	SF	7	\$0	
	Lighting - Pendent/Surface	307F Bakery	4	EA	7	\$0	
	Walls - Structural Glazed Tile	307F Bakery	880	SF	6	\$2,768	
<b>Library</b>							
	AC Unit	1st floor Room 115	5	EA	5	\$9,129	Not per CPS support standards
	Casework	1st floor Room 115	104	LF	6	\$2,626	
	Ceiling - Lay-in	1st floor Room 115	2,001	SF	6	\$6,009	
	Doors - Wood Doors inclu hw	1st floor Room 115	2	EA	6	\$602	
	Floor - Tile	1st floor Room 115	2,001	SF	6	\$4,378	
	Lighting - Lay-in	1st floor Room 115	57	EA	7	\$0	
	Storage/ Closet	1st floor Room 115	469	SF	6	\$3,400	
	Walls - Metal Panel	1st floor Room 115	1,802	SF	6	\$13,451	Wood Panel
	Walls - Plaster/Drywall	1st floor Room 115	600	SF	6	\$1,656	Spline
<b>Locker/Shower Room</b>							
	Accessories	1st Fl, Staff Locker room (next to engineer office)	250	SF	6	\$980	
	Ceiling - Plaster/ Drywall	1st Fl, Staff Locker room (next to engineer office)	250	SF	6	\$865	
	Doors - Transom Window	1st Fl, Staff Locker room (next to engineer office)	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Fl, Staff Locker room (next to engineer office)	2	EA	6	\$602	bathroom door has 1 cracked piece of glazing
	Floor Drain	1st Fl, Staff Locker room (next to engineer office)	1	EA	6	\$1,059	
	Floor - Concrete Epoxy/ Painted	1st Fl, Staff Locker room (next to engineer office)	174	SF	5	\$299	needs a new coat/ peeling
	Floor - Tile Ceramic/ Porcelain	1st Fl, Staff Locker room (next to engineer office)	174	SF	6	\$368	
	Lavatory	1st Fl, Staff Locker room (next to engineer office)	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Fl, Staff Locker room (next to engineer office)	3	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Locker/Shower Room</b>							
	Showers	1st Fl, Staff Locker room (next to engineer office)	1	EA	6	\$311	
	Student Lockers - One Tier	1st Fl, Staff Locker room (next to engineer office)	9	EA	6	\$836	
	Walls - Plaster/Drywall	1st Fl, Staff Locker room (next to engineer office)	944	SF	6	\$2,605	
	Walls - Tile Ceramic/ Porcelain	1st Fl, Staff Locker room (next to engineer office)	85	SF	6	\$192	
	Water Closet	1st Fl, Staff Locker room (next to engineer office)	1	EA	6	\$336	
	Accessories	223A Locker Room	262	SF	6	\$1,027	
	Ceiling - Plaster/ Drywall	223A Locker Room	262	SF	6	\$907	
	Doors - Side-lite	223A Locker Room	8	SF	6	\$134	
	Doors - Transom Window	223A Locker Room	4	SF	6	\$68	Wood panel
	Doors - Wood Doors inclu hw	223A Locker Room	1	EA	6	\$301	
	Floor Drain	223A Locker Room	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	223A Locker Room	262	SF	6	\$554	
	Lavatory	223A Locker Room	1	EA	6	\$320	
	Lighting - Pendent/Surface	223A Locker Room	3	EA	7	\$0	
	Showers	223A Locker Room	1	EA	6	\$311	
	Student Lockers - One Tier	223A Locker Room	7	EA	6	\$650	
	Walls - Plaster/Drywall	223A Locker Room	672	SF	6	\$1,855	
	Water Closet	223A Locker Room	1	EA	6	\$336	
	Accessories	Rm 121- Boys Locker	680	SF	6	\$2,664	
	Benches, ped mounted	Rm 121- Boys Locker	32	LF	6	\$3,484	
	Ceiling - Plaster/ Drywall	Rm 121- Boys Locker	3,912	SF	6	\$13,538	
	Ceiling - Plaster/ Drywall	Rm 121- Boys Locker	42	SF	5	\$548	peeling
	Doors - Transom Window	Rm 121- Boys Locker	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	Rm 121- Boys Locker	2	EA	6	\$602	
	Floor Drain	Rm 121- Boys Locker	7	EA	6	\$7,414	
	Floor - Concrete Epoxy/ Painted	Rm 121- Boys Locker	1,421	SF	6	\$752	
	Floor - Terrazzo	Rm 121- Boys Locker	105	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Rm 121- Boys Locker	1,418	SF	6	\$3,001	
	Lavatory	Rm 121- Boys Locker	2	EA	6	\$639	
	Lighting - Pendent/Surface	Rm 121- Boys Locker	32	EA	7	\$0	
	Lighting - Wall Mounted	Rm 121- Boys Locker	1	EA	7	\$0	
	Partitions	Rm 121- Boys Locker	2	EA	6	\$594	
	Showers	Rm 121- Boys Locker	15	EA	6	\$4,671	
	Student Lockers - One Tier	Rm 121- Boys Locker	11	EA	6	\$1,021	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Locker/Shower Room</b>							
	Student Lockers - Two Tier	Rm 121- Boys Locker	125	EA	6	\$5,802	
	Student Lockers - Two Tier	Rm 121- Boys Locker	3	EA	5	\$281	missing handle & lock hardware
	Urinals	Rm 121- Boys Locker	4	EA	6	\$1,344	
	Walls - Metal Panel	Rm 121- Boys Locker	200	SF	6	\$1,493	FRP
	Walls - Plaster/Drywall	Rm 121- Boys Locker	311	SF	6	\$858	
	Walls - Structural Glazed Tile	Rm 121- Boys Locker	6,794	SF	6	\$21,374	
	Walls - Structural Glazed Tile	Rm 121- Boys Locker	1,078	SF	6	\$4,702	
	Walls - Structural Glazed Tile	Rm 121- Boys Locker	12	SF	5	\$766	crack
	Walls - Tile Ceramic/ Porcelain	Rm 121- Boys Locker	53	SF	6	\$120	
	Water Closet	Rm 121- Boys Locker	2	EA	6	\$672	
	Accessories	Rm 125- Womens Locker	238	SF	6	\$933	
	Benches, ped mounted	Rm 125- Womens Locker	136	LF	6	\$14,808	
	Ceiling - Lay-In	Rm 125- Womens Locker	238	SF	6	\$715	
	Ceiling - Plaster/ Drywall	Rm 125- Womens Locker	4,406	SF	6	\$15,247	
	Ceiling - Plaster/ Drywall	Rm 125- Womens Locker	30	SF	5	\$392	peeling
	Doors - Transom Window	Rm 125- Womens Locker	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	Rm 125- Womens Locker	3	EA	6	\$903	
	Doors - Wood Doors inclu hw	Rm 125- Womens Locker	1	EA	5	\$1,174	corner is damaged
	Floor Drain	Rm 125- Womens Locker	33	EA	6	\$34,952	
	Floor - Terrazzo	Rm 125- Womens Locker	147	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Rm 125- Womens Locker	4,436	SF	6	\$9,388	
	Lavatory	Rm 125- Womens Locker	2	EA	6	\$639	
	Lighting - Lay-in	Rm 125- Womens Locker	5	EA	7	\$0	
	Lighting - Pendent/Surface	Rm 125- Womens Locker	47	EA	7	\$0	
	Lighting - Pendent/Surface	Rm 125- Womens Locker	3	EA	7	\$0	
	Lighting - Wall Mounted	Rm 125- Womens Locker	1	EA	7	\$0	
	Partitions	Rm 125- Womens Locker	4	EA	6	\$1,188	
	Showers	Rm 125- Womens Locker	23	EA	6	\$7,162	
	Showers	Rm 125- Womens Locker	29	EA	5	\$78,720	shower heads missing
	Student Lockers - Three Tiers	Rm 125- Womens Locker	96	EA	6	\$2,971	
	Student Lockers - Two Tier	Rm 125- Womens Locker	145	EA	6	\$6,731	
	Walls - Plaster/Drywall	Rm 125- Womens Locker	1,122	SF	6	\$3,097	
	Walls - Plaster/Drywall	Rm 125- Womens Locker	449	SF	6	\$1,470	
	Walls - Structural Glazed Tile	Rm 125- Womens Locker	382	SF	6	\$1,852	
	Walls - Structural Glazed Tile	Rm 125- Womens Locker	5,350	SF	6	\$16,831	
	Water Closet	Rm 125- Womens Locker	4	EA	6	\$1,344	



## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Lunch &amp; Multipurpose Room</b>							
	Ceiling - Plaster/Drywall	307 Lunchroom	3,500	SF	6	\$12,112	
	Doors - Wood Doors inclu hw	307 Lunchroom	4	EA	6	\$1,204	
	Floor - Tile	307 Lunchroom	4,175	SF	6	\$9,134	
	Lighting - Pendent/Surface	307 Lunchroom	48	EA	7	\$0	
	Storage/ Closet	307 Lunchroom	164	SF	6	\$1,189	
	Walls - Plaster/Drywall	307 Lunchroom	1,744	SF	6	\$4,813	
	Walls - Structural Glazed Tile	307 Lunchroom	1,744	SF	6	\$5,487	
<b>MDF_IDF</b>							
	AC Unit	Located in Room 213A	1	EA	5	\$1,826	Not per CPS support standards
	Doors - Steel Doors incl hw	Located in Room 213A	1	EA	6	\$301	
	Finishes	Located in Room 213A	522	SF	6	\$3,725	Painted drywall/plaster
<b>Mechanical/ Service Rooms</b>							
	Janitor's Closet	1st Floor	64	SF	6	\$459	
	Storage Room	1st Floor	22	SF	5	\$355	Closet next to freight elevator- has water damage on wall
	Storage Room	1st Floor	496	SF	6	\$3,553	including Yard Storage
	Vaults	1st Floor	25	SF	6	\$179	in the Main office 113
	Janitor's Closet	2nd Floor	61	SF	6	\$437	#230
	Janitor's Closet	2nd Floor	75	SF	6	\$537	#263
	Storage Room	2nd Floor	60	SF	6	\$430	Storage 223C
	Storage Room	2nd Floor	170	SF	6	\$1,218	#262
	Storage Room	2nd Floor	210	SF	6	\$1,505	Book Storage 231A
	Vaults	2nd Floor	7	SF	6	\$50	No combination available
	Janitor's Closet	3rd Floor	66	SF	6	\$473	#352
	Janitor's Closet	3rd Floor	75	SF	6	\$537	#363
	Storage Room	3rd Floor	60	SF	6	\$430	323B next to room 323
	Storage Room	3rd Floor	170	SF	6	\$1,218	#362 Book Storage
	Storage Room	3rd Floor	10	SF	6	\$72	#311
	Storage Room	3rd Floor	214	SF	6	\$1,533	#330B
	Janitor's Closet	4th Floor	65	SF	6	\$466	424
	Storage Room	4th Floor	600	SF	6	\$4,299	409A, 413A, 426
	Air Tunnel	Basement	8,000	SF	6	\$49,535	
	Boiler Room	Basement	2,590	SF	6	\$18,556	
	Crawl Space - Unfinished	Basement	1,168	SF	6	\$7,232	Sub-Basement under boiler room
	Interior Stairs	Basement	10	LF	6	\$90	Leading up to yard storage
	Interior Stairs	Basement	57	LF	6	\$514	Leading up to main floor (3 sets of stairs in basement)



## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Mechanical/ Service Rooms</b>							
	Mechanical/ Service Rooms	Basement	40	SF	5	\$0	cracks in Mech Rm B5 ceiling/walls
	Mechanical/ Service Rooms	Basement	336	SF	6	\$2,407	Switchgear
	Mechanical/ Service Rooms	Basement	13,724	SF	6	\$98,323	Mech. room B7A & B7A-1 & B5
	Mechanical/ Service Rooms	Basement	1,935	SF	6	\$13,863	Exhaust Chamber use as janitor's lounge
	Mechanical/ Service Rooms	Basement	3,651	SF	6	\$26,157	Pump room
	Storage Room	Basement	10,588	SF	6	\$75,856	
<b>Pool &amp; Natatorium</b>							
	Bleachers Seating/Plank Seating	1st Floor	65	EA	6	\$1,881	
	Ceiling - Plaster/ Drywall	1st Floor	232	SF	6	\$1,281	
	Ceiling - Splined (Moister Resistance)	1st Floor	3,114	SF	6	\$3,251	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
	Doors - Transom Window	1st Floor	60	SF	6	\$1,016	
	Floor - Terrazzo	1st Floor	132	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	59	EA	5	\$10,772	rusting
	Pool Basin	1st Floor	1,279	SF	6	\$43,273	
	Pool Basin	1st Floor	200	SF	2	\$50,962	pool basing is leaking into the basement
	Pool Deck	1st Floor	20	SF	5	\$506	cracked tile, but seems like concrete below has also cracked, as crack bulges up
	Pool Deck	1st Floor	1,735	SF	6	\$16,474	
	Pool Deck Drains	1st Floor	7	EA	6	\$2,954	
	Storage/ Closet	1st Floor	67	SF	6	\$486	
	Walls - Structural Glazed Tile	1st Floor	3,012	SF	6	\$9,476	
	Walls - Structural Glazed Tile	1st Floor	8	SF	5	\$511	crack
<b>Prep Room</b>							
	Casework	413A	4	LF	6	\$101	
	Ceiling - Lay-in	413A	72	SF	6	\$216	
	Doors - Steel Doors incl hw	413A	1	EA	6	\$301	
	Floor - Tile	413A	72	SF	6	\$158	
	Lighting - Lay-in	413A	2	EA	7	\$0	
	Walls - Plaster/Drywall	413A	312	SF	6	\$861	
	Work Sink	413A	1	EA	6	\$379	
	Casework	413B inside 413	30	LF	6	\$758	
	Ceiling - Lay-in	413B inside 413	174	SF	6	\$523	
	Doors - Steel Doors incl hw	413B inside 413	1	EA	6	\$301	
	Floor - Tile	413B inside 413	174	SF	6	\$381	
	Lighting - Lay-in	413B inside 413	3	EA	7	\$0	
	Walls - Plaster/Drywall	413B inside 413	300	SF	6	\$828	

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Prep Room</b>							
	Work Sink	413B inside 413	2	EA	6	\$758	
	Casework	421B	10	LF	6	\$253	
	Ceiling - Lay-in	421B	70	SF	6	\$210	
	Doors - Steel Doors incl hw	421B	1	EA	6	\$301	Vault type door
	Floor - Tile	421B	70	SF	6	\$153	
	Lighting - Lay-in	421B	1	EA	7	\$0	
	Walls - Plaster/Drywall	421B	350	SF	6	\$966	
	Work Sink	421B	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	Prep Room 215A in 215	168	SF	6	\$581	
	Doors - Side-lite	Prep Room 215A in 215	30	SF	6	\$502	
	Doors - Wood Doors inclu hw	Prep Room 215A in 215	1	EA	6	\$301	
	Floor - Tile	Prep Room 215A in 215	168	SF	5	\$754	
	Lighting - Pendent/Surface	Prep Room 215A in 215	2	EA	7	\$0	
	Walls - Plaster/Drywall	Prep Room 215A in 215	2	SF	5	\$10	Peeling paint
	Walls - Plaster/Drywall	Prep Room 215A in 215	665	SF	6	\$1,835	
	Casework	Prep Room in 309 Room 309A	10	LF	6	\$253	
	Ceiling - Lay-in	Prep Room in 309 Room 309A	188	SF	6	\$565	
	Doors - Steel Doors incl hw	Prep Room in 309 Room 309A	1	EA	6	\$301	
	Floor - Tile	Prep Room in 309 Room 309A	188	SF	6	\$411	
	Lighting - Lay-in	Prep Room in 309 Room 309A	4	EA	7	\$0	
	Walls - Plaster/Drywall	Prep Room in 309 Room 309A	480	SF	6	\$1,325	
	Work Sink	Prep Room in 309 Room 309A	1	EA	6	\$379	
	Casework	Prep room in 313	10	LF	6	\$253	
	Ceiling - Lay-in	Prep room in 313	72	SF	6	\$216	
	Doors - Steel Doors incl hw	Prep room in 313	1	EA	6	\$301	Vault type door
	Floor - Tile/Sheet	Prep room in 313	72	SF	6	\$72	
	Lighting - Lay-in	Prep room in 313	2	EA	6	\$238	
	Walls - Plaster/Drywall	Prep room in 313	312	SF	6	\$861	
	Work Sink	Prep room in 313	1	EA	6	\$379	
	Casework	Rm 114A- Prep room for food for Community Rm 112	20	LF	6	\$505	
	Ceiling - Lay-in	Rm 114A- Prep room for food for Community Rm 112	164	SF	6	\$492	
	Doors - Steel Doors incl hw	Rm 114A- Prep room for food for Community Rm 112	1	EA	6	\$301	
	Floor - Tile	Rm 114A- Prep room for food for Community Rm 112	164	SF	4	\$1,409	lifting & damaged
	Lighting - Lay-in	Rm 114A- Prep room for food for Community Rm 112	4	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Prep Room</b>							
	Walls - Plaster/Drywall	Rm 114A- Prep room for food for Community Rm 112	490	SF	6	\$1,352	
	Work Sink	Rm 114A- Prep room for food for Community Rm 112	1	EA	6	\$379	
	Ceiling - Lay-in	Room 413C	153	SF	6	\$459	
	Doors - Steel Doors incl hw	Room 413C	1	EA	6	\$301	
	Floor - Tile	Room 413C	153	SF	6	\$335	
	Lighting - Lay-in	Room 413C	2	EA	7	\$0	
	Walls - Plaster/Drywall	Room 413C	253	SF	6	\$698	
<b>Restroom</b>							
	Accessories	1st Fl- Across from Freight Elevator	23	SF	6	\$212	
	Ceiling - Plaster/Drywall	1st Fl- Across from Freight Elevator	23	SF	6	\$80	
	Doors - Wood Doors inclu hw	1st Fl- Across from Freight Elevator	1	EA	6	\$301	
	Floor - Tile	1st Fl- Across from Freight Elevator	7	SF	6	\$15	
	Floor - Tile Ceramic/ Porcelain	1st Fl- Across from Freight Elevator	15	SF	6	\$32	
	Floor - Tile Ceramic/ Porcelain	1st Fl- Across from Freight Elevator	1	SF	5	\$21	damaged
	Lavatory	1st Fl- Across from Freight Elevator	1	EA	6	\$320	
	Lighting - Pendant/Surface	1st Fl- Across from Freight Elevator	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Fl- Across from Freight Elevator	170	SF	6	\$469	
	Water Closet	1st Fl- Across from Freight Elevator	1	EA	6	\$336	
	Accessories	1st Fl- Auditorium- Men's	150	SF	6	\$1,384	
	Ceiling - Plaster/Drywall	1st Fl- Auditorium- Men's	150	SF	6	\$519	
	Doors - Wood Doors inclu hw	1st Fl- Auditorium- Men's	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Fl- Auditorium- Men's	150	SF	6	\$317	
	Lavatory	1st Fl- Auditorium- Men's	2	EA	6	\$639	
	Lighting - Pendant/Surface	1st Fl- Auditorium- Men's	1	EA	7	\$0	
	Lighting - Wall Mounted	1st Fl- Auditorium- Men's	2	EA	7	\$0	
	Partitions	1st Fl- Auditorium- Men's	2	EA	6	\$594	Marble
	Urinals	1st Fl- Auditorium- Men's	2	EA	6	\$672	
	Walls - Plaster/Drywall	1st Fl- Auditorium- Men's	166	SF	6	\$544	
	Walls - Plaster/Drywall	1st Fl- Auditorium- Men's	333	SF	6	\$919	Marble
	Walls - Tile Ceramic/ Porcelain	1st Fl- Auditorium- Men's	50	SF	6	\$113	
	Water Closet	1st Fl- Auditorium- Men's	2	EA	6	\$672	
	Accessories	1st Fl- Auditorium Women's	150	SF	6	\$1,384	
	Ceiling - Plaster/Drywall	1st Fl- Auditorium Women's	150	SF	6	\$519	
	Doors - Wood Doors inclu hw	1st Fl- Auditorium Women's	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Fl- Auditorium Women's	150	SF	6	\$317	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lavatory	1st Fl- Auditorium Women's	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Fl- Auditorium Women's	2	EA	7	\$0	
	Lighting - Wall Mounted	1st Fl- Auditorium Women's	1	EA	7	\$0	
	Partitions	1st Fl- Auditorium Women's	2	EA	6	\$594	Marble
	Walls - Plaster/Drywall	1st Fl- Auditorium Women's	333	SF	6	\$919	Marble
	Walls - Plaster/Drywall	1st Fl- Auditorium Women's	166	SF	6	\$544	
	Water Closet	1st Fl- Auditorium Women's	2	EA	6	\$672	
	Accessories	1st Fl Boys- by 120	259	SF	6	\$2,389	
	Ceiling - Lay-in	1st Fl Boys- by 120	221	SF	6	\$664	
	Ceiling - Plaster/Drywall	1st Fl Boys- by 120	38	SF	6	\$132	
	Doors - Side-lite	1st Fl Boys- by 120	21	SF	6	\$351	wood panel
	Doors - Transom Window	1st Fl Boys- by 120	16	SF	6	\$271	wood panel
	Doors - Wood Doors inclu hw	1st Fl Boys- by 120	1	EA	6	\$301	
	Floor Drain	1st Fl Boys- by 120	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Fl Boys- by 120	254	SF	6	\$538	
	Floor - Tile Ceramic/ Porcelain	1st Fl Boys- by 120	5	SF	5	\$104	cracked tile
	Lavatory	1st Fl Boys- by 120	2	EA	6	\$639	
	Lighting - Lay-in	1st Fl Boys- by 120	4	EA	7	\$0	
	Lighting - Pendent/Surface	1st Fl Boys- by 120	1	EA	7	\$0	
	Partitions	1st Fl Boys- by 120	2	EA	6	\$594	
	Urinals	1st Fl Boys- by 120	4	EA	6	\$1,344	
	Walls - Structural Glazed Tile	1st Fl Boys- by 120	760	SF	6	\$2,391	
	Water Closet	1st Fl Boys- by 120	2	EA	6	\$672	
	Accessories	1st Fl- By 104	246	SF	6	\$2,269	
	Ceiling - Lay-in	1st Fl- By 104	215	SF	6	\$646	
	Ceiling - Plaster/Drywall	1st Fl- By 104	31	SF	6	\$107	
	Doors - Transom Window	1st Fl- By 104	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	1st Fl- By 104	4	EA	6	\$1,204	
	Floor Drain	1st Fl- By 104	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Fl- By 104	246	SF	6	\$521	
	Lavatory	1st Fl- By 104	2	EA	6	\$639	
	Lighting - Lay-in	1st Fl- By 104	5	EA	7	\$0	
	Lighting - Lay-in	1st Fl- By 104	1	EA	6	\$119	cover is cracked
	Lighting - Pendent/Surface	1st Fl- By 104	1	EA	7	\$0	
	Partitions	1st Fl- By 104	4	EA	6	\$1,188	
	Urinals	1st Fl- By 104	6	EA	6	\$2,016	
	Urinals	1st Fl- By 104	1	EA	4	\$7,669	missing

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Walls - Structural Glazed Tile	1st Fl- By 104	700	SF	6	\$2,202	
	Walls - Tile Ceramic/ Porcelain	1st Fl- By 104	4	SF	4	\$153	missing
	Walls - Tile Ceramic/ Porcelain	1st Fl- By 104	50	SF	6	\$113	
	Water Closet	1st Fl- By 104	2	EA	6	\$672	
	Accessories	1st Fl Girls- By 108	338	SF	6	\$3,118	
	Ceiling - Lay-in	1st Fl Girls- By 108	303	SF	6	\$910	
	Ceiling - Plaster/Drywall	1st Fl Girls- By 108	35	SF	6	\$121	
	Doors - Side-lite	1st Fl Girls- By 108	21	SF	6	\$351	wood panel
	Doors - Transom Window	1st Fl Girls- By 108	16	SF	6	\$271	wood panel
	Doors - Wood Doors inclu hw	1st Fl Girls- By 108	1	EA	6	\$301	
	Floor Drain	1st Fl Girls- By 108	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Fl Girls- By 108	333	SF	6	\$705	
	Floor - Tile Ceramic/ Porcelain	1st Fl Girls- By 108	5	SF	5	\$104	damaged
	Lavatory	1st Fl Girls- By 108	2	EA	6	\$639	
	Lighting - Lay-in	1st Fl Girls- By 108	6	EA	7	\$0	
	Lighting - Pendent/Surface	1st Fl Girls- By 108	1	EA	7	\$0	
	Partitions	1st Fl Girls- By 108	4	EA	6	\$1,188	
	Walls - Structural Glazed Tile	1st Fl Girls- By 108	778	SF	6	\$2,448	
	Water Closet	1st Fl Girls- By 108	4	EA	6	\$1,344	
	Accessories	1st Fl Girls- By 122	276	SF	6	\$2,546	
	Ceiling - Lay-in	1st Fl Girls- By 122	243	SF	6	\$730	
	Ceiling - Plaster/Drywall	1st Fl Girls- By 122	33	SF	6	\$114	
	Doors - Side-lite	1st Fl Girls- By 122	21	SF	6	\$351	wood panel
	Doors - Transom Window	1st Fl Girls- By 122	16	SF	6	\$271	wood panel
	Doors - Wood Doors inclu hw	1st Fl Girls- By 122	1	EA	6	\$301	
	Floor Drain	1st Fl Girls- By 122	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Fl Girls- By 122	261	SF	6	\$552	
	Floor - Tile Ceramic/ Porcelain	1st Fl Girls- By 122	15	SF	5	\$313	damaged tile
	Lavatory	1st Fl Girls- By 122	2	EA	6	\$639	
	Lighting - Lay-in	1st Fl Girls- By 122	8	EA	7	\$0	
	Lighting - Pendent/Surface	1st Fl Girls- By 122	1	EA	7	\$0	
	Partitions	1st Fl Girls- By 122	3	EA	6	\$891	
	Walls - Structural Glazed Tile	1st Fl Girls- By 122	798	SF	6	\$2,511	
	Water Closet	1st Fl Girls- By 122	4	EA	6	\$1,344	
	Accessories	1st Fl Men's- Across from 108	121	SF	6	\$1,116	
	Ceiling - Lay-in	1st Fl Men's- Across from 108	121	SF	6	\$363	
	Doors - Wood Doors inclu hw	1st Fl Men's- Across from 108	1	EA	6	\$301	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Floor - Tile Ceramic/ Porcelain	1st Fl Men's- Across from 108	121	SF	6	\$256	
	Lavatory	1st Fl Men's- Across from 108	1	EA	6	\$320	
	Lighting - Lay-in	1st Fl Men's- Across from 108	2	EA	7	\$0	
	Partitions	1st Fl Men's- Across from 108	2	EA	6	\$594	
	Walls - Plaster/Drywall	1st Fl Men's- Across from 108	450	SF	6	\$1,242	
	Water Closet	1st Fl Men's- Across from 108	2	EA	6	\$672	
	Accessories	1st Fl, in principal office	28	SF	6	\$258	
	Ceiling - Plaster/Drywall	1st Fl, in principal office	28	SF	6	\$97	
	Doors - Wood Doors inclu hw	1st Fl, in principal office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Fl, in principal office	28	SF	6	\$59	
	Lavatory	1st Fl, in principal office	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Fl, in principal office	1	EA	7	\$0	
	Lighting - Wall Mounted	1st Fl, in principal office	1	EA	6	\$124	
	Walls - Plaster/Drywall	1st Fl, in principal office	320	SF	6	\$883	
	Water Closet	1st Fl, in principal office	1	EA	6	\$336	
	Accessories	1st flr Men- next to 110	291	SF	6	\$2,684	
	Ceiling - Lay-in	1st flr Men- next to 110	255	SF	6	\$766	
	Ceiling - Plaster/Drywall	1st flr Men- next to 110	36	SF	6	\$125	
	Doors - Side-lite	1st flr Men- next to 110	21	SF	6	\$351	wood panel
	Doors - Transom Window	1st flr Men- next to 110	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	1st flr Men- next to 110	1	EA	6	\$301	
	Floor Drain	1st flr Men- next to 110	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st flr Men- next to 110	291	SF	6	\$616	
	Lavatory	1st flr Men- next to 110	2	EA	6	\$639	
	Lighting - Lay-in	1st flr Men- next to 110	6	EA	7	\$0	
	Lighting - Pendent/Surface	1st flr Men- next to 110	1	EA	7	\$0	
	Partitions	1st flr Men- next to 110	3	EA	6	\$891	
	Urinals	1st flr Men- next to 110	4	EA	6	\$1,344	
	Walls - Structural Glazed Tile	1st flr Men- next to 110	798	SF	6	\$2,511	
	Water Closet	1st flr Men- next to 110	2	EA	6	\$672	
	Accessories	3rd Flr Men faculty next to 306	291	SF	6	\$2,684	
	Ceiling - Lay-in	3rd Flr Men faculty next to 306	291	SF	6	\$874	
	Doors - Transom Window	3rd Flr Men faculty next to 306	24	SF	6	\$406	
	Doors - Wood Doors inclu hw	3rd Flr Men faculty next to 306	4	EA	6	\$1,204	
	Floor Drain	3rd Flr Men faculty next to 306	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd Flr Men faculty next to 306	291	SF	6	\$616	
	Lavatory	3rd Flr Men faculty next to 306	2	EA	6	\$639	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lighting - Lay-in	3rd Flr Men faculty next to 306	4	EA	7	\$0	
	Partitions	3rd Flr Men faculty next to 306	4	EA	6	\$1,188	
	Urinals	3rd Flr Men faculty next to 306	2	EA	6	\$672	
	Walls - Structural Glazed Tile	3rd Flr Men faculty next to 306	798	SF	6	\$2,511	
	Water Closet	3rd Flr Men faculty next to 306	2	EA	6	\$672	
	Accessories	4th Fl North, Boys	265	SF	6	\$2,444	
	Ceiling - Lay-in	4th Fl North, Boys	265	SF	6	\$796	
	Doors - Side-lite	4th Fl North, Boys	21	SF	6	\$351	wood panel
	Doors - Transom Window	4th Fl North, Boys	16	SF	6	\$271	wood panel
	Doors - Wood Doors inclu hw	4th Fl North, Boys	1	EA	6	\$301	
	Floor Drain	4th Fl North, Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	4th Fl North, Boys	265	SF	6	\$561	
	Lavatory	4th Fl North, Boys	2	EA	6	\$639	
	Lighting - Lay-in	4th Fl North, Boys	6	EA	7	\$0	
	Partitions	4th Fl North, Boys	2	EA	6	\$594	
	Urinals	4th Fl North, Boys	8	EA	6	\$2,688	
	Walls - Structural Glazed Tile	4th Fl North, Boys	760	SF	6	\$2,391	
	Water Closet	4th Fl North, Boys	2	EA	6	\$672	
	Accessories	4th Fl South, Girls	350	SF	6	\$3,228	
	Ceiling - Lay-in	4th Fl South, Girls	350	SF	6	\$1,051	
	Doors - Side-lite	4th Fl South, Girls	21	SF	6	\$351	wood panel
	Doors - Transom Window	4th Fl South, Girls	16	SF	6	\$271	wood panel
	Doors - Wood Doors inclu hw	4th Fl South, Girls	1	EA	6	\$301	
	Floor Drain	4th Fl South, Girls	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	4th Fl South, Girls	350	SF	6	\$741	
	Lavatory	4th Fl South, Girls	2	EA	6	\$639	
	Lighting - Lay-in	4th Fl South, Girls	8	EA	7	\$0	
	Partitions	4th Fl South, Girls	9	EA	6	\$2,672	
	Walls - Structural Glazed Tile	4th Fl South, Girls	700	SF	6	\$2,202	
	Water Closet	4th Fl South, Girls	9	EA	6	\$3,024	
	Accessories	In Rm 103A, Engineer Restroom	23	SF	6	\$212	
	Ceiling - Plaster/Drywall	In Rm 103A, Engineer Restroom	23	SF	6	\$80	
	Doors - Wood Doors inclu hw	In Rm 103A, Engineer Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	In Rm 103A, Engineer Restroom	23	SF	6	\$49	
	Lavatory	In Rm 103A, Engineer Restroom	1	EA	6	\$320	
	Lighting - Pendant/Surface	In Rm 103A, Engineer Restroom	1	EA	7	\$0	
	Walls - Plaster/Drywall	In Rm 103A, Engineer Restroom	256	SF	6	\$707	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Walls - Plaster/Drywall	In Rm 103A, Engineer Restroom	10	SF	5	\$51	efflorescence & water damage on wall
	Water Closet	In Rm 103A, Engineer Restroom	1	EA	6	\$336	
	Accessories	In Rm 103B, Asst Engineer Restroom	42	SF	6	\$387	
	Ceiling - Plaster/Drywall	In Rm 103B, Asst Engineer Restroom	42	SF	6	\$145	
	Doors - Wood Doors inclu hw	In Rm 103B, Asst Engineer Restroom	2	EA	6	\$602	
	Floor Drain	In Rm 103B, Asst Engineer Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	In Rm 103B, Asst Engineer Restroom	42	SF	6	\$89	
	Lavatory	In Rm 103B, Asst Engineer Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	In Rm 103B, Asst Engineer Restroom	2	EA	7	\$0	
	Showers	In Rm 103B, Asst Engineer Restroom	1	EA	6	\$311	
	Walls - Plaster/Drywall	In Rm 103B, Asst Engineer Restroom	181	SF	6	\$500	
	Walls - Plaster/Drywall	In Rm 103B, Asst Engineer Restroom	16	SF	5	\$82	efflorescence
	Walls - Tile Ceramic/ Porcelain	In Rm 103B, Asst Engineer Restroom	148	SF	6	\$334	shower surround
	Water Closet	In Rm 103B, Asst Engineer Restroom	1	EA	6	\$336	
	Accessories	Men next to 204	259	SF	6	\$2,389	
	Ceiling - Lay-in	Men next to 204	229	SF	6	\$688	
	Ceiling - Plaster/Drywall	Men next to 204	30	SF	6	\$104	
	Doors - Transom Window	Men next to 204	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	Men next to 204	4	EA	6	\$1,204	
	Floor Drain	Men next to 204	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Men next to 204	259	SF	6	\$548	
	Lavatory	Men next to 204	2	EA	6	\$639	
	Lighting - Lay-in	Men next to 204	4	EA	7	\$0	
	Lighting - Pendent/Surface	Men next to 204	1	EA	7	\$0	
	Partitions	Men next to 204	4	EA	6	\$1,188	
	Walls - Structural Glazed Tile	Men next to 204	760	SF	6	\$2,391	
	Water Closet	Men next to 204	4	EA	6	\$1,344	
	Accessories	Men next to 210	291	SF	6	\$2,684	
	Ceiling - Lay-in	Men next to 210	255	SF	6	\$766	
	Ceiling - Plaster/Drywall	Men next to 210	36	SF	6	\$125	
	Doors - Side-lite	Men next to 210	21	SF	6	\$351	Wood panel
	Doors - Transom Window	Men next to 210	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	Men next to 210	1	EA	6	\$301	
	Floor Drain	Men next to 210	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Men next to 210	291	SF	6	\$616	
	Lavatory	Men next to 210	2	EA	6	\$639	
	Lighting - Lay-in	Men next to 210	6	EA	7	\$0	



**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lighting - Pendent/Surface	Men next to 210	1	EA	7	\$0	
	Partitions	Men next to 210	2	EA	6	\$594	
	Urinals	Men next to 210	4	EA	6	\$1,344	
	Walls - Structural Glazed Tile	Men next to 210	798	SF	6	\$2,511	
	Water Closet	Men next to 210	2	EA	6	\$672	
	Accessories	Men next to 218	246	SF	6	\$2,269	
	Ceiling - Lay-in	Men next to 218	210	SF	6	\$631	
	Ceiling - Plaster/Drywall	Men next to 218	36	SF	6	\$125	
	Doors - Side-lite	Men next to 218	21	SF	6	\$351	wood panel
	Doors - Transom Window	Men next to 218	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	Men next to 218	1	EA	6	\$301	
	Floor Drain	Men next to 218	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Men next to 218	246	SF	6	\$521	
	Lavatory	Men next to 218	2	EA	6	\$639	
	Lighting - Lay-in	Men next to 218	4	EA	7	\$0	
	Lighting - Pendent/Surface	Men next to 218	1	EA	7	\$0	
	Partitions	Men next to 218	2	EA	6	\$594	
	Urinals	Men next to 218	4	EA	6	\$1,344	
	Walls - Structural Glazed Tile	Men next to 218	754	SF	6	\$2,372	
	Water Closet	Men next to 218	2	EA	6	\$672	
	Accessories	Men next to 310	291	SF	6	\$2,684	
	Ceiling - Lay-in	Men next to 310	291	SF	6	\$874	
	Ceiling - Plaster/Drywall	Men next to 310	36	SF	6	\$125	
	Doors - Side-lite	Men next to 310	21	SF	6	\$351	wood panel
	Doors - Transom Window	Men next to 310	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	Men next to 310	1	EA	6	\$301	
	Floor Drain	Men next to 310	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Men next to 310	291	SF	6	\$616	
	Lavatory	Men next to 310	2	EA	6	\$639	
	Lighting - Lay-in	Men next to 310	6	EA	7	\$0	
	Lighting - Pendent/Surface	Men next to 310	1	EA	7	\$0	
	Partitions	Men next to 310	2	EA	6	\$594	
	Urinals	Men next to 310	4	EA	6	\$1,344	
	Walls - Structural Glazed Tile	Men next to 310	798	SF	6	\$2,511	
	Water Closet	Men next to 310	2	EA	6	\$672	
	Accessories	Men next to 318	259	SF	6	\$2,389	
	Ceiling - Lay-in	Men next to 318	210	SF	6	\$631	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Ceiling - Plaster/Drywall	Men next to 318	36	SF	6	\$125	
	Doors - Side-lite	Men next to 318	21	SF	6	\$351	wood panel
	Doors - Transom Window	Men next to 318	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	Men next to 318	1	EA	6	\$301	
	Floor Drain	Men next to 318	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Men next to 318	259	SF	6	\$548	
	Lavatory	Men next to 318	2	EA	6	\$639	
	Lighting - Lay-in	Men next to 318	4	EA	7	\$0	
	Lighting - Pendent/Surface	Men next to 318	1	EA	7	\$0	
	Partitions	Men next to 318	2	EA	6	\$594	
	Urinals	Men next to 318	4	EA	6	\$1,344	
	Walls - Structural Glazed Tile	Men next to 318	760	SF	6	\$2,391	
	Water Closet	Men next to 318	2	EA	6	\$672	
	Accessories	North restroom inside 203B office	23	SF	6	\$212	
	Ceiling - Plaster/Drywall	North restroom inside 203B office	23	SF	6	\$80	
	Doors - Transom Window	North restroom inside 203B office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	North restroom inside 203B office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	North restroom inside 203B office	23	SF	6	\$49	
	Lavatory	North restroom inside 203B office	1	EA	6	\$320	
	Lighting - Pendent/Surface	North restroom inside 203B office	1	EA	7	\$0	
	Walls - Plaster/Drywall	North restroom inside 203B office	256	SF	6	\$707	
	Water Closet	North restroom inside 203B office	1	EA	6	\$336	
	Accessories	North restroom inside 203C office	39	SF	6	\$360	
	Ceiling - Plaster/Drywall	North restroom inside 203C office	39	SF	6	\$135	
	Doors - Wood Doors inclu hw	North restroom inside 203C office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	North restroom inside 203C office	39	SF	6	\$83	
	Lavatory	North restroom inside 203C office	1	EA	6	\$320	
	Lighting - Pendent/Surface	North restroom inside 203C office	1	EA	7	\$0	
	Partitions	North restroom inside 203C office	1	EA	6	\$297	
	Walls - Plaster/Drywall	North restroom inside 203C office	322	SF	6	\$889	
	Water Closet	North restroom inside 203C office	1	EA	6	\$336	
	Accessories	Staff Restroom next to room 208	121	SF	6	\$1,116	
	Ceiling - Plaster/Drywall	Staff Restroom next to room 208	121	SF	6	\$419	
	Doors - Transom Window	Staff Restroom next to room 208	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	Staff Restroom next to room 208	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Staff Restroom next to room 208	121	SF	6	\$256	
	Lavatory	Staff Restroom next to room 208	1	EA	6	\$320	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lighting - Lay-in	Staff Restroom next to room 208	2	EA	6	\$238	
	Partitions	Staff Restroom next to room 208	2	EA	6	\$594	
	Walls - Plaster/Drywall	Staff Restroom next to room 208	450	SF	6	\$1,242	
	Water Closet	Staff Restroom next to room 208	2	EA	6	\$672	
	Accessories	Staff Restroom next to room 308	121	SF	6	\$1,116	
	Ceiling - Plaster/Drywall	Staff Restroom next to room 308	121	SF	6	\$419	
	Doors - Transom Window	Staff Restroom next to room 308	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	Staff Restroom next to room 308	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Staff Restroom next to room 308	121	SF	6	\$256	
	Lavatory	Staff Restroom next to room 308	1	EA	6	\$320	
	Lighting - Lay-in	Staff Restroom next to room 308	2	EA	7	\$0	
	Partitions	Staff Restroom next to room 308	2	EA	6	\$594	
	Walls - Plaster/Drywall	Staff Restroom next to room 308	450	SF	6	\$1,242	
	Water Closet	Staff Restroom next to room 308	2	EA	6	\$672	
	Accessories	Women across from 307	355	SF	6	\$3,274	
	Ceiling - Lay-in	Women across from 307	319	SF	6	\$958	
	Ceiling - Plaster/Drywall	Women across from 307	36	SF	6	\$125	
	Doors - Side-lite	Women across from 307	21	SF	6	\$351	wood panel
	Doors - Transom Window	Women across from 307	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	Women across from 307	1	EA	6	\$301	
	Floor Drain	Women across from 307	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Women across from 307	355	SF	6	\$751	
	Lavatory	Women across from 307	2	EA	6	\$639	
	Lighting - Lay-in	Women across from 307	6	EA	7	\$0	
	Lighting - Pendent/Surface	Women across from 307	3	EA	7	\$0	
	Partitions	Women across from 307	3	EA	6	\$891	
	Walls - Structural Glazed Tile	Women across from 307	805	SF	6	\$2,533	
	Water Closet	Women across from 307	4	EA	6	\$1,344	
	Accessories	Women next to 208B	276	SF	6	\$2,546	
	Ceiling - Lay-in	Women next to 208B	240	SF	6	\$721	
	Ceiling - Plaster/Drywall	Women next to 208B	36	SF	6	\$125	
	Doors - Side-lite	Women next to 208B	21	SF	6	\$351	wood panel
	Doors - Transom Window	Women next to 208B	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	Women next to 208B	1	EA	6	\$301	
	Floor Drain	Women next to 208B	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Women next to 208B	276	SF	6	\$584	
	Lavatory	Women next to 208B	2	EA	6	\$639	

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lighting - Lay-in	Women next to 208B	6	EA	7	\$0	
	Lighting - Pendent/Surface	Women next to 208B	1	EA	7	\$0	
	Partitions	Women next to 208B	3	EA	6	\$891	
	Walls - Structural Glazed Tile	Women next to 208B	778	SF	6	\$2,448	
	Water Closet	Women next to 208B	4	EA	6	\$1,344	
	Accessories	Women next to 220	338	SF	6	\$3,118	
	Ceiling - Lay-in	Women next to 220	302	SF	6	\$907	
	Ceiling - Plaster/Drywall	Women next to 220	36	SF	6	\$125	
	Doors - Side-lite	Women next to 220	21	SF	6	\$351	Wood panel
	Doors - Transom Window	Women next to 220	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	Women next to 220	1	EA	6	\$301	
	Floor Drain	Women next to 220	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Women next to 220	338	SF	6	\$715	
	Lavatory	Women next to 220	2	EA	6	\$639	
	Lighting - Lay-in	Women next to 220	8	EA	7	\$0	
	Lighting - Pendent/Surface	Women next to 220	1	EA	7	\$0	
	Partitions	Women next to 220	3	EA	6	\$891	
	Walls - Structural Glazed Tile	Women next to 220	778	SF	6	\$2,448	
	Water Closet	Women next to 220	4	EA	6	\$1,344	
	Accessories	Women next to 320	355	SF	6	\$3,274	
	Ceiling - Lay-in	Women next to 320	319	SF	6	\$958	
	Ceiling - Plaster/Drywall	Women next to 320	36	SF	6	\$125	
	Doors - Side-lite	Women next to 320	21	SF	6	\$351	wood panel
	Doors - Transom Window	Women next to 320	16	SF	6	\$271	Wood panel
	Doors - Wood Doors inclu hw	Women next to 320	1	EA	6	\$301	
	Floor Drain	Women next to 320	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Women next to 320	355	SF	6	\$751	
	Lavatory	Women next to 320	2	EA	6	\$639	
	Lighting - Lay-in	Women next to 320	8	EA	7	\$0	
	Lighting - Pendent/Surface	Women next to 320	1	EA	7	\$0	
	Partitions	Women next to 320	3	EA	6	\$891	
	Walls - Structural Glazed Tile	Women next to 320	805	SF	6	\$2,533	
	Water Closet	Women next to 320	4	EA	6	\$1,344	

**Rooms (Other Than Classrooms) Subtotal:**

**\$1,916,471**

**Building: Main**

## Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Ceiling - Lay-in	1st Floor	8,708	SF	6	\$26,150	
	Ceiling - Plaster/Drywall	1st Floor	1,789	SF	6	\$11,077	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Doors - Transom Window	1st Floor	159	EA	6	\$2,692	
	Doors - Wood Doors include hw	1st Floor	35	EA	6	\$10,535	
	Drinking Fountains - Single Fountain	1st Floor	12	EA	6	\$3,309	
	Floor - Terrazzo	1st Floor	3,306	SF	6	\$27,751	
	Floor - Terrazzo	1st Floor	34	SF	5	\$1,779	chipped
	Floor - Tile/Sheet	1st Floor	7,157	SF	6	\$3,889	
	Lighting - Lay-in	1st Floor	92	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	22	EA	7	\$0	
	Stairs - Terrazzo	1st Floor	50	LF	7	\$0	stairwell from 1st- 2nd floor 226-S & Locker Room stairs in Girls & Boys
	Stairs - Terrazzo	1st Floor	7	LF	5	\$380	cracked stair
	Student Lockers - One Tier	1st Floor	465	EA	6	\$43,169	
	Walls - Plaster/Drywall	1st Floor	14,777	SF	6	\$65,506	
	Walls - Structural Glazed Tile	1st Floor	10,556	SF	6	\$33,209	
	Walls - Tile Ceramic/ Porcelain	1st Floor	760	SF	6	\$2,391	
	Ceiling - Lay-in	2nd Floor	8,708	SF	6	\$26,150	
	Doors - Transom Window	2nd Floor	140	EA	6	\$2,370	
	Doors - Wood Doors include hw	2nd Floor	15	EA	6	\$4,515	
	Drinking Fountains - Single Fountain	2nd Floor	10	EA	6	\$2,757	
	Floor - Terrazzo	2nd Floor	20	SF	5	\$1,046	cracks
	Floor - Terrazzo	2nd Floor	1,759	SF	7	\$0	
	Floor - Tile/Sheet	2nd Floor	6,900	SF	6	\$3,749	
	Floor - Tile/Sheet	2nd Floor	30	SF	5	\$173	damaged
	Lighting - Lay-in	2nd Floor	79	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	\$0	
	Stairs - Terrazzo	2nd Floor	32	LF	6	\$297	stairwell from 2nd-3rd floor 225-S & 203-S
	Stairs - Terrazzo	2nd Floor	6	LF	5	\$325	cracked stair
	Student Lockers - One Tier	2nd Floor	521	EA	6	\$48,367	
	Walls - Plaster/Drywall	2nd Floor	10,333	SF	6	\$45,806	
	Walls - Structural Glazed Tile	2nd Floor	14,528	SF	6	\$45,705	
	Ceiling - Lay-in	3rd Floor	8,528	SF	6	\$25,610	
	Ceiling - Plaster/Drywall	3rd Floor	180	SF	6	\$1,115	
	Doors - Transom Window	3rd Floor	140	EA	6	\$2,370	
	Doors - Wood Doors include hw	3rd Floor	15	EA	6	\$4,515	
	Drinking Fountains - Single Fountain	3rd Floor	11	EA	6	\$3,033	
	Floor - Terrazzo	3rd Floor	1,751	SF	7	\$0	

**Building: Main**

**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Floor - Terrazzo	3rd Floor	28	SF	5	\$1,465	cracked
	Floor - Tile/Sheet	3rd Floor	6,930	SF	5	\$31,117	cracked/chipped throughout
	Lighting - Lay-in	3rd Floor	74	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	\$0	
	Student Lockers - One Tier	3rd Floor	521	EA	6	\$48,367	
	Walls - Plaster/Drywall	3rd Floor	10,333	SF	6	\$45,806	
	Walls - Structural Glazed Tile	3rd Floor	14,528	SF	6	\$45,705	
	Ceiling - Lay-in	4th Floor	4,013	SF	6	\$12,051	
	Ceiling - Lay-in	4th Floor	1	SF	5	\$9	water stain
	Doors - Transom Window	4th Floor	126	EA	6	\$2,133	
	Doors - Wood Doors include hw	4th Floor	15	EA	6	\$4,515	
	Drinking Fountains - Single Fountain	4th Floor	4	EA	6	\$1,103	
	Floor - Terrazzo	4th Floor	1,294	SF	7	\$0	
	Floor - Tile/Sheet	4th Floor	2,720	SF	6	\$1,478	
	Lighting - Lay-in	4th Floor	34	EA	7	\$0	
	Student Lockers - One Tier	4th Floor	174	EA	6	\$16,153	
	Walls - Plaster/Drywall	4th Floor	3,080	SF	6	\$13,654	
	Walls - Structural Glazed Tile	4th Floor	4,328	SF	6	\$13,616	
	Ceiling - Exposed	Basement	138	SF	6	\$205	Vest B7-0
	Doors - Wood Doors include hw	Basement	2	EA	6	\$602	Vest B7-0
	Floor - Concrete	Basement	138	SF	6	\$73	Vest B7-0
	Lighting - Pendent/Surface	Basement	1	EA	7	\$0	Vest B7-0
	Stairs - Concrete Stairs	Basement	8	LF	6	\$66	Vest B7-0
	Walls - Masonry	Basement	472	SF	6	\$1,485	Vest B7-0
<b>Safety</b>							
	Camera Viewing Station	1st Floor	2	EA	6	\$1,365	Main office & Police Office
	Security Cameras	1st Floor / Entire Building	10	EA	6	\$1,940	
	Metal Dedector	1st Floor	2	EA	6	\$1,761	Vestibule C-1
<b>Stairs</b>							
	Ceiling - Lay-in	Stairwell B (SW)	45	SF	6	\$135	
	Ceiling - Plaster/Drywall	Stairwell B (SW)	445	SF	6	\$3,258	
	Floor - Terrazzo	Stairwell B (SW)	4	SF	5	\$209	cracks
	Floor - Terrazzo	Stairwell B (SW)	836	SF	7	\$0	
	Handrails	Stairwell B (SW)	150	LF	6	\$1,300	
	Lighting - Pendent/Surface	Stairwell B (SW)	6	EA	7	\$0	
	Stairs - Terrazzo	Stairwell B (SW)	75	LF	7	\$0	

**Building: Main**

**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Stairs</b>							
	Walls - Plaster/Drywall	Stairwell B (SW)	1,424	SF	6	\$3,930	
	Walls - Plaster/Drywall	Stairwell B (SW)	6	SF	5	\$37	peeling
	Walls - Structural Glazed Tile	Stairwell B (SW)	2,340	SF	6	\$7,362	
	Ceiling - Lay-in	Stairwell C (S)	45	SF	6	\$135	
	Ceiling - Plaster/Drywall	Stairwell C (S)	445	SF	6	\$3,258	
	Floor - Terrazzo	Stairwell C (S)	840	SF	7	\$0	
	Handrails	Stairwell C (S)	150	LF	6	\$1,300	
	Lighting - Pendent/Surface	Stairwell C (S)	6	EA	7	\$0	
	Stairs - Terrazzo	Stairwell C (S)	75	LF	7	\$0	
	Walls - Plaster/Drywall	Stairwell C (S)	1,430	SF	6	\$3,947	
	Walls - Structural Glazed Tile	Stairwell C (S)	2,340	SF	6	\$7,362	
	Ceiling - Lay-in	Stairwell D (SE)	2	SF	5	\$18	water damaged
	Ceiling - Lay-in	Stairwell D (SE)	43	SF	6	\$129	
	Ceiling - Plaster/Drywall	Stairwell D (SE)	445	SF	6	\$3,258	
	Floor - Terrazzo	Stairwell D (SE)	840	SF	7	\$0	
	Handrails	Stairwell D (SE)	150	LF	6	\$1,300	
	Lighting - Pendent/Surface	Stairwell D (SE)	6	EA	7	\$0	
	Stairs - Terrazzo	Stairwell D (SE)	71	LF	7	\$0	
	Stairs - Terrazzo	Stairwell D (SE)	4	LF	5	\$217	edge damaged
	Walls - Plaster/Drywall	Stairwell D (SE)	1,415	SF	6	\$3,905	
	Walls - Plaster/Drywall	Stairwell D (SE)	15	SF	5	\$93	water damage & peeling paint
	Walls - Structural Glazed Tile	Stairwell D (SE)	2,340	SF	6	\$7,362	
	Ceiling - Plaster/Drywall	Stairwell E (NE)	286	SF	6	\$2,094	
	Floor - Terrazzo	Stairwell E (NE)	154	SF	6	\$1,293	
	Handrails	Stairwell E (NE)	116	LF	6	\$1,005	
	Lighting - Pendent/Surface	Stairwell E (NE)	4	EA	7	\$0	
	Stairs - Terrazzo	Stairwell E (NE)	2	LF	5	\$108	edging damaged
	Stairs - Terrazzo	Stairwell E (NE)	56	LF	7	\$0	
	Walls - Structural Glazed Tile	Stairwell E (NE)	1,980	SF	6	\$6,229	
	Ceiling - Plaster/Drywall	Stairwell H (NW)	286	SF	6	\$2,094	
	Floor - Terrazzo	Stairwell H (NW)	154	SF	7	\$0	
	Handrails	Stairwell H (NW)	116	LF	6	\$1,005	
	Lighting - Pendent/Surface	Stairwell H (NW)	4	EA	7	\$0	
	Stairs - Terrazzo	Stairwell H (NW)	58	LF	7	\$0	
	Walls - Structural Glazed Tile	Stairwell H (NW)	1,980	SF	6	\$6,229	
	Ceiling - Plaster/Drywall	Stairwell J (photo name 205S) (W)	84	SF	6	\$615	
	Ceiling - Plaster/Drywall	Stairwell J (photo name 205S) (W)	5	SF	5	\$102	peeling

**Building: Main**

**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Stairs</b>							
	Floor - Terrazzo	Stairwell J (photo name 205S) (W)	40	SF	7	\$0	
	Handrails	Stairwell J (photo name 205S) (W)	82	LF	6	\$711	
	Lighting - Pendant/Surface	Stairwell J (photo name 205S) (W)	1	EA	7	\$0	
	Lighting - Wall Mounted	Stairwell J (photo name 205S) (W)	1	EA	7	\$0	
	Stairs - Terrazzo	Stairwell J (photo name 205S) (W)	41	LF	7	\$0	
	Walls - Plaster/Drywall	Stairwell J (photo name 205S) (W)	3,978	SF	6	\$10,979	

**Vertical Conveyance**

	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	\$19,238	
	Elevator - Freight Elevator	Basement	1	EA	5	\$86,984	Not working

**Building Interior Subtotal:**

**\$881,914**

**Total Building Cost**

**\$9,939,486**

**SITE**

**Category: Site**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Athletic</b>							
	Surface - Synthetic	Southwest	15,000	SF	7	\$0	
<b>Civil/Drainage</b>							
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	6	\$9,845	
	Civil/ Drainage - Site Manhole	Entire Site	23	EA	6	\$34,333	
<b>Fencing</b>							
	Fencing - Chain Link	Entire Site / North East	27	LF	6	\$507	
	Fencing - New Standard Ornamental	Entire Site	1,521	LF	6	\$48,525	
<b>Landscape</b>							
	Benches	Entire Site / East Courtyard	14	EA	6	\$6,021	
	Landscape - Grass	Entire Site	17,540	SF	6	\$14,548	
	Landscape - Hardscape- Concrete	Entire Site	6,570	SF	6	\$33,916	
	Landscape - Hardscape- Concrete	Entire Site / South Courtyard	450	SF	4	\$9,582	Cracked
	Landscape - Hardscape- Pavers	Entire Site / North West	204	SF	6	\$1,155	
	Parkway trees	Entire Site	9	EA	6	\$5,940	
	Planting Beds/ Area	Entire Site	3,320	SF	6	\$5,460	
	Retaining Wall - Concrete	Entire Site / East Courtyard	850	SF	6	\$19,922	



## SITE

### Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Landscape</b>							
	Trash Receptacles	Entire Site	6	EA	6	\$1,874	
<b>Parking Lot</b>							
	Surface - Asphalt	South Courtyard	9,048	SF	5	\$41,274	Cracking throughout
<b>Sidewalks</b>							
	Sidewalks - Internal Walks	Entire site, Site West	975	LF	6	\$11,712	
	Sidewalks - Perimeter Sidewalks	Entire site, Site West / Site West	6,210	SF	6	\$12,344	
<b>Signage</b>							
	Flag Pole - Flag Pole	Northwest at property, West and East Facade	1	EA	7	\$0	
	Monument - Building Mounted Cut Letter Sign	Northwest at property, West and East Facade / West Entrances	4	EA	7	\$0	Above entrance doors AW, BW, CW, DW
	Monument - Sign	Northwest at property, West and East Facade / East Entrances	1	EA	7	\$0	On fabric canopy @ Entrance F East

**Site Subtotal:** **\$256,957**

**Total Site Cost** **\$256,957**

**Campus Total <sup>2 3</sup>** **\$10,196,443**

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

<sup>2</sup> As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

<sup>3</sup> The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

## Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

- 
- **Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
  - **For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
  - **Campus Total** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.
-

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Art Room	Art Room	3rd Floor	322	324	1,075	1	40	80	258	12	40	Y	N	Y
Band Room	Music Room	3rd Floor	305	305	1,754	1	2	8	348	17	40	Y	Y	N
Choral Room	Music Room	3rd Floor	303	303	1,531	1	2	20	0	0	40	N	Y	Y
Computer Lab	Regular Classroom	1st Floor	116	116	896	1	19	37	109	6	40	Y	Y	N
Computer Lab	Regular Classroom	2nd Floor	213	213	716	1	30	92	84	5	40	Y	N	N
Faculty Lounge	Regular Classroom	3rd Floor	306	306	720	1	0	10	172	8	40	Y	Y	N
Other Instructional Use	Art Room	3rd Floor	324	324	1,075	1	40	80	258	12	40	Y	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	724	1	2	22	84	5	40	Y	N	Y
Regular Classroom	Regular Classroom	1st Floor	102	102	730	1	1	20	84	5	40	Y	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	725	1	2	16	84	5	40	Y	N	Y
Regular Classroom	Regular Classroom	1st Floor	106	106	780	1	2	16	84	5	40	Y	N	N
Regular Classroom	Regular Classroom	1st Floor	118	118	496	0	0	5	40	2	40	Y	N	N
Regular Classroom	Regular Classroom	1st Floor	120	120	496	0	0	5	40	2	40	Y	N	N
Regular Classroom	Art Room	1st Floor	122	122	962	0	0	8	91	5	40	Y	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	720	1	1	19	84	5	40	Y	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	730	1	1	19	84	5	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	720	1	2	19	84	5	40	Y	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	716	1	2	19	84	5	40	Y	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	703	2	23	72	84	5	40	Y	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	726	0	0	19	84	5	40	Y	N	N
Regular Classroom	Office	2nd Floor	214	214	430	0	0	8	40	2	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	720	1	0	6	172	8	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	720	1	0	6	172	8	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	720	1	0	6	172	8	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	720	1	4	14	172	8	40	Y	N	N
Regular Classroom	Science Classroom	3rd Floor	316	316	1,107	1	14	28	258	12	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	317	317	720	1	8	20	172	8	40	Y	N	N
Regular Classroom	Art Room	3rd Floor	318	318	720	1	2	8	172	8	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	319	319	720	1	2	8	172	8	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	320	320	800	1	2	8	166	8	40	Y	Y	N
Regular Classroom	Regular Classroom	4th Floor	410	410	720	1	9	28	176	8	40	Y	Y	N
Regular Classroom	Regular Classroom	4th Floor	412	412	720	1	9	28	176	8	40	Y	Y	N
Regular Classroom	Regular Classroom	4th Floor	414	414	598	1	4	14	90	6	40	Y	Y	N
Regular Classroom	Regular Classroom	4th Floor	416	416	598	1	4	14	90	6	40	Y	Y	N
Regular Classroom	Regular Classroom	4th Floor	418	418	720	1	4	14	176	8	40	Y	Y	N
Regular Classroom	Regular Classroom	4th Floor	420	420	720	1	4	14	176	8	40	Y	Y	Y
Science Lab Level 1	Science Lab Level 1	4th Floor	409	409/411	972	1	4	34	236	11	40	Y	N	N

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Science Lab Level 1	Regular Classroom	4th Floor	413	413	972	1	4	34	236	11	40	Y	N	N
Science Lab Level 1	Science Lab Level 1	4th Floor	419	419	1,075	1	4	30	166	8	40	Y	N	N
Science Lab Level 1	Science Lab Level 1	4th Floor	421	423	1,075	1	4	22	258	12	40	Y	N	N
Science Lab Level 2	Science Lab Level 2	2nd Floor	215	215	1,095	1	2	24	84	5	40	Y	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	309	311	1,075	1	16	40	172	12	40	Y	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	312	312	1,107	1	4	60	258	12	40	Y	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	313	313	1,075	1	0	50	172	12	40	Y	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	315	315	1,075	1	0	50	172	12	40	Y	N	N
Special Education	Office	3rd Floor	314	314	426	1	4	8	86	4	40	Y	Y	N
Store Room	Regular Classroom	1st Floor	124	124	1,017	1	2	13	109	6	40	Y	N	Y
Vacant	Computer Lab	2nd Floor	211	211	720	1	44	19	104	5	40	Y	Y	N
Vacant	Computer Lab	2nd Floor	212	212	1,117	2	56	112	126	7	40	Y	N	N
Vacant	Computer Lab	2nd Floor	216	216	1,185	2	58	116	126	7	40	Y	N	N
Vacant	Regular Classroom	2nd Floor	217	217	745	1	1	12	84	5	40	Y	Y	N
Vacant	Regular Classroom	2nd Floor	218	218	787	1	1	7	84	5	40	Y	Y	N
Vacant	Regular Classroom	2nd Floor	219	219	720	1	2	24	84	5	40	Y	N	N
Vacant	Regular Classroom	2nd Floor	220	220	962	0	0	8	91	5	40	Y	N	N
Vacant	Regular Classroom	2nd Floor	222	222	972	2	2	11	109	6	40	Y	N	N
Vacant	Regular Classroom	2nd Floor	224	224	1,083	1	2	24	113	7	40	Y	N	N