

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1971	3	310,545	\$9,238,468
SITE				\$708,491
Campus Total		·	310,545	\$9,946,959

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	e						
	Entrance Control - Audio	#1 W Main Entrance	1	EA	6	\$497	
	Entrance Control - Audio	#20 N	1	EA	6	\$497	
	Exterior Doors - Exterior FRP Door	#3_Exit W	1	EA	6	\$631	
	Exterior Doors - Exterior FRP Door	#4_Exit W	1	EA	6	\$631	
	Exterior Doors - Exterior FRP Door	#5 S	2	EA	6	\$1,263	
	Exterior Doors - Exterior Steel Door	#1 W Main Entrance	4	EA	6	\$1,922	
	Exterior Doors - Exterior Steel Door	#10 E	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#11 E	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#12 E	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#13 E	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#14 E / Boiler Room	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#15 N / Boiler Room	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#15.1 N	2	EA	6	\$961	Transformer Vault
	Exterior Doors - Exterior Steel Door	#16 N	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#17 NW	4	EA	6	\$1,922	
	Exterior Doors - Exterior Steel Door	#18_Exit N	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#19 N	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#2 W Main entrance	4	EA	6	\$1,922	
	Exterior Doors - Exterior Steel Door	#20 N	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#21 W	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#22 W	1	EA	6	\$481	Stairway



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran	ce						
	Exterior Doors - Exterior Steel Door	#7 E	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#8 E	1	EA	6	\$481	Swimming Pool
	Exterior Doors - Exterior Steel Door	#9 E	1	EA	6	\$481	Swimming Pool
	Exterior Doors - Overhead Rolling/ Garage Door	#15.2	1	EA	6	\$1,433	Outside Storage
	Exterior Doors - Overhead Rolling/ Garage Door	#6 S / Loading Dock Ramp	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	#6.1 S / Loading Dock	1	EA	6	\$1,433	
	Exterior Doors - Side lite	#21 W	1	EA	6	\$313	
	Exterior Doors - Side lite	#7 E	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#10 E	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#11 E	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#12 E	1	EA	6	\$313	Painted Wood Panel
	Exterior Doors - Transom Lite	#13 E	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#14 E	2	EA	6	\$627	Louvers
	Exterior Doors - Transom Lite	#15 N	2	EA	6	\$627	Metal Louvers
	Exterior Doors - Transom Lite	#19 N	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#20 N	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#21 W	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#22 W	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#3_Exit W	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#4_Exit W	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#5 S	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#7 E	4	EA	6	\$1,253	
	Exterior Doors - Transom Lite	#8 E	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#9 E	1	EA	6	\$313	
	Exterior Stairs - Concrete	#15 N	20	LF	6	\$1,635	
	Exterior Stairs - Concrete	#15.1 N	20	LF	6	\$1,635	
	Exterior Stairs - Concrete	#15.2	20	LF	6	\$1,635	
	Exterior Stairs - Concrete	#16 N	20	LF	6	\$1,635	
Found	ation						
	Foundation - Concrete	Entire Building	1,903	LF	7	\$0	
	Superstructure - Concrete	Entire Building	310,245	SF	7	\$0	
	Superstructure - Concrete	Entire Building / North West	300	SF	5	\$0	Cracking in ceiling at adjacent to door #22 & 21; exposed rebar
Lightin	g						
	Exterior Lighting - Wall Mounted	Entire Building	133	EA	6	\$38,403	Clean housing and lenses



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof S	vstem						
	Chimney - Metal Flue	#1	86	LF	6	\$13,600	
	Chimney - Metal Flue	#4	183	LF	6	\$28,940	
	Coping - Metal	#1	2,295	LF	6	\$73,710	
	Coping - Metal	#2	629	LF	6	\$20,202	
	Coping - Metal	#3	919	LF	6	\$29,516	
	Coping - Metal	#4	372	LF	6	\$11,948	
	Downspouts - Interior Downspouts	#1	1,080	LF	6	\$35,892	
	Downspouts - Interior Downspouts	#2	240	LF	6	\$7,976	
	Downspouts - Interior Downspouts	#3	360	LF	6	\$11,964	
	Downspouts - Interior Downspouts	#4	100	LF	6	\$3,323	
	Parapet - 16" - 30" Height	#3	300	LF	6	\$11,986	
	Parapet - Parapet < 16" Height	#1	2,295	LF	6	\$48,900	
	Parapet - Parapet < 16" Height	#3	619	LF	6	\$13,189	
	Parapet - Parapet > 30"	#2	629	LF	6	\$40,206	
	Parapet - Parapet > 30"	#4	372	LF	6	\$23,779	
	Roof Structure - Concrete	#1	61,630	SF	7	\$0	
	Roof Structure - Concrete	#2	16,843	SF	7	\$0	
	Roof Structure - Concrete	#3	33,126	SF	7	\$0	
	Roof Structure - Concrete	#4	11,662	SF	7	\$0	
	Roof - Modified Bitumen	#1	61,630	SF	6	\$579,901	
	Roof - Modified Bitumen	#2	16,843	SF	6	\$158,483	
	Roof - Modified Bitumen	#3	33,126	SF	6	\$311,696	
	Roof - Modified Bitumen	#4	11,662	SF	6	\$109,732	Minor ponding
Walls							
	Canopy - Concrete/ Stucco	Entire Building	215	SF	6	\$7,114	
	Exterior Walls - Concrete Block	Entire Building	42,015	SF	6	\$282,383	
	Exterior Walls - Precast Panel Wall	Entire Building	3,627	SF	5	\$30,030	Vegitative Growth
	Exterior Walls - Precast Panel Wall	Entire Building	3,410	SF	6	\$26,673	
Window	vs						
	Curtain wall - Glazed Double Pane	Entire Building	17,796	SF	6	\$199,515	
	Curtain wall - Insulated Panel	Entire Building	16,534	SF	6	\$185,366	
	Curtain wall - Louver	Entire Building	1,173	SF	6	\$13,151	
	Guard - Guards perforated	Entire Building	8,461	SF	6	\$108,046	
	Skylite - Lexan	Entire Building / Roofs	7,368	SF	6	\$176,061	
	Windows - Sash Aluminum Double-pane	Entire Building	2,473	SF	6	\$18,460	
	Windows - Sash Aluminum	Entire Building	275	SF	5	\$9,875	bad ballasts



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Buildi	ng Exterior Subtotal:				\$	2,670,789	
Buildi	ng: Main						
Categ	ory: Electrical System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Automatic Transfer Switch	Electrical Room	4	EA	6	\$1,632	
	Emergency A/C Power - Auditoium and Aisle Lighting	1st floor, Entire Building / 1st Floor	8,152	SF	6	\$4,313	
	Emergency A/C Power - Corridors and Stairs	1st floor, Entire Building / Entire Building	56,861	SF	6	\$17,075	
	Emergency A/C Power - Gym	1st floor, Entire Building / 1st Floor	15,555	SF	6	\$5,783	
	Emergency A/C Power - Lunchrooms	1st floor, Entire Building / 1st Floor	5,544	SF	6	\$2,061	
	Emergency A/C Power - Pool	1st floor, Entire Building / 1st Floor	4,806	SF	6	\$1,787	
	Emergency A/C Power - Students Toilets	1st floor, Entire Building / Entire Building	3,645	SF	6	\$1,355	
	Emergency Battery Packs - Auditoium and Aisle Lighting	1st Floor	2	EA	6	\$405	older technology
	Emergency Battery Packs - Corridors and Stairs	1st Floor / Entire Building	12	EA	6	\$2,430	
	Emergency Generator- Indoor- Natural Gas - 151 - 200 KW	Mechanical Room	1	EA	7	\$0	
	Exit Signs - Auditoium	1st floor, Entire Building / 1st Floor	16	EA	7	\$0	
	Exit Signs - Corridors and Stairs	1st floor, Entire Building / Entire Building	52	EA	7	\$0	
	Exit Signs - Gym	1st floor, Entire Building / 1st Floor	7	EA	7	\$0	
	Exit Signs - Lunchroom	1st floor, Entire Building / 1st Floor	4	EA	7	\$0	
	Exit Signs - Pool	1st floor, Entire Building / 1st Floor	5	EA	7	\$0	
	Security System - CCTV	Entire Building	310,545	SF	6	\$93,257	
	Security System - Intrusion Detection	Entire Building	310,545	SF	6	\$79,934	
Main Se	ervice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	\$0	2'nd feed from ComEd
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	\$5,641	
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	\$5,641	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	\$10,867	
	PA System	Entire Building	310,545	SF	6	\$102,138	
Power D	Distribution						
	Lighting and Power Panels - 100 A	Electrical Room, Entire Building / Entire Building	18	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Electrical Room, Entire Building / Electrical Room	1	EA	4	\$6,578	corroded, deteriorated fuse panel
	Lighting and Power Panels - Above 100 A	Electrical Room, Entire Building / Electrical Room	1	EA	6	\$497	fuse panel



Building: Main

Category: Electrical System

p Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
r Distribution						
Lighting and Power Panels - Above 100 A	Electrical Room, Entire Building / Electrical Room	1	EA	4	\$6,578	rusted enclosure, corroded contacts, near pool
Lighting and Power Panels - Above 100 A	Electrical Room, Entire Building / Entire Building	3	EA	7	\$0	
Lighting and Power Panels - Above 100 A	Electrical Room, Entire Building / Entire Building	34	EA	7	\$0	
Lighting and Power Panels - Above 100 A	Electrical Room, Entire Building / Entire Building	2	EA	7	\$0	
Main Distribution Panels - 400 - 600 amp	Electrical Room, Entire Building / Electrical Room	1	EA	7	\$0	
Main Distribution Panels - 400 - 600 amp	Electrical Room, Entire Building / Entire Building	4	EA	7	\$0	Westinghouse
Main Distribution Panels - Greater than 600 amp	Electrical Room, Entire Building / Entire Building	4	EA	7	\$0	
Transformers - 277/480 - 120/240	Electrical Room, Entire Building / Entire Building	9	EA	6	\$9,173	

Electrical System Subtotal:

\$357,147

Building: Main

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Ala	arm						
	Fire Alarm Panel	Mechanical Room	1	EA	6	\$6,406	
	Fire Alarm Strobe Lights	Mechanical Room / Entire Building	310,545	SF	6	\$111,020	Some rooms do not have strobes
	Fire Alarm_System	Mechanical Room / Entire Building	310,545	SF	6	\$150,987	
	Fire Pump Controller	Mechanical Room	1	EA	5	\$8,100	
Pump F	Room Assembly						
	Fire Pump - Less than 25hp	Pump Room / Mechanical Room	1	EA	6	\$1,558	Serves only auditorium and near boiler room areas
	Jockey Pump	Pump Room / Mechanical Room	1	EA	6	\$758	Wet system only, no compressor found
Sprinkl	er System						
	Sprinkler Heads	1st Floor	14,000	SF	7	\$0	auditorium and near boiler room areas only
	Sprinkler Piping	1st Floor	14,000	SF	7	\$0	auditorium and near boiler room areas only
	Wet Sprinkler System	1st Floor	14,000	SF	7	\$0	auditorium and near boiler room areas only
Safty	System Subtotal:					\$278,829	

Salty System Subtotal:

Building: Main



Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Con	ditioning						
	Chemical Pot Feeder	Mechanical Room	1	EA	6	\$725	
	Chiller-Water Cooled- Absorber - 201 - 300 tons	Mechanical Room	2	EA	5	\$140,931	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	\$3,334	serves MDF room
	Cooling Tower - Closed Cell- 201 - 300 tons	Mechanical Room / Roof	1	EA	5	\$44,289	
	Glycol Feed	Mechanical Room	1	EA	6	\$490	
	Pipes - Chilled Water Pipe- Copper	Mechanical Room / Entire Building	200	LF	7	\$0	
	Pipes - Chilled Water Pipe- Galvanized	Mechanical Room / Entire Building	800	LF	6	\$1,510	
	Pressure Fill System	Mechanical Room / Entire Building	1	EA	6	\$1,405	
Air Han	dling Systems						
	Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - 15001-20000 cfm	Mechanical Room	1	EA	5	\$64,830	serves 3rd floor classrooms
	Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - 15001-20000 cfm	Mechanical Room	1	EA	6	\$3,350	serve office area
	Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - 6000-10000 cfm	Mechanical Room	1	EA	5	\$42,727	serves band room
	Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - Less than 6000 cfm	Mechanical Room	1	EA	5	\$35,240	6 zones per BAS screen, serves library
	Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - Less than 6000 cfm	Mechanical Room	1	EA	5	\$35,240	serves portion of third floor
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils 10001-15000 cfm	1st Floor	1	EA	5	\$52,178	serves auditorium
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils 6000-10000 cfm	1st Floor	1	EA	5	\$42,727	serves large auditorium
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils 6000-10000 cfm	Mechanical Room	1	EA	5	\$42,727	serves lobby
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils Less than 6000 cfm	1st Floor	1	EA	5	\$35,240	serves kitchen
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils Less than 6000 cfm	1st Floor	1	EA	5	\$35,240	serves food serving area
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils Less than 6000 cfm	1st Floor	1	EA	5	\$35,240	serves little theater
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils Less than 6000 cfm	1st Floor	4	EA	5	\$140,960	serves NW, NE. SW, SE of boy's gym
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils Less than 6000 cfm	2nd Floor	1	EA	5	\$35,240	serves girls' locker room
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils Less than 6000 cfm	2nd Floor	2	EA	5	\$70,480	serve girl's gym West, East
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils Less than 6000 cfm	Basement	1	EA	5	\$35,240	serves gun range in basement
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm	1st Floor	2	EA	5	\$40,746	serves pool
	Air Intake	1st Floor / Roof	1	EA	7	\$0	
	Air Intake	1st Floor / Roof	2	EA	7	\$0	



Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Hane	dling Systems						
	Air Intake	1st Floor / Roof	4	EA	7	\$0	
	Air Intake	1st Floor / Roof	1	EA	7	\$0	
	Air Intake	1st Floor / Roof	1	EA	7	\$0	
	Air Intake	1st Floor / Roof	1	EA	7	\$0	
	Air Intake	1st Floor / Roof	1	EA	7	\$0	
	Air Intake	2nd Floor / Roof	2	EA	7	\$0	
	Air Intake	2nd Floor / Roof	1	EA	7	\$0	
	Air Intake	Basement / Roof	1	EA	7	\$0	
	Air Intake	Mechanical Room / Roof	1	EA	7	\$0	
	Air Intake	Mechanical Room / Roof	1	EA	7	\$0	
	Air Intake	Mechanical Room / Roof	1	EA	5	\$7,471	
	Air Intake	Mechanical Room / Roof	1	EA	7	\$0	
	Air Intake	Mechanical Room / Roof	1	EA	7	\$0	
	Air Intake	Mechanical Room / Roof	1	EA	7	\$0	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - Less than 10 tons	Roof	1	EA	5	\$11,226	3 zones, serves media center rooms
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons	Roof	1	EA	5	\$10,623	serves west side computer room
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons	Roof	1	EA	5	\$10,623	serves south side computer room
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons	Roof	1	EA	5	\$10,623	serves north, computer rooms
	Zone Dampers	Mechanical Room / 1st Floor	9	EA	5	\$17,222	
	Zone Dampers	Mechanical Room / 2nd Floor	3	EA	6	\$2,499	
	Zone Dampers	Mechanical Room / 2nd Floor	6	EA	6	\$4,998	
	Zone Dampers	Mechanical Room / 3rd Floor	4	EA	5	\$7,654	
	Zone Dampers	Mechanical Room / Entire Building	7	EA	6	\$5,831	
Boiler S	ystems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - Greater than 300 HP	Boiler Room	2	EA	6	\$1,996	
	Chemical Feeder	Boiler Room	1	EA	6	\$1,078	
	Combustion Dampers	Boiler Room	2	EA	7	\$0	
	Condensate Pump	Boiler Room / Entire Building	1	EA	6	\$2,021	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	\$2,545	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	2	EA	6	\$1,996	serve heat exchangers
	Piping - Condensate Pipe- Steel	Boiler Room	100	LF	6	\$189	serve heat exchangers
	Piping - Steam Pipe- Steel	Boiler Room	100	LF	6	\$189	serve heat exchangers
	Steam Traps	Boiler Room	7	EA	5	\$9,204	serve heat exchangers and boilers only



Building: Main

Category: Mechanical System

							· ·
•	tem - Type	Location	Quantity	Unit	Rank	Cost	Comments
iler Sy	stems						
`	Vacuum Pump	Boiler Room / Mechanical Room	2	EA	6	\$4,942	serve absorbers
at Excl	nangers						
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	3	EA	6	\$0	
-	Devices						
(Cabinet Heaters - With Hot Water Coil	Entire Building	32	EA	6	\$11,338	
I	Fin Tube - Hot Water	Entire Building	600	LF	6	\$5,663	
I	Jnit Heater - Electric	Entire Building	4	EA	6	\$1,111	
l	Jnit Heater - Hot Water	Entire Building	5	EA	6	\$1,396	
١	Nall Heater - Electric	Entire Building	11	EA	6	\$1,528	
chanic	al Plumbing						
(Condenser Pump - 21 - 50 HP	Mechanical Room	2	EA	6	\$2,485	
I	Daul Temperature Pump - 21 - 50 HP	Mechanical Room	2	EA	6	\$2,485	
I	Hot Water Pump - 21 - 50 HP	Mechanical Room	3	EA	6	\$3,727	One pump per heat exchanger. No back-up pumps.
1	Hydronic Supply and Return - Galvanized	Entire Building	150	LF	6	\$11.598	Condenser water.
	Hydronic Supply and Return - Galvanized	Entire Building	1,550	LF	6	\$119,846	
nperat	ure Control						
	Electric Thermostat	Entire Building	6	EA	6	\$0	for unit heaters
I	Hybrid Pneumatic/DDC System	Entire Building	310,545	SF	6	\$279,770	
-	Thermostats - DDC	Entire Building	186	EA	6	\$0	
-	Thermostats - DDC	Entire Building	10	EA	4	\$8,191	
t Vent	ilation						
	Jnit Ventilators- Ceiling Mounted- Dual Temperature Coils (Hot/Chilled) Nater	Entire Building / 1st Floor	15	EA	5	\$113,589	
I	Jnit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Nater	Entire Building	50	EA	6	\$62,116	
I	Jnit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Nater	Entire Building	8	EA	5	\$68,289	
l	Jnit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Nater	Entire Building	8	EA	6	\$9,939	
ntilatio	n						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building / 2nd Floor	2	EA	6	\$1,185	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / 1st Floor	- 1	EA	6		serves pool
1				-/ `	5	ΨŪŪΖ	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	16	EA	6	\$9,478	



Category: Mechanical System

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntilation						
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	17	EA	6	\$10,071	
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	6	EA	6	\$1,777	
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	4	\$3,884	noisy, deteriorted
Lab Exhaust Hood	Entire Building	4	EA	6	\$4,991	
Roof Mounted Duct Work	Entire Building / Roof	40	LF	6	\$15,161	
Type I Exhaust Hood- Kitchen	Entire Building / 1st Floor	1	EA	6	\$1,248	
Type II Exhaust Hood- Warming Kitchen	Entire Building / 1st Floor	2	EA	6	\$1,840	in serving area
					040 400	

Mechanical System Subtotal:

\$1,819,100

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	er						
	Electric Heater - Less than 20 KW	1st Floor, Boiler Room / 1st Floor	1	EA	6	\$682	serves kitchen
	Electric Heater - Less than 20 KW	1st Floor, Boiler Room / Boiler Room	1	EA	6	\$682	serves art room
	Gas Heater - 150000 - 300000 BTU/HR	Kitchen	1	EA	6	\$310	
	Steam Heat Exchanger	Boiler Room	1	EA	6	\$0	
	Steam Storage Tank - 501 - 1000 Gallons	Boiler Room	1	EA	7	\$0	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	310,545	SF	6	\$62,171	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	310,545	SF	6	\$75,493	
	Domestic Piping-Cold Water Risers	Entire Building	310,545	SF	6	\$57,730	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	310,545	SF	6	\$48,849	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	310,545	SF	6	\$57,730	
	Domestic Piping-Hot Water Return Lines	Entire Building	310,545	SF	6	\$44,408	
	Domestic Piping-Hot Water Return Risers	Entire Building	310,545	SF	6	\$44,408	
	Sanitary Piping	Entire Building	310,545	SF	6	\$284,211	
	Storm Piping	Entire Building	310,545	SF	6	\$270,888	
	Vent Piping	Entire Building	310,545	SF	6	\$208,717	
Pool Sy	stems						
	Pool Drain Piping	Pool Area / Basement	100	LF	6	\$2,863	
	Pool Filtration System including Pump	Pool Area / Basement	1	EA	6	\$12,330	
	Pool Hot Water Heater - Gas Fired	Pool Area / 1st Floor	1	EA	7	\$0	
	Pool Supply and Return Piping	Pool Area / Basement	100	LF	6	\$4,805	



Category: Plumbing System

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
Pumps						
Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	6	\$1,446	
Pumps - Ejector-Simplex	Mechanical Room	1	EA	6	\$745	
Pumps - Sump-Simplex	Mechanical Room / 1st Floor	1	EA	6	\$745	
Pumps - Sump-Simplex	Mechanical Room / Boiler Room	1	EA	6	\$745	
Plumbing System Subtotal:				\$1	,179,960	

Plumbing System Subtotal:

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #004 (Fitness Room)						
	Ceiling - Exposed	Basement	2,450	SF	6	\$3,644	
	Doors - Side-lite	Basement	5	SF	6	\$84	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	\$602	
	Floor - Concrete	Basement	2,450	SF	6	\$1,296	
	Lighting - Pendent/Surface	Basement	59	EA	7	\$0	
	Storage/ Closet	Basement	252	SF	6	\$1,827	
	Walls - Concrete Block	Basement	2,100	SF	6	\$6,156	
Classro	oom #005 (Weight)						
	Ceiling - Exposed	Basement	2,415	SF	6	\$3,592	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	\$602	
	Floor - Tile	Basement	665	SF	6	\$1,455	Rubber tiles
	Floor - Weight/ Fitness Room Floor Matting	Basement	1,750	SF	6	\$9,159	
	Lighting - Pendent/Surface	Basement	56	EA	7	\$0	
	Student Lockers - Two Tiers	Basement	184	EA	6	\$8,541	
	Wall Mirrors	Basement	200	SF	6	\$0	
	Walls - Concrete Block	Basement	1,690	SF	6	\$4,954	
Classro	oom #105 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	1,172	SF	6	\$3,520	
	Ceiling - Lay-in	1st Floor	128	SF	5	\$1,021	damaged
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	\$903	
	Floor - Tile	1st Floor	1,300	SF	6	\$2,844	
	Lighting - Pendent/Surface	1st Floor	57	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,480	SF	6	\$4,339	
	Wireless System	1st Floor	1	EA	7	\$0	



..... B

Building: Main						
Category: Classrooms						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #105 (Computer Lab)						
Classroom #106 (Art Room)						
Ceiling - Lay-in	1st Floor	1,600	SF	6	\$4,805	
Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	
Floor - Tile	1st Floor	1,600	SF	6	\$3,501	
Lighting - Pendent/Surface	1st Floor	52	EA	7	\$0	
Marker Board	1st Floor	10	LF	7	\$0	
Walls - Concrete Block	1st Floor	1,755	SF	6	\$5,145	
Work Sink	1st Floor	1	EA	6	\$379	
Classroom #107 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	1,600	SF	6	\$4,805	
Doors - Wood Doors inclu hw	1st Floor	4	EA	7	\$0	
Floor - Tile	1st Floor	1,600	SF	6	\$3,501	
Lighting - Pendent/Surface	1st Floor	57	EA	7	\$0	
Marker Board	1st Floor	10	LF	7	\$0	
Storage/ Closet	1st Floor	124	SF	6	\$899	
Walls - Concrete Block	1st Floor	1,755	SF	6	\$5,145	
Classroom #108 (Other Instructional Use)						
Ceiling - Lay-in	1st Floor	1,596	SF	6	\$4,793	
Ceiling - Lay-in	1st Floor	4	SF	5	\$32	damaged
Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	
Floor - Tile	1st Floor	1,600	SF	6	\$3,501	
Lighting - Lay-in	1st Floor	8	EA	6	\$952	
Lighting - Pendent/Surface	1st Floor	58	EA	7	\$0	
Marker Board	1st Floor	30	LF	7	\$0	
Storage/ Closet	1st Floor	140	SF	6	\$1,015	
Walls - Concrete Block	1st Floor	1,755	SF	6	\$5,145	
Classroom #110 (Laboratory/Shop)						
Casework	1st Floor	20	LF	6	\$505	
Ceiling - Lay-in	1st Floor	684	SF	6	\$2,054	
Ceiling - Lay-in	1st Floor	16	SF	5	\$128	
Doors - Wood Doors inclu hw	1st Floor	3	EA	6	\$903	
Floor - Tile	1st Floor	700	SF	6	\$1,532	
Lighting - Pendent/Surface	1st Floor	45	EA	7	\$0	
		10		-	^	

1st Floor

Marker Board

16 LF 7

\$0



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	bom #110 (Laboratory/Shop)	Location	quantity	0		0000	
0100010	Storage/ Closet	1st Floor	250	SF	6	\$1,813	
	Walls - Concrete Block	1st Floor	825	SF	6	\$2,418	
	Work Sink	1st Floor	1	EA	6	\$379	
				2/1	Ũ	Q 010	
Classro	oom #111 (Art Room)						
	Ceiling - Plaster/Drywall	1st Floor	2,162	SF	6	\$7,482	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	2,162	SF	6	\$4,730	
	Lighting - Pendent/Surface	1st Floor	37	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	11	EA	6	\$1,363	
	Walls - Concrete Block	1st Floor	2,784	SF	6	\$8,161	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #114 (Dance Room)						
	Ceiling - Plaster/Drywall	1st Floor	2,166	SF	6	\$7,496	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	\$1,505	
	Floor - Wood	1st Floor	2,166	SF	6	\$15,270	
	Lighting - Pendent/Surface	1st Floor	60	EA	7	\$0	
	Marker Board	1st Floor	10	LF	7	\$0	
	Storage/ Closet	1st Floor	6	SF	6	\$44	
	Wall Mirrors	1st Floor	557	EA	7	\$0	
	Walls - Concrete Block	1st Floor	3,251	SF	6	\$9,530	
Classro	oom #118 (Special Education)						
	Ceiling - Lay-in	1st Floor	3,120	SF	7	\$0	
	Doors - Steel Doors incl hw	1st Floor	9	EA	6	\$2,709	
	Floor - Tile	1st Floor	3,120	SF	6	\$6,826	
	Lighting - Lay-in	1st Floor	35	EA	7	\$0	
	Marker Board	1st Floor	10	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,000	SF	6	\$2,932	
	Walls - Plaster/Drywall	1st Floor	1,750	SF	6	\$4,830	
	Work Sink	1st Floor	2	EA	6	\$758	
Classro	oom #200 (Store Room)						
	Ceiling - Lay-in	2nd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	2nd Floor	9	EA	7	\$0	



Building: Main

Groun	Itom Tuno	Location	Quertite	l lesit	Dank	Cost	Commente
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #200 (Store Room)	- · · -:		. –		^	
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	420	SF	6	\$1,231	
	Walls - Plaster/Drywall	2nd Floor	220	SF	6	\$607	
Classro	oom #202 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	694	SF	6	\$2,084	
	Ceiling - Lay-in	2nd Floor	6	SF	5	\$48	water damaged
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	2nd Floor	9	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	640	SF	6	\$1,876	
Classro	om #204 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	677	SF	6	\$2,033	
	Ceiling - Lay-in	2nd Floor	23	SF	5	\$184	
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	700	SF	6	\$701	
	Lighting - Lay-in	2nd Floor	9	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	640	SF	6	\$1,876	
Classro	oom #206 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	688	SF	6	\$2,066	
	Ceiling - Lay-in	2nd Floor	12	SF	5	\$96	water damaged
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	2nd Floor	9	EA	7	\$0	
	Marker Board	2nd Floor	28	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	640	SF	6	\$1,876	
Classro	oom #208 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	871	SF	6	\$2,616	
	Ceiling - Lay-in	2nd Floor	4	SF	5	\$32	water damaged
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	875	SF	6	\$876	



-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #208 (Regular Classroom)						
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	720	SF	6	\$2,111	
Classro	oom #210 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	693	SF	6	\$2,081	
	Ceiling - Lay-in	2nd Floor	7	SF	5	\$56	water damaged
	Doors - Side-lite	2nd Floor	64	SF	6	\$1,070	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	2nd Floor	9	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	640	SF	6	\$1,876	
Classro	oom #212 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	863	SF	6	\$2,592	
	Ceiling - Lay-in	2nd Floor	12	SF	5	\$96	water damage
	Doors - Side-lite	2nd Floor	71	SF	6	\$1,187	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	875	SF	6	\$1,914	
	Floor - Tile	2nd Floor	1	SF	5	\$6	Electrical boxes protruding from the floor are a tripping hazard
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	11 0
	Marker Board	2nd Floor	24	LF	7	\$0	
	Storage/ Closet	2nd Floor	115	SF	6	\$834	Rm 212A
	Walls - Concrete Block	2nd Floor	720	SF	6	\$2,111	
Classro	oom #214 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	\$152	
	Ceiling - Lay-in	2nd Floor	1,150	SF	6	\$3,453	
	Ceiling - Lay-in	2nd Floor	10	SF	5	\$80	water damaged
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	1,160	SF	6	\$2,538	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	800	SF	6	\$2,345	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	bom #216 (Special Education)		,	•••••			
	Ceiling - Lay-in	2nd Floor	1,152	SF	6	\$3,459	
	Ceiling - Lay-in	2nd Floor	8	SF	5		water damage
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	5
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	1,160	SF	6	\$2,538	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	800	SF	6	\$2,345	
	Work Sink	2nd Floor	4	EA	6	\$1,516	
Classro	oom #218 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	865	SF	6	\$2,598	
	Ceiling - Lay-in	2nd Floor	10	SF	5		water damaged
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	875	SF	6	\$1,914	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	720	SF	6	\$2,111	
Classro	oom #220 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	870	SF	6	\$2,613	
	Ceiling - Lay-in	2nd Floor	5	SF	5	\$40	water damage
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	875	SF	6	\$1,914	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	720	SF	6	\$2,111	
Classro	oom #222 (Music Room)						
	Ceiling - Splined	2nd Floor	1,500	SF	6	\$1,223	
	Doors - Wood Doors inclu hw	2nd Floor	6	EA	6	\$1,806	*including 5 doors to practice booths
	Floor - Tile	2nd Floor	1,470	SF	6	\$3,216	
	Floor - Tile	2nd Floor	30	SF	5	\$173	damaged
	Lighting - Pendent/Surface	2nd Floor	40	EA	5	\$7,303	Room lights are not working, waiting on an electrician to come check out why
	Lighting - Pendent/Surface	2nd Floor	7	EA	7	\$0	lights in practice booth & passage, are working
	Sound Panels	2nd Floor	2,000	EA	6	\$8,065	



Building: Main

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #222 (Music Room)						
Storage/ Closet	2nd Floor	276	SF	6	\$2,001	
Walls - Concrete Block	2nd Floor	3,392	SF	6	\$9,944	has acoustic panels applied
Classroom #224 (Music Room)						
Ceiling - Splined	2nd Floor	1,500	SF	6	\$1,223	
Doors - Side-lite	2nd Floor	7	SF	6	\$117	
Doors - Wood Doors inclu hw	2nd Floor	7	EA	6	\$2,107	*including 5 doors to practice booths
Floor - Tile	2nd Floor	1,496	SF	6	\$3,273	
Floor - Tile	2nd Floor	4	SF	5	\$23	damaged
Lighting - Pendent/Surface	2nd Floor	47	EA	7	\$0	
Marker Board	2nd Floor	12	LF	7	\$0	
Sound Panels	2nd Floor	2,000	EA	6	\$8,065	
Storage/ Closet	2nd Floor	240	SF	6	\$1,740	
Walls - Concrete Block	2nd Floor	3,392	SF	6	\$9,944	with acoustic panels applied
Work Sink	2nd Floor	1	EA	6	\$379	
Classroom #226 (Choral Room)						
Ceiling - Splined	2nd Floor	1,300	SF	6	\$1,060	
Doors - Side-lite	2nd Floor	14	SF	6	\$234	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
Floor - Tile	2nd Floor	1,250	SF	6	\$2,735	
Floor - Tile	2nd Floor	50	SF	5	\$288	damaged
Lighting - Pendent/Surface	2nd Floor	27	EA	7	\$0	
Marker Board	2nd Floor	6	LF	7	\$0	
Risers	2nd Floor	135	LF	6	\$3,039	
Sound Panels	2nd Floor	600	EA	6	\$2,420	
Walls - Concrete Block	2nd Floor	220	SF	6	\$645	
Walls - Plaster/Drywall	2nd Floor	300	SF	6	\$828	
Classroom #226 A, B, C & D (Choral Room)						
Ceiling - Lay-in	2nd Floor	260	SF	6	\$781	
Doors - Side-lite	2nd Floor	136	SF	6	\$2,273	
Doors - Wood Doors inclu hw	2nd Floor	5	EA	6	\$1,505	
Floor - Tile	2nd Floor	235	SF	6	\$514	
Floor - Tile	2nd Floor	25	SF	5	\$144	damaged
Lighting - Pendent/Surface	2nd Floor	11	EA	7	\$0	
Sound Panels	2nd Floor	720	EA	6	\$2,903	
Walls - Concrete Block	2nd Floor	960	SF	6	\$2,814	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #228 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	1,010	SF	6	\$3,033	
	Ceiling - Lay-in	2nd Floor	5	SF	5		water damaged
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	-
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	1,015	SF	6	\$2,221	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	760	SF	6	\$2,228	
Classr	oom #230 (Science Lab Level 1)						
	Casework	2nd Floor	52	LF	6	\$1,313	
	Ceiling - Lay-in	2nd Floor	1,305	SF	6	\$3,919	
	Ceiling - Lay-in	2nd Floor	15	SF	5	\$120	water damaged
	Doors - Side-lite	2nd Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Eye Wash Station	2nd Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	2nd Floor	1,314	SF	6	\$1,315	
	Floor - Tile/Sheet	2nd Floor	6	SF	5	\$35	lifting at seams
	Fume Hood	2nd Floor	1	EA	6	\$816	
	Gas Line	2nd Floor	22	EA	6	\$11,201	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Science Lab Elements	2nd Floor	30	SF	6	\$203	
	Science Lab Shower	2nd Floor	1	EA	6	\$379	
	Walls - Concrete Block	2nd Floor	1,140	SF	6	\$3,342	
	Work Sink	2nd Floor	10	EA	6	\$3,790	
Classro	oom #232 (Science Lab Level 1)						
	Casework	2nd Floor	52	LF	6	\$1,313	
	Ceiling - Lay-in	2nd Floor	1,320	SF	6	\$3,964	
	Doors - Side-lite	2nd Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Eye Wash Station	2nd Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	2nd Floor	1,320	SF	6	\$1,321	
	Fume Hood	2nd Floor	1	EA	6	\$816	
	Gas Line	2nd Floor	22	EA	6	\$11,201	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	



	,,						
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #232 (Science Lab Level 1)						
	Science Lab Elements	2nd Floor	30	SF	6	\$203	
	Science Lab Shower	2nd Floor	1	EA	6	\$379	
	Walls - Concrete Block	2nd Floor	1,140	SF	6	\$3,342	
	Work Sink	2nd Floor	10	EA	6	\$3,790	
Classro	oom #234 (Art Room)						
	Ceiling - Lay-in	2nd Floor	1,603	SF	6	\$4,814	
	Ceiling - Lay-in	2nd Floor	7	SF	5	\$56	damaged
	Doors - Side-lite	2nd Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	1,610	SF	6	\$3,523	
	Instructional Surface	2nd Floor	12	LF	6	\$404	
	Lighting - Lay-in	2nd Floor	27	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	920	SF	6	\$2,697	
	Work Sink	2nd Floor	2	EA	6	\$758	The ADA sink is missing a faucet knob
Classro	oom #236 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	1,154	SF	6	\$3,465	
	Ceiling - Lay-in	2nd Floor	4	SF	5	\$32	damaged
	Doors - Side-lite	2nd Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	1,160	SF	6	\$2,538	
	Lighting - Lay-in	2nd Floor	18	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	800	SF	6	\$2,345	
Classro	oom #238 (Special Education)						
	Ceiling - Lay-in	2nd Floor	1,150	SF	6	\$3,453	
	Ceiling - Lay-in	2nd Floor	10	SF	5	\$80	water damaged
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	1,160	SF	6	\$2,538	
	Lighting - Lay-in	2nd Floor	18	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	560	SF	6	\$1,642	
	Walls - Plaster/Drywall	2nd Floor	240	SF	6	\$662	



Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ssro	oom #240 (Laboratory/Shop)						
	Ceiling - Lay-in	2nd Floor	1,160	SF	6	\$3,483	
	Ceiling - Lay-in	2nd Floor	10	SF	5	\$80	water damaged
	Doors - Side-lite	2nd Floor	64	SF	6	\$1,070	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	1,170	SF	6	\$2,560	
	Lighting - Lay-in	2nd Floor	25	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Storage/ Closet	2nd Floor	161	SF	6	\$1,167	
	Walls - Concrete Block	2nd Floor	400	SF	6	\$1,173	
	Walls - Plaster/Drywall	2nd Floor	327	SF	6	\$902	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	\$15	damaged
ssro	oom #241 (Special Education)						
	Ceiling - Lay-in	2nd Floor	577	SF	6	\$1,733	
	Ceiling - Lay-in	2nd Floor	5	SF	5	\$40	water damaged
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	582	SF	6	\$1,273	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	972	SF	6	\$2,849	
ssro	oom #242 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	845	SF	6	\$2,538	
	Ceiling - Lay-in	2nd Floor	10	SF	5	\$80	water damaged
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	851	SF	6	\$1,862	
	Floor - Tile	2nd Floor	4	SF	5	\$23	damaged
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Storage/ Closet	2nd Floor	194	SF	6	\$1,407	about 4' of water damage on ceiling
	Walls - Concrete Block	2nd Floor	470	SF	6	\$1,378	
	Walls - Plaster/Drywall	2nd Floor	155	SF	6	\$428	
	Wireless System	2nd Floor	1	EA	6	\$372	
ssro	oom #244 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	850	SF	6	\$2,553	
	Ceiling - Lay-in	2nd Floor	5	SF	5	\$40	water damaged



_	,,		-			-	•
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #244 (Regular Classroom)						
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	855	SF	6	\$856	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	725	SF	6	\$2,125	
Classro	oom #246 (Store Room)						
	Ceiling - Lay-in	2nd Floor	710	SF	6	\$2,132	
	Ceiling - Lay-in	2nd Floor	5	SF	5	\$40	water damaged
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	638	SF	6	\$1,870	
	Walls - Concrete Block	2nd Floor	2	SF	5		damaged
Classro	oom #248 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	1,233	SF	6	\$3,703	
	Ceiling - Lay-in	2nd Floor	25	SF	5	\$199	water damage
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	-
	Floor - Tile	2nd Floor	1,288	SF	6	\$2,818	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	595	SF	6	\$1,744	
	Walls - Concrete Block	2nd Floor	5	SF	5	\$70	crack
	Walls - Plaster/Drywall	2nd Floor	240	SF	6	\$662	
Classro	oom #300 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	420	SF	6	\$1,231	
	Walls - Plaster/Drywall	3rd Floor	220	SF	6	\$607	



			-			-	•
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #302 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
lassro	om #304 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
lassro	om #306 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	15	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
lassro	om #308 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	875	SF	6	\$2,628	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	875	SF	6	\$1,914	
	Lighting - Lay-in	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	720	SF	6	\$2,111	
lassro	om #310 (Computer Lab)						
	Ceiling - Lay-in	3rd Floor	975	SF	6	\$2,928	
	Doors - Side-lite	3rd Floor	92	SF	6	\$1,538	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassroo	om #310 (Computer Lab)						
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	620	SF	6	\$1,818	
	Walls - Plaster/Drywall	3rd Floor	200	SF	6	\$552	
	Wireless System	3rd Floor	1	EA	6	\$372	
assroo	om #312 (Computer Lab)						
	Ceiling - Lay-in	3rd Floor	975	SF	6	\$2,928	
	Doors - Side-lite	3rd Floor	7	SF	5	\$490	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	975	SF	6	\$2,133	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	820	SF	6	\$2,404	
	Wireless System	3rd Floor	1	EA	6	\$372	
assroo	om #314 (Vacant)						
	Ceiling - Lay-in	3rd Floor	870	SF	6	\$2,613	
	Ceiling - Lay-in	3rd Floor	4	SF	5	\$32	water damaged
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	-
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	875	SF	6	\$876	
	Lighting - Lay-in	3rd Floor	10	EA	7	\$0	
	Marker Board	3rd Floor	16	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	713	SF	6	\$2,090	
	Walls - Concrete Block	3rd Floor	7	SF	5	\$99	crack in the wall
assroo	om #316 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
assroo	om #318 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	



up Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
sroom #318 (Regular Classroom)						
Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - Tile	3rd Floor	700	SF	6	\$1,532	
Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
Marker Board	3rd Floor	24	LF	7	\$0	
Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
sroom #320 (Regular Classroom)						
Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
Doors - Side-lite	3rd Floor	7	SF	6	\$117	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - Tile	3rd Floor	700	SF	6	\$1,532	
Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
Marker Board	3rd Floor	24	LF	7	\$0	
Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
sroom #322 (Regular Classroom)						
Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
Doors - Side-lite	3rd Floor	7	SF	6	\$117	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - Tile	3rd Floor	700	SF	6	\$1,532	
Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
Marker Board	3rd Floor	15	LF	7	\$0	
Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
sroom #324 (Regular Classroom)						
Ceiling - Lay-in	3rd Floor	874	SF	6	\$2,625	
Ceiling - Lay-in	3rd Floor	1	SF	5	\$8	water damage
Doors - Side-lite	3rd Floor	7	SF	6	\$117	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - Tile	3rd Floor	875	SF	6	\$1,914	
Lighting - Lay-in	3rd Floor	12	EA	7	\$0	
Marker Board	3rd Floor	24	LF	7	\$0	
Walls - Concrete Block	3rd Floor	476	SF	6	\$1,395	
Walls - Concrete Block	3rd Floor	4	SF	5	\$56	damaged
Walls - Plaster/Drywall	3rd Floor	240	SF	6	\$662	
sroom #326 (Regular Classroom)						
Ceiling - Lay-in	3rd Floor	875	SF	6	\$2,628	
Doors - Side-lite	3rd Floor	7	SF	6	\$117	



Building: Main

-	Item - Type	Location	Quantity	l Ini+	Pank	Cost	Comments
-	om #326 (Regular Classroom)	Location	Quantity	Unit	Nalik	COSL	Comments
13310	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	875	SF	6	\$301 \$1,914	
		3rd Floor	12	EA	7	\$1,914 \$0	
	Lighting - Lay-in Marker Board	3rd Floor	20		7	\$0 \$0	
	Walls - Concrete Block	3rd Floor		SF			
	Walls - Concrete Block	3rd Floor	720	55	6	\$2,111	
assro	om #328 (Special Education)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	692	SF	6	\$1,514	
	Floor - Tile	3rd Floor	8	SF	5	\$46	damaged
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	16	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
issro	om #330 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	695	SF	6	\$1,521	
	Floor - Tile	3rd Floor	5	SF	5	\$29	damaged
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	-
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
ssro	om #332 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	536	SF	6	\$1,571	
	Walls - Plaster/Drywall	3rd Floor	104	SF	6	\$287	
assro	om #334 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #334 (Regular Classroom)	Location	wantity	U.III	Kulik	0031	Common to
433100	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0 \$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
	Waiis - Concrete Diock	514 1100	040	31	0	φ1,070	
assro	om #336 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
assro	om #338 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
Issro	om #339 (Special Education)						
	Ceiling - Lay-in	3rd Floor	712	SF	6	\$2,138	
	Doors - Side-lite	3rd Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile	3rd Floor	712	SF	6	\$1,558	
	Lighting - Lay-in	3rd Floor	10	EA	7	\$0	
	Marker Board	3rd Floor	8	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	916	SF	6	\$2,685	
assro	om #340 (Store Room)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	46	SF	6	\$769	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	695	SF	6	\$1,521	
	Floor - Tile	3rd Floor	5	SF	5	\$ 00	damaged



	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	bom #340 (Store Room)	Location	quantity	onit	Kunk	0031	Comments
0103510	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	16	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
			0.0	0.	0	¢.,010	
Classro	oom #342 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	875	SF	6	\$2,628	
	Doors - Side-lite	3rd Floor	46	SF	6	\$769	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	8	SF	6	\$8	
	Floor - Tile	3rd Floor	867	SF	6	\$1,897	
	Lighting - Lay-in	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	720	SF	6	\$2,111	
Classro	oom #344 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	700	SF	6	\$2,102	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	700	SF	6	\$1,532	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	640	SF	6	\$1,876	
Classro	oom #346 (Science Lab Level 1)						
	Casework	3rd Floor	44	LF	6	\$1,111	
	Ceiling - Lay-in	3rd Floor	1,015	SF	6	\$3,048	
	Doors - Side-lite	3rd Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd Floor	1,015	SF	6	\$1,016	
	Fume Hood	3rd Floor	. 1	EA	6	\$816	
	Gas Line	3rd Floor	6	EA	6	\$3,055	
	Lighting - Lay-in	3rd Floor	13	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Science Lab Elements	3rd Floor	9	SF	6	\$61	
	Walls - Concrete Block	3rd Floor	760	SF	6	\$2,228	
	Work Sink	3rd Floor	3	EA	6	\$1,137	
Classro	oom #348 (Science Lab Level 3)						
	Ceiling - Lay-in	3rd Floor	1,170	SF	6	\$3,514	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	boom #348 (Science Lab Level 3)	Location	Qualitity	Unit	Nann	COSL	Comments
018551	Doors - Side-lite	3rd Floor	63	SF	6	\$1,053	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$1,053 \$301	
	Floor - Tile/Sheet	3rd Floor	1,170	SF	6	\$301 \$1,171	
	Gas Line	3rd Floor	10	EA	6	\$5,091	
	Lighting - Lay-in	3rd Floor	10	EA	7	\$5,091 \$0	
	Marker Board	3rd Floor	12		7	\$0 \$0	
	Science Lab Elements	3rd Floor	1,170	SF	6		
		3rd Floor		SF		\$7,930	
	Walls - Concrete Block	3rd Floor	400	SF	6	\$1,173	
	Walls - Plaster/Drywall		330		6	\$911	
	Work Sink	3rd Floor	3	EA	6	\$1,137	
Classro	oom #350 (Science Lab Level 1)						
	Casework	3rd Floor	40	LF	6	\$1,010	
	Ceiling - Lay-in	3rd Floor	1,170	SF	6	\$3,514	
	Doors - Side-lite	3rd Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	3rd Floor	1,750	SF	6	\$1,752	
	Fume Hood	3rd Floor	1	EA	6	\$816	
	Lighting - Lay-in	3rd Floor	19	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Science Lab Elements	3rd Floor	30	SF	6	\$203	
	Science Lab Shower	3rd Floor	1	EA	6	\$379	
	Storage/ Closet	3rd Floor	41	SF	6	\$297	Rm 341B
	Walls - Concrete Block	3rd Floor	700	SF	6	\$2,052	
	Walls - Plaster/Drywall	3rd Floor	210	SF	6	\$580	
	Work Sink	3rd Floor	10	EA	6	\$3,790	
Classro	oom #352 (Science Lab Level 3)						
Clabert	Casework	3rd Floor	40	LF	6	\$1,010	
	Ceiling - Lay-in	3rd Floor	873	SF	6	\$2,622	
	Ceiling - Lay-in	3rd Floor	2	SF	5		water stains
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	3	SF	5		damaged
	Floor - Tile/Sheet	3rd Floor	872	SF	6	\$873	
	Lighting - Lay-in	3rd Floor	12	EA	7	\$075 \$0	
	Marker Board	3rd Floor	28	LF	7	\$0 \$0	
			20		,	ψΟ	



Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comme
lassro	om #352 (Science Lab Level 3)						
	Science Lab Elements	3rd Floor	3	SF	6	\$20	
	Walls - Concrete Block	3rd Floor	720	SF	6	\$2,111	
	Work Sink	3rd Floor	1	EA	6	\$379	
Classro	om #354 (Science Lab Level 3)						
	Casework	3rd Floor	6	LF	6	\$152	
	Ceiling - Lay-in	3rd Floor	875	SF	6	\$2,628	
	Doors - Side-lite	3rd Floor	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	845	SF	6	\$846	
	Floor - Tile/Sheet	3rd Floor	30	SF	5	\$173	damaged
	Lighting - Lay-in	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Science Lab Elements	3rd Floor	12	SF	6	\$81	
	Walls - Concrete Block	3rd Floor	480	SF	6	\$1,407	
	Walls - Plaster/Drywall	3rd Floor	240	SF	6	\$662	
	Work Sink	3rd Floor	1	EA	6	\$379	
lassr	ooms Subtotal:					\$711,497	

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comment
Admini	strative Suites/Offices						
	Ceiling - Exposed	012 - Athletic office	210	SF	6	\$312	
	Doors - Wood Doors inclu hw	012 - Athletic office	2	EA	6	\$602	
	Floor - Tile	012 - Athletic office	210	SF	6	\$459	
	Lighting - Pendent/Surface	012 - Athletic office	4	EA	7	\$0	
	Power Distribution	012 - Athletic office	4	EA	7	\$0	
	Walls - Masonry	012 - Athletic office	580	SF	6	\$1,825	
	Ceiling - Exposed	014 - Girl's locker room office	168	SF	6	\$250	
	Doors - Wood Doors inclu hw	014 - Girl's locker room office	1	EA	6	\$301	
	Floor - Tile	014 - Girl's locker room office	168	SF	6	\$368	
	Lighting - Pendent/Surface	014 - Girl's locker room office	4	EA	7	\$0	
	Power Distribution	014 - Girl's locker room office	4	EA	7	\$0	
	Walls - Concrete Block	014 - Girl's locker room office	520	SF	6	\$1,524	
	Ceiling - Exposed	030A - Girl's Locker Room Office	88	SF	6	\$131	



roup Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
dministrative Suites	o/Offices						
Doors - Wood	d Doors inclu hw	030A - Girl's Locker Room Office	1	EA	6	\$301	
Floor - Tile		030A - Girl's Locker Room Office	88	SF	6	\$193	Rubber tile
Lighting - Pe	ndent/Surface	030A - Girl's Locker Room Office	2	EA	7	\$0	
Power Distrib	ution	030A - Girl's Locker Room Office	4	EA	7	\$0	
Walls - Conci	rete Block	030A - Girl's Locker Room Office	376	SF	6	\$1,102	
Ceiling - Lay-	in	100 - Main Office	28	SF	5	\$223	
Ceiling - Lay-	in	100 - Main Office	672	SF	6	\$2,018	
Doors - Trans	som Window	100 - Main Office	12	SF	6	\$203	Solid wood panel
Doors - Wood	d Doors inclu hw	100 - Main Office	2	EA	6	\$602	
Floor - Carpet	t	100 - Main Office	360	SF	6	\$767	
Floor - Tile		100 - Main Office	340	SF	6	\$744	
Lighting - Pe	ndent/Surface	100 - Main Office	30	EA	7	\$0	
Power Distrib	ution	100 - Main Office	6	EA	7	\$0	
Storage/ Clos	et	100 - Main Office	360	SF	6	\$2,610	
Walls - Concr	rete Block	100 - Main Office	672	SF	6	\$1,970	
Walls - Plaste	er/Drywall	100 - Main Office	160	SF	6	\$442	
Ceiling - Lay-	in	100B - Program Office	300	SF	6	\$901	
Doors - Side-	lite	100B - Program Office	7	SF	6	\$117	
Doors - Trans	som Window	100B - Program Office	54	SF	6	\$914	
Doors - Wood	d Doors inclu hw	100B - Program Office	1	EA	6	\$301	
Floor - Carpet	t	100B - Program Office	300	SF	6	\$639	
Lighting - Pe	ndent/Surface	100B - Program Office	8	EA	7	\$0	
Power Distrib	ution	100B - Program Office	8	EA	7	\$0	
Walls - Concr	rete Block	100B - Program Office	885	SF	6	\$2,594	
Ceiling - Lay-	in	100C - Clerk office	135	SF	6	\$405	
Doors - Side-	lite	100C - Clerk office	7	SF	6	\$117	
Doors - Trans	som Window	100C - Clerk office	45	SF	6	\$762	
Doors - Wood	d Doors inclu hw	100C - Clerk office	2	EA	6	\$602	
Floor - Carpet	t	100C - Clerk office	135	SF	6	\$288	
Lighting - Lay	y-in	100C - Clerk office	4	EA	7	\$0	
Power Distrib	ution	100C - Clerk office	6	EA	7	\$0	
Storage/ Clos	et	100C - Clerk office	25	SF	6	\$181	
Walls - Concr	rete Block	100C - Clerk office	512	SF	6	\$1,501	
Ceiling - Lay-	in	100E - Principal's office	350	SF	6	\$1,051	
Doors - Side-		100E - Principal's office	14	SF	6	\$234	
Doors - Trans	som Window	100E - Principal's office	72	SF	6	\$1,219	
Doors - Wood	d Doors inclu hw	100E - Principal's office	3	EA	6	\$903	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dminis	trative Suites/Offices						
	Floor - Carpet	100E - Principal's office	350	SF	6	\$746	
	Lighting - Pendent/Surface	100E - Principal's office	10	EA	7	\$0	
	Power Distribution	100E - Principal's office	8	EA	7	\$0	
	Storage/ Closet	100E - Principal's office	25	SF	6	\$181	
	Walls - Concrete Block	100E - Principal's office	832	SF	6	\$2,439	
	Ceiling - Lay-in	100H - Office	135	SF	6	\$405	
	Doors - Side-lite	100H - Office	7	SF	6	\$117	
	Doors - Transom Window	100H - Office	45	SF	6	\$762	
	Doors - Wood Doors inclu hw	100H - Office	1	EA	6	\$301	
	Floor - Carpet	100H - Office	135	SF	6	\$288	
	Lighting - Pendent/Surface	100H - Office	4	EA	7	\$0	
	Power Distribution	100H - Office	4	EA	7	\$0	
	Walls - Concrete Block	100H - Office	512	SF	6	\$1,501	
	Ceiling - Lay-in	100J - Conference Room	300	SF	6	\$901	
	Doors - Side-lite	100J - Conference Room	7	SF	6	\$117	
	Doors - Transom Window	100J - Conference Room	72	SF	6	\$1,219	
	Doors - Wood Doors inclu hw	100J - Conference Room	1	EA	6	\$301	
	Floor - Carpet	100J - Conference Room	300	SF	6	\$639	
	Lighting - Pendent/Surface	100J - Conference Room	12	EA	7	\$0	
	Power Distribution	100J - Conference Room	8	EA	7	\$0	
	Storage/ Closet	100J - Conference Room	25	SF	6	\$181	
	Walls - Concrete Block	100J - Conference Room	747	SF	6	\$2,190	
	Ceiling - Lay-in	100K - Treasurer's Office	131	SF	6	\$393	
	Ceiling - Lay-in	100K - Treasurer's Office	4	SF	5	\$32	damaged
	Doors - Side-lite	100K - Treasurer's Office	7	SF	6	\$117	
	Doors - Transom Window	100K - Treasurer's Office	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	100K - Treasurer's Office	1	EA	6	\$301	
	Floor - Carpet	100K - Treasurer's Office	135	SF	6	\$288	
	Lighting - Pendent/Surface	100K - Treasurer's Office	4	EA	7	\$0	
	Power Distribution	100K - Treasurer's Office	4	EA	7	\$0	
	Walls - Concrete Block	100K - Treasurer's Office	512	SF	6	\$1,501	
	Ceiling - Lay-in	100P - Copy room	135	SF	6	\$405	
	Doors - Side-lite	100P - Copy room	7	SF	6	\$117	
	Doors - Transom Window	100P - Copy room	27	SF	4	\$2,064	Cracked glass
	Doors - Wood Doors inclu hw	100P - Copy room	1	EA	6	\$301	
	Floor - Carpet	100P - Copy room	135	SF	6	\$288	
	Lighting - Pendent/Surface	100P - Copy room	3	EA	7	\$0	



oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
minis	trative Suites/Offices						
	Power Distribution	100P - Copy room	6	EA	7	\$0	
	Walls - Concrete Block	100P - Copy room	512	SF	6	\$1,501	
	Ceiling - Lay-in	101 - Attendance Office	360	SF	6	\$1,081	
	Doors - Side-lite	101 - Attendance Office	21	SF	6	\$351	
	Doors - Transom Window	101 - Attendance Office	90	SF	6	\$1,524	
	Doors - Wood Doors inclu hw	101 - Attendance Office	3	EA	6	\$903	
	Floor - Carpet	101 - Attendance Office	360	SF	6	\$767	
	Lighting - Pendent/Surface	101 - Attendance Office	12	EA	7	\$0	
	Power Distribution	101 - Attendance Office	10	EA	7	\$0	
	Walls - Concrete Block	101 - Attendance Office	640	SF	6	\$1,876	
	Ceiling - Lay-in	103 - Counseling Suite	836	SF	6	\$2,511	
	Doors - Side-lite	103 - Counseling Suite	14	SF	6	\$234	
	Doors - Transom Window	103 - Counseling Suite	72	SF	6	\$1,219	
	Doors - Wood Doors inclu hw	103 - Counseling Suite	2	EA	6	\$602	
	Floor - Carpet	103 - Counseling Suite	836	SF	6	\$1,781	
	Lighting - Pendent/Surface	103 - Counseling Suite	26	EA	7	\$0	
	Power Distribution	103 - Counseling Suite	12	EA	7	\$0	
	Walls - Concrete Block	103 - Counseling Suite	1,600	SF	6	\$4,690	
	Ceiling - Lay-in	103A - Office	100	SF	6	\$300	
	Doors - Side-lite	103A - Office	7	SF	6	\$117	
	Doors - Transom Window	103A - Office	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	103A - Office	1	EA	6	\$301	
	Floor - Carpet	103A - Office	100	SF	6	\$213	
	Lighting - Pendent/Surface	103A - Office	2	EA	7	\$0	
	Power Distribution	103A - Office	4	EA	7	\$0	
	Walls - Concrete Block	103A - Office	426	SF	6	\$1,249	
	Ceiling - Lay-in	103B - Office	4	SF	5	\$32	damaged
	Ceiling - Lay-in	103B - Office	96	SF	6	\$288	
	Doors - Side-lite	103B - Office	7	SF	6	\$117	
	Doors - Transom Window	103B - Office	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	103B - Office	1	EA	6	\$301	
	Floor - Carpet	103B - Office	100	SF	6	\$213	
	Lighting - Pendent/Surface	103B - Office	2	EA	7	\$0	
	Power Distribution	103B - Office	4	EA	7	\$0	
	Walls - Concrete Block	103B - Office	426	SF	6	\$1,249	
	Ceiling - Lay-in	103C - Office	90	SF	6	\$270	
	Ceiling - Lay-in	103C - Office	90	SF	6	\$270	



-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninis	strative Suites/Offices						
	Doors - Side-lite	103C - Office	7	SF	6	\$117	
	Doors - Side-lite	103C - Office	7	SF	6	\$117	
	Doors - Transom Window	103C - Office	36	SF	6	\$610	
	Doors - Transom Window	103C - Office	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	103C - Office	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	103C - Office	1	EA	6	\$301	
	Floor - Carpet	103C - Office	90	SF	6	\$192	
	Floor - Carpet	103C - Office	90	SF	6	\$192	
	Lighting - Pendent/Surface	103C - Office	2	EA	7	\$0	
	Lighting - Pendent/Surface	103C - Office	2	EA	7	\$0	
	Power Distribution	103C - Office	4	EA	7	\$0	
	Power Distribution	103C - Office	4	EA	7	\$0	
	Walls - Concrete Block	103C - Office	405	SF	6	\$1,187	
	Walls - Concrete Block	103C - Office	405	SF	6	\$1,187	
	Ceiling - Lay-in	103D - Office	90	SF	6	\$270	
	Doors - Side-lite	103D - Office	7	SF	6	\$117	
	Doors - Transom Window	103D - Office	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	103D - Office	1	EA	6	\$301	
	Floor - Carpet	103D - Office	90	SF	6	\$192	
	Lighting - Pendent/Surface	103D - Office	2	EA	7	\$0	
	Power Distribution	103D - Office	4	EA	7	\$0	
	Walls - Concrete Block	103D - Office	405	SF	6	\$1,187	
	Ceiling - Lay-in	103E - Office	90	SF	6	\$270	
	Doors - Side-lite	103E - Office	7	SF	6	\$117	
	Doors - Transom Window	103E - Office	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	103E - Office	1	EA	6	\$301	
	Floor - Carpet	103E - Office	90	SF	6	\$192	
	Lighting - Pendent/Surface	103E - Office	2	EA	7	\$0	
	Power Distribution	103E - Office	4	EA	7	\$0	
	Walls - Concrete Block	103E - Office	405	SF	6	\$1,187	
	Ceiling - Lay-in	103F - Office	90	SF	6	\$270	
	Doors - Side-lite	103F - Office	7	SF	6	\$117	
	Doors - Transom Window	103F - Office	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	103F - Office	1	EA	6	\$301	
	Floor - Carpet	103F - Office	90	SF	6	\$192	
	Lighting - Pendent/Surface	103F - Office	2	EA	7	\$0	
	Power Distribution	103F - Office	4	EA	7	\$0	



p Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
nistrative Suites/Offices						
Walls - Concrete Block	103F - Office	405	SF	6	\$1,187	
Ceiling - Lay-in	103G - Office	90	SF	6	\$270	
Doors - Side-lite	103G - Office	7	SF	6	\$117	
Doors - Transom Window	103G - Office	36	SF	6	\$610	
Doors - Wood Doors inclu hw	103G - Office	1	EA	5	\$1,174	
Floor - Carpet	103G - Office	90	SF	6	\$192	
Lighting - Pendent/Surface	103G - Office	2	EA	7	\$0	
Power Distribution	103G - Office	4	EA	7	\$0	
Walls - Concrete Block	103G - Office	405	SF	6	\$1,187	
Ceiling - Lay-in	103H - Office	90	SF	6	\$270	
Doors - Side-lite	103H - Office	7	SF	6	\$117	
Doors - Transom Window	103H - Office	36	SF	6	\$610	
Doors - Wood Doors inclu hw	103H - Office	1	EA	6	\$301	
Floor - Carpet	103H - Office	90	SF	6	\$192	
Lighting - Pendent/Surface	103H - Office	2	EA	7	\$0	
Power Distribution	103H - Office	4	EA	7	\$0	
Walls - Concrete Block	103H - Office	405	SF	6	\$1,187	
Ceiling - Lay-in	103I - Office	150	SF	6	\$450	
Doors - Side-lite	103I - Office	14	SF	6	\$234	
Doors - Transom Window	103I - Office	72	SF	6	\$1,219	
Doors - Wood Doors inclu hw	103I - Office	2	EA	6	\$602	
Floor - Carpet	103I - Office	150	SF	6	\$320	
Lighting - Pendent/Surface	103I - Office	3	EA	7	\$0	
Power Distribution	103I - Office	4	EA	7	\$0	
Walls - Concrete Block	103I - Office	533	SF	6	\$1,562	
Ceiling - Plaster/Drywall	115A - Pool office	80	SF	6	\$277	
Doors - Steel Doors incl hw	115A - Pool office	1	EA	6	\$301	
Floor - Tile Ceramic/ Porcelain	115A - Pool office	80	SF	6	\$169	
Lighting - Pendent/Surface	115A - Pool office	2	EA	7	\$0	
Power Distribution	115A - Pool office	4	EA	7	\$0	
Walls - Concrete Block	115A - Pool office	360	SF	6	\$1,055	
Ceiling - Exposed	128 - Engineer's Office	129	SF	6	\$192	
Doors - Side-lite	128 - Engineer's Office	7	SF	6	\$117	
Doors - Wood Doors inclu hw	128 - Engineer's Office	1	EA	6	\$301	
Floor - Tile	128 - Engineer's Office	129	SF	6	\$282	
Lighting - Pendent/Surface	128 - Engineer's Office	5	EA	7	\$0	
Power Distribution	128 - Engineer's Office	4	EA	7	\$0	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	rative Suites/Offices						
	Walls - Concrete Block	128 - Engineer's Office	371	SF	6	\$1,088	
	Ceiling - Lay-in	Rm 243D- Library Work Rm	325	SF	6	\$976	
	Doors - Side-lite	Rm 243D- Library Work Rm	64	SF	6	\$1,070	
	Doors - Wood Doors inclu hw	Rm 243D- Library Work Rm	1	EA	6	\$301	
	Floor - Tile/Sheet	Rm 243D- Library Work Rm	325	SF	6	\$325	
	Lighting - Pendent/Surface	Rm 243D- Library Work Rm	9	EA	7	\$0	
	Power Distribution	Rm 243D- Library Work Rm	8	EA	7	\$0	
	Walls - Concrete Block	Rm 243D- Library Work Rm	579	SF	6	\$1,697	
	Work Sink	Rm 243D- Library Work Rm	1	EA	6	\$508	
	Ceiling - Splined	Rm 343A- IT Work Room, Office	688	SF	6	\$561	
	Doors - Side-lite	Rm 343A- IT Work Room, Office	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	Rm 343A- IT Work Room, Office	1	EA	6	\$301	
	Floor - Tile/Sheet	Rm 343A- IT Work Room, Office	663	SF	6	\$664	
	Floor - Tile/Sheet	Rm 343A- IT Work Room, Office	25	SF	5	\$144	Damage
	Lighting - Pendent/Surface	Rm 343A- IT Work Room, Office	16	EA	7	\$0	Damage
	Power Distribution	Rm 343A- IT Work Room, Office	14	EA	7	\$0	
	Walls - Concrete Block	Rm 343A- IT Work Room, Office	876	SF	6	\$2,568	
	Ceiling - Lay-in	Room 104	858	SF	6	\$2,577	
	Ceiling - Lay-in	Room 104	8	SF	5	\$64	damaged
	Doors - Side-lite	Room 104	64	SF	6	\$1,070	5
	Doors - Transom Window	Room 104	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	Room 104	1	EA	6	\$301	
	Floor - Carpet	Room 104	866	SF	6	\$1,845	
	Lighting - Pendent/Surface	Room 104	36	EA	7	\$0	
	Power Distribution	Room 104	24	EA	7	\$0	
	Walls - Concrete Block	Room 104	864	SF	6	\$2,533	
	Ceiling - Lay-in	Room 105B	56	SF	6	\$168	
	Ceiling - Lay-in	Room 105B	24	SF	5	\$166	damaged
	Doors - Wood Doors inclu hw	Room 105B	1	EA	6	\$301	-
	Floor - Tile	Room 105B	80	SF	6	\$175	
	Lighting - Pendent/Surface	Room 105B	2	EA	7	\$0	
	Power Distribution	Room 105B	4	EA	7	\$0	
	Walls - Concrete Block	Room 105B	300	SF	6	\$879	
	Ceiling - Lay-in	Room 106A	140	SF	6	\$420	
	Doors - Wood Doors inclu hw	Room 106A	1	EA	6	\$301	
	Floor - Tile	Room 106A	140	SF	6	\$306	
	Lighting - Lay-in	Room 106A	3	EA	7	\$0	



Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
minis	trative Suites/Offices						
	Power Distribution	Room 106A	4	EA	7	\$0	
	Walls - Concrete Block	Room 106A	235	SF	6	\$689	
	Ceiling - Lay-in	Room 203, Workroom	500	SF	6	\$1,502	
	Ceiling - Lay-in	Room 203, Workroom	25	SF	5	\$199	water damage
	Doors - Side-lite	Room 203, Workroom	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 203, Workroom	1	EA	6	\$301	
	Floor - Tile	Room 203, Workroom	525	SF	6	\$1,149	
	Lighting - Lay-in	Room 203, Workroom	8	EA	7	\$0	
	Power Distribution	Room 203, Workroom	18	EA	7	\$0	
	Storage/ Closet	Room 203, Workroom	170	SF	6	\$1,233	
	Walls - Concrete Block	Room 203, Workroom	737	SF	6	\$2,161	
	Ceiling - Lay-in	Room 205, Disciplinarian Office	501	SF	6	\$1,505	
	Ceiling - Lay-in	Room 205, Disciplinarian Office	24	SF	5	\$192	water damaged
	Doors - Side-lite	Room 205, Disciplinarian Office	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 205, Disciplinarian Office	1	EA	6	\$301	
	Floor - Tile/Sheet	Room 205, Disciplinarian Office	525	SF	6	\$526	
	Lighting - Lay-in	Room 205, Disciplinarian Office	8	EA	7	\$0	
	Power Distribution	Room 205, Disciplinarian Office	8	EA	7	\$0	
	Storage/ Closet	Room 205, Disciplinarian Office	153	SF	6	\$1,109	
	Walls - Concrete Block	Room 205, Disciplinarian Office	737	SF	6	\$2,161	
	Ceiling - Lay-in	Room 213, CPD School Unit Office	285	SF	6	\$856	
	Doors - Side-lite	Room 213, CPD School Unit Office	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	Room 213, CPD School Unit Office	2	EA	6	\$602	
	Floor - Tile	Room 213, CPD School Unit Office	285	SF	6	\$624	
	Lighting - Lay-in	Room 213, CPD School Unit Office	6	EA	7	\$0	
	Power Distribution	Room 213, CPD School Unit Office	12	EA	7	\$0	
	Walls - Concrete Block	Room 213, CPD School Unit Office	544	SF	6	\$1,595	
	Ceiling - Lay-in	Room 215, Health Services	522	SF	6	\$1,568	
	Ceiling - Lay-in	Room 215, Health Services	1	SF	5	\$8	water stains
	Doors - Side-lite	Room 215, Health Services	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 215, Health Services	1	EA	6	\$301	
	Floor - Tile/Sheet	Room 215, Health Services	523	SF	6	\$524	
	Lighting - Lay-in	Room 215, Health Services	8	EA	7	\$0	
	Power Distribution	Room 215, Health Services	6	EA	7	\$0	
	Walls - Concrete Block	Room 215, Health Services	737	SF	6	\$2,161	
	Ceiling - Lay-in	Room 217, Coaches Office	172	SF	6	\$517	
	Doors - Side-lite	Room 217, Coaches Office	7	SF	6	\$117	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Doors - Wood Doors inclu hw	Room 217, Coaches Office	1	EA	6	\$301	
	Floor - Tile	Room 217, Coaches Office	172	SF	6	\$376	
	Lighting - Lay-in	Room 217, Coaches Office	3	EA	7	\$0	
	Power Distribution	Room 217, Coaches Office	6	EA	7	\$0	
	Walls - Concrete Block	Room 217, Coaches Office	441	SF	6	\$1,293	
	Ceiling - Plaster/Drywall	Room 222A, Music Office	200	SF	6	\$692	
	Doors - Side-lite	Room 222A, Music Office	90	SF	6	\$1,505	
	Doors - Wood Doors inclu hw	Room 222A, Music Office	2	EA	6	\$602	
	Floor - Tile	Room 222A, Music Office	200	SF	6	\$438	
	Lighting - Pendent/Surface	Room 222A, Music Office	6	EA	7	\$0	
	Power Distribution	Room 222A, Music Office	6	EA	7	\$0	
	Walls - Concrete Block	Room 222A, Music Office	480	SF	6	\$1,407	
	Ceiling - Lay-in	Room 226E, Music Office	195	SF	6	\$586	
	Doors - Side-lite	Room 226E, Music Office	81	SF	6	\$1,354	
	Doors - Wood Doors inclu hw	Room 226E, Music Office	2	EA	6	\$602	
	Floor - Tile	Room 226E, Music Office	196	SF	6	\$429	
	Floor - Tile	Room 226E, Music Office	4	SF	5	\$23	Rm 226F About 4Sf damaged floor tiles.
	Lighting - Lay-in	Room 226E, Music Office	4	EA	7	\$0	
	Power Distribution	Room 226E, Music Office	6	EA	7	\$0	
	Storage/ Closet	Room 226E, Music Office	267	SF	6	\$1,936	
	Storage/ Closet	Room 226E, Music Office	5	SF	5	\$81	Rm 226F. Has minor water damage on ceiling
	Walls - Concrete Block	Room 226E, Music Office	480	SF	6	\$1,407	
	Ceiling - Lay-in	Room 229, Biology Office/Work Rm	335	SF	6	\$1,006	
	Doors - Side-lite	Room 229, Biology Office/Work Rm	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 229, Biology Office/Work Rm	1	EA	6	\$301	
	Floor - Tile	Room 229, Biology Office/Work Rm	335	SF	6	\$733	
	Lighting - Pendent/Surface	Room 229, Biology Office/Work Rm	6	EA	7	\$0	
	Power Distribution	Room 229, Biology Office/Work Rm	12	EA	7	\$0	
	Walls - Concrete Block	Room 229, Biology Office/Work Rm	588	SF	6	\$1,724	
	Ceiling - Lay-in	Room 237, Copy Room	251	SF	6	\$754	
	Ceiling - Lay-in	Room 237, Copy Room	10	SF	5	\$80	water damaged
	Doors - Side-lite	Room 237, Copy Room	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 237, Copy Room	1	EA	6	\$301	
	Floor - Tile	Room 237, Copy Room	261	SF	6	\$571	
	Lighting - Pendent/Surface	Room 237, Copy Room	4	EA	7	\$0	
	Power Distribution	Room 237, Copy Room	18	EA	7	\$0	
	Storage/ Closet	Room 237, Copy Room	130	SF	6	\$943	Rm 127B- vacant work room



up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninis	strative Suites/Offices						
	Walls - Concrete Block	Room 237, Copy Room	507	SF	6	\$1,486	
	Ceiling - Lay-in	Room 237A -Conference Room	137	SF	6	\$411	
	Ceiling - Lay-in	Room 237A -Conference Room	3	SF	5	\$24	water damaged
	Doors - Wood Doors inclu hw	Room 237A -Conference Room	1	EA	6	\$301	
	Floor - Tile	Room 237A -Conference Room	140	SF	6	\$306	
	Lighting - Lay-in	Room 237A -Conference Room	2	EA	7	\$0	
	Power Distribution	Room 237A -Conference Room	4	EA	7	\$0	
	Walls - Concrete Block	Room 237A -Conference Room	387	SF	6	\$1,134	
	Ceiling - Lay-in	Room 239, Special Ed Office	352	SF	6	\$1,057	
	Doors - Side-lite	Room 239, Special Ed Office	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 239, Special Ed Office	1	EA	6	\$301	
	Floor - Tile	Room 239, Special Ed Office	352	SF	6	\$770	
	Lighting - Lay-in	Room 239, Special Ed Office	6	EA	7	\$0	
	Power Distribution	Room 239, Special Ed Office	6	EA	7	\$0	
	Walls - Concrete Block	Room 239, Special Ed Office	587	SF	6	\$1,721	
	Ceiling - Lay-in	Room 243B, Teacher's Resource Room in Library	226	SF	6	\$679	
	Doors - Side-lite	Room 243B, Teacher's Resource Room in Library	64	SF	6	\$1,070	
	Doors - Wood Doors inclu hw	Room 243B, Teacher's Resource Room in Library	1	EA	6	\$301	
	Floor - Carpet	Room 243B, Teacher's Resource Room in Library	226	SF	6	\$482	
	Lighting - Pendent/Surface	Room 243B, Teacher's Resource Room in Library	7	EA	7	\$0	
	Power Distribution	Room 243B, Teacher's Resource Room in Library	6	EA	7	\$0	
	Walls - Concrete Block	Room 243B, Teacher's Resource Room in Library	500	SF	6	\$1,466	
	Ceiling - Lay-in	Room 303A	170	SF	6	\$511	
	Doors - Wood Doors inclu hw	Room 303A	1	EA	6	\$301	
	Floor - Tile	Room 303A	170	SF	6	\$372	
	Lighting - Lay-in	Room 303A	3	EA	7	\$0	
	Power Distribution	Room 303A	6	EA	7	\$0	
	Walls - Concrete Block	Room 303A	427	SF	6	\$1,252	
	Ceiling - Lay-in	Room 303B	129	SF	6	\$387	
	Doors - Side-lite	Room 303B	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 303B	1	EA	6	\$301	
	Floor - Tile	Room 303B	129	SF	6	\$282	



iroup	Item - Type	Location	Quantity	Unit	Rank	Cost	Com
mini	strative Suites/Offices						
	Lighting - Lay-in	Room 303B	2	EA	7	\$0	
	Power Distribution	Room 303B	4	EA	7	\$0	
	Walls - Concrete Block	Room 303B	371	SF	6	\$1,088	
	Ceiling - Lay-in	Room 303D	129	SF	6	\$387	
	Doors - Side-lite	Room 303D	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 303D	1	EA	6	\$301	
	Floor - Tile	Room 303D	129	SF	6	\$282	
	Lighting - Lay-in	Room 303D	2	EA	7	\$0	
	Power Distribution	Room 303D	4	EA	7	\$0	
	Walls - Concrete Block	Room 303D	371	SF	6	\$1,088	
	Ceiling - Lay-in	Room 303E	129	SF	6	\$387	
	Doors - Side-lite	Room 303E	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 303E	1	EA	6	\$301	
	Floor - Tile	Room 303E	129	SF	6	\$282	
	Lighting - Lay-in	Room 303E	2	EA	7	\$0	
	Power Distribution	Room 303E	4	EA	7	\$0	
	Walls - Concrete Block	Room 303E	371	SF	6	\$1,088	
	Ceiling - Lay-in	Room 313, Office/work room	683	SF	6	\$2,051	
	Doors - Side-lite	Room 313, Office/work room	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 313, Office/work room	1	EA	6	\$301	
	Floor - Tile	Room 313, Office/work room	683	SF	6	\$1,494	
	Lighting - Lay-in	Room 313, Office/work room	10	EA	7	\$0	
	Power Distribution	Room 313, Office/work room	30	EA	7	\$0	
	Walls - Concrete Block	Room 313, Office/work room	908	SF	6	\$2,662	
	Ceiling - Lay-in	Room 319, Office	172	SF	6	\$517	
	Doors - Side-lite	Room 319, Office	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Room 319, Office	1	EA	6	\$301	
	Floor - Tile	Room 319, Office	172	SF	6	\$376	
	Lighting - Lay-in	Room 319, Office	2	EA	7	\$0	
	Power Distribution	Room 319, Office	4	EA	7	\$0	
	Walls - Concrete Block	Room 319, Office	441	SF	6	\$1,293	
	Ceiling - Lay-in	Room 328 A&B	225	SF	6	\$676	
	Doors - Side-lite	Room 328 A&B	53	SF	6	\$886	
	Doors - Wood Doors inclu hw	Room 328 A&B	2	EA	6	\$602	
	Floor - Tile	Room 328 A&B	225	SF	6	\$492	
	Lighting - Lay-in	Room 328 A&B	3	EA	7	\$0	
	Power Distribution	Room 328 A&B	8	EA	7	\$0	



Building: Main

лb	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninis	strative Suites/Offices						
	Walls - Concrete Block	Room 328 A&B	500	SF	6	\$1,466	
	Ceiling - Lay-in	Room 339A, Office	155	SF	6	\$465	
	Doors - Wood Doors inclu hw	Room 339A, Office	1	EA	6	\$301	
	Floor - Tile	Room 339A, Office	147	SF	6	\$322	
	Floor - Tile	Room 339A, Office	8	SF	5	\$46	damaged
	Lighting - Lay-in	Room 339A, Office	2	EA	7	\$0	
	Power Distribution	Room 339A, Office	6	EA	7	\$0	
	Walls - Concrete Block	Room 339A, Office	412	SF	6	\$1,208	
	Ceiling - Splined	Room 343, Media Meeting Room	3,214	SF	6	\$2,620	
	Doors - Wood Doors inclu hw	Room 343, Media Meeting Room	4	EA	6	\$1,204	
	Floor - Tile	Room 343, Media Meeting Room	3,193	SF	6	\$6,986	
	Floor - Tile	Room 343, Media Meeting Room	21	SF	5	\$121	damaged
	Lighting - Pendent/Surface	Room 343, Media Meeting Room	76	EA	7	\$0	
	Power Distribution	Room 343, Media Meeting Room	30	EA	7	\$0	
	Storage/ Closet	Room 343, Media Meeting Room	209	SF	6	\$1,515	Rm 343B
	Walls - Concrete Block	Room 343, Media Meeting Room	5,892	SF	6	\$17,272	
	Ceiling - Lay-in	Room120A Kitchen Office	109	SF	6	\$327	
	Doors - Wood Doors inclu hw	Room120A Kitchen Office	1	EA	7	\$0	
	Floor - Tile	Room120A Kitchen Office	97	SF	6	\$212	
	Floor - Tile	Room120A Kitchen Office	12	SF	5	\$59	Damaged
	Lighting - Pendent/Surface	Room120A Kitchen Office	3	EA	7	\$0	
	Power Distribution	Room120A Kitchen Office	4	EA	7	\$0	
	Walls - Structural Glazed Tile	Room120A Kitchen Office	428	SF	6	\$1,346	
itori	ium & Theater						
	Ceiling - Plaster/Drywall	1st Floor - 117	5,871	SF	6	\$48,946	
	Floor - Carpet	1st Floor - 117	2,935	SF	6	\$6,254	
	Floor - Concrete	1st Floor - 117	2,936	SF	6	\$1,553	
	Lighting - Pendent/Surface	1st Floor - 117	80	EA	7	\$0	
	Main Floor Seating	1st Floor - 117	620	EA	6	\$107,828	
	Sound System	1st Floor - 117	1	EA	6	\$10,721	
	Stage	1st Floor - 117	390	SF	6	\$2,253	
	Stage Curtain	1st Floor - 117	3	EA	6	\$0	
	Stage Lighting System	1st Floor - 117	1	EA	7	\$0	
	Stage-Stairs - Tile	1st Floor - 117	4	LF	6	\$37	
	Walls - Plaster/Drywall	1st Floor - 117	10,091	SF	6	\$48,052	
	Ceiling - Exposed	Room 116	2,281	SF	6	\$3,392	
	Doors - Wood Doors inclu hw	Room 116	1	EA	6	\$301	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Audito	rium & Theater						
	Floor - Carpet	Room 116	1,710	SF	6	\$3,643	
	Floor - Terrazzo	Room 116	570	SF	7	\$0	
	Lighting - Pendent/Surface	Room 116	30	EA	7	\$0	
	Main Floor Seating	Room 116	120	EA	6	\$20,870	
	Sound System	Room 116	1	EA	6	\$10,721	
	Stage	Room 116	345	SF	6	\$1,993	
	Stage Lighting System	Room 116	1	EA	7	\$0	
	Walls - Tile	Room 116	5,265	SF	6	\$11,519	Acoustic
Green	House						
	Finishes	Rm 346C	172	SF	6	\$942	cement floor is cracked, but otherwise good
	Glazing	Rm 346C	124	SF	6	\$3,087	
	Plumbing	Rm 346C	3	SF	6	\$2	sink
Gymna	asia						
	Ceiling - Exposed	Room 113, Girl's Gym	6,157	SF	6	\$9,157	
	Doors - Side-lite	Room 113, Girl's Gym	14	SF	7	\$0	
	Doors - Transom Window	Room 113, Girl's Gym	20	SF	7	\$0	Solid wood panels
	Doors - Wood Doors inclu hw	Room 113, Girl's Gym	4	EA	6	\$1,204	
	Floor - Wood	Room 113, Girl's Gym	6,157	SF	6	\$43,406	
	Lighting - Metal Halide/Sodium Vapor	Room 113, Girl's Gym	24	EA	7	\$0	
	Walls - Concrete Block	Room 113, Girl's Gym	9,666	SF	6	\$28,336	
	Bleacher Seating	Room 114, Boy's Gym	1,096	EA	6	\$31,722	
	Ceiling - Exposed	Room 114, Boy's Gym	9,398	SF	6	\$13,977	
	Doors - Side-lite	Room 114, Boy's Gym	14	SF	7	\$0	
	Doors - Transom Window	Room 114, Boy's Gym	20	SF	7	\$0	Solid wood panels
	Doors - Wood Doors inclu hw	Room 114, Boy's Gym	4	EA	6	\$1,204	
	Floor - Wood	Room 114, Boy's Gym	9,398	SF	6	\$66,255	
	Lighting - Metal Halide/Sodium Vapor	Room 114, Boy's Gym	36	EA	7	\$0	
	Scoreboards	Room 114, Boy's Gym	2	EA	6	\$4,489	
	Sound System	Room 114, Boy's Gym	1	EA	6	\$41,654	
	Walls - Concrete Block	Room 114, Boy's Gym	8,725	SF	6	\$25,577	
	Walls - Plaster/Drywall	Room 114, Boy's Gym	2,917	SF	6	\$8,051	
Kitche	n						
	Ceiling - Lay-in	1st Floor	2,567	SF	6	\$7,709	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	1st Floor	2,567	SF	6	\$5,433	
	Lighting - Lay-in	1st Floor	28	EA	7	\$0	



	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Kitchen	1						
	Storage/ Closet	1st Floor	144	SF	6	\$1,044	
	Walls - Structural Glazed Tile	1st Floor	2,948	SF	6	\$9,274	
Library							
LINAIY	Ceiling - Lay-in	Room 243	2,927	SF	6	\$8,790	
	Ceiling - Plaster/Drywall	Room 243	1,464	SF	6	\$5,066	
	Ceiling - Splined	Room 243	1,464	SF	6	\$1,193	
	Doors - Side-lite	Room 243	104	SF	6	\$1,739	
	Doors - Wood Doors inclu hw	Room 243	4	EA	6	\$1,204	
	Floor - Carpet	Room 243	5,855	SF	6	\$12,475	
	Lighting - Pendent/Surface	Room 243	152	EA	7	\$0	
	Storage/ Closet	Room 243	224	SF	6		Rm 243C
	Walls - Concrete Block	Room 243	1,764	SF	6	\$5,171	
			.,			+-,	
Locker/	/Shower Room			~-		^	
	Accessories	018 Girls Locker Room	1,964	SF	6	\$7,695	
	Benches, ped mounted	018 Girls Locker Room	30	LF	6	\$3,266	
	Ceiling - Exposed	018 Girls Locker Room	1,460	SF	6	\$2,171	
	Ceiling - Plaster/ Drywall	018 Girls Locker Room	504	SF	6	\$1,744	
	Doors - Steel Doors incl hw	018 Girls Locker Room	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	018 Girls Locker Room	1	EA	6	\$301	
	Floor Drain	018 Girls Locker Room	6	EA	6	\$6,355	
	Floor - Tile Ceramic/ Porcelain	018 Girls Locker Room	504	SF	6	\$1,067	
	Floor - Tile/Sheet	018 Girls Locker Room	1,460	SF	6	\$1,461	Rubber tile
	Hand Dryer	018 Girls Locker Room	6	EA	6	\$1,380	
	Lavatory	018 Girls Locker Room	4	EA	6	\$1,278	
	Lighting - Pendent/Surface	018 Girls Locker Room	12	EA	7	\$0	
	Lighting - Pendent/Surface	018 Girls Locker Room	21	EA	7	\$0	
	Partitions	018 Girls Locker Room	4	EA	6	\$1,188	
	Showers	018 Girls Locker Room	17	EA	6	\$5,294	
	Student Lockers - One Tier	018 Girls Locker Room	32	EA	6	\$2,971	
	Student Lockers - Two Tier	018 Girls Locker Room	70	EA	6	\$3,249	
	Walls - Concrete Block	018 Girls Locker Room	1,860	SF	6	\$5,453	
	Walls - Structural Glazed Tile	018 Girls Locker Room	1,660	SF	6	\$5,222	
	Water Closet	018 Girls Locker Room	7	EA	6	\$2,352	
	Accessories	030 - Girl's Locker Room Basement	1,384	SF	6	\$5,423	
	Benches, ped mounted	030 - Girl's Locker Room Basement	40	LF	6	\$4,355	
	Ceiling - Exposed	030 - Girl's Locker Room Basement	663	SF	6	\$986	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/	Shower Room						
	Ceiling - Plaster/ Drywall	030 - Girl's Locker Room Basement	721	SF	6	\$2,495	
	Doors - Steel Doors incl hw	030 - Girl's Locker Room Basement	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	030 - Girl's Locker Room Basement	2	EA	6	\$602	
	Floor Drain	030 - Girl's Locker Room Basement	5	EA	6	\$5,296	
	Floor - Tile Ceramic/ Porcelain	030 - Girl's Locker Room Basement	721	SF	6	\$1,526	
	Floor - Tile/Sheet	030 - Girl's Locker Room Basement	663	SF	6	\$664	Rubber tile
	Hand Dryer	030 - Girl's Locker Room Basement	5	EA	6	\$1,150	
	Lavatory	030 - Girl's Locker Room Basement	4	EA	6	\$1,278	
	Lighting - Lay-in	030 - Girl's Locker Room Basement	18	EA	7	\$0	
	Lighting - Pendent/Surface	030 - Girl's Locker Room Basement	16	EA	7	\$0	
	Partitions	030 - Girl's Locker Room Basement	4	EA	6	\$1,188	
	Showers	030 - Girl's Locker Room Basement	10	EA	6	\$3,114	
	Storage/ Closet	030 - Girl's Locker Room Basement	150	SF	6	\$1,088	
	Student Lockers - One Tier	030 - Girl's Locker Room Basement	88	EA	6	\$8,170	
	Walls - Concrete Block	030 - Girl's Locker Room Basement	1,470	SF	6	\$4,309	
	Walls - Tile Ceramic/ Porcelain	030 - Girl's Locker Room Basement	690	SF	6	\$1,559	
	Water Closet	030 - Girl's Locker Room Basement	4	EA	6	\$1,344	
	Accessories	036 - Boy's Locker Room	1,384	SF	6	\$5,423	
	Benches, ped mounted	036 - Boy's Locker Room	40	LF	6	\$4,355	
	Ceiling - Exposed	036 - Boy's Locker Room	663	SF	6	\$986	
	Ceiling - Plaster/ Drywall	036 - Boy's Locker Room	721	SF	6	\$2,495	
	Doors - Steel Doors incl hw	036 - Boy's Locker Room	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	036 - Boy's Locker Room	2	EA	6	\$602	
	Floor Drain	036 - Boy's Locker Room	6	EA	6	\$6,355	
	Floor - Tile Ceramic/ Porcelain	036 - Boy's Locker Room	721	SF	6	\$1,526	
	Floor - Tile/Sheet	036 - Boy's Locker Room	663	SF	6	\$664	Rubber tile
	Lavatory	036 - Boy's Locker Room	2	EA	6	\$639	
	Lighting - Lay-in	036 - Boy's Locker Room	3	EA	6	\$357	Relamp
	Lighting - Lay-in	036 - Boy's Locker Room	15	EA	7	\$0	
	Lighting - Pendent/Surface	036 - Boy's Locker Room	15	EA	6	\$1,858	Relamp
	Lighting - Pendent/Surface	036 - Boy's Locker Room	1	EA	7	\$0	
	Partitions	036 - Boy's Locker Room	2	EA	6	\$594	
	Showers	036 - Boy's Locker Room	8	EA	6	\$2,491	
	Storage/ Closet	036 - Boy's Locker Room	50	SF	6	\$363	
	Student Lockers	036 - Boy's Locker Room	46	EA	6	\$0	
	Urinals	036 - Boy's Locker Room	3	EA	6	\$1,008	
	Walls - Concrete Block	036 - Boy's Locker Room	1,470	SF	6	\$4,309	



Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
/Shower Room						
Walls - Tile Ceramic/ Porcelain	036 - Boy's Locker Room	4	SF	6	\$19	
Walls - Tile Ceramic/ Porcelain	036 - Boy's Locker Room	686	SF	6	\$1,550	
Water Closet	036 - Boy's Locker Room	4	EA	6	\$1,344	
Accessories	123A - Kitchen staff locker	140	SF	6	\$549	
Ceiling - Plaster/ Drywall	123A - Kitchen staff locker	140	SF	6	\$484	
Doors - Wood Doors inclu hw	123A - Kitchen staff locker	1	EA	6	\$301	
Floor - Tile Ceramic/ Porcelain	123A - Kitchen staff locker	140	SF	6	\$296	
Lavatory	123A - Kitchen staff locker	1	EA	6	\$320	
Lighting - Pendent/Surface	123A - Kitchen staff locker	3	EA	7	\$0	
Partitions	123A - Kitchen staff locker	1	EA	6	\$297	
Student Lockers - One Tier	123A - Kitchen staff locker	3	EA	6	\$279	Staff
Urinals	123A - Kitchen staff locker	1	EA	6	\$336	
Walls - Concrete Block	123A - Kitchen staff locker	480	SF	6	\$1,407	
Water Closet	123A - Kitchen staff locker	1	EA	6	\$336	
Accessories	123B - Kitchen staff lockers	140	SF	6	\$549	
Ceiling - Plaster/ Drywall	123B - Kitchen staff lockers	140	SF	6	\$484	
Doors - Wood Doors inclu hw	123B - Kitchen staff lockers	1	EA	6	\$301	
Floor - Tile Ceramic/ Porcelain	123B - Kitchen staff lockers	140	SF	6	\$296	
Lavatory	123B - Kitchen staff lockers	1	EA	6	\$320	
Lighting - Pendent/Surface	123B - Kitchen staff lockers	1	EA	7	\$0	
Lighting - Pendent/Surface	123B - Kitchen staff lockers	2	EA	6	\$248	
Student Lockers - One Tier	123B - Kitchen staff lockers	14	EA	6	\$1,300	Staff
Walls - Concrete Block	123B - Kitchen staff lockers	480	SF	6	\$1,407	
Water Closet	123B - Kitchen staff lockers	2	EA	6	\$672	
Ceiling - Exposed	Boy's Varsity shower/locker room	900	SF	6	\$1,338	
Ceiling - Plaster/ Drywall	Boy's Varsity shower/locker room	1,750	SF	6	\$6,056	
Doors - Wood Doors inclu hw	Boy's Varsity shower/locker room	2	EA	6	\$602	
Floor Drain	Boy's Varsity shower/locker room	10	EA	6	\$10,592	
Floor - Tile Ceramic/ Porcelain	Boy's Varsity shower/locker room	1,750	SF	6	\$3,704	
Floor - Tile/Sheet	Boy's Varsity shower/locker room	900	SF	6	\$901	Rubber tile
Lavatory	Boy's Varsity shower/locker room	2	EA	6	\$639	
Lighting - Lay-in	Boy's Varsity shower/locker room	24	EA	7	\$0	
Lighting - Pendent/Surface	Boy's Varsity shower/locker room	15	EA	7	\$0	
Partitions	Boy's Varsity shower/locker room	3	EA	6	\$891	
Showers	Boy's Varsity shower/locker room	20	EA	6	\$6,228	
Urinals	Boy's Varsity shower/locker room	4	EA	6	\$1,344	
Walls - Concrete Block	Boy's Varsity shower/locker room	1,100	SF	6	\$3,225	



Group	o Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locke	r/Shower Room						
	Walls - Tile Ceramic/ Porcelain	Boy's Varsity shower/locker room	1,460	SF	6	\$3,299	
	Water Closet	Boy's Varsity shower/locker room	2	EA	6	\$672	
Lunch	a & Multipurpose Room						
	Ceiling - Lay-in	119B - Serving Room	1,512	SF	6	\$4,541	
	Doors - Wood Doors inclu hw	119B - Serving Room	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	119B - Serving Room	1,512	SF	6	\$3,200	
	Lighting - Lay-in	119B - Serving Room	36	EA	7	\$0	
	Serving Line	119B - Serving Room	117	LF	6	\$6,963	
	Walls - Tile Ceramic/ Porcelain	119B - Serving Room	1,963	SF	7	\$0	
	Ceiling - Lay-in	119C - Faculty dining	16	SF	5	\$128	water stains
	Ceiling - Lay-in	119C - Faculty dining	944	SF	6	\$2,835	
	Doors - Side-lite	119C - Faculty dining	20	SF	7	\$0	
	Doors - Transom Window	119C - Faculty dining	18	SF	7	\$0	Solid wood panels
	Doors - Wood Doors inclu hw	119C - Faculty dining	2	EA	7	\$0	
	Floor - Tile	119C - Faculty dining	960	SF	6	\$2,100	
	Lighting - Lay-in	119C - Faculty dining	15	EA	7	\$0	
	Walls - Plaster/Drywall	119C - Faculty dining	939	SF	6	\$2,592	
	Ceiling - Lay-in	1st floor adjacent to Room 119B Serving Room	5,464	SF	6	\$16,408	
	Ceiling - Lay-in	1st floor adjacent to Room 119B Serving Room	80	SF	5	\$638	water stains
	Doors - Transom Window	1st floor adjacent to Room 119B Serving Room	36	SF	7	\$0	Solid wood panels
	Doors - Wood Doors inclu hw	1st floor adjacent to Room 119B Serving Room	6	EA	6	\$1,806	
	Floor - Tile/Sheet	1st floor adjacent to Room 119B Serving Room	5,544	SF	6	\$5,550	
	Lighting - Lay-in	1st floor adjacent to Room 119B Serving Room	3	EA	6	\$357	Bulbs burned out
	Lighting - Lay-in	1st floor adjacent to Room 119B Serving Room	65	EA	7	\$0	
	Storage/ Closet	1st floor adjacent to Room 119B Serving Room	50	SF	6	\$363	
	Walls - Concrete Block	1st floor adjacent to Room 119B Serving Room	3,307	SF	6	\$9,694	
MDF_I	IDF						
	AC Unit	Rm 243A (in library)	1	EA	4	\$6,086	not working.
	Doors - Wood Doors inclu hw	Rm 243A (in library)	1	EA	6	\$301	
	Finishes	Rm 243A (in library)	326	SF	5	\$5,263	crack in wall & water stained ceiling



Building: Main

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
DF_IDF						
echanical/ Service Rooms						
Boiler Room	1st Floor	1,750	SF	6	\$12,538	
Janitor's Closet	1st Floor	450	SF	6	\$3,224	
Loading Docks	1st Floor	250	SF	6	\$1,791	
Mechanical/ Service Rooms	1st Floor	3,210	SF	5	\$51,779	
Storage Room	1st Floor	700	SF	6	\$5,015	
Janitor's Closet	2nd Floor	207	SF	6	\$1,483	
Mechanical/ Service Rooms	2nd Floor	1,906	SF	6	\$13,655	
Storage Room	2nd Floor	941	SF	6	\$6,742	
Janitor's Closet	3rd Floor	34	SF	6	\$244	
Mechanical/ Service Rooms	3rd Floor	1,775	SF	6	\$12,717	
Storage Room	3rd Floor	3,401	SF	6	\$24,366	Rm 305, 341, 329, 327, 325A/B/C/D, 323, 321
						303F, 315
ool & Natatorium						
Accessories	Basement	4,806	SF	6	\$3,299	
Bleachers Seating/Plank Seating	Basement	66	EA	6	\$1,910	
Ceiling - Exposed	Basement	4,806	SF	6	\$7,147	
Doors - Side-lite	Basement	14	SF	7	\$0	at wood doors
Doors - Steel Doors incl hw	Basement	2	EA	5	\$2,348	
Doors - Wood Doors inclu hw	Basement	4	EA	6	\$1,204	
Floor - Concrete	Basement	1,068	SF	6	\$565	
Lighting - Lay-in	Basement	13	EA	7	\$0	1st floor
Lighting - Metal Halide/Sodium Vapor	Basement	26	EA	7	\$0	
Pool Basin	Basement	1,800	SF	6	\$60,901	
Pool Deck	Basement	1,938	SF	6	\$18,402	
Pool Deck Drains	Basement	22	EA	6	\$9,285	
Walls - Concrete Block	Basement	7,436	SF	6	\$21,799	
ep Room						
Casework	Rm 230A	13	LF	6	\$328	
Ceiling - Lay-in	Rm 230A	4	SF	5	\$32	water stains
Ceiling - Lay-in	Rm 230A	567	SF	6	\$1,703	
Doors - Wood Doors inclu hw	Rm 230A	2	EA	6	\$602	
Floor - Tile/Sheet	Rm 230A	571	SF	6	\$572	
Lighting - Lay-in	Rm 230A	6	EA	7	\$0	
Walls - Concrete Block	Rm 230A	552	SF	6	\$1,618	
Work Sink	Rm 230A	2	EA	6	\$758	



oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ep Ro	bom						
	Casework	Rm 346A	21	LF	6	\$530	
	Ceiling - Lay-in	Rm 346A	110	SF	6	\$330	
	Doors - Side-lite	Rm 346A	46	SF	6	\$769	
	Doors - Wood Doors inclu hw	Rm 346A	1	EA	6	\$301	
	Floor - Tile/Sheet	Rm 346A	110	SF	6	\$110	
	Lighting - Lay-in	Rm 346A	1	EA	7	\$0	
	Walls - Concrete Block	Rm 346A	336	SF	6	\$985	
	Work Sink	Rm 346A	1	EA	6	\$379	
	Casework	Rm 346B	21	LF	6	\$530	
	Ceiling - Lay-in	Rm 346B	110	SF	6	\$330	
	Doors - Side-lite	Rm 346B	46	SF	6	\$769	
	Doors - Wood Doors inclu hw	Rm 346B	1	EA	6	\$301	
	Floor - Tile/Sheet	Rm 346B	110	SF	6	\$110	
	Lighting - Lay-in	Rm 346B	1	EA	7	\$0	
	Walls - Concrete Block	Rm 346B	336	SF	6	\$985	
	Work Sink	Rm 346B	1	EA	6	\$379	
	Casework	Rm 348A	29	LF	6	\$732	
	Ceiling - Lay-in	Rm 348A	1	SF	5	\$8	water stains
	Ceiling - Lay-in	Rm 348A	153	SF	6	\$459	
	Doors - Side-lite	Rm 348A	7	SF	6	\$117	
	Doors - Wood Doors inclu hw	Rm 348A	1	EA	6	\$301	
	Floor - Tile/Sheet	Rm 348A	154	SF	6	\$154	
	Lighting - Lay-in	Rm 348A	2	EA	7	\$0	
	Walls - Concrete Block	Rm 348A	388	SF	6	\$1,137	
	Work Sink	Rm 348A	2	EA	6	\$758	
	Casework	Rm 348B	30	LF	6	\$758	
	Ceiling - Lay-in	Rm 348B	141	SF	6	\$423	
	Doors - Side-lite	Rm 348B	53	SF	6	\$886	
	Doors - Wood Doors inclu hw	Rm 348B	1	EA	6	\$301	
	Floor - Tile/Sheet	Rm 348B	141	SF	6	\$141	
	Lighting - Lay-in	Rm 348B	1	EA	7	\$0	
	Walls - Concrete Block	Rm 348B	368	SF	6	\$1,079	
	Work Sink	Rm 348B	1	EA	6	\$379	
	Casework	Rm 350A	13	LF	6	\$328	
	Ceiling - Lay-in	Rm 350A	2	SF	5	\$16	water stains
	Ceiling - Lay-in	Rm 350A	291	SF	6	\$874	
	Floor - Tile/Sheet	Rm 350A	293	SF	6	\$293	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Prep Ro	bom						
	Lighting - Lay-in	Rm 350A	2	EA	7	\$0	
	Walls - Concrete Block	Rm 350A	552	SF	6	\$1,618	
	Work Sink	Rm 350A	1	EA	6	\$379	
Restroo	om						
	Accessories	1st Floor North Boys	226	SF	6	\$2,085	
	Ceiling - Plaster/Drywall	1st Floor North Boys	226	SF	6	\$782	
	Doors - Wood Doors inclu hw	1st Floor North Boys	1	EA	6	\$301	
	Floor Drain	1st Floor North Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor North Boys	226	SF	6	\$478	
	Lavatory	1st Floor North Boys	2	EA	6	\$639	
	Lighting - Lay-in	1st Floor North Boys	4	EA	7	\$0	
	Partitions	1st Floor North Boys	3	EA	6	\$891	
	Urinals	1st Floor North Boys	2	EA	6	\$672	
	Walls - Concrete Block	1st Floor North Boys	465	SF	6	\$1,363	
	Water Closet	1st Floor North Boys	1	EA	6	\$336	
	Accessories	1st Floor North Girls Restroom	226	SF	6	\$2,085	
	Ceiling - Plaster/Drywall	1st Floor North Girls Restroom	226	SF	6	\$782	
	Doors - Wood Doors inclu hw	1st Floor North Girls Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor North Girls Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor North Girls Restroom	226	SF	6	\$478	
	Lavatory	1st Floor North Girls Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor North Girls Restroom	4	EA	7	\$0	
	Partitions	1st Floor North Girls Restroom	3	EA	6	\$891	
	Walls - Plaster/Drywall	1st Floor North Girls Restroom	465	SF	6	\$1,283	
	Water Closet	1st Floor North Girls Restroom	3	EA	6	\$1,008	
	Accessories	1st Floor South Boys Room	215	SF	6	\$1,983	
	Ceiling - Plaster/Drywall	1st Floor South Boys Room	215	SF	6	\$744	
	Doors - Wood Doors inclu hw	1st Floor South Boys Room	1	EA	6	\$301	
	Floor Drain	1st Floor South Boys Room	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor South Boys Room	215	SF	6	\$455	
	Lavatory	1st Floor South Boys Room	2	EA	6	\$639	
	Lighting - Lay-in	1st Floor South Boys Room	4	EA	7	\$0	
	Partitions	1st Floor South Boys Room	3	EA	6	\$891	
	Urinals	1st Floor South Boys Room	2	EA	6	\$672	
	Walls - Concrete Block	1st Floor South Boys Room	465	SF	6	\$1,363	
	Water Closet	1st Floor South Boys Room	1	EA	6	\$336	
	Accessories	1st Floor South Girls Room	226	SF	6	\$2,085	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	bm						
	Ceiling - Plaster/Drywall	1st Floor South Girls Room	226	SF	6	\$782	
	Doors - Wood Doors inclu hw	1st Floor South Girls Room	1	EA	6	\$301	
	Floor Drain	1st Floor South Girls Room	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor South Girls Room	226	SF	6	\$478	
	Lavatory	1st Floor South Girls Room	1	EA	6	\$320	
	Lighting - Lay-in	1st Floor South Girls Room	4	EA	7	\$0	
	Partitions	1st Floor South Girls Room	3	EA	6	\$891	
	Walls - Concrete Block	1st Floor South Girls Room	465	SF	6	\$1,363	
	Water Closet	1st Floor South Girls Room	3	EA	6	\$1,008	
	Accessories	2nd FIr- Across from 212	336	SF	6	\$3,099	
	Ceiling - Plaster/Drywall	2nd Flr- Across from 212	336	SF	6	\$1,163	
	Doors - Wood Doors inclu hw	2nd FIr- Across from 212	1	EA	6	\$301	
	Floor Drain	2nd Flr- Across from 212	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd FIr- Across from 212	336	SF	6	\$711	
	Lavatory	2nd Flr- Across from 212	3	EA	6	\$959	
	Lighting - Lay-in	2nd Flr- Across from 212	7	EA	7	\$0	
	Partitions	2nd FIr- Across from 212	6	EA	6	\$1,782	
	Walls - Concrete Block	2nd FIr- Across from 212	595	SF	6	\$1,744	
	Water Closet	2nd FIr- Across from 212	7	EA	6	\$2,352	
	Accessories	2nd FIr- Across from 214	352	SF	6	\$3,247	
	Ceiling - Plaster/Drywall	2nd Flr- Across from 214	352	SF	6	\$1,218	
	Doors - Wood Doors inclu hw	2nd Flr- Across from 214	1	EA	6	\$301	
	Floor Drain	2nd Flr- Across from 214	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd FIr- Across from 214	352	SF	6	\$745	
	Lavatory	2nd FIr- Across from 214	3	EA	6	\$959	
	Lighting - Lay-in	2nd FIr- Across from 214	6	EA	7	\$0	
	Lighting - Lay-in	2nd FIr- Across from 214	1	EA	6	\$119	cover missing
	Partitions	2nd FIr- Across from 214	4	EA	6	\$1,188	
	Urinals	2nd Flr- Across from 214	3	EA	6	\$1,008	
	Walls - Concrete Block	2nd FIr- Across from 214	611	SF	6	\$1,791	
	Water Closet	2nd FIr- Across from 214	4	EA	6	\$1,344	
	Accessories	2nd Flr- By 232	336	SF	6	\$3,099	
	Ceiling - Plaster/Drywall	2nd Flr- By 232	336	SF	6	\$1,163	
	Doors - Wood Doors inclu hw	2nd Flr- By 232	1	EA	6	\$301	
	Floor Drain	2nd Flr- By 232	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Flr- By 232	336	SF	6	\$711	
	Lavatory	2nd Flr- By 232	3	EA	6	\$959	



Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
m						
Lighting - Lay-in	2nd Flr- By 232	7	EA	7	\$0	
Partitions	2nd Flr- By 232	6	EA	6	\$1,782	
Walls - Concrete Block	2nd Flr- By 232	595	SF	6	\$1,744	
Water Closet	2nd Flr- By 232	7	EA	6	\$2,352	
Accessories	2nd Flr- By 234	352	SF	6	\$3,247	
Ceiling - Plaster/Drywall	2nd Flr- By 234	352	SF	6	\$1,218	
Doors - Wood Doors inclu hw	2nd Flr- By 234	1	EA	6	\$301	
Floor Drain	2nd Flr- By 234	1	EA	6	\$1,059	
Floor - Tile Ceramic/ Porcelain	2nd FIr- By 234	4	SF	5	\$84	damaged
Floor - Tile Ceramic/ Porcelain	2nd FIr- By 234	348	SF	6	\$737	
Lavatory	2nd Flr- By 234	3	EA	6	\$959	
Lighting - Lay-in	2nd FIr- By 234	6	EA	7	\$0	
Lighting - Lay-in	2nd FIr- By 234	1	EA	6	\$119	cover missing
Partitions	2nd FIr- By 234	4	EA	6	\$1,188	-
Urinals	2nd FIr- By 234	3	EA	6	\$1,008	
Walls - Concrete Block	2nd FIr- By 234	611	SF	6	\$1,791	
Water Closet	2nd FIr- By 234	4	EA	6	\$1,344	
Accessories	2nd FIr Mens- Across from 208	143	SF	6	\$1,319	
Ceiling - Plaster/Drywall	2nd FIr Mens- Across from 208	143	SF	6	\$495	
Doors - Wood Doors inclu hw	2nd FIr Mens- Across from 208	1	EA	6	\$301	
Floor Drain	2nd FIr Mens- Across from 208	1	EA	6	\$1,059	
Floor - Tile Ceramic/ Porcelain	2nd FIr Mens- Across from 208	143	SF	6	\$303	
Lavatory	2nd FIr Mens- Across from 208	2	EA	6	\$639	
Lighting - Lay-in	2nd Flr Mens- Across from 208	4	EA	7	\$0	
Partitions	2nd FIr Mens- Across from 208	2	EA	6	\$594	
Urinals	2nd Flr Mens- Across from 208	1	EA	6	\$336	
Walls - Concrete Block	2nd Flr Mens- Across from 208	408	SF	6	\$1,196	
Water Closet	2nd Flr Mens- Across from 208	2	EA	6	\$672	
Accessories	2nd FIr Womens- By 208	143	SF	6	\$1,319	
Ceiling - Plaster/Drywall	2nd Flr Womens- By 208	143	SF	6	\$495	
Doors - Wood Doors inclu hw	2nd FIr Womens- By 208	1	EA	6	\$301	
Floor Drain	2nd Flr Womens- By 208	1	EA	6	\$1,059	
Floor - Tile Ceramic/ Porcelain	2nd FIr Womens- By 208	143	SF	6	\$303	
Lavatory	2nd Flr Womens- By 208	2	EA	6	\$639	
Lighting - Lay-in	2nd Flr Womens- By 208	3	EA	7	\$0	
Partitions	2nd Flr Womens- By 208	3	EA	6	\$891	
Walls - Concrete Block	2nd Flr Womens- By 208	408	SF	6	\$1,196	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Water Closet	2nd Flr Womens- By 208	3	EA	6	\$1,008	
	Accessories	3rd FIr- Across from 312	336	SF	6	\$3,099	
	Accessories	3rd FIr- Across from 312	352	SF	6	\$3,247	
	Ceiling - Plaster/Drywall	3rd FIr- Across from 312	336	SF	6	\$1,163	
	Ceiling - Plaster/Drywall	3rd FIr- Across from 312	352	SF	6	\$1,218	
	Doors - Wood Doors inclu hw	3rd FIr- Across from 312	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd FIr- Across from 312	1	EA	6	\$301	
	Floor Drain	3rd FIr- Across from 312	1	EA	6	\$1,059	
	Floor Drain	3rd FIr- Across from 312	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd FIr- Across from 312	336	SF	6	\$711	
	Floor - Tile Ceramic/ Porcelain	3rd FIr- Across from 312	352	SF	6	\$745	
	Lavatory	3rd FIr- Across from 312	3	EA	6	\$959	
	Lavatory	3rd FIr- Across from 312	3	EA	6	\$959	
	Lighting - Lay-in	3rd FIr- Across from 312	7	EA	7	\$0	
	Lighting - Lay-in	3rd FIr- Across from 312	7	EA	7	\$0	
	Partitions	3rd FIr- Across from 312	6	EA	6	\$1,782	
	Partitions	3rd FIr- Across from 312	4	EA	6	\$1,188	
	Urinals	3rd FIr- Across from 312	3	EA	6	\$1,008	
	Walls - Concrete Block	3rd FIr- Across from 312	595	SF	6	\$1,744	
	Walls - Concrete Block	3rd FIr- Across from 312	611	SF	6	\$1,791	
	Water Closet	3rd FIr- Across from 312	7	EA	6	\$2,352	
	Water Closet	3rd FIr- Across from 312	4	EA	6	\$1,344	
	Accessories	3rd FIr- Across from 338	336	SF	6	\$3,099	
	Ceiling - Plaster/Drywall	3rd FIr- Across from 338	336	SF	6	\$1,163	
	Doors - Wood Doors inclu hw	3rd FIr- Across from 338	1	EA	6	\$301	
	Floor Drain	3rd FIr- Across from 338	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd FIr- Across from 338	336	SF	6	\$711	
	Lavatory	3rd FIr- Across from 338	3	EA	6	\$959	
	Lighting - Lay-in	3rd FIr- Across from 338	7	EA	7	\$0	
	Partitions	3rd FIr- Across from 338	6	EA	6	\$1,782	
	Walls - Concrete Block	3rd FIr- Across from 338	595	SF	6	\$1,744	
	Water Closet	3rd FIr- Across from 338	7	EA	6	\$2,352	
	Accessories	3rd FIr- Across from 340	352	SF	6	\$3,247	
	Ceiling - Plaster/Drywall	3rd FIr- Across from 340	352	SF	6	\$1,218	
	Doors - Wood Doors inclu hw	3rd FIr- Across from 340	1	EA	6	\$301	
	Floor Drain	3rd FIr- Across from 340	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd FIr- Across from 340	352	SF	6	\$745	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Lavatory	3rd FIr- Across from 340	3	EA	6	\$959	
	Lighting - Lay-in	3rd FIr- Across from 340	7	EA	7	\$0	
	Partitions	3rd FIr- Across from 340	4	EA	6	\$1,188	
	Urinals	3rd FIr- Across from 340	3	EA	6	\$1,008	
	Walls - Concrete Block	3rd FIr- Across from 340	611	SF	6	\$1,791	
	Water Closet	3rd FIr- Across from 340	4	EA	6	\$1,344	
	Accessories	3rd FIr Mens- Across from 344	143	SF	6	\$1,319	
	Ceiling - Plaster/Drywall	3rd FIr Mens- Across from 344	143	SF	6	\$495	
	Doors - Wood Doors inclu hw	3rd FIr Mens- Across from 344	1	EA	6	\$301	
	Floor Drain	3rd FIr Mens- Across from 344	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd FIr Mens- Across from 344	143	SF	6	\$303	
	Lavatory	3rd FIr Mens- Across from 344	2	EA	6	\$639	
	Lighting - Lay-in	3rd FIr Mens- Across from 344	4	EA	7	\$0	
	Partitions	3rd FIr Mens- Across from 344	2	EA	6	\$594	
	Urinals	3rd Flr Mens- Across from 344	1	EA	6	\$336	
	Walls - Concrete Block	3rd Flr Mens- Across from 344	408	SF	6	\$1,196	
	Water Closet	3rd Flr Mens- Across from 344	2	EA	6	\$672	
	Accessories	3rd Flr Womens- Across from 308	143	SF	6	\$1,319	
	Ceiling - Plaster/Drywall	3rd Flr Womens- Across from 308	143	SF	6	\$495	
	Doors - Wood Doors inclu hw	3rd Flr Womens- Across from 308	1	EA	6	\$301	
	Floor Drain	3rd Flr Womens- Across from 308	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd Flr Womens- Across from 308	143	SF	6	\$303	
	Lavatory	3rd Flr Womens- Across from 308	2	EA	6	\$639	
	Lighting - Lay-in	3rd Flr Womens- Across from 308	3	EA	7	\$0	
	Partitions	3rd Flr Womens- Across from 308	3	EA	6	\$891	
	Walls - Concrete Block	3rd Flr Womens- Across from 308	408	SF	6	\$1,196	
	Water Closet	3rd Flr Womens- Across from 308	3	EA	6	\$1,008	
	Benches	Basement	5	LF	6	\$72	
	Ceiling	Basement	300		6	\$0	
	Doors - Steel Doors incl hw	Basement	1	EA	6	\$301	
	Floor Drain	Basement	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	Basement	300	SF	6	\$635	
	Hand Dryer	Basement	1	EA	6	\$230	
	Lavatory	Basement	1	EA	6	\$320	
	Lighting - Pendent/Surface	Basement	3	EA	7	\$0	
	Showers	Basement	1	EA	6	\$311	
	Walls - Plaster/Drywall	Basement	562	SF	6	\$1,551	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Walls - Tile Ceramic/ Porcelain	Basement	188	SF	6	\$425	
	Water Closet	Basement	1	EA	6	\$336	
	Accessories	In 012	75	SF	6	\$692	
	Ceiling - Plaster/Drywall	In 012	75	SF	6	\$260	
	Doors - Wood Doors inclu hw	In 012	1	EA	6	\$301	
	Floor Drain	In 012	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	In 012	75	SF	6	\$159	
	Lavatory	In 012	1	EA	6	\$320	
	Lighting - Lay-in	In 012	2	EA	7	\$0	
	Showers	In 012	1	EA	6	\$311	
	Walls - Concrete Block	In 012	250	SF	6	\$733	
	Walls - Tile Ceramic/ Porcelain	In 012	150	SF	6	\$339	
	Water Closet	In 012	1	EA	6	\$336	
	Accessories	In 100E	45	SF	6	\$415	
	Ceiling - Plaster/Drywall	In 100E	45	SF	6	\$156	
	Doors - Wood Doors inclu hw	In 100E	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	In 100E	45	SF	6	\$95	
	Lavatory	In 100E	1	EA	6	\$320	
	Lighting - Pendent/Surface	In 100E	1	EA	7	\$0	
	Lighting - Wall Mounted	In 100E	1	EA	7	\$0	
	Partitions	In 100E	1	EA	6	\$297	
	Walls - Concrete Block	In 100E	299	SF	6	\$877	
	Water Closet	In 100E	1	EA	6	\$336	
	Accessories	In Engineers Office	68	SF	6	\$627	
	Ceiling - Plaster/Drywall	In Engineers Office	68	SF	6	\$235	
	Doors - Wood Doors inclu hw	In Engineers Office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	In Engineers Office	68	SF	6	\$144	
	Lavatory	In Engineers Office	1	EA	6	\$320	
	Lighting - Lay-in	In Engineers Office	2	EA	7	\$0	
	Partitions	In Engineers Office	1	EA	6	\$297	
	Showers	In Engineers Office	1	EA	5	\$1,172	
	Walls - Concrete Block	In Engineers Office	283	SF	6	\$830	
	Water Closet	In Engineers Office	1	EA	6	\$336	
	Accessories	In office 014	5	SF	6	\$46	
	Ceiling - Plaster/Drywall	In office 014	50	SF	6	\$173	
	Doors - Wood Doors inclu hw	In office 014	1	EA	6	\$301	
	Floor Drain	In office 014	1	EA	6	\$1,059	



L L F	n Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Lay-in Lighting - Lay-in Partitions Showers	In office 014 In office 014 In office 014 In office 014	50 1 1	SF EA	6	\$106	
L L F	Lavatory Lighting - Lay-in Lighting - Lay-in Partitions	In office 014 In office 014	1	-			
l I F	Lighting - Lay-in Lighting - Lay-in Partitions	In office 014		EA	6		
L F	Lighting - Lay-in Partitions		4		0	\$320	
F	Partitions	In office 014	1	EA	6	\$119	
			1	EA	7	\$0	
ş	Chausera	In office 014	1	EA	6	\$297	
	Showers	In office 014	1	EA	6	\$311	
١	Nalls - Concrete Block	In office 014	200	SF	6	\$586	
١	Nalls - Tile Ceramic/ Porcelain	In office 014	100	SF	6	\$226	
١	Nater Closet	In office 014	1	EA	6	\$336	
1	Accessories	In office 030A	5	SF	6	\$46	
(Ceiling - Plaster/Drywall	In office 030A	50	SF	6	\$173	
I	Doors - Wood Doors inclu hw	In office 030A	1	EA	6	\$301	
I	Floor Drain	In office 030A	1	EA	6	\$1,059	
I	Floor - Tile Ceramic/ Porcelain	In office 030A	50	SF	6	\$106	
I	Lavatory	In office 030A	1	EA	6	\$320	
- I	Lighting - Lay-in	In office 030A	2	EA	7	\$0	
I	Partitions	In office 030A	1	EA	6	\$297	
;	Showers	In office 030A	1	EA	6	\$311	
١	Nalls - Concrete Block	In office 030A	200	SF	6	\$586	
١	Nalls - Tile Ceramic/ Porcelain	In office 030A	100	SF	6	\$226	
١	Nater Closet	In office 030A	1	EA	6	\$336	
1	Accessories	Men's Room in Main Office (unisex)	84	SF	6	\$775	
(Ceiling - Plaster/Drywall	Men's Room in Main Office (unisex)	84	SF	6	\$291	
I	Doors - Wood Doors inclu hw	Men's Room in Main Office (unisex)	1	EA	6	\$301	
I	Floor - Tile Ceramic/ Porcelain	Men's Room in Main Office (unisex)	84	SF	6	\$178	
- I	Lavatory	Men's Room in Main Office (unisex)	1	EA	6	\$320	
I	_ighting - Pendent/Surface	Men's Room in Main Office (unisex)	2	EA	7	\$0	
- I	_ighting - Wall Mounted	Men's Room in Main Office (unisex)	1	EA	7	\$0	
I	Partitions	Men's Room in Main Office (unisex)	2	EA	6	\$594	
1	Jrinals	Men's Room in Main Office (unisex)	1	EA	6	\$336	
١	Nalls - Concrete Block	Men's Room in Main Office (unisex)	280	SF	6	\$821	
١	Nater Closet	Men's Room in Main Office (unisex)	1	EA	6	\$336	
1	Accessories	North restroom near Engineer's office	90	SF	5	\$1,781	
(Ceiling - Plaster/Drywall	North restroom near Engineer's office	90	SF	6	\$311	
	Doors - Wood Doors inclu hw	North restroom near Engineer's office	1	EA	6	\$301	
1	Floor - Tile Ceramic/ Porcelain	North restroom near Engineer's office	90	SF	6	\$190	
	_avatory	North restroom near Engineer's office	1	EA	6	\$320	



Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Lighting - Lay-in	North restroom near Engineer's office	3	EA	7	\$0	
	Partitions	North restroom near Engineer's office	1	EA	6	\$297	
	Walls - Concrete Block	North restroom near Engineer's office	448	SF	6	\$1,313	
	Water Closet	North restroom near Engineer's office	1	EA	5	\$1,344	Not working
	Accessories	South restroom near Engineer's office	210	SF	6	\$1,937	
	Ceiling - Plaster/Drywall	South restroom near Engineer's office	210	SF	6	\$727	
	Doors - Wood Doors inclu hw	South restroom near Engineer's office	1	EA	7	\$0	
	Floor Drain	South restroom near Engineer's office	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	South restroom near Engineer's office	210	SF	6	\$444	
	Lavatory	South restroom near Engineer's office	1	EA	6	\$320	
	Lighting - Lay-in	South restroom near Engineer's office	5	EA	7	\$0	
	Partitions	South restroom near Engineer's office	2	EA	6	\$594	
	Urinals	South restroom near Engineer's office	1	EA	6	\$336	
	Walls - Concrete Block	South restroom near Engineer's office	715	SF	6	\$2,096	
	Water Closet	South restroom near Engineer's office	1	EA	6	\$336	
	Accessories	Women's Room in Main Office	84	SF	6	\$775	
	Ceiling - Plaster/Drywall	Women's Room in Main Office	84	SF	6	\$291	
	Doors - Wood Doors inclu hw	Women's Room in Main Office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Women's Room in Main Office	84	SF	6	\$178	
	Lavatory	Women's Room in Main Office	1	EA	6	\$320	
	Lighting - Pendent/Surface	Women's Room in Main Office	3	EA	7	\$0	
	Lighting - Wall Mounted	Women's Room in Main Office	1	EA	7	\$0	
	Partitions	Women's Room in Main Office	1	EA	6	\$297	
	Walls - Concrete Block	Women's Room in Main Office	280	SF	6	\$821	
	Water Closet	Women's Room in Main Office	1	EA	6	\$336	
						_	

Rooms (Other Than Classrooms) Subtotal:

\$1,599,983

Categ	ory: Building Interior						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	Dr						
	Ceiling - Lay-in	1st Floor	23,285	SF	6	\$69,925	
	Doors - Wood Doors include hw	1st Floor	6	EA	6	\$1,806	
	Drinking Fountains - Double Water Cooler	1st Floor	6	EA	6	\$2,262	
	Floor - Tile/Sheet	1st Floor	23,285	SF	6	\$12,653	
	Lighting - Lay-in	1st Floor	56	EA	7	\$0	

Building: Main



Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	pr						
	Lighting - Pendent/Surface	1st Floor	302	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	231	EA	7	\$0	
	Walls - Concrete Block	1st Floor	15,737	SF	6	\$46,133	
	Walls - Plaster/Drywall	1st Floor	15,737	SF	6	\$69,762	
	Ceiling - Lay-in	2nd Floor	12,578	SF	6	\$37,772	
	Ceiling - Lay-in	2nd Floor	27	SF	5	\$241	water damaged
	Drinking Fountains - Double Water Cooler	2nd Floor	4	EA	6	\$1,508	
	Floor - Tile/Sheet	2nd Floor	12,599	SF	6	\$6,846	
	Floor - Tile/Sheet	2nd Floor	6	SF	5	\$35	damaged
	Lighting - Pendent/Surface	2nd Floor	238	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	595	EA	6	\$55,237	
	Walls - Concrete Block	2nd Floor	17,693	SF	6	\$51,867	
	Walls - Concrete Block	2nd Floor	4	SF	5	\$56	crack in cmu
	Ceiling - Lay-in	3rd Floor	12,591	SF	6	\$37,811	
	Ceiling - Lay-in	3rd Floor	14	SF	5	\$125	water damaged
	Drinking Fountains - Double Water Cooler	3rd Floor	4	EA	6	\$1,508	
	Floor - Tile/Sheet	3rd Floor	12,605	SF	6	\$6,850	
	Lighting - Pendent/Surface	3rd Floor	250	EA	7	\$0	
	Student Lockers - One Tier	3rd Floor	394	EA	6	\$36,577	
	Walls - Concrete Block	3rd Floor	17,697	SF	6	\$51,879	
	Ceiling - Exposed	Basement	3,500	SF	6	\$5,205	
	Doors - Wood Doors include hw	Basement	2	EA	6	\$602	
	Floor - Concrete	Basement	2,200	SF	5	\$3,775	
	Floor - Tile/Sheet	Basement	1,300	SF	6	\$706	
	Lighting - Pendent/Surface	Basement	26	EA	7	\$0	
	Walls - Concrete Block	Basement	7,540	SF	6	\$22,104	
Safety							
	Camera Viewing Station	1st Floor	3	EA	6	\$2,048	1 in principal, 1 at security desk & 1 in Engineer
	Metal Dedector	1st Floor	3	EA	6	\$2,642	
	Security Cameras	Entire Building	1	EA	5	\$688	not working
	Security Cameras	Entire Building	7	EA	6	\$1,358	
	Security Cameras	Entire Building	1	EA	5	\$688	not working
	Security Cameras	Entire Building	27	EA	6	\$5,239	-
Stairs							
	Ceiling - Exposed	Stairwell A	326	SF	6	\$485	
	Floor - Tile	Stairwell A	792	SF	6	\$430	



Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Handrails	Stairwell A	86	LF	6	\$745	
	Lighting - Pendent/Surface	Stairwell A	10	EA	7	\$0	
	Stairs - Concrete	Stairwell A	43	LF	6	\$357	
	Walls - Concrete Block	Stairwell A	1,350	SF	6	\$3,958	
	Ceiling - Plaster/Drywall	Stairwell B	652	SF	6	\$4,774	
	Floor - Terrazzo	Stairwell B	384	SF	6	\$3,223	
	Handrails	Stairwell B	172	LF	6	\$1,491	
	Lighting - Pendent/Surface	Stairwell B	10	EA	7	\$0	
	Stairs - Terrazzo	Stairwell B	43	LF	6	\$399	
	Walls - Concrete Block	Stairwell B	1,683	SF	6	\$4,934	
	Ceiling - Exposed	Stairwell C	326	SF	6	\$485	
	Floor - Tile	Stairwell C	792	SF	6	\$430	
	Handrails	Stairwell C	86	LF	6	\$745	
	Lighting - Pendent/Surface	Stairwell C	10	EA	7	\$0	
	Stairs - Concrete	Stairwell C	43	LF	6	\$357	
	Walls - Concrete Block	Stairwell C	1,350	SF	6	\$3,958	
	Ceiling - Exposed	Stairwell D	326	SF	6	\$485	
	Floor - Tile	Stairwell D	792	SF	6	\$430	
	Handrails	Stairwell D	86	LF	6	\$745	
	Lighting - Pendent/Surface	Stairwell D	10	EA	7	\$0	
	Stairs - Concrete	Stairwell D	43	LF	6	\$357	
	Walls - Concrete Block	Stairwell D	1,350	SF	6	\$3,958	
	Ceiling - Plaster/Drywall	Stairwell E	652	SF	6	\$4,774	
	Floor - Terrazzo	Stairwell E	384	SF	6	\$3,223	
	Handrails	Stairwell E	172	LF	6	\$1,491	
	Lighting - Pendent/Surface	Stairwell E	10	EA	7	\$0	
	Stairs - Terrazzo	Stairwell E	43	LF	6	\$399	
	Walls - Concrete Block	Stairwell E	1,683	SF	6	\$4,934	
	Ceiling - Exposed	Stairwell F	326	SF	6	\$485	
	Floor - Tile	Stairwell F	792	SF	6	\$430	
	Handrails	Stairwell F	86	LF	6	\$745	
	Lighting - Pendent/Surface	Stairwell F	10	EA	7	\$0	
	Stairs - Concrete	Stairwell F	43	LF	6	\$357	
	Walls - Concrete Block	Stairwell F	1,350	SF	6	\$3,958	
	Ceiling - Exposed	Stairwell L (2nd to Basement)	230	SF	6	\$342	
	Floor - Tile	Stairwell L (2nd to Basement)	96	SF	6	\$52	
	Handrails	Stairwell L (2nd to Basement)	72	LF	6	\$624	



Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Lighting - Pendent/Surface	Stairwell L (2nd to Basement)	1	EA	7	\$0	
	Lighting - Wall Mounted	Stairwell L (2nd to Basement)	2	EA	7	\$0	
	Stairs - Concrete	Stairwell L (2nd to Basement)	36	LF	6	\$299	
	Walls - Concrete Block	Stairwell L (2nd to Basement)	826	SF	6	\$2,421	
	Ceiling - Plaster/Drywall	Stairwell M (1st to Basement)	134	SF	6	\$981	
	Floor - Tile	Stairwell M (1st to Basement)	48	SF	6	\$26	
	Handrails	Stairwell M (1st to Basement)	36	LF	6	\$312	
	Lighting - Wall Mounted	Stairwell M (1st to Basement)	1	EA	7	\$0	
	Stairs - Concrete	Stairwell M (1st to Basement)	18	LF	6	\$149	
	Walls - Concrete Block	Stairwell M (1st to Basement)	413	SF	6	\$1,211	
	Ceiling - Exposed	Stairwell N	326	SF	6	\$485	
	Floor - Tile	Stairwell N	792	SF	6	\$430	
	Handrails	Stairwell N	86	LF	6	\$745	
	Lighting - Pendent/Surface	Stairwell N	10	EA	7	\$0	
	Stairs - Concrete	Stairwell N	43	LF	6	\$357	
	Walls - Concrete Block	Stairwell N	1,342	SF	6	\$3,934	
	Walls - Concrete Block	Stairwell N	8	SF	5	\$113	crack in cmu
Vertical	Conveyance						
Vertical			1	EA	6	\$19,238	
	Conveyance Elevator - Hydraulic Elevator		1	EA			
	Conveyance		1	EA		\$19,238 \$621,164	
Buildi	Conveyance Elevator - Hydraulic Elevator		1	EA			
Buildi Total	Conveyance Elevator - Hydraulic Elevator ng Interior Subtotal:		1	EA		\$621,164	
Buildi Total SITE	Conveyance Elevator - Hydraulic Elevator ng Interior Subtotal: Building Cost		1	EA		\$621,164	
Buildi Total SITE	Conveyance Elevator - Hydraulic Elevator ng Interior Subtotal:		1	EA		\$621,164	
Buildi Total SITE Categ	Conveyance Elevator - Hydraulic Elevator ng Interior Subtotal: Building Cost	Location	Quantity		\$9	\$621,164),238,468	Comments
Buildi Total SITE Categ Group	Conveyance Elevator - Hydraulic Elevator ng Interior Subtotal: Building Cost ory: Site Item - Type				\$9	\$621,164),238,468	Comments
Buildi Total SITE Categ Group	Conveyance Elevator - Hydraulic Elevator ng Interior Subtotal: Building Cost ory: Site Item - Type			Unit	\$9	\$621,164),238,468	Comments
Buildi Total SITE Categ Group Athletic	Conveyance Elevator - Hydraulic Elevator ng Interior Subtotal: Building Cost ory: Site Item - Type Surface - Natural	Location Baseball/Football fields N of site,	Quantity	Unit	\$9 Rank	\$621,164 9,238,468 Cost	Comments
Buildi Total SITE Categ	Conveyance Elevator - Hydraulic Elevator ng Interior Subtotal: Building Cost ory: Site Item - Type Surface - Natural	Location Baseball/Football fields N of site,	Quantity	Unit	\$9 Rank	\$621,164 9,238,468 Cost	Comments
Buildi Total SITE Categ Group Athletic	Conveyance Elevator - Hydraulic Elevator ng Interior Subtotal: Building Cost ory: Site Item - Type Surface - Natural ainage	Location Baseball/Football fields N of site, through alley	Quantity 99,336	Unit SF	\$9 Rank	\$621,164 9,238,468 Cost \$82,389	Comments



SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fencing	I						
	Fencing - Chain Link	Athletic Site	1,924	LF	6	\$36,125	Secure fence to supports
	Fencing - New Standard Ornamental	Entire Site	1,987	LF	6	\$63,392	Scrape, Prime and Paint
Landsc	ape						
	Benches	Entire Site	5	EA	6	\$2,150	
	Irrigation	Entire Site	12,417	SF	6	\$14,027	Athletic Field
	Landscape - Grass	Entire Site	12,417	SF	6	\$10,299	Athletic Field
	Landscape - Grass	Entire Site	68,797	SF	5	\$104,282	Need to re-seed
	Landscape - Hardscape- Asphalt	Entire Site	5,182	SF	6	\$12,523	
	Landscape - Hardscape- Concrete	Entire Site	27,130	SF	7	\$0	
	Landscape - Hardscape- Concrete	Entire Site / Loading Dock	2,007	SF	6	\$14,235	Cracks
	Landscape - Hardscape- Concrete	Entire Site / Site South	1,620	SF	4	\$34,494	Cracks/ Heeving/ Bulging
	Landscape - Hardscape- Concrete	Entire Site / South West	1,201	SF	5	\$15,319	Poured rubber surface -Cracking Splitting
	Landscape - Hardscape- Pavers	Entire Site	5,017	SF	6	\$28,410	
	Parkway trees	Entire Site	64	EA	6	\$42,243	
	Planting Beds/ Area	Entire Site	5,534	SF	6	\$9,101	
	Retaining Wall - Concrete	Entire Site	294	SF	6	\$6,891	
	Trash Receptacles	Entire Site	5	EA	6	\$1,561	
Parking	Lot						
U	Concrete Curbs	Parking Lot- North	1,004	LF	6	\$12,893	
	Interior Plantings	Parking Lot- North	215	LF	6	\$9,147	
	Lighting - Pole Mounted	Parking Lot- North	6	EA	6	\$8,715	
	Surface - Asphalt	Parking Lot- North	37,928	SF	6	\$91,661	
	Trash Compactor	Parking Lot- North	1	EA	6	\$0	
	Trash Enclosure - Chain Links	Parking Lot- North	276	SF	6	\$4,843	
	Vehicular Screening	Parking Lot- North	99	LF	6	\$7,795	
Sidewal	ks						
	Sidewalks - Internal Walks	Entire Site	2,026	LF	6	\$24,336	Cracks
	Sidewalks - Perimeter Sidewalks	Entire Site	15,884	SF	6	\$31,573	
Signage			,				
Cignage	Flag Pole - Flag Pole	Site South, West and NW and SW Corners of the Building / Site West	1	EA	6	\$1,657	
	Marquee - Free Standing Back lighted w/ LED	Site South, West and NW and SW Corners of the Building / Site South	1	EA	6	\$0	
	Monument - Building Mounted Cut Letter Sign	Site South, West and NW and SW Corners of the Building	2	EA	6	\$0	NW & SW Corners of Building



\$9.946.959

SITE

Category: Site							
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments	
Signage							
Monument - Sign	Site South, West and NW and SW Corners of the Building / Site West	1	EA	6	\$0		
Site Subtotal:					\$708,491		
Total Site Cost					\$708,491		

Campus Total ^{2 3}

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main		•	ŀ			1		1				ļ		ļ
Art Room	Art Room	1st Floor	106	108	1,600	1	30	80	305	16	50	Ν	Ν	Ν
Art Room	Other Instructional Use	1st Floor	111	NA	2,162	1	4	20	130	0	50	Ν	N	N
Art Room	Other Instructional Use	2nd Floor	234	224	1,610	1	8	20	325	20	50	Ν	N	Ν
Choral Room	Choral Room	2nd Floor	226	216	1,300	1	1	16	230	16	50	Ν	N	Y
Choral Room	Choral Room	2nd Floor	226 A, B, C & C	216 Practice	260	4	4	16	0	0	40	Ν	N	N
Computer Lab	Other Instructional Use	1st Floor	105	107	1,300	1	16	36	0	0	50	Ν	N	Ν
Computer Lab	Regular Classroom	2nd Floor	242	230	855	1	32	40	145	8	50	Ν	N	N
Computer Lab	Other Instructional Use	3rd Floor	310	305	975	1	38	130	212	16	50	Ν	N	Ν
Computer Lab	Language Lab	3rd Floor	312	306	975	1	38	130	212	16	50	Ν	Ν	N
Dance Room	Dance Room	1st Floor	114	114	2,166	1	1	8	0	0	50	Ν	Ν	N
Fitness Room	Other Instructional Use	Basement	004	OTC Rifle Ran	2,450	0	0	6	0	0	40	Ν	N	N
Laboratory/Shop	Other Instructional Use	1st Floor	110	111	700	1	8	20	126	0	50	Ν	N	N
Laboratory/Shop	Other Instructional Use	2nd Floor	240	229	1,170	1	26	60	335	16	50	Ν	N	N
Music Room	Music Room	2nd Floor	222	213	1,500	1	2	16	0	0	40	Ν	N	N
Music Room	Music Room	2nd Floor	224	215	1,500	1	1	16	0	0	40	Ν	N	N
Other Instructional Use	Other Instructional Use	1st Floor	108	109	1,600	1	8	20	126	0	50	Ν	N	N
Regular Classroom	Other Instructional Use	1st Floor	107	110	1,600	1	8	20	0	0	50	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	202	201	700	1	8	20	120	8	50	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	204	202	700	1	8	20	120	8	50	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	206	203	700	1	8	20	120	8	50	Ν	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	204	875	1	8	20	148	12	50	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	210	205	700	1	8	44	120	8	50	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	212	206	875	1	26	56	148	12	50	Ν	N	N
Regular Classroom	Art Room	2nd Floor	214	208	1,160	1	8	20	210	16	50	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	218	210	875	1	8	20	148	12	50	Ν	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	220	211	875	1	8	20	148	12	50	Ν	Ν	N
Regular Classroom	Music Room	2nd Floor	228	218	1,015	1	8	20	175	12	50	Ν	N	N
Regular Classroom	Laboratory/Shop	2nd Floor	236	226	1,160	1	8	30	210	16	50	Ν	N	N
Regular Classroom	Regular Classroom	2nd Floor	244	231	855	1	8	20	145	8	50	Ν	N	N
Regular Classroom	Regular Classroom	2nd Floor	248	234	1,288	1	12	28	230	12	50	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	300	300	700	1	8	20	120	12	40	N	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	302	301	700	1	8	20	120	12	40	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	304	302	700	1	2	20	120	12	40	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	306	303	700	1	8	20	120	12	50	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	308	304	875	1	8	20	148	12	50	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	316	308	700	1	8	20	120	12	50	N	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	318	309	700	1	8	20	120	12	50	Ν	Ν	Ν



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main		1	+		ļ.	1	1	I			+	ł		+
Regular Classroom	Regular Classroom	3rd Floor	320	310	700	1	8	20	120	12	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	322	311	700	1	8	20	120	12	50	N	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	324	316	875	1	8	20	120	12	50	N	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	326	317	875	1	8	20	120	8	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	330	319	700	1	8	20	120	8	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	332	320	700	1	8	20	120	8	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	334	321	700	1	8	20	120	12	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	336	322	700	1	8	20	120	8	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	338	323	700	1	8	20	120	8	50	Ν	Ν	Y
Regular Classroom	Regular Classroom	3rd Floor	342	325	875	1	8	20	120	12	50	Ν	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	344	326	700	1	8	20	120	8	50	Ν	Ν	Ν
Science Lab Level 1	Other Instructional Use	2nd Floor	230	220	1,320	1	2	60	230	12	50	Ν	Ν	Ν
Science Lab Level 1	Other Instructional Use	2nd Floor	232	222	1,320	1	2	60	230	12	50	Ν	Ν	Ν
Science Lab Level 1	Science Lab Level 1	3rd Floor	346	327	1,015	1	2	8	200	12	50	Ν	Ν	Ν
Science Lab Level 1	Science Lab Level 1	3rd Floor	350	330	1,750	1	30	100	300	8	50	Ν	Ν	Ν
Science Lab Level 3	Science Lab Level 3	3rd Floor	348	329	1,170	1	2	30	335	8	50	Ν	Ν	Ν
Science Lab Level 3	Science Lab Level 3	3rd Floor	352	332	875	1	8	20	200	8	50	Ν	Ν	Y
Science Lab Level 3	Science Lab Level 3	3rd Floor	354	334	875	1	8	20	200	8	50	Ν	Ν	Y
Special Education	Other Instructional Use	1st Floor	118	NA	3,120	3	10	60	900	36	50	Ν	Y	Ν
Special Education	Art Room	2nd Floor	216	209	1,160	1	8	20	210	16	50	Ν	Ν	Ν
Special Education	Other Instructional Use	2nd Floor	238	227	1,160	1	8	30	210	16	50	Ν	Ν	Ν
Special Education	Other Instructional Use	2nd Floor	241	220	582	1	2	8	200	12	40	Ν	Ν	Ν
Special Education	Other Instructional Use	3rd Floor	328	318	700	1	8	20	120	8	50	Ν	Ν	Ν
Special Education	Multi Purpose Room	3rd Floor	339	328	712	1	2	18	200	12	40	Ν	Ν	Ν
Store Room	Regular Classroom	2nd Floor	200	200	700	1	8	20	120	12	50	Ν	Ν	Ν
Store Room	Regular Classroom	2nd Floor	246	232	715	1	8	20	120	8	50	Ν	Ν	Ν
Store Room	Regular Classroom	3rd Floor	340	324	700	1	8	20	120	12	50	Ν	Ν	Ν
Vacant	Regular Classroom	3rd Floor	314	307	875	1	32	42	148	12	50	N	Ν	Ν
Weight	Multi Purpose Room	Basement	005	Boy's Locker	2,415	0	0	12	0	0	40	Ν	Ν	Ν