

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|-----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1957 | 1 | 17,250 | \$958,986 |
| Addition | 1986 | 1 | 15,000 | \$1,001,443 |
| Linked Addition | 1997 | 2 | 160,000 | \$4,951,734 |
| SITE | | | | \$2,876,312 |
| Campus Total | | | 192,250 | \$9,788,474 |

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|-----------------|----------|------|------|---------|---|
| Entrand | e | | | | | | |
| | Entrance Control - Audio and Video | 4 | 1 | EA | 7 | \$0 | power operator on interior of vestibules |
| | Exterior Doors - Exterior Steel Door | 4A | 1 | EA | 5 | \$1,341 | peeling paint, deteriorated door surround |
| | Exterior Doors - Side lite | 4 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Side lite | 5 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | 4 | 3 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | 5 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 4 | 3 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 4A | 1 | EA | 5 | \$822 | |
| | Exterior Doors - Transom Lite | 5 | 2 | EA | 7 | \$0 | |
| | Exterior Stairs - Concrete | 4A | 5 | LF | 6 | \$409 | |
| | Exterior Stairs - Concrete | 5 | 8 | LF | 6 | \$654 | |
| | Ramp Handrail - Steel_Ramp Handrail | 5 | 20 | LF | 6 | \$173 | |
| | Ramps - Concrete | 5 | 12 | LF | 6 | \$1,803 | |
| Founda | tion | | | | | | |
| | Foundation - Concrete | Entire Building | 913 | LF | 7 | \$0 | |
| | Superstructure - Concrete | Entire Building | 20,264 | SF | 7 | \$0 | |



Building: Main

Category: Building Exterior

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|--|-----------------------------|---------------|------|-----------|------------------------|---|
| _ighting | 3 | | | | | | |
| | Exterior Lighting - Wall Mounted | Building Exterior | 6 | EA | 6 | \$1,732 | |
| Roof Sy | vstem | | | | | | |
| - | Chimney - Brick Chimney- Concrete/ Mortar Liner | A / North | 29 | LF | 6 | \$27,686 | |
| | Coping - Metal | А | 54 | LF | 6 | \$1,734 | |
| | Downspouts - Interior Downspouts | А | 52 | LF | 6 | \$1,728 | clean debris from drains at roof level |
| | Roof Structure - Concrete | А | 15,100 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | А | 15,100 | SF | 5 | \$317,633 | ponding, cracked seams |
| Valls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building | 85 | SF | 4 | \$23,706 | rebar exposed, spalled |
| | Canopy - Concrete/ Stucco | Entire Building | 77 | SF | 5 | \$9,038 | spalled at corners |
| | Exterior Walls - Brick | Entire Building | 45 | SF | 5 | \$1,071 | ivy and efflorescence |
| | Exterior Walls - Brick | Entire Building | 264 | SF | 4 | \$43,468 | step cracking, open joints bulging above window |
| | Exterior Walls - Brick | Entire Building | 8,636 | SF | 6 | \$58,043 | |
| | Exterior Walls - Stone-Cast | Entire Building | 416 | SF | 6 | \$2,796 | |
| Vindow | /S | | | | | | |
| | Curtain wall - Louver | Entire Building | 12 | SF | 6 | \$135 | |
| | Lintels - Brick | Entire Building | 12 | LF | 6 | \$0 | louvers |
| | Lintels - Steel | Entire Building | 256 | LF | 6 | \$7,431 | |
| | Lintels - Steel | Entire Building | 40 | LF | 4 | \$18,111 | corroded, causing brick above to bulge, spall |
| | Windows - Decorative | Entire Building | 1,950 | SF | 7 | \$0 | fixed, double pane |
| | ng Exterior Subtotal: | | | | | \$519,514 | |
| Buildi | | | | | | · · · / · | |
| Buildi | | | | | | | |
| | ng: Main | | | | | · - ,- | |
| Buildi | | | | | | | |
| Buildi Catego | ng: Main | Location | Quantity | Unit | | | Comments |
| Buildi Catego Group | ng: Main ory: Electrical System | Location | Quantity | Unit | | | Comments |
| Buildi Catego Group | ng: Main ory: Electrical System Item - Type | Location Entire Building | Quantity 4 | Unit | | | Comments |
| Buildin Catego Group Emerge | ng: Main ory: Electrical System Item - Type ncy System Exit Signs - Corridors and Stairs | | | | Rank | Cost | Comments |
| Buildi Catego Group Emerge | ng: Main ory: Electrical System Item - Type ncy System Exit Signs - Corridors and Stairs | | | | Rank | Cost | Comments |
| Buildin Catego Group Emerge Main Se | ng: Main ory: Electrical System Item - Type ncy System Exit Signs - Corridors and Stairs ervice | Entire Building | 4 | EA | Rank 2 | Cost \$2,182 | Comments |
| Buildin Catego Group Emerge Main Se | ng: Main ory: Electrical System Item - Type ncy System Exit Signs - Corridors and Stairs ervice Main Electrical Service - 2000 A 120/208/3PH | Entire Building | 4 | EA | Rank 2 | Cost \$2,182 | Comments |

Main Distribution Panels - Greater than 600 amp

Boiler Room

1 EA 7

\$0



Building: Main

| | Leasting | Oursetter | I In it | Daul | Onst | Commonto |
|---|------------------------------|-----------|---------|------|----------|------------------------|
| Group Item - Type | Location | Quantity | Unit | Rank | | Comments |
| Electrical System Subtotal: | | | | | \$21,915 | |
| Building: Main | | | | | | |
| Category: Safty System | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Fire Alarm | Location | Quantity | Onit | Nank | 0031 | Comments |
| Fire Alarm Panel | Entire Building / North East | 1 | EA | 7 | \$0 | Serves addition |
| Fire Alarm Strobe Lights | Entire Building | 17,250 | SF | 7 | \$0 | |
| Fire Alarm_System | Entire Building | 17,250 | SF | 7 | \$0 | |
| Safty System Subtotal: | | | | | \$0 | |
| Building: Main | | | | | | |
| Category: Mechanical System | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Air Conditioning | | | | | | |
| Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | \$3,334 | |
| Air Handling Systems | | | | | | |
| Fan Coil Unit- Floor Mounted - Steam | Northwest rooms / 1st Floor | 3 | EA | 6 | \$4,592 | |
| Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons | Roof | 1 | EA | 6 | \$2,051 | |
| Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Less than 5 tons | Roof | 1 | EA | 6 | \$1,898 | |
| Boiler Systems | | | | | | |
| Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 H | P Boiler Room | 1 | EA | 6 | \$2,046 | |
| Chemical Feed System | Boiler Room | 1 | EA | 7 | \$0 | |
| Chemical Feeder | Boiler Room | 1 | EA | 7 | \$0 | |
| Combustion Dampers | Boiler Room | 1 | EA | 7 | \$0 | |
| Condensate Pump | Boiler Room | 1 | EA | 5 | \$18,196 | |
| Feed Water Pumps and Tank | Boiler Room | 1 | EA | 7 | \$0 | |
| Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP | Boiler Room | 1 | EA | 5 | \$8,508 | |
| Piping - Condensate Pipe- Steel | Boiler Room | 450 | LF | 5 | \$5,489 | |
| Piping - Steam Pipe- Steel | Boiler Room | 450 | LF | 5 | \$6,338 | |
| Heating Devices | | | | | | |
| Cabinet Heaters - With Steam Coil | Entire Building | 6 | EA | 5 | \$10,577 | |
| | Dage 2 of 64 | | | | | Accompany Data: E/21/2 |



Building: Main

Category: Mechanical System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------|----------|------|------|-----------|--|
| Heating Devices | | | | | | |
| Fin Tube - Steam | Entire Building | 24 | LF | 5 | \$1,954 | |
| Temperature Control | | | | | | |
| Thermostats - DDC | Entire Building | 2 | EA | 7 | \$0 | |
| Thermostats - Pneumatic | Entire Building | 8 | EA | 4 | \$5,898 | Thermostats are not working and cannot be refurbished. |
| Unit Ventilation | | | | | | |
| Unit Ventilators- Floor Mounted- Steam Heating Coils Only | Entire Building | 6 | EA | 4 | \$119,955 | |
| Ventilation | | | | | | |
| Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 2 | EA | 4 | \$12,784 | |
| Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 1 | EA | 4 | \$6,392 | |
| Mechanical System Subtotal: | | | | | \$210,013 | |

Building: Main

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-----------------|----------|------|------|-----------|---|
| Hot Wa | ter | | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 6 | \$310 | |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 20,264 | SF | 4 | \$14,489 | Piping > 50 years old, and has many pipe clamps |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 20,264 | SF | 4 | \$29,267 | Piping > 50 years old, and has many pipe clamps |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 20,264 | SF | 4 | \$11,011 | Piping > 50 years old, and has many pipe clamps |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 20,264 | SF | 4 | \$26,080 | Piping > 50 years old, and has many pipe clamps |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 20,264 | SF | 4 | \$17,387 | Piping > 50 years old, and has many pipe clamps |
| | Sanitary Piping | Entire Building | 20,264 | SF | 6 | \$18,546 | |
| | Storm Piping | Entire Building | 20,264 | SF | 6 | \$17,676 | |
| | Vent Piping | Entire Building | 20,264 | SF | 6 | \$13,619 | |
| Plum | bing System Subtotal: | | | | | \$148,385 | |
| | | | | | | •••••• | |
| Buildi | ng: Main | | | | | | |

| Group Item - Type Location Quantity Unit Rank Cost Comments |
|---|
|---|



Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|-------------------------------------|
| Classro | oom #101 (Special Education) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | \$0 | |
| | Casework | 1st Floor | 21 | LF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 642 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 3 | EA | 6 | \$903 | |
| | Floor - Carpet | 1st Floor | 642 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 8 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 820 | SF | 7 | \$0 | |
| | Work Sink | 1st Floor | 1 | EA | 7 | \$0 | |
| Classro | oom #102 (Pre School) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | \$0 | |
| | Casework | 1st Floor | 48 | LF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 994 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 1st Floor | 994 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 1,004 | SF | 6 | \$2,943 | |
| Classro | oom #103 (Special Education) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | \$0 | |
| | Casework | 1st Floor | 42 | LF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 994 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | 1st Floor | 994 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 16 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 1,514 | SF | 6 | \$4,438 | 15 If of a stepped settlement crack |
| | Wireless System | 1st Floor | 1 | EA | 7 | \$0 | |
| Classro | oom #104 (Computer Lab) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 6 | \$991 | |
| | Casework | 1st Floor | 42 | LF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 989 | SF | 6 | \$806 | |
| | Ceiling - Splined | 1st Floor | 5 | SF | 4 | \$70 | Missing and loose ceiling tiles. |
| | Chalk Board | 1st Floor | 18 | LF | 4 | | Obsolete Material. |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |



Building: Main

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|-------------------------------|-----------|----------|------|------|---------|--|
| sroo | om #104 (Computer Lab) | | | | | | |
| | Floor - Tile | 1st Floor | 994 | SF | 6 | \$2,175 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 8 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | \$0 | |
| | Student Lockers - One Tier | 1st Floor | 11 | EA | 6 | \$1,021 | |
| | Walls - Concrete Block | 1st Floor | 1,050 | SF | 6 | \$3,078 | |
| | Wireless System | 1st Floor | 1 | EA | 6 | \$372 | |
| | Work Sink | 1st Floor | 1 | EA | 7 | \$0 | |
| sroc | om #105 (Special Education) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 6 | \$991 | |
| | Casework | 1st Floor | 40 | LF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 994 | SF | 7 | \$0 | |
| | Chalk Board | 1st Floor | 21 | LF | 4 | \$1,928 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 1st Floor | 994 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 1,514 | SF | 7 | \$0 | Glass wall separating teaching kitchen not quantified |
| | Work Sink | 1st Floor | 1 | EA | 7 | \$0 | quantitiou |
| sroo | om #106 (Special Education) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | \$0 | |
| | Casework | 1st Floor | 38 | LF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 994 | SF | 7 | \$0 | 1 ceiling tile missing |
| | Chalk Board | 1st Floor | 21 | LF | 4 | \$1,928 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 3 | EA | 6 | \$903 | |
| | Floor - Tile/Sheet | 1st Floor | 994 | SF | 6 | \$995 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 50 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 1,514 | SF | 7 | \$0 | |
| sro | om #107 (Science Lab Level 3) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | \$0 | |
| | Casework | 1st Floor | 144 | LF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 1,086 | SF | 6 | \$885 | |
| | Chalk Board | 1st Floor | 14 | LF | 4 | \$1,285 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |



Building: Main

Category: Classrooms

| Group Item - Type | Loc | ation Quanti | ty Un | it Rank | Cost | Comments |
|----------------------------------|-----|--------------|-------|---------|----------|--|
| Classroom #107 (Science Lab Leve | 3) | | | | | |
| Floor - Tile/Sheet | 1st | Floor 1,08 | 6 SI | F 7 | \$0 | |
| Gas Line | 1st | Floor | 1 E/ | A 7 | \$0 | |
| Lighting - Pendent/Surface | 1st | Floor 2 | 0 E/ | A 7 | \$0 | |
| Marker Board | 1st | Floor | 8 LF | - 7 | \$0 | |
| Storage/ Closet | 1st | Floor 3 | 6 SI | F 7 | \$0 | |
| Walls - Concrete Block | 1st | Floor 1,04 | 0 SI | F 7 | \$0 | |
| Work Sink | 1st | Floor | 2 E/ | A 7 | \$0 | |
| Classroom #108 (Science Classroo | n) | | | | | |
| Casework | 1st | Floor 8 | 8 LF | - 6 | \$2,222 | |
| Ceiling - Lay-in | 1st | Floor 1,01 | 4 SI | F 7 | \$0 | |
| Doors - Side-lite | 1st | Floor 1 | 5 SI | F 7 | \$0 | |
| Doors - Wood Doors inclu h | 1st | Floor | 2 E/ | A 7 | \$0 | |
| Floor - Tile/Sheet | 1st | Floor 1,01 | 4 SI | F 7 | \$0 | |
| Lighting - Pendent/Surface | 1st | Floor 3 | 0 E/ | A 7 | \$0 | |
| Marker Board | 1st | Floor 2 | 0 LF | - 7 | \$0 | |
| Storage/ Closet | 1st | Floor 18 | 5 SI | F 7 | \$0 | |
| Walls - Concrete Block | 1st | Floor 86 | 5 SI | F 7 | \$0 | Greenhouse including glass wall assessed under room tab 'Greenhouse' |
| Work Sink | 1st | Floor | 1 E/ | A 7 | \$0 | |
| Classrooms Subtotal: | | | | | \$32,598 | |

Classrooms Subtotal:

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost Comments |
|---------|-----------------------------|---------------|----------|------|------|---------------|
| Adminis | strative Suites/Offices | | | | | |
| | AC Unit | Office Room A | 1 | EA | 7 | \$0 |
| | Ceiling - Splined | Office Room A | 296 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | Office Room A | 3 | EA | 6 | \$903 |
| | Floor - Carpet | Office Room A | 296 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | Office Room A | 5 | EA | 7 | \$0 |
| | Power Distribution | Office Room A | 14 | EA | 7 | \$0 |
| | Storage/ Closet | Office Room A | 42 | SF | 7 | \$0 |
| | Walls - Concrete Block | Office Room A | 635 | SF | 7 | \$0 |
| | AC Unit | Office Room B | 1 | EA | 7 | \$0 |
| | Ceiling - Splined | Office Room B | 270 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | Office Room B | 2 | EA | 6 | \$602 |



Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|------------------------|----------|------|------|---------|--|
| Admini | strative Suites/Offices | | | | | | |
| | Floor - Carpet | Office Room B | 270 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Office Room B | 5 | EA | 7 | \$0 | |
| | Power Distribution | Office Room B | 8 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Office Room B | 660 | SF | 7 | \$0 | |
| | Work SInk | Office Room B | 1 | EA | 7 | \$0 | |
| Green I | House | | | | | | |
| | Finishes | In Classroom 108 | 325 | SF | 6 | \$1,780 | Greenhouse wall/roof connection to main building |
| | Glazing | In Classroom 108 | 375 | SF | 6 | \$9,336 | |
| | 5 | | | | | +-, | |
| MDF_IC | | | | | | | |
| | Doors - Wood Doors inclu hw | In Special Ed Room 103 | 1 | EA | 6 | \$301 | |
| | Finishes | In Special Ed Room 103 | 50 | SF | 7 | \$0 | |
| | Ventilation and Cooling | In Special Ed Room 103 | 1 | EA | 6 | \$1,855 | Room was warm |
| Mechar | nical/ Service Rooms | | | | | | |
| | Boiler Room | North end | 780 | SF | 7 | \$0 | |
| | Mechanical/ Service Rooms | North end | 242 | SF | 7 | \$0 | |
| | Storage Room | North end | 50 | SF | 7 | \$0 | |
| | Janitor's Closet | Off of Corridor | 40 | SF | 7 | \$0 | |
| | Storage Room | Off of Corridor | 55 | SF | 7 | \$0 | |
| Prep Ro | oom | | | | | | |
| | Casework | In Classroom 107 | 9 | LF | 7 | \$0 | |
| | Ceiling - Splined | In Classroom 107 | 128 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | In Classroom 107 | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | In Classroom 107 | 128 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | In Classroom 107 | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | In Classroom 107 | 450 | SF | 7 | \$0 | |
| Restro | om | | | | | | |
| | Accessories | 1st Floor | 258 | SF | 7 | \$0 | |
| | Accessories | 1st Floor | 258 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 258 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 258 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 258 | SF | 7 | \$0 | |



Building: Main

| Note with the construction of the cons | Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|--------|---------------------------------|------------------|----------|------|------|-------|--|
| Lavatory1st Floor2FA7S0Lavatory1st Floor1FA7S0Lavatory1st Floor1FA7S0Light is a recessed incandescentLighting - Lay-in1st Floor1FA7S0Light is a recessed incandescentLighting - Pendert/Surface1st Floor4FA7S0Light is a recessed incandescentLighting - Pendert/Surface1st Floor4FA7S0Partitions1st Floor4FA7S0Partitions1st Floor7S0SPartition is missing a door handleWalls - Concrete Block1st FloorSF7S0Walls - Concrete Block1st FloorSF7S0Walls - Structural Glazed Tile1st FloorSF7S0Walls - Structural Glazed Tile1st FloorSF7S0Walls - Concrete Block1st FloorSF7S0Walls - Structural Glazed Tile1st FloorSF7S0Walls - Structural Glazed Tile1st FloorSF7S0Walls - Concrete Block1st FloorSF7S0Walls - Structural Glazed Tile1st FloorSF7S0Walls - Structural Glazed Tile1st FloorSF7S0Doors - Word Doors inclu hwIn Baler RoomSF7S0Lighting - Pendert/Surface1st FloorSF7S0< | Restro | om | | | | | | |
| Lavatory1st Floor2EA7S00Lighting - Lay-in1st Floor1EA7S010Lighting - Lay-in1st Floor1EA7S01Lighting - Pendert/Surface1st Floor4EA7S00Lighting - Pendert/Surface1st Floor4EA7S00Partitions1st Floor4EA7S00Partitions1st Floor4EA7S00Partitions1st Floor13EA7S00Walls - Concrete Block1st Floor13SF7S00Walls - Concrete Block1st Floor13SF7S00Walls - Concrete Block1st Floor14EA7S00Walls - Concrete Block1st Floor14EA7S00Walls - Concrete Block1st Floor14EA7S00Walls - Concrete Block1st Floor4EA7S00Walls - Concrete Block1st Floor4EA7S00Walls - Concrete Block1st Floor4EA7S00Walls - Concrete Block1st Floor4EA7S00Walls - Concrete Block1st Floor4EA7S00Water Closet1st Floor4EA7S00Colling - Pladete/DywallIn Balier Room10EA7S00Lighting - Pladete/DywallIn Balier Room | | Floor - Tile Ceramic/ Porcelain | 1st Floor | 258 | SF | 7 | \$0 | |
| Lavatory1st Floor1FA69 330Lighting - Lay-in1st Floor1FA7S0Light is a recessed incandescentLighting - Pendent/Surface1st Floor4FA7S0Light is a recessed incandescentLighting - Pendent/Surface1st Floor4FA7S0Partitions1st Floor4FA7S0Partitions1st Floor2FA7S0Walls - Concrete Block1st Floor18SF7S0Walls - Concrete Block1st FloorSF7S0Walls - Concrete Block1st FloorSF7S0Caling - Plaster/DynallIn Boler Room1FA7S0Concrete BlockIn Bioler Room1FA7S0Lighting - Lay - MaxerIn Bioler Room1FA7S0Concrete BlockIn Bioler Room1FA7S0Lighting - Pendent/SurfaceIn Bioler Room1FA7S0Doors - Wood Doors inclu hwIn Bioler Room1FA7S0Lighting - Pendent/Surface | | Lavatory | 1st Floor | 1 | EA | 7 | \$0 | |
| LightingLughtingLughting1st Floor1EA7\$0Light is a racessed incandescentLighting- Pendent/Surface1st Floor4EA7\$0Pendent/SurfaceLighting- Pendent/Surface1st Floor4EA7\$0Pendent/SurfacePartitions1st Floor4EA7\$0Pendent/SurfacePartitions1st Floor2EA7\$0Pendent/SurfaceUrinals1st Floor3SF7\$0Pendent/SurfaceWalis<-Concrete Block | | Lavatory | 1st Floor | 2 | EA | 7 | \$0 | |
| Lighting1 st Floor1EA7\$0Light is a recessed incandescentLightingPendent/Surface1st Floor4EA7\$0Partitions1st Floor4EA7\$0Partitions1st Floor2EA7\$0Partitions1st Floor3EA7\$0UninalsConcrete Block1st Floor3SF7\$0WallsConcrete Block1st Floor38SF7\$0WallsStructural Glazed Tile1st Floor54SF7\$0WallsStructural Glazed Tile1st Floor54SF7\$0WallsStructural Glazed Tile1st Floor4EA7\$0WallsStructural Glazed Tile1st Floor4EA7\$0Water Closet1st Floor4EA7\$0Water Closet1st Floor4EA7\$0CellingPlater Room1EA7\$0DoorsNod Doors inclu hwIn Boiler Room1EA7\$0LightingPlater Room1EA7\$0UnditClassrom 10230SF7\$0Vater ClosetIn Boiler Room1EA7\$0Water ClosetIn Boiler Room1EA7\$0UnditsConstrue BlockIn Boiler Room1EA7\$0 <tr<< td=""><td></td><td>Lavatory</td><td>1st Floor</td><td>1</td><td>EA</td><td>6</td><td>\$320</td><td></td></tr<<> | | Lavatory | 1st Floor | 1 | EA | 6 | \$320 | |
| Lighting - Pendent/Surface1st Ploor4EA7SOPartitions1st Ploor4EA7SOPartitions1st Ploor2EA7SOUrinals1st Ploor2EA7SOWalls - Concrete Block1st Ploor183SF7SOWalls - Concrete Block1st Ploor183SF7SOWalls - Structural Glazed Tile1st PloorSF7SOWalls - Structural Glazed Tile1st PloorSF7SOWalls - Structural Glazed Tile1st PloorSF7SOWater Closet1st PloorSF7SOWater Closet1st PloorSF7SOCosting - Plaster/DrywallIn Boiler RoomSF7SODoors - Wood Doors inclu twoIn Boiler RoomSF7SOUring - Pendent/SurfaceIn Boile | | Lighting - Lay-in | 1st Floor | 1 | EA | 7 | \$0 | Light is a recessed incandescent |
| Lighting - Pendent/Surface1st Floor4EA7SOPartitions1st Floor4EA7SOPartitons1st Floor3EA7SOWales - Concrete Block1st Floor3SF7SOWales - Concrete Block1st FloorSOSF7SOWales - Concrete Block1st FloorSOSF7SOWales - Structural Glazed Tile1st FloorSOSF7SOWales - Structural Glazed Tile1st FloorSF7SOWater Closet1st FloorSF7SOWater Closet1st FloorSF7SOAccessoriesIn Bolier RoomSF7SODors - Wader ClosetIn Bolier RoomSF7SODors - Wader ClosetIn Bolier RoomSF7SODors - Wader ClosetIn Bolier RoomSF7SOLawatoryIn Bolier RoomSF7SOLawatoryIn Bolier RoomSF7SOValle - Consete BlockIn Classroom 102SF7SOCeling - Plaster/DrywallIn Classroom 102SF7SOAccessoriesIn Classroom 102SF7SODors - Wood Dors inclub wIn Classroom 102SF7SOCeling - Plaster/DrywallIn Classroom 102SF7SODors - Wood Dors inclub wIn Classroom 102SF7 | | Lighting - Lay-in | 1st Floor | 1 | EA | 7 | \$0 | Light is a recessed incandescent |
| Paritions1st Floor4EA7S0One parition is missing a door handleParitions1st Floor2EA730Urinals1st Floor3SF730Walls - Concrete Block1st Floor103SF730Walls - Structural Glazed Tile1st Floor54SF730Walls - Structural Glazed Tile1st Floor54SF730Water Closet1st Floor4EA730Water Closet1st Floor4EA730Water Closet1st Floor4EA730Celling - Plaster/DywallIn Boler Room30SF730Doors - Wood Doors inclu hwIn Boler Room10EA730ElavatoryIn Boler Room10EA730Upining - Pendent/SurfaceIn Boler Room1EA730Walls - Concrete BlockIn Boler Room1EA730Walls - Concrete BlockIn Boler Room1EA730Walls - Structural BloaceIn Classroom 10230SF730Walls - Concrete BlockIn Classroom 1021EA730Walls - Concrete BlockIn Classroom 1021EA730Walls - Concrete BlockIn Classroom 1021EA730Doors - Wood Doors inclu hwIn Classroom 1021EA< | | Lighting - Pendent/Surface | 1st Floor | 4 | EA | 7 | \$0 | |
| Paritions1st Floor2EA7S0Urinals1st Floor13EA7S0Walls - Concrete Block1st Floor183SF7S0Walls - Structural Glazed Tile1st Floor183SF7S0Walls - Structural Glazed Tile1st Floor504SF7S0Walls - Structural Glazed Tile1st Floor2EA7S0Water Closet1st Floor2EA7S0Water Closet1st Floor2EA7S0Water Closet1st Floor30SF7S0Coling - Plaster/DryvallIn Boller Room30SF7S0Doors - Wood Doors inclu hwIn Boller Room1EA7S0LavatoryIn Boller Room1EA7S0LavatoryIn Boller Room1EA7S0Mater ClosetIn Boller Room1EA7S0Mater ClosetIn Boller Room1EA7S0Mater ClosetIn Boller Room1EA7S0Mater ClosetIn Boller Room1EA7S0Ceiling - Plaster/DryvallIn Classroom 10230SF7S0Doors - Wood Doors inclu hwIn Classroom 1021EA7S0Ceiling - Plaster/DryvallIn Classroom 1021EA7S0Doors - Wood Doors inclu hwIn Clas | | Lighting - Pendent/Surface | 1st Floor | 4 | EA | 7 | \$0 | |
| Urinals1st Floor357\$0Walls - Concrete Block1st Floor183SF7\$0Walls - Concrete Block1st Floor183SF7\$0Walls - Structural Glazed Tile1st Floor504SF7\$0Walls - Structural Glazed Tile1st Floor2EA7\$0Water Closet1st Floor2EA7\$0Accessories1st Floor4EA7\$0Celling - Plaster/DywallIn Boler Room30SF7\$0Doors - Wood Doors inclu hwIn Boler Room10EA6\$331Floor - Tile SheetIn Boler Room11EA7\$0Lightling - Pendent/SurfaceIn Boler Room16SF7\$0Uing ing - Pendent/SurfaceIn Boler Room16SF7\$0Water ClosetIn Boler Room16SF7\$0Water ClosetIn Boler Room16SF7\$0Water ClosetIn Boler Room16SF7\$0Water ClosetIn Boler Room16SF7\$0Mater ClosetIn Boler Room16SF7\$0Mater ClosetIn Boler Room16SF7\$0Mater ClosetIn Classroom 10218SF7\$0Doors - Wood Doors inclu hwIn Classroom 10218SF7\$0Lightling - Water Closet< | | Partitions | 1st Floor | 4 | EA | 7 | \$0 | One partition is missing a door handle |
| Walls - Concrete Block1st Floor183SF7\$0Walls - Concrete Block1st Floor184SF7\$0Walls - Structural Glazed Tile1st Floor504SF7\$0Walls - Structural Glazed Tile1st Floor2EA7\$0Water Closet1st Floor2EA7\$0Water Closet1st Floor4EA7\$0Ceiling - Plaster/DrywallIn Boiler Room30SF7\$0Concrete BlockIn Boiler Room30SF7\$0Cons - Wood Doors inclu hwIn Boiler Room1EA7\$00Hoors - Tile/SheetIn Boiler Room1EA7\$0LavatoryIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room1EA7\$0Water ClosetIn Boiler Room1EA7\$0Mater ClosetIn Boiler Room1EA7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF7\$0Floor - TileIn Classroom 1021EA7\$0Doors - Wood Doors inclu hwIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0 | | Partitions | 1st Floor | 2 | EA | 7 | \$0 | |
| Walls - Concrete Block1st Floor183SF7\$0Walls - Structural Glazed Tile1st Floor504SF7\$0Water Closet1st Floor604SF7\$0Water Closet1st Floor4EA7\$0Ceiling - Plaster/DrywallIn Boiler Room30SF7\$0Doors - Wood Doors inclu hwIn Boiler Room1EA6\$301Floor - Tile/SheetIn Boiler Room1EA7\$0Lighting - Pendent/SurfaceIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room16SF7\$0Walls - Concrete BlockIn Boiler Room16SF7\$0Walls - Concrete BlockIn Boiler Room16SF7\$0AccessoriesIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF7\$0Walls - Concrete BlockIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10216SF7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Wall Concrete Block | | Urinals | 1st Floor | 3 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tile1st Floor504SF7S0Water Closet1st Floor2EA7S0Water Closet1st Floor4EA7S0Water Closet1st Floor4EA7S0Ceiling - Plaster/DrywallIn Boiler Room30SF7S0Doors Wood Doors inclu hwIn Boiler Room30SF7S0Floor - Tile/SheetIn Boiler Room30SF7S0LavatoryIn Boiler Room1EA7S0Ughting - Pendent/SurfaceIn Boiler Room1EA7S0Walls - Concrete BlockIn Boiler Room15SF7S0Walls - Concrete BlockIn Boiler Room1EA7S0Mater ClosetIn Boiler Room15SF7S0Water ClosetIn Boiler Room15SF7S0Water ClosetIn Boiler Room1EA7S0AccessoriesIn Classroom 1023SF7S0Doors - Wood Doors inclu hwIn Classroom 1021EA7S0Lighting - Vall MountedIn Classroom 1021EA7S0Lighting - Wall MountedIn Classroom 1021EA7S0Lighting - Vall MountedIn Classroom 1021EA7S0Walls - Concrete BlockIn Classroom 1021EA7S0 <t< td=""><td></td><td>Walls - Concrete Block</td><td>1st Floor</td><td>183</td><td>SF</td><td>7</td><td>\$0</td><td></td></t<> | | Walls - Concrete Block | 1st Floor | 183 | SF | 7 | \$0 | |
| Walls - Structural Glazed Tile1st Floor504SF7\$0Water Closet1st Floor2EA7\$0Water Closet1st Floor4EA7\$0AccessoriesIn Boiler Room30SF7\$0Ceiling - Plaster/DrywallIn Boiler Room30SF7\$0Doors - Wood Doors inclu hwIn Boiler Room30SF7\$0LavatoryIn Boiler Room30SF7\$0Lighting - Pendent/SurfaceIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room1EA7\$0AccessoriesIn Classroom 10230SF7\$0Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF7\$0AccessoriesIn Classroom 1021EA7\$0Floor - TileIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA </td <td></td> <td>Walls - Concrete Block</td> <td>1st Floor</td> <td>183</td> <td>SF</td> <td>7</td> <td>\$0</td> <td></td> | | Walls - Concrete Block | 1st Floor | 183 | SF | 7 | \$0 | |
| Water Closet1st Floor2EA7\$0Water Closet1st Floor14EA7\$0AccessoriesIn Bolier Room30SF7\$0Ceiling - Plaster/DrywallIn Bolier Room30SF7\$0Doors - Wood Doors inclu hwIn Bolier Room30SF7\$0Floor - Tile/SheetIn Bolier Room10EA7\$0LavatoryIn Bolier Room10EA7\$0Lighting - Pendent/SurfaceIn Bolier Room16EA7\$0Water ClosetIn Bolier Room16EA7\$0AccessoriesIn Bolier Room1EA7\$0AccessoriesIn Bolier Room1EA7\$0AccessoriesIn Bolier Room1EA7\$0AccessoriesIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10210EA7\$0Floor - TileIn Classroom 1021EA7\$0LavatoryIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA< | | Walls - Structural Glazed Tile | 1st Floor | 504 | SF | 7 | \$0 | |
| Water Closet1st Floor4EA7\$0AccessoriesIn Boiler Room30SF7\$0Ceiling - Plaster/DywallIn Boiler Room30SF7\$0Doors - Wood Doors inclu hwIn Boiler Room30SF7\$0Floor - Tile/SheetIn Boiler Room30SF7\$0LavatoryIn Boiler Room1EA7\$0Watle - Concrete BlockIn Boiler Room16SF7\$0Water ClosetIn Boiler Room16SF7\$0AccessoriesIn Boiler Room16SF7\$0Ceiling - Plaster/DywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF7\$0Floor - TileIn Classroom 10230SF6\$66LavatoryIn Classroom 10216SF7\$0Floor - TileIn Classroom 10216SF7\$0Lighting - Wall MountedIn Classroom 10216SF7\$0Watle - ClosetIn Classroom 10216SF7\$0Watle - Close | | Walls - Structural Glazed Tile | 1st Floor | 504 | SF | 7 | \$0 | |
| AccessoriesIn Boiler Room30SF7\$0Ceiling - Plaster/DrywallIn Boiler Room30SF7\$0Doors - Wood Doors inclu hwIn Boiler Room1EA6\$301Floor - Tile/SheetIn Boiler Room30SF7\$0LavatoryIn Boiler Room1EA7\$0Lighting - Pendent/SurfaceIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room16SF7\$0Water ClosetIn Boiler Room1EA7\$0AccessoriesIn Boiler Room1EA7\$0Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF7\$0Floor - TileIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0HaustoryIn Classroom 1021EA7\$0Ughting - Wall MountedIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Wat | | Water Closet | 1st Floor | 2 | EA | 7 | \$0 | |
| Ceiling - Plaster/DrywallIn Boiler Room30SF7\$0Doors - Wood Doors inclu hwIn Boiler Room1EA6\$301Floor - Tile/SheetIn Boiler Room30SF7\$0LavatoryIn Boiler Room1EA7\$0Lighting - Pendent/SurfaceIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room16EA7\$0Vater ClosetIn Classroom 10230SF7\$0AccessoriesIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF56\$16Lighting - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 1021EA7\$0Lighting - Vall MountedIn Classroom 1021EA7\$0Lighting - Vall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Lighting - Vall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Water Cl | | Water Closet | 1st Floor | 4 | EA | 7 | \$0 | |
| Doors - Wood Doors inclu hwIn Boiler Room1EA6\$301Floor - Tile/SheetIn Boiler Room30SF7\$0LavatoryIn Boiler Room1EA7\$0Lighting - Pendent/SurfaceIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room16SF7\$0Water ClosetIn Boiler Room16SF7\$0AccessoriesIn Classroom 10230SF7\$0Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF6\$66LavatoryIn Classroom 1021EA7\$0Floor - TileIn Classroom 1021EA7\$0LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0 | | Accessories | In Boiler Room | 30 | SF | 7 | \$0 | |
| Floor - Tile/SheetIn Boiler Room30SF7\$0LavatoryIn Boiler Room1EA7\$0Lighting - Pendent/SurfaceIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room165SF7\$0Water ClosetIn Boiler Room1EA7\$0AccessoriesIn Classroom 10230SF7\$0Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF6\$66Floor - TileIn Classroom 10230SF6\$66Lighting - Wall MountedIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Valls - Concrete BlockIn Classroom 1021EA7\$0Floor - TileIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Waller ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104CoessoriesIn Classroom 10530SF6 | | Ceiling - Plaster/Drywall | In Boiler Room | 30 | SF | 7 | \$0 | |
| LavatoryIn Boiler Room1EA7\$0Lighting - Pendent/SurfaceIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room165SF7\$0Water ClosetIn Boiler Room1EA7\$0AccessoriesIn Classroom 10230SF7\$0Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF6\$66LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Ughting - Wall MountedIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0KocessoriesIn Classroom 1021EA7\$0Coling - Plaster/DrywallIn Classroom 10530SF7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$14Lighting - Mater DownIn Classroom 10530SF6\$30Doors - Wood Doors inclu hwIn Classroom 1051EA6 <td></td> <td>Doors - Wood Doors inclu hw</td> <td>In Boiler Room</td> <td>1</td> <td>EA</td> <td>6</td> <td>\$301</td> <td></td> | | Doors - Wood Doors inclu hw | In Boiler Room | 1 | EA | 6 | \$301 | |
| Lighting - Pendent/SurfaceIn Boiler Room1EA7\$0Walls - Concrete BlockIn Boiler Room165SF7\$0Water ClosetIn Boiler Room1EA7\$0AccessoriesIn Classroom 10230SF7\$0Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF6\$66Floor - TileIn Classroom 10230SF6\$66LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 10530SF7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Floor - Tile/Sheet | In Boiler Room | 30 | SF | 7 | \$0 | |
| Walls - Concrete BlockIn Boiler Room165SF7\$0Water ClosetIn Boiler Room1EA7\$0AccessoriesIn Classroom 10230SF7\$0Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 10230SF6\$66Floor - TileIn Classroom 10230SF6\$66LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 1021EA7\$0Operative StrikeIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 10530SF6\$104Ceiling - Plaster/DrywallIn Classroom 10530SF6\$301Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Lavatory | In Boiler Room | 1 | EA | 7 | \$0 | |
| Water ClosetIn Boiler RoomIEA7\$0AccessoriesIn Classroom 10230SF7\$0Toilet paper available.Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 1021EA7\$0Floor - TileIn Classroom 10230SF6\$66LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 1021EA7\$0Ceiling - Plaster/DrywallIn Classroom 1021EA7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF5\$10Doors - Wood Doors inclu hwIn Classroom 10530SF6\$104Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Lighting - Pendent/Surface | In Boiler Room | 1 | EA | 7 | \$0 | |
| AccessoriesIn Classroom 10230SF7\$0Toilet paper available.Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 1021EA7\$0Floor - TileIn Classroom 10230SF6\$66LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 1021EA7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 1021EA7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Walls - Concrete Block | In Boiler Room | 165 | SF | 7 | \$0 | |
| Ceiling - Plaster/DrywallIn Classroom 10230SF7\$0Doors - Wood Doors inclu hwIn Classroom 1021EA7\$0Floor - TileIn Classroom 10230SF6\$66LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 102165SF7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 1021EA7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Water Closet | In Boiler Room | 1 | EA | 7 | \$0 | |
| Doors - Wood Doors inclu hwIn Classroom 1021EA7NoFloor - TileIn Classroom 10230SF6\$66LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 102165SF7\$0Water ClosetIn Classroom 102165SF7\$0AccessoriesIn Classroom 1021EA7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Accessories | In Classroom 102 | 30 | SF | 7 | \$0 | Toilet paper available. |
| Floor - TileIn Classroom 10230SF6\$66LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 102165SF7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 10530SF7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Ceiling - Plaster/Drywall | In Classroom 102 | 30 | SF | 7 | \$0 | |
| LavatoryIn Classroom 1021EA7\$0Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 102165SF7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 10530SF7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Doors - Wood Doors inclu hw | In Classroom 102 | 1 | EA | 7 | \$0 | |
| Lighting - Wall MountedIn Classroom 1021EA7\$0Walls - Concrete BlockIn Classroom 102165SF7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 10530SF7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA5\$30 | | Floor - Tile | In Classroom 102 | 30 | SF | 6 | \$66 | |
| Walls - Concrete BlockIn Classroom 102165SF7\$0Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 10530SF7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Lavatory | In Classroom 102 | 1 | EA | 7 | \$0 | |
| Water ClosetIn Classroom 1021EA7\$0AccessoriesIn Classroom 10530SF7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Lighting - Wall Mounted | In Classroom 102 | 1 | EA | 7 | \$0 | |
| AccessoriesIn Classroom 10530SF7\$0Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Walls - Concrete Block | In Classroom 102 | 165 | SF | 7 | \$0 | |
| Ceiling - Plaster/DrywallIn Classroom 10530SF6\$104Doors - Wood Doors inclu hwIn Classroom 1051EA6\$301 | | Water Closet | In Classroom 102 | 1 | EA | 7 | \$0 | |
| Doors - Wood Doors inclu hw In Classroom 105 1 EA 6 \$301 | | Accessories | In Classroom 105 | 30 | SF | 7 | \$0 | |
| | | Ceiling - Plaster/Drywall | In Classroom 105 | 30 | SF | 6 | \$104 | |
| Floor - Tile/SheetIn Classroom 10530SF7\$0 | | Doors - Wood Doors inclu hw | In Classroom 105 | 1 | EA | 6 | \$301 | |
| | | Floor - Tile/Sheet | In Classroom 105 | 30 | SF | 7 | \$0 | |



Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|------------------------------|----------|------|------|-------|------------------------|
| Restroc | om | | | | | | |
| | Lavatory | In Classroom 105 | 1 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | In Classroom 105 | 1 | EA | 6 | \$124 | |
| | Walls - Concrete Block | In Classroom 105 | 165 | SF | 7 | \$0 | |
| | Water Closet | In Classroom 105 | 1 | EA | 7 | \$0 | |
| | Accessories | Outside Office Room B | 50 | SF | 6 | \$461 | |
| | Ceiling - Plaster/Drywall | Outside Office Room B | 50 | SF | 6 | \$173 | 5 sf of clg is damaged |
| | Doors - Wood Doors inclu hw | Outside Office Room B | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | Outside Office Room B | 50 | SF | 7 | \$0 | |
| | Lavatory | Outside Office Room B | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Outside Office Room B | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Outside Office Room B | 270 | SF | 7 | \$0 | |
| | Water Closet | Outside Office Room B | 1 | EA | 7 | \$0 | |
| | Accessories | Unisex at center of corridor | 30 | SF | 6 | \$277 | |
| | Ceiling - Plaster/Drywall | Unisex at center of corridor | 30 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Unisex at center of corridor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | Unisex at center of corridor | 30 | SF | 7 | \$0 | |
| | Lavatory | Unisex at center of corridor | 1 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | Unisex at center of corridor | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Unisex at center of corridor | 165 | SF | 7 | \$0 | |
| | Water Closet | Unisex at center of corridor | 1 | EA | 7 | \$0 | |

Rooms (Other Than Classrooms) Subtotal:

\$18,564

Building: Main

| | , , | | | | | | |
|---------|--|-----------------|----------|------|------|---------|--------------------|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Corrido | r | | | | | | |
| | Ceiling - Splined | 1st Floor | 1,955 | SF | 6 | \$5,647 | |
| | Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 6 | \$336 | |
| | Drinking Fountains - Single Water Cooler | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 1,955 | SF | 6 | \$1,062 | |
| | Lighting - Pendent/Surface | 1st Floor | 23 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 2,414 | SF | 7 | \$0 | |
| | Doors - Wood Doors include hw | Mechanical Room | 3 | EA | 6 | \$903 | |
| | Ceiling - Splined | Vestibules | 134 | SF | 7 | \$0 | |
| | Ceiling - Splined | Vestibules | 5 | SF | 5 | \$48 | Some tiles damaged |
| | Doors - Side-lite | Vestibules | 50 | EA | 7 | \$0 | |
| | | | | | | | |



Building: Main

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|-------------------------------|------------|----------|------|------|---------|-----------------------------------|
| Corrido | r | | | | | | |
| | Doors - Store Front | Vestibules | 5 | EA | 7 | \$0 | |
| | Floor - Tile Quarry | Vestibules | 139 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Vestibules | 3 | EA | 7 | \$0 | Lighting is recessed incandescent |
| | Walls - Masonry | Vestibules | 240 | SF | 7 | \$0 | |
| Vertical | Conveyance | | | | | | |
| | Elevator - Hydraulic Elevator | | 1 | EA | 7 | \$0 | |
| Buildi | ng Interior Subtotal: | | | | | \$7,997 | |

Total Building Cost

\$958,986

Building: Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|--------------------------------|----------|------|------|---------|----------|
| Intranc | e | | | | | | |
| | Exterior Doors - Exterior Steel Door | 2 | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 3A- Boiler Room | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 6 | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 6A- Mechanical Room/Head House | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Side lite | North Courtyard | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Side lite | South Courtyard | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Store Front | 3 | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | 5A | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | North Courtyard | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | South Courtyard | 1 | EA | 6 | \$546 | |
| | Exterior Doors - Transom Lite | 3 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 5A | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | North Courtyard | 2 | EA | 6 | \$627 | |
| | Exterior Stairs - Concrete | 5A | 8 | LF | 7 | \$0 | |
| | Exterior Stairs - Concrete | 6 | 15 | LF | 7 | \$0 | |
| oundat | tion | | | | | | |
| | Foundation - Concrete | Entire Building | 713 | LF | 7 | \$0 | |
| | Superstructure - Concrete | Entire Building | 20,264 | SF | 7 | \$0 | |
| ighting | 3 | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 3 | EA | 6 | \$866 | |



Building: Addition

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|--------------------------------|----------|------|------|-----------|-----------------------------|
| Lighting | 1 | | | | | | |
| Roof Sy | stem | | | | | | |
| | Coping - Metal | В | 165 | LF | 6 | \$5,299 | mod bit applied over coping |
| | Coping - Metal | С | 140 | LF | 6 | \$4,496 | |
| | Downspouts - Exterior Downspouts | С | 176 | LF | 7 | \$0 | |
| | Downspouts - Interior Downspouts | В | 104 | LF | 6 | \$3,456 | |
| | Parapet - Parapet < 16" Height | В | 165 | LF | 7 | \$0 | |
| | Parapet - Parapet < 16" Height | С | 140 | LF | 7 | \$0 | |
| | Roof Structure - Concrete | В | 14,390 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | С | 4,290 | SF | 7 | \$0 | |
| | Roof - Metal | В | 2 | SF | 3 | \$141 | hole in seam |
| | Roof - Metal | B / South | 160 | SF | 5 | \$4,409 | |
| | Roof - Metal | С | 990 | SF | 6 | \$13,265 | |
| | Roof - Modified Bitumen | В | 250 | SF | 4 | \$12,859 | ponding |
| | Roof - Modified Bitumen | В | 14,854 | SF | 5 | \$312,458 | |
| | Roof - Modified Bitumen | С | 3,300 | SF | 5 | \$69,416 | |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 9,945 | SF | 6 | \$66,840 | |
| | Exterior Walls - Brick | Entire Building / North Façade | 105 | SF | 5 | \$2,500 | cracking |
| | Exterior Walls - Stone-Cast | Entire Building | 100 | SF | 6 | \$672 | |
| Window | s | | | | | | |
| | Clerestory - Glass Double-Pane | Entire Building | 480 | SF | 6 | \$4,496 | |
| | Curtain wall - Louver | Entire Building | 183 | SF | 6 | \$2,052 | |
| | Guard - Guards wire guard | Entire Building | 2,294 | SF | 7 | \$0 | |
| | Lintels - Brick | Entire Building | 54 | LF | 6 | \$0 | |
| | Lintels - Steel | Entire Building | 30 | LF | 7 | \$0 | |
| | Skylite - Glass Double-Pane | Entire Building / South | 100 | SF | 6 | \$2,390 | fiberglass, translucent |
| | Skylite - Lexan | Entire Building / North | 5 | SF | 5 | \$0 | puncture |
| | Skylite - Lexan | Entire Building / South | 3,430 | SF | 6 | \$81,961 | |
| | Storefront Windows | Entire Building | 126 | SF | 6 | \$1,413 | |
| | Windows - Casement Aluminum Double-pane | Entire Building | 751 | SF | 7 | \$0 | |
| | Windows - Decorative | Entire Building | 1,971 | SF | 7 | \$0 | fixed, double pane |
| | na Evterior Cubtetel | | | | | ¢500 047 | |

Building Exterior Subtotal:

\$596,317

Building: Addition



Category: Electrical System

| Location | Quantity | Unit | Rank | Cost | Comments |
|---|--|--|---|--|--|
| | | | | | |
| Electrical Room | 1 | EA | 7 | \$0 | |
| Entire Building / 1st Floor | 3,498 | SF | 6 | \$1,050 | |
| Entire Building / 1st Floor | 548 | SF | 6 | \$204 | |
| Entire Building | 7 | EA | 6 | \$1,048 | |
| | | | | | |
| Electrical Room | 1 | EA | 7 | \$0 | |
| Entire Building | 1 | EA | 7 | \$0 | |
| | | | | | |
| Electrical Room | 7 | EA | 7 | \$0 | |
| Electrical Room | 1 | EA | 7 | \$0 | |
| | | | | \$2,302 | |
| | | | | | |
| | | | | | |
| | | | | | |
| Location | Quantity | Unit | Rank | Cost | Comments |
| | | | | | |
| Entire Building | 20,264 | SF | 6 | \$7,244 | |
| | | | | \$7,244 | |
| | | | | | |
| | | | | | |
| | | | | | |
| Location | Quantity | Unit | Rank | Cost | Comments |
| | | | | | |
| g Roof | 1 | EA | 6 | \$2,792 | |
| | | | | | |
| | | | | | |
| Boiler Room | 1 | EA | 5 | \$34,472 | Combustion dampers shared with main. |
| Boiler Room Boiler Room | 1 | EA EA | 5 6 | \$34,472 \$725 | Combustion dampers shared with main. |
| | | | | | Combustion dampers shared with main. |
| Boiler Room | 1 | EA | 6 | \$725 | Combustion dampers shared with main. |
| Boiler Room Boiler Room | 1 1 | EA EA | 6 6 | \$725 \$539 | Combustion dampers shared with main. |
| Boiler Room Boiler Room Boiler Room | 1 1 4 | EA EA EA | 6 6 6 | \$725 \$539 \$1,497 | Combustion dampers shared with main. |
| Boiler Room Boiler Room Boiler Room | 1 1 4 1 | EA EA EA | 6 6 6 | \$725 \$539 \$1,497 | Combustion dampers shared with main. |
| | Electrical Room Entire Building / 1st Floor Entire Building / 1st Floor Entire Building Electrical Room Electrical Room Electrical Room Electrical Room | Electrical Room 1 Entire Building / 1st Floor 3,498 Entire Building / 1st Floor 548 Entire Building 7 Electrical Room 1 Entire Building 1 Electrical Room 1 Electrical Room 7 Electrical Room 7 Electrical Room 7 Electrical Room 1 Entire Building 1 Location Quantity Entire Building 20,264 | Electrical Room1EAEntire Building / 1st Floor3,498SFEntire Building / 1st Floor548SFEntire Building1EAElectrical Room1EAElectrical Room7EAElectrical Room7EAElectrical Room1EAElectrical Room1EAElectrical Room1EAElectrical Room1EAElectrical Room1SFLocationQuantityUnitEntire Building20,264SFLocationQuantityUnit | Electrical Room1EA7Entire Building / 1st Floor3,498SF6Entire Building / 1st Floor548SF6Entire Building7EA6Electrical Room1EA7Electrical Room7EA7Electrical Room7EA7Electrical Room1EA7Electrical Room7EA7Electrical Room7EA7Electrical Room20,264SF6Entire Building20,264SF6LocationQuantityUnitRankEntire Building20,264SF6 | Electrical Room1EA7\$0Entire Building / 1st Floor3,498SF6\$1,050Entire Building1 st Floor548SF6\$204Entire Building7EA6\$1,048Electrical Room1EA7\$0Entire Building1EA7\$0Electrical Room1EA7\$0Electrical Room7EA7\$0Electrical Room7EA7\$0Electrical Room1EA7\$0Electrical Room1EA7\$0Electrical Room20,264SF6\$7,244Entire Building20,264SF6\$7,244LocationQuantityUnitRankCostLocationQuantityUnitRankCost |



Building: Addition

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|-----------------------------|----------|------|------|-----------|----------|
| Heating | Devices | | | | | | |
| | Fin Tube - Hot Water | Entire Building | 45 | LF | 5 | \$3,664 | |
| | Unit Heater - Gas | Greenhouse | 2 | EA | 6 | \$556 | |
| Mechan | ical Plumbing | | | | | | |
| | Hydronic Supply and Return - Galvanized | Entire Building | 500 | LF | 6 | \$38,660 | |
| Unit Ver | itilation | | | | | | |
| | Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors | Entire Building | 7 | EA | 6 | \$8,734 | |
| Ventilat | ion | | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Greenhouse | 4 | EA | 5 | \$0 | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building / 1st Floor | 1 | EA | 7 | \$0 | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building / Roof | 2 | EA | 4 | \$12,784 | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building / Roof | 4 | EA | 4 | \$25,568 | |
| Mecha | inical System Subtotal: | | | | | \$138,007 | |

Building: Addition

Category: Plumbing System

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|--|-----------------|----------|------|------|----------|--|
| ping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 20,264 | SF | 6 | \$4,057 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 20,264 | SF | 6 | \$4,926 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 20,264 | SF | 6 | \$3,188 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 20,264 | SF | 6 | \$3,767 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 20,264 | SF | 6 | \$2,898 | |
| | Sanitary Piping | Entire Building | 20,264 | SF | 6 | \$18,546 | |
| | Storm Piping | Entire Building | 20,264 | SF | 6 | \$17,676 | |
| | Vent Piping | Entire Building | 20,264 | SF | 6 | \$13,619 | |
| imps | | | | | | | |
| | Pumps - Domestic Booster Pump-Simplex | Greenhouse | 1 | EA | 4 | \$25,441 | Booster pump for greenhouse areas not functional, but parts are available for repair |
| lumk | bing System Subtotal: | | | | | \$94,117 | |

Building: Addition



Chicago High School for Agricultural Sciences

3857 W 111th St Chicago, IL 60655

| roup | Item - Type | Location Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|-------------------|------|------|---------|----------|
| - | om #152 (Computer Lab) | | | | | |
| | Ceiling - Lay-in | 930 | SF | 6 | \$2,793 | |
| | Chalk Board | 8 | LF | 4 | \$734 | |
| | Doors - Side-lite | 10 | SF | 6 | \$167 | |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 930 | SF | 6 | \$1,982 | |
| | Lighting - Lay-in | 21 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1,040 | SF | 6 | \$3,049 | |
| | Wireless System | 1 | EA | 7 | \$0 | |
| lassrc | om #153 (Regular Classroom) | | | | | |
| | Casework | 50 | LF | 6 | \$1,263 | |
| | Ceiling - Lay-in | 930 | SF | 6 | \$2,793 | |
| | Chalk Board | 6 | LF | 4 | \$551 | |
| | Doors - Side-lite | 10 | SF | 6 | \$167 | |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 930 | SF | 6 | \$2,035 | |
| | Lighting - Lay-in | 21 | EA | 7 | \$0 | |
| | Marker Board | 8 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1,040 | SF | 6 | \$3,049 | |
| | Work Sink | 1 | EA | 6 | \$379 | |
| assrc | om #155 (Special Education) | | | | | |
| | Casework | 38 | LF | 6 | \$960 | |
| | Ceiling - Lay-in | 1,196 | SF | 6 | \$3,592 | |
| | Chalk Board | 36 | LF | 4 | \$3,305 | |
| | Doors - Transom Window | 20 | SF | 6 | \$339 | |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 1,196 | SF | 6 | \$2,617 | |
| | Lighting - Lay-in | 30 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1,200 | SF | 6 | \$3,518 | |
| | Work Sink | 1 | EA | 6 | \$379 | |
| assrc | om #159 (Laboratory/Shop) | | | | | |
| | Ceiling - Exposed | 3,170 | SF | 7 | \$0 | |
| | Chalk Board | 8 | LF | 4 | \$734 | |
| | Doors - Side-lite | 20 | SF | 6 | \$334 | |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 | |
| | Floor - Concrete | 3,050 | SF | 6 | \$1,614 | |
| | Lighting - Pendent/Surface | 16 | EA | 6 | \$1,982 | |
| | | | | | | |
| | Storage/ Closet | 380 | SF | 6 | \$2,755 | |

Building: Addition

| tegory: Classrooms | | • | | | • | • |
|----------------------------------|----------|----------|------|------|----------|----------------------------|
| oup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| ssroom #159 (Laboratory/Shop) | | | | | | |
| Work Sink | | 2 | EA | 6 | \$758 | 1 is backed up with water. |
| ssroom #166 (Regular Classroom) | | | | | | |
| Casework | | 26 | LF | 6 | \$657 | |
| Ceiling - Lay-in | | 920 | SF | 6 | \$2,763 | |
| Chalk Board | | 44 | LF | 4 | \$4,039 | |
| Doors - Side-lite | | 10 | SF | 6 | \$167 | |
| Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| Floor - Tile | | 920 | SF | 6 | \$2,013 | |
| Lighting - Lay-in | | 21 | EA | 6 | \$2,498 | |
| Walls - Concrete Block | | 1,060 | SF | 6 | \$3,107 | |
| issroom #167 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in | | 920 | SF | 6 | \$2,763 | |
| Chalk Board | | 44 | LF | 4 | \$4,039 | |
| Doors - Side-lite | | 10 | SF | 6 | \$167 | |
| Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| Floor - Tile | | 920 | SF | 6 | \$2,013 | |
| Lighting - Lay-in | | 21 | EA | 7 | \$0 | |
| Walls - Concrete Block | | 1,060 | SF | 6 | \$3,107 | |
| assrooms Subtotal: | | | | | \$90,066 | |

Classrooms Subtotal:

Building: Addition

| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | | | |
|------------------------------|---------------------------|----------|------|------|---------|----------|--|--|--|--|
| dministrative Suites/Offices | nistrative Suites/Offices | | | | | | | | | |
| Ceiling - Lay-in | 154 | 330 | SF | 6 | \$991 | | | | | |
| Doors - Wood Doors inclu hw | 154 | 2 | EA | 6 | \$602 | | | | | |
| Floor - Tile | 154 | 330 | SF | 6 | \$722 | | | | | |
| Lighting - Lay-in | 154 | 10 | EA | 6 | \$1,190 | | | | | |
| Power Distribution | 154 | 10 | EA | 7 | \$0 | | | | | |
| Storage/ Closet | 154 | 32 | SF | 6 | \$232 | | | | | |
| Walls - Concrete Block | 154 | 800 | SF | 6 | \$2,345 | | | | | |
| AC Unit | in 159 Wood Shop | 1 | EA | 7 | \$0 | | | | | |
| Ceiling - Lay-in | in 159 Wood Shop | 120 | SF | 6 | \$360 | | | | | |
| Doors - Wood Doors inclu hw | in 159 Wood Shop | 1 | EA | 6 | \$301 | | | | | |
| Floor - Tile | in 159 Wood Shop | 120 | SF | 5 | \$539 | | | | | |



Building: Addition

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|---------------------------------------|----------|------|------|---------|--|
| | strative Suites/Offices | | , | | | | |
| | Lighting - Lay-in | in 159 Wood Shop | 2 | EA | 6 | \$238 | |
| | Power Distribution | in 159 Wood Shop | 4 | EA | 7 | \$0 | |
| | Storage/ Closet | in 159 Wood Shop | 8 | SF | 6 | \$58 | |
| | Walls - Concrete Block | in 159 Wood Shop | 300 | SF | 6 | \$879 | |
| Green H | louse | | | | | | |
| | Finishes | Research Greenhouse (Room 1 + Room 2) | 3,420 | SF | 7 | \$0 | |
| | Glazing | Research Greenhouse (Room 1 + Room 2) | 3,860 | SF | 7 | \$0 | Roof glazing |
| | Glazing | Research Greenhouse (Room 1 + Room 2) | 2,540 | SF | 7 | \$0 | Wall glazing |
| | Mechanical | Research Greenhouse (Room 1 + Room 2) | 3,420 | SF | 7 | \$0 | |
| | Plumbing | Research Greenhouse (Room 1 + Room 2) | 3,420 | SF | 7 | \$0 | |
| Mechan | ical/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 22 | SF | 6 | \$158 | |
| | Storage Room | off Greenhouse | 300 | SF | 6 | \$2,149 | |
| Prep Ro | oom | | | | | | |
| | Ceiling - Plaster/Drywall | off Greenhouse | 600 | SF | 6 | \$2,076 | |
| | Doors - Steel Doors incl hw | off Greenhouse | 4 | EA | 6 | \$1,204 | these 4 doors exit into greenhouse. not sure if accounted for with exterior? |
| | Floor - Concrete | off Greenhouse | 600 | SF | 6 | \$317 | sealed |
| | Lighting - Pendent/Surface | off Greenhouse | 16 | EA | 6 | \$1,982 | |
| | Walls - Concrete Block | off Greenhouse | 866 | SF | 6 | \$2,539 | |
| Restroc | om | | | | | | |
| | Accessories | 1st Floor | 294 | SF | 5 | \$5,819 | |
| | Accessories | 1st Floor | 294 | SF | 6 | \$2,712 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 294 | SF | 6 | \$1,017 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 294 | SF | 6 | \$1,017 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 5 | \$1,174 | door to shower area |
| | Floor Drain | 1st Floor | 2 | EA | 6 | \$2,118 | |
| | Floor Drain | 1st Floor | 2 | EA | 6 | \$2,118 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 274 | SF | 6 | \$580 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 274 | SF | 6 | \$580 | |



Building: Addition

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|------|------|---------|---------------------------------|
| Restroc | m | | | | | | |
| | Hand Dryer | 1st Floor | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st Floor | 2 | EA | 5 | \$3,179 | replace faucets |
| | Lavatory | 1st Floor | 2 | EA | 5 | \$3,179 | need new faucets |
| | Lighting - Lay-in | 1st Floor | 2 | EA | 6 | \$238 | recessed compact fluorescents |
| | Lighting - Lay-in | 1st Floor | 1 | EA | 7 | \$0 | recessed linear cove 16 lf |
| | Lighting - Lay-in | 1st Floor | 1 | EA | 7 | \$0 | recessed linear cove 16 lf |
| | Lighting - Lay-in | 1st Floor | 2 | EA | 6 | \$238 | recessed compact fluorescents |
| | Lighting - Pendent/Surface | 1st Floor | 3 | EA | 6 | \$372 | |
| | Lighting - Pendent/Surface | 1st Floor | 3 | EA | 6 | \$372 | |
| | Partitions | 1st Floor | 1 | EA | 6 | \$297 | |
| | Partitions | 1st Floor | 2 | EA | 6 | \$594 | |
| | Showers | 1st Floor | 2 | EA | 5 | \$2,344 | Area currently used as storage. |
| | Showers | 1st Floor | 2 | EA | 6 | \$623 | |
| | Urinals | 1st Floor | 2 | EA | 6 | \$672 | |
| | Walls - Concrete Block | 1st Floor | 640 | SF | 6 | \$1,876 | |
| | Walls - Concrete Block | 1st Floor | 640 | SF | 6 | \$1,876 | |
| | Walls - Structural Glazed Tile | 1st Floor | 320 | SF | 6 | \$1,007 | |
| | Walls - Structural Glazed Tile | 1st Floor | 320 | SF | 6 | \$1,007 | |
| | Water Closet | 1st Floor | 1 | EA | 6 | \$336 | |
| | Water Closet | 1st Floor | 2 | EA | 6 | \$672 | |

Rooms (Other Than Classrooms) Subtotal:

\$56,033

Building: Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-----------|----------|------|------|----------|-----------------------------------|
| orrido | r | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,473 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,671 | SF | 6 | \$10,347 | Ceiling shows some water spotting |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Drinking Fountains - Single Water Cooler | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 3,144 | SF | 6 | \$1,708 | Floor has some cracks & spalling |
| | Lighting - Pendent/Surface | 1st Floor | 79 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 1st Floor | 138 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 3,207 | SF | 7 | \$0 | |
| | Walls - Masonry | 1st Floor | 2,712 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 414 | SF | 7 | \$0 | |



Building: Addition

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|------------------------|----------|------|------|---------|---|
| Corrido | or and the second s | | | | | | |
| | Ceiling - Plaster/Drywall | to Research Greenhouse | 280 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | to Research Greenhouse | 2 | EA | 6 | \$602 | |
| | Doors - Steel Doors incl hw | to Research Greenhouse | 2 | EA | 6 | \$602 | |
| | Doors - Wood Doors include hw | to Research Greenhouse | 2 | EA | 6 | \$602 | |
| | Floor - Concrete | to Research Greenhouse | 280 | SF | 6 | \$148 | |
| | Lighting - Pendent/Surface | to Research Greenhouse | 5 | EA | 6 | \$619 | |
| | Walls - Concrete Block | to Research Greenhouse | 600 | SF | 6 | \$1,759 | |
| | Ceiling - Plaster/Drywall | Vestibules | 10 | SF | 4 | \$241 | Water damage/moisture leak at soffit above door |
| | Ceiling - Plaster/Drywall | Vestibules | 69 | SF | 6 | \$427 | |
| | Doors - Side-lite | Vestibules | 15 | EA | 7 | \$0 | |
| | Doors - Store Front | Vestibules | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | Vestibules | 25 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | Vestibules | 74 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Vestibules | 2 | EA | 7 | \$0 | Lighting is recessed incandescent |
| | Walls - Masonry | Vestibules | 144 | SF | 7 | \$0 | |

Building Interior Subtotal:

Total Building Cost

\$1,001,443

\$17,357

Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--------------------------------------|----------------------|----------|------|------|---------|--------------------------------------|
| Entrance |) | | | | | | |
| | Entrance Control - Audio | 1 | 1 | EA | 6 | \$497 | power operator in interior vestibule |
| | Entrance Control - Audio | 7 | 1 | EA | 6 | \$497 | |
| | Exterior Doors - Exterior Steel Door | 10A- Mechanical Room | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | 10B | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | 10C | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | 11 | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 11A- Loading Dock | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | 11B | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | 12 | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 9A | 1 | EA | 5 | \$1,341 | corrosion at base |
| | Exterior Doors - Exterior Steel Door | 9B | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 9C- Sprinkler Room | 1 | EA | 7 | \$0 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|-------------------|----------|------|------|---------|----------|
| Entranc | e | | | | | | |
| | Exterior Doors - Exterior Steel Door | Garage Door 1 | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | Garage Door 2 | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | Garage Door 3 | 11 | EA | 6 | \$5,286 | |
| | Exterior Doors - Side lite | 10 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Side lite | 10D | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Side lite | 10E | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Side lite | 13 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Side lite | 13A | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Side lite | 14 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Side lite | 15 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Side lite | 8 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Side lite | 9 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | 1 | 6 | EA | 6 | \$3,276 | |
| | Exterior Doors - Store Front | 10 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | 10D | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | 10E | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | 13 | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | 13A | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | 14 | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | 15 | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | 7 | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | 8 | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | 9 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | Courtyard A | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Courtyard B | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Courtyard C | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Courtyard D | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Courtyard D | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Library Courtyard | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Transom Lite | 1 | 6 | EA | 6 | \$1,880 | |
| | Exterior Doors - Transom Lite | 10 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 10D | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 10E | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 13 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 13A | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 14 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 15 | 2 | EA | 6 | \$627 | |
| | | | | | | | |



Building: Linked Addition

| Entranc | e e | | Quantity | | | | |
|----------|---|-------------------|----------|----|---|----------|--|
| | | | | | | | |
| | Exterior Doors - Transom Lite | 7 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 8 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 9 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | Courtyard A | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | Courtyard B | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | Courtyard C | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | Library Courtyard | 2 | EA | 6 | \$627 | |
| | Exterior Stairs - Concrete | 10C | 6 | LF | 6 | \$491 | |
| | Exterior Stairs - Concrete | 11A- Loading Dock | 12 | LF | 6 | \$981 | |
| | Ramps - Concrete | 10B | 5 | LF | 7 | \$0 | |
| Founda | tion | | | | | | |
| | Foundation - Concrete | Entire Building | 2,916 | LF | 7 | \$0 | |
| | Superstructure - Concrete | Entire Building | 182,797 | SF | 7 | \$0 | |
| Lighting | 3 | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 16 | EA | 7 | \$0 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 4 | EA | 6 | \$1,155 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 3 | EA | 5 | \$1,282 | |
| Roof Sy | vstem | | | | | | |
| | Chimney - Metal Flue | G | 20 | LF | 6 | \$3,163 | |
| | Coping - Metal | E | 358 | LF | 7 | \$0 | |
| | Coping - Metal | F | 721 | LF | 6 | \$23,157 | |
| | Coping - Metal | G | 1,043 | LF | 6 | \$33,499 | |
| | Coping - Metal | 1 | 228 | LF | 6 | \$7,323 | |
| | Downspouts - Exterior Downspouts | E | 44 | LF | 6 | \$1,462 | |
| | Downspouts - Exterior Downspouts | Н | 40 | LF | 6 | \$1,329 | |
| | Downspouts - Exterior Downspouts | J | 28 | LF | 6 | \$931 | |
| | Downspouts - Exterior Downspouts | К | 28 | LF | 6 | \$931 | |
| | Downspouts - Exterior Downspouts | L | 132 | LF | 6 | \$4,387 | |
| | Downspouts - Interior Downspouts | E | 58 | LF | 6 | \$1,928 | |
| | Downspouts - Interior Downspouts | F | 58 | LF | 6 | \$1,928 | |
| | Downspouts - Interior Downspouts | G | 292 | LF | 6 | \$9,704 | |
| | Parapet - Parapet < 16" Height | E | 358 | LF | 7 | \$0 | |
| | Parapet - Parapet < 16" Height | F | 721 | LF | 7 | \$0 | |
| | Parapet - Parapet < 16" Height | G | 1,043 | LF | 6 | \$22,223 | |
| | Parapet - Parapet < 16" Height | 1 | 228 | LF | 6 | \$4,858 | |
| | Roof Structure - Concrete | D | 1,494 | SF | 7 | \$0 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|--------------------------------|----------|------|------|-----------|---|
| Roof Sy | ystem | | | | | | |
| | Roof Structure - Concrete | E | 13,705 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | F | 25,272 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | G | 32,356 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Н | 4,228 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | I | 10,663 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | J | 10,241 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | К | 10,241 | SF | 7 | \$0 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | L | 4,200 | SF | 7 | \$0 | |
| | Roof - EPDM/ Synthetic Rubber | E | 100 | SF | 4 | \$4,803 | leaking |
| | Roof - EPDM/ Synthetic Rubber | E | 13,605 | SF | 5 | \$263,228 | EPDM cracking at seams |
| | Roof - EPDM/ Synthetic Rubber | F | 25,272 | SF | 5 | \$488,960 | |
| | Roof - EPDM/ Synthetic Rubber | G | 150 | SF | 4 | \$7,205 | leakage |
| | Roof - EPDM/ Synthetic Rubber | G | 32,206 | SF | 5 | \$623,118 | |
| | Roof - EPDM/ Synthetic Rubber | I | 100 | SF | 4 | \$4,803 | leakage |
| | Roof - EPDM/ Synthetic Rubber | I | 10,563 | SF | 5 | \$204,372 | |
| | Roof - Metal | D | 1,494 | SF | 6 | \$20,018 | |
| | Roof - Metal | Н | 4,228 | SF | 6 | \$56,651 | |
| | Roof - Metal | J | 10,241 | SF | 7 | \$0 | |
| | Roof - Metal | К | 10,241 | SF | 7 | \$0 | |
| | Roof - Metal | L | 4,200 | SF | 6 | \$56,276 | |
| Walls | | | | | | | |
| | Canopy - Metal | Entire Building / West Façade | 2,724 | SF | 7 | \$0 | |
| | Exterior Walls - Brick | Entire Building | 37,226 | SF | 6 | \$250,196 | |
| | Exterior Walls - Brick | Entire Building | 25 | SF | 5 | \$595 | |
| | Exterior Walls - Brick | Entire Building | 25 | SF | 5 | \$595 | efflorescence |
| | Exterior Walls - Brick | Entire Building / Courtyard | 300 | SF | 5 | \$7,143 | efflorescence |
| | Exterior Walls - Brick | Entire Building / North Façade | 300 | SF | 5 | \$7,143 | ivy |
| | Exterior Walls - Stucco | Entire Building | 7,040 | SF | 6 | \$33,725 | |
| | Exterior Walls - Stucco | Entire Building / North Façade | 40 | SF | 3 | \$1,927 | stone deteriorated, bird nest in wall, cracks |
| Window | vs | | | | | | |
| | Clerestory - Glass Double-Pane | Entire Building | 1,448 | SF | 7 | \$0 | |
| | Curtain wall - Louver | Entire Building | 486 | SF | 6 | \$5,449 | |
| | Lintels - Steel | Entire Building | 839 | LF | 6 | \$24,355 | |
| | Skylite - Glass Double-Pane | Entire Building / North | 10 | SF | 3 | \$2,698 | cracked |
| | Skylite - Glass Double-Pane | Entire Building / West | 1,320 | SF | 7 | \$0 | |
| | Storefront Windows | Entire Building / North Façade | 470 | SF | 7 | \$0 | |
| | | - | | | | | |



Building: Linked Addition

| Building Exterior Subtotal: | | \$2 | 2,228,291 | | |
|-----------------------------|-----------------|--------------|-----------|------------------------|--|
| Windows - Decorative | Entire Building | 4,163 SF | 7 | \$0 fixed, double pane | |
| Windows | | | | | |
| Group Item - Type | Location | Quantity Uni | t Rank | Cost Comments | |
| Category: Building Exterior | | | | | |

Building Exterior Subtotal:

Building: Linked Addition

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------------|----------|------|------|-----------|-------------------------------|
| Emerge | ency System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 3 | EA | 7 | \$0 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 30,216 | SF | 7 | \$0 | |
| | Emergency A/C Power - Gym | Entire Building | 13,450 | SF | 7 | \$0 | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 5,640 | SF | 7 | \$0 | |
| | Emergency A/C Power - Multipurpose Room | Entire Building | 4,430 | SF | 7 | \$0 | |
| | Emergency A/C Power - Pool | Entire Building | 4,017 | SF | 7 | \$0 | |
| | Emergency A/C Power - Students Toilets | Entire Building | 2,261 | SF | 7 | \$0 | |
| | Emergency Battery Packs - Corridors and Stairs | Basement / Entire Building | 3 | EA | 6 | \$608 | Batteries need to be replaced |
| | Emergency Generator- Outdoor- Diesel - 151 - 200 KW | Southwest Site / South Courtyard | 1 | EA | 6 | \$12,534 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 58 | EA | 7 | \$0 | |
| | Exit Signs - Gym | Entire Building | 11 | EA | 7 | \$0 | |
| | Exit Signs - Lunchroom | Entire Building | 5 | EA | 7 | \$0 | |
| | Exit Signs - Pool | Entire Building | 3 | EA | 7 | \$0 | |
| | Security System - CCTV | Entire Building | 223,325 | SF | 6 | \$67,064 | |
| | Security System - Intrusion Detection | Entire Building | 223,325 | SF | 6 | \$57,484 | |
| Main Se | ervice | | | | | | |
| | Main Electrical Service - 2000 A 120/208/3PH | Electrical Room | 2 | EA | 7 | \$0 | |
| | Main Electrical Service - 2001 to 3000 A 277/480/3PH | Electrical Room / 1st Floor | 1 | EA | 7 | \$0 | |
| | PA System | Entire Building | 223,325 | SF | 6 | \$73,452 | |
| Power I | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 28 | EA | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Mechanical Room | 3 | EA | 7 | \$0 | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 7 | EA | 7 | \$0 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Electrical Room | 1 | EA | 7 | \$0 | |
| Electr | ical System Subtotal: | | | | | \$211,142 | |



Category: Safty System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------|-----------------------------------|----------|------|------|----------|----------|
| Fire Alarm | | | | | | |
| Fire Alarm Panel | Entire Building / Electrical Room | 1 | EA | 7 | \$0 | |
| Fire Alarm Strobe Lights | Entire Building | 182,797 | SF | 7 | \$0 | |
| Fire Alarm_System | Entire Building | 182,797 | SF | 7 | \$0 | |
| Fire Pump Controller | Entire Building | 1 | EA | 7 | \$0 | |
| Pump Room Assembly | | | | | | |
| Fire Pump - 25-50 hp | Sprinkler Room | 1 | EA | 5 | \$8,163 | |
| Sprinkler System | | | | | | |
| Dry Sprinkler System | Entire Building | 182,797 | SF | 6 | \$47,052 | |
| Sprinkler Heads | Entire Building | 182,797 | SF | 6 | \$0 | |
| Sprinkler Piping | Entire Building | 182,797 | SF | 6 | \$33,982 | |
| Safty System Subtotal: | | | | | \$89,197 | |

Safty System Subtotal:

Building: Linked Addition

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--|-----------------------------|----------|------|------|-----------|-------------------------------|
| Air Con | ditioning | | | | | | |
| | Chiller-Air Cooled-Screw Type-Ground Mounted - 201 - 300 tons | Site West / South West | 2 | EA | 5 | \$140,540 | |
| | Condensing Unit- Roof Mounted - 21-30 tons | Roof | 1 | EA | 5 | \$12,315 | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 7 | \$0 | |
| Air Hand | dling Systems | | | | | | |
| | Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - 20001-30000 cfm | Boiler Room | 1 | EA | 6 | \$3,350 | |
| | Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - 6000-10000 cfm | Basement | 2 | EA | 6 | \$6,700 | |
| | Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - 6000-10000 cfm | Boiler Room | 1 | EA | 6 | \$3,350 | |
| | Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - 6000-10000 cfm | Boiler Room | 1 | EA | 6 | \$3,350 | |
| | Air Handling Unit Package Multi Zone- Indoor- Daul Temperature Coils - Less than 6000 cfm | Plenum | 2 | EA | 6 | \$6,700 | |
| | Air Handling Unit- Package Multi Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm | Southwest corner | 1 | EA | 5 | \$99,199 | Damaged supply and insulation |
| | Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils Less than 6000 cfm | Ceiling-mounted in art room | 1 | EA | 7 | \$0 | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm | Southwest corner | 1 | EA | 6 | \$3,350 | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 8001-12000 cfm | Basement | 1 | EA | 6 | \$3,350 | |



Building: Linked Addition

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--|-------------------------------------|----------|------|------|-----------|---|
| Air Han | dling Systems | | | | | | |
| | Air Intake | Boiler Room / South Façade | 1 | EA | 7 | \$0 | |
| | Air Intake | Boiler Room / South Façade | 1 | EA | 7 | \$0 | |
| | Air Intake | Boiler Room / South Façade | 1 | EA | 7 | \$0 | |
| | Air Intake | Ceiling-mounted in art room / Roofs | 1 | EA | 7 | \$0 | |
| | Air Intake | Plenum / Roofs | 2 | EA | 7 | \$0 | |
| | Air Intake | Southwest corner / South Façade | 1 | EA | 7 | \$0 | |
| | Air Intake | Southwest corner / South Façade | 1 | EA | 7 | \$0 | |
| | Auxiliaries - 20001-30000 cfm | Boiler Room | 1 | EA | 6 | \$0 | |
| | Fan Power Box - Fan Power Box with Hot Water Coil | Entire Building | 55 | EA | 5 | \$86,656 | |
| | Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM | Mechanical Room | 4 | EA | 6 | \$7,429 | |
| | Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM | Mechanical Room | 3 | EA | 6 | \$7,298 | |
| | Make Up Air Unit- Indoor Mounted- Hot Water Coils - Less than 6000 cfm | Plenum | 2 | EA | 6 | \$6,700 | Located in out building plenum (inaccessible) |
| | Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm | Roof | 1 | EA | 5 | \$22,527 | |
| Boiler S | ystems | | | | | | |
| | Boiler Auxiliary- Non Condensing Hot Water - Greater than 4000 MBH | Boiler Room | 2 | EA | 6 | \$4,093 | |
| | Chemical Pot Feeder | Boiler Room | 3 | EA | 6 | \$2,175 | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | \$818 | |
| | Dual Temperature Pump | Boiler Room | 2 | EA | 6 | \$748 | |
| | Glycol Feed System | Boiler Room | 1 | EA | 6 | \$539 | |
| | Hot Water Pump | Boiler Room | 2 | EA | 6 | \$748 | |
| | Hot Water Pump | Boiler Room | 2 | EA | 6 | \$748 | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - Greater than 4000 MBH | Boiler Room | 2 | EA | 6 | \$1,996 | |
| Heating | Devices | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 12 | EA | 7 | \$0 | |
| | Fin Tube - Hot Water | Entire Building | 64 | LF | 7 | \$0 | |
| | Unit Heater - Electric | Out Building | 1 | EA | 7 | \$0 | |
| | Unit Heater - Gas | Out Buildings | 13 | EA | 6 | \$3,611 | |
| | Unit Heater - Hot Water | Entire Building | 4 | EA | 7 | \$0 | |
| | Unit Heater - Hot Water | Entire Building / Boiler Room | 3 | EA | 7 | \$0 | |
| Mechan | ical Plumbing | | | | | | |
| | Chilled Water Pump - 10 - 20 HP | Boiler Room | 2 | EA | 7 | \$0 | |
| | Hydronic Supply and Return - Steel | Entire Building | 1,500 | LF | 6 | \$115,165 | |



Building: Linked Addition

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--|-------------------------|----------|------|------|-----------|-------------------|
| Temper | ature Control | | | | | | |
| | DDC System | Entire Building | 182,797 | SF | 5 | \$300,610 | |
| | Thermostats - DDC | Entire Building | 2 | EA | 4 | \$1,638 | |
| | Thermostats - DDC | Entire Building | 102 | EA | 7 | \$0 | |
| Ventilat | ion | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | \$1,185 | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 2 | EA | 6 | \$1,185 | |
| | Exhaust Fans- Indoor - Greater than 8000 CFM | Entire Building | 1 | EA | 6 | \$592 | Serves Pool |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building / South | 1 | EA | 7 | \$0 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building / Roof | 12 | EA | 6 | \$7,109 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building / Roof | 2 | EA | 7 | \$0 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building / Roof | 1 | EA | 4 | \$4,245 | Vibrating heavily |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building / Roof | 4 | EA | 6 | \$1,185 | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building / Roof | 2 | EA | 7 | \$0 | |
| | Lab Exhaust Hood | Entire Building | 2 | EA | 7 | \$0 | |
| | Type I Exhaust Hood- Kitchen | Entire Building | 3 | EA | 7 | \$0 | |

Mechanical System Subtotal:

\$861,202

Building: Linked Addition

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------|----------|------|------|----------|---|
| Hot Wat | ter | | | | | | |
| | Gas Heater - Greater than 600000 BTU/HR | Mezzanine / Mechanical Room | 2 | EA | 6 | \$620 | |
| | Gas Heater - Greater than 600000 BTU/HR | Mezzanine / Mechanical Room | 1 | EA | 3 | \$43,134 | One of the three hot water heaters has a leak that cannot be repaired |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 182,797 | SF | 6 | \$36,596 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 182,797 | SF | 6 | \$44,438 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 182,797 | SF | 6 | \$33,982 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 182,797 | SF | 6 | \$28,754 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 182,797 | SF | 6 | \$33,982 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 182,797 | SF | 6 | \$26,140 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 182,797 | SF | 6 | \$26,140 | |
| | Sanitary Piping | Entire Building | 182,797 | SF | 7 | \$0 | |
| | Storm Piping | Entire Building | 182,797 | SF | 7 | \$0 | |
| | Vent Piping | Entire Building | 182,797 | SF | 7 | \$0 | |



Building: Linked Addition

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost Comme | nts | |
|---------|---------------------------------------|--------------------------------|----------|------|------|------------|-----|--|
| Pool Sy | vstems | | | | | | | |
| | Pool Drain Piping | Pool equipment room | 50 | LF | 7 | \$0 | | |
| | Pool Filtration System including Pump | Pool equipment room | 1 | EA | 7 | \$0 | | |
| | Pool Hot Water Heater - Gas Fired | Pool equipment room / Basement | 1 | EA | 6 | \$310 | | |
| | Pool Supply and Return Piping | Pool equipment room | 150 | LF | 7 | \$0 | | |
| Pumps | | | | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | Entire Building / Boiler Room | 2 | EA | 7 | \$0 | | |
| | Pumps - Sump-Simplex | Entire Building | 3 | EA | 6 | \$2,235 | | |
| | in a Oracle or Oral (a fal | | | | | 070 004 | | |

Plumbing System Subtotal:

\$276,331

Building: Linked Addition

| up | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|-----------------------------|-----------|----------|------|------|---------|----------|
| sroc | om #120 (Regular Classroom) | | | | | | |
| | Casework | | 17 | LF | 6 | \$429 | |
| | Ceiling - Lay-in | | 900 | SF | 7 | \$0 | |
| | Doors - Side-lite | | 6 | SF | 6 | \$100 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 900 | SF | 6 | \$1,969 | |
| | Lighting - Lay-in | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 1,070 | SF | 6 | \$3,137 | |
| | Wireless System | | 1 | EA | 7 | \$0 | |
| sroc | om #121 (Computer Lab) | | | | | | |
| | Casework | | 17 | LF | 6 | \$429 | |
| | Ceiling - Lay-in | | 900 | SF | 7 | \$0 | |
| | Doors - Side-lite | | 6 | SF | 6 | \$100 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 900 | SF | 6 | \$1,969 | |
| | Lighting - Lay-in | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 1,166 | SF | 6 | \$3,418 | |
| | Wireless System | | 1 | EA | 7 | \$0 | |
| sroc | om #122 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 16 | LF | 7 | \$0 | |

Building: Linked Addition

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|-----------------------------|-----------|----------|------|------|---------|--------------------|
| assro | om #122 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 744 | SF | 7 | \$0 | |
| | Chalk Board | 1st Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 5 | EA | 7 | \$0 | |
| | Floor - Tile | 1st Floor | 744 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 968 | SF | 7 | \$0 | |
| assro | om #123 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 1st Floor | 744 | SF | 7 | \$0 | |
| | Chalk Board | 1st Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 1st Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 1st Floor | 744 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 968 | SF | 7 | \$0 | |
| assro | om #124 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 1st Floor | 744 | SF | 7 | \$0 | |
| | Chalk Board | 1st Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 1st Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 1st Floor | 744 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 968 | SF | 7 | \$0 | |
| assro | om #125 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 1st Floor | 744 | SF | 6 | \$2,234 | |
| | Chalk Board | 1st Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 1st Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 1st Floor | 744 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 968 | SF | 7 | \$0 | |

Building: Linked Addition

| | Item - Type | Location | Quantity | Unit | Dank | Cast | Comments |
|---------|------------------------------|----------|----------|------|-------|----------------|--------------------|
| - | | Location | Quantity | Unit | Ralik | Cost | Comments |
| Classro | bom #126 (Laboratory/Shop) | | 101 | | _ | 004 447 | |
| | Casework | | 101 | LF | 5 | \$21,117 | |
| | Ceiling - Lay-in | | 1,329 | SF | 6 | \$3,991 | Objective Material |
| | Chalk Board | | 5 | LF | 4 | | Obsolete Material. |
| | Doors - Side-lite | | 7 | SF | 6 | \$117 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile | | 1,329 | SF | 6 | \$2,908 | |
| | Lighting - Lay-in | | 15 | EA | 6 | \$1,785 | |
| | Student Lockers - One Tier | | 4 | EA | 6 | \$371 | |
| | Walls - Concrete Block | | 1,330 | SF | 6 | \$3,899 | |
| | Work Sink | | 8 | EA | 6 | \$3,032 | |
| Classro | oom #127 (Laboratory/Shop) | | | | | | |
| | Casework | | 44 | LF | 6 | \$1,111 | |
| | Ceiling - Lay-in | | 758 | SF | 5 | \$4,509 | |
| | Chalk Board | | 5 | LF | 4 | \$459 | Obsolete Material. |
| | Doors - Side-lite | | 7 | SF | 6 | \$117 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 758 | SF | 6 | \$1,658 | |
| | Lighting - Lay-in | | 8 | EA | 6 | \$952 | |
| | Walls - Concrete Block | | 998 | SF | 6 | \$2,926 | |
| | Work Sink | | 3 | EA | 6 | \$1,137 | |
| Classro | oom #128 (Laboratory/Shop) | | | | | | |
| | Casework | | 69 | LF | 6 | \$1,743 | |
| | Ceiling - Lay-in | | 1,353 | SF | 6 | \$4,063 | |
| | Chalk Board | | 12 | LF | 4 | \$1,102 | Obsolete Material. |
| | Doors - Side-lite | | 7 | SF | 6 | \$117 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile | | 1,353 | SF | 6 | \$2,960 | |
| | Lighting - Lay-in | | 15 | EA | 6 | \$1,785 | |
| | Walls - Concrete Block | | 1,330 | SF | 6 | \$3,899 | |
| | Work Sink | | 3 | EA | 6 | \$1,137 | |
| Classro | oom #134 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | | 716 | SF | 6 | \$2,150 | |
| | Doors - Side-lite | | 14 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 7 | \$0 | |
| | Floor - Carpet | | 716 | SF | 6 | \$1,526 | |
| | Lighting - Lay-in | | 20 | EA | 7 | \$0 | |
| | | | | | | | |

| oun | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|--|-----------|----------|------|-------|------------|--|
| - | nom #134 (Regular Classroom) | Location | Quantity | Unit | Nalik | COSI | Comments |
| a3310 | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 950 | SF | 7 | \$0 \$0 | |
| | | | 300 | 01 | ' | ψυ | |
| assro | om #179 (Art Room) | | | | | | |
| | Casework | 1st Floor | 35 | LF | 6 | \$884 | |
| | Ceiling - Exposed | 1st Floor | 766 | SF | 5 | \$2,103 | water damaged, due to leaking skylight |
| | Doors - Side-lite | 1st Floor | 63 | SF | 6 | \$1,053 | |
| | Doors - Steel Doors incl hw | 1st Floor | 3 | EA | 6 | \$903 | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 1,532 | SF | 6 | \$811 | |
| | Kiln | 1st Floor | 1 | EA | 6 | \$2,321 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 6 | \$2,230 | |
| | Marker Board | 1st Floor | 16 | LF | 6 | \$343 | |
| | Walls - Concrete Block | 1st Floor | 2,030 | SF | 5 | \$20,843 | Water damage. |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| assro | oom #180 (Laboratory/Shop) | | | | | | |
| | Casework | 1st Floor | 47 | LF | 6 | \$1,187 | |
| | Ceiling - Exposed | 1st Floor | 1,111 | SF | 6 | \$1,652 | Skylights/exposed metal deck and structure |
| | Doors - Side-lite | 1st Floor | 63 | SF | 6 | \$1,053 | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 6 | \$102 | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 2,222 | SF | 6 | \$1,176 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | \$1,858 | |
| | Walls - Concrete Block | 1st Floor | 2,943 | SF | 5 | \$30,217 | Water damage. |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| assro | oom #180 Work Room (Laboratory/Shop) | | | | | | |
| | Ceiling - Exposed | 1st Floor | 378 | SF | 6 | \$562 | Precast concrete panel. |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Concrete | 1st Floor | 378 | SF | 6 | \$200 | Sealed concrete. |
| | Lighting - Pendent/Surface | 1st Floor | 4 | EA | 6 | \$496 | |
| | Walls - Concrete Block | 1st Floor | 582 | SF | 6 | \$1,706 | |
| assro | om #181 Farm Stand (Other Instructional Use) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 899 | SF | 6 | \$2,700 | |
| | Doors - Side-lite | 1st Floor | 30 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Store Front | 1st Floor | 2 | EA | 6 | \$2,416 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | \$0 | |

| - | ory: Classrooms | 1 | • | | D 1 | • | 0 |
|-----|---|-----------|----------|------|------------|----------|-------------------------------------|
| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| sro | bom #181 Farm Stand (Other Instructional Use) | Act Floor | 000 | 05 | 0 | ¢ 470 | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 899 | SF | 6 | \$476 | |
| | Lighting - Lay-in | 1st Floor | 15 | EA | 6 | \$1,785 | |
| | Walls - Concrete Block | 1st Floor | 392 | SF | 6 | \$1,149 | |
| sro | om #183 Crop Sort (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 33 | LF | 6 | \$833 | |
| | Ceiling - Lay-in | 1st Floor | 936 | SF | 6 | \$2,811 | |
| | Chalk Board | 1st Floor | 27 | LF | 4 | \$2,479 | Obsolete Material. |
| | Doors - Side-lite | 1st Floor | 11 | SF | 6 | \$184 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 936 | SF | 6 | \$2,048 | |
| | Lighting - Lay-in | 1st Floor | 14 | EA | 6 | \$1,666 | |
| | Walls - Concrete Block | 1st Floor | 1,096 | SF | 7 | \$0 | |
| sro | om #184 Show/Exerc (Regular Classroom) | | | | | | |
| | Casework | | 30 | LF | 6 | \$758 | |
| | Ceiling - Lay-in | | 936 | SF | 6 | \$2,811 | |
| | Chalk Board | | 16 | LF | 4 | \$1,469 | Obsolete Material. |
| | Doors - Steel Doors incl hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 936 | SF | 6 | \$2,048 | |
| | Lighting - Lay-in | | 15 | EA | 6 | \$1,785 | |
| | Marker Board | | 16 | LF | 6 | \$343 | |
| | Walls - Concrete Block | | 1,085 | SF | 6 | \$3,181 | |
| sro | om #186 Fish Hatch (Laboratory/Shop) | | | | | | |
| | Casework | 1st Floor | 47 | LF | 6 | \$1,187 | |
| | Ceiling - Lay-in | 1st Floor | 900 | SF | 6 | \$2,703 | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 900 | SF | 4 | \$25,302 | Painted concrete. Paint is flaking. |
| | Lighting - Lay-in | 1st Floor | 15 | EA | 6 | \$1,785 | - |
| | Walls - Concrete Block | 1st Floor | 1,111 | SF | 6 | \$3,257 | |
| | Work Sink | 1st Floor | 2 | EA | 6 | \$758 | |
| sro | om #201 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 744 | SF | 6 | \$2,234 | |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |

| Catego | ory: Classrooms | | | | | | |
|---------|-----------------------------|-----------|----------|------|------|---------|---------------------------------------|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | om #201 (Regular Classroom) | | | | | | |
| | Floor - Tile | 2nd Floor | 744 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 968 | SF | 7 | \$0 | |
| Classro | om #202 (Regular Classroom) | | | | | | |
| | Casework | | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | | 744 | SF | 6 | \$2,234 | |
| | Chalk Board | | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| | Floor - Tile | | 744 | SF | 7 | \$0 | |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | | 968 | SF | 5 | \$9,939 | Crack over window. Leaking in corner. |
| Classro | om #203 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 744 | SF | 6 | \$2,234 | |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 744 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 968 | SF | 6 | \$2,838 | Crack in CMU. Leakage in corner. |
| Classro | om #204 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 744 | SF | 7 | \$0 | |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 744 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 968 | SF | 7 | \$0 | |
| Classro | om #205 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 802 | SF | 5 | \$4,771 | Water damage. |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 6 | \$84 | |
| | | | | | | | |

3857 W 111th St Chicago, IL 60655

| | ing. Einkea Addition | | | | | | |
|---------|--------------------------------|-----------|----------|------|------|---------|---------------------|
| Categ | jory: Classrooms | | | | | | |
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | oom #205 (Regular Classroom) | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 802 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 988 | SF | 6 | \$2,896 | |
| Classro | oom #206 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 734 | SF | 6 | \$2,204 | |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 734 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 11 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 988 | SF | 7 | \$0 | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | \$0 | |
| Classro | oom #207 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 734 | SF | 7 | \$0 | |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 734 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 11 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 988 | SF | 7 | \$0 | |
| | Work Sink | 2nd Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #208 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 802 | SF | 5 | \$4,771 | Water damage spots. |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 802 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 988 | SF | 7 | \$0 | |
| Classro | oom #209 (Science Lab Level 1) | | | | | | |
| | Casework | 2nd Floor | 70 | LF | 7 | \$0 | |
| | | | | | | | |

Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|------|------|----------|--------------------------|
| | bom #209 (Science Lab Level 1) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,030 | SF | 7 | \$0 | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | \$1,102 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 4 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 1,030 | SF | 7 | \$0 | |
| | Gas Line | 2nd Floor | 17 | EA | 6 | \$8,655 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 448 | SF | 6 | \$3,248 | |
| | Walls - Concrete Block | 2nd Floor | 1,135 | SF | 5 | \$11,653 | Crack near storage room. |
| | Work Sink | 2nd Floor | 12 | EA | 5 | \$18,093 | |
| Classro | oom #210 (Science Lab Level 2) | | | | | | |
| | Casework | 2nd Floor | 70 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 1,030 | SF | 7 | \$0 | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | \$1,102 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 6 | \$84 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 4 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 1,030 | SF | 7 | \$0 | |
| | Gas Line | 2nd Floor | 17 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 448 | SF | 6 | \$3,248 | |
| | Walls - Concrete Block | 2nd Floor | 1,135 | SF | 6 | \$3,327 | |
| | Work Sink | 2nd Floor | 10 | EA | 6 | \$3,790 | |
| Classro | oom #211 (Science Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 862 | SF | 7 | \$0 | |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | \$2,938 | Obsolete Material. |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 862 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 943 | SF | 7 | \$0 | |
| | Work Sink | 2nd Floor | 2 | EA | 6 | \$758 | |
| Classro | oom #214 (Science Classroom) | | | | | | |
| | Casework | 2nd Floor | 18 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 1,080 | SF | 6 | \$3,243 | Water stains. |
| | Chalk Board | 2nd Floor | 24 | LF | 4 | \$2,203 | Obsolete Material. |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 7 | \$0 | |

| Categ | ory: Classrooms | | | | | | |
|---------|--|-----------|----------|------|------|----------|--|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | oom #214 (Science Classroom) | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 1,080 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 19 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 1,215 | SF | 6 | \$3,562 | |
| Classro | oom #215 (Science Classroom) | | | | | | |
| | Casework | 2nd Floor | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | 2nd Floor | 837 | SF | 7 | \$0 | |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | \$2,938 | |
| | Doors - Side-lite | 2nd Floor | 5 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 837 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 1,028 | SF | 7 | \$0 | |
| Classro | oom #Crop Sorting Rm (Special Program) | | | | | | |
| | Casework | 1st Floor | 21 | LF | 6 | \$530 | |
| | Ceiling - Exposed | 1st Floor | 4,619 | SF | 6 | \$6,869 | |
| | Ceiling - Lay-in | 1st Floor | 1,212 | SF | 6 | \$3,640 | |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 6 | \$1,204 | Overhead doors. |
| | Doors - Steel Doors incl hw | 1st Floor | 14 | EA | 6 | \$4,214 | |
| | Doors - Store Front | 1st Floor | 2 | EA | 6 | \$2,416 | |
| | Floor - Concrete | 1st Floor | 5,831 | SF | 6 | \$3,085 | |
| | Lighting - Lay-in | 1st Floor | 6 | EA | 6 | \$714 | |
| | Lighting - Pendent/Surface | 1st Floor | 32 | EA | 6 | \$3,965 | |
| | Storage/ Closet | 1st Floor | 245 | SF | 6 | \$1,776 | |
| | Walls - Concrete Block | 1st Floor | 9,048 | SF | 6 | \$26,524 | |
| | Work Sink | 1st Floor | 3 | EA | 6 | \$1,137 | |
| Classro | oom #Locker Rm (Fitness Room) | | | | | | |
| | Casework | | 40 | LF | 5 | \$8,363 | Missing doors and doors need adjustment, |
| | Ceiling - Lay-in | | 700 | SF | 6 | \$2,102 | |
| | Chalk Board | | 10 | LF | 4 | \$918 | |
| | Doors - Steel Doors incl hw | | 1 | EA | 7 | \$0 | |
| | Floor - Tile | | 700 | SF | 6 | \$1,532 | |
| | Lighting - Lay-in | | 13 | EA | 6 | \$1,547 | |
| | Marker Board | | 6 | LF | 6 | \$129 | |
| | Walls - Concrete Block | | 860 | SF | 6 | \$2,521 | |
| | | | | | | | |

Building: Linked Addition

Category: Classrooms

| Group Item - Type | | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------|--------------------------|-----------|----------|------|------|----------|-----------------|
| Classroom #Show & Ex | ercise (Laboratory/Shop) | | | | | | |
| AC Units | | 1st Floor | 4 | EA | 6 | \$1,982 | |
| Ceiling - Expos | ed | 1st Floor | 5,831 | SF | 6 | \$8,672 | |
| Doors - Steel D | pors incl hw | 1st Floor | 6 | EA | 6 | \$1,806 | Overhead doors. |
| Floor - Epoxy/ F | ainted | 1st Floor | 5,831 | SF | 6 | \$3,085 | |
| Lighting - Pend | ent/Surface | 1st Floor | 12 | EA | 6 | \$1,487 | |
| Storage/ Closet | | 1st Floor | 360 | SF | 6 | \$2,610 | |
| Walls - Concret | e Block | 1st Floor | 658 | SF | 6 | \$1,929 | |
| Work Sink | | 1st Floor | 3 | EA | 6 | \$1,137 | |
| Classrooms Subto | Classrooms Subtotal: | | | | \$ | 6464,501 | |

Classrooms Subtotal:

Building: Linked Addition

| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | |
|-------------------------------|---|--|---|--|---|--|--|
| Administrative Suites/Offices | | | | | | | |
| Ceiling - Lay-in | 100 Main Office (Wait, Reception, + Admin) | 1,554 | SF | 7 | \$0 | | |
| Doors - Side-lite | 100 Main Office (Wait, Reception, + Admin) | 16 | SF | 7 | \$0 | | |
| Doors - Wood Doors inclu hw | 100 Main Office (Wait, Reception, + Admin) | 9 | EA | 7 | \$0 | | |
| Floor - Carpet | 100 Main Office (Wait, Reception, + Admin) | 1,184 | SF | 6 | \$2,523 | | |
| Floor - Tile | 100 Main Office (Wait, Reception, + Admin) | 370 | SF | 7 | \$0 | | |
| Lighting - Lay-in | 100 Main Office (Wait, Reception, + Admin) | 28 | EA | 7 | \$0 | | |
| Power Distribution | 100 Main Office (Wait, Reception, + Admin) | 10 | EA | 7 | \$0 | | |
| Storage/ Closet | 100 Main Office (Wait, Reception, + Admin) | 146 | SF | 7 | \$0 | | |
| Walls - Concrete Block | 100 Main Office (Wait, Reception, + Admin) | 1,925 | SF | 7 | \$0 | | |
| Ceiling - Lay-in | 101 | 156 | SF | 7 | \$0 | | |
| Doors - Side-lite | 101 | 8 | SF | 7 | \$0 | | |
| Doors - Wood Doors inclu hw | 101 | 1 | EA | 7 | \$0 | | |
| Floor - Carpet | 101 | 156 | SF | 6 | \$332 | | |
| Lighting - Lay-in | 101 | 4 | EA | 7 | \$0 | | |
| Power Distribution | 101 | 6 | EA | 7 | \$0 | | |
| | Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Lay-in Power Distribution Storage/ Closet Walls - Concrete Block Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Carpet Lighting - Lay-in | Suites/OfficesCeiling - Lay-in100 Main Office (Wait, Reception, + Admin)Doors - Side-lite100 Main Office (Wait, Reception, + Admin)Doors - Wood Doors inclu hw100 Main Office (Wait, Reception, + Admin)Floor - Carpet100 Main Office (Wait, Reception, + Admin)Floor - Carpet100 Main Office (Wait, Reception, + Admin)Floor - Tile100 Main Office (Wait, Reception, + Admin)Lighting - Lay-in100 Main Office (Wait, Reception, + Admin)Storage/ Closet100 Main Office (Wait, Reception, + Admin)Walls - Concrete Block100 Main Office (Wait, Reception, + Admin)Ceiling - Lay-in101 Doors - Side-liteDoors - Side-lite101Doors - Wood Doors inclu hw101Floor - Carpet101Lighting - Lay-in101 | strative Suites/OfficesCeiling - Lay-in100 Main Office (Wait, Reception, + Admin)1,554 Admin)Doors - Side-lite100 Main Office (Wait, Reception, + Admin)16 Admin)Doors - Wood Doors inclu hw100 Main Office (Wait, Reception, + Admin)9 Admin)Floor - Carpet100 Main Office (Wait, Reception, + Admin)1,184 Admin)Floor - Tile100 Main Office (Wait, Reception, + Admin)370 Admin)Lighting - Lay-in100 Main Office (Wait, Reception, + Admin)28 Admin)Power Distribution100 Main Office (Wait, Reception, + Admin)10 Storage/ Closet100 Main Office (Wait, Reception, + Admin)Walls - Concrete Block100 Main Office (Wait, Reception, + Admin)1,925 Admin)Ceiling - Lay-in101156 Doors - Side-liteDoors - Side-lite1011Doors - Side-lite1011Itor - Carpet1011Elighting - Lay-in1011 | Strative Suites/OfficesCeiling - Lay-in100 Main Office (Wait, Reception, + Admin)1,554SFDoors - Side-lite100 Main Office (Wait, Reception, + Admin)16SFDoors - Wood Doors inclu hw100 Main Office (Wait, Reception, + Admin)9EAFloor - Carpet100 Main Office (Wait, Reception, + Admin)1,184SFFloor - Tile100 Main Office (Wait, Reception, + Admin)370SFLighting - Lay-in100 Main Office (Wait, Reception, + Admin)28EAStorage/ Closet100 Main Office (Wait, Reception, + Admin)10EAWalls - Concrete Block100 Main Office (Wait, Reception, + Admin)146SFDoors - Side-lite101156SFDoors - Side-lite101156SFDoors - Side-lite101156SFLighting - Lay-in1011EACeiling - Lay-in1011EAFloor - Carpet1014EAFloor - Carpet1014EA | strative Suites/OfficesCeiling - Lay-in100 Main Office (Wait, Reception, + Admin)1,554SF7Doors - Side-lite100 Main Office (Wait, Reception, + Admin)16SF7Doors - Wood Doors inclu hw100 Main Office (Wait, Reception, + Admin)16SF7Poors - Carpet100 Main Office (Wait, Reception, + Admin)9EA7Floor - Carpet100 Main Office (Wait, Reception, + Admin)1,184SF6Floor - Tile100 Main Office (Wait, Reception, + Admin)370SF7Lighting - Lay-in100 Main Office (Wait, Reception, + Admin)370SF7Power Distribution100 Main Office (Wait, Reception, + Admin)28EA7Storage/ Closet100 Main Office (Wait, Reception, + Admin)10EA7Walls - Concrete Block100 Main Office (Wait, Reception, + Admin)1,925SF7Ceiling - Lay-in101156SF7Doors - Side-lite1011EA7Doors - Wood Doors inclu hw1011EA7Floor - Carpet1011EA7Ceiling - Lay-in1011EA7Floor - Carpet1011EA7Lighting - Lay-in1011EA7Floor - Carpet1011EA7Floor - Carpet1011EA7Floor - Carpet1011 | Strative Suites/OfficesCeiling - Lay-in100 Main Office (Wait, Reception, + Admin)1,554SF7\$0Doors - Side-lite100 Main Office (Wait, Reception, + Admin)16SF7\$0Doors - Wood Doors inclu hw100 Main Office (Wait, Reception, + Admin)9EA7\$0Floor - Carpet100 Main Office (Wait, Reception, + Admin)9EA7\$0Floor - Tile100 Main Office (Wait, Reception, + Admin)1,184SF6\$2,523Floor - Tile100 Main Office (Wait, Reception, + Admin)370SF7\$0Lighting - Lay-in100 Main Office (Wait, Reception, + Admin)370SF7\$0Power Distribution100 Main Office (Wait, Reception, + Admin)28EA7\$0Storage/ Closet100 Main Office (Wait, Reception, + Admin)10EA7\$0Walls - Concrete Block100 Main Office (Wait, Reception, + Admin)146SF7\$0Doors - Wood Doors inclu hw101156SF7\$0Doors - Wood Doors inclu hw101166SF7\$0Ceiling - Lay-in10116SF7\$0Doors - Wood Doors inclu hw1011EA7\$0Doors - Wood Doors inclu hw10116SF6\$332Lighting - Lay-in10116SF6\$332Lighting - Lay-in1014EA </td | |



Building: Linked Addition

| p Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|-----------|----------|------|------|-------|----------|
| nistrative Suites/Offices | | | | | | |
| Walls - Concrete Block | 101 | 396 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 102 Nurse | 174 | SF | 7 | \$0 | |
| Doors - Side-lite | 102 Nurse | 8 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 102 Nurse | 1 | EA | 7 | \$0 | |
| Floor - Tile | 102 Nurse | 174 | SF | 6 | \$381 | |
| Lighting - Lay-in | 102 Nurse | 5 | EA | 7 | \$0 | |
| Power Distribution | 102 Nurse | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | 102 Nurse | 470 | SF | 7 | \$0 | |
| Work SInk | 102 Nurse | 1 | EA | 7 | \$0 | |
| Ceiling - Lay-in | 103 | 135 | SF | 7 | \$0 | |
| Doors - Side-lite | 103 | 8 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 103 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | 103 | 135 | SF | 6 | \$288 | |
| Lighting - Lay-in | 103 | 4 | EA | 7 | \$0 | |
| Power Distribution | 103 | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | 103 | 400 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 104 | 142 | SF | 7 | \$0 | |
| Doors - Side-lite | 104 | 8 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 104 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | 104 | 142 | SF | 6 | \$303 | |
| Lighting - Lay-in | 104 | 4 | EA | 7 | \$0 | |
| Power Distribution | 104 | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | 104 | 394 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 105 | 128 | SF | 7 | \$0 | |
| Doors - Side-lite | 105 | 8 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 105 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | 105 | 128 | SF | 6 | \$273 | |
| Lighting - Lay-in | 105 | 3 | EA | 7 | \$0 | |
| Power Distribution | 105 | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | 105 | 340 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 106 | 128 | SF | 7 | \$0 | |
| Doors - Side-lite | 106 | 8 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 106 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | 106 | 128 | SF | 6 | \$273 | |
| Lighting - Lay-in | 106 | 3 | EA | 7 | \$0 | |
| Power Distribution | 106 | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | 106 | 340 | SF | 7 | \$0 | |



Building: Linked Addition

| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------------------|--------------------|----------|------|------|---------|----------|
| dministrative Suites/Offices | | | | | | |
| Ceiling - Lay-in | 107 | 132 | SF | 7 | \$0 | |
| Doors - Side-lite | 107 | 8 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 107 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | 107 | 132 | SF | 6 | \$281 | |
| Lighting - Lay-in | 107 | 4 | EA | 7 | \$0 | |
| Power Distribution | 107 | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | 107 | 374 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 108 | 180 | SF | 7 | \$0 | |
| Doors - Side-lite | 108 | 22 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 108 | 2 | EA | 7 | \$0 | |
| Floor - Carpet | 108 | 180 | SF | 6 | \$384 | |
| Lighting - Lay-in | 108 | 6 | EA | 7 | \$0 | |
| Power Distribution | 108 | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | 108 | 420 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 109 | 160 | SF | 7 | \$0 | |
| Doors - Side-lite | 109 | 10 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 109 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | 109 | 160 | SF | 6 | \$341 | |
| Lighting - Lay-in | 109 | 4 | EA | 7 | \$0 | |
| Power Distribution | 109 | 4 | EA | 7 | \$0 | |
| Walls - Concrete Block | 109 | 394 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 110 | 225 | SF | 6 | \$676 | |
| Doors - Steel Doors incl hw | 110 | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 110 | 225 | SF | 6 | \$479 | |
| Lighting - Lay-in | 110 | 6 | EA | 7 | \$0 | |
| Power Distribution | 110 | 8 | EA | 7 | \$0 | |
| Walls - Concrete Block | 110 | 600 | SF | 7 | \$0 | |
| Work SInk | 110 | 1 | EA | 6 | \$508 | |
| Ceiling - Lay-in | 132 Library Office | 415 | SF | 6 | \$1,246 | |
| Doors - Side-lite | 132 Library Office | 28 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 132 Library Office | 2 | EA | 7 | \$0 | |
| Floor - Carpet | 132 Library Office | 415 | SF | 6 | \$884 | |
| Lighting - Lay-in | 132 Library Office | 8 | EA | 7 | \$0 | |
| Power Distribution | 132 Library Office | 8 | EA | 7 | \$0 | |
| Walls - Concrete Block | 132 Library Office | 644 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 135 | 290 | SF | 7 | \$0 | |
| Doors - Side-lite | 135 | 48 | SF | 7 | \$0 | |



Building: Linked Addition

| Group Item - Type | | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------------------|---|--------------------|----------|------|------|---------|------------------------------|
| Administrative Suites/Offices | | | | | | | |
| Doors - Wood Doors inclu hu | N | 135 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | | 135 | 290 | SF | 7 | \$0 | |
| Lighting - Lay-in | | 135 | 8 | EA | 7 | \$0 | |
| Power Distribution | | 135 | 8 | EA | 7 | \$0 | |
| Walls - Concrete Block | | 135 | 494 | SF | 7 | \$0 | |
| Ceiling - Lay-in | | 136 | 152 | SF | 7 | \$0 | |
| Doors - Side-lite | | 136 | 24 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hy | N | 136 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | | 136 | 152 | SF | 7 | \$0 | |
| Lighting - Lay-in | | 136 | 4 | EA | 7 | \$0 | |
| Power Distribution | | 136 | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | | 136 | 345 | SF | 6 | \$1,011 | |
| Ceiling - Lay-in | | 140 Faculty Center | 780 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | | 140 Faculty Center | 42 | SF | 7 | \$0 | |
| Doors - Side-lite | | 140 Faculty Center | 12 | SF | 6 | \$201 | |
| Doors - Wood Doors inclu h | N | 140 Faculty Center | 2 | EA | 6 | \$602 | |
| Floor - Carpet | | 140 Faculty Center | 764 | SF | 6 | \$1,628 | |
| Floor - Tile | | 140 Faculty Center | 58 | SF | 6 | \$127 | |
| Lighting - Lay-in | | 140 Faculty Center | 18 | EA | 7 | \$0 | |
| Lighting - Lay-in | | 140 Faculty Center | 3 | EA | 7 | \$0 | recessed compact fluorescent |
| Power Distribution | | 140 Faculty Center | 40 | EA | 7 | \$0 | |
| Walls - Concrete Block | | 140 Faculty Center | 285 | SF | 6 | \$835 | |
| Walls - Plaster/Drywall | | 140 Faculty Center | 780 | SF | 6 | \$2,153 | |
| Work SInk | | 140 Faculty Center | 1 | EA | 6 | \$508 | |
| Ceiling - Lay-in | | 141 | 280 | SF | 7 | \$0 | |
| Doors - Side-lite | | 141 | 6 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu h | N | 141 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | | 141 | 280 | SF | 6 | \$597 | |
| Lighting - Lay-in | | 141 | 6 | EA | 7 | \$0 | |
| Power Distribution | | 141 | 22 | EA | 7 | \$0 | |
| Walls - Concrete Block | | 141 | 330 | SF | 7 | \$0 | |
| Walls - Plaster/Drywall | | 141 | 300 | SF | 7 | \$0 | |
| Ceiling - Lay-in | | 142 | 324 | SF | 7 | \$0 | |
| Doors - Side-lite | | 142 | 6 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu h | N | 142 | 1 | EA | 7 | \$0 | |
| Floor - Carpet | | 142 | 324 | SF | 5 | \$1,663 | |
| Lighting - Lay-in | | 142 | 6 | EA | 7 | \$0 | |



Building: Linked Addition

| ıp 🏻 | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|-----------------------------|-------------------|----------|------|------|---------|----------|
| inist | rative Suites/Offices | | | | | | |
| | Power Distribution | 142 | 24 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 142 | 355 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 142 | 368 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 143 | 233 | SF | 7 | \$0 | |
| | Doors - Side-lite | 143 | 6 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 143 | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 143 | 233 | SF | 6 | \$496 | |
| | Lighting - Lay-in | 143 | 4 | EA | 7 | \$0 | |
| | Power Distribution | 143 | 16 | EA | 7 | \$0 | |
| 1 | Walls - Concrete Block | 143 | 150 | SF | 7 | \$0 | |
| 1 | Walls - Plaster/Drywall | 143 | 420 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 144 | 233 | SF | 7 | \$0 | |
| | Doors - Side-lite | 144 | 6 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 144 | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 144 | 233 | SF | 6 | \$496 | |
| | Lighting - Lay-in | 144 | 4 | EA | 7 | \$0 | |
| | Power Distribution | 144 | 20 | EA | 7 | \$0 | |
| 1 | Walls - Concrete Block | 144 | 80 | SF | 7 | \$0 | |
| , | Walls - Plaster/Drywall | 144 | 420 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 145 | 353 | SF | 7 | \$0 | |
| | Doors - Side-lite | 145 | 6 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 145 | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 145 | 353 | SF | 6 | \$752 | |
| | Lighting - Lay-in | 145 | 6 | EA | 7 | \$0 | |
| | Power Distribution | 145 | 24 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 145 | 344 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 145 | 340 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 146 | 298 | SF | 6 | \$895 | |
| | Doors - Side-lite | 146 | 6 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 146 | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 146 | 298 | SF | 5 | \$1,530 | |
| | Lighting - Lay-in | 146 | 6 | EA | 6 | \$714 | |
| | Power Distribution | 146 | 20 | EA | 7 | \$0 | |
| , | Walls - Concrete Block | 146 | 420 | SF | 7 | \$0 | |
| , | Walls - Plaster/Drywall | 146 | 242 | SF | 7 | \$0 | |
| 1 | Ceiling - Lay-in | 152 Practice Room | 80 | SF | 7 | \$0 | |
| | Doors - Side-lite | 152 Practice Room | 10 | SF | 6 | \$167 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-------------------|----------|------|------|---------|---|
| Adminis | strative Suites/Offices | | | | | | |
| | Doors - Wood Doors inclu hw | 152 Practice Room | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 152 Practice Room | 80 | SF | 6 | \$170 | |
| | Lighting - Lay-in | 152 Practice Room | 1 | EA | 7 | \$0 | |
| | Power Distribution | 152 Practice Room | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 152 Practice Room | 276 | SF | 6 | \$809 | |
| | Walls - Concrete Block | 152 Practice Room | 155 | SF | 5 | \$1,871 | acoustical panel over the concrete block wall |
| | Ceiling - Lay-in | 153 Practice Room | 80 | SF | 7 | \$0 | |
| | Doors - Side-lite | 153 Practice Room | 10 | SF | 6 | \$167 | |
| | Doors - Wood Doors inclu hw | 153 Practice Room | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 153 Practice Room | 80 | SF | 6 | \$170 | |
| | Lighting - Lay-in | 153 Practice Room | 1 | EA | 7 | \$0 | |
| | Power Distribution | 153 Practice Room | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 153 Practice Room | 276 | SF | 6 | \$809 | |
| | Walls - Concrete Block | 153 Practice Room | 155 | SF | 4 | \$6,517 | acoustical panel over the concrete block wall |
| | Ceiling - Lay-in | 154 Music Office | 160 | SF | 7 | \$0 | |
| | Doors - Side-lite | 154 Music Office | 10 | SF | 6 | \$167 | |
| | Doors - Wood Doors inclu hw | 154 Music Office | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 154 Music Office | 160 | SF | 6 | \$341 | |
| | Lighting - Lay-in | 154 Music Office | 3 | EA | 7 | \$0 | |
| | Power Distribution | 154 Music Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 154 Music Office | 430 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 155 Practice Room | 80 | SF | 7 | \$0 | |
| | Doors - Side-lite | 155 Practice Room | 10 | SF | 6 | \$167 | |
| | Doors - Wood Doors inclu hw | 155 Practice Room | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 155 Practice Room | 80 | SF | 6 | \$170 | |
| | Lighting - Lay-in | 155 Practice Room | 1 | EA | 7 | \$0 | |
| | Power Distribution | 155 Practice Room | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 155 Practice Room | 276 | SF | 6 | \$809 | |
| | Walls - Concrete Block | 155 Practice Room | 155 | SF | 5 | \$1,871 | acoustical panel over the concrete block wall |
| | Ceiling - Lay-in | 156 Practice Room | 80 | SF | 7 | \$0 | |
| | Doors - Side-lite | 156 Practice Room | 10 | SF | 6 | \$167 | |
| | Doors - Wood Doors inclu hw | 156 Practice Room | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 156 Practice Room | 80 | SF | 6 | \$170 | |
| | Lighting - Lay-in | 156 Practice Room | 1 | EA | 7 | \$0 | |
| | Power Distribution | 156 Practice Room | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 156 Practice Room | 276 | SF | 6 | \$809 | |
| | Walls - Concrete Block | 156 Practice Room | 155 | SF | 4 | \$6 517 | acoustical panel over the concrete block wall |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|--------------------------|----------|------|------|---------|--------------------------|
| Admini | strative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | 157 (coat/tickets) | 166 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 157 (coat/tickets) | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 157 (coat/tickets) | 166 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 157 (coat/tickets) | 3 | EA | 7 | \$0 | |
| | Power Distribution | 157 (coat/tickets) | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 157 (coat/tickets) | 420 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 163, Engineers Office | 185 | SF | 7 | \$0 | |
| | Doors - Side-lite | 163, Engineers Office | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 163, Engineers Office | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 163, Engineers Office | 185 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 163, Engineers Office | 3 | EA | 7 | \$0 | |
| | Power Distribution | 163, Engineers Office | 10 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 163, Engineers Office | 535 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 171 Gym Office | 150 | SF | 6 | \$450 | |
| | Doors - Steel Doors incl hw | 171 Gym Office | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 171 Gym Office | 150 | SF | 6 | \$328 | |
| | Lighting - Lay-in | 171 Gym Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | 171 Gym Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 171 Gym Office | 320 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 172 Gym Office | 150 | SF | 6 | \$450 | |
| | Doors - Steel Doors incl hw | 172 Gym Office | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 172 Gym Office | 150 | SF | 6 | \$328 | |
| | Lighting - Lay-in | 172 Gym Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | 172 Gym Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 172 Gym Office | 320 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 182 Crop Sorting Office | 240 | SF | 5 | \$1,428 | |
| | Doors - Side-lite | 182 Crop Sorting Office | 9 | SF | 6 | \$150 | |
| | Doors - Steel Doors incl hw | 182 Crop Sorting Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 182 Crop Sorting Office | 240 | SF | 6 | \$525 | |
| | Lighting - Lay-in | 182 Crop Sorting Office | 6 | EA | 6 | \$714 | |
| | Power Distribution | 182 Crop Sorting Office | 4 | EA | 6 | \$8,500 | |
| | Walls - Concrete Block | 182 Crop Sorting Office | 570 | SF | 6 | \$1,671 | |
| | Ceiling - Lay-in | 185 Show/Exercise Office | 240 | SF | 4 | \$2,440 | Water damage throughout. |
| | Doors - Side-lite | 185 Show/Exercise Office | 12 | SF | 6 | \$201 | |
| | Doors - Steel Doors incl hw | 185 Show/Exercise Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 185 Show/Exercise Office | 240 | SF | 6 | \$525 | |
| | Lighting - Lay-in | 185 Show/Exercise Office | 5 | EA | 6 | \$595 | |
| | | | | | | | |



Building: Linked Addition

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|---------------------------|----------|------|------|---------|------------------|
| Adminis | strative Suites/Offices | | | | | | |
| | Lighting - Lay-in | 185 Show/Exercise Office | 1 | EA | 4 | \$336 | Lens is falling. |
| | Walls - Concrete Block | 185 Show/Exercise Office | 570 | SF | 6 | \$1,671 | |
| | Ceiling - Lay-in | 206 Office | 365 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 206 Office | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 206 Office | 365 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 206 Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | 206 Office | 4 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 206 Office | 430 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 228 Teachers Lounge | 215 | SF | 7 | \$0 | |
| | Doors - Side-lite | 228 Teachers Lounge | 90 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 228 Teachers Lounge | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 228 Teachers Lounge | 215 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 228 Teachers Lounge | 2 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 228 Teachers Lounge | 380 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | Copy Room in 140 | 96 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Copy Room in 140 | 1 | EA | 7 | \$0 | |
| | Floor - Tile | Copy Room in 140 | 96 | SF | 6 | \$210 | |
| | Lighting - Lay-in | Copy Room in 140 | 2 | EA | 7 | \$0 | |
| | Power Distribution | Copy Room in 140 | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Copy Room in 140 | 398 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | Kitchen Office | 80 | SF | 6 | \$240 | |
| | Doors - Steel Doors incl hw | Kitchen Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile Quarry | Kitchen Office | 80 | SF | 6 | \$169 | |
| | Lighting - Lay-in | Kitchen Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | Kitchen Office | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Kitchen Office | 326 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | L06 Office | 292 | SF | 6 | \$877 | |
| | Doors - Wood Doors inclu hw | L06 Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | L06 Office | 292 | SF | 6 | \$292 | |
| | Lighting - Lay-in | L06 Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | L06 Office | 4 | EA | 6 | \$8,500 | |
| | Walls - Concrete Block | L06 Office | 524 | SF | 6 | \$1,536 | |
| | Ceiling - Lay-in | L22 Male Locker Rm Office | 340 | SF | 6 | \$1,021 | |
| | Doors - Wood Doors inclu hw | L22 Male Locker Rm Office | 3 | EA | 6 | \$903 | |
| | Floor - Tile/Sheet | L22 Male Locker Rm Office | 340 | SF | 6 | \$340 | |
| | Lighting - Pendent/Surface | L22 Male Locker Rm Office | 6 | EA | 6 | \$743 | |
| | Walls - Concrete Block | L22 Male Locker Rm Office | 768 | SF | 6 | \$2,251 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|---|----------|------|------|---------|-----------------------|
| Adminis | strative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | L49 Female Locker Rm Office | 340 | SF | 5 | \$2,023 | water damage. |
| | Doors - Wood Doors inclu hw | L49 Female Locker Rm Office | 3 | EA | 7 | \$0 | |
| | Floor - Tile | L49 Female Locker Rm Office | 340 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | L49 Female Locker Rm Office | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | L49 Female Locker Rm Office | 768 | SF | 6 | \$2,251 | |
| | Ceiling - Lay-in | Office inside former Drivers Ed | 140 | SF | 6 | \$420 | |
| | Doors - Wood Doors inclu hw | Office inside former Drivers Ed | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Office inside former Drivers Ed | 140 | SF | 6 | \$306 | |
| | Lighting - Lay-in | Office inside former Drivers Ed | 3 | EA | 7 | \$0 | |
| | Power Distribution | Office inside former Drivers Ed | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Office inside former Drivers Ed | 240 | SF | 7 | \$0 | |
| | Walls - Metal Panel | Office inside former Drivers Ed | 240 | SF | 6 | \$1,792 | storefront |
| | Ceiling - Lay-in | Pool Office | 100 | SF | 6 | \$300 | |
| | Doors - Wood Doors inclu hw | Pool Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | Pool Office | 100 | SF | 6 | \$212 | |
| | Lighting - Lay-in | Pool Office | 2 | EA | 6 | \$238 | |
| | Power Distribution | Pool Office | 4 | EA | 6 | \$8,500 | |
| | Storage/ Closet | Pool Office | 200 | SF | 6 | \$1,450 | Pool Storage Room |
| | Walls - Concrete Block | Pool Office | 280 | SF | 6 | \$821 | |
| | Ceiling - Lay-in | Security Office | 100 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Security Office | 1 | EA | 7 | \$0 | |
| | Floor - Tile | Security Office | 100 | SF | 4 | \$859 | worn and deteriorated |
| | Lighting - Lay-in | Security Office | 1 | EA | 7 | \$0 | |
| | Power Distribution | Security Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Security Office | 370 | SF | 6 | \$1,085 | |
| Gymnas | sia | | | | | | |
| | Bleacher Seating | 1st Floor | 632 | EA | 7 | \$0 | 1264 lf |
| | Ceiling - Exposed | 1st Floor | 11,500 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 13 | EA | 6 | \$3,913 | |
| | Floor - Wood | 1st Floor | 11,500 | SF | 7 | \$0 | |
| | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 32 | EA | 7 | \$0 | |
| | Scoreboards | 1st Floor | 1 | EA | 7 | \$0 | |
| | Sound System | 1st Floor | 1 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 150 | SF | 6 | \$1,088 | |
| | Walls - Concrete Block | 1st Floor | 13,500 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | Exercise + Apparatus Room (100 on plan) | 1,650 | SF | 6 | \$4,955 | ACT are sagging. |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|--|----------|------|------|----------|----------------|
| Gymna | sia | | | | | | |
| | Ceiling - Lay-in | Exercise + Apparatus Room (100 on plan) | 300 | SF | 6 | \$1,064 | |
| | Doors - Wood Doors inclu hw | Exercise + Apparatus Room (100 on plan) | 4 | EA | 6 | \$1,204 | |
| | Floor - Tile/Sheet | Exercise + Apparatus Room (100 on plan) | 300 | SF | 6 | \$300 | |
| | Floor - Weight/ Fitness Room Floor Matting | Exercise + Apparatus Room (100 on plan) | 1,000 | SF | 5 | \$10,582 | worn |
| | Floor - Weight/ Fitness Room Floor Matting | Exercise + Apparatus Room (100 on plan) | 650 | SF | 6 | \$3,969 | |
| | Lighting - Lay-in | Exercise + Apparatus Room (100 on plan) | 42 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Exercise + Apparatus Room (100 on plan) | 1,600 | SF | 7 | \$0 | |
| Kitcher | | | | | | | |
| | Ceiling - Lay-in | Kitchen/Service Line/Dishwashing | 2,040 | SF | 6 | \$6,126 | |
| | Ceiling - Plaster/Drywall | Kitchen/Service Line/Dishwashing | 80 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Kitchen/Service Line/Dishwashing | 11 | EA | 6 | \$3,311 | |
| | Doors - Transom Window | Kitchen/Service Line/Dishwashing | 20 | SF | 6 | \$339 | |
| | Floor - Tile Quarry | Kitchen/Service Line/Dishwashing | 2,120 | SF | 6 | \$4,487 | |
| | Lighting - Lay-in | Kitchen/Service Line/Dishwashing | 44 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Kitchen/Service Line/Dishwashing | 1 | EA | 7 | \$0 | |
| | Serving Line | Kitchen/Service Line/Dishwashing | 45 | LF | 7 | \$0 | |
| | Storage/ Closet | Kitchen/Service Line/Dishwashing | 480 | SF | 6 | \$3,480 | |
| | Walls - Concrete Block | Kitchen/Service Line/Dishwashing | 3,450 | SF | 6 | \$10,114 | |
| Library | | | | | | | |
| | Ceiling - Lay-in | 130 | 3,066 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 130 | 300 | SF | 7 | \$0 | |
| | Doors - Side-lite | 130 | 24 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 130 | 7 | EA | 7 | \$0 | |
| | Floor - Carpet | 130 | 3,366 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 130 | 68 | EA | 7 | \$0 | |
| | Storage/ Closet | 130 | 328 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 130 | 2,040 | SF | 7 | \$0 | terrazzo block |
| | Walls - Plaster/Drywall | 130 | 200 | SF | 7 | \$0 | |
| Locker/ | Shower Room | | | | | | |
| | Ceiling - Lay-In | Home Team Rm | 400 | SF | 5 | \$2,380 | |
| | Ceiling - Lay-In | Home Team Rm | 400 | SF | 5 | \$2,380 | |



Building: Linked Addition

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-------------------|----------|------|------|----------|----------|
| .ocker/ | Shower Room | | | | | | |
| | Doors - Wood Doors inclu hw | Home Team Rm | 3 | EA | 6 | \$903 | |
| | Doors - Wood Doors inclu hw | Home Team Rm | 3 | EA | 6 | \$903 | |
| | Floor - Tile/Sheet | Home Team Rm | 400 | SF | 6 | \$400 | |
| | Floor - Tile/Sheet | Home Team Rm | 400 | SF | 6 | \$400 | |
| | Lighting - Lay-in | Home Team Rm | 6 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Home Team Rm | 6 | EA | 6 | \$714 | |
| | Storage/ Closet | Home Team Rm | 104 | SF | 7 | \$0 | |
| | Student Lockers - One Tier | Home Team Rm | 29 | EA | 6 | \$2,692 | |
| | Student Lockers - One Tier | Home Team Rm | 29 | EA | 6 | \$2,692 | |
| | Walls - Concrete Block | Home Team Rm | 600 | SF | 7 | \$0 | |
| | Walls - Concrete Block | Home Team Rm | 600 | SF | 7 | \$0 | |
| | Benches, ped mounted | L01 Basement Pool | 100 | LF | 6 | \$10,888 | |
| | Ceiling - Lay-In | L01 Basement Pool | 3,728 | SF | 6 | \$11,195 | |
| | Doors - Steel Doors incl hw | L01 Basement Pool | 1 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | L01 Basement Pool | 4 | EA | 7 | \$0 | |
| | Floor Drain | L01 Basement Pool | 10 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | L01 Basement Pool | 378 | SF | 6 | \$800 | |
| | Floor - Tile/Sheet | L01 Basement Pool | 3,350 | SF | 6 | \$3,353 | |
| | Hand Dryer | L01 Basement Pool | 8 | EA | 6 | \$1,840 | |
| | Lavatory | L01 Basement Pool | 4 | EA | 6 | \$1,278 | |
| | Lighting - Lay-in | L01 Basement Pool | 27 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | L01 Basement Pool | 6 | EA | 7 | \$0 | |
| | Partitions | L01 Basement Pool | 5 | EA | 6 | \$1,485 | |
| | Showers | L01 Basement Pool | 12 | EA | 7 | \$0 | |
| | Storage/ Closet | L01 Basement Pool | 172 | SF | 6 | \$1,247 | |
| | Student Lockers - Two Tier | L01 Basement Pool | 492 | EA | 7 | \$0 | |
| | Walls - Concrete Block | L01 Basement Pool | 1,800 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | L01 Basement Pool | 700 | SF | 7 | \$0 | |
| | Water Closet | L01 Basement Pool | 5 | EA | 6 | \$1,680 | |
| | Benches, ped mounted | L02 Basement Pool | 100 | LF | 6 | \$10,888 | |
| | Ceiling - Lay-In | L02 Basement Pool | 3,350 | SF | 5 | \$19,928 | |
| | Doors - Steel Doors incl hw | L02 Basement Pool | 1 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | L02 Basement Pool | 5 | EA | 7 | \$0 | |
| | Floor Drain | L02 Basement Pool | 10 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | L02 Basement Pool | 3,350 | SF | 6 | \$7,090 | |
| | Hand Dryer | L02 Basement Pool | 8 | EA | 6 | \$1,840 | |
| | Lavatory | L02 Basement Pool | 3 | EA | 6 | \$959 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---------------------------------|-----------------------------|----------|------|------|---------|--|
| Locker/S | Shower Room | | | | | | |
| | Lighting - Lay-in | L02 Basement Pool | 27 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | L02 Basement Pool | 6 | EA | 7 | \$0 | |
| | Partitions | L02 Basement Pool | 2 | EA | 6 | \$594 | |
| | Showers | L02 Basement Pool | 12 | EA | 7 | \$0 | |
| | Student Lockers - Two Tier | L02 Basement Pool | 492 | EA | 7 | \$0 | |
| | Urinals | L02 Basement Pool | 3 | EA | 6 | \$1,008 | |
| | Walls - Concrete Block | L02 Basement Pool | 1,800 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | L02 Basement Pool | 700 | SF | 7 | \$0 | |
| | Water Closet | L02 Basement Pool | 3 | EA | 6 | \$1,008 | |
| | Ceiling - Lay-In | L07 Visiting Boys Basement | 166 | SF | 5 | \$988 | |
| | Ceiling - Plaster/ Drywall | L07 Visiting Boys Basement | 317 | SF | 6 | \$1,097 | |
| | Doors - Wood Doors inclu hw | L07 Visiting Boys Basement | 1 | EA | 6 | \$301 | |
| | Floor Drain | L07 Visiting Boys Basement | 4 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | L07 Visiting Boys Basement | 317 | SF | 6 | \$671 | |
| | Floor - Tile/Sheet | L07 Visiting Boys Basement | 166 | SF | 6 | \$166 | |
| | Hand Dryer | L07 Visiting Boys Basement | 2 | EA | 7 | \$0 | |
| | Lavatory | L07 Visiting Boys Basement | 2 | EA | 7 | \$0 | |
| | Lighting - Lay-in | L07 Visiting Boys Basement | 4 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | L07 Visiting Boys Basement | 2 | EA | 7 | \$0 | |
| | Partitions | L07 Visiting Boys Basement | 1 | EA | 7 | \$0 | |
| | Showers | L07 Visiting Boys Basement | 3 | EA | 5 | \$8,143 | |
| | Student Lockers - Two Tier | L07 Visiting Boys Basement | 48 | EA | 7 | \$0 | |
| | Urinals | L07 Visiting Boys Basement | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | L07 Visiting Boys Basement | 325 | SF | 6 | \$953 | |
| | Walls - Concrete Block | L07 Visiting Boys Basement | 150 | SF | 6 | \$504 | |
| | Walls - Structural Glazed Tile | L07 Visiting Boys Basement | 325 | SF | 6 | \$1,022 | |
| | Water Closet | L07 Visiting Boys Basement | 1 | EA | 7 | \$0 | |
| | Accessories | L08 Visiting Girls Basement | 483 | SF | 6 | \$1,892 | Toilet paper dispenser but no actual toilet paper was available, soap dispenser, |
| | Ceiling - Lay-In | L08 Visiting Girls Basement | 166 | SF | 5 | \$988 | · · · · · · · · · · · · · · · · · · · |
| | Ceiling - Plaster/ Drywall | L08 Visiting Girls Basement | 317 | SF | 6 | \$1,097 | |
| | Doors - Wood Doors inclu hw | L08 Visiting Girls Basement | 1 | EA | 6 | \$301 | |
| | Floor Drain | L08 Visiting Girls Basement | 4 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | L08 Visiting Girls Basement | 317 | SF | 6 | \$671 | |
| | Floor - Tile/Sheet | L08 Visiting Girls Basement | 166 | SF | 6 | \$166 | |
| | Hand Dryer | L08 Visiting Girls Basement | 2 | EA | 7 | \$0 | |
| | Lavatory | L08 Visiting Girls Basement | 2 | EA | 7 | \$0 | |
| | Lighting - Lay-in | L08 Visiting Girls Basement | 4 | EA | 7 | \$0 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|---|----------|------|------|---------|----------|
| ocker | /Shower Room | | | | | | |
| | Lighting - Pendent/Surface | L08 Visiting Girls Basement | 2 | EA | 7 | \$0 | |
| | Partitions | L08 Visiting Girls Basement | 2 | EA | 7 | \$0 | |
| | Showers | L08 Visiting Girls Basement | 3 | EA | 5 | \$8,143 | |
| | Student Lockers - Two Tier | L08 Visiting Girls Basement | 48 | EA | 7 | \$0 | |
| | Walls - Concrete Block | L08 Visiting Girls Basement | 325 | SF | 6 | \$953 | |
| | Walls - Concrete Block | L08 Visiting Girls Basement | 150 | SF | 6 | \$504 | |
| | Walls - Structural Glazed Tile | L08 Visiting Girls Basement | 325 | SF | 6 | \$1,022 | |
| | Water Closet | L08 Visiting Girls Basement | 2 | EA | 7 | \$0 | |
| | Ceiling - Lay-In | Physical Therapy Rm | 172 | SF | 6 | \$517 | |
| | Ceiling - Lay-In | Physical Therapy Rm | 172 | SF | 6 | \$517 | |
| | Doors - Wood Doors inclu hw | Physical Therapy Rm | 1 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Physical Therapy Rm | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | Physical Therapy Rm | 172 | SF | 6 | \$172 | |
| | Floor - Tile/Sheet | Physical Therapy Rm | 172 | SF | 6 | \$172 | |
| | Lighting - Lay-in | Physical Therapy Rm | 2 | EA | 6 | \$238 | |
| | Lighting - Lay-in | Physical Therapy Rm | 2 | EA | 6 | \$238 | |
| | Walls - Concrete Block | Physical Therapy Rm | 416 | SF | 6 | \$1,220 | |
| | Walls - Concrete Block | Physical Therapy Rm | 416 | SF | 6 | \$1,220 | |
| | Accessories | South Central Service Area (sheet A2.3) | 200 | SF | 6 | \$784 | |
| | Accessories | South Central Service Area (sheet A2.3) | 200 | SF | 6 | \$784 | |
| | Benches, ped mounted | South Central Service Area (sheet A2.3) | 12 | LF | 7 | \$0 | |
| | Benches, ped mounted | South Central Service Area (sheet A2.3) | 12 | LF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | South Central Service Area (sheet A2.3) | 200 | SF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | South Central Service Area (sheet A2.3) | 200 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | South Central Service Area (sheet A2.3) | 1 | EA | 6 | \$301 | |
| | Doors - Steel Doors incl hw | South Central Service Area (sheet A2.3) | 1 | EA | 6 | \$301 | |
| | Floor Drain | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Floor Drain | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | South Central Service Area (sheet A2.3) | 200 | SF | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | South Central Service Area (sheet A2.3) | 200 | SF | 7 | \$0 | |
| | Hand Dryer | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Hand Dryer | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Lavatory | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Lavatory | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | South Central Service Area (sheet A2.3) | 3 | EA | 7 | \$0 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------|---|----------|------|------|----------|---|
| Locker | /Shower Room | | | | | | |
| | Lighting - Pendent/Surface | South Central Service Area (sheet A2.3) | 3 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Partitions | South Central Service Area (sheet A2.3) | 1 | EA | 6 | \$297 | |
| | Partitions | South Central Service Area (sheet A2.3) | 1 | EA | 6 | \$297 | |
| | Showers | South Central Service Area (sheet A2.3) | 1 | EA | 6 | \$311 | |
| | Showers | South Central Service Area (sheet A2.3) | 1 | EA | 6 | \$311 | |
| | Student Lockers - One Tier | South Central Service Area (sheet A2.3) | 6 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | South Central Service Area (sheet A2.3) | 5 | EA | 6 | \$464 | |
| | Student Lockers - One Tier | South Central Service Area (sheet A2.3) | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | South Central Service Area (sheet A2.3) | 590 | SF | 6 | \$1,730 | |
| | Walls - Concrete Block | South Central Service Area (sheet A2.3) | 590 | SF | 6 | \$1,730 | |
| | Walls - Structural Glazed Tile | South Central Service Area (sheet A2.3) | 90 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | South Central Service Area (sheet A2.3) | 90 | SF | 7 | \$0 | |
| | Water Closet | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Water Closet | South Central Service Area (sheet A2.3) | 1 | EA | 7 | \$0 | |
| Lunch | & Multipurpose Room | | | | | | |
| | Ceiling - Lay-in | 150 Demonstration Room | 2,630 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 150 Demonstration Room | 7 | EA | 6 | \$2,107 | |
| | Floor - Carpet | 150 Demonstration Room | 2,630 | SF | 6 | \$5,604 | |
| | Lighting - Pendent/Surface | 150 Demonstration Room | 20 | EA | 7 | \$0 | 8'-0" long pendent tubes |
| | Lighting - Pendent/Surface | 150 Demonstration Room | 45 | EA | 7 | \$0 | track type lighting which plugs into pendent fixtures. |
| | Stage | 150 Demonstration Room | 192 | SF | 7 | \$0 | demountable stage with ramp |
| | Storage/ Closet | 150 Demonstration Room | 60 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 150 Demonstration Room | 2,015 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 150 Demonstration Room | 700 | SF | 7 | \$0 | accordian type folding partition |
| | Ceiling - Lay-in | 151 Music Room | 1,800 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 151 Music Room | 5 | EA | 7 | \$0 | |
| | Floor - Carpet | 151 Music Room | 1,800 | SF | 5 | \$9,241 | some carpet seams are pulling |
| | Lighting - Pendent/Surface | 151 Music Room | 21 | EA | 7 | \$0 | |
| | Storage/ Closet | 151 Music Room | 190 | SF | 6 | \$1,378 | |
| | Walls - Concrete Block | 151 Music Room | 1,526 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 160 Dining | 4,800 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 160 Dining | 500 | SF | 7 | \$0 | soffit |
| | Doors - Wood Doors inclu hw | 160 Dining | 6 | EA | 6 | \$1,806 | |
| | Floor - Tile | 160 Dining | 4,800 | SF | 6 | \$10,502 | |
| | | - | | | | | |



Building: Linked Addition

| up | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|-----------------------------|----------|------|------|----------|--|
| ch & | Multipurpose Room | | | | | | |
| | Lighting - Lay-in | 160 Dining | 119 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 160 Dining | 2,400 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 161 Faculty Dining Room | 840 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 161 Faculty Dining Room | 30 | SF | 7 | \$0 | soffit |
| | Chalk Board | 161 Faculty Dining Room | 16 | LF | 4 | \$1,469 | |
| | Doors - Wood Doors inclu hw | 161 Faculty Dining Room | 3 | EA | 7 | \$0 | |
| | Floor - Tile | 161 Faculty Dining Room | 840 | SF | 6 | \$1,838 | |
| | Lighting - Lay-in | 161 Faculty Dining Room | 23 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 161 Faculty Dining Room | 1,100 | SF | 6 | \$3,225 | |
| IDF | | | | | | | |
| | Doors - Wood Doors inclu hw | 131 (in Library AV Storage) | 1 | EA | 7 | \$0 | |
| | Finishes | 131 (in Library AV Storage) | 185 | SF | 7 | \$0 | |
| | Ventilation and Cooling | 131 (in Library AV Storage) | 1 | EA | 7 | \$0 | |
| hanio | cal/ Service Rooms | | | | | | |
| | Janitor's Closet | | 75 | SF | 6 | \$537 | NW JC |
| | Janitor's Closet | | 30 | SF | 7 | \$0 | 2nd Floor JC |
| | Loading Docks | | 900 | SF | 6 | \$6,448 | Receiving sheet A2.3 |
| | Mechanical/ Service Rooms | | 688 | SF | 6 | \$4,929 | L05 Chlorine/Filter Room. |
| | Mechanical/ Service Rooms | | 85 | SF | 7 | \$0 | Basement Elevator Room |
| | Mechanical/ Service Rooms | | 124 | SF | 6 | \$888 | 1st Floor Miscellaneous tele/elec. |
| | Mechanical/ Service Rooms | | 89 | SF | 6 | \$638 | 2nd Floor Electrical Room. |
| | Mechanical/ Service Rooms | | 202 | SF | 7 | \$0 | 2nd Floor Electrical room |
| | Mechanical/ Service Rooms | | 84 | SF | 7 | \$0 | Library 130; Electrical Room (Room 040 on Plan in Library 130 |
| | Mechanical/ Service Rooms | | 3,470 | SF | 7 | \$0 | Off of receiving. |
| | Mechanical/ Service Rooms | | 2,028 | SF | 7 | \$0 | South of Gymnasium. |
| | Mechanical/ Service Rooms | | 110 | SF | 6 | \$788 | Rm.110 Fitness Room |
| | Mechanical/ Service Rooms | | 115 | SF | 6 | \$824 | Basement Electrical Room |
| | Storage Room | | 760 | SF | 6 | \$5,445 | L03 Laundry Room |
| | Storage Room | | 460 | SF | 6 | \$3,296 | L05 Storage. |
| | Storage Room | | 200 | SF | 5 | | L05 Pool storage |
| | Storage Room | | 680 | SF | 7 | | Includes yard storage; off of receiving. |
| I& N | atatorium | | | | | | |
| | Bleachers Seating/Plank Seating | Basement | 15 | EA | 6 | \$434 | |
| | Ceiling - Lay-In | Basement | 7,334 | SF | 5 | \$43,628 | |
| | Doors - Steel Doors incl hw | Basement | 6 | EA | 6 | \$1,806 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|------------------------|----------|------|------|-----------|--------------------------------|
| Pool & | Natatorium | | | | | | |
| | Doors - Wood Doors inclu hw | Basement | 2 | EA | 6 | \$602 | |
| | Floor - Concrete Epoxy/ Painted | Basement | 1,417 | SF | 6 | \$750 | pool balcony- painted concrete |
| | Floor - Tile Ceramic/ Porcelain | Basement | 2,600 | SF | 6 | \$5,503 | |
| | Lighting - Lay-in | Basement | 16 | EA | 6 | \$1,904 | |
| | Lighting - Pendent/Surface | Basement | 34 | EA | 7 | \$0 | |
| | Pool Basin | Basement | 3,317 | SF | 6 | \$112,227 | |
| | Walls - Concrete Block | Basement | 1,620 | SF | 7 | \$0 | |
| | Walls - Concrete Block | Basement | 1,170 | SF | 6 | \$3,932 | |
| | Walls - Tile Ceramic/ Porcelain | Basement | 4,809 | SF | 7 | \$0 | |
| Restroc | om | | | | | | |
| | Accessories | 100 Womens - Reception | 64 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 100 Womens - Reception | 64 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 100 Womens - Reception | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 100 Womens - Reception | 64 | SF | 7 | \$0 | |
| | Hand Dryer | 100 Womens - Reception | 1 | EA | 7 | \$0 | |
| | Lavatory | 100 Womens - Reception | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 100 Womens - Reception | 1 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 100 Womens - Reception | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 100 Womens - Reception | 176 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 100 Womens - Reception | 54 | SF | 7 | \$0 | |
| | Water Closet | 100 Womens - Reception | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 308 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 308 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 308 | SF | 6 | \$652 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 308 | SF | 6 | \$652 | |
| | Hand Dryer | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Hand Dryer | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Lavatory | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Lavatory | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 5 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 5 | EA | 7 | \$0 | |
| | Partitions | 2nd Floor | 6 | EA | 6 | \$1,782 | |
| | Partitions | 2nd Floor | 3 | EA | 7 | \$0 | |



Building: Linked Addition

| Peters 2.4 Place 3. E.A. 7. Social Walls - Concrete Block 2.04 Ploor 2.00 SF 7. Social Walls - Concrete Block 2.04 Ploor 120 SF 7. Social Walls - Structural Glazed Tile 2.04 Ploor 122 SF 7. Social Walls - Structural Glazed Tile 2.04 Ploor 122 SF 7. Social Walls - Structural Glazed Tile 2.04 Ploor 128 SF 7. Social Walls - Closet 2.04 Ploor 128 SF 7. Social Cealing - Ploster/Dryvall in 102 Unisex - Nurse 4.2 SF 7. Social Ploor - Tile Cearriel/ Protebian in 102 Unisex - Nurse 1.2 E.4 7. Social Hard Dryer in 102 Unisex - Nurse 1.8 7. Social Social Walls - Structural Glazed Tile in 102 Unisex - Nurse 1.8 F.4 7. Social Walls - Structural Glazed Tile in 102 Unisex - Nurse 1.8 F.4 7. Social Walls - Structu | Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|---------|---------------------------------|-------------------------|----------|------|------|---------|----------|
| Walls - Concrete Block2nd Floor260SF7\$0Walls - Structural Glazed Tile2nd Floor286SF7\$0Walls - Structural Glazed Tile2nd Floor192SF7\$0Water Closet2nd Floor32SF7\$0Water Closet2nd Floor6EA7\$0Constructural Glazed Tile2nd Floor6EA7\$0Accessories1n 102 Unisex - Nurse42SF7\$0Caling - Plaster/Dryvallin 102 Unisex - Nurse42SF7\$0Doors - Wood Doors inclu hwin 102 Unisex - Nurse42SF7\$0Floor - Tile Carrain/ Proteianin 102 Unisex - Nurse4K7\$0Hand Dryerin 102 Unisex - Nurse1EA7\$0Uphting - Pendem%Unfacein 102 Unisex - Nurse1EA7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse1EA7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse1EA7\$0Walls - Goncrete Blockin 102 Unisex - Nurse1EA7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse1EA7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse1EA7\$0Walls - Goncrete Blockin 103 Principal15SF7\$0Walls - Concrete Blockin 104 Principal1 | Restroc | om | | | | | | |
| Walls - Concrete Block 2nd Floor 20 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor 12 SF 7 \$0 Water Closet 2nd Floor 12 SF 7 \$0 Water Closet 2nd Floor 12 SF 7 \$0 Colleging - Plaster/Dryvall 2nd Floor 12 SF 7 \$0 Colling - Plaster/Dryvall in 102 Unisex - Nurse 42 SF 7 \$0 Doors - Wood Doors inclu hw in 102 Unisex - Nurse 42 SF 7 \$0 Hand Dryer in 102 Unisex - Nurse 42 SF 7 \$0 Lustory in 102 Unisex - Nurse 42 SF 7 \$0 Ughting - Pendent/Surface in 102 Unisex - Nurse 14 EA 7 \$0 Walls - Structural Glazed Tile in 102 Unisex - Nurse 48 SF 7 \$0 Concrete Block in 102 Unisex - Nurse 48 SF 7 \$0 \$0 Walls - Structural Glazed Tile in 102 Unisex - Nurse 156 <t< td=""><td></td><td>Urinals</td><td>2nd Floor</td><td>3</td><td>EA</td><td>7</td><td>\$0</td><td></td></t<> | | Urinals | 2nd Floor | 3 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tile2nd Floor192SF7\$0Water Closet2nd Floor6EA6\$2.016Mater Closet2nd Floor6EA6\$2.016Accessories1nd 2Unisex - Nurse42SF7\$0Ceiling - Plaster/Dryvallin 102 Unisex - Nurse42SF7\$0Doors - Wood Doors inclu hwin 102 Unisex - Nurse4EA7\$0Floor - Tile Certanic/ Porcelainin 102 Unisex - Nurse1EA7\$0Hand Dryerin 102 Unisex - Nurse1EA7\$0Lavatoryin 102 Unisex - Nurse1EA7\$0Walls - Concrete Blockin 102 Unisex - Nurse1EA7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Doors - Wood Doors inclu hwin 109 - Principal5SF7\$0Doors - Wood Doors inclu hwin 109 - Principal1EA7\$0Hand Dryerin 109 - Principal1EA7\$0Lavatoryin 109 - Principal1EA7\$0Doors - Wood Doors inclu hwin 109 - Principal1EA7\$ | | Walls - Concrete Block | 2nd Floor | 260 | SF | 7 | \$0 | |
| Walle - Structurd Glazed TileZnd Floor122SF7\$0Water Closet2nd Floor3EA6\$22.016Water Closet10 20 Unisex - Nurse42SF7\$0Celling - Plaster/Dynall10 10 Unisex - Nurse42SF7\$0Doors - Wood Doors inclu hwin 102 Unisex - Nurse41EA7\$0Floor - Tile Caramic / Porcelainin 102 Unisex - Nurse1EA7\$0Hand Dyerin 102 Unisex - Nurse1EA7\$0Lavatoryin 102 Unisex - Nurse1EA7\$0Ughting - Penden/Surfacein 102 Unisex - Nurse1EA7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse1EA7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse1EA7\$0Walls - Structural Glazed Tilein 109 Principal56SF7\$0Celling - Plaster/Dynallin 109 Principal1EA7\$0Doors - Wood Doors inclu hwin 109 Principal1EA7\$0Lavatoryin 109 Principal1EA7\$0Lavatoryin 109 Principal1EA7\$0Lavatoryin 109 Principal1EA7\$0Lavatoryin 109 Principal1EA7\$0 </td <td></td> <td>Walls - Concrete Block</td> <td>2nd Floor</td> <td>260</td> <td>SF</td> <td>7</td> <td>\$0</td> <td></td> | | Walls - Concrete Block | 2nd Floor | 260 | SF | 7 | \$0 | |
| Water Closet2nd Floor3EA750Water Closet2nd FloorFL6\$2.016Accessoriesin 102 Unisex - Nurse42SF7\$0Ceiling - Plaster/Dryvallin 102 Unisex - Nurse42SF7\$0Doors - Wood Doors indu hwin 102 Unisex - Nurse42SF7\$0Floor - Tile Ceramic/ Porcelainin 102 Unisex - Nurse42SF7\$0Lavatoryin 102 Unisex - Nurse44SF7\$0Lighting - Pendent/Surfacein 102 Unisex - Nurse48SF7\$0Walts - Concrete Blockin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal58SF7\$0Doors - Wood Doors inclu hwin 109 - Principal48SF7\$0Hand Dryerin 109 - Principal48SF7\$0Doors - Wood Doors inclu hwin 109 - Principal48SF7\$0Hand Dryerin 109 - Principal48SF7\$0Lavatoryin 109 - Principal48SF7\$0Walts - Concrete Blockin 109 - Principal58SF7\$0 | | Walls - Structural Glazed Tile | 2nd Floor | 192 | SF | 7 | \$0 | |
| Water Closet2nd Floor6EA6\$2.016Accessoriesin 102 Unisex - Nurse42SF7\$0Doors - Wood Doors indu hwin 102 Unisex - Nurse42SF7\$0Doors - Wood Doors indu hwin 102 Unisex - Nurse42SF7\$0Hand Dyorin 102 Unisex - Nurse42SF7\$0Hand Dyorin 102 Unisex - Nurse4EA7\$0Lavatoryin 102 Unisex - Nurse4EA7\$0Ughting - Pendent/Surfacein 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Accessoriesin 109 - Principal55SF7\$0Accessoriesin 109 - Principal55SF7\$0Doors - Wood Doors inclu hwin 109 - Principal18SF7\$0Hand Dyerin 109 - Principal14EA7\$0Hand Dyerin 109 - Principal14EA7\$0Ughting - Pendent/Surfacein 109 - Principal15SF7\$0Ughting - Pendent/Surfacein 109 - Principal14EA7\$0Walls - Concrete Blockin 109 - Principal15SF7\$ | | Walls - Structural Glazed Tile | 2nd Floor | 192 | SF | 7 | \$0 | |
| Accessoriesin 102 Unisex - Nurse42SF7\$0Ceiling - Plaster/Drywallin 102 Unisex - Nurse42SF7\$0Doors - Wood Doors inclu hwin 102 Unisex - Nurse42SF7\$0Floor - Tile Ceramic/ Porcelainin 102 Unisex - Nurse42SF7\$0Lavatoryin 102 Unisex - Nurse42SF7\$0Lavatoryin 102 Unisex - Nurse1EA7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Water Closetin 102 Unisex - Nurse18SF7\$0Doors - Wood Doors inclu hwin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal18EA7\$0Lavatoryin 109 - Principal18EA7\$0Lavatoryin 109 - Principal18EA7\$0Lavatoryin 109 - Principal18EA7\$0Lavatoryin 109 - Principal18EA7\$0Walls - Concrete Blockin 109 - Principal18EA7\$0Walls - Structural Glazed Tilein 109 - Principal18 <td></td> <td>Water Closet</td> <td>2nd Floor</td> <td>3</td> <td>EA</td> <td>7</td> <td>\$0</td> <td></td> | | Water Closet | 2nd Floor | 3 | EA | 7 | \$0 | |
| Ceiling - Plaster/Drywallin 102 Unisex - Nurse42SF7\$0Doors - Wood Doors inclu hwin 102 Unisex - Nurse42SF7\$0Floor - Tile Ceramic/ Porcelainin 102 Unisex - Nurse42SF7\$0Hand Dryerin 102 Unisex - Nurse1EA7\$0Lavatoryin 102 Unisex - Nurse1EA7\$0Unighting - Pendent/Surfacein 102 Unisex - Nurse1EA7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Concrete Blockin 109 - Principal56SF7\$0Ceiling - Plaster/Drywallin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal18EA7\$0Hand Dryerin 09 - Principal16SF7\$0Uniser - Nurse19FMFA7\$0Doors - Wood Doors inclu hwin 109 - Principal18EA7\$0Hand Dryerin 09 - Principal170SF7\$0Walls - Concrete Blockin 109 - Principal18EA7\$0Walls - Concrete Blockin 109 - Principal< | | Water Closet | 2nd Floor | 6 | EA | 6 | \$2,016 | |
| DoorsWood Doors inclu hwin 102 Unisex - Nurse1EA7\$0Floor - Tile Ceramic/ Porcelainin 102 Unisex - Nurse42SF7\$0Hand Dryerin 102 Unisex - Nurse1EA7\$0Lavatoryin 102 Unisex - Nurse1EA7\$0Lighting - Pendent/Surfacein 102 Unisex - Nurse1EA7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse1EA7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse1EA7\$0Ocining - Plaster/Drywallin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal1EA7\$0Floor - Tile Ceramic/ Porcelainin 109 - Principal1EA7\$0Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Ughting - Pendent/Surfacein 109 - Principal1EA7\$0Ughting - Pendent/Surfacein 109 - Principal1EA7\$0Ughting - Pendent/Surfacein 109 - Principal1EA7\$0Walls - Structural Glazed Tilein 109 - Principal1EA7\$0Walls - Structural Glazed Tilein 109 - Principal1EA <td< td=""><td></td><td>Accessories</td><td>in 102 Unisex - Nurse</td><td>42</td><td>SF</td><td>7</td><td>\$0</td><td></td></td<> | | Accessories | in 102 Unisex - Nurse | 42 | SF | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelainin 102 Unisex - Nurse42SF7\$0Hand Dryerin 102 Unisex - Nurse1EA7\$0Lavatoryin 102 Unisex - Nurse18SF7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Water Closetin 102 Unisex - Nurse18SF7\$0Ceiling - Plaster/Drywallin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal18EA7\$0Hand Dryerin 109 - Principal14EA7\$0Lighting - Pendent/Surfacein 109 - Principal14EA7\$0Walls - Concrete Blockin 109 - Principal14EA7 <t< td=""><td></td><td>Ceiling - Plaster/Drywall</td><td>in 102 Unisex - Nurse</td><td>42</td><td>SF</td><td>7</td><td>\$0</td><td></td></t<> | | Ceiling - Plaster/Drywall | in 102 Unisex - Nurse | 42 | SF | 7 | \$0 | |
| Hand Dyerin 102 Unisex - Nurse1EA7\$0Lavatoryin 102 Unisex - Nurse1EA7\$0Uighting - Pendem/Surfacein 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse48SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse48SF7\$0Accessoriesin 102 Unisex - Nurse48SF7\$0Ceiling - Plaster/Drywallin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal1EA7\$0Hand Dryerin 109 - Principal1EA7\$0Uighting - Pendem/Surfacein 109 - Principal1EA7\$0Uighting - Pendem/Surfacein 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal1EA7\$0Walls - Structural Glazed Tilein 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal1EA7\$0Walls - Structural Glazed Tilein 109 - Principal1EA7\$0Doors - Wood Doors inclu hwin 104 - Faculty Center | | Doors - Wood Doors inclu hw | in 102 Unisex - Nurse | 1 | EA | 7 | \$0 | |
| Lavatoryin 102 Unisex - Nurse1EA7\$0Lighting - Pendent/Surfacein 102 Unisex - Nurse1EA7\$0Walls - Concrete Blockin 102 Unisex - Nurse18SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Water Closetin 102 Unisex - Nurse1EA7\$0Accessoriesin 109 - Principal56SF7\$0Ceiling - Plaster/Drywallin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal56SF7\$0Floor - Tile Ceramic/ Porcelainin 109 - Principal1EA7\$0Hand Dryerin 109 - Principal1EA7\$0Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Uavatoryin 109 - Principal1EA7\$0Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal1EA7\$0Walls - Structural Glazed Tilein 109 - Principal1EA7\$0Accessoriesin 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal1EA7\$0Ocors inclu hwin 109 - Principal1EA7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF <td></td> <td>Floor - Tile Ceramic/ Porcelain</td> <td>in 102 Unisex - Nurse</td> <td>42</td> <td>SF</td> <td>7</td> <td>\$0</td> <td></td> | | Floor - Tile Ceramic/ Porcelain | in 102 Unisex - Nurse | 42 | SF | 7 | \$0 | |
| Lighting - Pendent/Surfacein 102 Unisex - Nurse1EA7\$0Walls - Concrete Blockin 102 Unisex - Nurse136SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse18SF7\$0Watc Closetin 102 Unisex - Nurse1EA7\$0Accessoriesin 109 - Principal56SF7\$0Ceiling - Plaster/Drywallin 109 - Principal1EA7\$0Doors - Wood Doors inclu hwin 109 - Principal1EA7\$0Hand Dryerin 109 - Principal1EA7\$0Hand Dryerin 109 - Principal1EA7\$0Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Uaylis - Concrete Blockin 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal1EA7\$0Water Closetin 109 - Principal1EA7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center54SF </td <td></td> <td>Hand Dryer</td> <td>in 102 Unisex - Nurse</td> <td>1</td> <td>EA</td> <td>7</td> <td>\$0</td> <td></td> | | Hand Dryer | in 102 Unisex - Nurse | 1 | EA | 7 | \$0 | |
| Walls - Concrete Blockin 102 Unisex - Nurse136SF7\$0Walls - Structural Glazed Tilein 102 Unisex - Nurse48SF7\$0Water Closetin 100 - Principal58SF7\$0Accessoriesin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal56SF7\$0Floor - Tile Ceramic/ Porcelainin 109 - Principal16EA7\$0Hand Dryerin 109 - Principal16EA7\$0Lighting - Pendent/Surfacein 109 - Principal18EA7\$0Lighting - Pendent/Surfacein 109 - Principal18EA7\$0Walls - Structural Glazed Tilein 109 - Principal18EA7\$0Walls - Concrete Blockin 109 - Principal170SF7\$0Walls - Concrete Blockin 109 - Principal57S\$0Walls - Structural Glazed Tilein 109 - Principal58SF7\$0Water Closetin 109 - Principal58SF7\$0Ceiling - Plaster/Drywallin 140 - Facutly Center54SF7\$0Coors - Wood Doors inclu hwin 140 - Facutly Center54SF7\$0Floor - Tile Ceramic/ Porcelainin 140 - Facutly Center54SF7\$0Lighting - Pendent/Surfacein 140 - Facutly Center54SF7\$0Lavatory< | | Lavatory | in 102 Unisex - Nurse | 1 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tilein 102 Unisex - Nurse48SF7\$0Water Closetin 102 Unisex - Nurse1EA7\$0Accessoriesin 109 - Principal56SF7\$0Ceiling - Plaster/Drywallin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal1EA7\$0Lavatoryin 109 - Principal1EA7\$0Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Walls - Structural Glazed Tilein 109 - Principal1EA7\$0Walls - Structural Glazed Tilein 109 - Principal1EA7\$0Walls - Structural Glazed Tilein 109 - Principal1EA7\$0Water Closetin 109 - Principal10SF7\$0Water Closetin 109 - Principal1EA7\$0Mater Closetin 109 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center <td></td> <td>Lighting - Pendent/Surface</td> <td>in 102 Unisex - Nurse</td> <td>1</td> <td>EA</td> <td>7</td> <td>\$0</td> <td></td> | | Lighting - Pendent/Surface | in 102 Unisex - Nurse | 1 | EA | 7 | \$0 | |
| Water Closetin 102 Unisex - Nurse1EA7\$0Accessoriesin 109 - Principal66SF7\$0Ceiling - Plaster/Drywallin 109 - Principal16SF7\$0Doors - Wood Doors inclu hwin 109 - Principal1EA7\$0Hand Dryerin 109 - Principal1EA7\$0Lavatoryin 109 - Principal1EA7\$0Ull shing - Pendent/Surfacein 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal10EA7\$0Walls - Structural Glazed Tilein 109 - Principal10EA7\$0Water Closetin 109 - Principal10EA7\$0Water Closetin 109 - Principal10EA7\$0Valls - Concrete Blockin 109 - Principal10EA7\$0Water Closetin 109 - Principal1EA7\$0Valls - Concrete Blockin 109 - Principal1EA7\$0Orors - Wood Doors inclu hwin 140 - Faculty Center5F7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center1EA7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Hand Dryerin 140 - Faculty Center1EA7\$0 | | Walls - Concrete Block | in 102 Unisex - Nurse | 136 | SF | 7 | \$0 | |
| Accessoriesin 109 - Principal56SF7\$0Ceiling - Plaster/Drywallin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal1EA7\$0Floor - Tile Ceramic/ Porcelainin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal1EA7\$0Lavatoryin 109 - Principal1EA7\$0Lavatoryin 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal10SF7\$0Walls - Concrete Blockin 109 - Principal50SF7\$0Walls - Concrete Blockin 109 - Principal10EA7\$0Walls - Concrete Blockin 109 - Principal50SF7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center54SF7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center1EA7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA <td></td> <td>Walls - Structural Glazed Tile</td> <td>in 102 Unisex - Nurse</td> <td>48</td> <td>SF</td> <td>7</td> <td>\$0</td> <td></td> | | Walls - Structural Glazed Tile | in 102 Unisex - Nurse | 48 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywallin 109 - Principal56SF7\$0Doors - Wood Doors inclu hwin 109 - Principal1EA7\$0Floor - Tile Ceramic/ Porcelainin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal1EA7\$0Lavatoryin 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal10SF7\$0Walls - Structural Glazed Tilein 109 - Principal10SF7\$0Water Closetin 109 - Principal10SF7\$0Ceiling - Plaster/Drywallin 109 - Principal10EA7\$0Water Closetin 109 - Principal1EA7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center1EA7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA7\$0 | | Water Closet | in 102 Unisex - Nurse | 1 | EA | 7 | \$0 | |
| Doors - Wood Doors inclu hwin 109 - Principal1EA7\$0Floor - Tile Ceramic/ Porcelainin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal1EA7\$0Lavatoryin 109 - Principal1EA7\$0Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal10SF7\$0Walls - Structural Glazed Tilein 109 - Principal50SF7\$0Water Closetin 109 - Principal1EA7\$0Accessoriesin 109 - Principal1EA7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center54SF7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Hand Dryerin 140 - Faculty Center54SF7\$0Lavatoryin 140 - Faculty Center1EA7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0 <t< td=""><td></td><td>Accessories</td><td>in 109 - Principal</td><td>56</td><td>SF</td><td>7</td><td>\$0</td><td></td></t<> | | Accessories | in 109 - Principal | 56 | SF | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelainin 109 - Principal56SF7\$0Hand Dryerin 109 - Principal1EA7\$0Lavatoryin 109 - Principal1EA7\$0Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal10SF7\$0Walls - Structural Glazed Tilein 109 - Principal50SF7\$0Water Closetin 109 - Principal1EA7\$0Accessoriesin 109 - Principal1EA7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center1EA7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0 <trr></trr> | | Ceiling - Plaster/Drywall | in 109 - Principal | 56 | SF | 7 | \$0 | |
| Hand Dryerin 109 - Principal1EA7\$0Lavatoryin 109 - Principal1EA7\$0Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal170SF7\$0Walls - Structural Glazed Tilein 109 - Principal50SF7\$0Walls - Structural Glazed Tilein 109 - Principal1EA7\$0Water Closetin 109 - Principal1EA7\$0Accessoriesin 140 - Faculty Center54SF7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center1EA7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighti | | | in 109 - Principal | 1 | EA | 7 | \$0 | |
| Lavatoryin 109 - Principal1EA7\$0Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal170SF7\$0Walls - Structural Glazed Tilein 109 - Principal50SF7\$0Water Closetin 109 - Principal1EA7\$0Accessoriesin 140 - Faculty Center54SF7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center54SF7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA7\$0 | | Floor - Tile Ceramic/ Porcelain | in 109 - Principal | 56 | SF | 7 | \$0 | |
| Lighting - Pendent/Surfacein 109 - Principal1EA7\$0Walls - Concrete Blockin 109 - Principal170SF7\$0Walls - Structural Glazed Tilein 109 - Principal50SF7\$0Water Closetin 109 - Principal1EA7\$0Accessoriesin 109 - Faculty Center54SF7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA7\$0 | | Hand Dryer | in 109 - Principal | 1 | EA | 7 | \$0 | |
| Walls - Concrete Blockin 109 - Principal170SF7\$0Walls - Structural Glazed Tilein 109 - Principal50SF7\$0Water Closetin 109 - Principal1EA7\$0Accessoriesin 140 - Faculty Center54SF7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA7\$0 | | Lavatory | in 109 - Principal | 1 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tilein 109 - Principal50SF7\$0Water Closetin 109 - Principal1EA7\$0Accessoriesin 140 - Faculty Center54SF7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA7\$0 | | Lighting - Pendent/Surface | in 109 - Principal | 1 | EA | 7 | \$0 | |
| Water Closetin 109 - Principal1EA7\$0Accessoriesin 140 - Faculty Center54SF7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA7\$0 | | Walls - Concrete Block | in 109 - Principal | 170 | SF | 7 | \$0 | |
| Accessoriesin 140 - Faculty Center54SF7\$0Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA6\$124 | | Walls - Structural Glazed Tile | in 109 - Principal | 50 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywallin 140 - Faculty Center54SF7\$0Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA6\$124 | | Water Closet | in 109 - Principal | 1 | EA | 7 | \$0 | |
| Doors - Wood Doors inclu hwin 140 - Faculty Center1EA7\$0Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA7\$124 | | Accessories | in 140 - Faculty Center | 54 | SF | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelainin 140 - Faculty Center54SF7\$0Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA6\$124 | | Ceiling - Plaster/Drywall | in 140 - Faculty Center | 54 | SF | 7 | \$0 | |
| Hand Dryerin 140 - Faculty Center1EA7\$0Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA6\$124 | | Doors - Wood Doors inclu hw | in 140 - Faculty Center | 1 | EA | 7 | \$0 | |
| Lavatoryin 140 - Faculty Center1EA7\$0Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA6\$124 | | Floor - Tile Ceramic/ Porcelain | in 140 - Faculty Center | 54 | SF | 7 | \$0 | |
| Lighting - Pendent/Surfacein 140 - Faculty Center1EA7\$0Lighting - Wall Mountedin 140 - Faculty Center1EA6\$124 | | Hand Dryer | in 140 - Faculty Center | 1 | EA | 7 | \$0 | |
| Lighting - Wall Mounted in 140 - Faculty Center 1 EA 6 \$124 | | Lavatory | in 140 - Faculty Center | 1 | EA | 7 | \$0 | |
| | | Lighting - Pendent/Surface | in 140 - Faculty Center | 1 | EA | 7 | \$0 | |
| Walls - Plaster/Dravall in 140 - Eaculty Center 152 SE 7 \$0 | | Lighting - Wall Mounted | in 140 - Faculty Center | 1 | EA | 6 | \$124 | |
| | | Walls - Plaster/Drywall | in 140 - Faculty Center | 152 | SF | 7 | \$0 | |
| Walls - Structural Glazed Tilein 140 - Faculty Center60SF7\$0 | | Walls - Structural Glazed Tile | in 140 - Faculty Center | 60 | SF | 7 | \$0 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|--------------------------------|----------|------|------|---------|---------------|
| Restro | om | | | | | | |
| | Water Closet | in 140 - Faculty Center | 1 | EA | 7 | \$0 | |
| | Accessories | in Kitchen Unisex | 45 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | in Kitchen Unisex | 45 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | in Kitchen Unisex | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | in Kitchen Unisex | 45 | SF | 7 | \$0 | |
| | Lavatory | in Kitchen Unisex | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | in Kitchen Unisex | 1 | EA | 6 | \$124 | |
| | Walls - Concrete Block | in Kitchen Unisex | 140 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | in Kitchen Unisex | 48 | SF | 7 | \$0 | |
| | Water Closet | in Kitchen Unisex | 1 | EA | 7 | \$0 | |
| | Ceiling - Lay-in | L22 Male Locker Rm Office | 25 | SF | 6 | \$75 | |
| | Doors - Wood Doors inclu hw | L22 Male Locker Rm Office | 1 | EA | 6 | \$301 | |
| | Floor Drain | L22 Male Locker Rm Office | 2 | EA | 6 | \$2,118 | |
| | Floor - Tile Ceramic/ Porcelain | L22 Male Locker Rm Office | 25 | SF | 6 | \$53 | |
| | Lavatory | L22 Male Locker Rm Office | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | L22 Male Locker Rm Office | 1 | EA | 7 | \$0 | |
| | Showers | L22 Male Locker Rm Office | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | L22 Male Locker Rm Office | 200 | SF | 6 | \$586 | |
| | Walls - Structural Glazed Tile | L22 Male Locker Rm Office | 100 | SF | 6 | \$315 | |
| | Water Closet | L22 Male Locker Rm Office | 1 | EA | 6 | \$336 | |
| | Ceiling - Plaster/Drywall | L49 Female Locker Rm Office | 25 | SF | 6 | \$87 | |
| | Doors - Wood Doors inclu hw | L49 Female Locker Rm Office | 1 | EA | 6 | \$301 | |
| | Floor Drain | L49 Female Locker Rm Office | 2 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | L49 Female Locker Rm Office | 25 | SF | 6 | \$53 | |
| | Lavatory | L49 Female Locker Rm Office | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | L49 Female Locker Rm Office | 1 | EA | 7 | \$0 | |
| | Showers | L49 Female Locker Rm Office | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | L49 Female Locker Rm Office | 200 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | L49 Female Locker Rm Office | 100 | SF | 7 | \$0 | |
| | Water Closet | L49 Female Locker Rm Office | 1 | EA | 6 | \$336 | |
| | Accessories | Mens in Crop Sorting Room (NW) | 71 | SF | 6 | \$655 | Toilet paper. |
| | Ceiling - Plaster/Drywall | Mens in Crop Sorting Room (NW) | 71 | SF | 6 | \$246 | |
| | Doors - Steel Doors incl hw | Mens in Crop Sorting Room (NW) | 1 | EA | 6 | \$301 | |
| | Floor Drain | Mens in Crop Sorting Room (NW) | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Mens in Crop Sorting Room (NW) | 71 | SF | 7 | \$0 | |
| | Hand Dryer | Mens in Crop Sorting Room (NW) | 1 | EA | 6 | \$230 | |
| | Lavatory | Mens in Crop Sorting Room (NW) | 1 | EA | 6 | \$320 | |
| | | | | | | | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-----------------------------------|----------|------|------|---------|-------------------------|
| Restroc | om | | | | | | |
| | Lighting - Pendent/Surface | Mens in Crop Sorting Room (NW) | 1 | EA | 6 | \$124 | |
| | Partitions | Mens in Crop Sorting Room (NW) | 2 | EA | 7 | \$0 | |
| | Urinals | Mens in Crop Sorting Room (NW) | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Mens in Crop Sorting Room (NW) | 65 | SF | 6 | \$191 | |
| | Walls - Structural Glazed Tile | Mens in Crop Sorting Room (NW) | 96 | SF | 6 | \$302 | |
| | Water Closet | Mens in Crop Sorting Room (NW) | 1 | EA | 7 | \$0 | |
| | Accessories | Mens in Show & Exercise Area (SW) | 71 | SF | 6 | \$655 | Toilet paper dispenser. |
| | Ceiling - Plaster/Drywall | Mens in Show & Exercise Area (SW) | 71 | SF | 6 | \$246 | |
| | Doors - Steel Doors incl hw | Mens in Show & Exercise Area (SW) | 1 | EA | 6 | \$301 | |
| | Floor Drain | Mens in Show & Exercise Area (SW) | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Mens in Show & Exercise Area (SW) | 71 | SF | 6 | \$150 | |
| | Hand Dryer | Mens in Show & Exercise Area (SW) | 1 | EA | 7 | \$0 | |
| | Lavatory | Mens in Show & Exercise Area (SW) | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Mens in Show & Exercise Area (SW) | 1 | EA | 6 | \$124 | |
| | Partitions | Mens in Show & Exercise Area (SW) | 2 | EA | 6 | \$594 | |
| | Urinals | Mens in Show & Exercise Area (SW) | 1 | EA | 6 | \$336 | |
| | Walls - Concrete Block | Mens in Show & Exercise Area (SW) | 65 | SF | 6 | \$191 | |
| | Walls - Structural Glazed Tile | Mens in Show & Exercise Area (SW) | 96 | SF | 6 | \$302 | |
| | Water Closet | Mens in Show & Exercise Area (SW) | 1 | EA | 6 | \$336 | |
| | Accessories | South of Dining (sheet A2.3) | 140 | SF | 6 | \$1,291 | |
| | Accessories | South of Dining (sheet A2.3) | 140 | SF | 6 | \$1,291 | |
| | Ceiling - Plaster/Drywall | South of Dining (sheet A2.3) | 140 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | South of Dining (sheet A2.3) | 140 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | South of Dining (sheet A2.3) | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | South of Dining (sheet A2.3) | 1 | EA | 6 | \$301 | |
| | Floor Drain | South of Dining (sheet A2.3) | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | South of Dining (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | South of Dining (sheet A2.3) | 140 | SF | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | South of Dining (sheet A2.3) | 140 | SF | 6 | \$296 | |
| | Hand Dryer | South of Dining (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Hand Dryer | South of Dining (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Lavatory | South of Dining (sheet A2.3) | 1 | EA | 6 | \$320 | |
| | Lavatory | South of Dining (sheet A2.3) | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | South of Dining (sheet A2.3) | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | South of Dining (sheet A2.3) | 2 | EA | 7 | \$0 | |
| | Partitions | South of Dining (sheet A2.3) | 1 | EA | 6 | \$297 | |
| | Partitions | South of Dining (sheet A2.3) | 2 | EA | 6 | \$594 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|----------------------------------|----------|------|------|---------|----------|
| Restroo | m | | | | | | |
| | Urinals | South of Dining (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | South of Dining (sheet A2.3) | 336 | SF | 6 | \$985 | |
| | Walls - Concrete Block | South of Dining (sheet A2.3) | 336 | SF | 6 | \$985 | |
| | Walls - Structural Glazed Tile | South of Dining (sheet A2.3) | 84 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | South of Dining (sheet A2.3) | 84 | SF | 7 | \$0 | |
| | Water Closet | South of Dining (sheet A2.3) | 2 | EA | 7 | \$0 | |
| | Water Closet | South of Dining (sheet A2.3) | 1 | EA | 7 | \$0 | |
| | Accessories | South of Main Entry (sheet A2.1) | 145 | SF | 6 | \$1,337 | |
| | Accessories | South of Main Entry (sheet A2.1) | 240 | SF | 6 | \$2,214 | |
| | Ceiling - Plaster/Drywall | South of Main Entry (sheet A2.1) | 240 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | South of Main Entry (sheet A2.1) | 145 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | South of Main Entry (sheet A2.1) | 1 | EA | 5 | \$1,174 | |
| | Doors - Wood Doors inclu hw | South of Main Entry (sheet A2.1) | 1 | EA | 5 | \$1,174 | |
| | Floor Drain | South of Main Entry (sheet A2.1) | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | South of Main Entry (sheet A2.1) | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | South of Main Entry (sheet A2.1) | 145 | SF | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | South of Main Entry (sheet A2.1) | 240 | SF | 7 | \$0 | |
| | Hand Dryer | South of Main Entry (sheet A2.1) | 2 | EA | 7 | \$0 | |
| | Hand Dryer | South of Main Entry (sheet A2.1) | 2 | EA | 7 | \$0 | |
| | Lavatory | South of Main Entry (sheet A2.1) | 1 | EA | 6 | \$320 | |
| | Lavatory | South of Main Entry (sheet A2.1) | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | South of Main Entry (sheet A2.1) | 4 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | South of Main Entry (sheet A2.1) | 3 | EA | 7 | \$0 | |
| | Partitions | South of Main Entry (sheet A2.1) | 1 | EA | 6 | \$297 | |
| | Partitions | South of Main Entry (sheet A2.1) | 4 | EA | 6 | \$1,188 | |
| | Urinals | South of Main Entry (sheet A2.1) | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | South of Main Entry (sheet A2.1) | 340 | SF | 6 | \$997 | |
| | Walls - Concrete Block | South of Main Entry (sheet A2.1) | 488 | SF | 6 | \$1,431 | |
| | Walls - Structural Glazed Tile | South of Main Entry (sheet A2.1) | 170 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | South of Main Entry (sheet A2.1) | 104 | SF | 7 | \$0 | |
| | Water Closet | South of Main Entry (sheet A2.1) | 4 | EA | 7 | \$0 | |
| | Water Closet | South of Main Entry (sheet A2.1) | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | South of Pool (sheet A2.2) | 287 | SF | 6 | \$993 | |
| | Ceiling - Plaster/Drywall | South of Pool (sheet A2.2) | 287 | SF | 6 | \$993 | |
| | Doors - Wood Doors inclu hw | South of Pool (sheet A2.2) | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | South of Pool (sheet A2.2) | 1 | EA | 6 | \$301 | |
| | | South of Pool (sheet A2.2) | 1 | EA | 6 | \$1,059 | |



Building: Linked Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-------------------------------------|----------|------|------|---------|--|
| Restroc | om | | | | | | |
| | Floor Drain | South of Pool (sheet A2.2) | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | South of Pool (sheet A2.2) | 287 | SF | 6 | \$607 | |
| | Floor - Tile Ceramic/ Porcelain | South of Pool (sheet A2.2) | 287 | SF | 7 | \$0 | |
| | Hand Dryer | South of Pool (sheet A2.2) | 3 | EA | 7 | \$0 | |
| | Hand Dryer | South of Pool (sheet A2.2) | 3 | EA | 7 | \$0 | |
| | Lavatory | South of Pool (sheet A2.2) | 3 | EA | 6 | \$959 | |
| | Lavatory | South of Pool (sheet A2.2) | 3 | EA | 6 | \$959 | |
| | Lighting - Pendent/Surface | South of Pool (sheet A2.2) | 4 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | South of Pool (sheet A2.2) | 3 | EA | 7 | \$0 | |
| | Partitions | South of Pool (sheet A2.2) | 2 | EA | 7 | \$0 | |
| | Partitions | South of Pool (sheet A2.2) | 6 | EA | 7 | \$0 | |
| | Urinals | South of Pool (sheet A2.2) | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | South of Pool (sheet A2.2) | 114 | SF | 6 | \$334 | |
| | Walls - Concrete Block | South of Pool (sheet A2.2) | 114 | SF | 6 | \$334 | |
| | Walls - Structural Glazed Tile | South of Pool (sheet A2.2) | 352 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | South of Pool (sheet A2.2) | 352 | SF | 7 | \$0 | |
| | Water Closet | South of Pool (sheet A2.2) | 6 | EA | 7 | \$0 | |
| | Water Closet | South of Pool (sheet A2.2) | 2 | EA | 6 | \$672 | |
| | Accessories | Womens in Crop Sorting Room (NW) | 132 | SF | 6 | \$1,218 | Toilet paper. |
| | Ceiling - Plaster/Drywall | Womens in Crop Sorting Room (NW) | 132 | SF | 6 | \$457 | |
| | Doors - Steel Doors incl hw | Womens in Crop Sorting Room (NW) | 1 | EA | 6 | \$301 | |
| | Floor Drain | Womens in Crop Sorting Room (NW) | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Womens in Crop Sorting Room (NW) | 132 | SF | 6 | \$279 | |
| | Hand Dryer | Womens in Crop Sorting Room (NW) | 1 | EA | 7 | \$0 | |
| | Lavatory | Womens in Crop Sorting Room (NW) | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Womens in Crop Sorting Room (NW) | 2 | EA | 6 | \$248 | |
| | Partitions | Womens in Crop Sorting Room (NW) | 2 | EA | 6 | \$594 | |
| | Walls - Concrete Block | Womens in Crop Sorting Room (NW) | 237 | SF | 6 | \$695 | |
| | Walls - Structural Glazed Tile | Womens in Crop Sorting Room (NW) | 96 | SF | 6 | \$302 | |
| | Water Closet | Womens in Crop Sorting Room (NW) | 2 | EA | 7 | \$0 | |
| | Accessories | Womens in Show & Exercise Area (SW) | 132 | SF | 6 | \$1,218 | Soap dispenser and toilet paper dispenser. |
| | Ceiling - Plaster/Drywall | Womens in Show & Exercise Area (SW) | 132 | SF | 4 | \$1,988 | Water damage and hole visible. |
| | Doors - Steel Doors incl hw | Womens in Show & Exercise Area (SW) | 1 | EA | 6 | \$301 | |
| | Floor Drain | Womens in Show & Exercise Area (SW) | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Womens in Show & Exercise Area (SW) | 132 | SF | 6 | \$279 | |
| | Hand Dryer | Womens in Show & Exercise Area (SW) | 1 | EA | 7 | \$0 | |
| | Lavatory | Womens in Show & Exercise Area (SW) | 1 | EA | 6 | \$320 | |
| | | | | | | | |



Building: Linked Addition

Category: Rooms (Other Than Classrooms)

| Group Item - Type | Location | Quantity | Unit | Rank | Cost Comments |
|---|-------------------------------------|----------|------|------|---------------|
| Restroom | | | | | |
| Lighting - Pendent/Surface | Womens in Show & Exercise Area (SW) | 2 | EA | 6 | \$248 |
| Partitions | Womens in Show & Exercise Area (SW) | 2 | EA | 7 | \$0 |
| Walls - Concrete Block | Womens in Show & Exercise Area (SW) | 237 | SF | 6 | \$695 |
| Walls - Structural Glazed Tile | Womens in Show & Exercise Area (SW) | 96 | SF | 6 | \$302 |
| Water Closet | Womens in Show & Exercise Area (SW) | 2 | EA | 6 | \$672 |
| Rooms (Other Than Classrooms) Subtotal: | | | | | \$590,594 |

Rooms (Other Than Classrooms) Subtotal:

Building: Linked Addition

Category: Building Interior

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|----------------------------------|----------|------|------|----------|-------------------|
| orridor | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 7,519 | SF | 6 | \$22,580 | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Doors - Steel Doors incl hw | 1st Floor | 6 | EA | 6 | \$1,806 | |
| | Doors - Store Front | 1st Floor | 6 | EA | 6 | \$7,249 | |
| | Doors - Wood Doors include hw | 1st Floor | 32 | EA | 6 | \$9,632 | |
| | Floor - Tile/Sheet | 1st Floor | 9,943 | SF | 6 | \$5,403 | |
| | Lighting - Lay-in | 1st Floor | 90 | EA | 6 | \$10,708 | |
| | Student Lockers - One Tier | 1st Floor | 310 | EA | 6 | \$28,779 | |
| | Walls - Plaster/Drywall | 1st Floor | 2,550 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Floor | 6,000 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 1st flr Mechanical Service rooms | 10 | EA | 7 | \$0 | |
| | Doors - Wood Doors include hw | 1st flr Mechanical Service rooms | 4 | EA | 7 | \$0 | Tele/Elec Closets |
| | Ceiling - Plaster/Drywall | 1st Vestibule Show/Exercise | 104 | SF | 6 | \$644 | |
| | Doors - Side-lite | 1st Vestibule Show/Exercise | 20 | EA | 6 | \$334 | |
| | Doors - Store Front | 1st Vestibule Show/Exercise | 4 | EA | 6 | \$4,833 | |
| | Floor - Concrete | 1st Vestibule Show/Exercise | 104 | SF | 6 | \$55 | |
| | Lighting - Pendent/Surface | 1st Vestibule Show/Exercise | 1 | EA | 6 | \$124 | |
| | Walls - Concrete Block | 1st Vestibule Show/Exercise | 290 | SF | 6 | \$850 | |
| | Ceiling - Exposed | 2nd Floor | 3,762 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 5,502 | SF | 6 | \$16,523 | |
| | Doors - Wood Doors include hw | 2nd Floor | 25 | EA | 7 | \$0 | |
| | Drinking Fountains - Single Water Cooler | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Carpet | 2nd Floor | 445 | SF | 6 | \$948 | |
| | Floor - Tile/Sheet | 2nd Floor | 6,337 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 42 | EA | 7 | \$0 | |



Building: Linked Addition

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------|----------|------|------|----------|---|
| Corrido | r | | | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 48 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 2nd Floor | 205 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 3,552 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 854 | SF | 7 | \$0 | Around columns. |
| | Walls - Structural Glazed Tile | 2nd Floor | 2,340 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | Basement | 2,988 | SF | 6 | \$8,973 | |
| | Doors - Steel Doors incl hw | Basement | 8 | EA | 6 | \$2,408 | |
| | Doors - Steel Doors incl hw | Basement | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors include hw | Basement | 17 | EA | 6 | \$5,117 | |
| | Floor - Tile/Sheet | Basement | 2,988 | SF | 6 | \$1,624 | |
| | Lighting - Lay-in | Basement | 26 | EA | 6 | \$3,093 | |
| | Walls - Concrete Block | Basement | 3,876 | SF | 6 | \$11,362 | |
| | Ceiling - Lay-in | Crop Sorting Hallway | 559 | SF | 5 | \$3,685 | |
| | Doors - Store Front | Crop Sorting Hallway | 2 | EA | 6 | \$2,416 | |
| | Floor - Concrete | Crop Sorting Hallway | 559 | SF | 6 | \$296 | |
| | Lighting - Lay-in | Crop Sorting Hallway | 7 | EA | 6 | \$833 | |
| | Walls - Concrete Block | Crop Sorting Hallway | 641 | SF | 6 | \$1,879 | |
| | Ceiling - Lay-in | Link - 1st Floor | 1,170 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Link - 1st Floor | 4 | EA | 6 | \$1,204 | |
| | Floor - Tile/Sheet | Link - 1st Floor | 1,170 | SF | 6 | \$636 | |
| | Lighting - Lay-in | Link - 1st Floor | 8 | EA | 6 | \$952 | |
| | Walls - Plaster/Drywall | Link - 1st Floor | 1,284 | SF | 6 | \$5,692 | |
| | Ceiling - Plaster/Drywall | Main Entry Vestibule, North | 365 | SF | 6 | \$2,260 | |
| | Doors - Store Front | Main Entry Vestibule, North | 6 | EA | 6 | \$7,249 | |
| | Doors - Transom Window | Main Entry Vestibule, North | 18 | EA | 7 | \$0 | |
| | Floor - Tile Quarry | Main Entry Vestibule, North | 365 | SF | 5 | \$8,461 | |
| | Lighting - Pendent/Surface | Main Entry Vestibule, North | 6 | EA | 6 | \$743 | |
| | Walls - Concrete Block | Main Entry Vestibule, North | 380 | SF | 6 | \$1,114 | |
| | Ceiling - Lay-in | Partial 1st floor | 7,293 | SF | 7 | \$0 | |
| | Drinking Fountains - Single Water Cooler | Partial 1st floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | Partial 1st floor | 7,293 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Partial 1st floor | 74 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | Partial 1st floor | 141 | EA | 7 | \$0 | |
| | Walls - Masonry | Partial 1st floor | 8,896 | SF | 7 | \$0 | Masonry is Decorative CMU |
| | Walls - Plaster/Drywall | Partial 1st floor | 427 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | Show/Exercise Hallway | 559 | SF | 4 | \$6,107 | Rusted ceiling frame, warped tiles, water damage. |
| | Doors - Store Front | Show/Exercise Hallway | 2 | EA | 6 | \$2,416 | |



Building: Linked Addition

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|--------------------------------|----------|------|------|---------|---|
| Corrido | r | | | | | | |
| | Drinking Fountains - Single Water Cooler | Show/Exercise Hallway | 1 | EA | 6 | \$317 | |
| | Floor - Concrete | Show/Exercise Hallway | 559 | SF | 6 | \$296 | |
| | Lighting - Lay-in | Show/Exercise Hallway | 7 | EA | 6 | \$833 | |
| | Student Lockers - One Tier | Show/Exercise Hallway | 23 | EA | 6 | \$2,135 | |
| | Walls - Concrete Block | Show/Exercise Hallway | 620 | SF | 6 | \$1,818 | |
| | Ceiling - Plaster/Drywall | Vestibule near pool | 215 | SF | 6 | \$1,331 | |
| | Doors - Store Front | Vestibule near pool | 4 | EA | 6 | \$4,833 | |
| | Floor - Tile Quarry | Vestibule near pool | 215 | SF | 6 | \$600 | |
| | Lighting - Pendent/Surface | Vestibule near pool | 2 | EA | 6 | \$248 | |
| | Walls - Concrete Block | Vestibule near pool | 380 | SF | 6 | \$1,114 | |
| | Ceiling - Plaster/Drywall | Vestibules, Partial 1st flr | 683 | SF | 7 | \$0 | |
| | Doors - Side-lite | Vestibules, Partial 1st flr | 86 | EA | 7 | \$0 | |
| | Doors - Store Front | Vestibules, Partial 1st flr | 12 | EA | 7 | \$0 | |
| | Doors - Transom Window | Vestibules, Partial 1st flr | 60 | EA | 7 | \$0 | |
| | Floor - Tile Quarry | Vestibules, Partial 1st flr | 683 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Vestibules, Partial 1st flr | 10 | EA | 7 | \$0 | |
| | Walls - Masonry | Vestibules, Partial 1st flr | 720 | SF | 7 | \$0 | |
| Safety | | | | | | | |
| | Security Cameras | Basement | 5 | EA | 7 | \$0 | Only in Service Corridor of Lower Level |
| Stairs | | | | | | | |
| otans | Ceiling - Exposed | Basement North East / Basement | 120 | SF | 6 | \$178 | |
| | Ceiling - Lay-in | Basement North East / Basement | 124 | SF | 6 | \$372 | |
| | Floor - Concrete | Basement North East / Basement | 240 | SF | 6 | \$127 | |
| | Handrails | Basement North East / Basement | 80 | LF | 6 | \$693 | |
| | Lighting - Lay-in | Basement North East / Basement | 6 | EA | 6 | \$714 | |
| | Lighting - Wall Mounted | Basement North East / Basement | 2 | EA | 6 | \$248 | |
| | Stairs - Concrete | Basement North East / Basement | 46 | LF | 6 | \$382 | |
| | Walls - Concrete Block | Basement North East / Basement | 1,500 | SF | 6 | \$4,397 | |
| | Ceiling - Exposed | Basement North West / Basement | 120 | SF | 6 | \$178 | |
| | Ceiling - Lay-in | Basement North West / Basement | 124 | SF | 5 | | Missing tiles. |
| | Floor - Concrete | Basement North West / Basement | 120 | SF | 6 | \$63 | |
| | Handrails | Basement North West / Basement | 54 | LF | 7 | \$0 | |
| | Lighting - Lay-in | Basement North West / Basement | 3 | EA | 6 | \$357 | |
| | Lighting - Wall Mounted | Basement North West / Basement | 1 | EA | 6 | \$124 | |
| | Stairs - Concrete | Basement North West / Basement | 24 | LF | 6 | \$199 | |
| | Walls - Concrete Block | Basement North West / Basement | 1,104 | SF | 6 | | Minor cracks. |
| | | | , | | | . , | |



Building: Linked Addition

Category: Building Interior

| Group | Item - Type | Location Q | | Unit | Rank | Cost | st Comments | | | | |
|--------|-------------------------|---|-------|------|------|---------|--|--|--|--|--|
| Stairs | | | | | | | | | | | |
| | Ceiling - Exposed | Basement South East / Basement | 120 | SF | 6 | \$178 | | | | | |
| | Ceiling - Lay-in | Basement South East / Basement | 124 | SF | 6 | \$372 | | | | | |
| | Floor - Concrete | Basement South East / Basement | 240 | SF | 6 | \$127 | | | | | |
| | Handrails | Basement South East / Basement | 80 | LF | 6 | \$693 | | | | | |
| | Lighting - Lay-in | Basement South East / Basement | 6 | EA | 6 | \$714 | | | | | |
| | Lighting - Wall Mounted | Basement South East / Basement | 2 | EA | 6 | \$248 | | | | | |
| | Stairs - Concrete | Basement South East / Basement | 46 | LF | 6 | \$382 | | | | | |
| | Walls - Concrete Block | Basement South East / Basement | 1,500 | SF | 6 | \$4,397 | | | | | |
| | Ceiling - Exposed | Basement South West / Basement | 120 | SF | 6 | \$178 | | | | | |
| | Ceiling - Lay-in | Basement South West / Basement | 124 | SF | 6 | \$372 | | | | | |
| | Floor - Concrete | Basement South West / Basement | 120 | SF | 6 | \$63 | | | | | |
| | Handrails | Basement South West / Basement | 54 | LF | 6 | \$468 | | | | | |
| | Lighting - Lay-in | Basement South West / Basement | 3 | EA | 6 | \$357 | | | | | |
| | Stairs - Concrete | Basement South West / Basement | 24 | LF | 6 | \$199 | | | | | |
| | Walls - Concrete Block | Basement South West / Basement | 1,104 | SF | 6 | \$3,236 | | | | | |
| | Floor - Rubber Floor | Main Stairs within Main Corridor / 1st Floor | 200 | SF | 6 | \$432 | | | | | |
| | Handrails | Main Stairs within Main Corridor / 1st Floor | 120 | LF | 7 | \$0 | | | | | |
| | Stairs - Rubber | Main Stairs within Main Corridor / 1st Floor | 48 | LF | 6 | \$516 | | | | | |
| | Ceiling - Lay-in | Stair off Main Entry Vestibule | 198 | SF | 7 | \$0 | | | | | |
| | Floor - Concrete | Stair off Main Entry Vestibule | 40 | SF | 7 | \$0 | | | | | |
| | Floor - Tile Quarry | Stair off Main Entry Vestibule | 120 | SF | 7 | \$0 | | | | | |
| | Handrails | Stair off Main Entry Vestibule | 41 | LF | 7 | \$0 | | | | | |
| | Lighting - Lay-in | Stair off Main Entry Vestibule | 3 | EA | 7 | \$0 | | | | | |
| | Lighting - Wall Mounted | Stair off Main Entry Vestibule | 2 | EA | 7 | \$0 | | | | | |
| | Stairs - Concrete | Stair off Main Entry Vestibule | 84 | LF | 7 | \$0 | | | | | |
| | Walls - Concrete Block | Stair off Main Entry Vestibule | 696 | SF | 6 | \$2,040 | Crack in CMU wall in northwest corner of tower | | | | |
| | Walls - Masonry | Stair off Main Entry Vestibule | 696 | SF | 7 | \$0 | Masonry is decorative CMU | | | | |

Building Interior Subtotal:

Total Building Cost

SITE

Category: Site

\$230,476



Chicago High School for Agricultural Sciences

3857 W 111th St Chicago, IL 60655

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---------------------------------------|---------------------------|----------|------|------|-------------|--|
| Athletic | | | | | | | |
| | Metal Bleachers | Northeast field | 40 | LF | 7 | \$0 | |
| | Metal Bleachers | Northwest field | 225 | LF | 7 | \$0 | |
| | Metal Bleachers | Southeast field | 225 | LF | 7 | \$0 | |
| | Metal Bleachers | Southwest field | 225 | LF | 7 | \$0 | |
| | Surface - Natural | Northwest field | 44,100 | SF | 6 | \$36,577 | |
| | Surface - Natural | Southeast field | 125,316 | SF | 6 | \$103,937 | |
| | Surface - Natural | Southwest field | 52,900 | SF | 6 | \$43,875 | |
| | Surface - Synthetic | Northeast field | 19,600 | SF | 6 | \$85,485 | |
| ivil/Dr | ainage | | | | | | |
| | Civil/ Drainage - Bioswale | Entire Site / Site South | 1,200 | SF | 7 | \$0 | |
| | Civil/ Drainage - Catch Basin | Entire Site | 16 | EA | 7 | \$0 | |
| | Civil/ Drainage - Site Manhole | Entire Site | 27 | EA | 7 | \$0 | |
| encin | 3 | | | | | | |
| | Fencing - Chain Link | Entire Site | 7,670 | LF | 6 | \$144,011 | baseball, south field, misc |
| | Fencing - New Standard Ornamental | Entire Site | 44 | LF | 7 | \$0 | beekeeping courtyard |
| | Fencing - Wood Fencing w/ Steel Frame | Entire Site | 2,167 | LF | 6 | \$28,416 | animal pens, wood fencing |
| andsc | ape | | | | | | |
| | Benches | Entire Site | 64 | EA | 6 | \$27,523 | front, courtyards |
| | Irrigation | Entire Site | 2,409,33 | SF | 7 | \$0 | school, farm |
| | Irrigation | Entire Site | 329,376 | SF | 4 | \$1,483,674 | not working |
| | Landscape - Grass | Entire Site | 2,429,36 | SF | 7 | \$0 | surrounding building; south |
| | Landscape - Hardscape- Concrete | Entire Site | 66,583 | SF | 6 | \$343,721 | |
| | Landscape - Hardscape- Pavers | Entire Site / Site - East | 564 | SF | 6 | \$3,194 | children's garden |
| | Parkway trees | Entire Site | 3 | EA | 6 | \$1,980 | stumps |
| | Parkway trees | Entire Site / Site South | 13 | EA | 6 | \$8,581 | along 115th |
| | Planting Beds/ Area | Entire Site | 16,227 | SF | 6 | \$26,685 | |
| | Retaining Wall - Concrete | Entire Site / Courtyard | 230 | SF | 6 | \$5,391 | |
| | Retaining Wall - Masonry | Entire Site | 84 | SF | 6 | \$1,226 | outdoor teaching area- wood retaining wall |
| | Trash Receptacles | Entire Site / Parking Lot | 6 | EA | 7 | \$0 | |
| | Walking Path - Crushed Stone | Entire Site | 53,344 | SF | 5 | \$205,961 | |
| arking | Lot | | | | | | |
| | Concrete Curbs | Entire Site | 2,753 | LF | 6 | | north and south lots |
| | Concrete Curbs | Entire Site | 20 | LF | 4 | \$1,193 | north and south lots-damaged |
| | Interior Plantings | Entire Site | 5 | LF | 6 | \$213 | north and south lots |
| | Surface - Asphalt | Entire Site | 113,204 | SF | 6 | \$273,580 | north and south lots |
| | Surface - Asphalt | Entire Site | 120 | SF | 5 | \$709 | north and south lots- potholes |
| | Trash Enclosure | Entire Site | 714 | SF | 6 | \$0 | south side of building |
| | Vehicular Screening | Entire Site | 316 | LF | 7 | \$0 | north side of north lot |



SITE

| - | ory: Site | | | | | | |
|---------|---|-------------------------------|----------|------|----------|----------|---|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Parking | Lot | | | | | | |
| Sidewa | ks | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 145 | LF | 7 | \$0 | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 7,560 | SF | 6 | \$15,027 | |
| Signage | | | | | | | |
| | Flag Pole - Flag Pole | Entire Site / North Entrances | 1 | EA | 7 | \$0 | |
| | Marquee - Free Standing Back Lighted | Entire Site | 1 | EA | 6 | \$0 | NW entrance to parking lot- wood, no backlighting |
| | Marquee - Free Standing Back lighted w/ LED | Entire Site / North West | 1 | EA | 6 | \$0 | corner of property |
| Site S | ubtotal: | | | \$2 | ,876,312 | | |
| Total | Site Cost | | | | | | |

Campus Total ^{2 3}

\$9,788,474

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------------|-------------------------|------------------|-----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | ł | | | | | | | | | | | | | |
| Computer Lab | Regular Classroom | 1st Floor | 104 | 104 | 1,014 | 1 | 26 | 58 | 215 | 30 | 40 | Ν | Y | Ν |
| Pre School | Library | 1st Floor | 102 | 102 | 1,014 | 1 | 1 | 10 | 215 | 30 | 40 | Ν | Y | Ν |
| Science Classroom | Science Classroom | 1st Floor | 108 | 108 | 1,199 | 1 | 6 | 44 | 375 | | 40 | N | Y | Y |
| Science Lab Level 3 | Science Lab Level 3 | 1st Floor | 107 | 107 | 1,122 | 1 | 9 | 32 | 215 | 30 | 40 | N | Y | Y |
| Special Education | Office | 1st Floor | 101 | 101 | 662 | 1 | 2 | 12 | 137 | 20 | 40 | Ν | Y | Y |
| Special Education | Computer Lab | 1st Floor | 103 | 103 | 994 | 1 | 14 | 22 | 215 | 30 | 40 | N | Y | Y |
| Special Education | Science | 1st Floor | 105 | 105 | 1,014 | 1 | 7 | 18 | 215 | 30 | 40 | Ν | Y | Y |
| Special Education | Other Instructional Use | 1st Floor | 106 | 106 | 1,044 | 1 | 8 | 20 | 215 | 30 | 40 | Ν | Y | Ν |
| Addition | | | | | | | | | | | | | | |
| Computer Lab | Regular Classroom | | 152 | N/A | 930 | 1 | 2 | 27 | 120 | 30 | 40 | Ν | Y | Ν |
| Laboratory/Shop | Laboratory/Shop | | 159 | 159 | 3,050 | 0 | 0 | 54 | 600 | 50 | 40 | N | Y | Ν |
| Regular Classroom | Regular Classroom | | 153 | N/A | 930 | 1 | 2 | 20 | 120 | 30 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 166 | N/A | 920 | 1 | 8 | 44 | 120 | 30 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | | 167 | N/A | 920 | 1 | 22 | 54 | 120 | 30 | 40 | N | Y | Y |
| Special Education | Regular Classroom | | 155 | N/A | 1,196 | 1 | 2 | 36 | 160 | 40 | 40 | Ν | Y | Ν |
| Linked Addition | | | | | | | | | | | | | | |
| Art Room | Other Instructional Use | 1st Floor | 179 | | 1,532 | 0 | 1 | 7 | 968 | 0 | 40 | Ν | N | Ν |
| Computer Lab | Computer Lab | | 121 | 042 | 900 | 1 | 33 | 76 | 0 | 0 | 40 | Ν | N | Ν |
| Fitness Room | Other Instructional Use | | Locker Rm | Drivers Ed | 700 | 0 | 0 | 0 | 0 | 0 | 40 | N | N | Ν |
| Laboratory/Shop | Laboratory/Shop | | 126 | 067 Food Lab | 1,329 | 1 | 3 | 30 | 94 | 47 | 55 | N | N | Ν |
| Laboratory/Shop | Laboratory/Shop | | 127 | | 758 | 2 | 3 | 15 | 94 | 47 | 60 | Ν | N | Ν |
| Laboratory/Shop | Laboratory/Shop | | 128 | | 1,353 | 1 | 8 | 67 | 94 | 47 | 40 | Ν | Y | Y |
| Laboratory/Shop | Laboratory/Shop | 1st Floor | 180 | 330 | 2,222 | 0 | 0 | 18 | 968 | 0 | 40 | Ν | N | Ν |
| Laboratory/Shop | Laboratory/Shop | 1st Floor | 180 Work Room | 131 | 378 | 0 | 0 | 0 | 0 | 0 | 40 | Ν | N | Ν |
| Laboratory/Shop | Laboratory/Shop | 1st Floor | 186 Fish Hatch | 162 | 900 | 0 | 5 | 96 | 47 | 7 | 40 | Ν | N | Ν |
| Laboratory/Shop | Other Instructional Use | 1st Floor | Show & Exercise | 167 | 6,191 | 0 | 0 | 2 | 48 | 0 | 40 | Ν | Y | Ν |
| Other Instructional Use | Other Instructional Use | 1st Floor | 181 Farm Stand | 142 | 889 | 1 | 1 | 16 | 104 | 6 | 50 | Ν | Y | Ν |
| Regular Classroom | Computer Lab | | 120 | 041 | 900 | 1 | 2 | 24 | 94 | 8 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 122 | | 744 | 1 | 8 | 24 | 92 | 6 | 40 | Ν | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 123 | | 744 | 1 | 8 | 24 | 92 | 6 | 40 | Ν | Ν | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 124 | | 744 | 1 | 8 | 24 | 92 | 6 | 40 | N | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 125 | | 744 | 1 | 8 | 24 | 92 | 6 | 40 | Ν | Ν | Y |
| Regular Classroom | Regular Classroom | | 134 | 035 | 716 | 1 | 6 | 16 | 70 | 15 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 183 Crop Sort | 144 | 936 | 1 | 0 | 56 | 103 | 7 | 40 | Ν | Ν | Ν |
| Regular Classroom | Regular Classroom | | 184 Show/Exerc | 166 | 936 | 1 | 10 | 58 | 105 | 7 | 40 | N | Y | Y |



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|---------------------|-------------------------|------------------|-----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Linked Addition | - | • | | | | | | | | | 4 | | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 744 | 1 | 8 | 24 | 92 | 6 | 40 | Ν | N | Y |
| Regular Classroom | Regular Classroom | | 202 | 202 | 744 | 1 | 8 | 24 | 92 | 6 | 40 | Ν | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 744 | 1 | 8 | 24 | 92 | 6 | 40 | N | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 744 | 1 | 8 | 24 | 96 | 6 | 40 | Ν | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | | 802 | 1 | 8 | 20 | 92 | 6 | 40 | Ν | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | | 734 | 1 | 8 | 20 | 92 | 6 | 40 | N | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | | 734 | 1 | 8 | 20 | 92 | 6 | 40 | Ν | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | | 802 | 1 | 8 | 20 | 92 | 6 | 40 | N | N | Y |
| Science Classroom | Science Classroom | 2nd Floor | 211 | 221 | 862 | 1 | 8 | 32 | 92 | 6 | 40 | Ν | Y | Y |
| Science Classroom | Science Classroom | 2nd Floor | 214 | 224 | 1,080 | 1 | 8 | 24 | 92 | 6 | 40 | Ν | N | Y |
| Science Classroom | Science Classroom | 2nd Floor | 215 | 225 | 837 | 1 | 12 | 28 | 92 | 6 | 40 | Ν | N | Y |
| Science Lab Level 1 | Science Lab Level 1 | 2nd Floor | 209 | 217 | 1,478 | 1 | 2 | 44 | 92 | 6 | 40 | Ν | N | Y |
| Science Lab Level 2 | Science Lab Level 2 | 2nd Floor | 210 | 220 | 1,478 | 1 | 2 | 44 | 92 | 6 | 40 | Ν | N | Y |
| Special Program | Other Instructional Use | 1st Floor | Crop Sorting Rm | 147 | 6,076 | 0 | 0 | 0 | 0 | 0 | 40 | Ν | N | Ν |