

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1975	3	186,327	\$9,434,567
Fine Arts Building	1975	1	27,456	\$2,040,454
Linked Addition-Athletic Building	1975	1	52,621	\$3,294,286
SITE				\$1,060,168
Campus Total			266,404	\$15,829,474

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
	Entrance Control - Audio and Video	#2- SW	1	EA	6	\$702	
	Entrance Control - Audio and Video	#3- NE	1	EA	6	\$702	
	Exterior Doors - Exterior FRP Door	#1- SE- Main	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#2- SW	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#3- NE	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#4- NW	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#9- SW- Exit (Rm 115)	1	EA	6	\$631	
	Exterior Doors - Exterior Steel Door	#23- Basement Dock Door	1	EA	5	\$1,341	broken push bar
	Exterior Doors - Overhead Rolling/ Garage Door	#22- Basement Dock Door	1	EA	6	\$1,433	
	Exterior Doors - Side lite	#2- SW	4	EA	6	\$1,253	
	Exterior Doors - Side lite	#3- NE	4	EA	6	\$1,253	
	Exterior Doors - Side lite	#4- NW	4	EA	6	\$1,253	
	Exterior Doors - Side lite	#9- SW- Exit (Rm 115)	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#2- SW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#3- NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#4- NW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#9- SW- Exit (Rm 115)	1	EA	6	\$313	
	Exterior Stairs - Concrete	#3- NE	540	LF	6	\$44,154	

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
	Power Door Operator and Controls	#2- SW	1	EA	6	\$0	
	Power Door Operator and Controls	#3- NE	1	EA	6	\$0	
	Stair Handrail - Steel_Stair Handrail	#3- NE	80	LF	4	\$12,019	missing
Foundation							
	Foundation - Concrete	Entire Building	4	LF	5	\$0	Seepage, cracks
	Foundation - Concrete	Entire Building	5	LF	5	\$0	seepage
	Foundation - Concrete	Entire Building	1,257	LF	7	\$0	
	Superstructure - Concrete	Entire Building	20	SF	5	\$0	spalling, cracks, seepage
	Superstructure - Concrete	Entire Building	184,751	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,556	SF	7	\$0	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	\$3,465	
Roof System							
	Coping - Metal	Dock entrance roof	294	LF	6	\$9,443	
	Coping - Metal	Main Roof	972	LF	6	\$31,219	rust
	Downspouts - Interior Downspouts	Dock entrance roof	36	LF	6	\$1,196	
	Downspouts - Interior Downspouts	Main Roof	660	LF	6	\$21,934	
	Parapet - 16" - 30" Height	Main Roof	972	LF	6	\$38,835	
	Parapet - Parapet < 16" Height	Dock entrance roof	294	LF	6	\$6,264	
	Roof Structure - Concrete	Main Roof	58,002	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Dock entrance roof	3,340	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Main Roof	58,002	SF	4	\$1,625,680	blisters, open flashing - solar panels are present on the roof
	Roof - Modified Bitumen	Dock entrance roof	3,340	SF	6	\$31,427	some water ponding
Walls							
	Exterior Walls - Brick	Entire Building	25,860	SF	5	\$459,659	caulk wall to sidewalk abutments to avoid water intrusion.
	Exterior Walls - Brick	Entire Building / Façade- SE	3	SF	4	\$494	spalling, missing
Windows							
	Curtain wall - Glazed Double Pane	Entire Building	4,299	SF	5	\$287,276	poor seals & glazing
	Curtain wall - Windows	Entire Building	17,822	SF	5	\$1,135,122	poor seals & glazing
	Curtain wall - Windows	Entire Building	76	SF	5	\$0	broken panes
	Lintels - Steel	Entire Building	26	LF	6	\$755	

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Building Exterior Subtotal:						\$3,724,443	

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

Emergency System

	Automatic Transfer Switch	Basement / Electrical Room	1	EA	6	\$408	
	Automatic Transfer Switch	Basement / Electrical Room	1	EA	6	\$408	
	Automatic Transfer Switch	Basement / Mechanical Room	1	EA	6	\$408	
	Automatic Transfer Switch	Basement / Mechanical Room	1	EA	6	\$408	
	Emergency Battery Packs - Lunchrooms	3rd Floor	6	EA	6	\$1,215	Location: Beta Lunchroom
	Emergency Generator- Indoor- Natural Gas - 101 - 150 KW	Basement	1	EA	7	\$0	
	Exit Signs - Corridors and Stairs	Entire Building	35	EA	6	\$5,241	
	Exit Signs - Lunchroom	Entire Building / 3rd Floor	4	EA	6	\$599	Location: Gamma Lunchroom
	Exit Signs - Multipurpose Room	Entire Building / 1st Floor	2	EA	6	\$299	
	Exit Signs - Multipurpose Room	Entire Building / 3rd Floor	4	EA	6	\$599	Location: Library (Room 222)
	Security System - CCTV	Entire Building	186,327	SF	6	\$55,954	
	Security System - Intrusion Detection	Entire Building	186,327	SF	6	\$47,961	

Main Service

	Independent Electrical Service for emergency power	Basement	1	EA	6	\$2,921	Location: Main Electrical Room (Standing Water Problems)
	Independent Electrical Service for emergency power	Basement	2	EA	7	\$0	Location: Main Electrical Room (Standing Water Problems)
	Main Electrical Service - 2000 A 277/480/3PH	Electrical Room	3	EA	6	\$25,985	
	PA System	Entire Building	186,327	SF	6	\$61,283	Location: Main Office (Serves all three buildings)

Power Distribution

	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Room 115A
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Room 113
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Classroom 214
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Electrical Closet
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Alpha Lunchroom
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Electrical Closet
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Gamma Lunchroom
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Room 301
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Room 302

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution							
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Room 304
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Room 305
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Gamma Lunchroom
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Gamma Lunchroom
	Lighting and Power Panels - 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Electrical Closet
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Kitchen
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Room
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Main Electrical Room (Standing Water Problems)
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Main Electrical Room (Standing Water Problems)
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Electrical Closet
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Electrical Closet
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Room 114
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: MDF Room 116
	Lighting and Power Panels - Above 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Electrical Closet
	Lighting and Power Panels - Above 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Electrical Closet
	Lighting and Power Panels - Above 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Gamma Serving Area
	Lighting and Power Panels - Above 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Gamma Serving Area
	Lighting and Power Panels - Above 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Electrical Closet
	Lighting and Power Panels - Above 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Gamma Lunchroom
	Lighting and Power Panels - Above 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Electrical Closet
	Lighting and Power Panels - Above 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Kitchen
	Lighting and Power Panels - Above 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Room
	Lighting and Power Panels - Above 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Electrical Closet
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Mechanical Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Main Electrical Room (Standing Water Problems)
	Main Distribution Panels - 400 - 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Main Electrical Room (Standing Water Problems)

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution							
	Main Distribution Panels - Greater than 600 amp	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Main Distribution Panels - Greater than 600 amp	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Main Distribution Panels - Greater than 600 amp	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Main Distribution Panels - Greater than 600 amp	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Main Distribution Panels - Greater than 600 amp	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Electrical Closet
	Main Distribution Panels - Greater than 600 amp	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Electrical Closet
	Main Distribution Panels - Greater than 600 amp	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Electrical Closet
	Main Distribution Panels - Greater than 600 amp	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Electrical Closet
	Main Distribution Panels - Greater than 600 amp	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Electrical Closet
	Main Distribution Panels - Greater than 600 amp	Entire Building / 3rd Floor	1	EA	4	\$21,104	Location: Electrical Closet (Water Damaged & Rusting)
	Main Distribution Panels - Greater than 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Main Electrical Room (Standing Water Problems)
	Main Distribution Panels - Greater than 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Kitchen
	Main Distribution Panels - Greater than 600 amp	Entire Building / Basement	1	EA	7	\$0	Location: Main Electrical Room (Standing Water Problems)
	Main Distribution Panels - Greater than 600 amp	Entire Building / Basement	1	EA	4	\$21,104	Location: Electrical Room
	Transformers - 277/480 - 120/208	Entire Building / 1st Floor	1	EA	6	\$1,265	Location: Main Electrical Room
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Main Electrical Room (Standing Water Problems)
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Electrical Room
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Main Electrical Room (Standing Water Problems)
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Main Electrical Room (Standing Water Problems)
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Main Electrical Room (Standing Water Problems)
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Electrical Room
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Main Electrical Room (Standing Water Problems)
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Electrical Room
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Main Electrical Room (Standing Water Problems)
Electrical System Subtotal:						\$258,548	

Building: Main

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

Building: Main

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm							
	Fire Alarm Panel	1st Floor	1	EA	6	\$6,406	Serves & links all three buildings (Location: Main Building)
	Fire Alarm Strobe Lights	1st Floor / Entire Building	186,327	SF	6	\$66,612	
	Fire Alarm_System	1st Floor / Entire Building	186,327	SF	6	\$90,592	
	Fire Pump Controller	1st Floor / Basement	1	EA	6	\$1,823	Also serves the Fine Arts and Athletic Building Emergency Run set in the: "OFF Position"
Pump Room Assembly							
	Fire Pump - 25-50 hp	Basement	1	EA	5	\$8,163	Also serves the Fine Arts and Athletic Building Pump Leaking, Drain Piping Corroded & Not Properly Supported from Pump to Floor Drain
	Jockey Pump	Basement	1	EA	4	\$5,981	Also serves the Fine Arts and Athletic Building Piping is Corroded & in "Poor Condition"
Sprinkler System							
	Sprinkler Heads	Entire Building	186,327	SF	6	\$0	
	Sprinkler Piping	Entire Building	186,327	SF	6	\$34,638	
	Wet Sprinkler System	Entire Building	186,327	SF	6	\$47,961	
Safty System Subtotal:						\$262,176	

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Conditioning							
	Condensing Unit- Ground Mounted - 5-10 tons	Basement	2	EA	6	\$6,667	Location: Mechanical Room
	Condensing Unit- Roof Mounted - Less than 5 tons	Main Roof	1	EA	6	\$3,334	
Air Handling Systems							
	Air Handling Unit- Built Up- Single Zone- Hot Water Coils - 4000 - 8000 cfm	Basement	1	EA	6	\$3,321	Location: Mechanical Room
	Air Handling Unit- Built Up- Single Zone- Hot Water Coils - 4000 - 8000 cfm	Basement	1	EA	6	\$3,321	Location: Mechanical Room
	Air Handling Unit- Built Up- Single Zone- Hot Water Coils - 4000 - 8000 cfm	Basement	1	EA	6	\$3,321	Location: Mechanical Room
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils- - 6000-10000 cfm	Basement	1	EA	5	\$42,727	Location: Mechanical Room
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils- - 6000-10000 cfm	Basement	1	EA	5	\$42,727	Location: Mechanical Room
	Air Handling Unit- Package Single Zone- Indoor- Daul Temperature Coils- - Less than 6000 cfm	Basement / 1st Floor	1	EA	4	\$118,207	Location: Mechanical Room (Evaporator Coil & Filter Clogged Clean & Replace Filter)

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Handling Systems							
	Air Intake	Basement / Roof	3	EA	6	\$17,294	
	Air Intake	Basement / Roof	2	EA	6	\$11,529	
	Auxiliaries - 4000 - 8000 cfm	Basement	1	EA	6	\$3,321	Location: Mechanical Room
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Basement	1	EA	6	\$1,857	Location: Mechanical Room
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Basement	1	EA	6	\$1,857	Location: Mechanical Room
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement / Entire Building	200	LF	7	\$0	Location: Mechanical Room Serves: HU1 to HU2
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 31 - 45 tons	Roof	1	EA	6	\$2,792	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards & Equipment Doors Missing
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Handling Systems							
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
Boiler Systems							
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	1	EA	6	\$2,046	
	Chemical Pot Feeder	Boiler Room	1	EA	6	\$725	
	Combustion Dampers	Boiler Room	1	EA	6	\$409	
	Hot Water Pump	Boiler Room	1	EA	6	\$374	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	6	\$998	
Gas Booster							
	Gas Booster	Basement	2	EA	4	\$180,404	Location: Mechanical Room
Heating Devices							
	Cabinet Heaters - With Electric Coil	1st Floor and Basement / Basement	1	EA	4	\$3,360	Location: Mechanical Room
	Cabinet Heaters - With Hot Water Coil	1st Floor and Basement / 1st Floor	2	EA	4	\$7,677	
	Duct Heater - Electric	Basement	2		6	\$855	Location: Mechanical Room
	Fin Tube - Hot Water	Basement	300	LF	6	\$2,831	
Mechanical Plumbing							
	Hydronic Supply and Return - Steel	1st Floor	500	LF	6	\$38,388	
Temperature Control							
	DDC System	Entire Building	186,327	SF	5	\$306,415	
	Thermostats - Pneumatic	Entire Building	100	EA	6	\$0	
Unit Ventilation							
	Unit Ventilators- Ceiling Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Basement	1	EA	6	\$1,248	Location: Elevator Room
Ventilation							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	7	\$0	Garage Ventilation

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Ventilation							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	4	\$6,392	Units Corroded, Seals deteriorating, soft metal & Ripped expansion joint (No Operational)
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	6	\$592	Units Corroded, Seals deteriorating, soft metal & Ripped expansion joint
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	4	EA	7	\$0	Serves four Lab Exhaust Hood
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	6	\$592	Units Corroded, Seals deteriorating, soft metal & Ripped expansion joint
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	6	\$592	Units Corroded, Seals deteriorating, soft metal & Ripped expansion joint
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	6	\$592	Units Corroded, Seals deteriorating, soft metal & Ripped expansion joint
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	7	\$0	
	Lab Exhaust Hood	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Science Lab 242
	Lab Exhaust Hood	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Science Lab 319
	Lab Exhaust Hood	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Science Lab 314A
	Lab Exhaust Hood	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Science Lab 316A
	Roof Mounted Duct Work	Entire Building / Roof	80	LF	6	\$30,322	Attached to four Lab Exhaust fans
	Type I Exhaust Hood- Culinary Arts	Entire Building / 2nd Floor	1	EA	6	\$1,248	Location: Alpha Commons Serving Area
	Type I Exhaust Hood- Culinary Arts	Entire Building / 3rd Floor	1	EA	6	\$1,248	Location: Gamma Commons Serving Area
	Type I Exhaust Hood- Culinary Arts	Entire Building / 3rd Floor	1	EA	6	\$1,248	Location: Beta Commons Serving Area
	Type I Exhaust Hood- Kitchen	Entire Building / Basement	4	EA	6	\$4,991	Location: Kitchen
	Type II Exhaust Hood- Warming Kitchen	Entire Building / 3rd Floor	1	EA	6	\$920	Location: Beta Commons Serving Area

Mechanical System Subtotal:

\$902,002

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Water							
	Electric Heater - Greater than 50 KW	Basement	2	EA	6	\$1,364	Location: Mechanical Room (Leaking)

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Water							
	Hot Water Storage Tank_Electric - 501 - 1000 Gallons	Basement	1	EA	6	\$678	Location: Mechanical Room
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	186,327	SF	7	\$0	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	186,327	SF	6	\$45,296	
	Domestic Piping-Cold Water Risers	Entire Building	186,327	SF	6	\$34,638	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	186,327	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	186,327	SF	6	\$34,638	
	Domestic Piping-Hot Water Return Lines	Entire Building	186,327	SF	6	\$26,645	
	Domestic Piping-Hot Water Return Risers	Entire Building	186,327	SF	7	\$0	
	Sanitary Piping	Entire Building	186,327	SF	6	\$170,526	
	Storm Piping	Entire Building	186,327	SF	6	\$162,533	
	Vent Piping	Entire Building	186,327	SF	6	\$125,230	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	6	\$1,977	Location: Mechanical Room
	Pumps - Ejector-Duplex	Basement	1	EA	6	\$1,387	Location: Mechanical Room
	Pumps - Sump-Duplex	Basement	2	EA	6	\$2,774	Location: Mechanical Room
Plumbing System Subtotal:						\$607,688	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #001 (Vacant)							
	Ceiling - Lay-in	1st Floor	673	SF	6	\$2,021	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	673	SF	6	\$1,472	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	1	EA	6	\$124	open wiring box
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	810	SF	6	\$2,236	
Classroom #003 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	785	SF	6	\$2,357	
	Doors - Steel Doors incl hw	1st Floor	1	EA	5	\$1,174	door frame is out of square & is very difficult to open/close.
	Floor - Tile	1st Floor	785	SF	6	\$1,718	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #003 (Regular Classroom)							
	Lighting - Lay-in	1st Floor	15	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Concrete Block	1st Floor	562	SF	6	\$1,648	
	Walls - Plaster/Drywall	1st Floor	563	SF	6	\$1,554	
Classroom #1004 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	778	SF	6	\$2,336	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	778	SF	6	\$1,702	
	Lighting - Lay-in	1st Floor	15	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Metal Panel	1st Floor	490	SF	6	\$3,658	
	Walls - Plaster/Drywall	1st Floor	610	SF	6	\$1,684	20 SqFt of wall is gouged
Classroom #1005 (Computer Lab)							
	Ceiling - Lay-in	1st Floor	570	SF	6	\$1,712	
	Doors - Side-lite	1st Floor	18	SF	6	\$301	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Doors - Transom Window	1st Floor	22	SF	6	\$372	
	Floor - Tile	1st Floor	570	SF	6	\$1,247	
	Lighting - Lay-in	1st Floor	11	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Metal Panel	1st Floor	985	SF	6	\$7,353	
Classroom #101A (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	673	SF	6	\$2,021	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	673	SF	6	\$1,472	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	18	LF	7	\$0	
	Walls - Concrete Block	1st Floor	280	SF	6	\$821	
	Walls - Plaster/Drywall	1st Floor	758	SF	6	\$2,092	
Classroom #103 (Laboratory/Shop)							
	Ceiling - Lay-in	1st Floor	1,300	SF	6	\$3,904	
	Doors - Side-lite	1st Floor	62	SF	6	\$1,036	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,300	SF	6	\$2,844	
	Lighting - Lay-in	1st Floor	35	EA	7	\$0	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #103 (Laboratory/Shop)							
	Walls - Metal Panel	1st Floor	1,823	SF	6	\$13,608	
Classroom #106 (Science)							
	Casework	1st Floor	25	LF	6	\$631	
	Ceiling - Lay-in	1st Floor	1,170	SF	6	\$3,514	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Eye Wash Station	1st Floor	1	EA	6	\$336	
	Floor - Tile	1st Floor	1,170	SF	6	\$2,560	
	Fume Hood	1st Floor	1	EA	6	\$816	
	Gas Line	1st Floor	3	EA	6	\$1,527	
	Lighting - Lay-in	1st Floor	47	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Science Lab Shower	1st Floor	1	EA	6	\$379	
	Storage/ Closet	1st Floor	480	SF	6	\$3,480	106-A is 137SqFt, 106-B is 157SqFt, Unmarked Storage room designed to shared with Rm125 is 186SqFt
	Walls - Concrete Block	1st Floor	1,385	SF	6	\$4,060	
	Work Sink	1st Floor	9	EA	5	\$13,570	7 inside classroom & 1 inside unmarked storage room. All have no faucet or broken handles. 1 sink inside 106-A is out of order.
	Work Sink	1st Floor	2	EA	6	\$758	
Classroom #107A (Office)							
	Ceiling - Lay-in	1st Floor	475	SF	6	\$1,426	
	Chalk Board	1st Floor	6	LF	4	\$551	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	475	SF	6	\$1,039	
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Concrete Block	1st Floor	395	SF	6	\$1,158	
	Walls - Masonry	1st Floor	246	SF	6	\$774	
	Walls - Metal Panel	1st Floor	246	SF	6	\$1,836	
Classroom #110A (Counseling Room)							
	Ceiling - Lay-in	1st Floor	723	SF	6	\$2,171	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	723	SF	6	\$1,582	
	Lighting - Lay-in	1st Floor	27	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #110A (Counseling Room)							
	Walls - Concrete Block	1st Floor	1,025	SF	6	\$3,005	
Classroom #112 (Special Program)							
	AC Units	1st Floor	1	EA	6	\$496	
	Ceiling - Lay-in	1st Floor	394	SF	6	\$1,183	
	Ceiling - Splined	1st Floor	1,111	SF	6	\$906	
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	\$903	
	Floor - Tile	1st Floor	1,505	SF	6	\$3,293	
	Lighting - Lay-in	1st Floor	18	EA	7	\$0	recessed cans
	Walls - Concrete Block	1st Floor	2,498	SF	6	\$7,323	
	Walls - Plaster/Drywall	1st Floor	398	SF	6	\$1,098	
Classroom #113 (Special Program)							
	Casework	1st Floor	6	LF	6	\$152	
	Ceiling - Lay-in	1st Floor	1,498	SF	6	\$4,498	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	1,498	SF	6	\$3,277	
	Lighting - Lay-in	1st Floor	13	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	1	SF	6	\$7	
	Walls - Concrete Block	1st Floor	610	SF	6	\$1,788	
	Walls - Metal Panel	1st Floor	490	SF	6	\$3,658	
	Walls - Plaster/Drywall	1st Floor	490	SF	6	\$1,352	
	Work Sink	1st Floor	2	EA	6	\$758	
Classroom #114B (Other Instructional Use)							
	Casework	1st Floor	6	LF	6	\$152	
	Ceiling - Lay-in	1st Floor	1,477	SF	6	\$4,435	
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	\$903	1 door won't close all the way.
	Doors - Transom Window	1st Floor	6	SF	6	\$102	
	Floor - Tile	1st Floor	1,477	SF	6	\$3,232	
	Lighting - Lay-in	1st Floor	44	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	138	SF	6	\$1,001	
	Walls - Concrete Block	1st Floor	770	SF	6	\$2,257	
	Walls - Metal Panel	1st Floor	770	SF	6	\$5,748	
	Walls - Plaster/Drywall	1st Floor	160	SF	6	\$442	
	Work Sink	1st Floor	2	EA	6	\$758	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #114B (Other Instructional Use)							
Classroom #115A (Computer Lab)							
	Ceiling - Lay-in	1st Floor	900	SF	6	\$2,703	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	2	SF	5	\$12	damaged
	Floor - Tile	1st Floor	898	SF	6	\$1,965	
	Lighting - Lay-in	1st Floor	36	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Concrete Block	1st Floor	6	SF	5	\$85	damaged
	Walls - Concrete Block	1st Floor	1,214	SF	6	\$3,559	
Classroom #115B (Other Instructional Use)							
	Ceiling - Lay-in	1st Floor	900	SF	6	\$2,703	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	900	SF	6	\$1,969	
	Lighting - Lay-in	1st Floor	33	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Concrete Block	1st Floor	598	SF	6	\$1,753	
	Walls - Plaster/Drywall	1st Floor	598	SF	6	\$1,650	
Classroom #116A (Vacant)							
	Ceiling - Lay-in	1st Floor	690	SF	6	\$2,072	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Doors - Transom Window	1st Floor	4	SF	6	\$68	
	Floor - Tile	1st Floor	690	SF	6	\$1,510	
	Lighting - Lay-in	1st Floor	27	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	1	EA	6	\$124	exposed wiring in open box & 1 cover plate is broken
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	158	SF	6	\$1,146	
	Walls - Concrete Block	1st Floor	12	SF	5	\$169	cracked
	Walls - Concrete Block	1st Floor	600	SF	6	\$1,759	
	Walls - Metal Panel	1st Floor	278	SF	6	\$2,075	
	Walls - Plaster/Drywall	1st Floor	278	SF	6	\$767	
Classroom #116B (Other Instructional Use)							
	Ceiling - Lay-in	1st Floor	870	SF	6	\$2,613	
	Doors - Side-lite	1st Floor	36	SF	6	\$602	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #116B (Other Instructional Use)							
	Doors - Transom Window	1st Floor	7	SF	6	\$119	
	Floor - Tile	1st Floor	870	SF	6	\$1,903	
	Lighting - Lay-in	1st Floor	33	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	1	EA	6	\$124	open circuit box- exposed wiring
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Concrete Block	1st Floor	580	SF	6	\$1,700	
	Walls - Metal Panel	1st Floor	298	SF	6	\$2,224	
	Walls - Plaster/Drywall	1st Floor	298	SF	6	\$822	
Classroom #117 (Special Program)							
	Ceiling - Lay-in	1st Floor	1,429	SF	6	\$4,291	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
	Doors - Transom Window	1st Floor	3	SF	6	\$51	
	Floor - Tile	1st Floor	1,429	SF	6	\$3,127	
	Lighting - Lay-in	1st Floor	53	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,340	SF	6	\$3,928	
	Walls - Metal Panel	1st Floor	220	SF	6	\$1,642	
Classroom #118 (Art Room)							
	Casework	1st Floor	63	LF	6	\$1,591	
	Ceiling - Lay-in	1st Floor	870	SF	6	\$2,613	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	870	SF	6	\$1,903	
	Lighting - Lay-in	1st Floor	18	EA	7	\$0	
	Marker Board	1st Floor	6	LF	6	\$129	
	Storage/ Closet	1st Floor	49	SF	6	\$355	
	Walls - Concrete Block	1st Floor	902	SF	6	\$2,644	
	Walls - Metal Panel	1st Floor	289	SF	6	\$2,157	
	Work Sink	1st Floor	2	EA	6	\$758	
Classroom #119 (Regular Classroom)							
	Casework	1st Floor	35	LF	6	\$884	
	Ceiling - Lay-in	1st Floor	778	SF	6	\$2,336	
	Chalk Board	1st Floor	5	LF	6	\$112	
	Doors - Side-lite	1st Floor	34	SF	6	\$568	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	778	SF	6	\$1,702	
	Lighting - Lay-in	1st Floor	15	EA	7	\$0	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #119 (Regular Classroom)							
	Marker Board	1st Floor	5	LF	7	\$0	
	Storage/ Closet	1st Floor	42	SF	6	\$305	
	Walls - Concrete Block	1st Floor	870	SF	6	\$2,550	
	Walls - Metal Panel	1st Floor	250	SF	6	\$1,866	
	Work Sink	1st Floor	2	EA	5	\$3,016	1 sink not draining & the other is missing a handle on faucet
Classroom #120 (Store Room)							
	Casework	1st Floor	48	LF	6	\$1,212	
	Ceiling - Lay-in	1st Floor	778	SF	6	\$2,336	
	Chalk Board	1st Floor	6	LF	4	\$551	
	Doors - Side-lite	1st Floor	45	SF	6	\$752	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Doors - Transom Window	1st Floor	15	SF	6	\$254	
	Floor - Tile	1st Floor	778	SF	6	\$1,702	
	Kiln	1st Floor	3	EA	6	\$6,962	
	Lighting - Lay-in	1st Floor	15	EA	7	\$0	
	Walls - Concrete Block	1st Floor	616	SF	6	\$1,806	
	Walls - Metal Panel	1st Floor	500	SF	6	\$3,732	
	Work Sink	1st Floor	2	EA	6	\$758	
Classroom #121 (Computer Lab)							
	Ceiling - Lay-in	1st Floor	1,214	SF	6	\$3,646	
	Doors - Side-lite	1st Floor	7	SF	6	\$117	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,214	SF	6	\$2,656	
	Lighting - Pendent/Surface	1st Floor	19	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Concrete Block	1st Floor	706	SF	6	\$2,070	
	Walls - Plaster/Drywall	1st Floor	764	SF	6	\$2,109	
Classroom #202 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	755	SF	6	\$2,267	
	Doors - Side-lite	2nd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	34	SF	6	\$576	
	Floor - Tile	2nd Floor	755	SF	6	\$1,652	
	Lighting - Lay-in	2nd Floor	13	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #202 (Regular Classroom)							
	Walls - Concrete Block	2nd Floor	93	SF	6	\$273	
	Walls - Metal Panel	2nd Floor	868	SF	6	\$6,479	
Classroom #203 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	771	SF	6	\$2,315	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	771	SF	6	\$1,687	
	Lighting - Lay-in	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	9	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	216	SF	6	\$633	
	Walls - Concrete Block	2nd Floor	3	SF	5	\$42	vertical crack at exterior wall, leaks in heavy rain
	Walls - Metal Panel	2nd Floor	560	SF	6	\$4,180	
Classroom #204 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	759	SF	6	\$2,279	
	Doors - Side-lite	2nd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	50	SF	6	\$847	
	Floor - Tile	2nd Floor	759	SF	6	\$1,661	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	90	SF	6	\$264	
	Walls - Concrete Block	2nd Floor	3	SF	5	\$42	vertical crack at exterior wall
	Walls - Metal Panel	2nd Floor	874	SF	6	\$6,524	
Classroom #205 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	757	SF	6	\$2,273	
	Doors - Side-lite	2nd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	42	SF	6	\$711	
	Floor - Tile	2nd Floor	757	SF	6	\$1,656	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	45	SF	6	\$132	
	Walls - Metal Panel	2nd Floor	965	SF	6	\$7,203	
Classroom #206 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	759	SF	6	\$2,279	
	Doors - Side-lite	2nd Floor	10	SF	6	\$167	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #206 (Regular Classroom)							
	Doors - Steel Doors incl hw	2nd Floor	1	EA	5	\$1,174	doesn't stay locked
	Doors - Transom Window	2nd Floor	42	SF	6	\$711	
	Floor - Tile	2nd Floor	759	SF	6	\$1,661	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	88	SF	6	\$258	
	Walls - Metal Panel	2nd Floor	869	SF	6	\$6,487	
Classroom #207 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	759	SF	6	\$2,279	
	Doors - Side-lite	2nd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	5	\$1,174	doesn't stay shut, welded steel plate for latch
	Doors - Transom Window	2nd Floor	42	SF	6	\$711	
	Floor - Tile	2nd Floor	759	SF	6	\$1,661	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	lamps being changed
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	88	SF	6	\$258	
	Walls - Metal Panel	2nd Floor	863	SF	6	\$6,442	
Classroom #208 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	757	SF	6	\$2,273	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	757	SF	6	\$1,656	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	863	SF	6	\$6,442	
Classroom #209 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	757	SF	6	\$2,273	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	757	SF	6	\$1,656	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #209 (Regular Classroom)							
	Walls - Metal Panel	3rd Floor	875	SF	6	\$6,532	
Classroom #210/211 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	624	SF	6	\$1,874	
	Doors - Side-lite	2nd Floor	196	SF	6	\$3,276	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	
	Floor - Tile	2nd Floor	624	SF	6	\$1,365	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	190	SF	6	\$557	
	Walls - Metal Panel	2nd Floor	510	SF	6	\$3,807	
Classroom #212 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	455	SF	6	\$1,366	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	20	SF	6	\$339	
	Floor - Tile	3rd Floor	455	SF	6	\$995	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	14	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	52	SF	6	\$152	
	Walls - Metal Panel	3rd Floor	770	SF	6	\$5,748	
Classroom #213 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	439	SF	6	\$1,318	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	439	SF	6	\$960	
	Lighting - Lay-in	2nd Floor	8	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Metal Panel	2nd Floor	894	SF	6	\$6,673	
	Work Sink	2nd Floor	1	EA	6	\$379	
Classroom #214 (Computer Lab)							
	Ceiling - Lay-in	2nd Floor	811	SF	6	\$2,435	
	Doors - Side-lite	2nd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	5	\$1,174	doesn't stay shut / welded steel plate to latch
	Doors - Transom Window	2nd Floor	10	SF	6	\$169	
	Floor - Tile	2nd Floor	811	SF	6	\$1,774	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #214 (Computer Lab)							
	Lighting - Lay-in	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	106	SF	6	\$311	
	Walls - Metal Panel	2nd Floor	910	SF	6	\$6,793	
Classroom #215 (Vacant)							
	Ceiling - Lay-in	2nd Floor	751	SF	6	\$2,255	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	
	Floor - Tile	2nd Floor	751	SF	6	\$1,643	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	88	SF	6	\$258	
	Walls - Metal Panel	2nd Floor	858	SF	6	\$6,405	
Classroom #216 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	441	SF	6	\$1,324	
	Chalk Board	2nd Floor	5	LF	4	\$459	
	Doors - Side-lite	2nd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	10	SF	6	\$169	
	Floor - Tile	2nd Floor	441	SF	6	\$965	
	Lighting - Lay-in	2nd Floor	9	EA	7	\$0	
	Marker Board	2nd Floor	11	LF	7	\$0	
	Walls - Metal Panel	2nd Floor	892	SF	6	\$6,658	
Classroom #217 (Computer Lab)							
	Ceiling - Lay-in	2nd Floor	1,360	SF	6	\$4,084	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	1,360	SF	6	\$2,976	
	Lighting - Lay-in	2nd Floor	48	EA	6	\$5,711	
	Walls - Concrete Block	2nd Floor	540	SF	6	\$1,583	
	Walls - Metal Panel	2nd Floor	792	SF	6	\$5,912	
Classroom #218 (Computer Lab)							
	Ceiling - Lay-in	2nd Floor	1,257	SF	6	\$3,775	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	1,257	SF	6	\$2,750	
	Lighting - Lay-in	2nd Floor	24	EA	7	\$0	18 floor outlets damaged

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #218 (Computer Lab)							
	Marker Board	2nd Floor	9	LF	7	\$0	
	Storage/ Closet	2nd Floor	113	SF	6	\$819	
	Walls - Concrete Block	2nd Floor	409	SF	6	\$1,199	
	Walls - Metal Panel	2nd Floor	845	SF	6	\$6,308	
	Wireless System	2nd Floor	1	EA	6	\$372	
Classroom #219 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	892	SF	6	\$2,679	
	Ceiling - Lay-in	2nd Floor	10	SF	5	\$80	stained
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	10	SF	6	\$169	
	Floor - Tile	2nd Floor	902	SF	6	\$1,973	
	Lighting - Lay-in	2nd Floor	18	EA	7	\$0	20 - floor outlets damaged
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	112	SF	6	\$328	
	Walls - Metal Panel	2nd Floor	1,026	SF	6	\$7,659	
	Work Sink	2nd Floor	1	EA	5	\$1,508	covered - not in use
Classroom #220 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	754	SF	6	\$2,264	
	Doors - Side-lite	2nd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Doors - Transom Window	2nd Floor	10	SF	6	\$169	
	Floor - Tile	2nd Floor	754	SF	6	\$1,650	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	112	SF	6	\$328	
	Walls - Metal Panel	2nd Floor	810	SF	6	\$6,046	
	Wireless System	2nd Floor	1	EA	6	\$372	
Classroom #221 (Computer Lab)							
	Ceiling - Lay-in	2nd Floor	1,168	SF	6	\$3,508	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	1,168	SF	6	\$2,555	
	Lighting - Lay-in	2nd Floor	23	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Storage/ Closet	2nd Floor	71	SF	6	\$515	
	Walls - Concrete Block	2nd Floor	481	SF	6	\$1,410	
	Walls - Metal Panel	2nd Floor	853	SF	6	\$6,367	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #221 (Computer Lab)							
Classroom #240 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	1,276	SF	6	\$3,832	
	Chalk Board	2nd Floor	14	LF	4	\$1,285	
	Doors - Side-lite	2nd Floor	20	SF	6	\$334	
	Doors - Store Front	2nd Floor	2	EA	6	\$2,416	
	Doors - Transom Window	2nd Floor	92	SF	6	\$1,558	
	Floor - Tile/Sheet	2nd Floor	1,276	SF	6	\$1,277	
	Lighting - Lay-in	2nd Floor	26	EA	7	\$0	
	Marker Board	2nd Floor	14	LF	7	\$0	
	Storage/ Closet	2nd Floor	198	SF	5	\$3,194	ceiling & light fixture stained, bad condition
	Walls - Metal Panel	2nd Floor	741	SF	6	\$5,531	
	Walls - Plaster/Drywall	2nd Floor	436	SF	6	\$1,203	
Classroom #242 (Science)							
	Casework	2nd Floor	73	LF	6	\$1,844	
	Ceiling - Lay-in	2nd Floor	1,309	SF	6	\$3,931	
	Ceiling - Lay-in	2nd Floor	20	SF	5	\$160	stained / cracked ceiling tiles
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Eye Wash Station	2nd Floor	1	EA	6	\$336	
	Floor - Tile	2nd Floor	1,327	SF	6	\$2,903	
	Floor - Tile	2nd Floor	2	SF	5	\$12	damaged access panels
	Fume Hood	2nd Floor	1	EA	6	\$816	
	Gas Line	2nd Floor	7	EA	6	\$3,564	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	9	LF	7	\$0	
	Science Lab Shower	2nd Floor	1	EA	6	\$379	
	Storage/ Closet	2nd Floor	417	SF	6	\$3,023	
	Walls - Plaster/Drywall	2nd Floor	1,055	SF	6	\$2,912	
	Work Sink	2nd Floor	10	EA	6	\$3,790	
Classroom #302 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	728	SF	5	\$4,331	stained
	Ceiling - Lay-in	3rd Floor	25	SF	4	\$351	damaged tiles
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	5	\$1,174	door doesn't shut properly in loose metal door frame
	Doors - Transom Window	3rd Floor	34	SF	6	\$576	
	Floor - Tile	3rd Floor	753	SF	6	\$1,647	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #302 (Regular Classroom)							
	Lighting - Lay-in	3rd Floor	13	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	6	\$214	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	865	SF	6	\$6,457	
Classroom #303 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	785	SF	6	\$2,357	
	Ceiling - Lay-in	3rd Floor	10	SF	5	\$80	stained
	Doors - Side-lite	3rd Floor	5	SF	6	\$84	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	5	\$1,174	door doesn't shut properly
	Doors - Transom Window	3rd Floor	10	SF	5	\$423	cracked
	Floor - Tile	3rd Floor	795	SF	6	\$1,739	
	Lighting - Lay-in	3rd Floor	16	EA	7	\$0	
	Marker Board	3rd Floor	14	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	205	SF	6	\$601	
	Walls - Metal Panel	3rd Floor	557	SF	6	\$4,158	
Classroom #304 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	757	SF	6	\$2,273	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	5	\$1,174	door doesn't shut properly
	Doors - Transom Window	3rd Floor	50	SF	6	\$847	
	Floor - Tile	3rd Floor	757	SF	6	\$1,656	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	866	SF	6	\$6,464	
Classroom #305 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	753	SF	6	\$2,261	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	5	\$1,174	door doesn't shut properly
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	753	SF	6	\$1,647	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	865	SF	6	\$6,457	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #306 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	755	SF	6	\$2,267	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	5	\$1,174	door doesn't shut properly
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	755	SF	6	\$1,652	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	859	SF	6	\$6,412	
Classroom #307 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	753	SF	6	\$2,261	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	5	\$1,174	door doesn't shut properly
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	753	SF	6	\$1,647	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	863	SF	6	\$6,442	
Classroom #308 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	755	SF	6	\$2,267	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	755	SF	6	\$1,652	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	865	SF	6	\$6,457	
Classroom #309 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	10	SF	5	\$80	stained / peeling
	Ceiling - Lay-in	3rd Floor	743	SF	6	\$2,231	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	5	\$1,174	door latch damaged, door doesn't shut
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	753	SF	6	\$1,647	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #309 (Regular Classroom)							
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	858	SF	6	\$6,405	
Classroom #310, 311 (Special Education)							
	Casework	3rd Floor	12	LF	6	\$303	
	Ceiling - Lay-in	3rd Floor	934	SF	6	\$2,805	
	Ceiling - Lay-in	3rd Floor	10	SF	5	\$80	stained
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	\$602	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	1 exterior window shattered for over year
	Floor - Tile	3rd Floor	944	SF	6	\$2,065	
	Lighting - Lay-in	3rd Floor	17	EA	7	\$0	
	Marker Board	3rd Floor	6	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	177	SF	6	\$519	
	Walls - Concrete Block	3rd Floor	10	SF	5	\$141	cracks / leaks when it rains
	Walls - Metal Panel	3rd Floor	607	SF	6	\$4,531	
	Work Sink	3rd Floor	1	EA	6	\$379	in base cabinet
Classroom #312 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	407	SF	6	\$1,222	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	407	SF	6	\$890	
	Lighting - Lay-in	3rd Floor	8	EA	7	\$0	
	Marker Board	3rd Floor	9	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	424	SF	6	\$1,243	
	Walls - Metal Panel	3rd Floor	424	SF	6	\$3,165	
Classroom #313 (Science)							
	Ceiling - Lay-in	3rd Floor	602	SF	6	\$1,808	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	1 exterior window cracked
	Floor - Tile	3rd Floor	602	SF	6	\$1,317	
	Lighting - Lay-in	3rd Floor	24	EA	7	\$0	
	Marker Board	3rd Floor	11	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	584	SF	6	\$1,712	
	Walls - Metal Panel	3rd Floor	305	SF	6	\$2,277	
	Work Sink	3rd Floor	1	EA	6	\$379	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #314A (Science)							
	Casework	3rd Floor	76	LF	6	\$1,919	
	Ceiling - Lay-in	3rd Floor	1,209	SF	6	\$3,631	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	\$602	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Tile	3rd Floor	1,209	SF	6	\$2,645	
	Fume Hood	3rd Floor	1	EA	6	\$816	
	Gas Line	3rd Floor	4	EA	6	\$2,036	remainder at each sink plugged
	Lighting - Lay-in	3rd Floor	47	EA	7	\$0	
	Marker Board	3rd Floor	6	LF	7	\$0	
	Science Lab Shower	3rd Floor	1	EA	6	\$379	
	Storage/ Closet	3rd Floor	359	SF	6	\$2,603	
	Walls - Concrete Block	3rd Floor	539	SF	6	\$1,580	
	Walls - Metal Panel	3rd Floor	608	SF	6	\$4,538	
	Work Sink	3rd Floor	8	EA	6	\$3,032	
Classroom #315 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	485	SF	6	\$1,456	
	Doors - Side-lite	3rd Floor	76	SF	6	\$1,270	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	5	\$1,174	door doesn't stay shut
	Doors - Transom Window	3rd Floor	10	SF	6	\$169	
	Floor - Tile	3rd Floor	485	SF	6	\$1,061	
	Lighting - Lay-in	3rd Floor	10	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	444	SF	6	\$1,302	
	Walls - Metal Panel	3rd Floor	444	SF	6	\$3,314	
Classroom #316A (Science)							
	Casework	3rd Floor	76	LF	6	\$1,919	
	Ceiling - Lay-in	3rd Floor	1,200	SF	6	\$3,604	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	\$602	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Tile	3rd Floor	1,200	SF	6	\$2,625	
	Fume Hood	3rd Floor	1	EA	6	\$816	
	Lighting - Lay-in	3rd Floor	48	EA	7	\$0	
	Science Lab Shower	3rd Floor	1	EA	6	\$379	
	Storage/ Closet	3rd Floor	94	SF	6	\$682	instrument room
	Walls - Concrete Block	3rd Floor	472	SF	6	\$1,384	
	Walls - Metal Panel	3rd Floor	792	SF	6	\$5,912	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #316A (Science)							
	Work Sink	3rd Floor	7	EA	6	\$2,653	
Classroom #317 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	481	SF	6	\$1,444	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile	3rd Floor	481	SF	6	\$1,052	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	626	SF	6	\$1,835	
	Walls - Metal Panel	3rd Floor	290	SF	6	\$2,165	
Classroom #318 (Science)							
	Ceiling - Lay-in	3rd Floor	602	SF	6	\$1,808	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	602	SF	6	\$1,317	
	Lighting - Lay-in	3rd Floor	24	EA	7	\$0	
	Walls - Concrete Block	3rd Floor	38	SF	6	\$111	
	Walls - Metal Panel	3rd Floor	843	SF	6	\$6,293	
	Work Sink	3rd Floor	2	EA	6	\$758	
Classroom #319 (Science)							
	Casework	3rd Floor	92	LF	6	\$2,323	
	Ceiling - Lay-in	3rd Floor	1,209	SF	6	\$3,631	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Tile	3rd Floor	1,209	SF	6	\$2,645	
	Fume Hood	3rd Floor	1	EA	6	\$816	
	Lighting - Lay-in	3rd Floor	48	EA	7	\$0	
	Marker Board	3rd Floor	6	LF	7	\$0	
	Science Lab Shower	3rd Floor	1	EA	6	\$379	
	Storage/ Closet	3rd Floor	402	SF	6	\$2,915	life house & project room
	Walls - Concrete Block	3rd Floor	392	SF	6	\$1,149	
	Walls - Metal Panel	3rd Floor	712	SF	6	\$5,315	
	Work Sink	3rd Floor	9	EA	6	\$3,411	
Classroom #320 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	436	SF	6	\$1,309	
	Chalk Board	3rd Floor	4	LF	4	\$367	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #320 (Regular Classroom)							
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Floor - Tile	3rd Floor	436	SF	6	\$954	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Walls - Concrete Block	3rd Floor	298	SF	6	\$874	
	Walls - Metal Panel	3rd Floor	597	SF	6	\$4,456	
Classroom #322 (Special Education)							
	Casework	3rd Floor	11	LF	6	\$278	
	Ceiling - Lay-in	3rd Floor	519	SF	6	\$1,559	
	Ceiling - Lay-in	3rd Floor	4	SF	5	\$32	stained ceiling tile
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	523	SF	6	\$1,144	
	Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
	Marker Board	3rd Floor	9	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	145	SF	6	\$425	
	Walls - Metal Panel	3rd Floor	465	SF	6	\$3,471	
	Work Sink	3rd Floor	1	EA	6	\$379	
Classroom #323 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	752	SF	6	\$2,258	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	752	SF	6	\$1,645	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	87	SF	6	\$255	
	Walls - Metal Panel	3rd Floor	862	SF	6	\$6,434	
Classroom #324 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	757	SF	6	\$2,273	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	5	\$1,174	doesn't shut properly
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	757	SF	6	\$1,656	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	867	SF	6	\$6,472	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #324 (Regular Classroom)							
Classroom #325 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	757	SF	6	\$2,273	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	757	SF	6	\$1,656	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	862	SF	6	\$6,434	
Classroom #326 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	757	SF	6	\$2,273	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	757	SF	6	\$1,656	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	869	SF	6	\$6,487	
Classroom #327 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	753	SF	6	\$2,261	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	
	Floor - Tile	3rd Floor	753	SF	6	\$1,647	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	855	SF	6	\$6,382	
Classroom #328 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	755	SF	6	\$2,267	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	42	SF	6	\$711	

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #328 (Regular Classroom)							
	Floor - Tile	3rd Floor	755	SF	6	\$1,652	
	Lighting - Lay-in	3rd Floor	13	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	862	SF	6	\$6,434	
Classroom #329 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	778	SF	6	\$2,336	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	10	SF	6	\$169	
	Floor - Tile	3rd Floor	778	SF	6	\$1,702	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	15	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	212	SF	6	\$621	
	Walls - Metal Panel	3rd Floor	564	SF	6	\$4,210	
Classroom #330 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	750	SF	6	\$2,252	
	Doors - Side-lite	3rd Floor	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Transom Window	3rd Floor	34	SF	6	\$576	
	Floor - Tile	3rd Floor	750	SF	6	\$1,641	
	Lighting - Lay-in	3rd Floor	15	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	88	SF	6	\$258	
	Walls - Metal Panel	3rd Floor	862	SF	6	\$6,434	
Classrooms Subtotal:						\$884,179	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Ceiling - Lay-in	1st- 114B Office	286	SF	6	\$859	
	Doors - Side-lite	1st- 114B Office	79	SF	6	\$1,321	
	Doors - Steel Doors incl hw	1st- 114B Office	1	EA	6	\$301	
	Doors - Transom Window	1st- 114B Office	240	SF	6	\$4,063	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Floor - Tile	1st- 114B Office	286	SF	6	\$626	
	Lighting - Lay-in	1st- 114B Office	6	EA	7	\$0	
	Power Distribution	1st- 114B Office	8	EA	6	\$16,999	
	Walls - Concrete Block	1st- 114B Office	535	SF	6	\$1,568	
	Walls - Metal Panel	1st- 114B Office	147	SF	6	\$1,097	
	Ceiling - Lay-in	1st- File Room (former Asst Principal)	153	SF	6	\$459	
	Doors - Side-lite	1st- File Room (former Asst Principal)	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st- File Room (former Asst Principal)	1	EA	6	\$301	
	Doors - Transom Window	1st- File Room (former Asst Principal)	10	SF	6	\$169	
	Floor - Carpet	1st- File Room (former Asst Principal)	153	SF	6	\$326	
	Lighting - Lay-in	1st- File Room (former Asst Principal)	3	EA	7	\$0	
	Power Distribution	1st- File Room (former Asst Principal)	4	EA	6	\$8,500	
	Walls - Metal Panel	1st- File Room (former Asst Principal)	505	SF	6	\$3,770	
	Ceiling - Lay-in	1st- Mail Room	193	SF	6	\$580	
	Doors - Steel Doors incl hw	1st- Mail Room	2	EA	6	\$602	
	Floor - Tile	1st- Mail Room	193	SF	6	\$422	
	Lighting - Lay-in	1st- Mail Room	4	EA	7	\$0	
	Power Distribution	1st- Mail Room	8	EA	6	\$16,999	
	Walls - Metal Panel	1st- Mail Room	590	SF	6	\$4,404	
	Ceiling - Lay-in	1st- Main Office Conference Room	510	SF	6	\$1,532	
	Floor - Tile	1st- Main Office Conference Room	510	SF	6	\$1,116	
	Lighting - Lay-in	1st- Main Office Conference Room	11	EA	7	\$0	
	Power Distribution	1st- Main Office Conference Room	14	EA	6	\$29,748	
	Walls - Metal Panel	1st- Main Office Conference Room	905	SF	6	\$6,755	
	Work Slnk	1st- Main Office Conference Room	1	EA	6	\$508	
	Ceiling - Lay-in	1st- Main Office	1,050	SF	6	\$3,153	
	Doors - Side-lite	1st- Main Office	219	SF	6	\$3,661	
	Doors - Steel Doors incl hw	1st- Main Office	2	EA	6	\$602	
	Doors - Transom Window	1st- Main Office	11	SF	6	\$186	
	Floor - Tile	1st- Main Office	1,050	SF	6	\$2,297	
	Lighting - Lay-in	1st- Main Office	19	EA	7	\$0	
	Power Distribution	1st- Main Office	6	EA	6	\$12,749	
	Walls - Metal Panel	1st- Main Office	985	SF	6	\$7,353	
	Ceiling - Lay-in	1st- Office inside 117	209	SF	6	\$628	
	Doors - Steel Doors incl hw	1st- Office inside 117	1	EA	6	\$301	
	Floor - Tile	1st- Office inside 117	209	SF	6	\$457	
	Lighting - Lay-in	1st- Office inside 117	6	EA	7	\$0	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Power Distribution	1st- Office inside 117	8	EA	6	\$16,999	
	Walls - Concrete Block	1st- Office inside 117	580	SF	6	\$1,700	
	Ceiling - Lay-in	1st- Operations Office	274	SF	6	\$823	
	Doors - Steel Doors incl hw	1st- Operations Office	3	EA	6	\$903	
	Floor - Carpet	1st- Operations Office	274	SF	6	\$584	
	Lighting - Lay-in	1st- Operations Office	5	EA	7	\$0	
	Power Distribution	1st- Operations Office	2	EA	6	\$4,250	
	Walls - Metal Panel	1st- Operations Office	400	SF	6	\$2,986	
	Ceiling - Lay-in	1st- Police Office	338	SF	6	\$1,015	
	Doors - Side-lite	1st- Police Office	9	SF	6	\$150	
	Doors - Steel Doors incl hw	1st- Police Office	2	EA	6	\$602	
	Doors - Transom Window	1st- Police Office	7	SF	6	\$119	
	Floor - Tile	1st- Police Office	338	SF	6	\$740	
	Lighting - Lay-in	1st- Police Office	11	EA	7	\$0	
	Power Distribution	1st- Police Office	12	EA	6	\$25,499	
	Walls - Concrete Block	1st- Police Office	465	SF	6	\$1,363	
	Ceiling - Lay-in	1st- Principal Office	307	SF	6	\$922	
	Doors - Steel Doors incl hw	1st- Principal Office	1	EA	6	\$301	
	Floor - Tile	1st- Principal Office	307	SF	6	\$672	
	Lighting - Lay-in	1st- Principal Office	7	EA	7	\$0	
	Power Distribution	1st- Principal Office	12	EA	6	\$25,499	
	Storage/ Closet	1st- Principal Office	35	SF	6	\$254	
	Walls - Metal Panel	1st- Principal Office	705	SF	6	\$5,263	
	Ceiling - Lay-in	1st- Principal's Conference Room	171	SF	6	\$514	
	Doors - Steel Doors incl hw	1st- Principal's Conference Room	2	EA	6	\$602	
	Doors - Transom Window	1st- Principal's Conference Room	10	SF	6	\$169	
	Floor - Carpet	1st- Principal's Conference Room	171	SF	6	\$364	
	Lighting - Lay-in	1st- Principal's Conference Room	3	EA	7	\$0	
	Power Distribution	1st- Principal's Conference Room	10	EA	6	\$21,249	
	Walls - Metal Panel	1st- Principal's Conference Room	530	SF	6	\$3,956	
	Ceiling - Lay-in	1st- Principal's Secretary	153	SF	6	\$459	
	Doors - Side-lite	1st- Principal's Secretary	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st- Principal's Secretary	1	EA	6	\$301	
	Doors - Transom Window	1st- Principal's Secretary	10	SF	6	\$169	
	Floor - Carpet	1st- Principal's Secretary	153	SF	6	\$326	
	Lighting - Lay-in	1st- Principal's Secretary	3	EA	7	\$0	
	Power Distribution	1st- Principal's Secretary	4	EA	6	\$8,500	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Walls - Metal Panel	1st- Principal's Secretary	505	SF	6	\$3,770	
	Ceiling - Lay-in	1st- Programming Office	236	SF	6	\$709	
	Ceiling - Lay-in	1st- Programming Office	2	SF	5	\$16	water damage
	Doors - Side-lite	1st- Programming Office	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st- Programming Office	2	EA	6	\$602	
	Doors - Transom Window	1st- Programming Office	22	SF	6	\$372	
	Floor - Carpet	1st- Programming Office	236	SF	6	\$503	
	Lighting - Chandelier, Incandescent	1st- Programming Office	4	EA	7	\$0	
	Power Distribution	1st- Programming Office	4	EA	6	\$8,500	
	Walls - Metal Panel	1st- Programming Office	610	SF	6	\$4,553	
	Ceiling - Lay-in	1st- Rm 105- Counseling/Mentor Office	1,493	SF	6	\$4,483	
	Doors - Side-lite	1st- Rm 105- Counseling/Mentor Office	49	SF	6	\$819	
	Doors - Steel Doors incl hw	1st- Rm 105- Counseling/Mentor Office	1	EA	6	\$301	
	Floor - Tile	1st- Rm 105- Counseling/Mentor Office	1,493	SF	6	\$3,267	
	Lighting - Lay-in	1st- Rm 105- Counseling/Mentor Office	30	EA	7	\$0	
	Power Distribution	1st- Rm 105- Counseling/Mentor Office	66	EA	7	\$0	44 are in floor
	Walls - Concrete Block	1st- Rm 105- Counseling/Mentor Office	798	SF	6	\$2,339	
	Walls - Metal Panel	1st- Rm 105- Counseling/Mentor Office	798	SF	6	\$5,957	
	Work Slnk	1st- Rm 105- Counseling/Mentor Office	1	EA	6	\$508	
	Ceiling - Lay-in	1st- Rm 105A- Counselor Office	144	SF	6	\$432	
	Doors - Steel Doors incl hw	1st- Rm 105A- Counselor Office	1	EA	6	\$301	
	Floor - Tile	1st- Rm 105A- Counselor Office	144	SF	6	\$315	
	Lighting - Lay-in	1st- Rm 105A- Counselor Office	3	EA	7	\$0	
	Power Distribution	1st- Rm 105A- Counselor Office	4	EA	6	\$8,500	
	Walls - Metal Panel	1st- Rm 105A- Counselor Office	490	SF	6	\$3,658	
	Ceiling - Lay-in	1st- Rm 107B Counselors Office	141	SF	6	\$423	
	Doors - Side-lite	1st- Rm 107B Counselors Office	20	SF	6	\$334	
	Doors - Steel Doors incl hw	1st- Rm 107B Counselors Office	1	EA	6	\$301	
	Floor - Tile	1st- Rm 107B Counselors Office	141	SF	6	\$308	
	Lighting - Lay-in	1st- Rm 107B Counselors Office	3	EA	7	\$0	
	Power Distribution	1st- Rm 107B Counselors Office	4	EA	6	\$8,500	
	Walls - Concrete Block	1st- Rm 107B Counselors Office	144	SF	6	\$422	
	Walls - Masonry	1st- Rm 107B Counselors Office	99	SF	6	\$311	
	Walls - Metal Panel	1st- Rm 107B Counselors Office	223	SF	6	\$1,665	
	Ceiling - Lay-in	1st- Rm 108 Call Center	290	SF	6	\$871	
	Doors - Side-lite	1st- Rm 108 Call Center	15	SF	6	\$251	
	Doors - Steel Doors incl hw	1st- Rm 108 Call Center	1	EA	6	\$301	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Doors - Transom Window	1st- Rm 108 Call Center	18	SF	6	\$305	
	Floor - Tile	1st- Rm 108 Call Center	290	SF	6	\$634	
	Lighting - Lay-in	1st- Rm 108 Call Center	6	EA	7	\$0	
	Power Distribution	1st- Rm 108 Call Center	6	EA	6	\$12,749	
	Walls - Concrete Block	1st- Rm 108 Call Center	342	SF	6	\$1,003	
	Walls - Metal Panel	1st- Rm 108 Call Center	343	SF	6	\$2,560	
	Ceiling - Lay-in	1st- Rm 108- Office B Operations	229	SF	6	\$688	
	Doors - Steel Doors incl hw	1st- Rm 108- Office B Operations	1	EA	6	\$301	
	Floor - Carpet	1st- Rm 108- Office B Operations	229	SF	6	\$488	
	Lighting - Lay-in	1st- Rm 108- Office B Operations	5	EA	7	\$0	
	Power Distribution	1st- Rm 108- Office B Operations	6	EA	6	\$12,749	
	Walls - Metal Panel	1st- Rm 108- Office B Operations	605	SF	6	\$4,516	
	Ceiling - Lay-in	1st- Rm 108- Office C Operations	137	SF	6	\$411	
	Doors - Steel Doors incl hw	1st- Rm 108- Office C Operations	1	EA	6	\$301	
	Floor - Tile	1st- Rm 108- Office C Operations	137	SF	6	\$300	
	Lighting - Lay-in	1st- Rm 108- Office C Operations	3	EA	7	\$0	
	Power Distribution	1st- Rm 108- Office C Operations	4	EA	6	\$8,500	
	Walls - Metal Panel	1st- Rm 108- Office C Operations	585	SF	6	\$4,367	
	Ceiling - Lay-in	1st- Rm 108-Office A Administrative Support	217	SF	6	\$652	
	Doors - Steel Doors incl hw	1st- Rm 108-Office A Administrative Support	1	EA	6	\$301	
	Floor - Tile	1st- Rm 108-Office A Administrative Support	217	SF	6	\$475	
	Lighting - Lay-in	1st- Rm 108-Office A Administrative Support	4	EA	7	\$0	
	Power Distribution	1st- Rm 108-Office A Administrative Support	8	EA	6	\$16,999	
	Storage/ Closet	1st- Rm 108-Office A Administrative Support	192	SF	6	\$1,392	
	Walls - Metal Panel	1st- Rm 108-Office A Administrative Support	590	SF	6	\$4,404	
	Ceiling - Lay-in	1st- Rm 122 Attendance Office	877	SF	6	\$2,634	
	Doors - Side-lite	1st- Rm 122 Attendance Office	270	SF	6	\$4,514	
	Doors - Steel Doors incl hw	1st- Rm 122 Attendance Office	1	EA	6	\$301	
	Doors - Transom Window	1st- Rm 122 Attendance Office	6	SF	6	\$102	
	Floor - Tile	1st- Rm 122 Attendance Office	877	SF	6	\$1,919	
	Lighting - Lay-in	1st- Rm 122 Attendance Office	18	EA	7	\$0	
	Power Distribution	1st- Rm 122 Attendance Office	36	EA	7	\$0	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Storage/ Closet	1st- Rm 122 Attendance Office	51	SF	6	\$370	
	Walls - Concrete Block	1st- Rm 122 Attendance Office	580	SF	6	\$1,700	
	Walls - Metal Panel	1st- Rm 122 Attendance Office	290	SF	6	\$2,165	
	Ceiling - Lay-in	1st- Rm 125 Counselor Office	145	SF	6	\$435	
	Doors - Side-lite	1st- Rm 125 Counselor Office	93	SF	6	\$1,555	
	Doors - Steel Doors incl hw	1st- Rm 125 Counselor Office	1	EA	6	\$301	
	Floor - Carpet	1st- Rm 125 Counselor Office	145	SF	6	\$309	
	Lighting - Lay-in	1st- Rm 125 Counselor Office	3	EA	7	\$0	
	Power Distribution	1st- Rm 125 Counselor Office	4	EA	6	\$8,500	
	Walls - Metal Panel	1st- Rm 125 Counselor Office	490	SF	6	\$3,658	
	Ceiling - Lay-in	1st- Security Office (across from 1005)	94	SF	6	\$282	
	Doors - Steel Doors incl hw	1st- Security Office (across from 1005)	1	EA	6	\$301	
	Floor - Carpet	1st- Security Office (across from 1005)	94	SF	6	\$200	
	Lighting - Lay-in	1st- Security Office (across from 1005)	2	EA	7	\$0	
	Power Distribution	1st- Security Office (across from 1005)	4	EA	6	\$8,500	
	Walls - Metal Panel	1st- Security Office (across from 1005)	385	SF	6	\$2,874	
	Ceiling - Lay-in	1st- Security Office	155	SF	6	\$465	
	Doors - Side-lite	1st- Security Office	9	SF	6	\$150	
	Doors - Steel Doors incl hw	1st- Security Office	1	EA	6	\$301	
	Doors - Transom Window	1st- Security Office	6	SF	6	\$102	
	Floor - Tile	1st- Security Office	155	SF	6	\$339	
	Lighting - Lay-in	1st- Security Office	6	EA	7	\$0	
	Power Distribution	1st- Security Office	18	EA	6	\$38,248	
	Walls - Concrete Block	1st- Security Office	357	SF	6	\$1,047	
	Ceiling - Lay-in	1st- VACANT Foreign Language Office	142	SF	6	\$426	
	Doors - Steel Doors incl hw	1st- VACANT Foreign Language Office	1	EA	6	\$301	
	Floor - Tile	1st- VACANT Foreign Language Office	142	SF	6	\$311	
	Lighting - Lay-in	1st- VACANT Foreign Language Office	3	EA	7	\$0	
	Power Distribution	1st- VACANT Foreign Language Office	8	EA	6	\$16,999	
	Walls - Concrete Block	1st- VACANT Foreign Language Office	242	SF	6	\$709	
	Walls - Metal Panel	1st- VACANT Foreign Language Office	243	SF	6	\$1,814	
	Ceiling - Lay-in	2nd - 201C Counselor's Office	152	SF	6	\$456	
	Doors - Side-lite	2nd - 201C Counselor's Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd - 201C Counselor's Office	1	EA	6	\$301	
	Doors - Transom Window	2nd - 201C Counselor's Office	30	SF	6	\$508	
	Floor - Carpet	2nd - 201C Counselor's Office	152	SF	6	\$324	
	Lighting - Lay-in	2nd - 201C Counselor's Office	3	EA	7	\$0	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Power Distribution	2nd - 201C Counselor's Office	2	EA	6	\$4,250	
	Walls - Concrete Block	2nd - 201C Counselor's Office	148	SF	6	\$434	
	Walls - Metal Panel	2nd - 201C Counselor's Office	356	SF	6	\$2,657	
	Ceiling - Lay-in	2nd - 201D Counselor's Office	137	SF	6	\$411	
	Doors - Side-lite	2nd - 201D Counselor's Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd - 201D Counselor's Office	1	EA	5	\$1,174	doesn't close properly
	Doors - Transom Window	2nd - 201D Counselor's Office	30	SF	6	\$508	
	Floor - Carpet	2nd - 201D Counselor's Office	137	SF	6	\$292	
	Lighting - Lay-in	2nd - 201D Counselor's Office	3	EA	7	\$0	
	Power Distribution	2nd - 201D Counselor's Office	2	EA	6	\$4,250	
	Walls - Concrete Block	2nd - 201D Counselor's Office	148	SF	6	\$434	
	Walls - Metal Panel	2nd - 201D Counselor's Office	103	SF	6	\$932	glass wall
	Walls - Metal Panel	2nd - 201D Counselor's Office	253	SF	6	\$1,889	
	Ceiling - Lay-in	2nd - 201E Office	207	SF	6	\$622	
	Doors - Side-lite	2nd - 201E Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	2nd - 201E Office	1	EA	6	\$301	
	Doors - Transom Window	2nd - 201E Office	40	SF	6	\$677	
	Floor - Carpet	2nd - 201E Office	207	SF	6	\$441	
	Lighting - Lay-in	2nd - 201E Office	5	EA	7	\$0	
	Power Distribution	2nd - 201E Office	4	EA	6	\$8,500	
	Walls - Concrete Block	2nd - 201E Office	138	SF	6	\$405	
	Walls - Metal Panel	2nd - 201E Office	304	SF	6	\$2,269	
	Walls - Metal Panel	2nd - 201E Office	138	SF	6	\$1,249	glass wall
	Ceiling - Lay-in	2nd - 222 Periodical Rm inside Library	301	SF	6	\$904	
	Doors - Side-lite	2nd - 222 Periodical Rm inside Library	72	SF	6	\$1,204	
	Doors - Steel Doors incl hw	2nd - 222 Periodical Rm inside Library	2	EA	6	\$602	
	Doors - Transom Window	2nd - 222 Periodical Rm inside Library	40	SF	6	\$677	
	Floor - Carpet	2nd - 222 Periodical Rm inside Library	301	SF	5	\$1,545	bad condition
	Lighting - Lay-in	2nd - 222 Periodical Rm inside Library	6	EA	7	\$0	
	Power Distribution	2nd - 222 Periodical Rm inside Library	24	EA	6	\$50,997	
	Walls - Metal Panel	2nd - 222 Periodical Rm inside Library	593	SF	6	\$4,427	
	Ceiling - Lay-in	2nd - 230 Seminar Room inside Library	771	SF	6	\$2,315	
	Doors - Side-lite	2nd - 230 Seminar Room inside Library	352	SF	6	\$5,884	
	Doors - Steel Doors incl hw	2nd - 230 Seminar Room inside Library	1	EA	6	\$301	
	Doors - Transom Window	2nd - 230 Seminar Room inside Library	10	SF	6	\$169	
	Floor - Carpet	2nd - 230 Seminar Room inside Library	771	SF	6	\$1,643	
	Lighting - Lay-in	2nd - 230 Seminar Room inside Library	15	EA	7	\$0	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Power Distribution	2nd - 230 Seminar Room inside Library	71	EA	7	\$0	
	Walls - Concrete Block	2nd - 230 Seminar Room inside Library	205	SF	6	\$601	
	Walls - Metal Panel	2nd - 230 Seminar Room inside Library	304	SF	6	\$2,269	
	Ceiling - Lay-in	2nd - 230-A Office	885	SF	6	\$2,658	
	Doors - Steel Doors incl hw	2nd - 230-A Office	1	EA	6	\$301	
	Floor - Carpet	2nd - 230-A Office	885	SF	6	\$1,886	
	Lighting - Lay-in	2nd - 230-A Office	18	EA	7	\$0	
	Power Distribution	2nd - 230-A Office	14	EA	6	\$29,748	8 - floor outlets
	Walls - Concrete Block	2nd - 230-A Office	298	SF	6	\$874	
	Walls - Metal Panel	2nd - 230-A Office	891	SF	6	\$6,651	
	Work Slnk	2nd - 230-A Office	1	EA	5	\$1,508	attached electrical box corrodated
	Ceiling - Lay-in	2nd - 260 Office	416	SF	6	\$1,249	
	Doors - Side-lite	2nd - 260 Office	74	SF	6	\$1,237	
	Doors - Steel Doors incl hw	2nd - 260 Office	1	EA	6	\$301	
	Doors - Transom Window	2nd - 260 Office	30	SF	6	\$508	
	Floor - Tile	2nd - 260 Office	416	SF	6	\$910	
	Lighting - Lay-in	2nd - 260 Office	9	EA	7	\$0	junction box damaged
	Power Distribution	2nd - 260 Office	4	EA	6	\$8,500	
	Walls - Metal Panel	2nd - 260 Office	580	SF	6	\$4,329	
	Ceiling - Lay-in	2nd - 301B Faculty Prep Rm	301	SF	6	\$904	
	Doors - Steel Doors incl hw	2nd - 301B Faculty Prep Rm	1	EA	5	\$1,174	door doesn't shut properly
	Doors - Transom Window	2nd - 301B Faculty Prep Rm	30	SF	6	\$508	
	Floor - Carpet	2nd - 301B Faculty Prep Rm	301	SF	6	\$641	
	Lighting - Lay-in	2nd - 301B Faculty Prep Rm	6	EA	7	\$0	
	Power Distribution	2nd - 301B Faculty Prep Rm	2	EA	6	\$4,250	
	Walls - Concrete Block	2nd - 301B Faculty Prep Rm	204	SF	6	\$598	
	Walls - Metal Panel	2nd - 301B Faculty Prep Rm	499	SF	6	\$3,725	
	Ceiling - Lay-in	2nd - Conference room shared by 230-A & Library	418	SF	6	\$1,255	
	Doors - Steel Doors incl hw	2nd - Conference room shared by 230-A & Library	2	EA	6	\$602	
	Floor - Carpet	2nd - Conference room shared by 230-A & Library	418	SF	6	\$891	
	Lighting - Lay-in	2nd - Conference room shared by 230-A & Library	9	EA	7	\$0	
	Power Distribution	2nd - Conference room shared by 230-A & Library	27	EA	6	\$57,372	
	Walls - Metal Panel	2nd - Conference room shared by 230-A & Library	433	SF	6	\$3,919	glass walls / transoms

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Walls - Metal Panel	2nd - Conference room shared by 230-A & Library	433	SF	6	\$3,919	
	Ceiling - Lay-in	2nd - Librarian Office - IDF area	423	SF	6	\$1,270	
	Doors - Steel Doors incl hw	2nd - Librarian Office - IDF area	2	EA	6	\$602	
	Doors - Transom Window	2nd - Librarian Office - IDF area	50	SF	6	\$847	
	Floor - Carpet	2nd - Librarian Office - IDF area	423	SF	6	\$901	
	Lighting - Lay-in	2nd - Librarian Office - IDF area	9	EA	7	\$0	
	Power Distribution	2nd - Librarian Office - IDF area	12	EA	6	\$25,499	
	Walls - Concrete Block	2nd - Librarian Office - IDF area	146	SF	6	\$428	
	Walls - Metal Panel	2nd - Librarian Office - IDF area	708	SF	6	\$5,285	glass wall
	Walls - Metal Panel	2nd - Librarian Office - IDF area	288	SF	6	\$2,607	
	Ceiling - Lay-in	2nd - Office 1 inside 221	98	SF	6	\$294	
	Doors - Steel Doors incl hw	2nd - Office 1 inside 221	1	EA	6	\$301	
	Floor - Tile	2nd - Office 1 inside 221	98	SF	6	\$214	
	Lighting - Lay-in	2nd - Office 1 inside 221	2	EA	7	\$0	
	Power Distribution	2nd - Office 1 inside 221	2	EA	6	\$4,250	
	Walls - Metal Panel	2nd - Office 1 inside 221	395	SF	6	\$2,949	
	Ceiling - Lay-in	2nd - Office in Listening Rm inside Library	291	SF	6	\$874	
	Doors - Side-lite	2nd - Office in Listening Rm inside Library	176	SF	6	\$2,942	
	Doors - Steel Doors incl hw	2nd - Office in Listening Rm inside Library	1	EA	6	\$301	
	Doors - Transom Window	2nd - Office in Listening Rm inside Library	10	SF	6	\$169	
	Floor - Carpet	2nd - Office in Listening Rm inside Library	291	SF	6	\$620	
	Lighting - Lay-in	2nd - Office in Listening Rm inside Library	6	EA	7	\$0	
	Power Distribution	2nd - Office in Listening Rm inside Library	14	EA	6	\$29,748	
	Walls - Metal Panel	2nd - Office in Listening Rm inside Library	523	SF	6	\$3,904	
	Ceiling - Lay-in	2nd - Office inside 214	91	SF	6	\$273	
	Doors - Side-lite	2nd - Office inside 214	120	SF	6	\$2,006	
	Doors - Steel Doors incl hw	2nd - Office inside 214	1	EA	6	\$301	
	Doors - Transom Window	2nd - Office inside 214	40	SF	6	\$677	
	Floor - Carpet	2nd - Office inside 214	91	SF	5	\$467	stained
	Lighting - Lay-in	2nd - Office inside 214	2	EA	7	\$0	
	Power Distribution	2nd - Office inside 214	2	EA	6	\$4,250	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Walls - Metal Panel	2nd - Office inside 214	235	SF	6	\$1,754	
	Ceiling - Lay-in	2nd - Office inside 221	101	SF	6	\$303	
	Doors - Side-lite	2nd - Office inside 221	171	SF	6	\$2,859	
	Doors - Steel Doors incl hw	2nd - Office inside 221	1	EA	6	\$301	
	Doors - Transom Window	2nd - Office inside 221	40	SF	6	\$677	
	Floor - Tile	2nd - Office inside 221	101	SF	6	\$221	
	Lighting - Lay-in	2nd - Office inside 221	2	EA	7	\$0	
	Power Distribution	2nd - Office inside 221	4	EA	6	\$8,500	
	Walls - Concrete Block	2nd - Office inside 221	103	SF	6	\$302	
	Walls - Metal Panel	2nd - Office inside 221	98	SF	6	\$732	
	Ceiling - Lay-in	2nd - Small Conference inside Library	159	SF	6	\$477	
	Doors - Steel Doors incl hw	2nd - Small Conference inside Library	1	EA	6	\$301	
	Floor - Carpet	2nd - Small Conference inside Library	159	SF	6	\$339	
	Lighting - Lay-in	2nd - Small Conference inside Library	2	EA	7	\$0	
	Walls - Concrete Block	2nd - Small Conference inside Library	100	SF	6	\$293	
	Walls - Metal Panel	2nd - Small Conference inside Library	150	SF	6	\$1,358	glass wall
	Walls - Metal Panel	2nd - Small Conference inside Library	250	SF	6	\$1,866	
	Ceiling - Lay-in	2nd - Student info process rm inside Library	436	SF	6	\$1,309	
	Doors - Side-lite	2nd - Student info process rm inside Library	101	SF	6	\$1,688	
	Doors - Steel Doors incl hw	2nd - Student info process rm inside Library	2	EA	6	\$602	
	Doors - Transom Window	2nd - Student info process rm inside Library	120	SF	6	\$2,032	
	Floor - Tile	2nd - Student info process rm inside Library	436	SF	6	\$954	
	Lighting - Lay-in	2nd - Student info process rm inside Library	9	EA	7	\$0	
	Power Distribution	2nd - Student info process rm inside Library	18	EA	6	\$38,248	
	Walls - Metal Panel	2nd - Student info process rm inside Library	679	SF	6	\$5,068	
	Ceiling - Lay-in	3rd - 301A Assistant Prin Office	157	SF	6	\$471	
	Doors - Side-lite	3rd - 301A Assistant Prin Office	175	SF	6	\$2,925	
	Doors - Steel Doors incl hw	3rd - 301A Assistant Prin Office	1	EA	6	\$301	
	Doors - Transom Window	3rd - 301A Assistant Prin Office	50	SF	6	\$847	
	Floor - Carpet	3rd - 301A Assistant Prin Office	157	SF	6	\$335	
	Lighting - Lay-in	3rd - 301A Assistant Prin Office	3	EA	7	\$0	
	Power Distribution	3rd - 301A Assistant Prin Office	4	EA	6	\$8,500	assessed from outside - AP off during assessment

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Walls - Metal Panel	3rd - 301A Assistant Prin Office	250	SF	6	\$1,866	
	Ceiling - Lay-in	3rd - 301B Faculty Prep Rm	298	SF	6	\$895	
	Doors - Side-lite	3rd - 301B Faculty Prep Rm	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd - 301B Faculty Prep Rm	1	EA	6	\$301	
	Doors - Transom Window	3rd - 301B Faculty Prep Rm	20	SF	6	\$339	
	Floor - Carpet	3rd - 301B Faculty Prep Rm	298	SF	6	\$635	
	Lighting - Lay-in	3rd - 301B Faculty Prep Rm	6	EA	7	\$0	
	Power Distribution	3rd - 301B Faculty Prep Rm	2	EA	6	\$4,250	
	Walls - Concrete Block	3rd - 301B Faculty Prep Rm	203	SF	6	\$595	
	Walls - Metal Panel	3rd - 301B Faculty Prep Rm	580	SF	6	\$4,329	
	Ceiling - Lay-in	3rd - 301C Counselor's Office	157	SF	6	\$471	
	Doors - Side-lite	3rd - 301C Counselor's Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd - 301C Counselor's Office	1	EA	5	\$1,174	door doesn't shut properly
	Doors - Transom Window	3rd - 301C Counselor's Office	30	SF	6	\$508	
	Floor - Carpet	3rd - 301C Counselor's Office	157	SF	6	\$335	
	Lighting - Lay-in	3rd - 301C Counselor's Office	3	EA	7	\$0	
	Power Distribution	3rd - 301C Counselor's Office	2	EA	6	\$4,250	
	Walls - Concrete Block	3rd - 301C Counselor's Office	45	SF	6	\$132	
	Walls - Metal Panel	3rd - 301C Counselor's Office	359	SF	6	\$2,680	
	Ceiling - Lay-in	3rd - 301D Counselor's Office	139	SF	6	\$417	
	Doors - Side-lite	3rd - 301D Counselor's Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd - 301D Counselor's Office	1	EA	6	\$301	
	Doors - Transom Window	3rd - 301D Counselor's Office	10	SF	6	\$169	
	Floor - Carpet	3rd - 301D Counselor's Office	139	SF	6	\$296	
	Lighting - Lay-in	3rd - 301D Counselor's Office	3	EA	6	\$357	
	Power Distribution	3rd - 301D Counselor's Office	2	EA	6	\$4,250	
	Walls - Concrete Block	3rd - 301D Counselor's Office	27	SF	6	\$79	
	Walls - Metal Panel	3rd - 301D Counselor's Office	244	SF	6	\$1,821	
	Walls - Metal Panel	3rd - 301D Counselor's Office	154	SF	6	\$1,394	glass wall
	Ceiling - Lay-in	3rd - 301E Office	194	SF	6	\$583	
	Ceiling - Lay-in	3rd - 301E Office	10	SF	5	\$80	bad stains
	Doors - Side-lite	3rd - 301E Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd - 301E Office	1	EA	6	\$301	
	Doors - Transom Window	3rd - 301E Office	34	SF	6	\$576	
	Floor - Carpet	3rd - 301E Office	204	SF	6	\$435	
	Lighting - Lay-in	3rd - 301E Office	5	EA	7	\$0	
	Power Distribution	3rd - 301E Office	2	EA	6	\$4,250	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Walls - Concrete Block	3rd - 301E Office	140	SF	6	\$410	
	Walls - Metal Panel	3rd - 301E Office	145	SF	6	\$1,313	glass wall
	Walls - Metal Panel	3rd - 301E Office	285	SF	6	\$2,127	
	Ceiling - Lay-in	3rd - 319-B	252	SF	6	\$757	
	Doors - Side-lite	3rd - 319-B	98	SF	6	\$1,638	
	Doors - Steel Doors incl hw	3rd - 319-B	1	EA	6	\$301	
	Doors - Transom Window	3rd - 319-B	30	SF	6	\$508	
	Floor - Carpet	3rd - 319-B	252	SF	6	\$537	
	Lighting - Lay-in	3rd - 319-B	5	EA	6	\$595	
	Power Distribution	3rd - 319-B	4	EA	6	\$8,500	
	Walls - Metal Panel	3rd - 319-B	338	SF	6	\$2,523	
	Ceiling - Lay-in	3rd - 321 Special Education Office	304	SF	6	\$913	
	Doors - Side-lite	3rd - 321 Special Education Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd - 321 Special Education Office	1	EA	6	\$301	
	Doors - Transom Window	3rd - 321 Special Education Office	10	SF	6	\$169	
	Floor - Tile	3rd - 321 Special Education Office	304	SF	6	\$665	
	Lighting - Lay-in	3rd - 321 Special Education Office	6	EA	7	\$0	
	Power Distribution	3rd - 321 Special Education Office	7	EA	6	\$14,874	
	Power Distribution	3rd - 321 Special Education Office	4	EA	5	\$15,407	Damaged
	Walls - Concrete Block	3rd - 321 Special Education Office	148	SF	6	\$434	
	Walls - Metal Panel	3rd - 321 Special Education Office	565	SF	6	\$4,217	
	Ceiling - Lay-in	3rd - 331A	157	SF	6	\$471	
	Doors - Side-lite	3rd - 331A	175	SF	6	\$2,925	
	Doors - Steel Doors incl hw	3rd - 331A	1	EA	5	\$1,174	lock broke, accessed from outside
	Doors - Transom Window	3rd - 331A	50	SF	6	\$847	
	Floor - Carpet	3rd - 331A	157	SF	6	\$335	
	Lighting - Lay-in	3rd - 331A	3	EA	6	\$357	
	Ceiling - Lay-in	3rd - 331A Teacher's Lounge	302	SF	6	\$907	
	Doors - Side-lite	3rd - 331A Teacher's Lounge	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd - 331A Teacher's Lounge	1	EA	5	\$1,174	door doesn't close properly
	Doors - Transom Window	3rd - 331A Teacher's Lounge	18	SF	6	\$305	
	Floor - Carpet	3rd - 331A Teacher's Lounge	302	SF	6	\$643	
	Lighting - Lay-in	3rd - 331A Teacher's Lounge	6	EA	7	\$0	
	Power Distribution	3rd - 331A Teacher's Lounge	10	EA	6	\$21,249	
	Walls - Concrete Block	3rd - 331A Teacher's Lounge	205	SF	6	\$601	
	Walls - Metal Panel	3rd - 331A Teacher's Lounge	507	SF	6	\$3,785	
	Walls - Metal Panel	3rd - 331A	250	SF	6	\$1,866	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Ceiling - Lay-in	3rd - 331C Counselor's Office	157	SF	6	\$471	
	Doors - Side-lite	3rd - 331C Counselor's Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd - 331C Counselor's Office	1	EA	6	\$301	
	Doors - Transom Window	3rd - 331C Counselor's Office	26	SF	6	\$440	
	Floor - Carpet	3rd - 331C Counselor's Office	157	SF	6	\$335	
	Lighting - Lay-in	3rd - 331C Counselor's Office	3	EA	7	\$0	
	Power Distribution	3rd - 331C Counselor's Office	6	EA	6	\$12,749	
	Walls - Concrete Block	3rd - 331C Counselor's Office	148	SF	6	\$434	
	Walls - Metal Panel	3rd - 331C Counselor's Office	361	SF	6	\$2,695	
	Ceiling - Lay-in	3rd - 331D Counselor's Office	138	SF	6	\$414	
	Doors - Side-lite	3rd - 331D Counselor's Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd - 331D Counselor's Office	1	EA	6	\$301	
	Doors - Transom Window	3rd - 331D Counselor's Office	10	SF	6	\$169	
	Floor - Carpet	3rd - 331D Counselor's Office	138	SF	6	\$294	
	Lighting - Lay-in	3rd - 331D Counselor's Office	3	EA	7	\$0	
	Power Distribution	3rd - 331D Counselor's Office	2	EA	6	\$4,250	
	Walls - Concrete Block	3rd - 331D Counselor's Office	153	SF	6	\$449	
	Walls - Metal Panel	3rd - 331D Counselor's Office	340	SF	6	\$2,538	
	Ceiling - Lay-in	3rd - 331E Conference Room	205	SF	6	\$616	
	Doors - Side-lite	3rd - 331E Conference Room	10	SF	6	\$167	
	Doors - Steel Doors incl hw	3rd - 331E Conference Room	1	EA	6	\$301	
	Doors - Transom Window	3rd - 331E Conference Room	10	SF	6	\$169	
	Floor - Carpet	3rd - 331E Conference Room	205	SF	6	\$437	
	Lighting - Lay-in	3rd - 331E Conference Room	4	EA	7	\$0	
	Power Distribution	3rd - 331E Conference Room	2	EA	6	\$4,250	
	Walls - Concrete Block	3rd - 331E Conference Room	140	SF	6	\$410	
	Walls - Metal Panel	3rd - 331E Conference Room	439	SF	6	\$3,277	
	Ceiling - Lay-in	3rd - Faculty inside 314A	8	SF	5	\$64	stained
	Ceiling - Lay-in	3rd - Faculty inside 314A	195	SF	6	\$586	
	Doors - Steel Doors incl hw	3rd - Faculty inside 314A	2	EA	6	\$602	
	Floor - Tile	3rd - Faculty inside 314A	195	SF	6	\$427	
	Lighting - Lay-in	3rd - Faculty inside 314A	4	EA	7	\$0	
	Power Distribution	3rd - Faculty inside 314A	6	EA	6	\$12,749	
	Walls - Metal Panel	3rd - Faculty inside 314A	599	SF	6	\$4,471	
	Work Sink	3rd - Faculty inside 314A	2	EA	6	\$1,016	1 stand alone / 1 in base cabinet
	Ceiling - Lay-in	3rd - inside 319	188	SF	6	\$565	
	Doors - Steel Doors incl hw	3rd - inside 319	1	EA	6	\$301	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Floor - Tile	3rd - inside 319	188	SF	6	\$411	
	Lighting - Lay-in	3rd - inside 319	8	EA	7	\$0	1 fixture cover falling out
	Power Distribution	3rd - inside 319	4	EA	6	\$8,500	
	Walls - Concrete Block	3rd - inside 319	194	SF	6	\$569	
	Walls - Metal Panel	3rd - inside 319	393	SF	6	\$2,934	
	Work Slnk	3rd - inside 319	1	EA	6	\$508	
	Ceiling - Lay-in	3rd - Instrument Room inside 314A	93	SF	6	\$279	
	Doors - Side-lite	3rd - Instrument Room inside 314A	20	SF	6	\$334	
	Doors - Steel Doors incl hw	3rd - Instrument Room inside 314A	1	EA	6	\$301	
	Doors - Transom Window	3rd - Instrument Room inside 314A	21	SF	6	\$356	
	Floor - Tile	3rd - Instrument Room inside 314A	93	SF	6	\$203	
	Lighting - Lay-in	3rd - Instrument Room inside 314A	4	EA	7	\$0	
	Power Distribution	3rd - Instrument Room inside 314A	2	EA	6	\$4,250	
	Walls - Concrete Block	3rd - Instrument Room inside 314A	98	SF	6	\$287	
	Walls - Metal Panel	3rd - Instrument Room inside 314A	292	SF	6	\$2,180	
	Ceiling - Lay-in	3rd - Project Room inside 314A	10	SF	5	\$80	stained
	Ceiling - Lay-in	3rd - Project Room inside 314A	197	SF	6	\$592	
	Doors - Steel Doors incl hw	3rd - Project Room inside 314A	1	EA	6	\$301	
	Doors - Steel Doors incl hw	3rd - Project Room inside 314A	20	EA	6	\$6,020	
	Doors - Transom Window	3rd - Project Room inside 314A	21	SF	6	\$356	
	Floor - Tile	3rd - Project Room inside 314A	207	SF	6	\$453	
	Lighting - Lay-in	3rd - Project Room inside 314A	8	EA	7	\$0	
	Power Distribution	3rd - Project Room inside 314A	6	EA	6	\$12,749	
	Walls - Concrete Block	3rd - Project Room inside 314A	198	SF	6	\$580	
	Walls - Metal Panel	3rd - Project Room inside 314A	408	SF	6	\$3,046	
	Work Slnk	3rd - Project Room inside 314A	2	EA	6	\$1,016	1 stand alone / 1 in base cabinet
	Ceiling - Splined	Basement - Custodian Women	71	SF	6	\$58	
	Doors - Steel Doors incl hw	Basement - Custodian Women	1	EA	6	\$301	
	Floor - Tile	Basement - Custodian Women	71	SF	6	\$155	
	Lighting - Lay-in	Basement - Custodian Women	2	EA	7	\$0	
	Power Distribution	Basement - Custodian Women	2	EA	6	\$4,250	
	Walls - Concrete Block	Basement - Custodian Women	269	SF	6	\$789	
	Ceiling - Plaster/Drywall	Basement - Engineer / fire alarm suite	150	SF	6	\$519	
	Doors - Side-lite	Basement - Engineer / fire alarm suite	10	SF	6	\$167	
	Doors - Steel Doors incl hw	Basement - Engineer / fire alarm suite	2	EA	6	\$602	
	Floor - Tile	Basement - Engineer / fire alarm suite	150	SF	6	\$328	
	Lighting - Lay-in	Basement - Engineer / fire alarm suite	3	EA	7	\$0	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Power Distribution	Basement - Engineer / fire alarm suite	6	EA	6	\$12,749	
	Walls - Concrete Block	Basement - Engineer / fire alarm suite	421	SF	6	\$1,234	
	Ceiling - Plaster/Drywall	Basement - Engineer Office	256	SF	6	\$886	
	Doors - Side-lite	Basement - Engineer Office	10	SF	6	\$167	
	Doors - Steel Doors incl hw	Basement - Engineer Office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Basement - Engineer Office	256	SF	6	\$542	
	Lighting - Lay-in	Basement - Engineer Office	4	EA	7	\$0	
	Power Distribution	Basement - Engineer Office	10	EA	6	\$21,249	
	Storage/ Closet	Basement - Engineer Office	90	SF	6	\$653	
	Walls - Concrete Block	Basement - Engineer Office	362	SF	6	\$1,061	
	Walls - Plaster/Drywall	Basement - Engineer Office	174	SF	6	\$480	
	Ceiling - Splined	Basement - inside kitchen	158	SF	6	\$129	
	Doors - Steel Doors incl hw	Basement - inside kitchen	1	EA	6	\$301	
	Floor - Terrazzo	Basement - inside kitchen	158	SF	6	\$346	
	Lighting - Lay-in	Basement - inside kitchen	3	EA	7	\$0	
	Power Distribution	Basement - inside kitchen	4	EA	6	\$8,500	
	Walls - Metal Panel	Basement - inside kitchen	204	SF	6	\$1,523	glass walls
	Walls - Structural Glazed Tile	Basement - inside kitchen	204	SF	6	\$642	
Clinic							
	Ceiling - Lay-in	1st- Rm 110 Nurse	292	SF	6	\$877	
	Doors - Steel Doors incl hw	1st- Rm 110 Nurse	2	EA	6	\$602	
	Floor - Tile/Sheet	1st- Rm 110 Nurse	292	SF	6	\$292	
	Lighting - Lay-in	1st- Rm 110 Nurse	12	EA	7	\$0	
	Walls - Concrete Block	1st- Rm 110 Nurse	705	SF	6	\$2,067	
Kitchen							
	Ceiling - Splined	Basement	2,000	SF	5	\$14,243	stained / missing / dirty / falling out
	Ceiling - Splined	Basement	1,399	SF	6	\$1,300	
	Doors - Steel Doors incl hw	Basement	4	EA	6	\$1,204	
	Floor - Terrazzo	Basement	3,399	SF	6	\$7,437	water on floor from leak at equipment
	Lighting - Lay-in	Basement	69	EA	7	\$0	
	Storage/ Closet	Basement	250	SF	6	\$1,813	
	Storage/ Closet	Basement	356	SF	5	\$5,742	3 coolers - stained conc and plywood floors / ceiling stained
	Storage/ Closet	Basement	109	SF	6	\$790	1 cooler has appropriate flooring
	Walls - Tile Ceramic/ Porcelain	Basement	4,252	SF	6	\$9,607	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Library							
	Casework	2nd - 222	227	LF	6	\$5,733	
	Ceiling - Lay-in	2nd - 222	5,193	SF	6	\$15,595	
	Doors - Side-lite	2nd - 222	10	SF	6	\$167	
	Doors - Store Front	2nd - 222	1	EA	5	\$2,969	1 door handle damaged
	Doors - Store Front	2nd - 222	3	EA	6	\$3,625	
	Floor - Carpet	2nd - 222	2,645	SF	6	\$5,636	
	Floor - Tile	2nd - 222	2,548	SF	6	\$5,575	
	Lighting - Lay-in	2nd - 222	210	EA	7	\$0	
	Storage/ Closet	2nd - 222	2,224	SF	6	\$16,124	
	Storage/ Closet	2nd - 222	25	SF	6	\$181	mech closet inside Library
	Walls - Concrete Block	2nd - 222	1,481	SF	6	\$4,342	
	Walls - Metal Panel	2nd - 222	1,670	SF	6	\$12,466	
Locker/Shower Room							
	Accessories	Basement - Custodian Men	292	SF	6	\$1,144	
	Ceiling - Plaster/ Drywall	Basement - Custodian Men	94	SF	6	\$325	
	Ceiling - Splined (Moister Resistance)	Basement - Custodian Men	292	SF	6	\$305	
	Doors - Steel Doors incl hw	Basement - Custodian Men	1	EA	6	\$301	
	Doors - Steel Doors incl hw	Basement - Custodian Men	1	EA	5	\$1,174	no hardware at door to toilet
	Floor Drain	Basement - Custodian Men	1	EA	6	\$1,059	
	Floor - Tile/Sheet	Basement - Custodian Men	386	SF	6	\$386	
	Lavatory	Basement - Custodian Men	1	EA	6	\$320	
	Lighting - Lay-in	Basement - Custodian Men	11	EA	7	\$0	
	Partitions	Basement - Custodian Men	1	EA	6	\$297	
	Showers	Basement - Custodian Men	1	EA	5	\$2,714	not in use / damaged
	Student Lockers - One Tier	Basement - Custodian Men	29	EA	5	\$4,064	damaged
	Walls - Concrete Block	Basement - Custodian Men	930	SF	6	\$2,726	
	Water Closet	Basement - Custodian Men	1	EA	6	\$336	
	Accessories	Basement - Custodian Women	144	SF	6	\$564	
	Ceiling - Splined (Moister Resistance)	Basement - Custodian Women	144	SF	6	\$150	
	Doors - Steel Doors incl hw	Basement - Custodian Women	2	EA	6	\$602	
	Floor Drain	Basement - Custodian Women	1	EA	6	\$1,059	
	Floor - Tile/Sheet	Basement - Custodian Women	144	SF	6	\$144	
	Lavatory	Basement - Custodian Women	1	EA	6	\$320	
	Lighting - Lay-in	Basement - Custodian Women	2	EA	7	\$0	
	Partitions	Basement - Custodian Women	1	EA	6	\$297	
	Showers	Basement - Custodian Women	1	EA	6	\$311	
	Student Lockers - One Tier	Basement - Custodian Women	7	EA	5	\$981	missing hardware

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/Shower Room							
	Walls - Concrete Block	Basement - Custodian Women	537	SF	6	\$1,574	
	Water Closet	Basement - Custodian Women	1	EA	6	\$336	
	Accessories	Basement - Men Staff Locker - used as storage	126	SF	6	\$494	
	Ceiling - Plaster/ Drywall	Basement - Men Staff Locker - used as storage	126	SF	6	\$436	
	Ceiling - Splined (Moister Resistance)	Basement - Men Staff Locker - used as storage	187	SF	6	\$195	
	Doors - Steel Doors incl hw	Basement - Men Staff Locker - used as storage	2	EA	6	\$602	
	Floor Drain	Basement - Men Staff Locker - used as storage	1	EA	6	\$1,059	
	Floor - Terrazzo	Basement - Men Staff Locker - used as storage	126	SF	6	\$276	
	Floor - Tile/Sheet	Basement - Men Staff Locker - used as storage	187	SF	6	\$187	
	Lavatory	Basement - Men Staff Locker - used as storage	2	EA	6	\$639	
	Lighting - Lay-in	Basement - Men Staff Locker - used as storage	8	EA	7	\$0	
	Partitions	Basement - Men Staff Locker - used as storage	1	EA	6	\$297	
	Showers	Basement - Men Staff Locker - used as storage	1	EA	5	\$2,714	not in use / damaged
	Student Lockers - One Tier	Basement - Men Staff Locker - used as storage	12	EA	5	\$1,682	damaged
	Urinals	Basement - Men Staff Locker - used as storage	1	EA	6	\$336	
	Walls - Concrete Block	Basement - Men Staff Locker - used as storage	437	SF	6	\$1,281	
	Water Closet	Basement - Men Staff Locker - used as storage	1	EA	6	\$336	
	Accessories	Basement - Women Staff Locker	474	SF	6	\$1,857	
	Ceiling - Plaster/ Drywall	Basement - Women Staff Locker	129	SF	6	\$446	
	Ceiling - Splined (Moister Resistance)	Basement - Women Staff Locker	345	SF	6	\$360	
	Doors - Steel Doors incl hw	Basement - Women Staff Locker	2	EA	6	\$602	
	Floor Drain	Basement - Women Staff Locker	1	EA	6	\$1,059	
	Floor - Tile/Sheet	Basement - Women Staff Locker	474	SF	6	\$474	
	Lavatory	Basement - Women Staff Locker	2	EA	6	\$639	
	Lighting - Lay-in	Basement - Women Staff Locker	12	EA	7	\$0	
	Partitions	Basement - Women Staff Locker	1	EA	6	\$297	
	Showers	Basement - Women Staff Locker	1	EA	6	\$311	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/Shower Room							
	Student Lockers - One Tier	Basement - Women Staff Locker	21	EA	5	\$2,943	damaged
	Walls - Concrete Block	Basement - Women Staff Locker	1,097	SF	6	\$3,216	
	Water Closet	Basement - Women Staff Locker	2	EA	6	\$672	
Lunch & Multipurpose Room							
	Ceiling - Lay-in	1st- Rm 104 Genesis Cafe	937	SF	6	\$2,814	
	Doors - Side-lite	1st- Rm 104 Genesis Cafe	6	SF	6	\$100	
	Doors - Steel Doors incl hw	1st- Rm 104 Genesis Cafe	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	1st- Rm 104 Genesis Cafe	937	SF	6	\$1,983	
	Lighting - Lay-in	1st- Rm 104 Genesis Cafe	38	EA	7	\$0	
	Market Board	1st- Rm 104 Genesis Cafe	12	LF	7	\$0	
	Walls - Concrete Block	1st- Rm 104 Genesis Cafe	240	SF	6	\$704	
	Walls - Metal Panel	1st- Rm 104 Genesis Cafe	240	SF	6	\$2,172	folding partition wall
	Walls - Metal Panel	1st- Rm 104 Genesis Cafe	1,016	SF	6	\$7,584	
	Ceiling - Lay-in	3rd - Beta Commons	20	SF	5	\$160	stained
	Ceiling - Lay-in	3rd - Beta Commons	2,796	SF	6	\$8,396	
	Doors - Steel Doors incl hw	3rd - Beta Commons	1	EA	6	\$301	
	Doors - Store Front	3rd - Beta Commons	2	EA	6	\$2,416	
	Doors - Transom Window	3rd - Beta Commons	32	SF	6	\$542	
	Floor - Tile	3rd - Beta Commons	2,816	SF	6	\$6,161	
	Lighting - Lay-in	3rd - Beta Commons	57	EA	7	\$0	1 falling out
	Walls - Concrete Block	3rd - Beta Commons	587	SF	6	\$1,721	
	Walls - Metal Panel	3rd - Beta Commons	442	SF	6	\$3,299	
	Ceiling - Splined	3rd - Beta Serving Area	772	SF	6	\$629	
	Doors - Steel Doors incl hw	3rd - Beta Serving Area	2	EA	6	\$602	
	Floor - Terrazzo	3rd - Beta Serving Area	772	SF	6	\$1,689	
	Lighting - Lay-in	3rd - Beta Serving Area	33	EA	7	\$0	
	Serving Line	3rd - Beta Serving Area	40	LF	6	\$2,381	
	Walls - Tile Ceramic/ Porcelain	3rd - Beta Serving Area	1,325	SF	6	\$2,994	
	Ceiling - Lay-in	3rd - Gamma Commons	401	SF	6	\$1,204	
	Ceiling - Plaster/Drywall	3rd - Gamma Commons	2,897	SF	6	\$10,025	
	Doors - Steel Doors incl hw	3rd - Gamma Commons	1	EA	6	\$301	
	Doors - Store Front	3rd - Gamma Commons	2	EA	6	\$2,416	
	Doors - Transom Window	3rd - Gamma Commons	68	SF	6	\$1,151	
	Floor - Tile	3rd - Gamma Commons	3,298	SF	6	\$7,216	
	Lighting - Lay-in	3rd - Gamma Commons	62	EA	7	\$0	
	Walls - Concrete Block	3rd - Gamma Commons	747	SF	6	\$2,190	
	Walls - Metal Panel	3rd - Gamma Commons	899	SF	6	\$6,711	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lunch & Multipurpose Room							
	Ceiling - Splined	3rd - Gamma Serving area	770	SF	5	\$5,483	bad condition
	Doors - Steel Doors incl hw	3rd - Gamma Serving area	3	EA	6	\$903	
	Floor - Terrazzo	3rd - Gamma Serving area	770	SF	6	\$1,685	
	Lighting - Lay-in	3rd - Gamma Serving area	33	EA	7	\$0	
	Serving Line	3rd - Gamma Serving area	40	LF	6	\$2,381	
	Walls - Tile Ceramic/ Porcelain	3rd - Gamma Serving area	1,325	SF	6	\$2,994	
	Ceiling - Lay-in	3rd - Teachers Cafeteria	420	SF	6	\$1,261	
	Doors - Steel Doors incl hw	3rd - Teachers Cafeteria	2	EA	6	\$602	
	Floor - Tile	3rd - Teachers Cafeteria	420	SF	6	\$919	
	Lighting - Lay-in	3rd - Teachers Cafeteria	9	EA	7	\$0	
	Walls	3rd - Teachers Cafeteria	825		6	\$0	glass walls
MDF_IDF							
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Finishes	1st Floor	113	SF	6	\$806	
	Ventilation and Cooling	1st Floor	1	EA	6	\$1,855	
Mechanical/ Service Rooms							
	Janitor's Closet	1st Floor	54	SF	6	\$387	
	Mechanical/ Service Rooms	1st Floor	276	SF	6	\$1,977	phone/electrical/ & elevator machine rooms
	Storage Room	1st Floor	154	SF	6	\$1,103	
	Vaults	1st Floor	104	SF	6	\$745	in Main Office Suite
	Janitor's Closet	2nd Floor	56	SF	6	\$401	adjacent to mens baths
	Mechanical/ Service Rooms	2nd Floor	126	SF	6	\$903	electrical room by 201 area / closets next to baths - 1 door missing hardware
	Storage Room	2nd Floor	663	SF	6	\$4,750	
	Janitor's Closet	3rd Floor	52	SF	6	\$373	
	Mechanical/ Service Rooms	3rd Floor	202	SF	6	\$1,447	electrical closets
	Storage Room	3rd Floor	711	SF	6	\$5,094	
	Boiler Room	Basement	902	SF	6	\$6,462	
	Interior Stairs	Basement	5	LF	6	\$45	concrete stairs up to loading dock
	Janitor's Closet	Basement	27	SF	6	\$193	
	Loading Docks	Basement	9,286	SF	6	\$66,528	underground drive and parking adjacent to loading dock / 42 surface lights / 6 halide pressure hang lights
	Loading Docks	Basement	418	SF	5	\$6,743	2 - overhead doors / ceiling and walls stained / holes - cracks- peeling - bubbling at ceiling and walls
	Loading Docks	Basement	2,000	SF	5	\$32,261	several holes / cracks at underground conc. drive
	Mechanical/ Service Rooms	Basement	804	SF	6	\$5,760	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechanical/ Service Rooms							
	Mechanical/ Service Rooms	Basement	577	SF	6	\$4,134	garage / compactor room / ceiling and floor damages
	Mechanical/ Service Rooms	Basement	535	SF	5	\$8,630	water on floor from leak / stains at walls and ceiling
	Storage Room	Basement	2,804	SF	6	\$20,089	yard storage
Restroom							
	Accessories	1st Floor	345	SF	6	\$3,182	
	Accessories	1st Floor	345	SF	6	\$3,182	
	Ceiling - Plaster/Drywall	1st Floor	345	SF	6	\$1,194	
	Ceiling - Plaster/Drywall	1st Floor	345	SF	6	\$1,194	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Terrazzo	1st Floor	345	SF	6	\$755	
	Floor - Terrazzo	1st Floor	345	SF	6	\$755	
	Hand Dryer	1st Floor	1	EA	6	\$230	
	Hand Dryer	1st Floor	1	EA	6	\$230	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lighting - Lay-in	1st Floor	8	EA	7	\$0	
	Lighting - Lay-in	1st Floor	8	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	1	EA	6	\$124	open circuit box, exposed wiring near hand dryer
	Partitions	1st Floor	3	EA	6	\$891	
	Partitions	1st Floor	5	EA	6	\$1,485	
	Urinals	1st Floor	3	EA	6	\$1,008	
	Walls - Masonry	1st Floor	525	SF	6	\$1,652	
	Walls - Masonry	1st Floor	525	SF	6	\$1,652	
	Walls - Tile Ceramic/ Porcelain	1st Floor	285	SF	6	\$644	
	Walls - Tile Ceramic/ Porcelain	1st Floor	285	SF	6	\$644	
	Water Closet	1st Floor	6	EA	6	\$2,016	
	Water Closet	1st Floor	3	EA	6	\$1,008	
	Accessories	1st- Main Office Suite- next to Principal	28	SF	6	\$258	
	Ceiling - Plaster/Drywall	1st- Main Office Suite- next to Principal	28	SF	6	\$97	
	Doors - Steel Doors incl hw	1st- Main Office Suite- next to Principal	1	EA	6	\$301	
	Floor - Terrazzo	1st- Main Office Suite- next to Principal	28	SF	6	\$61	
	Lavatory	1st- Main Office Suite- next to Principal	1	EA	6	\$320	
	Lighting - Lay-in	1st- Main Office Suite- next to Principal	1	EA	7	\$0	recessed can
	Walls - Metal Panel	1st- Main Office Suite- next to Principal	204	SF	6	\$1,523	
	Walls - Metal Panel	1st- Main Office Suite- next to Principal	6	SF	5	\$240	damaged

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Water Closet	1st- Main Office Suite- next to Principal	1	EA	6	\$336	
	Accessories	1st- Men's Staff inside Boy's RR	26	SF	6	\$240	
	Ceiling - Plaster/Drywall	1st- Men's Staff inside Boy's RR	26	SF	6	\$90	
	Doors - Steel Doors incl hw	1st- Men's Staff inside Boy's RR	1	EA	6	\$301	
	Floor - Terrazzo	1st- Men's Staff inside Boy's RR	26	SF	6	\$57	
	Lavatory	1st- Men's Staff inside Boy's RR	1	EA	6	\$320	
	Lighting - Lay-in	1st- Men's Staff inside Boy's RR	1	EA	7	\$0	
	Walls - Masonry	1st- Men's Staff inside Boy's RR	80	SF	6	\$252	
	Walls - Plaster/Drywall	1st- Men's Staff inside Boy's RR	80	SF	6	\$221	
	Water Closet	1st- Men's Staff inside Boy's RR	1	EA	6	\$336	
	Accessories	1st- Principals Toilet	28	SF	6	\$258	
	Ceiling - Plaster/Drywall	1st- Principals Toilet	28	SF	6	\$97	
	Doors - Steel Doors incl hw	1st- Principals Toilet	1	EA	6	\$301	
	Floor - Terrazzo	1st- Principals Toilet	28	SF	6	\$61	
	Lavatory	1st- Principals Toilet	1	EA	6	\$320	
	Lighting - Lay-in	1st- Principals Toilet	1	EA	7	\$0	recessed can
	Walls - Plaster/Drywall	1st- Principals Toilet	8	SF	5	\$41	damaged
	Walls - Plaster/Drywall	1st- Principals Toilet	210	SF	6	\$580	
	Water Closet	1st- Principals Toilet	1	EA	6	\$336	
	Accessories	1st- Rm 108- Unisex #1	25	SF	6	\$231	
	Ceiling - Plaster/Drywall	1st- Rm 108- Unisex #1	25	SF	6	\$87	
	Doors - Steel Doors incl hw	1st- Rm 108- Unisex #1	1	EA	6	\$301	
	Floor - Terrazzo	1st- Rm 108- Unisex #1	25	SF	6	\$55	
	Lavatory	1st- Rm 108- Unisex #1	1	EA	6	\$320	
	Lighting - Lay-in	1st- Rm 108- Unisex #1	1	EA	7	\$0	recessed can
	Walls - Plaster/Drywall	1st- Rm 108- Unisex #1	155	SF	6	\$428	
	Walls - Plaster/Drywall	1st- Rm 108- Unisex #1	5	SF	5	\$26	peeling
	Water Closet	1st- Rm 108- Unisex #1	1	EA	6	\$336	
	Accessories	1st- Rm 108- Unisex #2	25	SF	6	\$231	
	Ceiling - Plaster/Drywall	1st- Rm 108- Unisex #2	25	SF	6	\$87	
	Doors - Steel Doors incl hw	1st- Rm 108- Unisex #2	1	EA	6	\$301	
	Floor - Tile	1st- Rm 108- Unisex #2	25	SF	6	\$55	
	Lavatory	1st- Rm 108- Unisex #2	1	EA	6	\$320	
	Lighting - Lay-in	1st- Rm 108- Unisex #2	1	EA	5	\$162	recessed can. Does not work
	Walls - Plaster/Drywall	1st- Rm 108- Unisex #2	2	SF	5	\$10	water damaged
	Walls - Plaster/Drywall	1st- Rm 108- Unisex #2	158	SF	6	\$436	
	Water Closet	1st- Rm 108- Unisex #2	1	EA	6	\$336	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Accessories	1st- Staff Restroom across from Rm1005	30	SF	6	\$277	
	Ceiling - Plaster/Drywall	1st- Staff Restroom across from Rm1005	30	SF	6	\$104	
	Doors - Steel Doors incl hw	1st- Staff Restroom across from Rm1005	1	EA	6	\$301	
	Floor - Terrazzo	1st- Staff Restroom across from Rm1005	30	SF	6	\$66	
	Lavatory	1st- Staff Restroom across from Rm1005	1	EA	6	\$320	
	Lighting - Lay-in	1st- Staff Restroom across from Rm1005	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st- Staff Restroom across from Rm1005	485	SF	6	\$1,339	
	Water Closet	1st- Staff Restroom across from Rm1005	1	EA	6	\$336	
	Accessories	1st- Unisex Staff RR by RM 001	39	SF	6	\$360	
	Ceiling - Plaster/Drywall	1st- Unisex Staff RR by RM 001	39	SF	6	\$135	
	Doors - Steel Doors incl hw	1st- Unisex Staff RR by RM 001	1	EA	6	\$301	
	Floor - Terrazzo	1st- Unisex Staff RR by RM 001	39	SF	6	\$85	
	Lavatory	1st- Unisex Staff RR by RM 001	1	EA	6	\$320	
	Lighting - Lay-in	1st- Unisex Staff RR by RM 001	1	EA	7	\$0	
	Walls - Concrete Block	1st- Unisex Staff RR by RM 001	62	SF	6	\$182	
	Walls - Plaster/Drywall	1st- Unisex Staff RR by RM 001	118	SF	6	\$326	
	Walls - Plaster/Drywall	1st- Unisex Staff RR by RM 001	24	SF	5	\$106	peeling
	Water Closet	1st- Unisex Staff RR by RM 001	1	EA	6	\$336	
	Accessories	1st- Unisex Staff RR#2- across from Rm1005	30	SF	6	\$277	
	Ceiling - Plaster/Drywall	1st- Unisex Staff RR#2- across from Rm1005	30	SF	6	\$104	
	Doors - Steel Doors incl hw	1st- Unisex Staff RR#2- across from Rm1005	1	EA	6	\$301	
	Floor - Terrazzo	1st- Unisex Staff RR#2- across from Rm1005	30	SF	6	\$66	
	Lavatory	1st- Unisex Staff RR#2- across from Rm1005	1	EA	6	\$320	
	Lighting - Lay-in	1st- Unisex Staff RR#2- across from Rm1005	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st- Unisex Staff RR#2- across from Rm1005	5	SF	5	\$26	damaged
	Walls - Plaster/Drywall	1st- Unisex Staff RR#2- across from Rm1005	480	SF	6	\$1,325	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Water Closet	1st- Unisex Staff RR#2- across from Rm1005	1	EA	6	\$336	
	Accessories	1st- Women's staff RR inside Girl's RR	26	SF	6	\$240	
	Ceiling - Plaster/Drywall	1st- Women's staff RR inside Girl's RR	26	SF	5	\$238	water damage
	Doors - Steel Doors incl hw	1st- Women's staff RR inside Girl's RR	1	EA	6	\$301	
	Floor - Terrazzo	1st- Women's staff RR inside Girl's RR	26	SF	6	\$57	
	Lavatory	1st- Women's staff RR inside Girl's RR	1	EA	6	\$320	
	Lighting - Lay-in	1st- Women's staff RR inside Girl's RR	1	EA	7	\$0	
	Walls - Concrete Block	1st- Women's staff RR inside Girl's RR	80	SF	6	\$235	
	Walls - Masonry	1st- Women's staff RR inside Girl's RR	80	SF	6	\$252	
	Water Closet	1st- Women's staff RR inside Girl's RR	1	EA	6	\$336	
	Accessories	2nd - Men staff west	23	SF	6	\$212	
	Ceiling - Plaster/Drywall	2nd - Men staff west	23	SF	6	\$80	
	Doors - Steel Doors incl hw	2nd - Men staff west	1	EA	6	\$301	
	Floor - Terrazzo	2nd - Men staff west	23	SF	6	\$50	
	Lavatory	2nd - Men staff west	1	EA	6	\$320	
	Lighting - Lay-in	2nd - Men staff west	1	EA	7	\$0	recessed can
	Walls - Concrete Block	2nd - Men staff west	157	SF	6	\$460	
	Water Closet	2nd - Men staff west	1	EA	6	\$336	
	Accessories	2nd - Mens East	334	SF	6	\$3,081	
	Ceiling - Plaster/Drywall	2nd - Mens East	334	SF	6	\$1,156	
	Floor Drain	2nd - Mens East	1	EA	6	\$1,059	
	Floor - Terrazzo	2nd - Mens East	334	SF	6	\$731	
	Hand Dryer	2nd - Mens East	1	EA	6	\$230	
	Lavatory	2nd - Mens East	1	EA	5	\$1,590	falling off wall
	Lavatory	2nd - Mens East	2	EA	6	\$639	
	Lighting - Lay-in	2nd - Mens East	8	EA	7	\$0	
	Partitions	2nd - Mens East	3	EA	6	\$891	
	Urinals	2nd - Mens East	3	EA	6	\$1,008	
	Walls - Concrete Block	2nd - Mens East	174	SF	6	\$510	
	Walls - Tile Ceramic/ Porcelain	2nd - Mens East	553	SF	6	\$1,249	
	Water Closet	2nd - Mens East	4	EA	6	\$1,344	
	Accessories	2nd - Mens staff east	24	SF	6	\$221	
	Ceiling - Plaster/Drywall	2nd - Mens staff east	24	SF	6	\$83	
	Doors - Steel Doors incl hw	2nd - Mens staff east	1	EA	6	\$301	
	Floor - Terrazzo	2nd - Mens staff east	24	SF	6	\$53	
	Lavatory	2nd - Mens staff east	1	EA	6	\$320	
	Lighting - Lay-in	2nd - Mens staff east	1	EA	7	\$0	recessed can

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Walls - Concrete Block	2nd - Mens staff east	157	SF	6	\$460	
	Water Closet	2nd - Mens staff east	1	EA	6	\$336	
	Accessories	2nd - Mens West	334	SF	6	\$3,081	
	Ceiling - Plaster/Drywall	2nd - Mens West	334	SF	6	\$1,156	
	Floor Drain	2nd - Mens West	1	EA	6	\$1,059	
	Floor - Terrazzo	2nd - Mens West	334	SF	6	\$731	
	Hand Dryer	2nd - Mens West	1	EA	6	\$230	
	Lavatory	2nd - Mens West	3	EA	6	\$959	
	Lighting - Lay-in	2nd - Mens West	8	EA	7	\$0	
	Partitions	2nd - Mens West	4	EA	6	\$1,188	
	Urinals	2nd - Mens West	3	EA	6	\$1,008	
	Walls - Concrete Block	2nd - Mens West	173	SF	6	\$507	
	Walls - Tile Ceramic/ Porcelain	2nd - Mens West	555	SF	6	\$1,254	
	Water Closet	2nd - Mens West	5	EA	6	\$1,680	
	Accessories	2nd - Unisex by 210	47	SF	6	\$434	
	Ceiling - Plaster/Drywall	2nd - Unisex by 210	47	SF	6	\$163	
	Doors - Steel Doors incl hw	2nd - Unisex by 210	1	EA	6	\$301	
	Floor Drain	2nd - Unisex by 210	1	EA	6	\$1,059	
	Floor - Tile	2nd - Unisex by 210	47	SF	6	\$103	
	Hand Dryer	2nd - Unisex by 210	1	EA	6	\$230	
	Lavatory	2nd - Unisex by 210	1	EA	6	\$320	
	Lighting - Lay-in	2nd - Unisex by 210	1	EA	7	\$0	
	Walls - Plaster/Drywall	2nd - Unisex by 210	249	SF	6	\$687	
	Water Closet	2nd - Unisex by 210	1	EA	6	\$336	
	Accessories	2nd - Unisex by 211	106	SF	6	\$978	
	Ceiling - Plaster/Drywall	2nd - Unisex by 211	106	SF	6	\$367	
	Doors - Steel Doors incl hw	2nd - Unisex by 211	1	EA	6	\$301	
	Floor Drain	2nd - Unisex by 211	1	EA	6	\$1,059	
	Floor - Tile	2nd - Unisex by 211	106	SF	6	\$232	
	Hand Dryer	2nd - Unisex by 211	1	EA	6	\$230	
	Lavatory	2nd - Unisex by 211	1	EA	6	\$320	
	Lighting - Lay-in	2nd - Unisex by 211	2	EA	7	\$0	
	Walls - Plaster/Drywall	2nd - Unisex by 211	398	SF	6	\$1,098	
	Water Closet	2nd - Unisex by 211	1	EA	6	\$336	
	Accessories	2nd - Women staff east	24	SF	6	\$221	
	Ceiling - Plaster/Drywall	2nd - Women staff east	24	SF	6	\$83	
	Doors - Steel Doors incl hw	2nd - Women staff east	1	EA	6	\$301	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Floor - Terrazzo	2nd - Women staff east	24	SF	6	\$53	
	Lavatory	2nd - Women staff east	1	EA	6	\$320	
	Lighting - Lay-in	2nd - Women staff east	1	EA	7	\$0	recessed can
	Walls - Concrete Block	2nd - Women staff east	157	SF	6	\$460	
	Water Closet	2nd - Women staff east	1	EA	6	\$336	
	Accessories	2nd - Women staff west	24	SF	6	\$221	
	Ceiling - Plaster/Drywall	2nd - Women staff west	24	SF	6	\$83	
	Doors - Steel Doors incl hw	2nd - Women staff west	1	EA	6	\$301	
	Floor - Terrazzo	2nd - Women staff west	24	SF	6	\$53	
	Lavatory	2nd - Women staff west	1	EA	6	\$320	
	Lighting - Lay-in	2nd - Women staff west	1	EA	7	\$0	recessed can
	Walls - Concrete Block	2nd - Women staff west	157	SF	6	\$460	
	Water Closet	2nd - Women staff west	1	EA	6	\$336	
	Accessories	2nd - Women's East Side	334	SF	6	\$3,081	
	Ceiling - Plaster/Drywall	2nd - Women's East Side	334	SF	6	\$1,156	
	Floor Drain	2nd - Women's East Side	1	EA	6	\$1,059	
	Floor - Terrazzo	2nd - Women's East Side	47	SF	6	\$103	
	Floor - Tile/Sheet	2nd - Women's East Side	287	SF	6	\$287	
	Hand Dryer	2nd - Women's East Side	1	EA	6	\$230	
	Lavatory	2nd - Women's East Side	3	EA	6	\$959	
	Lighting - Lay-in	2nd - Women's East Side	8	EA	7	\$0	
	Partitions	2nd - Women's East Side	3	EA	6	\$891	
	Walls - Concrete Block	2nd - Women's East Side	173	SF	6	\$507	
	Walls - Tile Ceramic/ Porcelain	2nd - Women's East Side	556	SF	6	\$1,256	
	Water Closet	2nd - Women's East Side	4	EA	6	\$1,344	
	Accessories	2nd - Women's West Side	334	SF	6	\$3,081	
	Ceiling - Plaster/Drywall	2nd - Women's West Side	334	SF	6	\$1,156	
	Floor Drain	2nd - Women's West Side	1	EA	6	\$1,059	
	Floor - Terrazzo	2nd - Women's West Side	47	SF	6	\$103	
	Floor - Tile/Sheet	2nd - Women's West Side	287	SF	6	\$287	
	Hand Dryer	2nd - Women's West Side	1	EA	6	\$230	
	Lavatory	2nd - Women's West Side	3	EA	6	\$959	
	Lighting - Lay-in	2nd - Women's West Side	8	EA	7	\$0	
	Partitions	2nd - Women's West Side	4	EA	6	\$1,188	some panels damages
	Walls - Concrete Block	2nd - Women's West Side	173	SF	6	\$507	
	Walls - Tile Ceramic/ Porcelain	2nd - Women's West Side	556	SF	6	\$1,256	
	Water Closet	2nd - Women's West Side	5	EA	6	\$1,680	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Accessories	3rd - Men's East Side	332	SF	6	\$3,062	
	Ceiling - Plaster/Drywall	3rd - Men's East Side	332	SF	6	\$1,149	
	Floor Drain	3rd - Men's East Side	1	EA	6	\$1,059	
	Floor - Terrazzo	3rd - Men's East Side	332	SF	6	\$726	
	Hand Dryer	3rd - Men's East Side	1	EA	6	\$230	
	Lavatory	3rd - Men's East Side	3	EA	6	\$959	
	Lighting - Lay-in	3rd - Men's East Side	8	EA	7	\$0	
	Partitions	3rd - Men's East Side	3	EA	6	\$891	
	Urinals	3rd - Men's East Side	3	EA	6	\$1,008	
	Walls - Concrete Block	3rd - Men's East Side	173	SF	6	\$507	
	Walls - Tile Ceramic/ Porcelain	3rd - Men's East Side	553	SF	6	\$1,249	
	Water Closet	3rd - Men's East Side	4	EA	6	\$1,344	
	Accessories	3rd - Mens inside 310	30	SF	6	\$277	
	Ceiling - Plaster/Drywall	3rd - Mens inside 310	30	SF	6	\$104	metal panel
	Doors - Steel Doors incl hw	3rd - Mens inside 310	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd - Mens inside 310	30	SF	6	\$30	
	Lavatory	3rd - Mens inside 310	1	EA	6	\$320	
	Lighting - Lay-in	3rd - Mens inside 310	1	EA	7	\$0	recessed can
	Walls - Metal Panel	3rd - Mens inside 310	179	SF	6	\$1,336	
	Water Closet	3rd - Mens inside 310	1	EA	6	\$336	
	Accessories	3rd - Men's West Side	287	SF	6	\$2,647	
	Ceiling - Plaster/Drywall	3rd - Men's West Side	334	SF	6	\$1,156	
	Floor Drain	3rd - Men's West Side	1	EA	6	\$1,059	
	Floor - Terrazzo	3rd - Men's West Side	334	SF	6	\$731	
	Hand Dryer	3rd - Men's West Side	1	EA	6	\$230	
	Lavatory	3rd - Men's West Side	3	EA	6	\$959	
	Lighting - Lay-in	3rd - Men's West Side	8	EA	7	\$0	
	Partitions	3rd - Men's West Side	2	EA	5	\$1,502	graffiti/damage
	Partitions	3rd - Men's West Side	3	EA	6	\$891	
	Urinals	3rd - Men's West Side	3	EA	6	\$1,008	
	Walls - Concrete Block	3rd - Men's West Side	176	SF	6	\$516	
	Walls - Tile Ceramic/ Porcelain	3rd - Men's West Side	555	SF	6	\$1,254	
	Water Closet	3rd - Men's West Side	5	EA	6	\$1,680	
	Accessories	3rd - Staff in men's west bath corridor	24	SF	6	\$221	
	Ceiling - Plaster/Drywall	3rd - Staff in men's west bath corridor	24	SF	6	\$83	
	Doors - Steel Doors incl hw	3rd - Staff in men's west bath corridor	1	EA	6	\$301	
	Floor - Terrazzo	3rd - Staff in men's west bath corridor	24	SF	6	\$53	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Lavatory	3rd - Staff in men's west bath corridor	1	EA	6	\$320	
	Lighting - Lay-in	3rd - Staff in men's west bath corridor	1	EA	7	\$0	recessed can
	Walls - Concrete Block	3rd - Staff in men's west bath corridor	158	SF	6	\$463	
	Water Closet	3rd - Staff in men's west bath corridor	1	EA	6	\$336	
	Accessories	3rd - Staff Unisex in Mens east corridor	24	SF	6	\$221	
	Ceiling - Plaster/Drywall	3rd - Staff Unisex in Mens east corridor	24	SF	6	\$83	
	Doors - Steel Doors incl hw	3rd - Staff Unisex in Mens east corridor	1	EA	6	\$301	
	Floor - Terrazzo	3rd - Staff Unisex in Mens east corridor	24	SF	6	\$53	
	Lavatory	3rd - Staff Unisex in Mens east corridor	1	EA	6	\$320	
	Lighting - Lay-in	3rd - Staff Unisex in Mens east corridor	1	EA	7	\$0	recessed can
	Walls - Concrete Block	3rd - Staff Unisex in Mens east corridor	157	SF	6	\$460	
	Water Closet	3rd - Staff Unisex in Mens east corridor	1	EA	6	\$336	
	Accessories	3rd - Unisex in women's east corridor	23	SF	6	\$212	
	Ceiling - Plaster/Drywall	3rd - Unisex in women's east corridor	23	SF	6	\$80	
	Doors - Steel Doors incl hw	3rd - Unisex in women's east corridor	1	EA	6	\$301	
	Floor - Terrazzo	3rd - Unisex in women's east corridor	23	SF	6	\$50	
	Lavatory	3rd - Unisex in women's east corridor	1	EA	6	\$320	
	Lighting - Lay-in	3rd - Unisex in women's east corridor	1	EA	7	\$0	recessed can
	Walls - Concrete Block	3rd - Unisex in women's east corridor	157	SF	6	\$460	
	Water Closet	3rd - Unisex in women's east corridor	1	EA	6	\$336	
	Accessories	3rd - Unisex inside 322	30	SF	6	\$277	
	Accessories	3rd - Unisex inside 322	38	SF	6	\$350	
	Ceiling - Plaster/Drywall	3rd - Unisex inside 322	38	SF	6	\$132	
	Ceiling - Plaster/Drywall	3rd - Unisex inside 322	30	SF	6	\$104	
	Doors - Steel Doors incl hw	3rd - Unisex inside 322	1	EA	6	\$301	
	Doors - Steel Doors incl hw	3rd - Unisex inside 322	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd - Unisex inside 322	30	SF	6	\$30	
	Floor - Tile/Sheet	3rd - Unisex inside 322	38	SF	6	\$38	
	Lavatory	3rd - Unisex inside 322	1	EA	6	\$320	
	Lavatory	3rd - Unisex inside 322	1	EA	5	\$1,590	faucet damaged
	Lighting - Lay-in	3rd - Unisex inside 322	1	EA	7	\$0	recessed can
	Lighting - Lay-in	3rd - Unisex inside 322	1	EA	7	\$0	recessed can
	Walls - Metal Panel	3rd - Unisex inside 322	179	SF	6	\$1,336	
	Walls - Metal Panel	3rd - Unisex inside 322	180	SF	6	\$1,344	
	Water Closet	3rd - Unisex inside 322	1	EA	6	\$336	
	Water Closet	3rd - Unisex inside 322	1	EA	6	\$336	
	Accessories	3rd - Unisex inside women's west corridor	49	SF	6	\$452	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Ceiling - Plaster/Drywall	3rd - Unisex inside women's west corridor	49	SF	6	\$170	
	Doors - Steel Doors incl hw	3rd - Unisex inside women's west corridor	1	EA	6	\$301	
	Floor - Terrazzo	3rd - Unisex inside women's west corridor	49	SF	6	\$107	
	Lavatory	3rd - Unisex inside women's west corridor	1	EA	6	\$320	
	Lighting - Lay-in	3rd - Unisex inside women's west corridor	1	EA	7	\$0	recessed can
	Walls - Concrete Block	3rd - Unisex inside women's west corridor	157	SF	6	\$460	
	Water Closet	3rd - Unisex inside women's west corridor	1	EA	6	\$336	
	Accessories	3rd - Women East Side	334	SF	6	\$3,081	
	Ceiling	3rd - Women East Side	334		6	\$0	
	Floor Drain	3rd - Women East Side	1	EA	6	\$1,059	
	Floor - Terrazzo	3rd - Women East Side	47	SF	6	\$103	
	Floor - Tile/Sheet	3rd - Women East Side	287	SF	6	\$287	
	Hand Dryer	3rd - Women East Side	1	EA	6	\$230	
	Lavatory	3rd - Women East Side	3	EA	6	\$959	
	Lighting - Lay-in	3rd - Women East Side	8	EA	7	\$0	
	Partitions	3rd - Women East Side	3	EA	6	\$891	
	Walls - Concrete Block	3rd - Women East Side	173	SF	6	\$507	
	Walls - Tile Ceramic/ Porcelain	3rd - Women East Side	556	SF	6	\$1,256	
	Water Closet	3rd - Women East Side	4	EA	6	\$1,344	
	Accessories	3rd - Women inside 310	30	SF	6	\$277	
	Ceiling - Plaster/Drywall	3rd - Women inside 310	30	SF	6	\$104	metal panel
	Doors - Steel Doors incl hw	3rd - Women inside 310	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd - Women inside 310	30	SF	6	\$30	
	Lavatory	3rd - Women inside 310	1	EA	6	\$320	
	Lighting - Lay-in	3rd - Women inside 310	1	EA	7	\$0	recessed can
	Walls - Metal Panel	3rd - Women inside 310	179	SF	6	\$1,336	
	Water Closet	3rd - Women inside 310	1	EA	6	\$336	
	Accessories	3rd - Women West Side	334	SF	6	\$3,081	
	Ceiling - Plaster/Drywall	3rd - Women West Side	334	SF	6	\$1,156	
	Floor Drain	3rd - Women West Side	1	EA	6	\$1,059	
	Floor - Terrazzo	3rd - Women West Side	47	SF	6	\$103	
	Floor - Tile/Sheet	3rd - Women West Side	287	SF	6	\$287	

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Hand Dryer	3rd - Women West Side	1	EA	6	\$230	
	Lavatory	3rd - Women West Side	3	EA	6	\$959	
	Lighting - Lay-in	3rd - Women West Side	8	EA	7	\$0	
	Partitions	3rd - Women West Side	4	EA	6	\$1,188	
	Walls - Concrete Block	3rd - Women West Side	173	SF	6	\$507	
	Walls - Tile Ceramic/ Porcelain	3rd - Women West Side	556	SF	6	\$1,256	
	Water Closet	3rd - Women West Side	5	EA	6	\$1,680	
	Accessories	Basement - inside Engineers Office	78	SF	6	\$719	
	Ceiling - Plaster/Drywall	Basement - inside Engineers Office	78	SF	6	\$270	
	Doors - Steel Doors incl hw	Basement - inside Engineers Office	1	EA	5	\$1,174	no hardware
	Floor Drain	Basement - inside Engineers Office	1	EA	6	\$1,059	
	Floor - Terrazzo	Basement - inside Engineers Office	78	SF	6	\$171	
	Lavatory	Basement - inside Engineers Office	1	EA	6	\$320	lav in base cabinet
	Lighting - Lay-in	Basement - inside Engineers Office	1	EA	7	\$0	
	Partitions	Basement - inside Engineers Office	1	EA	6	\$297	
	Showers	Basement - inside Engineers Office	1	EA	6	\$311	
	Urinals	Basement - inside Engineers Office	1	EA	6	\$336	
	Walls - Concrete Block	Basement - inside Engineers Office	292	SF	6	\$856	
	Water Closet	Basement - inside Engineers Office	1	EA	6	\$336	
	Accessories	Basement - Unisex	28	SF	6	\$258	
	Ceiling - Plaster/Drywall	Basement - Unisex	28	SF	6	\$97	
	Doors - Steel Doors incl hw	Basement - Unisex	1	EA	6	\$301	
	Floor - Terrazzo	Basement - Unisex	28	SF	6	\$61	
	Lavatory	Basement - Unisex	1	EA	6	\$320	
	Lighting - Lay-in	Basement - Unisex	1	EA	7	\$0	
	Walls - Concrete Block	Basement - Unisex	168	SF	6	\$492	
	Water Closet	Basement - Unisex	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$1,830,983

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	7,387	SF	6	\$22,183	
	Ceiling - Plaster/Drywall	1st Floor	1,160	SF	6	\$7,183	
	Ceiling - Splined	1st Floor	11,379	SF	6	\$32,869	

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Doors - Side-lite	1st Floor	544	EA	6	\$9,094	
	Doors - Store Front	1st Floor	17	EA	6	\$20,540	
	Doors - Transom Window	1st Floor	180	EA	6	\$3,048	
	Drinking Fountains	1st Floor	7	EA	6	\$0	
	Floor - Terrazzo	1st Floor	60	SF	5	\$3,139	
	Floor - Terrazzo	1st Floor	20,537	SF	6	\$172,390	
	Lighting - Lay-in	1st Floor	415	EA	7	\$0	
	Student Lockers - One Tier	1st Floor	106	EA	6	\$9,841	
	Student Lockers - Two Tiers	1st Floor	320	EA	6	\$14,854	
	Walls - Masonry	1st Floor	8,364	SF	6	\$26,313	
	Walls - Metal Panel	1st Floor	5,372	SF	6	\$40,100	
	Walls - Plaster/Drywall	1st Floor	9,076	SF	6	\$40,234	
	Ceiling - Lay-in	2nd Floor	8,572	SF	6	\$25,742	
	Ceiling - Plaster/Drywall	2nd Floor	1,348	SF	6	\$8,347	
	Doors - Side-lite	2nd Floor	148	EA	6	\$2,474	
	Doors - Store Front	2nd Floor	8	EA	6	\$9,666	
	Doors - Transom Window	2nd Floor	72	EA	6	\$1,219	
	Drinking Fountains - Single Fountain	2nd Floor	5	EA	6	\$1,379	
	Floor - Terrazzo	2nd Floor	728	SF	6	\$6,111	
	Floor - Tile/Sheet	2nd Floor	9,192	SF	6	\$4,995	
	Lighting - Lay-in	2nd Floor	315	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	349	EA	6	\$32,400	
	Walls - Concrete Block	2nd Floor	1,982	SF	6	\$5,810	
	Walls - Masonry	2nd Floor	360	SF	6	\$1,133	
	Walls - Metal Panel	2nd Floor	6,862	SF	6	\$51,222	
	Ceiling - Lay-in	3rd Floor	11,418	SF	6	\$34,288	
	Ceiling - Plaster/Drywall	3rd Floor	1,143	SF	6	\$7,077	
	Doors - Side-lite	3rd Floor	168	EA	6	\$2,808	
	Doors - Store Front	3rd Floor	8	EA	6	\$9,666	
	Doors - Transom Window	3rd Floor	72	EA	6	\$1,219	
	Drinking Fountains - Single Fountain	3rd Floor	8	EA	6	\$2,206	
	Floor - Terrazzo	3rd Floor	728	SF	6	\$6,111	
	Floor - Tile/Sheet	3rd Floor	11,833	SF	6	\$6,430	
	Lighting - Lay-in	3rd Floor	284	EA	7	\$0	
	Student Lockers - One Tier	3rd Floor	510	EA	6	\$47,346	
	Walls - Concrete Block	3rd Floor	2,351	SF	6	\$6,892	
	Walls - Masonry	3rd Floor	350	SF	6	\$1,101	

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Walls - Metal Panel	3rd Floor	10,400	SF	6	\$77,632	
	Walls - Plaster/Drywall	3rd Floor	800	SF	6	\$3,546	
	Ceiling - Exposed	Basement	1,770	SF	6	\$2,632	
	Ceiling - Plaster/Drywall	Basement	750	SF	6	\$4,644	
	Ceiling - Splined	Basement	957	SF	5	\$6,815	
	Doors - Steel Doors incl hw	Basement	7	EA	6	\$2,107	
	Drinking Fountains - Single Fountain	Basement	1	EA	6	\$276	
	Floor - Terrazzo	Basement	1,050	SF	6	\$8,814	
	Floor - Tile/Sheet	Basement	2,615	SF	6	\$1,421	
	Lighting - Lay-in	Basement	49	EA	7	\$0	
	Walls - Concrete Block	Basement	5,046	SF	6	\$14,792	
	Walls - Masonry	Basement	1,883	SF	6	\$5,924	
Safety							
	Camera Viewing Station	1st Floor	4	EA	6	\$2,730	viewed in Principal, Asst Principal, Police & Security offices
	Metal Dedector	1st Floor	3	EA	6	\$2,642	
	Security Cameras	1st Floor / Entire Building	3	EA	6	\$582	
	Security Cameras	1st Floor / Entire Building	29	EA	6	\$5,627	
Stairs							
	Floor - Terrazzo	Center stair - 1st to Basement	86	SF	6	\$722	
	Handrails	Center stair - 1st to Basement	77	LF	6	\$667	
	Stairs - Terrazzo	Center stair - 1st to Basement	24	LF	6	\$223	
	Walls - Masonry	Center stair - 1st to Basement	118	SF	6	\$371	
	Ceiling - Plaster/Drywall	North East	424	SF	6	\$3,104	
	Floor - Terrazzo	North East	184	SF	6	\$1,545	
	Handrails	North East	117	LF	6	\$1,014	
	Lighting - Lay-in	North East	6	EA	7	\$0	
	Stairs - Terrazzo	North East	48	LF	6	\$445	
	Walls	North East	388	SF	6	\$0	
	Walls - Masonry	North East	844	SF	6	\$2,655	
	Ceiling - Plaster/Drywall	North West	424	SF	6	\$3,104	
	Floor - Terrazzo	North West	184	SF	6	\$1,545	
	Handrails	North West	117	LF	6	\$1,014	
	Lighting - Lay-in	North West	6	EA	7	\$0	
	Stairs - Terrazzo	North West	48	LF	6	\$445	
	Walls	North West	388	SF	6	\$0	
	Walls - Masonry	North West	844	SF	6	\$2,655	

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Ceiling - Plaster/Drywall	South East	320	SF	6	\$2,343	
	Floor - Terrazzo	South East	320	SF	6	\$2,686	
	Handrails	South East	205	LF	6	\$1,776	
	Lighting	South East	8	EA	7	\$0	
	Stairs - Terrazzo	South East	96	LF	6	\$891	
	Walls - Masonry	South East	1,400	SF	6	\$4,404	
	Ceiling - Plaster/Drywall	South West	240	SF	6	\$1,757	
	Floor - Terrazzo	South West	240	SF	6	\$2,015	
	Handrails	South West	157	LF	6	\$1,361	
	Lighting - Lay-in	South West	6	EA	7	\$0	
	Stairs - Terrazzo	South West	72	LF	6	\$668	
	Walls - Masonry	South West	1,050	SF	6	\$3,303	
Vertical Conveyance							
	Elevator - Hydraulic Elevator	East	1	EA	6	\$19,238	motor was being replaced during the site assessment
	Elevator - Hydraulic Elevator	West	1	EA	5	\$86,984	door not sliding properly

Building Interior Subtotal: \$964,548

Total Building Cost \$9,434,567

Building: Fine Arts Building

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	#5- W	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#6- NE	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#7- NE	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#8- W	2	EA	6	\$1,263	
	Exterior Doors - Exterior Steel Door	#10- SW	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#11- NW	1	EA	6	\$481	
	Exterior Doors - Transom Lite	#5- W	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#6- NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#7- NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#8- W	1	EA	6	\$313	

Building: Fine Arts Building

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Foundation							
	Foundation - Concrete	Entire Building	647	LF	7	\$0	
	Foundation - Concrete	Entire Building	10	LF	5	\$5,519	seepage
	Superstructure - Steel	Entire Building	27,456	SF	7	\$0	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
Roof System							
	Coping - Metal	Link roof	64	LF	6	\$2,056	
	Coping - Metal	Main Roof	640	LF	6	\$20,555	rust
	Downspouts - Interior Downspouts	Link roof	12	LF	6	\$399	
	Downspouts - Interior Downspouts	Main Roof	333	LF	6	\$11,067	
	Parapet - 16" - 30" Height	Main Roof	640	LF	6	\$25,571	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Link roof	1,001	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	25,225	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Link roof	1,001	SF	4	\$28,056	blisters - not accessible
	Roof - Asphalt Gravel Ballast	Main Roof	25,225	SF	4	\$707,006	blisters, water ponding, bubbles, brittle
Walls							
	Exterior Walls - Brick	Entire Building	21,139	SF	6	\$142,075	caulk wall to sidewalk abutments to avoid water intrusion.
	Exterior Walls - Brick	Entire Building / Façade- NE	2	SF	4	\$329	missing
	Exterior Walls - Brick	Entire Building / Façade- NW	2	SF	4	\$329	missing
	Exterior Walls - Brick	Entire Building / Façade- SE	4	SF	4	\$659	cracked, missing
	Exterior Walls - Brick	Entire Building / South Façade	130	SF	5	\$3,095	step cracks, open joints
Windows							
	Curtain wall - Glazed Single Pane	Entire Building	3,100	SF	5	\$138,088	poor glazing & seals
	Curtain wall - Windows	Entire Building	532	SF	5	\$33,884	poor seals & glazing
	Lintels - Steel	Entire Building	18	LF	6	\$523	

Building Exterior Subtotal:

\$1,128,401

Building: Fine Arts Building

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System							
	Exit Signs - Auditorium	Entire Building / 1st Floor	6	EA	6	\$898	
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	\$898	

Building: Fine Arts Building

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System							
	Security System - CCTV	Entire Building	27,456	SF	6	\$8,245	
	Security System - Intrusion Detection	Entire Building	27,456	SF	6	\$7,067	
Main Service							
	Main Electrical Service - 1000 A 120/240/3PH	Basement	1	EA	6	\$4,540	
	PA System	Entire Building	27,456	SF	6	\$9,030	Serves all three buildings (Location: Main Building)
Power Distribution							
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Radio/TV Classroom
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Backstage
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Radio/TV Classroom
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	5	\$0	Location: Main Electrical Room (Main Buss Cover Missing & Shock Hazard)
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Main Distribution Panels - Greater than 600 amp	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Main Distribution Panels - Less than 400 amp	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Transformers - 277/480 - 120/208	Entire Building / 1st Floor	1	EA	6	\$1,265	Location: Main Electrical Room
	Transformers - 277/480 - 120/208	Entire Building / 1st Floor	1	EA	6	\$1,265	Location: Main Electrical Room

Electrical System Subtotal:

\$33,210

Building: Fine Arts Building

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm							
	Fire Alarm Strobe Lights	Entire Building	27,456	SF	6	\$9,816	

Building: Fine Arts Building

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm							
	Fire Alarm_System	Entire Building	27,456	SF	6	\$13,349	
Sprinkler System							
	Sprinkler Heads	Entire Building	27,456	SF	6	\$0	
	Sprinkler Piping	Entire Building	27,456	SF	6	\$5,104	
	Wet Sprinkler System	Entire Building	27,456	SF	6	\$7,067	

Safty System Subtotal: \$35,336

Building: Fine Arts Building

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Handling Systems							
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	5	\$39,774	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	5	\$39,774	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	5	\$39,774	PVC Traps, Drainlines either broken off, missing, not connected or cut off at unit & Impalement hazards
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons	Roof	1	EA	5	\$17,658	Unit Dented, Square Ductwork Rusted, Soft, Leaking Air at Reducing Fitting

Temperature Control

	DDC System	Entire Building	27,456	SF	6	\$15,705	
	Thermostats - DDC	Entire Building	18	EA	6	\$0	

Ventilation

	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	7	\$0	

Mechanical System Subtotal: \$152,684

Building: Fine Arts Building

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

Building: Fine Arts Building

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Water							
	Gas Heater - 300001 - 600000 BTU/HR	Basement	2	EA	5	\$4,498	
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	27,456	SF	6	\$6,675	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	27,456	SF	6	\$5,104	
	Domestic Piping-Hot Water Return Lines	Entire Building	27,456	SF	6	\$3,926	
	Sanitary Piping	Entire Building	27,456	SF	6	\$25,128	
	Storm Piping	Entire Building	27,456	SF	6	\$23,950	
	Vent Piping	Entire Building	27,456	SF	6	\$18,453	

Plumbing System Subtotal: \$87,734

Building: Fine Arts Building

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #150 (Music Room)							
	Ceiling - Lay-in	1st Floor	714	SF	6	\$2,144	
	Chalk Board	1st Floor	10	LF	4	\$918	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Doors - Transom Window	1st Floor	4	SF	6	\$68	solid panel
	Floor - Carpet	1st Floor	714	SF	6	\$1,521	
	Floor - Carpet	1st Floor	1	SF	6	\$3	Has a open pipe or drain hole in floor. Could be a trip hazard.
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Concrete Block	1st Floor	2,580	SF	6	\$7,563	
Classroom #151 (Music Room)							
	Ceiling - Splined	1st Floor	1,206	SF	6	\$983	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor - Carpet	1st Floor	491	SF	6	\$1,046	
	Floor - Tile	1st Floor	715	SF	6	\$1,564	
	Lighting - Lay-in	1st Floor	39	EA	7	\$0	recessed cans
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,782	SF	6	\$5,224	Includes 3 practice booths
	Walls - Plaster/Drywall	1st Floor	570	SF	6	\$1,573	

Building: Fine Arts Building

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #152 (Music Room)							
	Ceiling - Splined	1st Floor	1,206	SF	6	\$983	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Carpet	1st Floor	419	SF	6	\$893	
	Floor - Tile	1st Floor	715	SF	6	\$1,564	
	Lighting - Lay-in	1st Floor	39	EA	7	\$0	recessed cans
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,782	SF	6	\$5,224	Includes 3 practice booths
	Walls - Plaster/Drywall	1st Floor	570	SF	6	\$1,573	
Classroom #160 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	756	SF	6	\$2,270	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	solid panel
	Floor - Exposed	1st Floor	60	SF	6	\$32	metal catwalk going around room, leading to storage
	Floor - Tile	1st Floor	756	SF	6	\$1,654	
	Lighting - Lay-in	1st Floor	20	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	1	EA	6	\$124	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	308	SF	6	\$2,233	storage up above classroom
	Walls - Concrete Block	1st Floor	2,640	SF	6	\$7,739	
Classroom #165 (Special Program)							
	Ceiling - Lay-in	1st Floor	480	SF	6	\$1,441	
	Chalk Board	1st Floor	6	LF	4	\$551	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Doors - Transom Window	1st Floor	6	SF	6	\$102	
	Floor - Carpet	1st Floor	480	SF	6	\$1,023	
	Lighting - Lay-in	1st Floor	10	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Concrete Block	1st Floor	2,124	SF	6	\$6,227	

Classrooms Subtotal:

\$58,551

Building: Fine Arts Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

Building: Fine Arts Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Auditorium & Theater							
	Ceiling - Exposed	1st Floor	2,733	SF	6	\$4,065	over stage
	Ceiling - Plaster/Drywall	1st Floor	7,073	SF	6	\$58,967	
	Doors - Steel Doors incl hw	1st Floor	6	EA	6	\$1,806	
	Floor - Carpet	1st Floor	7,073	SF	5	\$36,311	Carpet is very stained
	Floor - Wood	1st Floor	2,733	SF	6	\$19,267	stage floor
	Lighting - Lay-in	1st Floor	47	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	6	EA	6	\$743	
	Main Floor Seating	1st Floor	798	EA	6	\$138,785	
	Sound System	1st Floor	1	EA	6	\$10,721	
	Stage	1st Floor	2,733	SF	6	\$15,789	
	Stage Curtain	1st Floor	4	EA	6	\$0	
	Stage Lighting System	1st Floor	1	EA	7	\$0	
	Stage-Stairs - Wood	1st Floor	14	LF	6	\$164	Movable stairs
	Stairs - Wood	1st Floor	50	LF	6	\$587	Carpet stairs
	Walls - Concrete Block	1st Floor	5,248	SF	6	\$15,385	stage walls
	Walls - Masonry	1st Floor	7,966	SF	6	\$25,061	
	Ceiling - Exposed	Backstage area (Rm 154 on map)	150	SF	5	\$412	ceiling in stairwell is leaking & causing damage to landings below & nearby wall
	Ceiling - Splined	Backstage area (Rm 154 on map)	839	SF	6	\$684	
	Doors - Steel Doors incl hw	Backstage area (Rm 154 on map)	2	EA	6	\$602	2 huge rolling metal doors
	Floor - Concrete	Backstage area (Rm 154 on map)	988	SF	6	\$523	
	Floor - Terrazzo	Backstage area (Rm 154 on map)	113	SF	6	\$247	stair landings
	Lighting - Lay-in	Backstage area (Rm 154 on map)	16	EA	7	\$0	
	Lighting - Lay-in	Backstage area (Rm 154 on map)	6	EA	7	\$0	recessed cans in stairwell
	Lighting - Wall Mounted	Backstage area (Rm 154 on map)	1	EA	7	\$0	in stairwell
	Stage Lift	Backstage area (Rm 154 on map)	1	EA	5	\$18,165	Not working even after a \$7,000 repair was done.
	Stairs - Terrazzo	Backstage area (Rm 154 on map)	69	LF	6	\$528	stairwell goes to room 160, stage lift, exterior door & roof.
	Storage/ Closet	Backstage area (Rm 154 on map)	61	SF	6	\$442	
	Walls - Concrete Block	Backstage area (Rm 154 on map)	6	SF	5	\$85	ceiling in stairwell is leaking & causing damage to wall, near roof
	Walls - Concrete Block	Backstage area (Rm 154 on map)	4,026	SF	6	\$11,802	
	Ceiling - Splined	Projection Room for Auditorium	8	SF	5	\$77	ceiling tiles missing
	Ceiling - Splined	Projection Room for Auditorium	418	SF	6	\$341	
	Doors - Steel Doors incl hw	Projection Room for Auditorium	1	EA	6	\$301	
	Floor - Tile	Projection Room for Auditorium	426	SF	6	\$932	
	Lighting - Lay-in	Projection Room for Auditorium	7	EA	7	\$0	
	Walls - Concrete Block	Projection Room for Auditorium	1,500	SF	6	\$4,397	

Building: Fine Arts Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechanical/ Service Rooms							
	Janitor's Closet	1st Floor	25	SF	6	\$179	Inside Men's RR
	Mechanical/ Service Rooms	1st Floor	479	SF	6	\$3,432	2 electrical rooms off back of auditorium + phone wiring room + a pump closet
	Storage Room	1st Floor	82	SF	6	\$587	1 on each side of auditorium
	Mechanical/ Service Rooms	Basement	474	SF	6	\$3,396	2 machine rooms + 1 sump pump room + 1 stage curtain pulley room
	Storage Room	Basement	48	SF	6	\$344	
Prep Room							
	Ceiling - Lay-in	1st- Boy's Dressing Room	228	SF	6	\$685	
	Doors - Steel Doors incl hw	1st- Boy's Dressing Room	1	EA	6	\$301	
	Floor - Tile	1st- Boy's Dressing Room	228	SF	6	\$499	
	Lighting - Lay-in	1st- Boy's Dressing Room	8	EA	7	\$0	can lights
	Walls - Concrete Block	1st- Boy's Dressing Room	496	SF	6	\$1,454	
	Ceiling - Lay-in	1st- Girl's Dressing Room	198	SF	5	\$1,178	tiles missing & damaged
	Doors - Steel Doors incl hw	1st- Girl's Dressing Room	1	EA	6	\$301	
	Doors - Transom Window	1st- Girl's Dressing Room	9	SF	6	\$152	solid panel
	Floor - Tile	1st- Girl's Dressing Room	198	SF	6	\$433	
	Lighting - Lay-in	1st- Girl's Dressing Room	7	EA	7	\$0	recessed cans
	Walls - Concrete Block	1st- Girl's Dressing Room	456	SF	6	\$1,337	
	Ceiling - Plaster/Drywall	1st- Make-Up Room	247	SF	6	\$855	
	Doors - Steel Doors incl hw	1st- Make-Up Room	2	EA	6	\$602	
	Floor - Tile	1st- Make-Up Room	247	SF	6	\$540	
	Lighting - Lay-in	1st- Make-Up Room	10	EA	7	\$0	can lights
	Lighting - Wall Mounted	1st- Make-Up Room	19	EA	7	\$0	
	Walls - Concrete Block	1st- Make-Up Room	552	SF	6	\$1,618	
	Work Sink	1st- Make-Up Room	2	EA	6	\$758	1 is missing a handle on faucet
Restroom							
	Accessories	1st- Boy's (inside Boy's Dressing Room)	101	SF	6	\$932	
	Ceiling - Plaster/Drywall	1st- Boy's (inside Boy's Dressing Room)	101	SF	6	\$350	
	Doors	1st- Boy's (inside Boy's Dressing Room)	1		6	\$0	
	Floor Drain	1st- Boy's (inside Boy's Dressing Room)	2	EA	6	\$2,118	
	Floor - Terrazzo	1st- Boy's (inside Boy's Dressing Room)	101	SF	6	\$221	
	Hand Dryer	1st- Boy's (inside Boy's Dressing Room)	1	EA	6	\$230	
	Lavatory	1st- Boy's (inside Boy's Dressing Room)	1	EA	6	\$320	
	Lighting - Lay-in	1st- Boy's (inside Boy's Dressing Room)	3	EA	7	\$0	recessed cans
	Partitions	1st- Boy's (inside Boy's Dressing Room)	1	EA	6	\$297	
	Showers	1st- Boy's (inside Boy's Dressing Room)	1	EA	6	\$311	

Building: Fine Arts Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Walls - Concrete Block	1st- Boy's (inside Boy's Dressing Room)	324	SF	6	\$950	
	Walls - Tile Ceramic/ Porcelain	1st- Boy's (inside Boy's Dressing Room)	72	SF	6	\$163	shower walls
	Water Closet	1st- Boy's (inside Boy's Dressing Room)	1	EA	6	\$336	
	Accessories	1st- Boy's	256	SF	6	\$2,361	
	Ceiling - Plaster/Drywall	1st- Boy's	256	SF	6	\$886	
	Doors - Steel Doors incl hw	1st- Boy's	1	EA	6	\$301	
	Floor Drain	1st- Boy's	1	EA	6	\$1,059	
	Floor - Terrazzo	1st- Boy's	8	SF	5	\$419	cracked
	Floor - Terrazzo	1st- Boy's	248	SF	6	\$543	
	Hand Dryer	1st- Boy's	2	EA	6	\$460	
	Lavatory	1st- Boy's	3	EA	6	\$959	
	Lighting - Lay-in	1st- Boy's	12	EA	7	\$0	recessed cans
	Partitions	1st- Boy's	3	EA	6	\$891	
	Urinals	1st- Boy's	2	EA	6	\$672	
	Walls - Concrete Block	1st- Boy's	260	SF	6	\$762	
	Walls - Tile Ceramic/ Porcelain	1st- Boy's	260	SF	6	\$587	
	Water Closet	1st- Boy's	4	EA	6	\$1,344	
	Accessories	1st- Girl's (inside Girl's Dressing Room)	101	SF	6	\$932	
	Ceiling - Plaster/Drywall	1st- Girl's (inside Girl's Dressing Room)	101	SF	6	\$350	
	Doors - Steel Doors incl hw	1st- Girl's (inside Girl's Dressing Room)	1	EA	6	\$301	
	Floor Drain	1st- Girl's (inside Girl's Dressing Room)	2	EA	6	\$2,118	
	Floor - Terrazzo	1st- Girl's (inside Girl's Dressing Room)	101	SF	6	\$221	
	Hand Dryer	1st- Girl's (inside Girl's Dressing Room)	1	EA	6	\$230	
	Lavatory	1st- Girl's (inside Girl's Dressing Room)	1	EA	6	\$320	
	Lighting - Lay-in	1st- Girl's (inside Girl's Dressing Room)	3	EA	7	\$0	recessed cans
	Partitions	1st- Girl's (inside Girl's Dressing Room)	1	EA	6	\$297	
	Showers	1st- Girl's (inside Girl's Dressing Room)	1	EA	6	\$311	
	Walls - Concrete Block	1st- Girl's (inside Girl's Dressing Room)	324	SF	6	\$950	
	Walls - Tile Ceramic/ Porcelain	1st- Girl's (inside Girl's Dressing Room)	72	SF	6	\$163	shower walls
	Water Closet	1st- Girl's (inside Girl's Dressing Room)	1	EA	6	\$336	
	Accessories	1st- Girl's	225	SF	6	\$2,075	
	Ceiling - Plaster/Drywall	1st- Girl's	225	SF	6	\$779	
	Doors - Steel Doors incl hw	1st- Girl's	1	EA	6	\$301	
	Floor Drain	1st- Girl's	1	EA	6	\$1,059	
	Floor - Terrazzo	1st- Girl's	225	SF	6	\$492	
	Floor - Terrazzo	1st- Girl's	20	SF	5	\$1,046	cracked
	Hand Dryer	1st- Girl's	2	EA	6	\$460	

Building: Fine Arts Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Lavatory	1st- Girl's	3	EA	6	\$959	
	Lighting - Lay-in	1st- Girl's	12	EA	7	\$0	recessed cans
	Lighting - Wall Mounted	1st- Girl's	1	EA	6	\$124	electrical conduit for electric dryers is rusting out
	Partitions	1st- Girl's	3	EA	6	\$891	
	Walls - Concrete Block	1st- Girl's	156	SF	6	\$457	
	Walls - Tile Ceramic/ Porcelain	1st- Girl's	388	SF	6	\$877	
	Water Closet	1st- Girl's	4	EA	6	\$1,344	

Rooms (Other Than Classrooms) Subtotal:

\$420,702

Building: Fine Arts Building

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	214	SF	6	\$1,325	
	Ceiling - Splined	1st Floor	4,007	SF	6	\$11,575	
	Ceiling - Splined	1st Floor	20	SF	5	\$193	
	Doors - Side-lite	1st Floor	112	EA	6	\$1,872	
	Doors - Store Front	1st Floor	4	EA	6	\$4,833	
	Doors - Transom Window	1st Floor	36	EA	6	\$610	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	6	\$1,103	
	Floor - Terrazzo	1st Floor	4,241	SF	6	\$35,599	
	Lighting - Lay-in	1st Floor	90	EA	7	\$0	
	Walls - Masonry	1st Floor	5,766	SF	6	\$18,140	
	Ceiling - Exposed	Basement	408	SF	6	\$607	concrete
	Doors - Steel Doors incl hw	Basement	1	EA	6	\$301	1 safety gate.
	Drinking Fountains - Single Fountain	Basement	1	EA	6	\$276	Water pipe in basement are rusting & deteriorating.
	Floor - Concrete	Basement	408	SF	6	\$216	
	Lighting - Pendent/Surface	Basement	7	EA	7	\$0	
	Walls - Concrete Block	Basement	1,209	SF	6	\$3,544	poured concrete
Safety							
	Security Cameras	Entire building	2	EA	6	\$388	
	Security Cameras	Entire building	10	EA	6	\$1,940	

Stairs

	Ceiling - Plaster/Drywall	Basement	194	SF	6	\$1,420	
	Floor - Concrete	Basement	16	SF	6	\$8	

Building: Fine Arts Building

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Handrails	Basement	30	LF	6	\$260	
	Lighting - Pendent/Surface	Basement	3	EA	7	\$0	
	Stairs - Concrete	Basement	11	LF	6	\$91	
	Stairs - Concrete	Basement	4	LF	5	\$396	water is leaking through stairs
	Walls - Concrete Block	Basement	385	SF	6	\$1,129	poured cement
Vertical Conveyance							
	Elevator - Elevator- Machine Roomless		1	EA	6	\$19,238	Engineer says it works, but no one had key to it
	Wheelchair Lift - Platform Lift		1	EA	5	\$18,772	Not working even after a \$7,000 repair was done.

Building Interior Subtotal:

\$123,837

Total Building Cost

\$2,040,454

Building: Linked Addition-Athletic Building

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
	Entrance Control - Audio and Video	#17- E	1	EA	6	\$702	
	Exterior Doors - Exterior FRP Door	#13- NW	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#14- NW	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#15- NE	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#16- NE	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#17- E	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	#20-W	2	EA	6	\$1,263	
	Exterior Doors - Exterior Steel Door	#12- NW	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#18-SE	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#19- SW	2	EA	5	\$2,683	replace weather-stripping. teacher advised that water protrudes during heavy storms
	Exterior Doors - Exterior Steel Door	#21-SW	1	EA	6	\$481	
	Exterior Doors - Transom Lite	#13- NW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#14- NW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#15- NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#16- NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#17- E	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#18-SE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#19- SW	1	EA	6	\$313	

Building: Linked Addition-Athletic Building

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
	Exterior Doors - Transom Lite	#20-W	1	EA	6	\$313	
	Power Door Operator and Controls	#17- E	1	EA	6	\$0	
Foundation							
	Foundation - Concrete	Entire Building	745	LF	7	\$0	
	Superstructure - Steel	Entire Building	52,621	SF	7	\$0	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	\$2,021	
Roof System							
	Chimney - Metal Flue	Main Roof	43	LF	6	\$6,800	
	Chimney - Metal Flue	Main Roof	43	LF	6	\$6,800	
	Chimney - Metal Flue	Main Roof	47	LF	6	\$7,433	
	Chimney - Metal Flue	Main Roof	48	LF	6	\$7,591	
	Chimney - Metal Flue	Main Roof	48	LF	6	\$7,591	
	Coping - Metal	Low W roof	42	LF	6	\$1,349	
	Coping - Metal	Main Roof	800	LF	6	\$25,694	
	Downspouts - Interior Downspouts	Low W roof	36	LF	6	\$1,196	
	Downspouts - Interior Downspouts	Main Roof	296	LF	6	\$9,837	
	Parapet - 16" - 30" Height	Low W roof	42	LF	6	\$1,678	
	Parapet - 16" - 30" Height	Main Roof	100	LF	6	\$3,995	
	Parapet - Parapet < 16" Height	Main Roof	700	LF	6	\$14,915	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Low W roof	1,974	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	39,921	SF	7	\$0	
	Roof - Modified Bitumen	Low W roof	1,974	SF	6	\$18,574	
	Roof - Modified Bitumen	Main Roof	39,921	SF	6	\$375,633	some water ponding
Walls							
	Exterior Walls - Brick	Entire Building	20,462	SF	6	\$137,525	caulk wall to sidewalk abutments to avoid water intrusion.
	Exterior Walls - Brick	Entire Building / Façade- SE	2	SF	5	\$48	wall penetrations
	Exterior Walls - Brick	Entire Building / South Façade	150	SF	5	\$3,571	efflorescence, spalling
Windows							
	Curtain wall - Glazed Single Pane	Entire Building	7,956	SF	5	\$354,396	poor seams & glazing
	Lintels - Steel	Entire Building	36	LF	6	\$1,045	

Building Exterior Subtotal:

\$1,003,083

Building: Linked Addition-Athletic Building

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System							
	Automatic Transfer Switch	Basement	1	EA	6	\$408	Location: Electrical Room
	Automatic Transfer Switch	Basement	1	EA	6	\$408	Location: Electrical Room
	Emergency Battery Packs - Gym	1st Floor	14	EA	6	\$2,835	
	Emergency Generator- Indoor- Natural Gas - Below 60 KW	Basement	1	EA	7	\$0	Location: Generator Room
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	\$898	
	Exit Signs - Gym	Entire Building / 1st Floor	6	EA	6	\$945	
	Exit Signs - Pool	Entire Building / 1st Floor	4	EA	6	\$620	
	Security System - CCTV	Entire Building	52,621	SF	6	\$15,802	
	Security System - Intrusion Detection	Entire Building	52,621	SF	6	\$13,545	
Main Service							
	Main Electrical Service - 2000 A 277/480/3PH	Basement	1	EA	6	\$8,662	
	PA System	Entire Building	52,621	SF	6	\$17,307	Serves all three buildings (Location: Main Building)
Power Distribution							
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	7	\$0	Location: Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Weight Room
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Main Electrical Room
	Transformers - 277/480 - 120/208	Entire Building / 1st Floor	1	EA	6	\$1,265	Location: Main Electrical Room
	Transformers - 277/480 - 120/208	Entire Building / Basement	1	EA	6	\$1,265	Location: Electrical Room

Electrical System Subtotal: \$63,959

Building: Linked Addition-Athletic Building

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm							
	Fire Alarm Strobe Lights	Entire Building	52,621	SF	6	\$18,812	
	Fire Alarm_System	Entire Building	52,621	SF	6	\$25,584	

Building: Linked Addition-Athletic Building

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm							
Sprinkler System							
	Sprinkler Heads	Entire Building	52,621	SF	6	\$0	
	Sprinkler Piping	Entire Building	52,621	SF	6	\$9,782	
	Wet Sprinkler System	Entire Building	52,621	SF	6	\$13,545	
Safty System Subtotal:						\$67,723	

Building: Linked Addition-Athletic Building

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Handling Systems							
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	1	EA	6	\$2,792	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - Greater than 60 tons	Roof	2	EA	6	\$5,583	Serves the Swimming Pool
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons	Lower Roof	1	EA	6	\$2,792	Location: Above Weight Room
Heating Devices							
	Fin Tube - Hot Water	1st Floor	300	LF	6	\$2,831	Location: Pool
Temperature Control							
	DDC System	Entire Building	52,621	SF	6	\$30,099	
	Thermostats - DDC	Entire Building	17	EA	6	\$0	
Ventilation							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Basement and Roof / Basement	3	EA	7	\$0	Location: Pool Equipment Area & Pipe Chase
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Basement and Roof / Roof	3	EA	7	\$0	

Building: Linked Addition-Athletic Building

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechanical System Subtotal:						\$58,055	

Building: Linked Addition-Athletic Building

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Water							
	Gas Heater - 300001 - 600000 BTU/HR	Basement	2	EA	5	\$4,498	
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	52,621	SF	6	\$12,792	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	52,621	SF	6	\$9,782	
	Domestic Piping-Hot Water Return Lines	Entire Building	52,621	SF	6	\$7,525	
	Sanitary Piping	Entire Building	52,621	SF	6	\$48,159	
	Storm Piping	Entire Building	52,621	SF	6	\$45,901	
	Vent Piping	Entire Building	52,621	SF	6	\$35,367	
Pool Systems							
	Pool Drain Piping	Basement	200	LF	4	\$20,257	System is leaking, tank structure is corroded and failing
	Pool Filtration System including Pump	Basement	1	EA	4	\$162,839	Leaking, Corrosion
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	6	\$310	
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	4	\$44,609	
	Pool Supply and Return Piping	Basement	200	LF	6	\$9,610	Piping is Leaking & Drainline around Pool Equipment Don't Drain
Pumps							
	Pumps - Ejector-Simplex	Basement	2	EA	6	\$1,490	Location: Mechanical Room
	Pumps - Sump-Duplex	Basement	1	EA	6	\$1,387	Location: Mechanical Room
Plumbing System Subtotal:						\$404,526	

Building: Linked Addition-Athletic Building

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #170 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	8	SF	5	\$64	Water damaged
	Ceiling - Lay-in	1st Floor	309	SF	6	\$928	
	Chalk Board	1st Floor	18	LF	4	\$1,653	
	Doors - Side-lite	1st Floor	11	SF	6	\$184	

Building: Linked Addition-Athletic Building

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #170 (Regular Classroom)							
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	317	SF	6	\$694	
	Lighting - Lay-in	1st Floor	6	EA	7	\$0	
	Lighting - Lay-in	1st Floor	3	EA	5	\$487	
	Walls - Concrete Block	1st Floor	10	SF	5	\$141	Cracking and localized damage
	Walls - Concrete Block	1st Floor	1,542	SF	6	\$4,520	Walls condensate
Classroom #180 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	876	SF	6	\$2,631	
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Side-lite	1st Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	876	SF	6	\$1,917	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Walls - Concrete Block	1st Floor	234	SF	5	\$2,824	Walls condensating and cracking
	Walls - Concrete Block	1st Floor	1,322	SF	6	\$3,875	

Classrooms Subtotal:

\$22,722

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Ceiling - Plaster/Drywall	420 Coach's Office	94	SF	6	\$325	
	Doors - Store Front	420 Coach's Office	1	EA	6	\$1,208	
	Floor - Tile Ceramic/ Porcelain	420 Coach's Office	94	SF	6	\$199	
	Lighting - Lay-in	420 Coach's Office	2	EA	6	\$238	Recessed lighting
	Power Distribution	420 Coach's Office	2	EA	6	\$4,250	
	Storage/ Closet	420 Coach's Office	28	SF	6	\$203	
	Walls - Concrete Block	420 Coach's Office	319	SF	6	\$935	
	Ceiling - Plaster/Drywall	421 Coach's Office	94	SF	5	\$862	Peeling paint
	Doors - Store Front	421 Coach's Office	1	EA	6	\$1,208	
	Floor - Tile Ceramic/ Porcelain	421 Coach's Office	94	SF	6	\$199	
	Lighting - Lay-in	421 Coach's Office	2	EA	6	\$238	Recessed lighting
	Power Distribution	421 Coach's Office	2	EA	6	\$4,250	
	Storage/ Closet	421 Coach's Office	28	SF	6	\$203	
	Walls - Concrete Block	421 Coach's Office	319	SF	6	\$935	

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Ceiling - Plaster/Drywall	423	137	SF	6	\$474	
	Doors - Steel Doors incl hw	423	1	EA	6	\$301	
	Floor - Terrazzo	423	137	SF	6	\$300	
	Lighting - Lay-in	423	3	EA	6	\$357	Recessed lighting
	Power Distribution	423	2	EA	6	\$4,250	
	Walls - Concrete Block	423	431	SF	6	\$1,263	
	Ceiling - Plaster/Drywall	440	94	SF	6	\$325	
	Doors - Store Front	440	1	EA	6	\$1,208	
	Floor - Tile Ceramic/ Porcelain	440	94	SF	6	\$199	
	Lighting - Lay-in	440	2	EA	6	\$238	Recessed lighting
	Power Distribution	440	2	EA	6	\$4,250	
	Storage/ Closet	440	28	SF	6	\$203	
	Walls - Concrete Block	440	319	SF	6	\$935	
	Ceiling - Splined	Men's Gym Office	1	SF	5	\$10	Missing tile
	Ceiling - Splined	Men's Gym Office	101	SF	6	\$82	
	Doors - Side-lite	Men's Gym Office	11	SF	6	\$184	
	Doors - Steel Doors incl hw	Men's Gym Office	1	EA	6	\$301	
	Floor - Tile	Men's Gym Office	101	SF	6	\$221	
	Lighting - Lay-in	Men's Gym Office	1	EA	6	\$119	Recessed light
	Power Distribution	Men's Gym Office	4	EA	6	\$8,500	
	Walls	Men's Gym Office	1		5	\$0	Open junction box
	Walls - Concrete Block	Men's Gym Office	313	SF	6	\$918	
	Ceiling - Lay-in	Weight Room Office	192	SF	6	\$577	
	Doors - Steel Doors incl hw	Weight Room Office	1	EA	6	\$301	
	Floor - Tile	Weight Room Office	192	SF	6	\$420	
	Lighting - Chandelier, Incandescent	Weight Room Office	4	EA	4	\$4,227	
	Power Distribution	Weight Room Office	2	EA	5	\$7,703	Improper use of extension cords
	Walls - Concrete Block	Weight Room Office	129	SF	6	\$378	
	Walls - Plaster/Drywall	Weight Room Office	323	SF	6	\$891	
	Ceiling - Splined	Women's Gym Office I	94	SF	6	\$77	
	Doors - Side-lite	Women's Gym Office I	11	SF	6	\$184	
	Doors - Steel Doors incl hw	Women's Gym Office I	1	EA	6	\$301	
	Floor - Tile	Women's Gym Office I	94	SF	6	\$206	
	Ceiling - Splined	Women's Gym Office II	94	SF	6	\$77	
	Doors - Side-lite	Women's Gym Office II	11	SF	6	\$184	
	Doors - Steel Doors incl hw	Women's Gym Office II	1	EA	6	\$301	
	Floor - Tile	Women's Gym Office II	94	SF	6	\$206	

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices							
	Lighting - Lay-in	Women's Gym Office II	2	EA	4	\$672	Recessed lighting
	Power Distribution	Women's Gym Office II	22	EA	6	\$46,747	
	Walls - Concrete Block	Women's Gym Office II	311	SF	6	\$912	
	Lighting - Lay-in	Women's Gym Office I	2	EA	4	\$672	Recessed lighting
	Power Distribution	Women's Gym Office I	2	EA	6	\$4,250	
	Walls - Concrete Block	Women's Gym Office I	311	SF	6	\$912	
Gymnasias							
	Bleacher Seating	Men's Gym	1,008	EA	6	\$29,175	
	Ceiling - Exposed	Men's Gym	11,946	SF	6	\$17,766	
	Doors - Steel Doors incl hw	Men's Gym	4	EA	6	\$1,204	
	Floor - Wood	Men's Gym	11,946	SF	6	\$84,218	
	Lighting - Pendent/Surface	Men's Gym	35	EA	7	\$0	9 lights out
	Scoreboards	Men's Gym	1	EA	6	\$2,244	
	Scoreboards	Men's Gym	1	EA	5	\$10,580	Needs lights
	Sound System	Men's Gym	1	EA	5	\$104,564	Was in need of repair. Current status unknown
	Ceiling - Exposed	Weight Room	2,403	SF	6	\$3,574	
	Doors - Steel Doors incl hw	Weight Room	2	EA	6	\$602	
	Floor - Tile/Sheet	Weight Room	3	SF	5	\$17	Gap at threshold
	Floor - Tile/Sheet	Weight Room	2,403	SF	6	\$2,405	
	Lighting - Pendent/Surface	Weight Room	3	EA	5	\$548	
	Lighting - Pendent/Surface	Weight Room	9	EA	7	\$0	
	Walls	Weight Room	1		5	\$0	Outlet wires exposed
	Walls - Concrete Block	Weight Room	446	SF	6	\$1,307	
	Walls - Plaster/Drywall	Weight Room	1,896	SF	6	\$5,233	
	Ceiling - Exposed	Women's Gym	8,090	SF	6	\$12,031	
	Doors - Steel Doors incl hw	Women's Gym	2	EA	6	\$602	
	Floor - Wood	Women's Gym	8,090	SF	6	\$57,034	
	Lighting - Pendent/Surface	Women's Gym	25	EA	6	\$3,097	5 lights out
	Storage/ Closet	Women's Gym	423	SF	6	\$3,067	
	Walls - Concrete Block	Women's Gym	8,008	SF	6	\$23,475	
Locker/Shower Room							
	Accessories	1M	237	SF	6	\$929	
	Benches, ped mounted	1M	7	LF	6	\$762	
	Ceiling - Plaster/ Drywall	1M	237	SF	6	\$820	
	Doors - Steel Doors incl hw	1M	2	EA	6	\$602	
	Floor Drain	1M	2	EA	6	\$2,118	

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/Shower Room							
	Floor - Terrazzo	1M	10	SF	6	\$22	
	Floor - Tile Ceramic/ Porcelain	1M	227	SF	6	\$480	
	Hand Dryer	1M	1	EA	6	\$230	
	Lavatory	1M	2	EA	6	\$639	
	Lighting - Lay-in	1M	3	EA	5	\$487	Recessed lighting. 3 lights out
	Lighting - Lay-in	1M	3	EA	6	\$357	Recessed lighting
	Partitions	1M	1	EA	6	\$297	
	Showers	1M	1	EA	6	\$311	
	Urinals	1M	1	EA	6	\$336	
	Walls - Concrete Block	1M	587	SF	6	\$1,721	
	Walls - Tile Ceramic/ Porcelain	1M	92	SF	6	\$208	
	Water Closet	1M	1	EA	6	\$336	
	Accessories	1st Floor	237	SF	6	\$929	
	Benches, ped mounted	1st Floor	7	LF	6	\$762	
	Ceiling - Plaster/ Drywall	1st Floor	237	SF	6	\$820	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor Drain	1st Floor	2	EA	6	\$2,118	
	Floor - Terrazzo	1st Floor	10	SF	6	\$22	
	Floor - Tile Ceramic/ Porcelain	1st Floor	227	SF	6	\$480	
	Hand Dryer	1st Floor	1	EA	6	\$230	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lighting - Lay-in	1st Floor	2	EA	5	\$324	Recessed lighting
	Lighting - Lay-in	1st Floor	4	EA	6	\$476	Recessed lighting
	Partitions	1st Floor	2	EA	6	\$594	
	Showers	1st Floor	1	EA	6	\$311	
	Walls - Concrete Block	1st Floor	587	SF	6	\$1,721	
	Walls - Tile Ceramic/ Porcelain	1st Floor	92	SF	6	\$208	
	Water Closet	1st Floor	2	EA	6	\$672	
	Accessories	Basement Women's Locker Room	3,001	SF	5	\$26,221	
	Ceiling - Plaster/ Drywall	Basement Women's Locker Room	3,001	SF	5	\$28,667	Peeling paint
	Doors - Steel Doors incl hw	Basement Women's Locker Room	2	EA	6	\$602	
	Floor Drain	Basement Women's Locker Room	30	EA	6	\$31,775	
	Floor - Concrete	Basement Women's Locker Room	2,563	SF	6	\$1,356	
	Hand Dryer	Basement Women's Locker Room	11	EA	6	\$2,530	
	Lavatory	Basement Women's Locker Room	5	EA	6	\$1,598	
	Lighting - Lay-in	Basement Women's Locker Room	22	EA	6	\$2,617	Recessed lighting
	Partitions	Basement Women's Locker Room	7	EA	6	\$2,078	

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/Shower Room							
	Showers	Basement Women's Locker Room	18	EA	6	\$5,605	
	Storage/ Closet	Basement Women's Locker Room	32	SF	6	\$232	
	Student Lockers - Three Tiers	Basement Women's Locker Room	996	EA	6	\$30,821	3 size lockers
	Walls	Basement Women's Locker Room	1	SF	5	\$0	Open junction box
	Walls - Concrete Block	Basement Women's Locker Room	3,695	SF	6	\$10,832	
	Walls - Plaster/Drywall	Basement Women's Locker Room	60	SF	5	\$455	Water damaged
	Water Closet	Basement Women's Locker Room	7	EA	6	\$2,352	
	Accessories	Basement	4,229	SF	6	\$16,570	
	Ceiling - Plaster/ Drywall	Basement	4,229	SF	6	\$14,635	
	Doors - Steel Doors incl hw	Basement	2	EA	6	\$602	
	Floor Drain	Basement	31	EA	6	\$32,834	
	Floor Drain	Basement	1	EA	5	\$2,094	Missing grate
	Floor - Terrazzo	Basement	3,746	SF	6	\$8,196	
	Floor - Tile Ceramic/ Porcelain	Basement	483	SF	6	\$1,022	
	Hand Dryer	Basement	4	EA	6	\$920	
	Lavatory	Basement	2	EA	6	\$639	
	Lighting - Lay-in	Basement	40	EA	7	\$0	
	Lighting - Lay-in	Basement	1	EA	5	\$162	
	Partitions	Basement	3	EA	6	\$891	
	Showers	Basement	28	EA	6	\$8,720	
	Storage/ Closet	Basement	45	SF	6	\$326	
	Student Lockers - Three Tiers	Basement	486	EA	6	\$15,039	3 size lockers
	Urinals	Basement	3	EA	6	\$1,008	
	Walls - Concrete Block	Basement	3,767	SF	6	\$11,043	
	Walls - Tile Ceramic/ Porcelain	Basement	384	SF	6	\$868	
	Accessories	Home Team Room	729	SF	6	\$2,856	
	Ceiling - Plaster/ Drywall	Home Team Room	729	SF	5	\$6,964	Peeling paint
	Doors - Steel Doors incl hw	Home Team Room	2	EA	6	\$602	
	Floor Drain	Home Team Room	2	EA	6	\$2,118	
	Floor Drain	Home Team Room	1	EA	5	\$2,094	Missing grate
	Floor - Terrazzo	Home Team Room	84	SF	6	\$184	
	Floor - Tile Ceramic/ Porcelain	Home Team Room	79	SF	6	\$167	
	Floor - Tile/Sheet	Home Team Room	566	SF	6	\$567	
	Hand Dryer	Home Team Room	1	EA	6	\$230	
	Lavatory	Home Team Room	1	EA	6	\$320	
	Lighting - Lay-in	Home Team Room	7	EA	7	\$0	
	Showers	Home Team Room	6	EA	6	\$1,868	

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/Shower Room							
	Storage/ Closet	Home Team Room	103	SF	6	\$747	
	Student Lockers - One Tier	Home Team Room	24	EA	6	\$2,228	
	Urinals	Home Team Room	1	EA	6	\$336	
	Walls - Concrete Block	Home Team Room	1,325	SF	6	\$3,884	
	Water Closet	Home Team Room	1	EA	5	\$3,894	Missing seat
Mechanical/ Service Rooms							
	Janitor's Closet	1st Floor	70	SF	6	\$502	
	Mechanical/ Service Rooms	1st Floor	268	SF	6	\$1,920	
	Mechanical/ Service Rooms	1st Floor	72	SF	5	\$1,161	Open wiring at junction box
	Vaults	1st Floor	22	SF	6	\$158	
	Air Intake Plenums	Basement	197	SF	6	\$1,220	
	Interior Stairs	Basement	5	LF	6	\$45	
	Janitor's Closet	Basement	45	SF	6	\$322	
	Mechanical/ Service Rooms	Basement	100	SF	5	\$1,613	Filter Room. Active leak
	Mechanical/ Service Rooms	Basement	7,780	SF	6	\$55,738	
	Storage Room	Basement	603	SF	6	\$4,320	
	Vaults	Basement	338	SF	6	\$2,422	
Pool & Natatorium							
	Accessories	1st Floor	12,515	SF	6	\$8,590	
	Bleachers Seating/Plank Seating	1st Floor	408	EA	6	\$11,809	
	Ceiling - Exposed	1st Floor	6,980	SF	6	\$10,381	
	Ceiling - Plaster/ Drywall	1st Floor	6,200	SF	6	\$34,223	
	Doors - Steel Doors incl hw	1st Floor	6	EA	6	\$1,806	
	Floor - Concrete	1st Floor	3,200	SF	6	\$1,693	
	Floor - Tile Ceramic/ Porcelain	1st Floor	4,585	SF	6	\$9,704	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	\$0	
	Pool Basin	1st Floor	4,730	SF	6	\$160,034	
	Pool Deck	1st Floor	4,585	SF	6	\$43,535	
	Pool Deck Drains	1st Floor	38	EA	6	\$16,038	
	Storage/ Closet	1st Floor	456	SF	6	\$3,306	
	Walls	1st Floor	4		6	\$0	drinking fountains
	Walls - Concrete Block	1st Floor	95,662	SF	6	\$280,433	
Restroom							
	Accessories	1st Floor Men's	123	SF	6	\$1,134	
	Ceiling - Plaster/Drywall	1st Floor Men's	123	SF	6	\$426	

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Doors - Steel Doors incl hw	1st Floor Men's	1	EA	5	\$1,174	
	Floor Drain	1st Floor Men's	1	EA	6	\$1,059	
	Floor - Terrazzo	1st Floor Men's	123	SF	6	\$269	
	Hand Dryer	1st Floor Men's	1	EA	6	\$230	
	Lavatory	1st Floor Men's	3	EA	6	\$959	
	Lighting - Lay-in	1st Floor Men's	5	EA	4	\$1,679	
	Partitions	1st Floor Men's	1	EA	6	\$297	
	Urinals	1st Floor Men's	1	EA	6	\$336	
	Walls - Concrete Block	1st Floor Men's	446	SF	6	\$1,307	
	Water Closet	1st Floor Men's	1	EA	6	\$336	
	Accessories	1st Floor Women's	123	SF	6	\$1,134	
	Ceiling - Plaster/Drywall	1st Floor Women's	123	SF	6	\$426	
	Doors - Steel Doors incl hw	1st Floor Women's	1	EA	6	\$301	
	Floor Drain	1st Floor Women's	1	EA	6	\$1,059	
	Floor - Terrazzo	1st Floor Women's	123	SF	6	\$269	
	Hand Dryer	1st Floor Women's	1	EA	6	\$230	
	Lavatory	1st Floor Women's	2	EA	6	\$639	
	Lighting - Lay-in	1st Floor Women's	5	EA	4	\$1,679	Recessed lights
	Partitions	1st Floor Women's	2	EA	6	\$594	
	Walls - Concrete Block	1st Floor Women's	446	SF	6	\$1,307	
	Water Closet	1st Floor Women's	2	EA	6	\$672	
	Accessories	1st Floor	118	SF	6	\$1,088	
	Accessories	1st Floor	135	SF	6	\$1,245	
	Ceiling - Plaster/Drywall	1st Floor	135	SF	6	\$467	
	Ceiling - Plaster/Drywall	1st Floor	118	SF	6	\$408	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Terrazzo	1st Floor	118	SF	6	\$258	
	Floor - Terrazzo	1st Floor	135	SF	6	\$295	
	Hand Dryer	1st Floor	1	EA	6	\$230	
	Hand Dryer	1st Floor	1	EA	6	\$230	
	Lavatory	1st Floor	3	EA	6	\$959	
	Lavatory	1st Floor	1	EA	5	\$1,590	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lighting - Lay-in	1st Floor	6	EA	4	\$2,015	Recessed lighting

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Lighting - Lay-in	1st Floor	6	EA	4	\$2,015	Recessed lighting
	Partitions	1st Floor	3	EA	6	\$891	
	Partitions	1st Floor	1	EA	6	\$297	
	Urinals	1st Floor	2	EA	6	\$672	
	Walls - Concrete Block	1st Floor	500	SF	6	\$1,466	
	Walls - Concrete Block	1st Floor	437	SF	6	\$1,281	
	Water Closet	1st Floor	3	EA	6	\$1,008	
	Water Closet	1st Floor	1	EA	6	\$336	
	Accessories	420	51	SF	6	\$470	
	Ceiling - Plaster/Drywall	420	51	SF	6	\$176	
	Doors - Steel Doors incl hw	420	1	EA	6	\$301	
	Floor Drain	420	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	420	51	SF	6	\$108	
	Lavatory	420	1	EA	6	\$320	
	Lighting - Lay-in	420	1	EA	6	\$119	Recessed Lighting
	Walls - Concrete Block	420	242	SF	6	\$709	
	Water Closet	420	1	EA	6	\$336	
	Accessories	421	51	SF	6	\$470	
	Ceiling - Plaster/Drywall	421	51	SF	6	\$176	
	Doors - Steel Doors incl hw	421	1	EA	6	\$301	
	Floor Drain	421	1	EA	6	\$1,059	
	Floor - Terrazzo	421	8	SF	6	\$18	
	Floor - Tile Ceramic/ Porcelain	421	43	SF	6	\$91	
	Lavatory	421	1	EA	6	\$320	
	Lighting - Lay-in	421	1	EA	6	\$119	Recessed lighting
	Showers	421	1	EA	6	\$311	
	Walls - Concrete Block	421	242	SF	6	\$709	
	Water Closet	421	1	EA	6	\$336	
	Accessories	423	115	SF	6	\$1,061	
	Ceiling - Plaster/Drywall	423	115	SF	6	\$398	
	Doors - Steel Doors incl hw	423	1	EA	6	\$301	
	Floor Drain	423	3	EA	6	\$3,177	
	Floor - Terrazzo	423	115	SF	6	\$252	
	Hand Dryer	423	1	EA	6	\$230	
	Lavatory	423	1	EA	6	\$320	
	Lighting - Lay-in	423	2	EA	4	\$672	
	Partitions	423	1	EA	6	\$297	

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Showers	423	2	EA	5	\$2,344	
	Student Lockers - One Tier	423	6	EA	6	\$557	
	Urinals	423	1	EA	6	\$336	
	Walls	423	1		5	\$0	Open wiring at outlets
	Walls - Concrete Block	423	423	SF	6	\$1,240	
	Water Closet	423	1	EA	6	\$336	
	Accessories	440	54	SF	6	\$498	
	Ceiling - Plaster/Drywall	440	54	SF	6	\$187	
	Doors - Steel Doors incl hw	440	1	EA	6	\$301	
	Floor Drain	440	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	440	54	SF	6	\$114	
	Lavatory	440	1	EA	5	\$1,590	Dripping
	Lighting - Lay-in	440	1	EA	6	\$119	Recessed
	Showers	440	1	EA	6	\$311	
	Walls - Concrete Block	440	242	SF	6	\$709	
	Water Closet	440	1	EA	6	\$336	
	Accessories	Men's Gym Office	37	SF	6	\$341	
	Ceiling - Plaster/Drywall	Men's Gym Office	37	SF	6	\$128	
	Doors - Steel Doors incl hw	Men's Gym Office	1	EA	6	\$301	
	Floor Drain	Men's Gym Office	1	EA	6	\$1,059	
	Floor - Tile	Men's Gym Office	37	SF	6	\$81	
	Lavatory	Men's Gym Office	1	EA	6	\$320	
	Lighting - Lay-in	Men's Gym Office	1	EA	4	\$336	Recessed light
	Walls - Concrete Block	Men's Gym Office	202	SF	6	\$592	
	Water Closet	Men's Gym Office	1	EA	6	\$336	
	Accessories	Women's Gym Office I	94	SF	6	\$867	
	Ceiling - Plaster/Drywall	Women's Gym Office I	38	SF	6	\$132	
	Doors - Steel Doors incl hw	Women's Gym Office I	1	EA	6	\$301	
	Floor - Tile	Women's Gym Office I	38	SF	6	\$83	
	Accessories	Women's Gym Office II	38	SF	6	\$350	
	Ceiling - Plaster/Drywall	Women's Gym Office II	38	SF	6	\$132	
	Doors - Steel Doors incl hw	Women's Gym Office II	1	EA	6	\$301	
	Floor - Tile	Women's Gym Office II	38	SF	6	\$83	
	Lavatory	Women's Gym Office II	1	EA	6	\$320	
	Lighting - Lay-in	Women's Gym Office II	1	EA	4	\$336	Recessed lighting
	Walls - Concrete Block	Women's Gym Office II	202	SF	6	\$592	
	Water Closet	Women's Gym Office II	1	EA	6	\$336	

Building: Linked Addition-Athletic Building

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Lavatory	Women's Gym Office I	1	EA	6	\$320	
	Lighting - Lay-in	Women's Gym Office I	1	EA	4	\$336	Recessed lighting
	Walls - Concrete Block	Women's Gym Office I	202	SF	6	\$592	
	Water Closet	Women's Gym Office I	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$1,508,532

Building: Linked Addition-Athletic Building

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,557	SF	6	\$10,682	
	Ceiling - Plaster/Drywall	1st Floor	1,381	SF	6	\$8,551	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	6	\$276	
	Floor - Terrazzo	1st Floor	4,938	SF	6	\$41,450	
	Lighting	1st Floor	33	EA	6	\$0	Recessed lights
	Lighting - Lay-in	1st Floor	18	EA	7	\$0	
	Walls - Masonry	1st Floor	10,759	SF	6	\$33,848	
	Ceiling - Exposed	Basement Tunnel to Main	845	SF	6	\$1,257	
	Ceiling - Plaster/Drywall	Basement Tunnel to Main	931	SF	6	\$5,765	
	Doors - Steel Doors incl hw	Basement Tunnel to Main	4	EA	6	\$1,204	
	Floor - Terrazzo	Basement Tunnel to Main	845	SF	6	\$7,093	
	Floor - Tile/Sheet	Basement Tunnel to Main	931	SF	6	\$506	
	Lighting - Lay-in	Basement Tunnel to Main	15	EA	7	\$0	
	Lighting - Pendant/Surface	Basement Tunnel to Main	24	EA	7	\$0	
	Walls - Concrete Block	Basement Tunnel to Main	1,801	SF	6	\$5,280	
	Walls - Plaster/Drywall	Basement Tunnel to Main	505	SF	6	\$2,239	
	Walls - Structural Glazed Tile	Basement Tunnel to Main	2,026	SF	6	\$6,374	
Safety							
	Security Cameras	Entire building	2	EA	6	\$388	
	Security Cameras	Entire building	10	EA	6	\$1,940	
Stairs							
	Ceiling - Plaster/Drywall	Mezzanine East to Roof	333	SF	6	\$2,438	
	Floor - Terrazzo	Mezzanine East to Roof	195	SF	6	\$1,637	
	Handrails	Mezzanine East to Roof	112	LF	6	\$971	

Building: Linked Addition-Athletic Building

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Lighting - Lay-in	Mezzanine East to Roof	6	EA	6	\$714	Recessed lighting
	Lighting - Lay-in	Mezzanine East to Roof	2	EA	5	\$324	Recessed lighting
	Stairs - Terrazzo	Mezzanine East to Roof	65	LF	6	\$603	
	Walls - Concrete Block	Mezzanine East to Roof	1,911	SF	6	\$5,602	
	Walls - Concrete Block	Mezzanine East to Roof	80	SF	5	\$1,127	Cracking and peeling paint
	Ceiling - Plaster/Drywall	Mezzanine West	333	SF	5	\$4,895	Peeling paint
	Floor - Terrazzo	Mezzanine West	195	SF	6	\$1,637	
	Handrails	Mezzanine West	112	LF	6	\$971	
	Lighting - Lay-in	Mezzanine West	8	EA	6	\$952	Recessed lighting
	Stairs - Terrazzo	Mezzanine West	65	LF	6	\$603	
	Walls - Concrete Block	Mezzanine West	1,911	SF	6	\$5,602	
	Ceiling - Plaster/Drywall	Women's Locker Room	333	SF	5	\$4,895	Peeling paint
	Floor - Epoxy/ Painted	Women's Locker Room	95	SF	6	\$50	
	Handrails	Women's Locker Room	50	LF	6	\$433	
	Lighting - Lay-in	Women's Locker Room	6	EA	6	\$714	Recessed lighting
	Stairs - Concrete	Women's Locker Room	30	LF	6	\$249	
	Walls - Concrete Block	Women's Locker Room	1,104	SF	6	\$3,236	
	Walls - Concrete Block	Women's Locker Room	60	SF	5	\$845	Holes, peeling paint

Building Interior Subtotal: \$165,686

Total Building Cost \$3,294,286

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Athletic							
	Surface - Asphalt	South	26,870	SF	5	\$122,573	spalling, cracks
	Surface - Concrete	South	12,816	SF	5	\$0	cracks, vegetation, spalling, water ponding
	Surface - Natural	South	56,310	SF	6	\$46,704	
Civil/Drainage							
	Civil/ Drainage - Catch Basin	Entire Site	15	EA	7	\$0	
	Civil/ Drainage - Catch Basin	Entire Site / Parking Lot- West	1	EA	5	\$2,570	clogged
	Civil/ Drainage - Site Drain	Entire Site	3	EA	6	\$931	Location: dock
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	7	\$0	

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fencing							
	Fencing - Chain Link	Entire Site	2,463	LF	6	\$46,245	
	Fencing - Chain Link	Entire Site	50	LF	5	\$3,049	Location: tennis courts - post movement
	Fencing - Guard Rail	Entire Site / Parking Lot- East	379	LF	6	\$4,379	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site / Site West	403	LF	6	\$5,285	
Landscape							
	Landscape - Grass	Entire Site	56,310	SF	6	\$46,704	
	Landscape - Hardscape- Concrete	Entire Site / Site North	33,516	SF	6	\$173,020	some hair line cracks
	Landscape - Hardscape- Concrete	Entire Site / Site South	2,000	SF	5	\$25,511	water ponding, spalling, cracks
	Landscape - Hardscape- Concrete	Entire Site / South West	5,660	SF	6	\$34,399	
	Landscape - Hardscape- Pavers	Entire Site / Site North	900	SF	6	\$5,097	
	Lighting - Pole Mounted	Entire Site	17	EA	6	\$18,424	
	Parkway trees	Entire Site	49	EA	7	\$0	
	Planting Beds/ Area	Entire Site	15,972	SF	6	\$26,266	
	Retaining Wall - Concrete	Entire Site / Site North	535	SF	5	\$28,613	movement, gaps, broken pieces
Parking Lot							
	Concrete Curbs	Parking Lot- West	2,342	LF	6	\$30,075	
	Concrete Curbs	Parking Lot- West / Site South	15	LF	5	\$542	spalling
	Interior Plantings	Parking Lot- East	60	LF	6	\$2,553	
	Interior Plantings	Parking Lot- West	45	LF	6	\$1,914	
	Lighting - Pole Mounted	Parking Lot- East	4	EA	5	\$11,190	need ballusts and bulbs
	Lighting - Pole Mounted	Parking Lot- West	2	EA	6	\$2,905	rust
	Pavers	Parking Lot- East	1,200	SF	5	\$12,063	missing, broken
	Surface - Asphalt	Parking Lot- West	13,940	SF	5	\$72,760	Location: NW & S driveways - cracks, pot holes
	Surface - Asphalt	Parking Lot- West	29,750	SF	6	\$71,897	
	Surface - Asphalt	Parking Lot- West	3,490	SF	4	\$36,981	Location: center aisle- cracks, pot holes, water ponding
	Surface - Concrete	Parking Lot- East	27,581	SF	6	\$66,655	
	Surface - Concrete	Parking Lot- East	1,500	SF	5	\$19,133	movement, cracks
	Surface - Concrete	Parking Lot- West	9,178	SF	5	\$85,834	Location: dock driveway - spalling, exposed steel, cracks
	Trash Compactor	Parking Lot- West	1	EA	6	\$0	Location: at dock
Sidewalks							
	Sidewalks - Internal Walks	Entire Site	10	LF	5	\$578	Location: door 7
	Sidewalks - Internal Walks	Entire Site	1,080	LF	6	\$12,973	
	Sidewalks - Internal Walks	Entire Site / Site South	25	LF	5	\$1,444	cracks, movement
	Sidewalks - Perimeter Sidewalks	Entire Site	18,671	SF	6	\$37,112	

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Sidewalks							
	Sidewalks - Perimeter Sidewalks	Entire Site / Site North	50	SF	5	\$478	movement
Signage							
	Flag Pole - Flag Pole	Entire Site / North East	2	EA	6	\$3,314	
	Marquee - Free Standing Back lighted w/ LED	Entire Site / North West	1	EA	6	\$0	
	Monument - Building Mounted Cut Letter Sign	Entire Site / Façade- NE	1	EA	6	\$0	
	Monument - Building Mounted Cut Letter Sign	Entire Site / Façade- NW	1	EA	6	\$0	

Site Subtotal: **\$1,060,168**

Total Site Cost **\$1,060,168**

Campus Total ^{2 3} **\$15,829,474**

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked “1” in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement “EA” for “each.” Other items, like chimneys, are measured in terms of linear feet (“LF”). Still other items, like flooring, are generally measured in square feet (“SF”).
- **Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- **For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- **Campus Total** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
Main														
Art Room	Art Room	1st Floor	118	118	870	2	3	8	168	0	40	N	N	N
Computer Lab	Regular Classroom	1st Floor	1005	102B	570	1	8	20	0	0	40	N	Y	N
Computer Lab	Computer Lab	1st Floor	115A	115A	900	1	10	56	426	0	40	N	N	N
Computer Lab	Regular Classroom	1st Floor	121	121	1,214	3	36	80	0	0	40	N	Y	N
Computer Lab	Computer Lab	2nd Floor	214	214	811	2	3	55	192	0	40	N	Y	Y
Computer Lab	Computer Lab	2nd Floor	217	219	1,360	3	45	114	252	0	40	N	N	Y
Computer Lab	Computer Lab	2nd Floor	218	216	1,257	1	16	35	186	0	40	N	Y	N
Computer Lab	Computer Lab	2nd Floor	221	219	1,168	2	5	27	372	0	40	N	Y	Y
Counseling Room	Regular Classroom	1st Floor	110A	110A	723	1	20	50			40	N	N	N
Laboratory/Shop	Laboratory/Shop	1st Floor	103	103	1,300	0	44	108	348	0	40	N	N	Y
Office	Science	1st Floor	107A	107A	475	1	2	12	0	0	40	N	Y	N
Other Instructional Use	Other Instructional Use	1st Floor	114B	114	1,477	4	11	72	0	0	40	N	N	N
Other Instructional Use	Computer Lab	1st Floor	115B	115B	900	1	12	56	33	0	40	N	N	N
Other Instructional Use	Computer Lab	1st Floor	116B	116	870	2	12	40	214	0	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	003	NA	785	0	4	50	389	0	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	1004	004	778	4	4	12	140	0	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	101A	002	673	1	14	34	168	0	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	119	119	778	2	2	14	308	0	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	755	2	3	15	155	0	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	771	1	1	41	341	0	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	759	2	3	13	155	0	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	757	2	3	13	160	0	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	759	2	3	15	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	759	2	3	13	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	208	208	757	2	3	15	160	0	40	N	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	209	209	757	2	3	15	160	0	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	210/211	210/211	624	0	0	19	320	0	40	N	N	N
Regular Classroom	Regular Classroom	3rd Floor	212	212	455	2	3	9	96	0	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	439	0	0	4	0	0	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	441	0	0	0	0	0	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	902	2	3	39	186	0	40	N	Y	N
Regular Classroom	Computer Lab	2nd Floor	220	218	754	2	4	23	186	0	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	240	240	1,276	2	3	9	189	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	753	2	1	15	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	795	1	3	12	352	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	757	1	3	13	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	753	2	3	15	160	0	40	N	Y	N

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
Main														
Regular Classroom	Regular Classroom	3rd Floor	306	306	755	2	3	12	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	753	2	3	15	160	0	40	N	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	755	2	2	15	160	0	40	N	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	753	2	3	15	160	0	40	N	N	N
Regular Classroom	Regular Classroom	3rd Floor	312	312	407	2	3	11	0	0	40	N	N	N
Regular Classroom	Science	3rd Floor	315	315	485	2	3	9	0	0	40	N	N	N
Regular Classroom	Science	3rd Floor	317	317	481	1	3	13	0	0	40	N	N	N
Regular Classroom	Regular Classroom	3rd Floor	320	320	436	0	0	6	0	0	40	N	N	N
Regular Classroom	Regular Classroom	3rd Floor	323	323	752	2	3	15	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	324	324	757	2	3	15	160	0	40	N	N	N
Regular Classroom	Regular Classroom	3rd Floor	325	325	757	2	3	15	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	326	326	757	2	3	13	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	327	327	753	2	3	13	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	755	2	3	15	160	0	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	329	329	778	2	3	15	352	0	40	N	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	330	330	750	2	3	13	160	0	40	N	Y	Y
Science	Science	1st Floor	106	106	1,170	2	2	38	168	0	40	N	Y	N
Science	Science	2nd Floor	242	242	1,329	0	15	37	267	0	40	N	Y	N
Science	Science	3rd Floor	313	313	602	2	3	15	128	0	40	N	Y	N
Science	Science	3rd Floor	314A	314	1,209	0	0	29	256	0	40	N	Y	N
Science	Science	3rd Floor	316A	318	1,200	2	3	32	256	0	40	N	Y	Y
Science	Science	3rd Floor	318	318	602	0	0	12	128	0	40	N	Y	N
Science	Science	3rd Floor	319	319	1,209	2	3	34	320	0	40	N	N	N
Special Education	Special Education	3rd Floor	310, 311	310, 311	944	5	3	16	416	0	40	N	Y	N
Special Education	Special Education	3rd Floor	322	322	523	2	2	17	320	0	40	N	N	N
Special Program	Special Program	1st Floor	112	112	1,505		6	22	0	0	40	N	Y	N
Special Program	Special Program	1st Floor	113	113	1,498	1	6	54	348	0	40	N	N	N
Special Program	Special Program	1st Floor	117	117	1,429	3	38	42	0	0	40	N	Y	N
Store Room	Art Room	1st Floor	120	120	778	2	3	12	168	0	40	N	N	N
Vacant	Regular Classroom	1st Floor	001	100	673	1	4	16	196	0	40	N	N	N
Vacant	Laboratory/Shop	1st Floor	116A	116A	690	1	11	24	212	0	40	N	N	N
Vacant	Regular Classroom	2nd Floor	215	214	751	2	3	97	160	0	40	N	Y	N

Fine Arts Building

Music Room	Music Room	1st Floor	150	150	714	0	20	56	234	0	40	N	N	N
Music Room	Music Room	1st Floor	151	151	1,206	1	0	12	0	0	40	N	N	N
Music Room	Music Room	1st Floor	152	152	1,206	1	0	10	0	0	40	N	N	N

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
Fine Arts Building														
Regular Classroom	Regular Classroom	1st Floor	160	153	756	1	2	20	0	0	40	N	N	N
Special Program	Regular Classroom	1st Floor	165		480	1	2	14	234	0	40	N	N	Y

Linked Addition-Athletic Building

Regular Classroom	Regular Classroom	1st Floor	170	170	317	0	1	8	781	0	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	180	180	876	1	2	20	780	0	40	N	N	N