

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1927	3	61,749	\$3,037,894
Addition 1	1955	2	24,672	\$740,951
Addition 2	1996	1	5,923	\$307,001
SITE				\$391,539
Campus Total			92,344	\$4,477,385

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
tranc	e						
	Entrance Control - Audio	Door 1: Southeast	1	EA	6	\$497	
	Exterior Doors - Exterior Steel Door	Door 1: Southeast	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Door 10: Southeast	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Door 2: Northeast	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Door 3: Northeast	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Door 6: North	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Door 8: Courtyard	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Door 9: West	2	EA	6	\$961	
	Exterior Doors - Overhead Rolling/ Garage Door	Door 7.5	1	EA	6	\$1,433	
	Exterior Doors - Transom Lite	Door 1: Southeast	1	EA	7	\$0	
	Exterior Doors - Transom Lite	Door 10: Southeast	1	EA	6	\$313	
	Exterior Doors - Transom Lite	Door 2: Northeast	1	EA	7	\$0	
	Exterior Doors - Transom Lite	Door 6: North	1	EA	7	\$0	
	Exterior Doors - Transom Lite	Door 8: Courtyard	1	EA	6	\$313	
	Exterior Stairs - Concrete	Door 1: Southeast	17	LF	6	\$1,390	
	Exterior Stairs - Concrete	Door 2: Northeast	102	LF	6	\$8,340	
	Exterior Stairs - Concrete	Door 6: North	40	LF	6	\$3,271	
	Exterior Stairs - Stone	Door 1: Southeast	64	LF	6	\$7,231	



Group	Item - Type	Location	Quantity	Unit	Pank	Cost	Comments
Entranc		Location	Quantity	Onit	Nank	0031	Comments
	Exterior Stairs - Stone	Door 10: Southeast	56	LF	6	\$6,327	
	Exterior Stairs - Stone	Door 2: Northeast	7	LF	6	\$0,327 \$791	
	Exterior Stairs - Stone	Door 3: Northeast	55	LF	6	\$6,214	
	Exterior Stairs - Stone	Door 6: North	6	LF	6	\$678	
	Exterior Stairs - Stone	Door 9: West	48	LF	6	\$5,423	
		Door 1: Southeast		EA	6	\$0,423 \$0	
	Power Door Operator and Controls		1		о 7		
	Stair Handrail - Steel_Stair Handrail Stair Handrail - Steel_Stair Handrail	Door 1: Southeast Door 6: North	8	LF		\$0 \$69	
				LF	6		
	Stair Handrail - Steel_Stair Handrail	Door 9: West	8	LF	6	\$69	
Founda	tion						
	Foundation - Concrete	Entire Building	722	LF	7	\$0	
	Superstructure - Concrete	Entire Building	61,749	SF	7	\$0	
Lighting	9						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	8	EA	6	\$4,292	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	\$2,310	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	\$427	Cover off
Roof Sy	vstem						
	Cell Tower	Roof 1	1	EA	7	\$0	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1	25	LF	6	\$23,867	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1	50	LF	7	\$0	
	Coping - Terra Cotta	Roof 1	460	LF	6	\$14,774	
	Coping - Terra Cotta	Roof 2	493	LF	6	\$15,834	
	Coping - Terra Cotta	Roof 3	380	LF	6	\$12,205	
	Coping - Terra Cotta	Roof 4	113	LF	6	\$3,629	
	Coping - Terra Cotta	Roof 6	50	LF	6	\$1,606	
	Downspouts - Interior Downspouts	Roof 1	200	LF	7	\$0	
	Downspouts - Interior Downspouts	Roof 2	124	LF	7	\$0	
	Downspouts - Interior Downspouts	Roof 3	140	LF	7	\$0	
	Downspouts - Interior Downspouts	Roof 4	42	LF	7	\$0	
	Parapet - 16" - 30" Height	Roof 1	60	LF	6	\$2,397	
	Parapet - 16" - 30" Height	Roof 3	380	LF	6	\$15,183	
	Parapet - 16" - 30" Height	Roof 6	50	LF	6	\$1,998	
	Parapet - Parapet < 16" Height	Roof 2	493	LF	6	\$10,504	
	Parapet - Parapet < 16" Height	Roof 4	113	LF	6	\$2,408	
	Parapet - Parapet > 30"	Roof 1	400	LF	6	\$25,568	



Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof S	/stem						
	Roof Structure - Concrete	Roof 2	8,723	SF	7	\$0	
	Roof Structure - Concrete	Roof 3	7,870	SF	7	\$0	
	Roof Structure - Concrete	Roof 4	1,502	SF	7	\$0	
	Roof Structure - Concrete	Roof 5	190	SF	7	\$0	
	Roof Structure - Concrete	Roof 6	170	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Roof 2	8,723	SF	6	\$88,689	
	Roof - Asphalt Gravel Ballast	Roof 4	1,502	SF	6	\$15,271	
	Roof - Metal	Roof 6	170	SF	6	\$2,278	
	Roof - Modified Bitumen	Roof 1	11,372	SF	6	\$107,004	
	Roof - Modified Bitumen	Roof 3	7,870	SF	6	\$74,052	
	Roof - Modified Bitumen	Roof 5	190	SF	5	\$3,997	
Walls							
	Cheek-Wall - Stone	Entire Building	50	SF	6	\$513	Terra cotta
	Cheek-Wall - Stone	Entire Building	75	SF	6	\$769	
	Cornice - Terra Cotta	Entire Building	1,163	LF	6	\$40,330	
	Exterior Walls - Brick	Entire Building	29,259	SF	6	\$196,650	
	Exterior Walls - Terra Cotta	Entire Building	1,913	SF	6	\$12,857	
Window	/S						
	Guard - Guards perforated	Entire Building	1,927	SF	7	\$0	
	Lintels - Steel	Entire Building	693	LF	6	\$20,117	
	Lintels - Terra Cotta	Entire Building	61	LF	6	\$0	
	Skylite - Glass Single-Pane	Entire Building	105	SF	5	\$6,285	Lack sealant, discolored
	Windows - Casement Steel	Entire Building	120	SF	5	\$9,814	
	Windows - Decorative	Entire Building	39	SF	7	\$0	
	Windows - Sash Aluminum Double-pane	Entire Building	6,970	SF	6	\$52,028	
Build	ng Exterior Subtotal:					\$816,265	

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Automatic Transfer Switch	Boiler Room	2	EA	6	\$816	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building / 1st Floor	3,960	SF	6	\$2,095	
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,885	SF	6	\$3,269	
	Emergency A/C Power - Gym	Entire Building / 1st Floor	3,020	SF	6	\$1,123	



Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Emergency A/C Power - Students Toilets	Entire Building	1,862	SF	6	\$692	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building / 1st Floor	9	EA	6	\$1,823	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	26	EA	6	\$5,265	
	Emergency Battery Packs - Gym	Entire Building / 1st Floor	2	EA	6	\$405	
	Exit Signs - Auditoium	Entire Building / 1st Floor	9	EA	6	\$1,348	
	Exit Signs - Corridors and Stairs	Entire Building	14	EA	6	\$2,096	
	Exit Signs - Gym	Entire Building / 1st Floor	2	EA	6	\$315	
	Security System - CCTV	Entire Building	61,749	SF	4	\$220,753	Only one camera located at main entrance.
	Security System - Intrusion Detection	Entire Building	61,749	SF	6	\$15,894	
	UPS - Less than 30 KW	Basement	1	EA	6	\$7,886	
Main S	ervice						
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	6	\$2,921	Secondary feed from utility company.
	Main Electrical Service - 1600 A 120/208/3PH	Mechanical Room	1	EA	6	\$5,641	
	PA System	Entire Building	61,749	SF	6	\$20,309	Serves main and additions. Control console located in main building.
Power	Distribution						
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	6	\$299	Fuses.
	Lighting and Power Panels - Above 100 A	Entire Building / Boiler Room	1	EA	4	\$6,578	Live front, exposed buss bars.
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	6	\$4,473	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	\$994	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	\$994	
	Main Distribution Panels - 400 - 600 amp	Entire Building / Boiler Room	2	EA	6	\$1,055	
	Main Distribution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	4	\$21,104	Live front, exposed buss bars.
						<u> </u>	

Electrical System Subtotal:

\$328,149

Building: Main

Category: Safty System

Group Item - Type	Location	Quantity l	Jnit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Panel	Entire Building / Boiler Room	1	EA	3	\$49,477	Panel manufacturer out of business. No replacement parts.
Fire Alarm Strobe Lights	Entire Building	13,298	SF	6	\$4,754	Corridors and toilet rooms only.
Fire Alarm_System	Entire Building	61,749	SF	6	\$30,022	



Category: S	afty S	ystem
-------------	--------	-------

Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Safty System Subtotal:		\$	\$84,253

Building: Main

Category: Mechanical System

ltem - Type	Location	Quantity	Unit	Rank	Cost	Comments
ndling Systems						
Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	\$34,007	Serves the gym.
Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	\$34,007	Serves the auditorium.
Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	\$44,262	Serves north classrooms.
Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	\$55,649	Serves the southeast classrooms.
Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	\$34,007	Serves the southwest classrooms.
Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	\$5,788	
Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	\$6,511	
Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	6	\$4,341	
Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	6	\$4,341	
Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	6	\$4,341	
Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room / Plenum	3	EA	6	\$3,153	
Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room / Plenum	6	EA	6	\$6,307	
Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room / Plenum	4	EA	6	\$4,204	
Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room / Entire Building	250	LF	7	\$0	
Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room / Entire Building	250	LF	7	\$0	
Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room / Entire Building	50	LF	7	\$0	
Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room / Entire Building	150	LF	7	\$0	
Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room / Entire Building	50	LF	7	\$0	
Zone Dampers	Mechanical Room / Plenum	11	EA	6	\$9,163	
Zone Dampers	Mechanical Room / Plenum	16	EA	6	\$13,329	
Zone Dampers	Mechanical Room / Plenum	8	EA	6	\$6,664	



Building: Main

Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler Systems						
Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	6	\$5,091	
Chemical Feed System	Boiler Room	1	EA	6	\$1,078	
Combustion Dampers	Boiler Room	3	EA	6	\$1,227	3rd damper for domestic water heaters.
Condensate Pump	Boiler Room / Basement	3	EA	6	\$6,063	Duplex.
Feed Water Pumps and Tank	Boiler Room	1	EA	6	\$2,545	4 pumps, 1 HP each.
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	6	\$5,091	Serves main and additions.
Piping - Condensate Pipe- Steel	Boiler Room / Entire Building	400	LF	6	\$755	
Piping - Steam Pipe- Steel	Boiler Room / Entire Building	400	LF	6	\$755	
Steam Traps	Boiler Room / Entire Building	72	EA	5	\$94,673	
Gas Booster						
Gas Booster	Boiler Room	2	EA	7	\$0	Being removed on 9/18/2015 for new medium pressure gas service from utility company.
Heating Devices						
Radiators - Steam	Entire Building	8	EA	5	\$13,403	Manual control valves.
Unit Heater - Gas	Boiler Room	1	EA	6	\$278	
Wall Heater - Electric	Entire Building	8	EA	6	\$1,111	
emperature Control						
DDC System	Entire Building	61,749	SF	6	\$35,320	
Thermostats - DDC	Entire Building	37	EA	6	\$0	
/entilation						
Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / Basement	1	EA	6	\$592	Located in engineers office. Serves UPS room.
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	2	EA	6	\$1,185	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	2	EA	6	\$1,185	
Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building / Roof	3	EA	6	\$1,777	
Roof Mounted Duct Work	Entire Building / Roof	30	LF	6	\$11,371	
Mechanical System Subtotal:					\$482,395	
Building: Main						
Category: Plumbing System						
Galegory. Fluinding System	Location	Quantity			• •	Commonto

Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Hot Water			
Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2 EA 6	\$620 Serves main and Addition 1.



Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	61,749	SF	6	\$12,362	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	61,749	SF	6	\$15,011	
	Domestic Piping-Cold Water Risers	Entire Building	61,749	SF	6	\$11,479	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	61,749	SF	6	\$9,713	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	61,749	SF	6	\$11,479	
	Domestic Piping-Hot Water Return Lines	Entire Building	61,749	SF	6	\$8,830	
	Domestic Piping-Hot Water Return Risers	Entire Building	61,749	SF	6	\$8,830	
	Sanitary Piping	Entire Building	61,749	SF	6	\$56,513	
	Storm Piping	Entire Building	61,749	SF	6	\$53,864	
	Vent Piping	Entire Building	61,749	SF	6	\$41,502	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	6	\$1,446	Serves main and addition 1.
	Pumps - Sump-Duplex	Mechanical Room	1	EA	6	\$1,387	

Plumbing System Subtotal:

\$233,035

Building: Main

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	6	LF	6	\$152	
	Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	6	\$1,564	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,386	SF	6	\$3,825	
lassro	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	6	LF	6	\$152	
	Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Transom Window	1st Floor	9	SF	7	\$0	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #102 (Regular Classroom)						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	6	\$1,564	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,386	SF	6	\$3,825	
Classro	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	6	LF	6	\$152	
	Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	6	\$1,564	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,386	SF	6	\$3,825	
Classro	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	1st Floor	715	SF	5	\$6,554	peeling throughout
	Chalk Board	1st Floor	2	LF	4	\$184	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	715	SF	6	\$5,041	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,386	SF	6	\$3,825	
Classro	om #105 (Music Room)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	6	LF	6	\$152	
	Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
	Chalk Board	1st Floor	25	LF	4	\$2,295	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	6	\$1,564	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	



Building: Main

-	em - Type	Location	Quantity	Unit	Rank	Cost	Comme
assroon	n #105 (Music Room)						
	arker Board	1st Floor	16	LF	7	\$0	
V	/alls - Plaster/Drywall	1st Floor	1,386	SF	6	\$3,825	
assroor	1 #106 (Dance Room)						
A	C Units	1st Floor	1	EA	6	\$496	
С	asework	1st Floor	8	LF	6	\$202	
С	eiling - Lay-in	1st Floor	715	SF	6	\$2,147	
С	halk Board	1st Floor	8	LF	4	\$734	
С	oors - Transom Window	1st Floor	18	SF	6	\$305	
С	oors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
F	oor - Wood	1st Floor	715	SF	6	\$5,041	
L	ghting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
Ν	arker Board	1st Floor	12	LF	7	\$0	
V	/alls - Plaster/Drywall	1st Floor	1,386	SF	6	\$3,825	
assroor	n #109 (Office)						
	C Units	1st Floor	1	EA	6	\$496	
С	asework	1st Floor	8	LF	6	\$202	
С	eiling - Lay-in	1st Floor	715	SF	6	\$2,147	
С	oors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
F	oor - Wood	1st Floor	715	SF	6	\$5,041	
L	ghting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
Ν	arker Board	1st Floor	6	LF	7	\$0	
V	/alls - Plaster/Drywall	1st Floor	1,386	SF	6	\$3,825	
assroor	n #110 (Regular Classroom)						
Ą	C Units	1st Floor	1	EA	6	\$496	
C	asework	1st Floor	10	LF	6	\$253	
C	eiling - Lay-in	1st Floor	730	SF	6	\$2,192	
C	halk Board	1st Floor	40	LF	4	\$3,672	
С	oors - Transom Window	1st Floor	18	SF	6	\$305	
С	oors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
F	oor - Wood	1st Floor	730	SF	6	\$5,146	
L	ghting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
N	arker Board	1st Floor	12	LF	7	\$0	
V	/alls - Plaster/Drywall	1st Floor	1,393	SF	6	\$3,845	
assroor	n #111 (Regular Classroom)						
^	C Units	1st Floor	1	EA	6	\$496	



Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #111 (Regular Classroom)	Loodion	quantity	onne	i turiit	0001	Commente
145510	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	715	SF	6	\$2,147	
	Chalk Board	1st Floor	6	LF	4	\$551	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	6	\$1,564	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,386	SF	6	\$3,825	
102210	om #113 (Regular Classroom) AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	8		6	\$496 \$202	
	Ceiling - Lay-in	1st Floor	o 715	SF	6	\$202 \$2,147	
	Chalk Board	1st Floor	2	LF	4	۶2,147 \$184	
	Doors - Transom Window	1st Floor	18	SF	4 6	\$104 \$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	715	SF	6	\$5,041	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$3,041 \$1,487	
	Marker Board	1st Floor	12	LF	7	\$1,487 \$0	
	Walls - Plaster/Drywall	1st Floor	1,386	SF	6	پ 0 \$3,825	
		13(1100)	1,500	01	0	ψ0,020	
lassro	om #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	30	LF	6	\$758	
	Ceiling - Lay-in	1st Floor	600	SF	6	\$1,802	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	600	SF	6	\$4,230	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	\$991	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,165	SF	6	\$3,215	
	Work Sink	1st Floor	1	EA	6	\$379	
lassro	om #117 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	16	LF	6	\$404	
	Ceiling - Lay-in	1st Floor	655	SF	6	\$1,967	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #117 (Regular Classroom)						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	655	SF	6	\$1,433	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,265	SF	6	\$3,491	
Classro	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	719	SF	6	\$2,159	
	Chalk Board	2nd Floor	10	LF	4	\$918	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	719	SF	6	\$5,069	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,155	SF	6	\$3,188	
	Walls - Tile	2nd Floor	1	SF	6	\$2	
Classro	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	719	SF	6	\$2,159	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	719	SF	6	\$5,069	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	6	LF	6	\$129	
	Walls - Plaster/Drywall	2nd Floor	1,155	SF	6	\$3,188	
	Walls - Tile	2nd Floor	1	SF	6	\$2	charging station
Classro	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	719	SF	6	\$2,159	
	Chalk Board	2nd Floor	16	LF	4	\$1,469	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #207 (Regular Classroom)						
	Floor - Wood	2nd Floor	719	SF	6	\$5,069	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,155	SF	6	\$3,188	
	Walls - Tile	2nd Floor	1	SF	7	\$0	Charging Station
Classro	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Lay-in	2nd Floor	719	SF	6	\$2,159	
	Chalk Board	2nd Floor	18	LF	4	\$1,653	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	719	SF	6	\$5,069	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	6	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,155	SF	6	\$3,188	
	Walls - Tile	2nd Floor	1	SF	7	\$0	Charging Station
Classro	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	719	SF	6	\$2,159	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	719	SF	6	\$5,069	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,155	SF	6	\$3,188	
	Walls - Tile	2nd Floor	1	SF	7	\$0	Charging Station
Classro	om #210 (Science Lab Level 1)						
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	2nd Floor	719	SF	6	\$2,159	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	



Building: Main

Fla Lig Ma W W Classroom	em - Type a #210 (Science Lab Level 1) oor - Wood ghting - Pendent/Surface larker Board /alls - Plaster/Drywall /ork Sink a #211 (Regular Classroom)	Location 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	Quantity 719 12 10 1,155	SF EA LF	6 7	Cost \$5,069 \$0	Comments
Fla Lig Ma W W Classroom	oor - Wood ghting - Pendent/Surface arker Board /alls - Plaster/Drywall /ork Sink	2nd Floor 2nd Floor 2nd Floor	12 10	EA	7		
Lig Ma W W	ghting - Pendent/Surface larker Board /alls - Plaster/Drywall /ork Sink	2nd Floor 2nd Floor 2nd Floor	12 10	EA	7		
Ma W W Classroom	arker Board /alls - Plaster/Drywall /ork Sink	2nd Floor 2nd Floor	10			\$0	
W W Classroom	/alls - Plaster/Drywall /ork Sink	2nd Floor		LF			
W	/ork Sink		1,155		7	\$0	
Classroom		2nd Floor		SF	6	\$3,188	
	n #211 (Regular Classroom)		1	EA	6	\$379	
AC							
/ (0	C Units	2nd Floor	1	EA	7	\$0	
Ca	asework	2nd Floor	8	LF	6	\$202	
Ce	eiling - Lay-in	2nd Floor	719	SF	6	\$2,159	
Cł	halk Board	2nd Floor	14	LF	4	\$1,285	
Do	oors - Transom Window	2nd Floor	8	SF	6	\$135	
Do	oors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
Flo	oor - Wood	2nd Floor	719	SF	6	\$5,069	
Liç	ghting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
Ma	arker Board	2nd Floor	10	LF	7	\$0	
W	/alls - Plaster/Drywall	2nd Floor	1,155	SF	6	\$3,188	
W	/alls - Tile	2nd Floor	1	SF	6	\$2	Charging Station
Classroom	n #213 (Regular Classroom)						
	C Units	2nd Floor	1	EA	6	\$496	
Ca	asework	2nd Floor	15	LF	6	\$379	
Ce	eiling - Lay-in	2nd Floor	719	SF	6	\$2,159	
	halk Board	2nd Floor	14	LF	4	\$1,285	
Dr	oors - Transom Window	2nd Floor	8	SF	6	\$135	
Do	oors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
Flo	oor - Wood	2nd Floor	719	SF	6	\$5,069	
Liç	ghting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	arker Board	2nd Floor	10	LF	7	\$0	
W	/alls - Plaster/Drywall	2nd Floor	1,155	SF	6	\$3,188	
W	/alls - Tile	2nd Floor	1	SF	6	\$2	Charging Station
Classroom	n #215 (Regular Classroom)						
	C Units	2nd Floor	1	EA	7	\$0	
Ca	asework	2nd Floor	8	LF	6	\$202	
	eiling - Lay-in	2nd Floor	734	SF	6	\$2,204	
	halk Board	2nd Floor	48	LF	4	\$4,407	
	oors - Transom Window	2nd Floor	4	SF	6	\$68	
	oors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #215 (Regular Classroom)	Location	Quantity	0	i tuint		
0.000.00	Floor - Wood	2nd Floor	734	SF	6	\$5,175	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,155	SF	6	\$3,188	
			,			. ,	
Classroo	om #217 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	\$0	
	Casework	2nd Floor	16	LF	6	\$404	
	Ceiling - Lay-in	2nd Floor	734	SF	6	\$2,204	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Charging Station	2nd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	734	SF	6	\$5,175	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,155	SF	6	\$3,188	
	Wireless System	2nd Floor	1	EA	7	\$0	
Classro	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	719	SF	6	\$2,159	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,155	SF	6	\$3,188	
	Walls - Tile	3rd Floor	1	SF	6	\$2	Charging Station
Classro	om #302 (Office)						
	AC Units	3rd Floor	1	EA	7	\$0	
	Ceiling - Lay-in	3rd Floor	350	SF	6	\$1,051	
	Doors - Transom Window	3rd Floor	4	SF	6	\$68	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	350	SF	6	\$2,467	
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	\$0	
	Marker Board	3rd Floor	6	LF	6	\$129	
	Walls - Masonry	3rd Floor	322	SF	6	\$1,013	
	Walls - Plaster/Drywall	3rd Floor	322	SF	6	\$889	



Building: Main

|--|

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classr	oom #302 (Office)						
Classr	oom #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	\$0	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	719	SF	6	\$2,159	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	6	LF	6	\$129	
	Walls - Plaster/Drywall	3rd Floor	1,155	SF	6	\$3,188	
	Walls - Tile	3rd Floor	1	SF	7	\$0	Charging Station
Classr	oom #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	\$0	
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	3rd Floor	730	SF	6	\$2,192	
	Chalk Board	3rd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	8	LF	7	\$0	
	Storage/ Closet	3rd Floor	150	SF	6	\$1,088	
	Walls - Plaster/Drywall	3rd Floor	1,393	SF	6	\$3,845	
	Walls - Tile	3rd Floor	1	SF	7	\$0	Charging Station
	Work Sink	3rd Floor	1	EA	6	\$379	
Classr	oom #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	\$0	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Lay-in	3rd Floor	719	SF	6	\$2,159	
	Chalk Board	3rd Floor	18	LF	4	\$1,653	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	719	SF	6	\$5,069	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	6	LF	7	\$0	



Building: Main

-	Item - Type	Location					
Classroo		Loodilon	Quantity	Unit	Rank	Cost	Comments
	m #305 (Regular Classroom)						
	Walls - Plaster/Drywall	3rd Floor	1,155	SF	6	\$3,188	
١	Walls - Tile	3rd Floor	1	SF	7	\$0	
Classroo	m #306 (Regular Classroom)						
1	AC Units	3rd Floor	1	EA	7	\$0	
(Casework	3rd Floor	10	LF	6	\$253	
(Ceiling - Lay-in	3rd Floor	730	SF	6	\$2,192	
(Chalk Board	3rd Floor	30	LF	4	\$2,754	
I	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
I	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
I	Floor - Tile/Sheet	3rd Floor	730	SF	6	\$731	
I	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
I	Marker Board	3rd Floor	8	LF	7	\$0	
١	Walls - Plaster/Drywall	3rd Floor	1,393	SF	6	\$3,845	
١	Walls - Tile	3rd Floor	1	SF	7	\$0	charging station
Classroo	m #307 (Regular Classroom)						
I	AC Units	3rd Floor	1	EA	7	\$0	
(Casework	3rd Floor	8	LF	6	\$202	
(Ceiling - Lay-in	3rd Floor	719	SF	6	\$2,159	
(Chalk Board	3rd Floor	43	LF	4	\$3,948	
I	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
I	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
I	Floor - Wood	3rd Floor	719	SF	6	\$5,069	
- I	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
I	Marker Board	3rd Floor	6	LF	7	\$0	
١	Walls - Plaster/Drywall	3rd Floor	1,155	SF	6	\$3,188	
١	Walls - Tile	3rd Floor	1	SF	7	\$0	Charging Station
Classroo	m #308 (Regular Classroom)						
1	AC Units	3rd Floor	1	EA	7	\$0	
(Casework	3rd Floor	10	LF	6	\$253	
(Ceiling - Lay-in	3rd Floor	730	SF	6	\$2,192	
(Chalk Board	3rd Floor	24	LF	4	\$2,203	
I	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
1	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
1	Floor - Tile/Sheet	3rd Floor	730	SF	6	\$731	
1	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	



Building: Main

Category: Classrooms

\$3,845
\$0 Charging Station

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dmini	strative Suites/Offices						
	AC Unit	1st floor west of boiler room 2 engineer's office	1	EA	5	\$1,826	Not supported properly
	Ceiling - Plaster/Drywall	1st floor west of boiler room 2 engineer's office	248	SF	6	\$858	
	Doors - Wood Doors inclu hw	1st floor west of boiler room 2 engineer's office	1	EA	6	\$301	
	Floor - Concrete	1st floor west of boiler room 2 engineer's office	107	SF	6	\$57	
	Floor - Tile/Sheet	1st floor west of boiler room 2 engineer's office	141	SF	6	\$141	
	Lighting - Pendent/Surface	1st floor west of boiler room 2 engineer's office	2	EA	7	\$0	
	Power Distribution	1st floor west of boiler room 2 engineer's office	12	EA	7	\$0	
	Walls - Plaster/Drywall	1st floor west of boiler room 2 engineer's office	739	SF	6	\$2,040	
	Ceiling - Plaster/Drywall	1st Floor-Case Manager Office, in Auditorium Lobby	85	SF	6	\$294	
	Doors - Wood Doors inclu hw	1st Floor-Case Manager Office, in Auditorium Lobby	1	EA	6	\$301	
	Floor - Carpet	1st Floor-Case Manager Office, in Auditorium Lobby	85	SF	5	\$436	
	Lighting - Pendent/Surface	1st Floor-Case Manager Office, in Auditorium Lobby	1	EA	6	\$124	
	Power Distribution	1st Floor-Case Manager Office, in Auditorium Lobby	4	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor-Case Manager Office, in Auditorium Lobby	380	SF	6	\$1,049	
	AC Unit	1st Floor-Main Office	1	EA	6	\$496	
	Ceiling - Lay-in	1st Floor-Main Office	410	SF	6	\$1,231	
	Doors - Transom Window	1st Floor-Main Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor-Main Office	2	EA	6	\$602	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Floor - Wood	1st Floor-Main Office	410	SF	6	\$2,890	
	Lighting - Pendent/Surface	1st Floor-Main Office	8	EA	6	\$991	
	Power Distribution	1st Floor-Main Office	12	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor-Main Office	1,040	SF	6	\$2,870	
	Ceiling - Plaster/Drywall	1st Floor-Nurse's Office	150	SF	6	\$519	
	Doors - Side-lite	1st Floor-Nurse's Office	20	SF	6	\$334	
	Doors - Wood Doors inclu hw	1st Floor-Nurse's Office	1	EA	6	\$301	
	Floor - Wood	1st Floor-Nurse's Office	150	SF	6	\$1,057	
	Lighting - Pendent/Surface	1st Floor-Nurse's Office	2	EA	6	\$248	
	Power Distribution	1st Floor-Nurse's Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor-Nurse's Office	545	SF	6	\$1,504	
	AC Unit	1st Floor-Office 108, former Teacher's Lounge	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st Floor-Office 108, former Teacher's Lounge	236	SF	6	\$817	
	Doors - Transom Window	1st Floor-Office 108, former Teacher's Lounge	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor-Office 108, former Teacher's Lounge	1	EA	6	\$301	
	Floor - Tile	1st Floor-Office 108, former Teacher's Lounge	236	SF	6	\$516	
	Lighting - Pendent/Surface	1st Floor-Office 108, former Teacher's Lounge	5	EA	6	\$619	
	Power Distribution	1st Floor-Office 108, former Teacher's Lounge	10	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor-Office 108, former Teacher's Lounge	875	SF	6	\$2,415	
	Ceiling - Plaster/Drywall	1st Floor-Office Diverse Learners, at Auditorium Lobby	135	SF	6	\$467	
	Doors - Wood Doors inclu hw	1st Floor-Office Diverse Learners, at Auditorium Lobby	1	EA	6	\$301	
	Floor - Carpet	1st Floor-Office Diverse Learners, at Auditorium Lobby	135	SF	4	\$1,241	ripped, stained, worn
	Lighting - Pendent/Surface	1st Floor-Office Diverse Learners, at Auditorium Lobby	1	EA	6	\$124	
	Power Distribution	1st Floor-Office Diverse Learners, at Auditorium Lobby	6	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor-Office Diverse Learners, at Auditorium Lobby	472	SF	6	\$1,303	
	AC Unit	1st Floor-Principal's Office	1	EA	6	\$496	
	Ceiling - Lay-in	1st Floor-Principal's Office	156	SF	6	\$468	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office	2	EA	6	\$602	
	Floor - Wood	1st Floor-Principal's Office	156	SF	6	\$1,100	
	Lighting - Pendent/Surface	1st Floor-Principal's Office	2	EA	6	\$248	
	Power Distribution	1st Floor-Principal's Office	12	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor-Principal's Office	650	SF	6	\$1,794	
	AC Unit	2nd floor south end of corridor	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	2nd floor south end of corridor	99	SF	6	\$343	
	Doors - Transom Window	2nd floor south end of corridor	4	SF	6	\$68	
	Doors - Wood Doors inclu hw	2nd floor south end of corridor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd floor south end of corridor	99	SF	6	\$99	
	Lighting - Pendent/Surface	2nd floor south end of corridor	1	EA	7	\$0	
	Power Distribution	2nd floor south end of corridor	6	EA	7	\$0	
	Walls - Plaster/Drywall	2nd floor south end of corridor	386	SF	6	\$1,065	
	AC Unit	Book room/office 3rd floor	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	Book room/office 3rd floor	326	SF	6	\$1,128	
	Doors - Transom Window	Book room/office 3rd floor	4	SF	6	\$68	
	Doors - Wood Doors inclu hw	Book room/office 3rd floor	1	EA	6	\$301	
	Floor - Wood	Book room/office 3rd floor	326	SF	6	\$2,298	
	Lighting - Pendent/Surface	Book room/office 3rd floor	3	EA	7	\$0	
	Power Distribution	Book room/office 3rd floor	16	EA	7	\$0	
	Walls - Plaster/Drywall	Book room/office 3rd floor	1,032	SF	6	\$2,848	
Auditor	ium & Theater						
	Balcony Seating	1st Floor	76	EA	6	\$13,218	
	Ceiling - Plaster/Drywall	1st Floor	4,480	SF	6	\$37,349	
	Doors - Wood Doors inclu hw	1st Floor	9	EA	6	\$2,709	
	Floor - Carpet	1st Floor	900	SF	4	\$8,275	worn, stained, ripped
	Floor - Concrete	1st Floor	860	SF	6	\$455	
	Floor - Terrazzo	1st Floor	338	SF	6	\$740	
	Floor - Tile	1st Floor	1,862	SF	6	\$4,074	
	Lighting - Chandelier, Incandescent	1st Floor	8	EA	6	\$3,821	
	Lighting - Lay-in	1st Floor	11	EA	6	\$1,309	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	\$1,982	
	Lighting - Wall Mounted	1st Floor	2	EA	6	\$248	
	Main Floor Seating	1st Floor	180	EA	6	\$31,305	
	Sound System	1st Floor	1	EA	6	\$10,721	
	Stage	1st Floor	520	SF	6	\$3,004	
	Stage Curtain	1st Floor	8	EA	6	\$0	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	ium & Theater	Location	Quantity	Unit	Nalik	COSI	Comments
Auditor	Stage Lighting System	1st Floor	1	EA	6	¢º 077	Pendant lights
	Stage-Stairs - Terrazzo	1st Floor	8		6	۶۵,077 \$61	
	Stage-Stairs - Wood	1st Floor	8	LF	6	\$94	
	Stairs - Asphalt	1st Floor	64	LF	6	\$594	Item Type: Concrete
	Stairs - Asphan	1st Floor	16	LF	6	\$122	item rype. Concrete
	Walls - Plaster/Drywall	1st Floor	6,640	SF	6	\$31,619	
		13111001	0,040	01	0	ψ01,019	
Gymna	sia						
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	\$200	peeling, water discoloration
	Ceiling - Plaster/Drywall	1st Floor	3,010	SF	6	\$16,615	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	3,020	SF	6	\$21,291	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	8	EA	6	\$1,070	
	Scoreboards	1st Floor	1	EA	6	\$2,244	
	Walls - Plaster/Drywall	1st Floor	4,625	SF	6	\$12,765	Item Type: Sound Panel
	Walls - Structural Glazed Tile	1st Floor	1,600	SF	6	\$5,034	
Mechar	nical/ Service Rooms						
	Janitor's Closet	1st Floor	26	SF	5	\$419	major cracking, peeling at ceiling
	Janitor's Closet	1st Floor	90	SF	6	\$645	
	Janitor's Closet	2nd Floor	160	SF	6	\$1,146	
	Janitor's Closet	3rd Floor	45	SF	6	\$322	
	Crawl Space - Unfinished	Boiler Room	1,170	SF	6	\$7,245	
	Interior Stairs	Boiler Room	36	LF	6	\$325	
	Mechanical/ Service Rooms	Boiler Room	3,765	SF	6	\$26,974	
	Storage Room	Boiler Room	180	SF	6	\$1,290	
Restroc	om						
	Accessories	1st floor inside engineer's office 2nd	32	SF	6	\$295	
	Ceiling - Plaster/Drywall	1st floor inside engineer's office 2nd	32	SF	6	\$111	
	Doors - Wood Doors inclu hw	1st floor inside engineer's office 2nd	1	EA	6	\$301	
	Floor - Tile/Sheet	1st floor inside engineer's office 2nd	32	SF	6	\$32	
	Lavatory	1st floor inside engineer's office 2nd	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st floor inside engineer's office 2nd	1	EA	7	\$0	
	Walls - Metal Panel	1st floor inside engineer's office 2nd	190	SF	6	\$1,418	
	Water Closet	1st floor inside engineer's office 2nd	1	EA	6	\$336	
	Accessories	1st floor inside engineer's office	32	SF	6	\$295	
	Ceiling - Plaster/Drywall	1st floor inside engineer's office	32	SF	6	\$111	
	Doors - Wood Doors inclu hw	1st floor inside engineer's office	1	EA	6	\$301	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Floor - Tile/Sheet	1st floor inside engineer's office	32	SF	6	\$32	
	Lavatory	1st floor inside engineer's office	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st floor inside engineer's office	1	EA	7	\$0	
	Walls - Metal Panel	1st floor inside engineer's office	190	SF	6	\$1,418	
	Water Closet	1st floor inside engineer's office	1	EA	6	\$336	
	Accessories	1st Floor-Boy's Restroom	300	SF	6	\$2,767	
	Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom	300	SF	6	\$1,038	
	Doors - Transom Window	1st Floor-Boy's Restroom	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor-Boy's Restroom	2	EA	6	\$602	
	Floor Drain	1st Floor-Boy's Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	300	SF	6	\$635	
	Hand Dryer	1st Floor-Boy's Restroom	1	EA	6	\$230	
	Lavatory	1st Floor-Boy's Restroom	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Floor-Boy's Restroom	3	EA	6	\$372	
	Partitions	1st Floor-Boy's Restroom	2	EA	6	\$594	
	Urinals	1st Floor-Boy's Restroom	8	EA	6	\$2,688	
	Walls - Concrete Block	1st Floor-Boy's Restroom	512	SF	6	\$1,501	
	Walls - Plaster/Drywall	1st Floor-Boy's Restroom	512	SF	6	\$1,413	
	Water Closet	1st Floor-Boy's Restroom	2	EA	6	\$672	
	Accessories	1st Floor-Girl's Restroom	350	SF	6	\$3,228	
	Ceiling - Plaster/Drywall	1st Floor-Girl's Restroom	350	SF	6	\$1,211	
	Doors - Steel Doors incl hw	1st Floor-Girl's Restroom	1	EA	6	\$301	
	Doors - Transom Window	1st Floor-Girl's Restroom	18	SF	6	\$305	
	Floor Drain	1st Floor-Girl's Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom	350	SF	6	\$741	
	Lavatory	1st Floor-Girl's Restroom	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Floor-Girl's Restroom	2	EA	6	\$248	
	Partitions	1st Floor-Girl's Restroom	8	EA	6	\$2,375	
	Walls - Plaster/Drywall	1st Floor-Girl's Restroom	562	SF	6	\$1,551	
	Walls - Structural Glazed Tile	1st Floor-Girl's Restroom	562	SF	6	\$1,768	
	Water Closet	1st Floor-Girl's Restroom	8	EA	6	\$2,688	
	Accessories	1st Floor-Main Office Restroom	26	SF	6	\$240	
	Ceiling - Plaster/Drywall	1st Floor-Main Office Restroom	26	SF	6	\$90	
	Doors - Wood Doors inclu hw	1st Floor-Main Office Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Main Office Restroom	26	SF	6	\$55	
	Lavatory	1st Floor-Main Office Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Main Office Restroom	1	EA	6	\$124	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Walls - Plaster/Drywall	1st Floor-Main Office Restroom	268	SF	6	\$740	
	Water Closet	1st Floor-Main Office Restroom	1	EA	6	\$336	
	Accessories	1st Floor-Men's Staff Restroom, next to Office 108	140	SF	6	\$1,291	
	Ceiling - Plaster/Drywall	1st Floor-Men's Staff Restroom, next to Office 108	140	SF	6	\$484	
	Doors - Transom Window	1st Floor-Men's Staff Restroom, next to Office 108	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor-Men's Staff Restroom, next to Office 108	1	EA	6	\$301	
	Floor Drain	1st Floor-Men's Staff Restroom, next to Office 108	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Men's Staff Restroom, next to Office 108	140	SF	6	\$296	
	Lavatory	1st Floor-Men's Staff Restroom, next to Office 108	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Floor-Men's Staff Restroom, next to Office 108	1	EA	6	\$124	
	Lighting - Wall Mounted	1st Floor-Men's Staff Restroom, next to Office 108	1	EA	6	\$124	
	Partitions	1st Floor-Men's Staff Restroom, next to Office 108	2	EA	6	\$594	
	Walls - Plaster/Drywall	1st Floor-Men's Staff Restroom, next to Office 108	626	SF	6	\$1,728	
	Water Closet	1st Floor-Men's Staff Restroom, next to Office 108	2	EA	6	\$672	
	Accessories	1st Floor-Women's Staff Restroom, next to 102	228	SF	6	\$2,103	
	Ceiling - Plaster/Drywall	1st Floor-Women's Staff Restroom, next to 102	228	SF	6	\$789	
	Doors - Transom Window	1st Floor-Women's Staff Restroom, next to 102	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	1st Floor-Women's Staff Restroom, next to 102	4	EA	6	\$1,204	
	Floor Drain	1st Floor-Women's Staff Restroom, next to 102	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Women's Staff Restroom, next to 102	228	SF	6	\$483	
	Lavatory	1st Floor-Women's Staff Restroom, next to 102	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Floor-Women's Staff Restroom, next to 102	3	EA	6	\$372	



RestroomPartitions1st Floor-Women's Staff Restroom, next to 1027FA6\$2,078Walls - Plaster/Drywall1st Floor-Women's Staff Restroom, next to 102478SF6\$1,319Walls - Structural Glazed Tile1st Floor-Women's Staff Restroom, next to 102478SF6\$1,504Water Closet1st Floor-Women's Staff Restroom, next to 1027FA6\$2,352Accessories2nd floor boy's room292SF6\$1,010Doors - Transom Window2nd floor boy's room12SF6\$203Floor Drain2nd floor boy's room1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd floor boy's room292SF6\$618	
to 102Walls - Plaster/Drywall1st Floor-Women's Staff Restroom, next to 102478SF6\$1,319Walls - Structural Glazed Tile1st Floor-Women's Staff Restroom, next to 102478SF6\$1,504Water Closet1st Floor-Women's Staff Restroom, next to 1027EA6\$2,352Accessories2nd floor boy's room292SF6\$2,693Ceiling - Plaster/Drywall2nd floor boy's room292SF6\$1,010Doors - Transom Window2nd floor boy's room1EA6\$2,033Floor Drain2nd floor boy's room1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd floor boy's room292SF6\$618	
to 102Walls - Structural Glazed Tile1st Floor-Women's Staff Restroom, next to 102478SF6\$1,504Water Closet1st Floor-Women's Staff Restroom, next to 1027EA6\$2,352Accessories2nd floor boy's room292SF6\$2,693Ceiling - Plaster/Drywall2nd floor boy's room292SF6\$1,010Doors - Transom Window2nd floor boy's room12SF6\$203Floor Drain2nd floor boy's room1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd floor boy's room292SF6\$618	
Water Closetto 102Water Closet1st Floor-Women's Staff Restroom, next to 1027EA6\$2,352Accessories2nd floor boy's room292SF6\$2,693Ceiling - Plaster/Drywall2nd floor boy's room292SF6\$1,010Doors - Transom Window2nd floor boy's room12SF6\$203Floor Drain2nd floor boy's room1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd floor boy's room292SF6\$618	
to 102Accessories2nd floor boy's room292SF6\$2,693Ceiling - Plaster/Drywall2nd floor boy's room292SF6\$1,010Doors - Transom Window2nd floor boy's room12SF6\$203Floor Drain2nd floor boy's room1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd floor boy's room292SF6\$618	
Ceiling - Plaster/Drywall2nd floor boy's room292SF6\$1,010Doors - Transom Window2nd floor boy's room12SF6\$203Floor Drain2nd floor boy's room1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd floor boy's room292SF6\$618	
Doors - Transom Window2nd floor boy's room12SF6\$203Floor Drain2nd floor boy's room1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd floor boy's room292SF6\$618	
Floor Drain2nd floor boy's room1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd floor boy's room292SF6\$618	
Floor - Tile Ceramic/ Porcelain2nd floor boy's room292SF6\$618	
Hand Dryer2nd floor boy's room1EA6\$230	
Lavatory 2nd floor boy's room 2 EA 6 \$639	
Lighting - Pendent/Surface 2nd floor boy's room 3 EA 7 \$0	
Partitions 2nd floor boy's room 3 EA 6 \$891	
Urinals 2nd floor boy's room 5 EA 6 \$1,680	
Walls - Concrete Block2nd floor boy's room501SF6\$1,469Brick and mortar	
Walls - Plaster/Drywall2nd floor boy's room501SF6\$1,383	
Water Closet2nd floor boy's room3EA6\$1,008	
Accessories 2nd floor girl's room 314 SF 6 \$2,896	
Ceiling - Plaster/Drywall 2nd floor girl's room 314 SF 6 \$1,087	
Doors - Transom Window 2nd floor girl's room 12 SF 6 \$203	
Floor Drain 2nd floor girl's room 1 EA 6 \$1,059	
Floor - Tile Ceramic/ Porcelain 2nd floor girl's room 314 SF 6 \$665	
Lavatory 2nd floor girl's room 2 EA 6 \$639	
Lighting - Pendent/Surface 2nd floor girl's room 3 EA 7 \$0	
Partitions 2nd floor girl's room 6 EA 6 \$1,782	
Walls - Concrete Block2nd floor girl's room507SF6\$1,486Brick and mortar	
Walls - Plaster/Drywall2nd floor girl's room507SF6\$1,399	
Water Closet 2nd floor girl's room 7 EA 6 \$2,352	
Accessories 3rd floor boy's room 292 SF 6 \$2,693	
Ceiling - Plaster/Drywall 3rd floor boy's room 292 SF 6 \$1,010	
Doors - Transom Window 3rd floor boy's room 12 SF 6 \$203	
Floor Drain 3rd floor boy's room 1 EA 6 \$1,059	
Floor - Tile Ceramic/ Porcelain 3rd floor boy's room 292 SF 6 \$618	
Hand Dryer3rd floor boy's room1EA6\$230	
Lavatory 3rd floor boy's room 2 EA 6 \$639	



\$419,806

6710 N Washtenaw Ave Chicago, IL 60645

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Lighting - Pendent/Surface	3rd floor boy's room	3	EA	7	\$0	
	Partitions	3rd floor boy's room	3	EA	6	\$891	
	Urinals	3rd floor boy's room	5	EA	6	\$1,680	
	Walls - Concrete Block	3rd floor boy's room	501	SF	6	\$1,469	Brick and mortar
	Walls - Plaster/Drywall	3rd floor boy's room	501	SF	6	\$1,383	
	Water Closet	3rd floor boy's room	3	EA	6	\$1,008	
	Accessories	3rd floor girl's room	314	SF	6	\$2,896	
	Ceiling - Plaster/Drywall	3rd floor girl's room	314	SF	6	\$1,087	
	Doors - Transom Window	3rd floor girl's room	12	SF	6	\$203	
	Floor Drain	3rd floor girl's room	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd floor girl's room	314	SF	6	\$665	
	Lavatory	3rd floor girl's room	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd floor girl's room	3	EA	7	\$0	
	Partitions	3rd floor girl's room	6	EA	6	\$1,782	
	Walls - Concrete Block	3rd floor girl's room	507	SF	6	\$1,486	Brick and mortar
	Walls - Plaster/Drywall	3rd floor girl's room	507	SF	6	\$1,399	
	Water Closet	3rd floor girl's room	7	EA	6	\$2,352	
	Accessories	Women's room 2nd floor	126	SF	6	\$1,162	
	Ceiling - Plaster/Drywall	Women's room 2nd floor	126	SF	6	\$436	
	Doors - Transom Window	Women's room 2nd floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	Women's room 2nd floor	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Women's room 2nd floor	126	SF	6	\$267	
	Lavatory	Women's room 2nd floor	2	EA	6	\$639	
	Lighting - Pendent/Surface	Women's room 2nd floor	1	EA	6	\$124	
	Partitions	Women's room 2nd floor	2	EA	6	\$594	
	Walls - Plaster/Drywall	Women's room 2nd floor	564	SF	6	\$1,557	
	Water Closet	Women's room 2nd floor	2	EA	6	\$672	

Rooms (Other Than Classrooms) Subtotal:

Building: Main

Group Item - Type	Location	Quantity	Unit	Rank	Cost Commer
Corridor					
Ceiling - Plaster/Drywall	1st Floor	5,255	SF	6	\$32,538
Doors - Wood Doors include hw	1st Floor	8	EA	6	\$2,408
Drinking Fountains - Single Fountain	1st Floor	5	EA	6	\$1,379



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Floor - Terrazzo	1st Floor	538	SF	6	\$4,516	
	Floor - Tile/Sheet	1st Floor	5,428	SF	6	\$2,950	
	Lighting - Pendent/Surface	1st Floor	66	EA	6	\$8,177	
	Student Lockers - One Tier	1st Floor	208	EA	6	\$19,310	
	Walls - Plaster/Drywall	1st Floor	6,780	SF	6	\$30,056	
	Walls - Structural Glazed Tile	1st Floor	5,748	SF	6	\$18,083	
	Ceiling - Plaster/Drywall	2nd Floor / 3rd Floor	3,709	SF	6	\$22,966	
	Drinking Fountains - Double Fountain	2nd Floor / 3rd Floor	1	EA	6	\$336	
	Drinking Fountains - Single Fountain	2nd Floor / 3rd Floor	1	EA	6	\$276	
	Drinking Fountains - Single Water Cooler	2nd Floor / 3rd Floor	1	EA	6	\$317	
	Floor - Tile/Sheet	2nd Floor / 3rd Floor	3,709	SF	6	\$2,015	
	Lighting - Pendent/Surface	2nd Floor / 3rd Floor	29	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor / 3rd Floor	208	EA	6	\$19,310	
	Walls - Plaster/Drywall	2nd Floor / 3rd Floor	3,523	SF	6	\$15,617	
	Walls - Structural Glazed Tile	2nd Floor / 3rd Floor	3,523	SF	6	\$11,083	
	Ceiling - Plaster/Drywall	3rd Floor	2,514	SF	6	\$15,566	
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	6	\$336	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	6	\$276	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	6	\$317	
	Floor - Terrazzo	3rd Floor	300	SF	6	\$2,518	
	Lighting - Pendent/Surface	3rd Floor	29	EA	7	\$0	
	Student Lockers - One Tier	3rd Floor	148	EA	6	\$13,740	
	Walls - Plaster/Drywall	3rd Floor	2,352	SF	6	\$10,426	
	Walls - Structural Glazed Tile	3rd Floor	2,352	SF	6	\$7,399	
Safety							
	Camera Viewing Station		1	EA	6	\$683	
	Security Cameras		1	EA	6	\$194	
Stairs							
	Ceiling - Plaster/Drywall	#1 Stair	192	SF	6	\$1,406	
	Floor - Terrazzo	#1 Stair	84	SF	6	\$705	
	Handrails	#1 Stair	54	LF	6	\$468	
	Lighting - Pendent/Surface	#1 Stair	2	EA	6	\$248	
	Stairs - Terrazzo	#1 Stair	24	LF	6	\$223	
	Walls - Plaster/Drywall	#1 Stair	755	SF	6	\$2,084	
	Walls - Structural Glazed Tile	#1 Stair	755	SF	6	\$2,375	
	Ceiling - Plaster/Drywall	#2 Stair	356	SF	6	\$2,606	



Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs	ion iypo	Location	Quantity	onit	Nullk	COSL	Jonnents
an 3	Floor - Terrazzo	#2 Stair	280	SF	6	\$2,350	
	Handrails	#2 Stair	132	LF	6	\$2,330 \$1,144	
	Lighting - Pendent/Surface	#2 Stair	4	EA	6	\$496	
	Stairs - Terrazzo	#2 Stair	54	LF	6	\$490 \$501	
	Walls - Plaster/Drywall	#2 Stair	1,590	SF	6	\$4,388	
	Walls - Structural Glazed Tile	#2 Stair	1,590	SF	6	\$5,002	
	Ceiling - Plaster/Drywall	#3 Stair	356	SF	6	\$2,606	
	Floor - Terrazzo	#3 Stair	280	SF	6	\$2,350	
	Handrails	#3 Stair	132	LF	6	\$1,144	
	Lighting - Pendent/Surface	#3 Stair	4	EA	6	\$496	
	Stairs - Terrazzo	#3 Stair	54	LF	6	\$501	
	Walls - Plaster/Drywall	#3 Stair	1,590	SF	6	\$4,388	
	Walls - Structural Glazed Tile	#3 Stair	1,590	SF	6	\$5,002	
	Ceiling - Plaster/Drywall	#4 Stair	390	SF	6	\$2,855	
	Floor - Terrazzo	#4 Stair	266	SF	6	\$2,233	
	Handrails	#4 Stair	26	LF	6	\$225	
	Lighting - Pendent/Surface	#4 Stair	4	EA	6	\$496	
	Stairs - Terrazzo	#4 Stair	64	LF	6	\$594	
	Walls - Plaster/Drywall	#4 Stair	1,035	SF	6	\$2,856	
	Walls - Structural Glazed Tile	#4 Stair	1,035	SF	6	\$3,256	
ildi	ng Interior Subtotal:					\$295,792	
otal	Building Cost				\$3	3,037,894	
3uildi	ng: Addition 1						
Categ	ory: Building Exterior						
roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntranc							
	Exterior Doors - Exterior Steel Door	Door 7	1	EA	6	\$481	
	Exterior Stairs - Concrete	Door 7	2	LF	6	\$164	
	Exterior Stairs - Stone	Door 7	4	LF	6	\$452	
ounda	tion						
	Foundation - Concrete	Entire Building	545	LF	7	\$0	
	Superstructure - Concrete	Entire Building	24,672	SF	7	\$0	
		-					



Building: Addition 1

Category: Building Exterior

JIOUP	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	\$2,146	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	\$577	
oof Sy	/stem						
	Coping - Terra Cotta	Roof 1	273	LF	6	\$8,768	
	Downspouts - Interior Downspouts	Roof 1	70	LF	6	\$2,326	
	Parapet - 16" - 30" Height	Roof 1	273	LF	6	\$10,907	
	Roof Structure - Concrete	Roof 1	5,122	SF	7	\$0	
	Roof - Modified Bitumen	Roof 1	5,122	SF	5	\$107,743	Leaking
Valls							
	Exterior Walls - Brick	Entire Building	14,008	SF	6	\$94,148	
	Exterior Walls - Brick	Entire Building / Façade- NW	3,944	SF	5	\$83,358	Open joints, efflorescence
	Exterior Walls - Terra Cotta	Entire Building	544	SF	6	\$3,656	
Vindow	vs						
	Guard - Guards perforated	Entire Building	1,763	SF	7	\$0	
	Lintels - Steel	Entire Building	336	LF	6	\$9,754	
	Lintels - Terra Cotta	Entire Building	28	LF	6	\$0	
		Entre Demaning					
	Windows - Sash Aluminum Double-pane	Entire Building	3,656	SF	6	\$27,291	
Buildi		•		SF	6	\$27,291 \$351,771	
	Windows - Sash Aluminum Double-pane	•		SF	6		
Buildi	Windows - Sash Aluminum Double-pane	•		SF	6		
Buildi Categ Group	Windows - Sash Aluminum Double-pane ng Exterior Subtotal: ng: Addition 1 ory: Electrical System Item - Type	•				\$351,771	Comments
Buildi Categ Group	Windows - Sash Aluminum Double-pane ng Exterior Subtotal: ng: Addition 1 ory: Electrical System Item - Type ency System	Entire Building	3,656	Unit		\$351,771 Cost	Comments
Buildi Categ Group	Windows - Sash Aluminum Double-pane ng Exterior Subtotal: ng: Addition 1 ory: Electrical System Item - Type ency System Emergency A/C Power - Corridors and Stairs	Entire Building Location Entire Building	3,656			\$351,771 Cost \$514	Comments
Buildi Categ Group	Windows - Sash Aluminum Double-pane ng Exterior Subtotal: ng: Addition 1 ory: Electrical System Item - Type Ency System Emergency A/C Power - Corridors and Stairs Emergency Battery Packs - Corridors and Stairs	Entire Building	3,656 Quantity	Unit	Rank	\$351,771 Cost	Comments
Buildi Categ Group	Windows - Sash Aluminum Double-pane ng Exterior Subtotal: ng: Addition 1 ory: Electrical System Item - Type ency System Emergency A/C Power - Corridors and Stairs	Entire Building Location Entire Building	3,656 Quantity 1,710	Unit	Rank 6	\$351,771 Cost \$514	Comments
Buildi Categ Group	Windows - Sash Aluminum Double-pane ng Exterior Subtotal: ng: Addition 1 ory: Electrical System Item - Type Ency System Emergency A/C Power - Corridors and Stairs Emergency Battery Packs - Corridors and Stairs	Entire Building Location Entire Building Entire Building Entire Building	3,656 Quantity 1,710 8	Unit SF EA	Rank 6 6	\$351,771 Cost \$514 \$1,620	Comments
Buildi Categ Group	Windows - Sash Aluminum Double-pane ng Exterior Subtotal: ng: Addition 1 ory: Electrical System Item - Type Ency System Emergency A/C Power - Corridors and Stairs Emergency Battery Packs - Corridors and Stairs Exit Signs - Corridors and Stairs Security System - Intrusion Detection	Entire Building Location Entire Building Entire Building Entire Building Entire Building	3,656 Quantity 1,710 8 8	Unit SF EA EA	Rank 6 6 6 6	\$351,771 Cost \$514 \$1,620 \$1,198	Comments

Building: Addition 1



Category: Safty System

Group Item - Type	Location	Quantity Un	it R	ank	Cost	Comments
Fire Alarm						
Fire Alarm Strobe Lights	Entire Building	24,672 SF	-	6	\$8,820	
Fire Alarm_System	Entire Building	24,672 SF	=	6	\$11,996	
Safty System Subtotal:					\$20,816	

Building: Addition 1

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler Sy	vstems						
	Piping - Condensate Pipe- Steel	Entire Building	200	LF	6	\$378	
	Piping - Steam Pipe- Steel	Entire Building	200	LF	6	\$378	
	Steam Traps	Entire Building	12	EA	5	\$15,779	
Tempera	ture Control						
	DDC System	Entire Building	24,672	SF	6	\$14,112	
	Thermostats - DDC	Entire Building	12	EA	6	\$0	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	12	EA	6	\$14,973	
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	\$592	
Mecha	nical System Subtotal:					\$46,804	

Building: Addition 1

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost C	Comments
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	24,672	SF	6	\$4,939	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	24,672	SF	6	\$5,998	
	Domestic Piping-Cold Water Risers	Entire Building	24,672	SF	6	\$4,587	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	24,672	SF	6	\$3,881	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	24,672	SF	6	\$4,587	
	Domestic Piping-Hot Water Return Lines	Entire Building	24,672	SF	6	\$3,528	
	Domestic Piping-Hot Water Return Risers	Entire Building	24,672	SF	6	\$3,528	
	Sanitary Piping	Entire Building	24,672	SF	6	\$22,580	
	Storm Piping	Entire Building	24,672	SF	6	\$21,521	



Category: Plumbing System Group Item - Type	Location	Quantity Unit Rank Cost Comments
Piping	Location	
Vent Piping	Entire Building	24,672 SF 6 \$16,582
Plumbing System Subtotal:		\$91,730

Building: Addition 1

Group Item -	Туре	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #11	12 (Regular Classroom)						
AC Ur	nits	1st Floor	1	EA	6	\$496	
Casev	work	1st Floor	14	LF	6	\$354	
Ceiling	g - Lay-in	1st Floor	640	SF	6	\$1,922	
Ceiling	g - Plaster/Drywall	1st Floor	80	SF	6	\$277	
Chalk	Board	1st Floor	8	LF	4	\$734	
Doors	- Transom Window	1st Floor	9	SF	6	\$152	
Doors	- Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor -	- Tile	1st Floor	720	SF	6	\$1,575	
Lightir	ng - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
Marke	er Board	1st Floor	8	LF	7	\$0	
Walls	- Plaster/Drywall	1st Floor	1,390	SF	6	\$3,836	
Work	Sink	1st Floor	1	EA	6	\$379	
lassroom #11	14 (Pre School)						
AC Ur	nits	1st Floor	2	EA	6	\$991	
Casev	work	1st Floor	45	LF	6	\$1,136	
Ceiling	g - Lay-in	1st Floor	1,235	SF	6	\$3,709	
Chalk	Board	1st Floor	22	LF	4	\$2,020	
Doors	- Transom Window	1st Floor	9	SF	6	\$152	
Doors	- Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor -	- Tile	1st Floor	1,235	SF	6	\$2,702	
Lightir	ng - Pendent/Surface	1st Floor	1	EA	5	\$183	Missing cover
Lightir	ng - Pendent/Surface	1st Floor	17	EA	6	\$2,106	
Marke	er Board	1st Floor	8	LF	7	\$0	
Storag	ge/ Closet	1st Floor	32	SF	6	\$232	
Walls	- Plaster/Drywall	1st Floor	1,723	SF	6	\$4,755	
Work	Sink	1st Floor	2	EA	6	\$758	
lassroom #11;	19 (Regular Classroom)						
AC Ur	nits	1st Floor	1	EA	6	\$496	
BOONE		Page 29 o	f 43				Assessment Date: 9/17

Building: Addition 1

oup Item - Type	۵	Location	Quantity	Unit	Rank	Cost	Comments
	egular Classroom)	Eccation	Quantity	Unit	Nalik	0031	Comments
Casework		1st Floor	14	LF	6	\$354	
Ceiling - La	av-in	1st Floor	640	SF	6	\$1,922	
	Plaster/Drywall	1st Floor	80	SF	6	\$277	
Chalk Boar		1st Floor	8	LF	4	\$734	
	ansom Window	1st Floor	9	SF	6	\$754 \$152	
	ood Doors inclu hw	1st Floor	9	EA	6	\$301	
Floor - Tile		1st Floor	720	SF	6	\$1,575	
	Pendent/Surface	1st Floor	12	EA	6	\$1,373 \$1,487	
Marker Boa		1st Floor	8	LF	7	\$1,487 \$0	
	ister/Drywall	1st Floor	1,390	SF	6	\$3,836	
Walls - Fla Work Sink		1st Floor	1,390	EA	6	\$3,830 \$379	
WOR SINK		15111001	I	LA	0	4019	
issroom #121 (P	re School)						
AC Units		1st Floor	2	EA	6	\$991	
Casework		1st Floor	60	LF	6	\$1,515	
Ceiling - La	ay-in	1st Floor	1,235	SF	6	\$3,709	
Chalk Boar	ď	1st Floor	22	LF	4	\$2,020	
Doors - Tra	ansom Window	1st Floor	9	SF	6	\$152	
Doors - Wo	ood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile		1st Floor	1,235	SF	6	\$2,702	
Lighting - I	Pendent/Surface	1st Floor	18	EA	6	\$2,230	
Storage/ Cl	loset	1st Floor	32	SF	6	\$232	
Walls - Pla	ster/Drywall	1st Floor	1,723	SF	6	\$4,755	
Work Sink		1st Floor	1	EA	5	\$1,508	Dripping
Work Sink		1st Floor	1	EA	6	\$379	
ssroom #201 (R	egular Classroom)						
AC Units		2nd Floor	1	EA	7	\$0	
Casework		2nd Floor	10	LF	6	\$253	
Ceiling - La	av-in	2nd Floor	730	SF	6	\$2,192	
Chalk Boar		2nd Floor	30	LF	4	\$2,754	
	ansom Window	2nd Floor	2	SF	6	\$34	
	ood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Tile		2nd Floor	730	SF	6	\$731	
	Pendent/Surface	2nd Floor	12	EA	7	\$0	
Marker Boa		2nd Floor	8	LF	7	\$0	
	ister/Drywall	2nd Floor	1,393	SF	6	\$3,845	
Walls - Tile	•	2nd Floor	.,000	SF	7		Charging Station



Building: Addition 1

				_			
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	730	SF	3	\$7,422	Ceiling is bubbled with water from an active roof drain problem
	Chalk Board	2nd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	2nd Floor	2	SF	6	\$34	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,393	SF	4	\$14,024	The west wall has major damage due to an active roof drain problem
	Walls - Tile	2nd Floor	1	SF	7	\$0	Charging Station
Classro	oom #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	730	SF	6	\$2,192	
	Chalk Board	2nd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	2nd Floor	2	SF	6	\$34	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,393	SF	6	\$3,845	
Classro	oom #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	730	SF	6	\$2,192	
	Chalk Board	2nd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	2nd Floor	2	SF	6	\$34	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,393	SF	6	\$3,845	
	Walls - Tile	2nd Floor	1	SF	7	\$0	



Building: Addition 1

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assroom #212 (Regular Classroom)						
AC Units	2nd Floor	1	EA	6	\$496	
Casework	2nd Floor	24	LF	6	\$606	
Ceiling - Lay-in	2nd Floor	704	SF	6	\$2,114	
Doors - Transom Window	2nd Floor	2	SF	6	\$34	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Tile/Sheet	2nd Floor	704	SF	6	\$705	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
Marker Board	2nd Floor	20	LF	7	\$0	
Walls - Plaster/Drywall	2nd Floor	1,208	SF	6	\$3,334	
Work Sink	2nd Floor	1	EA	6	\$379	
assroom #214 (Art Room)						
AC Units	2nd Floor	2	EA	7	\$0	
Casework	2nd Floor	72	LF	6	\$1,818	
Ceiling - Lay-in	2nd Floor	1,235	SF	6	\$3,709	
Doors - Transom Window	2nd Floor	2	SF	6	\$34	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Tile/Sheet	2nd Floor	1,235	SF	6	\$1,236	
Lighting - Pendent/Surface	2nd Floor	18	EA	7	\$0	
Marker Board	2nd Floor	8	LF	7	\$0	
Walls - Plaster/Drywall	2nd Floor	1,723	SF	6	\$4,755	
Walls - Tile	2nd Floor	1	SF	6	\$2	
Work Sink	2nd Floor	1	EA	6	\$379	
assroom #219 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	\$0	
Casework	2nd Floor	18	LF	6	\$455	
Ceiling - Lay-in	2nd Floor	704	SF	6	\$2,114	
Chalk Board	2nd Floor	20	LF	4	\$1,836	
Doors - Transom Window	2nd Floor	2	SF	6	\$34	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Tile/Sheet	2nd Floor	704	SF	6	\$705	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
Walls - Plaster/Drywall	2nd Floor	1,208	SF	6	\$3,334	
Walls - Tile	2nd Floor	4	SF	7	\$0	Charging Station
Work Sink	2nd Floor	1	EA	6	\$379	



Category:	Classrooms
-----------	------------

Group Item - Type	Location	Quantity Unit Rank	Cost Comments	
Classrooms Subtotal:		\$1	47,771	

Building: Addition 1

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ministrative Suites/Offices						
AC Unit	Room 202A teacher's lounge	1	EA	6	\$496	
Ceiling - Plaster/Drywall	Room 202A teacher's lounge	352	SF	6	\$1,218	
Doors - Transom Window	Room 202A teacher's lounge	2	SF	6	\$34	
Doors - Wood Doors inclu hw	Room 202A teacher's lounge	1	EA	6	\$301	
Floor - Tile/Sheet	Room 202A teacher's lounge	352	SF	6	\$352	
Lighting - Pendent/Surface	Room 202A teacher's lounge	4	EA	7	\$0	
Power Distribution	Room 202A teacher's lounge	8	EA	7	\$0	
Walls - Plaster/Drywall	Room 202A teacher's lounge	1,008	SF	6	\$2,782	
Ceiling - Plaster/Drywall	Room 205A SPED office(not on plan)	99	SF	6	\$343	
Doors - Wood Doors inclu hw	Room 205A SPED office(not on plan)	1	EA	6	\$301	
Floor - Tile/Sheet	Room 205A SPED office(not on plan)	99	SF	6	\$99	
Lighting - Pendent/Surface	Room 205A SPED office(not on plan)	1	EA	7	\$0	
Power Distribution	Room 205A SPED office(not on plan)	6	EA	7	\$0	
Walls - Plaster/Drywall	Room 205A SPED office(not on plan)	342	SF	6	\$944	
prary						
Casework	2nd Floor	54	LF	6	\$1,364	
Ceiling - Splined	2nd Floor	1,235	SF	6	\$1,007	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Carpet	2nd Floor	1,235	SF	6	\$2,631	
Lighting - Pendent/Surface	2nd Floor	18	EA	7	\$0	
Walls - Plaster/Drywall	2nd Floor	1,888	SF	6	\$5,211	
Walls - Tile	2nd Floor	1	SF	7	\$0	Charging Station
stroom						
Accessories	1st Floor-Classroom 114 Restroom	18	SF	6	\$166	
Ceiling - Plaster/Drywall	1st Floor-Classroom 114 Restroom	18	SF	6	\$62	
Doors - Wood Doors inclu hw	1st Floor-Classroom 114 Restroom	1	EA	6	\$301	
Floor - Tile	1st Floor-Classroom 114 Restroom	18	SF	6	\$39	
Lighting - Pendent/Surface	1st Floor-Classroom 114 Restroom	1	EA	6	\$124	
Walls - Plaster/Drywall	1st Floor-Classroom 114 Restroom	138	SF	6	\$381	
Water Closet	1st Floor-Classroom 114 Restroom	1	EA	6	\$336	



Category: Rooms (Other Than Classrooms)

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
estroom						
Accessories	1st Floor-Classroom 121 Restroom	18	SF	6	\$166	
Ceiling - Plaster/Drywall	1st Floor-Classroom 121 Restroom	18	SF	6	\$62	
Doors - Wood Doors inclu hw	1st Floor-Classroom 121 Restroom	1	EA	6	\$301	
Floor - Tile	1st Floor-Classroom 121 Restroom	18	SF	6	\$39	
Lighting - Pendent/Surface	1st Floor-Classroom 121 Restroom	1	EA	6	\$124	
Walls - Plaster/Drywall	1st Floor-Classroom 121 Restroom	138	SF	6	\$381	
Water Closet	1st Floor-Classroom 121 Restroom	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$20,202

Building: Addition 1

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido)r						
	Ceiling - Plaster/Drywall	1st Floor	556	SF	6	\$3,443	
	Doors - Wood Doors include hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	556	SF	6	\$302	
	Lighting - Pendent/Surface	1st Floor	7	EA	6	\$867	
	Stairs - Terrazzo	1st Floor	4	LF	6	\$37	
	Student Lockers - One Tier	1st Floor	32	EA	6	\$2,971	
	Walls - Plaster/Drywall	1st Floor	884	SF	6	\$3,919	
	Walls - Structural Glazed Tile	1st Floor	642	SF	6	\$2,020	
	Ceiling - Plaster/Drywall	2nd Floor	1,072	SF	6	\$6,638	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	2nd Floor	1,072	SF	6	\$583	
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	90	EA	6	\$8,355	
	Walls - Plaster/Drywall	2nd Floor	967	SF	6	\$4,287	
	Walls - Structural Glazed Tile	2nd Floor	967	SF	6	\$3,042	
Stairs							
	Ceiling - Plaster/Drywall	#5 Stair	210	SF	6	\$1,538	
	Floor - Tile	#5 Stair	82	SF	6	\$45	
	Handrails	#5 Stair	58	LF	6	\$503	
	Lighting - Pendent/Surface	#5 Stair	2	EA	6	\$248	
	Stairs - Terrazzo	#5 Stair	24	LF	6	\$223	
	Walls - Plaster/Drywall	#5 Stair	695	SF	6	\$1,918	



Building: Addition 1

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments	
Stairs							
Walls - Structural Glazed Tile	#5 Stair	695	SF	6	\$2,186		
Building Interior Subtotal:		\$44,061					
Total Building Cost					\$740,951		

Building: Addition 2

Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
e						
Exterior Doors - Exterior Steel Door	Door 5.5: West	1	EA	6	\$481	
Exterior Doors - Store Front	Door 4: East	2	EA	6	\$1,092	
Exterior Doors - Store Front	Door 5: North	2	EA	6	\$1,092	
Exterior Doors - Transom Lite	Door 4: East	2	EA	7	\$0	
Exterior Doors - Transom Lite	Door 5: North	2	EA	7	\$0	
Exterior Stairs - Concrete	Door 4: East	6	LF	7	\$0	
tion						
Foundation - Concrete	Entire Building	279	LF	7	\$0	
Superstructure - Steel	Entire Building	5,923	SF	7	\$0	
3						
Exterior Lighting - Wall Mounted	Entire Building	11	EA	6	\$3,176	
rstem						
Chimney - Metal Flue	Roof 1	22	LF	7	\$0	
Coping - Stone	Roof 1	351	LF	6	\$11,273	
Downspouts - Interior Downspouts	Roof 1	119	LF	7	\$0	
Parapet - 16" - 30" Height	Roof 1	351	LF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 1	5,923	SF	7	\$0	
Roof - EPDM/ Synthetic Rubber	Roof 1	5,923	SF	5	\$114,598	leaking
Canopy - Metal	Entire Building	109	SF	5	\$5,836	Bent, open joint
Exterior Walls - Brick	Entire Building	4,743	SF	6	\$31,878	
/s						
Guard - Guards perforated	Entire Building	81	SF	7	\$0	
Lintels - Steel	Entire Building	102	LF	6	\$2,961	Needs paint
	e Exterior Doors - Exterior Steel Door Exterior Doors - Store Front Exterior Doors - Store Front Exterior Doors - Transom Lite Exterior Doors - Transom Lite Exterior Stairs - Concrete tion Foundation - Concrete Superstructure - Steel Exterior Lighting - Wall Mounted rstem Chimney - Metal Flue Coping - Stone Downspouts - Interior Downspouts Parapet - 16" - 30" Height Roof Structure - Steel / Metal Deck/ Concrete Topping Roof - EPDM/ Synthetic Rubber Canopy - Metal Exterior Walls - Brick rs Guard - Guards perforated	e Exterior Doors - Exterior Steel Door Door 5.5: West Exterior Doors - Store Front Door 4: East Exterior Doors - Store Front Door 4: East Exterior Doors - Transom Lite Door 4: East Exterior Doors - Transom Lite Door 5: North Exterior Doors - Transom Lite Door 5: North Exterior Stairs - Concrete Door 4: East tion Exterior Stairs - Concrete Foundation - Concrete Entire Building Superstructure - Steel Entire Building Stem Exterior Lighting - Wall Mounted Stem Roof 1 Chimney - Metal Flue Roof 1 Coping - Stone Roof 1 Downspouts - Interior Downspouts Roof 1 Parapet - 16" - 30" Height Roof 1 Roof - EPDM/ Synthetic Rubber Roof 1 Canopy - Metal Entire Building Exterior Walls - Brick Entire Building S Guard - Guards perforated Entire Building	e Exterior Doors - Exterior Steel Door Door 5.5: West 1 Exterior Doors - Store Front Door 4: East 2 Exterior Doors - Store Front Door 4: East 2 Exterior Doors - Transom Lite Door 4: East 2 Exterior Doors - Transom Lite Door 5: North 2 Exterior Stairs - Concrete Door 4: East 6 Exterior Stairs - Concrete Door 4: East 6 Foundation - Concrete Entire Building 279 Superstructure - Steel Entire Building 5,923 J Exterior Lighting - Wall Mounted Entire Building 11 Stem Exterior Lighting - Wall Mounted Entire Building 11 Stem Chinney - Metal Flue Roof 1 22 Coping - Stone Roof 1 351 351 Roof Structure - Steel / Metal Deck/ Concrete Topping Roof 1 5,923 Roof - EPDM/ Synthetic Rubber Roof 1 5,923 Canopy - Metal Entire Building 109 Exterior Walls - Brick Entire Building 4,743 S Guard - Guards perforated En	e Exterior Doors - Exterior Steel Door Door 5.5: West 1 EA Exterior Doors - Store Front Door 4: East 2 EA Exterior Doors - Store Front Door 5: North 2 EA Exterior Doors - Transom Lite Door 4: East 2 EA Exterior Doors - Transom Lite Door 4: East 2 EA Exterior Stairs - Concrete Door 4: East 6 LF Door 4: East 6 LF Exterior Stairs - Concrete Entire Building 279 LF Superstructure - Steel Entire Building 5,923 SF Exterior Lighting - Wall Mounted Entire Building 11 EA Exterior Lighting - Wall Mounted Entire Building 11 EA Exterior Joors - Store From Roof 1 22 LF Coping - Stone Roof 1 351 LF Downspouts - Interior Downspouts Roof 1 351 LF Parapet - 16' - 30' Height Roof 1 351 LF Roof 1 351 LF Roof 1 351 LF Roof 1 5,923 SF Roof - EPDM/ Synthetic Rubber Roof 1 5,923 SF Roof 1 5,923 SF Roof - EPDM/ Synthetic Rubber Roof 1 5,923 SF	e Exterior Doors - Exterior Steel Door Door 5.5: West 1 EA 6 Exterior Doors - Store Front Door 4: East 2 EA 6 Exterior Doors - Store Front Door 5: North 2 EA 6 Exterior Doors - Transom Lite Door 4: East 2 EA 7 Exterior Doors - Transom Lite Door 4: East 2 EA 7 Exterior Doors - Transom Lite Door 4: East 6 LF 7 Exterior Stairs - Concrete Door 4: East 6 LF 7 Foundation - Concrete Entire Building 2.79 LF 7 Superstructure - Steel Entire Building 1 EA 6 Sterior Exterior Lighting - Wall Mounted Entire Building 11 EA 6 Sterior Chimney - Metal Flue Roof 1 22 LF 7 Coping - Stone Roof 1 351 LF 6 Downspouts - Interior Downspouts Roof 1 351 LF 7 Parapet - 16" - 30" Height Roof 1 351 LF <td>eExterior Doors - Exterior Steel DoorDoor 5.5: West1EA6\$481Exterior Doors - Store FrontDoor 4: East2EA6\$1,092Exterior Doors - Store FrontDoor 5: North2EA7\$0Exterior Doors - Transom LiteDoor 5: North2EA7\$0Exterior Doors - Transom LiteDoor 4: East2EA7\$0Exterior Stairs - ConcreteDoor 4: East6LF7\$0Exterior Stairs - ConcreteEntire Building279LF7\$0Superstructure - SteelEntire Building5,923SF7\$0Chinney - Metal FlueRoof 122LF7\$0Coping - StoneRoof 123LF7\$0Parapet - 16" - 30" HeightRoof 123LF7\$0Parapet - 16" - 30" HeightRoof 1351LF7\$0Roof Structure - Steel / Metal Deck/ Concrete ToppingRoof 15,923SF7\$0Roof Structure - Steel / Metal Deck/ Concrete ToppingRoof 15,923SF7\$0Roof Structure - Steel / Metal Deck/ Concrete ToppingRoof 15,923SF5\$5,836Exterior Walls - BrickEntire Building109SF5\$5,836Exterior Walls - BrickEntire Building4,743SF6\$31,878Guard - Guards perforatedEntire Building4,743SF6\$31,87</td>	eExterior Doors - Exterior Steel DoorDoor 5.5: West1EA6\$481Exterior Doors - Store FrontDoor 4: East2EA6\$1,092Exterior Doors - Store FrontDoor 5: North2EA7\$0Exterior Doors - Transom LiteDoor 5: North2EA7\$0Exterior Doors - Transom LiteDoor 4: East2EA7\$0Exterior Stairs - ConcreteDoor 4: East6LF7\$0Exterior Stairs - ConcreteEntire Building279LF7\$0Superstructure - SteelEntire Building5,923SF7\$0Chinney - Metal FlueRoof 122LF7\$0Coping - StoneRoof 123LF7\$0Parapet - 16" - 30" HeightRoof 123LF7\$0Parapet - 16" - 30" HeightRoof 1351LF7\$0Roof Structure - Steel / Metal Deck/ Concrete ToppingRoof 15,923SF7\$0Roof Structure - Steel / Metal Deck/ Concrete ToppingRoof 15,923SF7\$0Roof Structure - Steel / Metal Deck/ Concrete ToppingRoof 15,923SF5\$5,836Exterior Walls - BrickEntire Building109SF5\$5,836Exterior Walls - BrickEntire Building4,743SF6\$31,878Guard - Guards perforatedEntire Building4,743SF6\$31,87



Building: Addition 2

Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
Windows						
Windows - Casement Aluminum Double-pane	Entire Building	108	SF	7	\$0	
Windows - Decorative	Entire Building	81	SF	7	\$0	
Windows - Sash Aluminum Double-pane	Entire Building	220	SF	7	\$O	
Building Exterior Subtotal:				\$172,386		

Building: Addition 2

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Emergency A/C Power - Corridors and Stairs	Entire Building	500	SF	6	\$150	
	Emergency A/C Power - Multipurpose Room	Entire Building / 1st Floor	3,032	SF	6	\$1,127	
	Emergency A/C Power - Students Toilets	Entire Building / 1st Floor	230	SF	6	\$86	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	6	\$810	
	Emergency Battery Packs - Multipurpose Room	Entire Building / 1st Floor	3	EA	6	\$608	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	\$599	
	Exit Signs - Multipurpose Room	Entire Building / 1st Floor	1	EA	2	\$545	Missing "EXIT" logo and no longer back lit.
	Exit Signs - Multipurpose Room	Entire Building / 1st Floor	2	EA	6	\$299	
	Security System - Intrusion Detection	Entire Building	5,923	SF	6	\$1,525	
Main Se	ervice						
	PA System	Entire Building	5,923	SF	6	\$1,948	Control console located in main building.
Power I	Distribution						
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	6	\$497	
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	6	\$497	
Electr	ical System Subtotal:					\$8,691	
Buildi	ng: Addition 2						
Categ	ory: Safty System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Ala	rm						
	Fire Alarm Strobe Lights	Entire Building	5,923	SF	6	\$2,117	
	Fire Alarm_System	Entire Building	5,923	SF	6	\$2,880	
	· · · · · · · · · · · · · · · · · · ·	g	0,020	2.	-	÷=,000	

Fire Alarm_System

Sprinkler System

Sprinkler Heads

5,923 SF

7

Entire Building

\$0



Building							
Catego	ory: Safty System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Sprinkle	er System						
	Sprinkler Piping	Entire Building	5,923	SF	6	\$1,101	
	Wet Sprinkler System	Entire Building	5,923	SF	6	\$1,525	
Safty	System Subtotal:					\$7,623	
Buildi	ng: Addition 2						
Catego	ory: Mechanical System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Hand	dling Systems						
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 21 - 30 tons	Roof	1	EA	5	\$25,152	Serves multipurpose room and kitchen.
leating	Devices						
	Unit Heater - Electric	1st Floor	1	EA	6	\$278	
	Wall Heater - Electric	Entire Building	2	EA	6	\$278	
emper	ature Control						
	DDC System	Entire Building	5,923	SF	6	\$3,388	
	Thermostats - DDC	Entire Building / 1st Floor	1	EA	6	\$0	
/entilati	ion						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	6	\$592	
	Type I Exhaust Hood- Kitchen	Entire Building / 1st Floor	1	EA	6	\$1,248	
Mecha	anical System Subtotal:					\$30,936	
	-						
Buildi	ng: Addition 2						
-	ory: Plumbing System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	er						
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	1	EA	6	\$310	
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	5,923	SF	6	\$1,440	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	5,923	SF	6	\$1,101	
	Domestic Piping-Hot Water Return Lines	Entire Building	5,923	SF	6	\$847	
	Sanitary Piping	Entire Building	5,923	SF	6	\$5,421	
		-					

Storm Piping

5,923 SF

6

\$5,167

Entire Building



Plumbing System Subtotal:		\$18,266	
Vent Piping	Entire Building	5,923 SF 6 \$3,981	
Piping			
Group Item - Type	Location	Quantity Unit Rank Cost Comments	
Category: Plumbing System			

Building: Addition 2

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices						
Ceiling - Lay-in	1st Floor-Kitchen Manager's Office	80	SF	6	\$240	
Doors - Steel Doors incl hw	1st Floor-Kitchen Manager's Office	1	EA	6	\$301	
Floor - Terrazzo	1st Floor-Kitchen Manager's Office	80	SF	6	\$175	
Lighting - Lay-in	1st Floor-Kitchen Manager's Office	1	EA	6	\$119	
Power Distribution	1st Floor-Kitchen Manager's Office	6	EA	7	\$0	
Walls - Concrete Block	1st Floor-Kitchen Manager's Office	335	SF	6	\$982	
Kitchen						
Ceiling - Lay-in	1st Floor	1,605	SF	6	\$4,820	
Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
Floor - Terrazzo	1st Floor	1,605	SF	6	\$3,512	
Lighting - Lay-in	1st Floor	15	EA	6	\$1,785	
Serving Line	1st Floor	20	LF	6	\$1,190	
Storage/ Closet	1st Floor	244	SF	6	\$1,769	
Walls - Concrete Block	1st Floor	2,042	SF	6	\$5,986	
unch & Multipurpose Room						
Ceiling - Exposed	1st Floor	3,032	SF	6	\$4,509	
Doors - Store Front	1st Floor	2	EA	6	\$2,416	
Floor - Tile	1st Floor	3,032	SF	6	\$6,634	
Lighting - Pendent/Surface	1st Floor	8	EA	6	\$991	
Lighting - Wall Mounted	1st Floor	18	EA	6	\$2,230	
Storage/ Closet	1st Floor	255	SF	6	\$1,849	
Walls - Concrete Block	1st Floor	3,330	SF	6	\$9,762	
Restroom						
Accessories	1st Floor-Boy's Restroom	115	SF	6	\$1,061	
Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom	115	SF	6	\$398	
Doors - Steel Doors incl hw	1st Floor-Boy's Restroom	1	EA	6	\$301	
Floor Drain	1st Floor-Boy's Restroom	1	EA	6	\$1,059	



Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments				
Restroc	estroom										
	Floor - Terrazzo	1st Floor-Boy's Restroom	115	SF	6	\$252					
	Lavatory	1st Floor-Boy's Restroom	1	EA	6	\$320					
	Lighting - Pendent/Surface	1st Floor-Boy's Restroom	2	EA	6	\$248					
	Partitions	1st Floor-Boy's Restroom	2	EA	6	\$594					
	Urinals	1st Floor-Boy's Restroom	1	EA	6	\$336					
	Walls - Concrete Block	1st Floor-Boy's Restroom	392	SF	6	\$1,149					
	Water Closet	1st Floor-Boy's Restroom	1	EA	6	\$336					
	Accessories	1st Floor-Girl's Restroom	115	SF	6	\$1,061					
	Ceiling - Plaster/Drywall	1st Floor-Girl's Restroom	115	SF	6	\$398					
	Doors - Steel Doors incl hw	1st Floor-Girl's Restroom	1	EA	6	\$301					
	Floor Drain	1st Floor-Girl's Restroom	1	EA	6	\$1,059					
	Floor - Terrazzo	1st Floor-Girl's Restroom	115	SF	6	\$252					
	Lavatory	1st Floor-Girl's Restroom	1	EA	6	\$320					
	Lighting - Pendent/Surface	1st Floor-Girl's Restroom	2	EA	6	\$248					
	Partitions	1st Floor-Girl's Restroom	2	EA	6	\$594					
	Walls - Concrete Block	1st Floor-Girl's Restroom	392	SF	6	\$1,149					
	Water Closet	1st Floor-Girl's Restroom	2	EA	6	\$672					
Room	s (Other Than Classrooms) Subtotal:					\$61,978					

Rooms (Other Than Classrooms) Subtotal:

Building: Addition 2

Category: Building Interior

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments				
rridor										
Ceiling - Lay-in	1st Floor	500	SF	6	\$1,502					
Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602					
Floor - Tile/Sheet	1st Floor	500	SF	6	\$272					
Lighting - Lay-in	1st Floor	5	EA	6	\$595					
Walls - Concrete Block	1st Floor	660	SF	6	\$1,935					
Walls - Plaster/Drywall	1st Floor	500	SF	6	\$2,217					
uilding Interior Subtotal:					\$7,121					
otal Building Cost					\$307,001					

SITE



Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-		Location	quantity	Unit	Nalik	COSL	Volumenta
Athletic		Nanth	0.000	05	0	MAE 440	
	Surface - Asphalt	North	6,266	SF	6	\$15,143	
Civil/Dra	ainage						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	7	\$0	
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	\$621	Location: window wells
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	7	\$0	
Fencing	1						
Tenonig	Fencing - Chain Link	Entire Site	2,099	LF	6	\$39,411	Needs paint
Landsca	2D6						
Lanusta	Benches	Entire Site	2	EA	4	\$5 652	Damaged
	Benches	Entire Site	15	EA	6	\$6,451	
	Landscape - Grass	Entire Site	17,857	SF	6	\$14,811	
	Landscape - Grass	Entire Site / North East	724	SF	5	\$1,097	Bare
	Landscape - Hardscape- Concrete	Entire Site	2,244	SF	5	\$20,986	Daio
	Parkway trees	Entire Site	32	EA	7	\$0,000	
	Planting Beds/ Area	Entire Site	4,478	SF	6	\$7,364	
	Play Area - Asphalt/ Hardscape	Entire Site	46,397	SF	6	\$112,128	
	Trash Receptacles	Entire Site	1	EA	6	\$312	
Parking							
I alking	Concrete Curbs	Northwest	140	LF	6	\$1,798	
	Interior Plantings	Northwest	30	LF	6	\$1,276	
	Surface - Asphalt	Northwest	17,223	SF	5	\$78,566	
	Surface - Asphalt	Northwest / Courtyard	742	SF	4	\$7,862	
	Vehicular Screening	Northwest	60	LF	6	\$4,724	
Diama	-					÷ .,. = .	
Playgro	Equipment - Pre K 3-5	East	1	EA	7	\$0	
	Equipment - School Age 5-12	East	1	EA	7	\$0 \$0	
	Surface - Poured Surface	East	3,307	SF	6	₄₀ \$24,213	
		Luot	0,001	0	0	Ψ=7,210	
Sidewal	lks						
	Sidewalks - Internal Walks	Entire Site	363	LF	6	\$4,360	
	Sidewalks - Perimeter Sidewalks	Entire Site	21,687	SF	6	\$43,107	
Signage	9						
	Flag Pole - Flag Pole	Entire Site	1	EA	6	\$1,657	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	\$0	



Category: Site

SITE

outegory. One				
Group Item - Type	Location	Quantity Unit Rank	Cost (Comments
Site Subtotal:		\$3	891,539	
Total Site Cost		\$3	91,539	
Campus Total ² ³		\$4,47	7.385	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main								II						
Computer Lab	Regular Classroom	2nd Floor	217	217	734	2	30	60	150	75	40	Ν	Y	Y
Dance Room	Regular Classroom	1st Floor	106	106	715	1	2	14	150	75	40	N	Y	Ν
Music Room	Regular Classroom	1st Floor	105	105	715	1	2	14	150	75	40	N	Y	Ν
Office	Regular Classroom	1st Floor	109	107	715	1	2	14	150	75	40	N	Y	Ν
Office	Regular Classroom	3rd Floor	302	302	350	1	1	6	80	40	40	N	N	Ν
Regular Classroom	Regular Classroom	1st Floor	101	101	715	1	2	14	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	102	102	715	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	103	103	715	1	2	14	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	104	104	715	1	2	14	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	110	108	730	1	2	14	200	100	40	N	N	Ν
Regular Classroom	Regular Classroom	1st Floor	111	109	715	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	113	111	715	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	115	113	600	1	2	14	200	100	40	N	N	Ν
Regular Classroom	Regular Classroom	1st Floor	117	115	655	1	2	14	200	100	40	N	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	204	204	719	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	206	206	719	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	207	207	719	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	208	208	719	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	209	209	719	1	2	14	150	75	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	211	211	719	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	213	213	719	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	215	215	734	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	301	301	719	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	303	303	719	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	304	304	730	1	2	14	200	100	40	N	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	305	305	719	1	2	14	150	75	40	N	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	306	306	730	1	2	14	200	100	40	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	307	307	719	1	2	14	150	75	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	308	308	730	1	2	14	200	100	40	Ν	N	Ν
Science Lab Level 1	Science Lab Level 1	2nd Floor	210	210	914	1	2	16	240	120	40	Ν	Ν	Ν
Addition 1														
Art Room	Art Room	2nd Floor	214	214	1,235	1	6	20	150	72	40	N	Y	Ν
Pre School	Kindergarten	1st Floor	114	112	1,235	1	6	20	150	72	40	N	Y	Ν
Pre School	Kindergarten	1st Floor	121	119	1,235	1	6	20	150	72	40	N	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	112	110	720	1	6	12	125	60	40	N	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	119	117	720	1	6	12	125	60	40	Ν	Y	Ν



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Addition 1														
Regular Classroom	Regular Classroom	2nd Floor	201	201	730	1	2	14	200	100	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	202	202	730	1	2	14	200	100	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	203	203	730	1	2	14	200	100	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	205	205	730	1	2	14	200	100	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	212	212	704	1	6	12	125	60	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	219	219	704	1	6	12	125	60	40	Ν	Y	Ν